Workorder: Problem:	1105633 Pre Delivery	Meter: Inspection	0			In Date:	05/31/2011	Closed:	05/31/2011
- Pre Delivery									
- Wash Vehic	le								
	Hou :	ırs 3.00		Labor:	180.00	Parts:	0.00	Total:	180.00
Workorder: Problem:	1105919 1 - Wash tick	Meter: tet(s) issued	276 d			In Date:	06/03/2011	Closed:	06/03/2011
- 1 - Wash tic	ket(s) issued								
	Hou :	ırs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1105973 1 - Wash tick	Meter: tet(s) issued	276 d			In Date:	06/06/2011	Closed:	06/06/2011
- 1 - Wash tic	ket(s) issued								
	Hou :	ırs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1107098 Move pintle h	Meter: hitch to lowy	1074 wer positio	n.		In Date:	07/06/2011	Closed:	07/08/2011
- Fabricate ar lowest point a	nd reposition H	litch pindel	hook and t	tongue to	Parts Li Shop Su				Qty 1.00
- Shop Suppli	es				enop et	,ppnee			
	Hou :	ırs 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00
Workorder: Problem:	Hou : 1108653 install fire pu	Meter:	2395	Labor:	60.00	Parts: In Date:	2.00 08/16/2011	Total: Closed:	62.00 09/13/2011
Problem: - R&r Tailgate	: 1108653	Meter: mp brakets			60.00 Parts Li	In Date:			
Problem: - R&r Tailgate Pump 4 times	: 1108653 install fire pu and bed liner	Meter: mp brakets r. Mod. and				In Date:			09/13/2011
Problem: - R&r Tailgate Pump 4 times - Modify suction	: 1108653 install fire pu	Meter: mp brakets r. Mod. and			Parts Li Shop Su	In Date:	08/16/2011		09/13/2011 Qty
Problem: - R&r Tailgate Pump 4 times - Modify suction - Test drive	: 1108653 install fire pu and bed liner on pipe on pu	Meter: mp brakets r. Mod. and			Parts Li Shop Su T-1 Blac	In Date:	08/16/2011 ss		09/13/2011 Qty 1.00
Problem: - R&r Tailgate Pump 4 times - Modify suction	: 1108653 install fire pu and bed liner on pipe on pu	Meter: mp brakets r. Mod. and			Parts Li Shop Su T-1 Blac 1x2 24 E 3"x3"x20	In Date: ist upplies k Paint Glo Box Tubing D' Alum Ang	08/16/2011 ss 1/8" Wall le Architectua	Closed:	09/13/2011 Qty 1.00 1.00 8.00 6.00
Problem: - R&r Tailgate Pump 4 times - Modify suction - Test drive	: 1108653 install fire pu and bed liner on pipe on pu	Meter: mp brakets r. Mod. and		pins.r&r	Parts L i Shop Su T-1 Blac 1x2 24 F 3"x3"x20 3/4" Spr	In Date: ist upplies ok Paint Glo Box Tubing	08/16/2011 ss 1/8" Wall le Architectua	Closed:	09/13/2011 Qty 1.00 1.00 8.00 6.00 12.00
Problem: - R&r Tailgate Pump 4 times - Modify suction - Test drive	: 1108653 install fire pu e and bed liner on pipe on pur es	Meter: mp brakets r. Mod. and		pins.r&r	Parts Li Shop Su T-1 Blac 1x2 24 E 3"x3"x20	In Date: ist upplies ok Paint Glo Box Tubing D' Alum Ang ing Lock La	08/16/2011 ss 1/8" Wall le Architectua	Closed:	09/13/2011 Qty 1.00 1.00 8.00 6.00
Problem: - R&r Tailgate Pump 4 times - Modify suction - Test drive - Shop Suppli Workorder:	: 1108653 install fire pu e and bed liner on pipe on pur es	Meter: mp brakets r. Mod. and mp		pins.r&r	Parts L i Shop Su T-1 Blac 1x2 24 F 3"x3"x20 3/4" Spr	In Date: ist upplies ok Paint Glo Box Tubing D' Alum Ang ing Lock La	08/16/2011 ss 1/8" Wall le Architectua tch	Closed:	09/13/2011 Qty 1.00 1.00 8.00 6.00 12.00
Problem: - R&r Tailgate Pump 4 times - Modify suction - Test drive - Shop Suppli Workorder:	: 1108653 install fire puide and bed liner on pipe on puide es Hout 1112609 Pm service	Meter: mp brakets r. Mod. and mp urs 15.50	weild lock	pins.r&r	Parts L i Shop Su T-1 Blac 1x2 24 F 3"x3"x20 3/4" Spr	In Date: ist upplies ok Paint Glo Box Tubing O' Alum Ang ing Lock La Parts: In Date:	08/16/2011 ss 1/8" Wall le Architectua tch 233.77	Closed: Il 1/4" Thick Total:	09/13/2011 Qty 1.00 1.00 8.00 6.00 12.00 1,163.77 12/15/2011
Problem: - R&r Tailgate Pump 4 times - Modify suction - Test drive - Shop Supplin Workorder: Problem: - P.m. Service	: 1108653 install fire puide and bed liner on pipe on puide es Hout 1112609 Pm service	Meter: mp brakets r. Mod. and mp urs 15.50 Meter:	weild lock	pins.r&r	Parts L i Shop Su T-1 Blac 1x2 24 E 3"x3"x20 3/4" Spr 930.00	In Date: ist upplies k Paint Glo Box Tubing D' Alum Ang ing Lock La Parts: In Date:	08/16/2011 ss 1/8" Wall le Architectua tch 233.77	Closed: Il 1/4" Thick Total:	09/13/2011 Qty 1.00 1.00 6.00 12.00 1,163.77
Problem: - R&r Tailgate Pump 4 times - Modify suctiv - Test drive - Shop Suppli Workorder: Problem: - P.m. Service - Install new fi	: 1108653 install fire puide and bed liner on pipe on puide es Hout : 1112609 Pm service e.	Meter: mp brakets r. Mod. and mp urs 15.50 Meter: er and brac	weild lock	pins.r&r	Parts L i Shop Su T-1 Blac 1x2 24 B 3"x3"x20 3/4" Spr 930.00 Parts L i Shop Su	In Date: ist upplies ok Paint Glo Box Tubing D' Alum Ang ing Lock La Parts: In Date: ist upplies	08/16/2011 ss 1/8" Wall le Architectua tch 233.77	Closed: Il 1/4" Thick Total: Closed:	09/13/2011 Qty 1.00 1.00 8.00 6.00 12.00 1,163.77 12/15/2011 Qty
Problem: - R&r Tailgate Pump 4 times - Modify suctiv - Test drive - Shop Suppli Workorder: Problem: - P.m. Service - Install new fi - Rotate and b	: 1108653 install fire puide and bed liner and bed liner on pipe on puide es Hou : 1112609 Pm service e. ire extinguishe	Meter: mp brakets r. Mod. and mp urs 15.50 Meter: er and brack	weild lock	pins.r&r	Parts Li Shop Su T-1 Blac 1x2 24 E 3"x3"x20 3/4" Spr 930.00 Parts Li Shop Su Ph1006	In Date: ist upplies ok Paint Glo Box Tubing D' Alum Ang ing Lock La Parts: In Date: ist upplies	08/16/2011 ss 1/8" Wall le Architectua tch 233.77 11/29/2011	Closed: Il 1/4" Thick Total: Closed:	09/13/2011 Qty 1.00 1.00 8.00 6.00 12.00 1,163.77 12/15/2011 Qty 1.00
Problem: - R&r Tailgate Pump 4 times - Modify suctiv - Test drive - Shop Suppli Workorder: Problem: - P.m. Service - Install new fi - Rotate and b	: 1108653 install fire puide and bed liner and bed liner on pipe on puide es Hou : 1112609 Pm service e. ire extinguisher palance all tire service winch	Meter: mp brakets r. Mod. and mp urs 15.50 Meter: er and brack	weild lock	pins.r&r	Parts Li Shop Su T-1 Blac 1x2 24 E 3"x3"x20 3/4" Spr 930.00 Parts Li Shop Su Ph1006 10-9050	In Date: ist upplies k Paint Glo Box Tubing 0' Alum Ang ing Lock La Parts: In Date: ist upplies 0 Oil Filter A 0 Oil Dexos	08/16/2011 ss 1/8" Wall le Architectua tch 233.77 11/29/2011	Closed: Il 1/4" Thick Total: Closed: 57060	09/13/2011 Qty 1.00 1.00 8.00 6.00 12.00 1,163.77 12/15/2011 Qty 1.00 1.00 1.00
Problem: - R&r Tailgate Pump 4 times - Modify suctiv - Test drive - Shop Suppli Workorder: Problem: - P.m. Service - Install new fi - Rotate and B - Inspect and	: 1108653 install fire puide and bed liner and bed liner on pipe on puide es Hou : 1112609 Pm service e. ire extinguisher palance all tire service winch	Meter: mp brakets r. Mod. and mp urs 15.50 Meter: er and brack	weild lock	pins.r&r	Parts Li Shop Su T-1 Blac 1x2 24 B 3"x3"x20 3/4" Spr 930.00 Parts Li Shop Su Ph1006 10-9050 Custom	In Date: ist upplies k Paint Glo Box Tubing O' Alum Ang ing Lock La Parts: In Date: ist upplies 0 Oil Filter A 0 Oil Dexos 51b Bracket	08/16/2011 ss 1/8" Wall le Architectua tch 233.77 11/29/2011	Closed: Il 1/4" Thick Total: Closed: 57060	09/13/2011 Qty 1.00 1.00 8.00 6.00 12.00 1,163.77 12/15/2011 Qty 1.00 6.00 6.00

Workorder: 1205738 Meter: 9593	In Date: 06/18/2012 Closed: 07/20/2012
Problem: P.M. service and request fire pump pigtail in be	ed and can not access winch controler connector.
- Perform pm service.	Parts List Qty
- Install new rear brake pads and resurface both rear brake	Shop Supplies 1.00
rotors.service calipers and flush brake fluid.automated bleed	Ph10060 Oil Filter Acd Pf48 Wix 57060 1.00
hydraulic system with scan tool.	Rear Brake Pad Set 1.00
 Install new battery isolator, circiut breaker and make up wiring harness.fabricate and make up heavy power and 	10-9050 Oil Dexos1 5w30 6.00
ground cables to rear of bed and install quick connect	2232 Brake Fluid Quart 1.00
receptacle.	Used Firex Refurbed Fire Extingshers 1.00
- Inspect and service power winch.remove and service rusted	Wiper Blade 2.00
planetary gears.reposition winch gear selector and relocate pendant plug receptacle to easy acess.	Battery Isolator 1.00
- Rotate and balance all four tires.	84-9633 Connector 2-gauge (grote) 2.00
- Shop Supplies	82-2178 Circuit Breaker 100amp 1.00
	Cs2rv Red Cable 2 Gauge 25.00
	Cs2l Black Cable 2 Gauge 6.00
Hours 17.75 Labor:	1,065.0 Parts: 484.07 Total: 1,549.07 0

Workorder:1301238Meter:14685In Date:02/04/2013Closed:02/27/2013Problem:Pm service.Check front suspension and whining noise.Larger plug for pump.

- P.m. Service.	Parts List	Qty
- Replace front shocks upper insulating bushings(worn	Dexos 5w30	6.00
out).repaired damaged driver side nerf bar mounting.replace	Filter	1.00
missing pintle pin.	12345841 Gear Oil Syn	2.00
 Diagnose whinning noise from engine area.replace defective belt tensioner. 	18410 Pintle Pin	1.00
- Resurface front and rear brake rotors.replace brake	tensioner	1.00
pads.clean mud and debris from brakes.service and lube	1401 Brake Fluid Bra	1.00
caliper.test drive.	Pads	1.00
- Replace aux. pump connector with bigger plug per request.	Pads	1.00
- Rotate and balance all tires	Plug	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 14.25 Labor:	855.00 Parts: 322.33	Total: 1,177.33

Workorder:1306851Meter:19953Problem:P.M. service.		I	n Date: 07/10/2013	Closed:	07/25/2013
- P.m. Service.		Parts List	t		Qty
- Replace two tires, rotate and balnce all four.		Dexos 5w	30		7.00
- Inspect and service winch.		Napagold Oil Filter			1.00
- Complete wheel alignment.test drive.		Wiper Blade			2.00
- Shop Supplies		Used Fire	X Refurbished		1.00
		Brake Cle	aner		1.00
		35x12.5r1	7 Nitto Grap		2.00
		Shop Sup	plies		1.00
		Tire Dispo	sal Fee		2.00
Hours 8.25 :	Labor:	495.00	Parts: 1,152.02	Total:	1,647.02

Workorder: Problem:	1401119 Pm service a	Meter: Ind check ti	25128 res.			In Date:	02/03/2014	Closed:	02/27/2014
- P.m. Service	Э.				Parts Li	st			Qty
			Dexos 5	w30 Oil			7.00		
rotors.replace				and	Napagol	d Oil Filter			1.00
leaking hub se					Wiper B	ade			2.00
and fabricate l	king and dama				Rr Brake	Pads			1.00
washer reserv		ppor moun		ouring	Rotor				2.00
- Rotate and I	palance all tire	s.			Pb Shoe	Kit			2.00
- Inspect and	service winch.				Cable				1.00
- Shop Suppli	es				2232 Bra	ake Fluid Q	uar		2.00
					Bushing				2.00
					Es9000	Shock Rr L	ift		2.00
					Shock B	oot Kit			1.00
					Napa Oi	l Seal			2.00
					real axle	seals			2.00
					Insulato	Nut			2.00
					Accufit E	Beam			2.00
					containe	r washer			1.00
					Indicato				1.00
					Shop Su	pplies			1.00
	Hou :	ırs 16.75		Labor:	1,005.0 0	Parts:	925.67	Total:	1,930.67
Workorder:	1402714 Tow in. dead	Meter:	25817			In Date:	03/20/2014	Closed:	03/28/2014
FIODIeIII.	TOW III. UEAU	Dattery							
	battery .test s				Parts List				Qty
point test and isolater.diagno #43 with new.					Shop Su	pplies			1.00
- Shop Suppli	es								
	Hou :	irs 3.00		Labor:	180.00	Parts:	2.00	Total:	182.00
Workorder:	1402782	Meter:	25652			In Date:	03/20/2014	Closed:	03/21/2014
Problem:	battery malfu	nction, serv	/ice engine, a	ll gauges	shut off,	vehicle shu	t down		
- Tow From: I	Mosquito Cont	rol To: vist	а						
	•	irs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
	пои	15 0.00		Labor.	0.00	Faits.	0.00	rotai.	0.00

Workorder: 14 Problem: Pr	108638 m service.	Meter:	31031		l	n Date:	08/27/2014	Closed:	09/15/20	014
- Pm service.					Parts List					Qty
- Inspect and tes	t horn electi	rical circuit	for horn inop	.water	Dexos 5w	30 Oil				7.00
 intrusion.relocate and replace horn assembly. Replace two tires and balance all four. Inspect and replace front and rear brake pads.resurface all four brake rotors.service all calipers.bleed brake system. Inspect and service winch. 				Napagold	Oil Filter				1.00	
				Napagold	Air Filter				1.00	
				Used Fire	X Refurb	ished			1.00	
				Brake Clea	aner				1.00	
- Perform comple		Lalianmon	t road tost		Accufit Be	am				2.00
- Shop Supplies		alignmen	1.1040 1651.		High Note	Horn Kit				1.00
					Front Brak	ke Pad Kit	t			1.00
					Rear Brak	e Pad Kit				1.00
					35x12.5r1	7 Nitto Gi	ар			2.00
					Shop Sup	plies				1.00
					Tire Dispo	sal Fee				2.00
	Hour :	s 17.25		Labor:	1,035.0 0	Parts:	1,526.15	Total:	2,561.18	5
Workorder: 15 Problem: Pr	501970 m service El	Meter:	35308		l	n Date:	02/24/2015	Closed:	03/18/20)15
- Pm service.		ectrical pro	blem.		Parts List					Qty
- Check battery a	and charging	n system h	attery failed I	oadtest	Brake Rote					2.00
after recharge.re					Dexos 5w					7.00
fusable link.					Napagold					1.00
 Inspect and ser cables for power 			sition heavy	power	Accufit Be					2.00
- Replace two fro	-		severe brake	<u>a</u>	Wd40 16o	z				1.00
pulsation.bleed b				5	Amg175 F	use				1.00
- Rotate and bala	ance all four	tires.			Battery					1.00
- Shop Supplies					Shop Sup	plies				1.00
	Hour	s 9.25		Labor:	555.00	Parts:	390.04	Total:	945.04	
Workorder: 15 Problem: Le	503432 eft tail lamp a	Meter:	35975 proken		l	n Date:	04/01/2015	Closed:	04/07/20)15
- Replace broker	-	-			Parts List					Qty
- Keplace blokel		ip assento	ıy.		Left Real		Lamn			1.00
					Len Neal	i ali Liyin	Lamp			
- Shop Supplies					Shop Sup	olios				
•	Hour	s 0.50		Labor:	Shop Supj 30.00		157.97	Total:	187.97	1.00
- Shop Supplies Workorder: 15	: 505225	Meter:	37058	Labor:	30.00		157.97 05/26/2015	Total: Closed:	187.97 06/02/20	
- Shop Supplies	: 505225	Meter:	37058	Labor:	30.00	Parts:				
- Shop Supplies Workorder: 15 Problem: To - Recharge batte	: 505225 owed in for n edry and test	Meter: no crank.			30.00	Parts: n Date:				015 Qty
- Shop Supplies Workorder: 15 Problem: To	: 505225 owed in for n edry and test for. ubbing on fe	Meter: no crank. t charging	system.repla	се	30.00	Parts:)15

Workorder: Problem:	1505242 w	Meter:	37022			In Date:	05/22/2015	Closed:	05/26/2015
- Tow From: b	eeline & pga	To: 2601	Lv shop						
	Hou :	urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1506465 Charging sys	Meter: stem messa	37598 ige on dash.			In Date:	06/26/2015	Closed:	07/15/2015
- Diagnose ch retest.test drive	e.	n.r&r defect	ive alternato	r and	Parts L Shop S				Qty 1.00
- Shop Supplie		ırs 1.25		Labor:	75.00	Parts:	2.00	Total:	77.00
Workorder: Problem:	1507860 Died on road	Meter:	38125			In Date:	08/05/2015	Closed:	08/05/2015
- Tow From: C Lv Shop	Cypress Creel	k Natural Ar	rea (mack Da	airy) To:					
	Hou :	urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1507863 Tow in,died (Meter: on the road	38359			In Date:	08/05/2015	Closed:	08/19/2015
- Charge batte					Parts L	ist			Qty
system.replace	e defective ba	attery isolate	or and retest	•	Parts L Pwr Co				Qty 1.00
system.replace - Diagnose for	e defective ba r noise.replac	attery isolato e rear rotor	or and retest s,calipers,bra	ake					•
system.replace - Diagnose for pads,parking b	e defective ba r noise.replac orake shoes a	attery isolato e rear rotor	or and retest s,calipers,bra	ake	Pwr Co	nv			1.00
 system.replace Diagnose for pads, parking b 	e defective ba r noise.replac orake shoes a test drive.	attery isolato e rear rotor	or and retest s,calipers,bra	ake	Pwr Co Rotor	nv			1.00 2.00
system.replace - Diagnose for pads,parking b brake system.t	e defective ba r noise.replac orake shoes a test drive.	attery isolato e rear rotor	or and retest s,calipers,bra	ake	Pwr Co Rotor Prk Brk L/rreal (nv			1.00 2.00 1.00
system.replace - Diagnose for pads,parking b brake system.t	e defective ba r noise.replac orake shoes a test drive.	attery isolato e rear rotor	or and retest s,calipers,bra	ake	Pwr Co Rotor Prk Brk L/rreal (R/r Rea	nv Caliper			1.00 2.00 1.00 1.00
system.replace - Diagnose for pads,parking b brake system.t	e defective ba r noise.replac orake shoes a test drive.	attery isolato e rear rotor	or and retest s,calipers,bra	ake	Pwr Co Rotor Prk Brk L/rreal (R/r Rea	nv Caliper Il Caliper Dot 3-32oz			1.00 2.00 1.00 1.00 1.00
system.replace - Diagnose for pads,parking b brake system.t	e defective ba r noise.replac orake shoes a test drive.	attery isolato e rear rotor	or and retest s,calipers,bra	ake	Pwr Co Rotor Prk Brk L/rreal (R/r Rea B Fluid Brake (nv Caliper Il Caliper Dot 3-32oz			1.00 2.00 1.00 1.00 1.00 1.00
system.replace - Diagnose for pads,parking b brake system.t	e defective ba r noise.replac orake shoes a test drive.	attery isolato e rear rotor	or and retest s,calipers,bra	ake	Pwr Co Rotor Prk Brk L/rreal (R/r Rea B Fluid Brake (nv Caliper Il Caliper Dot 3-32oz Cleaner cake Pad Kit			1.00 2.00 1.00 1.00 1.00 1.00 2.00
system.replace - Diagnose for pads,parking b brake system.t	e defective ba r noise.replac orake shoes a test drive.	attery isolato e rear rotor	or and retest s,calipers,bra	ake	Pwr Co Rotor Prk Brk L/rreal 0 R/r Rea B Fluid Brake 0 Rear Br	nv Caliper Il Caliper Dot 3-32oz Cleaner cake Pad Kit			1.00 2.00 1.00 1.00 1.00 1.00 2.00 1.00
system.replace - Diagnose for pads,parking b brake system.t	e defective ba r noise.replac orake shoes a test drive.	attery isolato e rear rotor	or and retest s,calipers,bra	ake	Pwr Co Rotor Prk Brk L/rreal (R/r Rea B Fluid Brake (Rear Br real axle lube	nv Caliper Il Caliper Dot 3-32oz Cleaner cake Pad Kit			1.00 2.00 1.00 1.00 1.00 2.00 1.00 2.00
system.replace - Diagnose for pads,parking b brake system.t	e defective ba r noise.replac orake shoes a test drive.	attery isolato e rear rotor	or and retest s,calipers,bra	ake	Pwr Co Rotor Prk Brk L/rreal (R/r Rea B Fluid Brake (Rear Br real axle lube	nv Caliper Il Caliper Dot 3-32oz Cleaner cake Pad Kit e seals Washer			1.00 2.00 1.00 1.00 1.00 2.00 1.00 2.00 1.00

Workorder:1512275Meter:41013Problem:Pm service.Check tires and trailer plug	In Date: 12/04/2	2015 Closed: 01/19/2016
- Pm service	Parts List	Qty
- Inspect and service winch.had to remove winch from	Dexos 5w30	7.00
bumper to to clean and lube binding planetary gears and	Napagold Oil Filter	1.00
replace housing.	Accufit Beam	2.00
- Check trailer plug and replace open fuse.	Used Fire X Refurbished	1.00
- Rotate and balance all four tires.	Female Conn Socket	1.00
- Shop Supplies	Winch End Cap	1.00
	Shop Supplies	1.00
	Freight Charge	1.00
Hours 6.75 Labor:	405.00 Parts: 185.82	Total: 590.82
Workorder: 1603839 Meter: 43344 Problem: Clicking and popping and squeeking from rear	In Date: 04/12/2	2016 Closed: 04/19/2016
- R&r driveshaft and replace both 'u' joints.	Parts List	Qty
- Shop Supplies	Joint Kit A/c Delco	2.00
	Shop Supplies	1.00
Hours 1.50 Labor:		Total: 339.29

Workorder: 1606869 Meter: 46346 Problem: P.M. service.	In Date: 07/07/2016 Close	d: 07/29/2016
- P.m. Service.	Parts List	Qty
- Replace brokeb transmission fill tube assemble.flush and	Dexos 5w30	7.00
refill transmission.	Napagold Oil Filter	1.00
- Inspect and service transfer case.	Used Fire X Refurbished	1.00
- Resurface front and rear brake rotors.replace front calipers, front and rear pads and parking brake shoes.replace	Accufit Beam	2.00
both axle seal.flush and bleed brake system.	Washer Fluid Concentr	1.00
- Replace rear bumper assemble.transfer pads.	tube seal	1.00
- Replace leaking front shocks.	Tram Tube Assy	1.00
- Rotate and balance all tires.	Syn-atf Trans Fluid S	13.00
- Inspect and service winch.	Syn-atf Trans Fluid S	2.00
- Shop Supplies	R/r Real Caliper	1.00
	L/rreal Caliper	1.00
	Rear Brake Pad Kit	1.00
	Rearparke Shoe	2.00
	B Fluid Dot 3-32oz	1.00
	Brake Cleaner	1.00
	Rear Bumper Assy	1.00
	Disc Pad	1.00
	Front Caliper A/c Delco	1.00
	Front Caliper A/c Delco	1.00
	Brake hose washer	4.00
	real axle seals	2.00
	Front Shock	2.00
	Shop Supplies	1.00
Hours 20.25 Labor:	1,215.0 Parts: 3,406.06 To 0	tal: 4,621.06
Workorder:1609679Meter:47866Problem:Check charging system light on.	In Date: 09/16/2016 Close	d: 09/27/2016
- Test batteries and charging system.recharge	Parts List	Qty
batteries.replace defective isolator.	Pwr Conv	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 1.50 Labor:		tal: 177.53
Workorder: 1612603 Meter: 49009 Problem: replace hitch lock	In Date: 12/08/2016 Close	d: 12/12/2016
- Install new hitch pin lock	Parts List Hitch Pin Lock	Qty 1.00
Hours 0.50 Labor:	30.00 Parts: 13.56 To	tal: 43.56

Workorder: 1702023 Meter: 50837 Problem: P.M. service.	In Date: 02/28/2017	Closed: 05/31/2017
- P.m. service.	Parts List	Qty
- Replace two tires.balance all four .nitro filled.	Seal A/c Delco	1.00
- Complete four wheel alignment.adjusted torsion bars.	Bearing A/c Delco	1.00
- Service winch.replace connector and winch remote due to	Seal A/c Delco	1.00
intermittent connection.replace defective solenoid due to out function inop.found no problems after repairs.	Link Buching	1.00
- Complete front differential service.replace drivers side inne	Bolt	1.00
axle shaft seal and bearing due to leaking.replace worn rear	Napagold Oil Filter	1.00
support bushing.	Napa Syn 5w30 Qt	6.00
- Complete rear differential service .replace leaking rear	Accufit Beam	2.00
pinion seal.refill rear end.	Washer Fluid Concentr	1.00
- Replaced broken passager side torsion key bolt.replace worn sway bar end links bushings.	Used Fire X Refurbished	1.00
- Shop Supplies	Napagold Air Filter	1.00
	Mac Wite Lithium Gres	1.00
	35x12.5r17 Nitto Grap	2.00
	1qt Syngear Oil 75-90	2.00
	Ptex Ultra Grey 3oz	1.00
	Non-chlor Brake Clnr	1.00
	1qt Syngear Oil 75-90	3.00
	Winch Remote	1.00
	Plug In For Winch	1.00
	Bushing	2.00
	Bushing	2.00
	Drop Brkt Bush N	1.00
	Solenoid Assy	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
	Freight Charge	1.00
	Freight Charge	1.00
Hours 23.40 Labor:	Freight Charge 1,404.0 Parts: 1,564.42	1.00 Total: 2,968.42
:	0	10tal. 2,300.42
Workorder: 1707596 Meter: 52198 Problem: Right rear tiregoing flat.	In Date: 08/03/2017	Closed: 08/03/2017
- Repair right rear tire and balance .nitrogen fill tires.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
	60.00 Parts: 2.00	Total: 62.00
:		

Workorder: 1710453 Meter: 53972 Problem: Right headlight inop and battery won't charge a	In Date: 10/24/2017	Closed:	10/31/2017
 Test charging system.perform circuit test .r&r defective battery isolator.retest charging system. Diagnoise noise from belt area.r&r defective belt tensioner and belt. Remove right headlight assembly to test and replace low beam bulb and harness and turn signal bulbs. Charge battery fully.load test battery ,failed .r&r defective battery. Shop Supplies 	Parts ListPwr ConvHalogen BulbHarnesslow Beam SocketBulbV BelttensionerBatteryShop Supplies258.00Parts: 387.86	Total:	Qty 1.00 1.00 2.00 1.00 1.00 1.00 645.86
Workorder: 1800355 Meter: 54904 Problem: P.M. service.	In Date: 01/10/2018	Closed:	01/30/2018
 P.m. service. Durning inspection found play in pitman arm and idler arm replace both and retest. R&r both front upper control arms for play in ball joints.replace worn swaybar links. Inspect and service winch. Balance and rotate all four wheels.nitrofill and reset Tpms. Performed four wheel alignment. Shop Supplies 	Parts List Napagold Oil Filter Napa Syn 5w30 Qt Macs Chain Cable Lube Wd40 Spr 20in Exactfit-beam 22in Exactfit-beam Used Fire X Refurbished Pitman Arm Arm Kit Arm Assy Link Buching Psf Qt Sway Bar Link Link Bushings Shop Supplies Freight Charge		Qty 1.00 6.00 1.00 1.00 1.00 1.00 1.00 2.00 2.00 1.00 1
Hours 15.20 Labor:	912.00 Parts: 881.42	Total:	1,793.42

Workorder:1809264Meter:59242Problem:P.M. service and traction control light comes on		osed: 09/26/2018
- P.m. service.	Parts List	Qty
- Test battery and charging system . Battery failed load test .	Napa Syn 5w30 Qt	6.00
R&r defective battery.	Napagold Oil Filter	1.00
- Resurface rear rotors, replace pads, service Rear calipers.	22in Exactfit-beam	1.00
Replace parking brake shoes and rear avle seals . Flush and bleed brake system . Test drive.	20in Exactfit-beam	1.00
- Replace two tires and balance all four tires . Nitrofill and	Battery	1.00
reset Tpms.	Brk Shoe	1.00
- Inspect and service winch . Cable end on spool missing .	Disc Pad	1.00
Install new end and respool cable .	B Fluid Dot 3-32oz	2.00
- Complete front end alignment. Test drive .	Non-chlor Brake Clnr	1.00
- Computer scan for code . No codes present . Test could not dupicate traction control light on .	35x12.5r17 Nitto Grap	2.00
- Shop Supplies	real axle seals	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 17.25 Labor:	1,035.0 Parts: 1,471.04 0	Total: 2,506.04
 Computer diagnose traction control light . Replace both front hub bearing assemblies . Replace steering anle sensor and calibrate steering and yaw rate sensors . Replace center steering link . Test drive. Perform complete front end alignment ,due to steering wheel offset fourty five degrees. Test drive . Diagnose and transport to and from dealer for Abs module programing . P.m. service. Inspect and service winch . Rotate and balance all four tires . Nitrofill all. Perform complete tune up . Replace all eight spark plugs 	Parts List Nut Axle Hub Berng Assy Sbs Sensor Sensor Wire Kit Spark Plug A/c Delco Spark Pul Gs Abs Module Labor Motor Tune-up 16oz Fuel Additive Rod Kit	Qty 2.00 2.00 1.00 1.00 1.00 1.00 2.00 1.00
and ignition wires . Perform engine decarb and flush injectors. Test drive.- Shop Supplies	Napagold Oil Filter Napa Syn 5w30 Qt 22in Exactfit-beam	1.00 1.00 6.00 1.00
	20in Exactfit-beam	1.00
	Chevy Gold Bow Swc	1.00
	Used Fire X Refurbished	1.00
	Shop Supplies	1.00
Hours 19.35 Labor:		Total: 3,776.39

Workorder: 19 Problem: Ste	03887 eering loose	Meter:	61030			In Date:	04/10/2019	Closed:	04/22/2019
 Diagnose play in steering . R&r worn steering gear box and upper and lower steering shafts . Test drive . Perform wheel alignment check and center steering wheel . Shop Supplies 					Steering Gear			Total:	Qty 1.00 1.00 1.00 1.00 1.00 1.791.12
<u></u>	:		0.400.4						4.4.100.100.4.0
Workorder: 19 Problem: P.I	11769 M. sonvice a	Meter:	64891	bandlo		In Date:	11/13/2019	Closed:	11/26/2019
FIUDIeIII. F.I				nanule.					
- P.m. service.					Parts List			Qty	
 Diagnose noise while driving from right front . R&r defective right front hub bearing assembly . Retest . Diagnose driver door hard to close . R&r defective lower left front door hinge . Replace broken left front inner door panel with handle . 					Napa Syn 5w30 Qt				1.00
									6.00
									1.00 2.00
- Rotate and balance all four tires . Nitrofill all.					Front Wheel Hub				1.00
- Inspect and service winch .					Door Trim W Handle				1.00
- Shop Supplies					GI Whit				1.00
					Hinge				1.00
					Shop Supplies				1.00
	Hour	s 10.50		Labor:	766.50	••	1,006.78	Total:	1,773.28
Workorder: 20 Problem: Tra	: 04932 ansition Pre	Meter: p Charge	67501			In Date:	05/15/2020	Closed:	05/15/2020
- Transition Prep	Charae								
	Ũ	s 2.00		Labor:	146.00	Parts:	0.00	Total:	146.00