

**Palm Beach County Fleet Management
Asset Maintenance History**

10183692 2011 FORD ESCAPE Suv, Mid Size, Hybrid

Workorder: 1103199 **Meter:** 0 **In Date:** 03/24/2011 **Closed:** 03/24/2011

Problem: Pre Delivery Inspection

- Pre Delivery Inspection
- Wash Vehicle

Hours 3.00 Labor: 180.00 Parts: 0.00 Total: 180.00
:

Workorder: 1103648 **Meter:** 611 **In Date:** 04/04/2011 **Closed:** 04/04/2011

Problem: 1 - Wash ticket(s) issued

- 1 - Wash ticket(s) issued

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1109800 **Meter:** 5126 **In Date:** 09/14/2011 **Closed:** 09/20/2011

Problem: P. M. SERVICE

- P. M. Service.

- Clean & adjust rear brakes.

- Shop Supplies

Parts List	Qty
Shop Supplies	1.00
1348 Oil Filter Frm Ph3614 Wix 51348	1.00
5w20 Engine Oil	5.00

Hours 3.75 Labor: 225.00 Parts: 28.78 Total: 253.78
:

Workorder: 1203666 **Meter:** 10550 **In Date:** 04/18/2012 **Closed:** 04/26/2012

Problem: pm service

- pm

- service rear brake drums

- Shop Supplies

Parts List	Qty
Shop Supplies	1.00
1348 Oil Filter Frm Ph3614 Wix 51348	1.00
5w20 Engine Oil	5.00

Hours 3.75 Labor: 225.00 Parts: 22.78 Total: 247.78
:

Workorder: 1209840 **Meter:** 15021 **In Date:** 10/15/2012 **Closed:** 10/22/2012

Problem: P.M.SERVICE

- pm

- rear brake drum service

- Shop Supplies

Parts List	Qty
Ph3614 Oil Filter Wi	1.00
Napa Quart 5w20	5.00
Ph3614 Oil Filter Wi	1.00
Napa Quart 5w20	5.00
Shop Supplies	1.00

Hours 3.00 Labor: 180.00 Parts: 49.04 Total: 229.04
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1306836	Meter: 21419	In Date: 07/10/2013	Closed: 07/25/2013
Problem: pm			
- pm	Parts List	Qty	
- rear brake drum svc	Napagold Oil Filter	1.00	
- Shop Supplies	Napa Quart 5w20	5.00	
	Washer Fl	1.00	
	Shop Supplies	1.00	
Hours 3.00	Labor: 180.00	Parts: 25.97	Total: 205.97
:			
Workorder: 1401304	Meter: 25414	In Date: 02/07/2014	Closed: 03/11/2014
Problem: Pm service.Wiper blades.Water in tail lamp.Power outlets inop.Request to detail vehicle.			
- P.m. Service.	Parts List	Qty	
- Replace broken right tail lamp assemble.fabricate and install strobe light.	Clr Rtv Silcn Sealant	1.00	
- Test and replace defective power outlets in dash and center console.	Lam Asy	1.00	
- Service and adjust rear brakes.	Socket	1.00	
- Rotate and balance all tires.	Base Asy	1.00	
- Shop Supplies	luminous	1.00	
	Ring	1.00	
	5w20 Engine Oil	5.00	
	Napagold Oil Filter	1.00	
	Napagold Air Filter	1.00	
	Wiper Blade	2.00	
	Ww-1202 Wiper Blade M	1.00	
	Bulb	1.00	
	Socket	1.00	
	Shop Supplies	1.00	
Hours 6.25	Labor: 375.00	Parts: 271.24	Total: 646.24
:			
Workorder: 1401580	Meter: 25414	In Date: 02/19/2014	Closed: 02/19/2014
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued			
- 1 - Detail Vehicle Wash Ticket(s) Issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1411033	Meter: 29650	In Date: 11/04/2014	Closed: 11/18/2014
Problem: Pm service.Check battery and wiper blades.Request to detail vehicle.			
- Pm service.	Parts List	Qty	
- Charge battery fully.test battery and charging system.replace defective battery.	Napagold Oil Filter	1.00	
- Test and replace defective right rear turnsignal lamp bulb and socket.	5w20 Engine Oil	5.00	
- Replace and balance all four tires.	Wiper Blade	2.00	
- Inspect and service rear drum brakes.	Washer FI	1.00	
- Perform wheel alignment.test drive.	Mac Wite Lithium Gres	1.00	
- Shop Supplies	Ww-1202 Wiper Blade M	1.00	
	Bxt96r 59	1.00	
	Bulb	1.00	
	Light Socket	1.00	
	183407418 P235-70r16	4.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	4.00	
Hours 9.00	Labor: 540.00	Parts: 1,013.40	Total: 1,553.40
:			
Workorder: 1411311	Meter: 15131	In Date: 11/12/2014	Closed: 11/12/2014
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued			
- 1 - Detail Vehicle Wash Ticket(s) Issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1502602	Meter: 31819	In Date: 03/12/2015	Closed: 03/31/2015
Problem: Pm service.Ac blows warm air.Detail.			
- Pm service.	Parts List	Qty	
- Ac performance test and leak test for ac blows warm air.	5w20 Engine Oil	5.00	
Evacuate system.replace defective leaking ac condenser and accumulator.vacume and recharge system to specs.	Napagold Oil Filter	1.00	
- Rotate and balance all four tires.	Wiper Blade	2.00	
- Inspect and service rear drum brakes.	Ww-1202 Wiper Blade M	1.00	
- Shop Supplies	Condeser Ac	1.00	
	dehydrator	1.00	
	Oil	1.00	
	R134a Lv Shop 1	2.00	
	Seal Kit	1.00	
	Shop Supplies	1.00	
Hours 9.00	Labor: 540.00	Parts: 526.27	Total: 1,066.27
:			
Workorder: 1502962	Meter: 31691	In Date: 03/20/2015	Closed: 03/20/2015
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued			
- 1 - Detail Vehicle Wash Ticket(s) Issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1510090	Meter: 34068	In Date: 10/05/2015	Closed: 10/20/2015
Problem: Pm service.Detail.			
- Pm service.	Parts List	Qty	
- Test and replace defective left rear tail lamp bulb.	5w20 Engine Oil	5.00	
- Rotate and balance all four wheels	Napagold Oil Filter	1.00	
- Inspect and service rear brakes.	Wiper Blade	2.00	
- Shop Supplies	Ww-1202 Wiper Blade M	1.00	
	Washer Fluid Concentr	1.00	
	Bulb	1.00	
	Shop Supplies	1.00	
Hours 4.50	Labor: 270.00	Parts: 71.02	Total: 341.02
:			
Workorder: 1510658	Meter: 34068	In Date: 10/21/2015	Closed: 10/21/2015
Problem: 1 - Wash ticket(s) issued			
- 1 - Wash ticket(s) issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1605906	Meter: 37457	In Date: 06/08/2016	Closed: 06/21/2016
Problem: P.M. Service.Windshield broke.Left tail light crack.Detail.			
- P.m. Service.	Parts List	Qty	
- Replace left tail light,replace bulb and socket.	Napagold Oil Filter	1.00	
- Service and adjust rear brakes.	5w20 Engine Oil	5.00	
- Rotate and balance tires.	Wiper Blade	2.00	
- Shop Supplies	Ww-1202 Wiper Blade M	1.00	
	Washer Fluid Concentr	1.00	
	Taiil Lamp Asy	1.00	
	Socket	1.00	
	Bulb	1.00	
	Shop Supplies	1.00	
Hours 5.00	Labor: 300.00	Parts: 145.13	Total: 445.13
:			
Workorder: 1606105	Meter: 37243	In Date: 06/14/2016	Closed: 06/21/2016
Problem: repair chipped windsheild			
- Repair chipped windshield	Parts List	Qty	
- Shop Supplies	Shop Supplies	1.00	
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
Workorder: 1606237	Meter: 37243	In Date: 06/17/2016	Closed: 06/17/2016
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued			
- 1 - Detail Vehicle Wash Ticket(s) Issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1704295	Meter: 41326	In Date: 04/28/2017	Closed: 05/08/2017
Problem: P.M.SERVICE			
- Pm Service.	Parts List	Qty	
- Replace tag lamp bulb.	Napagold Oil Filter	1.00	
- Service rear brakes.clean and adjust.	Napa Quart 5w20	5.00	
- Rorate and balance four tires.	Accufit Rear	1.00	
- Shop Supplies	Washer Fluid Concentr	1.00	
	Bulb	1.00	
	Shop Supplies	1.00	
Hours 4.00	Labor: 240.00	Parts: 34.84	Total: 274.84
:			
Workorder: 1800123	Meter: 44430	In Date: 01/03/2018	Closed: 01/19/2018
Problem: PM Service.			
- Pm Service	Parts List	Qty	
- Service rear brakes.	Napagold Oil Filter	1.00	
- Rotate and balance tires.	Napa Quart 5w20	5.00	
- Shop Supplies	Washer Fluid Concentr	1.00	
	20in Exactfit-beam	2.00	
	Shop Supplies	1.00	
Hours 3.75	Labor: 225.00	Parts: 51.04	Total: 276.04
:			
Workorder: 1808659	Meter: 47973	In Date: 08/22/2018	Closed: 08/31/2018
Problem: PM Service.Check engine light on.			
- Pm Service	Parts List	Qty	
- Scan and clear emisions code P2450.road test ok at this time.	Napa Quart 5w20	5.00	
- Rear brake service clean and adjust.	Napagold Oil Filter	1.00	
- Rotate and balance four tires.	Washer Fluid Concentr	1.00	
- Vacume debris from engine compartment and air cowl.	20in Exactfit-beam	2.00	
- Shop Supplies	12in Exactfit-rear	1.00	
	Shop Supplies	1.00	
Hours 6.50	Labor: 390.00	Parts: 60.86	Total: 450.86
:			
Workorder: 1904274	Meter: 50026	In Date: 04/18/2019	Closed: 04/18/2019
Problem: Transition Prep Charge			
- Transition Prep Charge			
Hours 2.00	Labor: 134.00	Parts: 0.00	Total: 134.00
:			