

**Palm Beach County Fleet Management
Asset Maintenance History**

10155124 2005 GMC C7500 Flatbed Dump Truck, 16 Ft., Lowside

Workorder: 533176 **Meter:** 45 **In Date:** 01/12/2005 **Closed:** 01/14/2005
Problem: CHECK IN

- Check In	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 6.00	Labor: 300.00 Parts: 2.00	Total: 302.00
:		

Workorder: 533199 **Meter:** 0 **In Date:** 01/12/2005 **Closed:** 01/12/2005
Problem: MAKE & APPLY DECALS. CHECK FLUIDS, BELTS, AND OPER

- Make & Apply Decals. Check Fluids, Belts, And Operation
As Applicable.

Hours 1.00	Labor: 50.00 Parts: 0.00	Total: 50.00
:		

Workorder: 534770 **Meter:** 45 **In Date:** 01/31/2005 **Closed:** 01/31/2005
Problem: CHECK THE WINDSHIELD WIPERS

- Checked Wiper Op. Npf.

Hours 0.30	Labor: 15.00 Parts: 0.00	Total: 15.00
:		

Workorder: 552451 **Meter:** 5043 **In Date:** 08/08/2005 **Closed:** 08/22/2005
Problem: REPAIR TAIL GATE AND TARP ASSY

- Repair Tail Gate And Tarp Assy.	Parts List	Qty
- Welding Supplies	Shop Supplies	1.00
	0311-963301 Swingarm Aero Tarp	1.00
Hours 4.50	Labor: 225.00 Parts: 83.93	Total: 308.93
:		

Workorder: 552466 **Meter:** 0 **In Date:** 08/08/2005 **Closed:** 08/08/2005
Problem: 002 QUARTS OF OIL ISSUED OUT 08/08/05

- 002 Quarts Of Oil Issued Out 08/08/05

	Parts List	Qty
	15/40 Oil	2.00
Hours 0.00	Labor: 0.00 Parts: 4.35	Total: 4.35
:		

Workorder: 552768 **Meter:** 5042 **In Date:** 08/11/2005 **Closed:** 08/24/2005
Problem: LIGHTS

- Repaired Tractor Plug
- Shop Supplies

	Parts List	Qty
	Shop Supplies	1.00
Hours 1.00	Labor: 50.00 Parts: 2.00	Total: 52.00
:		

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 555474	Meter: 5354	In Date: 09/21/2005	Closed: 09/29/2005
Problem: PM SERVICE			
- Pm	Parts List	Qty	
- Replace Body Up Light Switch	Shop Supplies	1.00	
- Replace Body Up Light Switch	Ca9736 Air Filter Lbf Laf2031 Wix 42824	1.00	
- Repair Rear Lights	Ph3545 Oil Filter Lbf Lfp6007 Wix 51798	1.00	
- Test Run	33442 Fuel Filter Frm Don't Use Lbf Lff902	1.00	
- Shop Supplies	Ps4886 Fuel Filter Lbf Fp941f Wix 33128	1.00	
	15/40 Oil	24.00	
	Wd40 Spray Lube Stock# 405540002	1.00	
	B90 Switch Body Up Switch	1.00	
Hours 11.00	Labor: 550.00	Parts: 144.55	Total: 694.55
:			
Workorder: 557127	Meter: 5591	In Date: 10/20/2005	Closed: 11/09/2005
Problem: TAIL GATE			
- Replace L/s Of Tailgate	Parts List	Qty	
- Welding Supplies	Shop Supplies	1.00	
Hours 3.00	Labor: 150.00	Parts: 3.00	Total: 153.00
:			
Workorder: 632657	Meter: 8714	In Date: 01/11/2006	Closed: 01/27/2006
Problem: RECALL			
- Fm-gmc Recall Reprogram Ecm	Parts List	Qty	
- Fender Markers R&r.	Shop Supplies	1.00	
- Shop Supplies	684-91001 Markers	1.00	
Hours 2.50	Labor: 125.00	Parts: 51.31	Total: 176.31
:			
Workorder: 633976	Meter: 9199	In Date: 02/07/2006	Closed: 02/08/2006
Problem: REPAIR BRAKE LIGHTS			
- Brake Light Switch.	Parts List	Qty	
- Shop Supplies	Shop Supplies	1.00	
	93801733 Switch B/light (acd D880a)	1.00	
Hours 2.00	Labor: 100.00	Parts: 11.99	Total: 111.99
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 636913	Meter: 11059	In Date: 04/06/2006	Closed: 04/14/2006
Problem: PM SERVICE			
- Pm Service/r&r Fire Ext.	Parts List	Qty	
- R&r Mud Flap	Shop Supplies	1.00	
- Test Run	Ca9736 Air Filter Lbf Laf2031 Wix 42824	1.00	
- Shop Supplies	Ph3545 Oil Filter Lbf Lfp6007 Wix 51798	1.00	
	33442 Fuel Filter Frm Don't Use Lbf Lff902	1.00	
	Ps4886 Fuel Filter Lbf Fp941f Wix 33128	1.00	
	09997 Brake Clean	1.00	
	15/40 Oil	24.00	
	31-22 Wiper Blades 22" Wiper Blade	2.00	
	Mud Flap 24x30 Splash Guard(spl66490730)	1.00	
	Mud Flap 24x30 Splash Guard(spl66490730)	-1.00	
	Mud Flap 24x36 Splash Guard (spl4-3)	1.00	
	Mud Flap 24x36 Splash Guard (spl4-3)	1.00	
Hours 8.00	Labor: 400.00	Parts: 139.24	Total: 539.24
:			
Workorder: 733692	Meter: 16506	In Date: 02/01/2007	Closed: 03/08/2007
Problem: WILL NOT START AND PM SERVICE			
- Pm Service	Parts List	Qty	
- R&r Nitrogen In Tires	Shop Supplies	1.00	
- R&r Sealed Beam	Ca9736 Air Filter Lbf Laf2031 Wix 42824	1.00	
- Repaired Brackets For Body Up Light And Adjusted.	Ph3545 Oil Filter Lbf Lfp6007 Wix 51798	1.00	
- Tightened Bolts On Frame Rail.	33442 Fuel Filter Frm Don't Use Lbf Lff902	1.00	
- Resealed Line	Ps4886 Fuel Filter Lbf Fp941f Wix 33128	1.00	
- Test Drive	15/40 Oil	24.00	
- Gmc And Back	Atfd Trans Fluid Mercon V	1.00	
- Repair At Gmc	Used Firex Refurbed Fire Extingshers	1.00	
- Fm-gmc	31-22 Wiper Blades 22" Wiper Blade	2.00	
- Shop Supplies	H6054 Sealed Beam	1.00	
Hours 15.00	Labor: 825.00	Parts: 142.87	Total: 967.87
:			
Workorder: 734932	Meter: 0	In Date: 02/01/2007	Closed: 02/28/2007
Problem: TIRESOLES OF BROWARD INC TOW FROM 441 N OF BELVEDE			
- Tiresoles Of Broward Inc Tow From 441 N Of Belvedere			
West Side - Tow To			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 736559	Meter: 0	In Date: 02/01/2007	Closed: 04/03/2007
Problem: SISTERS TOWING & TRANSPORTATON TOW FROM 441 BELVED			
- Sisters Towing & Transportaton Tow From 441 Belvedere			
Rd - Tow To Fleet Yard			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 737616	Meter: 18130	In Date: 04/25/2007	Closed: 06/28/2007
Problem: FUEL GUAGE,DOOR LATCH AND TRANS REPAIR			
- Disassemble Door Panel.straighten Rods.r&r Handle Assembly Reassembled Above.	Parts List		Qty
	Shop Supplies		1.00
- Installed Tech# Operated Gauges Through Pcm No Prob At This Time	15827690 Rh Outter Door Latch		1.00
- Installed Laptop.ck For Codes2215 5611 Perform Diag.ck.graphed Sensors.turbine Sensor Dropping Out.	16600277 Lock Cylinder Clip		1.00
- Rd Tesed For Shift Pattern.			
- Shop Supplies			
Hours 7.00	Labor: 385.00	Parts: 50.33	Total: 435.33
:			
Workorder: 743207	Meter: 19829	In Date: 08/27/2007	Closed: 08/30/2007
Problem: REPAIR TAIL GATE			
- Repair Broken Tailgate Post & Tailgate	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
Hours 3.00	Labor: 165.00	Parts: 2.00	Total: 167.00
:			
Workorder: 743696	Meter: 0	In Date: 08/06/2007	Closed: 09/06/2007
Problem: TIRESOLES OF BROWARD INC			
- Tiresoles Of Broward Inc			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 743697	Meter: 0	In Date: 08/03/2007	Closed: 09/06/2007
Problem: TIRESOLES OF BROWARD INC			
- Tiresoles Of Broward Inc			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 832374	Meter: 22983	In Date: 01/07/2008	Closed: 01/24/2008
Problem: PM SERVICE			
- Pm	Parts List	Qty	
- Repair Open Circuit In Signal (r. Light) Light	Shop Supplies	1.00	
- R&r Body Up Switch & Dash Light.	3"x25 Alum Channel	2.00	
- Air Valve Replaced & Test For Leaks.	3/16x4x12 Alum Plate 5052	2.00	
- Repair Chain Gear For The Truck Body (canvas) Tarp	Ps4886 Fuel Filter Lbf Fp941f Wix 33128	1.00	
- Rep Broke Off Door & Pillar That Supports Door.fabricate Pillar;weld 2 Hinges On Door,weld Door To Pillar.create New Door Latch System.	Ca9736 Air Filter Lbf Laf2031 Wix 42824	1.00	
	Ph3545 Oil Filter Lbf Lfp6007 Wix 51798	1.00	
- Shop Supplies	33442 Fuel Filter Frm Don't Use Lbf Lff902	1.00	
	15173404 Air Valve Manifold	1.00	
	15/40 Oil	24.00	
	31-22 Wiper Blades 22" Wiper Blade	2.00	
	Used Firex Refurbed Fire Extingshers	1.00	
	B90 Switch Body Up Switch	1.00	
	Ds366 Red Pilot Light	1.00	
	06133 3m Electric Tape Stock #832260101	1.00	
	12cal Alum Tail-gate Hing	2.00	
Hours 26.00	Labor: 1,560.0	Parts: 380.87	Total: 1,940.87
:	0		
Workorder: 834784	Meter: 23687	In Date: 02/28/2008	Closed: 03/03/2008
Problem: LIST			
- Repair Wiring & Socket R/f Lamp Replace L/f Lamp Assy.	Parts List	Qty	
- Replace 2 Rear Reflectors	Shop Supplies	1.00	
- Replace Pintal Hook And Chain	5800aa Turn Signal Fender Mount 2 Studs	1.00	
- Repair Air Filter Clap To Hold Housing Properly	47 Red Reflector 3" Round Stick(grt 40052)	2.00	
- Ck Fuel Gauge Operaton Use Tech 11 Ck All Fuses Operation Ok At This Time.	18410 Pintle Pin	1.00	
- Shop Supplies			
Hours 5.00	Labor: 300.00	Parts: 35.97	Total: 335.97
:			
Workorder: 842671	Meter: 26912	In Date: 08/12/2008	Closed: 08/20/2008
Problem: PM SERVICE			
- Pm Service	Parts List	Qty	
- Trans Service	Shop Supplies	1.00	
- Repair R/f Turn Lamp And Marker Light	29526898 Trans Filter Frm C9031 Wix 57740xe	1.00	
- Road Test	Ca9736 Air Filter Lbf Laf2031 Wix 42824	1.00	
- Top Off Nitrogen 105psi	Ph3545 Oil Filter Lbf Lfp6007 Wix 51798	1.00	
- Shop Supplies	33442 Fuel Filter Frm Don't Use Lbf Lff902	1.00	
	Ps4886 Fuel Filter Lbf Fp941f Wix 33128	1.00	
	09997 Brake Clean	1.00	
	Syn/atf Trans Fluid Synthetic	19.00	
	15/40 Oil	24.00	
	31-22 Wiper Blades 22" Wiper Blade	2.00	
	Used Firex Refurbed Fire Extingshers	1.00	
Hours 12.00	Labor: 720.00	Parts: 260.62	Total: 980.62
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 843462	Meter: 27312	In Date: 08/28/2008	Closed: 09/09/2008
Problem: TRAN WILL NOT SHIFT AND FUEL GUAGE IS NOT WORKING			
- R&r Fuel Filter Change Water Refuel Sensor.	Parts List	Qty	
- Diagnose Fuel Gauge Not Working.replace Instrument Cluster. Send Out To Gm.hook Up Tech li & Program Cluster.	Shop Supplies	1.00	
- Diagnose Engine Has No Power.hookup Tech li,run All Engine Tests.determine Air Filter Housing Cracked & Hose Pulled Out Of Turbo.	Ps4886 Fuel Filter Lbf Fp941f Wix 33128	1.00	
	Air Filter Houseing	1.00	
	Air Filter Houseing	1.00	
- Replace Entire Air Filter Housing.resecure Cold Air Hose To Turbo Inlet.	Adapter	1.00	
	Seal	1.00	
- Diagnose Body-up Light On Constantly.found Closed Circuit With Bed Down.body-up Switch Bad.r&r Switch & Readjust Deactivation Bolt On Bed.	Cluster	1.00	
	B90 Switch Body Up Switch	1.00	
- Test Run Vehicle 2 Times To Check For Trans Shifting & Power			
- Shop Supplies			
Hours 12.50	Labor: 750.00	Parts: 611.55	Total: 1,361.55
:			
Workorder: 844802	Meter: 27639	In Date: 09/29/2008	Closed: 09/30/2008
Problem: BRAKES/FUEL GAUGE			
- Check All Brakes 80-90percent.brake Shoe Left Clean Dirt Anddust From Shoes.	Parts List	Qty	
	Shop Supplies	1.00	
- Test Fuel Gauge Using Tech 11 All Gauges Functio Properly Gauge Read Ok.(note:both Fuel Tanks Mut Be Filled At Same Time For Sys To Func			
- Road Test			
- Shop Supplies			
Hours 4.00	Labor: 240.00	Parts: 2.00	Total: 242.00
:			
Workorder: 847419	Meter: 28772	In Date: 11/24/2008	Closed: 12/04/2008
Problem: REPAIR TAIL GATE HINGES			
- Repair Rh Rear Lower Hinge.repl Bushing On Tarp Arms.	Parts List	Qty	
- Replace Drivers Lh Door Panel	Shop Supplies	1.00	
- Replace Broken Refletors.repl Tail Light Right Rear.	Lh Inner Door Panel	1.00	
- Shop Supplies	44302r Tail Light 4" Red 6 Led	1.00	
	94789 Adapter Plug Led Lights	1.00	
	47 Red Reflector 3" Round Stick(grt 40052)	1.00	
	0311-863308 Bushing Insert Aero Tarp	4.00	
	12cal Alum Tail-gate Hing	1.00	
Hours 10.50	Labor: 630.00	Parts: 351.84	Total: 981.84
:			
Workorder: 932230	Meter: 29430	In Date: 01/05/2009	Closed: 01/15/2009
Problem: TARP			
- Replace Chain Gear And Tarp For Truck Body	Parts List	Qty	
- Shop Supplies	Shop Supplies	1.00	
	4645 Tarp 7.5x18 Finished Size Donovan	1.00	
Hours 4.00	Labor: 240.00	Parts: 98.09	Total: 338.09
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 934751	Meter: 30490	In Date: 03/04/2009	Closed: 03/12/2009
Problem: PM SERVICE			
- Pm Service	Parts List	Qty	
- Power Steering Fluid Dirty-flush Power Steering And Change Filter.replace W/new Fluid And Test.	Shop Supplies	1.00	
	Drive Belt	1.00	
- Engine Serpentine Belt Dried & Worn-replaced.r&r Belt Water Pump,belt Is Loose Adj Belt To Spec. U-belt Appears Ok.test.	Ph3545 Oil Filter Lbf Lfp6007 Wix 51798	1.00	
	33442 Fuel Filter Frm Don't Use Lbf Lff902	1.00	
- Remv Pintle Chain Fr Hitch & Remv Wrong Pintle Pin.attach Correct Pintle Chaian And Reinstall To Hitch.	Ps4886 Fuel Filter Lbf Fp941f Wix 33128	1.00	
	Power Stg Filter	1.00	
- Test Run.	09997 Brake Clean	1.00	
- Rf Turn Signal Not Working Loosen Assy Fr Hood & Take Apart Test Power & Ground Open In Flasher Element.replace 1157 Bulb.	15/40 Oil	24.00	
	61a P/steering Fluid	1.00	
- Shop Supplies	31-22 Wiper Blades 22" Wiper Blade	2.00	
	66060 Lock Pin 3/8"x2-1/2"	1.00	
Hours 11.50	Labor: 690.00	Parts: 229.86	Total: 919.86
:			
Workorder: 936385	Meter: 31052	In Date: 04/13/2009	Closed: 04/15/2009
Problem: REWEILD BED			
- Grind Nad Cut Out Cracked And Broken Welds, Clean Area,weld All Cracks,fabricate And Weld In Extra Braces.	Parts List	Qty	
	Shop Supplies	1.00	
- Shop Supplies	1/4x6x12 Alum Flat Bar	1.00	
Hours 5.00	Labor: 300.00	Parts: 5.95	Total: 305.95
:			
Workorder: 940058	Meter: 32319	In Date: 07/02/2009	Closed: 07/09/2009
Problem: Tail gate			
- Piller broken for the Rs bed door. Grind area align doors and reweld	Parts List	Qty	
	Shop Supplies	1.00	
- Commercial Workorder Entry			
- Shop Supplies			
Hours 6.00	Labor: 360.00	Parts: 2.00	Total: 362.00
:			
Workorder: 943597	Meter: 33399	In Date: 09/23/2009	Closed: 09/28/2009
Problem: pm service			
- Pm Service	Parts List	Qty	
- Replace the turn signal assembly	Shop Supplies	1.00	
- Fill all tires with nitrogen	Ph3545 Oil Filter Lbf Lfp6007 Wix 51798	1.00	
- Repair and weld tailgate hindges	33442 Fuel Filter Frm Don't Use Lbf Lff902	1.00	
- Shop Supplies	Ps4886 Fuel Filter Lbf Fp941f Wix 33128	1.00	
	09997 Brake Clean	1.00	
	15/40 Oil	24.00	
	Used Firex Refurbed Fire Extingshers	1.00	
	31-22 Wiper Blades 22" Wiper Blade	2.00	
	5800aa Turn Signal Fender Mount 2 Studs	1.00	
Hours 11.50	Labor: 690.00	Parts: 144.43	Total: 834.43
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1002603	Meter: 35990	In Date: 03/15/2010	Closed: 03/30/2010
Problem: add engine oil and pm service			
- P.m.	Parts List	Qty	
- Repair lights	Shop Supplies	1.00	
- Repair Pto	Ph3545 Oil Filter Lbf Lfp6007 Wix 51798	1.00	
- Nitro tires	33442 Fuel Filter Frm Don't Use Lbf Lff902	1.00	
- Install safty hitch pin	Ps4886 Fuel Filter Lbf Fp941f Wix 33128	1.00	
- Road test	15/40 Oil	24.00	
- Move tag	Used Firex Refurbed Fire Extingshers	1.00	
- Shop Supplies	31-22 Wiper Blades 22" Wiper Blade	2.00	
	26330 Tag Light (tkr Lite)	1.00	
	66060 Lock Pin 3/8"x2-1/2"	1.00	
	Pto Pressure Switch	1.00	
Hours 15.00	Labor: 900.00	Parts: 234.57	Total: 1,134.57
:			
Workorder: 1006000	Meter: 37307	In Date: 06/08/2010	Closed: 06/15/2010
Problem: bed door broken			
- fab and weld new hinges and door latches	Parts List	Qty	
- test run	Shop Supplies	1.00	
- Shop Supplies	12cal Alum Tail-gate Hing	2.00	
Hours 8.00	Labor: 480.00	Parts: 111.09	Total: 591.09
:			
Workorder: 1010043	Meter: 39490	In Date: 09/14/2010	Closed: 09/21/2010
Problem: pm service			
- pm service	Parts List	Qty	
- repair air filter tubing from housing to hood	Shop Supplies	1.00	
- replace brake pedal pad	Ca9736 Air Filter Lbf Laf2031 Wix 42824	1.00	
- replace fan clutch	Air Filter Seal	1.00	
- repair bracket for tarp gear box	Ph3545 Oil Filter Lbf Lfp6007 Wix 51798	1.00	
- Shop Supplies	33442 Fuel Filter Frm Don't Use Lbf Lff902	1.00	
	Ps4886 Fuel Filter Lbf Fp941f Wix 33128	1.00	
	15/40 Oil	24.00	
	31-22 Wiper Blades 22" Wiper Blade	2.00	
	Used Firex Refurbed Fire Extingshers	1.00	
	Brake Pedal Pad	1.00	
	Fan Clutch	1.00	
Hours 12.00	Labor: 720.00	Parts: 701.05	Total: 1,421.05
:			
Workorder: 1010624	Meter: 39669	In Date: 09/28/2010	Closed: 09/29/2010
Problem: broken latch on rear door			
- fab and install body bracket	Parts List	Qty	
- Shop Supplies	Shop Supplies	1.00	
	1/2x20 Alum Round Stock	5.00	
	2" Alum Pipe X 20'	5.00	
	1/4x12x12 Alum Flat Bar 6061	3.00	
Hours 2.50	Labor: 150.00	Parts: 56.49	Total: 206.49
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1011968	Meter: 39669	In Date: 10/26/2010	Closed: 11/02/2010
Problem: Build Steps			
- fad / weld folding steps		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
		1/2x20 Alum Round Stock	9.00
		3/4x20 Alum Round Stock	9.00
		1/4x2x4x20 Alum Angle 6063	10.00
		3/8"x12"x12'alum Flat Bar	4.00
		2560 Hitch Pin/clip	1.00
Hours 8.50	Labor: 510.00	Parts: 166.61	Total: 676.61
:			
Workorder: 1012872	Meter: 39758	In Date: 11/18/2010	Closed: 11/18/2010
Problem: install rear door			
- install rear body door weld/ fab		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 2.00	Total: 242.00
:			
Workorder: 1102514	Meter: 40650	In Date: 03/07/2011	Closed: 03/25/2011
Problem: Repair tailgate and lights			
- fm to vanlinda		Parts List	Qty
- repair swing doors by vanlinda		Shop Supplies	1.00
- pm service		Ph3545 Oil Filter Lbf Lfp6007 Wix 51798	1.00
- Shop Supplies		33442 Fuel Filter Frm Don't Use Lbf Lff902	1.00
		Ps4886 Fuel Filter Lbf Fp941f Wix 33128	1.00
		15/40 Oil	24.00
		31-22 Wiper Blades 22" Wiper Blade	2.00
		Used Firex Refurbed Fire Extingshers	1.00
Hours 12.40	Labor: 744.00	Parts: 115.08	Total: 859.08
:			
Workorder: 1104190	Meter: 41121	In Date: 04/18/2011	Closed: 04/18/2011
Problem: Ladder repair			
- Repair broken ladder mount		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
		3/82x2x20 Steel Angle	3.00
Hours 2.50	Labor: 150.00	Parts: 9.14	Total: 159.14
:			
Workorder: 1108441	Meter: 42858	In Date: 08/10/2011	Closed: 08/11/2011
Problem: check all tires			
- check all tires			
Hours 0.50	Labor: 30.00	Parts: 0.00	Total: 30.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1110142	Meter: 43242	In Date: 09/22/2011	Closed: 09/30/2011
Problem: pm service			
- pm service	Parts List	Qty	
- repair tag light	Shop Supplies	1.00	
- test drive	Ph3545 Oil Filter Lbf Lfp6007 Wix 51798	1.00	
- Shop Supplies	Ps4886 Fuel Filter Lbf Fp941f Wix 33128	1.00	
	33442 Fuel Filter Frm Don't Use Lbf Lff902	1.00	
	15/40 Oil	24.00	
	31-22 Wiper Blades 22" Wiper Blade	2.00	
Hours 7.00	Labor: 420.00	Parts: 121.69	Total: 541.69
:			
Workorder: 1203013	Meter: 46881	In Date: 03/29/2012	Closed: 04/10/2012
Problem: Tarp arm / P.M.			
- pm service	Parts List	Qty	
- repair lf and rr turn lights	Shop Supplies	1.00	
- repair tarp arms and replace pintal pin	Ph3545 Oil Filter Lbf Lfp6007 Wix 51798	1.00	
- replace batteries	Ps4886 Fuel Filter Lbf Fp941f Wix 33128	1.00	
- replace 2 new fronts and 4 rear recaps boulevard	33442 Fuel Filter Frm Don't Use Lbf Lff902	1.00	
- Shop Supplies	15/40 Oil	24.00	
	1066 White Lithium (crc 05037)	1.00	
	31-22 Wiper Blades 22" Wiper Blade	2.00	
	798 Flare Kits Triangle Reflector Kits	1.00	
	Used Firex Refurbed Fire Extingshers	1.00	
	44302r Tail Light 4" Red 6 Led	1.00	
	94706 Adapter 3 Prong	1.00	
	Group 31 Stud Battery (acd 31-900ct)	2.00	
	11r225rc Tire Recapped	4.00	
	0311-863308 Bushing Insert Aero Tarp	2.00	
	18410 Pintle Pin	1.00	
	3006875 Pin Assembly (buyers)	1.00	
	0311-963301 Swingarm Aero Tarp	1.00	
Hours 9.00	Labor: 540.00	Parts: 1,288.64	Total: 1,828.64
:			
Workorder: 1203928	Meter: 47045	In Date: 04/26/2012	Closed: 04/27/2012
Problem: flat tire			
- replace Lro tire boulevard	Parts List	Qty	
- Shop Supplies	Shop Supplies	1.00	
	11r225rc Tire Recapped	1.00	
Hours 0.00	Labor: 0.00	Parts: 183.28	Total: 183.28
:			
Workorder: 1207962	Meter: 48553	In Date: 08/22/2012	Closed: 08/22/2012
Problem: oil light is on			
- reset oil change light	Parts List	Qty	
- test run	Shop Supplies	1.00	
- Shop Supplies			
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1209145 **Meter:** 48925 **In Date:** 09/25/2012 **Closed:** 10/24/2012

Problem: will not start

	Parts List	Qty
- scan for codes and flash ecm	15-40 Oil	24.00
- replace fuel filters and fuel manifold lines	Ph3545 Oil Filter Lbf	1.00
- jump start in yard charge batteries and check charging system	33442 Fuel Filter Frm	1.00
- replace tarp bushings and chain box	Ca9736 Air Filter Lbf	1.00
- pm service	31-22 Wiper Blades 22	2.00
- replace accum, compressor, orifice tube, evac and recharge	H-duty A-freeze Ext-l	1.00
- weld cracks in bed	Control Crank Kit	1.00
- test drive	Freight	1.00
- Shop Supplies	Accumulator	1.00
	A/c Compressor	1.00
	Orifice Tube	1.00
	Seal	2.00
	E8 A-c Oil R134a A-c	1.00
	Used Firex Refurberd F	2.00
	R134a Refrigerant	3.00
	Bushing	4.00
	Shop Supplies	1.00
	12639277 Water Sensor (gmc)	1.00
	Ps4886 Fuel Filter Lbf Fp941f Wix 33128	1.00
	Lh Fuel Harness	1.00
	Rh Fuel Harness	1.00
Hours 28.00	Labor: 1,680.0	Parts: 2,174.23
:	0	Total: 3,854.23

Workorder: 1210412 **Meter:** 49124 **In Date:** 10/30/2012 **Closed:** 11/14/2012

Problem: repair drivers door handle

	Parts List	Qty
- pm service	Door Panel	1.00
- replace drivers door panel	15-40 Oil	24.00
- clean evap and housing	Ph3545 Oil Filter Lbf	1.00
- replace two tail light assy. and replace bulbs on cab marker lights	fuel filter	1.00
- road test	31-22 Wiper Blades 22	2.00
- Shop Supplies	Used Firex Refurberd F	1.00
	05088 Brake Clean	2.00
	Evap Odor Eliminator	1.00
	V417kr Tail Light 4in	2.00
	Miniature Bulb	2.00
	fuel filter	1.00
	Shop Supplies	1.00
Hours 12.50	Labor: 750.00	Parts: 778.36
:		Total: 1,528.36

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1300967	Meter: 50160	In Date: 01/29/2013	Closed: 01/29/2013
Problem: 1 - Key(s) issued			
- 1 - Key(s) issued		Parts List	Qty
		Duplicate Vehicle Keys	1.00
Hours 0.20	Labor: 12.00	Parts: 3.00	Total: 15.00
:			
Workorder: 1302977	Meter: 51270	In Date: 03/27/2013	Closed: 04/15/2013
Problem: no throttle, left turn light and right gate hook missing			
- replace turn signal assembly		Parts List	Qty
- replace missing hardware and adjust tarp box and chain		Turn Lmp	1.00
- fab/ weld hook for tail gate chains		Shop Supplies	1.00
- test run			
- Shop Supplies			
Hours 7.00	Labor: 420.00	Parts: 41.00	Total: 461.00
:			
Workorder: 1304794	Meter: 51820	In Date: 05/14/2013	Closed: 05/17/2013
Problem: pm service			
- pm service		Parts List	Qty
- replace body up switch		15-40 Oil	24.00
- replace rear red reflectors		Ph3545 Oil Filter Lbf	1.00
- repalce air pressure switch in air tank		Napagold Fuel Filter	1.00
- Shop Supplies		31-22 Wiper Blades 22	2.00
		Ca9736 Air Filter Lbf	1.00
		Washer Fl	1.00
		B90 Switch Body Up Sw	1.00
		47 Red Reflector 3in	2.00
		Air Tank Switch	1.00
		Napagold Fuel Filter	1.00
		Shop Supplies	1.00
Hours 11.00	Labor: 660.00	Parts: 291.56	Total: 951.56
:			
Workorder: 1305729	Meter: 52105	In Date: 06/10/2013	Closed: 08/09/2013
Problem: Stalls out			
- fill and pressure test cooling system		Parts List	Qty
- found oil and white smoke		H-duty A-freeze Ext-l	1.00
- fm to Gmc		Shop Supplies	1.00
- engie repair by Gmc			
- Shop Supplies			
Hours 5.70	Labor: 342.00	Parts: 22.72	Total: 364.72
:			
Workorder: 1306594	Meter: 51905	In Date: 07/02/2013	Closed: 08/05/2013
Problem: replace engine oil cooler			
- Replace engine cooler			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1310120	Meter: 52933	In Date: 10/07/2013	Closed: 10/16/2013
Problem: A/C			
- replace compressor, accum, orifice tube, condenser, evac and recharge	Parts List	Qty	
- replace fan clutch	A/c Compressor	1.00	
- replace fan belt	Accumulator	1.00	
- test drive	Orifice Tube	1.00	
- Shop Supplies	R134a Refrigerant	3.00	
	Condenser	1.00	
	Fan Clutch	1.00	
	Belt	1.00	
	Brake Cleaner	2.00	
	A/c Seal	3.00	
	Seal	3.00	
	A/c Seal	4.00	
	Shop Supplies	1.00	
Hours 9.00	Labor: 540.00	Parts: 1,947.97	Total: 2,487.97
:			
Workorder: 1310492	Meter: 52933	In Date: 10/18/2013	Closed: 11/08/2013
Problem: tail gate hinge			
- Drivers rear door hinge broken. Replaced and gusseted both	Parts List	Qty	
- Shop Supplies	12cal Alum Tail-gate	2.00	
	Shop Supplies	1.00	
	1-1/4x1-1/4 Sqr Tubing Alum Non-radius 1/8 Wall	10.00	
Hours 7.00	Labor: 420.00	Parts: 162.26	Total: 582.26
:			
Workorder: 1311723	Meter: 53254	In Date: 11/20/2013	Closed: 12/13/2013
Problem: mirror			
- replace rh mirror assembly	Parts List	Qty	
- pm service	Mirror Assembly	1.00	
- replace hitch safety pin and chain	15-40 Oil	24.00	
- replace tarp gear box	Napagold Oil Filter	1.00	
- test run	Napagold Fuel Filter	1.00	
- Shop Supplies	Wiper Blade	2.00	
	Napagold Fuel Filter	1.00	
	Used Fire X Refurbished	1.00	
	Pintle Pin W/chain	1.00	
	66060 Lock Pin 3-8in	1.00	
	Control Crank Kit	1.00	
	Shop Supplies	1.00	
Hours 10.00	Labor: 600.00	Parts: 853.31	Total: 1,453.31
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1403780	Meter: 55524	In Date: 04/17/2014	Closed: 06/04/2014
Problem: Bed damage			
- P.m.	Parts List	Qty	
- Service Trans.	15-40 Oil	24.00	
- Coolent Service	Napagold Oil Filter	1.00	
- Service air dryer	Napagold Fuel Filter	1.00	
- Rebuild corner on tailgate	Wiper Blade	2.00	
- Ls fuel sender inop. R&r and reflash Pcm	Used Fire X Refurbished	1.00	
- Test Drive	Brake Cleaner	4.00	
- Shop Supplies	Napa Trans Filter	1.00	
	Syn-atf Trans Fluid S	20.00	
	H Duty Anti-freeze	5.00	
	Ad-sp Dryer Cartridge	1.00	
	1/12x25' Angle Bar	1.00	
	Napagold Fuel Filter	1.00	
	Fuel Watr Separtr Sen	1.00	
	Fuel Sender Module	1.00	
	Shop Supplies	1.00	
Hours 25.00	Labor: 1,500.00	Parts: 1,010.20	Total: 2,510.20
:	0		
Workorder: 1409200	Meter: 57421	In Date: 09/12/2014	Closed: 09/15/2014
Problem: LRO tire			
- Lro tire	Parts List	Qty	
- Shop Supplies	Shop Supplies	1.00	
	11r225rc Tire Recapped	1.00	
	Tire Disposal Fee	1.00	
Hours 0.00	Labor: 0.00	Parts: 186.12	Total: 186.12
:			
Workorder: 1411629	Meter: 58780	In Date: 11/18/2014	Closed: 12/18/2014
Problem: Transmission and brake pull / P.M.			
- pm	Parts List	Qty	
- check fluid level. replace orings for cooler line add fluid	Napagold Fuel Filter	1.00	
- check brake pull. replace both front brake chambers and replace lines	Napagold Oil Filter	1.00	
	15-40 Oil	24.00	
- test run	Ca9736 Air Filter Lbf	1.00	
- Shop Supplies	Napagold Fuel Filter	1.00	
	Used Fire X Refurbished	1.00	
	Wiper Blade	2.00	
	Syn-atf Trans Fluid S	5.00	
	Extinguisher Sing	2.00	
	Front Brake Chamber	2.00	
	Brake Air Hose Front	2.00	
	Shop Supplies	1.00	
Hours 13.50	Labor: 810.00	Parts: 839.23	Total: 1,649.23
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1506273	Meter: 62078	In Date: 06/23/2015	Closed: 07/07/2015
Problem: PM			
- pm	Parts List	Qty	
- replace air drier	15-40 Oil	24.00	
- install safety pin	Napagold Oil Filter	1.00	
- replace air tank low pressure switch	Napagold Fuel Filter	1.00	
- repair reverse lights	Napagold Fuel Filter	1.00	
- Shop Supplies	Ca9736 Air Filter Lbf	1.00	
	Wiper Blade	2.00	
	Ad-sp Dryer Cartridge	1.00	
	1cart Palladium 2 Grs	2.00	
	66060 Lock Pin 3-8in	1.00	
	Air Tank Switch	1.00	
	Shop Supplies	1.00	
Hours 12.00	Labor: 720.00	Parts: 327.52	Total: 1,047.52
:			
Workorder: 1510536	Meter: 64197	In Date: 10/19/2015	Closed: 10/30/2015
Problem: tarp lock			
- replace tarp gear box	Parts List	Qty	
- Shop Supplies	Control Crank Kit	1.00	
	Shop Supplies	1.00	
Hours 2.00	Labor: 120.00	Parts: 326.23	Total: 446.23
:			
Workorder: 1600051	Meter: 65119	In Date: 01/04/2016	Closed: 01/20/2016
Problem: pm/list			
- pm	Parts List	Qty	
- replace air dryer	15-40 Oil	24.00	
- replace front bump stops	Napagold Oil Filter	1.00	
- straighten rear tailgate beam and weld. rebend grab	Napagold Fuel Filter	1.00	
handle and weld. straighten beam onleft rear side panel.	Ca9736 Air Filter Lbf	1.00	
make new bracket for ladder. patch right rear tailgate	Napagold Fuel Filter	1.00	
- disassmble door to fix latch assembly	22" Wiper Blade	2.00	
- replace front left blinker. make grommet to hold Pto light	Washer Fluid Concentr	1.00	
- road test	Vinyl Electrical Tape	1.00	
- Shop Supplies	Used Fire X Refurbished	1.00	
	Ad-sp Dryer Cartridge	1.00	
	Brake Cleaner	2.00	
	Bump Stopper	2.00	
	Bulb	1.00	
	Shop Supplies	1.00	
Hours 34.50	Labor: 2,070.00	Parts: 397.42	Total: 2,467.42
:	0		

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1601257	Meter: 65294	In Date: 02/04/2016	Closed: 02/26/2016
Problem: Weld tailgate			
- weld repair gate hinges and repair.	Parts List	Qty	
- Tarp handle	Hinge Alum	1.00	
- Shop Supplies	Handle	1.00	
	Shop Supplies	1.00	
Hours 6.50	Labor: 390.00	Parts: 137.17	Total: 527.17
:			
Workorder: 1601276	Meter: 65233	In Date: 02/05/2016	Closed: 02/10/2016
Problem: LRI flat			
- Lfi flat			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1605625	Meter: 66818	In Date: 06/01/2016	Closed: 06/30/2016
Problem: AC			
- replace evap, condenser, ac lines, orifice tubes, accumulator, compressor, seals	Parts List	Qty	
- drive belt	Belt	1.00	
- tarp arm bushings and adjust arms	Module Kit	1.00	
- road test	Ac Hose	1.00	
- Shop Supplies	Condenser	1.00	
	Accumalator	1.00	
	A/c Compressor	1.00	
	A/c Evaporator	1.00	
	Seal	1.00	
	A/c Seal	1.00	
	Ac Hose	1.00	
	a/c hose	1.00	
	A/c Seal	1.00	
	Orifice Tube	1.00	
	Bushing	4.00	
	Shop Supplies	1.00	
Hours 13.00	Labor: 780.00	Parts: 2,376.01	Total: 3,156.01
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1606906	Meter: 67040	In Date: 07/08/2016	Closed: 08/03/2016
Problem: PM			
- Pm	Parts List	Qty	
- Tag light	15-40 Oil	24.00	
- Replace batteries	Napagold Oil Filter	1.00	
- Replace drag ling	Napagold Fuel Filter	1.00	
- Repair tarp	Ca9736 Air Filter Lbf	1.00	
- Replace Pto light	Napagold Fuel Filter	1.00	
- Replaced asset #	Wiper Blade	2.00	
- Road test	Washer Fluid Concentr	1.00	
- Passeinger door handle	Brake Cleaner	2.00	
- Shop Supplies	Used Fire X Refurbished	1.00	
	License Lamp	1.00	
	Group 31 Stud Delco	2.00	
	Drag Link	1.00	
	Cable Tie	1.00	
	Ptex Thrd Lck Red Sm	1.00	
	Marker Lamp	1.00	
	Shop Supplies	1.00	
Hours 13.00	Labor: 780.00	Parts: 809.74	Total: 1,589.74
:			
Workorder: 1607621	Meter: 66987	In Date: 07/26/2016	Closed: 07/27/2016
Problem: tires			
- tires			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1700518	Meter: 70152	In Date: 01/18/2017	Closed: 02/08/2017
Problem: PM / No Power			
- pm	Parts List	Qty	
- replace air dryer	15-40 Oil	24.00	
- repair wiring for side marker	Napagold Oil Filter	1.00	
- road test	Napagold Fuel Filter	1.00	
- Shop Supplies	Ca9736 Air Filter Lbf	1.00	
	Napagold Fuel Filter	1.00	
	Wiper Blade	2.00	
	Washer Fluid Concentr	1.00	
	Non-chlor Brake Clnr	2.00	
	Used Fire X Refurbished	1.00	
	red paint pin	1.00	
	Air Dryer Cartridge	1.00	
	Shop Supplies	1.00	
Hours 11.00	Labor: 660.00	Parts: 281.71	Total: 941.71
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1701973	Meter: 70457	In Date: 02/27/2017	Closed: 03/13/2017
Problem: repair hinge			
- rear doors weld new hinges	Parts List		Qty
- Shop Supplies	Hinge Alum		2.00
	Shop Supplies		1.00
Hours 11.00	Labor: 660.00	Parts: 147.59	Total: 807.59
:			
Workorder: 1702578	Meter: 70458	In Date: 03/13/2017	Closed: 05/16/2017
Problem: rear door hinge broken			
- Fab & weld rear barn doors	Parts List		Qty
- Shop Supplies	Hinge Alum		2.00
	Shop Supplies		1.00
Hours 20.00	Labor: 1,200.00	Parts: 147.59	Total: 1,347.59
:	0		
Workorder: 1708493	Meter: 72021	In Date: 08/29/2017	Closed: 09/18/2017
Problem: pm			
- pm	Parts List		Qty
- replace marker driver side repair harness	15-40 Oil		24.00
- road test	Napagold Oil Filter		1.00
- Shop Supplies	Napagold Fuel Filter		1.00
	Ca9736 Air Filter Lbf		1.00
	Napagold Fuel Filter		1.00
	Wiper Blade		2.00
	M C Lamp		1.00
	C M PI10 Pigtail		1.00
	Shop Supplies		1.00
Hours 7.50	Labor: 450.00	Parts: 158.59	Total: 608.59
:			
Workorder: 1709115	Meter: 72550	In Date: 09/21/2017	Closed: 09/29/2017
Problem: no start			
- to traffic	Parts List		Qty
- repair wiring for ecu	Relay		1.00
- road test	Shop Supplies		1.00
- Shop Supplies			
Hours 5.50	Labor: 330.00	Parts: 9.53	Total: 339.53
:			
Workorder: 1712106	Meter: 73355	In Date: 12/11/2017	Closed: 12/20/2017
Problem: no acceleration			
- jump start	Parts List		Qty
- replace clogged filters prime system	Napagold Fuel Filter		1.00
- replaced pinched wires between frame	Napagold Fuel Filter		1.00
- to traffic lot	Electrical Tape		2.00
- test run	Cable Tie		1.00
- Shop Supplies	Shop Supplies		1.00
Hours 6.00	Labor: 360.00	Parts: 52.16	Total: 412.16
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1801520	Meter: 73923	In Date: 02/08/2018	Closed: 03/08/2018
Problem: No Power			
- Pm	Parts List	Qty	
- Replaced Rf turn signal assembly &rr reflector	15-40 Oil	24.00	
- Replace hitch pin	Napagold Oil Filter	1.00	
- Repair air leak behind dash assembly	Napagold Fuel Filter	1.00	
- Using scan tool found no stored codes. Took for extended test ride and found all to be normal	Ca9736 Air Filter Lbf	1.00	
	Napagold Fuel Filter	1.00	
- Test run	Wiper Blade	1.00	
- Shop Supplies	Washer Fluid Concentr	1.00	
	Non-chlor Brake Clnr	3.00	
	Distilled Water 1gal	1.00	
	Turn Light Assy	1.00	
	Reflectr	2.00	
	hitch pin 1/4x3	1.00	
	push air line fitting 3/16	2.00	
	Shop Supplies	1.00	
Hours 13.00	Labor: 780.00	Parts: 317.66	Total: 1,097.66
:			
Workorder: 1804203	Meter: 74784	In Date: 04/23/2018	Closed: 06/01/2018
Problem: check engine light/AC/truck stalls			
- scan codes found p0381. replace bad ignition relay and repair broken corroded wires	Parts List	Qty	
	Relay	1.00	
- R&r air tank drain valves replace pressure sensor and cracked hoses	Strbrt Liq Elec Tape	1.00	
	W W Vacuum Tubing	6.00	
- R&r hyd line to pto	Relay	1.00	
- R&r tail light cab marker light and install steering wheel cover	Cable Tie	1.00	
	Vinyl Electrical Tape	1.00	
- fabricate locking mount for dump bed side gate and weld cracks in bed	Leather S Whl Cov	1.00	
- Shop Supplies	Drain Valve	3.00	
	Air Tank Switch	1.00	
	Hose Made Mako	1.00	
	Lamp	1.00	
	Fab/loom	4.00	
	1cart Palladium 2 Grs	1.00	
	Shop Supplies	1.00	
Hours 31.00	Labor: 1,860.00	Parts: 298.63	Total: 2,158.63
:	0		
Workorder: 1807054	Meter: 75495	In Date: 07/11/2018	Closed: 08/01/2018
Problem: No throttle / AC			
- scan codes for throttle issue	Parts List	Qty	
- ac system inop. vacuum lines reinstall	Acc Pedal	1.00	
- R&r accelerator pedal	Shop Supplies	1.00	
- road test			
- Shop Supplies			
Hours 4.00	Labor: 240.00	Parts: 131.51	Total: 371.51
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1809157 **Meter:** 76096 **In Date:** 09/06/2018 **Closed:** 10/10/2018
Problem: pm/stalls in traffic

- Pm	Parts List	Qty
- Pull codes P0088, R&r injection supply pump assembly	Psf Qt	1.00
- R&r broken door, repair bent pull assembly	Gear Oil	1.00
- Clean diff breather tube	15-40 Oil	24.00
- Replace furl filter assembly	Napagold Oil Filter	1.00
- Replace Bu light	Napagold Fuel Filter	1.00
- R&r trailer control, Pto control bracket,speaker control bracket, and radio	Napagold Fuel Filter	1.00
- Shop Supplies	Used Fire X Refurbished	3.00
	Washer Fluid Concentr	1.00
	Wiper Blade	2.00
	Door Panel	1.00
	Fuel Filter Assembly	1.00
	Pump	1.00
	Rail Fuel	1.00
	Fuel Valve	1.00
	Led Adapter Plug	1.00
	Led Back-up Lamp Sys	1.00
	Hose Clamp	4.00
	Shop Supplies	1.00
Hours 46.00	Labor: 3,082.0	Parts: 5,198.42
:	0	Total: 8,280.42

Workorder: 1902334 **Meter:** 77559 **In Date:** 03/01/2019 **Closed:** 03/07/2019
Problem: Fues

- 2 Fuse packs	Parts List	Qty
- Shop Supplies	Fuse Kit	2.00
	Valu Pak	2.00
	Shop Supplies	1.00
Hours 0.00	Labor: 0.00	Parts: 86.19
:		Total: 86.19

Workorder: 1904244 **Meter:** 77774 **In Date:** 04/18/2019 **Closed:** 04/18/2019
Problem: Transition Prep Charge

- Transition Prep Charge			
Hours 2.00	Labor: 134.00	Parts: 0.00	Total: 134.00
:			