

2/1/2022
12:52:37 PM

Palm Beach County Fleet Management Asset Maintenance History
10186218 2012 FORD EXPLORER Suv, Lg Mid Size, 4X4

Total Hours: 108.40		Labor: 6,902.25	Parts: 3,829.38	Comm: 1,137.76	Charged: 11869.38
Work Order: 1200316	Meter: 92			In Date: 01/10/2012	Closed: 01/12/2012
Problem: install rain guards					
Work Completed			Parts Issued		Quantity
- Order rim guards and install on all 4 doors			Shop Supplies		1.00
- Shop Supplies			Vent Shades		1.00
Hours: 1.50		Comm: 0.00	Labor: 90.00	Parts: 100.13	Total: 190.13
Work Order: 1200336	Meter: 92			In Date: 01/10/2012	Closed: 01/10/2012
Problem: 1061 - Pre Delivery Inspection					
Work Completed					
- Pre Delivery Inspection					
- Wash Vehicle					
Hours: 3.50		Comm: 0.00	Labor: 210.00	Parts: 0.00	Total: 210.00
Work Order: 1200424	Meter: 92			In Date: 01/12/2012	Closed: 01/12/2012
Problem: 1 - Wash ticket(s) issued					
Work Completed					
- 1 - Wash ticket(s) issued					
Hours: 0.00		Comm: 9.73	Labor: 0.00	Parts: 0.00	Total: 9.73
Work Order: 1201363	Meter: 456			In Date: 02/09/2012	Closed: 02/09/2012
Problem: no start/ tried to jump					
Work Completed					
- Tow From: 20 s. military Eoc pam at reception has keys To: lv shop					
Hours: 0.00		Comm: 104.15	Labor: 0.00	Parts: 0.00	Total: 104.15
Work Order: 1201421	Meter: 473			In Date: 02/13/2012	Closed: 02/14/2012
Problem: Tow in,dead battery.					
Work Completed			Parts Issued		Quantity
- Recharge battery and test charging system.system test good at this time.			Shop Supplies		1.00
- Shop Supplies					
Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.00	Total: 62.00

2/1/2022
12:52:37 PM

Palm Beach County Fleet Management Asset Maintenance History
10186218 2012 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1301155 **Meter:** 5201 **In Date:** 01/31/2013 **Closed:** 02/06/2013
Problem: Pm service .Maintenance reminder light on.

Work Completed

- P.m. Service.
- Rotate and balance all tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Shop Supplies	1.00

Hours: 3.75

Comm: 0.00

Labor: 225.00

Parts: 25.27

Total: 250.27

Work Order: 1301301 **Meter:** 5107 **In Date:** 02/05/2013 **Closed:** 02/05/2013
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00

Comm: 97.92

Labor: 0.00

Parts: 0.00

Total: 97.92

Work Order: 1307675 **Meter:** 9120 **In Date:** 08/01/2013 **Closed:** 08/15/2013
Problem: P.M. service .

Work Completed

- P.m. Service.
- Rotate and balance all tires.
- Reconfigure strobe light pattern and harness for grille lights.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Shop Supplies	1.00

Hours: 4.75

Comm: 0.00

Labor: 285.00

Parts: 22.00

Total: 307.00

Work Order: 1401208 **Meter:** 11592 **In Date:** 02/05/2014 **Closed:** 02/18/2014
Problem: Pm service.

Work Completed

- P.m. Service.
- Rotate and balance all tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Accufit Beam	1.00
Accufit Beam	1.00
Blade	1.00
Shop Supplies	1.00

Hours: 3.75

Comm: 0.00

Labor: 225.00

Parts: 66.43

Total: 291.43

2/1/2022
12:52:37 PM

Palm Beach County Fleet Management Asset Maintenance History
10186218 2012 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1407921 **Meter:** 15374 **In Date:** 08/11/2014 **Closed:** 08/22/2014
Problem: Pm service and recall 14S 06 power steering.

Work Completed

Parts Issued

Quantity

- Pm service.
- Rotate and balance all four tires.
- Transport vehicle to and from dealer for safety recall 14s06 Inspect and reprogram power steering control module.
- Shop Supplies

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Shop Supplies	1.00

Hours: 5.75 Comm: 0.00 Labor: 345.00 Parts: 21.19 Total: 366.19

Work Order: 1502026 **Meter:** 17978 **In Date:** 02/25/2015 **Closed:** 03/09/2015
Problem: Pm service.Dead battery.Check brakes and wiper blades.

Work Completed

Parts Issued

Quantity

- Pm service
- Test starting and charging system.battery failed loadtest after recharge.replace defective battery.
- Rotate and balance all four tires.
- Shop Supplies

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Accufit Beam	1.00
Accufit Beam	1.00
Blade	1.00
Washer Fluid Concentr	1.00
Battery	1.00
Shop Supplies	1.00

Hours: 4.75 Comm: 0.00 Labor: 285.00 Parts: 226.40 Total: 511.40

Work Order: 1504345 **Meter:** 18627 **In Date:** 04/28/2015 **Closed:** 04/28/2015
Problem: 10 - Wash ticket(s) issued

Work Completed

- 10 - Wash ticket(s) issued

Hours: 0.00 Comm: 95.40 Labor: 0.00 Parts: 0.00 Total: 95.40

2/1/2022
12:52:37 PM

Palm Beach County Fleet Management Asset Maintenance History
10186218 2012 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1511474 **Meter:** 24548 **In Date:** 11/09/2015 **Closed:** 11/23/2015
Problem: Pm service.Recall.

Work Completed

- Pm service.
- Rotate and balance all four tires.
- Transport vehicle to and from dealer for safety recall # 15s11
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Accufit Beam	1.00
Accufit Beam	1.00
Blade	1.00
Shop Supplies	1.00

Hours: 5.75 Comm: 0.00 Labor: 345.00 Parts: 73.12 Total: 418.12

Work Order: 1511934 **Meter:** 24548 **In Date:** 11/23/2015 **Closed:** 11/23/2015
Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 9.54 Labor: 0.00 Parts: 0.00 Total: 9.54

Work Order: 1512689 **Meter:** 25465 **In Date:** 12/16/2015 **Closed:** 12/31/2015
Problem: Check a/c for intermittent operation.

Work Completed

- Drive vehicle several times.unable to duplicate operators complain.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

2/1/2022
12:52:37 PM

Palm Beach County Fleet Management Asset Maintenance History
10186218 2012 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1606726 **Meter:** 30082 **In Date:** 07/01/2016 **Closed:** 07/11/2016
Problem: P.M. Service.

Work Completed

- P.m. Service.
- Rotate and balance all tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Accufit Beam	1.00
Accufit Beam	1.00
Blade	1.00
Shop Supplies	1.00

Hours: 3.75

Comm: 0.00

Labor: 225.00 Parts: 69.98 Total: 294.98

Work Order: 1607925 **Meter:** 30325 **In Date:** 08/02/2016 **Closed:** 08/10/2016
Problem: Has to jump start in the A/M.

Work Completed

- Recharge battery and test charging system.battery failed load test.replace bad battery.
- Shop Supplies

Parts Issued

Quantity

Battery	1.00
Macs Battery Cleaner	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 60.00 Parts: 154.43 Total: 214.43

Work Order: 1701485 **Meter:** 35299 **In Date:** 02/13/2017 **Closed:** 02/28/2017
Problem: P.M. Service.

Work Completed

- P.m. Service.
- Pressure test and inspect cooling system.flush and refill system.
- Replace and balance four new tires.
- Complete wheel alignment.test drive.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Accufit Beam	1.00
Accufit Beam	1.00
Wpr/blde	1.00
Napagold Air Filter	1.00
Anti Freeze Motorcraft	2.00
Tire 245/60/18 Mic	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 9.25

Comm: 0.00

Labor: 555.00 Parts: 1,031.55 Total: 1,586.55

2/1/2022
12:52:37 PM

Palm Beach County Fleet Management Asset Maintenance History
10186218 2012 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1701734 **Meter:** 35299 **In Date:** 02/16/2017 **Closed:** 02/16/2017
Problem: 10 - Wash ticket(s) issued

Work Completed

- 10 - Wash ticket(s) issued

Hours: 0.00 Comm: 95.40 Labor: 0.00 Parts: 0.00 Total: 95.40

Work Order: 1708104 **Meter:** 39194 **In Date:** 08/17/2017 **Closed:** 08/24/2017
Problem: P.M. service and inspect for ehaust fumes.

Work Completed

- P.m. service.

- Perform automatic transmission flush exchange with new fluid.

- Rotate and balance four tires.

- Inspect and perform Tsb16-0166,procedure one.check seams and plugs
for leaks and reprogram with scan tool the Hvac system to latest calibration.

- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil 6.00

Napagold Oil Filter 1.00

Washer Fluid Concentr 1.00

Accufit Beam 1.00

Accufit Beam 1.00

Wpr/blde 1.00

Napa Cabin Air Filter 1.00

Syn-atf Trans Fluid S 12.00

Shop Supplies 1.00

Hours: 6.25 Comm: 0.00 Labor: 375.00 Parts: 113.51 Total: 488.51

2/1/2022
12:52:37 PM

Palm Beach County Fleet Management Asset Maintenance History
10186218 2012 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1801707 **Meter:** 41477 **In Date:** 02/13/2018 **Closed:** 02/27/2018
Problem: PM Service

Work Completed

- P.m. service.
- Rear shocks leaking .r&r with new.
- Replace front brake pads, service calipers and resurface front rotors.bleed system and test drive.
- Rotate and high speed balance all four tires.
- Transport to and from dealer for 17n03 recall.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
26in Exactfit-beam	1.00
22in Exactfit-beam	1.00
11in Exactfit-rear	1.00
Washer Fluid Concentr	1.00
Shock Absorber	2.00
Front Brake Pad	1.00
Shop Supplies	1.00

Hours: 11.35

Comm: 0.00

Labor: 681.00

Parts: 304.27

Total: 985.27

Work Order: 1807711 **Meter:** 44881 **In Date:** 07/30/2018 **Closed:** 08/01/2018
Problem: Driver side windshield moulding blew off.

Work Completed

- Replace missing left side of windsield molding.
- Repair right rear tire and balance . Nitrogen fill tires.
- Shop Supplies

Parts Issued

Quantity

Moulding	1.00
Moulding	1.00
Shop Supplies	1.00

Hours: 1.50

Comm: 0.00

Labor: 90.00

Parts: 237.61

Total: 327.61

2/1/2022
12:52:37 PM

Palm Beach County Fleet Management Asset Maintenance History
10186218 2012 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1809331 **Meter:** 45126 **In Date:** 09/11/2018 **Closed:** 09/19/2018
Problem: PM Service, Dead battery had to jump

Work Completed

Parts Issued

Quantity

- P.m. service.
- Perform battery load and analizing test . Battery failed load test . R&i defective battery .
- Inspect oil in air intake port . Replace left front valve cover and gasket due to stuck Pcv valve.
- Rotate and high speed balance all four wheels . Nitrogen fill tires.
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22in Exactfit-beam	1.00
26in Exactfit-beam	1.00
11in Exactfit-rear	1.00
Washer Fluid Concentr	1.00
Battery	1.00
Vallve Cover Asm	1.00
Shop Supplies	1.00

Hours: 6.05

Comm: 0.00

Labor: 363.00

Parts: 308.33

Total: 671.33

Work Order: 1809726 **Meter:** 45126 **In Date:** 09/20/2018 **Closed:** 09/20/2018
Problem: 5 - Wash ticket(s) issued

Work Completed

- 5 - Wash ticket(s) issued

Hours: 0.00

Comm: 47.70

Labor: 0.00

Parts: 0.00

Total: 47.70

Work Order: 1901406 **Meter:** 46946 **In Date:** 02/05/2019 **Closed:** 02/14/2019
Problem: Had to lump start.

Work Completed

- Charge battery fully . Test battery and charging system ,ok. Perform draw test .038 amps .remove phone charger retest .018 amps. Ok.

Hours: 0.50

Comm: 0.00

Labor: 33.50

Parts: 0.00

Total: 33.50

Work Order: 1902449 **Meter:** 47160 **In Date:** 03/05/2019 **Closed:** 03/05/2019
Problem: 8 - Wash ticket(s) issued

Work Completed

- 8 - Wash ticket(s) issued

Hours: 0.00

Comm: 76.32

Labor: 0.00

Parts: 0.00

Total: 76.32

2/1/2022
12:52:37 PM

Palm Beach County Fleet Management Asset Maintenance History
10186218 2012 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1903848 **Meter:** 47541 **In Date:** 04/09/2019 **Closed:** 04/17/2019
Problem: P.M. service and left side windshield molding cracked .

Work Completed

- P.m. service.
- Rotate and balance all four tires . Nitrogen fill all .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
11in Exactfit-rear	1.00
22in Exactfit-beam	1.00
26in Exactfit-beam	1.00
Moulding	1.00
Moulding	1.00
Shop Supplies	1.00

Hours: 3.75

Comm: 0.00

Labor: 251.25

Parts: 296.54

Total: 547.79

Work Order: 1903924 **Meter:** 47478 **In Date:** 04/10/2019 **Closed:** 04/16/2019
Problem: replace cracket windsheild

Work Completed

- set up repairs & reasset
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 410.80

Labor: 67.00

Parts: 3.00

Total: 480.80

Work Order: 1904910 **Meter:** 47746 **In Date:** 05/06/2019 **Closed:** 05/13/2019
Problem: Had to jump start in A.M.

Work Completed

- Perform eletrical system diagnosis . No codes from battery or charging system . No parasitic draws found . Charge battery and retest .

Hours: 0.50

Comm: 0.00

Labor: 33.50

Parts: 0.00

Total: 33.50

Work Order: 1905290 **Meter:** 47746 **In Date:** 05/15/2019 **Closed:** 05/15/2019
Problem: 5 - Wash ticket(s) issued

Work Completed

- 5 - Wash ticket(s) issued

Hours: 0.00

Comm: 47.70

Labor: 0.00

Parts: 0.00

Total: 47.70

2/1/2022
12:52:37 PM

Palm Beach County Fleet Management Asset Maintenance History
10186218 2012 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1905852 **Meter:** 47886 **In Date:** 06/03/2019 **Closed:** 06/10/2019
Problem: Vibrating noise at highway speeds .

Work Completed

- Test drive for noise . R&r damaged cowl panel . road test noise gone .
- Shop Supplies

Hours: 1.00

Comm: 0.00

Parts Issued

Quantity

Grille	1.00
--------	------

Shop Supplies	1.00
---------------	------

Labor: 67.00	Parts: 236.28	Total: 303.28
--------------	---------------	---------------

Work Order: 1910253 **Meter:** 48337 **In Date:** 10/03/2019 **Closed:** 10/24/2019
Problem: P.M. service and recall 19S17 .

Work Completed

- P.m. service.
- Test and repair circuit to left rear strobe light .
- Rotate and high speed balance all four tires . Nitrofill all.
- Transport to and from dealer for recall 19s17 .
- Shop Supplies

Hours: 6.75

Comm: 0.00

Parts Issued

Quantity

Napagold Oil Filter	1.00
---------------------	------

5w20 Engine Oil	6.00
-----------------	------

11in Exactfit-rear	1.00
--------------------	------

22in Exactfit-beam	1.00
--------------------	------

26in Exactfit-beam	1.00
--------------------	------

Mac Wite Lithium Gres	1.00
-----------------------	------

Napa Cabin Air Filter	1.00
-----------------------	------

Vinyl Electrical Tape	1.00
-----------------------	------

Shop Supplies	1.00
---------------	------

Labor: 492.75	Parts: 75.73	Total: 568.48
---------------	--------------	---------------

Work Order: 1910375 **Meter:** 48239 **In Date:** 10/07/2019 **Closed:** 10/07/2019
Problem: 10 - Wash ticket(s) issued

Work Completed

- 10 - Wash ticket(s) issued

Hours: 0.00

Comm: 95.40

Labor: 0.00

Parts: 0.00

Total: 95.40

2/1/2022
12:52:37 PM

Palm Beach County Fleet Management Asset Maintenance History
10186218 2012 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 2006799 **Meter:** 50534 **In Date:** 07/13/2020 **Closed:** 07/20/2020
Problem: P.M. service.

Work Completed

Parts Issued

Quantity

- P.m. service.
- Replace both rear brake rotors and pads . Service calipers . Flush and bleed brake system . Road test .
- Rotate and high speed balance all four tires . Nitrofill all.
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
11in Exactfit-rear	1.00
26in Exactfit-beam	1.00
22in Exactfit-beam	1.00
Brake Rotor	2.00
Rear Brake Pad	1.00
Shop Supplies	1.00

Hours: 7.75

Comm: 0.00

Labor: 565.75

Parts: 312.30

Total: 878.05

Work Order: 2101492 **Meter:** 51713 **In Date:** 02/09/2021 **Closed:** 02/19/2021
Problem: P.M. service.

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- replace cabin a/c filter and refresh intake air
- balance and rotate all 4 tires Nitro fill all.
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
11in Exactfit-rear	1.00
22in Exactfit-beam	1.00
26in Exactfit-beam	1.00
Cabin Filter	1.00
Shop Supplies	1.00

Hours: 4.25

Comm: 0.00

Labor: 310.25

Parts: 93.21

Total: 403.46

Work Order: 2102630 **Meter:** 51907 **In Date:** 03/04/2021 **Closed:** 03/08/2021
Problem: 5 - Wash ticket(s) issued

Work Completed

- 5 - Wash ticket(s) issued

Hours: 0.00

Comm: 47.70

Labor: 0.00

Parts: 0.00

Total: 47.70

2/1/2022
12:52:37 PM

Palm Beach County Fleet Management Asset Maintenance History
10186218 2012 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 2110172 **Meter:** 52593 **In Date:** 09/20/2021 **Closed:** 09/30/2021
Problem: PM Service

Work Completed

- Preventive Maint. Service
- Rotate and speed balance all, nitro fill
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
26in Exactfit-beam	1.00
22in Exactfit-beam	1.00
11in Exactfit-rear	1.00
Washer Fluid Concentr	1.00
Shop Supplies	1.00

Hours: 3.75

Comm: 0.00

Labor: 273.75

Parts: 51.50

Total: 325.25

Work Order: 2200070 **Meter:** 53215 **In Date:** 01/04/2022 **Closed:** 01/04/2022
Problem: get ready for auction

Work Completed

- Prepare For Auction, R&i Grill To Remove Emergency Lights
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 2.50

Comm: 0.00

Labor: 182.50

Parts: 2.65

Total: 185.15

Work Order: 2200082 **Meter:** 53214 **In Date:** 01/04/2022 **Closed:** 01/04/2022
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 0.00

Total: 146.00

Total Hours: 108.40

Total Labor: 6,902.25

Total Comm: 1,137.76

Total Parts: 3,829.38