

# Report Description: Work Order History by Asset and System Code

WO Close Date Range: 01/26/2010 to 09/26/2021

System Code Range: 1201 to 9700

Print Date: 1/31/2023

Asset# Range: PT0900 to PT0900

| BUS#         | SYS Code | SYS Code Description      |           |                                                                                     |  |                                         |                    |
|--------------|----------|---------------------------|-----------|-------------------------------------------------------------------------------------|--|-----------------------------------------|--------------------|
| PT0900       | 1201     | TROUBLESHOOT COOLING SYS  |           |                                                                                     |  | Total Line Count for System Code 1201 : | 3                  |
|              |          |                           |           |                                                                                     |  |                                         | Cause-Reason       |
| Work Order # | Line#    | Close Date                | Employee# | Description of Work                                                                 |  |                                         | OPERATOR COMPLAINT |
| 1311437      | 1        | 09/23/2013                | 762       | TS COOLING SYS - CHECKED OPERATION OF COOLANT PUMP ON SERVICE TRUCK. NEED TO REPL F |  |                                         | OPERATOR COMPLAINT |
| 1511181      | 1        | 08/12/2015                | 809       | t/s cooling system                                                                  |  |                                         | OPERATOR COMPLAINT |
| 1922556      | 1        | 12/05/2019                | 849       | TROUBLESHOOT COOLING SYSTEM---FOUND LOWER HOSE BAD--REPAIR LOWER HOSE--CKD FOR I    |  |                                         |                    |
| PT0900       | 1301     | TROUBLESHOOT AC SYSTEM    |           |                                                                                     |  | Total Line Count for System Code 1301 : | 4                  |
|              |          |                           |           |                                                                                     |  |                                         | Cause-Reason       |
| Work Order # | Line#    | Close Date                | Employee# | Description of Work                                                                 |  |                                         | OPERATOR COMPLAINT |
| 1922556      | 2        | 12/05/2019                | 849       | TROUBLESHOOT AC SYSTEM---NOT WORKING--RECOVERED FREON--TRIED TO RECHARGE, WOU       |  |                                         | OPERATOR COMPLAINT |
| 2001259      | 1        | 01/21/2020                | 849       | T/S A/C SYSTEM                                                                      |  |                                         | OPERATOR COMPLAINT |
| 2018415      | 1        | 10/05/2020                | 849       | TROUBLESHOOT AC SYSTEM---NEEDS HIGH PSI HOSE TO CONDENSOR--AC & CONDENSOR ON OF     |  |                                         | OPERATOR COMPLAINT |
| 2004624      | 1        | 03/16/2020                | 849       | TROUBLESHOOT AC SYSTEM-----AC DOES NOT BLOW ON SPEED 1&2--NEED TO REPLC BLOW RESIS  |  |                                         |                    |
| PT0900       | 1312     | A/C CONDENSOR             |           |                                                                                     |  | Total Line Count for System Code 1312 : | 1                  |
|              |          |                           |           |                                                                                     |  |                                         | Cause-Reason       |
| Work Order # | Line#    | Close Date                | Employee# | Description of Work                                                                 |  |                                         | OPERATOR COMPLAINT |
| 2018415      | 4        | 10/05/2020                | 849       | R/R CONDENSOR & HIGH PSI TUBE TO CONDENSOR                                          |  |                                         |                    |
| PT0900       | 1314     | A/C ELEC COMPONENTS REPL. |           |                                                                                     |  | Total Line Count for System Code 1314 : | 2                  |
|              |          |                           |           |                                                                                     |  |                                         | Cause-Reason       |
| Work Order # | Line#    | Close Date                | Employee# | Description of Work                                                                 |  |                                         | OPERATOR COMPLAINT |
| 2004624      | 2        | 03/16/2020                | 849       | REPLCD BLOWER RESTRICTOR--AC BLOWS WARM                                             |  |                                         | SCHEDULED SERVICE  |
| 1415751      | 3        | 10/30/2014                | 809       | R/R BLOWN RESISTOR                                                                  |  |                                         |                    |
| PT0900       | 1318     | A/C SYSTEM RE-CHARGE      |           |                                                                                     |  | Total Line Count for System Code 1318 : | 3                  |
|              |          |                           |           |                                                                                     |  |                                         | Cause-Reason       |
| Work Order # | Line#    | Close Date                | Employee# | Description of Work                                                                 |  |                                         | OPERATOR COMPLAINT |
| 2004624      | 5        | 03/16/2020                | 849       | ADDED DYE & FREON TO CK FOR LEAKS--NONE                                             |  |                                         | OPERATOR COMPLAINT |
| 2018415      | 5        | 10/05/2020                | 849       | TRIED TO RECHARGE AC SYSTEM--WOULDNT HOLD--CHANGED O RINGS--CLEANED TUBE--REALIZE   |  |                                         | SCHEDULED SERVICE  |
| 1918037      | 11       | 10/29/2019                | 849       | VACUUM AND RECHARGER A/C SYSTEM                                                     |  |                                         |                    |
| PT0900       | 1336     | Pressure Test A/C System  |           |                                                                                     |  | Total Line Count for System Code 1336 : | 1                  |
|              |          |                           |           |                                                                                     |  |                                         | Cause-Reason       |
| Work Order # | Line#    | Close Date                | Employee# | Description of Work                                                                 |  |                                         | OPERATOR COMPLAINT |
| 2004624      | 4        | 03/16/2020                | 849       | HOOKEED UP AC MACHINE TO CK PSI--EVACUATE/VACUUM SYSTEM                             |  |                                         |                    |

# Report Description: Work Order History by Asset and System Code

WO Close Date Range: 01/26/2010 to 09/26/2021

System Code Range: 1201 to 9700

Print Date: 1/31/2023

Asset# Range: PT0900 to PT0900

| BUS#         | SYS Code | SYS Code Description |           |                                                                               |                      |    |
|--------------|----------|----------------------|-----------|-------------------------------------------------------------------------------|----------------------|----|
| PT0900       | 1400     | ELECTRICAL SYSTEM    |           | Total Line Count for System Code 1400 :                                       |                      | 16 |
| Work Order # | Line#    | Close Date           | Employee# | Description of Work                                                           | Cause-Reason         |    |
| 1109708      | 1        | 11/04/2011           | 753       | ELEC SYS - FOUND NOT CONNECTING                                               | SCHEDULED SERVICE    |    |
| 1000581      | 1        | 01/26/2010           | 740       | elec. syst.                                                                   | EQUIPMENT CONVERSION |    |
| 1000581      | 2        | 01/26/2010           | 740       | elec. lights                                                                  | EQUIPMENT CONVERSION |    |
| 1000581      | 2        | 01/26/2010           | 780       | elec. lights                                                                  | EQUIPMENT CONVERSION |    |
| 1000581      | 3        | 01/26/2010           | 780       | installed 2 - strobe lights                                                   | EQUIPMENT CONVERSION |    |
| 1000581      | 3        | 01/26/2010           | 736       | installed 2 - strobe lights                                                   | EQUIPMENT CONVERSION |    |
| 1918037      | 14       | 10/29/2019           | 849       | DIAG -TOP AND REAR STROBS NOT WORKING FOUND WIRE UNPLUGGED FROM TOGGLE SWITCH | SCHEDULED SERVICE    |    |
| 2105437      | 4        | 03/18/2021           | 753       | R/R ALL PUMP SWITCHES--INSTALL RUBBER BOOTS                                   | SCHEDULED SERVICE    |    |
| 2105437      | 5        | 03/18/2021           | 753       | EMPTY SERVICE OUL TANK--REFILL W/FRESH FUEL                                   | SCHEDULED SERVICE    |    |
| 1921733      | 4        | 09/26/2021           | 828       | CONTINUE REWIRE                                                               | OPERATOR COMPLAINT   |    |
| 1921733      | 5        | 09/26/2021           | 828       | COMPLETE INSTALLATION                                                         | OPERATOR COMPLAINT   |    |
| 1921733      | 6        | 09/26/2021           | 828       | PART ON THIS LINE                                                             | OPERATOR COMPLAINT   |    |
| 1921733      | 1        | 09/26/2021           | 828       | ELECTRICAL SYSTEM--BEGIN INSTALL/REMOVAL                                      | OPERATOR COMPLAINT   |    |
| 1921733      | 2        | 09/26/2021           | 828       | BEGIN RE-WIRE                                                                 | OPERATOR COMPLAINT   |    |
| 1921733      | 3        | 09/26/2021           | 828       | CONTINUE RE--WIRE                                                             | OPERATOR COMPLAINT   |    |
| 1410803      | 1        | 08/01/2014           | 752       | ELECTRICAL SYSTEM - R/R AIR COMP CONTROL                                      | OPERATOR COMPLAINT   |    |

**Report Description: Work Order History by Asset and System Code**

WO Close Date Range: 01/26/2010 to 09/26/2021

System Code Range: **1201** to **9700**

Print Date: 1/31/2023

**Asset# Range:** **PT0900** to **PT0900**

| BUS#         | SYS Code | SYS Code Description      |           |                                                                                    |                                         |   |                    |
|--------------|----------|---------------------------|-----------|------------------------------------------------------------------------------------|-----------------------------------------|---|--------------------|
| PT0900       | 1401     | TROUBLESHOOT ELECTRICAL S |           |                                                                                    | Total Line Count for System Code 1401 : | 4 | Cause-Reason       |
| Work Order # | Line#    | Close Date                | Employee# | Description of Work                                                                |                                         |   | OPERATOR COMPLAINT |
| 1702913      | 1        | 02/27/2017                | 756       | TROUBLESHOOT ELECTRICALS---BAD SENSORS                                             |                                         |   | MECHANIC DEFECT    |
| 1723272      | 7        | 02/22/2018                | 849       | SEARCH FOR ELECTRICAL ISSUE--FOUND 1 WIRE RUBBING--FIXED--STILL HAS ISSUE          |                                         |   | OPERATOR COMPLAINT |
| 1821007      | 2        | 03/20/2019                | 828       | CHECK CHARGING SYSTEM NEED SET OF BATTERIES DONE ON W/O 1821505                    |                                         |   | OPERATOR COMPLAINT |
| 2123019      | 3        | 09/01/2021                | 823       | CHECK CHARGING SYSTEM                                                              |                                         |   |                    |
| PT0900       | 1407     | BATTERIES CHECK           |           |                                                                                    | Total Line Count for System Code 1407 : | 2 | Cause-Reason       |
| Work Order # | Line#    | Close Date                | Employee# | Description of Work                                                                |                                         |   | OPERATOR COMPLAINT |
| 2123019      | 2        | 09/01/2021                | 823       | CHARGING BATTERY                                                                   |                                         |   | SCHEDULED SERVICE  |
| 2105437      | 2        | 03/18/2021                | 822       | CHARGE BATTERY                                                                     |                                         |   |                    |
| PT0900       | 1408     | BATTERIES REPLACE         |           |                                                                                    | Total Line Count for System Code 1408 : | 5 | Cause-Reason       |
| Work Order # | Line#    | Close Date                | Employee# | Description of Work                                                                |                                         |   | OPERATOR COMPLAINT |
| 2008761      | 1        | 05/14/2020                | 820       | REPLCD BATTERIES--DISCONNECTED BATTERIES--REMVD BRACKETS, STRAPS, ETC---R/R BATTER |                                         |   | SCHEDULED SERVICE  |
| 1307438      | 2        | 06/18/2013                | 752       | REPLC BATT                                                                         |                                         |   | SCHEDULED SERVICE  |
| 1814358      | 1        | 07/06/2018                | 797       | BATTERIES CHECK BOTH BATTERY REPLACE ONE BATTERY CHECK CHARGING SYSTEM OK          |                                         |   | NORMAL WEAR        |
| 1821505      | 2        | 10/02/2018                | 756       | R/R BATTERIES                                                                      |                                         |   | OPERATOR COMPLAINT |
| 1604313      | 1        | 03/25/2016                | 791       | BATTERIES REPLACE                                                                  |                                         |   |                    |

**Report Description: Work Order History by Asset and System Code**

WO Close Date Range: 01/26/2010 to 09/26/2021

System Code Range: **1201** to **9700**

Print Date: 1/31/2023

**Asset# Range:** **PT0900** to **PT0900**

| <b>BUS#</b>         | <b>SYS Code</b> | <b>SYS Code Description</b>      |                  |                                                                                      |                                                |          |
|---------------------|-----------------|----------------------------------|------------------|--------------------------------------------------------------------------------------|------------------------------------------------|----------|
| <b>PT0900</b>       | <b>1409</b>     | <b>EXTERIOR LIGHTING</b>         |                  |                                                                                      | <b>Total Line Count for System Code 1409 :</b> | <b>7</b> |
| <u>Work Order #</u> | <u>Line#</u>    | <u>Close Date</u>                | <u>Employee#</u> | <u>Description of Work</u>                                                           | <u>Cause-Reason</u>                            |          |
| 1508505             | 2               | 06/11/2015                       | 818              | REPLCD BRAKE BULB, CARGO BULB, TAG BULB                                              | SCHEDULED SERVICE                              |          |
|                     |                 |                                  |                  |                                                                                      | SCHEDULED SERVICE                              |          |
| 1415751             | 2               | 10/30/2014                       | 809              | T/T CLEARANCE LIGHT BULB                                                             | OPERATOR COMPLAINT                             |          |
| 1700633             | 1               | 01/17/2017                       | 797              | EXTERIOR LIGHTING                                                                    | OPERATOR COMPLAINT                             |          |
| 1503397             | 1               | 02/26/2015                       | 762              | EXTERIOR LIGHTING - R/R BOTH SIDES TAKE LAMP AND REVERSE LAMP ASSMBLY AND REWIRED PL | OPERATOR COMPLAINT                             |          |
| 2001951             | 1               | 02/07/2020                       | 809              | EXTERIOR LIGHTING----REPLCD LEFT HEAD BULB                                           | OPERATOR COMPLAINT                             |          |
| 2001259             | 2               | 01/21/2020                       | 849              | TESTED WIRES AND FOUND BLOWN FUSE -CHANGED FUSE AND STROBES NOW WORKING              | SCHEDULED SERVICE                              |          |
| 2105437             | 3               | 03/18/2021                       | 753              | R/R TAG LIGHT--R/R MARKER & RED LIGHT BULBS                                          |                                                |          |
| <b>PT0900</b>       | <b>1410</b>     | <b>INTERIOR LIGHTING</b>         |                  |                                                                                      | <b>Total Line Count for System Code 1410 :</b> | <b>1</b> |
| <u>Work Order #</u> | <u>Line#</u>    | <u>Close Date</u>                | <u>Employee#</u> | <u>Description of Work</u>                                                           | <u>Cause-Reason</u>                            |          |
| 2004624             | 3               | 03/16/2020                       | 849              | REPLCD (3) DOME LIGHTS                                                               | OPERATOR COMPLAINT                             |          |
| <b>PT0900</b>       | <b>1413</b>     | <b>ELEC.SYS.SWITCHES-BREAKER</b> |                  |                                                                                      | <b>Total Line Count for System Code 1413 :</b> | <b>2</b> |
| <u>Work Order #</u> | <u>Line#</u>    | <u>Close Date</u>                | <u>Employee#</u> | <u>Description of Work</u>                                                           | <u>Cause-Reason</u>                            |          |
| 1811514             | 1               | 06/26/2018                       | 837              | ELEC SYSTEM SWITCHES BREAKER RECIEVED PARTS                                          | OPERATOR COMPLAINT                             |          |
| 1811514             | 2               | 06/26/2018                       | 837              | RR SWITCH                                                                            | OPERATOR COMPLAINT                             |          |
| <b>PT0900</b>       | <b>1417</b>     | <b>WIRING HARNESSES</b>          |                  |                                                                                      | <b>Total Line Count for System Code 1417 :</b> | <b>1</b> |
| <u>Work Order #</u> | <u>Line#</u>    | <u>Close Date</u>                | <u>Employee#</u> | <u>Description of Work</u>                                                           | <u>Cause-Reason</u>                            |          |
| 1109708             | 2               | 11/04/2011                       | 753              | RUN NEW WIRE HARNESS TO FUEL PUMP-NOW WORKS                                          | SCHEDULED SERVICE                              |          |

**Report Description: Work Order History by Asset and System Code**

WO Close Date Range: 01/26/2010 to 09/26/2021

System Code Range: **1201** to **9700**

Print Date: 1/31/2023

**Asset# Range:** **PT0900** to **PT0900**

| BUS#         | SYS Code | SYS Code Description |           |                                                |  |                                            |              |
|--------------|----------|----------------------|-----------|------------------------------------------------|--|--------------------------------------------|--------------|
| PT0900       | 2500     | BODY                 |           |                                                |  | Total Line Count for System Code 2500 : 11 | Cause-Reason |
| Work Order # | Line#    | Close Date           | Employee# | Description of Work                            |  | SCHEDULED SERVICE                          |              |
| 1009443      | 1        | 09/29/2010           | 752       | INSTALL CONE HOLDER                            |  |                                            |              |
|              |          |                      |           |                                                |  | OPERATOR COMPLAINT                         |              |
| 2021028      | 2        | 11/24/2020           | 849       | WINDSHIELD NEEDS RESEALING                     |  |                                            |              |
|              |          |                      |           |                                                |  | SCHEDULED SERVICE                          |              |
| 1517952      | 2        | 01/05/2016           | 828       | adj. wiper and added wiper fluid               |  |                                            |              |
|              |          |                      |           |                                                |  | OPERATOR COMPLAINT                         |              |
| 1109298      | 1        | 10/24/2011           | 752       | BODY-REPAIR CONE HOLDER                        |  |                                            |              |
|              |          |                      |           |                                                |  | MISCELLANEOUS                              |              |
| 1000836      | 3        | 02/01/2010           | 780       | apply palm tran stickers on truck              |  |                                            |              |
|              |          |                      |           |                                                |  | SCHEDULED SERVICE                          |              |
| 1000836      | 1        | 02/01/2010           | 759       | body - decal                                   |  |                                            |              |
|              |          |                      |           |                                                |  | SCHEDULED SERVICE                          |              |
| 1918037      | 3        | 10/29/2019           | 849       | STARTED TO REMOVE CAB                          |  |                                            |              |
|              |          |                      |           |                                                |  | OPERATOR COMPLAINT                         |              |
| 1910972      | 1        | 07/05/2019           | 828       | BODY -REMOVE HYDROLIC PUMP COVER               |  |                                            |              |
|              |          |                      |           |                                                |  | OPERATOR COMPLAINT                         |              |
| 1910972      | 2        | 07/05/2019           | 29        | SYSTEM REPAIRED BY BAYSIDE TRUCK TRAILER       |  |                                            |              |
|              |          |                      |           |                                                |  | SCHEDULED SERVICE                          |              |
| 1918037      | 12       | 10/29/2019           | 849       | FINISH ASSEMBLY BODY PARTS AND FFILTER HOUSING |  |                                            |              |
|              |          |                      |           |                                                |  | SCHEDULED SERVICE                          |              |
| 1918037      | 10       | 10/29/2019           | 849       | EINSTALL CAB ON CHASSES                        |  |                                            |              |
| PT0900       | 2505     | WIPERS               |           |                                                |  | Total Line Count for System Code 2505 : 5  | Cause-Reason |
| Work Order # | Line#    | Close Date           | Employee# | Description of Work                            |  | OPERATOR COMPLAINT                         |              |
| 2020483      | 1        | 10/15/2020           | 800       | WIPERS----REPLCD BOTH WIPER BLADES             |  |                                            |              |
|              |          |                      |           |                                                |  | OPERATOR COMPLAINT                         |              |
| 1814440      | 1        | 07/11/2018           | 797       | REPLCD WIPER SPRAY NOZZLE                      |  |                                            |              |
|              |          |                      |           |                                                |  | OPERATOR COMPLAINT                         |              |
| 1316483      | 1        | 12/23/2013           | 762       | WIPERS. R/R WIPERS                             |  |                                            |              |
|              |          |                      |           |                                                |  | OPERATOR COMPLAINT                         |              |
| 1614923      | 1        | 10/22/2016           | 756       | R/R WIPERS , ADD FLUID AND FILLED COOLANT TANK |  |                                            |              |
|              |          |                      |           |                                                |  | OPERATOR COMPLAINT                         |              |
| 1103081      | 1        | 04/11/2011           | 753       | WIPERS-R&R                                     |  |                                            |              |
| PT0900       | 2600     | BRAKES               |           |                                                |  | Total Line Count for System Code 2600 : 1  | Cause-Reason |
| Work Order # | Line#    | Close Date           | Employee# | Description of Work                            |  | OPERATOR COMPLAINT                         |              |
| 1508867      | 1        | 06/17/2015           | 809       | R/R FRONT BRAKE PADS                           |  |                                            |              |

**Report Description: Work Order History by Asset and System Code**

WO Close Date Range: 01/26/2010 to 09/26/2021

System Code Range: **1201** to **9700**

Print Date: 1/31/2023

**Asset# Range:** **PT0900** to **PT0900**

| BUS#         | SYS Code | SYS Code Description    |           |                                                                                    |                                         |   |              |
|--------------|----------|-------------------------|-----------|------------------------------------------------------------------------------------|-----------------------------------------|---|--------------|
| PT0900       | 2701     | TROUBLESHOOT AIR SYSTEM |           |                                                                                    | Total Line Count for System Code 2701 : | 1 | Cause-Reason |
| Work Order # | Line#    | Close Date              | Employee# | Description of Work                                                                | OPERATOR COMPLAINT                      |   |              |
| 1821007      | 1        | 03/20/2019              | 828       | T/S A/R SYSTEM                                                                     |                                         |   |              |
| PT0900       | 2709     | AIR PRESSURE SWITCHES   |           |                                                                                    | Total Line Count for System Code 2709 : | 1 | Cause-Reason |
| Work Order # | Line#    | Close Date              | Employee# | Description of Work                                                                | OPERATOR COMPLAINT                      |   |              |
| 1821007      | 3        | 03/20/2019              | 828       | RR PRESSURE SWITCH                                                                 |                                         |   |              |
| PT0900       | 2800     | ENGINE                  |           |                                                                                    | Total Line Count for System Code 2800 : | 6 | Cause-Reason |
| Work Order # | Line#    | Close Date              | Employee# | Description of Work                                                                | OPERATOR COMPLAINT                      |   |              |
| 2018415      | 3        | 10/05/2020              | 849       | REMVD COOLANT PUMP--FLUSHED PUMP--OK                                               |                                         |   |              |
| 1918037      | 5        | 10/29/2019              | 849       | INSTALLED HPFP -OIL COOLAER TURBO PEDESTALL FRP SENSOR PASSENER INJECTOR HARNESS   | SCHEDULED SERVICE                       |   |              |
| 1918037      | 6        | 10/29/2019              | 849       | START ASSEMBLY ENGINE                                                              | SCHEDULED SERVICE                       |   |              |
| 1918037      | 4        | 10/29/2019              | 849       | REMOVE INTAKE MANIFOLD OIL COOLER -HPFP-TURBO -PEDISTAL -COOLANT HOSES -FAN        | SCHEDULED SERVICE                       |   |              |
| 1723272      | 8        | 02/22/2018              | 837       | ECT VOLTAGE DROPS--POSSIBLE BAD ECT--ENGINE CONTROL TEMP                           | SCHEDULED SERVICE                       |   |              |
| 1722392      | 2        | 12/18/2017              | 818       | TOPPED OF OIL                                                                      | OPERATOR COMPLAINT                      |   |              |
| PT0900       | 2801     | TROUBLESHOOT ENGINE     |           |                                                                                    | Total Line Count for System Code 2801 : | 8 | Cause-Reason |
| Work Order # | Line#    | Close Date              | Employee# | Description of Work                                                                | OPERATOR COMPLAINT                      |   |              |
| 1722392      | 1        | 12/18/2017              | 818       | T/S ENGINE                                                                         |                                         |   |              |
| 2021028      | 1        | 11/24/2020              | 849       | TROUBLESHOOT ENGINE---DPF CLOGGED CODES--ROAD TEST--STATION REGEN--RESET DPF LIFI  | OPERATOR COMPLAINT                      |   |              |
| 1804399      | 1        | 05/04/2018              | 848       | T/S ENGINE                                                                         | OPERATOR COMPLAINT                      |   |              |
| 1723272      | 4        | 02/22/2018              | 828       | FOUND CODE 2291--CHANGING THE ENGINE OIL--RUNNING SMOOTH                           | SCHEDULED SERVICE                       |   |              |
| 1506194      | 6        | 05/21/2015              | 809       | SCAN ECM-P0193 ACTIVE-FUEL RAIL PRESSURE SENSOR LOCATED UNDER VALVE COVER-MAY NEEI | OPERATOR COMPLAINT                      |   |              |
| 1506194      | 1        | 05/21/2015              | 756       | TROUBLESHOOT ENGINE-ORDER PART FILTER                                              | OPERATOR COMPLAINT                      |   |              |
| 1609145      | 1        | 06/28/2016              | 818       | TROUBLESHOOT ENGINE--CODES P200E, P242B,P0703---                                   | OPERATOR COMPLAINT                      |   |              |
| 2123019      | 1        | 09/01/2021              | 753       | TROUBLESHOOT ENGINE---FOUND AFTER RECHARGE BATTERY'S SHOW PWER REDUCED & CEL--EI   | OPERATOR COMPLAINT                      |   |              |

**Report Description: Work Order History by Asset and System Code**

WO Close Date Range: 01/26/2010 to 09/26/2021

System Code Range: **1201** to **9700**

Print Date: 1/31/2023

**Asset# Range:** **PT0900** to **PT0900**

| BUS#         | SYS Code | SYS Code Description      |           |                                   |  |                                         |   |              |
|--------------|----------|---------------------------|-----------|-----------------------------------|--|-----------------------------------------|---|--------------|
| PT0900       | 2803     | NO START                  |           |                                   |  | Total Line Count for System Code 2803 : | 1 | Cause-Reason |
| Work Order # | Line#    | Close Date                | Employee# | Description of Work               |  | OPERATOR COMPLAINT                      |   |              |
| 1821505      | 1        | 10/02/2018                | 756       | NO START-----NEEDS BATTERIES      |  |                                         |   |              |
| PT0900       | 2810     | AIR FILTER REPL           |           |                                   |  | Total Line Count for System Code 2810 : | 1 | Cause-Reason |
| Work Order # | Line#    | Close Date                | Employee# | Description of Work               |  | SCHEDULED SERVICE                       |   |              |
| 1723272      | 6        | 02/22/2018                | 764       | REPLCD AIR FILTER                 |  |                                         |   |              |
| PT0900       | 2815     | ENGINE HOSES REPL         |           |                                   |  | Total Line Count for System Code 2815 : | 1 | Cause-Reason |
| Work Order # | Line#    | Close Date                | Employee# | Description of Work               |  | SCHEDULED SERVICE                       |   |              |
| 1918037      | 9        | 10/29/2019                | 849       | INSTALLED BOTTOM TO ENGINE        |  |                                         |   |              |
| PT0900       | 2817     | ENGINE PULLEYS/TENSIONERS |           |                                   |  | Total Line Count for System Code 2817 : | 2 | Cause-Reason |
| Work Order # | Line#    | Close Date                | Employee# | Description of Work               |  | NORMAL WEAR                             |   |              |
| 1918037      | 8        | 10/29/2019                | 849       | INSTALLED TENSIONER               |  |                                         |   |              |
|              |          |                           |           |                                   |  | SCHEDULED SERVICE                       |   |              |
| 1918037      | 7        | 10/29/2019                | 849       | CONTINUE ASSEMBLY ENGINE          |  |                                         |   |              |
| PT0900       | 2819     | ENGINE SWIT/SENS/THERM RE |           |                                   |  | Total Line Count for System Code 2819 : | 2 | Cause-Reason |
| Work Order # | Line#    | Close Date                | Employee# | Description of Work               |  | NORMAL WEAR                             |   |              |
| 1702913      | 2        | 02/27/2017                | 828       | REPLC PARTICULATE FILTERS SENSORS |  |                                         |   |              |
|              |          |                           |           |                                   |  | OPERATOR COMPLAINT                      |   |              |
| 1506194      | 4        | 05/21/2015                | 819       | R/R FUEL RAIL PRESSURE SENSOR     |  |                                         |   |              |
| PT0900       | 2820     | FUEL FILTERS REPL         |           |                                   |  | Total Line Count for System Code 2820 : | 1 | Cause-Reason |
| Work Order # | Line#    | Close Date                | Employee# | Description of Work               |  | MECHANIC DEFECT                         |   |              |
| 1505748      | 1        | 04/08/2015                | 819       | FUEL FILTERS REPLACED             |  |                                         |   |              |
| PT0900       | 2822     | FUEL LINES REPL           |           |                                   |  | Total Line Count for System Code 2822 : | 1 | Cause-Reason |
| Work Order # | Line#    | Close Date                | Employee# | Description of Work               |  | SCHEDULED SERVICE                       |   |              |
| 1517952      | 3        | 01/05/2016                | 818       | r/r fuel tank                     |  |                                         |   |              |
| PT0900       | 2823     | ENGINE ECM REPL           |           |                                   |  | Total Line Count for System Code 2823 : | 1 | Cause-Reason |
| Work Order # | Line#    | Close Date                | Employee# | Description of Work               |  | SCHEDULED SERVICE                       |   |              |
| 1723272      | 9        | 02/22/2018                | 837       | REMOVE ECM                        |  |                                         |   |              |
| PT0900       | 2833     | PART FILTER ELEMENT CLEAN |           |                                   |  | Total Line Count for System Code 2833 : | 1 | Cause-Reason |
| Work Order # | Line#    | Close Date                | Employee# | Description of Work               |  | OPERATOR COMPLAINT                      |   |              |
| 1506194      | 2        | 05/21/2015                | 756       | REMOVE FILTER/CLEAN-CLEAR CODES   |  |                                         |   |              |
| PT0900       | 2834     | PART FILTER R&R           |           |                                   |  | Total Line Count for System Code 2834 : | 1 | Cause-Reason |
| Work Order # | Line#    | Close Date                | Employee# | Description of Work               |  | OPERATOR COMPLAINT                      |   |              |
| 1617813      | 3        | 12/28/2016                | 819       | PICK UP AT FORD R/R FILTER        |  |                                         |   |              |

**Report Description: Work Order History by Asset and System Code**

WO Close Date Range: 01/26/2010 to 09/26/2021

System Code Range: **1201** to **9700**

Print Date: 1/31/2023

**Asset# Range:** **PT0900** to **PT0900**

| BUS#         | SYS Code | SYS Code Description   |           |                                                                   |                                         |                    |              |
|--------------|----------|------------------------|-----------|-------------------------------------------------------------------|-----------------------------------------|--------------------|--------------|
| PT0900       | 4000     | TIRES                  |           |                                                                   | Total Line Count for System Code 4000 : | 9                  | Cause-Reason |
| Work Order # | Line#    | Close Date             | Employee# | Description of Work                                               | OPERATOR COMPLAINT                      |                    |              |
| 1201257      | 1        | 01/31/2012             | 753       | TIRES R&R R/F/TIRE                                                | OPERATOR COMPLAINT                      |                    |              |
| 2011525      | 1        | 06/22/2020             | 849       | TIRES -CHECKED LEFT REAR TIRES AND FOUND BOTH WITH NALS -REPAIRED | ONE TIRE THE OTHEI                      | OPERATOR COMPLAINT |              |
| 2105437      | 6        | 03/18/2021             | 822       | ROTATED TIRES                                                     | SCHEDULED SERVICE                       | OPERATOR COMPLAINT |              |
| 1408268      | 1        | 06/17/2014             | 767       | TIRES-REPLC (2) REAR TIRES                                        | SCHEDULED SERVICE                       | OPERATOR COMPLAINT |              |
| 1213871      | 1        | 09/28/2012             | 765       | TIRES - REPLACED FRONT TIRES                                      | OPERATOR COMPLAINT                      | OPERATOR COMPLAINT |              |
| 1304371      | 1        | 04/09/2013             | 752       | TIRES-REPLC ALL BAD TIRES                                         | OPERATOR COMPLAINT                      | OPERATOR COMPLAINT |              |
| 1516065      | 1        | 11/16/2015             | 664       | TOOK VEHICLE TO TIRE SHOP                                         | OPERATOR COMPLAINT                      | OPERATOR COMPLAINT |              |
| 1600761      | 1        | 01/19/2016             | 809       | repair tire                                                       | OPERATOR COMPLAINT                      | OPERATOR COMPLAINT |              |
| 1708956      | 1        | 05/25/2017             | 752       | TIRES---NEEDS ALL NEW 6 TIRES                                     | OPERATOR COMPLAINT                      | OPERATOR COMPLAINT |              |
| PT0900       | 4001     | TIRE REPAIR            |           |                                                                   | Total Line Count for System Code 4001 : | 1                  | Cause-Reason |
| Work Order # | Line#    | Close Date             | Employee# | Description of Work                                               | SUPERVISOR DEFECT                       |                    |              |
| 1611568      | 1        | 08/14/2016             | 809       | TIRE REPAIR                                                       | SUPERVISOR DEFECT                       |                    |              |
| PT0900       | 4011     | L/F TIRE REPLACEMENT   |           |                                                                   | Total Line Count for System Code 4011 : | 2                  | Cause-Reason |
| Work Order # | Line#    | Close Date             | Employee# | Description of Work                                               | SCHEDULED SERVICE                       |                    |              |
| 2020031      | 1        | 10/12/2020             | 764       | L//S TIRE REPALCEMENT -                                           | SCHEDULED SERVICE                       |                    |              |
| 1005104      | 1        | 05/28/2010             | 609       | l/f replacement                                                   | OUTSIDE REPAIR                          |                    |              |
| PT0900       | 4012     | R/F TIRE REPLACEMENT   |           |                                                                   | Total Line Count for System Code 4012 : | 1                  | Cause-Reason |
| Work Order # | Line#    | Close Date             | Employee# | Description of Work                                               | SCHEDULED SERVICE                       |                    |              |
| 1918037      | 2        | 10/29/2019             | 849       | REPALCED R/F TIRE                                                 | SCHEDULED SERVICE                       |                    |              |
| PT0900       | 4014     | L/R/I TIRE REPLACEMENT |           |                                                                   | Total Line Count for System Code 4014 : | 1                  | Cause-Reason |
| Work Order # | Line#    | Close Date             | Employee# | Description of Work                                               | OPERATOR COMPLAINT                      |                    |              |
| 2018415      | 2        | 10/05/2020             | 849       | REPLCD LRI TIRE                                                   | OPERATOR COMPLAINT                      |                    |              |

**Report Description: Work Order History by Asset and System Code**

WO Close Date Range: 01/26/2010 to 09/26/2021

System Code Range: **1201** to **9700**

Print Date: 1/31/2023

**Asset# Range:** **PT0900** to **PT0900**

| <b>BUS#</b>         | <b>SYS Code</b> | <b>SYS Code Description</b>        |                  |                                           |                                                |          |
|---------------------|-----------------|------------------------------------|------------------|-------------------------------------------|------------------------------------------------|----------|
| <b>PT0900</b>       | <b>5002</b>     | <b>RADIOS</b>                      |                  |                                           | <b>Total Line Count for System Code 5002 :</b> | <b>4</b> |
| <u>Work Order #</u> | <u>Line#</u>    | <u>Close Date</u>                  | <u>Employee#</u> | <u>Description of Work</u>                | <u>Cause-Reason</u>                            |          |
| 1905550             | 1               | 03/22/2019                         | 27               | RADIOS                                    | OPERATOR COMPLAINT                             |          |
| 1904934             | 1               | 03/14/2019                         | 29               | RADIOS--PART CHARGE OUT                   | PARTS ONLY                                     |          |
| 1905319             | 1               | 03/20/2019                         | 27               | RADIOS----PART CHARGE OUT                 | SCHEDULED SERVICE                              |          |
| 1826416             | 1               | 12/11/2018                         | 29               | RADIOS----PART CHARGE OUT                 | PARTS ONLY                                     |          |
| <b>PT0900</b>       | <b>5004</b>     | <b>AVL -- Repairs</b>              |                  |                                           | <b>Total Line Count for System Code 5004 :</b> | <b>2</b> |
| <u>Work Order #</u> | <u>Line#</u>    | <u>Close Date</u>                  | <u>Employee#</u> | <u>Description of Work</u>                | <u>Cause-Reason</u>                            |          |
| 1204029             | 1               | 03/28/2012                         | 706              | AVL-REPAIRS                               | OPERATOR COMPLAINT                             |          |
| 1906904             | 1               | 04/16/2019                         | 29               | AVL----- REPAIRS---PART CHARGE OUT        | PARTS ONLY                                     |          |
| <b>PT0900</b>       | <b>8010</b>     | <b>TRAVEL TIME - Road Call</b>     |                  |                                           | <b>Total Line Count for System Code 8010 :</b> | <b>1</b> |
| <u>Work Order #</u> | <u>Line#</u>    | <u>Close Date</u>                  | <u>Employee#</u> | <u>Description of Work</u>                | <u>Cause-Reason</u>                            |          |
| 1617813             | 1               | 12/28/2016                         | 819              | TRAVEL TIME ROAD CALL -TOWED BACK TO SHOP | MAJOR MECHANICAL BREAKDOWN                     |          |
| <b>PT0900</b>       | <b>8011</b>     | <b>TROUBLESHOOT ROAD CALL</b>      |                  |                                           | <b>Total Line Count for System Code 8011 :</b> | <b>1</b> |
| <u>Work Order #</u> | <u>Line#</u>    | <u>Close Date</u>                  | <u>Employee#</u> | <u>Description of Work</u>                | <u>Cause-Reason</u>                            |          |
| 1617813             | 2               | 12/28/2016                         | 819              | T/S ROAD CALL CONFIRMED NO START          | OPERATOR COMPLAINT                             |          |
| <b>PT0900</b>       | <b>8015</b>     | <b>Travel Time - Parts Pick-Up</b> |                  |                                           | <b>Total Line Count for System Code 8015 :</b> | <b>1</b> |
| <u>Work Order #</u> | <u>Line#</u>    | <u>Close Date</u>                  | <u>Employee#</u> | <u>Description of Work</u>                | <u>Cause-Reason</u>                            |          |
| 1723272             | 2               | 02/22/2018                         | 841              | PICKED UP PARTS @ DEALERSHIP              | SCHEDULED SERVICE                              |          |
| <b>PT0900</b>       | <b>8020</b>     | <b>MISCELLANEOUS Travel Time</b>   |                  |                                           | <b>Total Line Count for System Code 8020 :</b> | <b>4</b> |
| <u>Work Order #</u> | <u>Line#</u>    | <u>Close Date</u>                  | <u>Employee#</u> | <u>Description of Work</u>                | <u>Cause-Reason</u>                            |          |
| 1000836             | 4               | 02/01/2010                         | 780              | travel time                               | TRANSPORT                                      |          |
| 1000836             | 4               | 02/01/2010                         | 780              | travel time                               | TRANSPORT                                      |          |
| 1000836             | 2               | 02/01/2010                         | 780              | travel time                               | TRANSPORT                                      |          |
| 1000836             | 2               | 02/01/2010                         | 780              | travel time                               | TRANSPORT                                      |          |
| <b>PT0900</b>       | <b>8060</b>     | <b>DRIVE TO DEALER</b>             |                  |                                           | <b>Total Line Count for System Code 8060 :</b> | <b>1</b> |
| <u>Work Order #</u> | <u>Line#</u>    | <u>Close Date</u>                  | <u>Employee#</u> | <u>Description of Work</u>                | <u>Cause-Reason</u>                            |          |
| 1708956             | 2               | 05/25/2017                         | 664              | DROVE TRUCK TO TIRE SHOP FOR TIRES        | OPERATOR COMPLAINT                             |          |

**Report Description: Work Order History by Asset and System Code**

WO Close Date Range: 01/26/2010 to 09/26/2021

System Code Range: **1201** to **9700**

Print Date: 1/31/2023

**Asset# Range:** **PT0900** to **PT0900**

| <u>BUS#</u>         | <u>SYS Code</u> | <u>SYS Code Description</u> |                                                |                                 |                     |          |
|---------------------|-----------------|-----------------------------|------------------------------------------------|---------------------------------|---------------------|----------|
| <b>PT0900</b>       | <b>9103</b>     | <b>4,000 MILE PM CARS</b>   | <b>Total Line Count for System Code 9103 :</b> |                                 |                     | <b>3</b> |
| <u>Work Order #</u> | <u>Line#</u>    | <u>Close Date</u>           | <u>Employee#</u>                               | <u>Description of Work</u>      | <u>Cause-Reason</u> |          |
| 1000873             | 1               | 02/03/2010                  | 752                                            | completed 4k pm                 | SCHEDULED SERVICE   |          |
| 1309843             | 1               | 08/16/2013                  | 767                                            | 4K PM - COMPLETED               | SCHEDULED SERVICE   |          |
| 1918037             | 1               | 10/29/2019                  | 849                                            | 4.000 MILE PM CARS              | SCHEDULED SERVICE   |          |
| <b>PT0900</b>       | <b>9108</b>     | <b>8,000 MILE PM CARS</b>   | <b>Total Line Count for System Code 9108 :</b> |                                 |                     | <b>3</b> |
| <u>Work Order #</u> | <u>Line#</u>    | <u>Close Date</u>           | <u>Employee#</u>                               | <u>Description of Work</u>      | <u>Cause-Reason</u> |          |
| 2105437             | 1               | 03/18/2021                  | 822                                            | 8K MILE PM CARS----COMPLETED    | SCHEDULED SERVICE   |          |
| 1405137             | 1               | 04/15/2014                  | 767                                            | 8K MILE PM CARS-COMPLETED       | SCHEDULED SERVICE   |          |
| 1007410             | 1               | 08/09/2010                  | 752                                            | 8.000 mile pm cars              | SCHEDULED SERVICE   |          |
| <b>PT0900</b>       | <b>9112</b>     | <b>12,000 MILE PM CARS</b>  | <b>Total Line Count for System Code 9112 :</b> |                                 |                     | <b>2</b> |
| <u>Work Order #</u> | <u>Line#</u>    | <u>Close Date</u>           | <u>Employee#</u>                               | <u>Description of Work</u>      | <u>Cause-Reason</u> |          |
| 1102576             | 1               | 03/23/2011                  | 752                                            | 12K MILE PM CARS                | SCHEDULED SERVICE   |          |
| 1415751             | 1               | 10/30/2014                  | 809                                            | 12,000 MILE PM CARS - COMPLETED | SCHEDULED SERVICE   |          |
| <b>PT0900</b>       | <b>9116</b>     | <b>16,000 MILE PM CARS</b>  | <b>Total Line Count for System Code 9116 :</b> |                                 |                     | <b>2</b> |
| <u>Work Order #</u> | <u>Line#</u>    | <u>Close Date</u>           | <u>Employee#</u>                               | <u>Description of Work</u>      | <u>Cause-Reason</u> |          |
| 1508505             | 1               | 06/11/2015                  | 818                                            | 16K MILE PM CARS                | SCHEDULED SERVICE   |          |
| 1110219             | 1               | 11/28/2011                  | 752                                            | 16K MILE PM CARS - COMPLETED    | SCHEDULED SERVICE   |          |
| <b>PT0900</b>       | <b>9120</b>     | <b>20,000 MILE PM CARS</b>  | <b>Total Line Count for System Code 9120 :</b> |                                 |                     | <b>2</b> |
| <u>Work Order #</u> | <u>Line#</u>    | <u>Close Date</u>           | <u>Employee#</u>                               | <u>Description of Work</u>      | <u>Cause-Reason</u> |          |
| 1214279             | 1               | 10/03/2012                  | 767                                            | 20K MILE PM - CARS - COMPLETED  | SCHEDULED SERVICE   |          |
| 1517952             | 1               | 01/05/2016                  | 828                                            | 20.000 mile pm                  | SCHEDULED SERVICE   |          |
| <b>PT0900</b>       | <b>9124</b>     | <b>24,000 MILE PM CARS</b>  | <b>Total Line Count for System Code 9124 :</b> |                                 |                     | <b>2</b> |
| <u>Work Order #</u> | <u>Line#</u>    | <u>Close Date</u>           | <u>Employee#</u>                               | <u>Description of Work</u>      | <u>Cause-Reason</u> |          |
| 1723272             | 1               | 02/22/2018                  | 841                                            | 24K MILE PM                     | SCHEDULED SERVICE   |          |
| 1307438             | 1               | 06/18/2013                  | 752                                            | 24K PM CARS                     | SCHEDULED SERVICE   |          |

**Report Description: Work Order History by Asset and System Code**

WO Close Date Range: 01/26/2010 to 09/26/2021

System Code Range: **1201** to **9700**

Print Date: 1/31/2023

**Asset# Range:** **PT0900** to **PT0900**

| <b>BUS#</b>         | <b>SYS Code</b> | <b>SYS Code Description</b> |                  |                                                       |                     |           |
|---------------------|-----------------|-----------------------------|------------------|-------------------------------------------------------|---------------------|-----------|
| <b>PT0900</b>       | <b>9700</b>     | <b>TEST RUN/ROAD TEST</b>   |                  | <b>Total Line Count for System Code 9700 :</b>        |                     | <b>14</b> |
| <u>Work Order #</u> | <u>Line#</u>    | <u>Close Date</u>           | <u>Employee#</u> | <u>Description of Work</u>                            | <u>Cause-Reason</u> |           |
| 1918037             | 13              | 10/29/2019                  | 849              | ROAD TEST                                             | SCHEDULED SERVICE   |           |
| 1814358             | 2               | 07/06/2018                  | 797              | RUN ENGINE AND ROAD TEST                              | OPERATOR COMPLAINT  |           |
| 1811514             | 3               | 06/26/2018                  | 837              | ROAD TEST VEHICLE NEDDS TO GO TO DEALER WILL NOT RUN  | OPERATOR COMPLAINT  |           |
| 1811514             | 4               | 06/26/2018                  | 753              | TAKE TO FORD BRAKE DOWN NEED TO TOW TO FORD           | OPERATOR COMPLAINT  |           |
| 1811514             | 4               | 06/26/2018                  | 762              | TAKE TO FORD BRAKE DOWN NEED TO TOW TO FORD           | OPERATOR COMPLAINT  |           |
| 1811514             | 5               | 06/26/2018                  | 764              | PICK UP FROM FORD                                     | OPERATOR COMPLAINT  |           |
| 1723272             | 3               | 02/22/2018                  | 841              | ROAD TEST--LOOSES POWER--ENGINE SURGED--CUTOUT        | SCHEDULED SERVICE   |           |
| 1723272             | 5               | 02/22/2018                  | 828              | LONG ROAD TEST--FOUND NO HESITATION                   | SCHEDULED SERVICE   |           |
| 1722392             | 3               | 12/18/2017                  | 818              | ROAD TEST                                             | OPERATOR COMPLAINT  |           |
| 1508867             | 2               | 06/17/2015                  | 809              | ROAD TEST - OK                                        | OPERATOR COMPLAINT  |           |
| 1506194             | 5               | 05/21/2015                  | 819              | ROAD TEST-STILLNO POWER-NEEDS FURTHER DIAGNOSIS       | OPERATOR COMPLAINT  |           |
| 1506194             | 3               | 05/21/2015                  | 756              | ROAD TEST TO CLEAN FILTER-CODE FOR FUEL RAIL PRESSURE | OPERATOR COMPLAINT  |           |
| 1609145             | 2               | 06/28/2016                  | 818              | DROVE TO CLEAN EXHAUST SYSTEM--                       | OPERATOR COMPLAINT  |           |
| 2123019             | 4               | 09/01/2021                  | 823              | ROAD TEST                                             | OPERATOR COMPLAINT  |           |