

6/29/2023
3:48:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10201569 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Total Hours: 191.55		Labor: 13,212.90	Parts: 15,888.89	Comm: 0.00	Charged: 29101.79	
Work Order: 1608116		Meter: 392		In Date: 08/08/2016 Closed: 08/08/2016		
Problem: 1061 - Pre Delivery Inspection						
Work Completed						
- Pre Delivery Inspection						
Hours: 2.00		Comm: 0.00		Labor: 120.00	Parts: 0.00	Total: 120.00
Work Order: 1608822		Meter: 392		In Date: 08/24/2016 Closed: 08/31/2016		
Problem: install saddle tank						
Work Completed				Parts Issued		Quantity
- Install new saddle tank and pump. Wire in install tool box from old asset				Adapter		1.00
- Shop Supplies				Fuel Filter 300mb-10		1.00
				Fuel Tank 100 Gal		1.00
				Alum Fuel Pump		1.00
				Shop Supplies		1.00
Hours: 9.00		Comm: 0.00		Labor: 540.00	Parts: 1,592.65	Total: 2,132.65
Work Order: 1700600		Meter: 5209		In Date: 01/19/2017 Closed: 01/31/2017		
Problem: P.M. service and trailer connector faults and seal fuel tank fill neck.						
Work Completed				Parts Issued		Quantity
- P.m. Service.				Napa Quart 5w30		7.00
- Replace and rewire corroded trailer connector.				Napagold Oil Filter		1.00
- Reseal transfer tankfiller neck .inspect and service tank.				Washer Fluid Concentr		1.00
- Inspect and service winch.				Used Fire X Refurbished		1.00
- Rotate and balance tires.				Clr Rtv Silcn Sealant		1.00
- R&r brake rotors and wash mud from rotor vanes.clean pads and calipers.				trailer plug		1.00
- Shop Supplies				Napagold Fuel Filter		1.00
				Shop Supplies		1.00
Hours: 10.00		Comm: 0.00		Labor: 600.00	Parts: 70.60	Total: 670.60

Palm Beach County Fleet Management Asset Maintenance History
10201569 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

In Date: 08/17/2017 **Closed:** 08/24/2017

Total: 430.21

6/29/2023
3:48:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10201569 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 1801816 **Meter:** 16343 **In Date:** 02/15/2018 **Closed:** 02/27/2018
Problem: P.M. service.

Work Completed

- P.m. service.
- Inspect and service auxiliary fuel tank and pump.
- Inspect front differential.remove both front axles to clean water and sand.replace missing outer axle seals and hub seals .drain and refill gear lube.test drive.
- Charge battery fully .load test battery .r&r failed battery and test charging system.
- Resurface rear rotors .replace rear parking brake shoes and brake pads .service calipers and replace right rear caliper slide.flush and bleed brake system.
- Balance and rotate all four wheels.nitrofill and reset Tpms.
- Inspect and service winch.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
22" Wiper Blade	2.00
Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
Napa Gear 80w-90 Qt	3.00
Ptex Ultra Grey 3oz	1.00
Battery 65	1.00
Real Brake Pad	1.00
Non-chlor Brake Clnr	3.00
Caliper Plate Asy	1.00
Brake Shoes Park	1.00
Left Axle Seal	2.00
seal	2.00
Link Asm	2.00
B Fluid Dot 3-32oz	1.00
Shop Supplies	1.00

Hours: 17.25

Comm: 0.00

Labor: 1,035.00 Parts: 1,014.73 Total: 2,049.73

6/29/2023
3:48:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10201569 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 1808538 **Meter:** 21206 **In Date:** 08/20/2018 **Closed:** 08/28/2018
Problem: P.M. service and winch will not free spool.

Work Completed

- P.m. service.
- Inspect and service winch . Disassemble winch gears to clean and lube . Retest.
- Rotate and high speed balance all four tires.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Used Fire X Refurbished	1.00
22" Wiper Blade	2.00
Wd40 Spr	1.00
Napagold Air Filter	1.00
Shop Supplies	1.00

Hours: 6.25

Comm: 0.00

Labor: 375.00

Parts: 72.52

Total: 447.52

6/29/2023
3:48:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10201569 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 1902674 **Meter:** 26555 **In Date:** 03/11/2019 **Closed:** 03/28/2019
Problem: P.M. service and check fuel cap on sadle tank .

Work Completed

- P.m. service.
- Check auxilary fuel tank cap and replace . Inspect and service fuel tank .
- Replace four tires and balance . Nitrogen fill all .
- Diagnose front axle seals leaking . Clean mud from axle tubes and replace seals and hub bearings and hub assemblies . Inspect and service front differential . Refill and road test.
- Resurface both front brake rotors and service calipers . Replace brake pads and flush and refill brake fluid. Road test
- Inspect and service winch .
- Perform complete front end alignment and road test.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
22" Wiper Blade	2.00
Cap	1.00
Napagold Fuel Filter	1.00
35x12.5r17 Nitto Grap	4.00
Link Asm	2.00
Non-chlor Brake Clnr	4.00
Ptex Ultra Grey 3oz	1.00
Napa Gear 80w-90 Qt	3.00
Left Axle Out Seal	2.00
Left Axle Seal	2.00
Brake Pad	1.00
Front Inner Diff Seal	2.00
Hub Beringn	2.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 19.50

Comm: 0.00

Labor: 1,306.50 Parts: 4,097.75 Total: 5,404.25

6/29/2023
3:48:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10201569 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 1910073 **Meter:** 31731 **In Date:** 09/30/2019 **Closed:** 10/10/2019
Problem: P.M. Service.Brakes aqual.

Work Completed

Parts Issued

Quantity

- P.m. service.
- Charge battery fully .test battery and charging system . Battery failed load test . R&r defective battery .
- Diagnose brake noise . Service all four calipers and brake pads . Clean debris from all brake surfaces. Road test .
- Rotate and balance all four tires . Nitrofill all.
- Inspect and service winch .
- Inspect and service aux fuel tank .
- Shop Supplies

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Battery 65	1.00
Napagold Fuel Filter	1.00
Shop Supplies	1.00

Hours: 9.25

Comm: 0.00

Labor: 675.25

Parts: 240.22

Total: 915.47

Work Order: 2002998 **Meter:** 36050 **In Date:** 03/25/2020 **Closed:** 03/26/2020
Problem: Right rear tire going flat .

Work Completed

Parts Issued

Quantity

- Repair right rear tire and balance . Nitrofill all.
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 4.00

Total: 77.00

6/29/2023
3:48:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10201569 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2003113 **Meter:** 36050 **In Date:** 03/27/2020 **Closed:** 04/06/2020
Problem: PM Service

Work Completed

- P.m. service.
- Inspect and service auxiliary fuel tank . Replace dry rotted fuel hose .
- Diagnose engine misfire . Perform tune up . Replace all sixteen spark plugs and wire set . . Retest .
- Perform complete airintake decarb and cleaning . Flush injectors .
- Inspect and service transer case .
- Test and replace right side tag light .
- Test and replace both front Tpms sensors . Rotate and balance all four tires . Nitrofill all.
- Inspect and service winch .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
22" Wiper Blade	2.00
Ford Triton Pvc Swc	1.00
Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
3/4" X 12 ' Hardwall UI330&ulc	1.00
Espak Plug Wire	4.00
Espak Plug Wire	4.00
Spark Plug	16.00
Intake Cleaner Kit	1.00
Motor Tune-up 16oz	1.00
oil auto	3.00
Lamp Asy	1.00
Tpms12 Sensor Tire Pr	2.00
Shop Supplies	1.00

Hours: 16.25

Comm: 0.00

Labor: 1,186.25

Parts: 612.40

Total: 1,798.65

6/29/2023
3:48:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10201569 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2009292 **Meter:** 40791 **In Date:** 09/16/2020 **Closed:** 09/28/2020
Problem: P.M. service and right front hub hard to engage .

Work Completed

- P.m. service.
- Diagnose right hub hard to turn . R&r locking hub assembly and clean debris from hub . Retest . Inspect and service front differentail . Due to water intrustion .
- Replace both rear brake rotors , calipers and pads . Flush and bleed brake system . Replace worn parking brake shoes . Road trest .
- Replace missing pintle pin .
- Rotate and balance all four tires . Nitrtofill all.
- Inspect and service winch .
- Inspect and service auxiliary fuel tank .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Px Grey Rtv Silicone	1.00
1qt Syngear Oil 75-90	3.00
Brake Caliper	1.00
Brake Caliper	1.00
Brk Fluid Dot 4-32oz	1.00
Non-chlor Brake Clnr	4.00
Real Brake Pad	1.00
Pintle Pin W/clip	1.00
Napagold Fuel Filter	1.00
Brake Rotor	2.00
Link Asm	1.00
Parking Brake Shoes	1.00
Shop Supplies	1.00

Hours: 14.95

Comm: 0.00

Labor: 1,091.35 Parts: 1,101.27 Total: 2,192.62

6/29/2023
3:48:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10201569 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2102309 **Meter:** 44449 **In Date:** 03/01/2021 **Closed:** 03/15/2021
Problem: P.M. service and right front tire flat . Thank you

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Replace all four tires and balance . Nitro fill all.
- Inspect And Service Auxillary Fuel Tank.
- Complete Front End Alignment And Road Test.
- Diagnose Abs Light On For Code C0034; Pinpoint Test Right Front Wheel Speed Sensor Circuit Not Responding. R&r Faulty Right Front Wheel Speed Sensor And Retest. Road Test To Verify Repair And Clear Code.
- R&r Broken Winch Cable Connector; Inspect And Service Winch.
- Shop Supplies

35x12.50/r17 Tire Countrym/t	4.00
Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napagold Fuel Filter	1.00
Wheel Sensor	1.00
Abs Sensor	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 11.75

Comm: 0.00

Labor: 857.75 Parts: 1,551.69 Total: 2,409.44

Work Order: 2102915 **Meter:** 44450 **In Date:** 03/16/2021 **Closed:** 03/17/2021
Problem: Left front tire going flat .

Work Completed

Parts Issued

Quantity

- Test and replace broken valve stem in left front tire . Nitro fill and reset Tpms .
- Shop Supplies

Tire Pressure Monitoring System Sensor (	1.00
Shop Supplies	1.00

Hours: 0.80

Comm: 0.00

Labor: 58.40 Parts: 7.62 Total: 66.02

6/29/2023
3:48:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10201569 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2108897 **Meter:** 49247 **In Date:** 08/17/2021 **Closed:** 08/30/2021
Problem: PM Service . Check lights and power steering leak .

Work Completed

- Performed P.m. Service & Inspection.
- Performed Tire Rotation Balance On All 4 Wheels, Reset Tpms.
- Performed Service & Inspection On Auxilary Fuel Tank.
- Performed Service & Inspection On Winch.
- Right Rear Brake Light Inop, Check Power And Ground, Power And Ground Was Ok, Bulb Filament Distorted Removed And Replaced.
- Removed Dirt & Debris Then Clean, Removed And Replaced Both Front Brake Pads, Calipers And Rotors, Lubricate Caliper Slides Then Bleed And Flush Entire Brake System, Test Drove Vehicle And Burnish Brakes.
- Front Differential Full With Water Due To Water Intrusion From Broken Vent Tube Hose. Replaced Vent Hose Then Clean And Reseal Unit And Fill To Manufac Specs.
- Shop Supplies

Parts Issued

Quantity

Napa Quart 5w30	8.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
Boxed Miniatures	1.00
Brk Fluid Dot 4-32oz	1.00
Front Brake Pad	1.00
Fuel Line Hose	3.00
Non-chlor Brake Clnr	4.00
Napa Gear 80w-90 Qt	4.00
Brake Rotor	2.00
Brake Caliper	1.00
Brake Caliper	1.00
Caliper Washer	4.00
Shop Supplies	1.00

Hours: 12.75

Comm: 0.00

Labor: 930.75

Parts: 731.75

Total: 1,662.50

6/29/2023
3:48:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10201569 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2201632 **Meter:** 52647 **In Date:** 02/14/2022 **Closed:** 02/28/2022
Problem: PM Service and 4X4 inop .

Work Completed

- Preventive Maint. Service
- rotate and balance all 4 tires nitro fill
- Inspect and service winch .operate to insure proper function lube all moving points
- Inspect and service aux fuel tank . replace fuel filter in auxiliary tank
- over haul front differential including all seals hubs and bearings and ring and pinon . test drive vehicle ensure proper 4x4 function . Reseal and service front differential .
- Shop Supplies

Parts Issued

Quantity

Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
Used Fire X Refurbished	1.00
Napagold Fuel Filter	1.00
Hub Bearin Assy	2.00
Non-chlor Brake Clnr	4.00
Napa Gear 80w-90 Qt	3.00
Px Grey Rtv Silicone	1.00
Front Inner Diff Seal	2.00
Left Axle Out Seal	2.00
Left Axle Seal	2.00
Ring & Pinion Kit	1.00
Link Asm	2.00
Bearing	2.00
Cup	2.00
Shop Supplies	1.00

Hours: 18.65

Comm: 0.00

Labor: 1,361.45 Parts: 2,081.49 Total: 3,442.94

Work Order: 2203468 **Meter:** 53890 **In Date:** 03/30/2022 **Closed:** 03/31/2022
Problem: check eng light is on

Work Completed

- Computer diagnose check engine light P06b6 .perform pin point test . Replace coil # 2 and # 3 for arcing and reprogram Pcm . test drive .
- Shop Supplies

Parts Issued

Quantity

Coil	2.00
Shop Supplies	1.00

Hours: 2.00

Comm: 0.00

Labor: 146.00 Parts: 236.93 Total: 382.93

6/29/2023
3:48:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10201569 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2208000 **Meter:** 57834 **In Date:** 08/02/2022 **Closed:** 08/18/2022
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Remove and replace rear pads ,cut rotors, flush and bleed brake system and service calipers . test drive after completion
- rotate and balance all 4 tires nitro fill all
- rebuild front diff after excessive diff pinion play was found test drive after completion
- operate winch and ensure proper function lube all moving parts
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Brk Fluid Dot 4-32oz	1.00
Non-chlor Brake Clnr	1.00
Brake Pad Set	1.00
Qt/75w90	3.00
Px Grey Rtv Silicone	1.00
Non-chlor Brake Clnr	4.00
Spacer	1.00
Seal	1.00
Cone	1.00
Cup	1.00
Cone And	1.00
Cup	1.00
Front Inner Diff Seal	2.00
Silinger	1.00
Nut Lock	1.00
Link Asm	2.00
Napa Oil Seal	2.00
Shop Supplies	1.00

Hours: 17.95

Comm: 0.00

Labor: 1,310.35

Parts: 791.92

Total: 2,102.27

6/29/2023
3:48:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10201569 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2211358 **Meter:** 60700 **In Date:** 11/04/2022 **Closed:** 11/08/2022
Problem: dead battery

Work Completed

- Battery failed load test, Replace and service cable ends and battery tray.
- Shop Supplies

Hours: 1.00

Comm: 0.00

Parts Issued

	Quantity
Battery	1.00
Shop Supplies	1.00
Labor: 73.00	Parts: 152.81
Total: 225.81	

Work Order: 2211763 **Meter:** 61202 **In Date:** 11/21/2022 **Closed:** 11/23/2022
Problem: REAR DRIVER SIDE BREAK LIGHT NEEDS REPLACED

Work Completed

- Test and replace left brake light bulb . Retest

Hours: 0.50

Comm: 0.00

Parts Issued

	Quantity
Boxed Miniatures	1.00
Labor: 36.50	Parts: 1.61
Total: 38.11	

Work Order: 2300450 **Meter:** 62764 **In Date:** 01/17/2023 **Closed:** 01/26/2023
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Mount And Balance Four Tires. Relearn Tire Sensors.
- Inspect And Service Auxillary Fuel System.
- Replace Broken Pintle Pin.
- Replace Broken Brake Master Cylinder Reservoir Cap, Bleed Brakes And Road Test To Verify Repair.
- Complete Frontend Alignment And Road Test To Verify Repair.
- Inspect And Service Power Winch.
- Inspect Excessive Steering Wheel Play, Found Steering Gear Nut Came Loose. R&i Sector Shaft Arm To Inspect Gearbox Splines, Clean Threads And Retorqued Steering Gear Nut. Verified Repair Complete.
- Shop Supplies

Hours: 10.95

Comm: 0.00

Parts Issued

	Quantity
Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Steering Wheel Cover Large	1.00
Napagold Fuel Filter	1.00
Pintle Pin W/clip	1.00
35x12.50/r17 Tire Countrym/t	4.00
Cap Brake Master	1.00
Brake Master Cap	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00
Labor: 799.35	Parts: 1,184.81
Total: 1,984.16	

6/29/2023
3:48:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10201569 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2301653 **Meter:** 63410 **In Date:** 02/21/2023 **Closed:** 02/24/2023
Problem: The truck is making engine noise. Pump bearings are shot.

Work Completed

Parts Issued

Quantity

- Diagnose noise, idler pulley bearing bad, replace idlers, Tensioner and belt. Remove debris from between radiator and coolers.
- Shop Supplies

V Belt	1.00
Tensioner	1.00
Pulley	2.00
Shop Supplies	1.00

Hours: 2.00 Comm: 0.00

Labor: 146.00 Parts: 256.95 Total: 402.95

Work Order: 2306028 **Meter:** 67337 **In Date:** 06/16/2023 **Closed:** 06/16/2023
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00

Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 191.55 Total Labor: 13,212.90 Total Comm: 0.00 Total Parts: 15,888.89