

6/29/2023
3:59:09 PM

Palm Beach County Fleet Management Asset Maintenance History
10198324 2015 FORD F350 Utility Body, 14,000 Gvwr

Total Hours: 159.00	Labor: 10,845.50	Parts: 9,044.45	Comm: 7,886.99	Charged: 27776.93
----------------------------	-------------------------	------------------------	-----------------------	--------------------------

Work Order: 1508753	Meter: 337	In Date: 09/01/2015	Closed: 09/01/2015
Problem: 1061 - Pre Delivery Inspection			

Work Completed

- Pre Delivery Inspection

Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 0.00	Total: 180.00
-------------	------------	---------------	-------------	---------------

Work Order: 1601656	Meter: 3399	In Date: 02/17/2016	Closed: 02/29/2016
Problem: Pm service.Noise in rear around turns.			

Work Completed

- Pm service.

- Rotate and balance all six tires.

- Transport vehicle to and from dealer for rear end noise.

- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
-----------------	------

Napagold Oil Filter	1.00
---------------------	------

Washer Fluid Concentr	1.00
-----------------------	------

Wd40 16oz	1.00
-----------	------

Shop Supplies	1.00
---------------	------

Hours: 7.50	Comm: 0.00	Labor: 450.00	Parts: 30.64	Total: 480.64
-------------	------------	---------------	--------------	---------------

Work Order: 1606406	Meter: 6223	In Date: 05/02/2016	Closed: 06/23/2016
Problem: Damage to right front fender, front bumper, right mirror, right side of bed, right front light &			

Work Completed

- Damage to right front fender, front bumper, right mirror, right side of bed,
right front light &

Hours: 0.00	Comm: 7,886.99	Labor: 0.00	Parts: 0.00	Total: 7,886.99
-------------	----------------	-------------	-------------	-----------------

6/29/2023
3:59:09 PM

Palm Beach County Fleet Management Asset Maintenance History
10198324 2015 FORD F350 Utility Body, 14,000 Gvwr

Work Order: 1609031 **Meter:** 7712 **In Date:** 08/31/2016 **Closed:** 09/21/2016
Problem: P.M. Service.

Work Completed

- P.m. Service.
- Diagnose and repair rear camera and rear strobe light wiring.
- Rotate and balance all six tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Stg Wheel Cov - Ford	1.00
Used Fire X Refurbished	1.00
Pintle Pin W/clip	1.00
Vinyl Electrical Tape	1.00
Shop Supplies	1.00

Hours: 7.50

Comm: 0.00

Labor: 450.00 Parts: 57.23 Total: 507.23

Work Order: 1701501 **Meter:** 13543 **In Date:** 02/13/2017 **Closed:** 02/23/2017
Problem: P.M. service.

Work Completed

- P.m. Service.
- Replace right tail marker lamp.
- Rotate and balance all six tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Led Sup Mdl 44 42 Dio	1.00
Shop Supplies	1.00

Hours: 6.00

Comm: 0.00

Labor: 360.00 Parts: 98.62 Total: 458.62

Work Order: 1703235 **Meter:** 14854 **In Date:** 03/31/2017 **Closed:** 04/12/2017
Problem: Had to jump start in A/ M.

Work Completed

- Recharge batteryand test charging system.battery failed load test.replace defective battery.
- Shop Supplies

Parts Issued

Quantity

Battery 65	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 60.00 Parts: 149.99 Total: 209.99

6/29/2023
3:59:09 PM

Palm Beach County Fleet Management Asset Maintenance History
10198324 2015 FORD F350 Utility Body, 14,000 Gvwr

Work Order: 1706862 **Meter:** 18258 **In Date:** 07/13/2017 **Closed:** 07/31/2017
Problem: P.M. Service.

Work Completed

- P.m. service.
- Left rear tail lamp failed R&r with new.
- Replace two front tires.nitrogen fill.high speed balance all six tires.
- Complete front end alignment.right side camber and caster off.replace camber caster bushing with new.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
22" Wiper Blade	2.00
Led Sup Mdl 44 42 Dio	1.00
179636492 Lt245-75r17	2.00
Caster-camber Bushing	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 10.50

Comm: 0.00

Labor: 630.00	Parts: 656.58	Total: 1,286.58
---------------	---------------	-----------------

Work Order: 1800996 **Meter:** 22464 **In Date:** 01/26/2018 **Closed:** 02/05/2018
Problem: P.M. service.

Work Completed

- P.m. service.
- Rotated and balanced all six tires.nitrogen filled all tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
22" Wiper Blade	2.00
Shop Supplies	1.00

Hours: 5.50

Comm: 0.00

Labor: 330.00	Parts: 36.49	Total: 366.49
---------------	--------------	---------------

6/29/2023
3:59:09 PM

Palm Beach County Fleet Management Asset Maintenance History
10198324 2015 FORD F350 Utility Body, 14,000 Gvwr

Work Order: 1807204 **Meter:** 26624 **In Date:** 07/16/2018 **Closed:** 07/19/2018
Problem: P.M. service.

Work Completed

- P.m. service.
- Replace four tires and high speed balance all six . Nitrogen fill tires.
- Complete front end alignment . Road test.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
179636492 Lt245-75r17	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 9.50

Comm: 0.00

Labor: 570.00 Parts: 926.82 Total: 1,496.82

Work Order: 1812596 **Meter:** 31506 **In Date:** 12/11/2018 **Closed:** 12/20/2018
Problem: P.M. service.

Work Completed

- P.m. service.
- Test and replace defective right brake light assembly .
- Resurface both front brake rotors . Replace brake pads and service calipers . Flush and bleed brake system . Road test.
- Repair right rear tire . Rotate and balance all six tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	7.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Led Sup Mdl 44 42 Dio	1.00
Non-chlor Brake Clnr	1.00
B Fluid Dot 3-32oz	1.00
Brake Pad Motorcraft	1.00
Shop Supplies	1.00

Hours: 12.00

Comm: 0.00

Labor: 804.00 Parts: 218.51 Total: 1,022.51

6/29/2023
3:59:09 PM

Palm Beach County Fleet Management Asset Maintenance History
10198324 2015 FORD F350 Utility Body, 14,000 Gvwr

Work Order: 1905775 **Meter:** 36363 **In Date:** 05/31/2019 **Closed:** 06/10/2019
Problem: P.M. service.

Work Completed

- P.m. service.
- Rotate and high speed balance all six tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Napagold Air Filter	1.00
Shop Supplies	1.00

Hours: 5.50

Comm: 0.00

Labor: 368.50 Parts: 56.81 Total: 425.31

Work Order: 1911580 **Meter:** 41650 **In Date:** 11/07/2019 **Closed:** 11/14/2019
Problem: P.M. service and tailgate hard to open .

Work Completed

- P.m. service.
- Replace all six tires and balance . Nitrofill all.
- Computer diagnose misfire . Replace all sixteen spark plugs ,wire set and number five and six coils . Clear codes and retest .
- Perform complete air intake decarb and cleaning . Flush injectors .
- Replace missing pintle pin .
- Test and replace right brake light bulb .
- Test tailgate . Unbend bent metal near handle . Lube and retest .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Lt245/75r17 Mich Defend Ltx	6.00
Dielect Silicone Comp	1.00
Spark Plug	16.00
Motor Tune-up 16oz	1.00
Intake Cleaner Kit	1.00
Pintle Pin W/clip	1.00
Led Sup Mdl 44 42 Dio	1.00
Al3z12029b	2.00
Espak Plug Wire	4.00
Espak Plug Wire	4.00
Shop Supplies	1.00
Tire Disposal Fee	6.00

Hours: 16.70

Comm: 0.00

Labor: 1,219.10 Parts: 2,166.21 Total: 3,385.31

6/29/2023
3:59:09 PM

Palm Beach County Fleet Management Asset Maintenance History
10198324 2015 FORD F350 Utility Body, 14,000 Gvwr

Work Order: 2002671 **Meter:** 45572 **In Date:** 03/16/2020 **Closed:** 03/23/2020
Problem: Check engine light on , runs rough and A/C blows warm ./

Work Completed

Parts Issued

Quantity

- Computer diagnose check engine light , P0352 . Perform pinpoint test .
R&r defective Pcm module . Pmi module with Ids . Clear code and reset
parameters and misfire monitor neutral setting . Test drive .

Pcm Module	1.00
Shop Supplies	1.00

- Shop Supplies

Hours: 2.50 Comm: 0.00 Labor: 182.50 Parts: 959.55 Total: 1,142.05

Work Order: 2004763 **Meter:** 47080 **In Date:** 05/12/2020 **Closed:** 05/26/2020
Problem: P.M. service.

Work Completed

Parts Issued

Quantity

- P.m. service.
- Charge battery fully . Test battery and charging system . Battery failed load
test . R&r defective battery .

Napagold Oil Filter	1.00
5w20 Engine Oil	8.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
Battery 65	1.00
Reflex Truck Shock	2.00
Shop Supplies	1.00

- R&r both leaking front shocks .

- Repair left front tire . Rotate and balance all six tires . Nitrofill all.

- Shop Supplies

Hours: 8.30 Comm: 0.00 Labor: 605.90 Parts: 383.38 Total: 989.28

Work Order: 2012051 **Meter:** 51369 **In Date:** 12/03/2020 **Closed:** 12/14/2020
Problem: This truck is coming in for PM Service. The gate latch is not working right. It does not release when the handle is pull

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Remove and readjust tailgate.
- Found Rf inner tie rod to have excessive play. R and R bad tie rod
- Rotated and balanced all 6 tires. Nitrogen filled all tires.
- Performed full front end alignment. Road test .
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	8.00
Steering Wheel Cover Large	1.00
22" Wiper Blade	2.00
Tie Rod Inner	1.00
Shop Supplies	1.00

Hours: 10.00 Comm: 0.00 Labor: 730.00 Parts: 204.01 Total: 934.01

6/29/2023
3:59:09 PM

Palm Beach County Fleet Management Asset Maintenance History
10198324 2015 FORD F350 Utility Body, 14,000 Gvwr

Work Order: 2106672 **Meter:** 55488 **In Date:** 06/18/2021 **Closed:** 06/29/2021
Problem: PM Service.Also has an issue with the bulbs on the passenger rear brake light.

Work Completed

- Preventive Maint. Service
- Resurface Front And Rear Rotors, R&r Both Front Calipers, Brake Pads All Around, Bleed And Flush Brake System. Road Test To Burnish Brakes.
- R&r Faulty Right Rear Led Stop Lamp.
- Rotate And Balance Six Tires. Nitro fill all.
- Back Up Camera Was Inop; Repaired Gound Wire In Camera Harness And Retest Ok.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Windshield Washer	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Front Brake Pad	1.00
Front Brake Pad Duty	1.00
Brk Fluid Dot 4-32oz	1.00
Reman/ca	1.00
Reman/ca	1.00
Led Sup Mdl 44 42 Dio	1.00
Shop Supplies	1.00

Hours: 17.00

Comm: 0.00

Labor: 1,241.00 Parts: 607.32 Total: 1,848.32

Work Order: 2111962 **Meter:** 58560 **In Date:** 11/05/2021 **Closed:** 11/15/2021
Problem: Need a spare key for this vehicle. Current key is locked in vehicle, so they were hoping to pick up spare today.

Work Completed

- Make Duplicate Keys
- Shop Supplies

Parts Issued

Quantity

Ford Ignition Key Blank	1.00
Shop Supplies	1.00

Hours: 0.50

Comm: 0.00

Labor: 36.50 Parts: 21.98 Total: 58.48

6/29/2023
3:59:10 PM

Palm Beach County Fleet Management Asset Maintenance History
10198324 2015 FORD F350 Utility Body, 14,000 Gvwr

Work Order: 2200777 **Meter:** 60191 **In Date:** 01/24/2022 **Closed:** 01/27/2022
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Inspect For Ignition Coil Arching; Found Cylinder One Right Side Ignition Coil Arching. R&r Faulty Ignition Coil, Recheck And Ok At This Time.
- Rotate And Balance Six Tires. Nitro Fill All .
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Wd40 Spr	1.00
Napagold Air Filter	1.00
Coil	1.00
Shop Supplies	1.00

Hours: 7.50

Comm: 0.00

Labor: 547.50 Parts: 162.67 Total: 710.17

Work Order: 2207614 **Meter:** 63611 **In Date:** 07/21/2022 **Closed:** 08/08/2022
Problem: PM Service Needs a tire plugged or replaced

Work Completed

- Performed P.m. Service & Inspection.
- Mount & Balance 6 New Tires, Reset Tpms.
- Performed Front Wheel Alignment, Removed & Install Camber Kit On Both Front Wheels.
- Right Rear Tail Lamp Inop, Check Power & Ground. Signal B + And Ground Ok. Led Light Defective Removed Then Replaced.
- Trailer Plug Corroded And Inop. Removed Then Rewire & Replaced.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Led Sup Mdl 44 42 Dio	1.00
trailer plug	1.00
Lt245/75r17 Mich Defend Ltx	6.00
Caster-camber Bushing	2.00
Caster-camber Bushing	2.00
Shop Supplies	1.00
Tire Disposal Fee	6.00

Hours: 13.00

Comm: 0.00

Labor: 949.00 Parts: 1,619.22 Total: 2,568.22

6/29/2023
3:59:10 PM

Palm Beach County Fleet Management Asset Maintenance History
10198324 2015 FORD F350 Utility Body, 14,000 Gvwr

Work Order: 2300761 **Meter:** 67048 **In Date:** 01/25/2023 **Closed:** 02/02/2023
Problem: PM Service. Check wipers and tires please.

Work Completed

- Preventive Maint. Service completed
- balance and rotate all 6 tires and nitro fill all.
- check,replaced defective trailer plug and fabricated wire as needed
- check battery,charging system after fully charge it fails load test,replaced defective battery
- check,sop and replaced all 6 body mounts
- Shop Supplies

Parts Issued

Quantity

Drain Plug	1.00
Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
trailer plug	1.00
Battery	1.00
Body Mount Kit	4.00
Body Mount Kit	2.00
Shop Supplies	1.00

Hours: 13.50 Comm: 0.00

Labor: 985.50 Parts: 688.47 Total: 1,673.97

Work Order: 2305289 **Meter:** 69538 **In Date:** 05/26/2023 **Closed:** 05/26/2023
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00

Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 159.00

Total Labor: 10,845.50

Total Comm: 7,886.99

Total Parts: 9,044.45