

6/29/2023
4:02:58 PM

Palm Beach County Fleet Management Asset Maintenance History
10198057 2015 TORO GRNDSMSTR 4000D Mower, 11 Ft, Riding

Total Hours: 126.00	Labor: 8,623.00	Parts: 15,024.63	Comm: 0.00	Charged: 23647.63
----------------------------	------------------------	-------------------------	-------------------	--------------------------

Work Order: 1500310	Meter: 1	In Date: 01/09/2015	Closed: 01/09/2015
Problem: 1061 - Pre Delivery Inspection			

Work Completed

- Pre Delivery Inspection

Hours: 2.00	Comm: 0.00	Labor: 120.00	Parts: 0.00	Total: 120.00
-------------	------------	---------------	-------------	---------------

Work Order: 1504583	Meter: 27	In Date: 05/05/2015	Closed: 05/11/2015
Problem: hydraulic hose fitting keeps leaking			

Work Completed

- Ck for hydro leak. Hector repair fitting. top off fluid
- Shop Supplies

Hours: 0.50	Comm: 0.00
-------------	------------

Parts Issued

Quantity

Aw68 Hydro Fluid Hydr	6.00	
Aw68 Hydro Fluid Hydr	8.00	
Shop Supplies	1.00	
Labor: 30.00	Parts: 34.97	Total: 64.97

Work Order: 1507324	Meter: 81	In Date: 07/22/2015	Closed: 07/31/2015
Problem: alt belt broke			

Work Completed

- replace alt belt, test run & operate
- Shop Supplies

Hours: 1.00	Comm: 0.00
-------------	------------

Parts Issued

Quantity

V-belt	1.00	
Shop Supplies	1.00	
Freight Charge	1.00	
Labor: 60.00	Parts: 60.55	Total: 120.55

6/29/2023
4:02:58 PM

Palm Beach County Fleet Management Asset Maintenance History
10198057 2015 TORO GRNDSMSTR 4000D Mower, 11 Ft, Riding

Work Order: 1512691 **Meter:** 173 **In Date:** 12/16/2015 **Closed:** 12/30/2015
Problem: pm service

Work Completed

- Pm
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Air Filter	1.00
Fuel Filter	1.00
Fuel Filter	1.00
Oil Filter	1.00
15-40 Oil	6.00
Shop Supplies	1.00

Hours: 4.00

Comm: 0.00

Labor: 240.00 Parts: 207.02 Total: 447.02

Work Order: 1607929 **Meter:** 187 **In Date:** 08/02/2016 **Closed:** 08/09/2016
Problem: NEEDS NEW FRONT TIRE (TIRE ONLY)

Work Completed

- Replace tire
- Shop Supplies

Parts Issued

Quantity

26x12.00x12 6 Ply Mt	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 1.00

Comm: 0.00

Labor: 60.00 Parts: 208.60 Total: 268.60

6/29/2023
4:02:58 PM

Palm Beach County Fleet Management Asset Maintenance History
10198057 2015 TORO GRNDSMSTR 4000D Mower, 11 Ft, Riding

Work Order: 1613097 **Meter:** 387 **In Date:** 12/28/2016 **Closed:** 01/06/2017
Problem: pm/ sometimes wont start

Work Completed

Parts Issued

Quantity

- Pm
- Hyd Service
- Ck for no Start-had Fault code for Ign switch fault or wiring r&r ign switch and tested-ok ck wiring and r&r starter relays tested Ng Replace starter relay
- Shop Supplies

Napagold Air Filter	1.00
Napagold Air Filter	1.00
Oil Filter	1.00
Fuel Filter	1.00
Fuel Filter	1.00
15-40 Oil	6.00
Hydraulic Filter	1.00
Napa Hydraulic Filtr	1.00
Aw68 Hydro Fluid Hydr	4.00
Relay	1.00
Shop Supplies	1.00

Hours: 9.00

Comm: 0.00

Labor: 540.00 Parts: 291.62 Total: 831.62

Work Order: 1703082 **Meter:** 387 **In Date:** 03/28/2017 **Closed:** 04/13/2017
Problem: no start

Work Completed

Parts Issued

Quantity

- Diag no start, r/r shorted battery
- Commercial replacement of instrument cluster
- Shop Supplies

Com Rplmt Of Ins Disp	1.00
Battery	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 60.00 Parts: 1,090.42 Total: 1,150.42

Work Order: 1703826 **Meter:** 417 **In Date:** 04/14/2017 **Closed:** 04/19/2017
Problem: left wing hydraulic hose blew

Work Completed

Parts Issued

Quantity

- Find Hydro leak-replace hydro high pressure hose and replace o'ring top off hydro fluid and test
- Shop Supplies

Hose Made	1.00
Aw68 Hydro Fluid Hydr	15.00
Shop Supplies	1.00

Hours: 1.50

Comm: 0.00

Labor: 90.00 Parts: 192.05 Total: 282.05

6/29/2023
4:02:58 PM

Palm Beach County Fleet Management Asset Maintenance History
10198057 2015 TORO GRNDSMSTR 4000D Mower, 11 Ft, Riding

Work Order: 1707159 **Meter:** 467 **In Date:** 07/21/2017 **Closed:** 08/08/2017
Problem: pm service, pto not working

Work Completed

- Pm
- Diag check engine lights, r/r pressure sensor
- R/r bearing in 5 caster wheels
- R/r pto switch
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Air Filter	1.00
Oil Filter	1.00
Fuel Filter	1.00
15-40 Oil	6.00
Fuel Filter	1.00
Bearing	10.00
Pto Switch	1.00
Pressure Sensor	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 8.50

Comm: 0.00

Labor: 510.00

Parts: 1,306.21

Total: 1,816.21

Work Order: 1711913 **Meter:** 467 **In Date:** 12/05/2017 **Closed:** 12/19/2017
Problem: need tire, tire only

Work Completed

- Replace Tire
- Shop Supplies

Parts Issued

Quantity

26x12.00x12 6 Ply Mt	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 1.00

Comm: 0.00

Labor: 60.00

Parts: 220.15

Total: 280.15

Work Order: 1712330 **Meter:** 537 **In Date:** 12/14/2017 **Closed:** 12/27/2017
Problem: needs lug nuts (nuts only)

Work Completed

- Secur parts for dept

Parts Issued

Quantity

Lug Nut	4.00
---------	------

Hours: 0.50

Comm: 0.00

Labor: 30.00

Parts: 7.50

Total: 37.50

6/29/2023
4:02:58 PM

Palm Beach County Fleet Management Asset Maintenance History
10198057 2015 TORO GRNDSMSTR 4000D Mower, 11 Ft, Riding

Work Order: 1808091 **Meter:** 634 **In Date:** 08/07/2018 **Closed:** 08/20/2018
Problem: pm service

Work Completed

- pm service
- replace upper and lower hoses, belt and flush cooling system
- hydraulic service
- Shop Supplies

Parts Issued

Quantity

Fuel Filter	1.00
Fuel Filter	1.00
Pm-22-a Additive Dies	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
15-40 Oil	6.00
Oil Filter	1.00
Non-chlor Brake Clnr	1.00
Napa Antifreeze Gal	2.00
Aw68 Hydro Fluid Hydr	12.00
Napa Hydraulic Filtr	1.00
Napagold Oil Filter	1.00
Upper Radiator Hose	1.00
Lower Radiator Hose	1.00
V-belt	1.00
Hydraulic Filter	1.00
Shop Supplies	1.00

Hours: 8.00

Comm: 0.00

Labor: 480.00 Parts: 469.22 Total: 949.22

6/29/2023
4:02:58 PM

Palm Beach County Fleet Management Asset Maintenance History
10198057 2015 TORO GRNDSMSTR 4000D Mower, 11 Ft, Riding

Work Order: 1812305 **Meter:** 704 **In Date:** 12/03/2018 **Closed:** 01/11/2019
Problem: RF blade vibrates/ F Lift arm bushings/ RF belt cover bolt stripped/ grease

Work Completed

- replace tensioners , belts and bushings on deck
- replace both front lift arm ball joints
- repair left rear tire
- Shop Supplies

Parts Issued

Quantity

Deck Belt	2.00
Bushing	4.00
Nut	2.00
Ball Joint Lh	2.00
Pulley	2.00
Driving Spindle Asm	1.00
Seal	2.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 5.00

Comm: 0.00

Labor: 335.00	Parts: 1,500.44	Total: 1,835.44
---------------	-----------------	-----------------

Work Order: 1908854 **Meter:** 816 **In Date:** 08/23/2019 **Closed:** 08/28/2019
Problem: pm service, check deck bolts, some stripped

Work Completed

- Pm Service
- Hydraulic service
- Replace 2 rear tires
- Repl. multiple grommets for belt cover fasteners
- Perform manual regen.
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	6.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Napa Fuel Filter	1.00
Fuel Filter	1.00
Non-chlor Brake Clnr	4.00
Aw68 Hydro Fluid Hydr	10.00
Napa Hydraulic Filtr	1.00
Hydraulic Filter	1.00
20x10.00x10 Multi Trac	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 8.50

Comm: 0.00

Labor: 569.50	Parts: 510.28	Total: 1,079.78
---------------	---------------	-----------------

6/29/2023
4:02:58 PM

Palm Beach County Fleet Management Asset Maintenance History
10198057 2015 TORO GRNDSMSTR 4000D Mower, 11 Ft, Riding

Work Order: 1913115 **Meter:** 874 **In Date:** 12/27/2019 **Closed:** 01/09/2020
Problem: needs 6 small solid deck wheels

Work Completed

- replace all 8 caster wheels. adjust other tire pressure
- Shop Supplies

Hours: 2.50

Comm: 0.00

Parts Issued

	Quantity
Caster Wheel	8.00

Shop Supplies	1.00
---------------	------

Labor: 182.50	Parts: 1,738.00	Total: 1,920.50
---------------	-----------------	-----------------

Work Order: 2007024 **Meter:** 874 **In Date:** 07/20/2020 **Closed:** 07/22/2020
Problem: needs new battery

Work Completed

- secure battery for dept
- Shop Supplies

Hours: 0.50

Comm: 0.00

Parts Issued

	Quantity
Battery	1.00

Shop Supplies	1.00
---------------	------

Labor: 36.50	Parts: 129.04	Total: 165.54
--------------	---------------	---------------

6/29/2023
4:02:58 PM

Palm Beach County Fleet Management Asset Maintenance History
10198057 2015 TORO GRNDSMSTR 4000D Mower, 11 Ft, Riding

Work Order: 2007477 **Meter:** 1014 **In Date:** 07/30/2020 **Closed:** 10/08/2020
Problem: pm/ hydraulic leak

Work Completed

- pm service
- found bad hydraulic line, replace & another from pum rep;ace & test
- found codes replace dpf sensor
- founded rusted out seat, replace & install panel back in place
- no start, adj pedal
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Air Filter	1.00
Napagold Oil Filter	1.00
Fuel Filter	1.00
Napa Fuel Filter	1.00
15-40 Oil	6.00
Hydraulic Filter	1.00
Napa Hydraulic Filtr	1.00
Aw68 Hydro Fluid Hydr	10.00
Hose Clamp	2.00
Pressure Sensor	1.00
Hose	1.00
Front Return Tube	1.00
Hydro Tube Assy	1.00
Seat Assy	1.00
Shop Supplies	1.00
Freight Charge	2.00
Freight Charge	1.00

Hours: 24.00

Comm: 0.00

Labor: 1,752.00

Parts: 3,275.39

Total: 5,027.39

6/29/2023
4:02:58 PM

Palm Beach County Fleet Management Asset Maintenance History
10198057 2015 TORO GRNDSMSTR 4000D Mower, 11 Ft, Riding

Work Order: 2109621 **Meter:** 1014 **In Date:** 09/02/2021 **Closed:** 09/30/2021
Problem: pm/ blades not coming on

Work Completed

- Preventive Maint. Service
- Replace right front tire
- Diagnose pto not working all the time,replace pto switch
- Hydraulic service
- Replace broken rod ends on both swing decks
- Replace 7 blades
- Replace all deck belts
- Wash equipment
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Qt 15w40	6.00
Napa Fuel Filter	1.00
Fuel Filter	1.00
Napagold Air Filter	1.00
Non-chlor Brake Clnr	4.00
26x12.00-12nhs/6 Car Multi-trac	1.00
Pto Switch	1.00
Hyd Filter	1.00
Hydraulic Filter	1.00
Aw68 Hydro Fluid Hydr	6.00
Mower Blade	7.00
Napagold Air Filter	1.00
Deck Belt	4.00
Tube-link	2.00
Rod End	4.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 15.50

Comm: 0.00

Labor: 1,131.50

Parts: 977.55

Total: 2,109.05

Work Order: 2110883 **Meter:** 1102 **In Date:** 10/07/2021 **Closed:** 10/12/2021
Problem: hydraulic leak on the bottom

Work Completed

- Check Hydraulic Leak. Replace Hose For Front Deck
- Wash Mower
- Shop Supplies

Parts Issued

Quantity

Mako Hose	1.00
Aw68 Hydro Fluid Hydr	8.00
Shop Supplies	1.00

Hours: 2.50

Comm: 0.00

Labor: 182.50

Parts: 125.81

Total: 308.31

6/29/2023
4:02:58 PM

Palm Beach County Fleet Management Asset Maintenance History
10198057 2015 TORO GRNDMSTR 4000D Mower, 11 Ft, Riding

Work Order: 2112186 **Meter:** 1214 **In Date:** 11/15/2021 **Closed:** 12/20/2021
Problem: Mowing decks are both striking the sides of the mower when they go in the up position. Need to be adjusted. Thanks

Work Completed

- Replace both swing arm pivot hubs and bumper pads
- Shop Supplies

Parts Issued

Quantity

Bushing Flange	2.00
Rivet	4.00
Pivot Hub Assy	2.00
Flange Bushing	2.00
Rubber Bumper	2.00
Shop Supplies	1.00
Freight Charge	1.00
Freight Charge	1.00

Hours: 3.00

Comm: 0.00

Labor: 219.00

Parts: 426.91

Total: 645.91

Work Order: 2203059 **Meter:** 1252 **In Date:** 03/21/2022 **Closed:** 03/22/2022
Problem: Mower won't move and decks get frozen in position frequently.

Work Completed

- Ck Mower Wont Go In Forward Or Reverse, And Decks Inop @ Times. Reconnect Seat Air Suspension, Test Seat Switch And Clean Connectors. Fill Air In Seat & Test Run, Problem Didnt Occur Again
- Perform Regen And Install Missing Bolts For Dpf Pressure Sensor.
- Wash Mower
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 5.50

Comm: 0.00

Labor: 401.50

Parts: 2.65

Total: 404.15

6/29/2023
4:02:58 PM

Palm Beach County Fleet Management Asset Maintenance History
10198057 2015 TORO GRNDSMSTR 4000D Mower, 11 Ft, Riding

Work Order: 2204203 **Meter:** 1265 **In Date:** 04/20/2022 **Closed:** 05/23/2022
Problem: Hydraulic leaks by front deck piston on both sides

Work Completed

- Torch & Cut Off Both Rusted Hydro Cylinders For Front Deck,replace Cylinders,bleed System
- Shop Supplies

Parts Issued

Quantity

Hyd Cylinder	2.00
Pin Clevis	2.00
Mako Hose	1.00
Aw68 Hydro Fluid Hydr	2.00
Non-chlor Brake Clnr	2.00
Shop Supplies	1.00
Freight Charge	1.00
Freight Charge	1.00

Hours: 6.50

Comm: 0.00

Labor: 474.50

Parts: 1,379.89

Total: 1,854.39

Work Order: 2205493 **Meter:** 1268 **In Date:** 05/24/2022 **Closed:** 05/27/2022
Problem: Mower won't move

Work Completed

- Ck Mower Wont Go Forward Or Reverse. Seat Indicator On Panel. Inflate Seat And Test Run Multiple Times.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.50

Comm: 0.00

Labor: 109.50

Parts: 2.65

Total: 112.15

Work Order: 2207277 **Meter:** 1268 **In Date:** 07/12/2022 **Closed:** 07/20/2022
Problem: replace tire - tire only

Work Completed

- replace tire and bent rim
- Shop Supplies

Parts Issued

Quantity

20x10.00x10 Multi Trac Tire	1.00
Rim	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 338.89

Total: 411.89

6/29/2023
4:02:58 PM

Palm Beach County Fleet Management Asset Maintenance History
10198057 2015 TORO GRNDSMSTR 4000D Mower, 11 Ft, Riding

Work Order: 2210650 **Meter:** 1347 **In Date:** 10/18/2022 **Closed:** 12/07/2022
Problem: PM Service. this machine runs then cuts off also

Work Completed

- Preventive Maint. Service
- Perform Regen And Install Missing Bolts For Dpf Pressure Sensor.
- Shop Supplies

Parts Issued

Quantity

Napa Fuel Filter	1.00
Fuel Filter	1.00
Pm-22-a Additive Dies	1.00
Tran Flu Qt Dexron3i	1.00
Napagold Oil Filter	1.00
Napa Qt 15w40	6.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Shop Supplies	1.00

Hours: 5.50

Comm: 0.00

Labor: 401.50 Parts: 132.87 Total: 534.37

Work Order: 2300297 **Meter:** 1347 **In Date:** 01/11/2023 **Closed:** 01/12/2023
Problem: replace tire only

Work Completed

- Replace Wheel And Tire
- Shop Supplies

Parts Issued

Quantity

Caster Wheel	1.00
Shop Supplies	1.00

Hours: 0.50

Comm: 0.00

Labor: 36.50 Parts: 198.37 Total: 234.87

Work Order: 2300342 **Meter:** 1402 **In Date:** 01/11/2023 **Closed:** 01/18/2023
Problem: Hardware needed for right side caster wheels

Work Completed

- Replace Left Side Deck Caster Wheel Brackets, Pins And Tension Rod.
- Steering Tilt Inop. Repair Lock Down Spring And Lube Tilt Lever.
- Shop Supplies

Parts Issued

Quantity

Rod	1.00
Clevis	4.00
Bracket	2.00
Shop Supplies	1.00
Freight Charge	1.00
Freight Charge	1.00

Hours: 3.00

Comm: 0.00

Labor: 219.00 Parts: 194.96 Total: 413.96

6/29/2023
4:02:58 PM

Palm Beach County Fleet Management Asset Maintenance History
10198057 2015 TORO GRNDSMSTR 4000D Mower, 11 Ft, Riding

Work Order: 2305502 **Meter:** 1446 **In Date:** 06/05/2023 **Closed:** 06/07/2023
Problem: right deck pto dont worck

Work Completed

Parts Issued

Quantity

- Diag Right Deck Pto, No Problems Found,
- Shop Supplies

Shop Supplies

1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 2.65

Total: 75.65

Work Order: 2306101 **Meter:** 1446 **In Date:** 06/20/2023 **Closed:** 06/20/2023
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 0.00

Total: 146.00

Total Hours: 126.00

Total Labor: 8,623.00

Total Comm: 0.00

Total Parts: 15,024.63