Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 55421655
Invoice No. 55345 - 55421655

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
QCC FLEET INSPECTION/	RETIRED UNIT	Ford E350 Champion Crusaders	
Requested By:	SPACE	**Status:**	40 - Closed (40)
Created By:	SPACE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	321,941 -

Chronology		
Reported	Jul 13, 2022 12:41:09 PM	Jul 13, 2022 12:41:09 PM
Started		
Completed	Dec 21, 2022 2:36:00 PM	Dec 21, 2022 2:36:00 PM
Down Time		

Work Order Notes

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: QCC FLEET INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55421655 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55827228
Invoice No. 55345 - 55827228

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMB
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 321,535 - DH

Chronology		
Reported	Sep 22, 2022 12:00:00 AM	Sep 22, 2022 12:00:00 AM
Started	Sep 29, 2022 3:59:00 PM	
Completed	Sep 30, 2022 12:23:00 AM	Sep 30, 2022 12:23:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMB

CAUSE:Service

CORRECTION:Perform PMB Service
oil filter B329 qty1
engine oil 10w30 qty u qts
add washer fluid
check inflate tires to spec

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 29-SEP-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Sep 29, 2022 10:39:00 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Sep 29, 2022 10:39:00 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RGASPARD	Sep 29, 2022 10:39:00 PM	No	
7 - Have you performed the proper LOTO?	Done		RGASPARD	Sep 29, 2022 10:39:00 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Sep 29, 2022 10:39:00 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Sep 29, 2022 10:39:00 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55827228
Invoice No. 55345 - 55827228

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMB		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	321,535 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Sep-22	B329	FILTER, OIL, SPIN-ON SEE P550965	1	2.86	2.86

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Sep-22	Gaspard,Ronald	1.33	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 29-SEP-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
20,800 - INSPECT_High Idle Control	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	Sep 29, 2022 11:01:07 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Sep 29, 2022 11:01:07 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
33,010 - CSF (Curb Side Front)	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	RGASPARD	Sep 29, 2022 11:01:07 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		RGASPARD	Sep 29, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression				11:01:07 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
50,400 - LUBE_All Chassis Components	Done	na	RGASPARD	Sep 29, 2022 11:01:07 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	37 Inch		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	37 Inch		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Sep 29, 2022 11:01:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	38 Inch		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	38 Inch		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	11245 Cycles		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper	Done		RGASPARD	Sep 29, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alignment				11:01:07 PM		
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Sep 29, 2022 11:01:07 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	2.86
Labor:	0.00
Labor Hours:	1.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.86**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55827228
Invoice No. 55345 - 55827228

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMB
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 321,535 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Sep-22	Gaspard,Ronald	0.37	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: RGASPARD Performed on: 30-SEP-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Sep 30, 2022 12:01:48 AM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Sep 30, 2022 12:01:48 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Sep 30, 2022 12:01:48 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Sep 30, 2022 12:01:48 AM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Sep 30, 2022 12:01:48 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Sep 30, 2022 12:01:48 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Sep 30, 2022 12:01:48 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Sep 30, 2022 12:01:48 AM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Sep 30, 2022 12:01:48 AM	No	
201,000 - Service Crankcase Breather	Done		RGASPARD	Sep 30, 2022 12:01:48 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Sep 30, 2022 12:01:48 AM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Sep 30, 2022 12:01:48 AM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Sep 30, 2022 12:01:48 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55827228 Total	
Parts:	2.86
Labor:	0.00
Labor Hours:	1.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.86**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55966497
Invoice No. 55345 - 55966497

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
rear tires low specs		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	320,835 - DH

Chronology		
Reported	Sep 20, 2022 10:26:00 AM	Sep 20, 2022 10:26:00 AM
Started	Sep 20, 2022 10:38:00 AM	
Completed	Sep 20, 2022 1:46:00 PM	Sep 20, 2022 1:46:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: all tires below 3 inches

Cause: preventive maintenance

Correction: replace the rear tires whit 4 use one and replace the ftont whit two new spare tire from the new bus torque all to 145 ft pound completed

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 20-SEP-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Sep 20, 2022 1:46:21 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Sep 20, 2022 1:46:21 PM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Sep 20, 2022 1:46:21 PM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Sep 20, 2022 1:46:21 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Sep 20, 2022 1:46:21 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Sep 20, 2022 1:46:21 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55966497
Invoice No. 55345 - 55966497

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
rear tires low specs		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	320,835 - DH

Activity Header
Activity: 15 016 SUSPENSION
Activity Note: PER DRIVER BUS PULLING TO THE SIDE
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Sep-22	Pierre,Hubert J	2.37	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55966497
Invoice No. 55345 - 55966497

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
rear tires low specs		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	320,835 - DH

Activity Header
Activity: 25 017/001/000 TIRE, PNEUMATIC
Activity Note: REAR TIRES LOW SPECS
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55966497 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55938208
Invoice No. 55345 - 55938208

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Front AC malfunction.		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	320,554 - DH

Chronology		
Reported	Sep 11, 2022 2:16:35 PM	Sep 11, 2022 2:16:35 PM
Started	Sep 11, 2022 2:19:00 PM	
Completed	Sep 18, 2022 1:51:00 PM	Sep 18, 2022 1:51:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Front AC malfunction.

Cause: Faulty Front AC Compressor.

Correction: Diag and noted for repair. Line 20 Remove and replaced front AC Compressor and Accumulator. Remove and replaced Orifice tube. Vacuum, leak tested, added PAG oil and recharged to spec. Front AC works properly. Replaced serpentine belt.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 11-SEP-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Sep 11, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				4:59:33 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Sep 11, 2022 4:59:33 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Sep 11, 2022 4:59:33 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Sep 11, 2022 4:59:33 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Sep 11, 2022 4:59:33 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Sep 11, 2022 4:59:33 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55938208
Invoice No. 55345 - 55938208

Client Department:
Department: 55345M
Work Order Description
Front AC malfunction.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 320,554 - DH

Activity Header
Activity: 15 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Front AC Diag
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Sep-22	Earl Johnson	3.75	0	0
14-Sep-22	Earl Johnson	0.02	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55938208
Invoice No. 55345 - 55938208

Client Department:
Department: 55345M
Work Order Description
Front AC malfunction.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 320,554 - DH

Activity Header
Activity: 25 001/001/002 COMPRESSOR, A/C
Activity Note: Replace Front AC Compressor
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Sep-22	6512376	COMPRESSOR, A/C, NEW	1	200.14	200.14
18-Sep-22	GC2Z-19C836-C	ACCUMULATOR, A/C, E450	1	87.36	87.36
18-Sep-22	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	25.38	25.38
14-Sep-22	3411885	TUBE, ORIFICE, A/C, FORD	1	0.77	0.77

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Sep-22	Earl Johnson	5.1	0	0
18-Sep-22	Earl Johnson	2.93	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	313.65
Labor:	0.00
Labor Hours:	8.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**313.65**

Work Order Footer

Work Order 55938208 Total	
Parts:	313.65
Labor:	0.00
Labor Hours:	11.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**313.65**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55898423
Invoice No. 55345 - 55898423

Client Department:
Department: 55345M
Work Order Description
NOISE COMING OUT THE ENGINE
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 319,651 - DH

Chronology		
Reported	Aug 30, 2022 8:29:00 AM	Aug 30, 2022 8:29:00 AM
Started	Aug 30, 2022 8:33:00 AM	
Completed	Aug 30, 2022 1:09:00 PM	Aug 30, 2022 1:09:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: road call driver said bus making noise

Cause: broken belt

Correction: replaced driver completed

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 30-AUG-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Aug 30, 2022 1:08:51 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		HPIERRE	Aug 30, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				1:08:51 PM		
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Aug 30, 2022 1:08:51 PM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Aug 30, 2022 1:08:51 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Aug 30, 2022 1:08:51 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Aug 30, 2022 1:08:51 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55898423
Invoice No. 55345 - 55898423

Client Department:
Department: 55345M
Work Order Description
NOISE COMING OUT THE ENGINE
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 319,651 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Aug-22	Pierre,Hubert J	2.2	0	0
30-Aug-22	Pierre,Hubert J	3.4	0	0
30-Aug-22	Pierre,Hubert J	-3.4	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55898423
Invoice No. 55345 - 55898423

Client Department:
Department: 55345M
Work Order Description
NOISE COMING OUT THE ENGINE
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 319,651 - DH

Activity Header
Activity: 20 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Aug-22	450K6	BELT, SERPENTINE	1	21.58	21.58

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Aug-22	Pierre,Hubert J	1.18	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	21.58
Labor:	0.00
Labor Hours:	1.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**21.58**

Work Order Footer

Work Order 55898423 Total	
Parts:	21.58
Labor:	0.00
Labor Hours:	3.38
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**21.58**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55897527
Invoice No. 55345 - 55897527

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check AC And Check Engine Light)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 319,481 - DH

Chronology		
Reported	Aug 29, 2022 6:54:00 PM	Aug 29, 2022 6:54:00 PM
Started	Aug 29, 2022 6:55:00 PM	
Completed	Aug 29, 2022 11:59:00 PM	Aug 29, 2022 11:59:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: Check AC/ Check engine light illuminated.

Cause: Rear thermostat pad damaged/ EVAP leak detected.

Correction: Remove and replaced thermostat pad with good uswd unit/ tightened fuel cap and cleared DTC.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 29-AUG-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Aug 29, 2022 11:58:53 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Aug 29, 2022 11:58:53 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Aug 29, 2022 11:58:53 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Aug 29, 2022 11:58:53 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Aug 29, 2022 11:58:53 PM	No	
11 - Have you successfully completed the	Done		EARJOHNSON	Aug 29, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				11:58:53 PM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55897527
Invoice No. 55345 - 55897527

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check AC And Check Engine Light)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 319,481 - DH

Activity Header
Activity: 20 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Check AC
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Aug-22	Earl Johnson	1.28	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55897527
Invoice No. 55345 - 55897527

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check AC And Check Engine Light)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 319,481 - DH

Activity Header
Activity: 30 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Check Engine Light On
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Aug-22	Earl Johnson	2.03	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55897527 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.31
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 55827211
Invoice No. 55345 - 55827211

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP-FT Light Duty
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 316,735 - DH

Chronology		
Reported	Aug 3, 2022 9:46:47 PM	Aug 3, 2022 9:46:47 PM
Started	Aug 3, 2022 9:47:00 PM	
Completed	Aug 4, 2022 12:13:00 AM	Aug 4, 2022 12:13:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========
To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.
==========

Complaint:needs front brakes job

Cause: low spec and sliding caliper bracket cease

Correction:replaced front brake pads , pull caliper bracket, clean sliding lube pins . brakes part number. 8C2Z-2V001-D qty1
torque wheels 140 lbs second torque 140 lbs

Activity Header
Activity: 10 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: needs front brakes job.
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Aug-22	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	43.87	43.87

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Aug-22	Gaspard,Ronald	1.7	0	0
04-Aug-22	Gaspard,Ronald	0.18	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	43.87
Labor:	0.00
Labor Hours:	1.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.87**

Work Order Footer

Work Order 55827211 Total	
Parts:	43.87
Labor:	0.00
Labor Hours:	1.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.87**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55691568
Invoice No. 55345 - 55691568

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	316,735 - DH

Chronology		
Reported	Aug 1, 2022 12:00:00 AM	Aug 1, 2022 12:00:00 AM
Started	Aug 3, 2022 4:01:00 PM	
Completed	Aug 3, 2022 10:15:00 PM	Aug 3, 2022 10:15:00 PM
Down Time		

Work Order Notes

Line 10 COMPLETED PMA INSPECTION AND SERVICE

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 03-AUG-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Aug 3, 2022 8:29:41 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Aug 3, 2022 8:29:41 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RGASPARD	Aug 3, 2022 8:29:41 PM	No	
7 - Have you performed the proper LOTO?	Done		RGASPARD	Aug 3, 2022 8:29:41 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Aug 3, 2022 8:29:41 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Aug 3, 2022 8:29:41 PM	No	

Activity Sub Total

Activity 5 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55691568
Invoice No. 55345 - 55691568

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	316,735 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Aug-22	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 03-AUG-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Aug 3, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:45:42 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
20,800 - INSPECT_High Idle Control	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	Aug 3, 2022 9:45:42 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Aug 3, 2022 9:45:42 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
33,010 - CSF (Curb Side Front)	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	RGASPARD	Aug 3, 2022 9:45:42 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		RGASPARD	Aug 3, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression				9:45:42 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
50,400 - LUBE_All Chassis Components	Done	na	RGASPARD	Aug 3, 2022 9:45:42 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	3 32nds of an inch	needs front brakes job.	RGASPARD	Aug 3, 2022 9:45:42 PM	Yes	55827211
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	3 32nds of an inch		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	37 Inch		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	37 Inch		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Aug 3, 2022 9:45:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	3 32nds of an inch		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	3 32nds of an inch		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	37 Inch		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	37 Inch		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	11245 Cycles		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Aug 3, 2022 9:45:42 PM	No	

Activity Sub Total

Activity 10 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	1.50
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55691568
Invoice No. 55345 - 55691568

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	316,735 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Aug-22	B329	FILTER, OIL, SPIN-ON SEE P550965	1	2.19	2.19

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Aug-22	Gaspard,Ronald	0.22	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 03-AUG-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Aug 3, 2022 10:01:13 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Aug 3, 2022 10:01:13 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Aug 3, 2022 10:01:13 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Aug 3, 2022 10:01:13 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Aug 3, 2022 10:01:13 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Aug 3, 2022 10:01:13 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Aug 3, 2022 10:01:13 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Aug 3, 2022 10:01:13 PM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	2.19
	Labor:	0.00
	Labor Hours:	0.22
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**2.19**

Work Order Footer

Work Order 55691568 Total	
Parts:	2.19
Labor:	0.00
Labor Hours:	1.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.19**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55717773
Invoice No. 55345 - 55717773

Client Department:
Department: 55345M
Work Order Description
CHECK AIR CONDITIONING SYSTEM
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 312,842 - DH

Chronology		
Reported	Jun 24, 2022 7:54:00 AM	Jun 24, 2022 7:54:00 AM
Started	Jul 22, 2022 7:45:00 AM	
Completed	Jul 22, 2022 9:38:00 AM	Jul 22, 2022 9:38:00 AM
Down Time		

Work Order Notes

Line 10 check air conditioning front

nothing wrong

no problem was founded A/C working very good completed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 22-JUL-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Jul 22, 2022 9:38:38 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Jul 22, 2022 9:38:38 AM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Jul 22, 2022 9:38:38 AM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Jul 22, 2022 9:38:38 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Jul 22, 2022 9:38:38 AM	No	
11 - Have you successfully completed the Personal	Done		HPIERRE	Jul 22, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				9:38:38 AM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55717773
Invoice No. 55345 - 55717773

Client Department:
Department: 55345M
Work Order Description
CHECK AIR CONDITIONING SYSTEM
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 312,842 - DH

Activity Header
Activity: 20 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: CHECK REAR AC
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Jul-22	Pierre,Hubert J	1.8	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55717773 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55783797
Invoice No. 55345 - 55783797

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Noise Under Vehicle Transmission)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 315,272 - DH

Chronology		
Reported	Jul 18, 2022 6:31:00 PM	Jul 18, 2022 6:31:00 PM
Started	Jul 18, 2022 6:32:00 PM	
Completed	Jul 19, 2022 12:29:00 AM	Jul 19, 2022 12:29:00 AM
Down Time		

Work Order Notes

Line 10 Complaint: Noise coming from by transmission.

Cause: TBD.

Correction: Road tested vehicle without any issues. Racked vehicle to inspect the undercarriage, found no issues. Transmission fluid is filled to spec. Will monitor.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 18-JUL-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jul 18, 2022 10:14:50 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jul 18, 2022 10:14:50 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jul 18, 2022 10:14:50 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jul 18, 2022 10:14:50 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jul 18, 2022 10:14:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jul 18, 2022 10:14:50 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55783797
Invoice No. 55345 - 55783797

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Noise Under Vehicle Transmission)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 315,272 - DH

Activity Header
Activity: 20 027 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: Check Noise Transmission
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Jul-22	Earl Johnson	1.95	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55783797 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55699424
Invoice No. 55345 - 55699424

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Check Seat Belt Buckle		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	312,213 - DH

Chronology		
Reported	Jun 16, 2022 7:40:00 PM	Jun 16, 2022 7:40:00 PM
Started	Jun 16, 2022 7:41:00 PM	
Completed	Jun 17, 2022 12:24:00 AM	Jun 17, 2022 12:24:00 AM
Down Time		

Work Order Notes

Line 10 Complaint: One seat belt buckle missing.

Cause: Buckle hanging under the seat (misplaced).

Correction: Replaced buckle through the locator strap on side of passenger seat.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 16-JUN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jun 16, 2022 11:04:59 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jun 16, 2022 11:04:59 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jun 16, 2022 11:04:59 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jun 16, 2022 11:04:59 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jun 16, 2022 11:04:59 PM	No	
11 - Have you successfully completed the	Done		EARJOHNSON	Jun 16, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				11:04:59 PM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55699424
Invoice No. 55345 - 55699424

Client Department:
Department: 55345M
Work Order Description
Check Seat Belt Buckle
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 312,213 - DH

Activity Header
Activity: 20 002/011/003 BELT & RETAINER, SEAT
Activity Note: Check Seat Belt Buckle
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jun-22	Earl Johnson	0.92	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55699424 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55564162
Invoice No. 55345 - 55564162

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	312,091 - DH

Chronology		
Reported	Jun 3, 2022 12:00:00 AM	Jun 3, 2022 12:00:00 AM
Started	Jun 14, 2022 9:30:00 AM	
Completed	Jun 14, 2022 12:44:00 PM	Jun 14, 2022 12:44:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA

CAUSE:preventive maintenance

CORRECTION:performed PMA Service lubes all Pivoting Points completed

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 14-JUN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Jun 14, 2022 10:09:08 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Jun 14, 2022 10:09:08 AM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Jun 14, 2022 10:09:08 AM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Jun 14, 2022 10:09:08 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Jun 14, 2022 10:09:08 AM	No	
11 - Have you successfully completed the Personal	Done		HPIERRE	Jun 14, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				10:09:08 AM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55564162
Invoice No. 55345 - 55564162

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 312,091 - DH

Activity Header
Activity: 10 017 TIRES, TUBES, LINERS & VALVES
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Jun-22	Pierre,Hubert J	0.85	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: HPIERRE Performed on: 14-JUN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		HPIERRE	Jun 14, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:21:23 AM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
20,800 - INSPECT_High Idle Control	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
21,100 - INSPECT_Parking Brake Operation	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
21,700 - INSPECT_Engine Fault Codes	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
31,000 - SSF (Street Side Front)	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
32,000 - Engine Inspection	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	190 Degree Fahrenheit		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
32,100 - INSPECT_Intake System	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12 Volt*		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
33,010 - CSF (Curb Side Front)	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	12 Volt*		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		HPIERRE	Jun 14, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression				10:21:23 AM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
50,400 - LUBE_All Chassis Components	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
50,700 - INSPECT_Tire Condition	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	17 Inch		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	17 Inch		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
52,100 - INSPECT_Vibration Damper	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
53,600 - INSPECT_Tire Condition	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Jun 14, 2022 10:21:23 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	7 32nds of an inch		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	17 Inch		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	17 Inch		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
60,100 - RECORD_Wheelchair Cycle Count	12345 Cycles		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper	Done		HPIERRE	Jun 14, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alignment				10:21:23 AM		
61,000 - INSPECT_Cable Condition (If Applicable)	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
62,400 - INSPECT_All Pivot Points	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
62,500 - INSPECT_Cams and Slots	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
62,600 - INSPECT_Rollers	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
62,700 - INSPECT_All Linkages	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		HPIERRE	Jun 14, 2022 10:21:23 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55564162
Invoice No. 55345 - 55564162

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 312,091 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Jun-22	B329	FILTER, OIL, SPIN-ON SEE P550965	1	2.14	2.14

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Jun-22	Pierre,Hubert J	2.38	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 14-JUN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Jun 14, 2022 10:09:54 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Jun 14, 2022 10:09:54 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Jun 14, 2022 10:09:54 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Jun 14, 2022 10:09:54 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Jun 14, 2022 10:09:54 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Jun 14, 2022 10:09:54 AM	No	
107,000 - FRA Change Primary Fuel Filter	No		HPIERRE	Jun 14, 2022 10:09:54 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Jun 14, 2022 10:09:54 AM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	2.14
	Labor:	0.00
	Labor Hours:	2.38
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**2.14**

Work Order Footer

Work Order 55564162 Total	
Parts:	2.14
Labor:	0.00
Labor Hours:	3.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.14**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55669812
Invoice No. 55345 - 55669812

Client Department:
Department: 55345M
Work Order Description
Rough Idle, Engine Light Flashing, Ac Blowing Hot Air
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 311,588 - DH

Chronology		
Reported	Jun 6, 2022 8:25:00 PM	Jun 6, 2022 8:25:00 PM
Started	Jun 6, 2022 8:27:00 PM	
Completed	Jun 7, 2022 9:08:00 PM	Jun 7, 2022 9:08:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: Check Engine light illuminated/ AC malfunction.

Cause: Cyl 5 &8 misfires, p0300/ both AC blow cold, front AC resistor issue.

Correction: Tune up recommended for misfires/ frontvAC resistor to be replaced. Line 20 vehicle came in for mis fire after checking engine i found the 8 Cylinder Misfire removed coil and plugs all was worn out replace 8 spark plugs part number SP521. REPLACE ONE NEW COIL TO # 7 CYLINDER PART # AS3W7Z-12029-AA CHANGE FOUR BOOT PART # 357006 Line 30 REMOVED AND REPLACE ONE PIGTAIL PART # WPT-1521. ALSO ONE RESISTOR PART # 4C2Z-19A706 A/C NOW WORKING ASDESIGN RETURN VEHICLE BACK TO WORK Line 40 can you please charge one coil for me also one resistor part # 4C2 Z-19A 706 -AA. AS 3W7Z-12029. THANK YOU Line 50 ALL PARTS CHARGED

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 07-JUN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Jun 7, 2022 9:06:43 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Jun 7, 2022 9:06:43 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Jun 7, 2022 9:06:43 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
7 - Have you performed the proper LOTO?	Done		JUHURST	Jun 7, 2022 9:06:43 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Jun 7, 2022 9:06:43 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Jun 7, 2022 9:06:43 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55669812
Invoice No. 55345 - 55669812

Client Department:
Department: 55345M
Work Order Description
Rough Idle, Engine Light Flashing, Ac Blowing Hot Air
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 311,588 - DH

Activity Header
Activity: 20 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Blowing Hot Air
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Jun-22	357006	BOOT, COIL-ON-PLUG, IGNITION	4	5.87	23.48
07-Jun-22	SP521	PLUG, SPARK, 5.4L, FORD	8	3.54	28.32
07-Jun-22	WPT-1521	PIGTAIL, RESISTOR, MOTOR, BLOWER	1	14.5	14.5

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Jun-22	Earl Johnson	0.57	0	0
07-Jun-22	Junior Hurst	3.28	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	66.30
Labor:	0.00
Labor Hours:	3.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**66.30**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55669812
Invoice No. 55345 - 55669812

Client Department:
Department: 55345M
Work Order Description
Rough Idle, Engine Light Flashing, Ac Blowing Hot Air
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 311,588 - DH

Activity Header
Activity: 30 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Engine Light On
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Jun-22	DG508	COIL, IGNITION SAME AS 3W7Z-12029-AA	1	35.92	35.92
08-Jun-22	YH-1697	RESISTOR, MOTOR, BLOWER, HEATER SAME AS 4C2Z-19A706-AA	1	19.3	19.3

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Jun-22	Junior Hurst	5.3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	55.22
Labor:	0.00
Labor Hours:	5.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**55.22**

Work Order Footer

Work Order 55669812 Total	
Parts:	121.52
Labor:	0.00
Labor Hours:	9.15
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**121.52**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55659054
Invoice No. 55345 - 55659054

Client Department:
Department: 55345M
Work Order Description
TOP FRONT CLEARENCE LIGHT OUT
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 311,402 - DH

Chronology		
Reported	Jun 2, 2022 1:15:00 PM	Jun 2, 2022 1:15:00 PM
Started	Jun 2, 2022 4:07:00 PM	
Completed	Jun 3, 2022 12:01:00 AM	Jun 3, 2022 12:01:00 AM
Down Time		

Work Order Notes

Line 10 Complaint: Front center clearance light not working.

Cause: Wear and tear.

Correction: Remove and replaced front clearance light.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 02-JUN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jun 2, 2022 11:21:37 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jun 2, 2022 11:21:37 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jun 2, 2022 11:21:37 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jun 2, 2022 11:21:37 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jun 2, 2022 11:21:37 PM	No	
11 - Have you successfully completed the	Done		EARJOHNSON	Jun 2, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				11:21:37 PM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55659054
Invoice No. 55345 - 55659054

Client Department:
Department: 55345M
Work Order Description
TOP FRONT CLEARENCE LIGHT OUT
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 311,402 - DH

Activity Header
Activity: 20 174/024/017 LAMP, CEILING, BUS
Activity Note: CHECK ALL THE LIGHTS
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Jun-22	3974688	LAMP, LED, AMBER	1	8.9	8.9

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jun-22	Earl Johnson	2.9	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	8.90
Labor:	0.00
Labor Hours:	2.90
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.90**

Work Order Footer

Work Order 55659054 Total	
Parts:	8.90
Labor:	0.00
Labor Hours:	2.90
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.90**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 5

Work Order No. 55624094
Invoice No. 55345 - 55624094

Client Department:
Department: 55345M
Work Order Description
ROAD CALL (OVERHEATING)
Requested By: RRENE
Created By: RRENE
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 309,841 - DH

Chronology		
Reported	May 20, 2022 10:08:00 AM	May 20, 2022 10:08:00 AM
Started	May 20, 2022 10:10:00 AM	
Completed	May 20, 2022 2:47:00 PM	May 20, 2022 2:47:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Road call, vehicle overheating

Cause: tech found tensioner was broken

Correction: replaced the belt tensioner, belt and idler pulley, vehicle okay at this time

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 20-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	May 20, 2022 2:47:14 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		NPIERRE-	May 20, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?			LOUIS	2:47:14 PM		
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	May 20, 2022 2:47:14 PM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	May 20, 2022 2:47:14 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	May 20, 2022 2:47:14 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	May 20, 2022 2:47:14 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 5

Work Order No. 55624094
Invoice No. 55345 - 55624094

Client Department:
Department: 55345M
Work Order Description
ROAD CALL (OVERHEATING)
Requested By: RRENE
Created By: RRENE
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 309,841 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 5

Work Order No. 55624094
Invoice No. 55345 - 55624094

Client Department:
Department: 55345M
Work Order Description
ROAD CALL (OVERHEATING)
Requested By: RRENE
Created By: RRENE
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 309,841 - DH

Activity Header
Activity:20 042/003/008 PULLEY, IDLER, DRIVEN, FAN
Activity Note:
Reason for Repair: 01 Breakdown
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-May-22	NELSON PIERRE-LOUIS	2.85	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 5

Work Order No. 55624094
Invoice No. 55345 - 55624094

Client Department:
Department: 55345M
Work Order Description
ROAD CALL (OVERHEATING)
Requested By: RRENE
Created By: RRENE
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 309,841 - DH

Activity Header
Activity: 30 042 COOLING SYSTEM
Activity Note: BUS TOWED IN (OVERHEATING)
Reason for Repair: TW Towing
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-May-22	DSP-TOWING	DIRECT PURCHASES FOR SERVICES TOWING	1	245	245

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	245.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**245.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 5

Work Order No. 55624094
Invoice No. 55345 - 55624094

Client Department:
Department: 55345M
Work Order Description
ROAD CALL (OVERHEATING)
Requested By: RRENE
Created By: RRENE
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 309,841 - DH

Activity Header
Activity: 40 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: idler pulley
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
31-May-22	89101	PULLEY, IDLER	1	24.14	24.14
31-May-22	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	21.32	21.32
31-May-22	89263	TENSIONER, BELT, SERPENTINE	1	32.44	32.44

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-May-22	NELSON PIERRE-LOUIS	1.63	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	99.22
Labor:	0.00
Labor Hours:	1.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**99.22**

Work Order Footer

Work Order 55624094 Total	
Parts:	344.22
Labor:	0.00
Labor Hours:	4.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**344.22**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55616958
Invoice No. 55345 - 55616958

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
WC LIFT INOP		Ford E350 Champion Crusaders	
Requested By:	KIVEY	**Status:**	40 - Closed (40)
Created By:	KIVEY	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	309,324 - DH

Chronology		
Reported	May 18, 2022 8:21:00 AM	May 18, 2022 8:21:00 AM
Started	May 18, 2022 12:00:00 AM	
Completed	May 20, 2022 7:33:00 AM	May 20, 2022 7:33:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:
W/C LIFT INOP

Cause: inner plate switch broken

Correction: removed and replace switch, all okay at this time

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-May-22	32519KS	SWITCH, RAISED, W/C	1	36.41	36.41

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 20-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	May 20, 2022 7:28:46 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	May 20, 2022 7:28:46 AM	No	
4 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	May 20, 2022 7:28:46 AM	No	
7 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	May 20, 2022 7:28:46 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	May 20, 2022 7:28:46 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	May 20, 2022 7:28:46 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	36.41
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**36.41**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55616958
Invoice No. 55345 - 55616958

Client Department:
Department: 55345M
Work Order Description
WC LIFT INOP
Requested By: KIVEY
Created By: KIVEY
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 309,324 - DH

Activity Header
Activity: 15 055/023/000 LIFT, WHEELCHAIR, PASSENGER
Activity Note: W/C LIFT INOP
Reason for Repair: 01 Breakdown
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-May-22	Rodriguez,Raul	1.15	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.15
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55616958 Total	
Parts:	36.41
Labor:	0.00
Labor Hours:	1.15
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**36.41**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55592785
Invoice No. 55345 - 55592785

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
CHECK WHEEL CHAIR LIFT		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	308,320 - DH

Chronology		
Reported	May 10, 2022 7:21:00 AM	May 10, 2022 7:21:00 AM
Started	May 10, 2022 7:25:00 AM	
Completed	May 11, 2022 6:49:00 AM	May 11, 2022 6:49:00 AM
Down Time		

Work Order Notes

Line 10 complaint. w/c lift is not working properly

cause. need inner plate shocks and control pendant

Correction. removed and replaced shocks and control pendant.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 11-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	May 11, 2022 6:38:30 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	May 11, 2022 6:38:30 AM	No	
4 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	May 11, 2022 6:38:30 AM	No	
7 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	May 11, 2022 6:38:30 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	May 11, 2022 6:38:30 AM	No	
11 - Have you successfully completed the	Done		RAURODRIGUEZ	May 11, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				6:38:30 AM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55592785
Invoice No. 55345 - 55592785

Client Department:
Department: 55345M
Work Order Description
CHECK WHEEL CHAIR LIFT
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 308,320 - DH

Activity Header
Activity: 20 055/023/000 LIFT, WHEELCHAIR, PASSENGER
Activity Note: CHECK WHEEL CHAIR LIFT FOR PROPER OPERATION
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-May-22	33659KS	PENDANT, CONTROL, W/C, BRAUN	1	184.89	184.89
11-May-22	32601	SPRING, ASSIST, GAS	2	15.57	31.14

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-May-22	Rodriguez,Raul	2.77	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	216.03
Labor:	0.00
Labor Hours:	2.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**216.03**

Work Order Footer

Work Order 55592785 Total	
Parts:	216.03
Labor:	0.00
Labor Hours:	2.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**216.03**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 55563781
Invoice No. 55345 - 55563781

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
FOLLOWUP-FT Light Duty		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	307,199 - DH

Chronology		
Reported	Apr 29, 2022 11:13:33 AM	Apr 29, 2022 11:13:33 AM
Started	Apr 29, 2022 12:00:00 AM	
Completed	Apr 29, 2022 12:51:00 PM	Apr 29, 2022 12:51:00 PM
Down Time		

Work Order Notes

Activity Header
Activity: 10 017/003/001 TIRE, CUSHION W/TREAD
Activity Note: front tire rotation
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Apr-22	NELSON PIERRE-LOUIS	1.1666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55563781 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55421653
Invoice No. 55345 - 55421653

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMC		Ford E350 Champion Crusaders	
Requested By:	SPACE	**Status:**	40 - Closed (40)
Created By:	SPACE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	307,199 - DH

Chronology		
Reported	Apr 25, 2022 12:00:00 AM	Apr 25, 2022 12:00:00 AM
Started	Apr 29, 2022 7:06:00 AM	
Completed	Apr 29, 2022 12:41:00 PM	Apr 29, 2022 12:41:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMC Service

Cause: preventive maintenance

Correction: Perform PMC Service ,lube all Pivoting Points, transmission Service, rear end

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 29-APR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Apr 29, 2022 12:40:55 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Apr 29, 2022 12:40:55 PM	No	
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Apr 29, 2022 12:40:55 PM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Apr 29, 2022 12:40:55 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Apr 29, 2022 12:40:55 PM	No	
11 - Have you successfully completed the Personal	Done		NPIERRE-	Apr 29, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	12:40:55 PM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55421653
Invoice No. 55345 - 55421653

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMC
Requested By: SPACE
Created By: SPACE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 307,199 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Apr-22	NELSON PIERRE-LOUIS	2.07	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS Performed on: 29-APR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-	Apr 29, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	11:14:32 AM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
20,800 - INSPECT_High Idle Control	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
21,100 - INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
21,700 - INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
31,000 - SSF (Street Side Front)	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
32,000 - Engine Inspection	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	280 Degree Fahrenheit		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
32,100 - INSPECT_Intake System	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.5 Volt*		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
33,010 - CSF (Curb Side Front)	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	12.2 Volt*		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		NPIERRE-	Apr 29, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression			LOUIS	11:14:32 AM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
50,400 - LUBE_All Chassis Components	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
50,700 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	69 Pounds per Square Inch		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	Yes	55563781
51,300 - RECORD_RF-Air Pressure (psi)	68 Pounds per Square Inch		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	35.5 Inch		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	35.5 Inch		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
52,100 - INSPECT_Vibration Damper	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
53,600 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	68 Pounds per Square Inch		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	69 Pounds per Square Inch		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	68 Pounds per Square Inch		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	25.5 Inch		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	25.5 Inch		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
60,100 - RECORD_Wheelchair Cycle Count	0 Cycles		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
60,800 - INSPECT_Operation of Platform Barrier	Done		NPIERRE-	Apr 29, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Mechanism			LOUIS	11:14:32 AM		
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
62,400 - INSPECT_All Pivot Points	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
62,500 - INSPECT_Cams and Slots	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
62,600 - INSPECT_Rollers	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
62,700 - INSPECT_All Linkages	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	Apr 29, 2022 11:14:32 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.07
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55421653
Invoice No. 55345 - 55421653

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMC
Requested By: SPACE
Created By: SPACE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 307,199 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Apr-22	20021	FILTER, TRANSMISSION 20021	1	17.44	17.44
29-Apr-22	B329	FILTER, OIL, SPIN-ON SEE P550965	1	1.99	1.99
29-Apr-22	P9600	FILTER, OIL SEE LF16424	1	3.49	3.49

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Apr-22	NELSON PIERRE-LOUIS	1.1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: NPIERRE-LOUIS Performed on: 29-APR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Apr 29, 2022 11:17:46 AM	No	
101,000 - FRA Change Oil Filters	No		NPIERRE-LOUIS	Apr 29, 2022 11:17:46 AM	No	
102,000 - FRA Drain Engine Oil	No		NPIERRE-LOUIS	Apr 29, 2022 11:17:46 AM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Apr 29, 2022 11:17:46 AM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Apr 29, 2022 11:17:46 AM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Apr 29, 2022 11:17:46 AM	No	
107,000 - FRA Change Primary Fuel Filter	Done		NPIERRE-LOUIS	Apr 29, 2022 11:17:46 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Apr 29, 2022 11:17:46 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		NPIERRE-LOUIS	Apr 29, 2022 11:17:46 AM	No	
201,000 - Service Crankcase Breather	Done		NPIERRE-LOUIS	Apr 29, 2022 11:17:46 AM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		NPIERRE-LOUIS	Apr 29, 2022 11:17:46 AM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		NPIERRE-LOUIS	Apr 29, 2022 11:17:46 AM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		NPIERRE-LOUIS	Apr 29, 2022 11:17:46 AM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		NPIERRE-LOUIS	Apr 29, 2022 11:17:46 AM	No	
301,000 - Check and Lubricate Door Linkages	Done		NPIERRE-LOUIS	Apr 29, 2022 11:17:46 AM	No	
302,000 - Check Toe-In and Record Reading	Done		NPIERRE-LOUIS	Apr 29, 2022 11:17:46 AM	No	
302,001 - Record Toe-In Reading	0 Inches, fraction-actual		NPIERRE-LOUIS	Apr 29, 2022 11:17:46 AM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		NPIERRE-LOUIS	Apr 29, 2022 11:17:46 AM	No	
305,000 - FRA Change Differential Fluid	No		NPIERRE-LOUIS	Apr 29, 2022 11:17:46 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	22.92
Labor:	0.00
Labor Hours:	1.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**22.92**

Work Order Footer

Work Order 55421653 Total	
Parts:	22.92
Labor:	0.00
Labor Hours:	3.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**22.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55540355
Invoice No. 55345 - 55540355

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Road Call		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WORC - WORK ORDER ROAD CALL	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	306,493 - DH

Chronology		
Reported	Apr 21, 2022 9:37:00 AM	Apr 21, 2022 9:37:00 AM
Started	Apr 21, 2022 9:43:00 AM	
Completed	Apr 21, 2022 2:03:00 PM	Apr 21, 2022 2:03:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: road call noise coming from the engine

Cause: broken serpentine belt

Correction: replace serpentine belt and double check engine compartment completed

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 21-APR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Apr 21, 2022 1:02:57 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		HPIERRE	Apr 21, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				1:02:57 PM		
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Apr 21, 2022 1:02:57 PM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Apr 21, 2022 1:02:57 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Apr 21, 2022 1:02:57 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Apr 21, 2022 1:02:57 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55540355
Invoice No. 55345 - 55540355

Client Department:
Department: 55345M
Work Order Description
Road Call
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 306,493 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Apr-22	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	21.32	21.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Apr-22	Pierre,Hubert J	3.33	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	21.32
Labor:	0.00
Labor Hours:	3.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**21.32**

Work Order Footer

Work Order 55540355 Total	
Parts:	21.32
Labor:	0.00
Labor Hours:	3.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**21.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55480256
Invoice No. 55345 - 55480256

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
CHECK FOR FUEL ODOR		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	303,622 - DH

Chronology		
Reported	Mar 31, 2022 8:46:00 AM	Mar 31, 2022 8:46:00 AM
Started	Mar 31, 2022 9:00:00 AM	
Completed	Mar 31, 2022 12:27:00 PM	Mar 31, 2022 12:27:00 PM
Down Time		

Work Order Notes

Line 10 complaint: Vehicle smelling gas and reverse camera was broken

Cause: Vehicle was overfill to much gas

correction: Replaced the back camera with a good used one ,clean up the bus inside and outside for gas overdue

Activity Header
Activity: 10 044/001/011 LINE, FUEL
Activity Note: INSPECT FUEL ODOR CHECK FOR EXTERNAL LEAKS
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Mar-22	NELSON PIERRE-LOUIS	1.9	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.90
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55480256
Invoice No. 55345 - 55480256

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
CHECK FOR FUEL ODOR		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	303,622 - DH

Activity Header
Activity: 20 036/008/002 CAMERA, SYSTEM, SURVEILLANCE
Activity Note: REAR CAMERA FELL OFF
Reason for Repair: 01 Breakdown
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Mar-22	NELSON PIERRE-LOUIS	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55480256 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.90
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55466280
Invoice No. 55345 - 55466280

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
REAR AC SYSTEM		Ford E350 Champion Crusaders	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	302,922 - DH

Chronology		
Reported	Mar 26, 2022 12:32:50 PM	Mar 26, 2022 12:32:50 PM
Started	Mar 26, 2022 12:33:00 PM	
Completed	Mar 29, 2022 7:45:00 AM	Mar 29, 2022 7:45:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT. rear ac not working properly

Cause. found system little low.

Correction. performance regular ac system maintenance, replaced orifice tube, and charged system, checked, all okay at this time.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 29-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Mar 29, 2022 7:40:02 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Mar 29, 2022 7:40:02 AM	No	
4 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Mar 29, 2022 7:40:02 AM	No	
7 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Mar 29, 2022 7:40:02 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Mar 29, 2022 7:40:02 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Mar 29, 2022 7:40:02 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55466280
Invoice No. 55345 - 55466280

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
REAR AC SYSTEM		Ford E350 Champion Crusaders	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	302,922 - DH

Activity Header
Activity: 20 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: REAR AC DIAG
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Mar-22	3411885	TUBE, ORIFICE, A/C, FORD	1	0.73	0.73

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Mar-22	Rodriguez,Raul	1.32	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.73
Labor:	0.00
Labor Hours:	1.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.73**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55466280
Invoice No. 55345 - 55466280

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
REAR AC SYSTEM		Ford E350 Champion Crusaders	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	302,922 - DH

Activity Header
Activity: 30 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 51 Inoperative
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Mar-22	Rodriguez,Raul	1.98	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.98
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55466280 Total	
Parts:	0.73
Labor:	0.00
Labor Hours:	3.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.73**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55456928
Invoice No. 55345 - 55456928

Client Department:
Department: 55345M
Work Order Description
CHECK ENGINE LIGHT ON + CK AIR CONDITIONING
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 302,922 - DH

Chronology		
Reported	Mar 23, 2022 7:07:00 AM	Mar 23, 2022 7:07:00 AM
Started	Mar 23, 2022 7:52:00 AM	
Completed	Mar 23, 2022 12:54:00 PM	Mar 23, 2022 12:54:00 PM
Down Time		

Work Order Notes

Line 10 check engine light on and check air conditioning

bad ignition coil and spark plug

replace spark plugs and coil not wrong found on the a/c Complaint

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 23-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Mar 23, 2022 12:54:23 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Mar 23, 2022 12:54:23 PM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Mar 23, 2022 12:54:23 PM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Mar 23, 2022 12:54:23 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Mar 23, 2022 12:54:23 PM	No	
11 - Have you successfully completed the Personal	Done		HPIERRE	Mar 23, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				12:54:23 PM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55456928
Invoice No. 55345 - 55456928

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
CHECK ENGINE LIGHT ON + CK AIR CONDITIONING		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	302,922 - DH

Activity Header
Activity: 20 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: CHECK ENGINE LIGHT ON
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Mar-22	Pierre,Hubert J	2.6	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55456928
Invoice No. 55345 - 55456928

Client Department:
Department: 55345M
Work Order Description
CHECK ENGINE LIGHT ON + CK AIR CONDITIONING
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 302,922 - DH

Activity Header
Activity: 30 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: AIR CONDITIONING SYSTEM
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Mar-22	DG508	COIL, IGNITION SAME AS 3W7Z-12029-AA	1	65.89	65.89
23-Mar-22	AP103	PLUG, SPARK	1	3.46	3.46

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Mar-22	Pierre,Hubert J	0.1	0	0
23-Mar-22	Pierre,Hubert J	2.15	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	69.35
Labor:	0.00
Labor Hours:	2.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**69.35**

Work Order Footer

Work Order 55456928 Total	
Parts:	69.35
Labor:	0.00
Labor Hours:	4.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**69.35**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 6

Work Order No. 55430669
Invoice No. 55345 - 55430669

Client Department:
Department: 55345M
Work Order Description
PREPARE BUS FOR P.T.C ANNUAL INSPECTION.
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 302,434 - DH

Chronology		
Reported	Mar 14, 2022 9:33:00 AM	Mar 14, 2022 9:33:00 AM
Started	Mar 14, 2022 9:39:00 AM	
Completed	Mar 23, 2022 7:02:00 AM	Mar 23, 2022 7:02:00 AM
Down Time		

Work Order Notes

Line 10 Prepare bus for PTC annual inspection.

fire alarm on, detector bottle low, no leaks, replaced detector bottle.

front tires near min. specs, replaced tires with used good ones (9/32).

installed geotab, camera and MDT.

Replaced bad batteries under warranty.

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: PREPARE BUS FOR P.T.C ANNUAL INSPECTION.
Reason for Repair: 11 Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Mar-22	Rodriguez,Raul	2.18	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 6

Work Order No. 55430669
Invoice No. 55345 - 55430669

Client Department:
Department: 55345M
Work Order Description
PREPARE BUS FOR P.T.C ANNUAL INSPECTION.
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 302,434 - DH

Activity Header
Activity:20 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 23-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Mar 23, 2022 6:58:32 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Mar 23, 2022 6:58:32 AM	No	
4 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Mar 23, 2022 6:58:32 AM	No	
7 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Mar 23, 2022 6:58:32 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Mar 23, 2022 6:58:32 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Mar 23, 2022 6:58:32 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 6

Work Order No. 55430669
Invoice No. 55345 - 55430669

Client Department:
Department: 55345M
Work Order Description
PREPARE BUS FOR P.T.C ANNUAL INSPECTION.
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 302,434 - DH

Activity Header
Activity:30 036/008/002 CAMERA, SYSTEM, SURVEILLANCE
Activity Note: GEO TAB AND CAMERAS
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Mar-22	Rodriguez,Raul	4.07	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	4.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 6

Work Order No. 55430669
Invoice No. 55345 - 55430669

Client Department:
Department: 55345M
Work Order Description
PREPARE BUS FOR P.T.C ANNUAL INSPECTION.
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 302,434 - DH

Activity Header
Activity:40 031/005/000 CHARGER, BATTERY, ON-BOARD, VEHICLES, PROPELLED, ELECTRICALLY
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure: 43 Weak
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Mar-22	Rodriguez,Raul	0.92	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 6

Work Order No. 55430669
Invoice No. 55345 - 55430669

Client Department:
Department: 55345M
Work Order Description
PREPARE BUS FOR P.T.C ANNUAL INSPECTION.
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 302,434 - DH

Activity Header
Activity: 50 999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Mar-22	Rodriguez,Raul	1.47	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 50 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 6 of 6

Work Order No. 55430669
Invoice No. 55345 - 55430669

Client Department:
Department: 55345M
Work Order Description
PREPARE BUS FOR P.T.C ANNUAL INSPECTION.
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 302,434 - DH

Activity Header
Activity:60 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Mar-22	Rodriguez,Raul	1.47	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 60 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55430669 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	10.11
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54820733
Invoice No. 55345 - 54820733

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Check engine light illuminated.		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	301,465 - DH

Chronology		
Reported	Aug 17, 2021 9:55:30 PM	Aug 17, 2021 9:55:30 PM
Started	Aug 17, 2021 9:58:00 PM	
Completed	Aug 26, 2021 5:31:00 PM	Aug 26, 2021 5:31:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:*****VOID*****

Cause:

Correction:

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 26-AUG-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Aug 26, 2021 5:30:29 PM	No	
2 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Aug 26, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				5:30:29 PM		
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Aug 26, 2021 5:30:29 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Aug 26, 2021 5:30:29 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Aug 26, 2021 5:30:29 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Aug 26, 2021 5:30:29 PM	No	
20 - Miles			EARJOHNSON	Aug 26, 2021 5:30:29 PM	No	
30 - Kilometers			EARJOHNSON	Aug 26, 2021 5:30:29 PM	No	
40 - Hours			EARJOHNSON	Aug 26, 2021 5:30:29 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54820733
Invoice No. 55345 - 54820733

Client Department:
Department: 55345M
Work Order Description
Check engine light illuminated.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 301,465 - DH

Activity Header
Activity: 15 043/000/000 EXHAUST SYSTEM
Activity Note: Check engine light illuminated.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Aug-21	Earl Johnson	0.65	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54820733 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 54770096
Invoice No. 55345 - 54770096

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
FOLLOWUP-FT Light Duty		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	299,460 - DH

Chronology

Reported	Jul 29, 2021 8:39:06 PM	Jul 29, 2021 8:39:06 PM
Started	Jul 29, 2021 8:52:00 PM	
Completed	Jul 29, 2021 10:32:00 PM	Jul 29, 2021 10:32:00 PM
Down Time		

Work Order Notes

Line 10 Remove & Replace Rear Brakes Lube all Slide Pins . Adjust emergency brakes.
Parts # 9C2Z-2V200-B Qty (1)

Activity Header

Activity: 10 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: Rear brakes
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Jul-21	9C2Z-2V200-B	PADS, BRAKE, DISC, REAR SAME AS BRSD1329B	1	50.04	50.04

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Jul-21	Arthurs,Durvin	1.03	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	50.04
Labor:	0.00
Labor Hours:	1.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**50.04**

Work Order Footer

Work Order 54770096 Total	
Parts:	50.04
Labor:	0.00
Labor Hours:	1.03
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**50.04**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54653336
Invoice No. 55345 - 54653336

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	299,460 - DH

Chronology		
Reported	Jul 29, 2021 12:00:00 AM	Jul 29, 2021 12:00:00 AM
Started	Jul 29, 2021 6:32:00 PM	
Completed	Jul 29, 2021 8:51:00 PM	Jul 29, 2021 8:51:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PMA Service.

CAUSE: Service Due by Mileage.

CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check brakes .clean batteries. Clean A/C Filter Replace Air Filter.
Parts # B329 Qty (1)
Parts # PA4075 Qty (1)
Oil 10W40 Qty (6.5) Qt

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 29-JUL-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jul 29, 2021 8:32:22 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jul 29, 2021 8:32:22 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jul 29, 2021 8:32:22 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jul 29, 2021 8:32:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jul 29, 2021 8:32:22 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 29, 2021 8:32:22 PM	No	
20 - Miles			DARTHURS	Jul 29, 2021 8:32:22 PM	No	
30 - Kilometers			DARTHURS	Jul 29, 2021 8:32:22 PM	No	
40 - Hours			DARTHURS	Jul 29, 2021 8:32:22 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54653336
Invoice No. 55345 - 54653336

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	299,460 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Jul-21	Arthurs,Durvin	1.97	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: DARTHURS Performed on: 29-JUL-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		DARTHURS	Jul 29, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:15:28 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
20,800 - INSPECT_High Idle Control	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
31,000 - SSF (Street Side Front)	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
32,000 - Engine Inspection	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	NA	DARTHURS	Jul 29, 2021 8:15:28 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	DARTHURS	Jul 29, 2021 8:15:28 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
32,100 - INSPECT_Intake System	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	1 Volt*		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
33,010 - CSF (Curb Side Front)	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	14.03 Volt*		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		DARTHURS	Jul 29, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression				8:15:28 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
50,400 - LUBE_All Chassis Components	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
50,700 - INSPECT_Tire Condition	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	10 32nds of an inch		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	10 32nds of an inch		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.554 Inch		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.554 Inch		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
52,100 - INSPECT_Vibration Damper	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
53,600 - INSPECT_Tire Condition	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	10 32nds of an inch		DARTHURS	Jul 29, 2021 8:15:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	5 32nds of an inch		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	4 32nds of an inch		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	4 32nds of an inch	Rear brakes	DARTHURS	Jul 29, 2021 8:15:28 PM	Yes	54770096
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	1.414 Inch		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	1.414 Inch		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	15799 Cycles		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
60,800 - INSPECT_Operation of Platform Barrier	Done		DARTHURS	Jul 29, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Mechanism				8:15:28 PM		
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
62,400 - INSPECT_All Pivot Points	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
62,500 - INSPECT_Cams and Slots	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
62,600 - INSPECT_Rollers	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
62,700 - INSPECT_All Linkages	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		DARTHURS	Jul 29, 2021 8:15:28 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.97
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54653336
Invoice No. 55345 - 54653336

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 299,460 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Jul-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.98	1.98
29-Jul-21	PA4075	FILTER, AIR SEE P546597	1	5.32	5.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Jul-21	Arthurs,Durvin	0.35	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 29-JUL-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Jul 29, 2021 8:31:29 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Jul 29, 2021 8:31:29 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Jul 29, 2021 8:31:29 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Jul 29, 2021 8:31:29 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Jul 29, 2021 8:31:29 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Jul 29, 2021 8:31:29 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Jul 29, 2021 8:31:29 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Jul 29, 2021 8:31:29 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	7.30
Labor:	0.00
Labor Hours:	0.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.30**

Work Order Footer

Work Order 54653336 Total	
Parts:	7.30
Labor:	0.00
Labor Hours:	2.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.30**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54749674
Invoice No. 55345 - 54749674

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Scheduled		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	298,790 - DH

Chronology		
Reported	Jul 22, 2021 10:06:43 AM	Jul 22, 2021 10:06:43 AM
Started	Jul 22, 2021 12:00:00 AM	
Completed	Jul 22, 2021 12:43:00 PM	Jul 22, 2021 12:43:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:Rubber spring was broken

Cause: preventive maintenance

Correction: replaced Dsr108-075 Rubber ,spring,shear

Line 20 Complaint: the rubber spring was broken

Cause: preventive maintenance

Correction: replaced the rubber,spring,shear

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 22-JUL-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Jul 22, 2021 12:31:54 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Jul 22, 2021 12:31:54 PM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Jul 22, 2021 12:31:54 PM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Jul 22, 2021 12:31:54 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Jul 22, 2021 12:31:54 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Jul 22, 2021 12:31:54 PM	No	
20 - Miles			NPIERRE-LOUIS	Jul 22, 2021 12:31:54 PM	No	
30 - Kilometers			NPIERRE-LOUIS	Jul 22, 2021 12:31:54 PM	No	
40 - Hours			NPIERRE-LOUIS	Jul 22, 2021 12:31:54 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54749674
Invoice No. 55345 - 54749674

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Scheduled		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	298,790 - DH

Activity Header
Activity: 15 016/000/000 SUSPENSION
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Jul-21	DSR108-075	RUBBER, SPRING, SHEAR, RUBBER, REAR, MOR/RYDE	1	152.75	152.75

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Jul-21	NELSON PIERRE-LOUIS	2.8333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	152.75
Labor:	0.00
Labor Hours:	2.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**152.75**

Work Order Footer

Work Order 54749674 Total	
Parts:	152.75
Labor:	0.00
Labor Hours:	2.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**152.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54744899
Invoice No. 55345 - 54744899

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Windshiel wipers not working.		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	298,572 - DH

Chronology		
Reported	Jul 20, 2021 10:18:12 PM	Jul 20, 2021 10:18:12 PM
Started	Jul 20, 2021 10:19:00 PM	
Completed	Jul 21, 2021 12:12:00 AM	Jul 21, 2021 12:12:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Windshield wipers stopped working.

Cause: Faulty wiper motor clip.

Correction: Replaced Wiper Motor clip.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 20-JUL-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jul 20, 2021 10:59:46 PM	No	
2 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Jul 20, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				10:59:46 PM		
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jul 20, 2021 10:59:46 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jul 20, 2021 10:59:46 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jul 20, 2021 10:59:46 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jul 20, 2021 10:59:46 PM	No	
20 - Miles			EARJOHNSON	Jul 20, 2021 10:59:46 PM	No	
30 - Kilometers			EARJOHNSON	Jul 20, 2021 10:59:46 PM	No	
40 - Hours			EARJOHNSON	Jul 20, 2021 10:59:46 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54744899
Invoice No. 55345 - 54744899

Client Department:
Department: 55345M
Work Order Description
Windshiel wipers not working.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 298,572 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note: Windshield wipers not working.
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Jul-21	E3TZ-17531-A	CLIP, ARM, WPER	1	7.38	7.38

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jul-21	Earl Johnson	1.68	0	0
21-Jul-21	Earl Johnson	0.2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	7.38
Labor:	0.00
Labor Hours:	1.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.38**

Work Order Footer

Work Order 54744899 Total	
Parts:	7.38
Labor:	0.00
Labor Hours:	1.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.38**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54671059
Invoice No. 55345 - 54671059

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345 PER DVIR exhaust fumes		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	295,437 - DH

Chronology		
Reported	Jun 22, 2021 11:02:00 AM	Jun 22, 2021 11:02:00 AM
Started	Jun 22, 2021 11:16:00 AM	
Completed	Jun 22, 2021 12:40:00 PM	Jun 22, 2021 12:40:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: Driver stated that vehicle had fumes coming out of exhaust

Cause: Couldn¿t duplicate the complaint...

Correction: No issues found....

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 22-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jun 22, 2021 11:19:05 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jun 22, 2021 11:19:05 AM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Jun 22, 2021 11:19:05 AM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Jun 22, 2021 11:19:05 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jun 22, 2021 11:19:05 AM	No	
10 - Have you successfully completed the Personal	Done		TDELVA	Jun 22, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				11:19:05 AM		
20 - Miles			TDELVA	Jun 22, 2021 11:19:05 AM	No	
30 - Kilometers			TDELVA	Jun 22, 2021 11:19:05 AM	No	
40 - Hours			TDELVA	Jun 22, 2021 11:19:05 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54671059
Invoice No. 55345 - 54671059

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR exhaust fumes
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 295,437 - DH

Activity Header
Activity:20
Activity Note: VERIFY COMPLAINT
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Jun-21	Delva,Terry	1.4	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54671059 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53557879
Invoice No. 55345 - 53557879

Client Department:
Department: 55345M
Work Order Description
55345-PTC INSPECTION
Requested By: NSTOLFO
Created By: NSTOLFO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 295,397 -

Chronology		
Reported	Jun 15, 2021 12:47:13 PM	Jun 15, 2021 12:47:13 PM
Started		
Completed	Jun 20, 2021 3:57:00 PM	Jun 20, 2021 3:57:00 PM
Down Time		

Work Order Notes

Line 10 Performed

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 20-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jun 20, 2021 3:09:06 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jun 20, 2021 3:09:06 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Jun 20, 2021 3:09:06 PM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Jun 20, 2021 3:09:06 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jun 20, 2021 3:09:06 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jun 20, 2021 3:09:06 PM	No	
20 - Miles			TDELVA	Jun 20, 2021 3:09:06 PM	No	
30 - Kilometers			TDELVA	Jun 20, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:09:06 PM		
40 - Hours			TDELVA	Jun 20, 2021 3:09:06 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53558055
Invoice No. 55345 - 53558055

Client Department:
Department: 55345M
Work Order Description
55345-FIRE SAFETY INSPECTION
Requested By: NSTOLFO
Created By: NSTOLFO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 295,397 -

Chronology		
Reported	Jun 15, 2021 12:47:13 PM	Jun 15, 2021 12:47:13 PM
Started		
Completed	Jun 20, 2021 3:57:00 PM	Jun 20, 2021 3:57:00 PM
Down Time		

Work Order Notes

Line 10 Performed

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 20-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jun 20, 2021 3:17:04 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jun 20, 2021 3:17:04 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Jun 20, 2021 3:17:04 PM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Jun 20, 2021 3:17:04 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jun 20, 2021 3:17:04 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jun 20, 2021 3:17:04 PM	No	
20 - Miles			TDELVA	Jun 20, 2021 3:17:04 PM	No	
30 - Kilometers			TDELVA	Jun 20, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:17:04 PM		
40 - Hours			TDELVA	Jun 20, 2021 3:17:04 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53557879
Invoice No. 55345 - 53557879

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-PTC INSPECTION		Ford E350 Champion Crusaders	
Requested By:	NSTOLFO	**Status:**	40 - Closed (40)
Created By:	NSTOLFO	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	295,397 -

Activity Header
Activity: 15 999 TOTAL VEHICLE
Activity Note: PTC INSPECTION
Reason for Repair: 11 Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53557879 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53558055
Invoice No. 55345 - 53558055

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-FIRE SAFETY INSPECTION		Ford E350 Champion Crusaders	
Requested By:	NSTOLFO	**Status:**	40 - Closed (40)
Created By:	NSTOLFO	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	295,397 -

Activity Header
Activity: 15 999 TOTAL VEHICLE
Activity Note: ANNUAL FIRE SAFETY INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53558055 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54664706
Invoice No. 55345 - 54664706

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
REAR AC SYSTEM		Ford E350 Champion Crusaders	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	295,397 - DH

Chronology		
Reported	Jun 20, 2021 3:47:20 PM	Jun 20, 2021 3:47:20 PM
Started	Jun 20, 2021 12:00:00 AM	
Completed	Jun 20, 2021 3:51:00 PM	Jun 20, 2021 3:51:00 PM
Down Time		

Work Order Notes

Line 10 Replaced Rear AC accumulator and Orifice tube
Replaced rear AC Relay Board

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 20-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jun 20, 2021 3:51:13 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jun 20, 2021 3:51:13 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Jun 20, 2021 3:51:13 PM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Jun 20, 2021 3:51:13 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jun 20, 2021 3:51:13 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jun 20, 2021 3:51:13 PM	No	
20 - Miles			TDELVA	Jun 20, 2021 3:51:13 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30 - Kilometers			TDELVA	Jun 20, 2021 3:51:13 PM	No	
40 - Hours			TDELVA	Jun 20, 2021 3:51:13 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54664706
Invoice No. 55345 - 54664706

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
REAR AC SYSTEM		Ford E350 Champion Crusaders	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	295,397 - DH

Activity Header
Activity: 20 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 51 Inoperative
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Jun-21	04278801A	BOARD, RELAY, A/C	1	153.43	153.43
20-Jun-21	08813825A	ACCUMLATOR, A/C	1	31.83	31.83
20-Jun-21	3411885	TUBE, ORIFICE, A/C, FORD	2	0.73	1.46

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jun-21	Delva,Terry	4.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	186.72
Labor:	0.00
Labor Hours:	4.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**186.72**

Work Order Footer

Work Order 54664706 Total	
Parts:	186.72
Labor:	0.00
Labor Hours:	4.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**186.72**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54546723
Invoice No. 55345 - 54546723

Client Department:
Department: 55345M
Work Order Description
FIRST TRANSIT - NORTH AMERICA - CONSPICUITY
Requested By: DGALLAGHER
Created By: DGALLAGHER
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 291,413 - DH

Chronology		
Reported	May 11, 2021 2:28:39 PM	May 11, 2021 2:28:39 PM
Started		
Completed	Jun 18, 2021 10:56:00 AM	Jun 18, 2021 10:56:00 AM
Down Time		

Work Order Notes

Line 10 Add Tape

Activity Header
Activity: 10 999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 18-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jun 18, 2021 10:54:40 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jun 18, 2021 10:54:40 AM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Jun 18, 2021 10:54:40 AM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Jun 18, 2021 10:54:40 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jun 18, 2021 10:54:40 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jun 18, 2021 10:54:40 AM	No	
20 - Miles			TDELVA	Jun 18, 2021 10:54:40 AM	No	
30 - Kilometers			TDELVA	Jun 18, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:54:40 AM		
40 - Hours			TDELVA	Jun 18, 2021 10:54:40 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54546723
Invoice No. 55345 - 54546723

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
FIRST TRANSIT - NORTH AMERICA - CONSPICUITY		Ford E350 Champion Crusaders	
Requested By:	DGALLAGHER	**Status:**	40 - Closed (40)
Created By:	DGALLAGHER	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	291,413 - DH

Activity Header
Activity:20 053/005/018 TAPE, REFLECTIVE
Activity Note: FIRST TRANSIT - NORTH AMERICA - CONSPICUITY
Reason for Repair: IC Internal Campaign
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: FIRST TRANSIT - NORTH AMERICA - CONSPICUITY
Task: FIRST TRANSIT - NORTH AMERICA - CONSPICUITY Performed by: TDELVA Performed on: 18-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Inspect Conspicuity tape:		Add Tape	TDELVA	Jun 18, 2021 10:54:56 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54546723 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53558237
Invoice No. 55345 - 53558237

Client Department:
Department: 55345M
Work Order Description
55345-A/C INSPECTION PERFORMED
Requested By: NSTOLFO
Created By: NSTOLFO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 295,241 -

Chronology		
Reported	Jun 15, 2021 12:47:13 PM	Jun 15, 2021 12:47:13 PM
Started		
Completed	Jun 18, 2021 9:22:00 AM	Jun 18, 2021 9:22:00 AM
Down Time		

Work Order Notes

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: CVERGARA Performed on: 18-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		CVERGARA	Jun 18, 2021 9:22:00 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		CVERGARA	Jun 18, 2021 9:22:00 AM	No	
3 - Are you wearing the appropriate PPE?	Done		CVERGARA	Jun 18, 2021 9:22:00 AM	No	
4 - Have you performed the proper LOTO?	Done		CVERGARA	Jun 18, 2021 9:22:00 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		CVERGARA	Jun 18, 2021 9:22:00 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		CVERGARA	Jun 18, 2021 9:22:00 AM	No	
20 - Miles			CVERGARA	Jun 18, 2021 9:22:00 AM	No	
30 - Kilometers			CVERGARA	Jun 18, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:22:00 AM		
40 - Hours			CVERGARA	Jun 18, 2021 9:22:00 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53558237
Invoice No. 55345 - 53558237

Client Department:
Department: 55345M
Work Order Description
55345-A/C INSPECTION PERFORMED
Requested By: NSTOLFO
Created By: NSTOLFO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 295,241 -

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: ANNUAL A/C INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53558237 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54654123
Invoice No. 55345 - 54654123

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
COOLING SISTEM		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	295,194 - DH

Chronology		
Reported	Jun 16, 2021 7:23:00 AM	Jun 16, 2021 7:23:00 AM
Started	Jun 16, 2021 7:47:00 AM	
Completed	Jun 17, 2021 12:43:00 PM	Jun 17, 2021 12:43:00 PM
Down Time		

Work Order Notes

Line 10 C: Coolant leak

C: inspect system for leak found right rear corner of intake manifold is leaking further inspection when the intake was off indicates that gasket was damaged when was install previously

C: Replaced gaskets and 1 ignition coil, retest system and road test vehicle ok at this time

Parts:
1 intake gasket ac2z-9439-a
1 intake gasket ac2z-9439-b
1 gasket yl3z-8c387-aa
1 gasket yl3z-8c388-aa
1 coil 26326
1 spark plug ap103

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 17-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Jun 17, 2021 12:42:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Jun 17, 2021 12:42:38 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Jun 17, 2021 12:42:38 PM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Jun 17, 2021 12:42:38 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Jun 17, 2021 12:42:38 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Jun 17, 2021 12:42:38 PM	No	
20 - Miles			JAPEREZ	Jun 17, 2021 12:42:38 PM	No	
30 - Kilometers			JAPEREZ	Jun 17, 2021 12:42:38 PM	No	
40 - Hours			JAPEREZ	Jun 17, 2021 12:42:38 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54654123
Invoice No. 55345 - 54654123

Client Department:
Department: 55345M
Work Order Description
COOLING SISTEM
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 295,194 - DH

Activity Header
Activity: 20 041 INTAKE, AIR
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Jun-21	AP103	PLUG, SPARK	1	3.35	3.35
17-Jun-21	26326	PLUG, COIL, IGNITION	1	24.57	24.57
17-Jun-21	40520	BLADE, WIPER, WINDSHIELD, 20"	2	4.4	8.8
17-Jun-21	YL3Z-8C388-AA	GASKET, PIPE, EXHAUST, CROSSOVER, 5.4L	1	5.54	5.54
17-Jun-21	AC2Z-9439-A	GASKET, MANIFOLD, INTAKE	1	20.45	20.45
17-Jun-21	AC2Z-9439-B	GASKET, MANIFOLD, INTAKE	1	12.55	12.55

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jun-21	Perez,Javier	7.67	0	0
17-Jun-21	Perez,Javier	4.97	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	75.26
Labor:	0.00
Labor Hours:	12.64
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**75.26**

Work Order Footer

Work Order 54654123 Total	
Parts:	75.26
Labor:	0.00
Labor Hours:	12.64
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**75.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54653314
Invoice No. 55345 - 54653314

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
FOLLOWUP-FT Light Duty		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	295,194 - DH

Chronology

Reported	Jun 15, 2021 6:55:21 PM	Jun 15, 2021 6:55:21 PM
Started	Jun 15, 2021 7:02:00 PM	
Completed	Jun 15, 2021 7:54:00 PM	Jun 15, 2021 7:54:00 PM
Down Time		

Work Order Notes

Line 10 Remove&Replace Serpentine belt. & Remove & Replace Tag Light .
Parts # 1360K6 Qty (1)
Parts # 3975927 Qty (1)

Activity Header
Activity: 10 002/008/001 PANEL, DASH
Activity Note: Tag Light Out
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Jun-21	3975927	LAMP, PLATE, LICENSE	1	11.96	11.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Jun-21	Arthurs,Durvin	0.35	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	11.96
Labor:	0.00
Labor Hours:	0.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**11.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54653314
Invoice No. 55345 - 54653314

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
FOLLOWUP-FT Light Duty		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	295,194 - DH

Activity Header
Activity: 20 042/004 PUMP, WATER
Activity Note: Serpentine belt
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Jun-21	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	21	21

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Jun-21	Arthurs,Durvin	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	21.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**21.00**

Work Order Footer

Work Order 54653314 Total	
Parts:	32.96
Labor:	0.00
Labor Hours:	0.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**32.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54535202
Invoice No. 55345 - 54535202

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	295,194 - DH

Chronology		
Reported	Jun 15, 2021 12:00:00 AM	Jun 15, 2021 12:00:00 AM
Started	Jun 15, 2021 12:00:00 AM	
Completed	Jun 15, 2021 7:01:00 PM	Jun 15, 2021 7:01:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PMA Service

CAUSE: Service Due by Mileage.

CORRECTION: Change Oil & Filter. Lube all Pivoting Points . Check brakes. Clean batteries.
Parts # B329 Qty (1)
Oil 10W30 Qty (6.5) Qt

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 15-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jun 15, 2021 6:57:30 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jun 15, 2021 6:57:30 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jun 15, 2021 6:57:30 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jun 15, 2021 6:57:30 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jun 15, 2021 6:57:30 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jun 15, 2021 6:57:30 PM	No	
20 - Miles			DARTHURS	Jun 15, 2021 6:57:30 PM	No	
30 - Kilometers			DARTHURS	Jun 15, 2021 6:57:30 PM	No	
40 - Hours			DARTHURS	Jun 15, 2021 6:57:30 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54535202
Invoice No. 55345 - 54535202

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	295,194 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Jun-21	Arthurs,Durvin	1.57	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: DARTHURS Performed on: 15-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		DARTHURS	Jun 15, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				6:55:19 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	-	Tag Light Out	DARTHURS	Jun 15, 2021 6:55:19 PM	Yes	54653314
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
20,800 - INSPECT_High Idle Control	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
31,000 - SSF (Street Side Front)	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
32,000 - Engine Inspection	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	NA	DARTHURS	Jun 15, 2021 6:55:19 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	DARTHURS	Jun 15, 2021 6:55:19 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	-	Serpentine belt	DARTHURS	Jun 15, 2021 6:55:19 PM	Yes	54653314
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
32,100 - INSPECT_Intake System	Done	intake Leaking	DARTHURS	Jun 15, 2021 6:55:19 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	0 Volt*		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
33,010 - CSF (Curb Side Front)	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	13.89 Volt*		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		DARTHURS	Jun 15, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression				6:55:19 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
50,400 - LUBE_All Chassis Components	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
50,700 - INSPECT_Tire Condition	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	11 32nds of an inch		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	11 32nds of an inch		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.554 Inch		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.554 Inch		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
52,100 - INSPECT_Vibration Damper	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
53,600 - INSPECT_Tire Condition	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	9 32nds of an inch		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	10 32nds of an inch		DARTHURS	Jun 15, 2021 6:55:19 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	7 32nds of an inch		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	1.414 Inch		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	1.414 Inch		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	23245 Cycles		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
60,800 - INSPECT_Operation of Platform Barrier	Done		DARTHURS	Jun 15, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Mechanism				6:55:19 PM		
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
62,400 - INSPECT_All Pivot Points	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
62,500 - INSPECT_Cams and Slots	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
62,600 - INSPECT_Rollers	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
62,700 - INSPECT_All Linkages	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		DARTHURS	Jun 15, 2021 6:55:19 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.57
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54535202
Invoice No. 55345 - 54535202

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: DKNOTT
Created By: DKNOTT
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 295,194 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Jun-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.98	1.98

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Jun-21	Arthurs,Durvin	0.33	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 15-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Jun 15, 2021 6:56:42 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Jun 15, 2021 6:56:42 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Jun 15, 2021 6:56:42 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Jun 15, 2021 6:56:42 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Jun 15, 2021 6:56:42 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Jun 15, 2021 6:56:42 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		DARTHURS	Jun 15, 2021 6:56:42 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Jun 15, 2021 6:56:42 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.98
Labor:	0.00
Labor Hours:	0.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.98**

Work Order Footer

Work Order 54535202 Total	
Parts:	1.98
Labor:	0.00
Labor Hours:	1.90
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.98**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54532460
Invoice No. 55345 - 54532460

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Motor Mount		Ford E350 Champion Crusaders	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	290,877 - DH

Chronology		
Reported	May 6, 2021 2:08:02 PM	May 6, 2021 2:08:02 PM
Started	May 6, 2021 12:00:00 AM	
Completed	May 7, 2021 2:59:00 PM	May 7, 2021 2:59:00 PM
Down Time		

Work Order Notes

Line 10 Replaced Lift rubber bumper

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 07-MAY-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	May 7, 2021 8:40:24 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	May 7, 2021 8:40:24 AM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	May 7, 2021 8:40:24 AM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	May 7, 2021 8:40:24 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	May 7, 2021 8:40:24 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	May 7, 2021 8:40:24 AM	No	
20 - Miles			TDELVA	May 7, 2021 8:40:24 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30 - Kilometers			TDELVA	May 7, 2021 8:40:24 AM	No	
40 - Hours			TDELVA	May 7, 2021 8:40:24 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54532460
Invoice No. 55345 - 54532460

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Motor Mount		Ford E350 Champion Crusaders	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	290,877 - DH

Activity Header
Activity: 20 016/000/000 SUSPENSION
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-May-21	Delva,Terry	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54532460
Invoice No. 55345 - 54532460

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Motor Mount		Ford E350 Champion Crusaders	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	290,877 - DH

Activity Header
Activity: 30 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-May-21	32831	SPRING, SHOCK, GAS, W/C	1	26.61	26.61
06-May-21	32408	BUMPER, RUBBER, W/C, BRAUN SAME AS 32408-10KS	4	2	8

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-May-21	Delva,Terry	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	34.61
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**34.61**

Work Order Footer

Work Order 54532460 Total	
Parts:	34.61
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**34.61**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54535099
Invoice No. 55345 - 54535099

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMB		Ford E350 Champion Crusaders	
Requested By:	DKNOTT	**Status:**	99 - Cancelled (99)
Created By:	DKNOTT	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	290,934 - DH

Chronology		
Reported	May 7, 2021 12:06:50 PM	May 7, 2021 12:06:50 PM
Started		
Completed	May 7, 2021 12:08:27 PM	May 7, 2021 12:08:27 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION:

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	-				No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	-				No	
3 - Are you wearing the appropriate PPE?	-				No	
4 - Have you performed the proper LOTO?	-				No	
5 - Are you aware of the potential risks of performing this repair?	-				No	
10 - Have you successfully completed the Personal Risk Assessment?	-				No	
20 - Miles					No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30 - Kilometers					No	
40 - Hours					No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54535099
Invoice No. 55345 - 54535099

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMB		Ford E350 Champion Crusaders	
Requested By:	DKNOTT	**Status:**	99 - Cancelled (99)
Created By:	DKNOTT	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	290,934 - DH

Activity Header
Activity: 10
Activity Note: Light Duty PMI
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	-				No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	-				No	
10,200 - !FRA!INSPECT_Starter Operation	-				No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	-				No	
10,400 - !FRA!INSPECT_Back Up Alarm	-				No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	-				No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	-				No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	-				No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	-				No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	-				No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	-				No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	-				No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	-				No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive	-				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
into Shop						
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	-				No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	-				No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	-				No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	-				No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	-				No	
20,800 - INSPECT_High Idle Control	-				No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	-				No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	-				No	
21,100 - INSPECT_Parking Brake Operation	-				No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	-				No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	-				No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	-				No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	-				No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	-				No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	-				No	
21,700 - INSPECT_Engine Fault Codes	-				No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	-				No	
31,000 - SSF (Street Side Front)	-				No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	-				No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	-				No	
31,030 - INSPECT_Mud Flaps, Brackets	-				No	
31,040 - INSPECT_Wiper Blades, Arms	-				No	
32,000 - Engine Inspection	-				No	
32,010 - INSPECT_Hood, Springs and Props	-				No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	-				No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	-				No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-				No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit				No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	-				No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	-				No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	-				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	-				No	
32,100 - INSPECT_Intake System	-				No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	Volt*				No	
33,010 - CSF (Curb Side Front)	-				No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	-				No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	-				No	
33,040 - INSPECT_Mud Flaps, Brackets	-				No	
33,050 - INSPECT_Wiper Blades, Arms	-				No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	-				No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*				No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	-				No	
40,000 - SECTION 4 - Interior Inspection	-				No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	-				No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	-				No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	-				No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	-				No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	-				No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	-				No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	-				No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	-				No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	-				No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	-				No	
41,100 - INSPECT_CLEAN_AC Filter	-				No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	-				No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	-				No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	-				No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	-				No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	-				No	
50,200 - INSPECT_Ball Joint Play	-				No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	-				No	
50,400 - LUBE_All Chassis Components	-				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,500 - !FRA!CHANGE_Engine oil,filters	-				No	
50,700 - INSPECT_Tire Condition	-				No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	-				No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	-				No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	32nds of an inch				No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	Pounds per Square Inch				No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	32nds of an inch				No	
51,300 - RECORD_RF-Air Pressure (psi)	Pounds per Square Inch				No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	-				No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	-				No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	-				No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	32nds of an inch				No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	32nds of an inch				No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	Inch				No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	Inch				No	
52,100 - INSPECT_Vibration Damper	-				No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	-				No	
52,400 - !FRA!INSPECT_ Starter Mounting	-				No	
52,500 - !FRA!INSPECT_Engine Exhaust System	-				No	
52,700 - INSPECT_ Engine, Transmission Mounts	-				No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	-				No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	-				No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	-				No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	-				No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	-				No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	-				No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	-				No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	-				No	
53,600 - INSPECT_Tire Condition	-				No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	-				No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	-				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,900 - INSPECT_Dual Mating Tires w/Square	-				No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	-				No	
54,100 - INSPECT_Mud Flaps, Brackets	-				No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	32nds of an inch				No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	32nds of an inch				No	
54,400 - RECORD_RRO-Air Pressure (psi)	Pounds per Square Inch				No	
54,500 - RECORD_RRI-Air Pressure (psi)	Pounds per Square Inch				No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	32nds of an inch				No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	32nds of an inch				No	
54,800 - RECORD_LRO-Air Pressure (psi)	Pounds per Square Inch				No	
54,900 - RECORD_LRI-Air Pressure (psi)	Pounds per Square Inch				No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	-				No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	-				No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	-				No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	32nds of an inch				No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	32nds of an inch				No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	Inch				No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	Inch				No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	-				No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	-				No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	-				No	
60,000 - SECTION 6 - Wheelchair Inspection	-				No	
60,100 - RECORD_Wheelchair Cycle Count	Cycles				No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	-				No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	-				No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	-				No	
60,500 - INSPECT_ Bridgeplate Operation	-				No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	-				No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	-				No	
60,800 - INSPECT_Operation of Platform Barrier	-				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Mechanism						
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	-				No	
61,000 - INSPECT_Cable Condition (If Applicable)	-				No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	-				No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	-				No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	-				No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	-				No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	-				No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	-				No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	-				No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	-				No	
61,900 - CLEAN_Linkages and Mechanisms	-				No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	-				No	
62,100 - INSPECT_Emergency Platform Release Mechanism	-				No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	-				No	
62,300 - INSPECT_Bridgeplate Hinge	-				No	
62,400 - INSPECT_All Pivot Points	-				No	
62,500 - INSPECT_Cams and Slots	-				No	
62,600 - INSPECT_Rollers	-				No	
62,700 - INSPECT_All Linkages	-				No	
80,000 - SECTION 8 - PMI Report Completion	-				No	
80,100 - COMPLETE_PM Report; Follow-ups	-				No	
80,200 - RETURN_Vehicle to Predetermined Location	-				No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54535099
Invoice No. 55345 - 54535099

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMB
Requested By: DKNOTT
Created By: DKNOTT
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 99 - Cancelled (99)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 290,934 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	-				No	
101,000 - FRA Change Oil Filters	No				No	
102,000 - FRA Drain Engine Oil	No				No	
103,000 - FRA Check Transmission Fluid	-				No	
104,000 - Lubricate Chassis	-				No	
105,000 - Replace or Clean A/C Filters	-				No	
107,000 - FRA Change Primary Fuel Filter	No				No	
108,000 - Lube all pivoting Mechanisms	-				No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	-				No	
201,000 - Service Crankcase Breather	-				No	
203,000 - FRA Change Automatic Transmission Fluid	No				No	
204,000 - FRA Change Power Steering Fluid and Filter	No				No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	-				No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 54535099 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54412407
Invoice No. 55345 - 54412407

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	290,934 - DH

Chronology		
Reported	May 6, 2021 9:37:22 AM	May 6, 2021 9:37:22 AM
Started	May 6, 2021 11:55:00 AM	
Completed	May 7, 2021 11:47:23 AM	May 7, 2021 11:47:23 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA

CAUSE: Service due

CORRECTION: Performed PMA Completed PMA service

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 07-MAY-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	May 7, 2021 8:40:47 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	May 7, 2021 8:40:47 AM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	May 7, 2021 8:40:47 AM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	May 7, 2021 8:40:47 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	May 7, 2021 8:40:47 AM	No	
10 - Have you successfully completed the Personal	Done		TDELVA	May 7, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				8:40:47 AM		
20 - Miles			TDELVA	May 7, 2021 8:40:47 AM	No	
30 - Kilometers			TDELVA	May 7, 2021 8:40:47 AM	No	
40 - Hours			TDELVA	May 7, 2021 8:40:47 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54412407
Invoice No. 55345 - 54412407

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 290,934 - DH

Activity Header
Activity: 10
Activity Note: Light Duty PMI
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-May-21	Delva,Terry	2.2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: TDELVA Performed on: 07-MAY-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		TDELVA	May 7, 2021 8:54:07 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
20,800 - INSPECT_High Idle Control	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
21,100 - INSPECT_Parking Brake Operation	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
21,700 - INSPECT_Engine Fault Codes	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
31,000 - SSF (Street Side Front)	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		TDELVA	May 7, 2021 8:54:07 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,000 - Engine Inspection	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	TDELVA	May 7, 2021 8:54:07 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
32,100 - INSPECT_Intake System	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	0 Volt*	na	TDELVA	May 7, 2021 8:54:07 AM	No	
33,010 - CSF (Curb Side Front)	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	12.89 Volt*		TDELVA	May 7, 2021 8:54:07 AM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	12.9 Volt*		TDELVA	May 7, 2021 8:54:07 AM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		TDELVA	May 7, 2021 8:54:07 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
50,400 - LUBE_All Chassis Components	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
50,700 - INSPECT_Tire Condition	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	10 32nds of an inch		TDELVA	May 7, 2021 8:54:07 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		TDELVA	May 7, 2021 8:54:07 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	10 32nds of an inch		TDELVA	May 7, 2021 8:54:07 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		TDELVA	May 7, 2021 8:54:07 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		TDELVA	May 7, 2021 8:54:07 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	May 7, 2021 8:54:07 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	May 7, 2021 8:54:07 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	38.5 Inch		TDELVA	May 7, 2021 8:54:07 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	38.5 Inch		TDELVA	May 7, 2021 8:54:07 AM	No	
52,100 - INSPECT_Vibration Damper	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
53,600 - INSPECT_Tire Condition	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	-	na	TDELVA	May 7, 2021 8:54:07 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	9 32nds of an inch		TDELVA	May 7, 2021 8:54:07 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	9 32nds of an inch		TDELVA	May 7, 2021 8:54:07 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		TDELVA	May 7, 2021 8:54:07 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		TDELVA	May 7, 2021 8:54:07 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	9 32nds of an inch		TDELVA	May 7, 2021 8:54:07 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	9 32nds of an inch		TDELVA	May 7, 2021 8:54:07 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		TDELVA	May 7, 2021 8:54:07 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		TDELVA	May 7, 2021 8:54:07 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	May 7, 2021 8:54:07 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	May 7, 2021 8:54:07 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	37.8 Inch		TDELVA	May 7, 2021 8:54:07 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	37.8 Inch		TDELVA	May 7, 2021 8:54:07 AM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
60,100 - RECORD_Wheelchair Cycle Count	0 Cycles		TDELVA	May 7, 2021 8:54:07 AM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		TDELVA	May 7, 2021 8:54:07 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
62,400 - INSPECT_All Pivot Points	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
62,500 - INSPECT_Cams and Slots	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
62,600 - INSPECT_Rollers	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
62,700 - INSPECT_All Linkages	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		TDELVA	May 7, 2021 8:54:07 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		TDELVA	May 7, 2021 8:54:07 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54412407
Invoice No. 55345 - 54412407

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	290,934 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-May-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.98	1.98
07-May-21	65266	PLUG, DRAIN, OIL, ENGINE	1	4.25	4.25

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: TDELVA Performed on: 07-MAY-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		TDELVA	May 7, 2021 8:41:16 AM	No	
101,000 - FRA Change Oil Filters	Yes		TDELVA	May 7, 2021 8:41:16 AM	No	
102,000 - FRA Drain Engine Oil	Yes		TDELVA	May 7, 2021 8:41:16 AM	No	
103,000 - FRA Check Transmission Fluid	Done		TDELVA	May 7, 2021 8:41:16 AM	No	
104,000 - Lubricate Chassis	Done		TDELVA	May 7, 2021 8:41:16 AM	No	
105,000 - Replace or Clean A/C Filters	Done		TDELVA	May 7, 2021 8:41:16 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	TDELVA	May 7, 2021 8:41:16 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		TDELVA	May 7, 2021 8:41:16 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	6.23
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**6.23**

Work Order Footer

Work Order 54412407 Total	
Parts:	6.23
Labor:	0.00
Labor Hours:	2.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**6.23**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54530969
Invoice No. 55345 - 54530969

Client Department:
Department: 55345M
Work Order Description
55345 PER driver fuel odor inside the bus
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 290,783 - DH

Chronology		
Reported	May 6, 2021 8:58:00 AM	May 6, 2021 8:58:00 AM
Started	May 6, 2021 9:07:00 AM	
Completed	May 6, 2021 9:43:00 AM	May 6, 2021 9:43:00 AM
Down Time		

Work Order Notes

Line 10 C: as per driver vehicle smell of gas

C: inspect all related items to fuel inside and out found gas cap was not installed properly

C: complete task

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 06-MAY-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	May 6, 2021 9:42:43 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	May 6, 2021 9:42:43 AM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	May 6, 2021 9:42:43 AM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	May 6, 2021 9:42:43 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	May 6, 2021 9:42:43 AM	No	
10 - Have you successfully completed the Personal	Done		JAPEREZ	May 6, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				9:42:43 AM		
20 - Miles			JAPEREZ	May 6, 2021 9:42:43 AM	No	
30 - Kilometers			JAPEREZ	May 6, 2021 9:42:43 AM	No	
40 - Hours			JAPEREZ	May 6, 2021 9:42:43 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54530969
Invoice No. 55345 - 54530969

Client Department:
Department: 55345M
Work Order Description
55345 PER driver fuel odor inside the bus
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 290,783 - DH

Activity Header
Activity: 20 044 FUEL SYSTEM
Activity Note: VERIFY COMPLAINT
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-May-21	Perez,Javier	0.55	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54530969 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54425881
Invoice No. 55345 - 54425881

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Front AC malfunction.		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	286,733 - DH

Chronology		
Reported	Mar 30, 2021 5:55:54 PM	Mar 30, 2021 5:55:54 PM
Started	Mar 30, 2021 5:59:00 PM	
Completed	Mar 30, 2021 7:13:00 PM	Mar 30, 2021 7:13:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Front AC malfunction.

Cause: Faulty blower motor.

Correction: Remove and replaced front AC blower motor.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Mar-21	Earl Johnson	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 30-MAR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Mar 30, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				7:10:44 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Mar 30, 2021 7:10:44 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Mar 30, 2021 7:10:44 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Mar 30, 2021 7:10:44 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Mar 30, 2021 7:10:44 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Mar 30, 2021 7:10:44 PM	No	
20 - Miles			EARJOHNSON	Mar 30, 2021 7:10:44 PM	No	
30 - Kilometers			EARJOHNSON	Mar 30, 2021 7:10:44 PM	No	
40 - Hours			EARJOHNSON	Mar 30, 2021 7:10:44 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54425881
Invoice No. 55345 - 54425881

Client Department:
Department: 55345M
Work Order Description
Front AC malfunction.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 286,733 - DH

Activity Header
Activity: 15 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Front AC malfunction.
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Mar-21	AC2Z-19834-A	WHEEL, MOTOR, BLOWER	1	29.83	29.83
30-Mar-21	XC2Z-19805-BA	MOTOR, BLOWER SAME AS MM-840	1	36.04	36.04

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Mar-21	Earl Johnson	1.18	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	65.87
Labor:	0.00
Labor Hours:	1.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**65.87**

Work Order Footer

Work Order 54425881 Total	
Parts:	65.87
Labor:	0.00
Labor Hours:	1.26
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**65.87**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54411891
Invoice No. 55345 - 54411891

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Rear brake pads		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	286,732 - DH

Chronology		
Reported	Mar 25, 2021 11:16:26 AM	Mar 25, 2021 11:16:26 AM
Started	Mar 25, 2021 11:17:00 AM	
Completed	Mar 25, 2021 1:24:00 PM	Mar 25, 2021 1:24:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: low tire,and rear brake pads

Cause: preventive maintenance

Correction: replaced rear brake pads,2 front tires

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 25-MAR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Mar 25, 2021 1:22:46 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Mar 25, 2021 1:22:46 PM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Mar 25, 2021 1:22:46 PM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Mar 25, 2021 1:22:46 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Mar 25, 2021 1:22:46 PM	No	
10 - Have you successfully completed the Personal	Done		NPIERRE-	Mar 25, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	1:22:46 PM		
20 - Miles			NPIERRE-LOUIS	Mar 25, 2021 1:22:46 PM	No	
30 - Kilometers			NPIERRE-LOUIS	Mar 25, 2021 1:22:46 PM	No	
40 - Hours			NPIERRE-LOUIS	Mar 25, 2021 1:22:46 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54411891
Invoice No. 55345 - 54411891

Client Department:
Department: 55345M
Work Order Description
Rear brake pads
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 286,732 - DH

Activity Header
Activity: 20 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Mar-21	NELSON PIERRE-LOUIS	1.93	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54411891
Invoice No. 55345 - 54411891

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Rear brake pads		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	286,732 - DH

Activity Header
Activity: 30 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Mar-21	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	117.57	235.14
25-Mar-21	9C2Z-2V200-B	PADS, BRAKE, DISC, REAR SAME AS BRSD1329B	1	40.88	40.88

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Mar-21	NELSON PIERRE-LOUIS	1.6	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	276.02
Labor:	0.00
Labor Hours:	1.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**276.02**

Work Order Footer

Work Order 54411891 Total	
Parts:	276.02
Labor:	0.00
Labor Hours:	3.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**276.02**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54296465
Invoice No. 55345 - 54296465

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	286,732 - DH

Chronology		
Reported	Mar 24, 2021 12:04:00 PM	Mar 24, 2021 12:04:00 PM
Started	Mar 25, 2021 9:03:00 AM	
Completed	Mar 25, 2021 1:11:00 PM	Mar 25, 2021 1:11:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PmA Service

CAUSE: preventive maintenance

CORRECTION: perform PmA Service and Lube all Pivoting Points

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 25-MAR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Mar 25, 2021 1:05:28 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Mar 25, 2021 1:05:28 PM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Mar 25, 2021 1:05:28 PM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Mar 25, 2021 1:05:28 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Mar 25, 2021 1:05:28 PM	No	
10 - Have you successfully completed the Personal	Done		NPIERRE-	Mar 25, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	1:05:28 PM		
20 - Miles			NPIERRE-LOUIS	Mar 25, 2021 1:05:28 PM	No	
30 - Kilometers			NPIERRE-LOUIS	Mar 25, 2021 1:05:28 PM	No	
40 - Hours			NPIERRE-LOUIS	Mar 25, 2021 1:05:28 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54296465
Invoice No. 55345 - 54296465

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 286,732 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Mar-21	NELSON PIERRE-LOUIS	2.2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS Performed on: 25-MAR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-	Mar 25, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	1:04:53 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
20,800 - INSPECT_High Idle Control	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
31,000 - SSF (Street Side Front)	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
32,000 - Engine Inspection	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	0 Degree Fahrenheit		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
32,100 - INSPECT_Intake System	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	13.5 Volt*		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
33,010 - CSF (Curb Side Front)	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	13.4 Volt*		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		NPIERRE-	Mar 25, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression			LOUIS	1:04:53 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
50,400 - LUBE_All Chassis Components	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
50,700 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	10 32nds of an inch		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	10 32nds of an inch		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	39.5 Inch		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	39.5 Inch		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
52,100 - INSPECT_Vibration Damper	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
53,600 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	5 32nds of an inch		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	10 32nds of an inch		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	11 32nds of an inch		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	4 32nds of an inch		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	4 32nds of an inch		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	35.5 Inch		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	35.5 Inch		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	0 Cycles		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper	Done		NPIERRE-	Mar 25, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alignment			LOUIS	1:04:53 PM		
61,000 - INSPECT_Cable Condition (If Applicable)	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
62,400 - INSPECT_All Pivot Points	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
62,500 - INSPECT_Cams and Slots	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
62,600 - INSPECT_Rollers	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
62,700 - INSPECT_All Linkages	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	Mar 25, 2021 1:04:53 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54296465
Invoice No. 55345 - 54296465

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 286,732 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Mar-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: NPIERRE-LOUIS Performed on: 25-MAR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Mar 25, 2021 1:06:08 PM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Mar 25, 2021 1:06:08 PM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Mar 25, 2021 1:06:08 PM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Mar 25, 2021 1:06:08 PM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Mar 25, 2021 1:06:08 PM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Mar 25, 2021 1:06:08 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		NPIERRE-LOUIS	Mar 25, 2021 1:06:08 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Mar 25, 2021 1:06:08 PM	No	

Activity Sub Total

Activity 20 Sub Total
Parts: 1.96

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order Footer

Work Order 54296465 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54296436
Invoice No. 55345 - 54296436

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP--->Replace Brakes
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 282,549 - DH

Chronology		
Reported	Feb 12, 2021 11:35:59 PM	Feb 12, 2021 11:35:59 PM
Started	Feb 12, 2021 11:40:00 PM	
Completed	Feb 22, 2021 5:01:00 PM	Feb 22, 2021 5:01:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========
To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.
==========

Complaint:needs front brakes and rotors

Cause: Wear and grooves

Correction:replaced front brakes; rotors ; bearings and seals
Brakes:8C2Z-2V001-D Qty1
Rotors:BC2Z-1102-B qty2
Inner bearings: LM102949 qty2
Outer bearings: 15101 qty2
Seals: SL260029 qty2
Repack bearings
Torque wheels 140 lbs second torque 140 lbs

Activity Header
Activity: 10 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: needs front brakes
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Feb-21	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	43.67	43.67

Activity Labor
No Data Available

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	43.67
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.67**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54296436
Invoice No. 55345 - 54296436

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP--->Replace Brakes
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 282,549 - DH

Activity Header
Activity: 20 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: needs front rotors
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Feb-21	LM102949	BEARING, WHEEL, INNER, FRONT, TAPERED	2	10.05	20.1
22-Feb-21	15101	BEARING, WHEEL, OUTER, FRONT	2	7.27	14.54
22-Feb-21	SL260029	SEAL, WHEEL	2	8.04	16.08
22-Feb-21	BC2Z-1102-B	ROTOR, BRAKE, DISC, FRONT W/INTEGRAL HUB	2	113.79	227.58

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Feb-21	Gaspard,Ronald	0.33	0	0
13-Feb-21	Gaspard,Ronald	0.53	0	0
17-Feb-21	Gaspard,Ronald	0.32	0	0
19-Feb-21	Gaspard,Ronald	0.02	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	278.30
Labor:	0.00
Labor Hours:	1.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**278.30**

Work Order Footer

Work Order 54296436 Total	
Parts:	321.97
Labor:	0.00
Labor Hours:	1.20
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**321.97**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54167857
Invoice No. 55345 - 54167857

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMC		Ford E350 Champion Crusaders	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	282,549 - DH

Chronology		
Reported	Feb 12, 2021 12:00:00 AM	Feb 12, 2021 12:00:00 AM
Started	Feb 12, 2021 9:15:00 PM	
Completed	Feb 13, 2021 12:32:00 AM	Feb 13, 2021 12:32:00 AM
Down Time		

Work Order Notes

Line 10 PMC
Service
Perform PMC Service
Oil filter B329 qty1
Engine oil 10w30 qty 7 qts
Air filter PA4075 qty1
Gear Oil 80w90 qty 4 qts

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 12-FEB-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Feb 12, 2021 9:15:09 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Feb 12, 2021 9:15:09 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Feb 12, 2021 9:15:09 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Feb 12, 2021 9:15:09 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Feb 12, 2021 9:15:09 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Feb 12, 2021 9:15:09 PM	No	
20 - Miles			RGASPARD	Feb 12, 2021 9:15:09 PM	No	
30 - Kilometers			RGASPARD	Feb 12, 2021 9:15:09 PM	No	
40 - Hours			RGASPARD	Feb 12, 2021 9:15:09 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54167857
Invoice No. 55345 - 54167857

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMC
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 282,549 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Feb-21	Gaspard,Ronald	1.92	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 12-FEB-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Feb 12, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:40:43 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
20,800 - INSPECT_High Idle Control	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	Feb 12, 2021 10:40:43 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Feb 12, 2021 10:40:43 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.23 Volt*		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.24 Volt*		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
33,010 - CSF (Curb Side Front)	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	RGASPARD	Feb 12, 2021 10:40:43 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
40,250 - INSPECT_Overhead Compartment for	Done		RGASPARD	Feb 12, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Water Leaks				10:40:43 PM		
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
50,400 - LUBE_All Chassis Components	Done	na	RGASPARD	Feb 12, 2021 10:40:43 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings,	Done		RGASPARD	Feb 12, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Sensors, Routing of Cables				10:40:43 PM		
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	3 32nds of an inch	needs front brakes	RGASPARD	Feb 12, 2021 10:40:43 PM	Yes	54296436
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	3 32nds of an inch		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	36 Inch	needs front rotors	RGASPARD	Feb 12, 2021 10:40:43 PM	Yes	54296436
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	36 Inch		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done	na	RGASPARD	Feb 12, 2021 10:40:43 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	36 Inch		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	36 Inch		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	17968 Cycles		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Feb 12, 2021 10:40:43 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54167857
Invoice No. 55345 - 54167857

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMC
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 282,549 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Feb-21	PA4075	FILTER, AIR SEE P546597	1	5.28	5.28
12-Feb-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Feb-21	Gaspard,Ronald	0.38	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: RGASPARD Performed on: 12-FEB-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Feb 12, 2021 11:11:58 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Feb 12, 2021 11:11:58 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Feb 12, 2021 11:11:58 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Feb 12, 2021 11:11:58 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Feb 12, 2021 11:11:58 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Feb 12, 2021 11:11:58 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	na	RGASPARD	Feb 12, 2021 11:11:58 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Feb 12, 2021 11:11:58 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Feb 12, 2021 11:11:58 PM	No	
201,000 - Service Crankcase Breather	Done		RGASPARD	Feb 12, 2021 11:11:58 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Feb 12, 2021 11:11:58 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Feb 12, 2021 11:11:58 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Feb 12, 2021 11:11:58 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		RGASPARD	Feb 12, 2021 11:11:58 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		RGASPARD	Feb 12, 2021 11:11:58 PM	No	
302,000 - Check Toe-In and Record Reading	-	na	RGASPARD	Feb 12, 2021 11:11:58 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	na	RGASPARD	Feb 12, 2021 11:11:58 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		RGASPARD	Feb 12, 2021 11:11:58 PM	No	
305,000 - FRA Change Differential Fluid	Yes		RGASPARD	Feb 12, 2021 11:11:58 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	7.24
Labor:	0.00
Labor Hours:	0.38
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.24**

Work Order Footer

Work Order 54167857 Total	
Parts:	7.24
Labor:	0.00
Labor Hours:	2.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.24**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54241190
Invoice No. 55345 - 54241190

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Wiper and Wiper Motor Clip		Ford E350 Champion Crusaders	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	280,505 - DH

Chronology		
Reported	Jan 26, 2021 8:54:12 AM	Jan 26, 2021 8:54:12 AM
Started	Jan 26, 2021 12:00:00 AM	
Completed	Jan 26, 2021 10:31:00 AM	Jan 26, 2021 10:31:00 AM
Down Time		

Work Order Notes

Line 10 Replaced wiper blades
Replaced right top mirror

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 26-JAN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jan 26, 2021 10:30:26 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jan 26, 2021 10:30:26 AM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Jan 26, 2021 10:30:26 AM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Jan 26, 2021 10:30:26 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jan 26, 2021 10:30:26 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jan 26, 2021 10:30:26 AM	No	
20 - Miles			TDELVA	Jan 26, 2021 10:30:26 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30 - Kilometers			TDELVA	Jan 26, 2021 10:30:26 AM	No	
40 - Hours			TDELVA	Jan 26, 2021 10:30:26 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54241190
Invoice No. 55345 - 54241190

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Wiper and Wiper Motor Clip		Ford E350 Champion Crusaders	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	280,505 - DH

Activity Header
Activity:20 050/000/000 GROUP, ACCESSORIES
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Jan-21	40520	BLADE, WIPER, WINDSHIELD, 20"	2	4.4	8.8

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Jan-21	Delva,Terry	0.9	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	8.80
Labor:	0.00
Labor Hours:	0.90
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54241190
Invoice No. 55345 - 54241190

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Wiper and Wiper Motor Clip		Ford E350 Champion Crusaders	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	280,505 - DH

Activity Header
Activity: 30 099/000/000 SAFETY DEVICES INSTRUMENTS & GAUGES (POWER UNITS, TRAILERS, ETC.)
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Jan-21	709770	PIVOT, HOUSING, GLASS, UPPER	1	24.53	24.53

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Jan-21	Delva,Terry	1.43	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	24.53
Labor:	0.00
Labor Hours:	1.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**24.53**

Work Order Footer

Work Order 54241190 Total	
Parts:	33.33
Labor:	0.00
Labor Hours:	2.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**33.33**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54047074
Invoice No. 55345 - 54047074

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	278,280 - DH

Chronology		
Reported	Dec 28, 2020 12:00:00 AM	Dec 28, 2020 12:00:00 AM
Started	Dec 29, 2020 12:57:00 PM	
Completed	Dec 29, 2020 2:52:00 PM	Dec 29, 2020 2:52:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Unit in for pM service A.
Please charge out filter for me it¿s not in the system B329
CAUSE:

CORRECTION: Service complete

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Dec-20	Junior Hurst	0.02	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 29-DEC-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Dec 29, 2020 12:58:04 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Dec 29, 2020 12:58:04 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Dec 29, 2020 12:58:04 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Dec 29, 2020 12:58:04 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Dec 29, 2020 12:58:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Dec 29, 2020 12:58:04 PM	No	
20 - Miles			JUHURST	Dec 29, 2020 12:58:04 PM	No	
30 - Kilometers			JUHURST	Dec 29, 2020 12:58:04 PM	No	
40 - Hours			JUHURST	Dec 29, 2020 12:58:04 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54047074
Invoice No. 55345 - 54047074

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 278,280 - DH

Activity Header
Activity: 10
Activity Note: Light Duty PMI
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Dec-20	3L3Z-8501-CA	PUMP, WATER, E450	1	36.96	36.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Dec-20	Junior Hurst	1.63	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: JUHURST Performed on: 29-DEC-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
20,800 - INSPECT_High Idle Control	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
32,000 - Engine Inspection	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Dec 29, 2020 2:36:43 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Dec 29, 2020 2:36:43 PM	No	
33,010 - CSF (Curb Side Front)	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	14 Volt*		JUHURST	Dec 29, 2020 2:36:43 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		JUHURST	Dec 29, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression				2:36:43 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
50,400 - LUBE_All Chassis Components	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
50,700 - INSPECT_Tire Condition	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Dec 29, 2020 2:36:43 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Dec 29, 2020 2:36:43 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Dec 29, 2020 2:36:43 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Dec 29, 2020 2:36:43 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		JUHURST	Dec 29, 2020 2:36:43 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		JUHURST	Dec 29, 2020 2:36:43 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	2 Inch		JUHURST	Dec 29, 2020 2:36:43 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	2 Inch		JUHURST	Dec 29, 2020 2:36:43 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	12 32nds of an inch		JUHURST	Dec 29, 2020 2:36:43 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	12 32nds of an inch		JUHURST	Dec 29, 2020 2:36:43 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Dec 29, 2020 2:36:43 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Dec 29, 2020 2:36:43 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	12 32nds of an inch		JUHURST	Dec 29, 2020 2:36:43 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	12 32nds of an inch		JUHURST	Dec 29, 2020 2:36:43 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Dec 29, 2020 2:36:43 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Dec 29, 2020 2:36:43 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		JUHURST	Dec 29, 2020 2:36:43 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		JUHURST	Dec 29, 2020 2:36:43 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	2 Inch		JUHURST	Dec 29, 2020 2:36:43 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	2 Inch		JUHURST	Dec 29, 2020 2:36:43 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	14485 Cycles		JUHURST	Dec 29, 2020 2:36:43 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper	Done		JUHURST	Dec 29, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alignment				2:36:43 PM		
61,000 - INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
62,400 - INSPECT_All Pivot Points	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
62,500 - INSPECT_Cams and Slots	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
62,600 - INSPECT_Rollers	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
62,700 - INSPECT_All Linkages	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	Dec 29, 2020 2:36:43 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	36.96
Labor:	0.00
Labor Hours:	1.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**36.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54047074
Invoice No. 55345 - 54047074

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 278,280 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Dec-20	Junior Hurst	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: JUHURST Performed on: 29-DEC-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		JUHURST	Dec 29, 2020 2:38:52 PM	No	
101,000 - FRA Change Oil Filters	Yes		JUHURST	Dec 29, 2020 2:38:52 PM	No	
102,000 - FRA Drain Engine Oil	Yes		JUHURST	Dec 29, 2020 2:38:52 PM	No	
103,000 - FRA Check Transmission Fluid	Done		JUHURST	Dec 29, 2020 2:38:52 PM	No	
104,000 - Lubricate Chassis	Done		JUHURST	Dec 29, 2020 2:38:52 PM	No	
105,000 - Replace or Clean A/C Filters	Done		JUHURST	Dec 29, 2020 2:38:52 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		JUHURST	Dec 29, 2020 2:38:52 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		JUHURST	Dec 29, 2020 2:38:52 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.05
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 54047074 Total	
Parts:	36.96
Labor:	0.00
Labor Hours:	1.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**36.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54151584
Invoice No. 55345 - 54151584

Client Department:
Department: 55345M
Work Order Description
FUEL PUMP
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 277,665 - DH

Chronology		
Reported	Dec 21, 2020 10:48:00 AM	Dec 21, 2020 10:48:00 AM
Started	Dec 21, 2020 10:56:00 AM	
Completed	Dec 23, 2020 12:07:00 AM	Dec 23, 2020 12:07:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Bus Stalling.

Cause: Fuel pump.

Correction: Remove & Replace fuel pump.
Parts #AC2Z-9H307-D Qty (1)

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 22-DEC-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Dec 22, 2020 5:44:11 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Dec 22, 2020 5:44:11 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Dec 22, 2020 5:44:11 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Dec 22, 2020 5:44:11 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Dec 22, 2020 5:44:11 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Dec 22, 2020 5:44:11 PM	No	
20 - Miles			DARTHURS	Dec 22, 2020 5:44:11 PM	No	
30 - Kilometers			DARTHURS	Dec 22, 2020 5:44:11 PM	No	
40 - Hours			DARTHURS	Dec 22, 2020 5:44:11 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54151584
Invoice No. 55345 - 54151584

Client Department:
Department: 55345M
Work Order Description
FUEL PUMP
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 277,665 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Dec-20	Perez,Javier	4.73	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	4.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54151584
Invoice No. 55345 - 54151584

Client Department:
Department: 55345M
Work Order Description
FUEL PUMP
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 277,665 - DH

Activity Header
Activity:20 042/000/000 COOLING SYSTEM
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Dec-20	AC2Z-9H307-D	PUMP, FUEL, E350	1	237.48	237.48

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Dec-20	Arthurs,Durvin	1.35	0	0
22-Dec-20	Perez,Javier	3.05	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	237.48
Labor:	0.00
Labor Hours:	4.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**237.48**

Work Order Footer

Work Order 54151584 Total	
Parts:	237.48
Labor:	0.00
Labor Hours:	9.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**237.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54089682
Invoice No. 55345 - 54089682

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Rough idle.		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	275,321 - DH

Chronology		
Reported	Nov 29, 2020 1:22:25 PM	Nov 29, 2020 1:22:25 PM
Started	Nov 29, 2020 1:25:00 PM	
Completed	Nov 29, 2020 6:27:00 PM	Nov 29, 2020 6:27:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rough idle.

Cause: TBD.

Correction: Road tested vehicle, could not duplicate issue.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Nov-20	Earl Johnson	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 29-NOV-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Nov 29, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				6:25:22 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Nov 29, 2020 6:25:22 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Nov 29, 2020 6:25:22 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Nov 29, 2020 6:25:22 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Nov 29, 2020 6:25:22 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Nov 29, 2020 6:25:22 PM	No	
20 - Miles			EARJOHNSON	Nov 29, 2020 6:25:22 PM	No	
30 - Kilometers			EARJOHNSON	Nov 29, 2020 6:25:22 PM	No	
40 - Hours			EARJOHNSON	Nov 29, 2020 6:25:22 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54089682
Invoice No. 55345 - 54089682

Client Department:
Department: 55345M
Work Order Description
Rough idle.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 275,321 - DH

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Rough idle
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Nov-20	Earl Johnson	0.68	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54089682 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54077461
Invoice No. 55345 - 54077461

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 274,896 - DH

Chronology		
Reported	Nov 23, 2020 8:42:00 AM	Nov 23, 2020 8:42:00 AM
Started	Nov 23, 2020 11:43:00 AM	
Completed	Nov 23, 2020 2:18:00 PM	Nov 23, 2020 2:18:00 PM
Down Time		

Work Order Notes

Line 10 C: as per driver vehicle was not running right

C: Check computer system found no codes perform engine running test

C: Road test vehicle can¿t duplicate concern at this time

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 23-NOV-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Nov 23, 2020 2:18:12 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Nov 23, 2020 2:18:12 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Nov 23, 2020 2:18:12 PM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Nov 23, 2020 2:18:12 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Nov 23, 2020 2:18:12 PM	No	
10 - Have you successfully completed the Personal	Done		JAPEREZ	Nov 23, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				2:18:12 PM		
20 - Miles			JAPEREZ	Nov 23, 2020 2:18:12 PM	No	
30 - Kilometers			JAPEREZ	Nov 23, 2020 2:18:12 PM	No	
40 - Hours			JAPEREZ	Nov 23, 2020 2:18:12 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54077461
Invoice No. 55345 - 54077461

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 274,896 - DH

Activity Header
Activity: 20 030 ELECTRICAL GROUP
Activity Note: VERIFY COMPLAINT
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Nov-20	Perez,Javier	2.55	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54077461 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 54047026
Invoice No. 55345 - 54047026

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP----> Replace 2 Tires
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 273,756 - DH

Chronology		
Reported	Nov 11, 2020 11:37:30 PM	Nov 11, 2020 11:37:30 PM
Started	Nov 12, 2020 4:40:00 PM	
Completed	Nov 12, 2020 6:00:00 PM	Nov 12, 2020 6:00:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========
To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.
==========

Complaint:needs tires

Cause: low spec

Correction:2 new tires mount and balance,wash rims
Torque wheels 140 lbs second torque 140 lbs
Part number 192659 qty2

Activity Header
Activity: 10 017/003/001 TIRE, CUSHION W/TREAD
Activity Note: needs 2 right rear tires
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Nov-20	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	113.72	227.44

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Nov-20	Gaspard,Ronald	1.28	0	0

Activity Sublet
No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	227.44
Labor:	0.00
Labor Hours:	1.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**227.44**

Work Order Footer

Work Order 54047026 Total	
Parts:	227.44
Labor:	0.00
Labor Hours:	1.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**227.44**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53921056
Invoice No. 55345 - 53921056

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	273,756 - DH

Chronology		
Reported	Nov 11, 2020 12:00:00 AM	Nov 11, 2020 12:00:00 AM
Started	Nov 11, 2020 10:34:00 PM	
Completed	Nov 12, 2020 12:30:00 AM	Nov 12, 2020 12:30:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE: Service

CORRECTION: Perform pmA Service
Oil filter B329 qty1
Engine oil 10w30 qty7 qts
Replaced AC filter
Replaced rear AC vents 14565100C qty2

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 11-NOV-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Nov 11, 2020 10:34:03 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Nov 11, 2020 10:34:03 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Nov 11, 2020 10:34:03 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Nov 11, 2020 10:34:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Nov 11, 2020 10:34:03 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Nov 11, 2020 10:34:03 PM	No	
20 - Miles			RGASPARD	Nov 11, 2020 10:34:03 PM	No	
30 - Kilometers			RGASPARD	Nov 11, 2020 10:34:03 PM	No	
40 - Hours			RGASPARD	Nov 11, 2020 10:34:03 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53921056
Invoice No. 55345 - 53921056

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	273,756 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Nov-20	14565100C	COVER, LOUVER, EVAPORATOR, A/C	2	15.91	31.82

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Nov-20	Gaspard,Ronald	1.43	0	0
12-Nov-20	Gaspard,Ronald	0.07	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 11-NOV-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
20,800 - INSPECT_High Idle Control	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	na	RGASPARD	Nov 11, 2020 11:22:38 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Nov 11, 2020 11:22:38 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	13.9 Volt*		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
33,010 - CSF (Curb Side Front)	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	RGASPARD	Nov 11, 2020 11:22:38 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
40,250 - INSPECT_Overhead Compartment for	Done		RGASPARD	Nov 11, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Water Leaks				11:22:38 PM		
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
50,400 - LUBE_All Chassis Components	-	na	RGASPARD	Nov 11, 2020 11:22:38 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings,	Done		RGASPARD	Nov 11, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Sensors, Routing of Cables				11:22:38 PM		
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	37 Inch		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	37 Inch		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	2 32nds of an inch	needs 2 right rear tires	RGASPARD	Nov 11, 2020 11:22:38 PM	Yes	54047026
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	2 32nds of an inch		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	36 Inch		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	36 Inch		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	14247 Cycles		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Nov 11, 2020 11:22:38 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	31.82
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**31.82**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53921056
Invoice No. 55345 - 53921056

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	273,756 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Nov-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Nov-20	Gaspard,Ronald	0.42	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 12-NOV-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Nov 12, 2020 12:05:09 AM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Nov 12, 2020 12:05:09 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Nov 12, 2020 12:05:09 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Nov 12, 2020 12:05:09 AM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Nov 12, 2020 12:05:09 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Nov 12, 2020 12:05:09 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Nov 12, 2020 12:05:09 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Nov 12, 2020 12:05:09 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order Footer

Work Order 53921056 Total	
Parts:	33.78
Labor:	0.00
Labor Hours:	1.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**33.78**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54023349
Invoice No. 55345 - 54023349

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345 PER DVIR		Ford E350 Champion Crusaders	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	272,839 - DH

Chronology		
Reported	Nov 4, 2020 8:57:51 AM	Nov 4, 2020 8:57:51 AM
Started	Nov 4, 2020 8:58:00 AM	
Completed	Nov 4, 2020 11:06:00 AM	Nov 4, 2020 11:06:00 AM
Down Time		

Work Order Notes

Line 10 Complaint: check engine light

Cause: misfire

Correction: replaced cyl#1 ignition coil and spark plug
Replaced wiper blades

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 04-NOV-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Nov 4, 2020 11:06:00 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Nov 4, 2020 11:06:00 AM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Nov 4, 2020 11:06:00 AM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Nov 4, 2020 11:06:00 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Nov 4, 2020 11:06:00 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Nov 4, 2020 11:06:00 AM	No	
20 - Miles			TDELVA	Nov 4, 2020 11:06:00 AM	No	
30 - Kilometers			TDELVA	Nov 4, 2020 11:06:00 AM	No	
40 - Hours			TDELVA	Nov 4, 2020 11:06:00 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54023349
Invoice No. 55345 - 54023349

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345 PER DVIR		Ford E350 Champion Crusaders	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	272,839 - DH

Activity Header
Activity:20
Activity Note: VERIFY COMPLAINT
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Nov-20	26326	PLUG, COIL, IGNITION	1	25.11	25.11

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Nov-20	Delva,Terry	2.07	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	25.11
Labor:	0.00
Labor Hours:	2.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**25.11**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54023349
Invoice No. 55345 - 54023349

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 272,839 - DH

Activity Header
Activity: 30 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Cylinder 1 misfire
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Nov-20	AP103	PLUG, SPARK	1	3.17	3.17

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Nov-20	Delva,Terry	2.25	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	3.17
Labor:	0.00
Labor Hours:	2.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**3.17**

Work Order Footer

Work Order 54023349 Total	
Parts:	28.28
Labor:	0.00
Labor Hours:	4.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**28.28**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53908300
Invoice No. 55345 - 53908300

Client Department:
Department: 55345M
Work Order Description
Road Call
Requested By: SHARRINGTON
Created By: SHARRINGTON
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 269,005 - DH

Chronology		
Reported	Sep 27, 2020 3:12:43 PM	Sep 27, 2020 3:12:43 PM
Started	Sep 27, 2020 3:13:00 PM	
Completed	Oct 30, 2020 11:48:00 PM	Oct 30, 2020 11:48:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: road call vehicle was stumbling at stops

Cause: fuel relay

Correction: replaced fuel relay aa87-9d370-b and test drove vehicle 6 or 8 miles no issues found at this time and driven early morning and no issue found.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: SHARRINGTON Performed on: 30-OCT-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		SHARRINGTON	Oct 30, 2020 11:48:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		SHARRINGTON	Oct 30, 2020 11:48:16 PM	No	
3 - Are you wearing the appropriate PPE?	Done		SHARRINGTON	Oct 30, 2020 11:48:16 PM	No	
4 - Have you performed the proper LOTO?	Done		SHARRINGTON	Oct 30, 2020 11:48:16 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		SHARRINGTON	Oct 30, 2020 11:48:16 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		SHARRINGTON	Oct 30, 2020 11:48:16 PM	No	
20 - Miles			SHARRINGTON	Oct 30, 2020 11:48:16 PM	No	
30 - Kilometers			SHARRINGTON	Oct 30, 2020 11:48:16 PM	No	
40 - Hours			SHARRINGTON	Oct 30, 2020 11:48:16 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53908300
Invoice No. 55345 - 53908300

Client Department:
Department: 55345M
Work Order Description
Road Call
Requested By: SHARRINGTON
Created By: SHARRINGTON
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 269,005 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Sep-20	AA8Z-9D370-B	MODULE, RELAY, PUMP, FUEL	1	39.02	39.02

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Sep-20	Stephen Harrington	0.3	0	0
27-Sep-20	Stephen Harrington	2.22	0	0
27-Sep-20	Stephen Harrington	0.4	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	39.02
Labor:	0.00
Labor Hours:	2.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**39.02**

Work Order Footer

Work Order 53908300 Total	
Parts:	39.02
Labor:	0.00
Labor Hours:	2.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**39.02**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53941590
Invoice No. 55345 - 53941590

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Missing gas cap		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	270,273 - DH

Chronology		
Reported	Oct 7, 2020 7:38:04 PM	Oct 7, 2020 7:38:04 PM
Started	Oct 7, 2020 12:00:00 AM	
Completed	Oct 7, 2020 7:41:00 PM	Oct 7, 2020 7:41:00 PM
Down Time		

Work Order Notes

Line 10 Driver reported missing gas cap
Replaced gas cap

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 07-OCT-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Oct 7, 2020 7:41:08 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Oct 7, 2020 7:41:08 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Oct 7, 2020 7:41:08 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Oct 7, 2020 7:41:08 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Oct 7, 2020 7:41:08 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Oct 7, 2020 7:41:08 PM	No	
20 - Miles			VAMRITTEEMAL	Oct 7, 2020 7:41:08 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30 - Kilometers			VAMRITTEEMAL	Oct 7, 2020 7:41:08 PM	No	
40 - Hours			VAMRITTEEMAL	Oct 7, 2020 7:41:08 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53941590
Invoice No. 55345 - 53941590

Client Department:
Department: 55345M
Work Order Description
Missing gas cap
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 270,273 - DH

Activity Header
Activity: 20 044/000/000 FUEL SYSTEM
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Oct-20	10840	CAP, FILLER, FUEL	1	12.63	12.63

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Oct-20	AMRIT TEEMAL,VISHNU	0.3333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	12.63
Labor:	0.00
Labor Hours:	0.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**12.63**

Work Order Footer

Work Order 53941590 Total	
Parts:	12.63
Labor:	0.00
Labor Hours:	0.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**12.63**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53929166
Invoice No. 55345 - 53929166

Client Department:
Department: 55345M
Work Order Description
Upper Radiator hose
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 269,753 - DH

Chronology		
Reported	Oct 4, 2020 6:16:03 PM	Oct 4, 2020 6:16:03 PM
Started	Oct 4, 2020 6:17:00 PM	
Completed	Oct 4, 2020 7:35:00 PM	Oct 4, 2020 7:35:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Loss of coolant (overheating).

Cause: Upper radiator hose cut.

Correction: Arrived at location, remove and replaced Upper radiator hose and added coolant.

Part# E71960 Qty.(1).

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Oct-20	Earl Johnson	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: PRAMETER Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 04-OCT-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Oct 4, 2020 7:31:22 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Oct 4, 2020 7:31:22 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Oct 4, 2020 7:31:22 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Oct 4, 2020 7:31:22 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Oct 4, 2020 7:31:22 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Oct 4, 2020 7:31:22 PM	No	
20 - Miles			EARJOHNSON	Oct 4, 2020 7:31:22 PM	No	
30 - Kilometers			EARJOHNSON	Oct 4, 2020 7:31:22 PM	No	
40 - Hours			EARJOHNSON	Oct 4, 2020 7:31:22 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53929166
Invoice No. 55345 - 53929166

Client Department:
Department: 55345M
Work Order Description
Upper Radiator hose
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 269,753 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Oct-20	Earl Johnson	1.2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53929166 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53770682
Invoice No. 55345 - 53770682

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMB		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	269,442 - DH

Chronology		
Reported	Sep 30, 2020 12:00:00 AM	Sep 30, 2020 12:00:00 AM
Started	Sep 30, 2020 9:37:00 PM	
Completed	Oct 1, 2020 12:25:00 AM	Oct 1, 2020 12:25:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMB

CAUSE:Service

CORRECTION:perform PMB service
Oil filter B329 qty1
Engine oil 10w30 qty 7 Qts

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 30-SEP-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Sep 30, 2020 9:37:31 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Sep 30, 2020 9:37:31 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Sep 30, 2020 9:37:31 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Sep 30, 2020 9:37:31 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Sep 30, 2020 9:37:31 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Sep 30, 2020 9:37:31 PM	No	
20 - Miles			RGASPARD	Sep 30, 2020 9:37:31 PM	No	
30 - Kilometers			RGASPARD	Sep 30, 2020 9:37:31 PM	No	
40 - Hours			RGASPARD	Sep 30, 2020 9:37:31 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53770682
Invoice No. 55345 - 53770682

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMB		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	269,442 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Sep-20	Gaspard,Ronald	1.58	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53770682
Invoice No. 55345 - 53770682

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMB		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	269,442 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Sep-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Sep-20	Gaspard,Ronald	0.73	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: RGASPARD Performed on: 30-SEP-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Sep 30, 2020 11:51:43 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Sep 30, 2020 11:51:43 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Sep 30, 2020 11:51:43 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Sep 30, 2020 11:51:43 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Sep 30, 2020 11:51:43 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Sep 30, 2020 11:51:43 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Sep 30, 2020 11:51:43 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Sep 30, 2020 11:51:43 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		RGASPARD	Sep 30, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				11:51:43 PM		
201,000 - Service Crankcase Breather	Done		RGASPARD	Sep 30, 2020 11:51:43 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Sep 30, 2020 11:51:43 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Sep 30, 2020 11:51:43 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Sep 30, 2020 11:51:43 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order Footer

Work Order 53770682 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.31
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53862132
Invoice No. 55345 - 53862132

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
replace starter		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	267,694 - DH

Chronology		
Reported	Sep 11, 2020 7:47:00 AM	Sep 11, 2020 7:47:00 AM
Started	Sep 11, 2020 8:02:00 AM	
Completed	Sep 16, 2020 12:46:00 PM	Sep 16, 2020 12:46:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: Vehicle wasn¿t stated

Cause: preventive maintenance ,tech found font Terminal was loose

Correction: readjust the positive side Terminal battery,vehicle start ok at this time.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 16-SEP-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Sep 16, 2020 12:39:19 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Sep 16, 2020 12:39:19 PM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Sep 16, 2020 12:39:19 PM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Sep 16, 2020 12:39:19 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Sep 16, 2020 12:39:19 PM	No	
10 - Have you successfully completed the Personal	Done		NPIERRE-	Sep 16, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	12:39:19 PM		
20 - Miles			NPIERRE-LOUIS	Sep 16, 2020 12:39:19 PM	No	
30 - Kilometers			NPIERRE-LOUIS	Sep 16, 2020 12:39:19 PM	No	
40 - Hours			NPIERRE-LOUIS	Sep 16, 2020 12:39:19 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53862132
Invoice No. 55345 - 53862132

Client Department:
Department: 55345M
Work Order Description
replace starter
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 267,694 - DH

Activity Header
Activity: 20 032/000/000 CRANKING
Activity Note: VERIFY COMPLAINT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Sep-20	800404	VALVE, PURGE, DRYER, AIR	6	8.78	52.68

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Sep-20	NELSON PIERRE-LOUIS	1.1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	52.68
Labor:	0.00
Labor Hours:	1.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**52.68**

Work Order Footer

Work Order 53862132 Total	
Parts:	52.68
Labor:	0.00
Labor Hours:	1.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**52.68**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53832699
Invoice No. 55345 - 53832699

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Wheel Chair Door)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 266,742 - DH

Chronology		
Reported	Aug 31, 2020 8:13:00 PM	Aug 31, 2020 8:13:00 PM
Started	Aug 31, 2020 9:06:00 PM	
Completed	Aug 31, 2020 11:33:00 PM	Aug 31, 2020 11:33:00 PM
Down Time		

Work Order Notes

Line 10 Reattached WC Lift door gas shock bracket.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 31-AUG-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Aug 31, 2020 10:43:09 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Aug 31, 2020 10:43:09 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Aug 31, 2020 10:43:09 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Aug 31, 2020 10:43:09 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Aug 31, 2020 10:43:09 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Aug 31, 2020 10:43:09 PM	No	
20 - Miles			EARJOHNSON	Aug 31, 2020 10:43:09 PM	No	
30 - Kilometers			EARJOHNSON	Aug 31, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:43:09 PM		
40 - Hours			EARJOHNSON	Aug 31, 2020 10:43:09 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53832699
Invoice No. 55345 - 53832699

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Wheel Chair Door)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 266,742 - DH

Activity Header
Activity:20 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: VERIFY COMPLAINT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Aug-20	Earl Johnson	0.82	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.82
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53832699
Invoice No. 55345 - 53832699

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Wheel Chair Door)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 266,742 - DH

Activity Header
Activity: 30 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: Check Wheel Chair Door
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Aug-20	Earl Johnson	0.78	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53832699 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53687793
Invoice No. 55345 - 53687793

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Exhaust pipe out		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	292,644 - DH

Chronology		
Reported	Jul 10, 2020 11:32:00 PM	Jul 10, 2020 11:32:00 PM
Started	Aug 28, 2020 7:41:00 AM	
Completed	Aug 28, 2020 8:35:00 AM	Aug 28, 2020 8:35:00 AM
Down Time		

Work Order Notes

Line 10 Complaint. Exhaust pipe out

Cause. Normal wear

Correction. Sent to muffler shop Line 20 Vehicle back in service

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 28-AUG-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Aug 28, 2020 8:33:42 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Aug 28, 2020 8:33:42 AM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Aug 28, 2020 8:33:42 AM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Aug 28, 2020 8:33:42 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Aug 28, 2020 8:33:42 AM	No	
10 - Have you successfully completed the	Done		RAURODRIGUEZ	Aug 28, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				8:33:42 AM		
20 - Miles			RAURODRIGUEZ	Aug 28, 2020 8:33:42 AM	No	
30 - Kilometers			RAURODRIGUEZ	Aug 28, 2020 8:33:42 AM	No	
40 - Hours			RAURODRIGUEZ	Aug 28, 2020 8:33:42 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53687793
Invoice No. 55345 - 53687793

Client Department:
Department: 55345M
Work Order Description
Exhaust pipe out
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 292,644 - DH

Activity Header
Activity:20 043/000/000 EXHAUST SYSTEM
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 12 Broken
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Aug-20	Rodriguez,Raul	0.88	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53687793 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53804908
Invoice No. 55345 - 53804908

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Replace Top Radiator Hose		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	266,088 - DH

Chronology		
Reported	Aug 21, 2020 10:56:00 PM	Aug 21, 2020 10:56:00 PM
Started	Aug 23, 2020 2:49:00 PM	
Completed	Aug 23, 2020 5:03:00 PM	Aug 23, 2020 5:03:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Coolant leaking.

Cause: Faulty coolant reservoir tank.

Correction: Removed and Replaced Coolant reservoir tank and upper radiator hose.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 23-AUG-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Aug 23, 2020 4:52:33 PM	No	
2 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Aug 23, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				4:52:33 PM		
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Aug 23, 2020 4:52:33 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Aug 23, 2020 4:52:33 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Aug 23, 2020 4:52:33 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Aug 23, 2020 4:52:33 PM	No	
20 - Miles			EARJOHNSON	Aug 23, 2020 4:52:33 PM	No	
30 - Kilometers			EARJOHNSON	Aug 23, 2020 4:52:33 PM	No	
40 - Hours			EARJOHNSON	Aug 23, 2020 4:52:33 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53804908
Invoice No. 55345 - 53804908

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Replace Top Radiator Hose		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	266,088 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Replace Top Radiator Hose
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Aug-20	Earl Johnson	0.13	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53804908
Invoice No. 55345 - 53804908

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Replace Top Radiator Hose		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	266,088 - DH

Activity Header
Activity: 25 042 COOLING SYSTEM
Activity Note: Coolant leak.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Aug-20	E71960	HOSE, RADIATOR, 7.3L, '01	1	12.47	12.47

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Aug-20	Earl Johnson	2.03	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	12.47
Labor:	0.00
Labor Hours:	2.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**12.47**

Work Order Footer

Work Order 53804908 Total	
Parts:	12.47
Labor:	0.00
Labor Hours:	2.16
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**12.47**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53791060
Invoice No. 55345 - 53791060

Client Department:
Department: 55345M
Work Order Description
Road Call (Belt Check)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 265,646 - DH

Chronology		
Reported	Aug 17, 2020 4:18:00 PM	Aug 17, 2020 4:18:00 PM
Started	Aug 18, 2020 6:53:00 AM	
Completed	Aug 18, 2020 9:41:00 AM	Aug 18, 2020 9:41:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Road call... Driver stated that vehicle¿s overheating

Cause: Broken Belt

Correction: Replaced engine Belt..Replaced idler pulleys

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 18-AUG-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Aug 18, 2020 6:59:32 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Aug 18, 2020 6:59:32 AM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Aug 18, 2020 6:59:32 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
4 - Have you performed the proper LOTO?	Done		TDELVA	Aug 18, 2020 6:59:32 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Aug 18, 2020 6:59:32 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Aug 18, 2020 6:59:32 AM	No	
20 - Miles			TDELVA	Aug 18, 2020 6:59:32 AM	No	
30 - Kilometers			TDELVA	Aug 18, 2020 6:59:32 AM	No	
40 - Hours			TDELVA	Aug 18, 2020 6:59:32 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53791060
Invoice No. 55345 - 53791060

Client Department:
Department: 55345M
Work Order Description
Road Call (Belt Check)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 265,646 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Aug-20	Delva,Terry	2.8	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53791060
Invoice No. 55345 - 53791060

Client Department:
Department: 55345M
Work Order Description
Road Call (Belt Check)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 265,646 - DH

Activity Header
Activity: 20 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Check Belt
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Aug-20	89026	PULLEY, IDLER, SMOOTH	1	13.57	13.57
18-Aug-20	89101	PULLEY, IDLER	1	24.14	24.14
18-Aug-20	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	21	21
18-Aug-20	89006	PULLEY, IDLER, GM	1	17.34	17.34

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	76.05
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**76.05**

Work Order Footer

Work Order 53791060 Total	
Parts:	76.05
Labor:	0.00
Labor Hours:	2.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**76.05**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 53616490
Invoice No. 55345 - 53616490

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	265,155 - DH

Chronology		
Reported	Aug 10, 2020 12:00:00 AM	Aug 10, 2020 12:00:00 AM
Started	Aug 10, 2020 7:24:00 PM	
Completed	Aug 11, 2020 12:21:00 AM	Aug 11, 2020 12:21:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA

CAUSE: Service

CORRECTION: perform PMA service
Oil filter B329 qty1
Engine oil 10w30 qty 7 Qts
Air filter PA4075 qty1

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 10-AUG-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Aug 10, 2020 7:24:19 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Aug 10, 2020 7:24:19 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Aug 10, 2020 7:24:19 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Aug 10, 2020 7:24:19 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Aug 10, 2020 7:24:19 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Aug 10, 2020 7:24:19 PM	No	
20 - Miles			RGASPARD	Aug 10, 2020 7:24:19 PM	No	
30 - Kilometers			RGASPARD	Aug 10, 2020 7:24:19 PM	No	
40 - Hours			RGASPARD	Aug 10, 2020 7:24:19 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 53616490
Invoice No. 55345 - 53616490

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	265,155 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Aug-20	Gaspard,Ronald	1.52	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53770485
Invoice No. 55345 - 53770485

Client Department:

Department: 55345M

Work Order Description
FOLLOWUP---->Mount And Balance 2 Tires And Fixed Right Rear Outer Tire

Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 265,155 - DH

Chronology		
Reported	Aug 10, 2020 8:53:00 PM	Aug 10, 2020 8:53:00 PM
Started	Aug 10, 2020 9:20:00 PM	
Completed	Aug 11, 2020 12:21:00 AM	Aug 11, 2020 12:21:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========
To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.
==========

Complaint:needs 2 front tires and right rear outer flat

Cause: Front Low spec ; right rear outer punctured

Correction:2 new tires mounted and balanced. Patched right rear outer
Torque wheels 140 lbs second torque 140 lbs
Part number 192659 qty 2

Activity Header
Activity: 10 017/003/001 TIRE, CUSHION W/TREAD
Activity Note: needs 2 front tires
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Aug-20	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	117.62	235.24

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Aug-20	Gaspard,Ronald	0.22	0	0
10-Aug-20	Gaspard,Ronald	0.57	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	235.24
Labor:	0.00
Labor Hours:	0.79
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**235.24**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 53616490
Invoice No. 55345 - 53616490

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 265,155 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Aug-20	PA4075	FILTER, AIR SEE P546597	1	5.28	5.28

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Aug-20	Gaspard,Ronald	0.17	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 10-AUG-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Aug 10, 2020 8:56:08 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Aug 10, 2020 8:56:08 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Aug 10, 2020 8:56:08 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Aug 10, 2020 8:56:08 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Aug 10, 2020 8:56:08 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Aug 10, 2020 8:56:08 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Aug 10, 2020 8:56:08 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Aug 10, 2020 8:56:08 PM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	5.28
	Labor:	0.00
	Labor Hours:	0.17
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**5.28**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53770485
Invoice No. 55345 - 53770485

Client Department:

Department: 55345M

Work Order Description
FOLLOWUP---->Mount And Balance 2 Tires And Fixed Right Rear Outer Tire

Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 265,155 - DH

Activity Header
Activity:20 017/009/016 VALVE, PROTECTION, PRESSURE, TIRE
Activity Note: punctured
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Aug-20	6C2Z-2780-A	LEVER, BRAKE, PARKING	1	79.67	79.67

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Aug-20	Gaspard,Ronald	0.2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	79.67
Labor:	0.00
Labor Hours:	0.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**79.67**

Work Order Footer

Work Order 53770485 Total	
Parts:	314.91
Labor:	0.00
Labor Hours:	0.99
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**314.91**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 53616490
Invoice No. 55345 - 53616490

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 265,155 - DH

Activity Header
Activity: 30 055/023 LIFT, WHEELCHAIR, PASSENGER
Activity Note: 55345-W/C LIFT INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Aug-20	Gaspard,Ronald	0.23	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: 55345-W/C LIFT INSPECTION
Task: First Transit Wheelchair Lift Inspection Performed by: RGASPARD Performed on: 10-AUG-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Wheelchair Cycle Count	13767 Cycles		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
1,000 - A.1 Check Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
2,000 - A.2 Check Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
3,000 - Operate Lift Through Complete Cycle and Check for:	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
3,003 - A.3 Unusual Noises	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
3,004 - A.4 Jerky Operation	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
3,005 - A.5 Operated Too Slowly or Too Fast	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
3,006 - A.6 Drift Down	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
7,000 - A.7 Check Bridgeplate Operation	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
8,000 - A.8 Check All Pivot Points for Wear and Looseness	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
9,000 - A.9 Check Rollers for Wear and Smooth Rotation	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
11,000 - A.11 Check Operation of Platform Barrier Mechanism	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
12,000 - A.12 Check Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
13,000 - A.13 Check Cable Condition (If Applicable)	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
14,000 - A.14 Check Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
15,000 - A.15 Check Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
16,000 - A.16 Check Operation and Adjustment of All Safety Switches	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
17,000 - A.17 Check All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
18,000 - A.18 Check the Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
19,000 - A.19 Check HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
20,000 - A.20 Are Operator Decals in Place? Consult Service Manual for Information.	Yes		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
21,000 - A.21 Check WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
90,000 - Clean all Linkages and Mechanisms If Needed before Lubrication	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
91,000 - Lubricate (Don¿t OVER Lubricate)	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
100,000 - B.1 Emergency Platform Release Mechanism	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
200,000 - B.2 Platform Barrier Latch Mechanism	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
300,000 - B.3 Bridgeplate Hinge	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
400,000 - B.4 All Pivot Points	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
500,000 - B.5 Cams and Slots	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
600,000 - B.6 Rollers	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	
700,000 - B.7 All Linkages	Done		RGASPARD	Aug 10, 2020 9:07:56 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53616490 Total	
Parts:	5.28

	Labor:	0.00
	Labor Hours:	1.92
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**5.28**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53763109
Invoice No. 55345 - 53763109

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Both exhaust brackets broken		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	264,729 - DH

Chronology		
Reported	Aug 6, 2020 8:27:45 PM	Aug 6, 2020 8:27:45 PM
Started	Aug 6, 2020 8:30:00 PM	
Completed	Aug 6, 2020 9:21:00 PM	Aug 6, 2020 9:21:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs both exhaust hangers

Cause: broken

Correction: Replaced hanger and 1 bracket

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 06-AUG-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Aug 6, 2020 8:30:33 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Aug 6, 2020 8:30:33 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Aug 6, 2020 8:30:33 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Aug 6, 2020 8:30:33 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Aug 6, 2020 8:30:33 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Aug 6, 2020 8:30:33 PM	No	
20 - Miles			RGASPARD	Aug 6, 2020 8:30:33 PM	No	
30 - Kilometers			RGASPARD	Aug 6, 2020 8:30:33 PM	No	
40 - Hours			RGASPARD	Aug 6, 2020 8:30:33 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53763109
Invoice No. 55345 - 53763109

Client Department:
Department: 55345M
Work Order Description
Both exhaust brackets broken
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 264,729 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Both exhaust brackets broken
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Aug-20	Gaspard,Ronald	0.83	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53763109 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 6

Work Order No. 53603721
Invoice No. 55345 - 53603721

Client Department:

Department: 55345M

Equipment No.: 5447

Work Order Description
55345 PER DVIR (Engine Light On Code P0766 Shift Solenoid D Performance)

VIN: 1FDEE3FLXFDA02748

Ford E350 Champion Crusaders

Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 260,739 - DH

Chronology		
Reported	Jun 5, 2020 10:33:00 PM	Jun 5, 2020 10:33:00 PM
Started	Jun 8, 2020 12:15:00 PM	
Completed	Jun 23, 2020 2:36:00 PM	Jun 23, 2020 2:36:00 PM
Down Time		

Work Order Notes

Line 10 C:Check engine light on

C:Check computer system found codes P0766and P2703 transmission solenoid D stuck off

C: Vehicle needs to replace solenoid and verify repair Line 20 C:Replaced solenoid

C:as per previous diagnostic replace solenoid D, road test vehicle

C: vehicle still doing the same issue, replaced PCM to test and verify road test vehicle still the same. Vehicle needs to be replaced the transmission Line 30 Replaced Bank 1 (O2 Sensor)

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 17-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jun 17, 2020 9:36:55 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jun 17, 2020 9:36:55 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jun 17, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:36:55 PM		
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jun 17, 2020 9:36:55 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jun 17, 2020 9:36:55 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jun 17, 2020 9:36:55 PM	No	
20 - Miles			DARTHURS	Jun 17, 2020 9:36:55 PM	No	
30 - Kilometers			DARTHURS	Jun 17, 2020 9:36:55 PM	No	
40 - Hours			DARTHURS	Jun 17, 2020 9:36:55 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 6

Work Order No. 53603721
Invoice No. 55345 - 53603721

Client Department:

Department: 55345M

Work Order Description
55345 PER DVIR (Engine Light On Code P0766 Shift Solenoid D Performance)

Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 260,739 - DH

Activity Header
Activity:20
Activity Note: VERIFY COMPLAINT
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Jun-20	Perez,Javier	2.12	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 6

Work Order No. 53603721
Invoice No. 55345 - 53603721

Client Department:

Department: 55345M

Equipment No.: 5447

VIN: 1FDEE3FLXFDA02748

Ford E350 Champion Crusaders

Work Order Description
55345 PER DVIR (Engine Light On Code P0766 Shift Solenoid D Performance)

Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 260,739 - DH

Activity Header
Activity: 30 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: replace SHIFT SOLENOID D
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Jun-20	3C3Z-7A136-AA	GASKET, PUMP, TRANSMISSION, FRONT, 5R110W	2	7.4	14.8

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Jun-20	Perez,Javier	5.08	0	0
11-Jun-20	Perez,Javier	0.88	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	14.80
Labor:	0.00
Labor Hours:	5.96
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**14.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 6

Work Order No. 53603721
Invoice No. 55345 - 53603721

Client Department:

Department: 55345M

Work Order Description
55345 PER DVIR (Engine Light On Code P0766 Shift Solenoid D Performance)

Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 260,739 - DH

Activity Header
Activity: 40 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: check engine light on -engine misfires
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Jun-20	Delva,Terry	1.77	0	0
15-Jun-20	Perez,Javier	0.2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 6

Work Order No. 53603721
Invoice No. 55345 - 53603721

Client Department:

Department: 55345M

Work Order Description
55345 PER DVIR (Engine Light On Code P0766 Shift Solenoid D Performance)

Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 260,739 - DH

Activity Header
Activity: 50 043/000/000 EXHAUST SYSTEM
Activity Note: O2 Sensor
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Jun-20	8F9Z-9F472-H	SENSOR, OXYGEN	1	69.54	69.54

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Jun-20	Delva,Terry	2.07	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 50 Sub Total	
Parts:	69.54
Labor:	0.00
Labor Hours:	2.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**69.54**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 6 of 6

Work Order No. 53603721
Invoice No. 55345 - 53603721

Client Department:

Department: 55345M

Work Order Description
55345 PER DVIR (Engine Light On Code P0766 Shift Solenoid D Performance)

Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 260,739 - DH

Activity Header
Activity: 60 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Cylinder Head
Reason for Repair: 38 Warranty
Work Accomplished: 04 Replace Rebuilt
Part Failure: 44 Worn
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jun-20	Arthurs,Durvin	3.92	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 60 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53603721 Total	
Parts:	84.34
Labor:	0.00
Labor Hours:	16.04
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**84.34**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 53630373
Invoice No. 55345 - 53630373

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
ENGINE ASSY REPLACED		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	261,380 - DH

Chronology		
Reported	Jun 17, 2020 4:28:00 PM	Jun 17, 2020 4:28:00 PM
Started	Jun 17, 2020 4:33:00 PM	
Completed	Jun 17, 2020 9:35:00 PM	Jun 17, 2020 9:35:00 PM
Down Time		

Work Order Notes

Line 10 Scan bus 5447 bus misfire Code PO305/ PO306 # 5& # 6 Cylinder Misfire Check Compression Found Both adjacent cylinder has the same amount of compression. 75 Psi each .add little ATF Fluid in Both cylinder recheck compression. did not make no improvement. Suspect . Blown head gasket or broken Rings. Line 20 Remove & Replace with a Remanufactured Engine. Replace front compressor& Replace condenser/ Replace transmission oil cooler./ Replace two motor mount / Replace crank shaft sensor/ Replace High Pressure hose Replace plug boots & Spark Plugs..Evacuate & Charge Rear A/C
Parts # B329 Qty (1)
Parts# 8C2Z-7A095-C Qty (1)
Parts # 9C2Z-19712-A. Qty (1)
Parts #6512376. Qty (1)
Parts # CC2Z-19972-A Qty (1)
Parts# F7UZ-6038-DB Qty(1)
Parts# F7UZ-6038-DC Qty (1)
Parts # 1W7Z-6C315-AB Qty (1)
Parts #AP103. Qty(8)
Parts # 357006 Qty (8)
Oil 10W30 Qty (6.5) Qt
Parts #6512376 Qty (1)

L

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
10 Desc: PRA

Check List

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 17-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jun 17, 2020 9:34:41 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jun 17, 2020 9:34:41 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jun 17, 2020 9:34:41 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jun 17, 2020 9:34:41 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jun 17, 2020 9:34:41 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jun 17, 2020 9:34:41 PM	No	
20 - Miles			DARTHURS	Jun 17, 2020 9:34:41 PM	No	
30 - Kilometers			DARTHURS	Jun 17, 2020 9:34:41 PM	No	
40 - Hours			DARTHURS	Jun 17, 2020 9:34:41 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 53630373
Invoice No. 55345 - 53630373

Client Department:
Department: 55345M
Work Order Description
ENGINE ASSY REPLACED
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 261,380 - DH

Activity Header
Activity: 20 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: VERIFY COMPLAINT
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Jun-20	Arthurs,Durvin	1.05	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 53630373
Invoice No. 55345 - 53630373

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
ENGINE ASSY REPLACED		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	261,380 - DH

Activity Header
Activity: 30 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Bus Fire
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Jun-20	6512376	COMPRESSOR, A/C, NEW	1	206.45	206.45
25-Jun-20	AP103	PLUG, SPARK	8	3.16	25.28
25-Jun-20	F7UZ-6038-DB	MOUNT, ENGINE	1	39.31	39.31
25-Jun-20	1W7Z-6C315-AB	SENSOR, POSITION, CRANKSHAFT	1	28.41	28.41
25-Jun-20	357006	BOOT, COIL-ON-PLUG, IGNITION	8	4.36	34.88
25-Jun-20	9C2Z-19712-A	CONDENSER, A/C, 5.4L SEE OMEGA 24-31351	1	151.63	151.63
25-Jun-20	F7UZ-6038-DC	INSULATOR	1	33.88	33.88

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Jun-20	Arthurs,Durvin	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	519.84
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**519.84**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 53630373
Invoice No. 55345 - 53630373

Client Department:
Department: 55345M
Work Order Description
ENGINE ASSY REPLACED
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 261,380 - DH

Activity Header
Activity: 40 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: REPLACE ENGINE ASSY
Reason for Repair: 38 Warranty
Work Accomplished: 04 Replace Rebuilt
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Jun-20	7L3Z-8575-D	THERMOSTAT, 4.6L	1	9.93	9.93

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	9.93
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**9.93**

Work Order Footer

Work Order 53630373 Total	
Parts:	529.77
Labor:	0.00
Labor Hours:	3.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**529.77**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53615634
Invoice No. 55345 - 53615634

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
REPLACE TRANSMISSION ASSY		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,833 - DH

Chronology		
Reported	Jun 11, 2020 2:02:00 PM	Jun 11, 2020 2:02:00 PM
Started	Jun 11, 2020 9:42:00 PM	
Completed	Jun 12, 2020 1:01:00 PM	Jun 12, 2020 1:01:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:vehicle hard to shift

Cause: preventive maintenance,transmission problem

Correction: replaced the transmission and drove test vehicle everything ok at this time

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 12-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Jun 12, 2020 1:00:47 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Jun 12, 2020 1:00:47 PM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Jun 12, 2020 1:00:47 PM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Jun 12, 2020 1:00:47 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Jun 12, 2020 1:00:47 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Jun 12, 2020 1:00:47 PM	No	
20 - Miles			NPIERRE-LOUIS	Jun 12, 2020 1:00:47 PM	No	
30 - Kilometers			NPIERRE-LOUIS	Jun 12, 2020 1:00:47 PM	No	
40 - Hours			NPIERRE-LOUIS	Jun 12, 2020 1:00:47 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53615634
Invoice No. 55345 - 53615634

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
REPLACE TRANSMISSION ASSY		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,833 - DH

Activity Header
Activity: 15 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: REPLACE TRANSMISSION ASSY (PREVIOUS TRANSMISSION IS DEFECTIVE)
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 43 Weak
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Jun-20	9C2Z-7A228-A	TUBE, FILTER, OIL	1	18.99	18.99
28-Aug-20	9C3Z-7902-B	OUT OF SERVICE CONVERTER, TORQUE, TRANSMISSION	1	515.92	515.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Jun-20	NELSON PIERRE-LOUIS	4.93	0	0
11-Jun-20	Arthurs,Durvin	2.3	0	0
12-Jun-20	Arthurs,Durvin	0.3	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

15 Desc: REPLACE TRANSMISSION ASSY (PREVIOUS TRANSMISSION IS DEFECTIVE)
Task: 55345 TRANSMISSION DTC P0751 SHIFT SOLENOID Performed by: NPIERRE-LOUIS Performed on: 12-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - 55345 TRANSMISSION DTC P0751 SHIFT SOLENOID	Done		NPIERRE-LOUIS	Jun 12, 2020 1:00:15 PM	No	

Activity Sub Total

Activity 15 Sub Total	
Parts:	534.91
Labor:	0.00
Labor Hours:	7.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**534.91**

Work Order Footer

Work Order 53615634 Total	
Parts:	534.91
Labor:	0.00
Labor Hours:	7.53

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**534.91**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 53616474
Invoice No. 55345 - 53616474

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP--->Replace Rear Brakes
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 260,833 - DH

Chronology		
Reported	Jun 11, 2020 6:54:27 PM	Jun 11, 2020 6:54:27 PM
Started	Jun 11, 2020 7:11:00 PM	
Completed	Jun 11, 2020 8:55:00 PM	Jun 11, 2020 8:55:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========
To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.
==========

Complaint: Rear Brakes & Rotor.

Cause: Rear Brakes Low / Rear Rotor Worn.

Correction: Remove & Replace Rear Brakes & Rear Rotor.
Parts # 9C2Z-2V200-B Qty (1)
Parts #8C2Z-2C026-A Qty (2)

Activity Header
Activity: 10 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: Rear Brakes
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Jun-20	9C2Z-2V200-B	PADS, BRAKE, DISC, REAR SAME AS BRSD1329B	1	39.21	39.21
11-Jun-20	8C2Z-2C026-A	ROTOR, BRAKE, DISC, REAR, E350 SUPERSEDED BY NC2Z-2C026-A	2	90.15	180.3

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Jun-20	Arthurs,Durvin	1.57	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	219.51
Labor:	0.00
Labor Hours:	1.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**219.51**

Work Order Footer

Work Order 53616474 Total	
Parts:	219.51
Labor:	0.00
Labor Hours:	1.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**219.51**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 53558576
Invoice No. 55345 - 53558576

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	NSTOLFO	**Status:**	40 - Closed (40)
Created By:	NSTOLFO	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,833 - DH

Chronology		
Reported	Jun 11, 2020 3:08:32 PM	Jun 11, 2020 3:08:32 PM
Started	Jun 11, 2020 4:25:00 PM	
Completed	Jun 11, 2020 7:10:00 PM	Jun 11, 2020 7:10:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA Service

CAUSE: Service Due by Mileage.

CORRECTION: Change Oil & Filter.Lube all Pivoting Points. Check brakes Clean batteries. Replace Oil filler tube.
Parts# B329 Qty (1)
Parts # 9C2Z-6763- C Qty (1)
Oil 10W30 Qty (6.5) Qt

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 11-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jun 11, 2020 6:21:24 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jun 11, 2020 6:21:24 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jun 11, 2020 6:21:24 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jun 11, 2020 6:21:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jun 11, 2020 6:21:24 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jun 11, 2020 6:21:24 PM	No	
20 - Miles			DARTHURS	Jun 11, 2020 6:21:24 PM	No	
30 - Kilometers			DARTHURS	Jun 11, 2020 6:21:24 PM	No	
40 - Hours			DARTHURS	Jun 11, 2020 6:21:24 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 53558576
Invoice No. 55345 - 53558576

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	NSTOLFO	**Status:**	40 - Closed (40)
Created By:	NSTOLFO	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,833 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Jun-20	Arthurs,Durvin	1.78	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 53558576
Invoice No. 55345 - 53558576

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: NSTOLFO
Created By: NSTOLFO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 260,833 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Jun-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96
11-Jun-20	9C2Z-6763-C	TUBE, FILLER, OIL, 6.8L	1	28.02	28.02

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Jun-20	Arthurs,Durvin	0.38	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 11-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Jun 11, 2020 6:25:52 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Jun 11, 2020 6:25:52 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Jun 11, 2020 6:25:52 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Jun 11, 2020 6:25:52 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Jun 11, 2020 6:25:52 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Jun 11, 2020 6:25:52 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Jun 11, 2020 6:25:52 PM	No	
108,000 - Lube all pivoting	Done		DARTHURS	Jun 11, 2020 6:25:52	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Mechanisms				PM		

Activity Sub Total

Activity 20 Sub Total	
Parts:	29.98
Labor:	0.00
Labor Hours:	0.38
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**29.98**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 53558576
Invoice No. 55345 - 53558576

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	NSTOLFO	**Status:**	40 - Closed (40)
Created By:	NSTOLFO	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,833 - DH

Activity Header
Activity: 30 055/023 LIFT, WHEELCHAIR, PASSENGER
Activity Note: 55345-W/C LIFT INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: 55345-W/C LIFT INSPECTION
Task: First Transit Wheelchair Lift Inspection Performed by: DARTHURS Performed on: 11-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Wheelchair Cycle Count	13229 Cycles		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
1,000 - A.1 Check Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
2,000 - A.2 Check Platform Emergency Release Mechanism for Ease of Operation	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
3,000 - Operate Lift Through Complete Cycle and Check for:	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
3,003 - A.3 Unusual Noises	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
3,004 - A.4 Jerky Operation	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
3,005 - A.5 Operated Too Slowly or Too Fast	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
3,006 - A.6 Drift Down	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
7,000 - A.7 Check Bridgeplate Operation	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
8,000 - A.8 Check All Pivot Points for Wear and Looseness	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
9,000 - A.9 Check Rollers for Wear and Smooth Rotation	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11,000 - A.11 Check Operation of Platform Barrier Mechanism	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
12,000 - A.12 Check Cam Slots for Wear and Proper Alignment	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
13,000 - A.13 Check Cable Condition (If Applicable)	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
14,000 - A.14 Check Hydraulic Hoses for Leaks, Chafing or Cracks	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
15,000 - A.15 Check Electrical Connections and Routing of Wires and Cables	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
16,000 - A.16 Check Operation and Adjustment of All Safety Switches	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
17,000 - A.17 Check All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
18,000 - A.18 Check the Manual Back-up Raise/Lower System (If Applicable)	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
19,000 - A.19 Check HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
20,000 - A.20 Are Operator Decals in Place? Consult Service Manual for Information.	Yes		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
21,000 - A.21 Check WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
90,000 - Clean all Linkages and Mechanisms If Needed before Lubrication	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
91,000 - Lubricate (Don¿t OVER Lubricate)	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
100,000 - B.1 Emergency Platform Release Mechanism	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
200,000 - B.2 Platform Barrier Latch Mechanism	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
300,000 - B.3 Bridgeplate Hinge	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
400,000 - B.4 All Pivot Points	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
500,000 - B.5 Cams and Slots	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
600,000 - B.6 Rollers	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	
700,000 - B.7 All Linkages	Done		DARTHURS	Jun 11, 2020 7:10:09 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53558576 Total	
Parts:	29.98
Labor:	0.00
Labor Hours:	2.16

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**29.98**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53616389
Invoice No. 55345 - 53616389

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Replace Wheel chair bag)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 260,833 - DH

Chronology		
Reported	Jun 11, 2020 5:49:00 PM	Jun 11, 2020 5:49:00 PM
Started		
Completed	Jun 11, 2020 6:01:00 PM	Jun 11, 2020 6:01:00 PM
Down Time		

Work Order Notes

Line 10

Complaint: Wheel bag ripped

Cause: Normal Usage

Correction: Replace Wheel Chair Bag

Parts# Q5-8522 Qty 1

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 11-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		AOWENS	Jun 11, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				6:00:27 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		AOWENS	Jun 11, 2020 6:00:27 PM	No	
3 - Are you wearing the appropriate PPE?	Done		AOWENS	Jun 11, 2020 6:00:27 PM	No	
4 - Have you performed the proper LOTO?	Done		AOWENS	Jun 11, 2020 6:00:27 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	Jun 11, 2020 6:00:27 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Jun 11, 2020 6:00:27 PM	No	
20 - Miles			AOWENS	Jun 11, 2020 6:00:27 PM	No	
30 - Kilometers			AOWENS	Jun 11, 2020 6:00:27 PM	No	
40 - Hours			AOWENS	Jun 11, 2020 6:00:27 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53616389
Invoice No. 55345 - 53616389

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Replace Wheel chair bag)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 260,833 - DH

Activity Header
Activity: 20 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: VERIFY COMPLAINT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53616389
Invoice No. 55345 - 53616389

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Replace Wheel chair bag)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 260,833 - DH

Activity Header
Activity: 30 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: Replace Wheel Chair Bag
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Jun-20	Q5-8522	POUCH, STORAGE, Q-STRAINT, NYLON	1	33.37	33.37

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	33.37
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**33.37**

Work Order Footer

Work Order 53616389 Total	
Parts:	33.37
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**33.37**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53580806
Invoice No. 55345 - 53580806

Client Department:
Department: 55345M
Work Order Description
TRANSMISSION AND DRIVE TRAIN.
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 260,362 - DH

Chronology		
Reported	May 28, 2020 10:51:00 AM	May 28, 2020 10:51:00 AM
Started	May 28, 2020 5:39:00 PM	
Completed	May 29, 2020 1:52:00 PM	May 29, 2020 1:52:00 PM
Down Time		

Work Order Notes

Line 10 Na Line 20 Complaint: road call vehicle not shifting

Cause: Transmission problem

Correction: replaced transmission,and transmission external harness add fluid :road test vehicle,every okay at this time

Part: 9c2z-7c078-ma out of stock.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-May-20	Earl Johnson	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 29-MAY-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	May 29, 2020 1:49:27 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	May 29, 2020 1:49:27 PM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	May 29, 2020 1:49:27 PM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-	May 29, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	1:49:27 PM		
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	May 29, 2020 1:49:27 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	May 29, 2020 1:49:27 PM	No	
20 - Miles			NPIERRE-LOUIS	May 29, 2020 1:49:27 PM	No	
30 - Kilometers	12		NPIERRE-LOUIS	May 29, 2020 1:49:27 PM	No	
40 - Hours	8		NPIERRE-LOUIS	May 29, 2020 1:49:27 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53580806
Invoice No. 55345 - 53580806

Client Department:
Department: 55345M
Work Order Description
TRANSMISSION AND DRIVE TRAIN.
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 260,362 - DH

Activity Header
Activity: 20 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Jun-20	19180251	TRANSMISSION, REMANUFACTURED	1	475.88	475.88
29-May-20	AP103	PLUG, SPARK	-2	3.16	-6.32
03-Jun-20	F81Z-7A527-AA	RING, SNAP, CLUTCH, TRANSMISSION	1	2.39	2.39
29-May-20	8025005	COMPRESSOR, A/C, TM21	-1	250.32	-250.32
03-Jun-20	7C3Z-7G387-B	CYLINDER, CLUTCH, TRANSMISSION	1	56.11	56.11
29-May-20	8025005	COMPRESSOR, A/C, TM21	1	250.32	250.32
29-May-20	26326	PLUG, COIL, IGNITION	2	28.12	56.24
03-Jun-20	3C3Z-7G299-AA	RETAINER, GEAR, PLANETARY	1	9.09	9.09
03-Jun-20	6C3Z-7A262-AA	CLUTCH, FORWARD, TRANSMISSION	1	21.63	21.63
03-Jun-20	20021	FILTER, TRANSMISSION 20021	1	17.27	17.27
03-Jun-20	8C3Z-7C155-A	GASKET, BODY, VALVE, TRANSMISSION, 5R110	1	7.09	7.09
03-Jun-20	BC3Z-7H141-A	SENSOR, TEMPERATURE, TRANSMISSION	1	10.39	10.39
03-Jun-20	4C3Z-7G276-AA	HARNESS, SOLENOID, INTERNAL, TRANSMISSION, 5R110W	1	123.53	123.53
29-May-20	AP103	PLUG, SPARK	2	3.16	6.32
29-May-20	26326	PLUG, COIL, IGNITION	-2	28.12	-56.24

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-May-20	NELSON PIERRE-LOUIS	2.02	0	0
28-May-20	Earl Johnson	5.5	0	0
29-May-20	Rodriguez,Raul	1.13	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	723.38
	Labor:	0.00
	Labor Hours:	8.65
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**723.38**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53580806
Invoice No. 55345 - 53580806

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
TRANSMISSION AND DRIVE TRAIN.		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,362 - DH

Activity Header
Activity: 30 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: External harness
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53580806 Total	
Parts:	723.38
Labor:	0.00
Labor Hours:	8.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**723.38**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53579203
Invoice No. 55345 - 53579203

Client Department:
Department: 55345M
Work Order Description
Road Call (Bus will not move)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 260,225 - DH

Chronology		
Reported	May 27, 2020 7:01:00 PM	May 27, 2020 7:01:00 PM
Started	May 27, 2020 7:05:00 PM	
Completed	May 27, 2020 11:37:00 PM	May 27, 2020 11:37:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:bus can¿t move

Cause: Transmission concerns

Correction:towed the bus to base

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 27-MAY-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	May 27, 2020 11:37:18 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		RGASPARD	May 27, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				11:37:18 PM		
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	May 27, 2020 11:37:18 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	May 27, 2020 11:37:18 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	May 27, 2020 11:37:18 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	May 27, 2020 11:37:18 PM	No	
20 - Miles			RGASPARD	May 27, 2020 11:37:18 PM	No	
30 - Kilometers			RGASPARD	May 27, 2020 11:37:18 PM	No	
40 - Hours			RGASPARD	May 27, 2020 11:37:18 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53579203
Invoice No. 55345 - 53579203

Client Department:
Department: 55345M
Work Order Description
Road Call (Bus will not move)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 260,225 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL (Bus Will not move)
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-May-20	Gaspard,Ronald	0.92	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53579203 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53577445
Invoice No. 55345 - 53577445

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345 BATTERY		Ford E350 Champion Crusaders	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,225 - DH

Chronology		
Reported	May 27, 2020 10:34:24 AM	May 27, 2020 10:34:24 AM
Started	May 27, 2020 12:00:00 AM	
Completed	May 27, 2020 12:24:00 PM	May 27, 2020 12:24:00 PM
Down Time		

Work Order Notes

Line 10 Battery.
Complaint.
Battery died multiple times

CAUSE:
Bad batteries. Trickle charged batteries for an hour. Then I load tested batteries separately and load tester indicates to replace both batteries. The results for 1 was 55CCAout of 740CCA. The result for 2nd battery was 11CCA out of 740CCA.

CORRECTION:
Installed 2 new batteries and the CCA is 740 under guarantee

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 27-MAY-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the	Done		RAURODRIGUEZ	May 27, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
task?				12:19:12 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	May 27, 2020 12:19:12 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	May 27, 2020 12:19:12 PM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	May 27, 2020 12:19:12 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	May 27, 2020 12:19:12 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	May 27, 2020 12:19:12 PM	No	
20 - Miles			RAURODRIGUEZ	May 27, 2020 12:19:12 PM	No	
30 - Kilometers			RAURODRIGUEZ	May 27, 2020 12:19:12 PM	No	
40 - Hours			RAURODRIGUEZ	May 27, 2020 12:19:12 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53577445
Invoice No. 55345 - 53577445

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345 BATTERY		Ford E350 Champion Crusaders	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,225 - DH

Activity Header
Activity:20 031/005/000 CHARGER, BATTERY, ON-BOARD, VEHICLES, PROPELLED, ELECTRICALLY
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure: 43 Weak
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-May-20	34AGM	BATTERY, AGM, GROUP-34	2	122.74	245.48

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-May-20	Rodriguez,Raul	1.7333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	245.48
Labor:	0.00
Labor Hours:	1.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**245.48**

Work Order Footer

Work Order 53577445 Total	
Parts:	245.48
Labor:	0.00
Labor Hours:	1.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**245.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53524788
Invoice No. 55345 - 53524788

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Left rear tireouer flat		Ford E350 Champion Crusaders	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	258,987 - DH

Chronology		
Reported	May 4, 2020 4:13:00 PM	May 4, 2020 4:13:00 PM
Started	May 4, 2020 7:29:00 PM	
Completed	May 4, 2020 8:27:00 PM	May 4, 2020 8:27:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Vehicle came in for flat tire left outer

Cause: Nail in tire

Correction: Removed on replace one good used tire on unit now vehicle is good for working

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: JUHURST Performed on: 04-MAY-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	May 4, 2020 7:56:54 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	May 4, 2020 7:56:54 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	May 4, 2020 7:56:54 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	May 4, 2020 7:56:54 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	May 4, 2020 7:56:54 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	May 4, 2020 7:56:54 PM	No	
20 - Miles			JUHURST	May 4, 2020 7:56:54 PM	No	
30 - Kilometers			JUHURST	May 4, 2020 7:56:54 PM	No	
40 - Hours			JUHURST	May 4, 2020 7:56:54 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53524788
Invoice No. 55345 - 53524788

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Left rear tireouer flat		Ford E350 Champion Crusaders	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	258,987 - DH

Activity Header
Activity: 15 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note: Outer rear tire flat
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-May-20	Junior Hurst	0.97	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53524788 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53492750
Invoice No. 55345 - 53492750

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Front ac evaporator.		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	258,105 - DH

Chronology		
Reported	Apr 20, 2020 5:21:40 PM	Apr 20, 2020 5:21:40 PM
Started	Apr 20, 2020 5:23:00 PM	
Completed	Apr 20, 2020 8:15:00 PM	Apr 20, 2020 8:15:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Front AC blowing warm.

Cause: Front evaporator leaking.

Correction: Remove and replaced front AC evaporator, accumulator and orifice tube.
Part# 3411885 Qty. (1). GC2Z-19C836-C Qty. (1). 6C2Z-19860-C Qty.(1).

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Apr-20	Earl Johnson	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 20-APR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Apr 20, 2020 7:48:37 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Apr 20, 2020 7:48:37 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Apr 20, 2020 7:48:37 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Apr 20, 2020 7:48:37 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Apr 20, 2020 7:48:37 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Apr 20, 2020 7:48:37 PM	No	
20 - Miles			EARJOHNSON	Apr 20, 2020 7:48:37 PM	No	
30 - Kilometers			EARJOHNSON	Apr 20, 2020 7:48:37 PM	No	
40 - Hours			EARJOHNSON	Apr 20, 2020 7:48:37 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53492750
Invoice No. 55345 - 53492750

Client Department:
Department: 55345M
Work Order Description
Front ac evaporator.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 258,105 - DH

Activity Header
Activity: 15 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Front ac evaporator.
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Apr-20	GC2Z-19C836-C	ACCUMULATOR, A/C, E450	1	100.77	100.77
20-Apr-20	6C2Z-19860-C	CORE, EVAPORATOR, A/C	1	101.19	101.19
20-Apr-20	3411885	TUBE, ORIFICE, A/C, FORD	1	0.75	0.75

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Apr-20	Earl Johnson	2.4	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	202.71
Labor:	0.00
Labor Hours:	2.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**202.71**

Work Order Footer

Work Order 53492750 Total	
Parts:	202.71
Labor:	0.00
Labor Hours:	2.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**202.71**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53275557
Invoice No. 55345 - 53275557

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM C		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	256,659 - DH

Chronology		
Reported	Mar 24, 2020 11:19:18 AM	Mar 24, 2020 11:19:18 AM
Started	Mar 24, 2020 8:09:00 PM	
Completed	Mar 24, 2020 11:41:00 PM	Mar 24, 2020 11:41:00 PM
Down Time		

Work Order Notes

Line 10 Perform PMC Service , Check Brakes. Clean batteries. Perform differential service. drain fill differential..changeOil &Filter no transmission service Fluid Clean. Replace hose clamp on Lower radiator neck.
Parts # B329 Qty (1)
Oil 10W30 Qty (6.5) Qt
Gear Oil 80W90 Qty (3) Qt

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Mar-20	Arthurs,Durvin	2.55	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53275557
Invoice No. 55345 - 53275557

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 256,659 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Mar-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Mar-20	Arthurs,Durvin	0.38	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: DARTHURS Performed on: 24-MAR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Mar 24, 2020 11:29:01 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Mar 24, 2020 11:29:01 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Mar 24, 2020 11:29:01 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Mar 24, 2020 11:29:01 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Mar 24, 2020 11:29:01 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Mar 24, 2020 11:29:01 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	NA	DARTHURS	Mar 24, 2020 11:29:01 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Mar 24, 2020 11:29:01 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		DARTHURS	Mar 24, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				11:29:01 PM		
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Mar 24, 2020 11:29:01 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No	Transmission fluid clean.	DARTHURS	Mar 24, 2020 11:29:01 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Mar 24, 2020 11:29:01 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Mar 24, 2020 11:29:01 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		DARTHURS	Mar 24, 2020 11:29:01 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		DARTHURS	Mar 24, 2020 11:29:01 PM	No	
302,000 - Check Toe-In and Record Reading	-	NA	DARTHURS	Mar 24, 2020 11:29:01 PM	No	
302,001 - Record Toe-In Reading	0 Inches, fraction-actual	NA	DARTHURS	Mar 24, 2020 11:29:01 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		DARTHURS	Mar 24, 2020 11:29:01 PM	No	
305,000 - FRA Change Differential Fluid	Yes		DARTHURS	Mar 24, 2020 11:29:01 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.38
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53275557
Invoice No. 55345 - 53275557

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM C		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	256,659 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 24-MAR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Mar 24, 2020 11:29:59 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Mar 24, 2020 11:29:59 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Mar 24, 2020 11:29:59 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Mar 24, 2020 11:29:59 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Mar 24, 2020 11:29:59 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Mar 24, 2020 11:29:59 PM	No	
20 - Miles			DARTHURS	Mar 24, 2020 11:29:59 PM	No	
30 - Kilometers			DARTHURS	Mar 24, 2020 11:29:59 PM	No	
40 - Hours			DARTHURS	Mar 24, 2020 11:29:59 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53275557 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53375014
Invoice No. 55345 - 53375014

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Road call. Rear A/C blowing hot		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	255,452 - DH

Chronology		
Reported	Mar 11, 2020 12:19:09 PM	Mar 11, 2020 12:19:09 PM
Started		
Completed	Mar 11, 2020 2:04:00 PM	Mar 11, 2020 2:04:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:road call rear A/c blowing hot

Cause: leaking valve

Correction:replace high pressure valve vacuumed and recharge completed

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 11-MAR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Mar 11, 2020 2:03:52 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Mar 11, 2020 2:03:52 PM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Mar 11, 2020 2:03:52 PM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Mar 11, 2020 2:03:52 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Mar 11, 2020 2:03:52 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Mar 11, 2020 2:03:52 PM	No	
20 - Miles			HPIERRE	Mar 11, 2020 2:03:52 PM	No	
30 - Kilometers	11		HPIERRE	Mar 11, 2020 2:03:52 PM	No	
40 - Hours	2		HPIERRE	Mar 11, 2020 2:03:52 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53375014
Invoice No. 55345 - 53375014

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Road call. Rear A/C blowing hot		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	255,452 - DH

Activity Header
Activity: 15 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 51 Inoperative
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53375014 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53351710
Invoice No. 55345 - 53351710

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Engine Removal		Ford E350 Champion Crusaders	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	254,940 - DH

Chronology		
Reported	Mar 4, 2020 4:11:52 PM	Mar 4, 2020 4:11:52 PM
Started	Mar 4, 2020 4:16:00 PM	
Completed	Mar 6, 2020 12:59:00 PM	Mar 6, 2020 12:59:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Assistant Nex-Tech remove an engine
Correction:

Stop working on unit # 5447 at 758 pm

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: JUHURST Performed on: 06-MAR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Mar 6, 2020 12:57:57 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Mar 6, 2020 12:57:57 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Mar 6, 2020 12:57:57 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Mar 6, 2020 12:57:57 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Mar 6, 2020 12:57:57 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Mar 6, 2020 12:57:57 PM	No	
20 - Miles		N/A	JUHURST	Mar 6, 2020 12:57:57 PM	No	
30 - Kilometers		NA	JUHURST	Mar 6, 2020 12:57:57 PM	No	
40 - Hours		N/A	JUHURST	Mar 6, 2020 12:57:57 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53351710
Invoice No. 55345 - 53351710

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Engine Removal		Ford E350 Champion Crusaders	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	254,940 - DH

Activity Header
Activity: 15 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Engine work
Reason for Repair: 38 Warranty
Work Accomplished: 04 Replace Rebuilt
Part Failure: 44 Worn
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Mar-20	Junior Hurst	3.7	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53351710 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53334813
Invoice No. 55345 - 53334813

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Engine Noise		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	254,940 - DH

Chronology		
Reported	Feb 28, 2020 4:13:49 PM	Feb 28, 2020 4:13:49 PM
Started	Feb 28, 2020 4:18:00 PM	
Completed	Mar 5, 2020 10:26:00 PM	Mar 5, 2020 10:26:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Engine noise & intake leaking

Cause: Engine internal damage. did Remove & Replace Engine to stop coolant leak but engine was still knocking..

Correction: Remove & Replace Engine . Replace water pump / Replace Left Motor Mount / Replace belt tensioner./ Replace intake / Replace Engine harness./ Replace intake gasket /replace Oil dip stick.Replace thermostat / Gasket . replace spark plugs& plug boots. Replace manifold bolts.. (11) Bolts.
Parts# F7UZ-6038-DB Qty (1)
Parts #4C2Z-6754-CA Qty (1)
Parts #305263. Qty (1)

parts #T4196 Qty (1)
Parts# 7L3Z-8575-D Qty (1)
Parts #F1VY-8255-A Qty (1)
Parts#9C2Z-9D930 -AA Qty (1)
Parts# AC2Z-9424-A Qty (1)
Parts#357006 Qty (8)
Parts# AP103 Qty (8)
Parts #AC2Z-9439 -B Qty (1)
Parts #AC2Z-9439-A Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List						
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 05-MAR-20						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Mar 5, 2020 9:05:59 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Mar 5, 2020 9:05:59 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Mar 5, 2020 9:05:59 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Mar 5, 2020 9:05:59 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Mar 5, 2020 9:05:59 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Mar 5, 2020 9:05:59 PM	No	
20 - Miles			DARTHURS	Mar 5, 2020 9:05:59 PM	No	
30 - Kilometers			DARTHURS	Mar 5, 2020 9:05:59 PM	No	
40 - Hours			DARTHURS	Mar 5, 2020 9:05:59 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53334813
Invoice No. 55345 - 53334813

Client Department:
Department: 55345M
Work Order Description
Engine Noise
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 254,940 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Check Engine Noise
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Mar-20	9C2Z-9D930-AA	HARNESS, ENGINE, V10	1	165.29	165.29
05-Mar-20	357006	BOOT, COIL-ON-PLUG, IGNITION	8	4.19	33.52
05-Mar-20	AC2Z-9439-B	GASKET, MANIFOLD, INTAKE	1	11.42	11.42
05-Mar-20	4C2Z-6754-CA	TUBE, DIPSTICK, LEVEL, OIL, ENGINE	1	19.23	19.23
05-Mar-20	AC2Z-9424-A	MANIFOLD, INTAKE	1	194.37	194.37
05-Mar-20	AP103	PLUG, SPARK	8	3.14	25.12
05-Mar-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96
05-Mar-20	T4196	PUMP, WATER, CQWPS	1	34.98	34.98
05-Mar-20	305263	TENSIONER, BELT, V10, FORD	1	34.74	34.74
05-Mar-20	AC2Z-9439-A	GASKET, MANIFOLD, INTAKE	1	6.56	6.56
05-Mar-20	F7UZ-6038-DB	MOUNT, ENGINE	1	37.95	37.95
05-Mar-20	7L3Z-8575-D	THERMOSTAT, 4.6L	1	9.91	9.91
05-Mar-20	F1VY-8255-A	SEAL, THERMOSTAT	1	4.16	4.16

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Mar-20	Arthurs,Durvin	7.98	0	0
05-Mar-20	Arthurs,Durvin	1.4	0	0

Booked Date	Technician	Hours	Shop Rate	Extended
03-Mar-20	Arthurs,Durvin	3.43	0	0
01-Mar-20	Arthurs,Durvin	3.52	0	0
05-Mar-20	Arthurs,Durvin	0.1	0	0
03-Mar-20	Arthurs,Durvin	0.43	0	0
28-Feb-20	Arthurs,Durvin	3.9	0	0
05-Mar-20	Arthurs,Durvin	2.33	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	579.21
Labor:	0.00
Labor Hours:	23.09
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**579.21**

Work Order Footer

Work Order 53334813 Total	
Parts:	579.21
Labor:	0.00
Labor Hours:	23.09
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**579.21**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53182749
Invoice No. 55345 - 53182749

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	252,645 - DH

Chronology		
Reported	Feb 10, 2020 10:59:48 AM	Feb 10, 2020 10:59:48 AM
Started	Feb 11, 2020 6:21:00 PM	
Completed	Feb 12, 2020 12:43:00 AM	Feb 12, 2020 12:43:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA

CAUSE:service

CORRECTION: perform PMA service
Oil filter B329 qty1
Engine oil 5w20 qty 7 qts
Replaced AC filter

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Feb-20	Gaspard,Ronald	1.47	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53182749
Invoice No. 55345 - 53182749

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 252,645 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Feb-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Feb-20	Gaspard,Ronald	0.85	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 11-FEB-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Feb 11, 2020 7:41:12 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Feb 11, 2020 7:41:12 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Feb 11, 2020 7:41:12 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Feb 11, 2020 7:41:12 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Feb 11, 2020 7:41:12 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Feb 11, 2020 7:41:12 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Feb 11, 2020 7:41:12 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Feb 11, 2020 7:41:12 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	0.85
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53182749
Invoice No. 55345 - 53182749

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	252,645 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 11-FEB-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Feb 11, 2020 8:41:15 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Feb 11, 2020 8:41:15 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Feb 11, 2020 8:41:15 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Feb 11, 2020 8:41:15 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Feb 11, 2020 8:41:15 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Feb 11, 2020 8:41:15 PM	No	
20 - Miles			RGASPARD	Feb 11, 2020 8:41:15 PM	No	
30 - Kilometers			RGASPARD	Feb 11, 2020 8:41:15 PM	No	
40 - Hours			RGASPARD	Feb 11, 2020 8:41:15 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53182749 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53251957
Invoice No. 55345 - 53251957

Client Department:
Department: 55345M
Work Order Description
Tech said replace gear box nothing wrong whit it
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 251,666 - DH

Chronology		
Reported	Feb 5, 2020 9:23:47 AM	Feb 5, 2020 9:23:47 AM
Started	Feb 5, 2020 9:27:00 AM	
Completed	Feb 6, 2020 8:50:00 AM	Feb 6, 2020 8:50:00 AM
Down Time		

Work Order Notes

Line 10 Tech said Replace gear box and A/C line nothing wrong with the gear box

Bad booster and hose

Replace brake booster and rear A/C line add Freon Completed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Feb-20	DC2Z-2005-A	BOOSTER, BRAKE, POWER, HYDRAULIC SAME AS BRB-103	1	188.55	188.55

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 06-FEB-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Feb 6, 2020 8:49:57 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Feb 6, 2020 8:49:57 AM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Feb 6, 2020 8:49:57 AM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Feb 6, 2020 8:49:57 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Feb 6, 2020 8:49:57 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Feb 6, 2020 8:49:57 AM	No	
20 - Miles			HPIERRE	Feb 6, 2020 8:49:57 AM	No	
30 - Kilometers	2		HPIERRE	Feb 6, 2020 8:49:57 AM	No	
40 - Hours	6		HPIERRE	Feb 6, 2020 8:49:57 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	188.55
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**188.55**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53251957
Invoice No. 55345 - 53251957

Client Department:
Department: 55345M
Work Order Description
Tech said replace gear box nothing wrong whit it
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 251,666 - DH

Activity Header
Activity: 20 013 BRAKES
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Feb-20	Pierre,Hubert J	5.25	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	5.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53251957
Invoice No. 55345 - 53251957

Client Department:
Department: 55345M
Work Order Description
Tech said replace gear box nothing wrong whit it
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 251,666 - DH

Activity Header
Activity: 30 001/001/000 AIR CONDITIONING
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: C PM Level C
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc:
Task: ELECTRICAL SYSTEM Performed by: HPIERRE Performed on: 06-FEB-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - A/C SYSTEM CHECK	Done		HPIERRE	Feb 6, 2020 8:48:53 AM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53251957 Total	
Parts:	188.55
Labor:	0.00
Labor Hours:	5.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**188.55**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53250825
Invoice No. 55345 - 53250825

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Rear A/C		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	251,666 - DH

Chronology		
Reported	Feb 4, 2020 10:11:58 PM	Feb 4, 2020 10:11:58 PM
Started	Feb 4, 2020 10:30:00 PM	
Completed	Feb 5, 2020 12:18:00 AM	Feb 5, 2020 12:18:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear A/C Compressor not coming On

Cause: Suction hose leaking

Correction: Evacuate .start to remove hose . Did not have time to complete the job.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 04-FEB-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Feb 4, 2020 11:51:07 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		DARTHURS	Feb 4, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				11:51:07 PM		
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Feb 4, 2020 11:51:07 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Feb 4, 2020 11:51:07 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Feb 4, 2020 11:51:07 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Feb 4, 2020 11:51:07 PM	No	
20 - Miles			DARTHURS	Feb 4, 2020 11:51:07 PM	No	
30 - Kilometers			DARTHURS	Feb 4, 2020 11:51:07 PM	No	
40 - Hours			DARTHURS	Feb 4, 2020 11:51:07 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53250825
Invoice No. 55345 - 53250825

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Rear A/C		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	251,666 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Rear A/C
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Feb-20	Arthurs,Durvin	1.33	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53250825 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53182718
Invoice No. 55345 - 53182718

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
FOLLOWUP-FT Light Duty		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	248,452 - DH

Chronology		
Reported	Jan 15, 2020 8:39:53 AM	Jan 15, 2020 8:39:53 AM
Started		
Completed	Jan 15, 2020 10:51:00 AM	Jan 15, 2020 10:51:00 AM
Down Time		

Work Order Notes

Line 10 Complaint: Pm follow up low front brake pads

Cause: preventive maintenance

Correction: replaced front brake pads and lube caliper bracket

Activity Header
Activity: 10 013 BRAKES
Activity Note: low brake pads
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: low brake pads
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 15-JAN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Jan 15, 2020 10:50:42 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Jan 15, 2020 10:50:42 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Jan 15, 2020 10:50:42 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Jan 15, 2020 10:50:42 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Jan 15, 2020 10:50:42 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Jan 15, 2020 10:50:42 AM	No	
20 - Miles			NPIERRE-LOUIS	Jan 15, 2020 10:50:42 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Jan 15, 2020 10:50:42 AM	No	
40 - Hours			NPIERRE-LOUIS	Jan 15, 2020 10:50:42 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53182718
Invoice No. 55345 - 53182718

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
FOLLOWUP-FT Light Duty		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	248,452 - DH

Activity Header
Activity: 20 013 BRAKES
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Jan-20	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	48.87	48.87

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 15-JAN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Jan 15, 2020 10:50:12 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Jan 15, 2020 10:50:12 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Jan 15, 2020 10:50:12 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Jan 15, 2020 10:50:12 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Jan 15, 2020 10:50:12 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Jan 15, 2020 10:50:12 AM	No	
20 - Miles			NPIERRE-LOUIS	Jan 15, 2020 10:50:12 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Jan 15, 2020 10:50:12 AM	No	
40 - Hours			NPIERRE-LOUIS	Jan 15, 2020 10:50:12 AM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	48.87
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**48.87**

Work Order Footer

Work Order 53182718 Total	
Parts:	48.87
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**48.87**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53079998
Invoice No. 55345 - 53079998

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	248,452 - DH

Chronology		
Reported	Jan 14, 2020 3:42:05 PM	Jan 14, 2020 3:42:05 PM
Started	Jan 15, 2020 12:00:00 AM	
Completed	Jan 15, 2020 8:47:00 AM	Jan 15, 2020 8:47:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PmA Service

CAUSE: preventive maintenance

CORRECTION: perform PmA Service lube all Pivoting Points

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Jan-20	NELSON PIERRE-LOUIS	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53079998
Invoice No. 55345 - 53079998

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 248,452 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Jan-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Jan-20	NELSON PIERRE-LOUIS	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: NPIERRE-LOUIS Performed on: 15-JAN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Jan 15, 2020 8:41:27 AM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Jan 15, 2020 8:41:27 AM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Jan 15, 2020 8:41:27 AM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Jan 15, 2020 8:41:27 AM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Jan 15, 2020 8:41:27 AM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Jan 15, 2020 8:41:27 AM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		NPIERRE-LOUIS	Jan 15, 2020 8:41:27 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Jan 15, 2020 8:41:27 AM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	1.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53079998
Invoice No. 55345 - 53079998

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	248,452 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Jan-20	NELSON PIERRE-LOUIS	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 15-JAN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Jan 15, 2020 8:42:02 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Jan 15, 2020 8:42:02 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Jan 15, 2020 8:42:02 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Jan 15, 2020 8:42:02 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Jan 15, 2020 8:42:02 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Jan 15, 2020 8:42:02 AM	No	
20 - Miles			NPIERRE-LOUIS	Jan 15, 2020 8:42:02 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Jan 15, 2020 8:42:02 AM	No	
40 - Hours			NPIERRE-LOUIS	Jan 15, 2020 8:42:02 AM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.50
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53079998 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	3.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53142900
Invoice No. 55345 - 53142900

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Misfire cyl #1		Ford E350 Champion Crusaders	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	247,009 - DH

Chronology		
Reported	Jan 2, 2020 11:50:41 AM	Jan 2, 2020 11:50:41 AM
Started		
Completed	Jan 2, 2020 12:06:00 PM	Jan 2, 2020 12:06:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: Driver stated that check engine light on

Cause: Misfire Cylinder #1

Correction: Replaced ignition coil and spark plugs

Parts: Line 20 Replaced gas cap

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 02-JAN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jan 2, 2020 11:55:53 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jan 2, 2020 11:55:53 AM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Jan 2, 2020 11:55:53 AM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Jan 2, 2020 11:55:53 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jan 2, 2020 11:55:53 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jan 2, 2020 11:55:53 AM	No	
20 - Miles			TDELVA	Jan 2, 2020 11:55:53 AM	No	
30 - Kilometers			TDELVA	Jan 2, 2020 11:55:53 AM	No	
40 - Hours			TDELVA	Jan 2, 2020 11:55:53 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53142900
Invoice No. 55345 - 53142900

Client Department:
Department: 55345M
Work Order Description
Misfire cyl #1
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 247,009 - DH

Activity Header
Activity: 20 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Ignition coil
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Jan-20	3W7Z-12029-AA	COIL, IGNITION SAME AS DG508	2	34.61	69.22
02-Jan-20	3W7Z-12029-AA	COIL, IGNITION SAME AS DG508	1	34.61	34.61
02-Jan-20	10840	CAP, FILLER, FUEL	1	12.13	12.13
02-Jan-20	AP103	PLUG, SPARK	1	3.13	3.13

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	119.09
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**119.09**

Work Order Footer

Work Order 53142900 Total	
Parts:	119.09
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**119.09**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53099504
Invoice No. 55345 - 53099504

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Multi-Function Switch		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	245,205 - DH

Chronology		
Reported	Dec 16, 2019 7:56:52 AM	Dec 16, 2019 7:56:52 AM
Started	Dec 16, 2019 12:00:00 AM	
Completed	Dec 16, 2019 9:08:00 AM	Dec 16, 2019 9:08:00 AM
Down Time		

Work Order Notes

Line 10 Complaint: hazard light button not working properly

Cause: Hazard multifunction switch was malfunction

Correction: Replaced the 7f1z-13k359-AB switch,multifunction signal with a new one.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 16-DEC-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Dec 16, 2019 9:08:22 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Dec 16, 2019 9:08:22 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Dec 16, 2019 9:08:22 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Dec 16, 2019 9:08:22 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Dec 16, 2019 9:08:22 AM	No	
10 - Have you successfully completed the Personal	Done		NPIERRE-	Dec 16, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	9:08:22 AM		
20 - Miles			NPIERRE-LOUIS	Dec 16, 2019 9:08:22 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Dec 16, 2019 9:08:22 AM	No	
40 - Hours			NPIERRE-LOUIS	Dec 16, 2019 9:08:22 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53099504
Invoice No. 55345 - 53099504

Client Department:
Department: 55345M
Work Order Description
Multi-Function Switch
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 245,205 - DH

Activity Header
Activity: 20 050/000/000 GROUP, ACCESSORIES
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Dec-19	7F1Z-13K359-AB	SWITCH, MULTIFUNCTION, SIGNAL, TURN	1	166.19	166.19

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Dec-19	NELSON PIERRE-LOUIS	1	65	65

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	166.19
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**231.19**

Work Order Footer

Work Order 53099504 Total	
Parts:	166.19
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**231.19**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52972413
Invoice No. 55345 - 52972413

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM B		Ford E350 Champion Crusaders	
Requested By:	RRENE	**Status:**	40 - Closed (40)
Created By:	RRENE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	244,331 - DH

Chronology		
Reported	Dec 9, 2019 12:00:00 AM	Dec 9, 2019 12:00:00 AM
Started		
Completed	Dec 9, 2019 11:54:00 PM	Dec 9, 2019 11:54:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMB

CAUSE: Service

CORRECTION: perform PMB service
Oil filter B329 qty1
Engine oil 5w20 qty 7 Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 09-DEC-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,140 - Check Service Brakes	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	RGASPARD	Dec 9, 2019 8:05:03 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	RGASPARD	Dec 9, 2019 8:05:03 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	RGASPARD	Dec 9, 2019 8:05:03 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	RGASPARD	Dec 9, 2019 8:05:03 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	RGASPARD	Dec 9, 2019 8:05:03 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
20,260 - Check Stop Request System	-	NA	RGASPARD	Dec 9, 2019 8:05:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	RGASPARD	Dec 9, 2019 8:05:03 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	RGASPARD	Dec 9, 2019 8:05:03 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
40,420 - Check Hood	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	RGASPARD	Dec 9, 2019 8:05:03 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	RGASPARD	Dec 9, 2019 8:05:03 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	RGASPARD	Dec 9, 2019 8:05:03 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	RGASPARD	Dec 9, 2019 8:05:03 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	RGASPARD	Dec 9, 2019 8:05:03 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	RGASPARD	Dec 9, 2019 8:05:03 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Dec 9, 2019 8:05:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
77,133 - Brake Pad Thickness LR	3 Inch		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
77,134 - Brake Pad Thickness RR	3 Inch		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
77,137 - Brake Rotor LR	36 Inch		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
77,138 - Brake Rotor RR	36 Inch		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
77,150 - Check King Pins	-	NA	RGASPARD	Dec 9, 2019 8:05:03 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Dec 9, 2019 8:05:03 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52972413
Invoice No. 55345 - 52972413

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM B		Ford E350 Champion Crusaders	
Requested By:	RRENE	**Status:**	40 - Closed (40)
Created By:	RRENE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	244,331 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Dec-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: RGASPARD Performed on: 09-DEC-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Dec 9, 2019 9:11:13 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Dec 9, 2019 9:11:13 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Dec 9, 2019 9:11:13 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Dec 9, 2019 9:11:13 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Dec 9, 2019 9:11:13 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Dec 9, 2019 9:11:13 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Dec 9, 2019 9:11:13 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Dec 9, 2019 9:11:13 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Dec 9, 2019 9:11:13 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
201,000 - Service Crankcase Breather	Done		RGASPARD	Dec 9, 2019 9:11:13 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Dec 9, 2019 9:11:13 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Dec 9, 2019 9:11:13 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Dec 9, 2019 9:11:13 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52972413
Invoice No. 55345 - 52972413

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM B		Ford E350 Champion Crusaders	
Requested By:	RRENE	**Status:**	40 - Closed (40)
Created By:	RRENE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	244,331 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 09-DEC-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Dec 9, 2019 9:14:01 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Dec 9, 2019 9:14:01 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Dec 9, 2019 9:14:01 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Dec 9, 2019 9:14:01 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Dec 9, 2019 9:14:01 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Dec 9, 2019 9:14:01 PM	No	
20 - Miles			RGASPARD	Dec 9, 2019 9:14:01 PM	No	
30 - Kilometers			RGASPARD	Dec 9, 2019 9:14:01 PM	No	
40 - Hours			RGASPARD	Dec 9, 2019 9:14:01 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 52972413 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53079816
Invoice No. 55345 - 53079816

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Needs rear brakes job		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	244,331 - DH

Chronology		
Reported	Dec 9, 2019 9:16:06 PM	Dec 9, 2019 9:16:06 PM
Started		
Completed	Dec 9, 2019 11:53:00 PM	Dec 9, 2019 11:53:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs rear brakes job

Cause: wear

Correction:replaced rear brake pads and lubed guide pins
Torque wheels 140 lbs second torque 140 lbs
Part number 9C2Z-2Z2V200-B qty1

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 09-DEC-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Dec 9, 2019 9:17:40 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Dec 9, 2019 9:17:40 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Dec 9, 2019 9:17:40 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Dec 9, 2019 9:17:40 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Dec 9, 2019 9:17:40 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Dec 9, 2019 9:17:40 PM	No	
20 - Miles			RGASPARD	Dec 9, 2019 9:17:40 PM	No	
30 - Kilometers			RGASPARD	Dec 9, 2019 9:17:40 PM	No	
40 - Hours			RGASPARD	Dec 9, 2019 9:17:40 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53079984
Invoice No. 55345 - 53079984

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Needs 2 tires		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	244,331 - DH

Chronology		
Reported	Dec 9, 2019 11:36:46 PM	Dec 9, 2019 11:36:46 PM
Started		
Completed	Dec 9, 2019 11:53:00 PM	Dec 9, 2019 11:53:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs 2 right rear tires

Cause: wear

Correction:2New tires mounted and balanced
Torque wheels 140 lbs second torque 140 lbs
Part 192659 qty2

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 09-DEC-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Dec 9, 2019 11:38:57 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Dec 9, 2019 11:38:57 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Dec 9, 2019 11:38:57 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Dec 9, 2019 11:38:57 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Dec 9, 2019 11:38:57 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Dec 9, 2019 11:38:57 PM	No	
20 - Miles			RGASPARD	Dec 9, 2019 11:38:57 PM	No	
30 - Kilometers			RGASPARD	Dec 9, 2019 11:38:57 PM	No	
40 - Hours			RGASPARD	Dec 9, 2019 11:38:57 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53079816
Invoice No. 55345 - 53079816

Client Department:
Department: 55345M
Work Order Description
Needs rear brakes job
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 244,331 - DH

Activity Header
Activity: 15 013/000/000 BRAKES
Activity Note: Needs rear brakes job
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Dec-19	9C2Z-2V200-B	PADS, BRAKE, DISC, REAR SAME AS BRSD1329B	1	46.22	46.22

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	46.22
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**46.22**

Work Order Footer

Work Order 53079816 Total	
Parts:	46.22
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**46.22**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53079984
Invoice No. 55345 - 53079984

Client Department:
Department: 55345M
Work Order Description
Needs 2 tires
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 244,331 - DH

Activity Header
Activity: 15 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note: Needs 2 new tires
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Dec-19	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	123.25	246.5

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	246.50
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**246.50**

Work Order Footer

Work Order 53079984 Total	
Parts:	246.50
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**246.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52862625
Invoice No. 55345 - 52862625

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	RRENE	**Status:**	40 - Closed (40)
Created By:	RRENE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	239,748 - DH

Chronology		
Reported	Nov 5, 2019 8:09:58 AM	Nov 5, 2019 8:09:58 AM
Started	Nov 5, 2019 12:00:00 AM	
Completed	Nov 6, 2019 7:48:58 AM	Nov 6, 2019 7:48:58 AM
Down Time		

Work Order Notes

Line 10 PM.

Perform pmA service, lube front end, tire rotation, torque and re torque tires (140 f/p), R&R engine oil and filter, road test, all okay at this time.

Parts. Engine oil filter part # B329 qty 1
engine oil. 5W20 Qty 6 qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Nov-19	Rodriguez,Raul	1.5666666	65	101.833329

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RAURODRIGUEZ Performed on: 05-NOV-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
10,100 - Safety Inspection	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
10,120 - FRA Check All Warning Lights and	Done		RAURODRIGUEZ	Nov 5, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				10:23:31 AM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
10,140 - Check Service Brakes	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
10,160 - FRA Check Instruments and Horns	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
10,170 - Check Fast Idle	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
10,180 - Check Starter Protection Circuit	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
10,190 - Check Reverse Warning System	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
11,100 - Check Parking Brake	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
11,150 - Perform Brake Test	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
11,170 - FRA Check Door Operation	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
20,210 - Check Condition of Operator's Area	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
20,240 - FRA Check Interior Lights	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
20,250 - FRA Check Interior Electrical	Done		RAURODRIGUEZ	Nov 5, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Panels				10:23:31 AM		
20,260 - Check Stop Request System	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
22,110 - Check Emergency Hatches	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
22,120 - Check All Safety Equipment	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
30,310 - Check Passenger Doors	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
30,340 - FRA Check Destination Sign and Run Box	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
30,360 - Check for Physical Damage and Decals	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
30,380 - Check Exterior Compartment Doors	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
33,100 - Check Lights and Reflectors	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
40,420 - Check Hood	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
40,442 - Freeze Point	Degree	na	RAURODRIGUEZ	Nov 5, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			10:23:31 AM		
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
44,130 - FRA Check Exhaust System	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
44,140 - FRA Check Intake System	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
44,150 - FRA Inspect Turbocharger	-	na	RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
44,180 - FRA Check for Leaks	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
44,190 - FRA Perform Battery Inspection	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
50,510 - Check Entire Steering System	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
60,615 - Air Pressure LRI	65 Pounds per		RAURODRIGUEZ	Nov 5, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			10:23:31 AM		
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
60,620 - Check Valve Stems and Caps	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
60,630 - Check and Record Tread Depth	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
60,631 - Tread Depth RF	11 32nds of an inch		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
60,632 - Tread Depth LF	11 32nds of an inch		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
60,633 - Tread Depth RRO	11 32nds of an inch		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
60,634 - Tread Depth RRI	11 32nds of an inch		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
60,636 - Tread Depth LRO	12 32nds of an inch		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
60,650 - Check Sidewall Wear	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
60,660 - Inspect for Cuts and Tears	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
60,670 - Check Dual Mating With Square	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
70,710 - Check Vibration Damper	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
70,730 - FRA Check Starter	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
70,770 - FRA Check Exhaust System	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
70,790 - Check All Body Mounts and	Done		RAURODRIGUEZ	Nov 5, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Chassis Frame				10:23:31 AM		
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
77,110 - FRA Check Fuel Tank	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
77,120 - Check Suspension Components	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
77,131 - Brake Pad Thickness LF	Inch	7mm	RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
77,132 - Brake Pad Thickness RF	Inch	7mm	RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
77,133 - Brake Pad Thickness LR	Inch	5mm	RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
77,134 - Brake Pad Thickness RR	Inch	5mm	RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
77,135 - Brake Rotor LF	Inch	39.1mm	RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
77,136 - Brake Rotor RF	Inch	39.1mm	RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
77,137 - Brake Rotor LR	Inch	34.8mm	RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
77,138 - Brake Rotor RR	Inch	34.8mm	RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
77,140 - FRA Check Brake Hoses	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
77,150 - Check King Pins	-	na	RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
80,810 - Completion of PMI Report	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		RAURODRIGUEZ	Nov 5, 2019 10:23:31 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	101.83
Labor Hours:	1.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**101.83**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52862625
Invoice No. 55345 - 52862625

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	RRENE	**Status:**	40 - Closed (40)
Created By:	RRENE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	239,748 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Nov-19	65266	PLUG, DRAIN, OIL, ENGINE	1	4.28	4.28
05-Nov-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Nov-19	Rodriguez,Raul	0.5666666	65	36.833329

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RAURODRIGUEZ Performed on: 05-NOV-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RAURODRIGUEZ	Nov 5, 2019 10:27:42 AM	No	
101,000 - FRA Change Oil Filters	Yes		RAURODRIGUEZ	Nov 5, 2019 10:27:42 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RAURODRIGUEZ	Nov 5, 2019 10:27:42 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RAURODRIGUEZ	Nov 5, 2019 10:27:42 AM	No	
104,000 - Lubricate Chassis	Done		RAURODRIGUEZ	Nov 5, 2019 10:27:42 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RAURODRIGUEZ	Nov 5, 2019 10:27:42 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RAURODRIGUEZ	Nov 5, 2019 10:27:42 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RAURODRIGUEZ	Nov 5, 2019 10:27:42 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	6.24
Labor:	36.83
Labor Hours:	0.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.07**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52862625
Invoice No. 55345 - 52862625

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	RRENE	**Status:**	40 - Closed (40)
Created By:	RRENE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	239,748 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 05-NOV-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Nov 5, 2019 10:28:54 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Nov 5, 2019 10:28:54 AM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Nov 5, 2019 10:28:54 AM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Nov 5, 2019 10:28:54 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Nov 5, 2019 10:28:54 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Nov 5, 2019 10:28:54 AM	No	
20 - Miles			RAURODRIGUEZ	Nov 5, 2019 10:28:54 AM	No	
30 - Kilometers			RAURODRIGUEZ	Nov 5, 2019 10:28:54 AM	No	
40 - Hours			RAURODRIGUEZ	Nov 5, 2019 10:28:54 AM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 52862625 Total	
Parts:	6.24
Labor:	138.67
Labor Hours:	2.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**144.91**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52865837
Invoice No. 55345 - 52865837

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Radiator Cap		Ford E350 Champion Crusaders	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	235,310 - DH

Chronology		
Reported	Oct 5, 2019 11:47:38 AM	Oct 5, 2019 11:47:38 AM
Started	Oct 8, 2019 12:00:00 AM	
Completed	Oct 9, 2019 9:33:35 AM	Oct 9, 2019 9:33:35 AM
Down Time		

Work Order Notes

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Oct-19	Delva,Terry	0.2833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 08-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Oct 8, 2019 3:29:57 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Oct 8, 2019 3:29:57 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Oct 8, 2019 3:29:57 PM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Oct 8, 2019 3:29:57 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Oct 8, 2019 3:29:57 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Oct 8, 2019 3:29:57 PM	No	
20 - Miles			TDELVA	Oct 8, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:29:57 PM		
30 - Kilometers			TDELVA	Oct 8, 2019 3:29:57 PM	No	
40 - Hours			TDELVA	Oct 8, 2019 3:29:57 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52865837
Invoice No. 55345 - 52865837

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Radiator Cap		Ford E350 Champion Crusaders	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	235,310 - DH

Activity Header
Activity:20
Activity Note:
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Oct-19	10238	CAP, RADIATOR, FORD	1	6.23	6.23

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Oct-19	Delva,Terry	0.2666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	6.23
Labor:	0.00
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**6.23**

Work Order Footer

Work Order 52865837 Total	
Parts:	6.23
Labor:	0.00
Labor Hours:	0.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**6.23**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52732415
Invoice No. 55345 - 52732415

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	235,224 - DH

Chronology		
Reported	Oct 3, 2019 6:26:41 AM	Oct 3, 2019 6:26:41 AM
Started		
Completed	Oct 4, 2019 8:30:14 AM	Oct 4, 2019 8:30:14 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PmA

CAUSE: preventive maintenance

CORRECTION: perform PmA Service lube all Pivoting Points Replace 4 Tires One new completed

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 03-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
10,100 - Safety Inspection	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Oct 3, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:50:21 AM		
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
11,152 - Decelerometer Results Test 1	FEET	N/A	HPIERRE	Oct 3, 2019 11:50:21 AM	No	
11,154 - Decelerometer Results Test 2	FEET	N/A	HPIERRE	Oct 3, 2019 11:50:21 AM	No	
11,156 - Decelerometer Results Test 3	FEET	N/A	HPIERRE	Oct 3, 2019 11:50:21 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	Oct 3, 2019 11:50:21 AM	No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	Oct 3, 2019 11:50:21 AM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Oct 3, 2019 11:50:21 AM	No	
20,270 - Check Fare Box Mounting (If	-	N/A	HPIERRE	Oct 3, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Applicable)				11:50:21 AM		
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Oct 3, 2019 11:50:21 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
40,420 - Check Hood	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Oct 3, 2019 11:50:21 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Oct 3, 2019 11:50:21 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Oct 3, 2019 11:50:21 AM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
40,460 - Record Antifreeze Protection Level	-	N/A	HPIERRE	Oct 3, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Using Refractometer				11:50:21 AM		
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Oct 3, 2019 11:50:21 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Oct 3, 2019 11:50:21 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Oct 3, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:50:21 AM		
60,630 - Check and Record Tread Depth	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
60,631 - Tread Depth RF	10 32nds of an inch		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
60,632 - Tread Depth LF	10 32nds of an inch		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
60,633 - Tread Depth RRO	3 32nds of an inch		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
60,634 - Tread Depth RRI	3 32nds of an inch		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
60,635 - Tread Depth LRI	3 32nds of an inch		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
60,636 - Tread Depth LRO	4 32nds of an inch	need rear tires	HPIERRE	Oct 3, 2019 11:50:21 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Oct 3, 2019 11:50:21 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Oct 3, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:50:21 AM		
77,120 - Check Suspension Components	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
77,131 - Brake Pad Thickness LF	10 Inch		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
77,132 - Brake Pad Thickness RF	10 Inch		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
77,133 - Brake Pad Thickness LR	6 Inch		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
77,134 - Brake Pad Thickness RR	6 Inch		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
77,135 - Brake Rotor LF	1.6 Inch		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
77,136 - Brake Rotor RF	1.6 Inch		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
77,137 - Brake Rotor LR	1.7 Inch		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
77,138 - Brake Rotor RR	1.7 Inch		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Oct 3, 2019 11:50:21 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Oct 3, 2019 11:50:21 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52732415
Invoice No. 55345 - 52732415

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 235,224 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Oct-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 03-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Oct 3, 2019 11:51:23 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Oct 3, 2019 11:51:23 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Oct 3, 2019 11:51:23 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Oct 3, 2019 11:51:23 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Oct 3, 2019 11:51:23 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Oct 3, 2019 11:51:23 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Oct 3, 2019 11:51:23 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Oct 3, 2019 11:51:23 AM	No	

Activity Sub Total

Activity 20 Sub Total
Parts: 1.96

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52732415
Invoice No. 55345 - 52732415

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 235,224 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 03-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Oct 3, 2019 11:52:09 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Oct 3, 2019 11:52:09 AM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Oct 3, 2019 11:52:09 AM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Oct 3, 2019 11:52:09 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Oct 3, 2019 11:52:09 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Oct 3, 2019 11:52:09 AM	No	
20 - Miles			HPIERRE	Oct 3, 2019 11:52:09 AM	No	
30 - Kilometers	2		HPIERRE	Oct 3, 2019 11:52:09 AM	No	
40 - Hours	6		HPIERRE	Oct 3, 2019 11:52:09 AM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 52732415 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52859485
Invoice No. 55345 - 52859485

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Pma follow up need tire		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	235,224 - DH

Chronology		
Reported	Oct 3, 2019 11:54:58 AM	Oct 3, 2019 11:54:58 AM
Started		
Completed	Oct 4, 2019 7:07:00 AM	Oct 4, 2019 7:07:00 AM
Down Time		

Work Order Notes

Line 10 PmA service follow up need rear tires

Preventive maintenance

Replace all 4 rear tires 3 use one new mounted and balance completed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 03-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Oct 3, 2019 11:57:28 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Oct 3, 2019 11:57:28 AM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Oct 3, 2019 11:57:28 AM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Oct 3, 2019 11:57:28 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Oct 3, 2019 11:57:28 AM	No	
10 - Have you successfully completed the Personal	Done		HPIERRE	Oct 3, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				11:57:28 AM		
20 - Miles			HPIERRE	Oct 3, 2019 11:57:28 AM	No	
30 - Kilometers	2		HPIERRE	Oct 3, 2019 11:57:28 AM	No	
40 - Hours	2		HPIERRE	Oct 3, 2019 11:57:28 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52859485
Invoice No. 55345 - 52859485

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Pma follow up need tire		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	235,224 - DH

Activity Header
Activity:20 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Oct-19	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	1	120.48	120.48

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	120.48
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**120.48**

Work Order Footer

Work Order 52859485 Total	
Parts:	120.48
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**120.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52755351
Invoice No. 55345 - 52755351

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Radiator		Ford E350 Champion Crusaders	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	231,003 - DH

Chronology		
Reported	Sep 4, 2019 11:32:40 AM	Sep 4, 2019 11:32:40 AM
Started	Sep 4, 2019 12:00:00 AM	
Completed	Sep 4, 2019 2:54:38 PM	Sep 4, 2019 2:54:38 PM
Down Time		

Work Order Notes

Line 10 Replaced radiator

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Sep-19	Delva,Terry	2.8166666	65	183.083329

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 04-SEP-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Sep 4, 2019 11:41:48 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Sep 4, 2019 11:41:48 AM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Sep 4, 2019 11:41:48 AM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Sep 4, 2019 11:41:48 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Sep 4, 2019 11:41:48 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Sep 4, 2019 11:41:48 AM	No	
20 - Miles			TDELVA	Sep 4, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:41:48 AM		
30 - Kilometers			TDELVA	Sep 4, 2019 11:41:48 AM	No	
40 - Hours			TDELVA	Sep 4, 2019 11:41:48 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	183.08
Labor Hours:	2.82
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**183.08**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52755351
Invoice No. 55345 - 52755351

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Radiator		Ford E350 Champion Crusaders	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	231,003 - DH

Activity Header
Activity:20 042/000/000 COOLING SYSTEM
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Sep-19	G1000382282CSF	RADIATOR, E450	1	205.18	205.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Sep-19	Delva,Terry	0.5166666	65	33.583329

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	205.18
Labor:	33.58
Labor Hours:	0.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**238.76**

Work Order Footer

Work Order 52755351 Total	
Parts:	205.18
Labor:	216.67
Labor Hours:	3.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**421.85**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52732263
Invoice No. 55345 - 52732263

Client Department:
Department: 55345M
Work Order Description
Replaced front tires and interior lights
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 230,625 - DH

Chronology		
Reported	Aug 27, 2019 8:31:35 PM	Aug 27, 2019 8:31:35 PM
Started	Aug 27, 2019 12:00:00 AM	
Completed	Aug 27, 2019 10:42:00 PM	Aug 27, 2019 10:42:00 PM
Down Time		

Work Order Notes

Line 10 Mount and balanced 2 front tires
Torqued wheels to 140ftlb test driven and retorqued
Replaced 2 interior led lights

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Aug-19	AMRIT TEEMAL,VISHNU	0.2666666	65	17.333329

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 27-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Aug 27, 2019 8:40:27 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Aug 27, 2019 8:40:27 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Aug 27, 2019 8:40:27 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Aug 27, 2019 8:40:27 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Aug 27, 2019 8:40:27 PM	No	
10 - Have you successfully completed the	Done		VAMRITTEEMAL	Aug 27, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				8:40:27 PM		
20 - Miles			VAMRITTEEMAL	Aug 27, 2019 8:40:27 PM	No	
30 - Kilometers			VAMRITTEEMAL	Aug 27, 2019 8:40:27 PM	No	
40 - Hours			VAMRITTEEMAL	Aug 27, 2019 8:40:27 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	17.33
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**17.33**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52732263
Invoice No. 55345 - 52732263

Client Department:
Department: 55345M
Work Order Description
Replaced front tires and interior lights
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 230,625 - DH

Activity Header
Activity:20 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Aug-19	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	120.48	240.96
27-Aug-19	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	120.48	240.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Aug-19	AMRIT TEEMAL,VISHNU	1	65	65

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	481.92
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**546.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52732263
Invoice No. 55345 - 52732263

Client Department:
Department: 55345M
Work Order Description
Replaced front tires and interior lights
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 230,625 - DH

Activity Header
Activity: 30 034/000/000 LIGHTING SYSTEM
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Aug-19	3976389	LAMP, INTERIOR, LED	2	26.71	53.42

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Aug-19	AMRIT TEEMAL,VISHNU	0.5	65	32.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	106.84
Labor:	32.50
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**139.34**

Work Order Footer

Work Order 52732263 Total	
Parts:	588.76
Labor:	114.83
Labor Hours:	1.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**703.59**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52635748
Invoice No. 55345 - 52635748

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 230,625 - DH

Chronology		
Reported	Aug 27, 2019 12:00:00 AM	Aug 27, 2019 12:00:00 AM
Started	Aug 27, 2019 12:00:00 AM	
Completed	Aug 27, 2019 10:40:00 PM	Aug 27, 2019 10:40:00 PM
Down Time		

Work Order Notes

Line 10 PMC SERVICE
PREVENTIVE MAINTENANCE
PERFORM AND COMPLETED PMC SERVICE

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Aug-19	AMRIT TEEMAL,VISHNU	2.5	65	162.5

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: VAMRITTEEMAL Performed on: 27-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
10,100 - Safety Inspection	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
10,140 - Check Service Brakes	Done		VAMRITTEEMAL	Aug 27, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:18:52 PM		
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
10,160 - FRA Check Instruments and Horns	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
10,170 - Check Fast Idle	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
10,180 - Check Starter Protection Circuit	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
10,190 - Check Reverse Warning System	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
11,100 - Check Parking Brake	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
11,150 - Perform Brake Test	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
11,152 - Decelerometer Results Test 1	FEET	n/a	VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
11,154 - Decelerometer Results Test 2	FEET	n/a	VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
11,156 - Decelerometer Results Test 3	FEET	n/a	VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
11,170 - FRA Check Door Operation	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
20,210 - Check Condition of Operator's Area	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
20,240 - FRA Check Interior Lights	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
20,260 - Check Stop Request System	-	n/a	VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
20,270 - Check Fare Box Mounting (If	-	n/a	VAMRITTEEMAL	Aug 27, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Applicable)				8:18:52 PM		
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
22,110 - Check Emergency Hatches	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
22,120 - Check All Safety Equipment	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
30,310 - Check Passenger Doors	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
30,360 - Check for Physical Damage and Decals	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
30,380 - Check Exterior Compartment Doors	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
33,100 - Check Lights and Reflectors	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
40,420 - Check Hood	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
40,460 - Record Antifreeze Protection Level	-	n/a	VAMRITTEEMAL	Aug 27, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Using Refractometer				8:18:52 PM		
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
44,130 - FRA Check Exhaust System	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
44,140 - FRA Check Intake System	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
44,180 - FRA Check for Leaks	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
44,190 - FRA Perform Battery Inspection	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
50,510 - Check Entire Steering System	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
60,620 - Check Valve Stems and Caps	Done		VAMRITTEEMAL	Aug 27, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:18:52 PM		
60,630 - Check and Record Tread Depth	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
60,631 - Tread Depth RF	4 32nds of an inch		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
60,632 - Tread Depth LF	4 32nds of an inch		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
60,650 - Check Sidewall Wear	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
60,660 - Inspect for Cuts and Tears	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
70,710 - Check Vibration Damper	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
70,730 - FRA Check Starter	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
70,770 - FRA Check Exhaust System	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
77,110 - FRA Check Fuel Tank	Done		VAMRITTEEMAL	Aug 27, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:18:52 PM		
77,120 - Check Suspension Components	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
77,135 - Brake Rotor LF	39.91 Inch		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
77,136 - Brake Rotor RF	39.9 Inch		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
77,137 - Brake Rotor LR	35.89 Inch		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
77,138 - Brake Rotor RR	35.86 Inch		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
77,140 - FRA Check Brake Hoses	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
77,150 - Check King Pins	-	n/a	VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
80,810 - Completion of PMI Report	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		VAMRITTEEMAL	Aug 27, 2019 8:18:52 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	162.50
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**162.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52635748
Invoice No. 55345 - 52635748

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 230,625 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Aug-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96
27-Aug-19	20021	FILTER, TRANSMISSION 20021	1	17.27	17.27

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Aug-19	AMRIT TEEMAL,VISHNU	2	65	130

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: VAMRITTEEMAL Performed on: 27-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		VAMRITTEEMAL	Aug 27, 2019 8:09:52 PM	No	
101,000 - FRA Change Oil Filters	Yes		VAMRITTEEMAL	Aug 27, 2019 8:09:52 PM	No	
102,000 - FRA Drain Engine Oil	Yes		VAMRITTEEMAL	Aug 27, 2019 8:09:52 PM	No	
103,000 - FRA Check Transmission Fluid	Done		VAMRITTEEMAL	Aug 27, 2019 8:09:52 PM	No	
104,000 - Lubricate Chassis	Done		VAMRITTEEMAL	Aug 27, 2019 8:09:52 PM	No	
105,000 - Replace or Clean A/C Filters	Done		VAMRITTEEMAL	Aug 27, 2019 8:09:52 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	n/a	VAMRITTEEMAL	Aug 27, 2019 8:09:52 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		VAMRITTEEMAL	Aug 27, 2019 8:09:52 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		VAMRITTEEMAL	Aug 27, 2019 8:09:52 PM	No	
201,000 - Service Crankcase Breather	-	n/a	VAMRITTEEMAL	Aug 27, 2019 8:09:52 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		VAMRITTEEMAL	Aug 27, 2019 8:09:52 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No	n/a	VAMRITTEEMAL	Aug 27, 2019 8:09:52 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		VAMRITTEEMAL	Aug 27, 2019 8:09:52 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		VAMRITTEEMAL	Aug 27, 2019 8:09:52 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		VAMRITTEEMAL	Aug 27, 2019 8:09:52 PM	No	
302,000 - Check Toe-In and Record Reading	-	n/a	VAMRITTEEMAL	Aug 27, 2019 8:09:52 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	n/a	VAMRITTEEMAL	Aug 27, 2019 8:09:52 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No	n/a	VAMRITTEEMAL	Aug 27, 2019 8:09:52 PM	No	
305,000 - FRA Change Differential Fluid	Yes		VAMRITTEEMAL	Aug 27, 2019 8:09:52 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	19.23
Labor:	130.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**149.23**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52635748
Invoice No. 55345 - 52635748

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM C		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	230,625 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Aug-19	AMRIT TEEMAL,VISHNU	0.2666666	65	17.333329

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 27-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Aug 27, 2019 8:07:14 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Aug 27, 2019 8:07:14 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Aug 27, 2019 8:07:14 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Aug 27, 2019 8:07:14 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Aug 27, 2019 8:07:14 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Aug 27, 2019 8:07:14 PM	No	
20 - Miles			VAMRITTEEMAL	Aug 27, 2019 8:07:14 PM	No	
30 - Kilometers			VAMRITTEEMAL	Aug 27, 2019 8:07:14 PM	No	
40 - Hours			VAMRITTEEMAL	Aug 27, 2019 8:07:14 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	17.33
	Labor Hours:	0.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**17.33**

Work Order Footer

Work Order 52635748 Total	
Parts:	19.23
Labor:	309.83
Labor Hours:	4.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**329.06**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52635732
Invoice No. 55345 - 52635732

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Right Motor mount		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	226,102 - DH

Chronology		
Reported	Jul 25, 2019 9:12:21 PM	Jul 25, 2019 9:12:21 PM
Started	Jul 25, 2019 12:00:00 AM	
Completed	Jul 25, 2019 9:21:00 PM	Jul 25, 2019 9:21:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Right Side Motor Mount

Cause: Motor Mount Broken.

Correction: Remove& Replace Right Side Motor Mount.
Parts# F7UZ-6038-DC Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Jul-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 25-JUL-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jul 25, 2019 9:13:56 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jul 25, 2019 9:13:56 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jul 25, 2019 9:13:56 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jul 25, 2019 9:13:56 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jul 25, 2019 9:13:56 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 25, 2019 9:13:56 PM	No	
20 - Miles			DARTHURS	Jul 25, 2019 9:13:56 PM	No	
30 - Kilometers			DARTHURS	Jul 25, 2019 9:13:56 PM	No	
40 - Hours			DARTHURS	Jul 25, 2019 9:13:56 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	5.42
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.42**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52547408
Invoice No. 55345 - 52547408

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	226,102 - DH

Chronology		
Reported	Jul 25, 2019 10:16:13 AM	Jul 25, 2019 10:16:13 AM
Started	Jul 25, 2019 12:00:00 AM	
Completed	Jul 25, 2019 9:21:00 PM	Jul 25, 2019 9:21:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PMA Service

CAUSE: Service due by Mileage.

CORRECTION: Change Oil & Filter. Lube all Pivoting Points . Check brakes. Clean batteries. Replace .A/C Filter.
Parts# B329 Qty (1)
Oil 5W20 Qty (6.5) Qt

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Jul-19	Arthurs,Durvin	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 25-JUL-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Jul 25, 2019 9:06:23 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Jul 25, 2019 9:06:23 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Jul 25, 2019 9:06:23 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Jul 25, 2019 9:06:23 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Jul 25, 2019 9:06:23 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	Jul 25, 2019 9:06:23 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Jul 25, 2019 9:06:23 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
40,420 - Check Hood	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Jul 25, 2019 9:06:23 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Jul 25, 2019 9:06:23 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Jul 25, 2019 9:06:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Jul 25, 2019 9:06:23 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Jul 25, 2019 9:06:23 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Jul 25, 2019 9:06:23 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Jul 25, 2019 9:06:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
60,631 - Tread Depth RF	6 32nds of an inch		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
60,632 - Tread Depth LF	6 32nds of an inch		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
60,634 - Tread Depth RRI	5 32nds of an inch		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
60,635 - Tread Depth LRI	5 32nds of an inch		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
60,636 - Tread Depth LRO	5 32nds of an inch		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Jul 25, 2019 9:06:23 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
77,131 - Brake Pad Thickness LF	12 Inch		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
77,132 - Brake Pad Thickness RF	12 Inch		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
77,135 - Brake Rotor LF	1.553 Inch		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
77,136 - Brake Rotor RF	1.554 Inch		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
77,137 - Brake Rotor LR	1.414 Inch		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
77,138 - Brake Rotor RR	1.413 Inch		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Jul 25, 2019 9:06:23 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Jul 25, 2019 9:06:23 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52635732
Invoice No. 55345 - 52635732

Client Department:
Department: 55345M
Work Order Description
Right Motor mount
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 226,102 - DH

Activity Header
Activity: 15 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Jul-19	F7UZ-6038-DC	INSULATOR	1	36.22	36.22

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Jul-19	Arthurs,Durvin	1	65	65

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	36.22
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**101.22**

Work Order Footer

Work Order 52635732 Total	
Parts:	36.22
Labor:	70.42
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**106.64**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52547408
Invoice No. 55345 - 52547408

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 226,102 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Jul-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Jul-19	Arthurs,Durvin	0.4166666	65	27.083329

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 25-JUL-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Jul 25, 2019 9:07:07 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Jul 25, 2019 9:07:07 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Jul 25, 2019 9:07:07 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Jul 25, 2019 9:07:07 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Jul 25, 2019 9:07:07 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Jul 25, 2019 9:07:07 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Jul 25, 2019 9:07:07 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Jul 25, 2019 9:07:07 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	27.08
	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**29.04**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52547408
Invoice No. 55345 - 52547408

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	226,102 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Jul-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 25-JUL-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jul 25, 2019 9:07:46 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jul 25, 2019 9:07:46 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jul 25, 2019 9:07:46 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jul 25, 2019 9:07:46 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jul 25, 2019 9:07:46 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 25, 2019 9:07:46 PM	No	
20 - Miles			DARTHURS	Jul 25, 2019 9:07:46 PM	No	
30 - Kilometers			DARTHURS	Jul 25, 2019 9:07:46 PM	No	
40 - Hours			DARTHURS	Jul 25, 2019 9:07:46 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	5.42
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**5.42**

Work Order Footer

Work Order 52547408 Total	
Parts:	1.96
Labor:	130.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**131.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52576947
Invoice No. 55345 - 52576947

Client Department:
Department: 55345M
Work Order Description
Overheating
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 223,262 - DH

Chronology		
Reported	Jul 5, 2019 12:33:51 PM	Jul 5, 2019 12:33:51 PM
Started		
Completed	Jul 8, 2019 10:00:23 AM	Jul 8, 2019 10:00:23 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:overheating

Cause: tech check the vehicle system found the pulley back side was frozen

Correction: replaced the pulley and the belt
Parts: pulley 89026
Serpentine belt: 1360k6

Activity Header
Activity:5 193 SYSTEM, BELT, CONVEYOR
Activity Note: PRAMETER
Reason for Repair: 10 Road Call
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 05-JUL-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-	Jul 5, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	12:48:51 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Jul 5, 2019 12:48:51 PM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Jul 5, 2019 12:48:51 PM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Jul 5, 2019 12:48:51 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Jul 5, 2019 12:48:51 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Jul 5, 2019 12:48:51 PM	No	
20 - Miles			NPIERRE-LOUIS	Jul 5, 2019 12:48:51 PM	No	
30 - Kilometers			NPIERRE-LOUIS	Jul 5, 2019 12:48:51 PM	No	
40 - Hours			NPIERRE-LOUIS	Jul 5, 2019 12:48:51 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52576947
Invoice No. 55345 - 52576947

Client Department:
Department: 55345M
Work Order Description
Overheating
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 223,262 - DH

Activity Header
Activity: 10 193 SYSTEM, BELT, CONVEYOR
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Jul-19	89026	PULLEY, IDLER, SMOOTH	1	13.57	13.57
05-Jul-19	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	21.09	21.09

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	34.66
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**34.66**

Work Order Footer

Work Order 52576947 Total	
Parts:	34.66
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**34.66**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52550640
Invoice No. 55345 - 52550640

Client Department:
Department: 55345M
Work Order Description
Replace Two rear a/c fans
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 222,042 - DH

Chronology		
Reported	Jun 25, 2019 5:15:00 PM	Jun 25, 2019 5:15:00 PM
Started	Jun 26, 2019 12:00:00 AM	
Completed	Jun 26, 2019 8:56:00 AM	Jun 26, 2019 8:56:00 AM
Down Time		

Work Order Notes

Line 10 Replaced rear Ac Condenser fans (2)
Please charge parts

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Jun-19	Delva,Terry	0.6666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 26-JUN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jun 26, 2019 8:53:50 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jun 26, 2019 8:53:50 AM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Jun 26, 2019 8:53:50 AM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Jun 26, 2019 8:53:50 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jun 26, 2019 8:53:50 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jun 26, 2019 8:53:50 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			TDELVA	Jun 26, 2019 8:53:50 AM	No	
30 - Kilometers			TDELVA	Jun 26, 2019 8:53:50 AM	No	
40 - Hours			TDELVA	Jun 26, 2019 8:53:50 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52550640
Invoice No. 55345 - 52550640

Client Department:
Department: 55345M
Work Order Description
Replace Two rear a/c fans
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 222,042 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Replace 2 rear a/c fans
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Jun-19	8050002	FAN, CONDENSER, A/C, MOUNT, FLUSH, 14"	3	66.04	198.12

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Jun-19	Delva,Terry	0.5166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	198.12
Labor:	0.00
Labor Hours:	0.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**198.12**

Work Order Footer

Work Order 52550640 Total	
Parts:	198.12
Labor:	0.00
Labor Hours:	1.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**198.12**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52547396
Invoice No. 55345 - 52547396

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Needs front brakes job		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	221,874 - DH

Chronology		
Reported	Jun 24, 2019 11:41:37 PM	Jun 24, 2019 11:41:37 PM
Started	Jun 24, 2019 12:00:00 AM	
Completed	Jun 25, 2019 12:00:00 AM	Jun 25, 2019 12:00:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs front brakes job

Cause: wear

Correction:Replaced front brake pads and lubed guide pins
Torque wheels 140 lbs second torque 140 lbs
Part number 8C2Z-2V001-D qty 1

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Jun-19	Gaspard,Ronald	0.1	65	6.5

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 24-JUN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Jun 24, 2019 11:43:13 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Jun 24, 2019 11:43:13 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Jun 24, 2019 11:43:13 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Jun 24, 2019 11:43:13 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Jun 24, 2019 11:43:13 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jun 24, 2019 11:43:13 PM	No	
20 - Miles			RGASPARD	Jun 24, 2019 11:43:13 PM	No	
30 - Kilometers			RGASPARD	Jun 24, 2019 11:43:13 PM	No	
40 - Hours			RGASPARD	Jun 24, 2019 11:43:13 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	6.50
Labor Hours:	0.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**6.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52458634
Invoice No. 55345 - 52458634

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	221,874 - DH

Chronology		
Reported	Jun 24, 2019 12:08:53 PM	Jun 24, 2019 12:08:53 PM
Started	Jun 24, 2019 12:00:00 AM	
Completed	Jun 25, 2019 12:00:00 AM	Jun 25, 2019 12:00:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE: Service

CORRECTION:Perform pmA Service
Oil filter B329 qty 1
Engine oil 5w20 qty 7 Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Jun-19	Gaspard,Ronald	1.5833333	65	102.9166645

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 24-JUN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
10,120 - FRA Check All Warning Lights and	Done		RGASPARD	Jun 24, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				11:34:17 PM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Jun 24, 2019 11:34:17 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Jun 24, 2019 11:34:17 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Jun 24, 2019 11:34:17 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Jun 24, 2019 11:34:17 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Jun 24, 2019 11:34:17 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Jun 24, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:34:17 PM		
20,260 - Check Stop Request System	-	na	RGASPARD	Jun 24, 2019 11:34:17 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Jun 24, 2019 11:34:17 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Jun 24, 2019 11:34:17 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
40,420 - Check Hood	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Jun 24, 2019 11:34:17 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Jun 24, 2019 11:34:17 PM	No	
40,442 - Freeze Point	Degree	na	RGASPARD	Jun 24, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			11:34:17 PM		
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Jun 24, 2019 11:34:17 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Jun 24, 2019 11:34:17 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Jun 24, 2019 11:34:17 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
60,615 - Air Pressure LRI	65 Pounds per		RGASPARD	Jun 24, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			11:34:17 PM		
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
60,631 - Tread Depth RF	6 32nds of an inch		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
60,632 - Tread Depth LF	7 32nds of an inch		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
60,634 - Tread Depth RRI	5 32nds of an inch		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
70,790 - Check All Body Mounts and Chassis	Done		RGASPARD	Jun 24, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Frame				11:34:17 PM		
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
77,131 - Brake Pad Thickness LF	4 Inch		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
77,132 - Brake Pad Thickness RF	4 Inch		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
77,137 - Brake Rotor LR	36 Inch		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
77,138 - Brake Rotor RR	36 Inch		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Jun 24, 2019 11:34:17 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Jun 24, 2019 11:34:17 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	102.92
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**102.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52547396
Invoice No. 55345 - 52547396

Client Department:
Department: 55345M
Work Order Description
Needs front brakes job
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 221,874 - DH

Activity Header
Activity: 15 013/000/000 BRAKES
Activity Note: Needs front brakes job
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Jun-19	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	48.87	48.87

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Jun-19	Gaspard,Ronald	1	65	65

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	48.87
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**113.87**

Work Order Footer

Work Order 52547396 Total	
Parts:	48.87
Labor:	71.50
Labor Hours:	1.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**120.37**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52458634
Invoice No. 55345 - 52458634

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	221,874 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Jun-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Jun-19	Gaspard,Ronald	1.1666666	65	75.833329

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 24-JUN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jun 24, 2019 11:38:21 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jun 24, 2019 11:38:21 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jun 24, 2019 11:38:21 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jun 24, 2019 11:38:21 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Jun 24, 2019 11:38:21 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jun 24, 2019 11:38:21 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Jun 24, 2019 11:38:21 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jun 24, 2019 11:38:21 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	75.83
	Labor Hours:	1.17
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**77.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52458634
Invoice No. 55345 - 52458634

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	221,874 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Jun-19	Gaspard,Ronald	0.2666666	65	17.333329

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 24-JUN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Jun 24, 2019 11:38:45 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Jun 24, 2019 11:38:45 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Jun 24, 2019 11:38:45 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Jun 24, 2019 11:38:45 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Jun 24, 2019 11:38:45 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jun 24, 2019 11:38:45 PM	No	
20 - Miles			RGASPARD	Jun 24, 2019 11:38:45 PM	No	
30 - Kilometers			RGASPARD	Jun 24, 2019 11:38:45 PM	No	
40 - Hours			RGASPARD	Jun 24, 2019 11:38:45 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	17.33
	Labor Hours:	0.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**17.33**

Work Order Footer

Work Order 52458634 Total	
Parts:	1.96
Labor:	196.08
Labor Hours:	3.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**198.04**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52523736
Invoice No. 55345 - 52523736

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Wheelchair Lift		Ford E350 Champion Crusaders	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	220,882 - DH

Chronology		
Reported	Jun 17, 2019 12:51:33 PM	Jun 17, 2019 12:51:33 PM
Started	Jun 17, 2019 12:00:00 AM	
Completed	Jun 20, 2019 8:21:56 AM	Jun 20, 2019 8:21:56 AM
Down Time		

Work Order Notes

Line 10 Lift outer barrier shocks.

Complaint:
Lift outter barrier shocks are bad.

Cause:
Normal wear

Correction:
Replaced the outer barrier shocks

Parts. 2 Outer barrier shocks

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
10 Desc: PERSONAL RISK ASSESMENT Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 17-JUN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Jun 17, 2019 12:55:25 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Jun 17, 2019 12:55:25 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Jun 17, 2019 12:55:25 PM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Jun 17, 2019 12:55:25 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Jun 17, 2019 12:55:25 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Jun 17, 2019 12:55:25 PM	No	
20 - Miles			RAURODRIGUEZ	Jun 17, 2019 12:55:25 PM	No	
30 - Kilometers			RAURODRIGUEZ	Jun 17, 2019 12:55:25 PM	No	
40 - Hours			RAURODRIGUEZ	Jun 17, 2019 12:55:25 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52523736
Invoice No. 55345 - 52523736

Client Department:
Department: 55345M
Work Order Description
Wheelchair Lift
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 220,882 - DH

Activity Header
Activity: 20 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: WheelChair Lift
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Jun-19	32831	SPRING, SHOCK, GAS, W/C	2	26.58	53.16

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Jun-19	Rodriguez,Raul	0.7	65	45.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	53.16
Labor:	45.50
Labor Hours:	0.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**98.66**

Work Order Footer

Work Order 52523736 Total	
Parts:	53.16
Labor:	45.50
Labor Hours:	0.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**98.66**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52493407
Invoice No. 55345 - 52493407

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Battery tray .		Ford E350 Champion Crusaders	
Requested By:	EJACKSON	**Status:**	40 - Closed (40)
Created By:	EJACKSON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	219,297 - DH

Chronology		
Reported	Jun 5, 2019 10:33:52 PM	Jun 5, 2019 10:33:52 PM
Started	Jun 5, 2019 12:00:00 AM	
Completed	Jun 5, 2019 11:39:00 PM	Jun 5, 2019 11:39:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Battery tray not secured.

Cause: Faulty Battery tray spring.

Correction: Remove and Replaced Battery tray spring.
Part# 0499252 quantity 1.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jun-19	EARL JACKSON	0.0333333	65	2.1666645

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EJACKSON Performed on: 05-JUN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EJACKSON	Jun 5, 2019 11:16:42 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EJACKSON	Jun 5, 2019 11:16:42 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EJACKSON	Jun 5, 2019 11:16:42 PM	No	
4 - Have you performed the proper LOTO?	Done		EJACKSON	Jun 5, 2019 11:16:42 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EJACKSON	Jun 5, 2019 11:16:42 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EJACKSON	Jun 5, 2019 11:16:42 PM	No	
20 - Miles			EJACKSON	Jun 5, 2019 11:16:42 PM	No	
30 - Kilometers			EJACKSON	Jun 5, 2019 11:16:42 PM	No	
40 - Hours			EJACKSON	Jun 5, 2019 11:16:42 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	2.17
Labor Hours:	0.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.17**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52493407
Invoice No. 55345 - 52493407

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Battery tray .		Ford E350 Champion Crusaders	
Requested By:	EJACKSON	**Status:**	40 - Closed (40)
Created By:	EJACKSON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	219,297 - DH

Activity Header
Activity: 15 031/005/000 CHARGER, BATTERY, ON-BOARD, VEHICLES, PROPELLED, ELECTRICALLY
Activity Note: Battery tray.
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure: 43 Weak
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Jun-19	0499252	SPRING, TRAY, BATTERY	1	2.87	2.87

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jun-19	EARL JACKSON	0.1666666	65	10.833329

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	2.87
Labor:	10.83
Labor Hours:	0.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**13.70**

Work Order Footer

Work Order 52493407 Total	
Parts:	2.87
Labor:	13.00
Labor Hours:	0.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**15.87**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52487872
Invoice No. 55345 - 52487872

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Heater Hose and Valve		Ford E350 Champion Crusaders	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	219,297 - DH

Chronology		
Reported	Jun 4, 2019 1:06:52 PM	Jun 4, 2019 1:06:52 PM
Started	Jun 4, 2019 12:00:00 AM	
Completed	Jun 4, 2019 1:51:00 PM	Jun 4, 2019 1:51:00 PM
Down Time		

Work Order Notes

Line 10 Replaced Heater Hose
Replaced rear Heater Valve

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Jun-19	Delva,Terry	0.3166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 04-JUN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jun 4, 2019 1:13:20 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jun 4, 2019 1:13:20 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Jun 4, 2019 1:13:20 PM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Jun 4, 2019 1:13:20 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jun 4, 2019 1:13:20 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jun 4, 2019 1:13:20 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			TDELVA	Jun 4, 2019 1:13:20 PM	No	
30 - Kilometers			TDELVA	Jun 4, 2019 1:13:20 PM	No	
40 - Hours			TDELVA	Jun 4, 2019 1:13:20 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52487872
Invoice No. 55345 - 52487872

Client Department:
Department: 55345M
Work Order Description
Heater Hose and Valve
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 219,297 - DH

Activity Header
Activity: 20 042/000/000 COOLING SYSTEM
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Jun-19	74612	VALVE, CONTROL, HEATER	1	9.19	9.19
04-Jun-19	BC2Z-18472-DA	TUBE, HEATER, WATER	1	56.59	56.59
04-Jun-19	BC2Z-18472-CA	TUBE, HEATER, WATER	1	59.54	59.54

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Jun-19	Delva,Terry	0.8833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	125.32
Labor:	0.00
Labor Hours:	0.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**125.32**

Work Order Footer

Work Order 52487872 Total	
Parts:	125.32
Labor:	0.00
Labor Hours:	1.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**125.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52372794
Invoice No. 55345 - 52372794

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM B		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	217,798 - DH

Chronology		
Reported	May 23, 2019 2:05:38 PM	May 23, 2019 2:05:38 PM
Started	May 23, 2019 12:00:00 AM	
Completed	May 23, 2019 11:04:00 PM	May 23, 2019 11:04:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMB SERVICE

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMA SERVICE
Replaced 1 interior light

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-May-19	AMRIT TEEMAL,VISHNU	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: VAMRITTEEMAL Performed on: 23-MAY-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
10,100 - Safety Inspection	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
10,140 - Check Service Brakes	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
10,160 - FRA Check Instruments and Horns	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
10,170 - Check Fast Idle	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
10,180 - Check Starter Protection Circuit	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
10,190 - Check Reverse Warning System	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
11,100 - Check Parking Brake	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
11,150 - Perform Brake Test	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
11,152 - Decelerometer Results Test 1	FEET	n/a	VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
11,154 - Decelerometer Results Test 2	FEET	n/a	VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
11,156 - Decelerometer Results Test 3	FEET	n/a	VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
11,170 - FRA Check Door Operation	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
20,210 - Check Condition of Operator's Area	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
20,240 - FRA Check Interior Lights	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	n/a	VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
22,110 - Check Emergency Hatches	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
22,120 - Check All Safety Equipment	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
30,310 - Check Passenger Doors	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
30,360 - Check for Physical Damage and Decals	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
30,380 - Check Exterior Compartment Doors	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
33,100 - Check Lights and Reflectors	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
40,420 - Check Hood	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
44,130 - FRA Check Exhaust System	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
44,140 - FRA Check Intake System	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
44,180 - FRA Check for Leaks	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
44,190 - FRA Perform Battery Inspection	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
50,510 - Check Entire Steering System	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	70 Pounds per Square Inch		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
60,620 - Check Valve Stems and Caps	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
60,630 - Check and Record Tread Depth	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
60,633 - Tread Depth RRO	10 32nds of an inch		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
60,635 - Tread Depth LRI	10 32nds of an inch		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
60,636 - Tread Depth LRO	10 32nds of an inch		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
60,650 - Check Sidewall Wear	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
60,660 - Inspect for Cuts and Tears	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
70,710 - Check Vibration Damper	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
70,730 - FRA Check Starter	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
70,770 - FRA Check Exhaust System	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
77,110 - FRA Check Fuel Tank	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
77,120 - Check Suspension Components	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
77,135 - Brake Rotor LF	39.79 Inch		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
77,136 - Brake Rotor RF	39.77 Inch		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
77,137 - Brake Rotor LR	35.91 Inch		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
77,138 - Brake Rotor RR	35.93 Inch		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
77,140 - FRA Check Brake Hoses	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
77,150 - Check King Pins	-	n/a	VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
80,810 - Completion of PMI Report	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		VAMRITTEEMAL	May 23, 2019 10:37:01 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52372794
Invoice No. 55345 - 52372794

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 217,798 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-May-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-May-19	AMRIT TEEMAL,VISHNU	1	65	65

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: VAMRITTEEMAL Performed on: 23-MAY-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		VAMRITTEEMAL	May 23, 2019 10:38:35 PM	No	
101,000 - FRA Change Oil Filters	Yes		VAMRITTEEMAL	May 23, 2019 10:38:35 PM	No	
102,000 - FRA Drain Engine Oil	Yes		VAMRITTEEMAL	May 23, 2019 10:38:35 PM	No	
103,000 - FRA Check Transmission Fluid	Done		VAMRITTEEMAL	May 23, 2019 10:38:35 PM	No	
104,000 - Lubricate Chassis	Done		VAMRITTEEMAL	May 23, 2019 10:38:35 PM	No	
105,000 - Replace or Clean A/C Filters	Done		VAMRITTEEMAL	May 23, 2019 10:38:35 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	VAMRITTEEMAL	May 23, 2019 10:38:35 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		VAMRITTEEMAL	May 23, 2019 10:38:35 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		VAMRITTEEMAL	May 23, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				10:38:35 PM		
201,000 - Service Crankcase Breather	-	n/a	VAMRITTEEMAL	May 23, 2019 10:38:35 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No	n/a	VAMRITTEEMAL	May 23, 2019 10:38:35 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No	n/a	VAMRITTEEMAL	May 23, 2019 10:38:35 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		VAMRITTEEMAL	May 23, 2019 10:38:35 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**66.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52372794
Invoice No. 55345 - 52372794

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM B		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	217,798 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-May-19	AMRIT TEEMAL,VISHNU	0.2666666	65	17.333329

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 23-MAY-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	May 23, 2019 10:39:00 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	May 23, 2019 10:39:00 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	May 23, 2019 10:39:00 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	May 23, 2019 10:39:00 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	May 23, 2019 10:39:00 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	May 23, 2019 10:39:00 PM	No	
20 - Miles			VAMRITTEEMAL	May 23, 2019 10:39:00 PM	No	
30 - Kilometers			VAMRITTEEMAL	May 23, 2019 10:39:00 PM	No	
40 - Hours			VAMRITTEEMAL	May 23, 2019 10:39:00 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	17.33
	Labor Hours:	0.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**17.33**

Work Order Footer

Work Order 52372794 Total	
Parts:	1.96
Labor:	179.83
Labor Hours:	2.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**181.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52288107
Invoice No. 55345 - 52288107

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	213,402 - DH

Chronology		
Reported	Apr 24, 2019 5:57:17 PM	Apr 24, 2019 5:57:17 PM
Started	Apr 24, 2019 12:00:00 AM	
Completed	Apr 25, 2019 12:36:00 AM	Apr 25, 2019 12:36:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PMA Service

CAUSE: Service due by Mileage.

CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check brakes . Clean batteries.
Parts# B329 Qty (1)
Oil 5W20 Qty (6.5) Qt

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Apr-19	Arthurs,Durvin	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 24-APR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Apr 24, 2019 11:40:51 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Apr 24, 2019 11:40:51 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Apr 24, 2019 11:40:51 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Apr 24, 2019 11:40:51 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Apr 24, 2019 11:40:51 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	Apr 24, 2019 11:40:51 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Apr 24, 2019 11:40:51 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Apr 24, 2019 11:40:51 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
40,420 - Check Hood	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Apr 24, 2019 11:40:51 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Apr 24, 2019 11:40:51 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Apr 24, 2019 11:40:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Apr 24, 2019 11:40:51 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Apr 24, 2019 11:40:51 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Apr 24, 2019 11:40:51 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Apr 24, 2019 11:40:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
60,631 - Tread Depth RF	12 32nds of an inch		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
60,634 - Tread Depth RRI	9 32nds of an inch		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
60,635 - Tread Depth LRI	10 32nds of an inch		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
60,636 - Tread Depth LRO	10 32nds of an inch		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Apr 24, 2019 11:40:51 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
77,131 - Brake Pad Thickness LF	6 Inch		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
77,132 - Brake Pad Thickness RF	6 Inch		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
77,133 - Brake Pad Thickness LR	3 Inch		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
77,134 - Brake Pad Thickness RR	3 Inch		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
77,135 - Brake Rotor LF	1.554 Inch		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
77,136 - Brake Rotor RF	1.555 Inch		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
77,137 - Brake Rotor LR	1.414 Inch		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
77,138 - Brake Rotor RR	1.413 Inch		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Apr 24, 2019 11:40:51 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Apr 24, 2019 11:40:51 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52288107
Invoice No. 55345 - 52288107

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	213,402 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Apr-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Apr-19	Arthurs,Durvin	0.4166666	65	27.083329

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 24-APR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Apr 24, 2019 11:47:06 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Apr 24, 2019 11:47:06 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Apr 24, 2019 11:47:06 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Apr 24, 2019 11:47:06 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Apr 24, 2019 11:47:06 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Apr 24, 2019 11:47:06 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Apr 24, 2019 11:47:06 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Apr 24, 2019 11:47:06 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	27.08
	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**29.04**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52288107
Invoice No. 55345 - 52288107

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	213,402 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Apr-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 24-APR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Apr 24, 2019 11:48:15 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Apr 24, 2019 11:48:15 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Apr 24, 2019 11:48:15 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Apr 24, 2019 11:48:15 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Apr 24, 2019 11:48:15 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 24, 2019 11:48:15 PM	No	
20 - Miles			DARTHURS	Apr 24, 2019 11:48:15 PM	No	
30 - Kilometers			DARTHURS	Apr 24, 2019 11:48:15 PM	No	
40 - Hours			DARTHURS	Apr 24, 2019 11:48:15 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	5.42
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**5.42**

Work Order Footer

Work Order 52288107 Total	
Parts:	1.96
Labor:	130.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**131.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52372725
Invoice No. 55345 - 52372725

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Rear Brakes		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	213,402 - DH

Chronology		
Reported	Apr 24, 2019 11:53:14 PM	Apr 24, 2019 11:53:14 PM
Started	Apr 24, 2019 12:00:00 AM	
Completed	Apr 25, 2019 12:33:00 AM	Apr 25, 2019 12:33:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear Brakes

Cause: Rear Brakes Low.

Correction: Remove & Replace Rear Brakes./ Clean & Lube slide pins.
Parts# 9C2Z-2V200-B Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Apr-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 24-APR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Apr 24, 2019 11:54:39 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Apr 24, 2019 11:54:39 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Apr 24, 2019 11:54:39 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Apr 24, 2019 11:54:39 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Apr 24, 2019 11:54:39 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 24, 2019 11:54:39 PM	No	
20 - Miles			DARTHURS	Apr 24, 2019 11:54:39 PM	No	
30 - Kilometers			DARTHURS	Apr 24, 2019 11:54:39 PM	No	
40 - Hours			DARTHURS	Apr 24, 2019 11:54:39 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	5.42
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.42**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52372725
Invoice No. 55345 - 52372725

Client Department:
Department: 55345M
Work Order Description
Rear Brakes
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 213,402 - DH

Activity Header
Activity: 15 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Apr-19	9C2Z-2V200-B	PADS, BRAKE, DISC, REAR SAME AS BRSD1329B	1	46.22	46.22

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Apr-19	Arthurs,Durvin	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	46.22
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**143.72**

Work Order Footer

Work Order 52372725 Total	
Parts:	46.22
Labor:	102.92
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**149.14**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52346282
Invoice No. 55345 - 52346282

Client Department:
Department: 55345M
Work Order Description
Needs rear AC thermostat controller
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 212,095 - DH

Chronology		
Reported	Apr 16, 2019 12:31:33 AM	Apr 16, 2019 12:31:33 AM
Started	Apr 16, 2019 12:00:00 AM	
Completed	Apr 16, 2019 8:14:45 AM	Apr 16, 2019 8:14:45 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:driver complaint controller working on high only

Cause: Bad

Correction:Check and replaced thermostat controller
Part number 04257712A qty 1

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Apr-19	04257712A	DISPLAY, DASH, LED, A/C, G4500	1	260.92	260.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Apr-19	Gaspard,Ronald	0.1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 16-APR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Apr 16, 2019 12:33:03 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Apr 16, 2019 12:33:03 AM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Apr 16, 2019 12:33:03 AM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Apr 16, 2019 12:33:03 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Apr 16, 2019 12:33:03 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Apr 16, 2019 12:33:03 AM	No	
20 - Miles			RGASPARD	Apr 16, 2019 12:33:03 AM	No	
30 - Kilometers			RGASPARD	Apr 16, 2019 12:33:03 AM	No	
40 - Hours			RGASPARD	Apr 16, 2019 12:33:03 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	260.92
Labor:	0.00
Labor Hours:	0.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**260.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52346282
Invoice No. 55345 - 52346282

Client Department:
Department: 55345M
Work Order Description
Needs rear AC thermostat controller
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 212,095 - DH

Activity Header
Activity: 15 000 CAB, CLIMATE CONTROL, INSTRUMENTS & AERODYNAMIC DEVICES
Activity Note: Rear AC thermostat controller
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Apr-19	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 52346282 Total	
Parts:	260.92
Labor:	0.00
Labor Hours:	1.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**260.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52320006
Invoice No. 55345 - 52320006

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Replaced rear a/c vent		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	210,800 - DH

Chronology

Reported	Apr 5, 2019 10:27:50 PM	Apr 5, 2019 10:27:50 PM
Started	Apr 5, 2019 12:00:00 AM	
Completed	Apr 8, 2019 11:21:00 PM	Apr 8, 2019 11:21:00 PM
Down Time		

Work Order Notes

Line 10 Replaced one rear a/c vent

Activity Header
Activity: 10 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 51 Inoperative
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Apr-19	14565100C	COVER, LOUVER, EVAPORATOR, A/C	1	15.38	15.38

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Apr-19	AMRIT TEEMAL,VISHNU	0.1666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	15.38
Labor:	0.00
Labor Hours:	0.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**15.38**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52320006
Invoice No. 55345 - 52320006

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Replaced rear a/c vent		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	210,800 - DH

Activity Header
Activity:20 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Apr-19	AMRIT TEEMAL,VISHNU	0.2666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 05-APR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Apr 5, 2019 10:33:43 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Apr 5, 2019 10:33:43 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Apr 5, 2019 10:33:43 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Apr 5, 2019 10:33:43 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Apr 5, 2019 10:33:43 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Apr 5, 2019 10:33:43 PM	No	
20 - Miles			VAMRITTEEMAL	Apr 5, 2019 10:33:43 PM	No	
30 - Kilometers			VAMRITTEEMAL	Apr 5, 2019 10:33:43 PM	No	
40 - Hours			VAMRITTEEMAL	Apr 5, 2019 10:33:43 PM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 52320006 Total	
Parts:	15.38
Labor:	0.00
Labor Hours:	0.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**15.38**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52306992
Invoice No. 55345 - 52306992

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Engine belt damaged		Ford E350 Champion Crusaders	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	210,235 - DH

Chronology		
Reported	Apr 2, 2019 1:43:21 PM	Apr 2, 2019 1:43:21 PM
Started	Apr 2, 2019 12:00:00 AM	
Completed	Apr 3, 2019 10:15:52 AM	Apr 3, 2019 10:15:52 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:engine belt is damaged

Cause: serpentine belt is broken

Correction:replaced belt retest system ok at this time

Part:
1 new belt1360k6

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 02-APR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Apr 2, 2019 1:50:21 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Apr 2, 2019 1:50:21 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Apr 2, 2019 1:50:21 PM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Apr 2, 2019 1:50:21 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Apr 2, 2019 1:50:21 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Apr 2, 2019 1:50:21 PM	No	
20 - Miles			JAPEREZ	Apr 2, 2019 1:50:21 PM	No	
30 - Kilometers			JAPEREZ	Apr 2, 2019 1:50:21 PM	No	
40 - Hours			JAPEREZ	Apr 2, 2019 1:50:21 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52306992
Invoice No. 55345 - 52306992

Client Department:
Department: 55345M
Work Order Description
Engine belt damaged
Requested By: JAPEREZ
Created By: JAPEREZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 210,235 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note: Engine belt damaged
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Apr-19	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	21.31	21.31

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Apr-19	Perez,Javier	1.25	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	21.31
Labor:	0.00
Labor Hours:	1.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**21.31**

Work Order Footer

Work Order 52306992 Total	
Parts:	21.31
Labor:	0.00
Labor Hours:	1.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**21.31**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52205209
Invoice No. 55345 - 52205209

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	209,073 - DH

Chronology		
Reported	Mar 26, 2019 9:48:46 AM	Mar 26, 2019 9:48:46 AM
Started	Mar 26, 2019 12:00:00 AM	
Completed	Mar 26, 2019 11:07:00 PM	Mar 26, 2019 11:07:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA SERVICE

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Mar-19	AMRIT TEEMAL,VISHNU	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: VAMRITTEEMAL Performed on: 26-MAR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
10,100 - Safety Inspection	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,140 - Check Service Brakes	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
10,160 - FRA Check Instruments and Horns	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
10,170 - Check Fast Idle	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
10,180 - Check Starter Protection Circuit	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
10,190 - Check Reverse Warning System	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
11,100 - Check Parking Brake	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
11,150 - Perform Brake Test	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
11,152 - Decelerometer Results Test 1	FEET	n/a	VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
11,154 - Decelerometer Results Test 2	FEET	n/a	VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
11,156 - Decelerometer Results Test 3	FEET	n/a	VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
11,170 - FRA Check Door Operation	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
20,210 - Check Condition of Operator's Area	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
20,240 - FRA Check Interior Lights	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
20,260 - Check Stop Request System	-	n/a	VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
22,110 - Check Emergency Hatches	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
22,120 - Check All Safety Equipment	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
30,310 - Check Passenger Doors	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
30,360 - Check for Physical Damage and Decals	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
30,380 - Check Exterior Compartment Doors	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
33,100 - Check Lights and Reflectors	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
40,420 - Check Hood	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
44,130 - FRA Check Exhaust System	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
44,140 - FRA Check Intake System	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
44,180 - FRA Check for Leaks	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
44,190 - FRA Perform Battery Inspection	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
50,510 - Check Entire Steering System	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
60,630 - Check and Record Tread Depth	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
60,631 - Tread Depth RF	4 32nds of an inch		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
60,632 - Tread Depth LF	4 32nds of an inch		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
60,633 - Tread Depth RRO	12 32nds of an inch		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
60,636 - Tread Depth LRO	12 32nds of an inch		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
60,650 - Check Sidewall Wear	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
60,660 - Inspect for Cuts and Tears	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
70,710 - Check Vibration Damper	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
70,730 - FRA Check Starter	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
70,770 - FRA Check Exhaust System	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
77,120 - Check Suspension Components	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
77,135 - Brake Rotor LF	39.47 Inch		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
77,136 - Brake Rotor RF	39.48 Inch		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
77,137 - Brake Rotor LR	35.63 Inch		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
77,138 - Brake Rotor RR	35.63 Inch		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
77,140 - FRA Check Brake Hoses	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
77,150 - Check King Pins	-	n/a	VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
80,810 - Completion of PMI Report	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:06 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52205209
Invoice No. 55345 - 52205209

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	209,073 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Mar-19	B329	FILTER, OIL, SPIN-ON SEE P550965	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Mar-19	AMRIT TEEMAL,VISHNU	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: VAMRITTEEMAL Performed on: 26-MAR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:40 PM	No	
101,000 - FRA Change Oil Filters	Yes		VAMRITTEEMAL	Mar 26, 2019 10:19:40 PM	No	
102,000 - FRA Drain Engine Oil	Yes		VAMRITTEEMAL	Mar 26, 2019 10:19:40 PM	No	
103,000 - FRA Check Transmission Fluid	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:40 PM	No	
104,000 - Lubricate Chassis	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:40 PM	No	
105,000 - Replace or Clean A/C Filters	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:40 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	VAMRITTEEMAL	Mar 26, 2019 10:19:40 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		VAMRITTEEMAL	Mar 26, 2019 10:19:40 PM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	1.96
	Labor:	0.00
	Labor Hours:	1.50
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52205209
Invoice No. 55345 - 52205209

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	209,073 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Mar-19	AMRIT TEEMAL,VISHNU	0.2666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 26-MAR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Mar 26, 2019 10:20:02 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Mar 26, 2019 10:20:02 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Mar 26, 2019 10:20:02 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Mar 26, 2019 10:20:02 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Mar 26, 2019 10:20:02 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Mar 26, 2019 10:20:02 PM	No	
20 - Miles			VAMRITTEEMAL	Mar 26, 2019 10:20:02 PM	No	
30 - Kilometers			VAMRITTEEMAL	Mar 26, 2019 10:20:02 PM	No	
40 - Hours			VAMRITTEEMAL	Mar 26, 2019 10:20:02 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 52205209 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52288060
Invoice No. 55345 - 52288060

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Replaced front tires		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	209,073 - DH

Chronology

Reported	Mar 26, 2019 10:25:27 PM	Mar 26, 2019 10:25:27 PM
Started	Mar 26, 2019 12:00:00 AM	
Completed	Mar 26, 2019 11:06:00 PM	Mar 26, 2019 11:06:00 PM
Down Time		

Work Order Notes

Line 10 Mount and balanced 2 front tires
Torqued to 140ftlb test driven and retorqued to 140ftlb

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Mar-19	AMRIT TEEMAL,VISHNU	0.2666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 26-MAR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Mar 26, 2019 10:27:57 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Mar 26, 2019 10:27:57 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Mar 26, 2019 10:27:57 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Mar 26, 2019 10:27:57 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Mar 26, 2019 10:27:57 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Mar 26, 2019 10:27:57 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			VAMRITTEEMAL	Mar 26, 2019 10:27:57 PM	No	
30 - Kilometers			VAMRITTEEMAL	Mar 26, 2019 10:27:57 PM	No	
40 - Hours			VAMRITTEEMAL	Mar 26, 2019 10:27:57 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52288060
Invoice No. 55345 - 52288060

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Replaced front tires		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	209,073 - DH

Activity Header
Activity: 20 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Mar-19	002760	TIRE, 225/75R16, 10-PLY, BSW, HT2, TRANSFORCE, FIRESTONE	2	108.36	216.72

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Mar-19	AMRIT TEEMAL,VISHNU	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	216.72
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**216.72**

Work Order Footer

Work Order 52288060 Total	
Parts:	216.72
Labor:	0.00
Labor Hours:	1.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**216.72**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52123623
Invoice No. 55345 - 52123623

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 204,772 - DH

Chronology		
Reported	Feb 26, 2019 10:45:38 AM	Feb 26, 2019 10:45:38 AM
Started	Feb 26, 2019 12:00:00 AM	
Completed	Feb 26, 2019 10:17:00 PM	Feb 26, 2019 10:17:00 PM
Down Time		

Work Order Notes

Line 10 PMC service
Preventive maintenance
Performed and completed PMC service
Replaced air filter

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Feb-19	AMRIT TEEMAL,VISHNU	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: VAMRITTEEMAL Performed on: 26-FEB-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
10,100 - Safety Inspection	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,140 - Check Service Brakes	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
10,160 - FRA Check Instruments and Horns	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
10,170 - Check Fast Idle	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
10,180 - Check Starter Protection Circuit	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
10,190 - Check Reverse Warning System	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
11,100 - Check Parking Brake	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
11,150 - Perform Brake Test	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
11,152 - Decelerometer Results Test 1	FEET	n/a	VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
11,154 - Decelerometer Results Test 2	FEET	n/a	VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
11,156 - Decelerometer Results Test 3	FEET	n/a	VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
11,170 - FRA Check Door Operation	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
20,210 - Check Condition of Operator's Area	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
20,240 - FRA Check Interior Lights	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
20,260 - Check Stop Request System	-	n/a	VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
22,110 - Check Emergency Hatches	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
22,120 - Check All Safety Equipment	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
30,310 - Check Passenger Doors	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
30,360 - Check for Physical Damage and Decals	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
30,380 - Check Exterior Compartment Doors	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
33,100 - Check Lights and Reflectors	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
40,420 - Check Hood	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
40,461 - Refractometer Reading	0 Degree Fahrenheit	n/a	VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
44,130 - FRA Check Exhaust System	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
44,140 - FRA Check Intake System	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
44,180 - FRA Check for Leaks	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
44,190 - FRA Perform Battery Inspection	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
50,510 - Check Entire Steering System	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
60,630 - Check and Record Tread Depth	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
60,631 - Tread Depth RF	12 32nds of an inch		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
60,650 - Check Sidewall Wear	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
60,660 - Inspect for Cuts and Tears	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
70,710 - Check Vibration Damper	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
70,730 - FRA Check Starter	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
70,770 - FRA Check Exhaust System	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
77,120 - Check Suspension Components	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
77,135 - Brake Rotor LF	39.84 Inch		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
77,136 - Brake Rotor RF	39.82 Inch		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
77,137 - Brake Rotor LR	35.9 Inch		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
77,138 - Brake Rotor RR	35.89 Inch		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
77,140 - FRA Check Brake Hoses	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
77,150 - Check King Pins	-	n/a	VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
80,810 - Completion of PMI Report	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		VAMRITTEEMAL	Feb 26, 2019 9:52:14 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52123623
Invoice No. 55345 - 52123623

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 204,772 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Feb-19	20021	FILTER, TRANSMISSION 20021	1	17.27	17.27
26-Feb-19	PA4075	FILTER, AIR SEE P546597	1	5.28	5.28
26-Feb-19	B329	FILTER, OIL, SPIN-ON SEE P550965	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Feb-19	AMRIT TEEMAL,VISHNU	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: VAMRITTEEMAL Performed on: 26-FEB-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		VAMRITTEEMAL	Feb 26, 2019 9:53:22 PM	No	
101,000 - FRA Change Oil Filters	Yes		VAMRITTEEMAL	Feb 26, 2019 9:53:22 PM	No	
102,000 - FRA Drain Engine Oil	Yes		VAMRITTEEMAL	Feb 26, 2019 9:53:22 PM	No	
103,000 - FRA Check Transmission Fluid	Done		VAMRITTEEMAL	Feb 26, 2019 9:53:22 PM	No	
104,000 - Lubricate Chassis	Done		VAMRITTEEMAL	Feb 26, 2019 9:53:22 PM	No	
105,000 - Replace or Clean A/C Filters	Done		VAMRITTEEMAL	Feb 26, 2019 9:53:22 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	n/a	VAMRITTEEMAL	Feb 26, 2019 9:53:22 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		VAMRITTEEMAL	Feb 26, 2019 9:53:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		VAMRITTEEMAL	Feb 26, 2019 9:53:22 PM	No	
201,000 - Service Crankcase Breather	Done		VAMRITTEEMAL	Feb 26, 2019 9:53:22 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		VAMRITTEEMAL	Feb 26, 2019 9:53:22 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No	n/a	VAMRITTEEMAL	Feb 26, 2019 9:53:22 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		VAMRITTEEMAL	Feb 26, 2019 9:53:22 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		VAMRITTEEMAL	Feb 26, 2019 9:53:22 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		VAMRITTEEMAL	Feb 26, 2019 9:53:22 PM	No	
302,000 - Check Toe-In and Record Reading	-	n/a	VAMRITTEEMAL	Feb 26, 2019 9:53:22 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	n/a	VAMRITTEEMAL	Feb 26, 2019 9:53:22 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No	n/a	VAMRITTEEMAL	Feb 26, 2019 9:53:22 PM	No	
305,000 - FRA Change Differential Fluid	Yes		VAMRITTEEMAL	Feb 26, 2019 9:53:22 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	24.51
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**24.51**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52123623
Invoice No. 55345 - 52123623

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 204,772 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Feb-19	AMRIT TEEMAL,VISHNU	0.2666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 26-FEB-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Feb 26, 2019 9:38:00 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Feb 26, 2019 9:38:00 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Feb 26, 2019 9:38:00 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Feb 26, 2019 9:38:00 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Feb 26, 2019 9:38:00 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Feb 26, 2019 9:38:00 PM	No	
20 - Miles			VAMRITTEEMAL	Feb 26, 2019 9:38:00 PM	No	
30 - Kilometers			VAMRITTEEMAL	Feb 26, 2019 9:38:00 PM	No	
40 - Hours			VAMRITTEEMAL	Feb 26, 2019 9:38:00 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 52123623 Total	
Parts:	24.51
Labor:	0.00
Labor Hours:	4.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**24.51**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52041017
Invoice No. 55345 - 52041017

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	200,626 - DH

Chronology		
Reported	Jan 29, 2019 1:19:21 PM	Jan 29, 2019 1:19:21 PM
Started	Jan 29, 2019 12:00:00 AM	
Completed	Jan 29, 2019 11:22:00 PM	Jan 29, 2019 11:22:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA Service

CAUSE: Service Due by Mileage.

CORRECTION: Change Oil & Filter. Lube all Pivoting Points .Check Brakes. Clean batteries. Replace. A/C filter. Replace .Oil drain plugs.
Parts# B329 Qty (1)
Parts# 65266 Qty (1)
Oil 5W20QTY (6.5) Qt

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Jan-19	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 29-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Jan 29, 2019 10:21:18 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Jan 29, 2019 10:21:18 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Jan 29, 2019 10:21:18 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Jan 29, 2019 10:21:18 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Jan 29, 2019 10:21:18 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
20,260 - Check Stop Request System	-	NA	DARTHURS	Jan 29, 2019 10:21:18 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Jan 29, 2019 10:21:18 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Jan 29, 2019 10:21:18 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
40,420 - Check Hood	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Jan 29, 2019 10:21:18 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Jan 29, 2019 10:21:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Jan 29, 2019 10:21:18 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Jan 29, 2019 10:21:18 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Jan 29, 2019 10:21:18 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Jan 29, 2019 10:21:18 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Jan 29, 2019 10:21:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
60,634 - Tread Depth RRI	3 32nds of an inch		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
60,635 - Tread Depth LRI	3 32nds of an inch		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
60,636 - Tread Depth LRO	3 32nds of an inch		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Jan 29, 2019 10:21:18 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
77,131 - Brake Pad Thickness LF	12 Inch		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
77,132 - Brake Pad Thickness RF	12 Inch		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
77,133 - Brake Pad Thickness LR	4 Inch		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
77,134 - Brake Pad Thickness RR	4 Inch		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
77,135 - Brake Rotor LF	1.557 Inch		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
77,136 - Brake Rotor RF	1.556 Inch		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
77,137 - Brake Rotor LR	1.415 Inch		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
77,138 - Brake Rotor RR	1.416 Inch		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Jan 29, 2019 10:21:18 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Jan 29, 2019 10:21:18 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52041017
Invoice No. 55345 - 52041017

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 200,626 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Jan-19	65266	PLUG, DRAIN, OIL, ENGINE	1	5.79	5.79
29-Jan-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Jan-19	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 29-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Jan 29, 2019 10:22:30 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Jan 29, 2019 10:22:30 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Jan 29, 2019 10:22:30 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Jan 29, 2019 10:22:30 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Jan 29, 2019 10:22:30 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Jan 29, 2019 10:22:30 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Jan 29, 2019 10:22:30 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Jan 29, 2019 10:22:30 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	7.75
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52041017
Invoice No. 55345 - 52041017

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	200,626 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Jan-19	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 29-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jan 29, 2019 10:23:13 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jan 29, 2019 10:23:13 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jan 29, 2019 10:23:13 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jan 29, 2019 10:23:13 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jan 29, 2019 10:23:13 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jan 29, 2019 10:23:13 PM	No	
20 - Miles			DARTHURS	Jan 29, 2019 10:23:13 PM	No	
30 - Kilometers			DARTHURS	Jan 29, 2019 10:23:13 PM	No	
40 - Hours			DARTHURS	Jan 29, 2019 10:23:13 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 52041017 Total	
Parts:	7.75
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52123572
Invoice No. 55345 - 52123572

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Rear Brakes/ Rear tires		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	200,626 - DH

Chronology		
Reported	Jan 29, 2019 10:39:13 PM	Jan 29, 2019 10:39:13 PM
Started	Jan 29, 2019 12:00:00 AM	
Completed	Jan 29, 2019 11:21:00 PM	Jan 29, 2019 11:21:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear Brakes / Rear Tires

Cause: Rear Brakes / uneven wear Low& Rear Tires Low spec

Correction: Mount& Balance Tire Replace on rear/ Remove& Replace Rear Brakes.
Parts# 002760 Qty (4)
Parts #9C2Z-2V200-B Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Jan-19	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 29-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jan 29, 2019 10:41:07 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jan 29, 2019 10:41:07 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jan 29, 2019 10:41:07 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jan 29, 2019 10:41:07 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jan 29, 2019 10:41:07 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jan 29, 2019 10:41:07 PM	No	
20 - Miles			DARTHURS	Jan 29, 2019 10:41:07 PM	No	
30 - Kilometers			DARTHURS	Jan 29, 2019 10:41:07 PM	No	
40 - Hours			DARTHURS	Jan 29, 2019 10:41:07 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52123572
Invoice No. 55345 - 52123572

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Rear Brakes/ Rear tires		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	200,626 - DH

Activity Header
Activity: 15 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Jan-19	9C2Z-2V200-B	PADS, BRAKE, DISC, REAR SAME AS BRSD1329B	1	46.22	46.22

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Jan-19	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	46.22
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**46.22**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52123572
Invoice No. 55345 - 52123572

Client Department:
Department: 55345M
Work Order Description
Rear Brakes/ Rear tires
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 200,626 - DH

Activity Header
Activity:25 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Jan-19	002760	TIRE, 225/75R16, 10-PLY, BSW, HT2, TRANSFORCE, FIRESTONE	4	108.36	433.44

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Jan-19	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	433.44
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**433.44**

Work Order Footer

Work Order 52123572 Total	
Parts:	479.66
Labor:	0.00
Labor Hours:	3.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**479.66**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52040662
Invoice No. 55345 - 52040662

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Shifter Cable		Ford E350 Champion Crusaders	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	196,524 - DH

Chronology		
Reported	Jan 3, 2019 9:00:04 AM	Jan 3, 2019 9:00:04 AM
Started	Jan 3, 2019 12:00:00 AM	
Completed	Jan 3, 2019 10:09:32 AM	Jan 3, 2019 10:09:32 AM
Down Time		

Work Order Notes

Line 10 Replaced shifter cable

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jan-19	Delva,Terry	0.4666666	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 03-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jan 3, 2019 9:02:38 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jan 3, 2019 9:02:38 AM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Jan 3, 2019 9:02:38 AM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Jan 3, 2019 9:02:38 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jan 3, 2019 9:02:38 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jan 3, 2019 9:02:38 AM	No	
20 - Miles			TDELVA	Jan 3, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:02:38 AM		
30 - Kilometers			TDELVA	Jan 3, 2019 9:02:38 AM	No	
40 - Hours			TDELVA	Jan 3, 2019 9:02:38 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52040662
Invoice No. 55345 - 52040662

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Shifter Cable		Ford E350 Champion Crusaders	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	196,524 - DH

Activity Header
Activity: 20 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Jan-19	8C2Z-7E395-A	CABLE, SELECTOR, SHIFT	1	43.68	43.68

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jan-19	Delva,Terry	1.2666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	43.68
Labor:	0.00
Labor Hours:	1.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.68**

Work Order Footer

Work Order 52040662 Total	
Parts:	43.68
Labor:	0.00
Labor Hours:	1.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.68**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51953399
Invoice No. 55345 - 51953399

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	196,524 - DH

Chronology		
Reported	Jan 2, 2019 4:27:02 PM	Jan 2, 2019 4:27:02 PM
Started	Jan 3, 2019 12:00:00 AM	
Completed	Jan 3, 2019 10:08:00 AM	Jan 3, 2019 10:08:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PM A

CAUSE: Service due

CORRECTION: Performed and completed pmA
Changed engine oil and replaced engine oil filter

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jan-19	Delva,Terry	1.5666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: TDELVA Performed on: 03-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
10,100 - Safety Inspection	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
10,140 - Check Service Brakes	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
10,160 - FRA Check Instruments and Horns	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
10,170 - Check Fast Idle	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
10,180 - Check Starter Protection Circuit	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
10,190 - Check Reverse Warning System	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
11,100 - Check Parking Brake	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
11,150 - Perform Brake Test	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	TDELVA	Jan 3, 2019 8:59:00 AM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	TDELVA	Jan 3, 2019 8:59:00 AM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	TDELVA	Jan 3, 2019 8:59:00 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	TDELVA	Jan 3, 2019 8:59:00 AM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	TDELVA	Jan 3, 2019 8:59:00 AM	No	
11,170 - FRA Check Door Operation	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
20,210 - Check Condition of Operator's Area	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
20,240 - FRA Check Interior Lights	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	TDELVA	Jan 3, 2019 8:59:00 AM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	TDELVA	Jan 3, 2019 8:59:00 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
22,110 - Check Emergency Hatches	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
22,120 - Check All Safety Equipment	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
30,310 - Check Passenger Doors	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	TDELVA	Jan 3, 2019 8:59:00 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
30,360 - Check for Physical Damage and Decals	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
30,380 - Check Exterior Compartment Doors	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
33,100 - Check Lights and Reflectors	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
40,420 - Check Hood	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	TDELVA	Jan 3, 2019 8:59:00 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	TDELVA	Jan 3, 2019 8:59:00 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	TDELVA	Jan 3, 2019 8:59:00 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	TDELVA	Jan 3, 2019 8:59:00 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	TDELVA	Jan 3, 2019 8:59:00 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done	NA	TDELVA	Jan 3, 2019 8:59:00 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
44,130 - FRA Check Exhaust System	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
44,140 - FRA Check Intake System	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
44,150 - FRA Inspect Turbocharger	-	NA	TDELVA	Jan 3, 2019 8:59:00 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
44,180 - FRA Check for Leaks	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
44,190 - FRA Perform Battery Inspection	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
50,510 - Check Entire Steering System	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		TDELVA	Jan 3, 2019 8:59:00 AM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		TDELVA	Jan 3, 2019 8:59:00 AM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		TDELVA	Jan 3, 2019 8:59:00 AM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		TDELVA	Jan 3, 2019 8:59:00 AM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		TDELVA	Jan 3, 2019 8:59:00 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		TDELVA	Jan 3, 2019 8:59:00 AM	No	
60,620 - Check Valve Stems and Caps	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
60,630 - Check and Record Tread Depth	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
60,631 - Tread Depth RF	10 32nds of an inch		TDELVA	Jan 3, 2019 8:59:00 AM	No	
60,632 - Tread Depth LF	10 32nds of an inch		TDELVA	Jan 3, 2019 8:59:00 AM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		TDELVA	Jan 3, 2019 8:59:00 AM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		TDELVA	Jan 3, 2019 8:59:00 AM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		TDELVA	Jan 3, 2019 8:59:00 AM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		TDELVA	Jan 3, 2019 8:59:00 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
60,650 - Check Sidewall Wear	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
60,660 - Inspect for Cuts and Tears	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
60,670 - Check Dual Mating With Square	-	NA	TDELVA	Jan 3, 2019 8:59:00 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
70,710 - Check Vibration Damper	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
70,730 - FRA Check Starter	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
70,770 - FRA Check Exhaust System	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
77,110 - FRA Check Fuel Tank	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
77,120 - Check Suspension Components	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
77,131 - Brake Pad Thickness LF	8 Inch		TDELVA	Jan 3, 2019 8:59:00 AM	No	
77,132 - Brake Pad Thickness RF	8 Inch		TDELVA	Jan 3, 2019 8:59:00 AM	No	
77,133 - Brake Pad Thickness LR	6 Inch		TDELVA	Jan 3, 2019 8:59:00 AM	No	
77,134 - Brake Pad Thickness RR	6 Inch		TDELVA	Jan 3, 2019 8:59:00 AM	No	
77,135 - Brake Rotor LF	39.6 Inch		TDELVA	Jan 3, 2019 8:59:00 AM	No	
77,136 - Brake Rotor RF	39.7 Inch		TDELVA	Jan 3, 2019 8:59:00 AM	No	
77,137 - Brake Rotor LR	38.6 Inch		TDELVA	Jan 3, 2019 8:59:00 AM	No	
77,138 - Brake Rotor RR	38.6 Inch		TDELVA	Jan 3, 2019 8:59:00 AM	No	
77,140 - FRA Check Brake Hoses	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
77,150 - Check King Pins	-	NA	TDELVA	Jan 3, 2019 8:59:00 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
80,810 - Completion of PMI Report	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		TDELVA	Jan 3, 2019 8:59:00 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51953399
Invoice No. 55345 - 51953399

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 196,524 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Jan-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jan-19	Delva,Terry	1.3166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: TDELVA Performed on: 03-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		TDELVA	Jan 3, 2019 8:59:42 AM	No	
101,000 - FRA Change Oil Filters	Yes		TDELVA	Jan 3, 2019 8:59:42 AM	No	
102,000 - FRA Drain Engine Oil	Yes		TDELVA	Jan 3, 2019 8:59:42 AM	No	
103,000 - FRA Check Transmission Fluid	Done		TDELVA	Jan 3, 2019 8:59:42 AM	No	
104,000 - Lubricate Chassis	Done		TDELVA	Jan 3, 2019 8:59:42 AM	No	
105,000 - Replace or Clean A/C Filters	Done		TDELVA	Jan 3, 2019 8:59:42 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	TDELVA	Jan 3, 2019 8:59:42 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		TDELVA	Jan 3, 2019 8:59:42 AM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	1.32
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51953399
Invoice No. 55345 - 51953399

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	196,524 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jan-19	Delva,Terry	0.55	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 03-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jan 3, 2019 8:51:15 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jan 3, 2019 8:51:15 AM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Jan 3, 2019 8:51:15 AM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Jan 3, 2019 8:51:15 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jan 3, 2019 8:51:15 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jan 3, 2019 8:51:15 AM	No	
20 - Miles			TDELVA	Jan 3, 2019 8:51:15 AM	No	
30 - Kilometers			TDELVA	Jan 3, 2019 8:51:15 AM	No	
40 - Hours			TDELVA	Jan 3, 2019 8:51:15 AM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.55
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 51953399 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	3.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51961429
Invoice No. 55345 - 51961429

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
REPLACE STARTER		Ford E350 Champion Crusaders	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	192,526 - DH

Chronology		
Reported	Dec 4, 2018 9:34:10 AM	Dec 4, 2018 9:34:10 AM
Started	Dec 4, 2018 12:00:00 AM	
Completed	Dec 5, 2018 11:28:16 AM	Dec 5, 2018 11:28:16 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Driver reported that Vehicle will not start

Cause: Bad starter

Correction: Tech Remove&Replace Starter.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Dec-18	KARLENS,Cyrius	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 04-DEC-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		CKARLENS	Dec 4, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:38:40 AM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		CKARLENS	Dec 4, 2018 9:38:40 AM	No	
3 - Are you wearing the appropriate PPE?	Done		CKARLENS	Dec 4, 2018 9:38:40 AM	No	
4 - Have you performed the proper LOTO?	Done		CKARLENS	Dec 4, 2018 9:38:40 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		CKARLENS	Dec 4, 2018 9:38:40 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Dec 4, 2018 9:38:40 AM	No	
20 - Miles			CKARLENS	Dec 4, 2018 9:38:40 AM	No	
30 - Kilometers			CKARLENS	Dec 4, 2018 9:38:40 AM	No	
40 - Hours			CKARLENS	Dec 4, 2018 9:38:40 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51961429
Invoice No. 55345 - 51961429

Client Department:
Department: 55345M
Work Order Description
REPLACE STARTER
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 192,526 - DH

Activity Header
Activity: 15 032/000/000 CRANKING
Activity Note: Replace Starter
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Dec-18	DL3Z-11002-A	STARTER, E350, '14	1	133.95	133.95

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Dec-18	KARLENS,Cyrius	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	133.95
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**133.95**

Work Order Footer

Work Order 51961429 Total	
Parts:	133.95
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**133.95**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51869856
Invoice No. 55345 - 51869856

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM B		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	192,142 - DH

Chronology		
Reported	Nov 30, 2018 11:55:39 AM	Nov 30, 2018 11:55:39 AM
Started	Nov 30, 2018 12:00:00 AM	
Completed	Nov 30, 2018 9:12:00 PM	Nov 30, 2018 9:12:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PMB Service

CAUSE: Service Due by Mileage

CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check brakes. Clean batteries.
Parts # B329 Qty (1)
Oil 5W 20 Qty(6.5) Qt

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Nov-18	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 30-NOV-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Nov 30, 2018 9:02:04 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Nov 30, 2018 9:02:04 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Nov 30, 2018 9:02:04 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Nov 30, 2018 9:02:04 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Nov 30, 2018 9:02:04 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	Nov 30, 2018 9:02:04 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Nov 30, 2018 9:02:04 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Nov 30, 2018 9:02:04 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
40,420 - Check Hood	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Nov 30, 2018 9:02:04 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Nov 30, 2018 9:02:04 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Nov 30, 2018 9:02:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Nov 30, 2018 9:02:04 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Nov 30, 2018 9:02:04 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Nov 30, 2018 9:02:04 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Nov 30, 2018 9:02:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
60,631 - Tread Depth RF	12 32nds of an inch		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
60,635 - Tread Depth LRI	5 32nds of an inch		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
60,636 - Tread Depth LRO	5 32nds of an inch		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Nov 30, 2018 9:02:04 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
77,131 - Brake Pad Thickness LF	12 Inch		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
77,132 - Brake Pad Thickness RF	12 Inch		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
77,135 - Brake Rotor LF	1.565 Inch		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
77,136 - Brake Rotor RF	1.563 Inch		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
77,137 - Brake Rotor LR	1.417 Inch		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
77,138 - Brake Rotor RR	1.416 Inch		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Nov 30, 2018 9:02:04 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Nov 30, 2018 9:02:04 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51869856
Invoice No. 55345 - 51869856

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 192,142 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Nov-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Nov-18	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: DARTHURS Performed on: 30-NOV-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Nov 30, 2018 9:03:17 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Nov 30, 2018 9:03:17 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Nov 30, 2018 9:03:17 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Nov 30, 2018 9:03:17 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Nov 30, 2018 9:03:17 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Nov 30, 2018 9:03:17 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Nov 30, 2018 9:03:17 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Nov 30, 2018 9:03:17 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		DARTHURS	Nov 30, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				9:03:17 PM		
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Nov 30, 2018 9:03:17 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		DARTHURS	Nov 30, 2018 9:03:17 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Nov 30, 2018 9:03:17 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Nov 30, 2018 9:03:17 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51869856
Invoice No. 55345 - 51869856

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM B		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	192,142 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Nov-18	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 30-NOV-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Nov 30, 2018 9:04:04 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Nov 30, 2018 9:04:04 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Nov 30, 2018 9:04:04 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Nov 30, 2018 9:04:04 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Nov 30, 2018 9:04:04 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Nov 30, 2018 9:04:04 PM	No	
20 - Miles			DARTHURS	Nov 30, 2018 9:04:04 PM	No	
30 - Kilometers			DARTHURS	Nov 30, 2018 9:04:04 PM	No	
40 - Hours			DARTHURS	Nov 30, 2018 9:04:04 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 51869856 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51869307
Invoice No. 55345 - 51869307

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Front Brakes& Both R/ R Tires		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	188,075 - DH

Chronology		
Reported	Nov 1, 2018 4:30:46 PM	Nov 1, 2018 4:30:46 PM
Started	Nov 1, 2018 12:00:00 AM	
Completed	Nov 1, 2018 9:03:00 PM	Nov 1, 2018 9:03:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: front Brakes& R/R Tires.

Cause: Front Brakes Low& Rotor Worn/ Both R/R tires below spec.

Correction:mount&Balance Both R/R Tires / Rotate to front & Both Front to R/R& Replace Both Front Rotor.both side wheel bearing & Seals.replace front pads.
Parts#BC2Z-1102-B Qty (2)
Parts# BC2Z-2V001-D Qty (1)
Parts# LM102949 Qty (2)
Parts#TM15101 Qty (2)
Parts# CR24000 Qty (2)
Parts# 189752 Qty (2)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Nov-18	Arthurs,Durvin	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 01-NOV-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Nov 1, 2018 9:00:40 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Nov 1, 2018 9:00:40 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Nov 1, 2018 9:00:40 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Nov 1, 2018 9:00:40 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Nov 1, 2018 9:00:40 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Nov 1, 2018 9:00:40 PM	No	
20 - Miles			DARTHURS	Nov 1, 2018 9:00:40 PM	No	
30 - Kilometers			DARTHURS	Nov 1, 2018 9:00:40 PM	No	
40 - Hours			DARTHURS	Nov 1, 2018 9:00:40 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51780465
Invoice No. 55345 - 51780465

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	188,075 - DH

Chronology		
Reported	Oct 31, 2018 11:23:03 AM	Oct 31, 2018 11:23:03 AM
Started	Nov 1, 2018 12:00:00 AM	
Completed	Nov 1, 2018 9:03:00 PM	Nov 1, 2018 9:03:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA Service

CAUSE: Service due by Mileage

CORRECTION: Change Oil &Filter .lube all Pivoting Points .check Brakes .clean batteries.replace A/C Filter.
Parts# B329 Qty (1)
Oil 5W20 Qty (6.5) Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Nov-18	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 01-NOV-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Nov 1, 2018 4:23:38 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Nov 1, 2018 4:23:38 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Nov 1, 2018 4:23:38 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Nov 1, 2018 4:23:38 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Nov 1, 2018 4:23:38 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	Nov 1, 2018 4:23:38 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Nov 1, 2018 4:23:38 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Nov 1, 2018 4:23:38 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
40,420 - Check Hood	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Nov 1, 2018 4:23:38 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Nov 1, 2018 4:23:38 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Nov 1, 2018 4:23:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Nov 1, 2018 4:23:38 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Nov 1, 2018 4:23:38 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Nov 1, 2018 4:23:38 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Nov 1, 2018 4:23:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
60,631 - Tread Depth RF	6 32nds of an inch		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
60,632 - Tread Depth LF	7 32nds of an inch		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
60,633 - Tread Depth RRO	3 32nds of an inch		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
60,634 - Tread Depth RRI	3 32nds of an inch		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Nov 1, 2018 4:23:38 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
77,131 - Brake Pad Thickness LF	4 Inch		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
77,132 - Brake Pad Thickness RF	4 Inch		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
77,135 - Brake Rotor LF	1.551 Inch		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
77,136 - Brake Rotor RF	1.549 Inch		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
77,137 - Brake Rotor LR	1.418 Inch		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
77,138 - Brake Rotor RR	1.419 Inch		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Nov 1, 2018 4:23:38 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Nov 1, 2018 4:23:38 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51869307
Invoice No. 55345 - 51869307

Client Department:
Department: 55345M
Work Order Description
Front Brakes& Both R/ R Tires
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 188,075 - DH

Activity Header
Activity: 15 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Nov-18	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	48.87	48.87
01-Nov-18	TM15101	BEARING, WHEEL, OUTER, CONE, ROLLER, TAPERED	2	8.16	16.32
01-Nov-18	BC2Z-1102-B	ROTOR, BRAKE, DISC, FRONT W/INTEGRAL HUB	2	112.53	225.06
01-Nov-18	CR24000	SEAL, WHEEL, HUB, FRONT	2	6.92	13.84
01-Nov-18	LM102949	BEARING, WHEEL, INNER, FRONT, TAPERED	2	7.44	14.88

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Nov-18	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	318.97
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**318.97**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51780465
Invoice No. 55345 - 51780465

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 188,075 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Nov-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Nov-18	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 01-NOV-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Nov 1, 2018 4:24:50 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Nov 1, 2018 4:24:50 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Nov 1, 2018 4:24:50 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Nov 1, 2018 4:24:50 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Nov 1, 2018 4:24:50 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Nov 1, 2018 4:24:50 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		DARTHURS	Nov 1, 2018 4:24:50 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Nov 1, 2018 4:24:50 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51869307
Invoice No. 55345 - 51869307

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Front Brakes& Both R/ R Tires		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	188,075 - DH

Activity Header
Activity: 25 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Nov-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	103.44	206.88

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Nov-18	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	206.88
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**206.88**

Work Order Footer

Work Order 51869307 Total	
Parts:	525.85
Labor:	0.00
Labor Hours:	3.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**525.85**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51780465
Invoice No. 55345 - 51780465

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	188,075 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Nov-18	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 01-NOV-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Nov 1, 2018 4:25:43 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Nov 1, 2018 4:25:43 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Nov 1, 2018 4:25:43 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Nov 1, 2018 4:25:43 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Nov 1, 2018 4:25:43 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Nov 1, 2018 4:25:43 PM	No	
20 - Miles			DARTHURS	Nov 1, 2018 4:25:43 PM	No	
30 - Kilometers			DARTHURS	Nov 1, 2018 4:25:43 PM	No	
40 - Hours			DARTHURS	Nov 1, 2018 4:25:43 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 51780465 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51842642
Invoice No. 55345 - 51842642

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
A/C front Evap		Ford E350 Champion Crusaders	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	186,649 - DH

Chronology		
Reported	Oct 24, 2018 11:53:24 AM	Oct 24, 2018 11:53:24 AM
Started	Oct 24, 2018 12:00:00 AM	
Completed	Oct 26, 2018 7:18:29 AM	Oct 26, 2018 7:18:29 AM
Down Time		

Work Order Notes

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Oct-18	KARLENS,Cyrius	0.3333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 24-OCT-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		CKARLENS	Oct 24, 2018 12:10:46 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		CKARLENS	Oct 24, 2018 12:10:46 PM	No	
3 - Are you wearing the appropriate PPE?	Done		CKARLENS	Oct 24, 2018 12:10:46 PM	No	
4 - Have you performed the proper LOTO?	Done		CKARLENS	Oct 24, 2018 12:10:46 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		CKARLENS	Oct 24, 2018 12:10:46 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Oct 24, 2018 12:10:46 PM	No	
20 - Miles			CKARLENS	Oct 24, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:10:46 PM		
30 - Kilometers			CKARLENS	Oct 24, 2018 12:10:46 PM	No	
40 - Hours			CKARLENS	Oct 24, 2018 12:10:46 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51842642
Invoice No. 55345 - 51842642

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
A/C front Evap		Ford E350 Champion Crusaders	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	186,649 - DH

Activity Header
Activity:20 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Oct-18	4C2Z-19A706-AA	RESISTOR, MOTOR, BLOWER SAME AS YH1697	1	21.03	21.03
24-Oct-18	3411885	TUBE, ORIFICE, A/C, FORD	1	0.75	0.75
24-Oct-18	6C2Z-19860-C	CORE, EVAPORATOR, A/C	1	145.88	145.88

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Oct-18	KARLENS,Cyrius	3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	167.66
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**167.66**

Work Order Footer

Work Order 51842642 Total	
Parts:	167.66
Labor:	0.00
Labor Hours:	3.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**167.66**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51780431
Invoice No. 55345 - 51780431

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Needs rear brakes job		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	183,616 - DH

Chronology		
Reported	Oct 3, 2018 11:28:28 PM	Oct 3, 2018 11:28:28 PM
Started	Oct 3, 2018 12:00:00 AM	
Completed	Oct 4, 2018 12:06:00 AM	Oct 4, 2018 12:06:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs rear brakes job

Cause: wear

Correction:Replaced rear brake pads and lubed guide pins
Torque wheels 140 lbs second torque 140 lbs
Part number 9C2Z-2V200-B Qty1

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Oct-18	Gaspard,Ronald	0.1333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 03-OCT-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Oct 3, 2018 11:30:48 PM	No	
2 - If this repair requires a lift, is the vehicle properly secured on lift and util	Done		RGASPARD	Oct 3, 2018 11:30:48 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Oct 3, 2018 11:30:48 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Oct 3, 2018 11:30:48 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Oct 3, 2018 11:30:48 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Oct 3, 2018 11:30:48 PM	No	
20 - Miles			RGASPARD	Oct 3, 2018 11:30:48 PM	No	
30 - Kilometers			RGASPARD	Oct 3, 2018 11:30:48 PM	No	
40 - Hours			RGASPARD	Oct 3, 2018 11:30:48 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51693655
Invoice No. 55345 - 51693655

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 183,616 - DH

Chronology		
Reported	Oct 3, 2018 11:15:45 PM	Oct 3, 2018 11:15:45 PM
Started	Oct 3, 2018 12:00:00 AM	
Completed	Oct 4, 2018 12:06:00 AM	Oct 4, 2018 12:06:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:Service

CORRECTION:Perform pmA Service
Oil filter B329 Qty1
Engine oil 5w20 qty 7 Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Oct-18	Gaspard,Ronald	1.55	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 03-OCT-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Oct 3, 2018 11:24:15 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Oct 3, 2018 11:24:15 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Oct 3, 2018 11:24:15 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Oct 3, 2018 11:24:15 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Oct 3, 2018 11:24:15 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	na	RGASPARD	Oct 3, 2018 11:24:15 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Oct 3, 2018 11:24:15 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Oct 3, 2018 11:24:15 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
40,420 - Check Hood	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Oct 3, 2018 11:24:15 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Oct 3, 2018 11:24:15 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Oct 3, 2018 11:24:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Oct 3, 2018 11:24:15 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Oct 3, 2018 11:24:15 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	-	na	RGASPARD	Oct 3, 2018 11:24:15 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Oct 3, 2018 11:24:15 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Oct 3, 2018 11:24:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
60,632 - Tread Depth LF	11 32nds of an inch		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
77,133 - Brake Pad Thickness LR	4 Inch		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
77,134 - Brake Pad Thickness RR	4 Inch		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
77,137 - Brake Rotor LR	36 Inch		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
77,138 - Brake Rotor RR	36 Inch		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Oct 3, 2018 11:24:15 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Oct 3, 2018 11:24:15 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51780431
Invoice No. 55345 - 51780431

Client Department:
Department: 55345M
Work Order Description
Needs rear brakes job
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 183,616 - DH

Activity Header
Activity: 15 013/000/000 BRAKES
Activity Note: Needs rear brakes job
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Oct-18	Gaspard,Ronald	1.55	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51780431 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51693655
Invoice No. 55345 - 51693655

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	183,616 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Oct-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Oct-18	Gaspard,Ronald	1.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 03-OCT-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Oct 3, 2018 11:25:00 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Oct 3, 2018 11:25:00 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Oct 3, 2018 11:25:00 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Oct 3, 2018 11:25:00 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Oct 3, 2018 11:25:00 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Oct 3, 2018 11:25:00 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Oct 3, 2018 11:25:00 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Oct 3, 2018 11:25:00 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	1.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51693655
Invoice No. 55345 - 51693655

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	183,616 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Oct-18	Gaspard,Ronald	0.2666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 03-OCT-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Oct 3, 2018 11:25:33 PM	No	
2 - If this repair requires a lift, is the vehicle properly secured on lift and util	Done		RGASPARD	Oct 3, 2018 11:25:33 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Oct 3, 2018 11:25:33 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Oct 3, 2018 11:25:33 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Oct 3, 2018 11:25:33 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Oct 3, 2018 11:25:33 PM	No	
20 - Miles			RGASPARD	Oct 3, 2018 11:25:33 PM	No	
30 - Kilometers			RGASPARD	Oct 3, 2018 11:25:33 PM	No	
40 - Hours			RGASPARD	Oct 3, 2018 11:25:33 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 51693655 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.90
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51690933
Invoice No. 55345 - 51690933

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Pmc follow up need double series rubber spring		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	179,421 - DH

Chronology		
Reported	Sep 5, 2018 1:28:10 PM	Sep 5, 2018 1:28:10 PM
Started		
Completed	Sep 11, 2018 6:53:00 AM	Sep 11, 2018 6:53:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:PMC follow up need bobble series rubble spring

Cause: normal wear

Correction:replace double series rubber spring passenger side completed

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 06-SEP-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Sep 6, 2018 8:39:53 AM	No	
20 - Miles			HPIERRE	Sep 6, 2018 8:39:53 AM	No	
30 - Kilometers			HPIERRE	Sep 6, 2018 8:39:53 AM	No	
40 - Hours			HPIERRE	Sep 6, 2018 8:39:53 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51690933
Invoice No. 55345 - 51690933

Client Department:
Department: 55345M
Work Order Description
Pmc follow up need double series rubber spring
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 179,421 - DH

Activity Header
Activity: 15 050/000 GROUP, ACCESSORIES
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 14 Install
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Sep-18	DSR108-075	RUBBER, SPRING, SHEAR, RUBBER, REAR, MOR/RYDE	1	130.95	130.95

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	130.95
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**130.95**

Work Order Footer

Work Order 51690933 Total	
Parts:	130.95
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**130.95**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51574696
Invoice No. 55345 - 51574696

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: DKNOTT
Created By: DKNOTT
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 179,526 - DH

Chronology		
Reported	Sep 5, 2018 7:07:01 AM	Sep 5, 2018 7:07:01 AM
Started	Sep 6, 2018 12:00:00 AM	
Completed	Sep 6, 2018 9:47:00 AM	Sep 6, 2018 9:47:00 AM
Down Time		

Work Order Notes

Line 10 PMC
Preventive maintenance

Perform service lube all Pivoting Points cross Rotate Tires completed

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Sep-18	Pierre,Hubert J	8	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 05-SEP-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
10,100 - Safety Inspection	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,140 - Check Service Brakes	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
11,152 - Decelerometer Results Test 1	FEET	N/A	HPIERRE	Sep 5, 2018 1:23:24 PM	No	
11,154 - Decelerometer Results Test 2	FEET	N/A	HPIERRE	Sep 5, 2018 1:23:24 PM	No	
11,156 - Decelerometer Results Test 3	FEET	N/A	HPIERRE	Sep 5, 2018 1:23:24 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	Sep 5, 2018 1:23:24 PM	No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	Sep 5, 2018 1:23:24 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Sep 5, 2018 1:23:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Sep 5, 2018 1:23:24 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Sep 5, 2018 1:23:24 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
40,420 - Check Hood	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Sep 5, 2018 1:23:24 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Sep 5, 2018 1:23:24 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Sep 5, 2018 1:23:24 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Sep 5, 2018 1:23:24 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Sep 5, 2018 1:23:24 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Sep 5, 2018 1:23:24 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Sep 5, 2018 1:23:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Sep 5, 2018 1:23:24 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	-	N/A	HPIERRE	Sep 5, 2018 1:23:24 PM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
77,135 - Brake Rotor LF	1.5 Inch		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
77,136 - Brake Rotor RF	1.5 Inch		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
77,137 - Brake Rotor LR	1.6 Inch		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
77,138 - Brake Rotor RR	1.6 Inch		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Sep 5, 2018 1:23:24 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Sep 5, 2018 1:23:24 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	8.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51574696
Invoice No. 55345 - 51574696

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: DKNOTT
Created By: DKNOTT
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 179,526 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Sep-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Sep-18	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: HPIERRE Performed on: 05-SEP-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Sep 5, 2018 1:25:36 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Sep 5, 2018 1:25:36 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Sep 5, 2018 1:25:36 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Sep 5, 2018 1:25:36 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Sep 5, 2018 1:25:36 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Sep 5, 2018 1:25:36 PM	No	
107,000 - FRA Change Primary Fuel Filter	Done		HPIERRE	Sep 5, 2018 1:25:36 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Sep 5, 2018 1:25:36 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		HPIERRE	Sep 5, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				1:25:36 PM		
201,000 - Service Crankcase Breather	Done		HPIERRE	Sep 5, 2018 1:25:36 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		HPIERRE	Sep 5, 2018 1:25:36 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	Yes		HPIERRE	Sep 5, 2018 1:25:36 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		HPIERRE	Sep 5, 2018 1:25:36 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		HPIERRE	Sep 5, 2018 1:25:36 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		HPIERRE	Sep 5, 2018 1:25:36 PM	No	
302,000 - Check Toe-In and Record Reading	-	N/A	HPIERRE	Sep 5, 2018 1:25:36 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	N/A	HPIERRE	Sep 5, 2018 1:25:36 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		HPIERRE	Sep 5, 2018 1:25:36 PM	No	
305,000 - FRA Change Differential Fluid	Yes		HPIERRE	Sep 5, 2018 1:25:36 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51574696
Invoice No. 55345 - 51574696

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: DKNOTT
Created By: DKNOTT
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 179,526 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Sep-18	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 05-SEP-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Sep 5, 2018 1:26:03 PM	No	
20 - Miles			HPIERRE	Sep 5, 2018 1:26:03 PM	No	
30 - Kilometers			HPIERRE	Sep 5, 2018 1:26:03 PM	No	
40 - Hours			HPIERRE	Sep 5, 2018 1:26:03 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51574696 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	8.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51631184
Invoice No. 55345 - 51631184

Client Department:
Department: 55345M
Work Order Description
RD CALLED FLAT TIRE -PAHOKKEE
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 176,823 - DH

Chronology		
Reported	Aug 17, 2018 10:12:00 AM	Aug 17, 2018 10:12:00 AM
Started	Aug 17, 2018 12:00:00 AM	
Completed	Aug 17, 2018 9:19:00 PM	Aug 17, 2018 9:19:00 PM
Down Time		

Work Order Notes

Line 10 Driver stated front driver tire is flat
Tech Replaced tires
Qty:1 part#189752

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Aug-18	KARLENS,Cyrius	0.3333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 17-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Aug 17, 2018 4:18:06 PM	No	
20 - Miles			CKARLENS	Aug 17, 2018 4:18:06 PM	No	
30 - Kilometers			CKARLENS	Aug 17, 2018 4:18:06 PM	No	
40 - Hours			CKARLENS	Aug 17, 2018 4:18:06 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00

	Labor Hours:	0.67
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51631184
Invoice No. 55345 - 51631184

Client Department:
Department: 55345M
Work Order Description
RD CALLED FLAT TIRE -PAHOKKEE
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 176,823 - DH

Activity Header
Activity: 20 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Aug-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	1	103.44	103.44
17-Aug-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	103.44	206.88
17-Aug-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	-2	103.44	-206.88

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Aug-18	KARLENS,Cyrius	3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	103.44
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**103.44**

Work Order Footer

Work Order 51631184 Total	
Parts:	103.44
Labor:	0.00
Labor Hours:	3.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**103.44**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51488560
Invoice No. 55345 - 51488560

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	175,141 - DH

Chronology		
Reported	Aug 6, 2018 11:00:02 AM	Aug 6, 2018 11:00:02 AM
Started	Aug 6, 2018 12:00:00 AM	
Completed	Aug 6, 2018 3:07:30 PM	Aug 6, 2018 3:07:30 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PmA

CAUSE: preventive maintenance

CORRECTION: perform service lube all Pivoting Points cross Rotate Tires completed

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Aug-18	Pierre,Hubert J	7	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 06-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
10,100 - Safety Inspection	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,140 - Check Service Brakes	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
11,152 - Decelerometer Results Test 1	FEET	N/A	HPIERRE	Aug 6, 2018 11:24:08 AM	No	
11,154 - Decelerometer Results Test 2	FEET	N/A	HPIERRE	Aug 6, 2018 11:24:08 AM	No	
11,156 - Decelerometer Results Test 3	FEET	N/A	HPIERRE	Aug 6, 2018 11:24:08 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	Aug 6, 2018 11:24:08 AM	No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	Aug 6, 2018 11:24:08 AM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Aug 6, 2018 11:24:08 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Aug 6, 2018 11:24:08 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Aug 6, 2018 11:24:08 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
40,420 - Check Hood	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Aug 6, 2018 11:24:08 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Aug 6, 2018 11:24:08 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Aug 6, 2018 11:24:08 AM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Aug 6, 2018 11:24:08 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Aug 6, 2018 11:24:08 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Aug 6, 2018 11:24:08 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Aug 6, 2018 11:24:08 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
60,631 - Tread Depth RF	8 32nds of an inch		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
60,632 - Tread Depth LF	8 32nds of an inch		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Aug 6, 2018 11:24:08 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
77,131 - Brake Pad Thickness LF	8 Inch		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
77,132 - Brake Pad Thickness RF	8 Inch		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
77,133 - Brake Pad Thickness LR	7 Inch		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
77,134 - Brake Pad Thickness RR	7 Inch		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
77,135 - Brake Rotor LF	1.5 Inch		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
77,136 - Brake Rotor RF	1.5 Inch		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
77,137 - Brake Rotor LR	1.6 Inch		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
77,138 - Brake Rotor RR	1.6 Inch		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Aug 6, 2018 11:24:08 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Aug 6, 2018 11:24:08 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	7.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51488560
Invoice No. 55345 - 51488560

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 175,141 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Aug-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Aug-18	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 06-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Aug 6, 2018 11:26:47 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Aug 6, 2018 11:26:47 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Aug 6, 2018 11:26:47 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Aug 6, 2018 11:26:47 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Aug 6, 2018 11:26:47 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Aug 6, 2018 11:26:47 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Aug 6, 2018 11:26:47 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Aug 6, 2018 11:26:47 AM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51488560
Invoice No. 55345 - 51488560

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	175,141 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Aug-18	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 06-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Aug 6, 2018 11:27:50 AM	No	
20 - Miles			HPIERRE	Aug 6, 2018 11:27:50 AM	No	
30 - Kilometers			HPIERRE	Aug 6, 2018 11:27:50 AM	No	
40 - Hours			HPIERRE	Aug 6, 2018 11:27:50 AM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51488560 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	7.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51408878
Invoice No. 55345 - 51408878

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	170,683 - DH

Chronology		
Reported	Jul 6, 2018 9:57:06 AM	Jul 6, 2018 9:57:06 AM
Started	Jul 6, 2018 12:00:00 AM	
Completed	Jul 7, 2018 12:00:00 AM	Jul 7, 2018 12:00:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA Service

CAUSE: Service due by Mileage

CORRECTION: Change Oil & Filter. lube all Pivoting Points.check brakes .clean batteries .replace A/C Filter. & Replace Air cleaner.
Parts# B329 Qty (1)
Parts# PA 4075 Qty (1)
Oil 5W20QTY (6.5) Qt

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jul-18	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 06-JUL-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Jul 6, 2018 10:46:54 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Jul 6, 2018 10:46:54 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Jul 6, 2018 10:46:54 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Jul 6, 2018 10:46:54 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Jul 6, 2018 10:46:54 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
20,260 - Check Stop Request System	-	NA	DARTHURS	Jul 6, 2018 10:46:54 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Jul 6, 2018 10:46:54 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Jul 6, 2018 10:46:54 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
40,420 - Check Hood	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Jul 6, 2018 10:46:54 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Jul 6, 2018 10:46:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Jul 6, 2018 10:46:54 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Jul 6, 2018 10:46:54 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Jul 6, 2018 10:46:54 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Jul 6, 2018 10:46:54 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Jul 6, 2018 10:46:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
60,631 - Tread Depth RF	3 32nds of an inch		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
60,632 - Tread Depth LF	3 32nds of an inch		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
60,633 - Tread Depth RRO	9 32nds of an inch		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
60,635 - Tread Depth LRI	10 32nds of an inch		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
60,636 - Tread Depth LRO	11 32nds of an inch		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Jul 6, 2018 10:46:54 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done	Left hub leaking	DARTHURS	Jul 6, 2018 10:46:54 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
77,135 - Brake Rotor LF	1.553 Inch		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
77,136 - Brake Rotor RF	1.554 Inch		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
77,137 - Brake Rotor LR	1.416 Inch		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
77,138 - Brake Rotor RR	1.414 Inch		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Jul 6, 2018 10:46:54 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Jul 6, 2018 10:46:54 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51408878
Invoice No. 55345 - 51408878

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	170,683 - DH

Activity Header
Activity: 20 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: PM A Replace Air filter
Reason for Repair: 05 Inspection, Routine
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Jul-18	PA4075	FILTER, AIR SEE P546597	1	5.28	5.28
06-Jul-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jul-18	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A Replace Air filter
Task: PM A SERVICE Performed by: DARTHURS Performed on: 06-JUL-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Jul 6, 2018 10:47:43 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Jul 6, 2018 10:47:43 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Jul 6, 2018 10:47:43 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Jul 6, 2018 10:47:43 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Jul 6, 2018 10:47:43 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Jul 6, 2018 10:47:43 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Jul 6, 2018 10:47:43 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Jul 6, 2018 10:47:43 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	7.24
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.24**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51408878
Invoice No. 55345 - 51408878

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	170,683 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jul-18	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 06-JUL-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 6, 2018 10:48:08 PM	No	
20 - Miles			DARTHURS	Jul 6, 2018 10:48:08 PM	No	
30 - Kilometers			DARTHURS	Jul 6, 2018 10:48:08 PM	No	
40 - Hours			DARTHURS	Jul 6, 2018 10:48:08 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51408878 Total	
Parts:	7.24
Labor:	0.00
Labor Hours:	2.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**7.24**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51488523
Invoice No. 55345 - 51488523

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Front Tire& Lefthub seal		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	170,683 - DH

Chronology		
Reported	Jul 6, 2018 10:56:58 PM	Jul 6, 2018 10:56:58 PM
Started	Jul 6, 2018 12:00:00 AM	
Completed	Jul 6, 2018 11:59:00 PM	Jul 6, 2018 11:59:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Front Tires& Left hub Seal

Cause: Left hub seal Leaking& Front Tires Worn.

Correction: Mount & Balance Both Front Tire& Replace .Remove Left Rear hub to replace seal
Parts# 189752 Qty (2)
Parts# 9864S Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jul-18	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 06-JUL-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 6, 2018 11:58:32 PM	No	
20 - Miles			DARTHURS	Jul 6, 2018 11:58:32 PM	No	
30 - Kilometers			DARTHURS	Jul 6, 2018 11:58:32 PM	No	
40 - Hours			DARTHURS	Jul 6, 2018 11:58:32 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51488523
Invoice No. 55345 - 51488523

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Front Tire& Lefthub seal		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	170,683 - DH

Activity Header
Activity: 15 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Aug-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	1	103.44	103.44
06-Jul-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	103.44	206.88

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jul-18	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	310.32
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**310.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51488523
Invoice No. 55345 - 51488523

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Front Tire& Lefthub seal		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	170,683 - DH

Activity Header
Activity: 25 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Jul-18	9864S	SEAL, BEARING, INNER, WHEEL, DRIVE	1	6.43	6.43

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jul-18	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	6.43
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**6.43**

Work Order Footer

Work Order 51488523 Total	
Parts:	316.75
Labor:	0.00
Labor Hours:	2.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**316.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 51408864
Invoice No. 55345 - 51408864

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
FOLLOW UP PMB		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	99 - Cancelled (99)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	166,616 - DH

Chronology		
Reported	Jun 7, 2018 10:35:35 PM	Jun 7, 2018 10:35:35 PM
Started		
Completed	Jun 12, 2018 8:01:10 AM	Jun 12, 2018 8:01:10 AM
Down Time		

Work Order Notes

Activity Header
Activity: 10 015/005/000 STEERING, POWER
Activity Note:
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51408864 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51336458
Invoice No. 55345 - 51336458

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM B		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	166,616 - DH

Chronology		
Reported	Jun 7, 2018 11:57:20 AM	Jun 7, 2018 11:57:20 AM
Started	Jun 7, 2018 12:00:00 AM	
Completed	Jun 7, 2018 10:44:00 PM	Jun 7, 2018 10:44:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PM-B

CAUSE: Preventive Maintenance

CORRECTION: Tech Performed PM-B

Parts used
Oil filter Qty1 part#B329
Oil Qty:6.5

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Jun-18	KARLENS,Cyrius	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: CKARLENS Performed on: 07-JUN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
10,100 - Safety Inspection	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,120 - FRA Check All Warning Lights and Alarms	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
10,140 - Check Service Brakes	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
10,160 - FRA Check Instruments and Horns	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
10,170 - Check Fast Idle	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
10,180 - Check Starter Protection Circuit	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
10,190 - Check Reverse Warning System	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
11,100 - Check Parking Brake	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
11,150 - Perform Brake Test	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	CKARLENS	Jun 7, 2018 10:23:32 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	CKARLENS	Jun 7, 2018 10:23:32 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	CKARLENS	Jun 7, 2018 10:23:32 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	CKARLENS	Jun 7, 2018 10:23:32 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	CKARLENS	Jun 7, 2018 10:23:32 PM	No	
11,170 - FRA Check Door Operation	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
20,210 - Check Condition of Operator's Area	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
20,240 - FRA Check Interior Lights	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,250 - FRA Check Interior Electrical Panels	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
20,260 - Check Stop Request System	-	NA	CKARLENS	Jun 7, 2018 10:23:32 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	CKARLENS	Jun 7, 2018 10:23:32 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
22,110 - Check Emergency Hatches	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
22,120 - Check All Safety Equipment	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
30,310 - Check Passenger Doors	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	CKARLENS	Jun 7, 2018 10:23:32 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
30,360 - Check for Physical Damage and Decals	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
30,380 - Check Exterior Compartment Doors	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
33,100 - Check Lights and Reflectors	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
40,420 - Check Hood	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	CKARLENS	Jun 7, 2018 10:23:32 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		CKARLENS	Jun 7, 2018 10:23:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,442 - Freeze Point	Degree Fahrenheit	NA	CKARLENS	Jun 7, 2018 10:23:32 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	CKARLENS	Jun 7, 2018 10:23:32 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	CKARLENS	Jun 7, 2018 10:23:32 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
44,130 - FRA Check Exhaust System	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
44,140 - FRA Check Intake System	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	CKARLENS	Jun 7, 2018 10:23:32 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
44,180 - FRA Check for Leaks	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
44,190 - FRA Perform Battery Inspection	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
50,510 - Check Entire Steering System	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		CKARLENS	Jun 7, 2018 10:23:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,615 - Air Pressure LRI	70 Pounds per Square Inch		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
60,620 - Check Valve Stems and Caps	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
60,630 - Check and Record Tread Depth	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
60,631 - Tread Depth RF	6 32nds of an inch		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
60,632 - Tread Depth LF	6 32nds of an inch		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
60,633 - Tread Depth RRO	11 32nds of an inch		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
60,634 - Tread Depth RRI	11 32nds of an inch		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
60,635 - Tread Depth LRI	11 32nds of an inch		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
60,636 - Tread Depth LRO	11 32nds of an inch		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
60,650 - Check Sidewall Wear	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
60,660 - Inspect for Cuts and Tears	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
60,670 - Check Dual Mating With Square	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
70,710 - Check Vibration Damper	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
70,730 - FRA Check Starter	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
70,770 - FRA Check Exhaust System	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,790 - Check All Body Mounts and Chassis Frame	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
77,110 - FRA Check Fuel Tank	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
77,120 - Check Suspension Components	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
77,135 - Brake Rotor LF	39.8 Inch		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
77,136 - Brake Rotor RF	39.8 Inch		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
77,137 - Brake Rotor LR	35.8 Inch		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
77,138 - Brake Rotor RR	35.8 Inch		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
77,140 - FRA Check Brake Hoses	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
77,150 - Check King Pins	-	NA	CKARLENS	Jun 7, 2018 10:23:32 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
80,810 - Completion of PMI Report	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		CKARLENS	Jun 7, 2018 10:23:32 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51336458
Invoice No. 55345 - 51336458

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 166,616 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Jun-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Jun-18	KARLENS,Cyrius	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: CKARLENS Performed on: 07-JUN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		CKARLENS	Jun 7, 2018 10:14:49 PM	No	
101,000 - FRA Change Oil Filters	Yes		CKARLENS	Jun 7, 2018 10:14:49 PM	No	
102,000 - FRA Drain Engine Oil	Yes		CKARLENS	Jun 7, 2018 10:14:49 PM	No	
103,000 - FRA Check Transmission Fluid	Done		CKARLENS	Jun 7, 2018 10:14:49 PM	No	
104,000 - Lubricate Chassis	Done		CKARLENS	Jun 7, 2018 10:14:49 PM	No	
105,000 - Replace or Clean A/C Filters	Done		CKARLENS	Jun 7, 2018 10:14:49 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	CKARLENS	Jun 7, 2018 10:14:49 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		CKARLENS	Jun 7, 2018 10:14:49 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		CKARLENS	Jun 7, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				10:14:49 PM		
201,000 - Service Crankcase Breather	Done		CKARLENS	Jun 7, 2018 10:14:49 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		CKARLENS	Jun 7, 2018 10:14:49 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		CKARLENS	Jun 7, 2018 10:14:49 PM	Yes	51408864
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		CKARLENS	Jun 7, 2018 10:14:49 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51336458
Invoice No. 55345 - 51336458

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 166,616 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Jun-18	KARLENS,Cyrius	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 07-JUN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Jun 7, 2018 10:14:02 PM	No	
20 - Miles			CKARLENS	Jun 7, 2018 10:14:02 PM	No	
30 - Kilometers			CKARLENS	Jun 7, 2018 10:14:02 PM	No	
40 - Hours			CKARLENS	Jun 7, 2018 10:14:02 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51336458 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	3.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51384307
Invoice No. 55345 - 51384307

Client Department:
Department: 55345M
Work Order Description
Vehicle needs a window latch for the sliding window
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 165,709 - DH

Chronology		
Reported	May 31, 2018 11:48:33 AM	May 31, 2018 11:48:33 AM
Started		
Completed	Jun 1, 2018 1:25:53 PM	Jun 1, 2018 1:25:53 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:
Window latch is missing

Cause:
Unknown.

Correction:
Installed a new window latch on passenger rear sliding window.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 31-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	May 31, 2018 11:59:34 AM	No	
20 - Miles			EDTORRES	May 31, 2018 11:59:34 AM	No	
30 - Kilometers			EDTORRES	May 31, 2018 11:59:34 AM	No	
40 - Hours			EDTORRES	May 31, 2018 11:59:34 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51384307
Invoice No. 55345 - 51384307

Client Department:
Department: 55345M
Work Order Description
Vehicle needs a window latch for the sliding window
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 165,709 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note: Window latch is missing.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Jun-18	10206730	HANDLE, WINDOW, SLIDER, CHAMPION	1	14.47	14.47

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	14.47
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**14.47**

Work Order Footer

Work Order 51384307 Total	
Parts:	14.47
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**14.47**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51378219
Invoice No. 55345 - 51378219

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345 Alternator		Ford E350 Champion Crusaders	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	165,460 - DH

Chronology		
Reported	May 29, 2018 12:49:55 PM	May 29, 2018 12:49:55 PM
Started	May 29, 2018 12:00:00 AM	
Completed	May 30, 2018 7:19:14 AM	May 30, 2018 7:19:14 AM
Down Time		

Work Order Notes

Line 10 Alternator

COMPLAINT:
Battery indicator light is illuminated on the dash screen

Alternator is not putting within specs. Checked system voltage and its at 12.2V. I checked the alternator pigtail and it was good. Determined that alternator is faulty.

CORRECTION: removed and replaced alternator and replaced alternator pigtail wire harness as a preventive maintenance. Checked the voltage post installation and with load alternator is putting out 14.1V and without load it puts out 14.1V. Charging system is working properly at this time.

PARTS
Quantity 1 alternator pigtail harness
1 Alternator

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
10 Desc: Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 29-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	May 29, 2018 1:01:47 PM	No	
20 - Miles			RAURODRIGUEZ	May 29, 2018 1:01:47 PM	No	
30 - Kilometers			RAURODRIGUEZ	May 29, 2018 1:01:47 PM	No	
40 - Hours			RAURODRIGUEZ	May 29, 2018 1:01:47 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51378219
Invoice No. 55345 - 51378219

Client Department:
Department: 55345M
Work Order Description
55345 Alternator
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 165,460 - DH

Activity Header
Activity: 20 031/000/000 CHARGING
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-May-18	GC2Z-10346-B	ALTERNATOR, E450	1	459	459
29-May-18	WPT118	PIGTAIL, SENSOR, CAM SAME AS 1U2Z-14S411-TA	1	36.47	36.47

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-May-18	Rodriguez,Raul	1.6666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	495.47
Labor:	0.00
Labor Hours:	1.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**495.47**

Work Order Footer

Work Order 51378219 Total	
Parts:	495.47
Labor:	0.00
Labor Hours:	1.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**495.47**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51367053
Invoice No. 55345 - 51367053

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
55345 SPARK PLUG GAS BUSSES		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	164,544 - DH

Chronology		
Reported	May 23, 2018 6:42:45 AM	May 23, 2018 6:42:45 AM
Started	May 23, 2018 12:00:00 AM	
Completed	May 23, 2018 1:57:50 PM	May 23, 2018 1:57:50 PM
Down Time		

Work Order Notes

Line 10
Spark plug

COMPLAINT:
Manufacturer recommended spark plug service by mileage

CAUSE:
Normal wear.

CORRECTION:
Removed all spark plugs and spark plug boots. Replaced them with new spark plugs and spark plug boots. Applied dielectric grease to the the spring inside the spark plug boot.

PARTSk
Qty 8 Boot WR-6128
Qty 8 spark plug SP521

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
10 Desc: PERSONAL RISK ASSESMENT

Check List

Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 23-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	May 23, 2018 6:48:22 AM	No	
20 - Miles			EDTORRES	May 23, 2018 6:48:22 AM	No	
30 - Kilometers			EDTORRES	May 23, 2018 6:48:22 AM	No	
40 - Hours			EDTORRES	May 23, 2018 6:48:22 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51367053
Invoice No. 55345 - 51367053

Client Department:
Department: 55345M
Work Order Description
55345 SPARK PLUG GAS BUSSES
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 164,544 - DH

Activity Header
Activity: 20 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-May-18	SP521	PLUG, SPARK, 5.4L, FORD	8	4.26	34.08
23-May-18	WR6128	BOOT, PLUG, SPARK	8	5.72	45.76

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-May-18	Torres,Edwin	2.1333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	79.84
Labor:	0.00
Labor Hours:	2.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**79.84**

Work Order Footer

Work Order 51367053 Total	
Parts:	79.84
Labor:	0.00
Labor Hours:	2.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**79.84**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51336287
Invoice No. 55345 - 51336287

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Front Brakes& Tag light		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	162,652 - DH

Chronology		
Reported	May 9, 2018 8:19:02 PM	May 9, 2018 8:19:02 PM
Started	May 9, 2018 12:00:00 AM	
Completed	May 9, 2018 11:04:00 PM	May 9, 2018 11:04:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction:

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-May-18	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 09-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	May 9, 2018 8:20:31 PM	No	
20 - Miles			DARTHURS	May 9, 2018 8:20:31 PM	No	
30 - Kilometers			DARTHURS	May 9, 2018 8:20:31 PM	No	
40 - Hours			DARTHURS	May 9, 2018 8:20:31 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51210290
Invoice No. 55345 - 51210290

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	162,652 - DH

Chronology		
Reported	May 9, 2018 10:33:36 AM	May 9, 2018 10:33:36 AM
Started	May 9, 2018 12:00:00 AM	
Completed	May 9, 2018 11:04:00 PM	May 9, 2018 11:04:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA Service

CAUSE: Service due by Mileage

CORRECTION: Change Oil& Filter.Lube all Pivoting Points. Check Brakes. Clean batteries. Replace A/C Filter. Replace front clearance light.clearance light shop supply. Qty (1)
Parts# B329 Qty (1)
Oil 5W20 Qty (6.5) Qt

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-May-18	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 09-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
10,120 - FRA Check All Warning Lights and	Done		DARTHURS	May 9, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				8:09:41 PM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	May 9, 2018 8:09:41 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	May 9, 2018 8:09:41 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	May 9, 2018 8:09:41 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	May 9, 2018 8:09:41 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	May 9, 2018 8:09:41 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	May 9, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:09:41 PM		
20,260 - Check Stop Request System	-	NA	DARTHURS	May 9, 2018 8:09:41 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	May 9, 2018 8:09:41 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	May 9, 2018 8:09:41 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
40,420 - Check Hood	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	May 9, 2018 8:09:41 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	May 9, 2018 8:09:41 PM	No	
40,442 - Freeze Point	Degree	NA	DARTHURS	May 9, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			8:09:41 PM		
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	May 9, 2018 8:09:41 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	May 9, 2018 8:09:41 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	May 9, 2018 8:09:41 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	May 9, 2018 8:09:41 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	May 9, 2018 8:09:41 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	May 9, 2018 8:09:41 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	May 9, 2018 8:09:41 PM	No	
60,615 - Air Pressure LRI	65 Pounds per		DARTHURS	May 9, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			8:09:41 PM		
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	May 9, 2018 8:09:41 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
60,631 - Tread Depth RF	6 32nds of an inch		DARTHURS	May 9, 2018 8:09:41 PM	No	
60,632 - Tread Depth LF	6 32nds of an inch		DARTHURS	May 9, 2018 8:09:41 PM	No	
60,633 - Tread Depth RRO	12 32nds of an inch		DARTHURS	May 9, 2018 8:09:41 PM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		DARTHURS	May 9, 2018 8:09:41 PM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		DARTHURS	May 9, 2018 8:09:41 PM	No	
60,636 - Tread Depth LRO	12 32nds of an inch		DARTHURS	May 9, 2018 8:09:41 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	May 9, 2018 8:09:41 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
70,790 - Check All Body Mounts and Chassis	Done		DARTHURS	May 9, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Frame				8:09:41 PM		
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
77,131 - Brake Pad Thickness LF	3 Inch		DARTHURS	May 9, 2018 8:09:41 PM	No	
77,132 - Brake Pad Thickness RF	4 Inch		DARTHURS	May 9, 2018 8:09:41 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		DARTHURS	May 9, 2018 8:09:41 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		DARTHURS	May 9, 2018 8:09:41 PM	No	
77,135 - Brake Rotor LF	1.556 Inch		DARTHURS	May 9, 2018 8:09:41 PM	No	
77,136 - Brake Rotor RF	1.557 Inch		DARTHURS	May 9, 2018 8:09:41 PM	No	
77,137 - Brake Rotor LR	1.418 Inch		DARTHURS	May 9, 2018 8:09:41 PM	No	
77,138 - Brake Rotor RR	1.417 Inch		DARTHURS	May 9, 2018 8:09:41 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	May 9, 2018 8:09:41 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	May 9, 2018 8:09:41 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51336287
Invoice No. 55345 - 51336287

Client Department:
Department: 55345M
Work Order Description
Front Brakes& Tag light
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 162,652 - DH

Activity Header
Activity: 15 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-May-18	BRSD1328	PADS, BRAKE, DISC, FRONT, DUTY, HEAVY, FORD SAME AS PFH132820	1	45.25	45.25

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-May-18	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	45.25
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**45.25**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51210290
Invoice No. 55345 - 51210290

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 162,652 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-May-18	F75Z-6730-BA	PLUG, DRAIN, OIL, ENGINE, 3.0L	1	6.66	6.66
09-May-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-May-18	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 09-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	May 9, 2018 8:10:30 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	May 9, 2018 8:10:30 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	May 9, 2018 8:10:30 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	May 9, 2018 8:10:30 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	May 9, 2018 8:10:30 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	May 9, 2018 8:10:30 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	May 9, 2018 8:10:30 PM	No	
108,000 - Lube all pivoting	Done		DARTHURS	May 9, 2018 8:10:30	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Mechanisms				PM		

Activity Sub Total

Activity 20 Sub Total	
Parts:	8.62
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.62**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51336287
Invoice No. 55345 - 51336287

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Front Brakes& Tag light		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	162,652 - DH

Activity Header
Activity: 25 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Replace Tag light
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-May-18	3975927	LAMP, PLATE, LICENSE	1	9.56	9.56

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-May-18	Arthurs,Durvin	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	9.56
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**9.56**

Work Order Footer

Work Order 51336287 Total	
Parts:	54.81
Labor:	0.00
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**54.81**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51210290
Invoice No. 55345 - 51210290

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	162,652 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-May-18	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 09-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	May 9, 2018 8:10:53 PM	No	
20 - Miles			DARTHURS	May 9, 2018 8:10:53 PM	No	
30 - Kilometers			DARTHURS	May 9, 2018 8:10:53 PM	No	
40 - Hours			DARTHURS	May 9, 2018 8:10:53 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51210290 Total	
Parts:	8.62
Labor:	0.00
Labor Hours:	2.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**8.62**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51280485
Invoice No. 55345 - 51280485

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Ford Body Parts		Ford E350 Champion Crusaders	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	160,149 - DH

Chronology		
Reported	Apr 24, 2018 7:12:41 AM	Apr 24, 2018 7:12:41 AM
Started	Apr 24, 2018 12:00:00 AM	
Completed	May 1, 2018 11:58:00 AM	May 1, 2018 11:58:00 AM
Down Time		

Work Order Notes

Line 10 Complaint: front bumper (right side) damage

Cause: accident

Correction: removed and replaced front bumper chrome.

Part: front bumper # 8c2z-17757-bop

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 01-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	May 1, 2018 11:57:40 AM	No	
20 - Miles			RAURODRIGUEZ	May 1, 2018 11:57:40 AM	No	
30 - Kilometers			RAURODRIGUEZ	May 1, 2018 11:57:40 AM	No	
40 - Hours			RAURODRIGUEZ	May 1, 2018 11:57:40 AM	No	

Activity Sub Total

	Activity 10 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51280485
Invoice No. 55345 - 51280485

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Ford Body Parts		Ford E350 Champion Crusaders	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	160,149 - DH

Activity Header
Activity:20 174/000/000 BODY, BUS
Activity Note:
Reason for Repair: 41 Abuse of Equipment - 56210
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Apr-18	Rodriguez,Raul	2.6166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.62
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51280485 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.62
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 51210235
Invoice No. 55345 - 51210235

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Rear Tires/Rear Brakes/ Serpentine belts		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	158,343 - DH

Chronology		
Reported	Apr 10, 2018 11:12:07 PM	Apr 10, 2018 11:12:07 PM
Started	Apr 10, 2018 12:00:00 AM	
Completed	Apr 10, 2018 11:29:00 PM	Apr 10, 2018 11:29:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:Rear Tire/Rear Brakes/ Serpentine belts

Cause: brakes low/ Tire Worn/ Belts cracks

Correction:Mount& Balance Rear tire&Replace on Rear. Remove&Replace Serpentine belts .remove & Replace Rear Brakes.
Parts# 5061360 Qty (1)
Parts# 189752Qty (4)
Parts#BRSD 1329 Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Apr-18	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 10-APR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 10, 2018 11:17:58 PM	No	
20 - Miles			DARTHURS	Apr 10, 2018 11:17:58 PM	No	
30 - Kilometers			DARTHURS	Apr 10, 2018 11:17:58 PM	No	
40 - Hours			DARTHURS	Apr 10, 2018 11:17:58 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51091083
Invoice No. 55345 - 51091083

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	158,343 - DH

Chronology		
Reported	Apr 10, 2018 9:50:13 AM	Apr 10, 2018 9:50:13 AM
Started	Apr 10, 2018 12:00:00 AM	
Completed	Apr 10, 2018 11:29:00 PM	Apr 10, 2018 11:29:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA Service

CAUSE: Service due by Mileage

CORRECTION: Change Oil & Filter. Lube all Pivoting Points. check brakes .Clean batteries.
Parts# B329 Qty (1)
Oil 5W20QTY Qty (6.5) Qt

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Apr-18	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 10-APR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Apr 10, 2018 11:05:37 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Apr 10, 2018 11:05:37 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Apr 10, 2018 11:05:37 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Apr 10, 2018 11:05:37 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Apr 10, 2018 11:05:37 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	Apr 10, 2018 11:05:37 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Apr 10, 2018 11:05:37 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Apr 10, 2018 11:05:37 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
40,420 - Check Hood	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Apr 10, 2018 11:05:37 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Apr 10, 2018 11:05:37 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Apr 10, 2018 11:05:37 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Apr 10, 2018 11:05:37 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Apr 10, 2018 11:05:37 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Apr 10, 2018 11:05:37 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Apr 10, 2018 11:05:37 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
60,633 - Tread Depth RRO	3 32nds of an inch		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
60,634 - Tread Depth RRI	3 32nds of an inch		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
60,635 - Tread Depth LRI	3 32nds of an inch		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
60,636 - Tread Depth LRO	3 32nds of an inch	replace all Rear tire	DARTHURS	Apr 10, 2018 11:05:37 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Apr 10, 2018 11:05:37 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
77,131 - Brake Pad Thickness LF	9 Inch		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
77,132 - Brake Pad Thickness RF	9 Inch		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
77,133 - Brake Pad Thickness LR	3 Inch		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
77,134 - Brake Pad Thickness RR	4 Inch		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
77,135 - Brake Rotor LF	1.556 Inch		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
77,136 - Brake Rotor RF	1.555 Inch		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
77,137 - Brake Rotor LR	1.418 Inch		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
77,138 - Brake Rotor RR	1.419 Inch		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Apr 10, 2018 11:05:37 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Apr 10, 2018 11:05:37 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 51210235
Invoice No. 55345 - 51210235

Client Department:
Department: 55345M
Work Order Description
Rear Tires/Rear Brakes/ Serpentine belts
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 158,343 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Replace Serpentine belts
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Apr-18	5061360	BELT, SERPENTINE, 6-RIB, 136.02"L X 0.82"W	1	26.47	26.47

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Apr-18	Arthurs,Durvin	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	26.47
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**26.47**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51091083
Invoice No. 55345 - 51091083

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 158,343 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Apr-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Apr-18	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 10-APR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Apr 10, 2018 11:06:25 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Apr 10, 2018 11:06:25 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Apr 10, 2018 11:06:25 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Apr 10, 2018 11:06:25 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Apr 10, 2018 11:06:25 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Apr 10, 2018 11:06:25 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Apr 10, 2018 11:06:25 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Apr 10, 2018 11:06:25 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 51210235
Invoice No. 55345 - 51210235

Client Department:
Department: 55345M
Work Order Description
Rear Tires/Rear Brakes/ Serpentine belts
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 158,343 - DH

Activity Header
Activity: 25 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Replace rear brakes
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Apr-18	BRSD1329	PADS, BRAKE, DISC, E450	1	45.82	45.82

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Apr-18	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	45.82
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**45.82**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51091083
Invoice No. 55345 - 51091083

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 158,343 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Apr-18	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 10-APR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 10, 2018 11:06:52 PM	No	
20 - Miles			DARTHURS	Apr 10, 2018 11:06:52 PM	No	
30 - Kilometers			DARTHURS	Apr 10, 2018 11:06:52 PM	No	
40 - Hours			DARTHURS	Apr 10, 2018 11:06:52 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51091083 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 51210235
Invoice No. 55345 - 51210235

Client Department:
Department: 55345M
Work Order Description
Rear Tires/Rear Brakes/ Serpentine belts
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 158,343 - DH

Activity Header
Activity: 35 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Replace rear Tires
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Apr-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	4	103.44	413.76

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Apr-18	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 35 Sub Total	
Parts:	413.76
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**413.76**

Work Order Footer

Work Order 51210235 Total	
Parts:	486.05
Labor:	0.00
Labor Hours:	4.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**486.05**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51095513
Invoice No. 55345 - 51095513

Client Department:
Department: 55345M
Work Order Description
Needs 2 batteries ,front blower motor and 2 front terminals
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 154,618 - DH

Chronology		
Reported	Mar 13, 2018 10:30:53 PM	Mar 13, 2018 10:30:53 PM
Started	Mar 13, 2018 12:00:00 AM	
Completed	Mar 13, 2018 11:36:00 PM	Mar 13, 2018 11:36:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs batteries,blower motor and 2 terminals

Cause: bad

Correction:replaced blower motor, 2 batteries and 2 front terminals

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Mar-18	Gaspard,Ronald	0.1166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 13-MAR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Mar 13, 2018 10:33:57 PM	No	
20 - Miles			RGASPARD	Mar 13, 2018 10:33:57 PM	No	
30 - Kilometers			RGASPARD	Mar 13, 2018 10:33:57 PM	No	
40 - Hours			RGASPARD	Mar 13, 2018 10:33:57 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51095513
Invoice No. 55345 - 51095513

Client Department:
Department: 55345M
Work Order Description
Needs 2 batteries ,front blower motor and 2 front terminals
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 154,618 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Mar-18	34AGM	BATTERY, AGM, GROUP-34	2	114.24	228.48
13-Mar-18	MM840	MOTOR, BLOWER, HVAC	1	58.35	58.35
13-Mar-18	3940905	BLOCK, TERMINAL, BATTERY, CHEV	2	13.83	27.66

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Mar-18	Gaspard,Ronald	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	314.49
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**314.49**

Work Order Footer

Work Order 51095513 Total	
Parts:	314.49
Labor:	0.00
Labor Hours:	2.62
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**314.49**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51091376
Invoice No. 55345 - 51091376

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
MDT not working.		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	154,293 - DH

Chronology		
Reported	Mar 12, 2018 10:13:08 AM	Mar 12, 2018 10:13:08 AM
Started	Mar 12, 2018 12:00:00 AM	
Completed	Mar 12, 2018 1:01:00 PM	Mar 12, 2018 1:01:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:
MDT not working.

Cause:
Screen is cracked, digitizer not working properly, and screen is frozen.

Correction:
Replaced the MDT with the spare MDT that we have. MDT will be sent to trap eye to be repaired under warranty. We are unsure how the screen cracked.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 12-MAR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Mar 12, 2018 10:48:27 AM	No	
20 - Miles			EDTORRES	Mar 12, 2018 10:48:27 AM	No	
30 - Kilometers			EDTORRES	Mar 12, 2018 10:48:27 AM	No	
40 - Hours			EDTORRES	Mar 12, 2018 10:48:27 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51091376
Invoice No. 55345 - 51091376

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
MDT not working.		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	154,293 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note: MDT not working
Reason for Repair: 41 Abuse of Equipment - 56210
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Mar-18	Torres,Edwin	0.7333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51091376 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51029558
Invoice No. 55345 - 51029558

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM C		Ford E350 Champion Crusaders	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	154,151 - DH

Chronology		
Reported	Mar 9, 2018 7:27:58 AM	Mar 9, 2018 7:27:58 AM
Started	Mar 9, 2018 12:00:00 AM	
Completed	Mar 12, 2018 9:03:00 AM	Mar 12, 2018 9:03:00 AM
Down Time		

Work Order Notes

Line 10 PMC

Preventive maintenance

Perform service lube all Pivoting Points cross rotate tires complete

Part # B329 qty1
Oil5w20 Qts 6

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Mar-18	B329	FILTER, OIL, SPIN-ON SEE P550965	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Mar-18	Pierre,Hubert J	6	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 09-MAR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
10,100 - Safety Inspection	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
10,110 - FRA Check Drivers Pre-trip or	Done		HPIERRE	Mar 9, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
DVIR/EVIR & Authorization Forms				12:19:17 PM		
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
11,152 - Decelerometer Results Test 1	FEET	N/A	HPIERRE	Mar 9, 2018 12:19:17 PM	No	
11,154 - Decelerometer Results Test 2	FEET	N/A	HPIERRE	Mar 9, 2018 12:19:17 PM	No	
11,156 - Decelerometer Results Test 3	FEET	N/A	HPIERRE	Mar 9, 2018 12:19:17 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	Mar 9, 2018 12:19:17 PM	No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	Mar 9, 2018 12:19:17 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Mar 9, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:19:17 PM		
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Mar 9, 2018 12:19:17 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Mar 9, 2018 12:19:17 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Mar 9, 2018 12:19:17 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	-	N/A	HPIERRE	Mar 9, 2018 12:19:17 PM	No	
40,420 - Check Hood	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Mar 9, 2018 12:19:17 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate	No	N/A	HPIERRE	Mar 9, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
with a Yes or No)				12:19:17 PM		
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Mar 9, 2018 12:19:17 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Mar 9, 2018 12:19:17 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Mar 9, 2018 12:19:17 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Mar 9, 2018 12:19:17 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
60,614 - Air Pressure RRI	70 Pounds per		HPIERRE	Mar 9, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			12:19:17 PM		
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
60,631 - Tread Depth RF	7 32nds of an inch		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
60,632 - Tread Depth LF	7 32nds of an inch		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
60,634 - Tread Depth RRI	5 32nds of an inch		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	-	N/A	HPIERRE	Mar 9, 2018 12:19:17 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Mar 9, 2018 12:19:17 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
70,780 - Check Driveline, U-joint and Slip	Done		HPIERRE	Mar 9, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Yokes				12:19:17 PM		
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
77,135 - Brake Rotor LF	1.5 Inch		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
77,136 - Brake Rotor RF	1.5 Inch		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
77,137 - Brake Rotor LR	1.6 Inch		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
77,138 - Brake Rotor RR	1.6 Inch		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Mar 9, 2018 12:19:17 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Mar 9, 2018 12:19:17 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	6.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51029558
Invoice No. 55345 - 51029558

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 154,151 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Mar-18	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: HPIERRE Performed on: 09-MAR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Mar 9, 2018 12:21:44 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Mar 9, 2018 12:21:44 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Mar 9, 2018 12:21:44 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Mar 9, 2018 12:21:44 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Mar 9, 2018 12:21:44 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Mar 9, 2018 12:21:44 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	N/A	HPIERRE	Mar 9, 2018 12:21:44 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Mar 9, 2018 12:21:44 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		HPIERRE	Mar 9, 2018 12:21:44 PM	No	
201,000 - Service Crankcase Breather	Done		HPIERRE	Mar 9, 2018 12:21:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	No		HPIERRE	Mar 9, 2018 12:21:44 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		HPIERRE	Mar 9, 2018 12:21:44 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		HPIERRE	Mar 9, 2018 12:21:44 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		HPIERRE	Mar 9, 2018 12:21:44 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		HPIERRE	Mar 9, 2018 12:21:44 PM	No	
302,000 - Check Toe-In and Record Reading	-	N/A	HPIERRE	Mar 9, 2018 12:21:44 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	N/A	HPIERRE	Mar 9, 2018 12:21:44 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		HPIERRE	Mar 9, 2018 12:21:44 PM	No	
305,000 - FRA Change Differential Fluid	Yes		HPIERRE	Mar 9, 2018 12:21:44 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51029558
Invoice No. 55345 - 51029558

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM C		Ford E350 Champion Crusaders	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	154,151 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Mar-18	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 09-MAR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Mar 9, 2018 12:22:28 PM	No	
20 - Miles			HPIERRE	Mar 9, 2018 12:22:28 PM	No	
30 - Kilometers			HPIERRE	Mar 9, 2018 12:22:28 PM	No	
40 - Hours			HPIERRE	Mar 9, 2018 12:22:28 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51029558 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	6.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 50981302
Invoice No. 55345 - 50981302

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	150,048 - DH

Chronology		
Reported	Feb 8, 2018 8:46:10 AM	Feb 8, 2018 8:46:10 AM
Started	Feb 8, 2018 12:00:00 AM	
Completed	Feb 8, 2018 12:08:00 PM	Feb 8, 2018 12:08:00 PM
Down Time		

Work Order Notes

Line 10 PM A

CAUSE:
PM

CORRECTION:
Perform pmA service, lube front end, tire rotation, torque and re torque tires (140 f/p), R&R engine oil and filter, road test, all okay at this time.

Parts. Engine oil filter part # B329 qty 1
engine oil. 5W20 Qty 6 qts
1 Air Filter # PA 4075

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Feb-18	Rodriguez,Raul	1.5333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RAURODRIGUEZ Performed on: 08-FEB-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,100 - Safety Inspection	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
10,140 - Check Service Brakes	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
10,170 - Check Fast Idle	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
10,180 - Check Starter Protection Circuit	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
10,190 - Check Reverse Warning System	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
11,100 - Check Parking Brake	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
11,150 - Perform Brake Test	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
11,170 - FRA Check Door Operation	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
20,210 - Check Condition of Operator's Area	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,230 - FRA Check Wiring Under Dash	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
20,240 - FRA Check Interior Lights	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
20,260 - Check Stop Request System	-	na	RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
22,110 - Check Emergency Hatches	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
22,120 - Check All Safety Equipment	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
30,310 - Check Passenger Doors	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
30,340 - FRA Check Destination Sign and Run Box	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
33,100 - Check Lights and Reflectors	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
40,420 - Check Hood	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,440 - Test Coolant System Using Test Strips and Record Results	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
44,130 - FRA Check Exhaust System	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
44,140 - FRA Check Intake System	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
44,180 - FRA Check for Leaks	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
50,510 - Check Entire Steering System	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
60,620 - Check Valve Stems and Caps	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
60,630 - Check and Record Tread Depth	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
60,631 - Tread Depth RF	11 32nds of an inch		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
60,632 - Tread Depth LF	11 32nds of an inch		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
60,650 - Check Sidewall Wear	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
60,670 - Check Dual Mating With Square	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
70,710 - Check Vibration Damper	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
70,730 - FRA Check Starter	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,770 - FRA Check Exhaust System	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
77,110 - FRA Check Fuel Tank	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
77,120 - Check Suspension Components	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
77,131 - Brake Pad Thickness LF	Inch	7mm	RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
77,132 - Brake Pad Thickness RF	Inch	7mm	RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
77,133 - Brake Pad Thickness LR	Inch	8mm	RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
77,134 - Brake Pad Thickness RR	Inch	8mm	RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
77,135 - Brake Rotor LF	Inch	39.6mm	RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
77,136 - Brake Rotor RF	Inch	39.6mm	RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
77,137 - Brake Rotor LR	Inch	35.7mm	RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
77,138 - Brake Rotor RR	Inch	35.7mm	RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
77,140 - FRA Check Brake Hoses	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
77,150 - Check King Pins	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
80,810 - Completion of PMI Report	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RAURODRIGUEZ	Feb 8, 2018 12:02:59 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 50981302
Invoice No. 55345 - 50981302

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	150,048 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:
Line 10 PM A

CAUSE:
PM

CORRECTION:
Perform pmA service, lube front end, tire rotation, torque and re torque tires (140 f/p), R&R engine oil and filter, road test, all okay at this time.

Parts. Engine oil filter part # B329 qty 1
engine oil. 5W20 Qty 6 qts

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Feb-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96
08-Feb-18	PA4075	FILTER, AIR SEE P546597	1	5.25	5.25

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Feb-18	Rodriguez,Raul	0.6666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
20 Desc: PM A Task: PM A SERVICE Performed by: RAURODRIGUEZ Performed on: 08-FEB-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RAURODRIGUEZ	Feb 8, 2018 12:06:47 PM	No	
101,000 - FRA Change Oil Filters	Yes		RAURODRIGUEZ	Feb 8, 2018 12:06:47 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RAURODRIGUEZ	Feb 8, 2018 12:06:47 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RAURODRIGUEZ	Feb 8, 2018 12:06:47 PM	No	
104,000 - Lubricate Chassis	Done		RAURODRIGUEZ	Feb 8, 2018 12:06:47 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RAURODRIGUEZ	Feb 8, 2018 12:06:47 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RAURODRIGUEZ	Feb 8, 2018 12:06:47 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RAURODRIGUEZ	Feb 8, 2018 12:06:47 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	7.21
Labor:	0.00
Labor Hours:	0.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.21**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 50981302
Invoice No. 55345 - 50981302

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	150,048 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 08-FEB-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Feb 8, 2018 12:07:51 PM	No	
20 - Miles			RAURODRIGUEZ	Feb 8, 2018 12:07:51 PM	No	
30 - Kilometers			RAURODRIGUEZ	Feb 8, 2018 12:07:51 PM	No	
40 - Hours			RAURODRIGUEZ	Feb 8, 2018 12:07:51 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 50981302 Total	
Parts:	7.21
Labor:	0.00
Labor Hours:	2.20
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**7.21**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 50996767
Invoice No. 55345 - 50996767

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Check engine light for transmission code P0751		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	147,280 - DH

Chronology		
Reported	Jan 18, 2018 7:11:22 AM	Jan 18, 2018 7:11:22 AM
Started	Jan 18, 2018 12:00:00 AM	
Completed	Jan 24, 2018 9:22:00 AM	Jan 24, 2018 9:22:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:
Check engine light for transmission code P0751

Cause:
Unknown.

CORRECTION:
Removed transmission from vehicle and sent transmission to be repaired. Received transmission back from the transmission shop and installed transmission back onto vehicle with the original torque converter. Filled transmission with approximately 17qts of transmission fluid. Erased check engine light. Test drove and re-checked fluid level. Transmission is shifting properly and the check engine light did not come on.

PARTS

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 18-JAN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Jan 18, 2018 7:26:42 AM	No	
20 - Miles			EDTORRES	Jan 18, 2018 7:26:42 AM	No	
30 - Kilometers			EDTORRES	Jan 18, 2018 7:26:42 AM	No	
40 - Hours			EDTORRES	Jan 18, 2018 7:26:42 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 50996767
Invoice No. 55345 - 50996767

Client Department:
Department: 55345M
Work Order Description
Check engine light for transmission code P0751
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 147,280 - DH

Activity Header
Activity: 15 027 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: Check engine light for transmission code P0751
Reason for Repair: 38 Warranty
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Jan-18	Torres,Edwin	4.65	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	4.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 50996767 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	4.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 50977832
Invoice No. 55345 - 50977832

Client Department:
Department: 55345M
Work Order Description
Eng. light on code P0751 Transmission
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 145,668 - DH

Chronology		
Reported	Jan 5, 2018 11:15:01 AM	Jan 5, 2018 11:15:01 AM
Started	Jan 5, 2018 12:00:00 AM	
Completed	Jan 9, 2018 11:25:00 AM	Jan 9, 2018 11:25:00 AM
Down Time		

Work Order Notes

Line 10

COMPLAINT:
Check engine light is on P0751 transmission shift solenoid stuck OFF

CAUSE:
Per FORD bulletin (TSB 16-0057) this transmission needs to be removed and rebuilt.

CORRECTION:
Removed transmission from vehicle and sent transmission to be repaired. Received transmission back from the transmission shop and installed transmission back onto vehicle with the original torque converter. Filled transmission with approximately 16qts of transmission fluid. Erased check engine light. Test drove and re-checked fluid level. Transmission is shifting properly and the check engine light did not come on.

PARTS
Qty 1 clutch cylinder # 7C3Z-7G387-B
Qty 1 Transmission filter 20021
Qty 1 F81Z-7A527-AA Clutch snap ring
Qty1 3C3Z-7G299-AA Planetary Gear Retainer
Qty 1 valve body gasket 8C3Z-7C155-A
Qty 1 transmission temperature sensor BC3Z-7H141-A
Qty 1 valve body, solenoid harness. 4C3Z-7G276-AAy
Qty 16.5 qts of transmission oil.

Transmission remanufacture (completed by by Transmission Xperts Pro)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 05-JAN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Jan 5, 2018 11:21:57 AM	No	
20 - Miles			RAURODRIGUEZ	Jan 5, 2018 11:21:57 AM	No	
30 - Kilometers			RAURODRIGUEZ	Jan 5, 2018 11:21:57 AM	No	
40 - Hours			RAURODRIGUEZ	Jan 5, 2018 11:21:57 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 50977832
Invoice No. 55345 - 50977832

Client Department:
Department: 55345M
Work Order Description
Eng. light on code P0751 Transmission
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 145,668 - DH

Activity Header
Activity: 15 027 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: Eng. light on code P0751 Transmission
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Jan-18	F81Z-7A527-AA	RING, SNAP, CLUTCH, TRANSMISSION	1	2.53	2.53
09-Jan-18	4C3Z-7G276-AA	HARNESS, SOLENOID, INTERNAL, TRANSMISSION, 5R110W	1	114.91	114.91
09-Jan-18	20021	FILTER, TRANSMISSION 20021	1	16.93	16.93
09-Jan-18	8C3Z-7C155-A	GASKET, BODY, VALVE, TRANSMISSION, 5R110	1	10.63	10.63
09-Jan-18	7C3Z-7G387-B	CYLINDER, CLUTCH, TRANSMISSION	1	77.72	77.72
09-Jan-18	6C3Z-7A262-AA	CLUTCH, FORWARD, TRANSMISSION	1	22.55	22.55
09-Jan-18	BC3Z-7H141-A	SENSOR, TEMPERATURE, TRANSMISSION	1	11.83	11.83
09-Jan-18	3C3Z-7G299-AA	RETAINER, GEAR, PLANETARY	1	9.46	9.46
09-Jan-18	19180251	TRANSMISSION, REMANUFACTURED	1	513.4	513.4

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jan-18	Rodriguez,Raul	4.2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	779.96
Labor:	0.00
Labor Hours:	4.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**779.96**

Work Order Footer

Work Order 50977832 Total	
Parts:	779.96
Labor:	0.00

	Labor Hours:	4.20
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**779.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 49801612
Invoice No. 55345 - 49801612

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	145,774 - DH

Chronology		
Reported	Dec 29, 2017 11:25:54 AM	Dec 29, 2017 11:25:54 AM
Started	Jan 5, 2018 12:00:00 AM	
Completed	Jan 8, 2018 11:37:44 AM	Jan 8, 2018 11:37:44 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE: preventive maintenance

CORRECTION:perform service lube all Pivoting Points cross rotate tires complete
Parts # B329 qty1
Oil5w20 Qts 6

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jan-18	Pierre,Hubert J	6	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 08-JAN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
10,100 - Safety Inspection	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
11,152 - Decelerometer Results Test 1	FEET	N/A	HPIERRE	Jan 8, 2018 8:37:02 AM	No	
11,154 - Decelerometer Results Test 2	FEET	N/A	HPIERRE	Jan 8, 2018 8:37:02 AM	No	
11,156 - Decelerometer Results Test 3	FEET	N/A	HPIERRE	Jan 8, 2018 8:37:02 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	Jan 8, 2018 8:37:02 AM	No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	Jan 8, 2018 8:37:02 AM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	N/A	HPIERRE	Jan 8, 2018 8:37:02 AM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Jan 8, 2018 8:37:02 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Jan 8, 2018 8:37:02 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
40,420 - Check Hood	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Jan 8, 2018 8:37:02 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Jan 8, 2018 8:37:02 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Jan 8, 2018 8:37:02 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Jan 8, 2018 8:37:02 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Jan 8, 2018 8:37:02 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Jan 8, 2018 8:37:02 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Jan 8, 2018 8:37:02 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
60,631 - Tread Depth RF	8 32nds of an inch		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
60,632 - Tread Depth LF	8 32nds of an inch		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Jan 8, 2018 8:37:02 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
77,131 - Brake Pad Thickness LF	8 Inch		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
77,132 - Brake Pad Thickness RF	8 Inch		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
77,133 - Brake Pad Thickness LR	5 Inch		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
77,134 - Brake Pad Thickness RR	5 Inch	need to be replace	HPIERRE	Jan 8, 2018 8:37:02 AM	No	
77,135 - Brake Rotor LF	1.6 Inch		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
77,136 - Brake Rotor RF	1.6 Inch		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
77,137 - Brake Rotor LR	1.7 Inch		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
77,138 - Brake Rotor RR	1.7 Inch		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Jan 8, 2018 8:37:02 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Jan 8, 2018 8:37:02 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	6.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 49801612
Invoice No. 55345 - 49801612

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 145,774 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Jan-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jan-18	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 05-JAN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Jan 5, 2018 9:53:41 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Jan 5, 2018 9:53:41 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Jan 5, 2018 9:53:41 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Jan 5, 2018 9:53:41 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Jan 5, 2018 9:53:41 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Jan 5, 2018 9:53:41 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Jan 5, 2018 9:53:41 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Jan 5, 2018 9:53:41 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 49801612
Invoice No. 55345 - 49801612

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	145,774 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jan-18	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 05-JAN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Jan 5, 2018 9:54:58 AM	No	
20 - Miles			HPIERRE	Jan 5, 2018 9:54:58 AM	No	
30 - Kilometers			HPIERRE	Jan 5, 2018 9:54:58 AM	No	
40 - Hours			HPIERRE	Jan 5, 2018 9:54:58 AM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 49801612 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	6.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 50977784
Invoice No. 55345 - 50977784

Client Department:
Department: 55345M
Work Order Description
PMA FOLLOW UP NEED REAR BRAKE PADS
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 145,668 - DH

Chronology		
Reported	Jan 5, 2018 10:13:10 AM	Jan 5, 2018 10:13:10 AM
Started		
Completed	Jan 8, 2018 11:32:13 AM	Jan 8, 2018 11:32:13 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT: pma follow up need rear brake pads

CAUSE:preventive maintenance

CORRECTION: replace rear brake pads completed
Part #brsd1329 qty 1

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 08-JAN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Jan 8, 2018 8:37:25 AM	No	
20 - Miles			HPIERRE	Jan 8, 2018 8:37:25 AM	No	
30 - Kilometers			HPIERRE	Jan 8, 2018 8:37:25 AM	No	
40 - Hours			HPIERRE	Jan 8, 2018 8:37:25 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 50977784
Invoice No. 55345 - 50977784

Client Department:
Department: 55345M
Work Order Description
PMA FOLLOW UP NEED REAR BRAKE PADS
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 145,668 - DH

Activity Header
Activity: 15 013 BRAKES
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Jan-18	BRSD1329	PADS, BRAKE, DISC, E450	1	44.48	44.48

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	44.48
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**44.48**

Work Order Footer

Work Order 50977784 Total	
Parts:	44.48
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**44.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 46850897
Invoice No. 55345 - 46850897

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM B		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	141,592 - DH

Chronology		
Reported	Dec 1, 2017 10:27:22 AM	Dec 1, 2017 10:27:22 AM
Started	Dec 1, 2017 12:00:00 AM	
Completed	Dec 1, 2017 9:26:00 PM	Dec 1, 2017 9:26:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMB Service

CAUSE: Service due by Mileage

CORRECTION: Change Oil & Filter . Lube all Pivoting Points . check Brakes clean batteries.Replace A/C Filter.
Parts#B329 Qty (1)
Oil 5W20 Qty (6.5) Qt

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Dec-17	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 01-DEC-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Dec 1, 2017 9:02:07 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Dec 1, 2017 9:02:07 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Dec 1, 2017 9:02:07 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Dec 1, 2017 9:02:07 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Dec 1, 2017 9:02:07 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	Dec 1, 2017 9:02:07 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Dec 1, 2017 9:02:07 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Dec 1, 2017 9:02:07 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
40,420 - Check Hood	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Dec 1, 2017 9:02:07 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Dec 1, 2017 9:02:07 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Dec 1, 2017 9:02:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Dec 1, 2017 9:02:07 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Dec 1, 2017 9:02:07 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Dec 1, 2017 9:02:07 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Dec 1, 2017 9:02:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
60,633 - Tread Depth RRO	3 32nds of an inch	R/R Tire	DARTHURS	Dec 1, 2017 9:02:07 PM	Yes	49799990
60,634 - Tread Depth RRI	6 32nds of an inch		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Dec 1, 2017 9:02:07 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
77,131 - Brake Pad Thickness LF	11 Inch		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
77,132 - Brake Pad Thickness RF	11 Inch		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
77,135 - Brake Rotor LF	1.555 Inch		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
77,136 - Brake Rotor RF	1.556 Inch		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
77,137 - Brake Rotor LR	1.417 Inch		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
77,138 - Brake Rotor RR	1.418 Inch		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Dec 1, 2017 9:02:07 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Dec 1, 2017 9:02:07 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 46850897
Invoice No. 55345 - 46850897

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 141,592 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Dec-17	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Dec-17	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: DARTHURS Performed on: 01-DEC-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Dec 1, 2017 9:03:52 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Dec 1, 2017 9:03:52 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Dec 1, 2017 9:03:52 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Dec 1, 2017 9:03:52 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Dec 1, 2017 9:03:52 PM	No	
105,000 - Replace or Clean A/C Filters	Done	Replace A/C filter	DARTHURS	Dec 1, 2017 9:03:52 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Dec 1, 2017 9:03:52 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Dec 1, 2017 9:03:52 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		DARTHURS	Dec 1, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				9:03:52 PM		
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Dec 1, 2017 9:03:52 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		DARTHURS	Dec 1, 2017 9:03:52 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Dec 1, 2017 9:03:52 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Dec 1, 2017 9:03:52 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 46850897
Invoice No. 55345 - 46850897

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM B		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	141,592 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Dec-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 01-DEC-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Dec 1, 2017 9:04:21 PM	No	
20 - Miles			DARTHURS	Dec 1, 2017 9:04:21 PM	No	
30 - Kilometers			DARTHURS	Dec 1, 2017 9:04:21 PM	No	
40 - Hours			DARTHURS	Dec 1, 2017 9:04:21 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 46850897 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 49799990
Invoice No. 55345 - 49799990

Client Department:
Department: 55345M
Work Order Description
PMB Follow up <<<<<<<R/R Tire
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 141,592 - DH

Chronology		
Reported	Dec 1, 2017 9:02:07 PM	Dec 1, 2017 9:02:07 PM
Started	Dec 1, 2017 12:00:00 AM	
Completed	Dec 1, 2017 9:25:00 PM	Dec 1, 2017 9:25:00 PM
Down Time		

Work Order Notes

Line 10 Mount& Balance both R/R Tire . Rotate New Tire to Front / Two Front to R/R.
Parts# 189752 Qty (2)

Activity Header
Activity: 10 017 TIRES, TUBES, LINERS & VALVES
Activity Note: R/R Tire
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Dec-17	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	103.57	207.14

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Dec-17	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	207.14
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**207.14**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 49799990
Invoice No. 55345 - 49799990

Client Department:
Department: 55345M
Work Order Description
PMB Follow up <<<<<<<R/R Tire
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 141,592 - DH

Activity Header
Activity: 20 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 01 Breakdown
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Dec-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 01-DEC-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Dec 1, 2017 9:12:07 PM	No	
20 - Miles			DARTHURS	Dec 1, 2017 9:12:07 PM	No	
30 - Kilometers			DARTHURS	Dec 1, 2017 9:12:07 PM	No	
40 - Hours			DARTHURS	Dec 1, 2017 9:12:07 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 49799990 Total	
Parts:	207.14
Labor:	0.00
Labor Hours:	1.08

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**207.14**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 49368857
Invoice No. 55345 - 49368857

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Rear carmera bracket broke		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	140,915 - DH

Chronology		
Reported	Nov 27, 2017 10:32:14 AM	Nov 27, 2017 10:32:14 AM
Started	Nov 27, 2017 12:00:00 AM	
Completed	Nov 28, 2017 9:04:00 AM	Nov 28, 2017 9:04:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT: broken rear camera bracket

CAUSE:exposure to weather

CORRECTION: replace bracket.

Parts
Parts under warranty

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 27-NOV-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Nov 27, 2017 10:46:46 AM	No	
20 - Miles			EDTORRES	Nov 27, 2017 10:46:46 AM	No	
30 - Kilometers			EDTORRES	Nov 27, 2017 10:46:46 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			EDTORRES	Nov 27, 2017 10:46:46 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 49368857
Invoice No. 55345 - 49368857

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Rear carmera bracket broke		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	140,915 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note: Rear camera brackets are broken
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Nov-17	Torres,Edwin	0.8333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 49368857 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 44186012
Invoice No. 55345 - 44186012

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	137,546 - DH

Chronology		
Reported	Oct 31, 2017 8:52:15 AM	Oct 31, 2017 8:52:15 AM
Started	Nov 1, 2017 12:00:00 AM	
Completed	Nov 1, 2017 7:31:00 AM	Nov 1, 2017 7:31:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PmA

CAUSE: preventive maintenance

CORRECTION: perform service pmA lube all Pivoting Points cross rotate tires completed
Parts#B329 qty 1
Oil5w30 Qts 6

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Nov-17	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Nov-17	Pierre,Hubert J	5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 01-NOV-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
10,100 - Safety Inspection	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
11,152 - Decelerometer Results Test 1	FEET	N/A	HPIERRE	Nov 1, 2017 7:27:33 AM	No	
11,154 - Decelerometer Results Test 2	FEET	N/A	HPIERRE	Nov 1, 2017 7:27:33 AM	No	
11,156 - Decelerometer Results Test 3	FEET	N/A	HPIERRE	Nov 1, 2017 7:27:33 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	Nov 1, 2017 7:27:33 AM	No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	Nov 1, 2017 7:27:33 AM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,240 - FRA Check Interior Lights	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Nov 1, 2017 7:27:33 AM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Nov 1, 2017 7:27:33 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Nov 1, 2017 7:27:33 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
40,420 - Check Hood	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Nov 1, 2017 7:27:33 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Nov 1, 2017 7:27:33 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Nov 1, 2017 7:27:33 AM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Nov 1, 2017 7:27:33 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Nov 1, 2017 7:27:33 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
44,130 - FRA Check Exhaust System	-	N/A	HPIERRE	Nov 1, 2017 7:27:33 AM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Nov 1, 2017 7:27:33 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Nov 1, 2017 7:27:33 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
60,631 - Tread Depth RF	10 32nds of an inch		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
60,632 - Tread Depth LF	10 32nds of an inch		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Nov 1, 2017 7:27:33 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
77,131 - Brake Pad Thickness LF	10 Inch		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
77,132 - Brake Pad Thickness RF	10 Inch		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
77,133 - Brake Pad Thickness LR	7 Inch		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
77,134 - Brake Pad Thickness RR	7 Inch		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
77,135 - Brake Rotor LF	1.5 Inch		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
77,136 - Brake Rotor RF	1.5 Inch		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
77,137 - Brake Rotor LR	1.6 Inch		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
77,138 - Brake Rotor RR	1.6 Inch		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Nov 1, 2017 7:27:33 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Nov 1, 2017 7:27:33 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	5.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 44186012
Invoice No. 55345 - 44186012

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	137,546 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Nov-17	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 01-NOV-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Nov 1, 2017 7:28:48 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Nov 1, 2017 7:28:48 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Nov 1, 2017 7:28:48 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Nov 1, 2017 7:28:48 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Nov 1, 2017 7:28:48 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Nov 1, 2017 7:28:48 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Nov 1, 2017 7:28:48 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Nov 1, 2017 7:28:48 AM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 44186012
Invoice No. 55345 - 44186012

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	137,546 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Nov-17	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 01-NOV-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Nov 1, 2017 7:29:07 AM	No	
20 - Miles			HPIERRE	Nov 1, 2017 7:29:07 AM	No	
30 - Kilometers			HPIERRE	Nov 1, 2017 7:29:07 AM	No	
40 - Hours			HPIERRE	Nov 1, 2017 7:29:07 AM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 44186012 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	5.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 40704099
Invoice No. 55345 - 40704099

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	133,526 - DH

Chronology		
Reported	Oct 4, 2017 4:20:12 PM	Oct 4, 2017 4:20:12 PM
Started	Oct 4, 2017 12:00:00 AM	
Completed	Oct 4, 2017 5:59:00 PM	Oct 4, 2017 5:59:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA Service

CAUSE: Service Due by Mileage

CORRECTION: Change Oil& Filter !lube all Pivoting Points, Check brakes , Clean batteries,
Parts# B329 Qty (1)
Oil 5W20 Qty (6.5) Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Oct-17	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 04-OCT-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
10,120 - FRA Check All Warning Lights and	Done		DARTHURS	Oct 4, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				5:38:16 PM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Oct 4, 2017 5:38:16 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Oct 4, 2017 5:38:16 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Oct 4, 2017 5:38:16 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Oct 4, 2017 5:38:16 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Oct 4, 2017 5:38:16 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Oct 4, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				5:38:16 PM		
20,260 - Check Stop Request System	-	NA	DARTHURS	Oct 4, 2017 5:38:16 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Oct 4, 2017 5:38:16 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Oct 4, 2017 5:38:16 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
40,420 - Check Hood	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Oct 4, 2017 5:38:16 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Oct 4, 2017 5:38:16 PM	No	
40,442 - Freeze Point	Degree	NA	DARTHURS	Oct 4, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			5:38:16 PM		
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Oct 4, 2017 5:38:16 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Oct 4, 2017 5:38:16 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Oct 4, 2017 5:38:16 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
60,615 - Air Pressure LRI	65 Pounds per		DARTHURS	Oct 4, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			5:38:16 PM		
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
60,632 - Tread Depth LF	11 32nds of an inch		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
60,635 - Tread Depth LRI	10 32nds of an inch		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
60,670 - Check Dual Mating With Square	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
70,720 - Check Engine and Transmission Mounts	-	motor mount	DARTHURS	Oct 4, 2017 5:38:16 PM	Yes	44184589
70,730 - FRA Check Starter	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
70,790 - Check All Body Mounts and Chassis	Done		DARTHURS	Oct 4, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Frame				5:38:16 PM		
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
77,131 - Brake Pad Thickness LF	3 Inch	Front pads	DARTHURS	Oct 4, 2017 5:38:16 PM	Yes	44184589
77,132 - Brake Pad Thickness RF	4 Inch		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
77,135 - Brake Rotor LF	1.558 Inch		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
77,136 - Brake Rotor RF	1.559 Inch		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
77,137 - Brake Rotor LR	1.414 Inch		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
77,138 - Brake Rotor RR	1.413 Inch		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Oct 4, 2017 5:38:16 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Oct 4, 2017 5:38:16 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 40704099
Invoice No. 55345 - 40704099

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 133,526 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Oct-17	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Oct-17	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 04-OCT-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Oct 4, 2017 5:39:11 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Oct 4, 2017 5:39:11 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Oct 4, 2017 5:39:11 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Oct 4, 2017 5:39:11 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Oct 4, 2017 5:39:11 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Oct 4, 2017 5:39:11 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Oct 4, 2017 5:39:11 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Oct 4, 2017 5:39:11 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 40704099
Invoice No. 55345 - 40704099

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	133,526 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Oct-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 04-OCT-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Oct 4, 2017 5:39:37 PM	No	
20 - Miles			DARTHURS	Oct 4, 2017 5:39:37 PM	No	
30 - Kilometers			DARTHURS	Oct 4, 2017 5:39:37 PM	No	
40 - Hours			DARTHURS	Oct 4, 2017 5:39:37 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 40704099
Invoice No. 55345 - 40704099

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	133,526 - DH

Activity Header
Activity: 40 999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 40704099 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 44184589
Invoice No. 55345 - 44184589

Client Department:
Department: 55345M
Work Order Description
PMA follow up>>>>>>Right side motor mount&Front brakes
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 133,526 - DH

Chronology		
Reported	Oct 4, 2017 5:38:16 PM	Oct 4, 2017 5:38:16 PM
Started	Oct 4, 2017 12:00:00 AM	
Completed	Oct 4, 2017 5:57:00 PM	Oct 4, 2017 5:57:00 PM
Down Time		

Work Order Notes

Line 10 Remove& Replace right Side motor mount&Remove&Replace front brakes.
Parts# BRSD1328 Qty (1)
Parts#F7UZ-6038DC Qty (1)

Activity Header
Activity: 10 014/003 MOUNTING, ENGINE
Activity Note: motor mount
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Oct-17	F7UZ-6038-DC	INSULATOR	1	52.58	52.58

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Oct-17	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	52.58
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**52.58**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 44184589
Invoice No. 55345 - 44184589

Client Department:
Department: 55345M
Work Order Description
PMA follow up>>>>>>Right side motor mount&Front brakes
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 133,526 - DH

Activity Header
Activity: 20 013/001 BRAKES & DRUMS, FRONT
Activity Note: Front pads
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Oct-17	BRSD-1328	PADS, BRAKE, DISC, FRONT	1	50.32	50.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Oct-17	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	50.32
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**50.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 44184589
Invoice No. 55345 - 44184589

Client Department:
Department: 55345M
Work Order Description
PMA follow up>>>>>>Right side motor mount&Front brakes
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 133,526 - DH

Activity Header
Activity: 30 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 01 Breakdown
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Oct-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc:
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 04-OCT-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Oct 4, 2017 5:47:48 PM	No	
20 - Miles			DARTHURS	Oct 4, 2017 5:47:48 PM	No	
30 - Kilometers			DARTHURS	Oct 4, 2017 5:47:48 PM	No	
40 - Hours			DARTHURS	Oct 4, 2017 5:47:48 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 44184589 Total	
Parts:	102.90
Labor:	0.00
Labor Hours:	2.08

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**102.90**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 43969438
Invoice No. 55345 - 43969438

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Change driver side mirror		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	133,148 - DH

Chronology		
Reported	Oct 2, 2017 12:14:19 PM	Oct 2, 2017 12:14:19 PM
Started		
Completed	Oct 3, 2017 10:29:00 AM	Oct 3, 2017 10:29:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:
Driver mirror is loose

CAUSE:
A lot of corrosion between the driver mirror mounting bracket and the screw. The screw was frozen in place

CORRECTION:
Replaced the driver side mirror assembly.

Parts under the warranty

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 02-OCT-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Oct 2, 2017 12:21:54 PM	No	
20 - Miles			EDTORRES	Oct 2, 2017 12:21:54 PM	No	
30 - Kilometers			EDTORRES	Oct 2, 2017 12:21:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			EDTORRES	Oct 2, 2017 12:21:54 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 43969438
Invoice No. 55345 - 43969438

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Change driver side mirror		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	133,148 - DH

Activity Header
Activity: 15 174 BODY, BUS
Activity Note: Changed driverside mirror
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 43969438 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 36841979
Invoice No. 55345 - 36841979

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM C		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	129,273 - DH

Chronology		
Reported	Aug 28, 2017 3:08:35 PM	Aug 28, 2017 3:08:35 PM
Started	Aug 29, 2017 12:00:00 AM	
Completed	Aug 30, 2017 10:53:00 AM	Aug 30, 2017 10:53:00 AM
Down Time		

Work Order Notes

Line 10 PM C

Perform pm c, change engine oil and filter, transmission fluid and filter, differential oil, rotate tires, torque and re torque (140 f/pound), lube front end, road test, all okay at this time.

Parts: 1 air filter # PA4075

1 transmission filter #20021

1 oil filter #B329

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Aug-17	20021	FILTER, TRANSMISSION 20021	1	14.67	14.67
29-Aug-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92
29-Aug-17	PA4075	OUT OF SERVICE DO NOT ORDER FILTER, AIR, PAPER SAME AS AF25590	1	5.18	5.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Aug-17	Rodriguez,Raul	0.8333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
10 Desc: Light Medium Duty PMI Task: First Transit Light-Medium Duty PMI Performed by: RAURODRIGUEZ Performed on: 29-AUG-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
10,100 - Safety Inspection	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
10,140 - Check Service Brakes	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
10,160 - FRA Check Instruments and Horns	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
10,170 - Check Fast Idle	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
10,180 - Check Starter Protection Circuit	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
10,190 - Check Reverse Warning System	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
11,100 - Check Parking Brake	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
11,150 - Perform Brake Test	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
11,152 - Decelerometer Results Test 1	FEET	N/A	RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
11,154 - Decelerometer Results Test 2	FEET	N/A	RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
11,156 - Decelerometer Results Test 3	FEET	N/A	RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	N/A	RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	N/A	RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
11,170 - FRA Check Door Operation	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
20,210 - Check Condition of Operator's Area	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,220 - Check Accelerator and Brake Pedals	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
20,240 - FRA Check Interior Lights	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
20,260 - Check Stop Request System	-	N/A	RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
22,110 - Check Emergency Hatches	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
22,120 - Check All Safety Equipment	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
30,310 - Check Passenger Doors	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
30,360 - Check for Physical Damage and Decals	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
30,380 - Check Exterior Compartment Doors	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
33,100 - Check Lights and Reflectors	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
40,420 - Check Hood	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,430 - Check Fan, Shroud and Radiator	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
44,130 - FRA Check Exhaust System	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
44,140 - FRA Check Intake System	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
44,180 - FRA Check for Leaks	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
44,190 - FRA Perform Battery Inspection	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
50,510 - Check Entire Steering System	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,612 - Air Pressure LF	70 Pounds per Square Inch		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
60,620 - Check Valve Stems and Caps	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
60,630 - Check and Record Tread Depth	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
60,631 - Tread Depth RF	13 32nds of an inch		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
60,632 - Tread Depth LF	13 32nds of an inch		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
60,633 - Tread Depth RRO	10 32nds of an inch		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
60,635 - Tread Depth LRI	11 32nds of an inch		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
60,636 - Tread Depth LRO	11 32nds of an inch		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
60,650 - Check Sidewall Wear	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
60,660 - Inspect for Cuts and Tears	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
60,670 - Check Dual Mating With Square	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
70,710 - Check Vibration Damper	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
70,730 - FRA Check Starter	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,760 - FRA Check Differential Breather and Fluid	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
70,770 - FRA Check Exhaust System	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
77,110 - FRA Check Fuel Tank	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
77,120 - Check Suspension Components	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
77,131 - Brake Pad Thickness LF	Inch	6mm	RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
77,132 - Brake Pad Thickness RF	Inch	6mm	RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
77,133 - Brake Pad Thickness LR	Inch	8mm	RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
77,134 - Brake Pad Thickness RR	Inch	8mm	RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
77,135 - Brake Rotor LF	Inch	39.7mm	RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
77,136 - Brake Rotor RF	Inch	39.7mm	RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
77,137 - Brake Rotor LR	Inch	35.8mm	RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
77,138 - Brake Rotor RR	Inch	35.8mm	RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
77,140 - FRA Check Brake Hoses	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
77,150 - Check King Pins	-	N/A	RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
80,810 - Completion of PMI Report	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:27 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	21.77
Labor:	0.00
Labor Hours:	0.83
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**21.77**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 36841979
Invoice No. 55345 - 36841979

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 129,273 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Aug-17	Rodriguez,Raul	2.5833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: RAURODRIGUEZ Performed on: 29-AUG-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	-	N/A	RAURODRIGUEZ	Aug 29, 2017 10:10:05 AM	No	
101,000 - FRA Change Oil Filters	Yes		RAURODRIGUEZ	Aug 29, 2017 10:10:05 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RAURODRIGUEZ	Aug 29, 2017 10:10:05 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:05 AM	No	
104,000 - Lubricate Chassis	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:05 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:05 AM	No	
107,000 - FRA Change Primary Fuel Filter	-	N/A	RAURODRIGUEZ	Aug 29, 2017 10:10:05 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:05 AM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	-	N/A	RAURODRIGUEZ	Aug 29, 2017 10:10:05 AM	No	
201,000 - Service Crankcase Breather	-	N/A	RAURODRIGUEZ	Aug 29, 2017 10:10:05 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	Yes		RAURODRIGUEZ	Aug 29, 2017 10:10:05 AM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No	N/A	RAURODRIGUEZ	Aug 29, 2017 10:10:05 AM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:05 AM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:05 AM	No	
301,000 - Check and Lubricate Door Linkages	Done		RAURODRIGUEZ	Aug 29, 2017 10:10:05 AM	No	
302,000 - Check Toe-In and Record Reading	-	N/A	RAURODRIGUEZ	Aug 29, 2017 10:10:05 AM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	N/A	RAURODRIGUEZ	Aug 29, 2017 10:10:05 AM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No	N/A	RAURODRIGUEZ	Aug 29, 2017 10:10:05 AM	No	
305,000 - FRA Change Differential Fluid	Yes		RAURODRIGUEZ	Aug 29, 2017 10:10:05 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 36841979
Invoice No. 55345 - 36841979

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 129,273 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 29-AUG-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Aug 29, 2017 10:09:44 AM	No	
20 - Miles			RAURODRIGUEZ	Aug 29, 2017 10:09:44 AM	No	
30 - Kilometers			RAURODRIGUEZ	Aug 29, 2017 10:09:44 AM	No	
40 - Hours			RAURODRIGUEZ	Aug 29, 2017 10:09:44 AM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 36841979 Total	
Parts:	21.77
Labor:	0.00
Labor Hours:	3.42
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**21.77**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 40174014
Invoice No. 55345 - 40174014

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Needs 2 front tires		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	128,276 - DH

Chronology		
Reported	Aug 24, 2017 11:15:43 PM	Aug 24, 2017 11:15:43 PM
Started	Aug 24, 2017 12:00:00 AM	
Completed	Aug 24, 2017 11:47:00 PM	Aug 24, 2017 11:47:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: needs 2 front tires

CAUSE:flat spot

CORRECTION: 2 new tires mounted and balanced
Torque wheels 140 lbs second torque 140 lbs
Part number 189752 qty 2

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Aug-17	Gaspard,Ronald	0.0333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 24-AUG-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Aug 24, 2017 11:18:57 PM	No	
20 - Miles			RGASPARD	Aug 24, 2017 11:18:57 PM	No	
30 - Kilometers			RGASPARD	Aug 24, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:18:57 PM		
40 - Hours			RGASPARD	Aug 24, 2017 11:18:57 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 40174014
Invoice No. 55345 - 40174014

Client Department:
Department: 55345M
Work Order Description
Needs 2 front tires
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 128,276 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Aug-17	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	108.09	216.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Aug-17	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	216.18
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**216.18**

Work Order Footer

Work Order 40174014 Total	
Parts:	216.18
Labor:	0.00
Labor Hours:	1.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**216.18**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 37327419
Invoice No. 55345 - 37327419

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Check front A/C		Ford E350 Champion Crusaders	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	125,143 - DH

Chronology		
Reported	Jul 26, 2017 10:19:16 AM	Jul 26, 2017 10:19:16 AM
Started	Jul 27, 2017 12:00:00 AM	
Completed	Jul 28, 2017 7:54:00 AM	Jul 28, 2017 7:54:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Front A/C not blowing cold

CAUSE:Leaky front evaporator

CORRECTION:Front evaporator replacement

Driver's complaint verified
Visual inspection performed
Front evaporator found leaky.
Front evaporator and orifice tube replaced
Vacuum done and oil added and recharge completed
Front A/C retested OK

Parts used:
One (1) evaporator#YK211
One (1) orifice tube #3411885

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 27-JUL-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Jul 27, 2017 12:13:44 PM	No	
20 - Miles			FSIMON	Jul 27, 2017 12:13:44 PM	No	
30 - Kilometers			FSIMON	Jul 27, 2017 12:13:44 PM	No	
40 - Hours			FSIMON	Jul 27, 2017 12:13:44 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 37327419
Invoice No. 55345 - 37327419

Client Department:
Department: 55345M
Work Order Description
Check front A/C
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 125,143 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Jul-17	YK211	CORE, EVAPORATOR, A/C	1	150.45	150.45
27-Jul-17	3411885	TUBE, ORIFICE, A/C, FORD	1	0.75	0.75

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Jul-17	Simon,Fritz	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	151.20
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**151.20**

Work Order Footer

Work Order 37327419 Total	
Parts:	151.20
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**151.20**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 36772075
Invoice No. 55345 - 36772075

Client Department:
Department: 55345M
Work Order Description
Pma followup needrear brake pads
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 124,554 - DH

Chronology		
Reported	Jul 20, 2017 1:42:03 PM	Jul 20, 2017 1:42:03 PM
Started	Jul 20, 2017 12:00:00 AM	
Completed	Jul 21, 2017 7:33:00 AM	Jul 21, 2017 7:33:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT: pmA follow up need rear brake pads

CAUSE: below spect

CORRECTION: replace rear brake pads
Part # Brsd 1329 qty 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jul-17	Pierre,Hubert J	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 20-JUL-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Jul 20, 2017 1:54:41 PM	No	
20 - Miles			HPIERRE	Jul 20, 2017 1:54:41 PM	No	
30 - Kilometers			HPIERRE	Jul 20, 2017 1:54:41 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			HPIERRE	Jul 20, 2017 1:54:41 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 36772075
Invoice No. 55345 - 36772075

Client Department:
Department: 55345M
Work Order Description
Pma followup needrear brake pads
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 124,554 - DH

Activity Header
Activity: 15 013 BRAKES
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Jul-17	BRSD1329	PADS, BRAKE, DISC, E450	1	44.48	44.48

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jul-17	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	44.48
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**44.48**

Work Order Footer

Work Order 36772075 Total	
Parts:	44.48
Labor:	0.00
Labor Hours:	2.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**44.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 34968339
Invoice No. 55345 - 34968339

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	124,554 - DH

Chronology		
Reported	Jul 20, 2017 8:37:49 AM	Jul 20, 2017 8:37:49 AM
Started	Jul 20, 2017 12:00:00 AM	
Completed	Jul 21, 2017 7:24:00 AM	Jul 21, 2017 7:24:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE: preventive maintenance

CORRECTION: perform service lube all pivot point cross tires complete
Part #b329 qty 1
Oil5w30 qts 6

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Jul-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jul-17	Pierre,Hubert J	6	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List						
10 Desc: Light Medium Duty PMI Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 20-JUL-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
10,100 - Safety Inspection	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
11,152 - Decelerometer Results Test 1	0 FEET	N/A	HPIERRE	Jul 20, 2017 12:18:12 PM	No	
11,154 - Decelerometer Results Test 2	FEET	N/A	HPIERRE	Jul 20, 2017 12:18:12 PM	No	
11,156 - Decelerometer Results Test 3	FEET	N/A	HPIERRE	Jul 20, 2017 12:18:12 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	Jul 20, 2017 12:18:12 PM	No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	Jul 20, 2017 12:18:12 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,240 - FRA Check Interior Lights	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Jul 20, 2017 12:18:12 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Jul 20, 2017 12:18:12 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Jul 20, 2017 12:18:12 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
40,420 - Check Hood	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Jul 20, 2017 12:18:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Jul 20, 2017 12:18:12 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Jul 20, 2017 12:18:12 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Jul 20, 2017 12:18:12 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Jul 20, 2017 12:18:12 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Jul 20, 2017 12:18:12 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Jul 20, 2017 12:18:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
60,631 - Tread Depth RF	12 32nds of an inch		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Jul 20, 2017 12:18:12 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
77,133 - Brake Pad Thickness LR	4 Inch		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
77,134 - Brake Pad Thickness RR	4 Inch	need rear brake pads	HPIERRE	Jul 20, 2017 12:18:12 PM	No	
77,135 - Brake Rotor LF	1.6 Inch		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
77,136 - Brake Rotor RF	1.6 Inch		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
77,137 - Brake Rotor LR	1.7 Inch		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
77,138 - Brake Rotor RR	1.7 Inch		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Jul 20, 2017 12:18:12 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Jul 20, 2017 12:18:12 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	6.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 34968339
Invoice No. 55345 - 34968339

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 124,554 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jul-17	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 20-JUL-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Jul 20, 2017 12:19:26 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Jul 20, 2017 12:19:26 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Jul 20, 2017 12:19:26 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Jul 20, 2017 12:19:26 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Jul 20, 2017 12:19:26 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Jul 20, 2017 12:19:26 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Jul 20, 2017 12:19:26 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Jul 20, 2017 12:19:26 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 34968339
Invoice No. 55345 - 34968339

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	124,554 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jul-17	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 20-JUL-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Jul 20, 2017 12:19:45 PM	No	
20 - Miles			HPIERRE	Jul 20, 2017 12:19:45 PM	No	
30 - Kilometers			HPIERRE	Jul 20, 2017 12:19:45 PM	No	
40 - Hours			HPIERRE	Jul 20, 2017 12:19:45 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34968339 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	6.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 34845728
Invoice No. 55345 - 34845728

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 120,504 - DH

Chronology		
Reported	Jun 16, 2017 7:09:50 AM	Jun 16, 2017 7:09:50 AM
Started	Jun 16, 2017 12:00:00 AM	
Completed	Jun 19, 2017 8:31:00 AM	Jun 19, 2017 8:31:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA

CAUSE: preventive maintenance

CORRECTION: preform service lube all pivoting points cross rotate tires completed
Part#B329 qty1
Oil5w20 Qts 6

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Jun-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jun-17	Pierre,Hubert J	6	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 19-JUN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
10,100 - Safety Inspection	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
11,152 - Decelerometer Results Test 1	FEET	N/A	HPIERRE	Jun 19, 2017 8:31:20 AM	No	
11,154 - Decelerometer Results Test 2	FEET	N/A	HPIERRE	Jun 19, 2017 8:31:20 AM	No	
11,156 - Decelerometer Results Test 3	FEET	N/A	HPIERRE	Jun 19, 2017 8:31:20 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	Jun 19, 2017 8:31:20 AM	No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	Jun 19, 2017 8:31:20 AM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,240 - FRA Check Interior Lights	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Jun 19, 2017 8:31:20 AM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Jun 19, 2017 8:31:20 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Jun 19, 2017 8:31:20 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
40,420 - Check Hood	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Jun 19, 2017 8:31:20 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Jun 19, 2017 8:31:20 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Jun 19, 2017 8:31:20 AM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Jun 19, 2017 8:31:20 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Jun 19, 2017 8:31:20 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Jun 19, 2017 8:31:20 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Jun 19, 2017 8:31:20 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
60,631 - Tread Depth RF	12 32nds of an inch		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
60,632 - Tread Depth LF	12 32nds of an inch		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
60,633 - Tread Depth RRO	10 32nds of an inch		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
60,635 - Tread Depth LRI	10 32nds of an inch		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
60,636 - Tread Depth LRO	10 32nds of an inch		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Jun 19, 2017 8:31:20 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
77,131 - Brake Pad Thickness LF	10 Inch		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
77,132 - Brake Pad Thickness RF	10 Inch		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
77,133 - Brake Pad Thickness LR	7 Inch		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
77,134 - Brake Pad Thickness RR	7 Inch		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
77,135 - Brake Rotor LF	1.6 Inch		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
77,136 - Brake Rotor RF	1.6 Inch		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
77,137 - Brake Rotor LR	1.7 Inch		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
77,138 - Brake Rotor RR	1.7 Inch		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Jun 19, 2017 8:31:20 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Jun 19, 2017 8:31:20 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	6.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 34845728
Invoice No. 55345 - 34845728

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 120,504 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jun-17	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 16-JUN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Jun 16, 2017 2:19:24 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Jun 16, 2017 2:19:24 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Jun 16, 2017 2:19:24 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Jun 16, 2017 2:19:24 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Jun 16, 2017 2:19:24 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Jun 16, 2017 2:19:24 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Jun 16, 2017 2:19:24 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Jun 16, 2017 2:19:24 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 34845728
Invoice No. 55345 - 34845728

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	120,504 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jun-17	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 16-JUN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Jun 16, 2017 2:19:52 PM	No	
20 - Miles			HPIERRE	Jun 16, 2017 2:19:52 PM	No	
30 - Kilometers			HPIERRE	Jun 16, 2017 2:19:52 PM	No	
40 - Hours			HPIERRE	Jun 16, 2017 2:19:52 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 34845728
Invoice No. 55345 - 34845728

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	120,504 - DH

Activity Header
Activity: 40 999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34845728 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	6.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34960415
Invoice No. 55345 - 34960415

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
W/C Lift inop		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	120,198 - DH

Chronology		
Reported	Jun 14, 2017 7:21:34 PM	Jun 14, 2017 7:21:34 PM
Started	Jun 14, 2017 12:00:00 AM	
Completed	Jun 15, 2017 11:07:00 PM	Jun 15, 2017 11:07:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: Lift Not Working

CAUSE: Lift Light Fuse blown.

CORRECTION: Replace Lift Light Fuse.& Tighten fuse socket.
Parts# 10 Amps fuse Qty (1)

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Jun-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 15-JUN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jun 15, 2017 11:07:24 PM	No	
20 - Miles			DARTHURS	Jun 15, 2017 11:07:24 PM	No	
30 - Kilometers			DARTHURS	Jun 15, 2017 11:07:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			DARTHURS	Jun 15, 2017 11:07:24 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34960415
Invoice No. 55345 - 34960415

Client Department:
Department: 55345M
Work Order Description
W/C Lift inop
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 120,198 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Lift not opperating replace blown fuse.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Jun-17	Arthurs,Durvin	0.25	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34960415 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34881031
Invoice No. 55345 - 34881031

Client Department:
Department: 55345M
Work Order Description
Road call lift and passenger doors stopped working.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 117,768 - DH

Chronology		
Reported	May 26, 2017 12:03:22 PM	May 26, 2017 12:03:22 PM
Started	May 26, 2017 12:00:00 AM	
Completed	May 26, 2017 12:15:31 PM	May 26, 2017 12:15:31 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT:
Driver called and stated that his passenger doors and lift stopped working.

CAUSE:
Unknown.

CORRECTION:
Changed the fuse and test drove the vehicle. Operated the lift and passenger doors and the fuse did not blow. Placed back and Service will monitor for future complaints.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 26-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	May 26, 2017 12:07:39 PM	No	
20 - Miles			EDTORRES	May 26, 2017 12:07:39 PM	No	
30 - Kilometers			EDTORRES	May 26, 2017 12:07:39 PM	No	
40 - Hours			EDTORRES	May 26, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:07:39 PM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34881031
Invoice No. 55345 - 34881031

Client Department:
Department: 55345M
Work Order Description
Road call lift and passenger doors stopped working.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 117,768 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note: Road call lift and passenger doors stopped working.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-May-17	Torres,Edwin	0.9666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34881031 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 34777786
Invoice No. 55345 - 34777786

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM B		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	116,580 - DH

Chronology		
Reported	May 18, 2017 8:37:23 AM	May 18, 2017 8:37:23 AM
Started	May 19, 2017 12:00:00 AM	
Completed	May 19, 2017 11:23:00 PM	May 19, 2017 11:23:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMB

CAUSE:service

CORRECTION:perform PMB service
Oil filter B329 qty 1
Engine oil 5w20 qty 7 qts
Air filter PA4075 qty 1

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-May-17	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 19-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
10,120 - FRA Check All Warning Lights and	Done		RGASPARD	May 19, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				9:40:06 PM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	May 19, 2017 9:40:06 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	May 19, 2017 9:40:06 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	May 19, 2017 9:40:06 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	May 19, 2017 9:40:06 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	May 19, 2017 9:40:06 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	May 19, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:40:06 PM		
20,260 - Check Stop Request System	-	na	RGASPARD	May 19, 2017 9:40:06 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	May 19, 2017 9:40:06 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	May 19, 2017 9:40:06 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
40,420 - Check Hood	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	May 19, 2017 9:40:06 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	May 19, 2017 9:40:06 PM	No	
40,442 - Freeze Point	Degree	na	RGASPARD	May 19, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			9:40:06 PM		
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	May 19, 2017 9:40:06 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	May 19, 2017 9:40:06 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	May 19, 2017 9:40:06 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	May 19, 2017 9:40:06 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	May 19, 2017 9:40:06 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	May 19, 2017 9:40:06 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	May 19, 2017 9:40:06 PM	No	
60,615 - Air Pressure LRI	65 Pounds per		RGASPARD	May 19, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			9:40:06 PM		
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	May 19, 2017 9:40:06 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		RGASPARD	May 19, 2017 9:40:06 PM	No	
60,632 - Tread Depth LF	11 32nds of an inch		RGASPARD	May 19, 2017 9:40:06 PM	No	
60,633 - Tread Depth RRO	10 32nds of an inch		RGASPARD	May 19, 2017 9:40:06 PM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		RGASPARD	May 19, 2017 9:40:06 PM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		RGASPARD	May 19, 2017 9:40:06 PM	No	
60,636 - Tread Depth LRO	10 32nds of an inch		RGASPARD	May 19, 2017 9:40:06 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
70,790 - Check All Body Mounts and Chassis	Done		RGASPARD	May 19, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Frame				9:40:06 PM		
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		RGASPARD	May 19, 2017 9:40:06 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		RGASPARD	May 19, 2017 9:40:06 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		RGASPARD	May 19, 2017 9:40:06 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		RGASPARD	May 19, 2017 9:40:06 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	May 19, 2017 9:40:06 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	May 19, 2017 9:40:06 PM	No	
77,137 - Brake Rotor LR	32 Inch		RGASPARD	May 19, 2017 9:40:06 PM	No	
77,138 - Brake Rotor RR	32 Inch		RGASPARD	May 19, 2017 9:40:06 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	May 19, 2017 9:40:06 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	May 19, 2017 9:40:06 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 34777786
Invoice No. 55345 - 34777786

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 116,580 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-May-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92
19-May-17	PA4075	OUT OF SERVICE DO NOT ORDER FILTER, AIR, PAPER SAME AS AF25590	1	5.18	5.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-May-17	Gaspard,Ronald	1.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: RGASPARD Performed on: 19-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	May 19, 2017 9:41:21 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	May 19, 2017 9:41:21 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	May 19, 2017 9:41:21 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	May 19, 2017 9:41:21 PM	No	
104,000 - Lubricate Chassis	Done		RGASPARD	May 19, 2017 9:41:21 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	May 19, 2017 9:41:21 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	May 19, 2017 9:41:21 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	May 19, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:41:21 PM		
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	May 19, 2017 9:41:21 PM	No	
201,000 - Service Crankcase Breather	Done		RGASPARD	May 19, 2017 9:41:21 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	May 19, 2017 9:41:21 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	May 19, 2017 9:41:21 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	May 19, 2017 9:41:21 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	1.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 34777786
Invoice No. 55345 - 34777786

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM B		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	116,580 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-May-17	Gaspard,Ronald	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 19-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	May 19, 2017 9:41:49 PM	No	
20 - Miles			RGASPARD	May 19, 2017 9:41:49 PM	No	
30 - Kilometers			RGASPARD	May 19, 2017 9:41:49 PM	No	
40 - Hours			RGASPARD	May 19, 2017 9:41:49 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34777786 Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	2.63

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**7.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34822287
Invoice No. 55345 - 34822287

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Worn wiper blade		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	115,388 - DH

Chronology		
Reported	May 12, 2017 9:58:07 AM	May 12, 2017 9:58:07 AM
Started	May 12, 2017 12:00:00 AM	
Completed	May 15, 2017 6:56:00 AM	May 15, 2017 6:56:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT: Wiper blades are worn

CAUSE: normal wear

CORRECTION: Remove the worn wiper blades and Replaced with new ones

PARTS: Two wiper blades #40520

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 12-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	May 12, 2017 10:10:57 AM	No	
20 - Miles			EDTORRES	May 12, 2017 10:10:57 AM	No	
30 - Kilometers			EDTORRES	May 12, 2017 10:10:57 AM	No	
40 - Hours			EDTORRES	May 12, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:10:57 AM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34822287
Invoice No. 55345 - 34822287

Client Department:
Department: 55345M
Work Order Description
Worn wiper blade
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 115,388 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note: Worn wiper blade
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-May-17	40520	BLADE, WIPER, WINDSHIELD, 20"	2	4.35	8.7

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-May-17	Torres,Edwin	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	8.70
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.70**

Work Order Footer

Work Order 34822287 Total	
Parts:	8.70
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34816469
Invoice No. 55345 - 34816469

Client Department:
Department: 55345M
Work Order Description
WIPER ARM CLIP REPLACEMENT
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 115,039 - DH

Chronology		
Reported	May 9, 2017 9:23:00 AM	May 9, 2017 9:23:00 AM
Started	May 9, 2017 12:00:00 AM	
Completed	May 10, 2017 4:22:00 AM	May 10, 2017 4:22:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT: WIPER ARM CLIP REPLACEMENT

CAUSE: preventive maintenance

CORRECTION: REMOVED & REPLACED WIPER ARM CLIP

PART: 1 W/ARM CLIP # E3TZ-17531-A

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-May-17	E3TZ-17531-A	CLIP, ARM, WPER	1	10.51	10.51

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 10-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	May 10, 2017 4:21:51 AM	No	
20 - Miles			RAURODRIGUEZ	May 10, 2017 4:21:51 AM	No	
30 - Kilometers			RAURODRIGUEZ	May 10, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				4:21:51 AM		
40 - Hours			RAURODRIGUEZ	May 10, 2017 4:21:51 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	10.51
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**10.51**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34816469
Invoice No. 55345 - 34816469

Client Department:
Department: 55345M
Work Order Description
WIPER ARM CLIP REPLACEMENT
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 115,039 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note: WIPER ARM CLIP REPLACED
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-May-17	Rodriguez,Raul	0.45	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34816469 Total	
Parts:	10.51
Labor:	0.00
Labor Hours:	0.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**10.51**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34774549
Invoice No. 55345 - 34774549

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
W/C LIFT INSPECTION		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	112,479 - DH

Chronology		
Reported	Apr 20, 2017 12:12:00 PM	Apr 20, 2017 12:12:00 PM
Started	Apr 20, 2017 12:00:00 AM	
Completed	Apr 20, 2017 10:34:00 PM	Apr 20, 2017 10:34:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: W/C lift inspection

CAUSE:preventive maintenance

CORRECTION: W/C pmi completion
W/C lift inspection completed no part used

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Apr-17	Gaspard,Ronald	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 20-APR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Apr 20, 2017 9:10:09 PM	No	
20 - Miles			RGASPARD	Apr 20, 2017 9:10:09 PM	No	
30 - Kilometers			RGASPARD	Apr 20, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:10:09 PM		
40 - Hours			RGASPARD	Apr 20, 2017 9:10:09 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 34726772
Invoice No. 55345 - 34726772

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 112,479 - DH

Chronology		
Reported	Apr 20, 2017 10:51:41 AM	Apr 20, 2017 10:51:41 AM
Started	Apr 20, 2017 12:00:00 AM	
Completed	Apr 20, 2017 10:34:00 PM	Apr 20, 2017 10:34:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA

CAUSE:service

CORRECTION:perform pmA service
Oil filter B329 qty 1
Engine oil 5w20 qty 7 qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Apr-17	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 20-APR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Apr 20, 2017 9:03:45 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Apr 20, 2017 9:03:45 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Apr 20, 2017 9:03:45 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Apr 20, 2017 9:03:45 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Apr 20, 2017 9:03:45 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	na	RGASPARD	Apr 20, 2017 9:03:45 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Apr 20, 2017 9:03:45 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Apr 20, 2017 9:03:45 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
40,420 - Check Hood	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Apr 20, 2017 9:03:45 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Apr 20, 2017 9:03:45 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Apr 20, 2017 9:03:45 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Apr 20, 2017 9:03:45 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Apr 20, 2017 9:03:45 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Apr 20, 2017 9:03:45 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Apr 20, 2017 9:03:45 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
60,632 - Tread Depth LF	11 32nds of an inch		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
60,633 - Tread Depth RRO	10 32nds of an inch		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
60,634 - Tread Depth RRI	11 32nds of an inch		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
60,636 - Tread Depth LRO	12 32nds of an inch		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
77,137 - Brake Rotor LR	32 Inch		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
77,138 - Brake Rotor RR	32 Inch		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Apr 20, 2017 9:03:45 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Apr 20, 2017 9:03:45 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34774549
Invoice No. 55345 - 34774549

Client Department:
Department: 55345M
Work Order Description
W/C LIFT INSPECTION
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 112,479 - DH

Activity Header
Activity: 15 055/023 LIFT, WHEELCHAIR, PASSENGER
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Apr-17	Gaspard,Ronald	0.45	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

15 Desc:
Task: Braun Wheelchair Lift Inspection Performed by: RGASPARD Performed on: 20-APR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Record Lift Model in Notes	Done	NCL954FIB3454HB-2	RGASPARD	Apr 20, 2017 9:15:01 PM	No	
200 - Record Serial # in Notes	Done	GA-01145	RGASPARD	Apr 20, 2017 9:15:01 PM	No	
300 - Cycle Count	5728 Cycles		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
10,000 - A - GENERAL INSPECTION	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
10,100 - Lift Battery, Circuit Breaker & Cable	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
10,200 - Lift Ground & Secondary Ground	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
10,300 - Vehicle Interlock Power	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
10,400 - Vehicle Interlock Prohits Vehicle Movement	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
10,500 - Lift Door Condition	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
10,600 - Hand Pendant Codition/Function	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,700 - Inspect Mounting Components	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
20,000 - B - CYCLE CHECK	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
20,100 - General Operation Throug Comple Cycle	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
20,200 - Main, Handrail, OB & IB Bumper Adjustments	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
20,300 - Floor Level Adjustment	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
20,400 - Platform Angle Adjustment	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
20,500 - Outer Barrier Interlock	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
20,600 - Inner Barrier Interlock	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
20,700 - Threshold Warning Interlock	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
20,800 - 50 Pound Fold Interlock	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
20,900 - Platform Lights	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
21,000 - Anti-Skid	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
21,100 - Operation & Warning Decals	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
21,200 - Back Pump Handdle Location	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
21,300 - Manual Override/Back-up System Function	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
30,000 - C - MECHANICAL COMPONENTS	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
30,100 - Base Plate, Tower, Arm & Platform Welds	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
30,200 - Outer Barrier Pins, Gas Springs & Fasteners	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
30,300 - Inner Barrier Pins, Gas Springs & Fasteners	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
30,400 - Pivot Pin Fasteners	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
30,500 - Pivot Pins & Bushing Condition	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
30,600 - Handrails	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
30,700 - Lift-Tite System	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
40,000 - D - HYDRAULIC COMPONENT CHECKS	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
40,100 - Leaks	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
40,200 - Hoses & Harness Routing/Condition (pump,parallel-vertical arms,platform)	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,300 - Remove Pump Cover & Check Fluid Level	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
40,400 - Fluid Condition	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
40,500 - LiftPump Motor Cables/Connections	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	
40,600 - Lift Pump Harnesses/Fuses/Electrical Components	Done		RGASPARD	Apr 20, 2017 9:15:01 PM	No	

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34774549 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 34726772
Invoice No. 55345 - 34726772

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 112,479 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Apr-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Apr-17	Gaspard,Ronald	1.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 20-APR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Apr 20, 2017 9:04:29 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Apr 20, 2017 9:04:29 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Apr 20, 2017 9:04:29 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Apr 20, 2017 9:04:29 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Apr 20, 2017 9:04:29 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Apr 20, 2017 9:04:29 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Apr 20, 2017 9:04:29 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Apr 20, 2017 9:04:29 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.92
	Labor:	0.00
	Labor Hours:	1.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 34726772
Invoice No. 55345 - 34726772

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	112,479 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Apr-17	Gaspard,Ronald	0.1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 20-APR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Apr 20, 2017 9:04:52 PM	No	
20 - Miles			RGASPARD	Apr 20, 2017 9:04:52 PM	No	
30 - Kilometers			RGASPARD	Apr 20, 2017 9:04:52 PM	No	
40 - Hours			RGASPARD	Apr 20, 2017 9:04:52 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34726772 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.68

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34755774
Invoice No. 55345 - 34755774

Client Department:
Department: 55345M
Work Order Description
REPLACE WIPER BLADES
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 111,488 - DH

Chronology		
Reported	Apr 12, 2017 7:46:00 PM	Apr 12, 2017 7:46:00 PM
Started	Apr 12, 2017 12:00:00 AM	
Completed	Apr 12, 2017 7:54:00 PM	Apr 12, 2017 7:54:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: WINDSHIELD WIPERS NOT PERFORM PROPERLY

CAUSE:NORMAL USEAGE

CORRECTION: REPLACE WIPER BLADES

PART#3120 QTY 2

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Apr-17	Owens,Arthur	0.3	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 12-APR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Apr 12, 2017 7:51:57 PM	No	
20 - Miles			AOWENS	Apr 12, 2017 7:51:57 PM	No	
30 - Kilometers			AOWENS	Apr 12, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				7:51:57 PM		
40 - Hours			AOWENS	Apr 12, 2017 7:51:57 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34755774
Invoice No. 55345 - 34755774

Client Department:
Department: 55345M
Work Order Description
REPLACE WIPER BLADES
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 111,488 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: REPLACE WIPER BLADES
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Apr-17	3120	BLADE, WIPER, WINDSHIELD, 20"	2	3.47	6.94

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Apr-17	Owens,Arthur	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	6.94
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**6.94**

Work Order Footer

Work Order 34755774 Total	
Parts:	6.94
Labor:	0.00
Labor Hours:	0.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**6.94**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34726756
Invoice No. 55345 - 34726756

Client Department:
Department: 55345M
Work Order Description
PMA >>>>Follow Up>>>>>>Wiper Blades
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 108,793 - DH

Chronology		
Reported	Mar 24, 2017 6:21:38 PM	Mar 24, 2017 6:21:38 PM
Started	Mar 24, 2017 12:00:00 AM	
Completed	Mar 24, 2017 6:41:00 PM	Mar 24, 2017 6:41:00 PM
Down Time		

Work Order Notes

Line 10 Remove&Replace Wiper Blades
Parts#3120 Qty (2)

Activity Header
Activity: 10 002/035 WIPER & WASHER, WINDSHIELD
Activity Note: wiper blade torn
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Mar-17	3120	BLADE, WIPER, WINDSHIELD, 20"	2	3.47	6.94

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Mar-17	Arthurs,Durvin	0.25	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	6.94
Labor:	0.00
Labor Hours:	0.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**6.94**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34726756
Invoice No. 55345 - 34726756

Client Department:
Department: 55345M
Work Order Description
PMA >>>>Follow Up>>>>>>Wiper Blades
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 108,793 - DH

Activity Header
Activity: 20 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 01 Breakdown
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Mar-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 24-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Mar 24, 2017 6:31:23 PM	No	
20 - Miles			DARTHURS	Mar 24, 2017 6:31:23 PM	No	
30 - Kilometers			DARTHURS	Mar 24, 2017 6:31:23 PM	No	
40 - Hours			DARTHURS	Mar 24, 2017 6:31:23 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34726756 Total	
Parts:	6.94
Labor:	0.00
Labor Hours:	0.33

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**6.94**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 34607985
Invoice No. 55345 - 34607985

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	108,793 - DH

Chronology		
Reported	Mar 24, 2017 1:29:37 PM	Mar 24, 2017 1:29:37 PM
Started	Mar 24, 2017 12:00:00 AM	
Completed	Mar 24, 2017 6:40:00 PM	Mar 24, 2017 6:40:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA Service

CAUSE: Service due by Mileage

CORRECTION: Change Oil & Filter Lube All Pivoting Points Check brakes Clean batteries
Parts# B329 Qty (1)
Oil 5W20 Qty (6.5) Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Mar-17	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 24-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
11,130 - FRA Check Wiper and Washer Operation	-	wiper blade torn	DARTHURS	Mar 24, 2017 6:21:38 PM	Yes	34726756
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Mar 24, 2017 6:21:38 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Mar 24, 2017 6:21:38 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
20,260 - Check Stop Request System	-	NA	DARTHURS	Mar 24, 2017 6:21:38 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Mar 24, 2017 6:21:38 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Mar 24, 2017 6:21:38 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
40,420 - Check Hood	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Mar 24, 2017 6:21:38 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Mar 24, 2017 6:21:38 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Mar 24, 2017 6:21:38 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Mar 24, 2017 6:21:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Mar 24, 2017 6:21:38 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,631 - Tread Depth RF	13 32nds of an inch		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
60,632 - Tread Depth LF	13 32nds of an inch		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
60,633 - Tread Depth RRO	12 32nds of an inch		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
60,634 - Tread Depth RRI	13 32nds of an inch		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
60,635 - Tread Depth LRI	13 32nds of an inch		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
60,636 - Tread Depth LRO	13 32nds of an inch		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Mar 24, 2017 6:21:38 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
77,135 - Brake Rotor LF	1.568 Inch		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
77,136 - Brake Rotor RF	1.567 Inch		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
77,137 - Brake Rotor LR	1.411 Inch		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
77,138 - Brake Rotor RR	1.412 Inch		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Mar 24, 2017 6:21:38 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Mar 24, 2017 6:21:38 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 34607985
Invoice No. 55345 - 34607985

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 108,793 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Mar-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Mar-17	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 24-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Mar 24, 2017 6:22:21 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Mar 24, 2017 6:22:21 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Mar 24, 2017 6:22:21 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Mar 24, 2017 6:22:21 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Mar 24, 2017 6:22:21 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Mar 24, 2017 6:22:21 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Mar 24, 2017 6:22:21 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Mar 24, 2017 6:22:21 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 34607985
Invoice No. 55345 - 34607985

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 108,793 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Mar-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 24-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Mar 24, 2017 6:22:48 PM	No	
20 - Miles			DARTHURS	Mar 24, 2017 6:22:48 PM	No	
30 - Kilometers			DARTHURS	Mar 24, 2017 6:22:48 PM	No	
40 - Hours			DARTHURS	Mar 24, 2017 6:22:48 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34607985 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34726188
Invoice No. 55345 - 34726188

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Front A/C not blowing cold		Ford E350 Champion Crusaders	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	108,434 - DH

Chronology		
Reported	Mar 24, 2017 12:25:20 PM	Mar 24, 2017 12:25:20 PM
Started	Mar 24, 2017 12:00:00 AM	
Completed	Mar 24, 2017 2:13:00 PM	Mar 24, 2017 2:13:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Front A/C not blowing cold

CAUSE:Leaky front evaporator and heater hose

CORRECTION: Front evaporator and heater replacement

Complaint verified
Front evaporator replaced
Vacuum and leak test done oil added and recharge completed.
Front AC retested OK.
Heater hose replaced

Parts used
One (1) Evaporator #YK 211
One (1) Orifice tube #YG380
One (1) heater hose(not all assembly)KT160

.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 24-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Mar 24, 2017 12:42:20 PM	No	
20 - Miles			FSIMON	Mar 24, 2017 12:42:20 PM	No	
30 - Kilometers			FSIMON	Mar 24, 2017 12:42:20 PM	No	
40 - Hours			FSIMON	Mar 24, 2017 12:42:20 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34726188
Invoice No. 55345 - 34726188

Client Department:
Department: 55345M
Work Order Description
Front A/C not blowing cold
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 108,434 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Mar-17	YG380	TUBE, ORIFICE, A/C, E450, BLACK	1	4.26	4.26
24-Mar-17	BC2Z-18472-CA	TUBE, HEATER, WATER	1	23.28	23.28
24-Mar-17	YK211	CORE, EVAPORATOR, A/C	1	150.45	150.45

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Mar-17	Simon,Fritz	3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	177.99
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**177.99**

Work Order Footer

Work Order 34726188 Total	
Parts:	177.99
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**177.99**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34661695
Invoice No. 55345 - 34661695

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Front tire		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	106,699 - DH

Chronology		
Reported	Mar 12, 2017 7:51:05 PM	Mar 12, 2017 7:51:05 PM
Started	Mar 12, 2017 12:00:00 AM	
Completed	Mar 12, 2017 7:56:00 PM	Mar 12, 2017 7:56:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: Front Tire

CAUSE: Tire Worn

CORRECTION: Mount& Balance Front Tire
Parts # 189752 Qty(2)

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Mar-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 12-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Mar 12, 2017 7:52:30 PM	No	
20 - Miles			DARTHURS	Mar 12, 2017 7:52:30 PM	No	
30 - Kilometers			DARTHURS	Mar 12, 2017 7:52:30 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			DARTHURS	Mar 12, 2017 7:52:30 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34661695
Invoice No. 55345 - 34661695

Client Department:
Department: 55345M
Work Order Description
Front tire
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 106,699 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Two Front tire
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Mar-17	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	99.72	199.44

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Mar-17	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	199.44
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**199.44**

Work Order Footer

Work Order 34661695 Total	
Parts:	199.44
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**199.44**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 33108606
Invoice No. 55345 - 33108606

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM C		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	104,277 - DH

Chronology		
Reported	Feb 21, 2017 11:12:32 AM	Feb 21, 2017 11:12:32 AM
Started	Feb 21, 2017 12:00:00 AM	
Completed	Feb 21, 2017 9:44:00 PM	Feb 21, 2017 9:44:00 PM
Down Time		

Work Order Notes

Line 10 Perform PMC Service , Change oil& Filter Lube all Pivoting Points, clean batteries, drain Transmission fluid , Replace filter &Refill /Drain& Fill Differential fluid,
Parts#B329 Qty (1)
Parts#20021 Qty (1)
Oil 5W20 Qty (6.5) Qts
Gear Oil 80W20 Qty (3)Qts,

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Feb-17	Arthurs,Durvin	3	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 21-FEB-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Feb 21, 2017 9:11:16 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Feb 21, 2017 9:11:16 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
20,260 - Check Stop Request System	-	NA	DARTHURS	Feb 21, 2017 9:11:16 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Feb 21, 2017 9:11:16 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Feb 21, 2017 9:11:16 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
40,420 - Check Hood	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Feb 21, 2017 9:11:16 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Feb 21, 2017 9:11:16 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Feb 21, 2017 9:11:16 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Feb 21, 2017 9:11:16 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Feb 21, 2017 9:11:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Feb 21, 2017 9:11:16 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,631 - Tread Depth RF	6 32nds of an inch		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
60,632 - Tread Depth LF	6 32nds of an inch		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
60,633 - Tread Depth RRO	2 32nds of an inch		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
60,634 - Tread Depth RRI	2 32nds of an inch		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
60,635 - Tread Depth LRI	2 32nds of an inch	Rear Tires	DARTHURS	Feb 21, 2017 9:11:16 PM	Yes	34607969
60,636 - Tread Depth LRO	2 32nds of an inch		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Feb 21, 2017 9:11:16 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
77,133 - Brake Pad Thickness LR	3 Inch		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
77,134 - Brake Pad Thickness RR	4 Inch	Rear Brakes	DARTHURS	Feb 21, 2017 9:11:16 PM	Yes	34607969
77,135 - Brake Rotor LF	1.567 Inch		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
77,136 - Brake Rotor RF	1.565 Inch		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
77,137 - Brake Rotor LR	1.409 Inch		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
77,138 - Brake Rotor RR	1.41 Inch		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Feb 21, 2017 9:11:16 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Feb 21, 2017 9:11:16 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 34607969
Invoice No. 55345 - 34607969

Client Department:
Department: 55345M
Work Order Description
PMA Follow up>>>>>> RearTire& Rear Brakes
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 104,277 - DH

Chronology		
Reported	Feb 21, 2017 9:11:16 PM	Feb 21, 2017 9:11:16 PM
Started	Feb 21, 2017 12:00:00 AM	
Completed	Feb 21, 2017 9:44:00 PM	Feb 21, 2017 9:44:00 PM
Down Time		

Work Order Notes

Line 10 Mount&Balance Rear tire/Remove& Replace Rear Brakes,
Parts# 192659 Qty (4)
Parts# BRSD 1329 Qty (1)

Activity Header
Activity: 10 013/002 REAR BRAKES & DRUMS
Activity Note: Rear Brakes
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Feb-17	BRSD1329	PADS, BRAKE, DISC, E450	1	44.48	44.48

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Feb-17	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	44.48
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**44.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 33108606
Invoice No. 55345 - 33108606

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 104,277 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Feb-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92
21-Feb-17	20021	FILTER, TRANSMISSION 20021	1	16.94	16.94
21-Feb-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Feb-17	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: DARTHURS Performed on: 21-FEB-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Feb 21, 2017 9:13:05 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Feb 21, 2017 9:13:05 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Feb 21, 2017 9:13:05 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Feb 21, 2017 9:13:05 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Feb 21, 2017 9:13:05 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Feb 21, 2017 9:13:05 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	NA	DARTHURS	Feb 21, 2017 9:13:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Feb 21, 2017 9:13:05 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	Feb 21, 2017 9:13:05 PM	No	
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Feb 21, 2017 9:13:05 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		DARTHURS	Feb 21, 2017 9:13:05 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Feb 21, 2017 9:13:05 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Feb 21, 2017 9:13:05 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		DARTHURS	Feb 21, 2017 9:13:05 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		DARTHURS	Feb 21, 2017 9:13:05 PM	No	
302,000 - Check Toe-In and Record Reading	-	NA	DARTHURS	Feb 21, 2017 9:13:05 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	NA	DARTHURS	Feb 21, 2017 9:13:05 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		DARTHURS	Feb 21, 2017 9:13:05 PM	No	
305,000 - FRA Change Differential Fluid	Yes		DARTHURS	Feb 21, 2017 9:13:05 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	20.78
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**20.78**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 34607969
Invoice No. 55345 - 34607969

Client Department:
Department: 55345M
Work Order Description
PMA Follow up>>>>>> RearTire& Rear Brakes
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 104,277 - DH

Activity Header
Activity: 20 017 TIRES, TUBES, LINERS & VALVES
Activity Note: Rear Tires
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Feb-17	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	4	111.19	444.76

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Feb-17	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	444.76
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**444.76**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 33108606
Invoice No. 55345 - 33108606

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM C		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	104,277 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Feb-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 21-FEB-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Feb 21, 2017 9:13:28 PM	No	
20 - Miles			DARTHURS	Feb 21, 2017 9:13:28 PM	No	
30 - Kilometers			DARTHURS	Feb 21, 2017 9:13:28 PM	No	
40 - Hours			DARTHURS	Feb 21, 2017 9:13:28 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 33108606 Total	
Parts:	20.78
Labor:	0.00
Labor Hours:	3.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**20.78**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 34607969
Invoice No. 55345 - 34607969

Client Department:
Department: 55345M
Work Order Description
PMA Follow up>>>>>> RearTire& Rear Brakes
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 104,277 - DH

Activity Header
Activity: 30 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 01 Breakdown
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Feb-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc:
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 21-FEB-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Feb 21, 2017 9:28:06 PM	No	
20 - Miles			DARTHURS	Feb 21, 2017 9:28:06 PM	No	
30 - Kilometers			DARTHURS	Feb 21, 2017 9:28:06 PM	No	
40 - Hours			DARTHURS	Feb 21, 2017 9:28:06 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34607969 Total	
Parts:	489.24
Labor:	0.00
Labor Hours:	3.58

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**489.24**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34258279
Invoice No. 55345 - 34258279

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
REPLACE WHEEL CHAIR BAG		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	103,676 - DH

Chronology		
Reported	Feb 16, 2017 9:45:00 PM	Feb 16, 2017 9:45:00 PM
Started	Feb 16, 2017 12:00:00 AM	
Completed	Feb 16, 2017 9:55:00 PM	Feb 16, 2017 9:55:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: WHEEL CHAIR BAG CAN NOT HOLD TIE DOWNS

CAUSE:WHEEL CHAIR BAG IS TORN

CORRECTION: REPLACE WHEEL CHAIR BAG

PART: WARRANTY QTY 1

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Feb-17	Owens,Arthur	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 16-FEB-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Feb 16, 2017 9:55:00 PM	No	
20 - Miles			AOWENS	Feb 16, 2017 9:55:00 PM	No	
30 - Kilometers			AOWENS	Feb 16, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:55:00 PM		
40 - Hours			AOWENS	Feb 16, 2017 9:55:00 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34258279
Invoice No. 55345 - 34258279

Client Department:
Department: 55345M
Work Order Description
REPLACE WHEEL CHAIR BAG
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 103,676 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: REPLACE WHEEL CHAIR BAG
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Feb-17	Owens,Arthur	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34258279 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 30297968
Invoice No. 55345 - 30297968

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	100,262 - DH

Chronology		
Reported	Jan 25, 2017 12:14:33 PM	Jan 25, 2017 12:14:33 PM
Started	Jan 25, 2017 12:00:00 AM	
Completed	Jan 25, 2017 11:48:00 PM	Jan 25, 2017 11:48:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:Service

CORRECTION:perform pmA service
Oil filter B329 qty 1
Engine oil 5w20 qty 7 qts
Air filter PA 4075 qty 1

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Jan-17	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 25-JAN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
10,120 - FRA Check All Warning Lights and	Done		RGASPARD	Jan 25, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				11:28:07 PM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Jan 25, 2017 11:28:07 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Jan 25, 2017 11:28:07 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Jan 25, 2017 11:28:07 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Jan 25, 2017 11:28:07 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails	Done		RGASPARD	Jan 25, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
and Floor Covering				11:28:07 PM		
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Jan 25, 2017 11:28:07 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
40,420 - Check Hood	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Jan 25, 2017 11:28:07 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Jan 25, 2017 11:28:07 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Jan 25, 2017 11:28:07 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Jan 25, 2017 11:28:07 PM	No	
40,461 - Refractometer Reading	Degree	na	RGASPARD	Jan 25, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			11:28:07 PM		
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Jan 25, 2017 11:28:07 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Jan 25, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:28:07 PM		
60,631 - Tread Depth RF	9 32nds of an inch		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
60,632 - Tread Depth LF	4 32nds of an inch	needs left front tire	RGASPARD	Jan 25, 2017 11:28:07 PM	Yes	33108209
60,633 - Tread Depth RRO	5 32nds of an inch		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
60,635 - Tread Depth LRI	5 32nds of an inch		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
60,636 - Tread Depth LRO	5 32nds of an inch		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Jan 25, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:28:07 PM		
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
77,131 - Brake Pad Thickness LF	3 Inch	needs front brakes job	RGASPARD	Jan 25, 2017 11:28:07 PM	Yes	33108209
77,132 - Brake Pad Thickness RF	3 Inch		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
77,137 - Brake Rotor LR	32 Inch		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
77,138 - Brake Rotor RR	32 Inch		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Jan 25, 2017 11:28:07 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Jan 25, 2017 11:28:07 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 30297968
Invoice No. 55345 - 30297968

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	100,262 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Jan-17	PA4075	OUT OF SERVICE DO NOT ORDER FILTER, AIR, PAPER SAME AS AF25590	1	5.18	5.18
25-Jan-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Jan-17	Gaspard,Ronald	1.1333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 25-JAN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jan 25, 2017 11:28:58 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jan 25, 2017 11:28:58 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jan 25, 2017 11:28:58 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jan 25, 2017 11:28:58 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Jan 25, 2017 11:28:58 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jan 25, 2017 11:28:58 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Jan 25, 2017 11:28:58 PM	No	
108,000 - Lube all pivoting	Done		RGASPARD	Jan 25, 2017 11:28:58	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Mechanisms				PM		

Activity Sub Total

Activity 20 Sub Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	1.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 30297968
Invoice No. 55345 - 30297968

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	100,262 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Jan-17	Gaspard,Ronald	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 25-JAN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jan 25, 2017 11:29:26 PM	No	
20 - Miles			RGASPARD	Jan 25, 2017 11:29:26 PM	No	
30 - Kilometers			RGASPARD	Jan 25, 2017 11:29:26 PM	No	
40 - Hours			RGASPARD	Jan 25, 2017 11:29:26 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 30297968 Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	2.72

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**7.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 33108209
Invoice No. 55345 - 33108209

Client Department:
Department: 55345M
Work Order Description
Followup---------> needs front brakes job and 1 left front tire
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 100,262 - DH

Chronology		
Reported	Jan 25, 2017 11:28:07 PM	Jan 25, 2017 11:28:07 PM
Started	Jan 25, 2017 12:00:00 AM	
Completed	Jan 25, 2017 11:47:00 PM	Jan 25, 2017 11:47:00 PM
Down Time		

Work Order Notes

Line 10 Needs front brakes job and left front tire
Normal wear
Replaced front brake pads lubed guide pins
Parts number BRSD1328
Replaced Left front tire
Part number 050017 qty 1
First torque 140 lbs test drive second torque 140 lbs

Activity Header
Activity: 10 017 TIRES, TUBES, LINERS & VALVES
Activity Note: needs left front tire
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Jan-17	050017	OUT OF SERVICE TIRE, LT225/75R16, KRO5, KENDA	1	81.63	81.63

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Jan-17	Gaspard,Ronald	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	81.63
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**81.63**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 33108209
Invoice No. 55345 - 33108209

Client Department:
Department: 55345M
Work Order Description
Followup---------> needs front brakes job and 1 left front tire
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 100,262 - DH

Activity Header
Activity: 20 013/001 BRAKES & DRUMS, FRONT
Activity Note: needs front brakes job
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Jan-17	BRSD-1328	PADS, BRAKE, DISC, FRONT	1	50.32	50.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Jan-17	Gaspard,Ronald	1.1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	50.32
Labor:	0.00
Labor Hours:	1.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**50.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 33108209
Invoice No. 55345 - 33108209

Client Department:
Department: 55345M
Work Order Description
Followup---------> needs front brakes job and 1 left front tire
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 100,262 - DH

Activity Header
Activity: 30 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Jan-17	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc:
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 25-JAN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jan 25, 2017 11:38:31 PM	No	
20 - Miles			RGASPARD	Jan 25, 2017 11:38:31 PM	No	
30 - Kilometers			RGASPARD	Jan 25, 2017 11:38:31 PM	No	
40 - Hours			RGASPARD	Jan 25, 2017 11:38:31 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 33108209 Total	
Parts:	131.95
Labor:	0.00
Labor Hours:	1.67

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**131.95**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 33095179
Invoice No. 55345 - 33095179

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Passenger side Headlight		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	100,262 - DH

Chronology		
Reported	Jan 25, 2017 12:43:33 PM	Jan 25, 2017 12:43:33 PM
Started	Jan 25, 2017 12:00:00 AM	
Completed	Jan 25, 2017 1:43:00 PM	Jan 25, 2017 1:43:00 PM
Down Time		

Work Order Notes

Line 10 Headlight P

COMPLAINT:
Passenger side headlight is out

CAUSE:
Normal wear

CORRECTION:
Replaced passenger side headlight bulb.

PARTS:
83982 headlight bulb qty 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 25-JAN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Jan 25, 2017 12:45:34 PM	No	
20 - Miles			EDTORRES	Jan 25, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:45:34 PM		
30 - Kilometers			EDTORRES	Jan 25, 2017 12:45:34 PM	No	
40 - Hours			EDTORRES	Jan 25, 2017 12:45:34 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 33095179
Invoice No. 55345 - 33095179

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Passenger side Headlight		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	100,262 - DH

Activity Header
Activity: 15 034 LIGHTING SYSTEM
Activity Note: Passenger side Headlight
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Jan-17	83982	BULB, HALOGEN, 9008	1	9.64	9.64

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Jan-17	Torres,Edwin	0.4833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	9.64
Labor:	0.00
Labor Hours:	0.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**9.64**

Work Order Footer

Work Order 33095179 Total	
Parts:	9.64
Labor:	0.00
Labor Hours:	0.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**9.64**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 32912102
Invoice No. 55345 - 32912102

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Check lift		Ford E350 Champion Crusaders	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	98,382 - DH

Chronology		
Reported	Jan 9, 2017 4:09:17 PM	Jan 9, 2017 4:09:17 PM
Started	Jan 10, 2017 12:00:00 AM	
Completed	Jan 11, 2017 8:20:00 AM	Jan 11, 2017 8:20:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Lift stop working

CAUSE:Short circuit and defective micro-switch

CORRECTION:Short circuit repair and sensor replacement

Short circuit repaired
Bridge plate micro-switch replaced

Part used
One (1) bridge plate micro- switch (under warranty)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 10-JAN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Jan 10, 2017 3:45:20 PM	No	
20 - Miles			FSIMON	Jan 10, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:45:20 PM		
30 - Kilometers			FSIMON	Jan 10, 2017 3:45:20 PM	No	
40 - Hours			FSIMON	Jan 10, 2017 3:45:20 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 32912102
Invoice No. 55345 - 32912102

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Check lift		Ford E350 Champion Crusaders	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	98,382 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Jan-17	Simon,Fritz	3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 32912102 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27990808
Invoice No. 55345 - 27990808

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 96,213 - DH

Chronology		
Reported	Dec 15, 2016 1:57:07 PM	Dec 15, 2016 1:57:07 PM
Started	Dec 15, 2016 12:00:00 AM	
Completed	Dec 15, 2016 8:03:00 PM	Dec 15, 2016 8:03:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA Service

CAUSE:Service due by Mileage

CORRECTION: Change Oil& Filter Lube all Pivoting points clean batteries Check brakes all is ok at this time,
Parts# B329 Qty (1)
Oil 5W20 Qty (6.5) Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Dec-16	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 15-DEC-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Dec 15, 2016 7:52:34 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Dec 15, 2016 7:52:34 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
20,260 - Check Stop Request System	-	NA	DARTHURS	Dec 15, 2016 7:52:34 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Dec 15, 2016 7:52:34 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Dec 15, 2016 7:52:34 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
40,420 - Check Hood	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Dec 15, 2016 7:52:34 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Dec 15, 2016 7:52:34 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Dec 15, 2016 7:52:34 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Dec 15, 2016 7:52:34 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Dec 15, 2016 7:52:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Dec 15, 2016 7:52:34 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,631 - Tread Depth RF	6 32nds of an inch		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
60,632 - Tread Depth LF	6 32nds of an inch		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
60,634 - Tread Depth RRI	5 32nds of an inch		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
60,635 - Tread Depth LRI	9 32nds of an inch		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Dec 15, 2016 7:52:34 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
77,131 - Brake Pad Thickness LF	6 Inch		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
77,132 - Brake Pad Thickness RF	6 Inch		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
77,135 - Brake Rotor LF	1.567 Inch		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
77,136 - Brake Rotor RF	1.568 Inch		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
77,137 - Brake Rotor LR	1.414 Inch		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
77,138 - Brake Rotor RR	1.414 Inch		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Dec 15, 2016 7:52:34 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Dec 15, 2016 7:52:34 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27990808
Invoice No. 55345 - 27990808

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 96,213 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Dec-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Dec-16	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 15-DEC-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Dec 15, 2016 7:53:26 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Dec 15, 2016 7:53:26 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Dec 15, 2016 7:53:26 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Dec 15, 2016 7:53:26 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Dec 15, 2016 7:53:26 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Dec 15, 2016 7:53:26 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Dec 15, 2016 7:53:26 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Dec 15, 2016 7:53:26 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27990808
Invoice No. 55345 - 27990808

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	96,213 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Dec-16	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 15-DEC-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Dec 15, 2016 7:54:05 PM	No	
20 - Miles			DARTHURS	Dec 15, 2016 7:54:05 PM	No	
30 - Kilometers			DARTHURS	Dec 15, 2016 7:54:05 PM	No	
40 - Hours			DARTHURS	Dec 15, 2016 7:54:05 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27990808 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 29923692
Invoice No. 55345 - 29923692

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Headlight		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	95,437 - DH

Chronology		
Reported	Dec 12, 2016 9:42:00 AM	Dec 12, 2016 9:42:00 AM
Started	Dec 12, 2016 12:00:00 AM	
Completed	Dec 15, 2016 11:29:44 AM	Dec 15, 2016 11:29:44 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:
Driver side headlight is out

CAUSE:
normal wear

CORRECTION:

replaced front driver side headlight

Parts

Qty 1 Headlight bulb 83982

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 12-DEC-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Dec 12, 2016 12:10:49 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			EDTORRES	Dec 12, 2016 12:10:49 PM	No	
30 - Kilometers			EDTORRES	Dec 12, 2016 12:10:49 PM	No	
40 - Hours			EDTORRES	Dec 12, 2016 12:10:49 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 29923692
Invoice No. 55345 - 29923692

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Headlight		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	95,437 - DH

Activity Header
Activity: 15 034 LIGHTING SYSTEM
Activity Note: Bad headlight
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Dec-16	83982	BULB, HALOGEN, 9008	1	0.32	0.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Dec-16	Torres,Edwin	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.32
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.32**

Work Order Footer

Work Order 29923692 Total	
Parts:	0.32
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27997610
Invoice No. 55345 - 27997610

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Spark plugs (Service)		Ford E350 Champion Crusaders	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	91,933 - DH

Chronology		
Reported	Nov 10, 2016 2:28:10 PM	Nov 10, 2016 2:28:10 PM
Started	Nov 10, 2016 12:00:00 AM	
Completed	Nov 11, 2016 7:05:00 AM	Nov 11, 2016 7:05:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Spark plugs replacement

CAUSE:Preventive maintenance

CORRECTION:Spark plugs(service) completion

Eight (8) boots and spark plugs replaced

Parts used:
Eight (8) spark plugs #SP521
Eight(8) boots #WR-6128

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 10-NOV-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Nov 10, 2016 2:42:30 PM	No	
20 - Miles			FSIMON	Nov 10, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				2:42:30 PM		
30 - Kilometers			FSIMON	Nov 10, 2016 2:42:30 PM	No	
40 - Hours			FSIMON	Nov 10, 2016 2:42:30 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27997610
Invoice No. 55345 - 27997610

Client Department:
Department: 55345M
Work Order Description
Spark plugs (Service)
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 91,933 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Nov-16	WR6128	BOOT, PLUG, SPARK	8	5.28	42.24
10-Nov-16	SP521	PLUG, SPARK, 5.4L, FORD	8	4.15	33.2

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Nov-16	Simon,Fritz	3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	75.44
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**75.44**

Work Order Footer

Work Order 27997610 Total	
Parts:	75.44
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**75.44**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27679810
Invoice No. 55345 - 27679810

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 91,933 - DH

Chronology		
Reported	Nov 9, 2016 8:06:31 AM	Nov 9, 2016 8:06:31 AM
Started	Nov 10, 2016 12:00:00 AM	
Completed	Nov 10, 2016 8:51:00 AM	Nov 10, 2016 8:51:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMB

CAUSE: preventive maintenance

CORRECTION:perform service lube all pivoting points cross rotate tires completed
Parts #B329 qty 1
Oil#5w20 qts 6

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Nov-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Nov-16	Pierre,Hubert J	6	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 10-NOV-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
10,100 - Safety Inspection	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1400 Pounds per Square Inch	N/A	HPIERRE	Nov 10, 2016 7:18:22 AM	No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	Nov 10, 2016 7:18:22 AM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Nov 10, 2016 7:18:22 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Nov 10, 2016 7:18:22 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Nov 10, 2016 7:18:22 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
40,420 - Check Hood	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Nov 10, 2016 7:18:22 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Nov 10, 2016 7:18:22 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Nov 10, 2016 7:18:22 AM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Nov 10, 2016 7:18:22 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Nov 10, 2016 7:18:22 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Nov 10, 2016 7:18:22 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Nov 10, 2016 7:18:22 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
60,631 - Tread Depth RF	8 32nds of an inch		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
60,632 - Tread Depth LF	8 32nds of an inch		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
60,633 - Tread Depth RRO	9 32nds of an inch		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
60,634 - Tread Depth RRI	9 32nds of an inch		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
60,635 - Tread Depth LRI	9 32nds of an inch		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
60,636 - Tread Depth LRO	9 32nds of an inch		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Nov 10, 2016 7:18:22 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
77,131 - Brake Pad Thickness LF	8 Inch		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
77,132 - Brake Pad Thickness RF	8 Inch		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
77,133 - Brake Pad Thickness LR	7 Inch		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
77,134 - Brake Pad Thickness RR	7 Inch		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
77,135 - Brake Rotor LF	1.6 Inch		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
77,136 - Brake Rotor RF	1.6 Inch		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
77,137 - Brake Rotor LR	1.7 Inch		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
77,138 - Brake Rotor RR	1.7 Inch		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Nov 10, 2016 7:18:22 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Nov 10, 2016 7:18:22 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	6.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27679810
Invoice No. 55345 - 27679810

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 91,933 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Nov-16	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: HPIERRE Performed on: 10-NOV-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Nov 10, 2016 7:23:33 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Nov 10, 2016 7:23:33 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Nov 10, 2016 7:23:33 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Nov 10, 2016 7:23:33 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Nov 10, 2016 7:23:33 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Nov 10, 2016 7:23:33 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Nov 10, 2016 7:23:33 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Nov 10, 2016 7:23:33 AM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		HPIERRE	Nov 10, 2016 7:23:33 AM	No	
201,000 - Service Crankcase Breather	Done		HPIERRE	Nov 10, 2016 7:23:33 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	No		HPIERRE	Nov 10, 2016 7:23:33 AM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		HPIERRE	Nov 10, 2016 7:23:33 AM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		HPIERRE	Nov 10, 2016 7:23:33 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27679810
Invoice No. 55345 - 27679810

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM B		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	91,933 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Nov-16	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 10-NOV-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Nov 10, 2016 7:24:52 AM	No	
20 - Miles			HPIERRE	Nov 10, 2016 7:24:52 AM	No	
30 - Kilometers			HPIERRE	Nov 10, 2016 7:24:52 AM	No	
40 - Hours			HPIERRE	Nov 10, 2016 7:24:52 AM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27679810 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	6.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27989510
Invoice No. 55345 - 27989510

Client Department:
Department: 55345M
Work Order Description
Passenger step door light not working
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 91,933 - DH

Chronology		
Reported	Nov 10, 2016 7:32:47 AM	Nov 10, 2016 7:32:47 AM
Started	Nov 10, 2016 12:00:00 AM	
Completed	Nov 10, 2016 8:46:00 AM	Nov 10, 2016 8:46:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT: passenger step door light not working

CAUSE: broke wires burn bulb

CORRECTION: repair wires replace light bulb completed
Part#under warranty qty1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Nov-16	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 10-NOV-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Nov 10, 2016 7:57:35 AM	No	
20 - Miles			HPIERRE	Nov 10, 2016 7:57:35 AM	No	
30 - Kilometers			HPIERRE	Nov 10, 2016 7:57:35 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			HPIERRE	Nov 10, 2016 7:57:35 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27989510
Invoice No. 55345 - 27989510

Client Department:
Department: 55345M
Work Order Description
Passenger step door light not working
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 91,933 - DH

Activity Header
Activity: 15 034 LIGHTING SYSTEM
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Nov-16	Pierre,Hubert J	3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27989510 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27722613
Invoice No. 55345 - 27722613

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Driver door lower hinge is bad		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	87,794 - DH

Chronology		
Reported	Oct 12, 2016 8:58:22 AM	Oct 12, 2016 8:58:22 AM
Started	Oct 12, 2016 12:00:00 AM	
Completed	Oct 14, 2016 9:33:00 AM	Oct 14, 2016 9:33:00 AM
Down Time		

Work Order Notes

Line 10 Hinge

COMPLAINT:
Driver door lower hinge is bad

CAUSE:
The roller and pin thats on the hinge are defected and have snapped out of place.

CORRECTION:
Removed bad hinge and installed a new lower hinge ob driver side

Parts
Qty 1 driver door lower hinge 6C2Z-1522-810Ab

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Oct-16	Torres,Edwin	-0.8333333	0	0
12-Oct-16	Torres,Edwin	0.85	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 14-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Oct 14, 2016 9:02:29 AM	No	
20 - Miles			EDTORRES	Oct 14, 2016 9:02:29 AM	No	
30 - Kilometers			EDTORRES	Oct 14, 2016 9:02:29 AM	No	
40 - Hours			EDTORRES	Oct 14, 2016 9:02:29 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27722613
Invoice No. 55345 - 27722613

Client Department:
Department: 55345M
Work Order Description
Driver door lower hinge is bad
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 87,794 - DH

Activity Header
Activity: 15 174 BODY, BUS
Activity Note: Driver door lower hinge is bad
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Oct-16	6C2Z-1522810-A	HINGE, DOOR, DRIVERS	1	46.61	46.61

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Oct-16	Torres,Edwin	0.8666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	46.61
Labor:	0.00
Labor Hours:	0.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**46.61**

Work Order Footer

Work Order 27722613 Total	
Parts:	46.61
Labor:	0.00
Labor Hours:	0.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**46.61**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27656526
Invoice No. 55345 - 27656526

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
FTLMPMI_FOLLOWUP		Ford E350 Champion Crusaders	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	87,433 - DH

Chronology		
Reported	Oct 11, 2016 12:49:51 PM	Oct 11, 2016 12:49:51 PM
Started	Oct 11, 2016 12:00:00 AM	
Completed	Oct 12, 2016 2:27:00 PM	Oct 12, 2016 2:27:00 PM
Down Time		

Work Order Notes

Line 10 Front hubs bearings and seals replaced

Part used:
Two (2) front hubs inner bearings #LM102949
Two (2) front hubs outer bearings#15101
Two(2) front hubs seals#CR24000

Activity Header
Activity: 10 013 BRAKES
Activity Note: FRONT WHEEL BEARINGS REPLACED
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27656526
Invoice No. 55345 - 27656526

Client Department:
Department: 55345M
Work Order Description
FTLMPMI_FOLLOWUP
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 87,433 - DH

Activity Header
Activity: 20 018 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Oct-16	CR24000	SEAL, WHEEL, HUB, FRONT	2	7.53	15.06
11-Oct-16	15101	BEARING, WHEEL, OUTER, FRONT	2	8.16	16.32
11-Oct-16	LM102949	BEARING, WHEEL, INNER, FRONT, TAPERED	2	6.95	13.9

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Oct-16	Simon,Fritz	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 11-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Oct 11, 2016 1:16:33 PM	No	
20 - Miles			FSIMON	Oct 11, 2016 1:16:33 PM	No	
30 - Kilometers			FSIMON	Oct 11, 2016 1:16:33 PM	No	
40 - Hours			FSIMON	Oct 11, 2016 1:16:33 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	45.28
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**45.28**

Work Order Footer

Work Order 27656526 Total	
Parts:	45.28
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**45.28**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27436168
Invoice No. 55345 - 27436168

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	LCAPAZZOLI	**Status:**	40 - Closed (40)
Created By:	LCAPAZZOLI	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	87,636 - DH

Chronology		
Reported	Oct 11, 2016 10:20:58 AM	Oct 11, 2016 10:20:58 AM
Started	Oct 11, 2016 12:00:00 AM	
Completed	Oct 12, 2016 10:11:00 AM	Oct 12, 2016 10:11:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA

CAUSE:PMA Due

CORRECTION:PMA completion

PMA performed
Engine oil filter changed
Engine oil changed
Engine drain plug changed
Grease fittings lubricated
Road test performed (ok)

NB:
-Driver door hinge needs to be changed
-Small cracks noticed in the engine mounts

Parts used
One (1) oil filter #B329
Six(6) quarts of oil 5W 20
One (1) drain plug #F75Z-6730-BA

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Oct-16	Simon,Fritz	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: FSIMON Performed on: 11-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
10,100 - Safety Inspection	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
10,140 - Check Service Brakes	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
10,160 - FRA Check Instruments and Horns	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
10,170 - Check Fast Idle	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
10,180 - Check Starter Protection Circuit	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
10,190 - Check Reverse Warning System	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
11,100 - Check Parking Brake	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
11,150 - Perform Brake Test	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	FSIMON	Oct 11, 2016 12:49:51 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	FSIMON	Oct 11, 2016 12:49:51 PM	No	
11,170 - FRA Check Door Operation	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
20,210 - Check Condition of Operator's Area	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		FSIMON	Oct 11, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:49:51 PM		
20,240 - FRA Check Interior Lights	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
20,260 - Check Stop Request System	-	n/a	FSIMON	Oct 11, 2016 12:49:51 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	FSIMON	Oct 11, 2016 12:49:51 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
22,110 - Check Emergency Hatches	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
22,120 - Check All Safety Equipment	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
30,310 - Check Passenger Doors	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	FSIMON	Oct 11, 2016 12:49:51 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
30,360 - Check for Physical Damage and Decals	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
30,380 - Check Exterior Compartment Doors	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
33,100 - Check Lights and Reflectors	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
40,420 - Check Hood	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
40,440 - Test Coolant System Using Test Strips	-	n/a	FSIMON	Oct 11, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
and Record Results				12:49:51 PM		
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	FSIMON	Oct 11, 2016 12:49:51 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	FSIMON	Oct 11, 2016 12:49:51 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	FSIMON	Oct 11, 2016 12:49:51 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	FSIMON	Oct 11, 2016 12:49:51 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
44,130 - FRA Check Exhaust System	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
44,140 - FRA Check Intake System	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	FSIMON	Oct 11, 2016 12:49:51 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
44,180 - FRA Check for Leaks	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
44,190 - FRA Perform Battery Inspection	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
50,510 - Check Entire Steering System	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		FSIMON	Oct 11, 2016 12:49:51 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		FSIMON	Oct 11, 2016 12:49:51 PM	No	
60,613 - Air Pressure RRO	70 Pounds per		FSIMON	Oct 11, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			12:49:51 PM		
60,614 - Air Pressure RRI	70 Pounds per Square Inch		FSIMON	Oct 11, 2016 12:49:51 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		FSIMON	Oct 11, 2016 12:49:51 PM	No	
60,616 - Air Pressure LRO	707 Pounds per Square Inch		FSIMON	Oct 11, 2016 12:49:51 PM	No	
60,620 - Check Valve Stems and Caps	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
60,630 - Check and Record Tread Depth	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
60,631 - Tread Depth RF	7 32nds of an inch		FSIMON	Oct 11, 2016 12:49:51 PM	No	
60,632 - Tread Depth LF	7 32nds of an inch		FSIMON	Oct 11, 2016 12:49:51 PM	No	
60,633 - Tread Depth RRO	10 32nds of an inch		FSIMON	Oct 11, 2016 12:49:51 PM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		FSIMON	Oct 11, 2016 12:49:51 PM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		FSIMON	Oct 11, 2016 12:49:51 PM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		FSIMON	Oct 11, 2016 12:49:51 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
60,650 - Check Sidewall Wear	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
60,660 - Inspect for Cuts and Tears	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
60,670 - Check Dual Mating With Square	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
70,710 - Check Vibration Damper	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
70,730 - FRA Check Starter	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
70,770 - FRA Check Exhaust System	Done		FSIMON	Oct 11, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:49:51 PM		
70,780 - Check Driveline, U-joint and Slip Yokes	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
77,110 - FRA Check Fuel Tank	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
77,120 - Check Suspension Components	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
77,131 - Brake Pad Thickness LF	Inch	9mm	FSIMON	Oct 11, 2016 12:49:51 PM	No	
77,132 - Brake Pad Thickness RF	Inch	9mm	FSIMON	Oct 11, 2016 12:49:51 PM	No	
77,133 - Brake Pad Thickness LR	Inch	8mm	FSIMON	Oct 11, 2016 12:49:51 PM	No	
77,134 - Brake Pad Thickness RR	Inch	8mm	FSIMON	Oct 11, 2016 12:49:51 PM	No	
77,135 - Brake Rotor LF	Inch	40mm	FSIMON	Oct 11, 2016 12:49:51 PM	No	
77,136 - Brake Rotor RF	Inch	40mm	FSIMON	Oct 11, 2016 12:49:51 PM	No	
77,137 - Brake Rotor LR	Inch	36mm	FSIMON	Oct 11, 2016 12:49:51 PM	No	
77,138 - Brake Rotor RR	Inch	36mm	FSIMON	Oct 11, 2016 12:49:51 PM	No	
77,140 - FRA Check Brake Hoses	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
77,150 - Check King Pins	-	n/a	FSIMON	Oct 11, 2016 12:49:51 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		FSIMON	Oct 11, 2016 12:49:51 PM	Yes	27656526
80,000 - SECTION 8 PMI Report Completion	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
80,810 - Completion of PMI Report	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		FSIMON	Oct 11, 2016 12:49:51 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27436168
Invoice No. 55345 - 27436168

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: LCAPAZZOLI
Created By: LCAPAZZOLI
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 87,636 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Oct-16	F757-6730-BA	PLUG, DRAIN, OIL, ENGINE	1	6.66	6.66
11-Oct-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Oct-16	Simon,Fritz	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: FSIMON Performed on: 11-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		FSIMON	Oct 11, 2016 12:49:31 PM	No	
101,000 - FRA Change Oil Filters	Yes		FSIMON	Oct 11, 2016 12:49:31 PM	No	
102,000 - FRA Drain Engine Oil	Yes		FSIMON	Oct 11, 2016 12:49:31 PM	No	
103,000 - FRA Check Transmission Fluid	Done		FSIMON	Oct 11, 2016 12:49:31 PM	No	
104,000 - Lubricate Chassis	Done		FSIMON	Oct 11, 2016 12:49:31 PM	No	
105,000 - Replace or Clean A/C Filters	Done		FSIMON	Oct 11, 2016 12:49:31 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	FSIMON	Oct 11, 2016 12:49:31 PM	No	
108,000 - Lube all pivoting	Done		FSIMON	Oct 11, 2016 12:49:31	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Mechanisms				PM		

Activity Sub Total

Activity 20 Sub Total	
Parts:	8.58
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.58**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27436168
Invoice No. 55345 - 27436168

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	LCAPAZZOLI	**Status:**	40 - Closed (40)
Created By:	LCAPAZZOLI	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	87,636 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 11-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Oct 11, 2016 12:43:26 PM	No	
20 - Miles			FSIMON	Oct 11, 2016 12:43:26 PM	No	
30 - Kilometers			FSIMON	Oct 11, 2016 12:43:26 PM	No	
40 - Hours			FSIMON	Oct 11, 2016 12:43:26 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27436168 Total	
Parts:	8.58
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**8.58**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27675805
Invoice No. 55345 - 27675805

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Driver door lower hinge.		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	87,433 - DH

Chronology		
Reported	Oct 12, 2016 7:05:55 AM	Oct 12, 2016 7:05:55 AM
Started	Oct 12, 2016 12:00:00 AM	
Completed	Oct 12, 2016 8:57:00 AM	Oct 12, 2016 8:57:00 AM
Down Time		

Work Order Notes

Line 10 Hinge

COMPLAINT:
Driver door lower hinge is bad

CAUSE:
The roller and pin thats on the hinge are defected and have snapped out of place.

CORRECTION:
Removed bad hinge and installed a new lower hinge ob driver side

Parts
Qty 1 driver door lower hinge 6C2Z-1522-810Ab

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 12-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Oct 12, 2016 7:09:31 AM	No	
20 - Miles			EDTORRES	Oct 12, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				7:09:31 AM		
30 - Kilometers			EDTORRES	Oct 12, 2016 7:09:31 AM	No	
40 - Hours			EDTORRES	Oct 12, 2016 7:09:31 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27675805
Invoice No. 55345 - 27675805

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Driver door lower hinge.		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	87,433 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note: Driver door lower hinge.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Oct-16	6C2Z-1522810-A	HINGE, DOOR, DRIVERS	1	46.61	46.61

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Oct-16	Torres,Edwin	0.8	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	46.61
Labor:	0.00
Labor Hours:	0.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**46.61**

Work Order Footer

Work Order 27675805 Total	
Parts:	46.61
Labor:	0.00
Labor Hours:	0.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**46.61**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27459659
Invoice No. 55345 - 27459659

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Driver side headlight is out		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	85,103 - DH

Chronology		
Reported	Sep 23, 2016 11:58:49 AM	Sep 23, 2016 11:58:49 AM
Started	Sep 23, 2016 12:00:00 AM	
Completed	Sep 23, 2016 3:48:53 PM	Sep 23, 2016 3:48:53 PM
Down Time		

Work Order Notes

Line 10 O Line 20 Headlight Pigtail

COMPLAINT:
Driver side headlight is out

CAUSE:
Pigtail harness is bad.

CORRECTION:
Replaced driver side headlight and pigtail harness.

PARTS:
9008 headlight bulb qty 1
891699 headlight pigtail qty 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 23-SEP-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Sep 23, 2016 12:02:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			EDTORRES	Sep 23, 2016 12:02:01 PM	No	
30 - Kilometers			EDTORRES	Sep 23, 2016 12:02:01 PM	No	
40 - Hours			EDTORRES	Sep 23, 2016 12:02:01 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27459659
Invoice No. 55345 - 27459659

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Driver side headlight is out		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	85,103 - DH

Activity Header
Activity: 15 034/001/000 HEADLAMP
Activity Note: Driver side headlight is out
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Sep-16	9008	BULB, HEADLAMP, HALOGEN, 12V	1	5.79	5.79
23-Sep-16	891699	OUT OF SERVICE DISCONTINUED USE 892292 PIGTAIL, HEADLAMP, 9008	1	7.41	7.41

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Sep-16	Torres,Edwin	0.6	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	13.20
Labor:	0.00
Labor Hours:	0.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**13.20**

Work Order Footer

Work Order 27459659 Total	
Parts:	13.20
Labor:	0.00
Labor Hours:	0.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**13.20**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27449506
Invoice No. 55345 - 27449506

Client Department:
Department: 55345M
Work Order Description
Passenger side headlight is out.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 84,416 - DH

Chronology		
Reported	Sep 20, 2016 6:12:45 AM	Sep 20, 2016 6:12:45 AM
Started	Sep 20, 2016 12:00:00 AM	
Completed	Sep 20, 2016 7:13:00 AM	Sep 20, 2016 7:13:00 AM
Down Time		

Work Order Notes

Line 10 Headlight Pigtail

COMPLAINT:
Passenger side headlight is out

CAUSE:
Pigtail harness is bad.

CORRECTION:
Replaced passenger side headlight and pigtail harness.

PARTS:
9008 headlight bulb qty 1
891699 headlight pigtail qty 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Sep-16	Torres,Edwin	0.5166666	0	0
20-Sep-16	Torres,Edwin	-0.4666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 20-SEP-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Sep 20, 2016 6:49:59 AM	No	
20 - Miles			EDTORRES	Sep 20, 2016 6:49:59 AM	No	
30 - Kilometers			EDTORRES	Sep 20, 2016 6:49:59 AM	No	
40 - Hours			EDTORRES	Sep 20, 2016 6:49:59 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27449506
Invoice No. 55345 - 27449506

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Passenger side headlight is out.		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	84,416 - DH

Activity Header
Activity: 15 034/001/000 HEADLAMP
Activity Note: Passenger side headlight is out.
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Sep-16	9008	BULB, HEADLAMP, HALOGEN, 12V	1	5.79	5.79
20-Sep-16	891699	OUT OF SERVICE DISCONTINUED USE 892292 PIGTAIL, HEADLAMP, 9008	1	7.41	7.41

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Sep-16	Torres,Edwin	0.4666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	13.20
Labor:	0.00
Labor Hours:	0.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**13.20**

Work Order Footer

Work Order 27449506 Total	
Parts:	13.20
Labor:	0.00
Labor Hours:	0.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**13.20**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27446151
Invoice No. 55345 - 27446151

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
A/C&tire		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	84,055 - DH

Chronology

Reported	Sep 16, 2016 9:45:57 PM	Sep 16, 2016 9:45:57 PM
Started	Sep 16, 2016 12:00:00 AM	
Completed	Sep 16, 2016 11:11:00 PM	Sep 16, 2016 11:11:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: Tire& A/C

CAUSE:Tire Worn below Spec& A/C not b,owing through vent,

CORRECTION: Mount& Balance tire Qty (2) Remove&Replace A/C Vacuum Reservoir/Check Valve
Parts# 050017 kenda Qty (2)
Parts#YC2Z-19A566-AA Qty (1)
Parts#D70Z-19A563-A Qty-1 same as YG193

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Sep-16	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 16-SEP-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Sep 16, 2016 10:46:57 PM	No	
20 - Miles			DARTHURS	Sep 16, 2016 10:46:57 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30 - Kilometers			DARTHURS	Sep 16, 2016 10:46:57 PM	No	
40 - Hours			DARTHURS	Sep 16, 2016 10:46:57 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27446151
Invoice No. 55345 - 27446151

Client Department:
Department: 55345M
Work Order Description
A/C&tire
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 84,055 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Two Right Rear tire low & A/C
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Sep-16	050017	OUT OF SERVICE TIRE, LT225/75R16, KRO5, KENDA	2	81.5	163
16-Sep-16	YC2Z-19A566-AA	RESERVOIR, VACUUM W/BRACKET	1	25.81	25.81
16-Sep-16	YG193	VALVE, CHECK, VACUUM, A/C SAME AS D7OZ-19A563-A	1	4.59	4.59

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Sep-16	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	193.40
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**193.40**

Work Order Footer

Work Order 27446151 Total	
Parts:	193.40
Labor:	0.00
Labor Hours:	2.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**193.40**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27367613
Invoice No. 55345 - 27367613

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 83,053 - DH

Chronology		
Reported	Sep 9, 2016 2:59:56 PM	Sep 9, 2016 2:59:56 PM
Started	Sep 9, 2016 12:00:00 AM	
Completed	Sep 9, 2016 7:57:00 PM	Sep 9, 2016 7:57:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pm-A inspection due

CAUSE: miles

CORRECTION: Completed pm-A inspection. Replaced oil and oil filter

Parts used. 6 quarts oil 5w-20. 1 oil filter. B-329

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Sep-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Sep-16	Capazzoli,Louis	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: LCAPAZZOLI Performed on: 09-SEP-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
10,100 - Safety Inspection	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
10,140 - Check Service Brakes	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
10,160 - FRA Check Instruments and Horns	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
10,170 - Check Fast Idle	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
10,180 - Check Starter Protection Circuit	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
10,190 - Check Reverse Warning System	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
11,100 - Check Parking Brake	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
11,150 - Perform Brake Test	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
11,170 - FRA Check Door Operation	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
20,210 - Check Condition of Operator's Area	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
20,240 - FRA Check Interior Lights	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
20,260 - Check Stop Request System	-	n/a	LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
22,110 - Check Emergency Hatches	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
22,120 - Check All Safety Equipment	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
30,310 - Check Passenger Doors	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
30,360 - Check for Physical Damage and Decals	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
30,380 - Check Exterior Compartment Doors	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
33,100 - Check Lights and Reflectors	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
40,420 - Check Hood	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
44,130 - FRA Check Exhaust System	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
44,140 - FRA Check Intake System	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
44,180 - FRA Check for Leaks	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
44,190 - FRA Perform Battery Inspection	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
50,510 - Check Entire Steering System	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
60,630 - Check and Record Tread Depth	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
60,631 - Tread Depth RF	12 32nds of an inch		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
60,636 - Tread Depth LRO	12 32nds of an inch		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
60,650 - Check Sidewall Wear	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
60,660 - Inspect for Cuts and Tears	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
70,710 - Check Vibration Damper	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
70,730 - FRA Check Starter	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
70,770 - FRA Check Exhaust System	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
77,120 - Check Suspension Components	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
77,131 - Brake Pad Thickness LF	Inch	10 mm	LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
77,132 - Brake Pad Thickness RF	Inch	10 mm	LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
77,133 - Brake Pad Thickness LR	Inch	10 mm	LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
77,134 - Brake Pad Thickness RR	Inch	10 mm	LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
77,135 - Brake Rotor LF	Inch	10 mm	LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
77,136 - Brake Rotor RF	Inch	40	LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
77,137 - Brake Rotor LR	Inch	40	LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
77,138 - Brake Rotor RR	Inch	40	LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
77,140 - FRA Check Brake Hoses	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
77,150 - Check King Pins	-	n/a	LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
80,810 - Completion of PMI Report	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		LCAPAZZOLI	Sep 9, 2016 7:15:46 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27367613
Invoice No. 55345 - 27367613

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 83,053 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Sep-16	Capazzoli,Louis	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: LCAPAZZOLI Performed on: 09-SEP-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		LCAPAZZOLI	Sep 9, 2016 7:16:17 PM	No	
101,000 - FRA Change Oil Filters	Yes		LCAPAZZOLI	Sep 9, 2016 7:16:17 PM	No	
102,000 - FRA Drain Engine Oil	Yes		LCAPAZZOLI	Sep 9, 2016 7:16:17 PM	No	
103,000 - FRA Check Transmission Fluid	Done		LCAPAZZOLI	Sep 9, 2016 7:16:17 PM	No	
104,000 - Lubricate Chassis	Done		LCAPAZZOLI	Sep 9, 2016 7:16:17 PM	No	
105,000 - Replace or Clean A/C Filters	Done		LCAPAZZOLI	Sep 9, 2016 7:16:17 PM	No	
107,000 - FRA Change Primary Fuel Filter	No		LCAPAZZOLI	Sep 9, 2016 7:16:17 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		LCAPAZZOLI	Sep 9, 2016 7:16:17 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.50
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27367613
Invoice No. 55345 - 27367613

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	83,053 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Sep-16	Capazzoli,Louis	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 09-SEP-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Sep 9, 2016 7:16:39 PM	No	
20 - Miles			LCAPAZZOLI	Sep 9, 2016 7:16:39 PM	No	
30 - Kilometers			LCAPAZZOLI	Sep 9, 2016 7:16:39 PM	No	
40 - Hours			LCAPAZZOLI	Sep 9, 2016 7:16:39 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27367613 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.08

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27223298
Invoice No. 55345 - 27223298

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 78,576 - DH

Chronology		
Reported	Aug 3, 2016 2:34:52 PM	Aug 3, 2016 2:34:52 PM
Started	Aug 3, 2016 12:00:00 AM	
Completed	Aug 3, 2016 8:31:00 PM	Aug 3, 2016 8:31:00 PM
Down Time		

Work Order Notes

Line 10 Perform PMC Service Change Oil & Filter Lube AllPivoting Points Check Brakes /Replace Air Filter Parts#B329 Qty (1)
Parts#PA4075 Qty (1) Line 20 Oil 5w20 Qty (6)

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Aug-16	PA4075	OUT OF SERVICE DO NOT ORDER FILTER, AIR, PAPER SAME AS AF25590	1	5.18	5.18
03-Aug-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Aug-16	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 03-AUG-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Aug 3, 2016 5:12:38 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Aug 3, 2016 5:12:38 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
20,260 - Check Stop Request System	-	NA	DARTHURS	Aug 3, 2016 5:12:38 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Aug 3, 2016 5:12:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Aug 3, 2016 5:12:38 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
40,420 - Check Hood	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Aug 3, 2016 5:12:38 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Aug 3, 2016 5:12:38 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Aug 3, 2016 5:12:38 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Aug 3, 2016 5:12:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Aug 3, 2016 5:12:38 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Aug 3, 2016 5:12:38 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
60,612 - Air Pressure LF	Pounds per Square Inch	65	DARTHURS	Aug 3, 2016 5:12:38 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,630 - Check and Record Tread Depth	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
60,631 - Tread Depth RF	11 32nds of an inch		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
60,632 - Tread Depth LF	11 32nds of an inch		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
60,634 - Tread Depth RRI	5 32nds of an inch		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
60,636 - Tread Depth LRO	12 32nds of an inch		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Aug 3, 2016 5:12:38 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,120 - Check Suspension Components	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
77,135 - Brake Rotor LF	1.596 Inch		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
77,136 - Brake Rotor RF	1.597 Inch		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
77,137 - Brake Rotor LR	1.415 Inch		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
77,138 - Brake Rotor RR	1.416 Inch		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Aug 3, 2016 5:12:38 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Aug 3, 2016 5:12:38 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27223298
Invoice No. 55345 - 27223298

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 78,576 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Aug-16	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: DARTHURS Performed on: 03-AUG-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Aug 3, 2016 5:14:40 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Aug 3, 2016 5:14:40 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Aug 3, 2016 5:14:40 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Aug 3, 2016 5:14:40 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Aug 3, 2016 5:14:40 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Aug 3, 2016 5:14:40 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	NA	DARTHURS	Aug 3, 2016 5:14:40 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Aug 3, 2016 5:14:40 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	Aug 3, 2016 5:14:40 PM	No	
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Aug 3, 2016 5:14:40 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	No		DARTHURS	Aug 3, 2016 5:14:40 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Aug 3, 2016 5:14:40 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Aug 3, 2016 5:14:40 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		DARTHURS	Aug 3, 2016 5:14:40 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		DARTHURS	Aug 3, 2016 5:14:40 PM	No	
302,000 - Check Toe-In and Record Reading	-	NA	DARTHURS	Aug 3, 2016 5:14:40 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	NA	DARTHURS	Aug 3, 2016 5:14:40 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		DARTHURS	Aug 3, 2016 5:14:40 PM	No	
305,000 - FRA Change Differential Fluid	No		DARTHURS	Aug 3, 2016 5:14:40 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27223298
Invoice No. 55345 - 27223298

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM C		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	78,576 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Aug-16	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 03-AUG-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Aug 3, 2016 5:15:08 PM	No	
20 - Miles			DARTHURS	Aug 3, 2016 5:15:08 PM	No	
30 - Kilometers			DARTHURS	Aug 3, 2016 5:15:08 PM	No	
40 - Hours			DARTHURS	Aug 3, 2016 5:15:08 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27223298 Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	2.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**7.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27230080
Invoice No. 55345 - 27230080

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Lower Radiator Hose Leaking		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	75,007 - DH

Chronology		
Reported	Jul 6, 2016 10:03:53 PM	Jul 6, 2016 10:03:53 PM
Started	Jul 6, 2016 12:00:00 AM	
Completed	Jul 6, 2016 10:32:00 PM	Jul 6, 2016 10:32:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: Lower Radiator Hose Leaking

CAUSE:Hose Rubbing against Center link /Damage

CORRECTION: Remove/Replace Center Link Qty (1) No Parts # For this Location #E72262
(3) Gallon of Extended Life Anti Freeze

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jul-16	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 06-JUL-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 6, 2016 10:05:25 PM	No	
20 - Miles			DARTHURS	Jul 6, 2016 10:05:25 PM	No	
30 - Kilometers			DARTHURS	Jul 6, 2016 10:05:25 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			DARTHURS	Jul 6, 2016 10:05:25 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27230080
Invoice No. 55345 - 27230080

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Lower Radiator Hose Leaking		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	75,007 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Lower Radiator Hose Leaking
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Jul-16	E72262	HOSE, RADIATOR, LOWER	1	57.69	57.69

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jul-16	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	57.69
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**57.69**

Work Order Footer

Work Order 27230080 Total	
Parts:	57.69
Labor:	0.00
Labor Hours:	2.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**57.69**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27228277
Invoice No. 55345 - 27228277

Client Department:
Department: 55345M
Work Order Description
REPLACE RIGHT SIDE SIGNAL BULB
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 74,931 - DH

Chronology		
Reported	Jul 5, 2016 7:17:10 PM	Jul 5, 2016 7:17:10 PM
Started	Jul 5, 2016 12:00:00 AM	
Completed	Jul 5, 2016 8:00:00 PM	Jul 5, 2016 8:00:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: RIGHT SIDE SIGNAL BULB OUT

CAUSE:BLOWN BULB

CORRECTION: REPLACE RIGHT SIDE SIGNAL BULB
PARTS 3157 N/A Qty 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jul-16	Owens,Arthur	0.1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 05-JUL-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Jul 5, 2016 7:56:07 PM	No	
20 - Miles			AOWENS	Jul 5, 2016 7:56:07 PM	No	
30 - Kilometers			AOWENS	Jul 5, 2016 7:56:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			AOWENS	Jul 5, 2016 7:56:07 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27228277
Invoice No. 55345 - 27228277

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
REPLACE RIGHT SIDE SIGNAL BULB		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	74,931 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: REPLACE RIGHT SIDE SIGNAL BULB
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Jul-16	3157	LAMP, WEDGE-MOUNT, PLASTIC SAME AS GE3157	1	0.48	0.48

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jul-16	Owens,Arthur	0.3166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.48
Labor:	0.00
Labor Hours:	0.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.48**

Work Order Footer

Work Order 27228277 Total	
Parts:	0.48
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27223179
Invoice No. 55345 - 27223179

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Front/Rear Brakes,		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	74,458 - DH

Chronology		
Reported	Jun 30, 2016 8:00:08 PM	Jun 30, 2016 8:00:08 PM
Started	Jun 30, 2016 12:00:00 AM	
Completed	Jun 30, 2016 10:41:00 PM	Jun 30, 2016 10:41:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: Rear Brake/Front Brake,/Tires

CAUSE:Slide Pin Seize

CORRECTION: Replace Slide Pin And Lubricate/Replace Front and Rear Pads and Mount /Balance (4) tire two new on Front/two new on L/R
Parts#LTR2072LL Qty (4)
Parts#BRSD1329 Rear Pads Qty(1)
Parts#BRSD1328Front Pads Qty (1) set

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Jun-16	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 30-JUN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jun 30, 2016 8:01:39 PM	No	
20 - Miles			DARTHURS	Jun 30, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:01:39 PM		
30 - Kilometers			DARTHURS	Jun 30, 2016 8:01:39 PM	No	
40 - Hours			DARTHURS	Jun 30, 2016 8:01:39 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27223179
Invoice No. 55345 - 27223179

Client Department:
Department: 55345M
Work Order Description
Front/Rear Brakes,
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 74,458 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Rear Brakes Low/Front Brakes Uneven wear
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Jul-16	LTR2072LL	OUT OF SERVICE DO NOT USE TIRE, LT225 75/R16, L780, LING-LONG	4	81.5	326
01-Jul-16	BRSD-1328	PADS, BRAKE, DISC, FRONT	1	50.32	50.32
01-Jul-16	BC2Z-2C150-A	PIN, CALIPER, BRAKE, DISC	1	14.45	14.45
01-Jul-16	BC2Z-2C150-A	PIN, CALIPER, BRAKE, DISC	-1	14.45	-14.45
01-Jul-16	BC2Z-2C150-A	PIN, CALIPER, BRAKE, DISC	2	14.45	28.9
01-Jul-16	BRSD1329	PADS, BRAKE, DISC, E450	1	44.48	44.48

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Jun-16	Arthurs,Durvin	3.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	449.70
Labor:	0.00
Labor Hours:	3.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**449.70**

Work Order Footer

Work Order 27223179 Total	
Parts:	449.70
Labor:	0.00
Labor Hours:	3.58

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**449.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27161977
Invoice No. 55345 - 27161977

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	74,458 - DH

Chronology		
Reported	Jun 30, 2016 10:34:58 AM	Jun 30, 2016 10:34:58 AM
Started	Jun 30, 2016 12:00:00 AM	
Completed	Jun 30, 2016 10:40:00 PM	Jun 30, 2016 10:40:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA Service

CAUSE:Service Due By Mileage

CORRECTION:Change Oil/Filter lube All Pivoting Points Remove All wheel And Check Brakes,
Parts# B329 Oil Filter Qty (1)
Oil 5w20 Qty (6) Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Jul-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Jun-16	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 30-JUN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Jun 30, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				7:52:38 PM		
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Jun 30, 2016 7:52:38 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Jun 30, 2016 7:52:38 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
20,260 - Check Stop Request System	-	NA	DARTHURS	Jun 30, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				7:52:38 PM		
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Jun 30, 2016 7:52:38 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Jun 30, 2016 7:52:38 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
40,420 - Check Hood	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Jun 30, 2016 7:52:38 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Jun 30, 2016 7:52:38 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Jun 30, 2016 7:52:38 PM	No	
40,450 - FRA Check Coolant Recovery System	Done		DARTHURS	Jun 30, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Condition & for Leaks				7:52:38 PM		
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Jun 30, 2016 7:52:38 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Jun 30, 2016 7:52:38 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Jun 30, 2016 7:52:38 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
60,616 - Air Pressure LRO	70 Pounds per		DARTHURS	Jun 30, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			7:52:38 PM		
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
60,631 - Tread Depth RF	3 32nds of an inch		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
60,632 - Tread Depth LF	3 32nds of an inch		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
60,635 - Tread Depth LRI	2 32nds of an inch		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
60,636 - Tread Depth LRO	3 32nds of an inch		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Jun 30, 2016 7:52:38 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
77,100 - FRA Check Security, Integrity and	Done		DARTHURS	Jun 30, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Length of Ground Straps				7:52:38 PM		
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
77,132 - Brake Pad Thickness RF	4 Inch		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
77,133 - Brake Pad Thickness LR	4 Inch		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
77,134 - Brake Pad Thickness RR	3 Inch		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
77,135 - Brake Rotor LF	1.596 Inch		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
77,136 - Brake Rotor RF	1.596 Inch		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
77,137 - Brake Rotor LR	1.415 Inch		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
77,138 - Brake Rotor RR	1.414 Inch		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Jun 30, 2016 7:52:38 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Jun 30, 2016 7:52:38 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27161977
Invoice No. 55345 - 27161977

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	74,458 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Jun-16	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 30-JUN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Jun 30, 2016 7:53:28 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Jun 30, 2016 7:53:28 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Jun 30, 2016 7:53:28 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Jun 30, 2016 7:53:28 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Jun 30, 2016 7:53:28 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Jun 30, 2016 7:53:28 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Jun 30, 2016 7:53:28 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Jun 30, 2016 7:53:28 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27161977
Invoice No. 55345 - 27161977

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	74,458 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Jun-16	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 30-JUN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jun 30, 2016 7:53:52 PM	No	
20 - Miles			DARTHURS	Jun 30, 2016 7:53:52 PM	No	
30 - Kilometers			DARTHURS	Jun 30, 2016 7:53:52 PM	No	
40 - Hours			DARTHURS	Jun 30, 2016 7:53:52 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27161977 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27212426
Invoice No. 55345 - 27212426

Client Department:
Department: 55345M
Work Order Description
Steering Box Leaking
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 73,849 - DH

Chronology		
Reported	Jun 26, 2016 8:31:16 PM	Jun 26, 2016 8:31:16 PM
Started	Jun 26, 2016 12:00:00 AM	
Completed	Jun 26, 2016 8:40:00 PM	Jun 26, 2016 8:40:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: Steering Box Leaking

CAUSE:Seal worn

CORRECTION: Replace Steering Box
Parts#AC2Z-3504-A Qty (1)
One Qts mercon -v power steering fluid

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Jun-16	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 26-JUN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jun 26, 2016 8:32:31 PM	No	
20 - Miles			DARTHURS	Jun 26, 2016 8:32:31 PM	No	
30 - Kilometers			DARTHURS	Jun 26, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:32:31 PM		
40 - Hours			DARTHURS	Jun 26, 2016 8:32:31 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27212426
Invoice No. 55345 - 27212426

Client Department:
Department: 55345M
Work Order Description
Steering Box Leaking
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 73,849 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Steering Box Leaking
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Jun-16	AC2Z-3504-A	BOX, GEAR, STEERING, E450, '08-'10 REPLACED BY GU2Z-3504-A	1	469.28	469.28

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Jun-16	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	469.28
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**469.28**

Work Order Footer

Work Order 27212426 Total	
Parts:	469.28
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**469.28**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27082661
Invoice No. 55345 - 27082661

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 70,183 - DH

Chronology		
Reported	May 27, 2016 4:00:21 PM	May 27, 2016 4:00:21 PM
Started	May 27, 2016 12:00:00 AM	
Completed	May 27, 2016 10:02:00 PM	May 27, 2016 10:02:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:service

CORRECTION:perform pmA service
Oil filter B329 qty 1
Engine oil 5w20 7 qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
31-May-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-May-16	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 27-MAY-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	May 27, 2016 9:54:51 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	May 27, 2016 9:54:51 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	May 27, 2016 9:54:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	May 27, 2016 9:54:51 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	May 27, 2016 9:54:51 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
40,420 - Check Hood	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	May 27, 2016 9:54:51 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	May 27, 2016 9:54:51 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	May 27, 2016 9:54:51 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	May 27, 2016 9:54:51 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	May 27, 2016 9:54:51 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	May 27, 2016 9:54:51 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RGASPARD	May 27, 2016 9:54:51 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RGASPARD	May 27, 2016 9:54:51 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	May 27, 2016 9:54:51 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	May 27, 2016 9:54:51 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	May 27, 2016 9:54:51 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	May 27, 2016 9:54:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
60,631 - Tread Depth RF	6 32nds of an inch		RGASPARD	May 27, 2016 9:54:51 PM	No	
60,632 - Tread Depth LF	7 32nds of an inch		RGASPARD	May 27, 2016 9:54:51 PM	No	
60,633 - Tread Depth RRO	4 32nds of an inch		RGASPARD	May 27, 2016 9:54:51 PM	No	
60,634 - Tread Depth RRI	5 32nds of an inch		RGASPARD	May 27, 2016 9:54:51 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		RGASPARD	May 27, 2016 9:54:51 PM	No	
60,636 - Tread Depth LRO	5 32nds of an inch		RGASPARD	May 27, 2016 9:54:51 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
60,670 - Check Dual Mating With Square	-	na	RGASPARD	May 27, 2016 9:54:51 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		RGASPARD	May 27, 2016 9:54:51 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		RGASPARD	May 27, 2016 9:54:51 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		RGASPARD	May 27, 2016 9:54:51 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		RGASPARD	May 27, 2016 9:54:51 PM	No	
77,135 - Brake Rotor LF	37 Inch		RGASPARD	May 27, 2016 9:54:51 PM	No	
77,136 - Brake Rotor RF	37 Inch		RGASPARD	May 27, 2016 9:54:51 PM	No	
77,137 - Brake Rotor LR	34 Inch		RGASPARD	May 27, 2016 9:54:51 PM	No	
77,138 - Brake Rotor RR	34 Inch		RGASPARD	May 27, 2016 9:54:51 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	May 27, 2016 9:54:51 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	May 27, 2016 9:54:51 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27082661
Invoice No. 55345 - 27082661

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	70,183 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-May-16	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 27-MAY-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	May 27, 2016 9:56:45 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	May 27, 2016 9:56:45 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	May 27, 2016 9:56:45 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	May 27, 2016 9:56:45 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	May 27, 2016 9:56:45 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	May 27, 2016 9:56:45 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	May 27, 2016 9:56:45 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	May 27, 2016 9:56:45 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	1.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27082661
Invoice No. 55345 - 27082661

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	70,183 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-May-16	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 27-MAY-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	May 27, 2016 9:58:36 PM	No	
20 - Miles			RGASPARD	May 27, 2016 9:58:36 PM	No	
30 - Kilometers			RGASPARD	May 27, 2016 9:58:36 PM	No	
40 - Hours			RGASPARD	May 27, 2016 9:58:36 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27082661 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.57

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27077967
Invoice No. 55345 - 27077967

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Battery died multiple times		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	66,635 - DH

Chronology		
Reported	Apr 26, 2016 9:06:26 AM	Apr 26, 2016 9:06:26 AM
Started	Apr 26, 2016 12:00:00 AM	
Completed	May 2, 2016 9:56:00 AM	May 2, 2016 9:56:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:
Battery died multiple times

CAUSE:
Charged batteries, then I performed a load test on each battery separately. Both batteries are bad

CORRECTION:
Replaced both batteries and installed 2 new interstate batteries.

PARTS: Line 20 Roof lights.

COMPLAINT:
2 interior roof lights are out.

CAUSE:
Normal wear

CORRECTION:
Replaced 2 interior roof lights, parts under warranty.

PARTS:
Parts under warranty. Line 30 batteries were replaced by durvin W.O 27082609

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 26-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Apr 26, 2016 9:11:51 AM	No	
20 - Miles			EDTORRES	Apr 26, 2016 9:11:51 AM	No	
30 - Kilometers			EDTORRES	Apr 26, 2016 9:11:51 AM	No	
40 - Hours			EDTORRES	Apr 26, 2016 9:11:51 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27077967
Invoice No. 55345 - 27077967

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Battery died multiple times		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	66,635 - DH

Activity Header
Activity: 15 031 CHARGING
Activity Note: Battery died multiple times
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Sep-17	MTP-24S-COR	CORE, BATTERY	2	16	32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Apr-16	Torres,Edwin	1.8333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	32.00
Labor:	0.00
Labor Hours:	1.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**32.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27077967
Invoice No. 55345 - 27077967

Client Department:
Department: 55345M
Work Order Description
Battery died multiple times
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 66,635 - DH

Activity Header
Activity: 25 034 LIGHTING SYSTEM
Activity Note: Interior roof lights
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Apr-16	9008	BULB, HEADLAMP, HALOGEN, 12V	1	5.79	5.79
26-Apr-16	9008	BULB, HEADLAMP, HALOGEN, 12V	-1	5.79	-5.79

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Apr-16	Torres,Edwin	0.5666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27077967 Total	
Parts:	32.00
Labor:	0.00
Labor Hours:	2.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**32.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27024993
Invoice No. 55345 - 27024993

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 66,142 - DH

Chronology		
Reported	Apr 28, 2016 11:55:38 AM	Apr 28, 2016 11:55:38 AM
Started	Apr 28, 2016 12:00:00 AM	
Completed	Apr 28, 2016 10:27:00 PM	Apr 28, 2016 10:27:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMB Service

CAUSE: Service Due By Mileage,

CORRECTION:change Oil / Filter ,Lube All pivoting points ,clean rear AC filter
Parts# B329 oil filter Qty (1)
Oil 5w20 Qty (6) Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Apr-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Apr-16	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 28-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Apr 28, 2016 8:21:21 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Apr 28, 2016 8:21:21 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
20,260 - Check Stop Request System	-	NA	DARTHURS	Apr 28, 2016 8:21:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Apr 28, 2016 8:21:21 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Apr 28, 2016 8:21:21 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
40,420 - Check Hood	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Apr 28, 2016 8:21:21 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Apr 28, 2016 8:21:21 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Apr 28, 2016 8:21:21 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Apr 28, 2016 8:21:21 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Apr 28, 2016 8:21:21 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Apr 28, 2016 8:21:21 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		DARTHURS	Apr 28, 2016 8:21:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
60,632 - Tread Depth LF	7 32nds of an inch		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
60,635 - Tread Depth LRI	5 32nds of an inch		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
60,636 - Tread Depth LRO	4 32nds of an inch		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Apr 28, 2016 8:21:21 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
77,135 - Brake Rotor LF	1.598 Inch		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
77,136 - Brake Rotor RF	1.596 Inch		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
77,137 - Brake Rotor LR	1.416 Inch		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
77,138 - Brake Rotor RR	1.417 Inch		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Apr 28, 2016 8:21:21 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Apr 28, 2016 8:21:21 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27024993
Invoice No. 55345 - 27024993

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 66,142 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Apr-16	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: DARTHURS Performed on: 28-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Apr 28, 2016 8:23:00 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Apr 28, 2016 8:23:00 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Apr 28, 2016 8:23:00 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Apr 28, 2016 8:23:00 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Apr 28, 2016 8:23:00 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Apr 28, 2016 8:23:00 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Apr 28, 2016 8:23:00 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Apr 28, 2016 8:23:00 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	Apr 28, 2016 8:23:00 PM	No	
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Apr 28, 2016 8:23:00 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	No		DARTHURS	Apr 28, 2016 8:23:00 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Apr 28, 2016 8:23:00 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Apr 28, 2016 8:23:00 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27024993
Invoice No. 55345 - 27024993

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM B		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	66,142 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Apr-16	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 28-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 28, 2016 8:23:30 PM	No	
20 - Miles			DARTHURS	Apr 28, 2016 8:23:30 PM	No	
30 - Kilometers			DARTHURS	Apr 28, 2016 8:23:30 PM	No	
40 - Hours			DARTHURS	Apr 28, 2016 8:23:30 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27024993 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27082609
Invoice No. 55345 - 27082609

Client Department:
Department: 55345M
Work Order Description
Battery/L/F head light and two front marker light
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 66,142 - DH

Chronology		
Reported	Apr 28, 2016 8:40:09 PM	Apr 28, 2016 8:40:09 PM
Started	Apr 28, 2016 12:00:00 AM	
Completed	Apr 28, 2016 10:26:00 PM	Apr 28, 2016 10:26:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: Bad battery, L/F head light /(2) front marker light

CAUSE:bulb blown/ Battery not holding charge,

CORRECTION: replace Battery Qty (2) inter state #MPT24S
Parts#H13 Qty (1)
Parts#168Qty (2)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 28-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 28, 2016 8:56:06 PM	No	
20 - Miles			DARTHURS	Apr 28, 2016 8:56:06 PM	No	
30 - Kilometers			DARTHURS	Apr 28, 2016 8:56:06 PM	No	
40 - Hours			DARTHURS	Apr 28, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:56:06 PM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27082609
Invoice No. 55345 - 27082609

Client Department:
Department: 55345M
Work Order Description
Battery/L/F head light and two front marker light
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 66,142 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: PMB Follow up
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Apr-16	MTP-24S	OUT OF SERVICE BATTERY	2	79.75	159.5
29-Apr-16	168	BULB, WEDGE, 12V/3CP	2	0.23	0.46
29-Apr-16	9008	BULB, HEADLAMP, HALOGEN, 12V	1	5.79	5.79

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Apr-16	Arthurs,Durvin	1.25	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	165.75
Labor:	0.00
Labor Hours:	1.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**165.75**

Work Order Footer

Work Order 27082609 Total	
Parts:	165.75
Labor:	0.00
Labor Hours:	1.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**165.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27049447
Invoice No. 55345 - 27049447

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Driver side headlight is out.		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	63,873 - DH

Chronology		
Reported	Apr 13, 2016 11:25:57 AM	Apr 13, 2016 11:25:57 AM
Started	Apr 13, 2016 12:00:00 AM	
Completed	Apr 14, 2016 7:39:00 AM	Apr 14, 2016 7:39:00 AM
Down Time		

Work Order Notes

Line 10 Headlight

COMPLAINT:
Driver side headlight is out

CAUSE:
Normal wear

CORRECTION:
Replaced driver side headlight bulb.

PARTS:
9008 headlight bulb qty 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 13-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Apr 13, 2016 11:34:27 AM	No	
20 - Miles			EDTORRES	Apr 13, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:34:27 AM		
30 - Kilometers			EDTORRES	Apr 13, 2016 11:34:27 AM	No	
40 - Hours			EDTORRES	Apr 13, 2016 11:34:27 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27049447
Invoice No. 55345 - 27049447

Client Department:
Department: 55345M
Work Order Description
Driver side headlight is out.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 63,873 - DH

Activity Header
Activity: 15 034/001/000 HEADLAMP
Activity Note: Driver side headlight is out
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Apr-16	9008	BULB, HEADLAMP, HALOGEN, 12V	1	5.79	5.79

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Apr-16	Torres,Edwin	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	5.79
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.79**

Work Order Footer

Work Order 27049447 Total	
Parts:	5.79
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26928450
Invoice No. 55345 - 26928450

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	61,881 - DH

Chronology		
Reported	Mar 28, 2016 11:40:02 AM	Mar 28, 2016 11:40:02 AM
Started	Mar 28, 2016 12:00:00 AM	
Completed	Mar 28, 2016 10:50:00 PM	Mar 28, 2016 10:50:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE:regular maintenance

CORRECTION:perform service,lube all pivoting point and cross rotate front tires completed
Parts #oil filter B329 qty1
Oil #5w20 qt6

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Mar-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Mar-16	Pierre,Hubert J	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 28-MAR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
10,100 - Safety Inspection	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	N/A	HPIERRE	Mar 28, 2016 5:06:55 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	N/A	HPIERRE	Mar 28, 2016 5:06:55 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Mar 28, 2016 5:06:55 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Mar 28, 2016 5:06:55 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Mar 28, 2016 5:06:55 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
40,420 - Check Hood	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Mar 28, 2016 5:06:55 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Mar 28, 2016 5:06:55 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Mar 28, 2016 5:06:55 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Mar 28, 2016 5:06:55 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Mar 28, 2016 5:06:55 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Mar 28, 2016 5:06:55 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Mar 28, 2016 5:06:55 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
60,631 - Tread Depth RF	6 32nds of an inch		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
60,632 - Tread Depth LF	6 32nds of an inch		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Mar 28, 2016 5:06:55 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
77,131 - Brake Pad Thickness LF	3 Inch		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
77,132 - Brake Pad Thickness RF	3 Inch		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
77,133 - Brake Pad Thickness LR	2.5 Inch		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
77,134 - Brake Pad Thickness RR	2.5 Inch		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
77,135 - Brake Rotor LF	1.6 Inch		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
77,136 - Brake Rotor RF	1.6 Inch		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
77,137 - Brake Rotor LR	1.4 Inch		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
77,138 - Brake Rotor RR	1.4 Inch		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Mar 28, 2016 5:06:55 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Mar 28, 2016 5:06:55 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26928450
Invoice No. 55345 - 26928450

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 61,881 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Mar-16	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 28-MAR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Mar 28, 2016 5:08:50 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Mar 28, 2016 5:08:50 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Mar 28, 2016 5:08:50 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Mar 28, 2016 5:08:50 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Mar 28, 2016 5:08:50 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Mar 28, 2016 5:08:50 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Mar 28, 2016 5:08:50 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Mar 28, 2016 5:08:50 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26928450
Invoice No. 55345 - 26928450

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	61,881 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Mar-16	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 28-MAR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Mar 28, 2016 5:09:25 PM	No	
20 - Miles			HPIERRE	Mar 28, 2016 5:09:25 PM	No	
30 - Kilometers			HPIERRE	Mar 28, 2016 5:09:25 PM	No	
40 - Hours			HPIERRE	Mar 28, 2016 5:09:25 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26928450 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27017068
Invoice No. 55345 - 27017068

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Check Interior lights		Ford E350 Champion Crusaders	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	61,590 - DH

Chronology		
Reported	Mar 25, 2016 9:35:50 AM	Mar 25, 2016 9:35:50 AM
Started	Mar 25, 2016 12:00:00 AM	
Completed	Mar 28, 2016 7:53:00 AM	Mar 28, 2016 7:53:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Three interior lights not glowing

CAUSE:Normal wear

CORRECTION:Three interior lights replacement

Complaint verified
Three interior Lights tested defective
Three (3) interior lights replaced
Bus returned to its predetermined spot

Parts used:
Three (3) lights led (under warranty)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Mar-16	Simon,Fritz	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 25-MAR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Mar 25, 2016 9:44:07 AM	No	
20 - Miles			FSIMON	Mar 25, 2016 9:44:07 AM	No	
30 - Kilometers			FSIMON	Mar 25, 2016 9:44:07 AM	No	
40 - Hours			FSIMON	Mar 25, 2016 9:44:07 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27017068
Invoice No. 55345 - 27017068

Client Department:
Department: 55345M
Work Order Description
Check Interior lights
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 61,590 - DH

Activity Header
Activity: 15 034 LIGHTING SYSTEM
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Mar-16	Simon,Fritz	0.75	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27017068 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26940539
Invoice No. 55345 - 26940539

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Driver Side headlight		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	58,792 - DH

Chronology		
Reported	Mar 7, 2016 7:21:57 AM	Mar 7, 2016 7:21:57 AM
Started	Mar 7, 2016 12:00:00 AM	
Completed	Mar 7, 2016 8:18:00 AM	Mar 7, 2016 8:18:00 AM
Down Time		

Work Order Notes

Line 10 Headlight

COMPLAINT:
Driver complained of bad headlight bulb on driver side.

CAUSE:
Normal wear.

CORRECTION: replaced driver side headlight bulb. Head light is working properly at this time.

Part- ford headlamp part number H13 qty 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 07-MAR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Mar 7, 2016 7:25:14 AM	No	
20 - Miles			EDTORRES	Mar 7, 2016 7:25:14 AM	No	
30 - Kilometers			EDTORRES	Mar 7, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				7:25:14 AM		
40 - Hours			EDTORRES	Mar 7, 2016 7:25:14 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26940539
Invoice No. 55345 - 26940539

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Driver Side headlight		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	58,792 - DH

Activity Header
Activity: 15 034 LIGHTING SYSTEM
Activity Note: Driver side headlight
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Mar-16	H13	BULB, CAPSULE, HEADLAMP, HALOGEN	1	7.86	7.86

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Mar-16	Torres,Edwin	0.4833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	7.86
Labor:	0.00
Labor Hours:	0.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.86**

Work Order Footer

Work Order 26940539 Total	
Parts:	7.86
Labor:	0.00
Labor Hours:	0.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.86**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26931828
Invoice No. 55345 - 26931828

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Replace side rear window on passenger side		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	58,064 - DH

Chronology		
Reported	Mar 1, 2016 8:05:54 AM	Mar 1, 2016 8:05:54 AM
Started	Mar 1, 2016 12:00:00 AM	
Completed	Mar 1, 2016 9:41:00 AM	Mar 1, 2016 9:41:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:
Found deep horizontal scratch on window

CAUSE:
Unknown

CORRECTION:
Replaced window farthest back on the left side.

Parts- side window, qty 1 # 5970740

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 01-MAR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Mar 1, 2016 8:26:03 AM	No	
20 - Miles			EDTORRES	Mar 1, 2016 8:26:03 AM	No	
30 - Kilometers			EDTORRES	Mar 1, 2016 8:26:03 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			EDTORRES	Mar 1, 2016 8:26:03 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26931828
Invoice No. 55345 - 26931828

Client Department:
Department: 55345M
Work Order Description
Replace side rear window on passenger side
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 58,064 - DH

Activity Header
Activity: 15 999 TOTAL VEHICLE
Activity Note: Replace side rear window.
Reason for Repair: 41 Abuse of Equipment - 56210
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Mar-16	5970740	OUT OF SERVICE WINDOW, FLAT, SOLID	1	105.69	105.69

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Mar-16	Torres,Edwin	2.1166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	105.69
Labor:	0.00
Labor Hours:	2.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**105.69**

Work Order Footer

Work Order 26931828 Total	
Parts:	105.69
Labor:	0.00
Labor Hours:	2.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**105.69**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26928460
Invoice No. 55345 - 26928460

Client Department:
Department: 55345M
Work Order Description
PMA follow up ------->need air filter
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 57,676 - DH

Chronology		
Reported	Feb 26, 2016 9:12:00 PM	Feb 26, 2016 9:12:00 PM
Started	Feb 26, 2016 12:00:00 AM	
Completed	Feb 26, 2016 9:19:00 PM	Feb 26, 2016 9:19:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: check air filter

CAUSE: air filter dirty

CORRECTION: replace air filter completed
Part #air filter pa4075 qty 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Feb-16	PA4075	OUT OF SERVICE DO NOT ORDER FILTER, AIR, PAPER SAME AS AF25590	1	5.18	5.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Feb-16	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 26-FEB-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Feb 26, 2016 9:19:39 PM	No	
20 - Miles			HPIERRE	Feb 26, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:19:39 PM		
30 - Kilometers			HPIERRE	Feb 26, 2016 9:19:39 PM	No	
40 - Hours			HPIERRE	Feb 26, 2016 9:19:39 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	5.18
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.18**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26928460
Invoice No. 55345 - 26928460

Client Department:
Department: 55345M
Work Order Description
PMA follow up ------->need air filter
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 57,676 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Feb-16	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26928460 Total	
Parts:	5.18
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.18**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26863583
Invoice No. 55345 - 26863583

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 57,676 - DH

Chronology		
Reported	Feb 26, 2016 10:01:30 AM	Feb 26, 2016 10:01:30 AM
Started	Feb 26, 2016 12:00:00 AM	
Completed	Feb 26, 2016 8:45:00 PM	Feb 26, 2016 8:45:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA

CAUSE:regular maintenance

CORRECTION: perform service,lube all pivoted point cross rotate front tires complete
Parts #oil filter B329 qty1
Oil#5w20 qt 6

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Feb-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Feb-16	Pierre,Hubert J	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 26-FEB-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
10,100 - Safety Inspection	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	N/A	HPIERRE	Feb 26, 2016 6:36:42 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	N/A	HPIERRE	Feb 26, 2016 6:36:42 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Feb 26, 2016 6:36:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Feb 26, 2016 6:36:42 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Feb 26, 2016 6:36:42 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
40,420 - Check Hood	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Feb 26, 2016 6:36:42 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Feb 26, 2016 6:36:42 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Feb 26, 2016 6:36:42 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Feb 26, 2016 6:36:42 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Feb 26, 2016 6:36:42 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Feb 26, 2016 6:36:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
60,631 - Tread Depth RF	7 32nds of an inch		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
60,632 - Tread Depth LF	7 32nds of an inch		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Feb 26, 2016 6:36:42 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
77,135 - Brake Rotor LF	40 Inch		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
77,136 - Brake Rotor RF	40 Inch		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
77,137 - Brake Rotor LR	38 Inch		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
77,138 - Brake Rotor RR	38 Inch		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Feb 26, 2016 6:36:42 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Feb 26, 2016 6:36:42 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26863583
Invoice No. 55345 - 26863583

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 57,676 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Feb-16	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 26-FEB-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Feb 26, 2016 6:37:32 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Feb 26, 2016 6:37:32 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Feb 26, 2016 6:37:32 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Feb 26, 2016 6:37:32 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Feb 26, 2016 6:37:32 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Feb 26, 2016 6:37:32 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Feb 26, 2016 6:37:32 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Feb 26, 2016 6:37:32 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26863583
Invoice No. 55345 - 26863583

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	57,676 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Feb-16	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 26-FEB-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Feb 26, 2016 8:45:04 PM	No	
20 - Miles			HPIERRE	Feb 26, 2016 8:45:04 PM	No	
30 - Kilometers			HPIERRE	Feb 26, 2016 8:45:04 PM	No	
40 - Hours			HPIERRE	Feb 26, 2016 8:45:04 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26863583 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26886111
Invoice No. 55345 - 26886111

Client Department:
Department: 55345M
Work Order Description
Repair and touch up bottom right corner by entrance door.
Requested By: RMANZINO
Created By: RMANZINO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 55,646 - DH

Chronology		
Reported	Feb 11, 2016 8:39:26 AM	Feb 11, 2016 8:39:26 AM
Started	Feb 11, 2016 12:00:00 AM	
Completed	Feb 11, 2016 2:37:00 PM	Feb 11, 2016 2:37:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: Repair and touch up bottom right corner by entrance door.

CAUSE: unknown

CORRECTION: repair molding and touchup paint

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Feb-16	Manzino,Robert C	0.1666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RMANZINO Performed on: 11-FEB-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RMANZINO	Feb 11, 2016 8:56:48 AM	No	
20 - Miles			RMANZINO	Feb 11, 2016 8:56:48 AM	No	
30 - Kilometers			RMANZINO	Feb 11, 2016 8:56:48 AM	No	
40 - Hours			RMANZINO	Feb 11, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:56:48 AM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26886111
Invoice No. 55345 - 26886111

Client Department:
Department: 55345M
Work Order Description
Repair and touch up bottom right corner by entrance door.
Requested By: RMANZINO
Created By: RMANZINO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 55,646 - DH

Activity Header
Activity: 15 999 TOTAL VEHICLE
Activity Note: Repair and touch up bottom right corner by entrance door.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Feb-16	Manzino,Robert C	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26886111 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26871114
Invoice No. 55345 - 26871114

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Driver complained of lift issues.		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	53,952 - DH

Chronology		
Reported	Feb 1, 2016 6:15:49 AM	Feb 1, 2016 6:15:49 AM
Started	Feb 1, 2016 12:00:00 AM	
Completed	Feb 1, 2016 8:19:00 AM	Feb 1, 2016 8:19:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT:
Driver submitted a complaint about lift needing re adjustment.

CORRECTION- noticed rear tower getting stuck when raising lift. Lubricated lift with 3in 1 lubricating oil and at this time the lift is working properly. Also adjusted switch for bridge plate.

No parts used at this time.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Feb-16	Torres,Edwin	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 01-FEB-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Feb 1, 2016 6:24:49 AM	No	
20 - Miles			EDTORRES	Feb 1, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				6:24:49 AM		
30 - Kilometers			EDTORRES	Feb 1, 2016 6:24:49 AM	No	
40 - Hours			EDTORRES	Feb 1, 2016 6:24:49 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26871114
Invoice No. 55345 - 26871114

Client Department:
Department: 55345M
Work Order Description
Driver complained of lift issues.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 53,952 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Feb-16	Torres,Edwin	0.8333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26871114 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26718166
Invoice No. 55345 - 26718166

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 53,456 - DH

Chronology

Reported	Jan 26, 2016 3:23:00 PM	Jan 26, 2016 3:23:00 PM
Started	Jan 26, 2016 12:00:00 AM	
Completed	Jan 26, 2016 11:44:00 PM	Jan 26, 2016 11:44:00 PM
Down Time		

Work Order Notes

Line 10 PmC
Service
Perform pmC service
Oil filter B329 qty1
Engine oil 5w20 qty 6qts
Transmission filter 8C3Z-7A098-D qty1
Transmission fluid 10 qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Jan-16	8C3Z-7A098-D	FILTER, TRANSMISSION	1	36.5	36.5
27-Jan-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Jan-16	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 26-JAN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,100 - Safety Inspection	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Jan 26, 2016 10:48:36 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Jan 26, 2016 10:48:36 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	na	RGASPARD	Jan 26, 2016 10:48:36 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Jan 26, 2016 10:48:36 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Jan 26, 2016 10:48:36 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
40,420 - Check Hood	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Jan 26, 2016 10:48:36 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Jan 26, 2016 10:48:36 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Jan 26, 2016 10:48:36 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Jan 26, 2016 10:48:36 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Jan 26, 2016 10:48:36 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Jan 26, 2016 10:48:36 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	Jan 26, 2016 10:48:36 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
60,632 - Tread Depth LF	7 32nds of an inch		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
60,633 - Tread Depth RRO	9 32nds of an inch		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
60,670 - Check Dual Mating With Square	-	na	RGASPARD	Jan 26, 2016 10:48:36 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
77,131 - Brake Pad Thickness LF	11 Inch		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
77,132 - Brake Pad Thickness RF	11 Inch		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
77,135 - Brake Rotor LF	37 Inch		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
77,136 - Brake Rotor RF	37 Inch		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
77,137 - Brake Rotor LR	34 Inch		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
77,138 - Brake Rotor RR	34 Inch		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Jan 26, 2016 10:48:36 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Jan 26, 2016 10:48:36 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	38.42
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**38.42**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26718166
Invoice No. 55345 - 26718166

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 53,456 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Jan-16	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: RGASPARD Performed on: 26-JAN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jan 26, 2016 10:50:22 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jan 26, 2016 10:50:22 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jan 26, 2016 10:50:22 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jan 26, 2016 10:50:22 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Jan 26, 2016 10:50:22 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jan 26, 2016 10:50:22 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	na	RGASPARD	Jan 26, 2016 10:50:22 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jan 26, 2016 10:50:22 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Jan 26, 2016 10:50:22 PM	No	
201,000 - Service Crankcase Breather	Done		RGASPARD	Jan 26, 2016 10:50:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	Yes		RGASPARD	Jan 26, 2016 10:50:22 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Jan 26, 2016 10:50:22 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Jan 26, 2016 10:50:22 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		RGASPARD	Jan 26, 2016 10:50:22 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		RGASPARD	Jan 26, 2016 10:50:22 PM	No	
302,000 - Check Toe-In and Record Reading	-	na	RGASPARD	Jan 26, 2016 10:50:22 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	na	RGASPARD	Jan 26, 2016 10:50:22 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		RGASPARD	Jan 26, 2016 10:50:22 PM	No	
305,000 - FRA Change Differential Fluid	No		RGASPARD	Jan 26, 2016 10:50:22 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26718166
Invoice No. 55345 - 26718166

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM C		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	53,456 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Jan-16	Gaspard,Ronald	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 26-JAN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jan 26, 2016 10:50:52 PM	No	
20 - Miles			RGASPARD	Jan 26, 2016 10:50:52 PM	No	
30 - Kilometers			RGASPARD	Jan 26, 2016 10:50:52 PM	No	
40 - Hours			RGASPARD	Jan 26, 2016 10:50:52 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26718166 Total	
Parts:	38.42
Labor:	0.00
Labor Hours:	3.05

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**38.42**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26718164
Invoice No. 55345 - 26718164

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
REPLACE FRONT AND REAR BRAKES		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	49,284 - DH

Chronology		
Reported	Dec 21, 2015 11:42:00 PM	Dec 21, 2015 11:42:00 PM
Started	Dec 21, 2015 12:00:00 AM	
Completed	Dec 21, 2015 11:58:00 PM	Dec 21, 2015 11:58:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT: needs front and rear brakes job.

CAUSE:normal wear.

CORRECTION: replaced front and rear brake pads.lubed guide pins
Rotate tires . Torque tires 140 lbs, tested drive second torque 140lbs
Part number BRSD 1328 qty 1front
Part number BRSD 1329 qty 1 rear

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Dec-15	Gaspard,Ronald	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 21-DEC-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Dec 21, 2015 11:57:16 PM	No	
20 - Miles			RGASPARD	Dec 21, 2015 11:57:16 PM	No	
30 - Kilometers			RGASPARD	Dec 21, 2015 11:57:16 PM	No	
40 - Hours			RGASPARD	Dec 21, 2015 11:57:16 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26718164
Invoice No. 55345 - 26718164

Client Department:
Department: 55345M
Work Order Description
REPLACE FRONT AND REAR BRAKES
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 49,284 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: REPLACE FRONT AND REAR BRAKES
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Dec-15	BRSD-1328	PADS, BRAKE, DISC, FRONT	1	50.32	50.32
22-Dec-15	BRSD-1328	PADS, BRAKE, DISC, FRONT	-1	50.32	-50.32
22-Dec-15	BRSD1329	PADS, BRAKE, DISC, E450	1	44.48	44.48

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Dec-15	Gaspard,Ronald	3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	94.80
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**94.80**

Work Order Footer

Work Order 26718164 Total	
Parts:	94.80
Labor:	0.00
Labor Hours:	3.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**94.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26602402
Invoice No. 55345 - 26602402

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	49,284 - DH

Chronology		
Reported	Dec 21, 2015 12:26:35 PM	Dec 21, 2015 12:26:35 PM
Started	Dec 21, 2015 12:00:00 AM	
Completed	Dec 21, 2015 11:48:00 PM	Dec 21, 2015 11:48:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:service

CORRECTION: perform pmA service
Oil filter B329 qty1
Engine oil 5w20 qty 6qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Dec-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Dec-15	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 21-DEC-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Dec 21, 2015 11:33:26 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Dec 21, 2015 11:33:26 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Dec 21, 2015 11:33:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Dec 21, 2015 11:33:26 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Dec 21, 2015 11:33:26 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
40,420 - Check Hood	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Dec 21, 2015 11:33:26 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Dec 21, 2015 11:33:26 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Dec 21, 2015 11:33:26 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Dec 21, 2015 11:33:26 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Dec 21, 2015 11:33:26 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Dec 21, 2015 11:33:26 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	Dec 21, 2015 11:33:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
60,631 - Tread Depth RF	7 32nds of an inch		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
60,632 - Tread Depth LF	7 32nds of an inch		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
60,633 - Tread Depth RRO	9 32nds of an inch		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
60,635 - Tread Depth LRI	10 32nds of an inch		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
60,636 - Tread Depth LRO	10 32nds of an inch		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
60,670 - Check Dual Mating With Square	-	na	RGASPARD	Dec 21, 2015 11:33:26 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
77,131 - Brake Pad Thickness LF	4 Inch		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
77,132 - Brake Pad Thickness RF	4 Inch		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
77,133 - Brake Pad Thickness LR	4 Inch		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
77,134 - Brake Pad Thickness RR	4 Inch		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
77,137 - Brake Rotor LR	34 Inch		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
77,138 - Brake Rotor RR	34 Inch		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Dec 21, 2015 11:33:26 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Dec 21, 2015 11:33:26 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26602402
Invoice No. 55345 - 26602402

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 49,284 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Dec-15	Gaspard,Ronald	0.6666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 21-DEC-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Dec 21, 2015 11:34:09 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Dec 21, 2015 11:34:09 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Dec 21, 2015 11:34:09 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Dec 21, 2015 11:34:09 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Dec 21, 2015 11:34:09 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Dec 21, 2015 11:34:09 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Dec 21, 2015 11:34:09 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Dec 21, 2015 11:34:09 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.67
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26602402
Invoice No. 55345 - 26602402

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	49,284 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Dec-15	Gaspard,Ronald	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 21-DEC-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Dec 21, 2015 11:34:58 PM	No	
20 - Miles			RGASPARD	Dec 21, 2015 11:34:58 PM	No	
30 - Kilometers			RGASPARD	Dec 21, 2015 11:34:58 PM	No	
40 - Hours			RGASPARD	Dec 21, 2015 11:34:58 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26602402 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.22

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26605068
Invoice No. 55345 - 26605068

Client Department:
Department: 55345M
Work Order Description
Lower left rear view mirror is broken
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 44,959 - DH

Chronology		
Reported	Nov 23, 2015 7:35:44 AM	Nov 23, 2015 7:35:44 AM
Started	Nov 23, 2015 12:00:00 AM	
Completed	Nov 23, 2015 7:52:00 AM	Nov 23, 2015 7:52:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT:
Lower left rear view mirror is broken

CAUSE:
Accident

CORRECTION:
Replaced lower mirror on driver side due to accident.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Nov-15	Torres,Edwin	0.0333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 23-NOV-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Nov 23, 2015 7:52:24 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			EDTORRES	Nov 23, 2015 7:52:24 AM	No	
30 - Kilometers			EDTORRES	Nov 23, 2015 7:52:24 AM	No	
40 - Hours			EDTORRES	Nov 23, 2015 7:52:24 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26605068
Invoice No. 55345 - 26605068

Client Department:
Department: 55345M
Work Order Description
Lower left rear view mirror is broken
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 44,959 - DH

Activity Header
Activity: 15 034 LIGHTING SYSTEM
Activity Note: Lower left rear view mirror is broken
Reason for Repair: 41 Abuse of Equipment - 56210
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Dec-15	709589	MIRROR, CONVEX, SENTRY W/BASE	1	24.96	24.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Nov-15	Torres,Edwin	0.75	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	24.96
Labor:	0.00
Labor Hours:	0.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**24.96**

Work Order Footer

Work Order 26605068 Total	
Parts:	24.96
Labor:	0.00
Labor Hours:	0.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**24.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26553491
Invoice No. 55345 - 26553491

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	44,803 - DH

Chronology		
Reported	Nov 19, 2015 3:24:39 PM	Nov 19, 2015 3:24:39 PM
Started	Nov 19, 2015 12:00:00 AM	
Completed	Nov 19, 2015 11:59:00 PM	Nov 19, 2015 11:59:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE: service

CORRECTION: perform pmA service.
Part number oil filter B329 qty1
Engine oil 5W20 qty 6qts.
Pulled all tires . Checked brakes.
Torque tires to spec.. 140lbs ,test drive second torque 140 lbs.

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Nov-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Nov-15	Gaspard,Ronald	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 19-NOV-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Nov 19, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:48:51 PM		
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Nov 19, 2015 11:48:51 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Nov 19, 2015 11:48:51 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Nov 19, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:48:51 PM		
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Nov 19, 2015 11:48:51 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Nov 19, 2015 11:48:51 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
40,420 - Check Hood	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Nov 19, 2015 11:48:51 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Nov 19, 2015 11:48:51 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Nov 19, 2015 11:48:51 PM	No	
40,450 - FRA Check Coolant Recovery System	Done		RGASPARD	Nov 19, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Condition & for Leaks				11:48:51 PM		
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Nov 19, 2015 11:48:51 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Nov 19, 2015 11:48:51 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Nov 19, 2015 11:48:51 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
60,616 - Air Pressure LRO	70 Pounds per		RGASPARD	Nov 19, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			11:48:51 PM		
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
60,632 - Tread Depth LF	7 32nds of an inch		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
60,633 - Tread Depth RRO	11 32nds of an inch		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
60,634 - Tread Depth RRI	11 32nds of an inch		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
60,636 - Tread Depth LRO	11 32nds of an inch		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
60,670 - Check Dual Mating With Square	-	na	RGASPARD	Nov 19, 2015 11:48:51 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
77,100 - FRA Check Security, Integrity and	Done		RGASPARD	Nov 19, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Length of Ground Straps				11:48:51 PM		
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
77,137 - Brake Rotor LR	34 Inch		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
77,138 - Brake Rotor RR	34 Inch		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Nov 19, 2015 11:48:51 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Nov 19, 2015 11:48:51 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26553491
Invoice No. 55345 - 26553491

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	44,803 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Nov-15	Gaspard,Ronald	0.7333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 19-NOV-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Nov 19, 2015 11:49:40 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Nov 19, 2015 11:49:40 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Nov 19, 2015 11:49:40 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Nov 19, 2015 11:49:40 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Nov 19, 2015 11:49:40 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Nov 19, 2015 11:49:40 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Nov 19, 2015 11:49:40 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Nov 19, 2015 11:49:40 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.73
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26553491
Invoice No. 55345 - 26553491

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	44,803 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Nov-15	Gaspard,Ronald	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 19-NOV-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Nov 19, 2015 11:50:11 PM	No	
20 - Miles			RGASPARD	Nov 19, 2015 11:50:11 PM	No	
30 - Kilometers			RGASPARD	Nov 19, 2015 11:50:11 PM	No	
40 - Hours			RGASPARD	Nov 19, 2015 11:50:11 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26553491 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.78

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26599062
Invoice No. 55345 - 26599062

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Check vehicle for alignment		Ford E350 Champion Crusaders	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	44,387 - DH

Chronology		
Reported	Nov 18, 2015 8:19:21 AM	Nov 18, 2015 8:19:21 AM
Started	Nov 18, 2015 8:42:00 AM	
Completed	Nov 18, 2015 8:45:00 AM	Nov 18, 2015 8:45:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT:Alignment needed

CAUSE:Tire small wear

CORRECTION:Front tires swapped

Vehicle road tested
Small pulling toward passenger side noticed
Front tires swapped
Vehicle drive tested ok.

No parts utilized

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Nov-15	Simon,Fritz	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 18-NOV-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Nov 18, 2015 8:41:20 AM	No	
20 - Miles			FSIMON	Nov 18, 2015 8:41:20 AM	No	
30 - Kilometers			FSIMON	Nov 18, 2015 8:41:20 AM	No	
40 - Hours			FSIMON	Nov 18, 2015 8:41:20 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26599062
Invoice No. 55345 - 26599062

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Check vehicle for alignment		Ford E350 Champion Crusaders	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	44,387 - DH

Activity Header
Activity: 15 016 SUSPENSION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Nov-15	Simon,Fritz	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26599062 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26575482
Invoice No. 55345 - 26575482

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Installed exhaust hanger		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	42,870 - DH

Chronology		
Reported	Nov 6, 2015 6:17:42 PM	Nov 6, 2015 6:17:42 PM
Started	Nov 6, 2015 6:24:00 PM	
Completed	Nov 6, 2015 7:38:00 PM	Nov 6, 2015 7:38:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT: EXHAUST HANGERS BROKE TWO OF THEM

CAUSE:VIBRATIONS OF THE BUS TAIL PIPE

CORRECTION: REMOVE TWO EXHAUST HANGERS REINSTALL TWO EXHAUST HANGERS
PARTS NUMBERS# 72660 QTY2 AND QTY 2 71658-1

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Nov-15	Owens,Arthur	0.03	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List						
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: AOWENS Performed on: 06-NOV-15						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Nov 6, 2015 7:37:09 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			AOWENS	Nov 6, 2015 7:37:09 PM	No	
30 - Kilometers			AOWENS	Nov 6, 2015 7:37:09 PM	No	
40 - Hours			AOWENS	Nov 6, 2015 7:37:09 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26575482
Invoice No. 55345 - 26575482

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Installed exhaust hanger		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	42,870 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Installed exhaust hanger
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Nov-15	72660	USE PUNCH-OUT HANGER, EXHAUST, STEEL, 5PK	2	2.33	4.66
09-Nov-15	71658-1	CLAMP, MUFFLER, EXHAUST, DUTY, HEAVY, SADDLE, 3"	2	2.17	4.34

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Nov-15	Owens,Arthur	1.18	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	9.00
Labor:	0.00
Labor Hours:	1.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**9.00**

Work Order Footer

Work Order 26575482 Total	
Parts:	9.00
Labor:	0.00
Labor Hours:	1.21
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**9.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26505520
Invoice No. 55345 - 26505520

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 40,505 - DH

Chronology		
Reported	Oct 21, 2015 10:22:51 AM	Oct 21, 2015 10:22:51 AM
Started	Oct 21, 2015 12:00:00 AM	
Completed	Oct 21, 2015 7:52:00 PM	Oct 21, 2015 7:52:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pm b

CAUSE: regular maintenance

CORRECTION: perform service and lube all pivoting point completed

Parts: oil filter # b329 qty 1
Parts : oil # 5w20 qt 6

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Oct-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.82	1.82
17-Nov-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	-1	1.84	-1.84
17-Nov-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Oct-15	Pierre,Hubert J	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
10 Desc: Light Mediun Duty PMI Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 21-OCT-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
10,100 - Safety Inspection	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	N/A	HPIERRE	Oct 21, 2015 7:44:36 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	N/A	HPIERRE	Oct 21, 2015 7:44:36 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Oct 21, 2015 7:44:36 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Oct 21, 2015 7:44:36 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Oct 21, 2015 7:44:36 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
40,420 - Check Hood	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Oct 21, 2015 7:44:36 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Oct 21, 2015 7:44:36 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Oct 21, 2015 7:44:36 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Oct 21, 2015 7:44:36 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Oct 21, 2015 7:44:36 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
60,631 - Tread Depth RF	11 32nds of an inch		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
60,632 - Tread Depth LF	11 32nds of an inch		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
60,633 - Tread Depth RRO	12 32nds of an inch		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
60,636 - Tread Depth LRO	12 32nds of an inch		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Oct 21, 2015 7:44:36 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
77,135 - Brake Rotor LF	38 Inch		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
77,136 - Brake Rotor RF	38 Inch		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
77,137 - Brake Rotor LR	34 Inch		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
77,138 - Brake Rotor RR	34 Inch		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Oct 21, 2015 7:44:36 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Oct 21, 2015 7:44:36 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.90
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.90**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26505520
Invoice No. 55345 - 26505520

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 40,505 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Oct-15	Pierre,Hubert J	0.95	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: HPIERRE Performed on: 21-OCT-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Oct 21, 2015 7:46:00 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Oct 21, 2015 7:46:00 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Oct 21, 2015 7:46:00 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Oct 21, 2015 7:46:00 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Oct 21, 2015 7:46:00 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Oct 21, 2015 7:46:00 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Oct 21, 2015 7:46:00 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Oct 21, 2015 7:46:00 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		HPIERRE	Oct 21, 2015 7:46:00 PM	No	
201,000 - Service Crankcase Breather	Done		HPIERRE	Oct 21, 2015 7:46:00 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	No		HPIERRE	Oct 21, 2015 7:46:00 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		HPIERRE	Oct 21, 2015 7:46:00 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		HPIERRE	Oct 21, 2015 7:46:00 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26505520
Invoice No. 55345 - 26505520

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM B		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	40,505 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Oct-15	Pierre,Hubert J	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 21-OCT-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Oct 21, 2015 7:46:23 PM	No	
20 - Miles			HPIERRE	Oct 21, 2015 7:46:23 PM	No	
30 - Kilometers			HPIERRE	Oct 21, 2015 7:46:23 PM	No	
40 - Hours			HPIERRE	Oct 21, 2015 7:46:23 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26505520 Total	
Parts:	1.90
Labor:	0.00
Labor Hours:	2.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.90**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26275980
Invoice No. 55345 - 26275980

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	LCAPAZZOLI	**Status:**	40 - Closed (40)
Created By:	LCAPAZZOLI	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	36,158 - DH

Chronology

Reported	Sep 23, 2015 4:18:42 PM	Sep 23, 2015 4:18:42 PM
Started	Sep 23, 2015 10:32:00 PM	
Completed	Sep 23, 2015 10:42:00 PM	Sep 23, 2015 10:42:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pm service

CAUSE:maintenance

CORRECTION:perform service.
Oil filter B329 qty 1
Engine oil 5w20 qty 6qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: LIGHT MEDIUM DUTY PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: LIGHT MEDIUM DUTY PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 23-SEP-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,140 - Check Service Brakes	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Sep 23, 2015 10:14:01 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Sep 23, 2015 10:14:01 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Sep 23, 2015 10:14:01 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Sep 23, 2015 10:14:01 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Sep 23, 2015 10:14:01 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
40,420 - Check Hood	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Sep 23, 2015 10:14:01 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Sep 23, 2015 10:14:01 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Sep 23, 2015 10:14:01 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Sep 23, 2015 10:14:01 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Sep 23, 2015 10:14:01 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Sep 23, 2015 10:14:01 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
60,631 - Tread Depth RF	11 32nds of an inch		RGASPARD	Sep 23, 2015 10:14:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,632 - Tread Depth LF	11 32nds of an inch		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
60,633 - Tread Depth RRO	12 32nds of an inch		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
60,635 - Tread Depth LRI	11 32nds of an inch		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
60,636 - Tread Depth LRO	11 32nds of an inch		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
60,670 - Check Dual Mating With Square	-	na	RGASPARD	Sep 23, 2015 10:14:01 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,131 - Brake Pad Thickness LF	10 Inch		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
77,137 - Brake Rotor LR	34 Inch		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
77,138 - Brake Rotor RR	34 Inch		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Sep 23, 2015 10:14:01 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Sep 23, 2015 10:14:01 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26275980
Invoice No. 55345 - 26275980

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	LCAPAZZOLI	**Status:**	40 - Closed (40)
Created By:	LCAPAZZOLI	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	36,158 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PMA
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Sep-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.52	1.52

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PMA
Task: PM A SERVICE Performed by: RGASPARD Performed on: 23-SEP-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Sep 23, 2015 10:15:37 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Sep 23, 2015 10:15:37 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Sep 23, 2015 10:15:37 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Sep 23, 2015 10:15:37 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Sep 23, 2015 10:15:37 PM	No	
105,000 - Replace or Clean A/C Filters	-	na	RGASPARD	Sep 23, 2015 10:15:37 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Sep 23, 2015 10:15:37 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Sep 23, 2015 10:15:37 PM	No	

Activity Sub Total

Activity 20 Sub Total
Parts: 1.52

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.52**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26275980
Invoice No. 55345 - 26275980

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	LCAPAZZOLI	**Status:**	40 - Closed (40)
Created By:	LCAPAZZOLI	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	36,158 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment and Meter Reading
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Sep-15	Gaspard,Ronald	0.02	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: Personal Risk Assessment and Meter Reading
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 23-SEP-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Sep 23, 2015 10:33:46 PM	No	
20 - Miles			RGASPARD	Sep 23, 2015 10:33:46 PM	No	
30 - Kilometers			RGASPARD	Sep 23, 2015 10:33:46 PM	No	
40 - Hours			RGASPARD	Sep 23, 2015 10:33:46 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26275980 Total	
Parts:	1.52
Labor:	0.00
Labor Hours:	0.02

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.52**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26447365
Invoice No. 55345 - 26447365

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Install a new driver side step.		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	34,456 - DH

Chronology		
Reported	Sep 14, 2015 9:47:29 AM	Sep 14, 2015 9:47:29 AM
Started	Sep 14, 2015 12:00:00 AM	
Completed	Sep 14, 2015 9:51:00 AM	Sep 14, 2015 9:51:00 AM
Down Time		

Work Order Notes

Line 10 Install a new driver side step.

Installed new driver retro step. Tested step several times, feels snug and secured in place.

No shop parts used. Parts under warranty.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Sep-15	Torres,Edwin	0.0333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 14-SEP-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Sep 14, 2015 9:49:58 AM	No	
20 - Miles			EDTORRES	Sep 14, 2015 9:49:58 AM	No	
30 - Kilometers			EDTORRES	Sep 14, 2015 9:49:58 AM	No	
40 - Hours			EDTORRES	Sep 14, 2015 9:49:58 AM	No	

Activity Sub Total

Activity 5 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.03
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26447365
Invoice No. 55345 - 26447365

Client Department:
Department: 55345M
Work Order Description
Install a new driver side step.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 34,456 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note: Install a new driver side step.
Reason for Repair: 23 Modification
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Sep-15	Torres,Edwin	1.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26447365 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26403537
Invoice No. 55345 - 26403537

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Wheelchair lift not working		Ford E350 Champion Crusaders	
Requested By:	RMANZINO	**Status:**	40 - Closed (40)
Created By:	RMANZINO	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	32,780 - DH

Chronology		
Reported	Sep 2, 2015 11:48:35 AM	Sep 2, 2015 11:48:35 AM
Started	Sep 2, 2015 12:00:00 AM	
Completed	Sep 2, 2015 11:55:00 AM	Sep 2, 2015 11:55:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT: driver complaint of wheelchair lift not working

CAUSE: confirmed complaint and diagnosed as control pennant not receiving power

CORRECTION: found the ground wire pin backed out of the connection for the pennant. Removed pin, fixed pin locks, gave wire slack, reinstalled pin in connector housing. All ok at this time. Line 20 No parts used

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RMANZINO Performed on: 02-SEP-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RMANZINO	Sep 2, 2015 11:54:23 AM	No	
20 - Miles			RMANZINO	Sep 2, 2015 11:54:23 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26403537
Invoice No. 55345 - 26403537

Client Department:
Department: 55345M
Work Order Description
Wheelchair lift not working
Requested By: RMANZINO
Created By: RMANZINO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 32,780 - DH

Activity Header
Activity: 15
Activity Note: Diagnose wheel chair lift issue
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Sep-15	Manzino,Robert C	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26403537 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26276400
Invoice No. 55345 - 26276400

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Needs seatbelt extension.		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	31,873 - DH

Chronology		
Reported	Aug 26, 2015 8:37:47 AM	Aug 26, 2015 8:37:47 AM
Started	Aug 26, 2015 12:00:00 AM	
Completed	Aug 26, 2015 8:46:00 AM	Aug 26, 2015 8:46:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT: driver complained that seatbelt extension is missing.

CORRECTION: place a new seatbelt extension in vehicle.

PARTS: Ford seatbelt extension
part# Q5-6340 (1) QTY

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Aug-15	Torres,Edwin	0.0333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 26-AUG-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Aug 26, 2015 8:46:05 AM	No	
20 - Miles			EDTORRES	Aug 26, 2015 8:46:05 AM	No	

Activity Sub Total

Activity 5 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.03
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26276400
Invoice No. 55345 - 26276400

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Needs seatbelt extension.		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	31,873 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Needs seatbelt extension.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
31-Aug-15	Q8-6340	BELT, SEAT, LAP, W/C, QSTRAINT SAME AS Q86340	1	20.64	20.64

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Aug-15	Torres,Edwin	0.75	0	0
26-Aug-15	Torres,Edwin	-0.3833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	20.64
Labor:	0.00
Labor Hours:	0.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**20.64**

Work Order Footer

Work Order 26276400 Total	
Parts:	20.64
Labor:	0.00
Labor Hours:	0.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**20.64**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26202691
Invoice No. 55345 - 26202691

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	31,873 - DH

Chronology		
Reported	Aug 25, 2015 2:22:26 PM	Aug 25, 2015 2:22:26 PM
Started	Aug 25, 2015 6:38:00 PM	
Completed	Aug 25, 2015 7:56:00 PM	Aug 25, 2015 7:56:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION: Line 20 Perform pma inspection. Change oil. Oil filter

Parts. 6 quarts oil. 5w-20. 1 oil filter b329

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Aug-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.52	1.52

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: LCAPAZZOLI Performed on: 25-AUG-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
10,100 - Safety Inspection	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
10,140 - Check Service Brakes	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
10,160 - FRA Check Instruments and Horns	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
10,170 - Check Fast Idle	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
10,180 - Check Starter Protection Circuit	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
10,190 - Check Reverse Warning System	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
11,100 - Check Parking Brake	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
11,150 - Perform Brake Test	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
11,170 - FRA Check Door Operation	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
20,210 - Check Condition of Operator's Area	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
20,240 - FRA Check Interior Lights	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
20,260 - Check Stop Request System	-	n/a	LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
22,110 - Check Emergency Hatches	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
22,120 - Check All Safety Equipment	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
30,310 - Check Passenger Doors	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
30,360 - Check for Physical Damage and Decals	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
30,380 - Check Exterior Compartment Doors	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
33,100 - Check Lights and Reflectors	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
40,420 - Check Hood	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	-	n/a	LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
44,130 - FRA Check Exhaust System	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
44,140 - FRA Check Intake System	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
44,180 - FRA Check for Leaks	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
44,190 - FRA Perform Battery Inspection	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
50,510 - Check Entire Steering System	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
60,630 - Check and Record Tread Depth	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
60,631 - Tread Depth RF	16 32nds of an inch		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
60,632 - Tread Depth LF	16 32nds of an inch		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
60,633 - Tread Depth RRO	16 32nds of an inch		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
60,634 - Tread Depth RRI	16 32nds of an inch		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
60,635 - Tread Depth LRI	16 32nds of an inch		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
60,636 - Tread Depth LRO	16 32nds of an inch		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
60,650 - Check Sidewall Wear	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
60,660 - Inspect for Cuts and Tears	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
70,710 - Check Vibration Damper	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
70,730 - FRA Check Starter	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
70,770 - FRA Check Exhaust System	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
77,120 - Check Suspension Components	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
77,135 - Brake Rotor LF	Inch	n/a	LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
77,136 - Brake Rotor RF	Inch	n/a	LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
77,137 - Brake Rotor LR	Inch	n/a	LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
77,138 - Brake Rotor RR	Inch	n/a	LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
77,140 - FRA Check Brake Hoses	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
77,150 - Check King Pins	-	n/a	LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
80,810 - Completion of PMI Report	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		LCAPAZZOLI	Aug 25, 2015 7:53:32 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.52
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.52**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26202691
Invoice No. 55345 - 26202691

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DCARTER
Created By: DCARTER
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 31,873 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A SERVICE
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Aug-15	Capazzoli,Louis	1.27	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A SERVICE
Task: PM A SERVICE Performed by: LCAPAZZOLI Performed on: 25-AUG-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		LCAPAZZOLI	Aug 25, 2015 7:53:07 PM	No	
101,000 - FRA Change Oil Filters	Yes		LCAPAZZOLI	Aug 25, 2015 7:53:07 PM	No	
102,000 - FRA Drain Engine Oil	Yes		LCAPAZZOLI	Aug 25, 2015 7:53:07 PM	No	
103,000 - FRA Check Transmission Fluid	Done		LCAPAZZOLI	Aug 25, 2015 7:53:07 PM	No	
104,000 - Lubricate Chassis	Done		LCAPAZZOLI	Aug 25, 2015 7:53:07 PM	No	
105,000 - Replace or Clean A/C Filters	Done		LCAPAZZOLI	Aug 25, 2015 7:53:07 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	LCAPAZZOLI	Aug 25, 2015 7:53:07 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		LCAPAZZOLI	Aug 25, 2015 7:53:07 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	1.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26202691
Invoice No. 55345 - 26202691

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	31,873 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 25-AUG-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Aug 25, 2015 7:25:07 PM	No	
20 - Miles			LCAPAZZOLI	Aug 25, 2015 7:25:07 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26202691 Total	
Parts:	1.52
Labor:	0.00
Labor Hours:	1.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.52**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26268606
Invoice No. 55345 - 26268606

Client Department:
Department: 55345M
Work Order Description
Needs new tires
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 30,891 - DH

Chronology		
Reported	Aug 20, 2015 8:31:01 AM	Aug 20, 2015 8:31:01 AM
Started	Aug 20, 2015 12:00:00 AM	
Completed	Aug 20, 2015 9:10:00 AM	Aug 20, 2015 9:10:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:
Check tires for low tread

CAUSE:
Normal wear

CORRECTION:
Mounted and balanced 2 Bridgestone tires. Placed 2 new tires on the rear right. Placed 2 used michelins on the rear left. The michelins have 11/32 of thread. Set tires to 70 psi. Torque lug nuts to 140 LBS. Test drove. Re-torqued to 140 LBS. Washed rear rims because they were there dirty.

Parts. Bridgestone tires. Part # 206361 qty 2

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Aug-15	Torres,Edwin	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 20-AUG-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Aug 20, 2015 8:49:39 AM	No	
20 - Miles			EDTORRES	Aug 20, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:49:39 AM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26268606
Invoice No. 55345 - 26268606

Client Department:
Department: 55345M
Work Order Description
Needs new tires
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 30,891 - DH

Activity Header
Activity: 15 017 TIRES, TUBES, LINERS & VALVES
Activity Note: Replace rear tires
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Aug-15	206361	TIRE, LT225/75R16, BSW, R250, DURAVIS, BRIDGESTONE	2	151.66	303.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Aug-15	Torres,Edwin	1.5166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	303.32
Labor:	0.00
Labor Hours:	1.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**303.32**

Work Order Footer

Work Order 26268606 Total	
Parts:	303.32
Labor:	0.00
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**303.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26255324
Invoice No. 55345 - 26255324

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Change engine air filter.		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	29,552 - DH

Chronology		
Reported	Aug 10, 2015 11:32:40 PM	Aug 10, 2015 11:32:40 PM
Started	Aug 10, 2015 12:00:00 AM	
Completed	Aug 11, 2015 12:06:00 AM	Aug 11, 2015 12:06:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:
Change engine air filter.

CAUSE:
Manufacturer recommended maintenance.

CORRECTION:
Replaced engine air filter with a new Baldwin filter.

Parts- Baldwin engine air filter Part # PA4075 QTY-1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 11-AUG-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Aug 11, 2015 12:06:31 AM	No	
20 - Miles			AOWENS	Aug 11, 2015 12:06:31 AM	No	

Activity Sub Total

Activity 5 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26255324
Invoice No. 55345 - 26255324

Client Department:
Department: 55345M
Work Order Description
Change engine air filter.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 29,552 - DH

Activity Header
Activity: 15 041 INTAKE, AIR
Activity Note: Change engine air filter.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Aug-15	PA4075	OUT OF SERVICE DO NOT ORDER FILTER, AIR, PAPER SAME AS AF25590	1	5.18	5.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Aug-15	Torres,Edwin	0.4833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	5.18
Labor:	0.00
Labor Hours:	0.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.18**

Work Order Footer

Work Order 26255324 Total	
Parts:	5.18
Labor:	0.00
Labor Hours:	0.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.18**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26251480
Invoice No. 55345 - 26251480

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
perform front brake job		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	29,127 - DH

Chronology		
Reported	Aug 7, 2015 3:30:00 PM	Aug 7, 2015 3:30:00 PM
Started	Aug 8, 2015 12:00:00 AM	
Completed	Aug 8, 2015 12:40:00 AM	Aug 8, 2015 12:40:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT:

CAUSE:

CORRECTION: replaced front brake pads .parts number.....brsd 1228

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 07-AUG-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Aug 7, 2015 11:46:40 PM	No	
20 - Miles			RGASPARD	Aug 7, 2015 11:46:40 PM	No	

Activity Sub Total

	Activity 5 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26251480
Invoice No. 55345 - 26251480

Client Department:
Department: 55345M
Work Order Description
perform front brake job
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 29,127 - DH

Activity Header
Activity: 15 013 BRAKES
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Aug-15	BRSD-1328	PADS, BRAKE, DISC, FRONT	1	50.32	50.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Aug-15	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	50.32
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**50.32**

Work Order Footer

Work Order 26251480 Total	
Parts:	50.32
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**50.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26217099
Invoice No. 55345 - 26217099

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Saftety. Belt loose on wheelchair lift		Ford E350 Champion Crusaders	
Requested By:	LCAPAZZOLI	**Status:**	40 - Closed (40)
Created By:	LCAPAZZOLI	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	27,803 - DH

Chronology		
Reported	Jul 30, 2015 5:45:54 PM	Jul 30, 2015 5:45:54 PM
Started	Jul 30, 2015 6:07:00 PM	
Completed	Jul 30, 2015 6:41:00 PM	Jul 30, 2015 6:41:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT: Driver is complaining that Seat belt on lift is loose.

CAUSE:

CORRECTION: seatbelt was not loose, the seatbelt clip was the part that was loose on lift. I tighten seat belt clip. No parts used.

No parts used.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 30-JUL-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Jul 30, 2015 6:40:07 PM	No	
20 - Miles			LCAPAZZOLI	Jul 30, 2015 6:40:07 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26217099
Invoice No. 55345 - 26217099

Client Department:
Department: 55345M
Work Order Description
Saftety. Belt loose on wheelchair lift
Requested By: LCAPAZZOLI
Created By: LCAPAZZOLI
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 27,803 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Safety belt loose on wheelchair lift
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Jul-15	Capazzoli,Louis	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26217099 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26083373
Invoice No. 55345 - 26083373

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM C		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	27,500 - DH

Chronology		
Reported	Jul 27, 2015 12:00:00 AM	Jul 27, 2015 12:00:00 AM
Started	Jul 27, 2015 12:00:00 AM	
Completed	Jul 28, 2015 3:10:12 PM	Jul 28, 2015 3:10:12 PM
Down Time		

Work Order Notes

Line 10 PM-C COMPLED

REPLACED OIL FILTER
CHANGED ENGINE OIL
ADD WASHER FLUID

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: 55345-PM C INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Jul-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.18	1.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Jul-15	Gaspard,Ronald	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.18
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.18**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26083373
Invoice No. 55345 - 26083373

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM C		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	27,500 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: 55345-PM C SERVICE
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26083373
Invoice No. 55345 - 26083373

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM C		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	27,500 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26083373 Total	
Parts:	1.18
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.18**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26112769
Invoice No. 55345 - 26112769

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
2 NEW TIRES		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	24,863 - DH

Chronology		
Reported	Jul 3, 2015 9:58:00 AM	Jul 3, 2015 9:58:00 AM
Started	Jul 3, 2015 12:00:00 AM	
Completed	Jul 10, 2015 10:11:57 AM	Jul 10, 2015 10:11:57 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT:

CAUSE:

CORRECTION: Line 20 NEED TIRES

2 NEW FRONT TIRES AND ROTATE TIRES , TORQUE TIRES TO SPEC

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles					No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26112769
Invoice No. 55345 - 26112769

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
2 NEW TIRES		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	24,863 - DH

Activity Header
Activity: 10 017 TIRES, TUBES, LINERS & VALVES
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Jul-15	08404	TIRE, LT225/75R16, MICHELIN SEE ATTACHED DOCUMENT	2	234.08	468.16

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jul-15	Gaspard,Ronald	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	468.16
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**468.16**

Work Order Footer

Work Order 26112769 Total	
Parts:	468.16
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**468.16**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 25945119
Invoice No. 55345 - 25945119

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	22,402 - DH

Chronology		
Reported	Jun 19, 2015 12:00:00 AM	Jun 19, 2015 12:00:00 AM
Started	Jun 19, 2015 12:00:00 AM	
Completed	Jun 23, 2015 3:18:00 PM	Jun 23, 2015 3:18:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION: Line 20 PM-A SERVICE COMPLETED
REPLACED OIL FILTER
CHANGED ENGINE OIL
WASHER FLUID

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: PM A INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Jun-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	2	1.77	3.54
23-Jun-15	Q5-8522	POUCH, STORAGE, Q-STRAINT, NYLON	1	33.92	33.92
30-Jun-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	-1	1.18	-1.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Jun-15	Gaspard,Ronald	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	36.28
Labor:	0.00

	Labor Hours:	2.50
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**36.28**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 25945119
Invoice No. 55345 - 25945119

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	22,402 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A SERVICE
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 25945119
Invoice No. 55345 - 25945119

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	22,402 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 25945119 Total	
Parts:	36.28
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**36.28**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 25963534
Invoice No. 55345 - 25963534

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
REAR BRAKE PADS		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	18,457 - DH

Chronology		
Reported	May 29, 2015 4:02:00 PM	May 29, 2015 4:02:00 PM
Started	May 29, 2015 12:00:00 AM	
Completed	May 29, 2015 4:09:19 PM	May 29, 2015 4:09:19 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT:

CAUSE:

CORRECTION: Line 20 REAR BRAKES

COMPLETED REAR

BRAKE JOB INSPECT

ALL REAR BRAKE ASSEMBLY

TORQUE TIRES 140

ROAD TESTED TORQUE, 2ND TIME 140

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 25963534
Invoice No. 55345 - 25963534

Client Department:
Department: 55345M
Work Order Description
REAR BRAKE PADS
Requested By: DCARTER
Created By: DCARTER
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5447
VIN: 1FDEE3FLXFDA02748
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 18,457 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-May-15	BRSD1329	PADS, BRAKE, DISC, E450	1	44.48	44.48

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-May-15	Capazzoli,Louis	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	44.48
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**44.48**

Work Order Footer

Work Order 25963534 Total	
Parts:	44.48
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**44.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 25887603
Invoice No. 55345 - 25887603

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	17,700 - DH

Chronology		
Reported	May 19, 2015 12:00:00 AM	May 19, 2015 12:00:00 AM
Started	May 19, 2015 12:00:00 AM	
Completed	May 20, 2015 10:03:54 AM	May 20, 2015 10:03:54 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION: Line 20

PM-A SERVICE PERFORM.

REPLACED OIL FILTER.

CHANGED ENGINE OIL.

WASHER FLUID ADDED.

ROTATE TIRES AND TORQUE TO SPEC.

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: PM A INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-May-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.71	1.71

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-May-15	Gaspard,Ronald	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.71
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.71**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 25887603
Invoice No. 55345 - 25887603

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	17,700 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A SERVICE
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 25887603
Invoice No. 55345 - 25887603

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	17,700 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 25887603 Total	
Parts:	1.71
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.71**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 25744181
Invoice No. 55345 - 25744181

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM B		Ford E350 Champion Crusaders	
Requested By:	KCONCEPCION	**Status:**	40 - Closed (40)
Created By:	KCONCEPCION	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	13,055 - DH

Chronology		
Reported	Apr 20, 2015 12:00:00 AM	Apr 20, 2015 12:00:00 AM
Started	Apr 20, 2015 12:00:00 AM	
Completed	Apr 21, 2015 9:15:07 AM	Apr 21, 2015 9:15:07 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION: Line 20 Replaced Oil Filter
Changed Engine Oil
Rotate and Torque Tires to Spec.
Washed Fluid Added.

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: PM B INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Apr-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.63	1.63

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Apr-15	Prevalus,Rodner	3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.63
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.63**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 25744181
Invoice No. 55345 - 25744181

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM B		Ford E350 Champion Crusaders	
Requested By:	KCONCEPCION	**Status:**	40 - Closed (40)
Created By:	KCONCEPCION	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	13,055 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B SERVICE
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 25744181
Invoice No. 55345 - 25744181

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM B		Ford E350 Champion Crusaders	
Requested By:	KCONCEPCION	**Status:**	40 - Closed (40)
Created By:	KCONCEPCION	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	13,055 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 25744181 Total	
Parts:	1.63
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.63**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 25734156
Invoice No. 55345 - 25734156

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	8,535 - DH

Chronology		
Reported	Mar 13, 2015 12:00:00 AM	Mar 13, 2015 12:00:00 AM
Started	Mar 13, 2015 12:00:00 AM	
Completed	Mar 20, 2015 3:00:39 PM	Mar 20, 2015 3:00:39 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION:

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: PM A INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Mar-15	Capazzoli,Louis	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 25734156
Invoice No. 55345 - 25734156

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	8,535 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A SERVICE
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 25734156
Invoice No. 55345 - 25734156

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
PM A		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	8,535 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 25734156 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 24687481
Invoice No. 55345 - 24687481

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
--> Followup on WO 25533721		Ford E350 Champion Crusaders	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	3,814 - DH

Chronology		
Reported	Feb 13, 2015 12:00:00 AM	Feb 13, 2015 12:00:00 AM
Started	Feb 13, 2015 12:00:00 AM	
Completed	Mar 16, 2015 3:14:28 PM	Mar 16, 2015 3:14:28 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION:

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: PM A INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Feb-15	Gaspard,Ronald	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 24687481
Invoice No. 55345 - 24687481

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
--> Followup on WO 25533721		Ford E350 Champion Crusaders	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	3,814 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A SERVICE
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 24687481
Invoice No. 55345 - 24687481

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
--> Followup on WO 25533721		Ford E350 Champion Crusaders	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	3,814 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 24687481 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 25533721
Invoice No. 55345 - 25533721

Client Department:			
Department:	55345M	**Equipment No.:**	5447
Work Order Description		**VIN:**	1FDEE3FLXFDA02748
Followup to PM WO 24687481		Ford E350 Champion Crusaders	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	3,814 - DH

Chronology		
Reported	Feb 23, 2015 12:00:00 AM	Feb 23, 2015 12:00:00 AM
Started		
Completed	Mar 16, 2015 3:11:25 PM	Mar 16, 2015 3:11:25 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

Activity Header
Activity: 1
Activity Note:
Reason for Repair: 11 Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 1 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 25533721 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

WorkOrder: 51210290
Invoice Number: 55345-51210290

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FLXFDA02748
Requested By:	DARTHURS	**Status:**	40
Created By:	DARTHURS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	May 9, 2018	10:33 AM
Started	May 9, 2018	
Completed	May 9, 2018	11:04 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	162,652	DH
System	162,824	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service CAUSE: Service due by Mileage CORRECTION: Change Oil& Filter.Lube all Pivoting Points. Check Brakes. Clean batteries. Replace A/C Filter. Replace front clearance light.clearance light shop supply. Qty (1) Parts# B329 Qty (1) Oil 5W20 Qty (6.5) Qt

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
09-May-18	Arthurs,Durvin	1.50	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

WorkOrder: 51210290
Invoice Number: 55345-51210290

Client Department:
MRC: 55345M
WO Desc:
PM A
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5447
Ford E350 Champion Crusaders
VIN: 1FDEE3FLXFDA02748
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Date	Part Number		Description	Qty.	Each	Extended
09-May-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96
09-May-18	F75Z-6730-BA		PLUG, DRAIN, OIL, ENGINE, 3.0L	1.00	6.66	6.66

Labor Posted

Date	Technician	Hours	Rate	Extended
09-May-18	Arthurs,Durvin	0.42	0.00	0.00

Activity 20 Sub Total

Parts:	8.62
Labor:	0.00
Labor Hours: 0.42	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.62**

Activity: 30 **999 TOTAL VEHICLE**

Activity Note: PRAMETER
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
09-May-18	Arthurs,Durvin	0.08	0.00	0.00

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.08	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

WorkOrder 51210290 Grand Total

Parts:	8.62
Labor:	0.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	**8.62**

WorkOrder: 51210290
Invoice Number: 55345-51210290

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FLXFDA02748
Requested By:	DARTHURS	**Status:**	40
Created By:	DARTHURS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
51384307	1-Jun-18	165,709	WO	Vehicle needs a window latch for the sliding window
51367053	23-May-18	164,544	WO	55345 SPARK PLUG GAS BUSSES
51336287	9-May-18	162,652	WO	Front Brakes& Tag light
51210290	9-May-18	162,652	WO	PM A
51091083	10-Apr-18	158,343	WO	PM A

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
51210235	10-Apr-18	158,343	WO	Rear Tires/Rear Brakes/ Serpentine belts

PH: Work Order: 51210290 Desc: PM A
Equip: 5447 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FLXFDA02748

LH: 10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 09-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	May 9, 2018 8:09:10 PM	No	
10,100	Safety Inspection	Done		DARTHURS	May 9, 2018 8:09:10 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	May 9, 2018 8:09:10 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		DARTHURS	May 9, 2018 8:09:10 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	May 9, 2018 8:09:10 PM	No	
10,140	Check Service Brakes	Done		DARTHURS	May 9, 2018 8:09:11 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	May 9, 2018 8:09:11 PM	No	
10,160	FRA Check Instruments and Horns	Done		DARTHURS	May 9, 2018 8:09:11 PM	No	
10,170	Check Fast Idle	Done		DARTHURS	May 9, 2018 8:09:11 PM	No	
10,180	Check Starter Protection Circuit	Done		DARTHURS	May 9, 2018 8:09:11 PM	No	
10,190	Check Reverse Warning System	Done		DARTHURS	May 9, 2018 8:09:11 PM	No	
11,100	Check Parking Brake	Done		DARTHURS	May 9, 2018 8:09:12 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		DARTHURS	May 9, 2018 8:09:12 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	May 9, 2018 8:09:12 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		DARTHURS	May 9, 2018 8:09:12 PM	No	
11,140	Road Test: Check for Proper Operation	Done		DARTHURS	May 9, 2018 8:09:12 PM	No	
11,150	Perform Brake Test	Done		DARTHURS	May 9, 2018 8:09:12 PM	No	
11,152	Decelerometer Results Test 1	FEET	NA	DARTHURS	May 9, 2018 8:09:12 PM	No	
11,154	Decelerometer Results Test 2	FEET	NA	DARTHURS	May 9, 2018 8:09:12 PM	No	
11,156	Decelerometer Results Test 3	FEET	NA	DARTHURS	May 9, 2018 8:09:13 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	May 9, 2018 8:09:13 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	May 9, 2018 8:09:13 PM	No	
11,170	FRA Check Door Operation	Done		DARTHURS	May 9, 2018 8:09:13 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		DARTHURS	May 9, 2018 8:09:13 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		DARTHURS	May 9, 2018 8:09:13 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		DARTHURS	May 9, 2018 8:09:13 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		DARTHURS	May 9, 2018 8:09:13 PM	No	
20,230	FRA Check Wiring Under Dash	Done		DARTHURS	May 9, 2018 8:09:14 PM	No	
20,240	FRA Check Interior Lights	Done		DARTHURS	May 9, 2018 8:09:14 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		DARTHURS	May 9, 2018 8:09:14 PM	No	
20,260	Check Stop Request System	-	NA	DARTHURS	May 9, 2018 8:09:14 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	May 9, 2018 8:09:14 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	May 9, 2018 8:09:14 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	May 9, 2018 8:09:14 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		DARTHURS	May 9, 2018 8:09:14 PM	No	
22,110	Check Emergency Hatches	Done		DARTHURS	May 9, 2018 8:09:15 PM	No	
22,120	Check All Safety Equipment	Done		DARTHURS	May 9, 2018 8:09:15 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		DARTHURS	May 9, 2018 8:09:15 PM	No	
30,310	Check Passenger Doors	Done		DARTHURS	May 9, 2018 8:09:15 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		DARTHURS	May 9, 2018 8:09:15 PM	No	
30,330	Check Wheelchair Lift Operation	Done		DARTHURS	May 9, 2018 8:09:15 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	NA	DARTHURS	May 9, 2018 8:09:16 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		DARTHURS	May 9, 2018 8:09:16 PM	No	
30,360	Check for Physical Damage and Decals	Done		DARTHURS	May 9, 2018 8:09:16 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		DARTHURS	May 9, 2018 8:09:16 PM	No	
30,380	Check Exterior Compartment Doors	Done		DARTHURS	May 9, 2018 8:09:16 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		DARTHURS	May 9, 2018 8:09:16 PM	No	
33,100	Check Lights and Reflectors	Done		DARTHURS	May 9, 2018 8:09:16 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	May 9, 2018 8:09:16 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		DARTHURS	May 9, 2018 8:09:17 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	May 9, 2018 8:09:17 PM	No	
40,420	Check Hood	Done		DARTHURS	May 9, 2018 8:09:17 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		DARTHURS	May 9, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					8:09:17 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	May 9, 2018 8:09:17 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	May 9, 2018 8:09:17 PM	No	
40,442	Freeze Point	Degree Fahrenheit	NA	DARTHURS	May 9, 2018 8:09:18 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	May 9, 2018 8:09:17 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	May 9, 2018 8:09:18 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	May 9, 2018 8:09:18 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	May 9, 2018 8:09:18 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		DARTHURS	May 9, 2018 8:09:18 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		DARTHURS	May 9, 2018 8:09:18 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	May 9, 2018 8:09:18 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		DARTHURS	May 9, 2018 8:09:19 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	May 9, 2018 8:09:19 PM	No	
44,130	FRA Check Exhaust System	Done		DARTHURS	May 9, 2018 8:09:19 PM	No	
44,140	FRA Check Intake System	Done		DARTHURS	May 9, 2018 8:09:19 PM	No	
44,150	FRA Inspect Turbocharger	-	NA	DARTHURS	May 9, 2018 8:09:19 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	May 9, 2018 8:09:19 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		DARTHURS	May 9, 2018 8:09:19 PM	No	
44,180	FRA Check for Leaks	Done		DARTHURS	May 9, 2018 8:09:19 PM	No	
44,190	FRA Perform Battery Inspection	Done		DARTHURS	May 9, 2018 8:09:20 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	May 9, 2018 8:09:20 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		DARTHURS	May 9, 2018 8:09:20 PM	No	
50,510	Check Entire Steering System	Done		DARTHURS	May 9, 2018 8:09:20 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	May 9, 2018 8:09:20 PM	No	
60,610	FRA Check and Record Air Pressure	Done		DARTHURS	May 9, 2018 8:09:20 PM	No	
60,611	Air Pressure RF	70 Pounds per Square Inch		DARTHURS	May 9, 2018 8:09:21 PM	No	
60,612	Air Pressure LF	70 Pounds per Square Inch		DARTHURS	May 9, 2018 8:09:21 PM	No	
60,613	Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	May 9, 2018 8:09:21 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	May 9, 2018 8:09:21 PM	No	
60,615	Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	May 9, 2018 8:09:21 PM	No	
60,616	Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	May 9, 2018 8:09:21 PM	No	
60,620	Check Valve Stems and Caps	Done		DARTHURS	May 9, 2018 8:09:21 PM	No	
60,630	Check and Record Tread Depth	Done		DARTHURS	May 9, 2018 8:09:21 PM	No	
60,631	Tread Depth RF	6 32nds of an inch		DARTHURS	May 9, 2018 8:09:21 PM	No	
60,632	Tread Depth LF	6 32nds of an inch		DARTHURS	May 9, 2018 8:09:22 PM	No	
60,633	Tread Depth RRO	12 32nds of an inch		DARTHURS	May 9, 2018 8:09:22 PM	No	
60,634	Tread Depth RRI	12 32nds of an inch		DARTHURS	May 9, 2018 8:09:22 PM	No	
60,635	Tread Depth LRI	12 32nds of an inch		DARTHURS	May 9, 2018 8:09:22 PM	No	
60,636	Tread Depth LRO	12 32nds of an inch		DARTHURS	May 9, 2018 8:09:22 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		DARTHURS	May 9, 2018 8:09:22 PM	No	
60,650	Check Sidewall Wear	Done		DARTHURS	May 9, 2018 8:09:22 PM	No	
60,660	Inspect for Cuts and Tears	Done		DARTHURS	May 9, 2018 8:09:22 PM	No	
60,670	Check Dual Mating With Square	-	NA	DARTHURS	May 9, 2018 8:09:22 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	May 9, 2018 8:09:23 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		DARTHURS	May 9, 2018 8:09:23 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		DARTHURS	May 9, 2018 8:09:23 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		DARTHURS	May 9, 2018 8:09:23 PM	No	
70,710	Check Vibration Damper	Done		DARTHURS	May 9, 2018 8:09:23 PM	No	
70,720	Check Engine and Transmission Mounts	Done		DARTHURS	May 9, 2018 8:09:23 PM	No	
70,730	FRA Check Starter	Done		DARTHURS	May 9, 2018 8:09:23 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	May 9, 2018 8:09:23 PM	No	
70,750	FRA Check Transmission for Leaks	Done		DARTHURS	May 9, 2018 8:09:23 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		DARTHURS	May 9, 2018 8:09:23 PM	No	
70,770	FRA Check Exhaust System	Done		DARTHURS	May 9, 2018 8:09:23 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	May 9, 2018 8:09:24 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		DARTHURS	May 9, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					8:09:24 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	May 9, 2018 8:09:24 PM	No	
77,110	FRA Check Fuel Tank	Done		DARTHURS	May 9, 2018 8:09:24 PM	No	
77,120	Check Suspension Components	Done		DARTHURS	May 9, 2018 8:09:24 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	May 9, 2018 8:09:24 PM	No	
77,131	Brake Pad Thickness LF	3 Inch		DARTHURS	May 9, 2018 8:09:24 PM	No	
77,132	Brake Pad Thickness RF	4 Inch		DARTHURS	May 9, 2018 8:09:24 PM	No	
77,133	Brake Pad Thickness LR	8 Inch		DARTHURS	May 9, 2018 8:09:25 PM	No	
77,134	Brake Pad Thickness RR	8 Inch		DARTHURS	May 9, 2018 8:09:25 PM	No	
77,135	Brake Rotor LF	1.556 Inch		DARTHURS	May 9, 2018 8:09:25 PM	No	
77,136	Brake Rotor RF	1.557 Inch		DARTHURS	May 9, 2018 8:09:25 PM	No	
77,137	Brake Rotor LR	1.418 Inch		DARTHURS	May 9, 2018 8:09:25 PM	No	
77,138	Brake Rotor RR	1.417 Inch		DARTHURS	May 9, 2018 8:09:25 PM	No	
77,140	FRA Check Brake Hoses	Done		DARTHURS	May 9, 2018 8:09:25 PM	No	
77,150	Check King Pins	-	NA	DARTHURS	May 9, 2018 8:09:25 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	May 9, 2018 8:09:26 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		DARTHURS	May 9, 2018 8:09:26 PM	No	
80,810	Completion of PMI Report	Done		DARTHURS	May 9, 2018 8:09:26 PM	No	
90,000	SECTION 9 Completion of PMI	Done		DARTHURS	May 9, 2018 8:09:26 PM	No	
90,910	Vehicle Returned to predetermined location	Done		DARTHURS	May 9, 2018 8:09:26 PM	No	

LH: 20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 09-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		DARTHURS	May 9, 2018 8:10:15 PM	No	
101,000	FRA Change Oil Filters	Yes		DARTHURS	May 9, 2018 8:10:15 PM	No	
102,000	FRA Drain Engine Oil	Yes		DARTHURS	May 9, 2018 8:10:16 PM	No	
103,000	FRA Check Transmission Fluid	Done		DARTHURS	May 9, 2018 8:10:15 PM	No	
104,000	Lubricate Chassis	Done		DARTHURS	May 9, 2018 8:10:16 PM	No	
105,000	Replace or Clean A/C Filters	Done		DARTHURS	May 9, 2018 8:10:16 PM	No	
107,000	FRA Change Primary Fuel Filter	No	NA	DARTHURS	May 9, 2018 8:10:16 PM	No	
108,000	Lube all pivoting Mechanisms	Done		DARTHURS	May 9, 2018 8:10:16 PM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 09-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	May 9, 2018 8:10:40 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	

WorkOrder: 51408878
Invoice Number: 55345-51408878

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FLXFDA02748
Requested By:	CKARLENS	**Status:**	40
Created By:	CKARLENS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jul 6, 2018	9:57 AM
Started	Jul 6, 2018	
Completed	Jul 7, 2018	12:00 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	170,683	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service CAUSE: Service due by Mileage CORRECTION: Change Oil & Filter. lube all Pivoting Points.check brakes .clean batteries .replace A/C Filter. & Replace Air cleaner. Parts# B329 Qty (1) Parts# PA 4075 Qty (1) Oil 5W20QTY (6.5) Qt

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
06-Jul-18	Arthurs,Durvin	1.50	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **079 DEVICES, SAFETY/STABILITY, TRAILER**

Activity Note: PM A Replace Air filter
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

WorkOrder: 51408878
Invoice Number: 55345-51408878

Client Department:
MRC: 55345M
WO Desc:
PM A
Requested By: CKARLENS
Created By: CKARLENS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5447
Ford E350 Champion Crusaders
VIN: 1FDEE3FLXFDA02748
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Date	Part Number		Description	Qty.	Each	Extended
06-Jul-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96
06-Jul-18	PA4075		FILTER, AIR, PAPER SAME AS AF25590	1.00	5.28	5.28

Labor Posted

Date	Technician	Hours	Rate	Extended
06-Jul-18	Arthurs,Durvin	0.42	0.00	0.00

Activity 20 Sub Total

Parts:	7.24
Labor:	0.00
Labor Hours: 0.42	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.24**

Activity: 30 **999 TOTAL VEHICLE**

Activity Note: PRAMETER
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
06-Jul-18	Arthurs,Durvin	0.08	0.00	0.00

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.08	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

WorkOrder 51408878 Grand Total

Parts:	7.24
Labor:	0.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	**7.24**

WorkOrder: 51408878
Invoice Number: 55345-51408878

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FLXFDA02748
Requested By:	CKARLENS	**Status:**	40
Created By:	CKARLENS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
51408878	7-Jul-18	170,683	WO	PM A
51488523	6-Jul-18	170,683	WO	Front Tire& Lefthub seal
51408864	12-Jun-18	166,616	WO	FOLLOW UP PMB
51336458	7-Jun-18	166,616	WO	PM B

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
51488523	6-Jul-18	170,683	WO	Front Tire& Lefthub seal
51210235	10-Apr-18	158,343	WO	Rear Tires/Rear Brakes/ Serpentine belts

PH: Work Order: 51408878 Desc: PM A
Equip: 5447 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FLXFDA02748

LH: 10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 06-JUL-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Jul 6, 2018 10:46:21 PM	No	
10,100	Safety Inspection	Done		DARTHURS	Jul 6, 2018 10:46:21 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jul 6, 2018 10:46:21 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		DARTHURS	Jul 6, 2018 10:46:21 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Jul 6, 2018 10:46:21 PM	No	
10,140	Check Service Brakes	Done		DARTHURS	Jul 6, 2018 10:46:21 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Jul 6, 2018 10:46:21 PM	No	
10,160	FRA Check Instruments and Horns	Done		DARTHURS	Jul 6, 2018 10:46:21 PM	No	
10,170	Check Fast Idle	Done		DARTHURS	Jul 6, 2018 10:46:22 PM	No	
10,180	Check Starter Protection Circuit	Done		DARTHURS	Jul 6, 2018 10:46:22 PM	No	
10,190	Check Reverse Warning System	Done		DARTHURS	Jul 6, 2018 10:46:22 PM	No	
11,100	Check Parking Brake	Done		DARTHURS	Jul 6, 2018 10:46:22 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		DARTHURS	Jul 6, 2018 10:46:22 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Jul 6, 2018 10:46:22 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		DARTHURS	Jul 6, 2018 10:46:22 PM	No	
11,140	Road Test: Check for Proper Operation	Done		DARTHURS	Jul 6, 2018 10:46:22 PM	No	
11,150	Perform Brake Test	Done		DARTHURS	Jul 6, 2018 10:46:23 PM	No	
11,152	Decelerometer Results Test 1	FEET	NA	DARTHURS	Jul 6, 2018 10:46:23 PM	No	
11,154	Decelerometer Results Test 2	FEET	NA	DARTHURS	Jul 6, 2018 10:46:23 PM	No	
11,156	Decelerometer Results Test 3	FEET	NA	DARTHURS	Jul 6, 2018 10:46:23 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Jul 6, 2018 10:46:23 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Jul 6, 2018 10:46:23 PM	No	
11,170	FRA Check Door Operation	Done		DARTHURS	Jul 6, 2018 10:46:23 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		DARTHURS	Jul 6, 2018 10:46:23 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		DARTHURS	Jul 6, 2018 10:46:24 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		DARTHURS	Jul 6, 2018 10:46:24 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		DARTHURS	Jul 6, 2018 10:46:24 PM	No	
20,230	FRA Check Wiring Under Dash	Done		DARTHURS	Jul 6, 2018 10:46:24 PM	No	
20,240	FRA Check Interior Lights	Done		DARTHURS	Jul 6, 2018 10:46:24 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		DARTHURS	Jul 6, 2018 10:46:24 PM	No	
20,260	Check Stop Request System	-	NA	DARTHURS	Jul 6, 2018 10:46:24 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Jul 6, 2018 10:46:24 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Jul 6, 2018 10:46:25 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Jul 6, 2018 10:46:24 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		DARTHURS	Jul 6, 2018 10:46:25 PM	No	
22,110	Check Emergency Hatches	Done		DARTHURS	Jul 6, 2018 10:46:25 PM	No	
22,120	Check All Safety Equipment	Done		DARTHURS	Jul 6, 2018 10:46:25 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Jul 6, 2018 10:46:25 PM	No	
30,310	Check Passenger Doors	Done		DARTHURS	Jul 6, 2018 10:46:25 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		DARTHURS	Jul 6, 2018 10:46:25 PM	No	
30,330	Check Wheelchair Lift Operation	Done		DARTHURS	Jul 6, 2018 10:46:25 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Jul 6, 2018 10:46:26 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		DARTHURS	Jul 6, 2018 10:46:26 PM	No	
30,360	Check for Physical Damage and Decals	Done		DARTHURS	Jul 6, 2018 10:46:26 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		DARTHURS	Jul 6, 2018 10:46:26 PM	No	
30,380	Check Exterior Compartment Doors	Done		DARTHURS	Jul 6, 2018 10:46:26 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		DARTHURS	Jul 6, 2018 10:46:26 PM	No	
33,100	Check Lights and Reflectors	Done		DARTHURS	Jul 6, 2018 10:46:26 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Jul 6, 2018 10:46:26 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Jul 6, 2018 10:46:27 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Jul 6, 2018 10:46:27 PM	No	
40,420	Check Hood	Done		DARTHURS	Jul 6, 2018 10:46:27 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		DARTHURS	Jul 6, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:46:27 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Jul 6, 2018 10:46:28 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Jul 6, 2018 10:46:28 PM	No	
40,442	Freeze Point	Degree Fahrenheit	NA	DARTHURS	Jul 6, 2018 10:46:27 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Jul 6, 2018 10:46:27 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Jul 6, 2018 10:46:28 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Jul 6, 2018 10:46:28 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Jul 6, 2018 10:46:28 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		DARTHURS	Jul 6, 2018 10:46:28 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		DARTHURS	Jul 6, 2018 10:46:29 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Jul 6, 2018 10:46:29 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Jul 6, 2018 10:46:29 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Jul 6, 2018 10:46:29 PM	No	
44,130	FRA Check Exhaust System	Done		DARTHURS	Jul 6, 2018 10:46:29 PM	No	
44,140	FRA Check Intake System	Done		DARTHURS	Jul 6, 2018 10:46:29 PM	No	
44,150	FRA Inspect Turbocharger	-	NA	DARTHURS	Jul 6, 2018 10:46:29 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Jul 6, 2018 10:46:29 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Jul 6, 2018 10:46:30 PM	No	
44,180	FRA Check for Leaks	Done		DARTHURS	Jul 6, 2018 10:46:30 PM	No	
44,190	FRA Perform Battery Inspection	Done		DARTHURS	Jul 6, 2018 10:46:30 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Jul 6, 2018 10:46:30 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		DARTHURS	Jul 6, 2018 10:46:30 PM	No	
50,510	Check Entire Steering System	Done		DARTHURS	Jul 6, 2018 10:46:30 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Jul 6, 2018 10:46:30 PM	No	
60,610	FRA Check and Record Air Pressure	Done		DARTHURS	Jul 6, 2018 10:46:30 PM	No	
60,611	Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Jul 6, 2018 10:46:31 PM	No	
60,612	Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Jul 6, 2018 10:46:31 PM	No	
60,613	Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Jul 6, 2018 10:46:31 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Jul 6, 2018 10:46:31 PM	No	
60,615	Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Jul 6, 2018 10:46:31 PM	No	
60,616	Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Jul 6, 2018 10:46:32 PM	No	
60,620	Check Valve Stems and Caps	Done		DARTHURS	Jul 6, 2018 10:46:31 PM	No	
60,630	Check and Record Tread Depth	Done		DARTHURS	Jul 6, 2018 10:46:31 PM	No	
60,631	Tread Depth RF	3 32nds of an inch		DARTHURS	Jul 6, 2018 10:46:32 PM	No	
60,632	Tread Depth LF	3 32nds of an inch		DARTHURS	Jul 6, 2018 10:46:32 PM	No	
60,633	Tread Depth RRO	9 32nds of an inch		DARTHURS	Jul 6, 2018 10:46:32 PM	No	
60,634	Tread Depth RRI	10 32nds of an inch		DARTHURS	Jul 6, 2018 10:46:32 PM	No	
60,635	Tread Depth LRI	10 32nds of an inch		DARTHURS	Jul 6, 2018 10:46:32 PM	No	
60,636	Tread Depth LRO	11 32nds of an inch		DARTHURS	Jul 6, 2018 10:46:32 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		DARTHURS	Jul 6, 2018 10:46:32 PM	No	
60,650	Check Sidewall Wear	Done		DARTHURS	Jul 6, 2018 10:46:32 PM	No	
60,660	Inspect for Cuts and Tears	Done		DARTHURS	Jul 6, 2018 10:46:32 PM	No	
60,670	Check Dual Mating With Square	-	NA	DARTHURS	Jul 6, 2018 10:46:33 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Jul 6, 2018 10:46:33 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Jul 6, 2018 10:46:33 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done	Left hub leaking	DARTHURS	Jul 6, 2018 10:46:33 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Jul 6, 2018 10:46:33 PM	No	
70,710	Check Vibration Damper	Done		DARTHURS	Jul 6, 2018 10:46:33 PM	No	
70,720	Check Engine and Transmission Mounts	Done		DARTHURS	Jul 6, 2018 10:46:33 PM	No	
70,730	FRA Check Starter	Done		DARTHURS	Jul 6, 2018 10:46:33 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Jul 6, 2018 10:46:34 PM	No	
70,750	FRA Check Transmission for Leaks	Done		DARTHURS	Jul 6, 2018 10:46:34 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		DARTHURS	Jul 6, 2018 10:46:34 PM	No	
70,770	FRA Check Exhaust System	Done		DARTHURS	Jul 6, 2018 10:46:34 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Jul 6, 2018 10:46:34 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		DARTHURS	Jul 6, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:46:34 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Jul 6, 2018 10:46:34 PM	No	
77,110	FRA Check Fuel Tank	Done		DARTHURS	Jul 6, 2018 10:46:34 PM	No	
77,120	Check Suspension Components	Done		DARTHURS	Jul 6, 2018 10:46:35 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Jul 6, 2018 10:46:35 PM	No	
77,131	Brake Pad Thickness LF	10 Inch		DARTHURS	Jul 6, 2018 10:46:35 PM	No	
77,132	Brake Pad Thickness RF	10 Inch		DARTHURS	Jul 6, 2018 10:46:35 PM	No	
77,133	Brake Pad Thickness LR	6 Inch		DARTHURS	Jul 6, 2018 10:46:35 PM	No	
77,134	Brake Pad Thickness RR	6 Inch		DARTHURS	Jul 6, 2018 10:46:35 PM	No	
77,135	Brake Rotor LF	1.553 Inch		DARTHURS	Jul 6, 2018 10:46:36 PM	No	
77,136	Brake Rotor RF	1.554 Inch		DARTHURS	Jul 6, 2018 10:46:36 PM	No	
77,137	Brake Rotor LR	1.416 Inch		DARTHURS	Jul 6, 2018 10:46:35 PM	No	
77,138	Brake Rotor RR	1.414 Inch		DARTHURS	Jul 6, 2018 10:46:36 PM	No	
77,140	FRA Check Brake Hoses	Done		DARTHURS	Jul 6, 2018 10:46:36 PM	No	
77,150	Check King Pins	-	NA	DARTHURS	Jul 6, 2018 10:46:36 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Jul 6, 2018 10:46:36 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		DARTHURS	Jul 6, 2018 10:46:36 PM	No	
80,810	Completion of PMI Report	Done		DARTHURS	Jul 6, 2018 10:46:36 PM	No	
90,000	SECTION 9 Completion of PMI	Done		DARTHURS	Jul 6, 2018 10:46:36 PM	No	
90,910	Vehicle Returned to predetermined location	Done		DARTHURS	Jul 6, 2018 10:46:36 PM	No	

LH: 20 Desc: PM A Replace Air filter
Task: PM A SERVICE Performed by: DARTHURS Performed on: 06-JUL-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		DARTHURS	Jul 6, 2018 10:47:28 PM	No	
101,000	FRA Change Oil Filters	Yes		DARTHURS	Jul 6, 2018 10:47:28 PM	No	
102,000	FRA Drain Engine Oil	Yes		DARTHURS	Jul 6, 2018 10:47:28 PM	No	
103,000	FRA Check Transmission Fluid	Done		DARTHURS	Jul 6, 2018 10:47:28 PM	No	
104,000	Lubricate Chassis	Done		DARTHURS	Jul 6, 2018 10:47:28 PM	No	
105,000	Replace or Clean A/C Filters	Done		DARTHURS	Jul 6, 2018 10:47:28 PM	No	
107,000	FRA Change Primary Fuel Filter	No	NA	DARTHURS	Jul 6, 2018 10:47:28 PM	No	
108,000	Lube all pivoting Mechanisms	Done		DARTHURS	Jul 6, 2018 10:47:28 PM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 06-JUL-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 6, 2018 10:47:54 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51488560
Invoice Number: 55345-51488560

Client Department:			
MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FLXFDA02748
Requested By:	DARTHURS	**Status:**	40
Created By:	DARTHURS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Aug 6, 2018	11:00 AM
Started	Aug 6, 2018	
Completed	Aug 6, 2018	3:07 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	175,141	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA CAUSE: preventive maintenance CORRECTION: perform service lube all Pivoting Points cross Rotate Tires completed

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
06-Aug-18	Pierre,Hubert J	7.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 7.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
06-Aug-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51693655
Invoice Number: 55345-51693655

Client Department:
MRC: 55345M
WO Desc:
PM A
Requested By: CVERGARA
Created By: CVERGARA
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5447
Ford E350 Champion Crusaders
VIN: 1FDEE3FLXFDA02748
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Oct 3, 2018	11:15 PM
Started	Oct 3, 2018	
Completed	Oct 4, 2018	12:06 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	183,616	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA CAUSE:Service CORRECTION:Perform pmA Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
03-Oct-18	Gaspard,Ronald	1.55	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.55	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
03-Oct-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51953399
Invoice Number: 55345-51953399

Client Department:			
MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FLXFDA02748
Requested By:	DARTHURS	**Status:**	40
Created By:	DARTHURS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jan 2, 2019	4:27 PM
Started	Jan 3, 2019	
Completed	Jan 3, 2019	10:08 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	196,524	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PM A CAUSE: Service due CORRECTION: Performed and completed pmA Changed engine oil and replaced engine oil filter

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
03-Jan-19	Delva,Terry	1.57	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.57	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
03-Jan-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52041017
Invoice Number: 55345-52041017

Client Department:			
MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FLXFDA02748
Requested By:	CVERGARA	**Status:**	40
Created By:	CVERGARA	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jan 29, 2019	1:19 PM
Started	Jan 29, 2019	
Completed	Jan 29, 2019	11:22 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	200,626	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMA Service CAUSE: Service Due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points .Check Brakes. Clean batteries. Replace. A/C filter. Replace .Oil drain plugs. Parts# B329 Qty (1) Parts# 65266 Qty (1) Oil 5W20QTY (6.5) Qt

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
29-Jan-19	Arthurs,Durvin	1.50	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52205209
Invoice Number: 55345-52205209

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FLXFDA02748
Requested By:	VAMRITTEEMAL	**Status:**	32
Created By:	VAMRITTEEMAL	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Mar 26, 2019	9:48 AM
Started	Mar 26, 2019	
Completed	Mar 26, 2019	11:07 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	209,073	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA SERVICE CAUSE: PREVENTIVE MAINTENANCE CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
26-Mar-19	AMRIT TEEMAL,VISHNU	1.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
26-Mar-19	B329		FILTER, OIL (FGA0000399/FSC0000399)	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52288107
Invoice Number: 55345-52288107

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FLXFDA02748
Requested By:	VAMRITTEEMAL	**Status:**	40
Created By:	VAMRITTEEMAL	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Apr 24, 2019	5:57 PM
Started	Apr 24, 2019	
Completed	Apr 25, 2019	12:36 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	213,402	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMA Service CAUSE: Service due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check brakes . Clean batteries. Parts# B329 Qty (1) Oil 5W20 Qty (6.5) Qt

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
24-Apr-19	Arthurs,Durvin	1.50	65.00	97.50

Activity 10 Sub Total

Parts:	0.00
Labor:	97.50
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
24-Apr-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52458634
Invoice Number: 55345-52458634

Client Department:
MRC: 55345M
WO Desc:
PM A
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5447
Ford E350 Champion Crusaders
VIN: 1FDEE3FLXFDA02748
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Jun 24, 2019	12:08 PM
Started	Jun 24, 2019	
Completed	Jun 25, 2019	12:00 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	221,874	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA CAUSE: Service CORRECTION:Perform pmA Service Oil filter B329 qty 1 Engine oil 5w20 qty 7 Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
24-Jun-19	Gaspard,Ronald	1.58	65.00	102.92

Activity 10 Sub Total

Parts:	0.00
Labor:	102.92
Labor Hours: 1.58	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**102.92**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
24-Jun-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52547408
Invoice Number: 55345-52547408

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FLXFDA02748
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jul 25, 2019	10:16 AM
Started	Jul 25, 2019	
Completed	Jul 25, 2019	9:21 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	226,102	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMA Service CAUSE: Service due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points . Check brakes. Clean batteries. Replace .A/C Filter. Parts# B329 Qty (1) Oil 5W20 Qty (6.5) Qt

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
25-Jul-19	Arthurs,Durvin	1.50	65.00	97.50

Activity 10 Sub Total

Parts:	0.00
Labor:	97.50
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
25-Jul-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52732415
Invoice Number: 55345-52732415

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FLXFDA02748
Requested By:	AOWENS	**Status:**	40
Created By:	AOWENS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Oct 3, 2019	6:26 AM
Started		
Completed	Oct 4, 2019	8:30 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	235,224	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA CAUSE: preventive maintenance CORRECTION: perform PmA Service lube all Pivoting Points Replace 4 Tires One new completed

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
03-Oct-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52862625
Invoice Number: 55345-52862625

Client Department:
MRC: 55345M
WO Desc:
PM A
Requested By: RRENE
Created By: RRENE
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5447
Ford E350 Champion Crusaders
VIN: 1FDEE3FLXFDA02748
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Nov 5, 2019	8:09 AM
Started	Nov 5, 2019	
Completed	Nov 6, 2019	7:48 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	239,748	DH

WorkOrder Notes

Line	Comment
10	PM. Perform pmA service, lube front end, tire rotation, torque and re torque tires (140 f/p), R&R engine oil and filter, road test, all okay at this time. Parts. Engine oil filter part # B329 qty 1 engine oil. 5W20 Qty 6 qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
05-Nov-19	Rodriguez,Raul	1.57	65.00	101.83

Activity 10 Sub Total

Parts:	0.00
Labor:	101.83
Labor Hours: 1.57	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**101.83**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
05-Nov-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53079998
Invoice Number: 55345-53079998

Client Department:
MRC: 55345M
Equipment: 5447
WO Desc:
PM A
Ford E350 Champion Crusaders
VIN: 1FDEE3FLXFDA02748
Requested By: RGASPARD
Status: 40
Created By: RGASPARD
Priority: 1
Class: WO
Driver:
Arrangement: Unassigned
Phone:
Potential Warranty: No
ETA:

Chronology		
Reported	Jan 14, 2020	3:42 PM
Started	Jan 15, 2020	
Completed	Jan 15, 2020	8:47 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	248,452	DH
System	248,730	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA Service CAUSE: preventive maintenance CORRECTION: perform PmA Service lube all Pivoting Points

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
15-Jan-20	NELSON PIERRE-LOUIS	2.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
15-Jan-20	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53182749
Invoice Number: 55345-53182749

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FLXFDA02748
Requested By:	NPIERRE-LOUIS	**Status:**	40
Created By:	NPIERRE-LOUIS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Feb 10, 2020	10:59 AM
Started	Feb 11, 2020	
Completed	Feb 12, 2020	12:43 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	252,645	DH
System	252,645	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA CAUSE:service CORRECTION: perform PMA service Oil filter B329 qty1 Engine oil 5w20 qty 7 qts Replaced AC filter

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
11-Feb-20	Gaspard,Ronald	1.47	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.47	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

WorkOrder: 53558576
Invoice Number: 55345-53558576

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FLXFDA02748
Requested By:	NSTOLFO	**Status:**	40
Created By:	NSTOLFO	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jun 11, 2020	3:08 PM
Started	Jun 11, 2020	
Completed	Jun 11, 2020	7:10 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	260,833	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service CAUSE: Service Due by Mileage. CORRECTION: Change Oil & Filter.Lube all Pivoting Points. Check brakes Clean batteries. Replace Oil filler tube. Parts# B329 Qty (1) Parts # 9C2Z-6763- C Qty (1) Oil 10W30 Qty (6.5) Qt

Activity: 5 **999/999/999 TOTAL VEHICLE**
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53616490
Invoice Number: 55345-53616490

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FLXFDA02748
Requested By:	DARTHURS	**Status:**	40
Created By:	DARTHURS	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Aug 10, 2020	12:00 AM
Started	Aug 10, 2020	
Completed	Aug 11, 2020	12:21 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	265,155	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMA CAUSE: Service CORRECTION: perform PMA service Oil filter B329 qty1 Engine oil 10w30 qty 7 Qts Air filter PA4075 qty1

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note:	PERSONAL RISK ASSESSMENT
Reason for Repair:	SW - Shop Work Order
Work Accomplished:	06 - Inspect
Part Failure:	00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note:	Light Duty PMI
Reason for Repair:	08 - Preventive Maintenance
Work Accomplished:	-
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53921056
Invoice Number: 55345-53921056

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FLXFDA02748
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Nov 11, 2020	12:00 AM
Started	Nov 11, 2020	
Completed	Nov 12, 2020	12:30 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	273,756	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service CORRECTION: Perform pmA Service Oil filter B329 qty1 Engine oil 10w30 qty7 qts Replaced AC filter Replaced rear AC vents 14565100C qty2

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note:	PERSONAL RISK ASSESSMENT
Reason for Repair:	SW - Shop Work Order
Work Accomplished:	06 - Inspect
Part Failure:	00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note:	Light Duty PMI
Reason for Repair:	08 - Preventive Maintenance
Work Accomplished:	-
Part Failure:	-

Activity Comments

Parts Issued

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 54047074
Invoice Number: 55345-54047074

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FLXFDA02748
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Dec 28, 2020	12:00 AM
Started	Dec 29, 2020	
Completed	Dec 29, 2020	2:52 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	278,280	DH
System	278,280	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Unit in for pM service A. Please charge out filter for me it¿s not in the system B329 CAUSE: CORRECTION: Service complete

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
29-Dec-20	Junior Hurst	0.02	0.00	0.00

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.02	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10

Activity Note: Light Duty PMI
Reason for Repair: -
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
29-Dec-20	3L3Z-8501-CA		PUMP, WATER, E450	1.00	36.96	36.96

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 54296465
Invoice Number: 55345-54296465

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FLXFDA02748
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Mar 24, 2021	12:04 PM
Started	Mar 25, 2021	
Completed	Mar 25, 2021	1:11 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	286,732	DH
System	286,732	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA Service CAUSE: preventive maintenance CORRECTION: perform PmA Service and Lube all Pivoting Points

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note:	PERSONAL RISK ASSESSMENT
Reason for Repair:	SW - Shop Work Order
Work Accomplished:	06 - Inspect
Part Failure:	00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999 TOTAL VEHICLE**

Activity Note:	Light Duty PMI
Reason for Repair:	08 - Preventive Maintenance
Work Accomplished:	-
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 54412407
Invoice Number: 55345-54412407

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FLXFDA02748
Requested By:	NPIERRE-LOUIS	**Status:**	40
Created By:	NPIERRE-LOUIS	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	May 6, 2021	9:37 AM
Started	May 6, 2021	
Completed	May 7, 2021	11:47 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	290,934	DH
System	290,934	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA CAUSE: Service due CORRECTION: Performed PMA Completed PMA service

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10

Activity Note: Light Duty PMI
Reason for Repair: -
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 54535202
Invoice Number: 55345-54535202

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FLXFDA02748
Requested By:	DKNOTT	**Status:**	40
Created By:	DKNOTT	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jun 15, 2021	12:00 AM
Started	Jun 15, 2021	
Completed	Jun 15, 2021	7:01 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	295,194	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMA Service CAUSE: Service Due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points . Check brakes. Clean batteries. Parts # B329 Qty (1) Oil 10W30 Qty (6.5) Qt

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note:	PERSONAL RISK ASSESSMENT
Reason for Repair:	SW - Shop Work Order
Work Accomplished:	06 - Inspect
Part Failure:	00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**

Activity Note:	Light Duty PMI
Reason for Repair:	05 - Inspection, Routine
Work Accomplished:	-
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 54653336
Invoice Number: 55345-54653336

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FLXFDA02748
Requested By:	DARTHURS	**Status:**	40
Created By:	DARTHURS	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jul 29, 2021	12:00 AM
Started	Jul 29, 2021	
Completed	Jul 29, 2021	8:51 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	299,460	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMA Service. CAUSE: Service Due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check brakes .clean batteries. Clean A/C Filter Replace Air Filter. Parts # B329 Qty (1) Parts # PA4075 Qty (1) Oil 10W40 Qty (6.5) Qt

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note:	PERSONAL RISK ASSESSMENT
Reason for Repair:	SW - Shop Work Order
Work Accomplished:	06 - Inspect
Part Failure:	00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**

Activity Note:	Light Duty PMI
Reason for Repair:	05 - Inspection, Routine
Work Accomplished:	-
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

WorkOrder: 55564162
Invoice Number: 55345-55564162

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FLXFDA02748
Requested By:	NPIERRE-LOUIS	**Status:**	40
Created By:	NPIERRE-LOUIS	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jun 3, 2022	12:00 AM
Started	Jun 14, 2022	
Completed	Jun 14, 2022	12:44 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	312,091	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA CAUSE:preventive maintenance CORRECTION:performed PMA Service lubes all Pivoting Points completed

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note:	PERSONAL RISK ASSESSMENT
Reason for Repair:	SW - Shop Work Order
Work Accomplished:	06 - Inspect
Part Failure:	00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **017 TIRES, TUBES, LINERS & VALVES**

Activity Note:	Light Duty PMI
Reason for Repair:	08 - Preventive Maintenance
Work Accomplished:	-
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder: 55564162
Invoice Number: 55345-55564162

Client Department:
MRC: 55345M
WO Desc:
55345-LIGHT DUTY PMA
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5447
Ford E350 Champion Crusaders
VIN: 1FDEE3FLXFDA02748
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Date	Technician	Hours	Rate	Extended
14-Jun-22	Pierre,Hubert J	0.85	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.85	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
14-Jun-22	B329		FILTER, OIL, SPIN-ON	1.00	2.14	2.14

Labor Posted

Date	Technician	Hours	Rate	Extended
14-Jun-22	Pierre,Hubert J	2.38	0.00	0.00

Activity 20 Sub Total

Parts:	2.14
Labor:	0.00
Labor Hours: 2.38	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.14**

WorkOrder 55564162 Grand Total

Parts:	2.14
Labor:	0.00
Labor Hours: 3.23	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	**2.14**

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
55564162	14-Jun-22	312,091	WO	55345-LIGHT DUTY PMA
55669812	7-Jun-22	311,588	WO	Rough Idle, Engine Light Flashing, Ac Blowing Hot Air

WorkOrder: 55564162
Invoice Number: 55345-55564162

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FLXFDA02748
Requested By:	NPIERRE-LOUIS	**Status:**	40
Created By:	NPIERRE-LOUIS	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

WorkOrder	Date Completed	Life Meter	Class	Description
55659054	3-Jun-22	311,402	WO	TOP FRONT CLEARENCE LIGHT OUT
55616958	20-May-22	309,324	WO	WC LIFT INOP
55592785	11-May-22	308,320	WO	CHECK WHEEL CHAIR LIFT

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description

PH: Work Order: 55564162 Desc: 55345-LIGHT DUTY PMA
Equip: 5447 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FLXFDA02748

LH: 10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: HPIERRE Performed on: 14-JUN-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		HPIERRE	Jun 14, 2022 10:19:32 AM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		HPIERRE	Jun 14, 2022 10:19:33 AM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		HPIERRE	Jun 14, 2022 10:19:34 AM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		HPIERRE	Jun 14, 2022 10:19:35 AM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		HPIERRE	Jun 14, 2022 10:19:35 AM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		HPIERRE	Jun 14, 2022 10:19:36 AM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Jun 14, 2022 10:19:37 AM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		HPIERRE	Jun 14, 2022 10:19:37 AM	No	
10,800	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		HPIERRE	Jun 14, 2022 10:11:13 AM	No	
10,900	INSPECT_Fuel Tank Cap, and Doors	Done		HPIERRE	Jun 14, 2022 10:19:38 AM	No	
11,100	INSPECT_License Plate, Bracket, Bumpers	Done		HPIERRE	Jun 14, 2022 10:19:39 AM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		HPIERRE	Jun 14, 2022 10:19:40 AM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		HPIERRE	Jun 14, 2022 10:19:40 AM	No	
20,200	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		HPIERRE	Jun 14, 2022 10:19:41 AM	No	
20,300	*RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		HPIERRE	Jun 14, 2022 10:11:24 AM	No	
20,400	PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		HPIERRE	Jun 14, 2022 10:19:42 AM	No	
20,500	*RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		HPIERRE	Jun 14, 2022 10:11:31 AM	No	
20,600	*RPT*INSPECT_Windshields, Sun Visors	Done		HPIERRE	Jun 14, 2022 10:11:36 AM	No	
20,700	INSPECT_Wiper/Washer Operation, Condition	Done		HPIERRE	Jun 14, 2022 10:19:42 AM	No	
20,800	INSPECT_High Idle Control	Done		HPIERRE	Jun 14, 2022 10:19:43 AM	No	
20,900	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		HPIERRE	Jun 14, 2022 10:11:45 AM	No	
21,000	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		HPIERRE	Jun 14, 2022 10:11:50 AM	No	
21,100	INSPECT_Parking Brake Operation	Done		HPIERRE	Jun 14, 2022 10:19:44 AM	No	
21,200	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		HPIERRE	Jun 14, 2022 10:19:44 AM	No	
21,300	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		HPIERRE	Jun 14, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:19:45 AM		
21,400	*RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		HPIERRE	Jun 14, 2022 10:12:36 AM	No	
21,500	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		HPIERRE	Jun 14, 2022 10:19:46 AM	No	
21,550	INSPECT_Driver Floor Area for Rust/Water Leaks	Done		HPIERRE	Jun 14, 2022 10:19:46 AM	No	
21,600	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		HPIERRE	Jun 14, 2022 10:12:43 AM	No	
21,700	INSPECT_Engine Fault Codes	Done		HPIERRE	Jun 14, 2022 10:19:47 AM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION - Front	Done		HPIERRE	Jun 14, 2022 10:19:47 AM	No	
31,000	SSF (Street Side Front)	Done		HPIERRE	Jun 14, 2022 10:19:48 AM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Jun 14, 2022 10:12:55 AM	No	
31,020	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Jun 14, 2022 10:13:00 AM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Jun 14, 2022 10:19:48 AM	No	
31,040	INSPECT_Wiper Blades, Arms	Done		HPIERRE	Jun 14, 2022 10:19:49 AM	No	
32,000	Engine Inspection	Done		HPIERRE	Jun 14, 2022 10:19:49 AM	No	
32,010	INSPECT_Hood, Springs and Props	Done		HPIERRE	Jun 14, 2022 10:19:50 AM	No	
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		HPIERRE	Jun 14, 2022 10:19:51 AM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done		HPIERRE	Jun 14, 2022 10:19:51 AM	No	
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		HPIERRE	Jun 14, 2022 10:19:52 AM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	190 Degree Fahrenheit		HPIERRE	Jun 14, 2022 10:19:52 AM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		HPIERRE	Jun 14, 2022 10:19:54 AM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		HPIERRE	Jun 14, 2022 10:13:26 AM	No	
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		HPIERRE	Jun 14, 2022 10:13:32 AM	No	
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		HPIERRE	Jun 14, 2022 10:13:37 AM	No	
32,100	INSPECT_Intake System	Done		HPIERRE	Jun 14, 2022 10:19:54 AM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12 Volt*		HPIERRE	Jun 14, 2022 10:13:46 AM	No	
33,010	CSF (Curb Side Front)	Done		HPIERRE	Jun 14, 2022 10:19:55 AM	No	
33,020	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Jun 14, 2022 10:13:53 AM	No	
33,030	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Jun 14, 2022 10:13:58 AM	No	
33,040	INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Jun 14, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:19:56 AM		
33,050	INSPECT_Wiper Blades, Arms	Done		HPIERRE	Jun 14, 2022 10:19:56 AM	No	
33,060	!FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		HPIERRE	Jun 14, 2022 10:19:57 AM	No	
33,070	*RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	12 Volt*		HPIERRE	Jun 14, 2022 10:14:10 AM	No	
33,080	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		HPIERRE	Jun 14, 2022 10:19:58 AM	No	
40,000	SECTION 4 - Interior Inspection	Done		HPIERRE	Jun 14, 2022 10:19:59 AM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		HPIERRE	Jun 14, 2022 10:14:20 AM	No	
40,200	INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		HPIERRE	Jun 14, 2022 10:19:59 AM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		HPIERRE	Jun 14, 2022 10:20:00 AM	No	
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		HPIERRE	Jun 14, 2022 10:20:01 AM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		HPIERRE	Jun 14, 2022 10:20:01 AM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		HPIERRE	Jun 14, 2022 10:20:02 AM	No	
40,700	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		HPIERRE	Jun 14, 2022 10:14:33 AM	No	
40,800	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		HPIERRE	Jun 14, 2022 10:14:40 AM	No	
40,900	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		HPIERRE	Jun 14, 2022 10:20:03 AM	No	
41,000	INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		HPIERRE	Jun 14, 2022 10:20:04 AM	No	
41,100	INSPECT_CLEAN_AC Filter	Done		HPIERRE	Jun 14, 2022 10:20:04 AM	No	
41,200	INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		HPIERRE	Jun 14, 2022 10:20:05 AM	No	
41,300	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done		HPIERRE	Jun 14, 2022 10:14:53 AM	No	
41,400	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done		HPIERRE	Jun 14, 2022 10:14:58 AM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done		HPIERRE	Jun 14, 2022 10:20:06 AM	No	
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		HPIERRE	Jun 14, 2022 10:15:04 AM	No	
50,200	INSPECT_Ball Joint Play	Done		HPIERRE	Jun 14, 2022 10:20:06 AM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		HPIERRE	Jun 14, 2022 10:20:07 AM	No	
50,400	LUBE_All Chassis Components	Done		HPIERRE	Jun 14, 2022 10:20:07 AM	No	
50,500	!FRA!CHANGE_Engine oil,filters	Done		HPIERRE	Jun 14, 2022 10:20:08 AM	No	
50,700	INSPECT_Tire Condition	Done		HPIERRE	Jun 14, 2022 10:20:09 AM	No	
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Jun 14, 2022 10:20:09 AM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
50,900	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Jun 14, 2022 10:20:10 AM	No	
51,000	RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Jun 14, 2022 10:20:10 AM	No	
51,100	RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Jun 14, 2022 10:20:11 AM	No	
51,200	RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Jun 14, 2022 10:20:11 AM	No	
51,300	RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Jun 14, 2022 10:20:12 AM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		HPIERRE	Jun 14, 2022 10:20:12 AM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		HPIERRE	Jun 14, 2022 10:20:13 AM	No	
51,600	!FRA!INSPECT_ Front Brake Assemblies	Done		HPIERRE	Jun 14, 2022 10:20:13 AM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	Jun 14, 2022 10:20:14 AM	No	
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		HPIERRE	Jun 14, 2022 10:20:14 AM	No	
51,900	INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	17 Inch		HPIERRE	Jun 14, 2022 10:20:15 AM	No	
52,000	INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	17 Inch		HPIERRE	Jun 14, 2022 10:20:16 AM	No	
52,100	INSPECT_Vibration Damper	Done		HPIERRE	Jun 14, 2022 10:20:16 AM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		HPIERRE	Jun 14, 2022 10:20:17 AM	No	
52,400	!FRA!INSPECT_ Starter Mounting	Done		HPIERRE	Jun 14, 2022 10:20:17 AM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		HPIERRE	Jun 14, 2022 10:20:18 AM	No	
52,700	INSPECT_ Engine, Transmission Mounts	Done		HPIERRE	Jun 14, 2022 10:20:19 AM	No	
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		HPIERRE	Jun 14, 2022 10:20:19 AM	No	
52,900	INSPECT_ Shift Cable Adjustment - All Transmissions	Done		HPIERRE	Jun 14, 2022 10:20:20 AM	No	
53,000	!FRA!INSPECT_ Transmission Breather and Clean	Done		HPIERRE	Jun 14, 2022 10:20:21 AM	No	
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		HPIERRE	Jun 14, 2022 10:16:35 AM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		HPIERRE	Jun 14, 2022 10:16:40 AM	No	
53,300	*RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		HPIERRE	Jun 14, 2022 10:16:45 AM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		HPIERRE	Jun 14, 2022 10:16:49 AM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		HPIERRE	Jun 14, 2022 10:20:21 AM	No	
53,600	INSPECT_Tire Condition	Done		HPIERRE	Jun 14, 2022 10:20:22 AM	No	
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Jun 14, 2022 10:20:23 AM	No	
53,800	INSPECT_ Mismatched Tire Tread, Casing Design	Done		HPIERRE	Jun 14, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:20:24 AM		
53,900	INSPECT_Dual Mating Tires w/Square	Done		HPIERRE	Jun 14, 2022 10:20:24 AM	No	
54,000	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Jun 14, 2022 10:20:25 AM	No	
54,100	INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Jun 14, 2022 10:20:26 AM	No	
54,200	RECORD_RRO-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Jun 14, 2022 10:20:26 AM	No	
54,300	RECORD_RRI-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Jun 14, 2022 10:20:27 AM	No	
54,400	RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Jun 14, 2022 10:20:28 AM	No	
54,500	RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Jun 14, 2022 10:20:28 AM	No	
54,600	RECORD_LRO-Tire Tread Depth (32nds)	7 32nds of an inch		HPIERRE	Jun 14, 2022 10:20:29 AM	No	
54,700	RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		HPIERRE	Jun 14, 2022 10:20:30 AM	No	
54,800	RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Jun 14, 2022 10:20:30 AM	No	
54,900	RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Jun 14, 2022 10:20:31 AM	No	
55,000	!FRA!INSPECT_ REAR Brake Assemblies	Done		HPIERRE	Jun 14, 2022 10:20:32 AM	No	
55,100	!FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		HPIERRE	Jun 14, 2022 10:20:33 AM	No	
55,200	!FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		HPIERRE	Jun 14, 2022 10:20:34 AM	No	
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		HPIERRE	Jun 14, 2022 10:20:35 AM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		HPIERRE	Jun 14, 2022 10:20:35 AM	No	
55,500	INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	17 Inch		HPIERRE	Jun 14, 2022 10:20:36 AM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	17 Inch		HPIERRE	Jun 14, 2022 10:20:37 AM	No	
55,700	!FRA!INSPECT_ Under Body Exhaust System	Done		HPIERRE	Jun 14, 2022 10:20:38 AM	No	
55,800	*RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		HPIERRE	Jun 14, 2022 10:18:36 AM	No	
55,900	*RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		HPIERRE	Jun 14, 2022 10:18:40 AM	No	
60,000	SECTION 6 - Wheelchair Inspection	Done		HPIERRE	Jun 14, 2022 10:20:38 AM	No	
60,100	RECORD_Wheelchair Cycle Count	12345 Cycles		HPIERRE	Jun 14, 2022 10:20:39 AM	No	
60,200	CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		HPIERRE	Jun 14, 2022 10:20:40 AM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		HPIERRE	Jun 14, 2022 10:20:41 AM	No	
60,400	OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		HPIERRE	Jun 14, 2022 10:20:41 AM	No	
60,500	INSPECT_ Bridgeplate Operation	Done		HPIERRE	Jun 14, 2022 10:20:42 AM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,600	INSPECT_All Pivot Points for Wear and Looseness	Done		HPIERRE	Jun 14, 2022 10:20:43 AM	No	
60,700	INSPECT_Rollers for Wear and Smooth Rotation	Done		HPIERRE	Jun 14, 2022 10:20:43 AM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	Done		HPIERRE	Jun 14, 2022 10:20:44 AM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	Done		HPIERRE	Jun 14, 2022 10:20:45 AM	No	
61,000	INSPECT_Cable Condition (If Applicable)	Done		HPIERRE	Jun 14, 2022 10:20:45 AM	No	
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		HPIERRE	Jun 14, 2022 10:20:46 AM	No	
61,200	INSPECT_Electrical Connections and Routing of Wires and Cables	Done		HPIERRE	Jun 14, 2022 10:20:47 AM	No	
61,300	INSPECT_Operation and Adjustment of All Safety Switches	Done		HPIERRE	Jun 14, 2022 10:20:47 AM	No	
61,400	INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		HPIERRE	Jun 14, 2022 10:20:48 AM	No	
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		HPIERRE	Jun 14, 2022 10:20:49 AM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		HPIERRE	Jun 14, 2022 10:20:50 AM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		HPIERRE	Jun 14, 2022 10:20:50 AM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		HPIERRE	Jun 14, 2022 10:20:51 AM	No	
61,900	CLEAN_Linkages and Mechanisms	Done		HPIERRE	Jun 14, 2022 10:20:52 AM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		HPIERRE	Jun 14, 2022 10:20:52 AM	No	
62,100	INSPECT_Emergency Platform Release Mechanism	Done		HPIERRE	Jun 14, 2022 10:20:53 AM	No	
62,200	INSPECT_Platform Barrier Latch Mechanism	Done		HPIERRE	Jun 14, 2022 10:20:54 AM	No	
62,300	INSPECT_Bridgeplate Hinge	Done		HPIERRE	Jun 14, 2022 10:20:54 AM	No	
62,400	INSPECT_All Pivot Points	Done		HPIERRE	Jun 14, 2022 10:20:55 AM	No	
62,500	INSPECT_Cams and Slots	Done		HPIERRE	Jun 14, 2022 10:20:55 AM	No	
62,600	INSPECT_Rollers	Done		HPIERRE	Jun 14, 2022 10:20:56 AM	No	
62,700	INSPECT_All Linkages	Done		HPIERRE	Jun 14, 2022 10:20:57 AM	No	
80,000	SECTION 8 - PMI Report Completion	Done		HPIERRE	Jun 14, 2022 10:20:57 AM	No	
80,100	COMPLETE_PM Report; Follow-ups	Done		HPIERRE	Jun 14, 2022 10:20:58 AM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		HPIERRE	Jun 14, 2022 10:20:59 AM	No	

LH: 20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 14-JUN-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		HPIERRE	Jun 14, 2022 10:09:33 AM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
101,000	FRA Change Oil Filters	Yes		HPIERRE	Jun 14, 2022 10:09:34 AM	No	
102,000	FRA Drain Engine Oil	Yes		HPIERRE	Jun 14, 2022 10:09:35 AM	No	
103,000	FRA Check Transmission Fluid	Done		HPIERRE	Jun 14, 2022 10:09:36 AM	No	
104,000	Lubricate Chassis	Done		HPIERRE	Jun 14, 2022 10:09:36 AM	No	
105,000	Replace or Clean A/C Filters	Done		HPIERRE	Jun 14, 2022 10:09:37 AM	No	
107,000	FRA Change Primary Fuel Filter	No		HPIERRE	Jun 14, 2022 10:09:37 AM	No	
108,000	Lube all pivoting Mechanisms	Done		HPIERRE	Jun 14, 2022 10:09:38 AM	No	

LH: 5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 14-JUN-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		HPIERRE	Jun 14, 2022 10:08:22 AM	No	
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Jun 14, 2022 10:08:23 AM	No	
4	Are you wearing the appropriate PPE?	Done		HPIERRE	Jun 14, 2022 10:08:24 AM	No	
7	Have you performed the proper LOTO?	Done		HPIERRE	Jun 14, 2022 10:08:22 AM	No	
10	Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Jun 14, 2022 10:08:24 AM	No	
11	Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Jun 14, 2022 10:08:25 AM	No	

FIRSTstudent
First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 55691568
Invoice Number: 55345-55691568

Client Department:
MRC: 55345M
WO Desc:
55345-LIGHT DUTY PMA
Requested By: HPIERRE
Created By: HPIERRE
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5447
Ford E350 Champion Crusaders
VIN: 1FDEE3FLXFDA02748
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Chronology		
Reported	Aug 1, 2022	12:00 AM
Started	Aug 3, 2022	
Completed	Aug 3, 2022	10:15 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	316,735	DH
System	316,607	DH

WorkOrder Notes

Line	Comment
10	COMPLETED PMA INSPECTION AND SERVICE

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**

Activity Note: Light Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
03-Aug-22	Gaspard,Ronald	1.50	0.00	0.00

Activity 10 Sub Total

WorkOrder: 55691568
Invoice Number: 55345-55691568

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FLXFDA02748
Requested By:	HPIERRE	**Status:**	40
Created By:	HPIERRE	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Parts:	0.00
Labor:	0.00
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
04-Aug-22	B329		FILTER, OIL, SPIN-ON	1.00	2.19	2.19

Labor Posted

Date	Technician	Hours	Rate	Extended
03-Aug-22	Gaspard,Ronald	0.22	0.00	0.00

Activity 20 Sub Total

Parts:	2.19
Labor:	0.00
Labor Hours: 0.22	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.19**

WorkOrder 55691568 Grand Total

Parts:	2.19
Labor:	0.00
Labor Hours: 1.72	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	**2.19**

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
55827211	4-Aug-22	316,735	WO	FOLLOWUP-FT Light Duty
55691568	3-Aug-22	316,735	WO	55345-LIGHT DUTY PMA
55717773	22-Jul-22	312,842	WO	CHECK AIR CONDITIONING SYSTEM
55783797	19-Jul-22	315,272	WO	55345 PER DVIR (Noise Under Vehicle Transmission)

Scheduled Preventative Maintenance

WorkOrder: 55691568
Invoice Number: 55345-55691568

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FLXFDA02748
Requested By:	HPIERRE	**Status:**	40
Created By:	HPIERRE	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
55421655	13-Jul-22	0	WO	QCC FLEET INSPECTION

PH: Work Order: 55691568 Desc: 55345-LIGHT DUTY PMA
Equip: 5447 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FLXFDA02748

LH: 10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 03-AUG-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		RGASPARD	Aug 3, 2022 9:11:51 PM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Aug 3, 2022 9:12:01 PM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		RGASPARD	Aug 3, 2022 9:12:06 PM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Aug 3, 2022 9:12:11 PM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Aug 3, 2022 9:12:16 PM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Aug 3, 2022 9:12:21 PM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Aug 3, 2022 9:12:26 PM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Aug 3, 2022 9:12:31 PM	No	
10,800	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Aug 3, 2022 9:12:35 PM	No	
10,900	INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Aug 3, 2022 9:12:40 PM	No	
11,100	INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Aug 3, 2022 9:12:45 PM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Aug 3, 2022 9:12:49 PM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Aug 3, 2022 9:12:54 PM	No	
20,200	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Aug 3, 2022 9:12:59 PM	No	
20,300	*RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Aug 3, 2022 9:13:03 PM	No	
20,400	PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Aug 3, 2022 9:13:08 PM	No	
20,500	*RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Aug 3, 2022 9:13:12 PM	No	
20,600	*RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Aug 3, 2022 9:13:17 PM	No	
20,700	INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Aug 3, 2022 9:13:22 PM	No	
20,800	INSPECT_High Idle Control	Done		RGASPARD	Aug 3, 2022 9:13:27 PM	No	
20,900	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Aug 3, 2022 9:13:32 PM	No	
21,000	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Aug 3, 2022 9:13:36 PM	No	
21,100	INSPECT_Parking Brake Operation	Done		RGASPARD	Aug 3, 2022 9:13:41 PM	No	
21,200	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Aug 3, 2022 9:13:46 PM	No	
21,300	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Aug 3, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					9:13:51 PM		
21,400	*RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Aug 3, 2022 9:13:55 PM	No	
21,500	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Aug 3, 2022 9:14:00 PM	No	
21,550	INSPECT_Driver Floor Area for Rust/Water Leaks	Done		RGASPARD	Aug 3, 2022 9:14:05 PM	No	
21,600	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Aug 3, 2022 9:14:11 PM	No	
21,700	INSPECT_Engine Fault Codes	Done		RGASPARD	Aug 3, 2022 9:14:16 PM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Aug 3, 2022 9:14:21 PM	No	
31,000	SSF (Street Side Front)	Done		RGASPARD	Aug 3, 2022 9:14:26 PM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Aug 3, 2022 9:14:30 PM	No	
31,020	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Aug 3, 2022 9:14:36 PM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Aug 3, 2022 9:14:43 PM	No	
31,040	INSPECT_Wiper Blades, Arms	Done		RGASPARD	Aug 3, 2022 9:14:47 PM	No	
32,000	Engine Inspection	Done		RGASPARD	Aug 3, 2022 9:14:52 PM	No	
32,010	INSPECT_Hood, Springs and Props	Done		RGASPARD	Aug 3, 2022 9:15:06 PM	No	
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Aug 3, 2022 9:15:13 PM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Aug 3, 2022 9:15:19 PM	No	
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	Aug 3, 2022 9:15:29 PM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Aug 3, 2022 9:15:37 PM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Aug 3, 2022 9:15:41 PM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Aug 3, 2022 9:15:46 PM	No	
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Aug 3, 2022 9:15:51 PM	No	
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Aug 3, 2022 9:15:56 PM	No	
32,100	INSPECT_Intake System	Done		RGASPARD	Aug 3, 2022 9:16:01 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Aug 3, 2022 9:16:09 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Aug 3, 2022 9:16:29 PM	No	
33,010	CSF (Curb Side Front)	Done		RGASPARD	Aug 3, 2022 9:16:34 PM	No	
33,020	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Aug 3, 2022 9:16:39 PM	No	
33,030	*RPT*INSPECT_ FRONT Springs, Shocks, Spring	Done		RGASPARD	Aug 3, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Shackles				9:16:44 PM		
33,040	INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Aug 3, 2022 9:16:49 PM	No	
33,050	INSPECT_Wiper Blades, Arms	Done		RGASPARD	Aug 3, 2022 9:16:54 PM	No	
33,060	!FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	Aug 3, 2022 9:16:59 PM	No	
33,070	*RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	RGASPARD	Aug 3, 2022 9:17:07 PM	No	
33,080	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Aug 3, 2022 9:17:12 PM	No	
40,000	SECTION 4 - Interior Inspection	Done		RGASPARD	Aug 3, 2022 9:17:16 PM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Aug 3, 2022 9:17:23 PM	No	
40,200	INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		RGASPARD	Aug 3, 2022 9:17:28 PM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Aug 3, 2022 9:17:33 PM	No	
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	Aug 3, 2022 9:17:38 PM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Aug 3, 2022 9:17:43 PM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Aug 3, 2022 9:17:47 PM	No	
40,700	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Aug 3, 2022 9:17:53 PM	No	
40,800	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Aug 3, 2022 9:17:59 PM	No	
40,900	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Aug 3, 2022 9:18:04 PM	No	
41,000	INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Aug 3, 2022 9:18:09 PM	No	
41,100	INSPECT_CLEAN_AC Filter	Done		RGASPARD	Aug 3, 2022 9:18:14 PM	No	
41,200	INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		RGASPARD	Aug 3, 2022 9:18:19 PM	No	
41,300	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Aug 3, 2022 9:18:25 PM	No	
41,400	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Aug 3, 2022 9:18:32 PM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Aug 3, 2022 9:18:36 PM	No	
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Aug 3, 2022 9:18:41 PM	No	
50,200	INSPECT_Ball Joint Play	Done		RGASPARD	Aug 3, 2022 9:18:46 PM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Aug 3, 2022 9:18:51 PM	No	
50,400	LUBE_All Chassis Components	Done	na	RGASPARD	Aug 3, 2022 9:19:01 PM	No	
50,500	!FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Aug 3, 2022 9:20:29 PM	No	
50,700	INSPECT_Tire Condition	Done		RGASPARD	Aug 3, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					9:20:34 PM		
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Aug 3, 2022 9:20:39 PM	No	
50,900	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Aug 3, 2022 9:20:44 PM	No	
51,000	RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Aug 3, 2022 9:21:58 PM	No	
51,100	RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Aug 3, 2022 9:22:04 PM	No	
51,200	RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Aug 3, 2022 9:22:09 PM	No	
51,300	RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Aug 3, 2022 9:22:16 PM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Aug 3, 2022 9:22:21 PM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Aug 3, 2022 9:22:26 PM	No	
51,600	!FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Aug 3, 2022 9:22:34 PM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	3 32nds of an inch	needs front brakes job.	RGASPARD	Aug 3, 2022 9:23:03 PM	Yes	55827211
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	3 32nds of an inch		RGASPARD	Aug 3, 2022 9:23:28 PM	No	
51,900	INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	37 Inch		RGASPARD	Aug 3, 2022 9:23:43 PM	No	
52,000	INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	37 Inch		RGASPARD	Aug 3, 2022 9:23:49 PM	No	
52,100	INSPECT_Vibration Damper	Done		RGASPARD	Aug 3, 2022 9:23:56 PM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Aug 3, 2022 9:24:02 PM	No	
52,400	!FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Aug 3, 2022 9:24:10 PM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Aug 3, 2022 9:24:21 PM	No	
52,700	INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Aug 3, 2022 9:24:29 PM	No	
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Aug 3, 2022 9:24:36 PM	No	
52,900	INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Aug 3, 2022 9:24:41 PM	No	
53,000	!FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Aug 3, 2022 9:24:49 PM	No	
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Aug 3, 2022 9:25:12 PM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Aug 3, 2022 9:25:27 PM	No	
53,300	*RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Aug 3, 2022 9:25:32 PM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Aug 3, 2022 9:25:39 PM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Aug 3, 2022 9:25:44 PM	No	
53,600	INSPECT_Tire Condition	Done		RGASPARD	Aug 3, 2022 9:25:48 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Aug 3, 2022 9:25:53 PM	No	
53,800	INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Aug 3, 2022 9:25:58 PM	No	
53,900	INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Aug 3, 2022 9:26:03 PM	No	
54,000	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Aug 3, 2022 9:26:08 PM	No	
54,100	INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Aug 3, 2022 9:26:14 PM	No	
54,200	RECORD_RRO-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Aug 3, 2022 9:26:21 PM	No	
54,300	RECORD_RRI-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Aug 3, 2022 9:26:26 PM	No	
54,400	RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Aug 3, 2022 9:26:33 PM	No	
54,500	RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Aug 3, 2022 9:26:40 PM	No	
54,600	RECORD_LRO-Tire Tread Depth (32nds)	3 32nds of an inch		RGASPARD	Aug 3, 2022 9:41:00 PM	No	
54,700	RECORD_LRI-Tire Tread Depth (32nds)	3 32nds of an inch		RGASPARD	Aug 3, 2022 9:41:06 PM	No	
54,800	RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Aug 3, 2022 9:41:20 PM	No	
54,900	RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Aug 3, 2022 9:41:27 PM	No	
55,000	!FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Aug 3, 2022 9:41:38 PM	No	
55,100	!FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Aug 3, 2022 9:41:46 PM	No	
55,200	!FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Aug 3, 2022 9:41:51 PM	No	
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Aug 3, 2022 9:41:59 PM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Aug 3, 2022 9:42:04 PM	No	
55,500	INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	37 Inch		RGASPARD	Aug 3, 2022 9:42:13 PM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	37 Inch		RGASPARD	Aug 3, 2022 9:42:18 PM	No	
55,700	!FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Aug 3, 2022 9:42:34 PM	No	
55,800	*RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Aug 3, 2022 9:42:40 PM	No	
55,900	*RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Aug 3, 2022 9:42:45 PM	No	
60,000	SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Aug 3, 2022 9:42:50 PM	No	
60,100	RECORD_Wheelchair Cycle Count	11245 Cycles		RGASPARD	Aug 3, 2022 9:42:57 PM	No	
60,200	CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Aug 3, 2022 9:43:02 PM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Aug 3, 2022 9:43:14 PM	No	
60,400	OPERATE_Lift thru Complete	Done		RGASPARD	Aug 3, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down				9:43:19 PM		
60,500	INSPECT_ Bridgeplate Operation	Done		RGASPARD	Aug 3, 2022 9:43:24 PM	No	
60,600	INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Aug 3, 2022 9:43:29 PM	No	
60,700	INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Aug 3, 2022 9:43:33 PM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Aug 3, 2022 9:43:38 PM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Aug 3, 2022 9:43:43 PM	No	
61,000	INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Aug 3, 2022 9:43:48 PM	No	
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Aug 3, 2022 9:43:53 PM	No	
61,200	INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Aug 3, 2022 9:43:58 PM	No	
61,300	INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Aug 3, 2022 9:44:03 PM	No	
61,400	INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Aug 3, 2022 9:44:08 PM	No	
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Aug 3, 2022 9:44:13 PM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Aug 3, 2022 9:44:17 PM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Aug 3, 2022 9:44:22 PM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Aug 3, 2022 9:44:27 PM	No	
61,900	CLEAN_Linkages and Mechanisms	Done		RGASPARD	Aug 3, 2022 9:44:34 PM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Aug 3, 2022 9:44:39 PM	No	
62,100	INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Aug 3, 2022 9:44:44 PM	No	
62,200	INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Aug 3, 2022 9:44:48 PM	No	
62,300	INSPECT_Bridgeplate Hinge	Done		RGASPARD	Aug 3, 2022 9:44:53 PM	No	
62,400	INSPECT_All Pivot Points	Done		RGASPARD	Aug 3, 2022 9:44:58 PM	No	
62,500	INSPECT_Cams and Slots	Done		RGASPARD	Aug 3, 2022 9:45:03 PM	No	
62,600	INSPECT_Rollers	Done		RGASPARD	Aug 3, 2022 9:45:10 PM	No	
62,700	INSPECT_All Linkages	Done		RGASPARD	Aug 3, 2022 9:45:15 PM	No	
80,000	SECTION 8 - PMI Report Completion	Done		RGASPARD	Aug 3, 2022 9:45:20 PM	No	
80,100	COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Aug 3, 2022 9:45:24 PM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Aug 3, 2022 9:45:29 PM	No	

LH: 20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 03-AUG-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		RGASPARD	Aug 3, 2022 10:00:24 PM	No	
101,000	FRA Change Oil Filters	Yes		RGASPARD	Aug 3, 2022 10:00:28 PM	No	
102,000	FRA Drain Engine Oil	Yes		RGASPARD	Aug 3, 2022 10:00:36 PM	No	
103,000	FRA Check Transmission Fluid	Done		RGASPARD	Aug 3, 2022 10:00:41 PM	No	
104,000	Lubricate Chassis	-	na	RGASPARD	Aug 3, 2022 10:00:47 PM	No	
105,000	Replace or Clean A/C Filters	Done		RGASPARD	Aug 3, 2022 10:00:51 PM	No	
107,000	FRA Change Primary Fuel Filter	No	na	RGASPARD	Aug 3, 2022 10:00:57 PM	No	
108,000	Lube all pivoting Mechanisms	Done		RGASPARD	Aug 3, 2022 10:01:01 PM	No	

LH: 5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 03-AUG-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		RGASPARD	Aug 3, 2022 8:29:05 PM	No	
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Aug 3, 2022 8:29:10 PM	No	
4	Are you wearing the appropriate PPE?	Done		RGASPARD	Aug 3, 2022 8:29:14 PM	No	
7	Have you performed the proper LOTO?	Done		RGASPARD	Aug 3, 2022 8:29:19 PM	No	
10	Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Aug 3, 2022 8:29:24 PM	No	
11	Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Aug 3, 2022 8:29:28 PM	No	

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51336458
Invoice Number: 55345-51336458

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
PM B		**VIN:**	1FDEE3FLXFDA02748
Requested By:	DARTHURS	**Status:**	40
Created By:	DARTHURS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jun 7, 2018	11:57 AM
Started	Jun 7, 2018	
Completed	Jun 7, 2018	10:44 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	166,616	DH
System	166,771	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PM-B CAUSE: Preventive Maintenance CORRECTION: Tech Performed PM-B Parts used Oil filter Qty1 part#B329 Oil Qty:6.5

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
07-Jun-18	KARLENS,Cyrius	2.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

WorkOrder: 51336458
Invoice Number: 55345-51336458

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
PM B		**VIN:**	1FDEE3FLXFDA02748
Requested By:	DARTHURS	**Status:**	40
Created By:	DARTHURS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Date	Part Number		Description	Qty.	Each	Extended
07-Jun-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted

Date	Technician	Hours	Rate	Extended
07-Jun-18	KARLENS,Cyrius	1.00	0.00	0.00

Activity 20 Sub Total

Parts:	1.96
Labor:	0.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Activity: 30 **999 TOTAL VEHICLE**

Activity Note: PRAMETER
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
07-Jun-18	KARLENS,Cyrius	0.50	0.00	0.00

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

WorkOrder 51336458 Grand Total

Parts:	1.96
Labor:	0.00
Labor Hours: 3.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	**1.96**

Recent Repair History

WorkOrder: 51336458
Invoice Number: 55345-51336458

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
PM B		**VIN:**	1FDEE3FLXFDA02748
Requested By:	DARTHURS	**Status:**	40
Created By:	DARTHURS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

WorkOrder	Date Completed	Life Meter	Class	Description
51336458	7-Jun-18	166,616	WO	PM B
51384307	1-Jun-18	165,709	WO	Vehicle needs a window latch for the sliding window
51367053	23-May-18	164,544	WO	55345 SPARK PLUG GAS BUSSES
51336287	9-May-18	162,652	WO	Front Brakes& Tag light
51210290	9-May-18	162,652	WO	PM A

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
51408864	7-Jun-18	166,616	WO	FOLLOW UP PMB
51210235	10-Apr-18	158,343	WO	Rear Tires/Rear Brakes/ Serpentine belts

PH: Work Order: 51336458 Desc: PM B
Equip: 5447 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FLXFDA02748

LH: 10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: CKARLENS Performed on: 07-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		CKARLENS	Jun 7, 2018 10:20:54 PM	No	
10,100	Safety Inspection	Done		CKARLENS	Jun 7, 2018 10:20:55 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		CKARLENS	Jun 7, 2018 10:20:55 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		CKARLENS	Jun 7, 2018 10:20:55 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		CKARLENS	Jun 7, 2018 10:20:54 PM	No	
10,140	Check Service Brakes	Done		CKARLENS	Jun 7, 2018 10:20:55 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		CKARLENS	Jun 7, 2018 10:20:55 PM	No	
10,160	FRA Check Instruments and Horns	Done		CKARLENS	Jun 7, 2018 10:20:55 PM	No	
10,170	Check Fast Idle	Done		CKARLENS	Jun 7, 2018 10:20:56 PM	No	
10,180	Check Starter Protection Circuit	Done		CKARLENS	Jun 7, 2018 10:20:56 PM	No	
10,190	Check Reverse Warning System	Done		CKARLENS	Jun 7, 2018 10:20:56 PM	No	
11,100	Check Parking Brake	Done		CKARLENS	Jun 7, 2018 10:20:56 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		CKARLENS	Jun 7, 2018 10:20:56 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		CKARLENS	Jun 7, 2018 10:20:56 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		CKARLENS	Jun 7, 2018 10:20:57 PM	No	
11,140	Road Test: Check for Proper Operation	Done		CKARLENS	Jun 7, 2018 10:20:57 PM	No	
11,150	Perform Brake Test	Done		CKARLENS	Jun 7, 2018 10:20:57 PM	No	
11,152	Decelerometer Results Test 1	FEET	NA	CKARLENS	Jun 7, 2018 10:20:57 PM	No	
11,154	Decelerometer Results Test 2	FEET	NA	CKARLENS	Jun 7, 2018 10:20:57 PM	No	
11,156	Decelerometer Results Test 3	FEET	NA	CKARLENS	Jun 7, 2018 10:20:57 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	CKARLENS	Jun 7, 2018 10:20:57 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	NA	CKARLENS	Jun 7, 2018 10:20:58 PM	No	
11,170	FRA Check Door Operation	Done		CKARLENS	Jun 7, 2018 10:20:58 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		CKARLENS	Jun 7, 2018 10:20:58 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		CKARLENS	Jun 7, 2018 10:20:58 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		CKARLENS	Jun 7, 2018 10:20:58 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		CKARLENS	Jun 7, 2018 10:20:59 PM	No	
20,230	FRA Check Wiring Under Dash	Done		CKARLENS	Jun 7, 2018 10:20:59 PM	No	
20,240	FRA Check Interior Lights	Done		CKARLENS	Jun 7, 2018 10:20:59 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		CKARLENS	Jun 7, 2018 10:20:59 PM	No	
20,260	Check Stop Request System	-	NA	CKARLENS	Jun 7, 2018 10:20:59 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	NA	CKARLENS	Jun 7, 2018 10:20:59 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		CKARLENS	Jun 7, 2018 10:20:59 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		CKARLENS	Jun 7, 2018 10:20:59 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		CKARLENS	Jun 7, 2018 10:21:00 PM	No	
22,110	Check Emergency Hatches	Done		CKARLENS	Jun 7, 2018 10:21:00 PM	No	
22,120	Check All Safety Equipment	Done		CKARLENS	Jun 7, 2018 10:21:00 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		CKARLENS	Jun 7, 2018 10:21:00 PM	No	
30,310	Check Passenger Doors	Done		CKARLENS	Jun 7, 2018 10:21:01 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		CKARLENS	Jun 7, 2018 10:21:01 PM	No	
30,330	Check Wheelchair Lift Operation	Done		CKARLENS	Jun 7, 2018 10:21:01 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	NA	CKARLENS	Jun 7, 2018 10:21:01 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		CKARLENS	Jun 7, 2018 10:21:01 PM	No	
30,360	Check for Physical Damage and Decals	Done		CKARLENS	Jun 7, 2018 10:21:02 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		CKARLENS	Jun 7, 2018 10:21:01 PM	No	
30,380	Check Exterior Compartment Doors	Done		CKARLENS	Jun 7, 2018 10:21:01 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		CKARLENS	Jun 7, 2018 10:21:02 PM	No	
33,100	Check Lights and Reflectors	Done		CKARLENS	Jun 7, 2018 10:21:02 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		CKARLENS	Jun 7, 2018 10:21:02 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		CKARLENS	Jun 7, 2018 10:21:02 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		CKARLENS	Jun 7, 2018 10:21:03 PM	No	
40,420	Check Hood	Done		CKARLENS	Jun 7, 2018 10:21:03 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		CKARLENS	Jun 7, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:21:03 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	NA	CKARLENS	Jun 7, 2018 10:21:03 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		CKARLENS	Jun 7, 2018 10:21:03 PM	No	
40,442	Freeze Point	Degree Fahrenheit	NA	CKARLENS	Jun 7, 2018 10:21:03 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		CKARLENS	Jun 7, 2018 10:21:03 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	NA	CKARLENS	Jun 7, 2018 10:21:03 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	NA	CKARLENS	Jun 7, 2018 10:21:03 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		CKARLENS	Jun 7, 2018 10:21:04 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		CKARLENS	Jun 7, 2018 10:21:04 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		CKARLENS	Jun 7, 2018 10:21:04 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		CKARLENS	Jun 7, 2018 10:21:04 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		CKARLENS	Jun 7, 2018 10:21:05 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		CKARLENS	Jun 7, 2018 10:21:05 PM	No	
44,130	FRA Check Exhaust System	Done		CKARLENS	Jun 7, 2018 10:21:05 PM	No	
44,140	FRA Check Intake System	Done		CKARLENS	Jun 7, 2018 10:21:05 PM	No	
44,150	FRA Inspect Turbocharger	-	NA	CKARLENS	Jun 7, 2018 10:21:05 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		CKARLENS	Jun 7, 2018 10:21:05 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		CKARLENS	Jun 7, 2018 10:21:05 PM	No	
44,180	FRA Check for Leaks	Done		CKARLENS	Jun 7, 2018 10:21:05 PM	No	
44,190	FRA Perform Battery Inspection	Done		CKARLENS	Jun 7, 2018 10:21:06 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		CKARLENS	Jun 7, 2018 10:21:06 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		CKARLENS	Jun 7, 2018 10:21:06 PM	No	
50,510	Check Entire Steering System	Done		CKARLENS	Jun 7, 2018 10:21:06 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		CKARLENS	Jun 7, 2018 10:21:06 PM	No	
60,610	FRA Check and Record Air Pressure	Done		CKARLENS	Jun 7, 2018 10:21:06 PM	No	
60,611	Air Pressure RF	70 Pounds per Square Inch		CKARLENS	Jun 7, 2018 10:21:06 PM	No	
60,612	Air Pressure LF	70 Pounds per Square Inch		CKARLENS	Jun 7, 2018 10:21:07 PM	No	
60,613	Air Pressure RRO	70 Pounds per Square Inch		CKARLENS	Jun 7, 2018 10:21:07 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	70 Pounds per Square Inch		CKARLENS	Jun 7, 2018 10:21:07 PM	No	
60,615	Air Pressure LRI	70 Pounds per Square Inch		CKARLENS	Jun 7, 2018 10:21:07 PM	No	
60,616	Air Pressure LRO	70 Pounds per Square Inch		CKARLENS	Jun 7, 2018 10:21:08 PM	No	
60,620	Check Valve Stems and Caps	Done		CKARLENS	Jun 7, 2018 10:21:08 PM	No	
60,630	Check and Record Tread Depth	Done		CKARLENS	Jun 7, 2018 10:21:08 PM	No	
60,631	Tread Depth RF	6 32nds of an inch		CKARLENS	Jun 7, 2018 10:21:08 PM	No	
60,632	Tread Depth LF	6 32nds of an inch		CKARLENS	Jun 7, 2018 10:21:08 PM	No	
60,633	Tread Depth RRO	11 32nds of an inch		CKARLENS	Jun 7, 2018 10:21:08 PM	No	
60,634	Tread Depth RRI	11 32nds of an inch		CKARLENS	Jun 7, 2018 10:21:09 PM	No	
60,635	Tread Depth LRI	11 32nds of an inch		CKARLENS	Jun 7, 2018 10:21:09 PM	No	
60,636	Tread Depth LRO	11 32nds of an inch		CKARLENS	Jun 7, 2018 10:21:09 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		CKARLENS	Jun 7, 2018 10:21:09 PM	No	
60,650	Check Sidewall Wear	Done		CKARLENS	Jun 7, 2018 10:21:09 PM	No	
60,660	Inspect for Cuts and Tears	Done		CKARLENS	Jun 7, 2018 10:21:09 PM	No	
60,670	Check Dual Mating With Square	Done		CKARLENS	Jun 7, 2018 10:21:09 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		CKARLENS	Jun 7, 2018 10:21:10 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		CKARLENS	Jun 7, 2018 10:21:10 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		CKARLENS	Jun 7, 2018 10:21:10 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		CKARLENS	Jun 7, 2018 10:21:10 PM	No	
70,710	Check Vibration Damper	Done		CKARLENS	Jun 7, 2018 10:21:10 PM	No	
70,720	Check Engine and Transmission Mounts	Done		CKARLENS	Jun 7, 2018 10:21:10 PM	No	
70,730	FRA Check Starter	Done		CKARLENS	Jun 7, 2018 10:21:10 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		CKARLENS	Jun 7, 2018 10:21:10 PM	No	
70,750	FRA Check Transmission for Leaks	Done		CKARLENS	Jun 7, 2018 10:21:11 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		CKARLENS	Jun 7, 2018 10:21:11 PM	No	
70,770	FRA Check Exhaust System	Done		CKARLENS	Jun 7, 2018 10:21:11 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		CKARLENS	Jun 7, 2018 10:21:11 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		CKARLENS	Jun 7, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:21:11 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		CKARLENS	Jun 7, 2018 10:23:11 PM	No	
77,110	FRA Check Fuel Tank	Done		CKARLENS	Jun 7, 2018 10:23:11 PM	No	
77,120	Check Suspension Components	Done		CKARLENS	Jun 7, 2018 10:23:11 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		CKARLENS	Jun 7, 2018 10:23:11 PM	No	
77,131	Brake Pad Thickness LF	10 Inch		CKARLENS	Jun 7, 2018 10:23:11 PM	No	
77,132	Brake Pad Thickness RF	10 Inch		CKARLENS	Jun 7, 2018 10:23:12 PM	No	
77,133	Brake Pad Thickness LR	8 Inch		CKARLENS	Jun 7, 2018 10:23:12 PM	No	
77,134	Brake Pad Thickness RR	8 Inch		CKARLENS	Jun 7, 2018 10:23:12 PM	No	
77,135	Brake Rotor LF	39.8 Inch		CKARLENS	Jun 7, 2018 10:23:12 PM	No	
77,136	Brake Rotor RF	39.8 Inch		CKARLENS	Jun 7, 2018 10:23:12 PM	No	
77,137	Brake Rotor LR	35.8 Inch		CKARLENS	Jun 7, 2018 10:23:12 PM	No	
77,138	Brake Rotor RR	35.8 Inch		CKARLENS	Jun 7, 2018 10:23:12 PM	No	
77,140	FRA Check Brake Hoses	Done		CKARLENS	Jun 7, 2018 10:23:12 PM	No	
77,150	Check King Pins	-	NA	CKARLENS	Jun 7, 2018 10:23:12 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		CKARLENS	Jun 7, 2018 10:23:13 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		CKARLENS	Jun 7, 2018 10:23:13 PM	No	
80,810	Completion of PMI Report	Done		CKARLENS	Jun 7, 2018 10:23:13 PM	No	
90,000	SECTION 9 Completion of PMI	Done		CKARLENS	Jun 7, 2018 10:23:13 PM	No	
90,910	Vehicle Returned to predetermined location	Done		CKARLENS	Jun 7, 2018 10:23:14 PM	No	

LH: 20 Desc: PM B
Task: PM B SERVICE Performed by: CKARLENS Performed on: 07-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		CKARLENS	Jun 7, 2018 10:14:28 PM	No	
101,000	FRA Change Oil Filters	Yes		CKARLENS	Jun 7, 2018 10:14:28 PM	No	
102,000	FRA Drain Engine Oil	Yes		CKARLENS	Jun 7, 2018 10:14:29 PM	No	
103,000	FRA Check Transmission Fluid	Done		CKARLENS	Jun 7, 2018 10:14:29 PM	No	
104,000	Lubricate Chassis	Done		CKARLENS	Jun 7, 2018 10:14:29 PM	No	
105,000	Replace or Clean A/C Filters	Done		CKARLENS	Jun 7, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:14:29 PM		
107,000	FRA Change Primary Fuel Filter	No	NA	CKARLENS	Jun 7, 2018 10:14:29 PM	No	
108,000	Lube all pivoting Mechanisms	Done		CKARLENS	Jun 7, 2018 10:14:29 PM	No	
200,000	"B" PMI SERVICING ITEMS (12 MONTH)	Done		CKARLENS	Jun 7, 2018 10:14:30 PM	No	
201,000	Service Crankcase Breather	Done		CKARLENS	Jun 7, 2018 10:14:30 PM	No	
203,000	FRA Change Automatic Transmission Fluid	Yes		CKARLENS	Jun 7, 2018 10:14:30 PM	No	
204,000	FRA Change Power Steering Fluid and Filter	No		CKARLENS	Jun 7, 2018 10:14:30 PM	Yes	51408864
205,000	Complete Engine Diagnostics and Clear Codes when Completed	Done		CKARLENS	Jun 7, 2018 10:14:30 PM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 07-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Jun 7, 2018 10:13:47 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51869856
Invoice Number: 55345-51869856

Client Department:			
MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
PM B		**VIN:**	1FDEE3FLXFDA02748
Requested By:	DARTHURS	**Status:**	32
Created By:	DARTHURS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Nov 30, 2018	11:55 AM
Started	Nov 30, 2018	
Completed	Nov 30, 2018	9:12 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	192,142	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMB Service CAUSE: Service Due by Mileage CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check brakes. Clean batteries. Parts # B329 Qty (1) Oil 5W 20 Qty(6.5) Qt

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
30-Nov-18	Arthurs,Durvin	2.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
30-Nov-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52372794
Invoice Number: 55345-52372794

Client Department:
MRC: 55345M
WO Desc:
PM B
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5447
Ford E350 Champion Crusaders
VIN: 1FDEE3FLXFDA02748
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	May 23, 2019	2:05 PM
Started	May 23, 2019	
Completed	May 23, 2019	11:04 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	217,798	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMB SERVICE CAUSE: PREVENTIVE MAINTENANCE CORRECTION: PERFORM AND COMPLETED PMA SERVICE Replaced 1 interior light

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
23-May-19	AMRIT TEEMAL,VISHNU	1.50	65.00	97.50

Activity 10 Sub Total

Parts:	0.00
Labor:	97.50
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
23-May-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52972413
Invoice Number: 55345-52972413

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
PM B		**VIN:**	1FDEE3FLXFDA02748
Requested By:	RRENE	**Status:**	40
Created By:	RRENE	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Dec 9, 2019	12:00 AM
Started		
Completed	Dec 9, 2019	11:54 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	244,331	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMB CAUSE: Service CORRECTION: perform PMB service Oil filter B329 qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
09-Dec-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53770682
Invoice Number: 55345-53770682

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMB		**VIN:**	1FDEE3FLXFDA02748
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Sep 30, 2020	12:00 AM
Started	Sep 30, 2020	
Completed	Oct 1, 2020	12:25 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	269,442	DH
System	269,582	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMB CAUSE:Service CORRECTION:perform PMB service Oil filter B329 qty1 Engine oil 10w30 qty 7 Qts

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note:	PERSONAL RISK ASSESSMENT
Reason for Repair:	SW - Shop Work Order
Work Accomplished:	06 - Inspect
Part Failure:	00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note:	Light Duty PMI
Reason for Repair:	08 - Preventive Maintenance
Work Accomplished:	-
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

FIRSTstudent
First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 55827228
Invoice Number: 55345-55827228

Client Department:
MRC: 55345M
Equipment: 5447
WO Desc: Ford E350 Champion Crusaders
55345-LIGHT DUTY PMB
VIN: 1FDEE3FLXFDA02748
Requested By: RGASPARD
Status: 40
Created By: RGASPARD
Priority: 3
Class: WO
Driver:
Arrangement: Unassigned
Phone:
Potential Warranty: No
ETA:

Chronology		
Reported	Sep 22, 2022	12:00 AM
Started	Sep 29, 2022	
Completed	Sep 30, 2022	12:23 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	321,535	DH
System	321,269	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMB CAUSE:Service CORRECTION:Perform PMB Service oil filter B329 qty1 engine oil 10w30 qty u qts add washer fluid check inflate tires to spec

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**

Activity Note: Light Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

WorkOrder: 55827228
Invoice Number: 55345-55827228

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMB		**VIN:**	1FDEE3FLXFDA02748
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Date	Part Number		Description	Qty.	Each	Extended
29-Sep-22	B329		FILTER, OIL, SPIN-ON	1.00	2.86	2.86

Labor Posted

Date	Technician	Hours	Rate	Extended
29-Sep-22	Gaspard,Ronald	1.33	0.00	0.00

Activity 10 Sub Total

Parts:	2.86
Labor:	0.00
Labor Hours: 1.33	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.86**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
30-Sep-22	Gaspard,Ronald	0.37	0.00	0.00

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.37	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

WorkOrder 55827228 Grand Total

Parts:	2.86
Labor:	0.00
Labor Hours: 1.70	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	**2.86**

Recent Repair History

WorkOrder: 55827228
Invoice Number: 55345-55827228

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMB		**VIN:**	1FDEE3FLXFDA02748
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

WorkOrder	Date Completed	Life Meter	Class	Description
55827228	30-Sep-22	321,535	WO	55345-LIGHT DUTY PMB
55966497	20-Sep-22	320,835	WO	rear tires low specs
55938208	18-Sep-22	320,554	WO	Front AC malfunction.
55897527	29-Aug-22	319,481	WO	55345 PER DVIR (Check AC And Check Engine Light)

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
55421655	13-Jul-22	0	WO	QCC FLEET INSPECTION

PH: Work Order: 55827228 Desc: 55345-LIGHT DUTY PMB
Equip: 5447 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FLXFDA02748

LH: 10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 29-SEP-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		RGASPARD	Sep 29, 2022 10:46:32 PM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Sep 29, 2022 10:46:37 PM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		RGASPARD	Sep 29, 2022 10:46:41 PM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Sep 29, 2022 10:46:46 PM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Sep 29, 2022 10:46:51 PM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Sep 29, 2022 10:46:55 PM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Sep 29, 2022 10:47:00 PM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Sep 29, 2022 10:47:05 PM	No	
10,800	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Sep 29, 2022 10:47:09 PM	No	
10,900	INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Sep 29, 2022 10:47:14 PM	No	
11,100	INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Sep 29, 2022 10:47:19 PM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Sep 29, 2022 10:47:24 PM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Sep 29, 2022 10:47:29 PM	No	
20,200	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Sep 29, 2022 10:47:33 PM	No	
20,300	*RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Sep 29, 2022 10:47:38 PM	No	
20,400	PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Sep 29, 2022 10:47:43 PM	No	
20,500	*RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Sep 29, 2022 10:47:47 PM	No	
20,600	*RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Sep 29, 2022 10:47:52 PM	No	
20,700	INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Sep 29, 2022 10:47:57 PM	No	
20,800	INSPECT_High Idle Control	Done		RGASPARD	Sep 29, 2022 10:48:02 PM	No	
20,900	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Sep 29, 2022 10:48:07 PM	No	
21,000	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Sep 29, 2022 10:48:11 PM	No	
21,100	INSPECT_Parking Brake Operation	Done		RGASPARD	Sep 29, 2022 10:48:16 PM	No	
21,200	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Sep 29, 2022 10:48:20 PM	No	
21,300	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Sep 29, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:48:25 PM		
21,400	*RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Sep 29, 2022 10:48:30 PM	No	
21,500	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Sep 29, 2022 10:48:35 PM	No	
21,550	INSPECT_Driver Floor Area for Rust/Water Leaks	Done		RGASPARD	Sep 29, 2022 10:48:39 PM	No	
21,600	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Sep 29, 2022 10:48:44 PM	No	
21,700	INSPECT_Engine Fault Codes	Done		RGASPARD	Sep 29, 2022 10:48:48 PM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Sep 29, 2022 10:48:53 PM	No	
31,000	SSF (Street Side Front)	Done		RGASPARD	Sep 29, 2022 10:48:58 PM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Sep 29, 2022 10:49:03 PM	No	
31,020	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Sep 29, 2022 10:49:07 PM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Sep 29, 2022 10:49:12 PM	No	
31,040	INSPECT_Wiper Blades, Arms	Done		RGASPARD	Sep 29, 2022 10:49:17 PM	No	
32,000	Engine Inspection	Done		RGASPARD	Sep 29, 2022 10:49:21 PM	No	
32,010	INSPECT_Hood, Springs and Props	Done		RGASPARD	Sep 29, 2022 10:49:26 PM	No	
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Sep 29, 2022 10:49:33 PM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Sep 29, 2022 10:49:37 PM	No	
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	Sep 29, 2022 10:49:45 PM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Sep 29, 2022 10:49:50 PM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Sep 29, 2022 10:49:55 PM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Sep 29, 2022 10:49:59 PM	No	
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Sep 29, 2022 10:50:04 PM	No	
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Sep 29, 2022 10:50:08 PM	No	
32,100	INSPECT_Intake System	Done		RGASPARD	Sep 29, 2022 10:50:13 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Sep 29, 2022 10:50:20 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Sep 29, 2022 10:50:42 PM	No	
33,010	CSF (Curb Side Front)	Done		RGASPARD	Sep 29, 2022 10:50:47 PM	No	
33,020	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Sep 29, 2022 10:50:51 PM	No	
33,030	*RPT*INSPECT_ FRONT Springs, Shocks, Spring	Done		RGASPARD	Sep 29, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Shackles				10:50:56 PM		
33,040	INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Sep 29, 2022 10:51:01 PM	No	
33,050	INSPECT_Wiper Blades, Arms	Done		RGASPARD	Sep 29, 2022 10:51:06 PM	No	
33,060	!FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	Sep 29, 2022 10:51:10 PM	No	
33,070	*RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	RGASPARD	Sep 29, 2022 10:51:18 PM	No	
33,080	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Sep 29, 2022 10:51:23 PM	No	
40,000	SECTION 4 - Interior Inspection	Done		RGASPARD	Sep 29, 2022 10:51:27 PM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Sep 29, 2022 10:51:32 PM	No	
40,200	INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		RGASPARD	Sep 29, 2022 10:51:37 PM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Sep 29, 2022 10:51:42 PM	No	
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	Sep 29, 2022 10:51:46 PM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Sep 29, 2022 10:51:51 PM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Sep 29, 2022 10:51:55 PM	No	
40,700	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Sep 29, 2022 10:52:00 PM	No	
40,800	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Sep 29, 2022 10:52:04 PM	No	
40,900	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Sep 29, 2022 10:52:09 PM	No	
41,000	INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Sep 29, 2022 10:52:13 PM	No	
41,100	INSPECT_CLEAN_AC Filter	Done		RGASPARD	Sep 29, 2022 10:52:18 PM	No	
41,200	INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		RGASPARD	Sep 29, 2022 10:52:23 PM	No	
41,300	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Sep 29, 2022 10:52:27 PM	No	
41,400	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Sep 29, 2022 10:52:32 PM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Sep 29, 2022 10:52:38 PM	No	
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Sep 29, 2022 10:52:43 PM	No	
50,200	INSPECT_Ball Joint Play	Done		RGASPARD	Sep 29, 2022 10:52:47 PM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Sep 29, 2022 10:52:52 PM	No	
50,400	LUBE_All Chassis Components	Done	na	RGASPARD	Sep 29, 2022 10:52:58 PM	No	
50,500	!FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Sep 29, 2022 10:53:03 PM	No	
50,700	INSPECT_Tire Condition	Done		RGASPARD	Sep 29, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:53:08 PM		
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Sep 29, 2022 10:53:12 PM	No	
50,900	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Sep 29, 2022 10:53:17 PM	No	
51,000	RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Sep 29, 2022 10:54:36 PM	No	
51,100	RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Sep 29, 2022 10:54:41 PM	No	
51,200	RECORD_RF-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Sep 29, 2022 10:54:45 PM	No	
51,300	RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Sep 29, 2022 10:54:50 PM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Sep 29, 2022 10:54:57 PM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Sep 29, 2022 10:55:01 PM	No	
51,600	!FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Sep 29, 2022 10:55:06 PM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		RGASPARD	Sep 29, 2022 10:55:10 PM	No	
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		RGASPARD	Sep 29, 2022 10:55:15 PM	No	
51,900	INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	37 Inch		RGASPARD	Sep 29, 2022 10:55:20 PM	No	
52,000	INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	37 Inch		RGASPARD	Sep 29, 2022 10:55:25 PM	No	
52,100	INSPECT_Vibration Damper	Done		RGASPARD	Sep 29, 2022 10:55:30 PM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Sep 29, 2022 10:55:34 PM	No	
52,400	!FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Sep 29, 2022 10:55:39 PM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Sep 29, 2022 10:55:43 PM	No	
52,700	INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Sep 29, 2022 10:55:48 PM	No	
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Sep 29, 2022 10:55:53 PM	No	
52,900	INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Sep 29, 2022 10:55:57 PM	No	
53,000	!FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Sep 29, 2022 10:56:02 PM	No	
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Sep 29, 2022 10:56:06 PM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Sep 29, 2022 10:56:11 PM	No	
53,300	*RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Sep 29, 2022 10:56:16 PM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Sep 29, 2022 10:56:21 PM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Sep 29, 2022 10:56:26 PM	No	
53,600	INSPECT_Tire Condition	Done		RGASPARD	Sep 29, 2022 10:56:31 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Sep 29, 2022 10:56:35 PM	No	
53,800	INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Sep 29, 2022 10:56:40 PM	No	
53,900	INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Sep 29, 2022 10:56:45 PM	No	
54,000	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Sep 29, 2022 10:56:49 PM	No	
54,100	INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Sep 29, 2022 10:56:54 PM	No	
54,200	RECORD_RRO-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Sep 29, 2022 10:57:00 PM	No	
54,300	RECORD_RRI-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Sep 29, 2022 10:57:05 PM	No	
54,400	RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Sep 29, 2022 10:57:10 PM	No	
54,500	RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Sep 29, 2022 10:57:15 PM	No	
54,600	RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Sep 29, 2022 10:57:26 PM	No	
54,700	RECORD_LRI-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Sep 29, 2022 10:57:31 PM	No	
54,800	RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Sep 29, 2022 10:57:37 PM	No	
54,900	RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Sep 29, 2022 10:57:41 PM	No	
55,000	!FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Sep 29, 2022 10:57:46 PM	No	
55,100	!FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Sep 29, 2022 10:57:51 PM	No	
55,200	!FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Sep 29, 2022 10:57:55 PM	No	
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch		RGASPARD	Sep 29, 2022 10:58:01 PM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch		RGASPARD	Sep 29, 2022 10:58:06 PM	No	
55,500	INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	38 Inch		RGASPARD	Sep 29, 2022 10:58:11 PM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	38 Inch		RGASPARD	Sep 29, 2022 10:58:15 PM	No	
55,700	!FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Sep 29, 2022 10:58:20 PM	No	
55,800	*RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Sep 29, 2022 10:58:25 PM	No	
55,900	*RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Sep 29, 2022 10:58:29 PM	No	
60,000	SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Sep 29, 2022 10:58:34 PM	No	
60,100	RECORD_Wheelchair Cycle Count	11245 Cycles		RGASPARD	Sep 29, 2022 10:58:40 PM	No	
60,200	CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Sep 29, 2022 10:58:45 PM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Sep 29, 2022 10:58:49 PM	No	
60,400	OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky	Done		RGASPARD	Sep 29, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Op,Too Fast-Slow,Drift Down				10:58:54 PM		
60,500	INSPECT_ Bridgeplate Operation	Done		RGASPARD	Sep 29, 2022 10:58:59 PM	No	
60,600	INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Sep 29, 2022 10:59:03 PM	No	
60,700	INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Sep 29, 2022 10:59:08 PM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Sep 29, 2022 10:59:13 PM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Sep 29, 2022 10:59:17 PM	No	
61,000	INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Sep 29, 2022 10:59:22 PM	No	
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Sep 29, 2022 10:59:27 PM	No	
61,200	INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Sep 29, 2022 10:59:31 PM	No	
61,300	INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Sep 29, 2022 10:59:36 PM	No	
61,400	INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Sep 29, 2022 10:59:41 PM	No	
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Sep 29, 2022 10:59:45 PM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Sep 29, 2022 10:59:50 PM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Sep 29, 2022 10:59:54 PM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Sep 29, 2022 10:59:59 PM	No	
61,900	CLEAN_Linkages and Mechanisms	Done		RGASPARD	Sep 29, 2022 11:00:04 PM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Sep 29, 2022 11:00:08 PM	No	
62,100	INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Sep 29, 2022 11:00:13 PM	No	
62,200	INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Sep 29, 2022 11:00:17 PM	No	
62,300	INSPECT_Bridgeplate Hinge	Done		RGASPARD	Sep 29, 2022 11:00:24 PM	No	
62,400	INSPECT_All Pivot Points	Done		RGASPARD	Sep 29, 2022 11:00:29 PM	No	
62,500	INSPECT_Cams and Slots	Done		RGASPARD	Sep 29, 2022 11:00:33 PM	No	
62,600	INSPECT_Rollers	Done		RGASPARD	Sep 29, 2022 11:00:38 PM	No	
62,700	INSPECT_All Linkages	Done		RGASPARD	Sep 29, 2022 11:00:43 PM	No	
80,000	SECTION 8 - PMI Report Completion	Done		RGASPARD	Sep 29, 2022 11:00:47 PM	No	
80,100	COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Sep 29, 2022 11:00:52 PM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Sep 29, 2022 11:00:57 PM	No	

LH: 20 Desc: PM B

Task: PM B SERVICE Performed by: RGASPARD Performed on: 30-SEP-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		RGASPARD	Sep 30, 2022 12:00:29 AM	No	
101,000	FRA Change Oil Filters	Yes		RGASPARD	Sep 30, 2022 12:00:34 AM	No	
102,000	FRA Drain Engine Oil	Yes		RGASPARD	Sep 30, 2022 12:00:38 AM	No	
103,000	FRA Check Transmission Fluid	Done		RGASPARD	Sep 30, 2022 12:00:43 AM	No	
104,000	Lubricate Chassis	-	na	RGASPARD	Sep 30, 2022 12:00:52 AM	No	
105,000	Replace or Clean A/C Filters	Done		RGASPARD	Sep 30, 2022 12:00:56 AM	No	
107,000	FRA Change Primary Fuel Filter	No	na	RGASPARD	Sep 30, 2022 12:01:04 AM	No	
108,000	Lube all pivoting Mechanisms	Done		RGASPARD	Sep 30, 2022 12:01:09 AM	No	
200,000	"B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Sep 30, 2022 12:01:13 AM	No	
201,000	Service Crankcase Breather	Done		RGASPARD	Sep 30, 2022 12:01:18 AM	No	
203,000	FRA Change Automatic Transmission Fluid	No		RGASPARD	Sep 30, 2022 12:01:24 AM	No	
204,000	FRA Change Power Steering Fluid and Filter	No		RGASPARD	Sep 30, 2022 12:01:29 AM	No	
205,000	Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Sep 30, 2022 12:01:35 AM	No	

LH: 5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 29-SEP-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		RGASPARD	Sep 29, 2022 10:38:24 PM	No	
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Sep 29, 2022 10:38:29 PM	No	
4	Are you wearing the appropriate PPE?	Done		RGASPARD	Sep 29, 2022 10:38:33 PM	No	
7	Have you performed the proper LOTO?	Done		RGASPARD	Sep 29, 2022 10:38:38 PM	No	
10	Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Sep 29, 2022 10:38:43 PM	No	
11	Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Sep 29, 2022 10:38:48 PM	No	

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51574696
Invoice Number: 55345-51574696

Client Department:			
MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
PM C		**VIN:**	1FDEE3FLXFDA02748
Requested By:	DKNOTT	**Status:**	40
Created By:	DKNOTT	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Sep 5, 2018	7:07 AM
Started	Sep 6, 2018	
Completed	Sep 6, 2018	9:47 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	179,526	DH
System	179,526	DH

WorkOrder Notes

Line	Comment
10	PMC Preventive maintenance Perform service lube all Pivoting Points cross Rotate Tires completed

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
06-Sep-18	Pierre,Hubert J	8.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 8.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
05-Sep-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52123623
Invoice Number: 55345-52123623

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
PM C		**VIN:**	1FDEE3FLXFDA02748
Requested By:	DARTHURS	**Status:**	40
Created By:	DARTHURS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Feb 26, 2019	10:45 AM
Started	Feb 26, 2019	
Completed	Feb 26, 2019	10:17 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	204,772	DH
System	204,948	DH

WorkOrder Notes

Line	Comment
10	PMC service Preventive maintenance Performed and completed PMC service Replaced air filter

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
26-Feb-19	AMRIT TEEMAL,VISHNU	2.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
26-Feb-19	B329		FILTER, OIL (FGA0000399/FSC0000399)	1.00	1.96	1.96
26-Feb-19	20021		FILTER, TRANSMISSION, E350, '09 W/RUBBER NECK SEAL SAME AS FT180	1.00	17.27	17.27

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52635748
Invoice Number: 55345-52635748

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
PM C		**VIN:**	1FDEE3FLXFDA02748
Requested By:	DARTHURS	**Status:**	40
Created By:	DARTHURS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Aug 27, 2019	12:00 AM
Started	Aug 27, 2019	
Completed	Aug 27, 2019	10:40 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	230,625	DH

WorkOrder Notes

Line	Comment
10	PMC SERVICE PREVENTIVE MAINTENANCE PERFORM AND COMPLETED PMC SERVICE

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
27-Aug-19	AMRIT TEEMAL,VISHNU	2.50	65.00	162.50

Activity 10 Sub Total

Parts:	0.00
Labor:	162.50
Labor Hours: 2.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**162.50**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
27-Aug-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96
27-Aug-19	20021		FILTER, TRANSMISSION, E350, '09 W/RUBBER NECK SEAL SAME AS FT180	1.00	17.27	17.27

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53275557
Invoice Number: 55345-53275557

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
PM C		**VIN:**	1FDEE3FLXFDA02748
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Mar 24, 2020	11:19 AM
Started	Mar 24, 2020	
Completed	Mar 24, 2020	11:41 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	256,659	DH

WorkOrder Notes

Line	Comment
10	Perform PMC Service , Check Brakes. Clean batteries. Perform differential service. drain fill differential..changeOil &Filter no transmission service Fluid Clean. Replace hose clamp on Lower radiator neck. Parts # B329 Qty (1) Oil 10W30 Qty (6.5) Qt Gear Oil 80W90 Qty (3) Qt

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
24-Mar-20	Arthurs,Durvin	2.55	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 2.55	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
24-Mar-20	B329(F)		FILTER, OIL, SPIN-ON	1.00	1.96	1.96

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 54167857
Invoice Number: 55345-54167857

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMC		**VIN:**	1FDEE3FLXFDA02748
Requested By:	JUHURST	**Status:**	40
Created By:	JUHURST	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Feb 12, 2021	12:00 AM
Started	Feb 12, 2021	
Completed	Feb 13, 2021	12:32 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	282,549	DH
System	282,652	DH

WorkOrder Notes

Line	Comment
10	PMC Service Perform PMC Service Oil filter B329 qty1 Engine oil 10w30 qty 7 qts Air filter PA4075 qty1 Gear Oil 80w90 qty 4 qts

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note:	PERSONAL RISK ASSESSMENT
Reason for Repair:	SW - Shop Work Order
Work Accomplished:	06 - Inspect
Part Failure:	00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**

Activity Note:	Light Duty PMI
Reason for Repair:	05 - Inspection, Routine
Work Accomplished:	-
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 55421653
Invoice Number: 55345-55421653

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMC		**VIN:**	1FDEE3FLXFDA02748
Requested By:	SPACE	**Status:**	40
Created By:	SPACE	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Apr 25, 2022	12:00 AM
Started	Apr 29, 2022	
Completed	Apr 29, 2022	12:41 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	307,199	DH
System	306,851	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMC Service Cause: preventive maintenance Correction: Perform PMC Service ,lube all Pivoting Points, transmission Service, rear end

Activity: 5 999/999/999 TOTAL VEHICLE

Activity Note:	PERSONAL RISK ASSESSMENT
Reason for Repair:	SW - Shop Work Order
Work Accomplished:	06 - Inspect
Part Failure:	00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 999 TOTAL VEHICLE

Activity Note:	Light Duty PMI
Reason for Repair:	08 - Preventive Maintenance
Work Accomplished:	-
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder: 55421653
Invoice Number: 55345-55421653

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMC		**VIN:**	1FDEE3FLXFDA02748
Requested By:	SPACE	**Status:**	40
Created By:	SPACE	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Date	Technician	Hours	Rate	Extended
29-Apr-22	NELSON PIERRE-LOUIS	2.07	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 2.07	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
29-Apr-22	B329		FILTER, OIL, SPIN-ON	1.00	1.99	1.99
29-Apr-22	20021		FILTER, TRANSMISSION 20021	1.00	17.44	17.44
29-Apr-22	P9600		FILTER, OIL	1.00	3.49	3.49

Labor Posted

Date	Technician	Hours	Rate	Extended
29-Apr-22	NELSON PIERRE-LOUIS	1.10	0.00	0.00

Activity 20 Sub Total

Parts:	22.92
Labor:	0.00
Labor Hours: 1.10	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**22.92**

WorkOrder 55421653 Grand Total

Parts:	22.92
Labor:	0.00
Labor Hours: 3.17	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	**22.92**

Recent Repair History

WorkOrder: 55421653
Invoice Number: 55345-55421653

Client Department:

MRC:	55345M	**Equipment:**	5447
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMC		**VIN:**	1FDEE3FLXFDA02748
Requested By:	SPACE	**Status:**	40
Created By:	SPACE	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

WorkOrder	Date Completed	Life Meter	Class	Description
55421653	29-Apr-22	307,199	WO	55345-LIGHT DUTY PMC
55480256	31-Mar-22	303,622	WO	CHECK FOR FUEL ODOR

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description

PH: Work Order: 55421653 Desc: 55345-LIGHT DUTY PMC
Equip: 5447 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FLXFDA02748

LH: 10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS Performed on: 29-APR-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:15 AM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:16 AM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:16 AM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:17 AM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:17 AM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:18 AM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:18 AM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:19 AM	No	
10,800	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		NPIERRE-LOUIS	Apr 29, 2022 10:53:39 AM	No	
10,900	INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:19 AM	No	
11,100	INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:20 AM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:20 AM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:21 AM	No	
20,200	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:21 AM	No	
20,300	*RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		NPIERRE-LOUIS	Apr 29, 2022 10:53:52 AM	No	
20,400	PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:22 AM	No	
20,500	*RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	Apr 29, 2022 10:53:58 AM	No	
20,600	*RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	Apr 29, 2022 10:54:03 AM	No	
20,700	INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:23 AM	No	
20,800	INSPECT_High Idle Control	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:23 AM	No	
20,900	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	Apr 29, 2022 10:54:12 AM	No	
21,000	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	Apr 29, 2022 10:54:16 AM	No	
21,100	INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:23 AM	No	
21,200	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:24 AM	No	
21,300	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		NPIERRE-	Apr 29, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
				LOUIS	10:59:24 AM		
21,400	*RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	Apr 29, 2022 10:54:27 AM	No	
21,500	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:25 AM	No	
21,550	INSPECT_Driver Floor Area for Rust/Water Leaks	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:26 AM	No	
21,600	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	Apr 29, 2022 10:54:35 AM	No	
21,700	INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:26 AM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION - Front	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:27 AM	No	
31,000	SSF (Street Side Front)	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:27 AM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Apr 29, 2022 10:54:47 AM	No	
31,020	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Apr 29, 2022 10:54:52 AM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:28 AM	No	
31,040	INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:28 AM	No	
32,000	Engine Inspection	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:29 AM	No	
32,010	INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:29 AM	No	
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:30 AM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:30 AM	No	
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:31 AM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	280 Degree Fahrenheit		NPIERRE-LOUIS	Apr 29, 2022 10:59:31 AM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:32 AM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	Apr 29, 2022 10:55:38 AM	No	
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		NPIERRE-LOUIS	Apr 29, 2022 10:55:48 AM	No	
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	Apr 29, 2022 10:55:53 AM	No	
32,100	INSPECT_Intake System	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:32 AM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.5 Volt*		NPIERRE-LOUIS	Apr 29, 2022 10:57:23 AM	No	
33,010	CSF (Curb Side Front)	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:33 AM	No	
33,020	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Apr 29, 2022 10:57:29 AM	No	
33,030	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Apr 29, 2022 10:57:34 AM	No	
33,040	INSPECT_Mud Flaps, Brackets	Done		NPIERRE-	Apr 29, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
				LOUIS	10:57:41 AM		
33,050	INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:33 AM	No	
33,060	!FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:34 AM	No	
33,070	*RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	12.2 Volt*		NPIERRE-LOUIS	Apr 29, 2022 10:58:01 AM	No	
33,080	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:35 AM	No	
40,000	SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:35 AM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	Apr 29, 2022 10:58:09 AM	No	
40,200	INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:36 AM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:36 AM	No	
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:37 AM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:37 AM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:38 AM	No	
40,700	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	Apr 29, 2022 10:58:25 AM	No	
40,800	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	Apr 29, 2022 10:58:31 AM	No	
40,900	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:38 AM	No	
41,000	INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:38 AM	No	
41,100	INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:39 AM	No	
41,200	INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:40 AM	No	
41,300	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	Apr 29, 2022 10:58:44 AM	No	
41,400	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	Apr 29, 2022 10:58:50 AM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:40 AM	No	
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	Apr 29, 2022 10:58:57 AM	No	
50,200	INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:41 AM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:41 AM	No	
50,400	LUBE_All Chassis Components	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:42 AM	No	
50,500	!FRA!CHANGE_Engine oil,filters	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:43 AM	No	
50,700	INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:43 AM	No	
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-	Apr 29, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
				LOUIS	10:59:44 AM		
50,900	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Apr 29, 2022 10:59:44 AM	No	
51,000	RECORD_LF-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Apr 29, 2022 11:09:29 AM	No	
51,100	RECORD_LF-Tire Air Pressure (psi)	69 Pounds per Square Inch		NPIERRE-LOUIS	Apr 29, 2022 11:09:30 AM	No	
51,200	RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Apr 29, 2022 11:13:25 AM	Yes	55563781
51,300	RECORD_RF-Air Pressure (psi)	68 Pounds per Square Inch		NPIERRE-LOUIS	Apr 29, 2022 11:09:31 AM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	Apr 29, 2022 11:09:31 AM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	Apr 29, 2022 11:09:32 AM	No	
51,600	!FRA!INSPECT_ Front Brake Assemblies	Done		NPIERRE-LOUIS	Apr 29, 2022 11:09:33 AM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Apr 29, 2022 11:09:33 AM	No	
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Apr 29, 2022 11:09:34 AM	No	
51,900	INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	35.5 Inch		NPIERRE-LOUIS	Apr 29, 2022 11:09:34 AM	No	
52,000	INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	35.5 Inch		NPIERRE-LOUIS	Apr 29, 2022 11:09:35 AM	No	
52,100	INSPECT_Vibration Damper	Done		NPIERRE-LOUIS	Apr 29, 2022 11:09:35 AM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	Apr 29, 2022 11:09:36 AM	No	
52,400	!FRA!INSPECT_ Starter Mounting	Done		NPIERRE-LOUIS	Apr 29, 2022 11:09:36 AM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	Apr 29, 2022 11:09:36 AM	No	
52,700	INSPECT_ Engine, Transmission Mounts	Done		NPIERRE-LOUIS	Apr 29, 2022 11:09:37 AM	No	
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	Apr 29, 2022 11:09:38 AM	No	
52,900	INSPECT_ Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	Apr 29, 2022 11:09:38 AM	No	
53,000	!FRA!INSPECT_ Transmission Breather and Clean	Done		NPIERRE-LOUIS	Apr 29, 2022 11:09:39 AM	No	
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	Apr 29, 2022 11:02:58 AM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	Apr 29, 2022 11:03:03 AM	No	
53,300	*RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	Apr 29, 2022 11:03:15 AM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	Apr 29, 2022 11:03:10 AM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	Apr 29, 2022 11:09:39 AM	No	
53,600	INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Apr 29, 2022 11:09:40 AM	No	
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Apr 29, 2022 11:09:40 AM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
53,800	INSPECT_ Mismatched Tire Tread, Casing Design	Done		NPIERRE-LOUIS	Apr 29, 2022 11:09:41 AM	No	
53,900	INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	Apr 29, 2022 11:09:41 AM	No	
54,000	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Apr 29, 2022 11:09:42 AM	No	
54,100	INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Apr 29, 2022 11:09:42 AM	No	
54,200	RECORD_RRO-Tire Tread Depth (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Apr 29, 2022 11:09:43 AM	No	
54,300	RECORD_RRI-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Apr 29, 2022 11:09:44 AM	No	
54,400	RECORD_RRO-Air Pressure (psi)	68 Pounds per Square Inch		NPIERRE-LOUIS	Apr 29, 2022 11:09:44 AM	No	
54,500	RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Apr 29, 2022 11:09:45 AM	No	
54,600	RECORD_LRO-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Apr 29, 2022 11:09:45 AM	No	
54,700	RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Apr 29, 2022 11:09:46 AM	No	
54,800	RECORD_LRO-Air Pressure (psi)	69 Pounds per Square Inch		NPIERRE-LOUIS	Apr 29, 2022 11:09:47 AM	No	
54,900	RECORD_LRI-Air Pressure (psi)	68 Pounds per Square Inch		NPIERRE-LOUIS	Apr 29, 2022 11:09:49 AM	No	
55,000	!FRA!INSPECT_ REAR Brake Assemblies	Done		NPIERRE-LOUIS	Apr 29, 2022 11:09:55 AM	No	
55,100	!FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	Apr 29, 2022 11:09:58 AM	No	
55,200	!FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	Apr 29, 2022 11:09:58 AM	No	
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Apr 29, 2022 11:09:59 AM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Apr 29, 2022 11:09:59 AM	No	
55,500	INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	25.5 Inch		NPIERRE-LOUIS	Apr 29, 2022 11:10:00 AM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	25.5 Inch		NPIERRE-LOUIS	Apr 29, 2022 11:10:00 AM	No	
55,700	!FRA!INSPECT_ Under Body Exhaust System	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:01 AM	No	
55,800	*RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	Apr 29, 2022 11:07:53 AM	No	
55,900	*RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		NPIERRE-LOUIS	Apr 29, 2022 11:07:59 AM	No	
60,000	SECTION 6 - Wheelchair Inspection	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:01 AM	No	
60,100	RECORD_Wheelchair Cycle Count	0 Cycles		NPIERRE-LOUIS	Apr 29, 2022 11:10:02 AM	No	
60,200	CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:02 AM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:03 AM	No	
60,400	OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:04 AM	No	
60,500	INSPECT_ Bridgeplate Operation	Done		NPIERRE-	Apr 29, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
				LOUIS	11:10:04 AM		
60,600	INSPECT_All Pivot Points for Wear and Looseness	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:04 AM	No	
60,700	INSPECT_Rollers for Wear and Smooth Rotation	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:05 AM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:05 AM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:06 AM	No	
61,000	INSPECT_Cable Condition (If Applicable)	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:06 AM	No	
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:07 AM	No	
61,200	INSPECT_Electrical Connections and Routing of Wires and Cables	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:07 AM	No	
61,300	INSPECT_Operation and Adjustment of All Safety Switches	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:08 AM	No	
61,400	INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:08 AM	No	
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:09 AM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:09 AM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:10 AM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:10 AM	No	
61,900	CLEAN_Linkages and Mechanisms	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:11 AM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:12 AM	No	
62,100	INSPECT_Emergency Platform Release Mechanism	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:13 AM	No	
62,200	INSPECT_Platform Barrier Latch Mechanism	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:13 AM	No	
62,300	INSPECT_Bridgeplate Hinge	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:14 AM	No	
62,400	INSPECT_All Pivot Points	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:15 AM	No	
62,500	INSPECT_Cams and Slots	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:14 AM	No	
62,600	INSPECT_Rollers	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:16 AM	No	
62,700	INSPECT_All Linkages	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:16 AM	No	
80,000	SECTION 8 - PMI Report Completion	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:16 AM	No	
80,100	COMPLETE_PM Report; Follow-ups	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:17 AM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	Apr 29, 2022 11:10:18 AM	No	

LH: 20 Desc: PM C
Task: PM C SERVICE Performed by: NPIERRE-LOUIS Performed on: 29-APR-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Apr 29, 2022 11:15:59 AM	No	
101,000	FRA Change Oil Filters	No		NPIERRE-LOUIS	Apr 29, 2022 11:15:59 AM	No	
102,000	FRA Drain Engine Oil	No		NPIERRE-LOUIS	Apr 29, 2022 11:16:00 AM	No	
103,000	FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Apr 29, 2022 11:16:01 AM	No	
104,000	Lubricate Chassis	Done		NPIERRE-LOUIS	Apr 29, 2022 11:16:01 AM	No	
105,000	Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Apr 29, 2022 11:16:02 AM	No	
107,000	FRA Change Primary Fuel Filter	Done		NPIERRE-LOUIS	Apr 29, 2022 11:16:02 AM	No	
108,000	Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Apr 29, 2022 11:16:03 AM	No	
200,000	"B" PMI SERVICING ITEMS (12 MONTH)	Done		NPIERRE-LOUIS	Apr 29, 2022 11:16:04 AM	No	
201,000	Service Crankcase Breather	Done		NPIERRE-LOUIS	Apr 29, 2022 11:16:04 AM	No	
203,000	FRA Change Automatic Transmission Fluid	No		NPIERRE-LOUIS	Apr 29, 2022 11:16:04 AM	No	
204,000	FRA Change Power Steering Fluid and Filter	No		NPIERRE-LOUIS	Apr 29, 2022 11:16:05 AM	No	
205,000	Complete Engine Diagnostics and Clear Codes when Completed	Done		NPIERRE-LOUIS	Apr 29, 2022 11:16:05 AM	No	
300,000	"C" PMI SERVICING ITEMS (24 MONTH)	Done		NPIERRE-LOUIS	Apr 29, 2022 11:16:06 AM	No	
301,000	Check and Lubricate Door Linkages	Done		NPIERRE-LOUIS	Apr 29, 2022 11:16:07 AM	No	
302,000	Check Toe-In and Record Reading	Done		NPIERRE-LOUIS	Apr 29, 2022 11:16:07 AM	No	
302,001	Record Toe-In Reading	0 Inches, fraction-actual		NPIERRE-LOUIS	Apr 29, 2022 11:16:08 AM	No	
304,000	1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		NPIERRE-LOUIS	Apr 29, 2022 11:16:08 AM	No	
305,000	FRA Change Differential Fluid	No		NPIERRE-LOUIS	Apr 29, 2022 11:16:09 AM	No	

LH: 5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 29-APR-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Apr 29, 2022 11:15:07 AM	No	
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Apr 29, 2022 11:15:06 AM	No	
4	Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Apr 29, 2022 11:15:06 AM	No	
7	Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Apr 29, 2022 11:15:05 AM	No	
10	Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Apr 29, 2022 11:15:04 AM	No	
11	Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Apr 29, 2022 11:15:04 AM	No	

Vehicle Processing Checklist

Form FAMO 2-010

Date Conducted:_____/_____/_____
Conducted By: _____
Phone Number: (_____)_____

Inspection Date/Time: _____
Location: _____
_____

Vehicle Year/Make/Model►

General Information

VIN: _____
Asset No: _____
Odometer: _____
Engine: ____4 cyl_____6 cyl ____ 8 cyl ____ Other
Engine Displacement: ____Liter ____ CID ____ HP
Fuel Type:_____Diesel ____CNG ____Other

General Condition (circle one in each category)

Exterior	Bad	2	3	4	Excllnt
Interior	Bad	2	3	4	Excllnt
Tires	Bad	2	3	4	Excllnt
Glass	Bad	2	3	4	Excllnt
Mechanical	DNR		Runs		Other

_____
(describe "Other")

Options & Equipment (✓each box that applies)

- ☐ A/C
- ☐ P/S
- ☐ P/B
- ☐ P/W
- ☐ A/T
- ☐ Manual Transmission (_____forward speeds)
- ☐ AM/FM Radio
- ☐ CD Player
- ☐ Cruise Control
- ☐ Airbags (circle one) 1 2 3 4
- ☐ Performance Package: _____

- ☐ ABS
- ☐ 4x4
- ☐ Power Door Locks
- ☐ Power Seats
- ☐ Sunroof
- ☐ Tilt Steering
- ☐ Tinted Windows
- ☐ _____
- ☐ _____
- ☐ _____
- ☐ _____

- ☐ Air Brakes
- ☐ Boom/Bucket
- ☐ Crane
- ☐ Dump Bed _____
- ☐ Tank Bed _____
- ☐ Lightbar/beacon
- ☐ Power Liftgate
- ☐ Tool Box
- ☐ Trailer Hitch
- ☐ Utility Bed
- ☐ Winch

Key

4X4	4-Wheel Drive	CID	Cubic Inch Displacement	P/B	Power Brakes
ABS	Antilock Braking System	CNG	Compressed Natural Gas	P/S	Power Steering
A/C	Air Conditioner	DNR	Does Not Run	P/W	Power Windows
A/T	Automatic Transmission	HP	Horsepower	VIN	Vehicle Identification Number

In order to show your vehicles and equipment at their best, use the following chart and descriptions as a guide for preferred camera angles, lighting conditions, and background.

1) Take the photos with a high-resolution digital camera (a minimum of 3 mega pixels is recommended).

2) Take the photo in an area that is well lighted, but not in a glare, and position yourself so that the sun or artificial light source does not cast your shadow into the picture.

3) Make sure the vehicle is washed and all logo decals have been removed with automotive adhesive remover (3M or similar). If primer must be used, select a primer color that closely matches the vehicle. If possible, pressure wash off-road equipment to remove grease and caked mud caught in treads, tracks and body panels. Make sure that truck beds are free of accumulated trash.

4) Select an area with a neutral background; avoid clutter showing up behind the vehicle. Shrubbery generally makes a good backdrop.

5) The preferred camera locations for common vehicles are the right or left front corners of the vehicle, at approximately a 40 degree angle from straight-on, standing 8-10 feet back from the vehicle, and holding the camera at just above rooftop level (except for very tall equipment). By pointing the camera about one-third of the distance down the right or left side of the vehicle, the entire vehicle should be in the photo frame. Under these conditions, the vehicle will be well displayed and you will avoid "fish-eye" distortions of shooting directly at the leading edge (the front edge of the front fender).