

3/27/2017
4:27:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179172 2009 TORO GRNDMASTER 7200 Mower, 72", Ztr, Side Discharge

Workorder: 939348

Problem: PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts		
In Date: 06/23/2009	Hours	Description	Quantity	
- Pre-Delivery Inspection	2.00			
Parts Charge:	0.00	Labor Charge:	120.00	

Workorder: 945907

Problem: P. M. Service, neec oil plug & filter change. Broken chute, lost 2 bolts on slop wheel.

Meter Reading: 198	Labor	Parts		
In Date: 11/10/2009	Hours	Description	Quantity	
- P.M., & Replace Damaged Drain Plug.	6.00	SHOP SUPPLIES	1.00	
- R/Repair Shute. Replace 2 Mising Bolt-On Lr Scalper		15/40 OIL	4.00	
Wheels.		FUEL FILTER	1.00	
- Shop Supplies		OIL FILTER	1.00	
		6438 AIR FILTERFRM CA9550 WIX 46438	1.00	
		OIL PAN PLUGS	2.00	
Parts Charge:	70.08	Labor Charge:	720.00	

Workorder: 1009828

Problem: Needs rubber deflector grass chute, Mr. Jim requests 2 chutes

Meter Reading: 505	Labor	Parts		
In Date: 09/08/2010	Hours	Description	Quantity	
- Replace Chute.	0.50	SHOP SUPPLIES	1.00	
- Shop Supplies		DEFLECTOR ASSY.	1.00	
Parts Charge:	96.49	Labor Charge:	30.00	

3/27/2017
4:27:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179172 2009 TORO GRNDMASTER 7200 Mower, 72", Ztr, Side Discharge

Workorder: 1012059

Problem: Scalping wheels wore out & needs a new rubber chute

Meter Reading: 574		Labor		Parts	
In Date: 10/27/2010	Close Date: 10/29/2010	Hours	Description		Quantity
-	Replace Damage Shute, Retread Bolts For Shute.	2.00	RUBBER DEFLECTOR ASSY.		2.00
	Replace Both Rear Scalper Wheels On Rear Of Deck.		ROLLER SCALP ANTI.		2.00
-	Shop Supplies		SCREW H H.		2.00
			TUBE SPANNER		2.00
			TUBE SPACER		2.00
			SHOP SUPPLIES		1.00
			NUT FLANGE,NI		2.00
Parts Charge:		286.22	Labor Charge:	120.00	

Workorder: 1014175

Problem: P. M., & check front tires

Meter Reading: 624		Labor		Parts	
In Date: 12/30/2010	Close Date: 01/10/2011	Hours	Description		Quantity
-	P. M. Service.	7.50	OIL FILTER		1.00
-	C/C: New Front Tires. Dismount By Hand, Mount, Add Nitrogen, Repack Wheel Bearings.		SHOP SUPPLIES		1.00
-	Lube Jack Stand. Install Zerk Fittings To Caster Fork.		TIRE DISPOSAL FEE		2.00
-	Adjust Accelerator Pedal, Play Forward & Reverse.		P8043 FUEL FILTER LBF LFF8062 WIX 33472		1.00
-	Shop Supplies		15X6.00-6NHS		2.00
			6438 AIR FILTERFRM CA9550 WIX 46438		1.00
			15/40 OIL		4.00
Parts Charge:		144.73	Labor Charge:	450.00	

Workorder: 1200952

Problem: P. M. SERVICE

Meter Reading: 1100		Labor		Parts	
In Date: 01/30/2012	Close Date: 02/17/2012	Hours	Description		Quantity
-	P. M. Service.	6.50	6438 AIR FILTERFRM CA9550 WIX 46438		1.00
-	Service Hydraulic System.		P8043 FUEL FILTER LBF LFF8062 WIX 33472		1.00
-	Wash Equipment For Service.		15/40 OIL		4.00
-	Shop Supplies		HYD. FILTER		1.00
			OIL FILTER		1.00
			AW68 HYDRO FLUID HYDRAULIC OIL 68		3.00
			SHOP SUPPLIES		1.00
Parts Charge:		63.04	Labor Charge:	390.00	

3/27/2017
4:27:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179172 2009 TORO GRNDMASTER 7200 Mower, 72", Ztr, Side Discharge

Workorder: 1205007

Problem: Need 4 new scalp wheels, and deck gouging into grass, needs adjustment. Also, radiator is leaking.

Meter Reading: 1209	Labor	Parts		
In Date: 05/30/2012	Hours	Description	Quantity	
- Ck Scalp Wheels Deck Adj Replace All G Anti Scalp	7.00	TUBE SPACER	2.00	
Wheels Etc Adj Deck And Test Now		SCREW HH F	1.00	
- Ck Rad Leaking Flush Coolant Flush Engine Clean		SHOP SUPPLIES	1.00	
Coolant Resivoir Etc Refill Test Run Hours Unable To		GREASE CAP	2.00	
Verify Leak At This Time		SHAFT ROLLER REAR	2.00	
- Verify Lr Tire Flat Dismount Froim Rim Clean Rim		BOLT	1.00	
Remount Fill All N2		ROLLER DECK	1.00	
- Shop Supplies		SCREW H H	2.00	
		NUT FLANGE	1.00	
		ROLLER DECK	2.00	
		SHAFT ROLLER	1.00	
		GREEN ANTIFREEZE STOCK #060030002	1.00	
		TUBE SPANNER	2.00	
		NUT FLANGE	3.00	
		ROLLER	1.00	
		SPACER ROLLER	1.00	
		ROLLER SCALP ANTI.	2.00	
Parts Charge:	336.81	Labor Charge:	420.00	

Workorder: 1206021

Problem: low on fluid 2 qts added by chris

Meter Reading: 1222	Labor	Parts		
In Date: 06/26/2012	Hours	Description	Quantity	
- Top Off Fluid	0.50	AW68 HYDRO FLUID HYDRAULIC OIL 68	2.00	
Parts Charge:	4.42	Labor Charge:	30.00	

Workorder: 1206072

Problem: Overheating/ see request

Meter Reading: 1223	Labor	Parts		
In Date: 06/28/2012	Hours	Description	Quantity	
- Repair Leak At Lower Radiator Hose, Top Off Sys Test	3.00	SHOP SUPPLIES	1.00	
Mow Ck Sys Temps =Ok		P8043 FUEL FILTER LBF LFF8062 WIX 33472	1.00	
- Install New Fuel Filter				
- Shop Supplies				
Parts Charge:	7.33	Labor Charge:	180.00	

3/27/2017
4:27:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179172 2009 TORO GRNDMASTER 7200 Mower, 72", Ztr, Side Discharge

Workorder: 1302453

Problem: PM, LEAKING DIESEL FUEL AROUND WATER SEPERATOR RIGHT SIDE FONT TIRE 2 GREASE FITTING

Meter Reading: 1485		Labor		Parts	
In Date: 03/12/2013	Close Date: 03/28/2013	Hours	Description	Quantity	
-	Pm	8.50	OIL FILTER PH7317	1.00	
-	Ck Missing Grease Fittings Install Missing Fittings On Front Wheels		15w40 BULK SOUTH REG	4.00	
-	Ck Leaking Fuel Remove Water Fuel Seperator Assy		SHAFT	2.00	
-	Repair Damaged Hose Reassemble		DECK ROLLER	2.00	
-	Svc Hyd Sys Inspect Lines And Hoses Correct Fuel Level		Freight Charge	1.00	
-	Wash Eq		NAPAGOLD FUEL FILTER	1.00	
-	Shop Supplies		SHOP SUPPLIES	1.00	
			NAPAGOLD AIR FILTER	1.00	
Parts Charge:		168.61	Labor Charge:	510.00	

Workorder: 1304953

Problem: left hand side chain that hold deck broken need to be weld, one of bearing in the front wheel needs

Meter Reading: 1548		Labor		Parts	
In Date: 05/17/2013	Close Date: 05/29/2013	Hours	Description	Quantity	
-	Ck Deck Linkage Front Wheel Bearings Replace Broken	4.00	SCREW	2.00	
-	Clevis On Deck Replace Bearings On Front Wheel Assys		SPACER	4.00	
-	Shop Supplies		SEAL	4.00	
			SHOP SUPPLIES	1.00	
			FRONT CASTER SPACER	2.00	
			STOP NUT	2.00	
			BEARING	4.00	
			CLEVIS ADJUST	1.00	
Parts Charge:		185.72	Labor Charge:	240.00	

Workorder: 1306857

Problem: CHECK BATTERY,NEEDS TIRES

Meter Reading: 1615		Labor		Parts	
In Date: 07/10/2013	Close Date: 07/25/2013	Hours	Description	Quantity	
-	Ck Dead Batt Test Bad Replace Battery Ck Charging Sys	3.25	SHOP SUPPLIES	1.00	
-	Ck Replace Tires Rr Four Tires Mount Add N2 Replace Valve Stems Pack Bearigs		Freight Charge	1.00	
-	Shop Supplies		GROUP 26 DELCO	1.00	
			TIRE 24X12X12 6 PLY	2.00	
			15-6.00-6 TIBBED TIRE	2.00	
Parts Charge:		634.48	Labor Charge:	195.00	

3/27/2017
4:27:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179172 2009 TORO GRNDMASTER 7200 Mower, 72", Ztr, Side Discharge

Workorder: 1404697

Problem: pm service

Meter Reading: 1813		Labor		Parts	
In Date: 05/14/2014	Close Date: 05/28/2014	Hours	Description		Quantity
- Pm		7.50	15-600-6 NHS STR RIB 04		2.00
- Hyd Service			TIRE DISPOSAL FEE		2.00
- Cooling Sys Service			NAPAGOLD AIR FILTER		1.00
- Replae 2 Frt Caster Tires			NAPAGOLD OIL FILTER		1.00
- Shop Supplies			NAPAGOLD FUEL FILTER		1.00
			15-40 OIL		4.00
			AW68 HYDRO FLUID HYDR		3.00
			NAPA ANTIFREEZE GAL		1.00
			SHOP SUPPLIES		1.00
			NAPA HYDRAULIC FILTR		1.00
Parts Charge: 185.01		Labor Charge: 450.00			

Workorder: 1406874

Problem: BELT BROKE

Meter Reading: 1855		Labor		Parts	
In Date: 07/11/2014	Close Date: 07/22/2014	Hours	Description		Quantity
- Ck Belt Broken Ck All Pulleys And Bushngs Rr Belt		2.00	SHOP SUPPLIES		1.00
- Shop Supplies			V-BELT		1.00
Parts Charge: 79.83		Labor Charge: 120.00			

3/27/2017
4:27:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179172 2009 TORO GRNDMASTER 7200 Mower, 72", Ztr, Side Discharge

Workorder: 1504862

Problem: pm, scalp wheels pto switch

Meter Reading: 2006		Labor		Parts	
In Date: 05/13/2015	Close Date: 05/29/2015	Hours	Description		Quantity
- Pm		8.50	P8043 FUEL FILTER LBF		1.00
- Svc And Inspect Lines And Hoses Replace Filter Correct			OIL FILTER NO SUPERCEDE		1.00
Fluid Level			NAPA HYDRAULIC FILTR		1.00
- Replace 3 Anti Scalp Wheels			AW68 BULK SR		2.00
- Ck Pto Turn Off Verify Bad Pto Switch Replace Switch			FLANGE NUT NI		2.00
- Wash Eq			ROLLER,DECK		1.00
- Shop Supplies			SCREW		2.00
			TUBE-SPANNER		2.00
			TUBE SPACER		2.00
			PTO SWITCH		1.00
			15w40 BULK SOUTH REG		3.00
			BOLT		1.00
			NUT		1.00
			SPACER-ROLLER		1.00
			NAPAGOLD AIR FILTER		1.00
			SHOP SUPPLIES		1.00
			ROLLER SCALP		2.00
Parts Charge:		243.85	Labor Charge:		510.00

3/27/2017
4:27:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179172 2009 TORO GRNDMASTER 7200 Mower, 72", Ztr, Side Discharge

Workorder: 1508334

Problem: blade do not turn on when engage pto button

Meter Reading: 2069		Labor		Parts	
In Date: 08/19/2015	Close Date: 08/27/2015	Hours	Description		Quantity
-	Ck Front Tires Replace Two Front Tires Mount Add N2	6.50	BOLT		3.00
	Grease Wheels		GEARBOX BRACKET LH		1.00
-	Replace Anti Scalp Wheels Deck Belt Brakets Bushings		SCREW		2.00
	Pto Switch Lube All		PTO SWITCH		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
			ROLLER SCALP		2.00
			V-BELT		1.00
			TUBE SPACER		2.00
			TIRE DISPOSAL FEE		2.00
			TUBE-SPANNER		2.00
			NAPAGOLD AIR FILTER		1.00
			WASHER		3.00
			GEARBOX BRACKET RH		1.00
			FLANGE NUT NI		5.00
			V-BELT		1.00
			RUBBER MOUNT		3.00
			AIR CLEANER COVER ASSY		1.00
			15-600-6 NHS STR RIB 04		2.00
Parts Charge: 623.86		Labor Charge:	390.00		

Workorder: 1508933

Problem: running hot red light n dash board stays on then blades shut off and then mower

Meter Reading: 2077		Labor		Parts	
In Date: 09/04/2015	Close Date: 09/18/2015	Hours	Description		Quantity
-	Ck Overheating Replace Water Pump Thermostate Temp	5.00	SHOP SUPPLIES		1.00
	Sensor Flush Rad Cooling Sys Reassemble Test Mow		RADIATOR CAP		1.00
-	Replace Air Filter Husing		THERMOSTAT GASKET		1.00
-	Shop Supplies		WATER PUMP ASSY		1.00
			SWITCH		1.00
			NAPA ANTIFREEZE GAL		1.00
			THERMOSTAT ASSY		1.00
			THERMOMETER SWITCH		1.00
			AIR CLEANER ASSY		1.00
Parts Charge: 1,023.47		Labor Charge:	300.00		

3/27/2017
4:27:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179172 2009 TORO GRNDMASTER 7200 Mower, 72", Ztr, Side Discharge

Workorder: 1605591

Problem: P.M.SERVICE, SEE NOTE

Meter Reading: 2209		Labor		Parts	
In Date: 05/31/2016	Close Date: 06/27/2016	Hours	Description		Quantity
- Pm Service.		11.25	15w40 BULK SOUTH REG		3.00
- Replace Two Front Tires.Hand Mount .Repack Bearings.			SOLENOID ASSY		1.00
- C/C Blades Inop.Replace Pto Switch And Electric.Pto			RUBBER DEFLECTOR ASSY		1.00
Solenoid.Test Mow.			RUBBER MOUNT		3.00
- Replace Gear Box Bracket,Chute,Wheels Etc..Lube All.			GEARBOX BRACKET RH		1.00
- Wash Equipment For Service.			BOLT		3.00
- Shop Supplies			TIRE		2.00
			TUBE-SPANNER		2.00
			FLANGE NUT NI		2.00
			SCREW		2.00
			TUBE SPACER		2.00
			GEARBOX BRACKET LH		1.00
			PTO SWITCH		1.00
			NAPAGOLD OIL FILTER		1.00
			ROLLER SCALP		2.00
			SHOP SUPPLIES		1.00
			NAPAGOLD AIR FILTER		1.00
			NAPAGOLD FUEL FILTER		1.00
Parts Charge:		933.34	Labor Charge:	675.00	

Workorder: 1606866

Problem: Belts for blades keep coming off.

Meter Reading: 2225		Labor		Parts	
In Date: 07/07/2016	Close Date: 07/28/2016	Hours	Description		Quantity
- C/C Belt Falls Off.Replace Gear Box Bracket Bushings		3.50	FLANGE NUT NI		3.00
And R/H Deck Belt.Lube All.Test Mow.			V-BELT		1.00
- Repair Leaking Front Tires.Plug And Correct N2			BOLT		3.00
- Shop Supplies			SHOP SUPPLIES		1.00
			RUBBER MOUNT		3.00
Parts Charge:		145.40	Labor Charge:	210.00	

3/27/2017
4:27:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179172 2009 TORO GRNDMASTER 7200 Mower, 72", Ztr, Side Discharge

Workorder: 1607647

Problem: Belts for blades came off.

Meter Reading: 2226		Labor		Parts	
In Date: 07/26/2016	Close Date: 07/28/2016	Hours	Description		Quantity
- Repair Tensioner On L/H Deck Belt.		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	60.00	

Workorder: 1608871

Problem: RIGHT & LEFT DECK ROLLERS BAD, TENTION BELT OFF PULLEY,ADJUST HAND BRAKE.

Meter Reading: 2255		Labor		Parts	
In Date: 08/25/2016	Close Date: 08/31/2016	Hours	Description		Quantity
- C/Cdeck Belts Pulleys Etc....R/R 2 Deck Belts,Tensioner		7.50	V-BELT		1.00
Pulley. All Rollers,Bracket Bushings, Lube All Un-Scize			V-BELT		1.00
Tensioner, Test Mow.			TUBE-SPANNER		2.00
- R/R 2 Front Tires,Hand Mount Repack Bearings, Grease.			TIRE		2.00
- C/C Parking Brake Doest Hold. Adjust Packing Brake.			SHAFT,ROLLER		1.00
- Wash Equioment For Repairs.			FLANGE NUT NI		2.00
- Shop Supplies			ROLLER SCALP		2.00
			ROLLER		1.00
			ROLLER,DECK		1.00
			SHOP SUPPLIES		1.00
			IDLER PULLEY		1.00
			TUBE SPACER		2.00
			SCREW		2.00
			RUBBER MOUNT		3.00
Parts Charge:		560.35	Labor Charge:	450.00	

3/27/2017
4:27:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179172 2009 TORO GRNDMASTER 7200 Mower, 72", Ztr, Side Discharge

Workorder: 1609218

Problem: SCALP WHEELS BROKEN, BELT CAME OFF

Meter Reading: 2257	Labor	Parts		
In Date: 09/02/2016	Hours	Description	Quantity	
- Replace Rear Rollers& Brackets,Idler Arm Assy.,Drive	4.00	RUBBER MOUNT	3.00	
Shaft. Change Oil In Gear Box. Test Mov.		PLATE-ROLLER	1.00	
- Shop Supplies		TUBE-SPANNER	2.00	
		SHOP SUPPLIES	1.00	
		DECK ROLLER	2.00	
		GEARBOX BRACKET LH	1.00	
		SHAFT	2.00	
		DRIVESHAFT	1.00	
		PLATE ROLLER	1.00	
		ROLLER SCALP	2.00	
		TORSION SPRING	1.00	
		GEARBOX BRACKET RH	1.00	
		WASHER	1.00	
		IDLER ARM ASSY	1.00	
Parts Charge:	1,379.14	Labor Charge:	240.00	

Workorder: 1610258

Problem: pto ionp.

Meter Reading: 2279	Labor	Parts		
In Date: 09/30/2016	Hours	Description	Quantity	
- C/C Pto Inop.Replace Module Computer. Intermittently	5.00	SHOP SUPPLIES	1.00	
Turning Off Blade.		RIGHT BRAKE CALIPER	1.00	
- Adjust Parking Brake.Replace Pads/Caliper Assembly.		CONTROL MODULE ASSY	1.00	
- Shop Supplies		LEFT BRAKE CALIPER	1.00	
Parts Charge:	876.70	Labor Charge:	300.00	

Workorder: 1701547

Problem: Transition Prep Charge

Meter Reading: 2305	Labor	Parts		
In Date: 02/14/2017	Hours	Description	Quantity	
- Transition Prep Charge	2.00			
Parts Charge:	0.00	Labor Charge:	0.00	

Total Parts Charges:	8,050.88	Total Labor Charges:	7,110.00	Total Comm. Charges:	0.00
----------------------	----------	----------------------	----------	----------------------	------