FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51204840
Invoice Number: 55345-51204840

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
PM A		**VIN:**	1FDFE4FS0EDB17178
Requested By:	CKARLENS	**Status:**	40
Created By:	CKARLENS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	May 8, 2018	11:14 AM
Started	May 8, 2018	
Completed	May 9, 2018	12:22 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	113,919	DH
System	114,085	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA CAUSE:Service CORRECTION:Perform pmA Service Oil filter B329 qty1 Engine oil 5w20 qty 7 Qts Rotate tires washed rims Torque wheels 140 lbs second torque 140 lbs

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
08-May-18	Gaspard,Ronald	1.83	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.83	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57202780
Invoice No. 55345 - 57202780

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FIRST TRANSIT AC INSPECTION		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	306,933 -

Chronology		
Reported	Feb 12, 2025 11:21:29 AM	Feb 12, 2025 11:21:29 AM
Started		
Completed	Feb 12, 2025 11:31:36 AM	Feb 12, 2025 11:31:36 AM
Down Time		

Work Order Notes

Line 10 VEHICLE RETIRED

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: VEHICLE RETIRED¿
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57202780
Invoice No. 55345 - 57202780

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FIRST TRANSIT AC INSPECTION		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	306,933 -

Activity Header
Activity: 10 001/001/001 AIR CONDITIONING
Activity Note: VEHICLE RETIRED¿
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57202780 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57500300
Invoice No. 55345 - 57500300

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PER DRIVER BUS STALLING		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	99 - Cancelled (99)
Created By:	CVERGARA	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	306,933 - DH

Chronology		
Reported	Sep 16, 2024 9:55:00 AM	Sep 16, 2024 9:55:00 AM
Started	Sep 16, 2024 10:06:00 AM	
Completed	Oct 5, 2024 11:23:31 AM	Oct 5, 2024 11:23:31 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction: Line 20 Bus Stalling /Check & Road test bus .didn¿t Stall out. Check for Coolant Leaks . Pressure test cooling System found. Water pump leaking. Recommend Water Pump.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00

	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57500300
Invoice No. 55345 - 57500300

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PER DRIVER BUS STALLING		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	99 - Cancelled (99)
Created By:	CVERGARA	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	306,933 - DH

Activity Header
Activity: 15 045 POWER PLANT
Activity Note: PER DRIVER BUS HAS AN INTERMITENT STALLING CONDITION
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Sep-24	Arthurs,Durvin	2.4	65	156

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	156.00
Labor Hours:	2.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**156.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57500300
Invoice No. 55345 - 57500300

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PER DRIVER BUS STALLING		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	99 - Cancelled (99)
Created By:	CVERGARA	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	306,933 - DH

Activity Header
Activity: 25 042 COOLING SYSTEM
Activity Note: CHECK COOLING SYSTEM
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Sep-24	Arthurs,Durvin	0.62	65	40.3

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	0.00
Labor:	40.30
Labor Hours:	0.62
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**40.30**

Work Order Footer

Work Order 57500300 Total	
Parts:	0.00
Labor:	196.30
Labor Hours:	3.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**196.30**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57490763
Invoice No. 55345 - 57490763

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
road call lift not working		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	306,186 - DH

Chronology		
Reported	Sep 4, 2024 9:29:00 AM	Sep 4, 2024 9:29:00 AM
Started	Sep 4, 2024 9:31:00 AM	
Completed	Sep 5, 2024 4:16:00 PM	Sep 5, 2024 4:16:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction: Line 20 Diver said lift not working

The lift bracket wasn¿t touched the switch

Recenter the bracket behind the switch the right way completed

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 05-SEP-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		HPIERRE	Sep 5, 2024 3:42:55 PM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		HPIERRE	Sep 5, 2024 3:42:55 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Sep 5, 2024 3:42:55 PM	No	
400 - Are you wearing the appropriate PPE?	Done		HPIERRE	Sep 5, 2024 3:42:55 PM	No	
700 - Have you performed the proper LOTO?	Done		HPIERRE	Sep 5, 2024 3:42:55 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Sep 5, 2024 3:42:55 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Sep 5, 2024 3:42:55 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57490763
Invoice No. 55345 - 57490763

Client Department:
Department: 55345M
Work Order Description
road call lift not working
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 306,186 - DH

Activity Header
Activity: 15 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: Lift not working
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Sep-24	Pierre,Hubert J	0.98	65	63.7
04-Sep-24	Pierre,Hubert J	0.2	65	13

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	76.70
Labor Hours:	1.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**76.70**

Work Order Footer

Work Order 57490763 Total	
Parts:	0.00
Labor:	76.70
Labor Hours:	1.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**76.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57450385
Invoice No. 55345 - 57450385

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
BRAKES ISSUE		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	303,660 - DH

Chronology		
Reported	Jul 17, 2024 9:26:00 AM	Jul 17, 2024 9:26:00 AM
Started	Jul 17, 2024 9:29:00 AM	
Completed	Jul 22, 2024 8:11:00 AM	Jul 22, 2024 8:11:00 AM
Down Time		

Work Order Notes

Line 20 Brake Pedal going To Floor when Brakes apply/ Check Found L/R Caliper & Rotor damage Remove & Replace L/R Rotor replace L/R Hub Seal . Remove & Replace L/R Caliper & Bracket Replace Rear Brake Pads Remove & Replace Both Side emergency Brake Shoes.
Parts # BRS-179 Qty (1)
Parts # 18-B5110 Qty (1)
Parts # S952(A) Qty (1)
Parts #BRSD1330 -B Qty (1)
Parts #YH255594P Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 22-JUL-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		DARTHURS	Jul 22, 2024 8:10:28 AM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		DARTHURS	Jul 22, 2024 8:10:28 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jul 22, 2024 8:10:28 AM	No	
400 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jul 22, 2024 8:10:28 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
700 - Have you performed the proper LOTO?	Done		DARTHURS	Jul 22, 2024 8:10:28 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jul 22, 2024 8:10:28 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 22, 2024 8:10:28 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57450385
Invoice No. 55345 - 57450385

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
BRAKES ISSUE		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	303,660 - DH

Activity Header
Activity: 15 013 BRAKES
Activity Note: Road Call
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Jul-24	18-B5110	CALIPER, BRAKE, DISC, LOADED, E450	1	59.15	59.15

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Jul-24	Arthurs,Durvin	1.78	65	115.7

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	59.15
Labor:	115.70
Labor Hours:	1.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**174.85**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57450385
Invoice No. 55345 - 57450385

Client Department:
Department: 55345M
Work Order Description
BRAKES ISSUE
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 303,660 - DH

Activity Header
Activity: 25 013 BRAKES
Activity Note: L/R Caliper leaking.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Jul-24	BRSD1330B	PADS, BRAKE, DISC, REAR SAME AS 8C2Z-2V200-C	1	55.79	55.79
19-Jul-24	SET38	SET, BEARING & RACE	1	18.51	18.51
19-Jul-24	NC2Z-2C026-A	ROTOR, BRAKE, DISC, REAR SUPERSEDES 8C2Z-2C026-A	1	99.96	99.96
19-Jul-24	387AS	BEARING, ROLLER, CONE, TAPERED	1	14.65	14.65
19-Jul-24	710625	SEAL, WHEEL, INNER, FRONT, FORD	1	17.28	17.28
18-Jul-24	BRS-179	SEAL, WHEEL, REAR	1	12.51	12.51

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Jul-24	Arthurs,Durvin	0.43	65	27.95
17-Jul-24	Arthurs,Durvin	0.67	65	43.55
18-Jul-24	Arthurs,Durvin	0.87	65	56.55
17-Jul-24	Arthurs,Durvin	3.2	65	208

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	168.26
Labor:	336.05
Labor Hours:	5.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**504.31**

Work Order Footer

Work Order 57450385 Total	
Parts:	227.41
Labor:	451.75

	Labor Hours:	6.95
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**679.16**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57447716
Invoice No. 55345 - 57447716

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	303,660 - DH

Chronology		
Reported	Jul 13, 2024 12:47:45 PM	Jul 13, 2024 12:47:45 PM
Started	Jul 14, 2024 10:00:00 AM	
Completed	Jul 14, 2024 11:32:00 AM	Jul 14, 2024 11:32:00 AM
Down Time		

Work Order Notes

Line 10 Tightened both WC lift handrails.

Removed serpentine belt. Checked all pulleys and accessories for defects, found none. Serpentine belt crystallized, replaced with new.

Activity Header
Activity: 10 042/004 PUMP, WATER
Activity Note: belt making noise
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Jul-24	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	30.37	30.37

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Jul-24	Earl Johnson	1	65	65

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	30.37
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**95.37**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57447716
Invoice No. 55345 - 57447716

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	303,660 - DH

Activity Header
Activity: 20 174 BODY, BUS
Activity Note: lift arm need adjust
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Jul-24	Earl Johnson	0.52	65	33.8

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	33.80
Labor Hours:	0.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**33.80**

Work Order Footer

Work Order 57447716 Total	
Parts:	30.37
Labor:	98.80
Labor Hours:	1.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**129.17**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57403913
Invoice No. 55345 - 57403913

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-MEDIUM DUTY PMB		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	303,660 - DH

Chronology		
Reported	Jul 10, 2024 12:00:00 AM	Jul 10, 2024 12:00:00 AM
Started	Jul 13, 2024 10:59:00 AM	
Completed	Jul 13, 2024 1:14:00 PM	Jul 13, 2024 1:14:00 PM
Down Time		

Work Order Notes

Line 10 PM.

Perform pm B service, lube front end, tire rotation, torque and re torque tires (140 f/p), R&R engine oil and filter, road test, all okay at this time.

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 13-JUL-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Jul 13, 2024 11:07:30 AM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		RAURODRIGUEZ	Jul 13, 2024 11:07:30 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Jul 13, 2024 11:07:30 AM	No	
400 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Jul 13, 2024 11:07:30	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				AM		
700 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Jul 13, 2024 11:07:30 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Jul 13, 2024 11:07:30 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Jul 13, 2024 11:07:30 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57403913
Invoice No. 55345 - 57403913

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-MEDIUM DUTY PMB		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	303,660 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Jul-24	Rodriguez,Raul	1.22	65	79.3

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: RAURODRIGUEZ Performed on: 13-JUL-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
10,800 - CHECK_All Destination Signage	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
20,200 - CHECK_Public Address System	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	na	RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	na	RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	na	RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	na	RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	na	RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	-	na	RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
21,500 - INSPECT_High Idle Control	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
31,000 - SSF (Street Side Front)	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
32,000 - Engine Inspection	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,010 - INSPECT_Hood, Springs and Props	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	na	RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done	belt making noise	RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	Yes	57447716
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
32,100 - INSPECT_Intake System	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	13.8 Volt*		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
33,000 - CSF (Curb Side Front)	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
33,050 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
33,060 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	13.8 Volt*		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,000 - SECTION 4 - Interior Inspection	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
40,700 - CHECK_Passenger Stop Request System	-	na	RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
50,100 - *RPT*INSPECT_Steering components- Drag Link, Tie Rods ends and Steering Damper	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
50,400 - LUBE_All Chassis Components	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
50,700 - INSPECT_Tire Condition	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	9 32nds of an inch		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	9 32nds of an inch		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	32nds of an inch	9mm	RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	32nds of an inch	9mm	RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	Inch	39.8mm	RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	Inch	39.8mm	RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
53,600 - INSPECT_Tire Condition	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	32nds of an inch	8mm	RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	32nds of an inch	8mm	RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	Inch	39.7mm	RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	Inch	39.7mm	RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,100 - RECORD_Wheelchair Cycle Count	Cycles	na	RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	-	na	RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done	lift arm need adjust	RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	Yes	57447716

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
62,400 - INSPECT_All Pivot Points	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
62,500 - INSPECT_Cams and Slots	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
62,600 - INSPECT_Rollers	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
62,700 - INSPECT_All Linkages	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	-	ma	RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RAURODRIGUEZ	Jul 13, 2024 12:52:34 PM	No	

Activity Sub Total

Activity 10 Sub Total

Parts: 0.00

	Labor:	79.30
	Labor Hours:	1.22
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**79.30**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57403913
Invoice No. 55345 - 57403913

Client Department:
Department: 55345M
Work Order Description
55345-MEDIUM DUTY PMB
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 303,660 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMB Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Jul-24	LF16424	FILTER, OIL SUPERSEDES P9600	1	6.22	6.22
13-Jul-24	75050	OIL, ENGINE, 5W/30	8	2.73	21.84

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Jul-24	Rodriguez,Raul	0.25	65	16.25

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMB Service
Task: 55345-Medium Duty PMB Inspection Performed by: RAURODRIGUEZ Performed on: 13-JUL-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RAURODRIGUEZ	Jul 13, 2024 11:09:27 AM	No	
101,000 - FRA Change Oil Filters	Yes		RAURODRIGUEZ	Jul 13, 2024 11:09:27 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RAURODRIGUEZ	Jul 13, 2024 11:09:27 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RAURODRIGUEZ	Jul 13, 2024 11:09:27 AM	No	
104,000 - Lubricate Chassis	Done		RAURODRIGUEZ	Jul 13, 2024 11:09:27 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RAURODRIGUEZ	Jul 13, 2024 11:09:27 AM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	-	na	RAURODRIGUEZ	Jul 13, 2024 11:09:27 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RAURODRIGUEZ	Jul 13, 2024 11:09:27 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RAURODRIGUEZ	Jul 13, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:09:27 AM		
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RAURODRIGUEZ	Jul 13, 2024 11:09:27 AM	No	
201,000 - Service Crankcase Breather	Done		RAURODRIGUEZ	Jul 13, 2024 11:09:27 AM	No	
202,000 - FRA Change Water Separator ¿ Secondary Fuel Filters	No	na	RAURODRIGUEZ	Jul 13, 2024 11:09:27 AM	No	
203,000 - FRA Change Automatic Transmission Fluid	No	na	RAURODRIGUEZ	Jul 13, 2024 11:09:27 AM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No	na	RAURODRIGUEZ	Jul 13, 2024 11:09:27 AM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RAURODRIGUEZ	Jul 13, 2024 11:09:27 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	28.06
Labor:	16.25
Labor Hours:	0.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**44.31**

Work Order Footer

Work Order 57403913 Total	
Parts:	28.06
Labor:	95.55
Labor Hours:	1.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**123.61**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57403873
Invoice No. 55345 - 57403873

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	299,774 - DH

Chronology		
Reported	May 21, 2024 11:18:24 PM	May 21, 2024 11:18:24 PM
Started	May 22, 2024 12:56:00 AM	
Completed	May 23, 2024 12:15:19 PM	May 23, 2024 12:15:19 PM
Down Time		

Work Order Notes

Line 10 Rear AC filter dirty
Needs to be clean
Pulled filter wash it and reinstall Line 20 Replaced front shocks (2)
Replaced drive shaft enter bearing

Activity Header
Activity: 10 001/001 AIR CONDITIONING
Activity Note: rear AC filter dirty
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-May-24	Gaspard,Ronald	0.37	65	24.05

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	24.05
Labor Hours:	0.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**24.05**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57403873
Invoice No. 55345 - 57403873

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	299,774 - DH

Activity Header
Activity:20 024/001/004 U-JOINT, DRIVESHAFT
Activity Note: needs central carrier bearing
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-May-24	E4TZ-4800-A	BEARING, SUPPORT, CENTER, DRIVESHAFT	1	49.72	49.72
23-May-24	ASH-1154	ABSORBER, SHOCK, FRONT	2	46.64	93.28

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-May-24	Delva,Terry	6.02	65	391.3

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	143.00
Labor:	391.30
Labor Hours:	6.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**534.30**

Work Order Footer

Work Order 57403873 Total	
Parts:	143.00
Labor:	415.35
Labor Hours:	6.39
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**558.35**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57329833
Invoice No. 55345 - 57329833

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-MEDIUM DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	299,774 - DH

Chronology		
Reported	May 21, 2024 12:00:00 AM	May 21, 2024 12:00:00 AM
Started	May 21, 2024 10:10:00 PM	
Completed	May 22, 2024 12:55:00 AM	May 22, 2024 12:55:00 AM
Down Time		

Work Order Notes

Line 10 PMA
Service
Perform PMA service
Oil filter LF3681 qty1
Engine oil 10w30 qty 8 QTs
Add washer fluid
Replace drain plug oil 090-053 qty1
Needs middle clearance light.

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 21-MAY-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		RGASPARD	May 21, 2024 10:10:22 PM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		RGASPARD	May 21, 2024 10:10:22 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	May 21, 2024 10:10:22 PM	No	
400 - Are you wearing the appropriate PPE?	Done		RGASPARD	May 21, 2024 10:10:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
700 - Have you performed the proper LOTO?	Done		RGASPARD	May 21, 2024 10:10:22 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	May 21, 2024 10:10:22 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	May 21, 2024 10:10:22 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57329833
Invoice No. 55345 - 57329833

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-MEDIUM DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	299,774 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-May-24	Gaspard,Ronald	1.67	65	108.55

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 21-MAY-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
10,800 - CHECK_All Destination Signage	-	NA	RGASPARD	May 21, 2024 11:18:48 PM	No	
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
20,200 - CHECK_Public Address System	-	NA	RGASPARD	May 21, 2024 11:18:48 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	NA	RGASPARD	May 21, 2024 11:18:48 PM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	NA	RGASPARD	May 21, 2024 11:18:48 PM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	NA	RGASPARD	May 21, 2024 11:18:48 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	NA	RGASPARD	May 21, 2024 11:18:48 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	NA	RGASPARD	May 21, 2024 11:18:48 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	-	NA	RGASPARD	May 21, 2024 11:18:48 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
21,500 - INSPECT_High Idle Control	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	NA	RGASPARD	May 21, 2024 11:18:48 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	RGASPARD	May 21, 2024 11:18:48 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	May 21, 2024 11:18:48 PM	No	
33,000 - CSF (Curb Side Front)	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
33,050 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
33,060 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	0 Volt*	NA	RGASPARD	May 21, 2024 11:18:48 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
40,700 - CHECK_Passenger Stop Request System	-	NA	RGASPARD	May 21, 2024 11:18:48 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done	rear AC filter dirty	RGASPARD	May 21, 2024 11:18:48 PM	Yes	57403873
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
50,100 - *RPT*INSPECT_Steering components- Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
50,400 - LUBE_All Chassis Components	-	NA	RGASPARD	May 21, 2024 11:18:48 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	10 32nds of an inch		RGASPARD	May 21, 2024 11:18:48 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	May 21, 2024 11:18:48 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	10 32nds of an inch		RGASPARD	May 21, 2024 11:18:48 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	May 21, 2024 11:18:48 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	May 21, 2024 11:18:48 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	May 21, 2024 11:18:48 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	38 Inch		RGASPARD	May 21, 2024 11:18:48 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	38 Inch		RGASPARD	May 21, 2024 11:18:48 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done	needs central carrier bearing	RGASPARD	May 21, 2024 11:18:48 PM	Yes	57403873
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	May 21, 2024 11:18:48 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		RGASPARD	May 21, 2024 11:18:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	May 21, 2024 11:18:48 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	May 21, 2024 11:18:48 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		RGASPARD	May 21, 2024 11:18:48 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		RGASPARD	May 21, 2024 11:18:48 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	May 21, 2024 11:18:48 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	May 21, 2024 11:18:48 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	May 21, 2024 11:18:48 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	May 21, 2024 11:18:48 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	May 21, 2024 11:18:48 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	May 21, 2024 11:18:48 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	-	NA	RGASPARD	May 21, 2024 11:18:48 PM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	-	NA	RGASPARD	May 21, 2024 11:18:48 PM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,100 - RECORD_Wheelchair Cycle Count	21856 Cycles		RGASPARD	May 21, 2024 11:18:48 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	May 21, 2024 11:18:48 PM	No	

Activity Sub Total

Activity 10 Sub Total

Parts: 0.00

	Labor:	108.55
	Labor Hours:	1.67
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**108.55**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57329833
Invoice No. 55345 - 57329833

Client Department:
Department: 55345M
Work Order Description
55345-MEDIUM DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 299,774 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-May-24	75050	OIL, ENGINE, 5W/30	8	2.73	21.84
23-May-24	LF16424	FILTER, OIL SUPERSEDES P9600	1	6.16	6.16
21-May-24	090-053	PLUG, DRAIN, OIL, ENGINE, 16MM, IMPALA	1	1.71	1.71

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: RGASPARD Performed on: 22-MAY-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	May 22, 2024 12:54:39 AM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	May 22, 2024 12:54:39 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	May 22, 2024 12:54:39 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	May 22, 2024 12:54:39 AM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	May 22, 2024 12:54:39 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	May 22, 2024 12:54:39 AM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	-	NA	RGASPARD	May 22, 2024 12:54:39 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	May 22, 2024 12:54:39 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	May 22, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:54:39 AM		

Activity Sub Total

Activity 20 Sub Total	
Parts:	29.71
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**29.71**

Work Order Footer

Work Order 57329833 Total	
Parts:	29.71
Labor:	108.55
Labor Hours:	1.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**138.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57351354
Invoice No. 55345 - 57351354

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Wiper blades worn.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	296,193 - DH

Chronology		
Reported	Mar 22, 2024 5:30:00 PM	Mar 22, 2024 5:30:00 PM
Started	Mar 22, 2024 5:31:00 PM	
Completed	Mar 22, 2024 8:27:00 PM	Mar 22, 2024 8:27:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Wiper blades worn.

Cause: Wear and tear.

Correction: Remove and replaced both wiper blades.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 22-MAR-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		EARJOHNSON	Mar 22, 2024 8:26:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		EARJOHNSON	Mar 22, 2024 8:26:38 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Mar 22, 2024 8:26:38 PM	No	
400 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Mar 22, 2024 8:26:38 PM	No	
700 - Have you performed the proper LOTO?	Done		EARJOHNSON	Mar 22, 2024 8:26:38 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Mar 22, 2024 8:26:38 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Mar 22, 2024 8:26:38 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57351354
Invoice No. 55345 - 57351354

Client Department:
Department: 55345M
Work Order Description
Wiper blades worn.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 296,193 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note: Wiper blades worn.
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Mar-24	20CA	BLADE, WIPER, WINDSHIELD	2	6.25	12.5

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Mar-24	Earl Johnson	1.53	65	99.45

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	12.50
Labor:	99.45
Labor Hours:	1.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**111.95**

Work Order Footer

Work Order 57351354 Total	
Parts:	12.50
Labor:	99.45
Labor Hours:	1.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**111.95**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57329804
Invoice No. 55345 - 57329804

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	295,807 - DH

Chronology		
Reported	Feb 28, 2024 12:07:17 AM	Feb 28, 2024 12:07:17 AM
Started		
Completed	Mar 20, 2024 5:37:00 PM	Mar 20, 2024 5:37:00 PM
Down Time		

Work Order Notes

Line 10 Under monitoring for repair.

Activity Header
Activity: 10 027/001/013 HARDWARE, MOUNTING, CASE, TRANSMISSION, AUTOMATIC APFI - 027-001-001
Activity Note: right side engine mount bad
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57329804
Invoice No. 55345 - 57329804

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	295,807 - DH

Activity Header
Activity: 20 045/009/003 BODY, PUMP, OIL, ENGINE
Activity Note: oil pan gascket leaking
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57329804 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 57336734
Invoice No. 55345 - 57336734

Client Department:
Department: 55345M
Work Order Description
front AC COMPRESSOR LEAKING
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 296,193 - DH

Chronology		
Reported	Mar 6, 2024 6:57:00 PM	Mar 6, 2024 6:57:00 PM
Started	Mar 6, 2024 7:38:00 PM	
Completed	Mar 20, 2024 2:28:00 PM	Mar 20, 2024 2:28:00 PM
Down Time		

Work Order Notes

Line 10 Compressor need to be changer Line 20 Tech replaced front compressor

Activity Header
Activity: 10 012 AXLE, NON-DRIVEN, REAR (POWER UNITS & TRAILERS)
Activity Note: Front AC compressor leaking
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Mar-24	CC2Z-19703-D	COMPRESSOR, A/C SAME AS 8020002 20-11403-AM	1	292.02	292.02

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Mar-24	NELSON PIERRE-LOUIS	3.3	65	214.5
06-Mar-24	Junior Hurst	1.13	65	73.45

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	292.02
Labor:	287.95
Labor Hours:	4.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**579.97**

Work Order Footer

Work Order 57336734 Total	
Parts:	292.02
Labor:	287.95
Labor Hours:	4.43
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**579.97**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57211767
Invoice No. 55345 - 57211767

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-MEDIUM DUTY PMA		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	295,807 - DH

Chronology		
Reported	Feb 22, 2024 12:00:00 AM	Feb 22, 2024 12:00:00 AM
Started	Feb 27, 2024 10:54:00 PM	
Completed	Feb 28, 2024 1:12:00 AM	Feb 28, 2024 1:12:00 AM
Down Time		

Work Order Notes

Line 10 PMA
Service
Perform PMA service
Oil filter LF3601 qty1
Engine oil 10w30 qty 7 qts
Add washer fluid
Right side motor mount cracked
Oil pan gasket leaking
Front AC compressor working fine but noisy.

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 27-FEB-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		RGASPARD	Feb 27, 2024 10:54:45 PM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		RGASPARD	Feb 27, 2024 10:54:45 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Feb 27, 2024 10:54:45 PM	No	
400 - Are you wearing the appropriate PPE?	Done		RGASPARD	Feb 27, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:54:45 PM		
700 - Have you performed the proper LOTO?	Done		RGASPARD	Feb 27, 2024 10:54:45 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Feb 27, 2024 10:54:45 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Feb 27, 2024 10:54:45 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57211767
Invoice No. 55345 - 57211767

Client Department:
Department: 55345M
Work Order Description
55345-MEDIUM DUTY PMA
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 295,807 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Feb-24	Gaspard,Ronald	0.58	65	37.7
27-Feb-24	Gaspard,Ronald	1.1	65	71.5

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 28-FEB-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
10,800 - CHECK_All Destination Signage	-	NA	RGASPARD	Feb 28, 2024 12:09:12 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
20,200 - CHECK_Public Address System	-	NA	RGASPARD	Feb 28, 2024 12:09:12 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	NA	RGASPARD	Feb 28, 2024 12:09:12 AM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	NA	RGASPARD	Feb 28, 2024 12:09:12 AM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	NA	RGASPARD	Feb 28, 2024 12:09:12 AM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	NA	RGASPARD	Feb 28, 2024 12:09:12 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	NA	RGASPARD	Feb 28, 2024 12:09:12 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	-	NA	RGASPARD	Feb 28, 2024 12:09:12 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
21,500 - INSPECT_High Idle Control	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
21,800 - INSPECT_Parking Brake Operation	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
32,000 - Engine Inspection	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	NA	RGASPARD	Feb 28, 2024 12:09:12 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	RGASPARD	Feb 28, 2024 12:09:12 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
33,000 - CSF (Curb Side Front)	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Feb 28, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:09:12 AM		
33,050 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
33,060 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	0 Volt*	NA	RGASPARD	Feb 28, 2024 12:09:12 AM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
40,700 - CHECK_Passenger Stop Request System	Done	NA	RGASPARD	Feb 28, 2024 12:09:12 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
50,100 - *RPT*INSPECT_Steering components- Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
50,400 - LUBE_All Chassis Components	-	NA	RGASPARD	Feb 28, 2024 12:09:12 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	38 Inch		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	38 Inch		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done	right side engine mount bad	RGASPARD	Feb 28, 2024 12:09:12 AM	Yes	57329804
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done	oil pan gascket leaking	RGASPARD	Feb 28, 2024 12:09:12 AM	Yes	57329804
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum,	40 Inch		RGASPARD	Feb 28, 2024 12:09:12 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Rotor Condition (inches)						
55,700 - CHECK_Spring Brake Inversion Valve	-	NA	RGASPARD	Feb 28, 2024 12:09:12 AM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	-	NA	RGASPARD	Feb 28, 2024 12:09:12 AM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
60,100 - RECORD_Wheelchair Cycle Count	17564 Cycles		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Feb 28, 2024 12:09:12 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	109.20
Labor Hours:	1.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**109.20**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57211767
Invoice No. 55345 - 57211767

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-MEDIUM DUTY PMA		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	295,807 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Feb-24	75050	OIL, ENGINE, 5W/30	8	2.75	22
28-Feb-24	LF3681	FILTER, OIL, SPIN-ON SEE P550965	1	9.19	9.19

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Feb-24	Gaspard,Ronald	0.53	65	34.45

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: RGASPARD Performed on: 28-FEB-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Feb 28, 2024 12:42:22 AM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Feb 28, 2024 12:42:22 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Feb 28, 2024 12:42:22 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Feb 28, 2024 12:42:22 AM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Feb 28, 2024 12:42:22 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Feb 28, 2024 12:42:22 AM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	-	NA	RGASPARD	Feb 28, 2024 12:42:22 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Feb 28, 2024 12:42:22 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Feb 28, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:42:22 AM		

Activity Sub Total

Activity 20 Sub Total	
Parts:	31.19
Labor:	34.45
Labor Hours:	0.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**65.64**

Work Order Footer

Work Order 57211767 Total	
Parts:	31.19
Labor:	143.65
Labor Hours:	2.21
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**174.84**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57302987
Invoice No. 55345 - 57302987

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
SHIFTER CABLE BROKE		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	294,999 - DH

Chronology		
Reported	Jan 26, 2024 11:43:00 AM	Jan 26, 2024 11:43:00 AM
Started	Jan 26, 2024 11:45:00 AM	
Completed	Jan 29, 2024 8:33:00 AM	Jan 29, 2024 8:33:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Shifter cable broken

Cause: normal wear

Correction: removed and replaced shifter cable

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 29-JAN-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Jan 29, 2024 8:26:51 AM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		RAURODRIGUEZ	Jan 29, 2024 8:26:51 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Jan 29, 2024 8:26:51 AM	No	
400 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Jan 29, 2024 8:26:51 AM	No	
700 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Jan 29, 2024 8:26:51 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Jan 29, 2024 8:26:51 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Jan 29, 2024 8:26:51 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57302987
Invoice No. 55345 - 57302987

Client Department:
Department: 55345M
Work Order Description
SHIFTER CABLE BROKE
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 294,999 - DH

Activity Header
Activity: 15 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: SHIFTER CABLE
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Jan-24	8C2Z-7E395-A	CABLE, SELECTOR, SHIFT	1	30.45	30.45

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Jan-24	Rodriguez,Raul	1.28	65	83.2

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	30.45
Labor:	83.20
Labor Hours:	1.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**113.65**

Work Order Footer

Work Order 57302987 Total	
Parts:	30.45
Labor:	83.20
Labor Hours:	1.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**113.65**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 5

Work Order No. 57294954
Invoice No. 55345 - 57294954

Client Department:
Department: 55345M
Work Order Description
Road Call-transmission issue
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 294,987 - DH

Chronology		
Reported	Jan 17, 2024 8:38:00 AM	Jan 17, 2024 8:38:00 AM
Started	Jan 17, 2024 8:42:00 AM	
Completed	Jan 24, 2024 4:57:00 PM	Jan 24, 2024 4:57:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction: Line 20 Road call driver said bus won¿t move

Code p0751

Town back to base wait on repair completed Line 30 Unit came in for transmission problem cause don¿t move worn out take unit apart and change the transmission after take unit for a test drive now working perfect return to shop and check fluid all good after park unit back in line Line 40 Installed mdt, camera and geo tab, release to service

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: PRAMETER

Check List

Task: PRA and Meter Readings Performed by: JUHURST Performed on: 23-JAN-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		JUHURST	Jan 23, 2024 7:18:58 PM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		JUHURST	Jan 23, 2024 7:18:58 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Jan 23, 2024 7:18:58 PM	No	
400 - Are you wearing the appropriate PPE?	Done		JUHURST	Jan 23, 2024 7:18:58 PM	No	
700 - Have you performed the proper LOTO?	Done		JUHURST	Jan 23, 2024 7:18:58 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Jan 23, 2024 7:18:58 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Jan 23, 2024 7:18:58 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 5

Work Order No. 57294954
Invoice No. 55345 - 57294954

Client Department:
Department: 55345M
Work Order Description
Road Call-transmission issue
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 294,987 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Jan-24	Pierre,Hubert J	4.88	65	317.2

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	317.20
Labor Hours:	4.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**317.20**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 5

Work Order No. 57294954
Invoice No. 55345 - 57294954

Client Department:
Department: 55345M
Work Order Description
Road Call-transmission issue
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 294,987 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: GARDENS TOWING TOWED BUS BACK TO BASE - NO POWER
Reason for Repair: TW Towing
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet

PO No.	ACD Code	Supplier No.	SUPPLIER	Order Date	Received Value
5017694	185,583,555	1005999	PALM BEACH GARDENS TOWING CORP,FL,RIVIERA BEACH,3525 AVE K	Jan 18, 2024 12:00:00 AM	280.5

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	280.50
Sublet Labor:	0.00
Activity Sub Total	**280.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 5

Work Order No. 57294954
Invoice No. 55345 - 57294954

Client Department:
Department: 55345M
Work Order Description
Road Call-transmission issue
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 294,987 - DH

Activity Header
Activity: 30 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: REPLACE TRANSMISSION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 43 Weak
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: REPLACE TRANSMISSION
Task: 55345 TRANSMISSION DTC P0751 SHIFT SOLENOID Performed by: NBARRETO Performed on: 24-JAN-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - 55345 TRANSMISSION DTC P0751 SHIFT SOLENOID	Done		NBARRETO	Jan 24, 2024 4:56:42 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 5

Work Order No. 57294954
Invoice No. 55345 - 57294954

Client Department:
Department: 55345M
Work Order Description
Road Call-transmission issue
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 294,987 - DH

Activity Header
Activity: 40 053/004/000 SAFETY EQUIPMENT
Activity Note: install mdt + camera
Reason for Repair: 07 Pre-Delivery
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Jan-24	Nicolas Barreto	1.47	65	95.55

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	95.55
Labor Hours:	1.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**95.55**

Work Order Footer

Work Order 57294954 Total	
Parts:	0.00
Labor:	412.75
Labor Hours:	6.35
Sublet Parts:	280.50
Sublet Labor:	0.00
Activity Sub Total	**693.25**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57287491
Invoice No. 55345 - 57287491

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Check front A/C		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	294,688 - DH

Chronology		
Reported	Jan 8, 2024 9:49:00 AM	Jan 8, 2024 9:49:00 AM
Started	Jan 8, 2024 5:50:00 PM	
Completed	Jan 9, 2024 11:10:00 PM	Jan 9, 2024 11:10:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Front AC malfunction.

Cause: Low charge pressure.

Correction: Recovered remaining Freon. Vacuum, leak tested, added PAG oil and recharged to spec. Front Ac blows properly.

WC lift bridge plate gas springs need to be replaced. Out of service, noted for repair.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 09-JAN-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jan 9, 2024 11:09:54 PM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		EARJOHNSON	Jan 9, 2024 11:09:54 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jan 9, 2024 11:09:54 PM	No	
400 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jan 9, 2024 11:09:54 PM	No	
700 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jan 9, 2024 11:09:54 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jan 9, 2024 11:09:54 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jan 9, 2024 11:09:54 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57287491
Invoice No. 55345 - 57287491

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Check front A/C		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	294,688 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Front AC malfunction.
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Jan-24	Earl Johnson	1.88	65	122.2

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	122.20
Labor Hours:	1.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**122.20**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57287491
Invoice No. 55345 - 57287491

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Check front A/C		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	294,688 - DH

Activity Header
Activity:25 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: WC lift malfunction.
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Jan-24	Earl Johnson	1.32	65	85.8

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	0.00
Labor:	85.80
Labor Hours:	1.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**85.80**

Work Order Footer

Work Order 57287491 Total	
Parts:	0.00
Labor:	208.00
Labor Hours:	3.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**208.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57286283
Invoice No. 55345 - 57286283

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
lift issue		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	294,688 - DH

Chronology		
Reported	Jan 5, 2024 4:55:00 PM	Jan 5, 2024 4:55:00 PM
Started	Jan 5, 2024 5:07:00 PM	
Completed	Jan 9, 2024 1:38:00 PM	Jan 9, 2024 1:38:00 PM
Down Time		

Work Order Notes

Line 10 Unit came in for lift issue Check and found sometime when in position to godown the flap don¿t jump up shocks need replace Line 20 Lift not working properly

The lift shock are bad

Replaced both rear back plate shocks completed

Activity Header
Activity: 10 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jan-24	Junior Hurst	0.58	65	37.7
05-Jan-24	Junior Hurst	0.22	65	14.3

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	52.00
Labor Hours:	0.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**52.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57286283
Invoice No. 55345 - 57286283

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
lift issue		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	294,688 - DH

Activity Header
Activity: 20 055/023/000 LIFT, WHEELCHAIR, PASSENGER
Activity Note: inspect and repair wheel chair lift
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Jan-24	32601	SPRING, ASSIST, GAS	2	15.57	31.14
09-Jan-24	32519KS	SWITCH, RAISED, W/C	1	37.86	37.86

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Jan-24	Pierre,Hubert J	3.22	65	209.3

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	69.00
Labor:	209.30
Labor Hours:	3.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**278.30**

Work Order Footer

Work Order 57286283 Total	
Parts:	69.00
Labor:	261.30
Labor Hours:	4.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**330.30**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57285338
Invoice No. 55345 - 57285338

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Belt squealing.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	294,687 - DH

Chronology		
Reported	Jan 4, 2024 5:31:00 PM	Jan 4, 2024 5:31:00 PM
Started	Jan 4, 2024 5:34:00 PM	
Completed	Jan 4, 2024 7:03:00 PM	Jan 4, 2024 7:03:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Belt squeaking.

Cause: Serpentine belt misaligned.

Correction: Removed belt and realigned at the rear AC compressor.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 04-JAN-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jan 4, 2024 6:52:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		EARJOHNSON	Jan 4, 2024 6:52:23 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jan 4, 2024 6:52:23 PM	No	
400 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jan 4, 2024 6:52:23 PM	No	
700 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jan 4, 2024 6:52:23 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jan 4, 2024 6:52:23 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jan 4, 2024 6:52:23 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57285338
Invoice No. 55345 - 57285338

Client Department:
Department: 55345M
Work Order Description
Belt squealing.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 294,687 - DH

Activity Header
Activity: 15 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Belt squealing.
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Jan-24	Earl Johnson	1.48	65	96.2

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	96.20
Labor Hours:	1.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**96.20**

Work Order Footer

Work Order 57285338 Total	
Parts:	0.00
Labor:	96.20
Labor Hours:	1.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**96.20**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57261649
Invoice No. 55345 - 57261649

Client Department:
Department: 55345M
Work Order Description
REAR A/C, CHECK BRAKES, INTERLOCK
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 293,909 - DH

Chronology		
Reported	Dec 5, 2023 5:23:00 PM	Dec 5, 2023 5:23:00 PM
Started	Dec 18, 2023 10:08:00 AM	
Completed	Dec 18, 2023 1:45:00 PM	Dec 18, 2023 1:45:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Driver said check rear ac and front brakes

Cause: Driver abuse

Correction: not wrong with the rear ac or the brakes the workers fined completed

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc:
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 18-DEC-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		HPIERRE	Dec 18, 2023 1:45:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		HPIERRE	Dec 18, 2023 1:45:33 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Dec 18, 2023 1:45:33 PM	No	
400 - Are you wearing the appropriate PPE?	Done		HPIERRE	Dec 18, 2023 1:45:33 PM	No	
700 - Have you performed the proper LOTO?	Done		HPIERRE	Dec 18, 2023 1:45:33 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Dec 18, 2023 1:45:33 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Dec 18, 2023 1:45:33 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57261649
Invoice No. 55345 - 57261649

Client Department:
Department: 55345M
Work Order Description
REAR A/C, CHECK BRAKES, INTERLOCK
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 293,909 - DH

Activity Header
Activity: 10 001/001 AIR CONDITIONING
Activity Note: CHECK REAR A/C
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Dec-23	Pierre,Hubert J	1.27	65	82.55

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: CHECK REAR A/C
Task: Air Conditioning Inspection Performed by: HPIERRE Performed on: 18-DEC-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
3,000 - FRONT A/C	Done		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
3,100 - Inspect All A/C Lines	Done		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
3,200 - Inspect A/C Pressure Switches/ Relays/ Fan Motors	Done		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
3,300 - Clean Evaporator & Condenser Coils / Change Evaporator Filter	Done		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
3,400 - un A/C Systems ³ 10 minutes. Check for Signs of Obvious Refrigerant Leaks.	Done		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
3,500 - Recover & Record Refrigerant lbs.	4.5 Liquid pounds		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
3,600 - Repair ALL Refri Leaks [perform #7 with major component failures / replacements	Done		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
3,700 - Flush Systems, Remove Contaminates. Remove & Fill Comp with Proper Oil Level	Done		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
3,800 - Replace Filter Dryers	Done		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
3,900 - Evacuate Systems (min. 30 inHg) & Hold ³ 5 Minutes. Recheck & Repair Leaks	Done		HPIERRE	Dec 18, 2023 1:44:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
4,000 - Recharge & Record Refrigerant lbs.	Done		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
4,100 - Run A/C Systems ³ 10 minutes	Done		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
4,200 - Check and Record Pressures: Lo Side Front	35 Pounds per Square Inch		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
4,300 - Check and Record Pressures: Hi Side Front	200 Pounds per Square Inch		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
4,400 - Record Ambient & Evaporator Outlet Temperatures: Ambient	70 Degree Fahrenheit		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
4,500 - Record Ambient & Evaporator Outlet Temperatures: Front Evap	70 Degree Fahrenheit		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
4,600 - Record Antifreeze Protection Level _____°F (min. -5°F / max. -34°F)	45 Degree Fahrenheit		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
4,700 - Check Radiator, Surge Tank, Pressure Cap, Hoses, etc.	Done		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
4,800 - Check All Belts & Pulleys	Done		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
4,900 - Check & Repair Any Mechanical Problems Detected.	Done		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
4,950 - Clean ALL signs of mechanical work.	Done		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
5,000 - REAR A/C	Done		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
5,100 - Inspect All A/C Lines	Done		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
5,200 - Inspect A/C Pressure Switches/ Relays/ Fan Motors	Done		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
5,300 - Clean Evaporator & Condenser Coils / Change Evaporator Filter	Done		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
5,400 - Run A/C Systems ³ 10 minutes. Check for Signs of Obvious Refrigerant Leaks.	Done		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
5,500 - Recover & Record Refrigerant lbs. REAR A/C	4.5 Liquid pounds		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
5,600 - Repair ALL Refri Leaks [perform #7 with major component failures / replacements	Done		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
5,700 - Flush Systems, Remove Contaminates. Remove & Fill Comp with Proper Oil levels	Done		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
5,800 - Replace Filter Dryers	Done		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
5,900 - Evacuate Systems (min. 30 inHg) & Hold ³ 5 Minutes. Recheck & Repair Leaks	Done		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
6,000 - Recharge & Record Refrigerant lbs. REAR A/C lbs	4.5 Liquid pounds		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
6,100 - Run A/C Systems ³ 10 minutes	Done		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
6,200 - Check and Record Pressures: Rear A/C Lo Side	45 Pounds per Square Inch		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
6,300 - Check and Record Pressures: Rear A/C Hi Side	45 Pounds per Square Inch		HPIERRE	Dec 18, 2023 1:44:17 PM	No	
6,400 - Record Ambient & Evaporator Outlet Temperatures: Ambient Rear	60 Degree Fahrenheit		HPIERRE	Dec 18, 2023 1:44:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
6,500 - Record Ambient & Evaporator Outlet Temperatures: Rear Evap	56 Degree Fahrenheit		HPIERRE	Dec 18, 2023 1:44:17 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	82.55
Labor Hours:	1.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**82.55**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57261649
Invoice No. 55345 - 57261649

Client Department:
Department: 55345M
Work Order Description
REAR A/C, CHECK BRAKES, INTERLOCK
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 293,909 - DH

Activity Header
Activity: 20 013/012/005 BRAKES, ELECTRIC
Activity Note: cHECK BRAKES AND INTERLOCK
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Dec-23	Pierre,Hubert J	2.22	65	144.3

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	144.30
Labor Hours:	2.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**144.30**

Work Order Footer

Work Order 57261649 Total	
Parts:	0.00
Labor:	226.85
Labor Hours:	3.49
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**226.85**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57262607
Invoice No. 55345 - 57262607

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Bus shaking		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	293,249 - DH

Chronology		
Reported	Dec 6, 2023 3:00:40 PM	Dec 6, 2023 3:00:40 PM
Started	Dec 6, 2023 3:02:00 PM	
Completed	Dec 12, 2023 10:17:00 AM	Dec 12, 2023 10:17:00 AM
Down Time		

Work Order Notes

Line 10 Driver stated that Bus is shaking and rear ac not blowing

Multiple cyl Misfire and random misfire

Replaced coil and spark plugs on cyl #1, 6 and 10 Line 20 Engine belt squeaks
Need engine belt
Coolant hose clamp to intake loose Line 30 Rear AC work is done and charged system with 5lbs Freon Line 40
Replaced engine belt
Replaced accumulator

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 12-DEC-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		TDELVA	Dec 12, 2023 10:00:23 AM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		TDELVA	Dec 12, 2023 10:00:23 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Dec 12, 2023 10:00:23 AM	No	
400 - Are you wearing the appropriate PPE?	Done		TDELVA	Dec 12, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:00:23 AM		
700 - Have you performed the proper LOTO?	Done		TDELVA	Dec 12, 2023 10:00:23 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Dec 12, 2023 10:00:23 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Dec 12, 2023 10:00:23 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57262607
Invoice No. 55345 - 57262607

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Bus shaking		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	293,249 - DH

Activity Header
Activity: 20 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Bus shaking
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Dec-23	SP521	PLUG, SPARK, 5.4L, FORD	3	4.14	12.42
07-Dec-23	DG508	COIL, IGNITION SAME AS 3W7Z-12029-AA	3	44.83	134.49

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Dec-23	Delva,Terry	1.12	65	72.8
06-Dec-23	Delva,Terry	1.98	65	128.7

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	146.91
Labor:	201.50
Labor Hours:	3.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**348.41**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57262607
Invoice No. 55345 - 57262607

Client Department:
Department: 55345M
Work Order Description
Bus shaking
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 293,249 - DH

Activity Header
Activity: 30 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear AC
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Dec-23	11127164A	ACCUMULATOR, A/C, 3"", 12FOX12M	1	36.23	36.23
11-Dec-23	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	47.16	47.16
12-Dec-23	11127164A	ACCUMULATOR, A/C, 3"", 12FOX12M	1	36.23	36.23

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Dec-23	Delva,Terry	3.68	65	239.2
12-Dec-23	Delva,Terry	1.7	65	110.5
08-Dec-23	Delva,Terry	1.18	65	76.7
10-Dec-23	Delva,Terry	3.58	65	232.7
10-Dec-23	Delva,Terry	4.72	65	306.8
08-Dec-23	Delva,Terry	1.4	65	91
08-Dec-23	Delva,Terry	0.2	65	13
07-Dec-23	Delva,Terry	2.92	65	189.8

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	119.62
Labor:	1,259.70
Labor Hours:	19.38
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1,379.32**

Work Order Footer

Work Order 57262607 Total	
Parts:	266.53

	Labor:	1,461.20
	Labor Hours:	22.48
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1,727.73**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57248903
Invoice No. 55345 - 57248903

Client Department:
Department: 55345M
Work Order Description
Driver said lift needs to be check and ac is hot
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 292,999 - DH

Chronology		
Reported	Nov 20, 2023 12:31:23 PM	Nov 20, 2023 12:31:23 PM
Started	Nov 20, 2023 12:32:00 PM	
Completed	Nov 29, 2023 11:17:00 AM	Nov 29, 2023 11:17:00 AM
Down Time		

Work Order Notes

Line 10 Driver said rear not working and he¿s smelling Freon

Rear compressor was leaking from the pressure valve

Replaced compressor flush the condenser and the evaporator

Replace ac filter orifice tube vacuum and recharge test driving bus completed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Rear ac not working
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Nov-23	Pierre,Hubert J	5.5	65	357.5

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Rear ac not working
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 29-NOV-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		HPIERRE	Nov 29, 2023 11:12:30 AM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		HPIERRE	Nov 29, 2023 11:12:30 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Nov 29, 2023 11:12:30 AM	No	
400 - Are you wearing the appropriate PPE?	Done		HPIERRE	Nov 29, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:12:30 AM		
700 - Have you performed the proper LOTO?	Done		HPIERRE	Nov 29, 2023 11:12:30 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Nov 29, 2023 11:12:30 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Nov 29, 2023 11:12:30 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	357.50
Labor Hours:	5.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**357.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57248903
Invoice No. 55345 - 57248903

Client Department:
Department: 55345M
Work Order Description
Driver said lift needs to be check and ac is hot
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 292,999 - DH

Activity Header
Activity: 20 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: REAR AC DIAG
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Nov-23	3411885	TUBE, ORIFICE, A/C, FORD	1	0.9	0.9
28-Nov-23	6512723	COMPRESSOR, A/C	1	251.03	251.03
30-Nov-23	3411885	TUBE, ORIFICE, A/C, FORD	2	0.9	1.8
01-Dec-23	843(A)	PIGTAIL, HEADLAMP	1	4.43	4.43

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Nov-23	Pierre,Hubert J	1.08	65	70.2
28-Nov-23	Pierre,Hubert J	3.83	65	248.95

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	258.16
Labor:	319.15
Labor Hours:	4.91
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**577.31**

Work Order Footer

Work Order 57248903 Total	
Parts:	258.16
Labor:	676.65
Labor Hours:	10.41
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**934.81**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57241769
Invoice No. 55345 - 57241769

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Vehicle stalled.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	292,485 - DH

Chronology		
Reported	Nov 12, 2023 4:03:12 PM	Nov 12, 2023 4:03:12 PM
Started	Nov 12, 2023 4:04:00 PM	
Completed	Nov 28, 2023 12:45:00 AM	Nov 28, 2023 12:45:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Check engine light illuminated.

Cause: P0340 DTC.

Correction: Noted for furthur repairs.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 28-NOV-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		EARJOHNSON	Nov 28, 2023 12:44:34 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		EARJOHNSON	Nov 28, 2023 12:44:34 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Nov 28, 2023 12:44:34 AM	No	
400 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Nov 28, 2023 12:44:34 AM	No	
700 - Have you performed the proper LOTO?	Done		EARJOHNSON	Nov 28, 2023 12:44:34 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Nov 28, 2023 12:44:34 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Nov 28, 2023 12:44:34 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57241769
Invoice No. 55345 - 57241769

Client Department:
Department: 55345M
Work Order Description
Vehicle stalled.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 292,485 - DH

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Vehicle stalled.
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Nov-23	Earl Johnson	2.08	65	135.2

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	135.20
Labor Hours:	2.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**135.20**

Work Order Footer

Work Order 57241769 Total	
Parts:	0.00
Labor:	135.20
Labor Hours:	2.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**135.20**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57248286
Invoice No. 55345 - 57248286

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Unscheduled Work		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	292,485 - DH

Chronology		
Reported	Nov 19, 2023 1:48:57 PM	Nov 19, 2023 1:48:57 PM
Started	Nov 19, 2023 1:52:00 PM	
Completed	Nov 19, 2023 9:22:00 PM	Nov 19, 2023 9:22:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Unit in for rear AC blowing warm. Also rear bumper issue

Cause: broken

Removed and replace 12 feet of Low pressure hoses afteer. Recharge rear AC unit now working asdesign return vehicle back to work.

Correction:

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 19-NOV-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		JUHURST	Nov 19, 2023 9:21:45 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		JUHURST	Nov 19, 2023 9:21:45 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Nov 19, 2023 9:21:45 PM	No	
400 - Are you wearing the appropriate PPE?	Done		JUHURST	Nov 19, 2023 9:21:45 PM	No	
700 - Have you performed the proper LOTO?	Done		JUHURST	Nov 19, 2023 9:21:45 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Nov 19, 2023 9:21:45 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Nov 19, 2023 9:21:45 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57248286
Invoice No. 55345 - 57248286

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Unscheduled Work		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	292,485 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Unit in for rear AC check
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Nov-23	Junior Hurst	7.5	65	487.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	487.50
Labor Hours:	7.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**487.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57248286
Invoice No. 55345 - 57248286

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Unscheduled Work		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	292,485 - DH

Activity Header
Activity: 25 020 GROUP, DRIVETRAIN
Activity Note: Part of rear bumper missing
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57248286 Total	
Parts:	0.00
Labor:	487.50
Labor Hours:	7.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**487.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 5

Work Order No. 57219110
Invoice No. 55345 - 57219110

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Steering is loose.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	292,174 - DH

Chronology		
Reported	Oct 29, 2023 11:15:15 AM	Oct 29, 2023 11:15:15 AM
Started	Oct 29, 2023 11:17:00 AM	
Completed	Nov 8, 2023 12:09:00 PM	Nov 8, 2023 12:09:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Steering is loose.

Cause: Upper ball joints have excessive play.

Correction: Noted for repair. Awaiting shop. Line 20 Upon inspection found that vehicle¿s water pump is leaking. AWP. Line 30 TECH HUBERT PIERRE , REPLACED UPPER AND LOWER BALL JOINTS, FRONT ROTORS, BRAKE PADS, BEARINGS AND SEALS. (HEXAGON TRANSITION) Line 40 Replaced crank sensor completed

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 08-NOV-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		HPIERRE	Nov 8, 2023 12:08:39 PM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		HPIERRE	Nov 8, 2023 12:08:39 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Nov 8, 2023 12:08:39 PM	No	
400 - Are you wearing the appropriate PPE?	Done		HPIERRE	Nov 8, 2023 12:08:39 PM	No	
700 - Have you performed the proper LOTO?	Done		HPIERRE	Nov 8, 2023 12:08:39 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Nov 8, 2023 12:08:39 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Nov 8, 2023 12:08:39 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 5

Work Order No. 57219110
Invoice No. 55345 - 57219110

Client Department:
Department: 55345M
Work Order Description
Steering is loose.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 292,174 - DH

Activity Header
Activity: 15 016 SUSPENSION
Activity Note: Steering is loose.
Reason for Repair:
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Oct-23	Earl Johnson	1.97	65	128.05

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	128.05
Labor Hours:	1.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**128.05**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 5

Work Order No. 57219110
Invoice No. 55345 - 57219110

Client Department:
Department: 55345M
Work Order Description
Steering is loose.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 292,174 - DH

Activity Header
Activity: 25 042/004/001 PUMP, WATER
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Nov-23	Pierre,Hubert J	2.98	65	193.7

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	0.00
Labor:	193.70
Labor Hours:	2.98
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**193.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 5

Work Order No. 57219110
Invoice No. 55345 - 57219110

Client Department:
Department: 55345M
Work Order Description
Steering is loose.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 292,174 - DH

Activity Header
Activity: 35 016/001/015 JOINT, BALL, ARM, CONTROL, LOWER
Activity Note: BALL JOINTS
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Nov-23	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	2	55.64	111.28
07-Nov-23	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	-1	55.64	-55.64
07-Nov-23	8C3Z-3049-B	JOINT, BALL, UPPER	2	37.76	75.52
07-Nov-23	LM102949	BEARING, WHEEL, INNER, FRONT, TAPERED	2	10.41	20.82
07-Nov-23	BRRF-1972	ROTOR & HUB, BRAKE, FRONT, FORD	2	164.61	329.22
07-Nov-23	15101	BEARING, WHEEL, OUTER, FRONT	2	8.49	16.98
07-Nov-23	8C2Z-3050-A	JOINT, BALL, LOWER	2	42.5	85

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 35 Sub Total	
Parts:	583.18
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**583.18**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 5

Work Order No. 57219110
Invoice No. 55345 - 57219110

Client Department:
Department: 55345M
Work Order Description
Steering is loose.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 292,174 - DH

Activity Header
Activity: 45 032 CRANKING
Activity Note: crank sensor
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Nov-23	1W7Z-6C315-AB	SENSOR, POSITION, CRANKSHAFT	1	31.84	31.84

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Nov-23	Pierre,Hubert J	0.8	65	52

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 45 Sub Total	
Parts:	31.84
Labor:	52.00
Labor Hours:	0.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**83.84**

Work Order Footer

Work Order 57219110 Total	
Parts:	615.02
Labor:	373.75
Labor Hours:	5.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**988.77**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57211528
Invoice No. 55345 - 57211528

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	291,849 - DH

Chronology		
Reported	Oct 26, 2023 8:22:41 AM	Oct 26, 2023 8:22:41 AM
Started	Oct 26, 2023 9:23:00 AM	
Completed	Nov 2, 2023 9:22:23 AM	Nov 2, 2023 9:22:23 AM
Down Time		

Work Order Notes

Activity Header
Activity: 10 017/003/001 TIRE, CUSHION W/TREAD
Activity Note: need front tire
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Oct-23	Pierre,Hubert J	4.72	65	306.8

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	306.80
Labor Hours:	4.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**306.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57211528
Invoice No. 55345 - 57211528

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	291,849 - DH

Activity Header
Activity: 20 016/000/000 SUSPENSION
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Nov-23	4940268	HANDLE, DOOR, W/C, RH	1	63.82	63.82

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	63.82
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**63.82**

Work Order Footer

Work Order 57211528 Total	
Parts:	63.82
Labor:	306.80
Labor Hours:	4.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**370.62**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 57211463
Invoice No. 55345 - 57211463

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Follow up Medium Duty PMC		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	291,849 - DH

Chronology		
Reported	Oct 26, 2023 8:06:16 AM	Oct 26, 2023 8:06:16 AM
Started		
Completed	Nov 2, 2023 9:01:49 AM	Nov 2, 2023 9:01:49 AM
Down Time		

Work Order Notes

Activity Header
Activity: 10 045 POWER PLANT
Activity Note: need tune up
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57211463 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56792558
Invoice No. 55345 - 56792558

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-MEDIUM DUTY PMC		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	291,849 - DH

Chronology		
Reported	Oct 25, 2023 12:00:00 AM	Oct 25, 2023 12:00:00 AM
Started	Oct 26, 2023 5:36:00 AM	
Completed	Oct 26, 2023 9:23:00 AM	Oct 26, 2023 9:23:00 AM
Down Time		

Work Order Notes

Line 10 Pmc

Preventive maintenance

Performed PMC service completed

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 26-OCT-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		HPIERRE	Oct 26, 2023 8:02:31 AM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		HPIERRE	Oct 26, 2023 8:02:31 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Oct 26, 2023 8:02:31 AM	No	
400 - Are you wearing the appropriate PPE?	Done		HPIERRE	Oct 26, 2023 8:02:31 AM	No	
700 - Have you performed the proper LOTO?	Done		HPIERRE	Oct 26, 2023 8:02:31 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,000 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Oct 26, 2023 8:02:31 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Oct 26, 2023 8:02:31 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56792558
Invoice No. 55345 - 56792558

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-MEDIUM DUTY PMC		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	291,849 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Oct-23	Pierre,Hubert J	0.67	65	43.55
26-Oct-23	Pierre,Hubert J	1.8	65	117

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: HPIERRE Performed on: 26-OCT-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
10,800 - CHECK_All Destination Signage	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
20,200 - CHECK_Public Address System	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	60 Second*		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
20,700 - RECORD_Brake Performance Test Speed	60 Miles per Hour		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
20,800 - RECORD_Brake Performance Test Distance	6 FEET		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	6 FEET		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	90 Gravitational Force		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
21,500 - INSPECT_High Idle Control	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
21,800 - INSPECT_Parking Brake Operation	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper	Done		HPIERRE	Oct 26, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Routing/Chafing/Securement				8:22:39 AM		
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
31,000 - SSF (Street Side Front)	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
32,000 - Engine Inspection	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	190 Degree Fahrenheit		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
32,100 - INSPECT_Intake System	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12 Volt*		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
33,000 - CSF (Curb Side Front)	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
33,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
33,050 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
33,060 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	12 Volt*		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
40,700 - CHECK_Passenger Stop Request System	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
50,400 - LUBE_All Chassis Components	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,700 - INSPECT_Tire Condition	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	4 32nds of an inch	need front tire	HPIERRE	Oct 26, 2023 8:22:39 AM	Yes	57211528
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	4 32nds of an inch		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	22 Inch		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	22 Inch		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
52,100 - INSPECT_Vibration Damper	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
53,600 - INSPECT_Tire Condition	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	7 32nds of an inch		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	7 32nds of an inch		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	22 Inch		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	22 Inch		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
60,100 - RECORD_Wheelchair Cycle Count	12230 Cycles		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
62,400 - INSPECT_All Pivot Points	Done		HPIERRE	Oct 26, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:22:39 AM		
62,500 - INSPECT_Cams and Slots	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
62,600 - INSPECT_Rollers	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
62,700 - INSPECT_All Linkages	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		HPIERRE	Oct 26, 2023 8:22:39 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	160.55
Labor Hours:	2.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**160.55**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56792558
Invoice No. 55345 - 56792558

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-MEDIUM DUTY PMC		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	291,849 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM C Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Oct-23	75050	OIL, ENGINE, 5W/30	8	2.73	21.84
26-Oct-23	20021	FILTER, TRANSMISSION 20021	1	21.59	21.59

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	43.43
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.43**

Work Order Footer

Work Order 56792558 Total	
Parts:	43.43
Labor:	160.55
Labor Hours:	2.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**203.98**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 57195214
Invoice No. 55345 - 57195214

Client Department:
Department: 55345M
Work Order Description
FOLLOW UP TO A/C INSPECTION
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 291,434 - DH

Chronology		
Reported	Oct 20, 2023 3:38:03 PM	Oct 20, 2023 3:38:03 PM
Started		
Completed	Oct 25, 2023 1:03:00 PM	Oct 25, 2023 1:03:00 PM
Down Time		

Work Order Notes

Activity Header
Activity: 10 001/001/002 COMPRESSOR, A/C
Activity Note: Bad Front Compressor
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Oct-23	YF38076	LINE, MANIFOLD, A/C, E450	1	111.6	111.6

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	111.60
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**111.60**

Work Order Footer

Work Order 57195214 Total	
Parts:	111.60
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**111.60**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 56109038
Invoice No. 55345 - 56109038

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FIRST TRANSIT AC INSPECTION		Ford E450 Champion Challenger	
Requested By:	SPACE	**Status:**	40 - Closed (40)
Created By:	SPACE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	291,434 -

Chronology		
Reported	Oct 20, 2023 2:33:50 PM	Oct 20, 2023 2:33:50 PM
Started	Oct 20, 2023 2:35:00 PM	
Completed	Oct 23, 2023 4:02:00 PM	Oct 23, 2023 4:02:00 PM
Down Time		

Work Order Notes

Line 10 ReQuire Front Compressor & front high Pressure hose . Rear low Side Service Valve Leaking & lRear low Side went into Vacuum. Need Service . Replace rear A/C Filter. Line 20 Remove & Replace Front A/C Compressor / High pressure hose. Add (8.0) Ozs pag Oil Charge (1.88) lbs freon & Evacuate & Recharge Rear A/C Flush evaporator. Replace Rear Orifice tube. Replace both Service Valve. add (6.0) OZ pag Oil &Charge (.50) Lbs freon.
Parts #3411885 Qty (1)
Parts #YF-38076 Qty (1)
Parts #6512376 Qty (1)

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assesment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assesment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 23-OCT-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		DARTHURS	Oct 23, 2023 4:02:03 PM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		DARTHURS	Oct 23, 2023 4:02:03 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Oct 23, 2023 4:02:03 PM	No	
400 - Are you wearing the appropriate PPE?	Done		DARTHURS	Oct 23, 2023 4:02:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
700 - Have you performed the proper LOTO?	Done		DARTHURS	Oct 23, 2023 4:02:03 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Oct 23, 2023 4:02:03 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Oct 23, 2023 4:02:03 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 56109038
Invoice No. 55345 - 56109038

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FIRST TRANSIT AC INSPECTION		Ford E450 Champion Challenger	
Requested By:	SPACE	**Status:**	40 - Closed (40)
Created By:	SPACE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	291,434 -

Activity Header
Activity: 10 001/001/001 AIR CONDITIONING
Activity Note: FIRST TRANSIT AC INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Oct-23	Arthurs,Durvin	1.28	65	83.2

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: FIRST TRANSIT AC INSPECTION
Task: FIRST TRANSIT AC INSPECTION Performed by: DARTHURS Performed on: 20-OCT-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 VISUAL INSPECTION	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
10,100 - CHECK PHYSICAL DAMAGE, MISSING PARTS	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
10,200 - CHECK REFRIGERANT HOSES FOR CHAFING	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
10,300 - CHECK EVAPORATOR AND CONDENSER FOR OBSTRUCTIONS	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
10,400 - CHECK OPERATION OF FAST IDLE	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
20,000 - SECTION 2 DIAGNOSE THE SYSTEM CONDITION	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
20,100 - ATTACH GAUGES AND RUN SYSTEM 10 MINUTES	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
20,200 - CHECK FOR EVEN AIR DISTRIBUTION	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
20,300 - CHECK FOR PROPER OPERATION OF ALL HVAC MODES	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
20,400 - CHECK DRIVERS A/C SYSTEM	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,500 - RECORD AMBIENT TEMPERATURE BEFORE	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
20,600 - RECORD DISCHARGE PRESSURE BEFORE	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
20,700 - RECORD SUCTION PRESSURE BEFORE	-	10	DARTHURS	Oct 20, 2023 3:38:21 PM	No	
20,710 - RECORD OUTLET TEMPERATURE BEFORE	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
20,800 - CHECK HIGH AND LOW PRESSURE CUTOUT SWITCHES FOR LEAKS	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
30,000 - SECTION 3 COMPRESSOR OPERATIONAL INSPCTION	-	Bad Front Compressor	DARTHURS	Oct 20, 2023 3:38:21 PM	Yes	57195214
30,100 - CHECK FOR UNUSUAL NOISES	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
30,200 - CHECK CLUTCH RESISTANCE READING	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
30,300 - CHECK AIR GAP IN COMPRESSOR CLUTCH	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
30,400 - CHECK COMPRESSOR MOUNTING AND ALIGHMENT	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
30,500 - INSPECT COMPRESSOR BELT(S) OR DRIVE SYSTEM	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
30,600 - CHECK FOR CRACKS AND WEAR	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
30,700 - CHECK FOR PROPER WIDTH AND LENGTH	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
30,800 - CHECK FOR PROPER ALIGNMENT	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
40,000 - SECTION 4 LEAK TEST SYSTEM	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
40,100 - CHICK A/C LINES WITH AN ELECTRONIC LEAK DETECTOR	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
40,200 - CHECK HOSES, FITTINGS, VALVES AND COMPRESSOR SHAFT SEAL	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
40,300 - CHECK HEATER HOSES FOR LEAKS	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
50,000 - SECTION 5 SYSTEM CONTAMINATION	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
50,100 - CHECK INLINE DRIER	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
50,200 - CHECK ACCUMULATOR	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
60,000 - SECTION 6 CHARGE SYSTEM	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
60,100 - IF CHARGING IS REQUIRED, CHARGE BY WEIGHT	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
60,200 - CHECK FOR LEAKS AFTER CHARGING	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
70,000 - SECTION 7 FAN MOTORS	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
70,100 - CHECK SEALED MOTORS FOR PROPER OPERATION	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,200 - INSPECT BLOWER WHEELS	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
70,300 - CHECK ELECTRICAL WIRING & CONNECTIONS	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
80,000 - SECTION 8 OPERATE SYSTEM	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
80,100 - CHECK FOR PROPER HEATING & COOLING	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
80,200 - CHECK TEMPERATURE CONTROLS	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
80,300 - CHECK DEFROST MODE	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
90,000 - SECTION 9 PERFORMANCE TEST READINGS	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
90,100 - RECORD AMBIENT TEMPERATURE READINGS AFTER	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
90,200 - RECORD DISCHARGE PRESSURE AFTER	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
90,300 - RECORD SUCTION PRESSURE AFTER	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
90,400 - RECORD OUTLET TEMPERATURE	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
100,000 - SECTION 10 RESTORE SYSTEM	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
100,100 - DISCONNECT GAUGES	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	
100,200 - CLOSE ALL PANELS, DOOR, ETC.	Done		DARTHURS	Oct 20, 2023 3:38:21 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	83.20
Labor Hours:	1.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**83.20**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 56109038
Invoice No. 55345 - 56109038

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FIRST TRANSIT AC INSPECTION		Ford E450 Champion Challenger	
Requested By:	SPACE	**Status:**	40 - Closed (40)
Created By:	SPACE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	291,434 -

Activity Header
Activity: 20 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Remove & Replace Front Compressor
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Oct-23	6512376	COMPRESSOR, A/C, NEW	1	213.93	213.93

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Oct-23	Arthurs,Durvin	2.15	65	139.75
23-Oct-23	Arthurs,Durvin	1.78	65	115.7

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	213.93
Labor:	255.45
Labor Hours:	3.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**469.38**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 56109038
Invoice No. 55345 - 56109038

Client Department:

Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FIRST TRANSIT AC INSPECTION		Ford E450 Champion Challenger	
Requested By:	SPACE	**Status:**	40 - Closed (40)
Created By:	SPACE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	291,434 -

Activity Header
Activity: 30 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Rear A/C Blowing Warm.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Oct-23	3411885	TUBE, ORIFICE, A/C, FORD	1	0.9	0.9

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Oct-23	Arthurs,Durvin	3.58	65	232.7

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.90
Labor:	232.70
Labor Hours:	3.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**233.60**

Work Order Footer

Work Order 56109038 Total	
Parts:	214.83
Labor:	571.35
Labor Hours:	8.79
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**786.18**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57130296
Invoice No. 55345 - 57130296

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
IN SERVICE INSPECTION		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	290,853 - DH

Chronology		
Reported	Sep 29, 2023 2:19:34 PM	Sep 29, 2023 2:19:34 PM
Started	Oct 6, 2023 2:32:00 PM	
Completed	Oct 10, 2023 7:07:00 PM	Oct 10, 2023 7:07:00 PM
Down Time		

Work Order Notes

Line 10 Vehicle inspected

Front AC not working
Front clearance light needed
Batteries needed Line 20 Two batteries installed and working properly

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: NBARRETO Performed on: 10-OCT-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		NBARRETO	Oct 10, 2023 7:06:57 PM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		NBARRETO	Oct 10, 2023 7:06:57 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NBARRETO	Oct 10, 2023 7:06:57 PM	No	
400 - Are you wearing the appropriate PPE?	Done		NBARRETO	Oct 10, 2023 7:06:57 PM	No	
700 - Have you performed the proper LOTO?	Done		NBARRETO	Oct 10, 2023 7:06:57 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,000 - Are you aware of the potential risks of performing this repair?	Done		NBARRETO	Oct 10, 2023 7:06:57 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		NBARRETO	Oct 10, 2023 7:06:57 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57130296
Invoice No. 55345 - 57130296

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
IN SERVICE INSPECTION		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	290,853 - DH

Activity Header
Activity: 15 999 TOTAL VEHICLE
Activity Note: IN SERVICE INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Oct-23	Nicolas Barreto	2.98	65	193.7
06-Oct-23	Delva,Terry	0.6	65	39

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	232.70
Labor Hours:	3.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**232.70**

Work Order Footer

Work Order 57130296 Total	
Parts:	0.00
Labor:	232.70
Labor Hours:	3.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**232.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56920430
Invoice No. 55345 - 56920430

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FRONT AND REAR AC NOT WORKING		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	290,111 - DH

Chronology		
Reported	Jul 24, 2023 2:28:00 PM	Jul 24, 2023 2:28:00 PM
Started	Jul 24, 2023 2:35:00 PM	
Completed	Aug 6, 2023 5:42:00 PM	Aug 6, 2023 5:42:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: No interior Light / rear A/C inoperative

Cause: Bad Circuit board,

Correction: Recoment circuit board,

Line 20 O
for Electric issue on rear AC REMOVED and replase next Circuit board REPLACE RENTRN BACK TO WORK Line 30 The lift is working no power from Anti-lock to front door and lift Line 40 Check for power for lift and Passenger door. Power up by the door antilock not sending Power out Line 50 Take system apart issue not found at this time Line 60 Take unit a part and check for issue Exchange part from next unit need more time Line 70 Replace Circuit bored from after replacing all parts unit now working asdesign ready for working now

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 24-JUL-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jul 24, 2023 2:35:32 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jul 24, 2023 2:35:32 PM	No	
4 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jul 24, 2023 2:35:32 PM	No	
7 - Have you performed the proper LOTO?	Done		DARTHURS	Jul 24, 2023 2:35:32 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jul 24, 2023 2:35:32 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 24, 2023 2:35:32 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56920430
Invoice No. 55345 - 56920430

Client Department:
Department: 55345M
Work Order Description
FRONT AND REAR AC NOT WORKING
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 290,111 - DH

Activity Header
Activity: 15 174/024/001 HARNESS, WIRING, BODY, BUS, MAIN
Activity Note: FRONT AND REAR AC NOT WORKING
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Jul-23	Arthurs,Durvin	1.37	65	89.05
27-Jul-23	Junior Hurst	0.43	65	27.95
04-Aug-23	Junior Hurst	6.05	65	393.25
06-Aug-23	Junior Hurst	3.52	65	228.8
31-Jul-23	Junior Hurst	4.88	65	317.2
25-Jul-23	Junior Hurst	5.68	65	369.2
30-Jul-23	Junior Hurst	4.55	65	295.75

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	1,721.20
Labor Hours:	26.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1,721.20**

Work Order Footer

Work Order 56920430 Total	
Parts:	0.00
Labor:	1,721.20
Labor Hours:	26.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1,721.20**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56841466
Invoice No. 55345 - 56841466

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Front AC not blowing cold.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	288,312 - DH

Chronology		
Reported	Jun 22, 2023 10:56:39 PM	Jun 22, 2023 10:56:39 PM
Started	Jun 22, 2023 10:58:00 PM	
Completed	Jun 23, 2023 12:32:00 AM	Jun 23, 2023 12:32:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Front AC not blowing cold.

Cause: Low charge pressure.

Correction: Recovered freon. Vacuum, leak tested, added PAG oil and recharged to spec. Will monitor for leaks.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 23-JUN-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jun 23, 2023 12:30:16 AM	No	
2 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Jun 23, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				12:30:16 AM		
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jun 23, 2023 12:30:16 AM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jun 23, 2023 12:30:16 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jun 23, 2023 12:30:16 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jun 23, 2023 12:30:16 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56841466
Invoice No. 55345 - 56841466

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Front AC not blowing cold.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	288,312 - DH

Activity Header
Activity: 15 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Front AC not blowing cold.
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jun-23	Earl Johnson	0.53	65	34.45
22-Jun-23	Earl Johnson	1.03	65	66.95

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	101.40
Labor Hours:	1.56
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**101.40**

Work Order Footer

Work Order 56841466 Total	
Parts:	0.00
Labor:	101.40
Labor Hours:	1.56
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**101.40**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56822628
Invoice No. 55345 - 56822628

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345 Transmission DTC P-0713		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	288,312 - DH

Chronology		
Reported	Jun 16, 2023 1:11:46 PM	Jun 16, 2023 1:11:46 PM
Started	Jun 16, 2023 1:12:00 PM	
Completed	Jun 20, 2023 1:17:56 PM	Jun 20, 2023 1:17:56 PM
Down Time		

Work Order Notes

Line 10 Replaced transmission Internal harness
Replaced valve body gasket
Replaced temperature fuid sensor
Replaced transmission filter

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 16-JUN-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jun 16, 2023 4:26:36 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jun 16, 2023 4:26:36 PM	No	
4 - Are you wearing the appropriate PPE?	Done		TDELVA	Jun 16, 2023 4:26:36 PM	No	
7 - Have you performed the proper LOTO?	Done		TDELVA	Jun 16, 2023 4:26:36 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jun 16, 2023 4:26:36 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jun 16, 2023 4:26:36 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56822628
Invoice No. 55345 - 56822628

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345 Transmission DTC P-0713		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	288,312 - DH

Activity Header
Activity: 20 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Jun-23	20021	FILTER, TRANSMISSION 20021	1	21.59	21.59
16-Jun-23	BC3Z-7H141-A	SENSOR, TEMPERATURE, TRANSMISSION	1	12.86	12.86

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jun-23	Delva,Terry	3.25	65	211.25

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	34.45
Labor:	211.25
Labor Hours:	3.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**245.70**

Work Order Footer

Work Order 56822628 Total	
Parts:	34.45
Labor:	211.25
Labor Hours:	3.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**245.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56819690
Invoice No. 55345 - 56819690

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
check and wrench light on		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	288,312 - DH

Chronology		
Reported	Jun 15, 2023 2:03:00 PM	Jun 15, 2023 2:03:00 PM
Started		
Completed	Jun 20, 2023 1:17:23 PM	Jun 20, 2023 1:17:23 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction:

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: diagnostic for check engine light on
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56819690
Invoice No. 55345 - 56819690

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
check and wrench light on		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	288,312 - DH

Activity Header
Activity: 25 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: transmission valve body harness and sensor replacement
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Jun-23	4C3Z-7G276-AA	HARNESS, SOLENOID, INTERNAL, TRANSMISSION, 5R110W	1	211.17	211.17
16-Jun-23	8C3Z-7C155-A	GASKET, BODY, VALVE, TRANSMISSION, 5R110	1	13.87	13.87

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	225.04
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**225.04**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56819690
Invoice No. 55345 - 56819690

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
check and wrench light on		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	288,312 - DH

Activity Header
Activity: 35 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: inspect and repair misfire condition
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 24 Repair
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 35 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 56819690 Total	
Parts:	225.04
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**225.04**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56810565
Invoice No. 55345 - 56810565

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
W/C LIFT NOT WORKING PROPERLY		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	287,849 - DH

Chronology		
Reported	Jun 13, 2023 12:47:57 AM	Jun 13, 2023 12:47:57 AM
Started	Jun 13, 2023 5:25:00 PM	
Completed	Jun 14, 2023 1:19:00 AM	Jun 14, 2023 1:19:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:W/C lift not working properly

Cause: Faulty lift hand control

Correction:W/C lift hand control monitor replaced

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 14-JUN-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		FSIMON	Jun 14, 2023 1:17:47 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		FSIMON	Jun 14, 2023 1:17:47 AM	No	
4 - Are you wearing the appropriate PPE?	Done		FSIMON	Jun 14, 2023 1:17:47 AM	No	
7 - Have you performed the proper LOTO?	Done		FSIMON	Jun 14, 2023 1:17:47 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		FSIMON	Jun 14, 2023 1:17:47 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Jun 14, 2023 1:17:47 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56810565
Invoice No. 55345 - 56810565

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
W/C LIFT NOT WORKING PROPERLY		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	287,849 - DH

Activity Header
Activity: 15 055 HANDLING, CARGO RESTRAINT & LIFT SYSTEM (POWER UNITS, TRAILERS)
Activity Note: W/C LIFT
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Jun-23	Fritz Simon	1	65	65

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**65.00**

Work Order Footer

Work Order 56810565 Total	
Parts:	0.00
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**65.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56795033
Invoice No. 55345 - 56795033

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Scheduled		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	287,849 - DH

Chronology		
Reported	Jun 7, 2023 10:09:12 AM	Jun 7, 2023 10:09:12 AM
Started	Jun 7, 2023 10:11:00 AM	
Completed	Jun 7, 2023 12:54:00 PM	Jun 7, 2023 12:54:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: bus leaking oil

Cause: drain plug bad

Correction: replaced drain plug and add oil completed

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 07-JUN-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Jun 7, 2023 12:53:01 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Jun 7, 2023 12:53:01 PM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Jun 7, 2023 12:53:01 PM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Jun 7, 2023 12:53:01 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Jun 7, 2023 12:53:01 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Jun 7, 2023 12:53:01 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56795033
Invoice No. 55345 - 56795033

Client Department:
Department: 55345M
Work Order Description
Scheduled
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 287,849 - DH

Activity Header
Activity: 15 999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Jun-23	090-053	PLUG, DRAIN, OIL, ENGINE, 16MM, IMPALA	1	1.71	1.71

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Jun-23	Pierre,Hubert J	1.03	65	66.95

Activity Sublet
No Data Available

Activity Checklist

Check List

15 Desc:
Task: LUBE OIL FILTER Performed by: HPIERRE Performed on: 07-JUN-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,100 - LUBE OIL FILTER	Done		HPIERRE	Jun 7, 2023 12:54:12 PM	No	
10,200 - 1. Obtain oil sample	Done		HPIERRE	Jun 7, 2023 12:54:12 PM	No	
10,300 - 2. Change oil and filter	Yes		HPIERRE	Jun 7, 2023 12:54:12 PM	No	
10,400 - 3. Check brakes	Done		HPIERRE	Jun 7, 2023 12:54:12 PM	No	
10,500 - 4. Check for leaks	Done		HPIERRE	Jun 7, 2023 12:54:12 PM	No	
10,600 - 5. Fill engine oil _____ QTS	7 Quart (1,136523 dm3)		HPIERRE	Jun 7, 2023 12:54:12 PM	No	
10,700 - 6. Check coolant level	Yes		HPIERRE	Jun 7, 2023 12:54:12 PM	No	
10,800 - 7. Check transmission fluid level	Yes		HPIERRE	Jun 7, 2023 12:54:12 PM	No	
10,900 - 8. Check washer fluid level	Yes		HPIERRE	Jun 7, 2023 12:54:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
101,000 - 9. Check wiper blades	Done		HPIERRE	Jun 7, 2023 12:54:12 PM	No	
101,100 - 10. Check Drivecam status and mounting	Done		HPIERRE	Jun 7, 2023 12:54:12 PM	No	
101,200 - 11. Check all lights	Done		HPIERRE	Jun 7, 2023 12:54:12 PM	No	
101,300 - 12. Cycle and check wheelchair lift	Done		HPIERRE	Jun 7, 2023 12:54:12 PM	No	
101,400 - 13. Check tire pressure	Done		HPIERRE	Jun 7, 2023 12:54:12 PM	No	
101,500 - 14. Check charging system : _____ Volts	14 Volt*		HPIERRE	Jun 7, 2023 12:54:12 PM	No	
101,600 - 15. Check batteries individually with Midtronics tester (attach printout to thi	Done		HPIERRE	Jun 7, 2023 12:54:12 PM	No	

Activity Sub Total

Activity 15 Sub Total	
Parts:	1.71
Labor:	66.95
Labor Hours:	1.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**68.66**

Work Order Footer

Work Order 56795033 Total	
Parts:	1.71
Labor:	66.95
Labor Hours:	1.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**68.66**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56634184
Invoice No. 55345 - 56634184

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-MEDIUM DUTY PMA		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	287,849 - DH

Chronology		
Reported	Jun 5, 2023 12:00:00 AM	Jun 5, 2023 12:00:00 AM
Started	Jun 5, 2023 3:58:00 PM	
Completed	Jun 6, 2023 1:40:00 PM	Jun 6, 2023 1:40:00 PM
Down Time		

Work Order Notes

Line 10 PMA

Preventive maintenance

Performed PMA service completed

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 06-JUN-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Jun 6, 2023 10:07:50 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Jun 6, 2023 10:07:50 AM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Jun 6, 2023 10:07:50 AM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Jun 6, 2023 10:07:50 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Jun 6, 2023 10:07:50 AM	No	
11 - Have you successfully completed the Personal	Done		HPIERRE	Jun 6, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				10:07:50 AM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56634184
Invoice No. 55345 - 56634184

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-MEDIUM DUTY PMA		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	287,849 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Jun-23	B329	FILTER, OIL, SPIN-ON SEE P550965	1	2.51	2.51

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jun-23	Pierre,Hubert J	2.72	65	176.8

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: HPIERRE Performed on: 06-JUN-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
10,800 - CHECK_All Destination Signage	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
20,200 - CHECK_Public Address System	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	190 Second*		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
20,700 - RECORD_Brake Performance Test Speed	60 Miles per Hour		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
20,800 - RECORD_Brake Performance Test Distance	6 FEET		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	6 FEET		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	190 Gravitational Force		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
21,500 - INSPECT_High Idle Control	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
21,800 - INSPECT_Parking Brake Operation	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
31,000 - SSF (Street Side Front)	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
32,000 - Engine Inspection	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	190 Degree Fahrenheit		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
32,100 - INSPECT_Intake System	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12 Volt*		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
33,000 - CSF (Curb Side Front)	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
33,050 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
33,060 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	12 Volt*		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
40,700 - CHECK_Passenger Stop Request System	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
50,400 - LUBE_All Chassis Components	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
50,700 - INSPECT_Tire Condition	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	20 Inch		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	20 Inch		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
52,100 - INSPECT_Vibration Damper	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,600 - INSPECT_Tire Condition	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	10 32nds of an inch		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	10 32nds of an inch		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	22 Inch		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	22 Inch		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,000 - SECTION 6 - Wheelchair Inspection	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
60,100 - RECORD_Wheelchair Cycle Count	12111 Cycles		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
62,400 - INSPECT_All Pivot Points	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
62,500 - INSPECT_Cams and Slots	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
62,600 - INSPECT_Rollers	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
62,700 - INSPECT_All Linkages	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		HPIERRE	Jun 6, 2023 10:07:19 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	2.51
Labor:	176.80
Labor Hours:	2.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**179.31**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56634184
Invoice No. 55345 - 56634184

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-MEDIUM DUTY PMA		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	287,849 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Jun-23	75050	OIL, ENGINE, 5W/30	6	2.11	12.66

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: HPIERRE Performed on: 06-JUN-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Jun 6, 2023 10:08:52 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Jun 6, 2023 10:08:52 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Jun 6, 2023 10:08:52 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Jun 6, 2023 10:08:52 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Jun 6, 2023 10:08:52 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Jun 6, 2023 10:08:52 AM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	Done		HPIERRE	Jun 6, 2023 10:08:52 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	Na	HPIERRE	Jun 6, 2023 10:08:52 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Jun 6, 2023 10:08:52 AM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	12.66
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**12.66**

Work Order Footer

Work Order 56634184 Total	
Parts:	15.17
Labor:	176.80
Labor Hours:	2.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**191.97**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56780767
Invoice No. 55345 - 56780767

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Scheduled		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	287,326 - DH

Chronology		
Reported	Jun 2, 2023 12:45:00 AM	Jun 2, 2023 12:45:00 AM
Started	Jun 2, 2023 12:46:00 AM	
Completed	Jun 2, 2023 5:29:00 PM	Jun 2, 2023 5:29:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:Front A/C not blowing cold

Cause:A/C High and low sides valves leaking

Correction:A/C system recovery,Valves replaced,vacuum ,and refrigerant recharge done

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 02-JUN-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		FSIMON	Jun 2, 2023 1:48:42 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		FSIMON	Jun 2, 2023 1:48:42 AM	No	
4 - Are you wearing the appropriate PPE?	Done		FSIMON	Jun 2, 2023 1:48:42 AM	No	
7 - Have you performed the proper LOTO?	Done		FSIMON	Jun 2, 2023 1:48:42 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		FSIMON	Jun 2, 2023 1:48:42 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Jun 2, 2023 1:48:42 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56780767
Invoice No. 55345 - 56780767

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Scheduled		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	287,326 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jun-23	Fritz Simon	1.23	65	79.95

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	79.95
Labor Hours:	1.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**79.95**

Work Order Footer

Work Order 56780767 Total	
Parts:	0.00
Labor:	79.95
Labor Hours:	1.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**79.95**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56765107
Invoice No. 55345 - 56765107

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
W/C LIFT NOT WORKING PROPERLY		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	287,326 - DH

Chronology		
Reported	May 26, 2023 5:11:45 PM	May 26, 2023 5:11:45 PM
Started	May 26, 2023 5:16:00 PM	
Completed	May 29, 2023 7:04:00 PM	May 29, 2023 7:04:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:W/C lift not working properly

Cause:Warning beeping when inner barrier sitting on the bus floor plate

Correction:W/C lift adjusted

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 26-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		FSIMON	May 26, 2023 5:17:34 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		FSIMON	May 26, 2023 5:17:34 PM	No	
4 - Are you wearing the appropriate PPE?	Done		FSIMON	May 26, 2023 5:17:34 PM	No	
7 - Have you performed the proper LOTO?	Done		FSIMON	May 26, 2023 5:17:34 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		FSIMON	May 26, 2023 5:17:34 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	May 26, 2023 5:17:34 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56765107
Invoice No. 55345 - 56765107

Client Department:
Department: 55345M
Work Order Description
W/C LIFT NOT WORKING PROPERLY
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 287,326 - DH

Activity Header
Activity: 15 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: W/C LIFT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-May-23	Fritz Simon	2.58	65	167.7

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	167.70
Labor Hours:	2.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**167.70**

Work Order Footer

Work Order 56765107 Total	
Parts:	0.00
Labor:	167.70
Labor Hours:	2.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**167.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56751226
Invoice No. 55345 - 56751226

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
W/C LIFT WORKING INTERMITTENTLY/MDT FALLING OFF		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	286,505 - DH

Chronology		
Reported	May 22, 2023 11:56:54 PM	May 22, 2023 11:56:54 PM
Started	May 23, 2023 12:00:00 AM	
Completed	May 23, 2023 1:59:00 AM	May 23, 2023 1:59:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:WC Lift working intermittently
:MDT FALLING OFF

Cause:

Correction:MDT tightened

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 23-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		FSIMON	May 23, 2023 1:58:53 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		FSIMON	May 23, 2023 1:58:53 AM	No	
4 - Are you wearing the appropriate PPE?	Done		FSIMON	May 23, 2023 1:58:53 AM	No	
7 - Have you performed the proper LOTO?	Done		FSIMON	May 23, 2023 1:58:53 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		FSIMON	May 23, 2023 1:58:53 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	May 23, 2023 1:58:53 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56751226
Invoice No. 55345 - 56751226

Client Department:
Department: 55345M
Work Order Description
W/C LIFT WORKING INTERMITTENTLY/MDT FALLING OFF
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 286,505 - DH

Activity Header
Activity: 15 055 HANDLING, CARGO RESTRAINT & LIFT SYSTEM (POWER UNITS, TRAILERS)
Activity Note: W/C LIFT WORKING INTRMITTENTLY/MDT FALLING OFF
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-May-23	Fritz Simon	1.17	65	76.05

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	76.05
Labor Hours:	1.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**76.05**

Work Order Footer

Work Order 56751226 Total	
Parts:	0.00
Labor:	76.05
Labor Hours:	1.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**76.05**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 6

Work Order No. 56741044
Invoice No. 55345 - 56741044

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	286,120 - DH

Chronology		
Reported	May 18, 2023 10:48:39 PM	May 18, 2023 10:48:39 PM
Started	May 19, 2023 10:05:00 AM	
Completed	May 19, 2023 9:15:00 PM	May 19, 2023 9:15:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========
To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.
==========

Complaint: Vehicle came in for Brake issue

Cause: left rear caliper frozen

Correction: REAR BRAKES REPLACE PART # 8C2Z-2V200-C. Also replace caliper part # 18-B5110 please charge out this part for me thank you. Check unit and found Battery terminal not good replace new Terminalnow now woringasdesign working asdesign Line 20 Check Battery found terminals Loose. removed and replace one new after wash battery service lift unit working perfect return unit back to work

Activity Header
Activity: 10 034 LIGHTING SYSTEM
Activity Note: Clearance light goes out and in at times middle one
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 6

Work Order No. 56741044
Invoice No. 55345 - 56741044

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	286,120 - DH

Activity Header
Activity:20
Activity Note: DRIVER SEAT NEEDS REPLACE
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-May-23	3974688	LAMP, LED, AMBER	1	9.04	9.04

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	9.04
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**9.04**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 6

Work Order No. 56741044
Invoice No. 55345 - 56741044

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	286,120 - DH

Activity Header
Activity: 30
Activity Note: Selector Bushing are bad
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 6

Work Order No. 56741044
Invoice No. 55345 - 56741044

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	286,120 - DH

Activity Header
Activity:40
Activity Note: Shifter Bushing for selector needs replacing
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-May-23	Junior Hurst	0.83	65	53.95

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	53.95
Labor Hours:	0.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**53.95**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 6

Work Order No. 56741044
Invoice No. 55345 - 56741044

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	286,120 - DH

Activity Header
Activity: 50 017 TIRES, TUBES, LINERS & VALVES
Activity Note: NEEDS REAR BRAKES (2 mm)
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-May-23	BC2Z-2553-B	CALIPER, BRAKE, DISC, REAR, LH, E450	1	54.77	54.77

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-May-23	Pierre,Hubert J	1.4	65	91

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 50 Sub Total	
Parts:	54.77
Labor:	91.00
Labor Hours:	1.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**145.77**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 6 of 6

Work Order No. 56741044
Invoice No. 55345 - 56741044

Client Department:
Department: 55345M
Work Order Description
FOLLOW UP TO QCC INSP
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 286,120 - DH

Activity Header
Activity: 60 018/002 HUBS & BEARINGS, AXLE, DRIVE
Activity Note: LEFT REAR CALIPER SEIZED
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-May-23	BRSD1330B	PADS, BRAKE, DISC, REAR SAME AS 8C2Z-2V200-C	1	53.78	53.78

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-May-23	Junior Hurst	5.75	65	373.75

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 60 Sub Total	
Parts:	53.78
Labor:	373.75
Labor Hours:	5.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**427.53**

Work Order Footer

Work Order 56741044 Total	
Parts:	117.59
Labor:	518.70
Labor Hours:	7.98
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**636.29**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55622347
Invoice No. 55345 - 55622347

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
QCC FLEET INSPECTION		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	286,120 -

Chronology		
Reported	May 18, 2023 3:07:54 PM	May 18, 2023 3:07:54 PM
Started	May 18, 2023 9:54:00 PM	
Completed	May 19, 2023 12:02:00 AM	May 19, 2023 12:02:00 AM
Down Time		

Work Order Notes

Line 10 PERFORM QCC INSPECTION VEHICLE NEEDS REAR BRAKES MIDDLE CLEARANCE LIGHT BLINKS OFF AND ON ALSO DRIVER SEAT NEEDS REPLACE

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 18-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		AOWENS	May 18, 2023 10:49:44 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		AOWENS	May 18, 2023 10:49:44 PM	No	
4 - Are you wearing the appropriate PPE?	Done		AOWENS	May 18, 2023 10:49:44 PM	No	
7 - Have you performed the proper LOTO?	Done		AOWENS	May 18, 2023 10:49:44 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	May 18, 2023 10:49:44 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	May 18, 2023 10:49:44 PM	No	

Activity Sub Total

Activity 10 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55622347
Invoice No. 55345 - 55622347

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
QCC FLEET INSPECTION		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	286,120 -

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: QCC FLEET INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-May-23	Owens,Arthur	1.15	65	74.75

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: QCC FLEET INSPECTION
Task: 55345 QCC FLEET INSPECTION Performed by: AOWENS Performed on: 18-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - EXTERIOR CIRCLE INSPECTION	Done		AOWENS	May 18, 2023 10:49:17 PM	No	
20 - Cleanliness	A		AOWENS	May 18, 2023 10:49:17 PM	No	
30 - Entrance Door Operation/Seals/Glass	A		AOWENS	May 18, 2023 10:49:17 PM	No	
40 - Body/Fenders/Bumpers	C	Scratches all over vehicle	AOWENS	May 18, 2023 10:49:17 PM	No	
50 - Tires/Wheels/Lugs	A		AOWENS	May 18, 2023 10:49:17 PM	No	
60 - Mirrors and Attachments	A		AOWENS	May 18, 2023 10:49:17 PM	No	
70 - Lights and Accessories	B	Clearance light goes out and in at times middle one	AOWENS	May 18, 2023 10:49:17 PM	Yes	56741044
80 - Compartment Doors	A		AOWENS	May 18, 2023 10:49:17 PM	No	
90 - Battery Compartment	A		AOWENS	May 18, 2023 10:49:17 PM	No	
100 - Check All Fluids	A		AOWENS	May 18, 2023 10:49:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
110 - Belt Drives	A		AOWENS	May 18, 2023 10:49:17 PM	No	
120 - Air Induction	A		AOWENS	May 18, 2023 10:49:17 PM	No	
130 - Exhaust System	A		AOWENS	May 18, 2023 10:49:17 PM	No	
140 - Engine Compartmetn Wiring	A		AOWENS	May 18, 2023 10:49:17 PM	No	
150 - DRIVERS AREA INSPECTION	Done		AOWENS	May 18, 2023 10:49:17 PM	No	
160 - Air System	A		AOWENS	May 18, 2023 10:49:17 PM	No	
170 - Audible Warnings	A		AOWENS	May 18, 2023 10:49:17 PM	No	
180 - Dash and Gauges	A		AOWENS	May 18, 2023 10:49:17 PM	No	
190 - Accessory components	A		AOWENS	May 18, 2023 10:49:17 PM	No	
200 - Exit Door Operation	A		AOWENS	May 18, 2023 10:49:17 PM	No	
210 - Exit Door Interlock	A		AOWENS	May 18, 2023 10:49:17 PM	No	
220 - Fare box and ticket cutter.	E		AOWENS	May 18, 2023 10:49:17 PM	No	
230 - Fast Idle	A		AOWENS	May 18, 2023 10:49:17 PM	No	
240 - Glass & Mirrors	A		AOWENS	May 18, 2023 10:49:17 PM	No	
250 - Floor Covering	A		AOWENS	May 18, 2023 10:49:17 PM	No	
260 - Horn and Lamps	A		AOWENS	May 18, 2023 10:49:17 PM	No	
270 - Start Function	A		AOWENS	May 18, 2023 10:49:17 PM	No	
280 - PA System	A		AOWENS	May 18, 2023 10:49:17 PM	No	
290 - Pedal Condition and Adjustment	A		AOWENS	May 18, 2023 10:49:17 PM	No	
300 - Reverse System	A		AOWENS	May 18, 2023 10:49:17 PM	No	
310 - Seat	B	DRIVER SEAT NEEDS REPLACE	AOWENS	May 18, 2023 10:49:17 PM	Yes	56741044
320 - Steering Wheel & Column	B	Selector Bushing are bad	AOWENS	May 18, 2023 10:49:17 PM	Yes	56741044
330 - Sun Visor	A		AOWENS	May 18, 2023 10:49:17 PM	No	
340 - Turn Signals Switch	A		AOWENS	May 18, 2023 10:49:17 PM	No	
350 - Electrical Compartment	A		AOWENS	May 18, 2023 10:49:17 PM	No	
360 - Wheel Chair Operation	A		AOWENS	May 18, 2023 10:49:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
370 - INTERIOR CIRCLE	Done		AOWENS	May 18, 2023 10:49:17 PM	No	
380 - Cleanliness	A		AOWENS	May 18, 2023 10:49:17 PM	No	
390 - HVAC	A		AOWENS	May 18, 2023 10:49:17 PM	No	
400 - Interior Passenger Area	A		AOWENS	May 18, 2023 10:49:17 PM	No	
410 - Stop Request	E		AOWENS	May 18, 2023 10:49:17 PM	No	
420 - Safety Equipment	A		AOWENS	May 18, 2023 10:49:17 PM	No	
430 - UNDERCARRIAGE	Done		AOWENS	May 18, 2023 10:49:17 PM	No	
440 - Air System	A		AOWENS	May 18, 2023 10:49:17 PM	No	
450 - Steering components		Shifter Bushing for selector needs replacing	AOWENS	May 18, 2023 10:49:17 PM	Yes	56741044
460 - Brake Inspection	D	NEEDS REAR BRAKES (2 mm)	AOWENS	May 18, 2023 10:49:17 PM	Yes	56741044
470 - Suspension Components	A		AOWENS	May 18, 2023 10:49:17 PM	No	
480 - Frame	A		AOWENS	May 18, 2023 10:49:17 PM	No	
490 - Fluid Leakage	A		AOWENS	May 18, 2023 10:49:17 PM	No	
500 - Fuel System	A		AOWENS	May 18, 2023 10:49:17 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	74.75
Labor Hours:	1.15
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**74.75**

Work Order Footer

Work Order 55622347 Total	
Parts:	0.00
Labor:	74.75
Labor Hours:	1.15
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**74.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56721740
Invoice No. 55345 - 56721740

Client Department:
Department: 55345M
Work Order Description
CATALYTIC CONVERTER THEFT DETERRENT KIT INSTALLATION
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 285,813 - DH

Chronology		
Reported	May 12, 2023 7:21:38 PM	May 12, 2023 7:21:38 PM
Started	May 12, 2023 7:27:00 PM	
Completed	May 13, 2023 1:33:00 AM	May 13, 2023 1:33:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction:

Catalytic converter theft deterrent installed

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 13-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		FSIMON	May 13, 2023 1:32:11 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		FSIMON	May 13, 2023 1:32:11 AM	No	
4 - Are you wearing the appropriate PPE?	Done		FSIMON	May 13, 2023 1:32:11 AM	No	
7 - Have you performed the proper LOTO?	Done		FSIMON	May 13, 2023 1:32:11 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		FSIMON	May 13, 2023 1:32:11 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	May 13, 2023 1:32:11 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56721740
Invoice No. 55345 - 56721740

Client Department:
Department: 55345M
Work Order Description
CATALYTIC CONVERTER THEFT DETERRENT KIT INSTALLATION
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 285,813 - DH

Activity Header
Activity: 15 043/001/030 CONVERTER, CATALYTIC
Activity Note: CATALYTIC CONVERTER THEFT DETERRENT KIT INSTALLATION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-May-23	Fritz Simon	3.3	65	214.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	214.50
Labor Hours:	3.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**214.50**

Work Order Footer

Work Order 56721740 Total	
Parts:	0.00
Labor:	214.50
Labor Hours:	3.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**214.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56709336
Invoice No. 55345 - 56709336

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Unscheduled Work		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	285,813 - DH

Chronology		
Reported	May 12, 2023 3:04:23 PM	May 12, 2023 3:04:23 PM
Started	May 12, 2023 3:07:00 PM	
Completed	May 12, 2023 11:00:00 PM	May 12, 2023 11:00:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: vehicle came in for A/C issue

Cause: Compressor not good

Correction: RECOVER freeon CHANGE COMPRESSOR.PART # 6512376 replace accumulator # GC2Z-19C836-Cand office tube #3411885. AC now working asdesign return unit back to work

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 12-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	May 12, 2023 9:26:13 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	May 12, 2023 9:26:13 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	May 12, 2023 9:26:13 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	May 12, 2023 9:26:13 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	May 12, 2023 9:26:13 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	May 12, 2023 9:26:13 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56709336
Invoice No. 55345 - 56709336

Client Department:
Department: 55345M
Work Order Description
Unscheduled Work
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 285,813 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: A/C issue
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-May-23	3411885	TUBE, ORIFICE, A/C, FORD	1	1.06	1.06
12-May-23	6512376	COMPRESSOR, A/C, NEW	1	210.86	210.86
12-May-23	GC2Z-19C836-C	ACCUMULATOR, A/C, E450	1	87.36	87.36

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-May-23	Junior Hurst	2.53	65	164.45
12-May-23	Junior Hurst	2.88	65	187.2
12-May-23	Junior Hurst	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	299.28
Labor:	449.15
Labor Hours:	6.91
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**748.43**

Work Order Footer

Work Order 56709336 Total	
Parts:	299.28
Labor:	449.15
Labor Hours:	6.91
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**748.43**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56705707
Invoice No. 55345 - 56705707

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Lift issue		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	285,624 - DH

Chronology		
Reported	May 11, 2023 8:29:13 PM	May 11, 2023 8:29:13 PM
Started	May 11, 2023 8:31:00 PM	
Completed	May 11, 2023 9:44:00 PM	May 11, 2023 9:44:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: vehicle came in for lift issue

Cause: loose ARMS

Correction: REPAIR ISSUE. UNIT NOW WORKING ASDESIGN CHECK UNIT COMPLETE RETURN BACK TO WORK

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 11-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	May 11, 2023 9:38:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	May 11, 2023 9:38:02 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	May 11, 2023 9:38:02 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	May 11, 2023 9:38:02 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	May 11, 2023 9:38:02 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	May 11, 2023 9:38:02 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56705707
Invoice No. 55345 - 56705707

Client Department:
Department: 55345M
Work Order Description
Lift issue
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 285,624 - DH

Activity Header
Activity: 15 020 GROUP, DRIVETRAIN
Activity Note: Lift issue
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-May-23	Junior Hurst	1.2	65	78

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	78.00
Labor Hours:	1.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**78.00**

Work Order Footer

Work Order 56705707 Total	
Parts:	0.00
Labor:	78.00
Labor Hours:	1.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**78.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56683722
Invoice No. 55345 - 56683722

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
NOISE UNDER THE HOOD		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	284,991 - DH

Chronology		
Reported	May 4, 2023 5:20:16 PM	May 4, 2023 5:20:16 PM
Started	May 4, 2023 11:53:00 PM	
Completed	May 6, 2023 1:30:00 AM	May 6, 2023 1:30:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:Noise under the hood

Cause:

Correction:Idler pulleys ,tensioner and belt checked.Front and rear ac pressures adjusted .

Repair process in progress.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 05-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		FSIMON	May 5, 2023 1:20:48 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		FSIMON	May 5, 2023 1:20:48 AM	No	
4 - Are you wearing the appropriate PPE?	Done		FSIMON	May 5, 2023 1:20:48 AM	No	
7 - Have you performed the proper LOTO?	Done		FSIMON	May 5, 2023 1:20:48 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		FSIMON	May 5, 2023 1:20:48 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	May 5, 2023 1:20:48 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56683722
Invoice No. 55345 - 56683722

Client Department:
Department: 55345M
Work Order Description
NOISE UNDER THE HOOD
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 284,991 - DH

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: NOISE UNDER THE HOOD
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-May-23	3411885	TUBE, ORIFICE, A/C, FORD	1	1.06	1.06

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-May-23	Fritz Simon	1.48	65	96.2
04-May-23	Fritz Simon	0.12	65	7.8

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	1.06
Labor:	104.00
Labor Hours:	1.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**105.06**

Work Order Footer

Work Order 56683722 Total	
Parts:	1.06
Labor:	104.00
Labor Hours:	1.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**105.06**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56665519
Invoice No. 55345 - 56665519

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Scheduled		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	284,440 - DH

Chronology		
Reported	Apr 28, 2023 5:24:30 PM	Apr 28, 2023 5:24:30 PM
Started	Apr 28, 2023 5:28:00 PM	
Completed	Apr 28, 2023 7:01:00 PM	Apr 28, 2023 7:01:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:Lift not working properly ,Tag light loose,Belt is loud

Cause: Complaints cannot be verified

Correction:Complaints cannot be verified

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 28-APR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		FSIMON	Apr 28, 2023 5:29:00 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		FSIMON	Apr 28, 2023 5:29:00 PM	No	
4 - Are you wearing the appropriate PPE?	Done		FSIMON	Apr 28, 2023 5:29:00 PM	No	
7 - Have you performed the proper LOTO?	Done		FSIMON	Apr 28, 2023 5:29:00 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		FSIMON	Apr 28, 2023 5:29:00 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Apr 28, 2023 5:29:00 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56665519
Invoice No. 55345 - 56665519

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Scheduled		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	284,440 - DH

Activity Header
Activity: 15 055 HANDLING, CARGO RESTRAINT & LIFT SYSTEM (POWER UNITS, TRAILERS)
Activity Note: W/C. LIFT
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Apr-23	Fritz Simon	1.55	65	100.75

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	100.75
Labor Hours:	1.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**100.75**

Work Order Footer

Work Order 56665519 Total	
Parts:	0.00
Labor:	100.75
Labor Hours:	1.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**100.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56664534
Invoice No. 55345 - 56664534

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Squeaking Noise		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	284,440 - DH

Chronology		
Reported	Apr 28, 2023 12:40:15 PM	Apr 28, 2023 12:40:15 PM
Started	Apr 28, 2023 1:33:00 PM	
Completed	Apr 28, 2023 3:47:00 PM	Apr 28, 2023 3:47:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: SQueaking noise

Cause: Worn drive belt

Correction: Move Over Idler pulley. Did not make any difference. Replace New belt. All is ok at this time.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 28-APR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Apr 28, 2023 1:34:06 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Apr 28, 2023 1:34:06 PM	No	
4 - Are you wearing the appropriate PPE?	Done		DARTHURS	Apr 28, 2023 1:34:06 PM	No	
7 - Have you performed the proper LOTO?	Done		DARTHURS	Apr 28, 2023 1:34:06 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Apr 28, 2023 1:34:06 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 28, 2023 1:34:06 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56664534
Invoice No. 55345 - 56664534

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Squeaking Noise		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	284,440 - DH

Activity Header
Activity: 15 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Apr-23	Arthurs,Durvin	2.23	65	144.95

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	144.95
Labor Hours:	2.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**144.95**

Work Order Footer

Work Order 56664534 Total	
Parts:	0.00
Labor:	144.95
Labor Hours:	2.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**144.95**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56659469
Invoice No. 55345 - 56659469

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Wheelchair Lift		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	284,440 - DH

Chronology		
Reported	Apr 27, 2023 8:39:06 AM	Apr 27, 2023 8:39:06 AM
Started	Apr 27, 2023 8:41:00 AM	
Completed	Apr 27, 2023 10:05:00 AM	Apr 27, 2023 10:05:00 AM
Down Time		

Work Order Notes

Line 10 Replaced 1 outer barrier shock
Adjust lift up and down
Adjust lift fold and unfold
Add inner barrier rubber

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 27-APR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Apr 27, 2023 10:04:47 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Apr 27, 2023 10:04:47 AM	No	
4 - Are you wearing the appropriate PPE?	Done		TDELVA	Apr 27, 2023 10:04:47 AM	No	
7 - Have you performed the proper LOTO?	Done		TDELVA	Apr 27, 2023 10:04:47 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Apr 27, 2023 10:04:47 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Apr 27, 2023 10:04:47 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56659469
Invoice No. 55345 - 56659469

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Wheelchair Lift		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	284,440 - DH

Activity Header
Activity: 20 055/023/000 LIFT, WHEELCHAIR, PASSENGER
Activity Note: WheelChair Lift
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Apr-23	32831	SPRING, SHOCK, GAS, W/C	1	24.15	24.15

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Apr-23	Delva,Terry	1.4	65	91

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	24.15
Labor:	91.00
Labor Hours:	1.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**115.15**

Work Order Footer

Work Order 56659469 Total	
Parts:	24.15
Labor:	91.00
Labor Hours:	1.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**115.15**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56654680
Invoice No. 55345 - 56654680

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Lift issue		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	284,440 - DH

Chronology		
Reported	Apr 25, 2023 5:41:34 PM	Apr 25, 2023 5:41:34 PM
Started	Apr 25, 2023 5:44:00 PM	
Completed	Apr 25, 2023 6:01:00 PM	Apr 25, 2023 6:01:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: lift issue. Supervisor the take job back

Cause:

Correction:

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 25-APR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Apr 25, 2023 6:01:24 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		JUHURST	Apr 25, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				6:01:24 PM		
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Apr 25, 2023 6:01:24 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Apr 25, 2023 6:01:24 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Apr 25, 2023 6:01:24 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Apr 25, 2023 6:01:24 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56654680
Invoice No. 55345 - 56654680

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Lift issue		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	284,440 - DH

Activity Header
Activity: 15 030 ELECTRICAL GROUP
Activity Note: Lift issue
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Apr-23	Junior Hurst	0.2	65	13

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	13.00
Labor Hours:	0.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**13.00**

Work Order Footer

Work Order 56654680 Total	
Parts:	0.00
Labor:	13.00
Labor Hours:	0.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**13.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56634077
Invoice No. 55345 - 56634077

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	283,956 - DH

Chronology		
Reported	Apr 19, 2023 7:57:35 AM	Apr 19, 2023 7:57:35 AM
Started	Apr 19, 2023 8:22:00 AM	
Completed	Apr 19, 2023 9:23:00 AM	Apr 19, 2023 9:23:00 AM
Down Time		

Work Order Notes

Line 10 PMA follow up need rotate and air filter

Preventive maintenance

Cross rotate and replace air filter completed

Activity Header
Activity: 10 017/008/004 CAP, VALVE, TIRE
Activity Note: need rotate
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Apr-23	Pierre,Hubert J	0.93	65	60.45

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	60.45
Labor Hours:	0.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**60.45**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56634077
Invoice No. 55345 - 56634077

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	283,956 - DH

Activity Header
Activity: 20 041/000/000 INTAKE, AIR
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Apr-23	PA4075	FILTER, AIR SEE P546597	1	6.69	6.69

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	6.69
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**6.69**

Work Order Footer

Work Order 56634077 Total	
Parts:	6.69
Labor:	60.45
Labor Hours:	0.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**67.14**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56255196
Invoice No. 55345 - 56255196

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-MEDIUM DUTY PMA		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	283,956 - DH

Chronology		
Reported	Apr 17, 2023 12:00:00 AM	Apr 17, 2023 12:00:00 AM
Started	Apr 19, 2023 5:34:00 AM	
Completed	Apr 19, 2023 8:21:00 AM	Apr 19, 2023 8:21:00 AM
Down Time		

Work Order Notes

Line 10 Pma

Preventive maintenance

Performed PMA completed

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 19-APR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Apr 19, 2023 7:35:39 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Apr 19, 2023 7:35:39 AM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Apr 19, 2023 7:35:39 AM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Apr 19, 2023 7:35:39 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Apr 19, 2023 7:35:39 AM	No	
11 - Have you successfully completed the Personal	Done		HPIERRE	Apr 19, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				7:35:39 AM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56255196
Invoice No. 55345 - 56255196

Client Department:
Department: 55345M
Work Order Description
55345-MEDIUM DUTY PMA
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 283,956 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Apr-23	B329	FILTER, OIL, SPIN-ON SEE P550965	1	2.51	2.51

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Apr-23	Pierre,Hubert J	0.4	65	26
19-Apr-23	Pierre,Hubert J	1.78	65	115.7

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: HPIERRE Performed on: 19-APR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,800 - CHECK_All Destination Signage	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
20,200 - CHECK_Public Address System	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	60 Second*		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
20,700 - RECORD_Brake Performance Test Speed	60 Miles per Hour		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
20,800 - RECORD_Brake Performance Test Distance	6 FEET		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	6 FEET		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	90 Gravitational Force		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
21,500 - INSPECT_High Idle Control	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
21,800 - INSPECT_Parking Brake Operation	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges,	Done		HPIERRE	Apr 19, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Handles, Controls and Panels				7:57:29 AM		
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
31,000 - SSF (Street Side Front)	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
32,000 - Engine Inspection	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	190 Degree Fahrenheit		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
32,100 - INSPECT_Intake System	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12 Volt*		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
33,000 - CSF (Curb Side Front)	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
33,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
33,050 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
33,060 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	12 Volt*		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
40,700 - CHECK_Passenger Stop Request System	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
50,400 - LUBE_All Chassis Components	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,500 - !FRA!CHANGE_Engine oil,filters	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
50,700 - INSPECT_Tire Condition	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done	need rotate	HPIERRE	Apr 19, 2023 7:57:29 AM	Yes	56634077
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	7 32nds of an inch		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	20 Inch		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	20 Inch		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
52,100 - INSPECT_Vibration Damper	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
53,600 - INSPECT_Tire Condition	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	22 Inch		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	22 Inch		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
60,100 - RECORD_Wheelchair Cycle Count	33352 Cycles		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		HPIERRE	Apr 19, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				7:57:29 AM		
62,400 - INSPECT_All Pivot Points	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
62,500 - INSPECT_Cams and Slots	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
62,600 - INSPECT_Rollers	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
62,700 - INSPECT_All Linkages	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		HPIERRE	Apr 19, 2023 7:57:29 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	2.51
Labor:	141.70
Labor Hours:	2.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**144.21**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56255196
Invoice No. 55345 - 56255196

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-MEDIUM DUTY PMA		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	283,956 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Apr-23	Pierre,Hubert J	0.37	65	24.05

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: HPIERRE Performed on: 19-APR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Apr 19, 2023 7:37:06 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Apr 19, 2023 7:37:06 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Apr 19, 2023 7:37:06 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Apr 19, 2023 7:37:06 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Apr 19, 2023 7:37:06 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Apr 19, 2023 7:37:06 AM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	Done		HPIERRE	Apr 19, 2023 7:37:06 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Apr 19, 2023 7:37:06 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Apr 19, 2023 7:37:06 AM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	0.00
	Labor:	24.05
	Labor Hours:	0.37
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**24.05**

Work Order Footer

Work Order 56255196 Total	
Parts:	2.51
Labor:	165.75
Labor Hours:	2.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**168.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56608747
Invoice No. 55345 - 56608747

Client Department:
Department: 55345M
Work Order Description
BLOWER MOTOR NOT BLOWING ON ANY MODE. LOST POWER
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 283,157 - DH

Chronology		
Reported	Apr 11, 2023 5:35:00 PM	Apr 11, 2023 5:35:00 PM
Started		
Completed	Apr 11, 2023 5:41:10 PM	Apr 11, 2023 5:41:10 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: BLOWER MOTOR NOT BLOWING ON ANY MODE. LOST POWER

Cause: WEAR AND TEARS

Correction: REPLACE BLOWER MOTOR
PARTS# MM840 QTY1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 11-APR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		CKARLENS	Apr 11, 2023 5:40:17 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		CKARLENS	Apr 11, 2023 5:40:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
4 - Are you wearing the appropriate PPE?	Done		CKARLENS	Apr 11, 2023 5:40:17 PM	No	
7 - Have you performed the proper LOTO?	Done		CKARLENS	Apr 11, 2023 5:40:17 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		CKARLENS	Apr 11, 2023 5:40:17 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Apr 11, 2023 5:40:17 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56608747
Invoice No. 55345 - 56608747

Client Department:
Department: 55345M
Work Order Description
BLOWER MOTOR NOT BLOWING ON ANY MODE. LOST POWER
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 283,157 - DH

Activity Header
Activity: 15 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: BLOWER MOTOR NOT BLOWING ON ANY MODE. LOST POWER
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Apr-23	MM840	MOTOR, BLOWER, HVAC	1	41.16	41.16

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	41.16
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**41.16**

Work Order Footer

Work Order 56608747 Total	
Parts:	41.16
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**41.16**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56550372
Invoice No. 55345 - 56550372

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Scheduled		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	281,262 - DH

Chronology		
Reported	Mar 28, 2023 11:05:44 PM	Mar 28, 2023 11:05:44 PM
Started	Mar 28, 2023 11:08:00 PM	
Completed	Mar 29, 2023 5:27:00 PM	Mar 29, 2023 5:27:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:Harsh shifting

Cause: Transmission Overfilled

Correction:Transmission fluid level adjusted

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 29-MAR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		FSIMON	Mar 29, 2023 5:24:27 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		FSIMON	Mar 29, 2023 5:24:27 PM	No	
4 - Are you wearing the appropriate PPE?	Done		FSIMON	Mar 29, 2023 5:24:27 PM	No	
7 - Have you performed the proper LOTO?	Done		FSIMON	Mar 29, 2023 5:24:27 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		FSIMON	Mar 29, 2023 5:24:27 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Mar 29, 2023 5:24:27 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56550372
Invoice No. 55345 - 56550372

Client Department:
Department: 55345M
Work Order Description
Scheduled
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 281,262 - DH

Activity Header
Activity: 15 027 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: HARSH SHIFTING
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Mar-23	Fritz Simon	0.87	65	56.55
29-Mar-23	Fritz Simon	0.95	65	61.75

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	118.30
Labor Hours:	1.82
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**118.30**

Work Order Footer

Work Order 56550372 Total	
Parts:	0.00
Labor:	118.30
Labor Hours:	1.82
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**118.30**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56546920
Invoice No. 55345 - 56546920

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Scheduled		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	281,052 - DH

Chronology		
Reported	Mar 28, 2023 12:46:42 AM	Mar 28, 2023 12:46:42 AM
Started	Mar 28, 2023 12:51:00 AM	
Completed	Mar 28, 2023 1:40:00 AM	Mar 28, 2023 1:40:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:Wiper fluid reservoir empty

Cause: Reservoir hose leaking

Correction:Hose repaired

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 28-MAR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		FSIMON	Mar 28, 2023 1:40:20 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		FSIMON	Mar 28, 2023 1:40:20 AM	No	
4 - Are you wearing the appropriate PPE?	Done		FSIMON	Mar 28, 2023 1:40:20 AM	No	
7 - Have you performed the proper LOTO?	Done		FSIMON	Mar 28, 2023 1:40:20 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		FSIMON	Mar 28, 2023 1:40:20 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Mar 28, 2023 1:40:20 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56546920
Invoice No. 55345 - 56546920

Client Department:
Department: 55345M
Work Order Description
Scheduled
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 281,052 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note: WASHER FLUID RESERVOIR LEAKING
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Mar-23	Fritz Simon	0.8	65	52

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	52.00
Labor Hours:	0.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**52.00**

Work Order Footer

Work Order 56546920 Total	
Parts:	0.00
Labor:	52.00
Labor Hours:	0.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**52.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56482436
Invoice No. 55345 - 56482436

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Check battery		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	280,068 - DH

Chronology		
Reported	Mar 7, 2023 1:26:14 PM	Mar 7, 2023 1:26:14 PM
Started	Mar 7, 2023 1:28:00 PM	
Completed	Mar 7, 2023 5:41:00 PM	Mar 7, 2023 5:41:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Vehicle came to for BATTERY ISSUE

Cause: BATTERY NOT GOOD

Correction: REMOVED AND REPLACE TWO BATTERY ONE NEW AND A GOOD USED ONE TO UNIT NOW CRANKING PERFECT Line 20 Replace new pendant control switch to lift now workin asdesign return unit back to work

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 07-MAR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Mar 7, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				5:39:45 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Mar 7, 2023 5:39:45 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Mar 7, 2023 5:39:45 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Mar 7, 2023 5:39:45 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Mar 7, 2023 5:39:45 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Mar 7, 2023 5:39:45 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56482436
Invoice No. 55345 - 56482436

Client Department:
Department: 55345M
Work Order Description
Check battery
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 280,068 - DH

Activity Header
Activity: 15 020 GROUP, DRIVETRAIN
Activity Note: Check battery
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Mar-23	ER65850-COR	CORE, BATTERY, GROUP-65, 850CCA, 150MIN RESERVE	-1	22.5	-22.5
07-Mar-23	ER65850-COR	CORE, BATTERY, GROUP-65, 850CCA, 150MIN RESERVE	1	22.5	22.5
07-Mar-23	33659KS	PENDANT, CONTROL, W/C, BRAUN	1	205.02	205.02

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Mar-23	Junior Hurst	4.2	65	273

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	205.02
Labor:	273.00
Labor Hours:	4.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**478.02**

Work Order Footer

Work Order 56482436 Total	
Parts:	205.02
Labor:	273.00
Labor Hours:	4.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**478.02**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 11

Work Order No. 56255191
Invoice No. 55345 - 56255191

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	280,068 - DH

Chronology		
Reported	Dec 25, 2022 6:23:13 PM	Dec 25, 2022 6:23:13 PM
Started	Dec 25, 2022 12:00:00 AM	
Completed	Jan 18, 2023 12:19:00 PM	Jan 18, 2023 12:19:00 PM
Down Time		

Work Order Notes

Line 10 Replaced front brakes
dismounted and mounted 4 new tires in the rear end
Replaced wiper blades....
replaced parking lights Line 20 CHANGE REAR MORE RIDE PART # DSR108-075 Line 30 CHANGE STEERING GEARS PART # 27-7632 unit now working asdesign job complete Line 40 UNIT SENT TO ELPEX GOOD YEAR WHEEL ALIGNAMENT WAS PERFORMED

Activity Header
Activity: 10 002/035/059 HARDWARE, MOUNTING, ARM, WIPER, WINDSHIELD, APFI - 002-035-016
Activity Note: Winshield Washer line leaks
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Dec-22	Delva,Terry	0.77	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 11

Work Order No. 56255191
Invoice No. 55345 - 56255191

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	280,068 - DH

Activity Header
Activity:20 013/003/002 HARDWARE, MOUNTING, LEVER, PEDAL& SECTOR, BRAKE, PARKING APFI - 013-003-001
Activity Note: Vehicle come out of park while e-brake apply
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Dec-22	277632	BOX, GEAR, STEERING, POWER, REMANUFACTURED	1	117.59	117.59

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	117.59
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**117.59**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 11

Work Order No. 56255191
Invoice No. 55345 - 56255191

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	280,068 - DH

Activity Header
Activity: 30 174/024/001 HARNESS, WIRING, BODY, BUS, MAIN
Activity Note: under dash wire need to be secure
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 11

Work Order No. 56255191
Invoice No. 55345 - 56255191

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	280,068 - DH

Activity Header
Activity:40 002/035/015 BLADE, WIPER
Activity Note: Wiper blades
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Dec-22	40520	BLADE, WIPER, WINDSHIELD, 20"	1	4.07	4.07
27-Dec-22	40526	BLADE, WIPER, WINDSHIELD	1	4.79	4.79
27-Dec-22	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	63.59	63.59

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Dec-22	Delva,Terry	0.25	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	72.45
Labor:	0.00
Labor Hours:	0.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**72.45**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 11

Work Order No. 56255191
Invoice No. 55345 - 56255191

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	280,068 - DH

Activity Header
Activity: 50 174/032/066 RESTRAINT, OCCUPANT, TIE-DOWN, WHEELCHAIR
Activity Note: Floor hold downs.
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 50 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 6 of 11

Work Order No. 56255191
Invoice No. 55345 - 56255191

Client Department:

Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	280,068 - DH

Activity Header
Activity: 60 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: Front brakes
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Dec-22	Delva,Terry	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 60 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 7 of 11

Work Order No. 56255191
Invoice No. 55345 - 56255191

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	280,068 - DH

Activity Header
Activity: 70 017/009/016 VALVE, PROTECTION, PRESSURE, TIRE
Activity Note: Rear Left tires
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Dec-22	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	4	150	600

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Dec-22	Delva,Terry	2.45	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 70 Sub Total	
Parts:	600.00
Labor:	0.00
Labor Hours:	2.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**600.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 8 of 11

Work Order No. 56255191
Invoice No. 55345 - 56255191

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	280,068 - DH

Activity Header
Activity: 80 016/008/064 KIT, SUSPENSION, AIR
Activity Note: Right rear rubber mount
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Jan-23	DSR108-075	RUBBER, SPRING, SHEAR, RUBBER, REAR, MOR/RYDE	1	192.39	192.39

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Jan-23	Junior Hurst	2.9	65	188.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 80 Sub Total	
Parts:	192.39
Labor:	188.50
Labor Hours:	2.90
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**380.89**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 9 of 11

Work Order No. 56255191
Invoice No. 55345 - 56255191

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	280,068 - DH

Activity Header
Activity: 90 174 BODY, BUS
Activity Note: Lift jerky
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 90 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 10 of 11

Work Order No. 56255191
Invoice No. 55345 - 56255191

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	280,068 - DH

Activity Header
Activity: 100 015/003/000 GEAR, STEERING, RACK & PINION
Activity Note: Gear Box
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Jan-23	Junior Hurst	4.72	65	306.8

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 100 Sub Total	
Parts:	0.00
Labor:	306.80
Labor Hours:	4.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**306.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 11 of 11

Work Order No. 56255191
Invoice No. 55345 - 56255191

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	280,068 - DH

Activity Header
Activity: 110 015 STEERING
Activity Note: UNIT SENT ELPEX GOOD YEAR WHEEL ALIGNAMENT WAS PERFORMED
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet

PO No.	ACD Code	Supplier No.	SUPPLIER	Order Date	Received Value
4627762	177,256,772	72882	MIAMI TIRESOLES, ELPEX,FL,DEERFIELD BEACH,dba MIAMI TIRESOLES ELPEX	Jan 23, 2023 12:00:00 AM	125

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 110 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	125.00
Sublet Labor:	0.00
Activity Sub Total	**125.00**

Work Order Footer

Work Order 56255191 Total	
Parts:	982.43
Labor:	495.30
Labor Hours:	13.09
Sublet Parts:	125.00
Sublet Labor:	0.00
Activity Sub Total	**1,602.73**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56195702
Invoice No. 55345 - 56195702

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-MEDIUM DUTY PMB		Ford E450 Champion Challenger	
Requested By:	SPACE	**Status:**	40 - Closed (40)
Created By:	SPACE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	280,068 - DH

Chronology		
Reported	Dec 23, 2022 12:00:00 AM	Dec 23, 2022 12:00:00 AM
Started	Dec 25, 2022 2:03:00 PM	
Completed	Dec 25, 2022 6:34:00 PM	Dec 25, 2022 6:34:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: PMB

cause: service due

Correction: Performed and completed PMB

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 25-DEC-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Dec 25, 2022 2:36:02 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Dec 25, 2022 2:36:02 PM	No	
4 - Are you wearing the appropriate PPE?	Done		TDELVA	Dec 25, 2022 2:36:02 PM	No	
7 - Have you performed the proper LOTO?	Done		TDELVA	Dec 25, 2022 2:36:02 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Dec 25, 2022 2:36:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Dec 25, 2022 2:36:02 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56195702
Invoice No. 55345 - 56195702

Client Department:
Department: 55345M
Work Order Description
55345-MEDIUM DUTY PMB
Requested By: SPACE
Created By: SPACE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 280,068 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Dec-22	Delva,Terry	2.67	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: TDELVA Performed on: 25-DEC-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
10,800 - CHECK_All Destination Signage	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
20,200 - CHECK_Public Address System	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	0 Second*		TDELVA	Dec 25, 2022 6:24:53 PM	No	
20,700 - RECORD_Brake Performance Test Speed	0 Miles per Hour		TDELVA	Dec 25, 2022 6:24:53 PM	No	
20,800 - RECORD_Brake Performance Test Distance	0 FEET		TDELVA	Dec 25, 2022 6:24:53 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	0 FEET		TDELVA	Dec 25, 2022 6:24:53 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	0 Gravitational Force		TDELVA	Dec 25, 2022 6:24:53 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done	Winshield Washer line leaks	TDELVA	Dec 25, 2022 6:24:53 PM	Yes	56255191
21,500 - INSPECT_High Idle Control	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done	Vehicle come out of park while e-brake apply	TDELVA	Dec 25, 2022 6:24:53 PM	Yes	56255191
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done	under dash wire need to be secure	TDELVA	Dec 25, 2022 6:24:53 PM	Yes	56255191
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
31,000 - SSF (Street Side Front)	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done	Wiper blades	TDELVA	Dec 25, 2022 6:24:53 PM	Yes	56255191
32,000 - Engine Inspection	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,010 - INSPECT_Hood, Springs and Props	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done	Power steering leaks	TDELVA	Dec 25, 2022 6:24:53 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	0 Degree Fahrenheit		TDELVA	Dec 25, 2022 6:24:53 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
32,100 - INSPECT_Intake System	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	0 Volt*		TDELVA	Dec 25, 2022 6:24:53 PM	No	
33,000 - CSF (Curb Side Front)	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
33,050 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
33,060 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	13.5 Volt*		TDELVA	Dec 25, 2022 6:24:53 PM	No	
33,060 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	13.8 Volt*		TDELVA	Dec 25, 2022 6:24:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
40,700 - CHECK_Passenger Stop Request System	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done	Floor hold downs.	TDELVA	Dec 25, 2022 6:24:53 PM	Yes	56255191
41,200 - INSPECT_CLEAN_AC Filter	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
50,100 - *RPT*INSPECT_Steering components- Drag Link, Tie Rods ends and Steering Damper	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,200 - INSPECT_Ball Joint Play	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
50,400 - LUBE_All Chassis Components	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
50,700 - INSPECT_Tire Condition	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		TDELVA	Dec 25, 2022 6:24:53 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		TDELVA	Dec 25, 2022 6:24:53 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		TDELVA	Dec 25, 2022 6:24:53 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		TDELVA	Dec 25, 2022 6:24:53 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch	Front brakes	TDELVA	Dec 25, 2022 6:24:53 PM	Yes	56255191
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch		TDELVA	Dec 25, 2022 6:24:53 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	36.8 Inch		TDELVA	Dec 25, 2022 6:24:53 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	36.8 Inch		TDELVA	Dec 25, 2022 6:24:53 PM	No	
52,100 - INSPECT_Vibration Damper	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
53,600 - INSPECT_Tire Condition	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	-	na	TDELVA	Dec 25, 2022 6:24:53 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	9 32nds of an inch		TDELVA	Dec 25, 2022 6:24:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	9 32nds of an inch		TDELVA	Dec 25, 2022 6:24:53 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		TDELVA	Dec 25, 2022 6:24:53 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		TDELVA	Dec 25, 2022 6:24:53 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	3 32nds of an inch	Rear Left tires	TDELVA	Dec 25, 2022 6:24:53 PM	Yes	56255191
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	4 32nds of an inch		TDELVA	Dec 25, 2022 6:24:53 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		TDELVA	Dec 25, 2022 6:24:53 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		TDELVA	Dec 25, 2022 6:24:53 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	Dec 25, 2022 6:24:53 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	Dec 25, 2022 6:24:53 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	38.6 Inch		TDELVA	Dec 25, 2022 6:24:53 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	38.6 Inch		TDELVA	Dec 25, 2022 6:24:53 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done	Right rear rubber mount	TDELVA	Dec 25, 2022 6:24:53 PM	Yes	56255191

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,000 - SECTION 6 - Wheelchair Inspection	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	16357 Cycles		TDELVA	Dec 25, 2022 6:24:53 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done	Lift jerky	TDELVA	Dec 25, 2022 6:24:53 PM	Yes	56255191
60,500 - INSPECT_ Bridgeplate Operation	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
61,900 - CLEAN_Linkages and Mechanisms	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
62,400 - INSPECT_All Pivot Points	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
62,500 - INSPECT_Cams and Slots	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
62,600 - INSPECT_Rollers	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
62,700 - INSPECT_All Linkages	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		TDELVA	Dec 25, 2022 6:24:53 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56195702
Invoice No. 55345 - 56195702

Client Department:
Department: 55345M
Work Order Description
55345-MEDIUM DUTY PMB
Requested By: SPACE
Created By: SPACE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 280,068 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMB Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Dec-22	B329	FILTER, OIL, SPIN-ON SEE P550965	1	3.05	3.05

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Dec-22	Delva,Terry	1.68	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	3.05
Labor:	0.00
Labor Hours:	1.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**3.05**

Work Order Footer

Work Order 56195702 Total	
Parts:	3.05
Labor:	0.00
Labor Hours:	4.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**3.05**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56175660
Invoice No. 55345 - 56175660

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Brakes)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 99 - Cancelled (99)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 277,961 - DH

Chronology		
Reported	Nov 29, 2022 5:37:00 PM	Nov 29, 2022 5:37:00 PM
Started	Nov 29, 2022 5:38:00 PM	
Completed	Dec 15, 2022 4:55:48 PM	Dec 15, 2022 4:55:48 PM
Down Time		

Work Order Notes

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	-				No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	-				No	
4 - Are you wearing the appropriate PPE?	-				No	
7 - Have you performed the proper LOTO?	-				No	
10 - Are you aware of the potential risks of performing this repair?	-				No	
11 - Have you successfully completed the Personal Risk Assessment?	-				No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56175660
Invoice No. 55345 - 56175660

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345 PER DVIR (Check Brakes)		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	99 - Cancelled (99)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	277,961 - DH

Activity Header
Activity: 20 013/001/029 PADS, BRAKE, DISC, FRONT
Activity Note: Check Brakes
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 56175660 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56179339
Invoice No. 55345 - 56179339

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Rear AC)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 277,961 - DH

Chronology		
Reported	Nov 30, 2022 6:09:00 PM	Nov 30, 2022 6:09:00 PM
Started	Nov 30, 2022 6:10:00 PM	
Completed	Nov 30, 2022 11:47:00 PM	Nov 30, 2022 11:47:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: Check rear AC .

Cause: Unknown.

Correction: Let vehicle idle for an hour with rear AC on, could not duplicate any issues. Will monitor.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 30-NOV-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Nov 30, 2022 9:32:37 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Nov 30, 2022 9:32:37 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Nov 30, 2022 9:32:37 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Nov 30, 2022 9:32:37 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Nov 30, 2022 9:32:37 PM	No	
11 - Have you successfully completed the	Done		EARJOHNSON	Nov 30, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				9:32:37 PM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56179339
Invoice No. 55345 - 56179339

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Rear AC)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 277,961 - DH

Activity Header
Activity: 20 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Check Rear AC
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Nov-22	Earl Johnson	0.67	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 56179339 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56164632
Invoice No. 55345 - 56164632

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
front A/C issue		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	277,961 - DH

Chronology		
Reported	Nov 24, 2022 9:44:26 AM	Nov 24, 2022 9:44:26 AM
Started	Nov 24, 2022 9:58:00 AM	
Completed	Nov 24, 2022 2:30:00 PM	Nov 24, 2022 2:30:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Vehicle came in for front A/C issue

Cause: EVAPORATOR LEAKING

Correction: REMOVE AND REPLACED NEW ONE PART #6C2Z-19860 ALSO ORIFICE 3411885. unit working asdesign return vehicle back to work

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 24-NOV-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Nov 24, 2022 2:28:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Nov 24, 2022 2:28:12 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Nov 24, 2022 2:28:12 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Nov 24, 2022 2:28:12 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Nov 24, 2022 2:28:12 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Nov 24, 2022 2:28:12 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56164632
Invoice No. 55345 - 56164632

Client Department:
Department: 55345M
Work Order Description
front A/C issue
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 277,961 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: FRONT A/C ISSUE
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Nov-22	6C2Z-19860-C	CORE, EVAPORATOR, A/C	1	90.5	90.5
24-Nov-22	3411885	TUBE, ORIFICE, A/C, FORD	1	0.77	0.77

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Nov-22	Junior Hurst	4.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	91.27
Labor:	0.00
Labor Hours:	4.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**91.27**

Work Order Footer

Work Order 56164632 Total	
Parts:	91.27
Labor:	0.00
Labor Hours:	4.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**91.27**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56137310
Invoice No. 55345 - 56137310

Client Department:
Department: 55345M
Work Order Description
PER DRIVER HEAT COMING OUT DOUG HOUSE
Requested By: RRENE
Created By: RRENE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 277,236 - DH

Chronology		
Reported	Nov 15, 2022 10:36:00 AM	Nov 15, 2022 10:36:00 AM
Started	Nov 15, 2022 11:21:00 AM	
Completed	Nov 15, 2022 12:45:00 PM	Nov 15, 2022 12:45:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:per driver heat coming out doug house

Cause: nothing found

Correction: test drive bus no haet coming at the doug house completed

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 15-NOV-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Nov 15, 2022 12:41:57 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Nov 15, 2022 12:41:57 PM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Nov 15, 2022 12:41:57 PM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Nov 15, 2022 12:41:57 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Nov 15, 2022 12:41:57 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Nov 15, 2022 12:41:57 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56137310
Invoice No. 55345 - 56137310

Client Department:
Department: 55345M
Work Order Description
PER DRIVER HEAT COMING OUT DOUG HOUSE
Requested By: RRENE
Created By: RRENE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 277,236 - DH

Activity Header
Activity: 15 053/004/000 SAFETY EQUIPMENT
Activity Note: PER DRIVER HEAT COMING OUT DOUG HOUSE
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Nov-22	Pierre,Hubert J	1.27	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 56137310 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 5

Work Order No. 55977009
Invoice No. 55345 - 55977009

Client Department:
Department: 55345M
Work Order Description
check batteries and charging system & wheel chair lift
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 276,437 - DH

Chronology		
Reported	Sep 23, 2022 8:56:00 AM	Sep 23, 2022 8:56:00 AM
Started	Nov 3, 2022 2:40:00 PM	
Completed	Nov 3, 2022 5:01:00 PM	Nov 3, 2022 5:01:00 PM
Down Time		

Work Order Notes

Line 10 VEHICLE CAME TO SHOP FOR BATTERY ISSUE CHECK AND FOUND BATTERY NOT GOOD REMOVED AND REPLACED TWO NEW DIE HARD TO VEHICLE. PLACE FINE THE RIGHT PART # AND GHARGE IT OUT FOR ME TANK YOU Line 20 BATTERIES PROVIDED UNDER WARRANTY

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 03-NOV-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Nov 3, 2022 4:59:25 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Nov 3, 2022 4:59:25 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Nov 3, 2022 4:59:25 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Nov 3, 2022 4:59:25 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Nov 3, 2022 4:59:25 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Nov 3, 2022 4:59:25 PM	No	

Activity Sub Total

	Activity 10 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 5

Work Order No. 55977009
Invoice No. 55345 - 55977009

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
check batteries and charging system & wheel chair lift		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	276,437 - DH

Activity Header
Activity: 20 174/024/017 LAMP, CEILING, BUS
Activity Note: CHECK INSTRUMENT CLUSTER LIGHT OPERATION
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 5

Work Order No. 55977009
Invoice No. 55345 - 55977009

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
check batteries and charging system & wheel chair lift		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	276,437 - DH

Activity Header
Activity: 30 055/023/000 LIFT, WHEELCHAIR, PASSENGER
Activity Note: CHECK WHEEL CHAIR LIFT FOR PROPER OPERATION
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 5

Work Order No. 55977009
Invoice No. 55345 - 55977009

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
check batteries and charging system & wheel chair lift		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	276,437 - DH

Activity Header
Activity: 40 999 TOTAL VEHICLE
Activity Note: road test unit
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 5

Work Order No. 55977009
Invoice No. 55345 - 55977009

Client Department:
Department: 55345M
Work Order Description
check batteries and charging system & wheel chair lift
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 276,437 - DH

Activity Header
Activity: 50 010 CHASSIS GROUP
Activity Note: vehicle in shop for battery test
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Nov-22	Junior Hurst	2.33	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 50 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55977009 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55968595
Invoice No. 55345 - 55968595

Client Department:
Department: 55345M
Work Order Description
Road Call (Crank No Start)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 276,372 - DH

Chronology		
Reported	Sep 20, 2022 4:33:00 PM	Sep 20, 2022 4:33:00 PM
Started	Sep 20, 2022 4:34:00 PM	
Completed	Sep 20, 2022 6:49:00 PM	Sep 20, 2022 6:49:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:driver complaint bus shut off on the road

Cause: Check the bus no problem found

Correction:switch the bus, drive the bus from west palm Beach to base never shut off.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 20-SEP-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Sep 20, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				6:35:49 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Sep 20, 2022 6:35:49 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RGASPARD	Sep 20, 2022 6:35:49 PM	No	
7 - Have you performed the proper LOTO?	Done		RGASPARD	Sep 20, 2022 6:35:49 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Sep 20, 2022 6:35:49 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Sep 20, 2022 6:35:49 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55968595
Invoice No. 55345 - 55968595

Client Department:
Department: 55345M
Work Order Description
Road Call (Crank No Start)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 276,372 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL (Crank No Start)
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Sep-22	Gaspard,Ronald	2.18	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55968595 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 5

Work Order No. 55946988
Invoice No. 55345 - 55946988

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
SERPENTINE BELT BROKE		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	276,251 - DH

Chronology		
Reported	Sep 13, 2022 1:42:00 PM	Sep 13, 2022 1:42:00 PM
Started	Sep 13, 2022 3:18:00 PM	
Completed	Sep 16, 2022 3:59:00 PM	Sep 16, 2022 3:59:00 PM
Down Time		

Work Order Notes

Line 10 complaints: vehicle overheated

cause: broken belt broken Tensioner seized front compressor

Correction: Installed new front compressor
Installed new high pressure hose
used engine belt... idler pulleys.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 16-SEP-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Sep 16, 2022 3:59:25 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Sep 16, 2022 3:59:25 PM	No	
4 - Are you wearing the appropriate PPE?	Done		TDELVA	Sep 16, 2022 3:59:25 PM	No	
7 - Have you performed the proper LOTO?	Done		TDELVA	Sep 16, 2022 3:59:25 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Sep 16, 2022 3:59:25 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Sep 16, 2022 3:59:25 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 5

Work Order No. 55946988
Invoice No. 55345 - 55946988

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
SERPENTINE BELT BROKE		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	276,251 - DH

Activity Header
Activity: 20 045/000 POWER PLANT
Activity Note: SERPENTINE BELT BROKE AT FUEL STATION
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Sep-22	Delva,Terry	1.65	0	0
13-Sep-22	Delva,Terry	1.57	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 5

Work Order No. 55946988
Invoice No. 55345 - 55946988

Client Department:
Department: 55345M
Work Order Description
SERPENTINE BELT BROKE
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 276,251 - DH

Activity Header
Activity: 30 001/001/002 COMPRESSOR, A/C
Activity Note: FRONT AC COMPRESSOR SEIZED
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Sep-22	6512376	COMPRESSOR, A/C, NEW	1	200.14	200.14
14-Sep-22	GC2Z-19C836-C	ACCUMULATOR, A/C, E450	1	95.2	95.2

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Sep-22	Delva,Terry	4.28	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	295.34
Labor:	0.00
Labor Hours:	4.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**295.34**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 5

Work Order No. 55946988
Invoice No. 55345 - 55946988

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
SERPENTINE BELT BROKE		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	276,251 - DH

Activity Header
Activity: 40 042/003/008 PULLEY, IDLER, DRIVEN, FAN
Activity Note: INSPECT SERPENTINE BELT TENSIONER AND IDLE PULLEYS
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Sep-22	89263	TENSIONER, BELT, SERPENTINE	1	31.37	31.37
15-Sep-22	89026	PULLEY, IDLER, SMOOTH	1	12.09	12.09
14-Sep-22	3411885	TUBE, ORIFICE, A/C, FORD	1	0.77	0.77

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Sep-22	Delva,Terry	0.82	0	0
16-Sep-22	Delva,Terry	5.3333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	44.23
Labor:	0.00
Labor Hours:	6.15
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**44.23**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 5

Work Order No. 55946988
Invoice No. 55345 - 55946988

Client Department:
Department: 55345M
Work Order Description
SERPENTINE BELT BROKE
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 276,251 - DH

Activity Header
Activity: 50 001/001 AIR CONDITIONING
Activity Note: discharge hose broke
Reason for Repair: 01 Breakdown
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Sep-22	CC2Z-19972-A	MANIFOLD, DISCHARGE, A/C	1	122.44	122.44

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Sep-22	Delva,Terry	2.5166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 50 Sub Total	
Parts:	122.44
Labor:	0.00
Labor Hours:	2.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**122.44**

Work Order Footer

Work Order 55946988 Total	
Parts:	462.01
Labor:	0.00
Labor Hours:	16.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**462.01**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55812645
Invoice No. 55345 - 55812645

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	275,288 - DH

Chronology		
Reported	Sep 2, 2022 12:00:00 AM	Sep 2, 2022 12:00:00 AM
Started	Sep 7, 2022 4:18:00 PM	
Completed	Sep 8, 2022 12:11:00 AM	Sep 8, 2022 12:11:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA

CAUSE:Service

CORRECTION:Perform PMA Service
oil filter B329 qty1
engine oil 10w30 qty 7qts
add washer fluid
check inflate tires to spec
air filter PA4075 qty1

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 07-SEP-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Sep 7, 2022 9:58:09 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Sep 7, 2022 9:58:09 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RGASPARD	Sep 7, 2022 9:58:09 PM	No	
7 - Have you performed the proper LOTO?	Done		RGASPARD	Sep 7, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:58:09 PM		
10 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Sep 7, 2022 9:58:09 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Sep 7, 2022 9:58:09 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55812645
Invoice No. 55345 - 55812645

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	275,288 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Sep-22	B329	FILTER, OIL, SPIN-ON SEE P550965	1	7.57	7.57
07-Sep-22	PA4075	FILTER, AIR SEE P546597	1	6.69	6.69

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Sep-22	Gaspard,Ronald	1.8	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 07-SEP-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
20,800 - INSPECT_High Idle Control	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	Sep 7, 2022 11:27:02 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Sep 7, 2022 11:27:02 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
33,010 - CSF (Curb Side Front)	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	RGASPARD	Sep 7, 2022 11:27:02 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
40,250 - INSPECT_Overhead Compartment for Water	Done		RGASPARD	Sep 7, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Leaks				11:27:02 PM		
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
50,400 - LUBE_All Chassis Components	Done	na	RGASPARD	Sep 7, 2022 11:27:02 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	37 Inch		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	37 Inch		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Sep 7, 2022 11:27:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	39 Inch		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	39 Inch		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	11243 Cycles		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
60,800 - INSPECT_Operation of Platform Barrier	Done		RGASPARD	Sep 7, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Mechanism				11:27:02 PM		
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Sep 7, 2022 11:27:02 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	14.26
Labor:	0.00
Labor Hours:	1.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**14.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55812645
Invoice No. 55345 - 55812645

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 275,288 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Sep-22	Gaspard,Ronald	0.15	0	0
07-Sep-22	Gaspard,Ronald	0.22	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 07-SEP-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Sep 7, 2022 11:48:09 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Sep 7, 2022 11:48:09 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Sep 7, 2022 11:48:09 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Sep 7, 2022 11:48:09 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Sep 7, 2022 11:48:09 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Sep 7, 2022 11:48:09 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Sep 7, 2022 11:48:09 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Sep 7, 2022 11:48:09 PM	No	

Activity Sub Total

Activity 20 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.37
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

	Work Order 55812645 Total	
	Parts:	14.26
	Labor:	0.00
	Labor Hours:	2.17
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**14.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55907130
Invoice No. 55345 - 55907130

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
driver side mirror broke		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	274,462 - DH

Chronology		
Reported	Sep 1, 2022 1:06:00 PM	Sep 1, 2022 1:06:00 PM
Started	Sep 1, 2022 1:18:00 PM	
Completed	Sep 1, 2022 1:49:00 PM	Sep 1, 2022 1:49:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: driver side mirror broke

Cause: driver abuse

Correction:replaced driver side mirror completed

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 01-SEP-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Sep 1, 2022 1:49:06 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Sep 1, 2022 1:49:06 PM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Sep 1, 2022 1:49:06 PM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Sep 1, 2022 1:49:06 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Sep 1, 2022 1:49:06 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Sep 1, 2022 1:49:06 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55907130
Invoice No. 55345 - 55907130

Client Department:
Department: 55345M
Work Order Description
driver side mirror broke
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 274,462 - DH

Activity Header
Activity: 15 053/004/000 SAFETY EQUIPMENT
Activity Note: driver side mirror broke
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Sep-22	709770	PIVOT, HOUSING, GLASS, UPPER	1	31.75	31.75

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Sep-22	Pierre,Hubert J	0.52	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	31.75
Labor:	0.00
Labor Hours:	0.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**31.75**

Work Order Footer

Work Order 55907130 Total	
Parts:	31.75
Labor:	0.00
Labor Hours:	0.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**31.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55854844
Invoice No. 55345 - 55854844

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
WINDSHIELD WIPERS NOT MOVING		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	271,866 - DH

Chronology		
Reported	Aug 15, 2022 7:13:00 AM	Aug 15, 2022 7:13:00 AM
Started	Aug 15, 2022 12:00:00 AM	
Completed	Aug 15, 2022 8:53:00 AM	Aug 15, 2022 8:53:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: windshield wipers not moving

Cause: the linkage was broken

Correction: replaced the windshield linkage wiper Ok

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 15-AUG-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Aug 15, 2022 8:51:31 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Aug 15, 2022 8:51:31 AM	No	
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Aug 15, 2022 8:51:31 AM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Aug 15, 2022 8:51:31 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Aug 15, 2022 8:51:31 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Aug 15, 2022 8:51:31 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55854844
Invoice No. 55345 - 55854844

Client Department:
Department: 55345M
Work Order Description
WINDSHIELD WIPERS NOT MOVING
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 271,866 - DH

Activity Header
Activity: 15 002/035 WIPER & WASHER, WINDSHIELD
Activity Note: WINDSHIELD WIPERS NOT MOVING
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Aug-22	1C2Z-17566-AA	LINKAGE, WIPER, WINDSHIELD	1	45.18	45.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Aug-22	NELSON PIERRE-LOUIS	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	45.18
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**45.18**

Work Order Footer

Work Order 55854844 Total	
Parts:	45.18
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**45.18**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55829976
Invoice No. 55345 - 55829976

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Check Wheel Chair Lift		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	271,288 - DH

Chronology		
Reported	Aug 4, 2022 5:46:00 PM	Aug 4, 2022 5:46:00 PM
Started	Aug 4, 2022 5:47:00 PM	
Completed	Aug 8, 2022 2:22:00 PM	Aug 8, 2022 2:22:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: WC lift malfunction.

Cause: BAD MAIN CIRCUIT BOARD

Correction: Remove and replaced main circuit board WITH A KNOWN USED GOOOD PART ,issue fixed, unit returned to service .

repair performed by tech Raul Rodriguez

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Aug-22	Rodriguez,Raul	2.4333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 08-AUG-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Aug 8, 2022 2:21:56 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Aug 8, 2022 2:21:56 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Aug 8, 2022 2:21:56 PM	No	
7 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Aug 8, 2022 2:21:56 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Aug 8, 2022 2:21:56 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Aug 8, 2022 2:21:56 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55829976
Invoice No. 55345 - 55829976

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Check Wheel Chair Lift		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	271,288 - DH

Activity Header
Activity: 15 055/023/000 LIFT, WHEELCHAIR, PASSENGER
Activity Note: Wheel Chair
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Aug-22	Earl Johnson	2.35	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55829976 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	4.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55812636
Invoice No. 55345 - 55812636

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	270,368 - DH

Chronology		
Reported	Jul 28, 2022 9:18:11 PM	Jul 28, 2022 9:18:11 PM
Started	Jul 28, 2022 9:19:00 PM	
Completed	Jul 29, 2022 12:30:00 AM	Jul 29, 2022 12:30:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========
To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.
==========

Complaint:needs rear AC filter and right rear inside tire flat

Cause: AC filter bad ,tire has a screw

Correction:replace AC filter . patch tire mount and balance
torque wheels 140 lbs second torque 140 lbs

Activity Header
Activity:10 001/001 AIR CONDITIONING
Activity Note: needs rear AC filter
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Jul-22	Gaspard,Ronald	0.45	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

	Activity 10 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.45
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55812636
Invoice No. 55345 - 55812636

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP-FT Light Duty
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 270,368 - DH

Activity Header
Activity:20 017/009/016 VALVE, PROTECTION, PRESSURE, TIRE
Activity Note: right rear inside flat
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Jul-22	Gaspard,Ronald	0.48	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55812636 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55696310
Invoice No. 55345 - 55696310

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	270,368 - DH

Chronology		
Reported	Jul 26, 2022 12:00:00 AM	Jul 26, 2022 12:00:00 AM
Started	Jul 28, 2022 3:53:00 PM	
Completed	Jul 28, 2022 9:28:00 PM	Jul 28, 2022 9:28:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA

CAUSE:Service

CORRECTION:Perform PMA Service
oil filter B329 qty1
engine oil 10w30 qty 7 qts
add washer fluid
washed batteries

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 28-JUL-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Jul 28, 2022 7:40:33 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Jul 28, 2022 7:40:33 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RGASPARD	Jul 28, 2022 7:40:33 PM	No	
7 - Have you performed the proper LOTO?	Done		RGASPARD	Jul 28, 2022 7:40:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Jul 28, 2022 7:40:33 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jul 28, 2022 7:40:33 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55696310
Invoice No. 55345 - 55696310

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	270,368 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Jul-22	Gaspard,Ronald	1.42	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 28-JUL-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Jul 28, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:04:44 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
20,800 - INSPECT_High Idle Control	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	na	RGASPARD	Jul 28, 2022 9:04:44 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Jul 28, 2022 9:04:44 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
33,010 - CSF (Curb Side Front)	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	RGASPARD	Jul 28, 2022 9:04:44 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		RGASPARD	Jul 28, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression				9:04:44 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done	needs rear AC filter	RGASPARD	Jul 28, 2022 9:04:44 PM	Yes	55812636
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
50,400 - LUBE_All Chassis Components	Done	na	RGASPARD	Jul 28, 2022 9:04:44 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	37 Inch		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	37 Inch		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Jul 28, 2022 9:04:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	35 Pounds per Square Inch	right rear inside flat	RGASPARD	Jul 28, 2022 9:04:44 PM	Yes	55812636
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	10845 Cycles		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
60,800 - INSPECT_Operation of Platform Barrier	Done		RGASPARD	Jul 28, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Mechanism				9:04:44 PM		
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Jul 28, 2022 9:04:44 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55696310
Invoice No. 55345 - 55696310

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	270,368 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Jul-22	B329	FILTER, OIL, SPIN-ON SEE P550965	1	2.19	2.19

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Jul-22	Gaspard,Ronald	0.35	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 28-JUL-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jul 28, 2022 9:07:07 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jul 28, 2022 9:07:07 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jul 28, 2022 9:07:07 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jul 28, 2022 9:07:07 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Jul 28, 2022 9:07:07 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jul 28, 2022 9:07:07 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Jul 28, 2022 9:07:07 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jul 28, 2022 9:07:07 PM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	2.19
	Labor:	0.00
	Labor Hours:	0.35
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**2.19**

Work Order Footer

Work Order 55696310 Total	
Parts:	2.19
Labor:	0.00
Labor Hours:	1.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.19**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55789907
Invoice No. 55345 - 55789907

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
WHEEL CHAIR LIFT		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	269,345 - DH

Chronology		
Reported	Jul 20, 2022 3:22:00 PM	Jul 20, 2022 3:22:00 PM
Started	Jul 21, 2022 7:24:00 AM	
Completed	Jul 21, 2022 9:12:00 AM	Jul 21, 2022 9:12:00 AM
Down Time		

Work Order Notes

Line 10 c. w/c. lift stop working

c. found wire damage at front outer barrier switch

c. removed and replaced switch, tested, all okay at this time.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 21-JUL-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Jul 21, 2022 9:11:24 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Jul 21, 2022 9:11:24 AM	No	
4 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Jul 21, 2022 9:11:24 AM	No	
7 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Jul 21, 2022 9:11:24 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Jul 21, 2022 9:11:24 AM	No	
11 - Have you successfully completed the	Done		RAURODRIGUEZ	Jul 21, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				9:11:24 AM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55789907
Invoice No. 55345 - 55789907

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
WHEEL CHAIR LIFT		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	269,345 - DH

Activity Header
Activity: 20 055/023/000 LIFT, WHEELCHAIR, PASSENGER
Activity Note: PER DRIVER CHECK WHEEL CHAIR LIFT
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Jul-22	400374AKS	SWITCH, BARRIER, OUTER, W/C, BRAUN	1	28.2	28.2

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jul-22	Rodriguez,Raul	1.63	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	28.20
Labor:	0.00
Labor Hours:	1.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**28.20**

Work Order Footer

Work Order 55789907 Total	
Parts:	28.20
Labor:	0.00
Labor Hours:	1.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**28.20**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55786645
Invoice No. 55345 - 55786645

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Left Head Light		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	269,227 - DH

Chronology		
Reported	Jul 19, 2022 4:05:36 PM	Jul 19, 2022 4:05:36 PM
Started	Jul 19, 2022 4:15:00 PM	
Completed	Jul 19, 2022 5:17:00 PM	Jul 19, 2022 5:17:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Left head Light

Cause: Bulb Blown

Correction: Remove & Replace Left Head Light Bulb.
parts #9008 Qty (1)

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 19-JUL-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jul 19, 2022 4:16:31 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jul 19, 2022 4:16:31 PM	No	
4 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jul 19, 2022 4:16:31 PM	No	
7 - Have you performed the proper LOTO?	Done		DARTHURS	Jul 19, 2022 4:16:31 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jul 19, 2022 4:16:31 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 19, 2022 4:16:31 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55786645
Invoice No. 55345 - 55786645

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Left Head Light		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	269,227 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Left head Light Out
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Jul-22	H13BP	BULB, HEADLAMP, HALOGEN	1	12.2	12.2

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Jul-22	Arthurs,Durvin	0.6	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	12.20
Labor:	0.00
Labor Hours:	0.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**12.20**

Work Order Footer

Work Order 55786645 Total	
Parts:	12.20
Labor:	0.00
Labor Hours:	0.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**12.20**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 55767527
Invoice No. 55345 - 55767527

Client Department:
Department: 55345M
Work Order Description
CHECK WHEEL CHAIR LIFT FOR PROPER OPERATION
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 268,767 - DH

Chronology		
Reported	Jul 12, 2022 3:19:00 PM	Jul 12, 2022 3:19:00 PM
Started	Jul 12, 2022 3:57:00 PM	
Completed	Jul 14, 2022 3:44:00 PM	Jul 14, 2022 3:44:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: WC lift malfunction.

Cause: WC lift handrail loose. Air in hydraulic system.

Correction: Tightened handrail set screws. Bled hydraulic system. Ran lift thru 5 consecutive cycles without any issues.

Line 20 Replaced Coolant overflow tank
Replaced windshield fluid reservoir motor with an old working one
Replaced WC lift rubber bumper mount

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 12-JUL-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jul 12, 2022 10:01:30 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jul 12, 2022 10:01:30 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jul 12, 2022 10:01:30 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jul 12, 2022 10:01:30 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jul 12, 2022 10:01:30 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jul 12, 2022 10:01:30 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 55767527
Invoice No. 55345 - 55767527

Client Department:
Department: 55345M
Work Order Description
CHECK WHEEL CHAIR LIFT FOR PROPER OPERATION
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 268,767 - DH

Activity Header
Activity: 15 055/023/000 LIFT, WHEELCHAIR, PASSENGER
Activity Note: CHECK WHEEL CHAIR LIFT FOR PROPER OPERATION
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Jul-22	Earl Johnson	2.22	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 55767527
Invoice No. 55345 - 55767527

Client Department:
Department: 55345M
Work Order Description
CHECK WHEEL CHAIR LIFT FOR PROPER OPERATION
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 268,767 - DH

Activity Header
Activity: 25 002/035/025 PUMP, WASHER, WINDSHIELD
Activity Note: windshield washer pump not working
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Jul-22	32408	BUMPER, RUBBER, W/C, BRAUN SAME AS 32408-10KS	2	2	4
14-Jul-22	33659KS	PENDANT, CONTROL, W/C, BRAUN	1	205.02	205.02

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Jul-22	Delva,Terry	2.52	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	209.02
Labor:	0.00
Labor Hours:	2.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**209.02**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 55767527
Invoice No. 55345 - 55767527

Client Department:
Department: 55345M
Work Order Description
CHECK WHEEL CHAIR LIFT FOR PROPER OPERATION
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 268,767 - DH

Activity Header
Activity: 35 042/002/009 TANK, SURGE, COOLANT
Activity Note: coolant reservoir tank leaking
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Jul-22	603-811	TANK, OVERFLOW, COOLANT	1	78.36	78.36

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Jul-22	Delva,Terry	2.48	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 35 Sub Total	
Parts:	78.36
Labor:	0.00
Labor Hours:	2.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**78.36**

Work Order Footer

Work Order 55767527 Total	
Parts:	287.38
Labor:	0.00
Labor Hours:	7.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**287.38**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55463093
Invoice No. 55345 - 55463093

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-LIGHT DUTY PMB		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	265,639 - DH

Chronology		
Reported	Jun 9, 2022 12:00:00 AM	Jun 9, 2022 12:00:00 AM
Started	Jun 15, 2022 4:32:00 PM	
Completed	Jun 15, 2022 10:07:00 PM	Jun 15, 2022 10:07:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PMB Service

CAUSE: Service due by Mileage.

CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check Brakes. Clean Batteries
parts # B329 Qty (1)
Oil 10W30 Qty (7,0) Qt

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 15-JUN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jun 15, 2022 9:46:44 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jun 15, 2022 9:46:44 PM	No	
4 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jun 15, 2022 9:46:44 PM	No	
7 - Have you performed the proper LOTO?	Done		DARTHURS	Jun 15, 2022 9:46:44 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jun 15, 2022 9:46:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jun 15, 2022 9:46:44 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55463093
Invoice No. 55345 - 55463093

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMB
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 265,639 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Jun-22	Arthurs,Durvin	1.88	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: DARTHURS Performed on: 15-JUN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		DARTHURS	Jun 15, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:42:17 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done	Washer inop not Spraying	DARTHURS	Jun 15, 2022 9:42:17 PM	No	
20,800 - INSPECT_High Idle Control	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
31,000 - SSF (Street Side Front)	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
32,000 - Engine Inspection	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	NA	DARTHURS	Jun 15, 2022 9:42:17 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	DARTHURS	Jun 15, 2022 9:42:17 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
32,100 - INSPECT_Intake System	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	0 Volt*		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
33,010 - CSF (Curb Side Front)	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	13.98 Volt*		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		DARTHURS	Jun 15, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression				9:42:17 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
50,400 - LUBE_All Chassis Components	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
50,700 - INSPECT_Tire Condition	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	12 32nds of an inch		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	12 32nds of an inch		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.554 Inch		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.554 Inch		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
52,100 - INSPECT_Vibration Damper	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
53,600 - INSPECT_Tire Condition	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		DARTHURS	Jun 15, 2022 9:42:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	10 32nds of an inch		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	7 32nds of an inch		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	11 32nds of an inch		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	11 32nds of an inch		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	1.665 Inch		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	1.665 Inch		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	15.554 Cycles		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
62,400 - INSPECT_All Pivot Points	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
62,500 - INSPECT_Cams and Slots	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
62,600 - INSPECT_Rollers	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
62,700 - INSPECT_All Linkages	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		DARTHURS	Jun 15, 2022 9:42:17 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55463093
Invoice No. 55345 - 55463093

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMB
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 265,639 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Jun-22	B329	FILTER, OIL, SPIN-ON SEE P550965	1	2.14	2.14

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Jun-22	Arthurs,Durvin	0.4	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: DARTHURS Performed on: 15-JUN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Jun 15, 2022 9:45:27 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Jun 15, 2022 9:45:27 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Jun 15, 2022 9:45:27 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Jun 15, 2022 9:45:27 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Jun 15, 2022 9:45:27 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Jun 15, 2022 9:45:27 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Jun 15, 2022 9:45:27 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Jun 15, 2022 9:45:27 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	Jun 15, 2022 9:45:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Jun 15, 2022 9:45:27 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		DARTHURS	Jun 15, 2022 9:45:27 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Jun 15, 2022 9:45:27 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Jun 15, 2022 9:45:27 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	2.14
Labor:	0.00
Labor Hours:	0.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.14**

Work Order Footer

Work Order 55463093 Total	
Parts:	2.14
Labor:	0.00
Labor Hours:	2.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.14**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55688557
Invoice No. 55345 - 55688557

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
REAR AC NOT WORKING		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	265,315 - DH

Chronology		
Reported	Jun 13, 2022 1:48:00 PM	Jun 13, 2022 1:48:00 PM
Started		
Completed	Jun 13, 2022 4:38:00 PM	Jun 13, 2022 4:38:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: from driver rear AC not blowing

Cause: operator don't understand the control

Correction: check unit complete working asdesign return vehicle back to work

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 13-JUN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Jun 13, 2022 4:37:53 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		JUHURST	Jun 13, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				4:37:53 PM		
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Jun 13, 2022 4:37:53 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Jun 13, 2022 4:37:53 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Jun 13, 2022 4:37:53 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Jun 13, 2022 4:37:53 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55688557
Invoice No. 55345 - 55688557

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
REAR AC NOT WORKING		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	265,315 - DH

Activity Header
Activity: 10 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: REAR AC NOT WORKING
Reason for Repair: 01 Breakdown
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55688557 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55657525
Invoice No. 55345 - 55657525

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Wheelchair Lift		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	264,137 - DH

Chronology		
Reported	Jun 2, 2022 7:15:00 AM	Jun 2, 2022 7:15:00 AM
Started	Jun 2, 2022 7:16:00 AM	
Completed	Jun 2, 2022 9:35:00 AM	Jun 2, 2022 9:35:00 AM
Down Time		

Work Order Notes

Line 10 complaint. w/c lift inop

Cause. bad inner plate shoks

correction. removed and replaced inner plate shoks

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 02-JUN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Jun 2, 2022 7:17:53 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Jun 2, 2022 7:17:53 AM	No	
4 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Jun 2, 2022 7:17:53 AM	No	
7 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Jun 2, 2022 7:17:53 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Jun 2, 2022 7:17:53 AM	No	
11 - Have you successfully completed the	Done		RAURODRIGUEZ	Jun 2, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				7:17:53 AM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55657525
Invoice No. 55345 - 55657525

Client Department:
Department: 55345M
Work Order Description
Wheelchair Lift
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 264,137 - DH

Activity Header
Activity: 20 055/023/000 LIFT, WHEELCHAIR, PASSENGER
Activity Note: WheelChair Lift
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Jun-22	32601	SPRING, ASSIST, GAS	2	15.57	31.14

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jun-22	Rodriguez,Raul	2.25	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	31.14
Labor:	0.00
Labor Hours:	2.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**31.14**

Work Order Footer

Work Order 55657525 Total	
Parts:	31.14
Labor:	0.00
Labor Hours:	2.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**31.14**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55641798
Invoice No. 55345 - 55641798

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Rear AC)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 263,542 - DH

Chronology		
Reported	May 26, 2022 7:18:00 PM	May 26, 2022 7:18:00 PM
Started	May 26, 2022 7:20:00 PM	
Completed	May 27, 2022 12:11:00 AM	May 27, 2022 12:11:00 AM
Down Time		

Work Order Notes

Line 10 Complaint: Rear AC malfunction.

Cause: Ambient temp sensor not reading.

Correction: Traced out a bad connection at the thermostat pad. Repaired connector pins. Rear AC operates properly.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 27-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	May 27, 2022 12:03:01 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	May 27, 2022 12:03:01 AM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	May 27, 2022 12:03:01 AM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	May 27, 2022 12:03:01 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	May 27, 2022 12:03:01 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	May 27, 2022 12:03:01 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55641798
Invoice No. 55345 - 55641798

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Rear AC)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 263,542 - DH

Activity Header
Activity: 20 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Check Rear AC
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-May-22	Earl Johnson	2.83	0	0
27-May-22	Earl Johnson	0.02	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55641798 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54648786
Invoice No. 55345 - 54648786

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
QCC FLEET INSPECTION		Ford E450 Champion Challenger	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	262,738 -

Chronology		
Reported	May 3, 2022 2:00:39 PM	May 3, 2022 2:00:39 PM
Started		
Completed	May 19, 2022 2:56:00 PM	May 19, 2022 2:56:00 PM
Down Time		

Work Order Notes

Line 10 QCC SERVICE PERFORMED

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: CVERGARA Performed on: 19-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		CVERGARA	May 19, 2022 2:54:24 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		CVERGARA	May 19, 2022 2:54:24 PM	No	
4 - Are you wearing the appropriate PPE?	Done		CVERGARA	May 19, 2022 2:54:24 PM	No	
7 - Have you performed the proper LOTO?	Done		CVERGARA	May 19, 2022 2:54:24 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		CVERGARA	May 19, 2022 2:54:24 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		CVERGARA	May 19, 2022 2:54:24 PM	No	

Activity Sub Total

Activity 10 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54648786
Invoice No. 55345 - 54648786

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
QCC FLEET INSPECTION		Ford E450 Champion Challenger	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	262,738 -

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: QCC FLEET INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54648786 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55603843
Invoice No. 55345 - 55603843

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
TRANSMISSION NOT SHIFTING PROPERLY		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	262,318 - DH

Chronology		
Reported	May 13, 2022 8:50:00 AM	May 13, 2022 8:50:00 AM
Started	May 13, 2022 9:53:00 AM	
Completed	May 15, 2022 5:22:00 PM	May 15, 2022 5:22:00 PM
Down Time		

Work Order Notes

Line 10 Replaced transmission with a good used one
, Replaced cyl#7 ignition coil due to a misfire..

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 15-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	May 15, 2022 5:21:05 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	May 15, 2022 5:21:05 PM	No	
4 - Are you wearing the appropriate PPE?	Done		TDELVA	May 15, 2022 5:21:05 PM	No	
7 - Have you performed the proper LOTO?	Done		TDELVA	May 15, 2022 5:21:05 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	May 15, 2022 5:21:05 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	May 15, 2022 5:21:05 PM	No	

Activity Sub Total

Activity 10 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55603843
Invoice No. 55345 - 55603843

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
TRANSMISSION NOT SHIFTING PROPERLY		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	262,318 - DH

Activity Header
Activity: 20 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: REMOVE AND REPLACE TRANSMISSION ASSY
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-May-22	Delva,Terry	3.23	0	0
13-May-22	Delva,Terry	6.22	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	9.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55603843
Invoice No. 55345 - 55603843

Client Department:
Department: 55345M
Work Order Description
TRANSMISSION NOT SHIFTING PROPERLY
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 262,318 - DH

Activity Header
Activity: 30 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Misfire
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-May-22	DG508	COIL, IGNITION SAME AS 3W7Z-12029-AA	1	35.92	35.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-May-22	Delva,Terry	0.5833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	35.92
Labor:	0.00
Labor Hours:	0.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**35.92**

Work Order Footer

Work Order 55603843 Total	
Parts:	35.92
Labor:	0.00
Labor Hours:	10.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**35.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 7

Work Order No. 55519726
Invoice No. 55345 - 55519726

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
CILYNDER HEAD REPLACEMENT		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	261,819 - DH

Chronology		
Reported	Apr 14, 2022 7:08:00 AM	Apr 14, 2022 7:08:00 AM
Started	Apr 18, 2022 8:38:00 AM	
Completed	May 4, 2022 1:54:00 PM	May 4, 2022 1:54:00 PM
Down Time		

Work Order Notes

Line 10 C: vehicle is not running properly

C: Check all related systems for engine running rough found head gaskets are damaged causing coolant to leak to cylinders

C: removed cylinder heads to replace gaskets retest and road test vehicle ok at this time

parts:
1 head gasket 4c3z-6051-aa
1 head gasket 4c3z-6051-ba
1 cylinder head bolt
10 exhaust studs w703902-s403
10 exhaust nuts n811313-s431
2 timing chains 5l3z-6268-a
1 timing chain guide 2l1z-6k297-aa
1 timing chain guide 4l3z-6m256-aa
1 timing chain tensioner arm f85z-6k255-aa
1 timing chain tensioner arm f85z-6m274-aa
1 hydraulic tensioner xl1z-6l266-aa
1 hydraulic tensioner 1l3z-6l266-aa
1 crank seal xw4z-6700-aa
1 intake gasket 4c2z-9439-aa
20 injectors o-rings f0pz-9229-a
1 dip stick 5c3z-6754-da
1 ignition coil dg-508
1 spark plug ap-103a
1 belt 1360k6 Line 20 C: wrench light on

C: Check computer system found code for transmission solenoid D stuck on or off, follow diagnostic test

C: vehicle needs solenoid Line 30 engine light on

solenoid D not working properly

replaced transmission solenoid d with a good use one and replace transmission filter completed Line 40 ALL PARTS CHARGED

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 04-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	May 4, 2022 1:54:38 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	May 4, 2022 1:54:38 PM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	May 4, 2022 1:54:38 PM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	May 4, 2022 1:54:38 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	May 4, 2022 1:54:38 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	May 4, 2022 1:54:38 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 7

Work Order No. 55519726
Invoice No. 55345 - 55519726

Client Department:
Department: 55345M
Work Order Description
CILYNDER HEAD REPLACEMENT
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 261,819 - DH

Activity Header
Activity: 20 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: CHECK ENGINE LIGHT ON
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Apr-22	Perez,Javier	2.22	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 7

Work Order No. 55519726
Invoice No. 55345 - 55519726

Client Department:
Department: 55345M
Work Order Description
CILYNDER HEAD REPLACEMENT
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 261,819 - DH

Activity Header
Activity: 30 033/003/005 PLUG, SPARK
Activity Note: SPARK PLUGS
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Apr-22	Perez,Javier	4.67	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	4.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 7

Work Order No. 55519726
Invoice No. 55345 - 55519726

Client Department:
Department: 55345M
Work Order Description
CILYNDER HEAD REPLACEMENT
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 261,819 - DH

Activity Header
Activity: 40 027 TRANSMISSION, MAIN, AUTOMATIC
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Apr-22	9R3Z-6065-A	BOLT, HEAD, CYLINDER, V10	1	2.06	2.06

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Apr-22	Perez,Javier	5.18	0	0
19-Apr-22	Perez,Javier	3.35	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	2.06
Labor:	0.00
Labor Hours:	8.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.06**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 7

Work Order No. 55519726
Invoice No. 55345 - 55519726

Client Department:
Department: 55345M
Work Order Description
CILYNDER HEAD REPLACEMENT
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 261,819 - DH

Activity Header
Activity: 50 045/007 HEAD, CYLINDER
Activity Note:
Reason for Repair: 01 Breakdown
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Apr-22	2L1Z-6K297-AA	GUIDE, CHAIN, TIMING, LH	1	16.72	16.72
29-Apr-22	1L3Z-6L266-AA	TENSIONER, CHAIN, TIMING	1	35.2	35.2
29-Apr-22	4L3Z-6M256-AA	GUIDE, CHAIN, TIMING, RH	1	19.19	19.19
29-Apr-22	4C2Z-9439-AA	GASKET, MANIFOLD, INTAKE	1	21.55	21.55
29-Apr-22	5C3Z-6754-DA	TUBE, DIPSTICK, LEVEL, OIL, ENGINE	1	19.66	19.66
29-Apr-22	4C3Z-6051-AA	GASKET, HEAD, CYLINDER	1	45.21	45.21
29-Apr-22	F85Z-6K255-AA	ARM, TENSIONER, CHAIN, TIMING	1	19.58	19.58
29-Apr-22	XL1Z-6L266-AA	TENSIONER, CHAIN, TIMING	1	30.35	30.35
29-Apr-22	AP103	PLUG, SPARK	1	3.5	3.5
29-Apr-22	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	21.32	21.32
29-Apr-22	5L3Z-6268-A	BELT, TIMING	2	31.35	62.7
29-Apr-22	4C3Z-6051-BA	GASKET, HEAD, CYLINDER	1	44.8	44.8
29-Apr-22	F85Z-6M274-AA	ARM, TENSIONER, CHAIN, TIMMING, 5.4L	1	14.85	14.85
29-Apr-22	XW4Z-6700-AA	SEAL, CRANKSHAFT, FRONT	1	8.24	8.24
29-Apr-22	DG508	COIL, IGNITION SAME AS 3W7Z-12029-AA	1	41.69	41.69

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Apr-22	Perez,Javier	7.9	0	0
29-Apr-22	Perez,Javier	1.05	0	0
20-Apr-22	Perez,Javier	7.9	0	0
21-Apr-22	Perez,Javier	5.63	0	0
27-Apr-22	Perez,Javier	7.9	0	0
25-Apr-22	Perez,Javier	3.57	0	0
22-Apr-22	Perez,Javier	5.92	0	0
26-Apr-22	Perez,Javier	7.78	0	0

Booked Date	Technician	Hours	Shop Rate	Extended
19-Apr-22	Perez,Javier	4.37	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 50 Sub Total	
Parts:	404.56
Labor:	0.00
Labor Hours:	52.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**404.56**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 6 of 7

Work Order No. 55519726
Invoice No. 55345 - 55519726

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
CILYNDER HEAD REPLACEMENT		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	261,819 - DH

Activity Header
Activity: 60 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: CYLINDER HEAD REFURB
Reason for Repair: 01 Breakdown
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-May-22	DSP-OUTSIDESERV	DIRECT PURCHASE FOR OUTSIDE SERV GL54354	1	1,190	1,190
06-May-22	FOPZ-9229-A	O-RING, SEAL, INJECTOR, FUEL SAME AS CM-4717	2	13.54	27.08

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 60 Sub Total	
Parts:	1,217.08
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1,217.08**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 7 of 7

Work Order No. 55519726
Invoice No. 55345 - 55519726

Client Department:
Department: 55345M
Work Order Description
CILYNDER HEAD REPLACEMENT
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 261,819 - DH

Activity Header
Activity: 70 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: REMOVE AND REPLACE TRANSMISSION SOLENOID D
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-May-22	20021	FILTER, TRANSMISSION 20021	1	17.44	17.44

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-May-22	Pierre,Hubert J	2.13	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 70 Sub Total	
Parts:	17.44
Labor:	0.00
Labor Hours:	2.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**17.44**

Work Order Footer

Work Order 55519726 Total	
Parts:	1,641.14
Labor:	0.00
Labor Hours:	69.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1,641.14**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55489217
Invoice No. 55345 - 55489217

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR REAR BUMPER FELL OFF
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 261,417 - DH

Chronology		
Reported	Apr 4, 2022 8:29:00 AM	Apr 4, 2022 8:29:00 AM
Started	Apr 4, 2022 8:39:00 AM	
Completed	Apr 8, 2022 10:44:00 AM	Apr 8, 2022 10:44:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Rear bumper fell off

Cause: pre driver

correction: Readjusted Rear bumper add new screws everything ok at this time, drop the bus to the exhaust shop for repair. Line 20 EXHAUST TAIL PIPE BROKE ,UNIT SENT TO MUFFLER SHOP(COSMOS) FAILED PART REPLACED .

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 08-APR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Apr 8, 2022 10:42:59 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Apr 8, 2022 10:42:59 AM	No	
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Apr 8, 2022 10:42:59 AM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Apr 8, 2022 10:42:59 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Apr 8, 2022 10:42:59 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Apr 8, 2022 10:42:59 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55489217
Invoice No. 55345 - 55489217

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR REAR BUMPER FELL OFF
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 261,417 - DH

Activity Header
Activity: 20 002 CAB & SHEET METAL
Activity Note: REAR BUMPER FELL OFF
Reason for Repair: 04 Driver's Report
Work Accomplished: 15 Paint Prep, & Repaint
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Apr-22	NELSON PIERRE-LOUIS	1.55	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55489217
Invoice No. 55345 - 55489217

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345 PER DVIR REAR BUMPER FELL OFF		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	261,417 - DH

Activity Header
Activity: 30 043/003 MUFFLER
Activity Note: TAIL PIPE NEEDS REPLACEMENT (BROKEN) SENT TO MUFFLER SHOP (COSMOS)
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-May-22	DSP-OUTSIDESERV	DIRECT PURCHASE FOR OUTSIDE SERV GL54354	1	605	605

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	605.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**605.00**

Work Order Footer

Work Order 55489217 Total	
Parts:	605.00
Labor:	0.00
Labor Hours:	1.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**605.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55482650
Invoice No. 55345 - 55482650

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Check vehicle.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	261,262 - DH

Chronology		
Reported	Mar 31, 2022 8:32:29 PM	Mar 31, 2022 8:32:29 PM
Started	Mar 31, 2022 8:35:00 PM	
Completed	Mar 31, 2022 11:56:00 PM	Mar 31, 2022 11:56:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Check vehicle.

Cause: Inspection.

Correction: Road tested vehicle without any issues. Visual revealed a leaking radiator cap, replaced.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 31-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Mar 31, 2022 11:30:59 PM	No	
2 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Mar 31, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				11:30:59 PM		
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Mar 31, 2022 11:30:59 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Mar 31, 2022 11:30:59 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Mar 31, 2022 11:30:59 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Mar 31, 2022 11:30:59 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55482650
Invoice No. 55345 - 55482650

Client Department:
Department: 55345M
Work Order Description
Check vehicle.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 261,262 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Check vehicle.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
31-Mar-22	10238	CAP, RADIATOR, FORD	1	5.89	5.89

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Mar-22	Earl Johnson	1.63	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	5.89
Labor:	0.00
Labor Hours:	1.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.89**

Work Order Footer

Work Order 55482650 Total	
Parts:	5.89
Labor:	0.00
Labor Hours:	1.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.89**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 55463524
Invoice No. 55345 - 55463524

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	KIVEY	**Status:**	40 - Closed (40)
Created By:	KIVEY	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,709 - DH

Chronology		
Reported	Mar 25, 2022 7:52:58 AM	Mar 25, 2022 7:52:58 AM
Started	Mar 25, 2022 8:58:00 AM	
Completed	Mar 28, 2022 3:57:00 PM	Mar 28, 2022 3:57:00 PM
Down Time		

Work Order Notes

Line 10 pm. follow-up need water pump and tires

preventive maintenance

replaced water pump add coolant completed Line 20 replaced 4 tires took tires from 4607 and installed tires on 4516
torque wheels 140 lbs second torque 140 lbs
replace tag light assembly and connectors
part number 3975927 qty1

Activity Header
Activity: 10 034/003/000 LAMPS, SIGNAL, PARKING & BACKUP
Activity Note: TAG LIGHT INOP
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Mar-22	3975927	LAMP, PLATE, LICENSE	1	12.1	12.1

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Mar-22	Gaspard,Ronald	0.45	0	0
25-Mar-22	Gaspard,Ronald	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	12.10
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**12.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 55463524
Invoice No. 55345 - 55463524

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	KIVEY	**Status:**	40 - Closed (40)
Created By:	KIVEY	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,709 - DH

Activity Header
Activity: 20 045/009/003 BODY, PUMP, OIL, ENGINE
Activity Note: WATER PUMP LEAK
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 55463524
Invoice No. 55345 - 55463524

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	KIVEY	**Status:**	40 - Closed (40)
Created By:	KIVEY	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,709 - DH

Activity Header
Activity:30 017/003/001 TIRE, CUSHION W/TREAD
Activity Note: FRONT TIRE BELOW SPEC NEED TO CHANGE
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Mar-22	Gaspard,Ronald	1.27	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 55463524
Invoice No. 55345 - 55463524

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	KIVEY	**Status:**	40 - Closed (40)
Created By:	KIVEY	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,709 - DH

Activity Header
Activity: 40 017/003/001 TIRE, CUSHION W/TREAD
Activity Note: REAR TIRE BELOW SPEC NEEDS TO BE CHANGED
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Mar-22	3L3Z-8501-CA	PUMP, WATER, E450	1	40.2	40.2

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Mar-22	Pierre,Hubert J	3.2	0	0
25-Mar-22	Gaspard,Ronald	1.07	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	40.20
Labor:	0.00
Labor Hours:	4.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**40.20**

Work Order Footer

Work Order 55463524 Total	
Parts:	52.30
Labor:	0.00
Labor Hours:	6.04
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**52.30**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54476337
Invoice No. 55345 - 54476337

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,709 - DH

Chronology		
Reported	Mar 23, 2022 12:00:00 AM	Mar 23, 2022 12:00:00 AM
Started	Mar 24, 2022 4:03:00 PM	
Completed	Mar 25, 2022 12:42:00 AM	Mar 25, 2022 12:42:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA

CAUSE:Service

CORRECTION:Perform PMA Service
oil filter B329 qty1
engine oil 10w30 qty 7 qts
clean AC filter
clean batteries

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 24-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Mar 24, 2022 11:00:19 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Mar 24, 2022 11:00:19 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RGASPARD	Mar 24, 2022 11:00:19 PM	No	
7 - Have you performed the proper LOTO?	Done		RGASPARD	Mar 24, 2022 11:00:19 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Mar 24, 2022 11:00:19 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Mar 24, 2022 11:00:19 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54476337
Invoice No. 55345 - 54476337

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 260,709 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Mar-22	B329	FILTER, OIL, SPIN-ON SEE P550965	1	1.99	1.99

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Mar-22	Gaspard,Ronald	1	0	0
25-Mar-22	Gaspard,Ronald	0.67	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: KIVEY Performed on: 25-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done	TAG LIGHT INOP	KIVEY	Mar 25, 2022 7:53:10 AM	Yes	55463524
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
20,800 - INSPECT_High Idle Control	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
21,100 - INSPECT_Parking Brake Operation	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
21,700 - INSPECT_Engine Fault Codes	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
31,000 - SSF (Street Side Front)	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
32,000 - Engine Inspection	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done	WATER PUMP LEAK	KIVEY	Mar 25, 2022 7:53:10 AM	Yes	55463524
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	KIVEY	Mar 25, 2022 7:53:10 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	KIVEY	Mar 25, 2022 7:53:10 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
32,100 - INSPECT_Intake System	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		KIVEY	Mar 25, 2022 7:53:10 AM	No	
33,010 - CSF (Curb Side Front)	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	KIVEY	Mar 25, 2022 7:53:10 AM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/ Lights;CHECK_for Leaks	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
50,400 - LUBE_All Chassis Components	Done	na	KIVEY	Mar 25, 2022 7:53:10 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
50,700 - INSPECT_Tire Condition	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	3 32nds of an inch	FRONT TIRE BELOW SPEC NEED TO CHANGE	KIVEY	Mar 25, 2022 7:53:10 AM	Yes	55463524
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		KIVEY	Mar 25, 2022 7:53:10 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,200 - RECORD_RF-Tire Tread Depth (32nds)	4 32nds of an inch	BELOW SPEC NEED TO CHANGE	KIVEY	Mar 25, 2022 7:53:10 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		KIVEY	Mar 25, 2022 7:53:10 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		KIVEY	Mar 25, 2022 7:53:10 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		KIVEY	Mar 25, 2022 7:53:10 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	38 Inch		KIVEY	Mar 25, 2022 7:53:10 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	38 Inch		KIVEY	Mar 25, 2022 7:53:10 AM	No	
52,100 - INSPECT_Vibration Damper	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
53,600 - INSPECT_Tire Condition	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	2 32nds of an inch	REAR TIRE BELOW SPEC NEEDS TO BE CHANGED	KIVEY	Mar 25, 2022 7:53:10 AM	Yes	55463524
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	3 32nds of an inch	BELOW SPEC NEEDS TO BE CHANGED	KIVEY	Mar 25, 2022 7:53:10 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		KIVEY	Mar 25, 2022 7:53:10 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		KIVEY	Mar 25, 2022 7:53:10 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	5 32nds of an inch	BELOW SPEC NEEDS TO BE CHANGED	KIVEY	Mar 25, 2022 7:53:10 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	5 32nds of an inch	BELOW SPEC NEEDS TO BE CHANGED	KIVEY	Mar 25, 2022 7:53:10 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		KIVEY	Mar 25, 2022 7:53:10 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		KIVEY	Mar 25, 2022 7:53:10 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		KIVEY	Mar 25, 2022 7:53:10 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		KIVEY	Mar 25, 2022 7:53:10 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	40 Inch		KIVEY	Mar 25, 2022 7:53:10 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	40 Inch		KIVEY	Mar 25, 2022 7:53:10 AM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
60,100 - RECORD_Wheelchair Cycle Count	12458 Cycles		KIVEY	Mar 25, 2022 7:53:10 AM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
62,400 - INSPECT_All Pivot Points	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
62,500 - INSPECT_Cams and Slots	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
62,600 - INSPECT_Rollers	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
62,700 - INSPECT_All Linkages	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		KIVEY	Mar 25, 2022 7:53:10 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.99
Labor:	0.00
Labor Hours:	1.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.99**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54476337
Invoice No. 55345 - 54476337

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,709 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 25-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Mar 25, 2022 12:33:51 AM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Mar 25, 2022 12:33:51 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Mar 25, 2022 12:33:51 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Mar 25, 2022 12:33:51 AM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Mar 25, 2022 12:33:51 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Mar 25, 2022 12:33:51 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Mar 25, 2022 12:33:51 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Mar 25, 2022 12:33:51 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00

	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 54476337 Total	
Parts:	1.99
Labor:	0.00
Labor Hours:	1.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.99**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55459490
Invoice No. 55345 - 55459490

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Transmission)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 99 - Cancelled (99)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 260,435 - DH

Chronology		
Reported	Mar 23, 2022 5:11:00 PM	Mar 23, 2022 5:11:00 PM
Started	Mar 23, 2022 5:13:00 PM	
Completed	Mar 24, 2022 12:25:00 AM	Mar 24, 2022 12:25:00 AM
Down Time		

Work Order Notes

Line 10 ***VOID***

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 24-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Mar 24, 2022 12:25:01 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Mar 24, 2022 12:25:01 AM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Mar 24, 2022 12:25:01 AM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Mar 24, 2022 12:25:01 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Mar 24, 2022 12:25:01 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Mar 24, 2022 12:25:01 AM	No	

Activity Sub Total

Activity 10 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55459490
Invoice No. 55345 - 55459490

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345 PER DVIR (Check Transmission)		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	99 - Cancelled (99)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,435 - DH

Activity Header
Activity: 20 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: VERIFY COMPLAINT (Check Transmission)
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55459490 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 55399390
Invoice No. 55345 - 55399390

Client Department:
Department: 55345M
Work Order Description
PREPARE BUS FOR P.T.C ANNUAL INSPECTION.
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 259,862 - DH

Chronology		
Reported	Mar 3, 2022 9:11:00 AM	Mar 3, 2022 9:11:00 AM
Started	Mar 3, 2022 9:57:00 AM	
Completed	Mar 9, 2022 7:12:00 AM	Mar 9, 2022 7:12:00 AM
Down Time		

Work Order Notes

Line 10 performed regular maintenance a/c , lift and prepare bus for PTC annual inspection.

installed F.T. camara and geotab, replaced driver seat with known use god part. Vehicle ready to service.

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: PREPARE BUS FOR P.T.C ANNUAL INSPECTION.
Reason for Repair: 11 Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Mar-22	Rodriguez,Raul	2.12	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 55399390
Invoice No. 55345 - 55399390

Client Department:
Department: 55345M
Work Order Description
PREPARE BUS FOR P.T.C ANNUAL INSPECTION.
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 259,862 - DH

Activity Header
Activity:20 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 09-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Mar 9, 2022 7:07:12 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Mar 9, 2022 7:07:12 AM	No	
4 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Mar 9, 2022 7:07:12 AM	No	
7 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Mar 9, 2022 7:07:12 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Mar 9, 2022 7:07:12 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Mar 9, 2022 7:07:12 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 55399390
Invoice No. 55345 - 55399390

Client Department:
Department: 55345M
Work Order Description
PREPARE BUS FOR P.T.C ANNUAL INSPECTION.
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 259,862 - DH

Activity Header
Activity: 30 036/008/002 CAMERA, SYSTEM, SURVEILLANCE
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Mar-22	Rodriguez,Raul	1.07	0	0
04-Mar-22	Rodriguez,Raul	1.47	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.54
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 55399390
Invoice No. 55345 - 55399390

Client Department:
Department: 55345M
Work Order Description
PREPARE BUS FOR P.T.C ANNUAL INSPECTION.
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 259,862 - DH

Activity Header
Activity:40 002/011/003 BELT & RETAINER, SEAT
Activity Note: DRIVER'S SEAT
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Mar-22	Rodriguez,Raul	3.13	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55399390 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	7.79
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55030820
Invoice No. 55345 - 55030820

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
INSPECT BUS		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,861 - DH

Chronology		
Reported	Oct 26, 2021 7:35:00 AM	Oct 26, 2021 7:35:00 AM
Started	Oct 26, 2021 7:46:00 AM	
Completed	Oct 27, 2021 8:45:00 AM	Oct 27, 2021 8:45:00 AM
Down Time		

Work Order Notes

Line 10 C: inspect vehicle

C: Check all systems found engine is misfiring

C: Replace one coil with a used one

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: PREPARE BUS FOR P.T.C ANNUAL INSPECTION.
Reason for Repair: 11 Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Oct-21	Perez,Javier	7.57	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	7.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55030820
Invoice No. 55345 - 55030820

Client Department:
Department: 55345M
Work Order Description
INSPECT BUS
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 259,861 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 27-OCT-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Oct 27, 2021 8:45:41 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Oct 27, 2021 8:45:41 AM	No	
4 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Oct 27, 2021 8:45:41 AM	No	
7 - Have you performed the proper LOTO?	Done		JAPEREZ	Oct 27, 2021 8:45:41 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Oct 27, 2021 8:45:41 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Oct 27, 2021 8:45:41 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55030820 Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	7.57
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54678442
Invoice No. 55345 - 54678442

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345 PER DVIR		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,861 - DH

Chronology		
Reported	Jun 24, 2021 12:10:17 PM	Jun 24, 2021 12:10:17 PM
Started		
Completed	Jul 1, 2021 1:49:00 PM	Jul 1, 2021 1:49:00 PM
Down Time		

Work Order Notes

Line 10 Replaced fuel injector spacer Line 20 Intake manifold gasket

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 01-JUL-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jul 1, 2021 1:49:24 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jul 1, 2021 1:49:24 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Jul 1, 2021 1:49:24 PM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Jul 1, 2021 1:49:24 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jul 1, 2021 1:49:24 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jul 1, 2021 1:49:24 PM	No	
20 - Miles			TDELVA	Jul 1, 2021 1:49:24 PM	No	
30 - Kilometers			TDELVA	Jul 1, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				1:49:24 PM		
40 - Hours			TDELVA	Jul 1, 2021 1:49:24 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54678442
Invoice No. 55345 - 54678442

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 259,861 - DH

Activity Header
Activity:20
Activity Note: VERIFY COMPLAINT
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Jun-21	(N)811625-S101	BOLT, BRACKET, CALIPER, BRAKE, DISC	2	2.16	4.32
24-Jun-21	8C2Z-3050-A	JOINT, BALL, LOWER	1	51.3	51.3
24-Jun-21	5U2Z-14S411-ZB	PIGTAIL, WIRE, INJECTOR, FUEL SAME AS WPT1051	1	16.18	16.18
24-Jun-21	DC2Z-7C078-S	HARNESS, TRANSMISSION, EXTERNAL, E450	2	73.14	146.28
24-Jun-21	3975927	LAMP, PLATE, LICENSE	2	11.96	23.92
24-Jun-21	80833	ALARM, BACK-UP	1	37.73	37.73
24-Jun-21	DL3Z-11002-A	STARTER, E350, '14	1	133.65	133.65
24-Jun-21	DC2Z-7C078-S	HARNESS, TRANSMISSION, EXTERNAL, E450	-2	73.14	-146.28
24-Jun-21	LC2Z-17508-A	MOTOR, WIPER, WINDSHIELD	1	89.17	89.17
24-Jun-21	GL3Z-13480-A	SWITCH, LAMP, STOP	1	32.33	32.33
24-Jun-21	P11JC-03D023-AA	SPACER, INJECTOR, FUEL	4	3.05	12.2

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	547.08
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**547.08**

Work Order Footer

Work Order 54678442 Total	
Parts:	547.08

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**547.08**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53558161
Invoice No. 55345 - 53558161

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-A/C INSPECTION		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	**Status:**	99 - Cancelled (99)
Created By:	NSTOLFO	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,861 -

Chronology		
Reported	Jun 14, 2021 2:00:40 PM	Jun 14, 2021 2:00:40 PM
Started		
Completed	Jun 14, 2021 2:19:26 PM	Jun 14, 2021 2:19:26 PM
Down Time		

Work Order Notes

Line 10 Bus is retired and no longer in service.

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	-				No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	-				No	
3 - Are you wearing the appropriate PPE?	-				No	
4 - Have you performed the proper LOTO?	-				No	
5 - Are you aware of the potential risks of performing this repair?	-				No	
10 - Have you successfully completed the Personal Risk Assessment?	-				No	
20 - Miles					No	
30 - Kilometers					No	
40 - Hours					No	

Activity Sub Total

	Activity 5 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53558161
Invoice No. 55345 - 53558161

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-A/C INSPECTION		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	**Status:**	99 - Cancelled (99)
Created By:	NSTOLFO	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,861 -

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: ANNUAL A/C INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53558161 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53557977
Invoice No. 55345 - 53557977

Client Department:
Department: 55345M
Work Order Description
55345-FIRE SAFETY INSPECTION
Requested By: NSTOLFO
Created By: NSTOLFO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 99 - Cancelled (99)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 259,861 -

Chronology		
Reported	Jun 14, 2021 2:00:40 PM	Jun 14, 2021 2:00:40 PM
Started		
Completed	Jun 14, 2021 2:19:07 PM	Jun 14, 2021 2:19:07 PM
Down Time		

Work Order Notes

Line 10 Bus is retired and no longer in service.

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	-				No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	-				No	
3 - Are you wearing the appropriate PPE?	-				No	
4 - Have you performed the proper LOTO?	-				No	
5 - Are you aware of the potential risks of performing this repair?	-				No	
10 - Have you successfully completed the Personal Risk Assessment?	-				No	
20 - Miles					No	
30 - Kilometers					No	
40 - Hours					No	

Activity Sub Total

	Activity 5 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53557977
Invoice No. 55345 - 53557977

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-FIRE SAFETY INSPECTION		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	**Status:**	99 - Cancelled (99)
Created By:	NSTOLFO	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,861 -

Activity Header
Activity: 15 999 TOTAL VEHICLE
Activity Note: ANNUAL FIRE SAFETY INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53557977 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53557801
Invoice No. 55345 - 53557801

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-PTC INSPECTION		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	**Status:**	99 - Cancelled (99)
Created By:	NSTOLFO	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,861 -

Chronology		
Reported	Jun 14, 2021 2:00:40 PM	Jun 14, 2021 2:00:40 PM
Started		
Completed	Jun 14, 2021 2:18:51 PM	Jun 14, 2021 2:18:51 PM
Down Time		

Work Order Notes

Line 10 Bus is retired and no longer in service.

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	-				No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	-				No	
3 - Are you wearing the appropriate PPE?	-				No	
4 - Have you performed the proper LOTO?	-				No	
5 - Are you aware of the potential risks of performing this repair?	-				No	
10 - Have you successfully completed the Personal Risk Assessment?	-				No	
20 - Miles					No	
30 - Kilometers					No	
40 - Hours					No	

Activity Sub Total

	Activity 5 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53557801
Invoice No. 55345 - 53557801

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-PTC INSPECTION		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	**Status:**	99 - Cancelled (99)
Created By:	NSTOLFO	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,861 -

Activity Header
Activity: 15 999 TOTAL VEHICLE
Activity Note: PTC INSPECTION
Reason for Repair: 11 Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53557801 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53544613
Invoice No. 55345 - 53544613

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
QCC FLEET INSPECTION		Ford E450 Champion Challenger	
Requested By:	RBOOTH	**Status:**	99 - Cancelled (99)
Created By:	RBOOTH	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,861 -

Chronology		
Reported	Jun 14, 2021 2:00:41 PM	Jun 14, 2021 2:00:41 PM
Started		
Completed	Jun 14, 2021 2:18:31 PM	Jun 14, 2021 2:18:31 PM
Down Time		

Work Order Notes

Line 10 Bus is retired and no longer in service.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	-				No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	-				No	
3 - Are you wearing the appropriate PPE?	-				No	
4 - Have you performed the proper LOTO?	-				No	
5 - Are you aware of the potential risks of performing this repair?	-				No	
10 - Have you successfully completed the Personal Risk Assessment?	-				No	
20 - Miles					No	
30 - Kilometers					No	
40 - Hours					No	

Activity Sub Total

	Activity 10 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53544613
Invoice No. 55345 - 53544613

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
QCC FLEET INSPECTION		Ford E450 Champion Challenger	
Requested By:	RBOOTH	**Status:**	99 - Cancelled (99)
Created By:	RBOOTH	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,861 -

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: QCC FLEET INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53544613 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54546641
Invoice No. 55345 - 54546641

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FIRST TRANSIT - NORTH AMERICA - CONSPICUITY		Ford E450 Champion Challenger	
Requested By:	DGALLAGHER	**Status:**	99 - Cancelled (99)
Created By:	DGALLAGHER	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,423 - DH

Chronology

Reported	May 11, 2021 2:27:18 PM	May 11, 2021 2:27:18 PM
Started		
Completed	May 19, 2021 1:40:15 PM	May 19, 2021 1:40:15 PM
Down Time		

Work Order Notes

Line 10 Unit is out of service

Activity Header
Activity: 10 999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	-				No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	-				No	
3 - Are you wearing the appropriate PPE?	-				No	
4 - Have you performed the proper LOTO?	-				No	
5 - Are you aware of the potential risks of performing this repair?	-				No	
10 - Have you successfully completed the Personal Risk Assessment?	-				No	
20 - Miles					No	
30 - Kilometers					No	
40 - Hours					No	

Activity Sub Total

	Activity 10 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54546641
Invoice No. 55345 - 54546641

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FIRST TRANSIT - NORTH AMERICA - CONSPICUITY		Ford E450 Champion Challenger	
Requested By:	DGALLAGHER	**Status:**	99 - Cancelled (99)
Created By:	DGALLAGHER	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,423 - DH

Activity Header
Activity:20 053/005/018 TAPE, REFLECTIVE
Activity Note: FIRST TRANSIT - NORTH AMERICA - CONSPICUITY
Reason for Repair: IC Internal Campaign
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: FIRST TRANSIT - NORTH AMERICA - CONSPICUITY
Task: FIRST TRANSIT - NORTH AMERICA - CONSPICUITY Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Inspect Conspicuity tape:					No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54546641 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54264468
Invoice No. 55345 - 54264468

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	255,946 - DH

Chronology		
Reported	Apr 16, 2021 12:00:00 AM	Apr 16, 2021 12:00:00 AM
Started	Apr 16, 2021 1:07:00 PM	
Completed	Apr 16, 2021 3:58:00 PM	Apr 16, 2021 3:58:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Vehicle came in for service

CAUSE: Time for service

CORRECTION: Job complete. Muffler has a small hole might¿ve been in the back

Activity Header

Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Apr-21	Junior Hurst	0.02	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 16-APR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Apr 16, 2021 2:56:13 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Apr 16, 2021 2:56:13 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Apr 16, 2021 2:56:13 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Apr 16, 2021 2:56:13 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Apr 16, 2021 2:56:13 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Apr 16, 2021 2:56:13 PM	No	
20 - Miles			JUHURST	Apr 16, 2021 2:56:13 PM	No	
30 - Kilometers			JUHURST	Apr 16, 2021 2:56:13 PM	No	
40 - Hours			JUHURST	Apr 16, 2021 2:56:13 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54264468
Invoice No. 55345 - 54264468

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 255,946 - DH

Activity Header
Activity: 10 020 GROUP, DRIVETRAIN
Activity Note: Light Duty PMI
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Apr-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.98	1.98

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Apr-21	Junior Hurst	1.7	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: JUHURST Performed on: 16-APR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
10,800 - *RPT*INSPECT_Body Damage,	Done		JUHURST	Apr 16, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Corrosion;DOCUMENT_Issues				2:47:38 PM		
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
20,800 - INSPECT_High Idle Control	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Apr 16, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				2:47:38 PM		
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
32,000 - Engine Inspection	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Apr 16, 2021 2:47:38 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Apr 16, 2021 2:47:38 PM	No	
33,010 - CSF (Curb Side Front)	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	14 Volt*		JUHURST	Apr 16, 2021 2:47:38 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
50,400 - LUBE_All Chassis Components	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
50,700 - INSPECT_Tire Condition	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Apr 16, 2021 2:47:38 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 16, 2021 2:47:38 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Apr 16, 2021 2:47:38 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 16, 2021 2:47:38 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		JUHURST	Apr 16, 2021 2:47:38 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		JUHURST	Apr 16, 2021 2:47:38 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.2299 Inch		JUHURST	Apr 16, 2021 2:47:38 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.2299 Inch		JUHURST	Apr 16, 2021 2:47:38 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Apr 16, 2021 2:47:38 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Apr 16, 2021 2:47:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 16, 2021 2:47:38 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 16, 2021 2:47:38 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Apr 16, 2021 2:47:38 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Apr 16, 2021 2:47:38 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 16, 2021 2:47:38 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 16, 2021 2:47:38 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	12 32nds of an inch		JUHURST	Apr 16, 2021 2:47:38 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	12 32nds of an inch		JUHURST	Apr 16, 2021 2:47:38 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	7.99 Inch		JUHURST	Apr 16, 2021 2:47:38 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	7.99 Inch		JUHURST	Apr 16, 2021 2:47:38 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	15008 Cycles		JUHURST	Apr 16, 2021 2:47:38 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
61,000 - INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
62,400 - INSPECT_All Pivot Points	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
62,500 - INSPECT_Cams and Slots	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
62,600 - INSPECT_Rollers	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
62,700 - INSPECT_All Linkages	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	Apr 16, 2021 2:47:38 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.98
Labor:	0.00
Labor Hours:	1.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.98**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54264468
Invoice No. 55345 - 54264468

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	255,946 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Apr-21	Junior Hurst	0.08	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: JUHURST Performed on: 16-APR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		JUHURST	Apr 16, 2021 2:51:21 PM	No	
101,000 - FRA Change Oil Filters	Yes		JUHURST	Apr 16, 2021 2:51:21 PM	No	
102,000 - FRA Drain Engine Oil	Yes		JUHURST	Apr 16, 2021 2:51:21 PM	No	
103,000 - FRA Check Transmission Fluid	Done		JUHURST	Apr 16, 2021 2:51:21 PM	No	
104,000 - Lubricate Chassis	Done		JUHURST	Apr 16, 2021 2:51:21 PM	No	
105,000 - Replace or Clean A/C Filters	Done		JUHURST	Apr 16, 2021 2:51:21 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		JUHURST	Apr 16, 2021 2:51:21 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		JUHURST	Apr 16, 2021 2:51:21 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 54264468 Total	
Parts:	1.98
Labor:	0.00
Labor Hours:	1.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.98**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54248642
Invoice No. 55345 - 54248642

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
COOLING SISTEM CHECK FOR LEAKS		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	251,007 - DH

Chronology		
Reported	Jan 28, 2021 6:55:00 AM	Jan 28, 2021 6:55:00 AM
Started	Jan 28, 2021 8:59:00 AM	
Completed	Apr 1, 2021 10:41:00 AM	Apr 1, 2021 10:41:00 AM
Down Time		

Work Order Notes

Line 10 Complaint. Vehicle has coolant leak

Cause. Reservoir tank broken

Correction. Removed and replaced reservoir tank.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 01-APR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Apr 1, 2021 10:38:15 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Apr 1, 2021 10:38:15 AM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Apr 1, 2021 10:38:15 AM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Apr 1, 2021 10:38:15 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Apr 1, 2021 10:38:15 AM	No	
10 - Have you successfully completed the	Done		RAURODRIGUEZ	Apr 1, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				10:38:15 AM		
20 - Miles			RAURODRIGUEZ	Apr 1, 2021 10:38:15 AM	No	
30 - Kilometers			RAURODRIGUEZ	Apr 1, 2021 10:38:15 AM	No	
40 - Hours			RAURODRIGUEZ	Apr 1, 2021 10:38:15 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54248642
Invoice No. 55345 - 54248642

Client Department:
Department: 55345M
Work Order Description
COOLING SISTEM CHECK FOR LEAKS
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 251,007 - DH

Activity Header
Activity: 20 042 COOLING SYSTEM
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Jan-21	603-811	TANK, OVERFLOW, COOLANT	1	73.31	73.31

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Apr-21	Rodriguez,Raul	2	0	0
28-Jan-21	Rodriguez,Raul	2.27	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	73.31
Labor:	0.00
Labor Hours:	4.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**73.31**

Work Order Footer

Work Order 54248642 Total	
Parts:	73.31
Labor:	0.00
Labor Hours:	4.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**73.31**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54350182
Invoice No. 55345 - 54350182

Client Department:
Department: 55345M
Work Order Description
ENGINE RUNING ROUGH & VIBRATES @ 40 MPH
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 255,224 - DH

Chronology		
Reported	Mar 4, 2021 11:15:00 AM	Mar 4, 2021 11:15:00 AM
Started	Mar 4, 2021 11:27:00 AM	
Completed	Mar 9, 2021 8:08:00 AM	Mar 9, 2021 8:08:00 AM
Down Time		

Work Order Notes

Line 10 C: Engine running rough

C: Check computer system found no codes, perform diagnostic test found spark plugs are were out

C: Replaced all spark plugs, 2 coils. Also starter is not working properly needed to be replaced

Parts:
10 spark plugs ap103
10 coil boots
2 ignition coil 26326
1 starter dl3z-11002-a

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 09-MAR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Mar 9, 2021 8:07:43 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Mar 9, 2021 8:07:43 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Mar 9, 2021 8:07:43 AM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Mar 9, 2021 8:07:43 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Mar 9, 2021 8:07:43 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Mar 9, 2021 8:07:43 AM	No	
20 - Miles			JAPEREZ	Mar 9, 2021 8:07:43 AM	No	
30 - Kilometers			JAPEREZ	Mar 9, 2021 8:07:43 AM	No	
40 - Hours			JAPEREZ	Mar 9, 2021 8:07:43 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54350182
Invoice No. 55345 - 54350182

Client Department:
Department: 55345M
Work Order Description
ENGINE RUNING ROUGH & VIBRATES @ 40 MPH
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 255,224 - DH

Activity Header
Activity: 20 033 IGNITION
Activity Note: VERIFY COMPLAINT
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Mar-21	DL3Z-11002-A	STARTER, E350, '14	1	134.49	134.49
09-Mar-21	26326	PLUG, COIL, IGNITION	2	23.94	47.88
09-Mar-21	AP103	PLUG, SPARK	10	3.43	34.3
09-Mar-21	26326	PLUG, COIL, IGNITION	-2	23.94	-47.88

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Mar-21	Perez,Javier	3.13	0	0
08-Mar-21	Perez,Javier	7.93	0	0
05-Mar-21	Perez,Javier	5.58	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	168.79
Labor:	0.00
Labor Hours:	16.64
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**168.79**

Work Order Footer

Work Order 54350182 Total	
Parts:	168.79
Labor:	0.00
Labor Hours:	16.64
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**168.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54293736
Invoice No. 55345 - 54293736

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Stalls		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	252,625 - DH

Chronology		
Reported	Feb 12, 2021 7:46:34 AM	Feb 12, 2021 7:46:34 AM
Started	Feb 12, 2021 7:57:00 AM	
Completed	Feb 12, 2021 10:56:00 AM	Feb 12, 2021 10:56:00 AM
Down Time		

Work Order Notes

Line 10 C: Vehicle stalls

C: Check vehicles computer found code for cylinder #1 misfire, further test indicates that someone left the heater hose clamp on the wrong place causing to leak coolant and damage the ignition coil

C: Replaced ignition coil retest system and road test vehicle ok at this time

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 12-FEB-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Feb 12, 2021 10:56:04 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Feb 12, 2021 10:56:04 AM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Feb 12, 2021 10:56:04 AM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Feb 12, 2021 10:56:04 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Feb 12, 2021 10:56:04 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Feb 12, 2021 10:56:04 AM	No	
20 - Miles			JAPEREZ	Feb 12, 2021 10:56:04 AM	No	
30 - Kilometers			JAPEREZ	Feb 12, 2021 10:56:04 AM	No	
40 - Hours			JAPEREZ	Feb 12, 2021 10:56:04 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54293736
Invoice No. 55345 - 54293736

Client Department:
Department: 55345M
Work Order Description
Stalls
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 252,625 - DH

Activity Header
Activity: 20 033 IGNITION
Activity Note: VERIFY COMPLAINT
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Feb-21	26326	PLUG, COIL, IGNITION	1	27.62	27.62

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Feb-21	Perez,Javier	2.92	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	27.62
Labor:	0.00
Labor Hours:	2.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**27.62**

Work Order Footer

Work Order 54293736 Total	
Parts:	27.62
Labor:	0.00
Labor Hours:	2.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**27.62**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54280945
Invoice No. 55345 - 54280945

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Vehiicle is stalling		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	252,270 - DH

Chronology		
Reported	Feb 8, 2021 2:04:30 PM	Feb 8, 2021 2:04:30 PM
Started	Feb 8, 2021 2:07:00 PM	
Completed	Feb 11, 2021 7:56:00 AM	Feb 11, 2021 7:56:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:Vehicle is stalling

Cause: Check computer system found codes for loss of communication between modules, perform diagnostic test and inspect systems

Correction:Replace engine harness and roush engine harness retest system and road test vehicle ok at this time

Parts:
1 engine harness dc2z-9d930-wa
1 roush engine harness p11gd-18a100-a2f
1 ignition coil 26326

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 11-FEB-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Feb 11, 2021 7:56:24 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Feb 11, 2021 7:56:24 AM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Feb 11, 2021 7:56:24 AM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Feb 11, 2021 7:56:24 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Feb 11, 2021 7:56:24 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Feb 11, 2021 7:56:24 AM	No	
20 - Miles			JAPEREZ	Feb 11, 2021 7:56:24 AM	No	
30 - Kilometers			JAPEREZ	Feb 11, 2021 7:56:24 AM	No	
40 - Hours			JAPEREZ	Feb 11, 2021 7:56:24 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54280945
Invoice No. 55345 - 54280945

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Vehiicle is stalling		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	252,270 - DH

Activity Header
Activity: 15 030 ELECTRICAL GROUP
Activity Note: Vehicle is stalling
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Feb-21	P11GD-18A100-A2F	HARNESS, UNDERHOOD	1	261.37	261.37
11-Feb-21	DC2Z-9D930-WA	HARNESS, WIRING, ENGINE	1	161.87	161.87
11-Feb-21	26326	PLUG, COIL, IGNITION	1	27.62	27.62

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Feb-21	Perez,Javier	7.85	0	0
08-Feb-21	Perez,Javier	1.45	0	0
09-Feb-21	Perez,Javier	7.95	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	450.86
Labor:	0.00
Labor Hours:	17.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**450.86**

Work Order Footer

Work Order 54280945 Total	
Parts:	450.86
Labor:	0.00
Labor Hours:	17.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**450.86**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54264417
Invoice No. 55345 - 54264417

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP--> Replace Right Rear Axle Seal And Replace Drive Belt
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 251,680 - DH

Chronology		
Reported	Feb 2, 2021 8:42:47 PM	Feb 2, 2021 8:42:47 PM
Started	Feb 2, 2021 9:23:00 PM	
Completed	Feb 3, 2021 4:20:00 PM	Feb 3, 2021 4:20:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========
To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.
==========

Complaint:right rear hub seal leaking .needs rotor, bearing and parking brake

Cause: bad

Correction:replaced parking brake, seal,inner bearing and rotor
Seal part number 9864S Qty1
Parking brake 8C2Z-2648-A Qty1
Seal F8UZ-4221-AA Qty1
Rotor 8C2Z-2C026-B Qty1

Activity Header
Activity:10 042/004 PUMP, WATER
Activity Note: needs serpentine belt.
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54264417
Invoice No. 55345 - 54264417

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP--> Replace Right Rear Axle Seal And Replace Drive Belt
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 251,680 - DH

Activity Header
Activity:20 018/002/046 HUB, AXLE, DRIVE, PREADJUSTED
Activity Note: right rear seal leaking.
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Feb-21	9864S	SEAL, BEARING, INNER, WHEEL, DRIVE	1	11.36	11.36
03-Feb-21	F8UZ-4221-AA	BEARING, CARRIER, DIFFERENTIAL, 80 DYNA	1	45.97	45.97
04-Feb-21	8C2Z-2648-A	SHOE, BRAKE, PARKING	1	46.19	46.19

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Feb-21	Gaspard,Ronald	0.37	0	0
02-Feb-21	Gaspard,Ronald	2.62	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	103.52
Labor:	0.00
Labor Hours:	2.99
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**103.52**

Work Order Footer

Work Order 54264417 Total	
Parts:	103.52
Labor:	0.00
Labor Hours:	2.99
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**103.52**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54173847
Invoice No. 55345 - 54173847

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-LIGHT DUTY PMC		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	251,680 - DH

Chronology		
Reported	Feb 2, 2021 12:16:31 PM	Feb 2, 2021 12:16:31 PM
Started	Feb 2, 2021 7:00:00 PM	
Completed	Feb 2, 2021 9:23:00 PM	Feb 2, 2021 9:23:00 PM
Down Time		

Work Order Notes

Line 10 PMC
Service
Perform PMC service
Oil filter B329 Qty1
Engine oil 10w30 qty 7 qts
Replaced AC filter
Replaced drain plug oil 65266 Qty1

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 02-FEB-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Feb 2, 2021 7:00:09 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Feb 2, 2021 7:00:09 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Feb 2, 2021 7:00:09 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Feb 2, 2021 7:00:09 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Feb 2, 2021 7:00:09 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Feb 2, 2021 7:00:09 PM	No	
20 - Miles			RGASPARD	Feb 2, 2021 7:00:09 PM	No	
30 - Kilometers			RGASPARD	Feb 2, 2021 7:00:09 PM	No	
40 - Hours			RGASPARD	Feb 2, 2021 7:00:09 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54173847
Invoice No. 55345 - 54173847

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMC
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 251,680 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Feb-21	Gaspard,Ronald	1.67	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 02-FEB-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Feb 2, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:33:07 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
20,800 - INSPECT_High Idle Control	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	Feb 2, 2021 8:33:07 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Feb 2, 2021 8:33:07 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	-	needs serpentine belt.	RGASPARD	Feb 2, 2021 8:33:07 PM	Yes	54264417
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	13.9 Volt*		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
33,010 - CSF (Curb Side Front)	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	RGASPARD	Feb 2, 2021 8:33:07 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		RGASPARD	Feb 2, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression				8:33:07 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
50,400 - LUBE_All Chassis Components	Done	na	RGASPARD	Feb 2, 2021 8:33:07 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Feb 2, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:33:07 PM		
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	37 Inch		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	37 Inch		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Feb 2, 2021 8:33:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	-	right rear seal leaking.	RGASPARD	Feb 2, 2021 8:33:07 PM	Yes	54264417
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done	na	RGASPARD	Feb 2, 2021 8:33:07 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	12143 Cycles		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Feb 2, 2021 8:33:07 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54173847
Invoice No. 55345 - 54173847

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMC
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 251,680 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Feb-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96
02-Feb-21	65266	PLUG, DRAIN, OIL, ENGINE	1	4.25	4.25

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Feb-21	Gaspard,Ronald	0.67	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: RGASPARD Performed on: 02-FEB-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Feb 2, 2021 8:42:35 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Feb 2, 2021 8:42:35 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Feb 2, 2021 8:42:35 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Feb 2, 2021 8:42:35 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Feb 2, 2021 8:42:35 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Feb 2, 2021 8:42:35 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	na	RGASPARD	Feb 2, 2021 8:42:35 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Feb 2, 2021 8:42:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Feb 2, 2021 8:42:35 PM	No	
201,000 - Service Crankcase Breather	Done		RGASPARD	Feb 2, 2021 8:42:35 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Feb 2, 2021 8:42:35 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Feb 2, 2021 8:42:35 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Feb 2, 2021 8:42:35 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		RGASPARD	Feb 2, 2021 8:42:35 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		RGASPARD	Feb 2, 2021 8:42:35 PM	No	
302,000 - Check Toe-In and Record Reading	-	na	RGASPARD	Feb 2, 2021 8:42:35 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	na	RGASPARD	Feb 2, 2021 8:42:35 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		RGASPARD	Feb 2, 2021 8:42:35 PM	No	
305,000 - FRA Change Differential Fluid	Yes		RGASPARD	Feb 2, 2021 8:42:35 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	6.21
Labor:	0.00
Labor Hours:	0.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**6.21**

Work Order Footer

Work Order 54173847 Total	
Parts:	6.21
Labor:	0.00
Labor Hours:	2.34
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**6.21**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54087992
Invoice No. 55345 - 54087992

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	247,562 - DH

Chronology		
Reported	Dec 31, 2020 8:58:50 AM	Dec 31, 2020 8:58:50 AM
Started	Jan 1, 2021 8:33:00 AM	
Completed	Jan 1, 2021 1:49:00 PM	Jan 1, 2021 1:49:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA

CAUSE: preventive maintenance

CORRECTION: Performed service lube all pivoting point cross tires completed

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 01-JAN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Jan 1, 2021 12:14:45 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Jan 1, 2021 12:14:45 PM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Jan 1, 2021 12:14:45 PM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Jan 1, 2021 12:14:45 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Jan 1, 2021 12:14:45 PM	No	
10 - Have you successfully completed the Personal	Done		HPIERRE	Jan 1, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				12:14:45 PM		
20 - Miles			HPIERRE	Jan 1, 2021 12:14:45 PM	No	
30 - Kilometers			HPIERRE	Jan 1, 2021 12:14:45 PM	No	
40 - Hours	5		HPIERRE	Jan 1, 2021 12:14:45 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54087992
Invoice No. 55345 - 54087992

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	247,562 - DH

Activity Header
Activity: 10
Activity Note: Light Duty PMI
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: HPIERRE Performed on: 01-JAN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
20,800 - INSPECT_High Idle Control	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
31,000 - SSF (Street Side Front)	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
32,000 - Engine Inspection	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,010 - INSPECT_Hood, Springs and Props	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	190 Degree Fahrenheit		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
32,100 - INSPECT_Intake System	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12 Volt*		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
33,010 - CSF (Curb Side Front)	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	12 Volt*		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
50,400 - LUBE_All Chassis Components	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
50,700 - INSPECT_Tire Condition	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		HPIERRE	Jan 1, 2021 12:30:49 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.7 Inch		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.7 Inch		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
52,100 - INSPECT_Vibration Damper	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
53,600 - INSPECT_Tire Condition	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Jan 1, 2021 12:30:49 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	1.7 Inch		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	1.7 Inch		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	1212 Cycles		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
62,400 - INSPECT_All Pivot Points	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
62,500 - INSPECT_Cams and Slots	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
62,600 - INSPECT_Rollers	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
62,700 - INSPECT_All Linkages	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		HPIERRE	Jan 1, 2021 12:30:49 PM	No	

Activity Sub Total

Activity 10 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54087992
Invoice No. 55345 - 54087992

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	247,562 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Jan-21	Pierre,Hubert J	5.27	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 01-JAN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Jan 1, 2021 12:13:58 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Jan 1, 2021 12:13:58 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Jan 1, 2021 12:13:58 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Jan 1, 2021 12:13:58 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Jan 1, 2021 12:13:58 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Jan 1, 2021 12:13:58 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		HPIERRE	Jan 1, 2021 12:13:58 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Jan 1, 2021 12:13:58 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	5.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

	Work Order 54087992 Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	5.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54117954
Invoice No. 55345 - 54117954

Client Department:
Department: 55345M
Work Order Description
O2 Sensor and Catalytic Converter
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 244,699 - DH

Chronology		
Reported	Dec 9, 2020 6:57:48 AM	Dec 9, 2020 6:57:48 AM
Started	Dec 9, 2020 7:01:00 AM	
Completed	Dec 9, 2020 8:25:00 AM	Dec 9, 2020 8:25:00 AM
Down Time		

Work Order Notes

Line 10 Complaint. Check engine light on

Cause. Faulty O2 sensor, bank 1 sensor 1.

Correction. Removed and replaced O 2 sensor, all okay at this time.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 09-DEC-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Dec 9, 2020 8:23:14 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Dec 9, 2020 8:23:14 AM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Dec 9, 2020 8:23:14 AM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Dec 9, 2020 8:23:14 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Dec 9, 2020 8:23:14 AM	No	
10 - Have you successfully completed the	Done		RAURODRIGUEZ	Dec 9, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				8:23:14 AM		
20 - Miles			RAURODRIGUEZ	Dec 9, 2020 8:23:14 AM	No	
30 - Kilometers			RAURODRIGUEZ	Dec 9, 2020 8:23:14 AM	No	
40 - Hours			RAURODRIGUEZ	Dec 9, 2020 8:23:14 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54117954
Invoice No. 55345 - 54117954

Client Department:
Department: 55345M
Work Order Description
O2 Sensor and Catalytic Converter
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 244,699 - DH

Activity Header
Activity: 20 043/000/000 EXHAUST SYSTEM
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Dec-20	8F9Z-9F472-H	SENSOR, OXYGEN	1	70.83	70.83

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Dec-20	Rodriguez,Raul	1.35	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	70.83
Labor:	0.00
Labor Hours:	1.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**70.83**

Work Order Footer

Work Order 54117954 Total	
Parts:	70.83
Labor:	0.00
Labor Hours:	1.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**70.83**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54117579
Invoice No. 55345 - 54117579

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Emergency flasher button stuck.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	244,699 - DH

Chronology		
Reported	Dec 8, 2020 11:34:19 PM	Dec 8, 2020 11:34:19 PM
Started	Dec 8, 2020 11:35:00 PM	
Completed	Dec 9, 2020 12:08:00 AM	Dec 9, 2020 12:08:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Emergency flasher button stuck.

Cause: Wear and tear.

Correction: Remove and replaced multifunction switch.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Dec-20	Earl Johnson	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 08-DEC-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Dec 8, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:43:09 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Dec 8, 2020 11:43:09 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Dec 8, 2020 11:43:09 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Dec 8, 2020 11:43:09 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Dec 8, 2020 11:43:09 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Dec 8, 2020 11:43:09 PM	No	
20 - Miles			EARJOHNSON	Dec 8, 2020 11:43:09 PM	No	
30 - Kilometers			EARJOHNSON	Dec 8, 2020 11:43:09 PM	No	
40 - Hours			EARJOHNSON	Dec 8, 2020 11:43:09 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54117579
Invoice No. 55345 - 54117579

Client Department:
Department: 55345M
Work Order Description
Emergency flasher button stuck.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 244,699 - DH

Activity Header
Activity: 15 050/000/000 GROUP, ACCESSORIES
Activity Note: Emrgency flashers.
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Dec-20	7F1Z-13K359-AB	SWITCH, MULTIFUNCTION, SIGNAL, TURN	1	180.02	180.02

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Dec-20	Earl Johnson	0.12	0	0
08-Dec-20	Earl Johnson	0.42	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	180.02
Labor:	0.00
Labor Hours:	0.54
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**180.02**

Work Order Footer

Work Order 54117579 Total	
Parts:	180.02
Labor:	0.00
Labor Hours:	0.61
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**180.02**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54087985
Invoice No. 55345 - 54087985

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	243,450 - DH

Chronology		
Reported	Nov 26, 2020 8:34:32 PM	Nov 26, 2020 8:34:32 PM
Started	Nov 26, 2020 9:03:00 PM	
Completed	Nov 26, 2020 10:23:00 PM	Nov 26, 2020 10:23:00 PM
Down Time		

Work Order Notes

Line 10 Replaced front brake pads. Remove and replaced RF caliper bracket.

Activity Header

Activity: 10 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: Out of spec.
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Nov-20	Earl Johnson	0.93	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54087985
Invoice No. 55345 - 54087985

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	243,450 - DH

Activity Header
Activity:20 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: Out of spec.
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Nov-20	BC2Z-2552-B	CALIPER, BRAKE, DISC, REAR, RH, E450	1	80.59	80.59
26-Nov-20	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	42.89	42.89

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Nov-20	Earl Johnson	0.35	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	123.48
Labor:	0.00
Labor Hours:	0.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**123.48**

Work Order Footer

Work Order 54087985 Total	
Parts:	123.48
Labor:	0.00
Labor Hours:	1.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**123.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53987879
Invoice No. 55345 - 53987879

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	243,450 - DH

Chronology		
Reported	Nov 25, 2020 12:00:00 AM	Nov 25, 2020 12:00:00 AM
Started	Nov 26, 2020 7:16:00 PM	
Completed	Nov 26, 2020 9:02:00 PM	Nov 26, 2020 9:02:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PM A service.

CAUSE: Due by Mileage.

CORRECTION: LOF engine oil and filter. Performed tire and brake inspection.

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Nov-20	Earl Johnson	0.2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 26-NOV-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Nov 26, 2020 8:49:47 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Nov 26, 2020 8:49:47 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Nov 26, 2020 8:49:47 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Nov 26, 2020 8:49:47 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Nov 26, 2020 8:49:47 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Nov 26, 2020 8:49:47 PM	No	
20 - Miles			EARJOHNSON	Nov 26, 2020 8:49:47 PM	No	
30 - Kilometers			EARJOHNSON	Nov 26, 2020 8:49:47 PM	No	
40 - Hours			EARJOHNSON	Nov 26, 2020 8:49:47 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53987879
Invoice No. 55345 - 53987879

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 243,450 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Nov-20	Earl Johnson	1.33	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: EARJOHNSON Performed on: 26-NOV-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
20,800 - INSPECT_High Idle Control	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
31,000 - SSF (Street Side Front)	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
32,000 - Engine Inspection	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	NA	EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
32,100 - INSPECT_Intake System	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	Volt*	NA	EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
33,010 - CSF (Curb Side Front)	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	12.6 Volt*		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
50,400 - LUBE_All Chassis Components	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
50,700 - INSPECT_Tire Condition	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	7 32nds of an inch		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	4 32nds of an inch	Out of spec.	EARJOHNSON	Nov 26, 2020 8:36:23 PM	Yes	54087985
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	4 32nds of an inch	Out of spec.	EARJOHNSON	Nov 26, 2020 8:36:23 PM	Yes	54087985
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.505 Inch		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.5 Inch		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
52,100 - INSPECT_Vibration Damper	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
53,600 - INSPECT_Tire Condition	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	9 32nds of an inch		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	7 32nds of an inch		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	1.49 Inch		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	1.487 Inch		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	15754 Cycles		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
62,400 - INSPECT_All Pivot Points	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
62,500 - INSPECT_Cams and Slots	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
62,600 - INSPECT_Rollers	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
62,700 - INSPECT_All Linkages	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		EARJOHNSON	Nov 26, 2020 8:36:23 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53987879
Invoice No. 55345 - 53987879

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 243,450 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Nov-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Nov-20	Earl Johnson	0.22	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: EARJOHNSON Performed on: 26-NOV-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		EARJOHNSON	Nov 26, 2020 8:37:34 PM	No	
101,000 - FRA Change Oil Filters	Yes		EARJOHNSON	Nov 26, 2020 8:37:34 PM	No	
102,000 - FRA Drain Engine Oil	Yes		EARJOHNSON	Nov 26, 2020 8:37:34 PM	No	
103,000 - FRA Check Transmission Fluid	Done		EARJOHNSON	Nov 26, 2020 8:37:34 PM	No	
104,000 - Lubricate Chassis	Done		EARJOHNSON	Nov 26, 2020 8:37:34 PM	No	
105,000 - Replace or Clean A/C Filters	Done		EARJOHNSON	Nov 26, 2020 8:37:34 PM	No	
107,000 - FRA Change Primary Fuel Filter	No		EARJOHNSON	Nov 26, 2020 8:37:34 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		EARJOHNSON	Nov 26, 2020 8:37:34 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order Footer

Work Order 53987879 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	1.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54076927
Invoice No. 55345 - 54076927

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345 Transmission DTC P-0713		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	242,732 - DH

Chronology		
Reported	Nov 23, 2020 6:35:45 AM	Nov 23, 2020 6:35:45 AM
Started	Nov 23, 2020 6:37:00 AM	
Completed	Nov 23, 2020 12:00:00 PM	Nov 23, 2020 12:00:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: check engine light on

Cause: trouble code,p0713 transmission

Correction: Removed and Replaced internal transmission wire harness and gasket,temperature sensor
Drove test vehicle all okay at this time

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 23-NOV-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Nov 23, 2020 11:57:27 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Nov 23, 2020 11:57:27 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Nov 23, 2020 11:57:27 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Nov 23, 2020 11:57:27 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Nov 23, 2020 11:57:27 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Nov 23, 2020 11:57:27 AM	No	
20 - Miles			NPIERRE-LOUIS	Nov 23, 2020 11:57:27 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Nov 23, 2020 11:57:27 AM	No	
40 - Hours			NPIERRE-LOUIS	Nov 23, 2020 11:57:27 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54076927
Invoice No. 55345 - 54076927

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345 Transmission DTC P-0713		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	242,732 - DH

Activity Header
Activity: 20 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Nov-20	11396003	SENDER, FUEL	1	95.08	95.08
30-Nov-20	BC3Z-7H141-A	SENSOR, TEMPERATURE, TRANSMISSION	1	11.55	11.55
30-Nov-20	4C3Z-7G276-AA	HARNESS, SOLENOID, INTERNAL, TRANSMISSION, 5R110W	1	137.76	137.76
30-Nov-20	8C3Z-7C155-A	GASKET, BODY, VALVE, TRANSMISSION, 5R110	1	7.53	7.53
30-Nov-20	20021	FILTER, TRANSMISSION 20021	1	17.27	17.27

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Nov-20	NELSON PIERRE-LOUIS	5.32	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	269.19
Labor:	0.00
Labor Hours:	5.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**269.19**

Work Order Footer

Work Order 54076927 Total	
Parts:	269.19
Labor:	0.00
Labor Hours:	5.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**269.19**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53987862
Invoice No. 55345 - 53987862

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP---> Coolant Leak And Rear A/C Blowing Hot
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 239,014 - DH

Chronology		
Reported	Oct 22, 2020 10:46:47 PM	Oct 22, 2020 10:46:47 PM
Started	Oct 22, 2020 11:11:00 PM	
Completed	Oct 23, 2020 12:01:00 AM	Oct 23, 2020 12:01:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========
To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.
==========

Complaint: Rear A/C / Coolant Leak.

Cause: Coolant Leaking from heather bypass hose clamp / rear A/C Compressor not coming on.

Correction: Check Rear A/C pressure Pressure Ok . Adjust thermostat switch set too high. A/C Ok at this time. Secure heather hose bypass clamp.

Activity Header
Activity: 10 001/002/015 HEATER
Activity Note: Rear A/C
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Oct-20	Arthurs,Durvin	0.48	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53987862
Invoice No. 55345 - 53987862

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP---> Coolant Leak And Rear A/C Blowing Hot
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 239,014 - DH

Activity Header
Activity:20 042/002/044 CAP, TANK, SURGE
Activity Note: Coolant Leak
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Oct-20	Arthurs,Durvin	0.33	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53987862 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.81
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53876299
Invoice No. 55345 - 53876299

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-LIGHT DUTY PMB		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	239,014 - DH

Chronology		
Reported	Oct 22, 2020 12:00:00 AM	Oct 22, 2020 12:00:00 AM
Started	Oct 22, 2020 9:15:00 PM	
Completed	Oct 22, 2020 11:11:00 PM	Oct 22, 2020 11:11:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PMB Service

CAUSE: Service Due by Mileage.

CORRECTION: Change Oil & Filter. Lube all Pivoting Points . Check brakes. Clean batteries.. replace air filter.
Parts # B329 Qty (1)
Parts # PA 4075 Qty (1)
Oil 10W20 Qty (7) Qt

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 22-OCT-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Oct 22, 2020 10:50:53 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Oct 22, 2020 10:50:53 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Oct 22, 2020 10:50:53 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Oct 22, 2020 10:50:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Oct 22, 2020 10:50:53 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Oct 22, 2020 10:50:53 PM	No	
20 - Miles			DARTHURS	Oct 22, 2020 10:50:53 PM	No	
30 - Kilometers			DARTHURS	Oct 22, 2020 10:50:53 PM	No	
40 - Hours			DARTHURS	Oct 22, 2020 10:50:53 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53876299
Invoice No. 55345 - 53876299

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-LIGHT DUTY PMB		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	239,014 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Oct-20	Arthurs,Durvin	1.52	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53876299
Invoice No. 55345 - 53876299

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMB
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 239,014 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Oct-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96
22-Oct-20	PA4075	FILTER, AIR SEE P546597	1	5.28	5.28

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Oct-20	Arthurs,Durvin	0.38	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: DARTHURS Performed on: 22-OCT-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Oct 22, 2020 10:49:59 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Oct 22, 2020 10:49:59 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Oct 22, 2020 10:49:59 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Oct 22, 2020 10:49:59 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Oct 22, 2020 10:49:59 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Oct 22, 2020 10:49:59 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Oct 22, 2020 10:49:59 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Oct 22, 2020 10:49:59 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	Oct 22, 2020 10:49:59 PM	No	
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Oct 22, 2020 10:49:59 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		DARTHURS	Oct 22, 2020 10:49:59 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Oct 22, 2020 10:49:59 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Oct 22, 2020 10:49:59 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	7.24
Labor:	0.00
Labor Hours:	0.38
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.24**

Work Order Footer

Work Order 53876299 Total	
Parts:	7.24
Labor:	0.00
Labor Hours:	1.90
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.24**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53963204
Invoice No. 55345 - 53963204

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
check Brakes		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	237,948 - DH

Chronology		
Reported	Oct 14, 2020 11:39:00 PM	Oct 14, 2020 11:39:00 PM
Started	Oct 15, 2020 9:46:00 AM	
Completed	Oct 16, 2020 3:13:00 PM	Oct 16, 2020 3:13:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: per driver, brakes making noise

Cause: leaking Hydro booster

Correction: Replaced hydro booster

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 15-OCT-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Oct 15, 2020 4:34:11 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Oct 15, 2020 4:34:11 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Oct 15, 2020 4:34:11 PM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Oct 15, 2020 4:34:11 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Oct 15, 2020 4:34:11 PM	No	
10 - Have you successfully completed the Personal	Done		TDELVA	Oct 15, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				4:34:11 PM		
20 - Miles			TDELVA	Oct 15, 2020 4:34:11 PM	No	
30 - Kilometers			TDELVA	Oct 15, 2020 4:34:11 PM	No	
40 - Hours			TDELVA	Oct 15, 2020 4:34:11 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53963204
Invoice No. 55345 - 53963204

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
check Brakes		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	237,948 - DH

Activity Header
Activity: 20
Activity Note: VERIFY COMPLAINT
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53963204
Invoice No. 55345 - 53963204

Client Department:
Department: 55345M
Work Order Description
check Brakes
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 237,948 - DH

Activity Header
Activity: 30 013 BRAKES
Activity Note: Hydro Booster
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Oct-20	DC2Z-2005-A	BOOSTER, BRAKE, POWER, HYDRAULIC SAME AS BRB-103	1	185.97	185.97

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Oct-20	Delva,Terry	6.77	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	185.97
Labor:	0.00
Labor Hours:	6.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**185.97**

Work Order Footer

Work Order 53963204 Total	
Parts:	185.97
Labor:	0.00
Labor Hours:	6.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**185.97**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53887167
Invoice No. 55345 - 53887167

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
RD CALL		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	235,274 - DH

Chronology		
Reported	Sep 18, 2020 11:37:00 PM	Sep 18, 2020 11:37:00 PM
Started	Sep 18, 2020 11:40:00 PM	
Completed	Sep 30, 2020 10:32:00 AM	Sep 30, 2020 10:32:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: bi door not closing

Cause: bi door switch had internal fault

Correction: replaced bi door switch ab09001

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 25-SEP-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Sep 25, 2020 11:55:20 AM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		NPIERRE-	Sep 25, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?			LOUIS	11:55:20 AM		
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Sep 25, 2020 11:55:20 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Sep 25, 2020 11:55:20 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Sep 25, 2020 11:55:20 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Sep 25, 2020 11:55:20 AM	No	
20 - Miles			NPIERRE-LOUIS	Sep 25, 2020 11:55:20 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Sep 25, 2020 11:55:20 AM	No	
40 - Hours			NPIERRE-LOUIS	Sep 25, 2020 11:55:20 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53887167
Invoice No. 55345 - 53887167

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
RD CALL		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	235,274 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Check Bi Fold Doors
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Sep-20	8C2Z-3304-C	LINK, DRAG, STEERING	1	82.52	82.52
30-Sep-20	F6UZ-18C680-AA	MOTOR & BRACKET, A/C	2	33.49	66.98

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Sep-20	Stephen Harrington	0.32	0	0
25-Sep-20	NELSON PIERRE-LOUIS	2.15	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	149.50
Labor:	0.00
Labor Hours:	2.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**149.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53887167
Invoice No. 55345 - 53887167

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
RD CALL		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	235,274 - DH

Activity Header
Activity: 25 052RTD STARTING SYSTEMS
Activity Note: RD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53887167 Total	
Parts:	149.50
Labor:	0.00
Labor Hours:	2.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**149.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53907347
Invoice No. 55345 - 53907347

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345 PER DVIR Stalling		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	236,160 - DH

Chronology		
Reported	Sep 26, 2020 12:03:00 AM	Sep 26, 2020 12:03:00 AM
Started	Sep 28, 2020 10:30:00 AM	
Completed	Sep 29, 2020 1:11:00 PM	Sep 29, 2020 1:11:00 PM
Down Time		

Work Order Notes

Line 10 C: vehicle stalls

C: Check computer system found no codes, inspect all systems

C: Clean all grounds and replaced crankshaft Sensor

Part:
1 new crank sensor tw7z-6c315-ab

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 29-SEP-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Sep 29, 2020 1:11:20 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Sep 29, 2020 1:11:20 PM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Sep 29, 2020 1:11:20 PM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Sep 29, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				1:11:20 PM		
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Sep 29, 2020 1:11:20 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Sep 29, 2020 1:11:20 PM	No	
20 - Miles			HPIERRE	Sep 29, 2020 1:11:20 PM	No	
30 - Kilometers	12		HPIERRE	Sep 29, 2020 1:11:20 PM	No	
40 - Hours	4		HPIERRE	Sep 29, 2020 1:11:20 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53907347
Invoice No. 55345 - 53907347

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR Stalling
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 236,160 - DH

Activity Header
Activity: 20 030 ELECTRICAL GROUP
Activity Note: VEHICLE STALLING
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Sep-20	1W7Z-6C315-AB	SENSOR, POSITION, CRANKSHAFT	1	28.41	28.41

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Sep-20	Perez,Javier	0.47	0	0
28-Sep-20	Perez,Javier	4.32	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	28.41
Labor:	0.00
Labor Hours:	4.79
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**28.41**

Work Order Footer

Work Order 53907347 Total	
Parts:	28.41
Labor:	0.00
Labor Hours:	4.79
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**28.41**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53908236
Invoice No. 55345 - 53908236

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Vehicle stalling.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	236,107 - DH

Chronology		
Reported	Sep 27, 2020 12:43:47 PM	Sep 27, 2020 12:43:47 PM
Started	Sep 27, 2020 2:52:00 PM	
Completed	Sep 27, 2020 3:58:00 PM	Sep 27, 2020 3:58:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Vehicle keeps stalling.

Cause: Suspected PCM fault.

Correction: TBD. Line 20 Scanned vehicle found that there was a P0340 code present. Replaced cam sensor and road tested vehicle and it stalled at Golf Rd. and congress. After 20 mins vehicle restarted and I made it to the base parking lot where it stalled again. After sitting 20mins vehicle started. Suspected PCM fault.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Sep-20	Earl Johnson	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 27-SEP-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Sep 27, 2020 2:44:52 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Sep 27, 2020 2:44:52 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Sep 27, 2020 2:44:52 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Sep 27, 2020 2:44:52 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Sep 27, 2020 2:44:52 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Sep 27, 2020 2:44:52 PM	No	
20 - Miles			EARJOHNSON	Sep 27, 2020 2:44:52 PM	No	
30 - Kilometers			EARJOHNSON	Sep 27, 2020 2:44:52 PM	No	
40 - Hours			EARJOHNSON	Sep 27, 2020 2:44:52 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53908236
Invoice No. 55345 - 53908236

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Vehicle stalling.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	236,107 - DH

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Sep-20	Earl Johnson	1.08	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53908236 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.15
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 53707699
Invoice No. 55345 - 53707699

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	234,691 - DH

Chronology		
Reported	Sep 15, 2020 12:00:00 AM	Sep 15, 2020 12:00:00 AM
Started	Sep 15, 2020 11:14:00 PM	
Completed	Sep 16, 2020 12:47:00 AM	Sep 16, 2020 12:47:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA

CAUSE: service

CORRECTION: perform PMA service
Oil filter B329 qty1
Engine oil 10w30 qty 7 qts

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 16-SEP-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Sep 16, 2020 12:14:38 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Sep 16, 2020 12:14:38 AM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Sep 16, 2020 12:14:38 AM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Sep 16, 2020 12:14:38 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Sep 16, 2020 12:14:38 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Sep 16, 2020 12:14:38 AM	No	
20 - Miles			RGASPARD	Sep 16, 2020 12:14:38 AM	No	
30 - Kilometers			RGASPARD	Sep 16, 2020 12:14:38 AM	No	
40 - Hours			RGASPARD	Sep 16, 2020 12:14:38 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 53707699
Invoice No. 55345 - 53707699

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	234,691 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Sep-20	Gaspard,Ronald	0.77	0	0
16-Sep-20	Gaspard,Ronald	0.33	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 53707699
Invoice No. 55345 - 53707699

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	234,691 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Sep-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Sep-20	Gaspard,Ronald	0.2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 16-SEP-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Sep 16, 2020 12:21:25 AM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Sep 16, 2020 12:21:25 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Sep 16, 2020 12:21:25 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Sep 16, 2020 12:21:25 AM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Sep 16, 2020 12:21:25 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Sep 16, 2020 12:21:25 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Sep 16, 2020 12:21:25 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Sep 16, 2020 12:21:25 AM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	0.20
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 53707699
Invoice No. 55345 - 53707699

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	234,691 - DH

Activity Header
Activity: 30 055/023 LIFT, WHEELCHAIR, PASSENGER
Activity Note: 55345-W/C LIFT INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Sep-20	Gaspard,Ronald	0.2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: 55345-W/C LIFT INSPECTION
Task: First Transit Wheelchair Lift Inspection Performed by: RGASPARD Performed on: 16-SEP-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Wheelchair Cycle Count	13850 Cycles		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
1,000 - A.1 Check Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
2,000 - A.2 Check Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
3,000 - Operate Lift Through Complete Cycle and Check for:	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
3,003 - A.3 Unusual Noises	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
3,004 - A.4 Jerky Operation	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
3,005 - A.5 Operated Too Slowly or Too Fast	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
3,006 - A.6 Drift Down	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
7,000 - A.7 Check Bridgeplate Operation	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
8,000 - A.8 Check All Pivot Points for Wear and Looseness	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
9,000 - A.9 Check Rollers for Wear and Smooth Rotation	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
11,000 - A.11 Check Operation of Platform Barrier Mechanism	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
12,000 - A.12 Check Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
13,000 - A.13 Check Cable Condition (If Applicable)	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
14,000 - A.14 Check Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
15,000 - A.15 Check Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
16,000 - A.16 Check Operation and Adjustment of All Safety Switches	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
17,000 - A.17 Check All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
18,000 - A.18 Check the Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
19,000 - A.19 Check HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
20,000 - A.20 Are Operator Decals in Place? Consult Service Manual for Information.	Yes		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
21,000 - A.21 Check WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
90,000 - Clean all Linkages and Mechanisms If Needed before Lubrication	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
91,000 - Lubricate (Don¿t OVER Lubricate)	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
100,000 - B.1 Emergency Platform Release Mechanism	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
200,000 - B.2 Platform Barrier Latch Mechanism	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
300,000 - B.3 Bridgeplate Hinge	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
400,000 - B.4 All Pivot Points	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
500,000 - B.5 Cams and Slots	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
600,000 - B.6 Rollers	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	
700,000 - B.7 All Linkages	Done		RGASPARD	Sep 16, 2020 12:34:42 AM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53707699 Total	
Parts:	1.96

	Labor:	0.00
	Labor Hours:	1.50
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 53857739
Invoice No. 55345 - 53857739

Client Department:
Department: 55345M
Work Order Description
Bus Making Growling Noise
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 234,209 - DH

Chronology		
Reported	Sep 9, 2020 8:42:00 PM	Sep 9, 2020 8:42:00 PM
Started	Sep 9, 2020 9:35:00 PM	
Completed	Sep 11, 2020 1:16:00 PM	Sep 11, 2020 1:16:00 PM
Down Time		

Work Order Notes

Line 10 Complaint. Bus Making Growling Noise

Cause. Bad Pulleys and rear ac compressor

Correction. Removed and replaced pulleys and compressor

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Sep-20	F7UZ-6038-DC	MOUNT, MOTOR, FRONT	1	36.31	36.31

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 11-SEP-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Sep 11, 2020 1:05:19 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Sep 11, 2020 1:05:19 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Sep 11, 2020 1:05:19 PM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Sep 11, 2020 1:05:19 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Sep 11, 2020 1:05:19 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Sep 11, 2020 1:05:19 PM	No	
20 - Miles			RAURODRIGUEZ	Sep 11, 2020 1:05:19 PM	No	
30 - Kilometers			RAURODRIGUEZ	Sep 11, 2020 1:05:19 PM	No	
40 - Hours			RAURODRIGUEZ	Sep 11, 2020 1:05:19 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	36.31
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**36.31**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 53857739
Invoice No. 55345 - 53857739

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Bus Making Growling Noise		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	234,209 - DH

Activity Header
Activity: 20 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: VERIFY COMPLAINT
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Sep-20	Gaspard,Ronald	1.72	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 53857739
Invoice No. 55345 - 53857739

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Bus Making Growling Noise		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	234,209 - DH

Activity Header
Activity: 30 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Bus Making Growling Noise
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Sep-20	Rodriguez,Raul	2.55	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 53857739
Invoice No. 55345 - 53857739

Client Department:
Department: 55345M
Work Order Description
Bus Making Growling Noise
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 234,209 - DH

Activity Header
Activity: 40 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 51 Inoperative
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Sep-20	GC2Z-10346-C	ALTERNATOR, 6.8L, E350	1	242.66	242.66
11-Sep-20	89026	PULLEY, IDLER, SMOOTH	1	13.57	13.57
11-Sep-20	89263	TENSIONER, BELT, SERPENTINE	1	29.42	29.42
11-Sep-20	14565100C	COVER, LOUVER, EVAPORATOR, A/C	2	15.38	30.76
11-Sep-20	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	21	21
11-Sep-20	3411885	TUBE, ORIFICE, A/C, FORD	1	0.75	0.75

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Sep-20	Rodriguez,Raul	2.47	0	0
11-Sep-20	Rodriguez,Raul	6.05	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	338.16
Labor:	0.00
Labor Hours:	8.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**338.16**

Work Order Footer

Work Order 53857739 Total	
Parts:	374.47
Labor:	0.00
Labor Hours:	12.79
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**374.47**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53822896
Invoice No. 55345 - 53822896

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Repair Mirror		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	232,744 - DH

Chronology		
Reported	Aug 27, 2020 10:05:00 PM	Aug 27, 2020 10:05:00 PM
Started		
Completed	Aug 27, 2020 10:09:00 PM	Aug 27, 2020 10:09:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction:

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 27-AUG-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		AOWENS	Aug 27, 2020 10:09:08 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		AOWENS	Aug 27, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				10:09:08 PM		
3 - Are you wearing the appropriate PPE?	Done		AOWENS	Aug 27, 2020 10:09:08 PM	No	
4 - Have you performed the proper LOTO?	Done		AOWENS	Aug 27, 2020 10:09:08 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	Aug 27, 2020 10:09:08 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Aug 27, 2020 10:09:08 PM	No	
20 - Miles			AOWENS	Aug 27, 2020 10:09:08 PM	No	
30 - Kilometers			AOWENS	Aug 27, 2020 10:09:08 PM	No	
40 - Hours			AOWENS	Aug 27, 2020 10:09:08 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53822896
Invoice No. 55345 - 53822896

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Repair Mirror		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	232,744 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Repair Mirror
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Aug-20	709589	MIRROR, CONVEX, SENTRY W/BASE	1	9.33	9.33

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	9.33
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**9.33**

Work Order Footer

Work Order 53822896 Total	
Parts:	9.33
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**9.33**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53815754
Invoice No. 55345 - 53815754

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Repair Rear Bumper		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	232,579 - DH

Chronology		
Reported	Aug 26, 2020 12:01:00 AM	Aug 26, 2020 12:01:00 AM
Started	Aug 26, 2020 6:39:00 AM	
Completed	Aug 27, 2020 12:52:00 PM	Aug 27, 2020 12:52:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: rear side bumper felt off

Cause: driver abuse

Correction:reinstall rear bumper completed

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 27-AUG-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Aug 27, 2020 12:52:26 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		HPIERRE	Aug 27, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				12:52:26 PM		
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Aug 27, 2020 12:52:26 PM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Aug 27, 2020 12:52:26 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Aug 27, 2020 12:52:26 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Aug 27, 2020 12:52:26 PM	No	
20 - Miles			HPIERRE	Aug 27, 2020 12:52:26 PM	No	
30 - Kilometers	12		HPIERRE	Aug 27, 2020 12:52:26 PM	No	
40 - Hours	4		HPIERRE	Aug 27, 2020 12:52:26 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53815754
Invoice No. 55345 - 53815754

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Repair Rear Bumper		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	232,579 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Repair Rear Bumper
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Aug-20	Rodriguez,Raul	0.32	0	0
26-Aug-20	Pierre,Hubert J	4.42	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	4.74
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53815754 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	4.74
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 53755398
Invoice No. 55345 - 53755398

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345 Transmission DTC P-0713		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	232,333 - DH

Chronology		
Reported	Aug 4, 2020 3:10:00 PM	Aug 4, 2020 3:10:00 PM
Started	Aug 4, 2020 3:24:00 PM	
Completed	Aug 21, 2020 10:09:00 PM	Aug 21, 2020 10:09:00 PM
Down Time		

Work Order Notes

Line 10 Complaint drive said that check engine light on

Cause p0173 transmission temperature sensor

Correction replaced sensor temp #bc37-h141-a, gasket 8c3z-7c155-a, harness 4c3z-7g276-aa
SHarrington Line 20 Replaced solenoid #D and internal harness and filter Line 30 C: Check engine light on

C: Check computer system found codes P0765 and P0768 pressure solenoid circuit

C: Replace PCM and Transmission external wire harness retest system and road test vehicle ok at this time

Parts:
1 new PCM dc2z-12a650-abh
1 wire harness dc2z-7c078-s

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: SHARRINGTON Performed on: 04-AUG-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		SHARRINGTON	Aug 4, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:02:12 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		SHARRINGTON	Aug 4, 2020 10:02:12 PM	No	
3 - Are you wearing the appropriate PPE?	Done		SHARRINGTON	Aug 4, 2020 10:02:12 PM	No	
4 - Have you performed the proper LOTO?	Done		SHARRINGTON	Aug 4, 2020 10:02:12 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		SHARRINGTON	Aug 4, 2020 10:02:12 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		SHARRINGTON	Aug 4, 2020 10:02:12 PM	No	
20 - Miles			SHARRINGTON	Aug 4, 2020 10:02:12 PM	No	
30 - Kilometers			SHARRINGTON	Aug 4, 2020 10:02:12 PM	No	
40 - Hours			SHARRINGTON	Aug 4, 2020 10:02:12 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 53755398
Invoice No. 55345 - 53755398

Client Department:
Department: 55345M
Work Order Description
55345 Transmission DTC P-0713
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 232,333 - DH

Activity Header
Activity: 20 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Aug-20	4C3Z-7G276-AA	HARNESS, SOLENOID, INTERNAL, TRANSMISSION, 5R110W	1	123.53	123.53
04-Aug-20	8C3Z-7C155-A	GASKET, BODY, VALVE, TRANSMISSION, 5R110	1	7.53	7.53
04-Aug-20	BC3Z-7H141-A	SENSOR, TEMPERATURE, TRANSMISSION	1	10.49	10.49
06-Aug-20	20021	FILTER, TRANSMISSION 20021	1	17.27	17.27
04-Aug-20	20021	FILTER, TRANSMISSION 20021	1	17.27	17.27

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Aug-20	Stephen Harrington	2.8	0	0
21-Aug-20	Rodriguez,Raul	0.78	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	176.09
Labor:	0.00
Labor Hours:	3.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**176.09**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 53755398
Invoice No. 55345 - 53755398

Client Department:
Department: 55345M
Work Order Description
55345 Transmission DTC P-0713
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 232,333 - DH

Activity Header
Activity: 30 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: Replace Trans Temp Sensor P0713
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Aug-20	3C3Z-7J136-AA	SOLENOID, COAST, TRANSMISSION, 5R110W	1	75.12	75.12

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	75.12
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**75.12**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 53755398
Invoice No. 55345 - 53755398

Client Department:
Department: 55345M
Work Order Description
55345 Transmission DTC P-0713
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 232,333 - DH

Activity Header
Activity: 40 030 ELECTRICAL GROUP
Activity Note: computer progamming
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Aug-20	DC2Z-12A650-ABH	MODULE, CONTROL, ENGINE, ELECTRONIC	1	551.23	551.23
21-Aug-20	DC2Z-7C078-S	HARNESS, TRANSMISSION, EXTERNAL, E450	1	72.46	72.46

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Aug-20	Perez,Javier	13.38	0	0
19-Aug-20	Perez,Javier	5.38	0	0
21-Aug-20	Perez,Javier	12.73	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	623.69
Labor:	0.00
Labor Hours:	31.49
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**623.69**

Work Order Footer

Work Order 53755398 Total	
Parts:	874.90
Labor:	0.00
Labor Hours:	35.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**874.90**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53725093
Invoice No. 55345 - 53725093

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Front A/C not working		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	230,933 - DH

Chronology		
Reported	Jul 23, 2020 12:25:34 PM	Jul 23, 2020 12:25:34 PM
Started	Jul 23, 2020 12:27:00 PM	
Completed	Jul 23, 2020 2:23:00 PM	Jul 23, 2020 2:23:00 PM
Down Time		

Work Order Notes

Line 10 Front A/C not working

Bad blend door actuator

Replaced blend door actuator completed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 23-JUL-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Jul 23, 2020 2:22:56 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Jul 23, 2020 2:22:56 PM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Jul 23, 2020 2:22:56 PM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Jul 23, 2020 2:22:56 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Jul 23, 2020 2:22:56 PM	No	
10 - Have you successfully completed the Personal	Done		HPIERRE	Jul 23, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				2:22:56 PM		
20 - Miles			HPIERRE	Jul 23, 2020 2:22:56 PM	No	
30 - Kilometers	3		HPIERRE	Jul 23, 2020 2:22:56 PM	No	
40 - Hours	5		HPIERRE	Jul 23, 2020 2:22:56 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53725093
Invoice No. 55345 - 53725093

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Front A/C not working		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	230,933 - DH

Activity Header
Activity: 20 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Jul-20	604-200	ACTUATOR, DOOR, BLEND	-1	26.83	-26.83
23-Jul-20	604-200	ACTUATOR, DOOR, BLEND	1	26.83	26.83

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jul-20	Pierre,Hubert J	1.88	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	26.83
Labor:	0.00
Labor Hours:	1.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**26.83**

Work Order Footer

Work Order 53725093 Total	
Parts:	26.83
Labor:	0.00
Labor Hours:	1.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**26.83**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 53707696
Invoice No. 55345 - 53707696

Client Department:
Department: 55345M
Work Order Description
FOLLOW-UP Wheelchair Outer Barrier Flap
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 230,240 - DH

Chronology		
Reported	Jul 17, 2020 11:37:48 PM	Jul 17, 2020 11:37:48 PM
Started	Jul 17, 2020 11:44:00 PM	
Completed	Jul 19, 2020 5:01:00 PM	Jul 19, 2020 5:01:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========
To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.
==========

Complaint: outer barrier lift flap.

Cause: Outer shock weak.found inner threshold plate intermittent.

Correction:Remove & Replace Outer barrier Shocks/ Replace inner flap shocks assembly.Replace up switch.
Parts # 32831 Qty (2(
Parts # 32519KS Qty (1)

Activity Header
Activity: 10 055 HANDLING, CARGO RESTRAINT & LIFT SYSTEM (POWER UNITS, TRAILERS)
Activity Note: Outer Barrier flap
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Jul-20	32831	SPRING, SHOCK, GAS, W/C	2	25.21	50.42
19-Jul-20	32519KS	SWITCH, RAISED, W/C	1	27.98	27.98

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Jul-20	Arthurs,Durvin	3.37	0	0
17-Jul-20	Arthurs,Durvin	0.27	0	0

Booked Date	Technician	Hours	Shop Rate	Extended
18-Jul-20	Arthurs,Durvin	12.62	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	78.40
Labor:	0.00
Labor Hours:	16.26
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**78.40**

Work Order Footer

Work Order 53707696 Total	
Parts:	78.40
Labor:	0.00
Labor Hours:	16.26
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**78.40**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 53604388
Invoice No. 55345 - 53604388

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	230,240 - DH

Chronology		
Reported	Jul 17, 2020 11:15:15 AM	Jul 17, 2020 11:15:15 AM
Started	Jul 17, 2020 3:43:00 PM	
Completed	Jul 17, 2020 11:43:00 PM	Jul 17, 2020 11:43:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PMA Service

CAUSE: Service Due by Mileage.

CORRECTION: Change Oil & Filter. Lube all Pivoting Points. check brakes. Clean batteries. Replace A/C Filter.
Parts # B329 Qty (1)
Oil 10W30 Qty(7.0) Qt

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 17-JUL-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jul 17, 2020 11:19:21 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jul 17, 2020 11:19:21 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jul 17, 2020 11:19:21 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jul 17, 2020 11:19:21 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jul 17, 2020 11:19:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 17, 2020 11:19:21 PM	No	
20 - Miles			DARTHURS	Jul 17, 2020 11:19:21 PM	No	
30 - Kilometers			DARTHURS	Jul 17, 2020 11:19:21 PM	No	
40 - Hours			DARTHURS	Jul 17, 2020 11:19:21 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 53604388
Invoice No. 55345 - 53604388

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	230,240 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Jul-20	Arthurs,Durvin	1.6	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 53604388
Invoice No. 55345 - 53604388

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 230,240 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Jul-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Jul-20	Arthurs,Durvin	0.32	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 17-JUL-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Jul 17, 2020 11:18:13 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Jul 17, 2020 11:18:13 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Jul 17, 2020 11:18:13 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Jul 17, 2020 11:18:13 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Jul 17, 2020 11:18:13 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Jul 17, 2020 11:18:13 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Jul 17, 2020 11:18:13 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Jul 17, 2020 11:18:13 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	0.32
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 53604388
Invoice No. 55345 - 53604388

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	230,240 - DH

Activity Header
Activity: 30 055/023 LIFT, WHEELCHAIR, PASSENGER
Activity Note: 55345-W/C LIFT INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: 55345-W/C LIFT INSPECTION
Task: First Transit Wheelchair Lift Inspection Performed by: DARTHURS Performed on: 17-JUL-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Wheelchair Cycle Count	14460 Cycles		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
1,000 - A.1 Check Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
2,000 - A.2 Check Platform Emergency Release Mechanism for Ease of Operation	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
3,000 - Operate Lift Through Complete Cycle and Check for:	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
3,003 - A.3 Unusual Noises	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
3,004 - A.4 Jerky Operation	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
3,005 - A.5 Operated Too Slowly or Too Fast	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
3,006 - A.6 Drift Down	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
7,000 - A.7 Check Bridgeplate Operation	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
8,000 - A.8 Check All Pivot Points for Wear and Looseness	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
9,000 - A.9 Check Rollers for Wear and Smooth Rotation	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11,000 - A.11 Check Operation of Platform Barrier Mechanism	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
12,000 - A.12 Check Cam Slots for Wear and Proper Alignment	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
13,000 - A.13 Check Cable Condition (If Applicable)	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
14,000 - A.14 Check Hydraulic Hoses for Leaks, Chafing or Cracks	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
15,000 - A.15 Check Electrical Connections and Routing of Wires and Cables	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
16,000 - A.16 Check Operation and Adjustment of All Safety Switches	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
17,000 - A.17 Check All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
18,000 - A.18 Check the Manual Back-up Raise/Lower System (If Applicable)	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
19,000 - A.19 Check HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
20,000 - A.20 Are Operator Decals in Place? Consult Service Manual for Information.	Yes		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
21,000 - A.21 Check WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
90,000 - Clean all Linkages and Mechanisms If Needed before Lubrication	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
91,000 - Lubricate (Don¿t OVER Lubricate)	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
100,000 - B.1 Emergency Platform Release Mechanism	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
200,000 - B.2 Platform Barrier Latch Mechanism	-	Outer Barrier flap	DARTHURS	Jul 17, 2020 11:34:42 PM	Yes	53707696
300,000 - B.3 Bridgeplate Hinge	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
400,000 - B.4 All Pivot Points	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
500,000 - B.5 Cams and Slots	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
600,000 - B.6 Rollers	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	
700,000 - B.7 All Linkages	Done		DARTHURS	Jul 17, 2020 11:34:42 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53604388 Total	
Parts:	1.96
Labor:	0.00

	Labor Hours:	1.92
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53697960
Invoice No. 55345 - 53697960

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Wrench Light On)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 229,845 - DH

Chronology		
Reported	Jul 14, 2020 11:42:00 PM	Jul 14, 2020 11:42:00 PM
Started	Jul 15, 2020 11:29:00 AM	
Completed	Jul 15, 2020 12:21:00 PM	Jul 15, 2020 12:21:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: Wrench Light On

Cause:Tech Found no code no check engine light at this time

Correction: no correction at this point,vehicle is under monitor for codes

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 15-JUL-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Jul 15, 2020 11:41:58 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Jul 15, 2020 11:41:58 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Jul 15, 2020 11:41:58 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Jul 15, 2020 11:41:58 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Jul 15, 2020 11:41:58 AM	No	
10 - Have you successfully completed the Personal	Done		NPIERRE-	Jul 15, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	11:41:58 AM		
20 - Miles			NPIERRE-LOUIS	Jul 15, 2020 11:41:58 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Jul 15, 2020 11:41:58 AM	No	
40 - Hours			NPIERRE-LOUIS	Jul 15, 2020 11:41:58 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53697960
Invoice No. 55345 - 53697960

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Wrench Light On)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 229,845 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: VERIFY COMPLAINT
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Jul-20	NELSON PIERRE-LOUIS	0.87	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53697960 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53670487
Invoice No. 55345 - 53670487

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Rear A/C fan stay on		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	228,589 - DH

Chronology		
Reported	Jul 3, 2020 1:18:36 PM	Jul 3, 2020 1:18:36 PM
Started	Jul 3, 2020 1:20:00 PM	
Completed	Jul 3, 2020 2:28:00 PM	Jul 3, 2020 2:28:00 PM
Down Time		

Work Order Notes

Line 10 Rear A/C fan stays on

Relay board bad

Replaced rally board completed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 03-JUL-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Jul 3, 2020 1:23:05 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Jul 3, 2020 1:23:05 PM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Jul 3, 2020 1:23:05 PM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Jul 3, 2020 1:23:05 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Jul 3, 2020 1:23:05 PM	No	
10 - Have you successfully completed the Personal	Done		HPIERRE	Jul 3, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				1:23:05 PM		
20 - Miles			HPIERRE	Jul 3, 2020 1:23:05 PM	No	
30 - Kilometers	4		HPIERRE	Jul 3, 2020 1:23:05 PM	No	
40 - Hours	2		HPIERRE	Jul 3, 2020 1:23:05 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53670487
Invoice No. 55345 - 53670487

Client Department:

Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Rear A/C fan stay on		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	228,589 - DH

Activity Header
Activity: 20 019 SYSTEM, LUBRICATION, CHASSIS, AUTOMATIC
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Jul-20	27059875A	ACCUMULATOR, A/C	2	80.51	161.02

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jul-20	Pierre,Hubert J	1.13	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	161.02
Labor:	0.00
Labor Hours:	1.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**161.02**

Work Order Footer

Work Order 53670487 Total	
Parts:	161.02
Labor:	0.00
Labor Hours:	1.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**161.02**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53640681
Invoice No. 55345 - 53640681

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
COOLING SISTEM		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	227,763 - DH

Chronology		
Reported	Jun 22, 2020 1:31:00 PM	Jun 22, 2020 1:31:00 PM
Started	Jun 22, 2020 2:07:00 PM	
Completed	Jun 23, 2020 2:33:00 PM	Jun 23, 2020 2:33:00 PM
Down Time		

Work Order Notes

Line 10 C: Vehicle is overheating

C: Check coolant system found top rad hose came off due to too much pressure build in coolant system, further test indicates that possible thermostat is not working as is designed

C: Replaced radiator, thermostat, gasket and rad cap. Retest and road test vehicle long way to check for overheating vehicle works ok at this time

Parts:
1 new radiator under warranty
1 thermostat 7l3z-8575-d
1 gasket f1vy-8255-a
1 rad cap 9c3z-8101-b

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 23-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Jun 23, 2020 2:32:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Jun 23, 2020 2:32:15 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Jun 23, 2020 2:32:15 PM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Jun 23, 2020 2:32:15 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Jun 23, 2020 2:32:15 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Jun 23, 2020 2:32:15 PM	No	
20 - Miles			JAPEREZ	Jun 23, 2020 2:32:15 PM	No	
30 - Kilometers			JAPEREZ	Jun 23, 2020 2:32:15 PM	No	
40 - Hours			JAPEREZ	Jun 23, 2020 2:32:15 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53640681
Invoice No. 55345 - 53640681

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
COOLING SISTEM		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	227,763 - DH

Activity Header
Activity: 20 042 COOLING SYSTEM
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Jun-20	F1VY-8255-A	SEAL, THERMOSTAT	1	4.13	4.13
23-Jun-20	9C3Z-8101-B	CAP, RADIATOR, E450 SAME AS 9C3Z-8101-A & F6DZ-8100-A	1	6.89	6.89
23-Jun-20	7L3Z-8575-D	THERMOSTAT, 4.6L	1	9.91	9.91

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jun-20	Perez,Javier	6.53	0	0
22-Jun-20	Perez,Javier	1.97	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	20.93
Labor:	0.00
Labor Hours:	8.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**20.93**

Work Order Footer

Work Order 53640681 Total	
Parts:	20.93
Labor:	0.00
Labor Hours:	8.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**20.93**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53633974
Invoice No. 55345 - 53633974

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Replace Wiper Blades)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 227,373 - DH

Chronology		
Reported	Jun 18, 2020 9:15:00 PM	Jun 18, 2020 9:15:00 PM
Started		
Completed	Jun 18, 2020 9:21:00 PM	Jun 18, 2020 9:21:00 PM
Down Time		

Work Order Notes

Line 10

Complaint: Need windshield wipers

Cause: Normal usage wear and tear

Correction: Replace wiper blades

Part# 40520 qty 2

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
10 Desc: PRA Task: PRA and Meter Readings Performed by: AOWENS Performed on: 18-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		AOWENS	Jun 18, 2020 9:20:47 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		AOWENS	Jun 18, 2020 9:20:47 PM	No	
3 - Are you wearing the appropriate PPE?	Done		AOWENS	Jun 18, 2020 9:20:47 PM	No	
4 - Have you performed the proper LOTO?	Done		AOWENS	Jun 18, 2020 9:20:47 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	Jun 18, 2020 9:20:47 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Jun 18, 2020 9:20:47 PM	No	
20 - Miles			AOWENS	Jun 18, 2020 9:20:47 PM	No	
30 - Kilometers			AOWENS	Jun 18, 2020 9:20:47 PM	No	
40 - Hours			AOWENS	Jun 18, 2020 9:20:47 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53633974
Invoice No. 55345 - 53633974

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Replace Wiper Blades)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 227,373 - DH

Activity Header
Activity: 20 050 GROUP, ACCESSORIES
Activity Note: VERIFY COMPLAINT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53633974
Invoice No. 55345 - 53633974

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Replace Wiper Blades)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 227,373 - DH

Activity Header
Activity: 30 050 GROUP, ACCESSORIES
Activity Note: Replace Wiper Blades
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Jun-20	40520	BLADE, WIPER, WINDSHIELD, 20"	2	4.16	8.32

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	8.32
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.32**

Work Order Footer

Work Order 53633974 Total	
Parts:	8.32
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53603716
Invoice No. 55345 - 53603716

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345 PER DVIR radiator leak (defective)		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	226,010 - DH

Chronology		
Reported	Jun 5, 2020 10:31:00 PM	Jun 5, 2020 10:31:00 PM
Started	Jun 11, 2020 7:21:00 AM	
Completed	Jun 11, 2020 12:28:00 PM	Jun 11, 2020 12:28:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: vehicle overheating

Cause: Tech Found Radiator was Leaking

Correction: replaced the radiator and add coolant

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 11-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Jun 11, 2020 10:03:19 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Jun 11, 2020 10:03:19 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Jun 11, 2020 10:03:19 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Jun 11, 2020 10:03:19 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Jun 11, 2020 10:03:19 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Jun 11, 2020 10:03:19 AM	No	
20 - Miles			NPIERRE-LOUIS	Jun 11, 2020 10:03:19 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Jun 11, 2020 10:03:19 AM	No	
40 - Hours			NPIERRE-LOUIS	Jun 11, 2020 10:03:19 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53603716
Invoice No. 55345 - 53603716

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR radiator leak (defective)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 226,010 - DH

Activity Header
Activity: 20 042 COOLING SYSTEM
Activity Note: VERIFY COMPLAINT
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Jun-20	NELSON PIERRE-LOUIS	1.03	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53603716
Invoice No. 55345 - 53603716

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR radiator leak (defective)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 226,010 - DH

Activity Header
Activity: 30 042 COOLING SYSTEM
Activity Note: Radiator
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Jun-20	G1000382282CSF	RADIATOR, E450	1	204.35	204.35

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Jun-20	NELSON PIERRE-LOUIS	1.78	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	204.35
Labor:	0.00
Labor Hours:	1.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**204.35**

Work Order Footer

Work Order 53603716 Total	
Parts:	204.35
Labor:	0.00
Labor Hours:	2.81
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**204.35**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53606844
Invoice No. 55345 - 53606844

Client Department:
Department: 55345M
Work Order Description
Road Call
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 226,151 - DH

Chronology		
Reported	Jun 8, 2020 2:05:35 PM	Jun 8, 2020 2:05:35 PM
Started	Jun 8, 2020 2:06:00 PM	
Completed	Jun 11, 2020 8:23:00 AM	Jun 11, 2020 8:23:00 AM
Down Time		

Work Order Notes

Line 20 Complaint. Road call. Vehicle overheated

Cause. Broken Thermostat hose

Correction. Replaced hose and drove back to the base.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 11-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Jun 11, 2020 8:23:04 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Jun 11, 2020 8:23:04 AM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Jun 11, 2020 8:23:04 AM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Jun 11, 2020 8:23:04 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Jun 11, 2020 8:23:04 AM	No	
10 - Have you successfully completed the	Done		RAURODRIGUEZ	Jun 11, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				8:23:04 AM		
20 - Miles			RAURODRIGUEZ	Jun 11, 2020 8:23:04 AM	No	
30 - Kilometers			RAURODRIGUEZ	Jun 11, 2020 8:23:04 AM	No	
40 - Hours			RAURODRIGUEZ	Jun 11, 2020 8:23:04 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53606844
Invoice No. 55345 - 53606844

Client Department:
Department: 55345M
Work Order Description
Road Call
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 226,151 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Jun-20	E71960	HOSE, RADIATOR, 7.3L, '01	1	12.47	12.47

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Jun-20	Rodriguez,Raul	1.83	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	12.47
Labor:	0.00
Labor Hours:	1.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**12.47**

Work Order Footer

Work Order 53606844 Total	
Parts:	12.47
Labor:	0.00
Labor Hours:	1.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**12.47**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 5

Work Order No. 53558500
Invoice No. 55345 - 53558500

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-LIGHT DUTY PMC		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	**Status:**	40 - Closed (40)
Created By:	NSTOLFO	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	226,010 - DH

Chronology		
Reported	Jun 5, 2020 12:00:00 AM	Jun 5, 2020 12:00:00 AM
Started	Jun 7, 2020 1:50:00 PM	
Completed	Jun 7, 2020 2:04:00 PM	Jun 7, 2020 2:04:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: PMC Service

Cause: preventive maintenance

Correction: perform PMC Service and lube all Pivoting Points,and Rear end Service replaced 2 passenger side rear tires

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 07-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Jun 7, 2020 12:49:36 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Jun 7, 2020 12:49:36 PM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Jun 7, 2020 12:49:36 PM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Jun 7, 2020 12:49:36 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Jun 7, 2020 12:49:36 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Jun 7, 2020 12:49:36 PM	No	
20 - Miles			NPIERRE-LOUIS	Jun 7, 2020 12:49:36 PM	No	
30 - Kilometers			NPIERRE-LOUIS	Jun 7, 2020 12:49:36 PM	No	
40 - Hours			NPIERRE-LOUIS	Jun 7, 2020 12:49:36 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 5

Work Order No. 53558500
Invoice No. 55345 - 53558500

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-LIGHT DUTY PMC		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	**Status:**	40 - Closed (40)
Created By:	NSTOLFO	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	226,010 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Jun-20	NELSON PIERRE-LOUIS	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 5

Work Order No. 53558500
Invoice No. 55345 - 53558500

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMC
Requested By: NSTOLFO
Created By: NSTOLFO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 226,010 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Jun-20	20021	FILTER, TRANSMISSION 20021	1	17.27	17.27
07-Jun-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: NPIERRE-LOUIS Performed on: 07-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Jun 7, 2020 12:59:15 PM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Jun 7, 2020 12:59:15 PM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Jun 7, 2020 12:59:15 PM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Jun 7, 2020 12:59:15 PM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Jun 7, 2020 12:59:15 PM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Jun 7, 2020 12:59:15 PM	No	
107,000 - FRA Change Primary Fuel Filter	Done		NPIERRE-LOUIS	Jun 7, 2020 12:59:15 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Jun 7, 2020 12:59:15 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		NPIERRE-	Jun 7, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)			LOUIS	12:59:15 PM		
201,000 - Service Crankcase Breather	Done		NPIERRE-LOUIS	Jun 7, 2020 12:59:15 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		NPIERRE-LOUIS	Jun 7, 2020 12:59:15 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	Yes		NPIERRE-LOUIS	Jun 7, 2020 12:59:15 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		NPIERRE-LOUIS	Jun 7, 2020 12:59:15 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		NPIERRE-LOUIS	Jun 7, 2020 12:59:15 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		NPIERRE-LOUIS	Jun 7, 2020 12:59:15 PM	No	
302,000 - Check Toe-In and Record Reading	Done		NPIERRE-LOUIS	Jun 7, 2020 12:59:15 PM	No	
302,001 - Record Toe-In Reading	0 Inches, fraction-actual		NPIERRE-LOUIS	Jun 7, 2020 12:59:15 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	Yes		NPIERRE-LOUIS	Jun 7, 2020 12:59:15 PM	No	
305,000 - FRA Change Differential Fluid	Yes		NPIERRE-LOUIS	Jun 7, 2020 12:59:15 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	19.23
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**19.23**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 5

Work Order No. 53558500
Invoice No. 55345 - 53558500

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345-LIGHT DUTY PMC		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	**Status:**	40 - Closed (40)
Created By:	NSTOLFO	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	226,010 - DH

Activity Header
Activity: 30 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: 55345-W/C LIFT INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 5

Work Order No. 53558500
Invoice No. 55345 - 53558500

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMC
Requested By: NSTOLFO
Created By: NSTOLFO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 226,010 - DH

Activity Header
Activity: 40 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note: Low tires
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Jun-20	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	117.62	235.24

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Jun-20	NELSON PIERRE-LOUIS	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	235.24
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**235.24**

Work Order Footer

Work Order 53558500 Total	
Parts:	254.47
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**254.47**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53574461
Invoice No. 55345 - 53574461

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Wont start		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	224,808 - DH

Chronology		
Reported	May 26, 2020 12:17:03 PM	May 26, 2020 12:17:03 PM
Started	May 26, 2020 12:19:00 PM	
Completed	May 26, 2020 3:21:00 PM	May 26, 2020 3:21:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: vehicle won¿t start

Cause: Check computer system found misfire on cylinder #8 also hard to start due to bad SRM module

Correction:Replaced ignition coil and a used SRM module

Parts:
1 ignition coil
1 used SRM module

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 26-MAY-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	May 26, 2020 3:21:15 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	May 26, 2020 3:21:15 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	May 26, 2020 3:21:15 PM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	May 26, 2020 3:21:15 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	May 26, 2020 3:21:15 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	May 26, 2020 3:21:15 PM	No	
20 - Miles			JAPEREZ	May 26, 2020 3:21:15 PM	No	
30 - Kilometers			JAPEREZ	May 26, 2020 3:21:15 PM	No	
40 - Hours			JAPEREZ	May 26, 2020 3:21:15 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53574461
Invoice No. 55345 - 53574461

Client Department:
Department: 55345M
Work Order Description
Wont start
Requested By: JAPEREZ
Created By: JAPEREZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 224,808 - DH

Activity Header
Activity: 15 030 ELECTRICAL GROUP
Activity Note: Wont start
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-May-20	3W7Z-12029-AA	COIL, IGNITION SAME AS DG508	1	37.41	37.41

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-May-20	Perez,Javier	2.97	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	37.41
Labor:	0.00
Labor Hours:	2.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**37.41**

Work Order Footer

Work Order 53574461 Total	
Parts:	37.41
Labor:	0.00
Labor Hours:	2.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**37.41**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53557207
Invoice No. 55345 - 53557207

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Rear a/c inop		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	223,878 - DH

Chronology		
Reported	May 18, 2020 12:46:55 PM	May 18, 2020 12:46:55 PM
Started	May 18, 2020 12:50:00 PM	
Completed	May 18, 2020 2:51:00 PM	May 18, 2020 2:51:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:Rear a/c inop

Cause: Check a/c system found condenser cooling fan damaged

Correction:Replaced both fans retest system ok at this time

Parts:
2 cooling fans 27059482a

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 18-MAY-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	May 18, 2020 2:51:23 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	May 18, 2020 2:51:23 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	May 18, 2020 2:51:23 PM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	May 18, 2020 2:51:23 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	May 18, 2020 2:51:23 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	May 18, 2020 2:51:23 PM	No	
20 - Miles			JAPEREZ	May 18, 2020 2:51:23 PM	No	
30 - Kilometers			JAPEREZ	May 18, 2020 2:51:23 PM	No	
40 - Hours			JAPEREZ	May 18, 2020 2:51:23 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53557207
Invoice No. 55345 - 53557207

Client Department:
Department: 55345M
Work Order Description
Rear a/c inop
Requested By: JAPEREZ
Created By: JAPEREZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 223,878 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear a/c inop
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-May-20	27059482A	FAN, CONDENSER, A/C SAME AS 25-14854-S	2	88.18	176.36

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-May-20	Perez,Javier	1.95	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	176.36
Labor:	0.00
Labor Hours:	1.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**176.36**

Work Order Footer

Work Order 53557207 Total	
Parts:	176.36
Labor:	0.00
Labor Hours:	1.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**176.36**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53548273
Invoice No. 55345 - 53548273

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Brakes squeaking.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	223,334 - DH

Chronology		
Reported	May 13, 2020 8:17:40 PM	May 13, 2020 8:17:40 PM
Started	May 13, 2020 8:19:00 PM	
Completed	May 13, 2020 10:20:00 PM	May 13, 2020 10:20:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Brakes squeaking.

Cause: Rear brake pads worn.

Correction: Remove and replaced rear brake pads.
Part# 8C2Z-2200-B Qty.(1).

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-May-20	Earl Johnson	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 13-MAY-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	May 13, 2020 10:09:04 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	May 13, 2020 10:09:04 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	May 13, 2020 10:09:04 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	May 13, 2020 10:09:04 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	May 13, 2020 10:09:04 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	May 13, 2020 10:09:04 PM	No	
20 - Miles			EARJOHNSON	May 13, 2020 10:09:04 PM	No	
30 - Kilometers			EARJOHNSON	May 13, 2020 10:09:04 PM	No	
40 - Hours			EARJOHNSON	May 13, 2020 10:09:04 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53548273
Invoice No. 55345 - 53548273

Client Department:
Department: 55345M
Work Order Description
Brakes squeaking.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 223,334 - DH

Activity Header
Activity: 15 013/000/000 BRAKES
Activity Note: Brakes squeaking.
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-May-20	9C2Z-2V200-B	PADS, BRAKE, DISC, REAR SAME AS BRSD1329B	1	39.96	39.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-May-20	Earl Johnson	1.8	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	39.96
Labor:	0.00
Labor Hours:	1.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**39.96**

Work Order Footer

Work Order 53548273 Total	
Parts:	39.96
Labor:	0.00
Labor Hours:	1.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**39.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53541865
Invoice No. 55345 - 53541865

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
AC doesnt work.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	223,042 - DH

Chronology		
Reported	May 11, 2020 11:13:24 PM	May 11, 2020 11:13:24 PM
Started	May 11, 2020 11:15:00 PM	
Completed	May 11, 2020 11:43:00 PM	May 11, 2020 11:43:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: AC not working.

Cause: Front ac blend door sticking.

Correction: Agitated blend door free.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 11-MAY-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	May 11, 2020 11:37:21 PM	No	
2 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	May 11, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				11:37:21 PM		
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	May 11, 2020 11:37:21 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	May 11, 2020 11:37:21 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	May 11, 2020 11:37:21 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	May 11, 2020 11:37:21 PM	No	
20 - Miles			EARJOHNSON	May 11, 2020 11:37:21 PM	No	
30 - Kilometers			EARJOHNSON	May 11, 2020 11:37:21 PM	No	
40 - Hours			EARJOHNSON	May 11, 2020 11:37:21 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53541865
Invoice No. 55345 - 53541865

Client Department:
Department: 55345M
Work Order Description
AC doesnt work.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 223,042 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: AC doesnt work.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-May-20	Earl Johnson	0.35	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53541865 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53518694
Invoice No. 55345 - 53518694

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Front end		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	222,280 - DH

Chronology		
Reported	May 1, 2020 5:24:59 AM	May 1, 2020 5:24:59 AM
Started	May 1, 2020 7:03:00 AM	
Completed	May 1, 2020 10:54:00 AM	May 1, 2020 10:54:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: vehicle pulling to the left

Cause: Front end has play

Correction: removed and replaced front end.

Rear a/c

Complaint:Rear a/c

Cause: Rear a/c maintenance pre season

Correction:recovered and re charged with 7 lbs of Freon - 6 oz page Oil, Replaced Orifice tube .

Line 20 Vehicle was sent to Elpex good year for wheel alignament.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 01-MAY-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	May 1, 2020 5:27:35 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	May 1, 2020 5:27:35 AM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	May 1, 2020 5:27:35 AM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	May 1, 2020 5:27:35 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	May 1, 2020 5:27:35 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	May 1, 2020 5:27:35 AM	No	
20 - Miles			RAURODRIGUEZ	May 1, 2020 5:27:35 AM	No	
30 - Kilometers			RAURODRIGUEZ	May 1, 2020 5:27:35 AM	No	
40 - Hours			RAURODRIGUEZ	May 1, 2020 5:27:35 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53518694
Invoice No. 55345 - 53518694

Client Department:
Department: 55345M
Work Order Description
Front end
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 222,280 - DH

Activity Header
Activity: 15 015/004 LINKAGE, STEERING
Activity Note: Front end
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-May-20	2U2Z-3V049-A	OUT OF SERVICE JOINT, BALL, UPPER	1	13.57	13.57
01-May-20	8C2Z-3304-C	LINK, DRAG, STEERING	2	99.38	198.76
01-May-20	8C2Z-3E651-B	DAMPER, STEERING SUPERSEDES 6C2Z-3E651-B	1	52.72	52.72
15-May-20	8C2Z-3A130-D	END, TIE-ROD, INNER, LH	-1	44.78	-44.78
01-May-20	8C2Z-3304-C	LINK, DRAG, STEERING	1	99.38	99.38
01-May-20	8C2Z-3A130-D	END, TIE-ROD, INNER, LH	1	44.78	44.78
01-May-20	8C2Z-3A131-C	TIE-ROD, OUTER, LH	2	31.45	62.9
01-May-20	8C2Z-3304-C	LINK, DRAG, STEERING	-2	99.38	-198.76

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-May-20	Rodriguez,Raul	2.33	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	228.57
Labor:	0.00
Labor Hours:	2.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**228.57**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53518694
Invoice No. 55345 - 53518694

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Front end		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	222,280 - DH

Activity Header
Activity: 25 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear ac
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-May-20	3411885	TUBE, ORIFICE, A/C, FORD	1	0.75	0.75

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-May-20	Rodriguez,Raul	1.52	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	0.75
Labor:	0.00
Labor Hours:	1.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.75**

Work Order Footer

Work Order 53518694 Total	
Parts:	229.32
Labor:	0.00
Labor Hours:	3.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**229.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53514380
Invoice No. 55345 - 53514380

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Passenger tire.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	222,155 - DH

Chronology		
Reported	Apr 29, 2020 8:41:46 PM	Apr 29, 2020 8:41:46 PM
Started	Apr 29, 2020 8:45:00 PM	
Completed	Apr 29, 2020 11:27:00 PM	Apr 29, 2020 11:27:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Passenger front tire.

Cause: Uneven wear pattern. (Needs alignment).

Correction: Removed and replaced 2 front tires.
Part# 192659 Qty. (2).

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Apr-20	Earl Johnson	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 29-APR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Apr 29, 2020 10:59:10 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Apr 29, 2020 10:59:10 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Apr 29, 2020 10:59:10 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Apr 29, 2020 10:59:10 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Apr 29, 2020 10:59:10 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Apr 29, 2020 10:59:10 PM	No	
20 - Miles			EARJOHNSON	Apr 29, 2020 10:59:10 PM	No	
30 - Kilometers			EARJOHNSON	Apr 29, 2020 10:59:10 PM	No	
40 - Hours			EARJOHNSON	Apr 29, 2020 10:59:10 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53514380
Invoice No. 55345 - 53514380

Client Department:
Department: 55345M
Work Order Description
Passenger tire.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 222,155 - DH

Activity Header
Activity: 15 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note: Passenger tire.
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Apr-20	Earl Johnson	2.22	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53514380 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53390670
Invoice No. 55345 - 53390670

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	221,618 - DH

Chronology		
Reported	Apr 24, 2020 11:28:28 AM	Apr 24, 2020 11:28:28 AM
Started	Apr 26, 2020 8:14:00 AM	
Completed	Apr 26, 2020 11:54:00 AM	Apr 26, 2020 11:54:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA service

CAUSE: preventive maintenance

CORRECTION: perform pmA service and lube all Pivoting Points

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Apr-20	NELSON PIERRE-LOUIS	3.02	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53390670
Invoice No. 55345 - 53390670

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 221,618 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Apr-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: NPIERRE-LOUIS Performed on: 26-APR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Apr 26, 2020 11:52:50 AM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Apr 26, 2020 11:52:50 AM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Apr 26, 2020 11:52:50 AM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Apr 26, 2020 11:52:50 AM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Apr 26, 2020 11:52:50 AM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Apr 26, 2020 11:52:50 AM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		NPIERRE-LOUIS	Apr 26, 2020 11:52:50 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Apr 26, 2020 11:52:50 AM	No	

Activity Sub Total

Activity 20 Sub Total
Parts: 1.96

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53390670
Invoice No. 55345 - 53390670

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 221,618 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 26-APR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Apr 26, 2020 11:34:02 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Apr 26, 2020 11:34:02 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Apr 26, 2020 11:34:02 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Apr 26, 2020 11:34:02 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Apr 26, 2020 11:34:02 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Apr 26, 2020 11:34:02 AM	No	
20 - Miles			NPIERRE-LOUIS	Apr 26, 2020 11:34:02 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Apr 26, 2020 11:34:02 AM	No	
40 - Hours			NPIERRE-LOUIS	Apr 26, 2020 11:34:02 AM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53390670 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	3.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53461250
Invoice No. 55345 - 53461250

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Check Engine light on		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	220,164 - DH

Chronology		
Reported	Apr 8, 2020 3:47:02 PM	Apr 8, 2020 3:47:02 PM
Started	Apr 8, 2020 3:50:00 PM	
Completed	Apr 8, 2020 5:46:00 PM	Apr 8, 2020 5:46:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Replace Catalytic converter.

Cause: Code P420

Correction: Remove & Replace Catalytic converter & 02 Sensor.
Parts #GU2Z-9G444-A Qty (1)
Parts #9C2Z-5E212-EnQty (1)

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 08-APR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Apr 8, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:51:32 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Apr 8, 2020 3:51:32 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Apr 8, 2020 3:51:32 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Apr 8, 2020 3:51:32 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Apr 8, 2020 3:51:32 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 8, 2020 3:51:32 PM	No	
20 - Miles			DARTHURS	Apr 8, 2020 3:51:32 PM	No	
30 - Kilometers			DARTHURS	Apr 8, 2020 3:51:32 PM	No	
40 - Hours			DARTHURS	Apr 8, 2020 3:51:32 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53461250
Invoice No. 55345 - 53461250

Client Department:
Department: 55345M
Work Order Description
Check Engine light on
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 220,164 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Replace Catalytic converter
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Apr-20	9C2Z-5E212-E	CONVERTER, CATALYTIC	1	565.95	565.95
08-Apr-20	GU2Z-9G444-A	SENSOR, OXYGEN, DOWNSTREAM	1	25.34	25.34

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Apr-20	Arthurs,Durvin	1.42	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	591.29
Labor:	0.00
Labor Hours:	1.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**591.29**

Work Order Footer

Work Order 53461250 Total	
Parts:	591.29
Labor:	0.00
Labor Hours:	1.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**591.29**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53390183
Invoice No. 55345 - 53390183

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP-FT Light Duty
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 217,598 - DH

Chronology		
Reported	Mar 16, 2020 4:15:39 PM	Mar 16, 2020 4:15:39 PM
Started	Mar 16, 2020 6:01:00 PM	
Completed	Mar 16, 2020 8:42:00 PM	Mar 16, 2020 8:42:00 PM
Down Time		

Work Order Notes

Line 10 Water pump leaking
Replaced water pump
Belt cracked
Replaced belt
Replaced bearing in belt tensioner

Activity Header
Activity: 10 042/004/000 PUMP, WATER
Activity Note: water pump leaking
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 18 Leaking
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Mar-20	4C3Z-8501-B	PUMP, WATER, 6.8L	1	77.97	77.97
16-Mar-20	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	21	21

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Mar-20	AMRIT TEEMAL,VISHNU	1.05	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	98.97
Labor:	0.00
Labor Hours:	1.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**98.97**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53390183
Invoice No. 55345 - 53390183

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	217,598 - DH

Activity Header
Activity:20 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 16-MAR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Mar 16, 2020 8:42:07 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Mar 16, 2020 8:42:07 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Mar 16, 2020 8:42:07 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Mar 16, 2020 8:42:07 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Mar 16, 2020 8:42:07 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Mar 16, 2020 8:42:07 PM	No	
20 - Miles			VAMRITTEEMAL	Mar 16, 2020 8:42:07 PM	No	
30 - Kilometers			VAMRITTEEMAL	Mar 16, 2020 8:42:07 PM	No	
40 - Hours			VAMRITTEEMAL	Mar 16, 2020 8:42:07 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53390183 Total	
Parts:	98.97
Labor:	0.00
Labor Hours:	1.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**98.97**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53306991
Invoice No. 55345 - 53306991

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	217,598 - DH

Chronology		
Reported	Mar 16, 2020 11:59:06 AM	Mar 16, 2020 11:59:06 AM
Started	Mar 16, 2020 3:34:00 PM	
Completed	Mar 16, 2020 8:37:00 PM	Mar 16, 2020 8:37:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA SERVICE

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Mar-20	AMRIT TEEMAL,VISHNU	0.83	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53306991
Invoice No. 55345 - 53306991

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	217,598 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Mar-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: VAMRITTEEMAL Performed on: 16-MAR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		VAMRITTEEMAL	Mar 16, 2020 8:37:18 PM	No	
101,000 - FRA Change Oil Filters	Yes		VAMRITTEEMAL	Mar 16, 2020 8:37:18 PM	No	
102,000 - FRA Drain Engine Oil	Yes		VAMRITTEEMAL	Mar 16, 2020 8:37:18 PM	No	
103,000 - FRA Check Transmission Fluid	Done		VAMRITTEEMAL	Mar 16, 2020 8:37:18 PM	No	
104,000 - Lubricate Chassis	Done		VAMRITTEEMAL	Mar 16, 2020 8:37:18 PM	No	
105,000 - Replace or Clean A/C Filters	Done		VAMRITTEEMAL	Mar 16, 2020 8:37:18 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	VAMRITTEEMAL	Mar 16, 2020 8:37:18 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		VAMRITTEEMAL	Mar 16, 2020 8:37:18 PM	No	

Activity Sub Total

Activity 20 Sub Total
Parts: 1.96

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53306991
Invoice No. 55345 - 53306991

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	217,598 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 16-MAR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Mar 16, 2020 8:36:52 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Mar 16, 2020 8:36:52 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Mar 16, 2020 8:36:52 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Mar 16, 2020 8:36:52 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Mar 16, 2020 8:36:52 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Mar 16, 2020 8:36:52 PM	No	
20 - Miles			VAMRITTEEMAL	Mar 16, 2020 8:36:52 PM	No	
30 - Kilometers			VAMRITTEEMAL	Mar 16, 2020 8:36:52 PM	No	
40 - Hours			VAMRITTEEMAL	Mar 16, 2020 8:36:52 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53306991 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53206482
Invoice No. 55345 - 53206482

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM B		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	213,570 - DH

Chronology		
Reported	Feb 20, 2020 10:14:07 AM	Feb 20, 2020 10:14:07 AM
Started	Feb 20, 2020 1:58:00 PM	
Completed	Feb 20, 2020 7:08:00 PM	Feb 20, 2020 7:08:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMB SERVICE

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Feb-20	AMRIT TEEMAL,VISHNU	0.43	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53305903
Invoice No. 55345 - 53305903

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	213,570 - DH

Chronology		
Reported	Feb 20, 2020 2:24:15 PM	Feb 20, 2020 2:24:15 PM
Started	Feb 20, 2020 2:37:00 PM	
Completed	Feb 20, 2020 7:08:00 PM	Feb 20, 2020 7:08:00 PM
Down Time		

Work Order Notes

Line 10 Replaced driver side motor mount
Please issue part

Activity Header
Activity: 10 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: driver side motor mount
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Feb-20	AMRIT TEEMAL,VISHNU	0.47	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53206482
Invoice No. 55345 - 53206482

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 213,570 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Feb-20	PA4456	FILTER, AIR, PANEL	1	5.02	5.02
20-Feb-20	P9600	FILTER, OIL SEE LF16424	1	3.45	3.45
20-Feb-20	P9600	FILTER, OIL SEE LF16424	-1	3.45	-3.45
20-Feb-20	PA4456	FILTER, AIR, PANEL	-1	5.02	-5.02
20-Feb-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Feb-20	AMRIT TEEMAL,VISHNU	0.23	0	0
20-Feb-20	AMRIT TEEMAL,VISHNU	0.17	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: VAMRITTEEMAL Performed on: 20-FEB-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		VAMRITTEEMAL	Feb 20, 2020 6:00:50 PM	No	
101,000 - FRA Change Oil Filters	Yes		VAMRITTEEMAL	Feb 20, 2020 6:00:50 PM	No	
102,000 - FRA Drain Engine Oil	Yes		VAMRITTEEMAL	Feb 20, 2020 6:00:50 PM	No	
103,000 - FRA Check Transmission Fluid	Done		VAMRITTEEMAL	Feb 20, 2020 6:00:50 PM	No	
104,000 - Lubricate Chassis	Done		VAMRITTEEMAL	Feb 20, 2020 6:00:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
105,000 - Replace or Clean A/C Filters	Done		VAMRITTEEMAL	Feb 20, 2020 6:00:50 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	VAMRITTEEMAL	Feb 20, 2020 6:00:50 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		VAMRITTEEMAL	Feb 20, 2020 6:00:50 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		VAMRITTEEMAL	Feb 20, 2020 6:00:50 PM	No	
201,000 - Service Crankcase Breather	-	n/a	VAMRITTEEMAL	Feb 20, 2020 6:00:50 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No	n/a	VAMRITTEEMAL	Feb 20, 2020 6:00:50 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No	n/a	VAMRITTEEMAL	Feb 20, 2020 6:00:50 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		VAMRITTEEMAL	Feb 20, 2020 6:00:50 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53305903
Invoice No. 55345 - 53305903

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP-FT Light Duty
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 213,570 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 20-FEB-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Feb 20, 2020 6:19:10 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Feb 20, 2020 6:19:10 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Feb 20, 2020 6:19:10 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Feb 20, 2020 6:19:10 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Feb 20, 2020 6:19:10 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Feb 20, 2020 6:19:10 PM	No	
20 - Miles			VAMRITTEEMAL	Feb 20, 2020 6:19:10 PM	No	
30 - Kilometers			VAMRITTEEMAL	Feb 20, 2020 6:19:10 PM	No	
40 - Hours			VAMRITTEEMAL	Feb 20, 2020 6:19:10 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53305903 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53206482
Invoice No. 55345 - 53206482

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM B		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	213,570 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 20-FEB-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Feb 20, 2020 5:59:25 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Feb 20, 2020 5:59:25 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Feb 20, 2020 5:59:25 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Feb 20, 2020 5:59:25 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Feb 20, 2020 5:59:25 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Feb 20, 2020 5:59:25 PM	No	
20 - Miles			VAMRITTEEMAL	Feb 20, 2020 5:59:25 PM	No	
30 - Kilometers			VAMRITTEEMAL	Feb 20, 2020 5:59:25 PM	No	
40 - Hours			VAMRITTEEMAL	Feb 20, 2020 5:59:25 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53206482 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53282997
Invoice No. 55345 - 53282997

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Replace Windshield wiper Blades		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	212,371 - DH

Chronology		
Reported	Feb 13, 2020 7:45:00 PM	Feb 13, 2020 7:45:00 PM
Started		
Completed	Feb 13, 2020 7:52:00 PM	Feb 13, 2020 7:52:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Windshield wiper not taking water off

Cause: normal usage

Correction: Replace windshield wiper blades
qty 2 40520

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 13-FEB-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		AOWENS	Feb 13, 2020 7:51:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		AOWENS	Feb 13, 2020 7:51:46 PM	No	
3 - Are you wearing the appropriate PPE?	Done		AOWENS	Feb 13, 2020 7:51:46 PM	No	
4 - Have you performed the proper LOTO?	Done		AOWENS	Feb 13, 2020 7:51:46 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	Feb 13, 2020 7:51:46 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Feb 13, 2020 7:51:46 PM	No	
20 - Miles			AOWENS	Feb 13, 2020 7:51:46 PM	No	
30 - Kilometers			AOWENS	Feb 13, 2020 7:51:46 PM	No	
40 - Hours			AOWENS	Feb 13, 2020 7:51:46 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53282997
Invoice No. 55345 - 53282997

Client Department:
Department: 55345M
Work Order Description
Replace Windshield wiper Blades
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 212,371 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Windshield wiper Blades
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Feb-20	40520	BLADE, WIPER, WINDSHIELD, 20"	2	4.28	8.56

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	8.56
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.56**

Work Order Footer

Work Order 53282997 Total	
Parts:	8.56
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.56**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53255851
Invoice No. 55345 - 53255851

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Vehicle s overheating		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	211,429 - DH

Chronology		
Reported	Feb 6, 2020 8:35:30 AM	Feb 6, 2020 8:35:30 AM
Started	Feb 6, 2020 8:37:00 AM	
Completed	Feb 7, 2020 2:14:00 PM	Feb 7, 2020 2:14:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: vehicle low on coolant and won¿t start

Cause: Check vehicle for no start condition found main fuse was burn, follow diagnostic test and pressure test found fuel pumps has power but they won¿t work

Correction: Removed propane from tank to replace fuel pumps and inspect wire harness, vehicle starts ok while running the engine found head gasket is leaking coolant. Install head gasket stop leak, road test vehicle ok at this time

Parts:
1 fuel pump kit 11396002
1 head gasket sealer 38386

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 07-FEB-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Feb 7, 2020 2:13:46 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Feb 7, 2020 2:13:46 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Feb 7, 2020 2:13:46 PM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Feb 7, 2020 2:13:46 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Feb 7, 2020 2:13:46 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Feb 7, 2020 2:13:46 PM	No	
20 - Miles			JAPEREZ	Feb 7, 2020 2:13:46 PM	No	
30 - Kilometers			JAPEREZ	Feb 7, 2020 2:13:46 PM	No	
40 - Hours			JAPEREZ	Feb 7, 2020 2:13:46 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53255851
Invoice No. 55345 - 53255851

Client Department:
Department: 55345M
Work Order Description
Vehicle s overheating
Requested By: JAPEREZ
Created By: JAPEREZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 211,429 - DH

Activity Header
Activity: 15 042 COOLING SYSTEM
Activity Note: Vehicle is overheating
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Feb-20	11396002	PUMP, FUEL, GASEOUS, GEN-3 W/KIT	1	414.31	414.31
07-Feb-20	38386	TREATMENT, SEALER, COOLANT	1	59.5	59.5

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Feb-20	Perez,Javier	5.58	0	0
07-Feb-20	Perez,Javier	5.62	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	473.81
Labor:	0.00
Labor Hours:	11.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**473.81**

Work Order Footer

Work Order 53255851 Total	
Parts:	473.81
Labor:	0.00
Labor Hours:	11.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**473.81**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53254348
Invoice No. 55345 - 53254348

Client Department:
Department: 55345M
Work Order Description
Dead Battery (Road Call)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 211,429 - DH

Chronology		
Reported	Feb 5, 2020 4:55:00 PM	Feb 5, 2020 4:55:00 PM
Started	Feb 5, 2020 4:59:00 PM	
Completed	Feb 5, 2020 9:27:00 PM	Feb 5, 2020 9:27:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:bus can¿t stay running shut off

Cause: possibility check fuel pump

Correction:tow it to base

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 05-FEB-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Feb 5, 2020 9:26:57 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		RGASPARD	Feb 5, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				9:26:57 PM		
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Feb 5, 2020 9:26:57 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Feb 5, 2020 9:26:57 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Feb 5, 2020 9:26:57 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Feb 5, 2020 9:26:57 PM	No	
20 - Miles			RGASPARD	Feb 5, 2020 9:26:57 PM	No	
30 - Kilometers			RGASPARD	Feb 5, 2020 9:26:57 PM	No	
40 - Hours			RGASPARD	Feb 5, 2020 9:26:57 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53254348
Invoice No. 55345 - 53254348

Client Department:
Department: 55345M
Work Order Description
Dead Battery (Road Call)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 211,429 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL (Dead Battery)
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Feb-20	Gaspard,Ronald	4.4	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	4.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53254348 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	4.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53206480
Invoice No. 55345 - 53206480

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	209,304 - DH

Chronology		
Reported	Jan 22, 2020 8:47:45 PM	Jan 22, 2020 8:47:45 PM
Started	Jan 22, 2020 12:00:00 AM	
Completed	Jan 22, 2020 8:57:00 PM	Jan 22, 2020 8:57:00 PM
Down Time		

Work Order Notes

Line 10 Front rotors worn and have hot spots
Replaced front rotors with wheel bearings and seals
Replaced front brake pads
Driver side caliper pins seized
Removed and replaced caliper pins

Activity Header
Activity: 10 013/000/000 BRAKES
Activity Note: rotors worn/hotspots
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Jan-20	BC2Z-1102-B	ROTOR, BRAKE, DISC, FRONT W/INTEGRAL HUB	2	114.23	228.46
22-Jan-20	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	48.87	48.87
22-Jan-20	CR24000	SEAL, WHEEL, HUB, FRONT	2	6.47	12.94
22-Jan-20	LM102949	BEARING, WHEEL, INNER, FRONT, TAPERED	2	7.81	15.62
22-Jan-20	8C2Z-2C150-C	PIN, CALIPER, BRAKE, DISC, FRONT SAME AS BKCOE10	1	10.6	10.6
22-Jan-20	15101	BEARING, WHEEL, OUTER, FRONT	2	8.46	16.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Jan-20	AMRIT TEEMAL,VISHNU	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	333.41
Labor:	0.00
Labor Hours:	2.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**333.41**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53206480
Invoice No. 55345 - 53206480

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	209,304 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 22-JAN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Jan 22, 2020 8:57:18 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Jan 22, 2020 8:57:18 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Jan 22, 2020 8:57:18 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Jan 22, 2020 8:57:18 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Jan 22, 2020 8:57:18 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Jan 22, 2020 8:57:18 PM	No	
20 - Miles			VAMRITTEEMAL	Jan 22, 2020 8:57:18 PM	No	
30 - Kilometers			VAMRITTEEMAL	Jan 22, 2020 8:57:18 PM	No	
40 - Hours			VAMRITTEEMAL	Jan 22, 2020 8:57:18 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53206480 Total	
Parts:	333.41
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**333.41**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53119478
Invoice No. 55345 - 53119478

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	209,304 - DH

Chronology		
Reported	Jan 22, 2020 10:33:28 AM	Jan 22, 2020 10:33:28 AM
Started	Jan 22, 2020 12:00:00 AM	
Completed	Jan 22, 2020 8:48:00 PM	Jan 22, 2020 8:48:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA SERVICE

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMA SERVICE
REPLACED AIR FILTER
REPLACED DRAIN PLUG

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Jan-20	AMRIT TEEMAL,VISHNU	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53119478
Invoice No. 55345 - 53119478

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 209,304 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Jan-20	PA4075	FILTER, AIR SEE P546597	1	5.28	5.28
22-Jan-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96
22-Jan-20	65266	PLUG, DRAIN, OIL, ENGINE	1	4.26	4.26

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Jan-20	AMRIT TEEMAL,VISHNU	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: VAMRITTEEMAL Performed on: 22-JAN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		VAMRITTEEMAL	Jan 22, 2020 8:39:50 PM	No	
101,000 - FRA Change Oil Filters	Yes		VAMRITTEEMAL	Jan 22, 2020 8:39:50 PM	No	
102,000 - FRA Drain Engine Oil	Yes		VAMRITTEEMAL	Jan 22, 2020 8:39:50 PM	No	
103,000 - FRA Check Transmission Fluid	Done		VAMRITTEEMAL	Jan 22, 2020 8:39:50 PM	No	
104,000 - Lubricate Chassis	Done		VAMRITTEEMAL	Jan 22, 2020 8:39:50 PM	No	
105,000 - Replace or Clean A/C Filters	Done		VAMRITTEEMAL	Jan 22, 2020 8:39:50 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	VAMRITTEEMAL	Jan 22, 2020 8:39:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
108,000 - Lube all pivoting Mechanisms	Done		VAMRITTEEMAL	Jan 22, 2020 8:39:50 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	11.50
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**11.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53119478
Invoice No. 55345 - 53119478

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	209,304 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 22-JAN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Jan 22, 2020 8:39:15 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Jan 22, 2020 8:39:15 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Jan 22, 2020 8:39:15 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Jan 22, 2020 8:39:15 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Jan 22, 2020 8:39:15 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Jan 22, 2020 8:39:15 PM	No	
20 - Miles			VAMRITTEEMAL	Jan 22, 2020 8:39:15 PM	No	
30 - Kilometers			VAMRITTEEMAL	Jan 22, 2020 8:39:15 PM	No	
40 - Hours			VAMRITTEEMAL	Jan 22, 2020 8:39:15 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53119478 Total	
Parts:	11.50
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**11.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53132514
Invoice No. 55345 - 53132514

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
W/C Lift		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	205,892 - DH

Chronology		
Reported	Dec 27, 2019 11:02:22 PM	Dec 27, 2019 11:02:22 PM
Started	Dec 27, 2019 11:05:00 PM	
Completed	Dec 28, 2019 12:12:00 AM	Dec 28, 2019 12:12:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: W/C Lift Stop When going down

Cause: Up Switch broken.

Correction: Replace up switch adjust Lift arm. & straighten bracket that activate up switch.
Parts# 32519Ks. Qty (1)

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 27-DEC-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Dec 27, 2019 11:04:13 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Dec 27, 2019 11:04:13 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Dec 27, 2019 11:04:13 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Dec 27, 2019 11:04:13 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Dec 27, 2019 11:04:13 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Dec 27, 2019 11:04:13 PM	No	
20 - Miles			DARTHURS	Dec 27, 2019 11:04:13 PM	No	
30 - Kilometers			DARTHURS	Dec 27, 2019 11:04:13 PM	No	
40 - Hours			DARTHURS	Dec 27, 2019 11:04:13 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53132514
Invoice No. 55345 - 53132514

Client Department:
Department: 55345M
Work Order Description
W/C Lift
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 205,892 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Check W/C Lift
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Dec-19	32519KS	SWITCH, RAISED, W/C	1	29.28	29.28

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Dec-19	Arthurs,Durvin	0.92	65	59.8
28-Dec-19	Arthurs,Durvin	0.12	65	7.8

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	29.28
Labor:	67.60
Labor Hours:	1.04
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**96.88**

Work Order Footer

Work Order 53132514 Total	
Parts:	29.28
Labor:	67.60
Labor Hours:	1.04
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**96.88**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53039638
Invoice No. 55345 - 53039638

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	RRENE	**Status:**	40 - Closed (40)
Created By:	RRENE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	205,096 - DH

Chronology		
Reported	Dec 20, 2019 8:59:36 AM	Dec 20, 2019 8:59:36 AM
Started		
Completed	Dec 22, 2019 11:19:00 AM	Dec 22, 2019 11:19:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PmA service

CAUSE: preventive maintenance

CORRECTION: perform PmA Service lube all Pivoting Points

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53039638
Invoice No. 55345 - 53039638

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RRENE
Created By: RRENE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 205,096 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Dec-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: NPIERRE-LOUIS Performed on: 22-DEC-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Dec 22, 2019 11:17:56 AM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Dec 22, 2019 11:17:56 AM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Dec 22, 2019 11:17:56 AM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Dec 22, 2019 11:17:56 AM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Dec 22, 2019 11:17:56 AM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Dec 22, 2019 11:17:56 AM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		NPIERRE-LOUIS	Dec 22, 2019 11:17:56 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Dec 22, 2019 11:17:56 AM	No	

Activity Sub Total

Activity 20 Sub Total
Parts: 1.96

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53039638
Invoice No. 55345 - 53039638

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	RRENE	**Status:**	40 - Closed (40)
Created By:	RRENE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	205,096 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 22-DEC-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Dec 22, 2019 10:33:18 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Dec 22, 2019 10:33:18 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Dec 22, 2019 10:33:18 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Dec 22, 2019 10:33:18 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Dec 22, 2019 10:33:18 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Dec 22, 2019 10:33:18 AM	No	
20 - Miles			NPIERRE-LOUIS	Dec 22, 2019 10:33:18 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Dec 22, 2019 10:33:18 AM	No	
40 - Hours			NPIERRE-LOUIS	Dec 22, 2019 10:33:18 AM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53039638 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53041884
Invoice No. 55345 - 53041884

Client Department:
Department: 55345M
Work Order Description
Replaced motor mount
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 201,052 - DH

Chronology		
Reported	Nov 26, 2019 3:13:33 PM	Nov 26, 2019 3:13:33 PM
Started	Nov 26, 2019 12:00:00 AM	
Completed	Nov 27, 2019 9:05:01 AM	Nov 27, 2019 9:05:01 AM
Down Time		

Work Order Notes

Line 10 Passenger side motor mount broken
Normal wear
Replaced motor mount

Activity Header
Activity: 10 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Nov-19	5U9Z-6038-AA	MOUNT, ENGINE, RH	1	35.37	35.37

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Nov-19	AMRIT TEEMAL,VISHNU	1	65	65

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	35.37
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**100.37**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53041884
Invoice No. 55345 - 53041884

Client Department:
Department: 55345M
Work Order Description
Replaced motor mount
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 201,052 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Nov-19	P13JC03P205AC	MODULE, RELAY, SMART, PROPANE, ROUSH	1	472.31	472.31

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Nov-19	AMRIT TEEMAL,VISHNU	0.2666666	65	17.333329

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 26-NOV-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Nov 26, 2019 3:29:14 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Nov 26, 2019 3:29:14 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Nov 26, 2019 3:29:14 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Nov 26, 2019 3:29:14 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Nov 26, 2019 3:29:14 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Nov 26, 2019 3:29:14 PM	No	
20 - Miles			VAMRITTEEMAL	Nov 26, 2019 3:29:14 PM	No	
30 - Kilometers			VAMRITTEEMAL	Nov 26, 2019 3:29:14 PM	No	
40 - Hours			VAMRITTEEMAL	Nov 26, 2019 3:29:14 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	472.31
Labor:	17.33
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**489.64**

Work Order Footer

Work Order 53041884 Total	
Parts:	507.68
Labor:	82.33
Labor Hours:	1.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**590.01**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52951492
Invoice No. 55345 - 52951492

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 200,808 - DH

Chronology		
Reported	Nov 25, 2019 12:04:35 PM	Nov 25, 2019 12:04:35 PM
Started	Nov 25, 2019 12:00:00 AM	
Completed	Nov 26, 2019 7:46:29 AM	Nov 26, 2019 7:46:29 AM
Down Time		

Work Order Notes

Line 10 PMC SERVICE
PREVENTIVE MAINTENANCE
PERFORM AND COMPLETED PMC SERVICE

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Nov-19	AMRIT TEEMAL,VISHNU	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: VAMRITTEEMAL Performed on: 25-NOV-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
10,100 - Safety Inspection	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
10,140 - Check Service Brakes	Done		VAMRITTEEMAL	Nov 25, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				4:02:44 PM		
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
10,160 - FRA Check Instruments and Horns	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
10,170 - Check Fast Idle	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
10,180 - Check Starter Protection Circuit	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
10,190 - Check Reverse Warning System	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
11,100 - Check Parking Brake	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
11,150 - Perform Brake Test	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
11,152 - Decelerometer Results Test 1	FEET	n/a	VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
11,154 - Decelerometer Results Test 2	FEET	n/a	VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
11,156 - Decelerometer Results Test 3	FEET	n/a	VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
11,170 - FRA Check Door Operation	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
20,210 - Check Condition of Operator's Area	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
20,240 - FRA Check Interior Lights	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
20,260 - Check Stop Request System	-	n/a	VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
20,270 - Check Fare Box Mounting (If	-	n/a	VAMRITTEEMAL	Nov 25, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Applicable)				4:02:44 PM		
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
22,110 - Check Emergency Hatches	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
22,120 - Check All Safety Equipment	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
30,310 - Check Passenger Doors	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
30,360 - Check for Physical Damage and Decals	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
30,380 - Check Exterior Compartment Doors	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
33,100 - Check Lights and Reflectors	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
40,420 - Check Hood	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
40,460 - Record Antifreeze Protection Level	-	n/a	VAMRITTEEMAL	Nov 25, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Using Refractometer				4:02:44 PM		
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
44,130 - FRA Check Exhaust System	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
44,140 - FRA Check Intake System	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
44,180 - FRA Check for Leaks	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
44,190 - FRA Perform Battery Inspection	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
50,510 - Check Entire Steering System	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
60,620 - Check Valve Stems and Caps	Done		VAMRITTEEMAL	Nov 25, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				4:02:44 PM		
60,630 - Check and Record Tread Depth	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
60,631 - Tread Depth RF	9 32nds of an inch		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
60,633 - Tread Depth RRO	10 32nds of an inch		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
60,635 - Tread Depth LRI	10 32nds of an inch		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
60,636 - Tread Depth LRO	10 32nds of an inch		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
60,650 - Check Sidewall Wear	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
60,660 - Inspect for Cuts and Tears	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
70,710 - Check Vibration Damper	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
70,730 - FRA Check Starter	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
70,770 - FRA Check Exhaust System	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
77,110 - FRA Check Fuel Tank	Done		VAMRITTEEMAL	Nov 25, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				4:02:44 PM		
77,120 - Check Suspension Components	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
77,135 - Brake Rotor LF	39.9 Inch		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
77,136 - Brake Rotor RF	39.88 Inch		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
77,137 - Brake Rotor LR	35.65 Inch		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
77,138 - Brake Rotor RR	35.88 Inch		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
77,140 - FRA Check Brake Hoses	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
77,150 - Check King Pins	-	n/a	VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
80,810 - Completion of PMI Report	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		VAMRITTEEMAL	Nov 25, 2019 4:02:44 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52951492
Invoice No. 55345 - 52951492

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 200,808 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Nov-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Nov-19	AMRIT TEEMAL,VISHNU	1	65	65

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: VAMRITTEEMAL Performed on: 25-NOV-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		VAMRITTEEMAL	Nov 25, 2019 3:57:13 PM	No	
101,000 - FRA Change Oil Filters	Yes		VAMRITTEEMAL	Nov 25, 2019 3:57:13 PM	No	
102,000 - FRA Drain Engine Oil	Yes		VAMRITTEEMAL	Nov 25, 2019 3:57:13 PM	No	
103,000 - FRA Check Transmission Fluid	Done		VAMRITTEEMAL	Nov 25, 2019 3:57:13 PM	No	
104,000 - Lubricate Chassis	Done		VAMRITTEEMAL	Nov 25, 2019 3:57:13 PM	No	
105,000 - Replace or Clean A/C Filters	Done		VAMRITTEEMAL	Nov 25, 2019 3:57:13 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	n/a	VAMRITTEEMAL	Nov 25, 2019 3:57:13 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		VAMRITTEEMAL	Nov 25, 2019 3:57:13 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		VAMRITTEEMAL	Nov 25, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				3:57:13 PM		
201,000 - Service Crankcase Breather	-	n/a	VAMRITTEEMAL	Nov 25, 2019 3:57:13 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No	n/a	VAMRITTEEMAL	Nov 25, 2019 3:57:13 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No	n/a	VAMRITTEEMAL	Nov 25, 2019 3:57:13 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		VAMRITTEEMAL	Nov 25, 2019 3:57:13 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		VAMRITTEEMAL	Nov 25, 2019 3:57:13 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		VAMRITTEEMAL	Nov 25, 2019 3:57:13 PM	No	
302,000 - Check Toe-In and Record Reading	-	n/a	VAMRITTEEMAL	Nov 25, 2019 3:57:13 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	n/a	VAMRITTEEMAL	Nov 25, 2019 3:57:13 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No	n/a	VAMRITTEEMAL	Nov 25, 2019 3:57:13 PM	No	
305,000 - FRA Change Differential Fluid	Yes		VAMRITTEEMAL	Nov 25, 2019 3:57:13 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**66.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52951492
Invoice No. 55345 - 52951492

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 200,808 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Nov-19	AMRIT TEEMAL,VISHNU	0.2666666	65	17.333329

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 25-NOV-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Nov 25, 2019 3:55:53 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Nov 25, 2019 3:55:53 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Nov 25, 2019 3:55:53 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Nov 25, 2019 3:55:53 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Nov 25, 2019 3:55:53 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Nov 25, 2019 3:55:53 PM	No	
20 - Miles			VAMRITTEEMAL	Nov 25, 2019 3:55:53 PM	No	
30 - Kilometers			VAMRITTEEMAL	Nov 25, 2019 3:55:53 PM	No	
40 - Hours			VAMRITTEEMAL	Nov 25, 2019 3:55:53 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	17.33
	Labor Hours:	0.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**17.33**

Work Order Footer

Work Order 52951492 Total	
Parts:	1.96
Labor:	179.83
Labor Hours:	2.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**181.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52951488
Invoice No. 55345 - 52951488

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Rear Brakes		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	196,547 - DH

Chronology		
Reported	Oct 31, 2019 12:16:02 AM	Oct 31, 2019 12:16:02 AM
Started	Oct 31, 2019 12:00:00 AM	
Completed	Oct 31, 2019 12:23:00 AM	Oct 31, 2019 12:23:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear Brakes

Cause: Rear Brakes Low

Correction: Removed & Replace Rear Brakes Lube Slide Pins.
Parts# 8C2Z-2V200-C Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Oct-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 31-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Oct 31, 2019 12:17:13 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Oct 31, 2019 12:17:13 AM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Oct 31, 2019 12:17:13 AM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Oct 31, 2019 12:17:13 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Oct 31, 2019 12:17:13 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Oct 31, 2019 12:17:13 AM	No	
20 - Miles			DARTHURS	Oct 31, 2019 12:17:13 AM	No	
30 - Kilometers			DARTHURS	Oct 31, 2019 12:17:13 AM	No	
40 - Hours			DARTHURS	Oct 31, 2019 12:17:13 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	5.42
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.42**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52857818
Invoice No. 55345 - 52857818

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 196,547 - DH

Chronology		
Reported	Oct 30, 2019 12:00:00 AM	Oct 30, 2019 12:00:00 AM
Started	Oct 31, 2019 12:00:00 AM	
Completed	Oct 31, 2019 12:23:00 AM	Oct 31, 2019 12:23:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA Service

CAUSE: Service due by Mileage.

CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check brakes . Clean batteries.
Parts # B329 Qty (1)
Oil 5W20 Qty (7.0) Qt

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Oct-19	Arthurs,Durvin	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 31-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
10,100 - Safety Inspection	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Oct 31, 2019 12:10:56 AM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Oct 31, 2019 12:10:56 AM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Oct 31, 2019 12:10:56 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Oct 31, 2019 12:10:56 AM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Oct 31, 2019 12:10:56 AM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	Oct 31, 2019 12:10:56 AM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Oct 31, 2019 12:10:56 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Oct 31, 2019 12:10:56 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
40,420 - Check Hood	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Oct 31, 2019 12:10:56 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Oct 31, 2019 12:10:56 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Oct 31, 2019 12:10:56 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Oct 31, 2019 12:10:56 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Oct 31, 2019 12:10:56 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Oct 31, 2019 12:10:56 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Oct 31, 2019 12:10:56 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
60,631 - Tread Depth RF	8 32nds of an inch		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
60,632 - Tread Depth LF	8 32nds of an inch		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
60,633 - Tread Depth RRO	11 32nds of an inch		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
60,636 - Tread Depth LRO	12 32nds of an inch		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
60,670 - Check Dual Mating With Square	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
77,131 - Brake Pad Thickness LF	9 Inch		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
77,132 - Brake Pad Thickness RF	9 Inch		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
77,133 - Brake Pad Thickness LR	4 Inch		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
77,134 - Brake Pad Thickness RR	5 Inch		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
77,135 - Brake Rotor LF	1.554 Inch		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
77,136 - Brake Rotor RF	1.555 Inch		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
77,137 - Brake Rotor LR	1.656 Inch		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
77,138 - Brake Rotor RR	1.657 Inch		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Oct 31, 2019 12:10:56 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Oct 31, 2019 12:10:56 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52951488
Invoice No. 55345 - 52951488

Client Department:
Department: 55345M
Work Order Description
Rear Brakes
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 196,547 - DH

Activity Header
Activity: 15 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
31-Oct-19	8C2Z-2V200-C	PADS, BRAKE, DISC, REAR	1	47.81	47.81

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Oct-19	Arthurs,Durvin	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	47.81
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**145.31**

Work Order Footer

Work Order 52951488 Total	
Parts:	47.81
Labor:	102.92
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**150.73**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52857818
Invoice No. 55345 - 52857818

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	196,547 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
31-Oct-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Oct-19	Arthurs,Durvin	0.4166666	65	27.083329

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 31-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Oct 31, 2019 12:11:49 AM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Oct 31, 2019 12:11:49 AM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Oct 31, 2019 12:11:49 AM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Oct 31, 2019 12:11:49 AM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Oct 31, 2019 12:11:49 AM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Oct 31, 2019 12:11:49 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Oct 31, 2019 12:11:49 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Oct 31, 2019 12:11:49 AM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	27.08
	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**29.04**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52857818
Invoice No. 55345 - 52857818

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	196,547 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Oct-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 31-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Oct 31, 2019 12:12:22 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Oct 31, 2019 12:12:22 AM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Oct 31, 2019 12:12:22 AM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Oct 31, 2019 12:12:22 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Oct 31, 2019 12:12:22 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Oct 31, 2019 12:12:22 AM	No	
20 - Miles			DARTHURS	Oct 31, 2019 12:12:22 AM	No	
30 - Kilometers			DARTHURS	Oct 31, 2019 12:12:22 AM	No	
40 - Hours			DARTHURS	Oct 31, 2019 12:12:22 AM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	5.42
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**5.42**

Work Order Footer

Work Order 52857818 Total	
Parts:	1.96
Labor:	130.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**131.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52902153
Invoice No. 55345 - 52902153

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Engine is leaking coolant		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	194,027 - DH

Chronology		
Reported	Oct 16, 2019 1:56:38 PM	Oct 16, 2019 1:56:38 PM
Started	Oct 16, 2019 12:00:00 AM	
Completed	Oct 18, 2019 1:10:23 PM	Oct 18, 2019 1:10:23 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:Engine is leaking coolant

Cause: check engine for leak found heater hose connector is broken

Correction:replaced both heater hoses, retest system ok at this time

Parts
2 new heater hoses Bc2z-18472-ca
Bc2z-18472-da

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 16-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Oct 16, 2019 2:06:11 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Oct 16, 2019 2:06:11 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Oct 16, 2019 2:06:11 PM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Oct 16, 2019 2:06:11 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Oct 16, 2019 2:06:11 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Oct 16, 2019 2:06:11 PM	No	
20 - Miles			JAPEREZ	Oct 16, 2019 2:06:11 PM	No	
30 - Kilometers			JAPEREZ	Oct 16, 2019 2:06:11 PM	No	
40 - Hours			JAPEREZ	Oct 16, 2019 2:06:11 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52902153
Invoice No. 55345 - 52902153

Client Department:
Department: 55345M
Work Order Description
Engine is leaking coolant
Requested By: JAPEREZ
Created By: JAPEREZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 194,027 - DH

Activity Header
Activity: 15 042 COOLING SYSTEM
Activity Note: Engine is leaking coolant
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Oct-19	BC2Z-18472-CA	TUBE, HEATER, WATER	1	59.54	59.54
16-Oct-19	BC2Z-18472-DA	TUBE, HEATER, WATER	1	56.59	56.59

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Oct-19	Perez,Javier	2.5	65	162.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	116.13
Labor:	162.50
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**278.63**

Work Order Footer

Work Order 52902153 Total	
Parts:	116.13
Labor:	162.50
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**278.63**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52765954
Invoice No. 55345 - 52765954

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 191,713 - DH

Chronology		
Reported	Oct 2, 2019 2:22:13 PM	Oct 2, 2019 2:22:13 PM
Started	Oct 3, 2019 12:00:00 AM	
Completed	Oct 3, 2019 12:13:00 AM	Oct 3, 2019 12:13:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA Service

CAUSE: Service due by Mileage.

CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check Brakes. Clean batteries.
Parts # B329 Qty (1)
Oil 5W20 Qty (7.0) Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Oct-19	Arthurs,Durvin	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 02-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Oct 2, 2019 11:57:12 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Oct 2, 2019 11:57:12 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Oct 2, 2019 11:57:12 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Oct 2, 2019 11:57:12 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Oct 2, 2019 11:57:12 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	Oct 2, 2019 11:57:12 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Oct 2, 2019 11:57:12 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Oct 2, 2019 11:57:12 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
40,420 - Check Hood	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Oct 2, 2019 11:57:12 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Oct 2, 2019 11:57:12 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Oct 2, 2019 11:57:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Oct 2, 2019 11:57:12 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Oct 2, 2019 11:57:12 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Oct 2, 2019 11:57:12 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Oct 2, 2019 11:57:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
60,633 - Tread Depth RRO	2 32nds of an inch		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
60,634 - Tread Depth RRI	2 32nds of an inch		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
60,635 - Tread Depth LRI	2 32nds of an inch		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
60,636 - Tread Depth LRO	2 32nds of an inch		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Oct 2, 2019 11:57:12 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
77,135 - Brake Rotor LF	1.554 Inch		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
77,136 - Brake Rotor RF	1.553 Inch		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
77,137 - Brake Rotor LR	1.656 Inch		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
77,138 - Brake Rotor RR	1.657 Inch		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Oct 2, 2019 11:57:12 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Oct 2, 2019 11:57:12 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52765954
Invoice No. 55345 - 52765954

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 191,713 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Oct-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Oct-19	Arthurs,Durvin	0.4166666	65	27.083329

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 02-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Oct 2, 2019 11:58:04 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Oct 2, 2019 11:58:04 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Oct 2, 2019 11:58:04 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Oct 2, 2019 11:58:04 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Oct 2, 2019 11:58:04 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Oct 2, 2019 11:58:04 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Oct 2, 2019 11:58:04 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Oct 2, 2019 11:58:04 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	27.08
	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**29.04**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52765954
Invoice No. 55345 - 52765954

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	191,713 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Oct-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 02-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Oct 2, 2019 11:58:38 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Oct 2, 2019 11:58:38 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Oct 2, 2019 11:58:38 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Oct 2, 2019 11:58:38 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Oct 2, 2019 11:58:38 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Oct 2, 2019 11:58:38 PM	No	
20 - Miles			DARTHURS	Oct 2, 2019 11:58:38 PM	No	
30 - Kilometers			DARTHURS	Oct 2, 2019 11:58:38 PM	No	
40 - Hours			DARTHURS	Oct 2, 2019 11:58:38 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	5.42
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**5.42**

Work Order Footer

Work Order 52765954 Total	
Parts:	1.96
Labor:	130.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**131.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52857810
Invoice No. 55345 - 52857810

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Rear Tires		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	191,713 - DH

Chronology		
Reported	Oct 3, 2019 12:02:43 AM	Oct 3, 2019 12:02:43 AM
Started	Oct 3, 2019 12:00:00 AM	
Completed	Oct 3, 2019 12:12:00 AM	Oct 3, 2019 12:12:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:Rear Tires

Cause: Tire Worn / Nail.

Correction: Mount & Balance all Rear Tires. Replace on rear.
Parts #. 192659 Qty (4)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Oct-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 03-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Oct 3, 2019 12:03:55 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Oct 3, 2019 12:03:55 AM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Oct 3, 2019 12:03:55 AM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Oct 3, 2019 12:03:55 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Oct 3, 2019 12:03:55 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Oct 3, 2019 12:03:55 AM	No	
20 - Miles			DARTHURS	Oct 3, 2019 12:03:55 AM	No	
30 - Kilometers			DARTHURS	Oct 3, 2019 12:03:55 AM	No	
40 - Hours			DARTHURS	Oct 3, 2019 12:03:55 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	5.42
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.42**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52857810
Invoice No. 55345 - 52857810

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Rear Tires		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	191,713 - DH

Activity Header
Activity: 15 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Oct-19	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	4	120.48	481.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Oct-19	Arthurs,Durvin	2	65	130

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	481.92
Labor:	130.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**611.92**

Work Order Footer

Work Order 52857810 Total	
Parts:	481.92
Labor:	135.42
Labor Hours:	2.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**617.34**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52765928
Invoice No. 55345 - 52765928

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Tag Light / Rear A/C		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	187,381 - DH

Chronology		
Reported	Sep 6, 2019 11:24:07 PM	Sep 6, 2019 11:24:07 PM
Started	Sep 6, 2019 12:00:00 AM	
Completed	Sep 7, 2019 12:00:00 AM	Sep 7, 2019 12:00:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear A/C / Tag Light

Cause: Rear A/C blown warm Air./ Tag Light Out.

Correction: Remove& Replace Tag Light & Evacuate Rear A/C Replace Orifice Tube. Recharge.
Parts #3975927 Qty (1)
Parts# 3411885 Qty (1)
Freon Qty (4.5) lb / add (3) Oz Oil

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Sep-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 06-SEP-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Sep 6, 2019 11:25:32 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Sep 6, 2019 11:25:32 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Sep 6, 2019 11:25:32 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Sep 6, 2019 11:25:32 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Sep 6, 2019 11:25:32 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Sep 6, 2019 11:25:32 PM	No	
20 - Miles			DARTHURS	Sep 6, 2019 11:25:32 PM	No	
30 - Kilometers			DARTHURS	Sep 6, 2019 11:25:32 PM	No	
40 - Hours			DARTHURS	Sep 6, 2019 11:25:32 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	5.42
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.42**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52658763
Invoice No. 55345 - 52658763

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM B		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	187,381 - DH

Chronology		
Reported	Sep 6, 2019 11:44:25 AM	Sep 6, 2019 11:44:25 AM
Started	Sep 6, 2019 12:00:00 AM	
Completed	Sep 7, 2019 12:00:00 AM	Sep 7, 2019 12:00:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PMB Service

CAUSE: Service due by Mileage.

CORRECTION: Change Oil & Filter Lube all Pivoting Points Check Brakes . Clean batteries.
Parts # B329 Qty (1)
Oil 5W20 Qty (7.0) Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Sep-19	Arthurs,Durvin	2	65	130

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 06-SEP-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Sep 6, 2019 11:18:09 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Sep 6, 2019 11:18:09 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Sep 6, 2019 11:18:09 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Sep 6, 2019 11:18:09 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Sep 6, 2019 11:18:09 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	Sep 6, 2019 11:18:09 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Sep 6, 2019 11:18:09 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Sep 6, 2019 11:18:09 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
40,420 - Check Hood	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Sep 6, 2019 11:18:09 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Sep 6, 2019 11:18:09 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Sep 6, 2019 11:18:09 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Sep 6, 2019 11:18:09 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Sep 6, 2019 11:18:09 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Sep 6, 2019 11:18:09 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Sep 6, 2019 11:18:09 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
60,631 - Tread Depth RF	11 32nds of an inch		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
60,632 - Tread Depth LF	11 32nds of an inch		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
60,634 - Tread Depth RRI	5 32nds of an inch		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
60,635 - Tread Depth LRI	5 32nds of an inch		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
60,636 - Tread Depth LRO	5 32nds of an inch		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Sep 6, 2019 11:18:09 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
77,131 - Brake Pad Thickness LF	11 Inch		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
77,132 - Brake Pad Thickness RF	11 Inch		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
77,133 - Brake Pad Thickness LR	9 Inch		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
77,134 - Brake Pad Thickness RR	9 Inch		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
77,135 - Brake Rotor LF	1.555 Inch		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
77,136 - Brake Rotor RF	1.556 Inch		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
77,137 - Brake Rotor LR	1.658 Inch		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
77,138 - Brake Rotor RR	1.656 Inch		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Sep 6, 2019 11:18:09 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Sep 6, 2019 11:18:09 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	130.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**130.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52765928
Invoice No. 55345 - 52765928

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Tag Light / Rear A/C		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	187,381 - DH

Activity Header
Activity: 15 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 51 Inoperative
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Sep-19	Arthurs,Durvin	2	65	130

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	130.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**130.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52658763
Invoice No. 55345 - 52658763

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 187,381 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Sep-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Sep-19	Arthurs,Durvin	0.4166666	65	27.083329

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: DARTHURS Performed on: 06-SEP-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Sep 6, 2019 11:19:13 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Sep 6, 2019 11:19:13 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Sep 6, 2019 11:19:13 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Sep 6, 2019 11:19:13 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Sep 6, 2019 11:19:13 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Sep 6, 2019 11:19:13 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Sep 6, 2019 11:19:13 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Sep 6, 2019 11:19:13 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		DARTHURS	Sep 6, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				11:19:13 PM		
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Sep 6, 2019 11:19:13 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		DARTHURS	Sep 6, 2019 11:19:13 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Sep 6, 2019 11:19:13 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Sep 6, 2019 11:19:13 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	27.08
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**29.04**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52765928
Invoice No. 55345 - 52765928

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Tag Light / Rear A/C		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	187,381 - DH

Activity Header
Activity:25 034/003/000 LAMPS, SIGNAL, PARKING & BACKUP
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Sep-19	3975927	LAMP, PLATE, LICENSE	1	11.08	11.08

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Sep-19	Arthurs,Durvin	0.5	65	32.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	11.08
Labor:	32.50
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.58**

Work Order Footer

Work Order 52765928 Total	
Parts:	11.08
Labor:	167.92
Labor Hours:	2.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**179.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52658763
Invoice No. 55345 - 52658763

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM B		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	187,381 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Sep-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 06-SEP-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Sep 6, 2019 11:19:51 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Sep 6, 2019 11:19:51 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Sep 6, 2019 11:19:51 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Sep 6, 2019 11:19:51 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Sep 6, 2019 11:19:51 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Sep 6, 2019 11:19:51 PM	No	
20 - Miles			DARTHURS	Sep 6, 2019 11:19:51 PM	No	
30 - Kilometers			DARTHURS	Sep 6, 2019 11:19:51 PM	No	
40 - Hours			DARTHURS	Sep 6, 2019 11:19:51 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	5.42
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**5.42**

Work Order Footer

Work Order 52658763 Total	
Parts:	1.96
Labor:	162.50
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**164.46**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52744066
Invoice No. 55345 - 52744066

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Transmission Harness		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	186,939 - DH

Chronology		
Reported	Aug 30, 2019 3:56:51 PM	Aug 30, 2019 3:56:51 PM
Started	Aug 30, 2019 12:00:00 AM	
Completed	Sep 4, 2019 9:02:14 AM	Sep 4, 2019 9:02:14 AM
Down Time		

Work Order Notes

Line 10 Replaced external Transmission Harness

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Aug-19	Delva,Terry	0.8	65	52

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 30-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Aug 30, 2019 4:02:29 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Aug 30, 2019 4:02:29 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Aug 30, 2019 4:02:29 PM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Aug 30, 2019 4:02:29 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Aug 30, 2019 4:02:29 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Aug 30, 2019 4:02:29 PM	No	
20 - Miles			TDELVA	Aug 30, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				4:02:29 PM		
30 - Kilometers			TDELVA	Aug 30, 2019 4:02:29 PM	No	
40 - Hours			TDELVA	Aug 30, 2019 4:02:29 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	52.00
Labor Hours:	0.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**52.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52744066
Invoice No. 55345 - 52744066

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Transmission Harness		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	186,939 - DH

Activity Header
Activity: 20 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Aug-19	DC2Z-7C078-S	HARNESS, TRANSMISSION, EXTERNAL, E450	1	72.4	72.4

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Aug-19	Delva,Terry	1.2833333	65	83.4166645

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	72.40
Labor:	83.42
Labor Hours:	1.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**155.82**

Work Order Footer

Work Order 52744066 Total	
Parts:	72.40
Labor:	135.42
Labor Hours:	2.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**207.82**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52706755
Invoice No. 55345 - 52706755

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
55345 Transmission DTC P-0713		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	185,821 - DH

Chronology		
Reported	Aug 20, 2019 11:46:42 AM	Aug 20, 2019 11:46:42 AM
Started	Aug 21, 2019 12:00:00 AM	
Completed	Aug 21, 2019 1:40:24 PM	Aug 21, 2019 1:40:24 PM
Down Time		

Work Order Notes

Line 10 Complaint. Check engine light on

Cause. Trouble code P0712 (Transmission)

Correction. Removed and replaced internal transmission harness and temperature sensor, drove test, all okay at this time.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 21-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Aug 21, 2019 10:07:36 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Aug 21, 2019 10:07:36 AM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Aug 21, 2019 10:07:36 AM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Aug 21, 2019 10:07:36 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Aug 21, 2019 10:07:36 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Aug 21, 2019 10:07:36 AM	No	
20 - Miles			RAURODRIGUEZ	Aug 21, 2019 10:07:36 AM	No	
30 - Kilometers			RAURODRIGUEZ	Aug 21, 2019 10:07:36 AM	No	
40 - Hours			RAURODRIGUEZ	Aug 21, 2019 10:07:36 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52706755
Invoice No. 55345 - 52706755

Client Department:
Department: 55345M
Work Order Description
55345 Transmission DTC P-0713
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 185,821 - DH

Activity Header
Activity: 20 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Aug-19	BC3Z-7H141-A	SENSOR, TEMPERATURE, TRANSMISSION	1	9.99	9.99
20-Aug-19	4C3Z-7G276-AA	HARNESS, SOLENOID, INTERNAL, TRANSMISSION, 5R110W	1	123.52	123.52
20-Aug-19	8C3Z-7C155-A	GASKET, BODY, VALVE, TRANSMISSION, 5R110	1	6.87	6.87
20-Aug-19	20021	FILTER, TRANSMISSION 20021	1	17.27	17.27

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Aug-19	Rodriguez,Raul	2.3666666	65	153.833329

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	157.65
Labor:	153.83
Labor Hours:	2.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**311.48**

Work Order Footer

Work Order 52706755 Total	
Parts:	157.65
Labor:	153.83
Labor Hours:	2.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**311.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52570674
Invoice No. 55345 - 52570674

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	183,066 - DH

Chronology		
Reported	Aug 2, 2019 12:31:27 PM	Aug 2, 2019 12:31:27 PM
Started	Aug 3, 2019 12:00:00 AM	
Completed	Aug 3, 2019 12:08:00 AM	Aug 3, 2019 12:08:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PMA Service

CAUSE: Service due by Mileage.

CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check Brakes. clean batteries
Parts# B329 Qty (1)
Oil 5w20 Qty (7.0) Qt

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Aug-19	Arthurs,Durvin	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 03-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
10,100 - Safety Inspection	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Aug 3, 2019 12:01:06 AM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Aug 3, 2019 12:01:06 AM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Aug 3, 2019 12:01:06 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Aug 3, 2019 12:01:06 AM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Aug 3, 2019 12:01:06 AM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	Aug 3, 2019 12:01:06 AM	No	
20,270 - Check Fare Box Mounting (If Applicable)	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Aug 3, 2019 12:01:06 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
40,420 - Check Hood	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Aug 3, 2019 12:01:06 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Aug 3, 2019 12:01:06 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Aug 3, 2019 12:01:06 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Aug 3, 2019 12:01:06 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Aug 3, 2019 12:01:06 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Aug 3, 2019 12:01:06 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Aug 3, 2019 12:01:06 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
60,631 - Tread Depth RF	11 32nds of an inch		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
60,632 - Tread Depth LF	11 32nds of an inch		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
60,633 - Tread Depth RRO	12 32nds of an inch		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
60,636 - Tread Depth LRO	12 32nds of an inch		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Aug 3, 2019 12:01:06 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
77,131 - Brake Pad Thickness LF	12 Inch		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
77,132 - Brake Pad Thickness RF	12 Inch		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
77,133 - Brake Pad Thickness LR	10 Inch		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
77,134 - Brake Pad Thickness RR	10 Inch		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
77,135 - Brake Rotor LF	1.554 Inch		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
77,136 - Brake Rotor RF	1.555 Inch		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
77,137 - Brake Rotor LR	1.657 Inch		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
77,138 - Brake Rotor RR	1.656 Inch		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Aug 3, 2019 12:01:06 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Aug 3, 2019 12:01:06 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52570674
Invoice No. 55345 - 52570674

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 183,066 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Aug-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Aug-19	Arthurs,Durvin	0.4166666	65	27.083329

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 03-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Aug 3, 2019 12:01:46 AM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Aug 3, 2019 12:01:46 AM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Aug 3, 2019 12:01:46 AM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Aug 3, 2019 12:01:46 AM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Aug 3, 2019 12:01:46 AM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Aug 3, 2019 12:01:46 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Aug 3, 2019 12:01:46 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Aug 3, 2019 12:01:46 AM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	27.08
	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**29.04**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52570674
Invoice No. 55345 - 52570674

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	183,066 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Aug-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 03-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Aug 3, 2019 12:02:18 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Aug 3, 2019 12:02:18 AM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Aug 3, 2019 12:02:18 AM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Aug 3, 2019 12:02:18 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Aug 3, 2019 12:02:18 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Aug 3, 2019 12:02:18 AM	No	
20 - Miles			DARTHURS	Aug 3, 2019 12:02:18 AM	No	
30 - Kilometers			DARTHURS	Aug 3, 2019 12:02:18 AM	No	
40 - Hours			DARTHURS	Aug 3, 2019 12:02:18 AM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	5.42
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**5.42**

Work Order Footer

Work Order 52570674 Total	
Parts:	1.96
Labor:	130.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**131.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52655558
Invoice No. 55345 - 52655558

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Replaced alternator and batteries		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	182,860 - DH

Chronology		
Reported	Aug 1, 2019 7:54:55 PM	Aug 1, 2019 7:54:55 PM
Started	Aug 1, 2019 12:00:00 AM	
Completed	Aug 1, 2019 10:48:00 PM	Aug 1, 2019 10:48:00 PM
Down Time		

Work Order Notes

Line 10 Replaced alternator (Warranty)
Replaced both batteries

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Aug-19	AMRIT TEEMAL,VISHNU	0.2666666	65	17.333329

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 01-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Aug 1, 2019 8:01:56 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Aug 1, 2019 8:01:56 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Aug 1, 2019 8:01:56 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Aug 1, 2019 8:01:56 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Aug 1, 2019 8:01:56 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Aug 1, 2019 8:01:56 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			VAMRITTEEMAL	Aug 1, 2019 8:01:56 PM	No	
30 - Kilometers			VAMRITTEEMAL	Aug 1, 2019 8:01:56 PM	No	
40 - Hours			VAMRITTEEMAL	Aug 1, 2019 8:01:56 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	17.33
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**17.33**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52655558
Invoice No. 55345 - 52655558

Client Department:
Department: 55345M
Work Order Description
Replaced alternator and batteries
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 182,860 - DH

Activity Header
Activity: 20 031/005/000 CHARGER, BATTERY, ON-BOARD, VEHICLES, PROPELLED, ELECTRICALLY
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure: 43 Weak
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Aug-19	34AGM	BATTERY, AGM, GROUP-34	2	115.74	231.48

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Aug-19	AMRIT TEEMAL,VISHNU	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	231.48
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**328.98**

Work Order Footer

Work Order 52655558 Total	
Parts:	231.48
Labor:	114.83
Labor Hours:	1.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**346.31**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 52578874
Invoice No. 55345 - 52578874

Client Department:
Department: 55345M
Work Order Description
Replaced front blower motor/radiator
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 178,807 - DH

Chronology		
Reported	Jul 7, 2019 11:15:56 AM	Jul 7, 2019 11:15:56 AM
Started	Jul 7, 2019 12:00:00 AM	
Completed	Jul 9, 2019 3:25:00 PM	Jul 9, 2019 3:25:00 PM
Down Time		

Work Order Notes

Line 10 Replaced front a/c blower motor w/ fan wheel
Replaced front a/c resistor and pigtail
Replaced radiator
Replaced air filter

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Jul-19	AMRIT TEEMAL,VISHNU	0.2666666	65	17.333329

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 07-JUL-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Jul 7, 2019 11:35:41 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Jul 7, 2019 11:35:41 AM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Jul 7, 2019 11:35:41 AM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Jul 7, 2019 11:35:41 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Jul 7, 2019 11:35:41 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Jul 7, 2019 11:35:41 AM	No	
20 - Miles			VAMRITTEEMAL	Jul 7, 2019 11:35:41 AM	No	
30 - Kilometers			VAMRITTEEMAL	Jul 7, 2019 11:35:41 AM	No	
40 - Hours			VAMRITTEEMAL	Jul 7, 2019 11:35:41 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	17.33
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**17.33**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 52578874
Invoice No. 55345 - 52578874

Client Department:
Department: 55345M
Work Order Description
Replaced front blower motor/radiator
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 178,807 - DH

Activity Header
Activity: 20 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Jul-19	AC2Z-19834-A	WHEEL, MOTOR, BLOWER	1	27.56	27.56
07-Jul-19	XC2Z-19805-BA	MOTOR, BLOWER SAME AS MM-840	1	36.38	36.38
07-Jul-19	4C2Z-19A706-AA	RESISTOR, MOTOR, BLOWER SAME AS YH1697	1	13.46	13.46

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Jul-19	AMRIT TEEMAL,VISHNU	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	77.40
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**174.90**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 52578874
Invoice No. 55345 - 52578874

Client Department:
Department: 55345M
Work Order Description
Replaced front blower motor/radiator
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 178,807 - DH

Activity Header
Activity: 30 042/000/000 COOLING SYSTEM
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Jul-19	G1000382282CSF	RADIATOR, E450	1	205.07	205.07

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Jul-19	AMRIT TEEMAL,VISHNU	2	65	130

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	205.07
Labor:	130.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**335.07**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 52578874
Invoice No. 55345 - 52578874

Client Department:
Department: 55345M
Work Order Description
Replaced front blower motor/radiator
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 178,807 - DH

Activity Header
Activity: 40 041/000/000 INTAKE, AIR
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Jul-19	AMRIT TEEMAL,VISHNU	0.1666666	65	10.833329

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	10.83
Labor Hours:	0.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**10.83**

Work Order Footer

Work Order 52578874 Total	
Parts:	282.47
Labor:	255.67
Labor Hours:	3.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**538.14**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52493511
Invoice No. 55345 - 52493511

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	178,701 - DH

Chronology		
Reported	Jul 1, 2019 12:55:45 PM	Jul 1, 2019 12:55:45 PM
Started	Jul 2, 2019 12:00:00 AM	
Completed	Jul 2, 2019 5:22:00 PM	Jul 2, 2019 5:22:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PM A service.

CAUSE: Due by Mileage.

CORRECTION: LOF engine oil and filter. Performed tire and brake inspection.

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jul-19	Earl Johnson	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: EARJOHNSON Performed on: 02-JUL-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
10,100 - Safety Inspection	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,140 - Check Service Brakes	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
10,160 - FRA Check Instruments and Horns	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
10,170 - Check Fast Idle	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
10,180 - Check Starter Protection Circuit	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
10,190 - Check Reverse Warning System	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
11,100 - Check Parking Brake	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
11,150 - Perform Brake Test	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
11,170 - FRA Check Door Operation	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
20,210 - Check Condition of Operator's Area	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
20,240 - FRA Check Interior Lights	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
20,260 - Check Stop Request System	-	NA	EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
22,110 - Check Emergency Hatches	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
22,120 - Check All Safety Equipment	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
30,310 - Check Passenger Doors	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
30,360 - Check for Physical Damage and Decals	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
30,380 - Check Exterior Compartment Doors	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
33,100 - Check Lights and Reflectors	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
40,420 - Check Hood	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	-	NA	EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
44,130 - FRA Check Exhaust System	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
44,140 - FRA Check Intake System	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
44,180 - FRA Check for Leaks	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
44,190 - FRA Perform Battery Inspection	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
50,510 - Check Entire Steering System	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
60,630 - Check and Record Tread Depth	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
60,632 - Tread Depth LF	7 32nds of an inch		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
60,633 - Tread Depth RRO	3 32nds of an inch		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
60,636 - Tread Depth LRO	4 32nds of an inch		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
60,650 - Check Sidewall Wear	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
60,660 - Inspect for Cuts and Tears	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
60,670 - Check Dual Mating With Square	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
70,710 - Check Vibration Damper	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
70,730 - FRA Check Starter	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
70,770 - FRA Check Exhaust System	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
77,120 - Check Suspension Components	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
77,131 - Brake Pad Thickness LF	4 Inch		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
77,132 - Brake Pad Thickness RF	5 Inch		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
77,135 - Brake Rotor LF	1.449 Inch		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
77,136 - Brake Rotor RF	1.456 Inch		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
77,137 - Brake Rotor LR	1.409 Inch		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
77,138 - Brake Rotor RR	1.414 Inch		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
77,140 - FRA Check Brake Hoses	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
77,150 - Check King Pins	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
80,810 - Completion of PMI Report	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		EARJOHNSON	Jul 2, 2019 5:04:42 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52493511
Invoice No. 55345 - 52493511

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 178,701 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Jul-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jul-19	Earl Johnson	1	65	65

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: EARJOHNSON Performed on: 02-JUL-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		EARJOHNSON	Jul 2, 2019 5:04:24 PM	No	
101,000 - FRA Change Oil Filters	Yes		EARJOHNSON	Jul 2, 2019 5:04:24 PM	No	
102,000 - FRA Drain Engine Oil	Yes		EARJOHNSON	Jul 2, 2019 5:04:24 PM	No	
103,000 - FRA Check Transmission Fluid	Done		EARJOHNSON	Jul 2, 2019 5:04:24 PM	No	
104,000 - Lubricate Chassis	Done		EARJOHNSON	Jul 2, 2019 5:04:24 PM	No	
105,000 - Replace or Clean A/C Filters	Done		EARJOHNSON	Jul 2, 2019 5:04:24 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		EARJOHNSON	Jul 2, 2019 5:04:24 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		EARJOHNSON	Jul 2, 2019 5:04:24 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	65.00
	Labor Hours:	1.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**66.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52493511
Invoice No. 55345 - 52493511

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 178,701 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Jul-19	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	48.87	48.87

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jul-19	Earl Johnson	0.2666666	65	17.333329

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 02-JUL-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jul 2, 2019 5:04:01 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jul 2, 2019 5:04:01 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jul 2, 2019 5:04:01 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jul 2, 2019 5:04:01 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jul 2, 2019 5:04:01 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jul 2, 2019 5:04:01 PM	No	
20 - Miles			EARJOHNSON	Jul 2, 2019 5:04:01 PM	No	
30 - Kilometers			EARJOHNSON	Jul 2, 2019 5:04:01 PM	No	
40 - Hours			EARJOHNSON	Jul 2, 2019 5:04:01 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	48.87
Labor:	17.33
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**66.20**

Work Order Footer

Work Order 52493511 Total	
Parts:	50.83
Labor:	179.83
Labor Hours:	2.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**230.66**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52418255
Invoice No. 55345 - 52418255

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 174,297 - DH

Chronology		
Reported	Jun 5, 2019 11:59:12 AM	Jun 5, 2019 11:59:12 AM
Started	Jun 5, 2019 12:00:00 AM	
Completed	Jun 6, 2019 12:04:00 AM	Jun 6, 2019 12:04:00 AM
Down Time		

Work Order Notes

Line 10 Perform PMC Service. Change Oil & Filter. Lube all Pivoting Points. Check Brakes .clean batteries. Replace A/C Filter.perform Transmission Service drain & Fill & Replace Filter. Perform differential service drain & Fill Swap L/R inner tire.
Parts# B329 Qty (1)
Oil 5W20 Qty (7) Qt
Parts# 20021 Qty (1)
ATF Fluid Qty (9.0) Qt
Gear Oil 80W90 Qty (3) Qt

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jun-19	Arthurs,Durvin	3.5	65	227.5

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 05-JUN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
10,120 - FRA Check All Warning Lights and	Done		DARTHURS	Jun 5, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				11:33:01 PM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Jun 5, 2019 11:33:01 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Jun 5, 2019 11:33:01 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Jun 5, 2019 11:33:01 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Jun 5, 2019 11:33:01 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Jun 5, 2019 11:33:01 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Jun 5, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:33:01 PM		
20,260 - Check Stop Request System	-	NA	DARTHURS	Jun 5, 2019 11:33:01 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Jun 5, 2019 11:33:01 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Jun 5, 2019 11:33:01 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
40,420 - Check Hood	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Jun 5, 2019 11:33:01 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Jun 5, 2019 11:33:01 PM	No	
40,442 - Freeze Point	Degree	NA	DARTHURS	Jun 5, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			11:33:01 PM		
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Jun 5, 2019 11:33:01 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Jun 5, 2019 11:33:01 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Jun 5, 2019 11:33:01 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
60,615 - Air Pressure LRI	65 Pounds per		DARTHURS	Jun 5, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			11:33:01 PM		
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
60,634 - Tread Depth RRI	5 32nds of an inch		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
60,635 - Tread Depth LRI	2 32nds of an inch		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
60,670 - Check Dual Mating With Square	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
70,790 - Check All Body Mounts and Chassis	Done		DARTHURS	Jun 5, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Frame				11:33:01 PM		
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
77,133 - Brake Pad Thickness LR	12 Inch		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
77,134 - Brake Pad Thickness RR	12 Inch		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
77,135 - Brake Rotor LF	1.554 Inch		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
77,136 - Brake Rotor RF	1.554 Inch		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
77,137 - Brake Rotor LR	1.653 Inch		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
77,138 - Brake Rotor RR	1.654 Inch		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Jun 5, 2019 11:33:01 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Jun 5, 2019 11:33:01 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	227.50
Labor Hours:	3.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**227.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52418255
Invoice No. 55345 - 52418255

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 174,297 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Jun-19	20021	FILTER, TRANSMISSION 20021	1	17.27	17.27
05-Jun-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jun-19	Arthurs,Durvin	0.4166666	65	27.083329

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: DARTHURS Performed on: 05-JUN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Jun 5, 2019 11:35:24 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Jun 5, 2019 11:35:24 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Jun 5, 2019 11:35:24 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Jun 5, 2019 11:35:24 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Jun 5, 2019 11:35:24 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Jun 5, 2019 11:35:24 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	NA	DARTHURS	Jun 5, 2019 11:35:24 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Jun 5, 2019 11:35:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	Jun 5, 2019 11:35:24 PM	No	
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Jun 5, 2019 11:35:24 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		DARTHURS	Jun 5, 2019 11:35:24 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Jun 5, 2019 11:35:24 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Jun 5, 2019 11:35:24 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		DARTHURS	Jun 5, 2019 11:35:24 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		DARTHURS	Jun 5, 2019 11:35:24 PM	No	
302,000 - Check Toe-In and Record Reading	-	NA	DARTHURS	Jun 5, 2019 11:35:24 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	NA	DARTHURS	Jun 5, 2019 11:35:24 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		DARTHURS	Jun 5, 2019 11:35:24 PM	No	
305,000 - FRA Change Differential Fluid	Yes		DARTHURS	Jun 5, 2019 11:35:24 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	19.23
Labor:	27.08
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**46.31**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52418255
Invoice No. 55345 - 52418255

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM C		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	174,297 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jun-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 05-JUN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jun 5, 2019 11:36:11 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jun 5, 2019 11:36:11 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jun 5, 2019 11:36:11 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jun 5, 2019 11:36:11 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jun 5, 2019 11:36:11 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jun 5, 2019 11:36:11 PM	No	
20 - Miles			DARTHURS	Jun 5, 2019 11:36:11 PM	No	
30 - Kilometers			DARTHURS	Jun 5, 2019 11:36:11 PM	No	
40 - Hours			DARTHURS	Jun 5, 2019 11:36:11 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	5.42
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**5.42**

Work Order Footer

Work Order 52418255 Total	
Parts:	19.23
Labor:	260.00
Labor Hours:	4.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**279.23**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52329366
Invoice No. 55345 - 52329366

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 170,103 - DH

Chronology		
Reported	May 9, 2019 12:00:00 AM	May 9, 2019 12:00:00 AM
Started	May 9, 2019 12:00:00 AM	
Completed	May 9, 2019 11:57:00 PM	May 9, 2019 11:57:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA Service

CAUSE: Service due by Mileage.

CORRECTION: Change Oil & Filter. Lube all Pivoting Points .check brakes Clean batteries.
Parts # B329 Qty (1)
Oil 5W20 Qty (7.0) Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-May-19	Arthurs,Durvin	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 09-MAY-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	May 9, 2019 11:40:44 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	May 9, 2019 11:40:44 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	May 9, 2019 11:40:44 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	May 9, 2019 11:40:44 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	May 9, 2019 11:40:44 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	May 9, 2019 11:40:44 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	May 9, 2019 11:40:44 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	May 9, 2019 11:40:44 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
40,420 - Check Hood	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	May 9, 2019 11:40:44 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	May 9, 2019 11:40:44 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	May 9, 2019 11:40:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	May 9, 2019 11:40:44 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	May 9, 2019 11:40:44 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	May 9, 2019 11:40:44 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	May 9, 2019 11:40:44 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	May 9, 2019 11:40:44 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	May 9, 2019 11:40:44 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	May 9, 2019 11:40:44 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	May 9, 2019 11:40:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	May 9, 2019 11:40:44 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
60,631 - Tread Depth RF	9 32nds of an inch		DARTHURS	May 9, 2019 11:40:44 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch		DARTHURS	May 9, 2019 11:40:44 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		DARTHURS	May 9, 2019 11:40:44 PM	No	
60,634 - Tread Depth RRI	9 32nds of an inch		DARTHURS	May 9, 2019 11:40:44 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		DARTHURS	May 9, 2019 11:40:44 PM	No	
60,636 - Tread Depth LRO	5 32nds of an inch		DARTHURS	May 9, 2019 11:40:44 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	May 9, 2019 11:40:44 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		DARTHURS	May 9, 2019 11:40:44 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		DARTHURS	May 9, 2019 11:40:44 PM	No	
77,133 - Brake Pad Thickness LR	4 Inch		DARTHURS	May 9, 2019 11:40:44 PM	No	
77,134 - Brake Pad Thickness RR	4 Inch		DARTHURS	May 9, 2019 11:40:44 PM	No	
77,135 - Brake Rotor LF	1.556 Inch		DARTHURS	May 9, 2019 11:40:44 PM	No	
77,136 - Brake Rotor RF	1.557 Inch		DARTHURS	May 9, 2019 11:40:44 PM	No	
77,137 - Brake Rotor LR	1.654 Inch		DARTHURS	May 9, 2019 11:40:44 PM	No	
77,138 - Brake Rotor RR	1.653 Inch		DARTHURS	May 9, 2019 11:40:44 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	May 9, 2019 11:40:44 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	May 9, 2019 11:40:44 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52329366
Invoice No. 55345 - 52329366

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 170,103 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-May-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-May-19	Arthurs,Durvin	0.4166666	65	27.083329

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 09-MAY-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	May 9, 2019 11:41:30 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	May 9, 2019 11:41:30 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	May 9, 2019 11:41:30 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	May 9, 2019 11:41:30 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	May 9, 2019 11:41:30 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	May 9, 2019 11:41:30 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	May 9, 2019 11:41:30 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	May 9, 2019 11:41:30 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	27.08
	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**29.04**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52329366
Invoice No. 55345 - 52329366

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	170,103 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-May-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 09-MAY-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	May 9, 2019 11:42:20 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	May 9, 2019 11:42:20 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	May 9, 2019 11:42:20 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	May 9, 2019 11:42:20 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	May 9, 2019 11:42:20 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	May 9, 2019 11:42:20 PM	No	
20 - Miles			DARTHURS	May 9, 2019 11:42:20 PM	No	
30 - Kilometers			DARTHURS	May 9, 2019 11:42:20 PM	No	
40 - Hours			DARTHURS	May 9, 2019 11:42:20 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	5.42
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**5.42**

Work Order Footer

Work Order 52329366 Total	
Parts:	1.96
Labor:	130.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**131.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52418230
Invoice No. 55345 - 52418230

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Rear Brakes		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	170,103 - DH

Chronology		
Reported	May 9, 2019 11:46:47 PM	May 9, 2019 11:46:47 PM
Started	May 9, 2019 12:00:00 AM	
Completed	May 9, 2019 11:56:00 PM	May 9, 2019 11:56:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear Brakes

Cause: Rear Brakes low/ uneven wear.

Correction: Remove&Replace Rear Brakes. Lube slide pins.
Parts#8C2Z-2V200-C Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-May-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 09-MAY-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	May 9, 2019 11:50:21 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	May 9, 2019 11:50:21 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	May 9, 2019 11:50:21 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	May 9, 2019 11:50:21 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	May 9, 2019 11:50:21 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	May 9, 2019 11:50:21 PM	No	
20 - Miles			DARTHURS	May 9, 2019 11:50:21 PM	No	
30 - Kilometers			DARTHURS	May 9, 2019 11:50:21 PM	No	
40 - Hours			DARTHURS	May 9, 2019 11:50:21 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	5.42
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.42**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52418230
Invoice No. 55345 - 52418230

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Rear Brakes		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	170,103 - DH

Activity Header
Activity: 15 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-May-19	8C2Z-2V200-C	PADS, BRAKE, DISC, REAR	1	47.81	47.81

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-May-19	Arthurs,Durvin	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	47.81
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**145.31**

Work Order Footer

Work Order 52418230 Total	
Parts:	47.81
Labor:	102.92
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**150.73**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52353783
Invoice No. 55345 - 52353783

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Left Driver Side Head light not working		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	166,760 - DH

Chronology		
Reported	Apr 17, 2019 11:14:00 PM	Apr 17, 2019 11:14:00 PM
Started	Apr 17, 2019 12:00:00 AM	
Completed	Apr 17, 2019 11:25:00 PM	Apr 17, 2019 11:25:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Front driver headlight not working

Cause: Head light bulb blown and pigtail is burned

Correction: Replace front driver head light and pigtail
Parts# 891699 Qty 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Apr-19	Owens,Arthur	0.2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: AOWENS Performed on: 17-APR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		AOWENS	Apr 17, 2019 11:24:45 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		AOWENS	Apr 17, 2019 11:24:45 PM	No	
3 - Are you wearing the appropriate PPE?	Done		AOWENS	Apr 17, 2019 11:24:45 PM	No	
4 - Have you performed the proper LOTO?	Done		AOWENS	Apr 17, 2019 11:24:45 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	Apr 17, 2019 11:24:45 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Apr 17, 2019 11:24:45 PM	No	
20 - Miles			AOWENS	Apr 17, 2019 11:24:45 PM	No	
30 - Kilometers			AOWENS	Apr 17, 2019 11:24:45 PM	No	
40 - Hours			AOWENS	Apr 17, 2019 11:24:45 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52353783
Invoice No. 55345 - 52353783

Client Department:
Department: 55345M
Work Order Description
Left Driver Side Head light not working
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 166,760 - DH

Activity Header
Activity: 15 034/001/000 HEADLAMP
Activity Note: Driver side Head light
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Apr-19	891699	OUT OF SERVICE DISCONTINUED USE 892292 PIGTAIL, HEADLAMP, 9008	1	7.41	7.41

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Apr-19	Owens,Arthur	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	7.41
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.41**

Work Order Footer

Work Order 52353783 Total	
Parts:	7.41
Labor:	0.00
Labor Hours:	1.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.41**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52252405
Invoice No. 55345 - 52252405

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	165,535 - DH

Chronology		
Reported	Apr 9, 2019 3:30:34 PM	Apr 9, 2019 3:30:34 PM
Started	Apr 9, 2019 12:00:00 AM	
Completed	Apr 9, 2019 11:53:00 PM	Apr 9, 2019 11:53:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION:

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Apr-19	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 09-APR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,140 - Check Service Brakes	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Apr 9, 2019 11:39:43 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Apr 9, 2019 11:39:43 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Apr 9, 2019 11:39:43 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Apr 9, 2019 11:39:43 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Apr 9, 2019 11:39:43 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
20,260 - Check Stop Request System	-	NA	DARTHURS	Apr 9, 2019 11:39:43 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Apr 9, 2019 11:39:43 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
40,420 - Check Hood	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Apr 9, 2019 11:39:43 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Apr 9, 2019 11:39:43 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Apr 9, 2019 11:39:43 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Apr 9, 2019 11:39:43 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Apr 9, 2019 11:39:43 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Apr 9, 2019 11:39:43 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Apr 9, 2019 11:39:43 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
60,631 - Tread Depth RF	9 32nds of an inch		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
60,632 - Tread Depth LF	11 32nds of an inch		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
60,633 - Tread Depth RRO	11 32nds of an inch		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
60,634 - Tread Depth RRI	11 32nds of an inch		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
60,635 - Tread Depth LRI	5 32nds of an inch		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Apr 9, 2019 11:39:43 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
77,131 - Brake Pad Thickness LF	9 Inch		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
77,132 - Brake Pad Thickness RF	9 Inch		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
77,135 - Brake Rotor LF	1.557 Inch		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
77,136 - Brake Rotor RF	1.558 Inch		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
77,137 - Brake Rotor LR	1.655 Inch		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
77,138 - Brake Rotor RR	1.654 Inch		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Apr 9, 2019 11:39:43 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Apr 9, 2019 11:39:43 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52252405
Invoice No. 55345 - 52252405

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 165,535 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Apr-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Apr-19	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 09-APR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Apr 9, 2019 11:40:38 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Apr 9, 2019 11:40:38 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Apr 9, 2019 11:40:38 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Apr 9, 2019 11:40:38 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Apr 9, 2019 11:40:38 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Apr 9, 2019 11:40:38 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Apr 9, 2019 11:40:38 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Apr 9, 2019 11:40:38 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52252405
Invoice No. 55345 - 52252405

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	165,535 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Apr-19	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 09-APR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Apr 9, 2019 11:41:20 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Apr 9, 2019 11:41:20 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Apr 9, 2019 11:41:20 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Apr 9, 2019 11:41:20 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Apr 9, 2019 11:41:20 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 9, 2019 11:41:20 PM	No	
20 - Miles			DARTHURS	Apr 9, 2019 11:41:20 PM	No	
30 - Kilometers			DARTHURS	Apr 9, 2019 11:41:20 PM	No	
40 - Hours			DARTHURS	Apr 9, 2019 11:41:20 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 52252405 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 5

Work Order No. 52250452
Invoice No. 55345 - 52250452

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Shifter Cable. Coolant Reservoir Front Tire		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	161,140 - DH

Chronology		
Reported	Mar 13, 2019 4:25:08 PM	Mar 13, 2019 4:25:08 PM
Started	Mar 13, 2019 12:00:00 AM	
Completed	Mar 14, 2019 10:06:16 AM	Mar 14, 2019 10:06:16 AM
Down Time		

Work Order Notes

Line 10 Complaints: front tire low thread

Cause: normal wear

Correction: Replaced Front Tire (1) Line 20 Complaints: Lift outer barrier Shock

Cause: normal wear

Correction: Replaced Outer battier Shock (1) Line 30 Complaints: coolant leaks

Cause: reservoir tank cracked

Correction: Replaced coolant reservoir tank
Line 40 Complaints: Shifter Cable

Cause: Shifter Cable cracked

Correction: Replaced Shifter Cable

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Mar-19	Delva,Terry	0.3833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
10 Desc: PERSONAL RISK ASSESMENT Task: PRA and Meter Readings Performed by: TDELVA Performed on: 14-MAR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Mar 14, 2019 9:37:29 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Mar 14, 2019 9:37:29 AM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Mar 14, 2019 9:37:29 AM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Mar 14, 2019 9:37:29 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Mar 14, 2019 9:37:29 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Mar 14, 2019 9:37:29 AM	No	
20 - Miles			TDELVA	Mar 14, 2019 9:37:29 AM	No	
30 - Kilometers			TDELVA	Mar 14, 2019 9:37:29 AM	No	
40 - Hours			TDELVA	Mar 14, 2019 9:37:29 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.38
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 5

Work Order No. 52250452
Invoice No. 55345 - 52250452

Client Department:
Department: 55345M
Work Order Description
Shifter Cable. Coolant Reservoir Front Tire
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 161,140 - DH

Activity Header
Activity: 20 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: Shifter Cable
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Mar-19	8C2Z-7E395-A	CABLE, SELECTOR, SHIFT	1	42.66	42.66
13-Mar-19	8C2Z-8A080-C	TANK, SURGE, COOLANT	1	80.22	80.22

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Mar-19	Delva,Terry	0.45	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	122.88
Labor:	0.00
Labor Hours:	0.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**122.88**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 5

Work Order No. 52250452
Invoice No. 55345 - 52250452

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Shifter Cable. Coolant Reservoir Front Tire		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	161,140 - DH

Activity Header
Activity: 30 042/000/000 COOLING SYSTEM
Activity Note: Coolant Reservoir
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Mar-19	Delva,Terry	1.4666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 5

Work Order No. 52250452
Invoice No. 55345 - 52250452

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Shifter Cable. Coolant Reservoir Front Tire		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	161,140 - DH

Activity Header
Activity: 40 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note: Front Tire
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Mar-19	002760	TIRE, 225/75R16, 10-PLY, BSW, HT2, TRANSFORCE, FIRESTONE	1	108.36	108.36
13-Mar-19	002760	TIRE, 225/75R16, 10-PLY, BSW, HT2, TRANSFORCE, FIRESTONE	1	108.36	108.36

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Mar-19	Delva,Terry	0.8833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	216.72
Labor:	0.00
Labor Hours:	0.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**216.72**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 5

Work Order No. 52250452
Invoice No. 55345 - 52250452

Client Department:
Department: 55345M
Work Order Description
Shifter Cable. Coolant Reservoir Front Tire
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 161,140 - DH

Activity Header
Activity: 50 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: Lift outer barrier shock
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Mar-19	32831	SPRING, SHOCK, GAS, W/C	1	26.46	26.46

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Mar-19	Delva,Terry	0.75	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 50 Sub Total	
Parts:	26.46
Labor:	0.00
Labor Hours:	0.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**26.46**

Work Order Footer

Work Order 52250452 Total	
Parts:	366.06
Labor:	0.00
Labor Hours:	3.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**366.06**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52188896
Invoice No. 55345 - 52188896

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM B		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	161,324 - DH

Chronology		
Reported	Mar 13, 2019 9:46:23 AM	Mar 13, 2019 9:46:23 AM
Started	Mar 13, 2019 12:00:00 AM	
Completed	Mar 14, 2019 10:00:00 AM	Mar 14, 2019 10:00:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMB

CAUSE: Service due

CORRECTION: Performed and completed pmB
Changed engine oil and replaced engine oil filter
Lube all Pivoting Points

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Mar-19	Delva,Terry	1.65	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: TDELVA Performed on: 13-MAR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
10,100 - Safety Inspection	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
10,140 - Check Service Brakes	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
10,160 - FRA Check Instruments and Horns	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
10,170 - Check Fast Idle	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
10,180 - Check Starter Protection Circuit	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
10,190 - Check Reverse Warning System	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
11,100 - Check Parking Brake	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
11,150 - Perform Brake Test	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	TDELVA	Mar 13, 2019 4:24:11 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	TDELVA	Mar 13, 2019 4:24:11 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	TDELVA	Mar 13, 2019 4:24:11 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	TDELVA	Mar 13, 2019 4:24:11 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	TDELVA	Mar 13, 2019 4:24:11 PM	No	
11,170 - FRA Check Door Operation	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
20,210 - Check Condition of Operator's Area	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
20,240 - FRA Check Interior Lights	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	TDELVA	Mar 13, 2019 4:24:11 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	TDELVA	Mar 13, 2019 4:24:11 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
22,110 - Check Emergency Hatches	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
22,120 - Check All Safety Equipment	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
30,310 - Check Passenger Doors	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	TDELVA	Mar 13, 2019 4:24:11 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
30,360 - Check for Physical Damage and Decals	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
30,380 - Check Exterior Compartment Doors	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
33,100 - Check Lights and Reflectors	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
40,420 - Check Hood	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	TDELVA	Mar 13, 2019 4:24:11 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	TDELVA	Mar 13, 2019 4:24:11 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	TDELVA	Mar 13, 2019 4:24:11 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	TDELVA	Mar 13, 2019 4:24:11 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
44,130 - FRA Check Exhaust System	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
44,140 - FRA Check Intake System	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	TDELVA	Mar 13, 2019 4:24:11 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
44,180 - FRA Check for Leaks	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
44,190 - FRA Perform Battery Inspection	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
50,510 - Check Entire Steering System	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		TDELVA	Mar 13, 2019 4:24:11 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		TDELVA	Mar 13, 2019 4:24:11 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		TDELVA	Mar 13, 2019 4:24:11 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		TDELVA	Mar 13, 2019 4:24:11 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		TDELVA	Mar 13, 2019 4:24:11 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		TDELVA	Mar 13, 2019 4:24:11 PM	No	
60,620 - Check Valve Stems and Caps	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
60,630 - Check and Record Tread Depth	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		TDELVA	Mar 13, 2019 4:24:11 PM	No	
60,632 - Tread Depth LF	5 32nds of an inch		TDELVA	Mar 13, 2019 4:24:11 PM	No	
60,633 - Tread Depth RRO	9 32nds of an inch		TDELVA	Mar 13, 2019 4:24:11 PM	No	
60,634 - Tread Depth RRI	9 32nds of an inch		TDELVA	Mar 13, 2019 4:24:11 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		TDELVA	Mar 13, 2019 4:24:11 PM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		TDELVA	Mar 13, 2019 4:24:11 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
60,650 - Check Sidewall Wear	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
60,660 - Inspect for Cuts and Tears	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
60,670 - Check Dual Mating With Square	-	NA	TDELVA	Mar 13, 2019 4:24:11 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
70,710 - Check Vibration Damper	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
70,730 - FRA Check Starter	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
70,770 - FRA Check Exhaust System	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
77,110 - FRA Check Fuel Tank	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
77,120 - Check Suspension Components	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		TDELVA	Mar 13, 2019 4:24:11 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		TDELVA	Mar 13, 2019 4:24:11 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		TDELVA	Mar 13, 2019 4:24:11 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		TDELVA	Mar 13, 2019 4:24:11 PM	No	
77,135 - Brake Rotor LF	39.7 Inch		TDELVA	Mar 13, 2019 4:24:11 PM	No	
77,136 - Brake Rotor RF	39.7 Inch		TDELVA	Mar 13, 2019 4:24:11 PM	No	
77,137 - Brake Rotor LR	39.6 Inch		TDELVA	Mar 13, 2019 4:24:11 PM	No	
77,138 - Brake Rotor RR	39.6 Inch		TDELVA	Mar 13, 2019 4:24:11 PM	No	
77,140 - FRA Check Brake Hoses	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
77,150 - Check King Pins	-	NA	TDELVA	Mar 13, 2019 4:24:11 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
80,810 - Completion of PMI Report	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		TDELVA	Mar 13, 2019 4:24:11 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52188896
Invoice No. 55345 - 52188896

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 161,324 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Mar-19	B329	FILTER, OIL, SPIN-ON SEE P550965	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Mar-19	Delva,Terry	1.4833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: TDELVA Performed on: 13-MAR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		TDELVA	Mar 13, 2019 4:24:50 PM	No	
101,000 - FRA Change Oil Filters	Yes		TDELVA	Mar 13, 2019 4:24:50 PM	No	
102,000 - FRA Drain Engine Oil	Yes		TDELVA	Mar 13, 2019 4:24:50 PM	No	
103,000 - FRA Check Transmission Fluid	Done		TDELVA	Mar 13, 2019 4:24:50 PM	No	
104,000 - Lubricate Chassis	Done		TDELVA	Mar 13, 2019 4:24:50 PM	No	
105,000 - Replace or Clean A/C Filters	Done		TDELVA	Mar 13, 2019 4:24:50 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	TDELVA	Mar 13, 2019 4:24:50 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		TDELVA	Mar 13, 2019 4:24:50 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		TDELVA	Mar 13, 2019 4:24:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
201,000 - Service Crankcase Breather	Done		TDELVA	Mar 13, 2019 4:24:50 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		TDELVA	Mar 13, 2019 4:24:50 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	Yes		TDELVA	Mar 13, 2019 4:24:50 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		TDELVA	Mar 13, 2019 4:24:50 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	1.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52188896
Invoice No. 55345 - 52188896

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM B		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	161,324 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Mar-19	Delva,Terry	0.8666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 13-MAR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Mar 13, 2019 4:13:36 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Mar 13, 2019 4:13:36 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Mar 13, 2019 4:13:36 PM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Mar 13, 2019 4:13:36 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Mar 13, 2019 4:13:36 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Mar 13, 2019 4:13:36 PM	No	
20 - Miles			TDELVA	Mar 13, 2019 4:13:36 PM	No	
30 - Kilometers			TDELVA	Mar 13, 2019 4:13:36 PM	No	
40 - Hours			TDELVA	Mar 13, 2019 4:13:36 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.87
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 52188896 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	4.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52106636
Invoice No. 55345 - 52106636

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 157,049 - DH

Chronology		
Reported	Feb 20, 2019 5:13:06 PM	Feb 20, 2019 5:13:06 PM
Started	Feb 20, 2019 12:00:00 AM	
Completed	Feb 20, 2019 11:56:00 PM	Feb 20, 2019 11:56:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE: Service

CORRECTION:Perform pmA Service
Oil filter B329 Qty1
Engine oil 5w20 qty 7 Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Feb-19	Gaspard,Ronald	1.6	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 20-FEB-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	RGASPARD	Feb 20, 2019 11:28:10 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	RGASPARD	Feb 20, 2019 11:28:10 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	RGASPARD	Feb 20, 2019 11:28:10 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	RGASPARD	Feb 20, 2019 11:28:10 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	RGASPARD	Feb 20, 2019 11:28:10 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	RGASPARD	Feb 20, 2019 11:28:10 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	RGASPARD	Feb 20, 2019 11:28:10 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	RGASPARD	Feb 20, 2019 11:28:10 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
40,420 - Check Hood	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	RGASPARD	Feb 20, 2019 11:28:10 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	RGASPARD	Feb 20, 2019 11:28:10 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	RGASPARD	Feb 20, 2019 11:28:10 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	RGASPARD	Feb 20, 2019 11:28:10 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	RGASPARD	Feb 20, 2019 11:28:10 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	RGASPARD	Feb 20, 2019 11:28:10 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Feb 20, 2019 11:28:10 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
60,632 - Tread Depth LF	11 32nds of an inch		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
60,633 - Tread Depth RRO	3 32nds of an inch		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
60,634 - Tread Depth RRI	3 32nds of an inch		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
77,137 - Brake Rotor LR	40 Inch		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
77,138 - Brake Rotor RR	40 Inch		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
77,150 - Check King Pins	-	NA	RGASPARD	Feb 20, 2019 11:28:10 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Feb 20, 2019 11:28:10 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52106636
Invoice No. 55345 - 52106636

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 157,049 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Feb-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Feb-19	Gaspard,Ronald	1.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 20-FEB-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Feb 20, 2019 11:28:51 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Feb 20, 2019 11:28:51 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Feb 20, 2019 11:28:51 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Feb 20, 2019 11:28:51 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Feb 20, 2019 11:28:51 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Feb 20, 2019 11:28:51 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Feb 20, 2019 11:28:51 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Feb 20, 2019 11:28:51 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	1.07
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52106636
Invoice No. 55345 - 52106636

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	157,049 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Feb-19	Gaspard,Ronald	0.25	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 20-FEB-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Feb 20, 2019 11:30:26 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Feb 20, 2019 11:30:26 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Feb 20, 2019 11:30:26 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Feb 20, 2019 11:30:26 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Feb 20, 2019 11:30:26 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Feb 20, 2019 11:30:26 PM	No	
20 - Miles			RGASPARD	Feb 20, 2019 11:30:26 PM	No	
30 - Kilometers			RGASPARD	Feb 20, 2019 11:30:26 PM	No	
40 - Hours			RGASPARD	Feb 20, 2019 11:30:26 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.25
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 52106636 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52188855
Invoice No. 55345 - 52188855

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Needs 2 new tires		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	157,049 - DH

Chronology		
Reported	Feb 20, 2019 11:32:43 PM	Feb 20, 2019 11:32:43 PM
Started	Feb 20, 2019 12:00:00 AM	
Completed	Feb 20, 2019 11:55:00 PM	Feb 20, 2019 11:55:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs 2 right rear tires

Cause: wear

Correction:2 new tires mounted and balanced washed rims
Torque wheels 140 lbs second torque wheels 140 lbs
Part number 002760 qty2

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Feb-19	Gaspard,Ronald	0.1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 20-FEB-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Feb 20, 2019 11:35:00 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Feb 20, 2019 11:35:00 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Feb 20, 2019 11:35:00 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Feb 20, 2019 11:35:00 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Feb 20, 2019 11:35:00 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Feb 20, 2019 11:35:00 PM	No	
20 - Miles			RGASPARD	Feb 20, 2019 11:35:00 PM	No	
30 - Kilometers			RGASPARD	Feb 20, 2019 11:35:00 PM	No	
40 - Hours			RGASPARD	Feb 20, 2019 11:35:00 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52188855
Invoice No. 55345 - 52188855

Client Department:
Department: 55345M
Work Order Description
Needs 2 new tires
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 157,049 - DH

Activity Header
Activity: 15 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note: Needs 2 new tires
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Feb-19	002760	TIRE, 225/75R16, 10-PLY, BSW, HT2, TRANSFORCE, FIRESTONE	2	108.36	216.72

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Feb-19	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	216.72
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**216.72**

Work Order Footer

Work Order 52188855 Total	
Parts:	216.72
Labor:	0.00
Labor Hours:	1.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**216.72**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52158105
Invoice No. 55345 - 52158105

Client Department:

Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Road call front driver tire flat		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	155,608 - DH

Chronology		
Reported	Feb 11, 2019 8:47:37 AM	Feb 11, 2019 8:47:37 AM
Started	Feb 14, 2019 12:00:00 AM	
Completed	Feb 14, 2019 7:19:00 AM	Feb 14, 2019 7:19:00 AM
Down Time		

Work Order Notes

Line 10 Road call front tire flat

Nail on it

Replace tire with new tire completed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Feb-19	Pierre,Hubert J	3	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 14-FEB-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Feb 14, 2019 7:15:26 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Feb 14, 2019 7:15:26 AM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Feb 14, 2019 7:15:26 AM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Feb 14, 2019 7:15:26 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Feb 14, 2019 7:15:26 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Feb 14, 2019 7:15:26 AM	No	
20 - Miles			HPIERRE	Feb 14, 2019 7:15:26 AM	No	
30 - Kilometers	4		HPIERRE	Feb 14, 2019 7:15:26 AM	No	
40 - Hours	4		HPIERRE	Feb 14, 2019 7:15:26 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52158105
Invoice No. 55345 - 52158105

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Road call front driver tire flat		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	155,608 - DH

Activity Header
Activity:20 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Feb-19	002760	TIRE, 225/75R16, 10-PLY, BSW, HT2, TRANSFORCE, FIRESTONE	1	112.26	112.26

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Feb-19	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	112.26
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**112.26**

Work Order Footer

Work Order 52158105 Total	
Parts:	112.26
Labor:	0.00
Labor Hours:	3.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**112.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52009321
Invoice No. 55345 - 52009321

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	152,700 - DH

Chronology		
Reported	Jan 23, 2019 1:01:46 PM	Jan 23, 2019 1:01:46 PM
Started	Jan 23, 2019 12:00:00 AM	
Completed	Jan 23, 2019 11:00:00 PM	Jan 23, 2019 11:00:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA Service

CAUSE: Service Due by Mileage

CORRECTION: Change Oil& Filter. Lube all Pivoting Points Clean batteries. Check brakes .Replace. A/C filter replace Oil drain plugs.
Parts# B329 Qty (1)
Oil 5W20QTY (7.0) Qt
Parts#65266 Qty (1)

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jan-19	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 23-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Jan 23, 2019 10:17:30 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Jan 23, 2019 10:17:30 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Jan 23, 2019 10:17:30 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Jan 23, 2019 10:17:30 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Jan 23, 2019 10:17:30 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
20,260 - Check Stop Request System	-	NA	DARTHURS	Jan 23, 2019 10:17:30 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Jan 23, 2019 10:17:30 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Jan 23, 2019 10:17:30 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
40,420 - Check Hood	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Jan 23, 2019 10:17:30 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Jan 23, 2019 10:17:30 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Jan 23, 2019 10:17:30 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Jan 23, 2019 10:17:30 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Jan 23, 2019 10:17:30 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Jan 23, 2019 10:17:30 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Jan 23, 2019 10:17:30 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
60,631 - Tread Depth RF	9 32nds of an inch		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
60,634 - Tread Depth RRI	5 32nds of an inch		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
60,635 - Tread Depth LRI	5 32nds of an inch		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
60,636 - Tread Depth LRO	3 32nds of an inch		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Jan 23, 2019 10:17:30 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
77,131 - Brake Pad Thickness LF	4 Inch		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
77,132 - Brake Pad Thickness RF	5 Inch		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
77,133 - Brake Pad Thickness LR	9 Inch		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
77,134 - Brake Pad Thickness RR	9 Inch		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
77,135 - Brake Rotor LF	1.554 Inch		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
77,136 - Brake Rotor RF	1.553 Inch		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
77,137 - Brake Rotor LR	1.654 Inch		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
77,138 - Brake Rotor RR	1.653 Inch		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Jan 23, 2019 10:17:30 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Jan 23, 2019 10:17:30 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52009321
Invoice No. 55345 - 52009321

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 152,700 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Jan-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96
23-Jan-19	65266	PLUG, DRAIN, OIL, ENGINE	1	4.5	4.5

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jan-19	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 23-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Jan 23, 2019 10:18:23 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Jan 23, 2019 10:18:23 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Jan 23, 2019 10:18:23 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Jan 23, 2019 10:18:23 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Jan 23, 2019 10:18:23 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Jan 23, 2019 10:18:23 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Jan 23, 2019 10:18:23 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Jan 23, 2019 10:18:23 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	6.46
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**6.46**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52009321
Invoice No. 55345 - 52009321

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	152,700 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jan-19	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 23-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jan 23, 2019 10:19:02 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jan 23, 2019 10:19:02 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jan 23, 2019 10:19:02 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jan 23, 2019 10:19:02 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jan 23, 2019 10:19:02 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jan 23, 2019 10:19:02 PM	No	
20 - Miles			DARTHURS	Jan 23, 2019 10:19:02 PM	No	
30 - Kilometers			DARTHURS	Jan 23, 2019 10:19:02 PM	No	
40 - Hours			DARTHURS	Jan 23, 2019 10:19:02 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 52009321 Total	
Parts:	6.46
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**6.46**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52106608
Invoice No. 55345 - 52106608

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Front Brakes		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	152,700 - DH

Chronology		
Reported	Jan 23, 2019 10:25:50 PM	Jan 23, 2019 10:25:50 PM
Started	Jan 23, 2019 12:00:00 AM	
Completed	Jan 23, 2019 10:59:00 PM	Jan 23, 2019 10:59:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Front Brakes

Cause: Brakes low

Correction: Remove& Replace Front Brakes& Lube Slide pins
Parts#8C2Z-2V001-D Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jan-19	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 23-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jan 23, 2019 10:27:20 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jan 23, 2019 10:27:20 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jan 23, 2019 10:27:20 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jan 23, 2019 10:27:20 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jan 23, 2019 10:27:20 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jan 23, 2019 10:27:20 PM	No	
20 - Miles			DARTHURS	Jan 23, 2019 10:27:20 PM	No	
30 - Kilometers			DARTHURS	Jan 23, 2019 10:27:20 PM	No	
40 - Hours			DARTHURS	Jan 23, 2019 10:27:20 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52106608
Invoice No. 55345 - 52106608

Client Department:
Department: 55345M
Work Order Description
Front Brakes
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 152,700 - DH

Activity Header
Activity: 15 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Jan-19	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	48.87	48.87

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jan-19	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	48.87
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**48.87**

Work Order Footer

Work Order 52106608 Total	
Parts:	48.87
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**48.87**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52047125
Invoice No. 55345 - 52047125

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Replaced transmission		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	150,048 - DH

Chronology		
Reported	Jan 4, 2019 7:16:58 PM	Jan 4, 2019 7:16:58 PM
Started	Jan 4, 2019 12:00:00 AM	
Completed	Jan 16, 2019 1:45:24 PM	Jan 16, 2019 1:45:24 PM
Down Time		

Work Order Notes

Line 10 Gas P0751 Transmission

COMPLAINT:
Check engine light is on P0751 transmission shift solenoid stuck OFF

CAUSE:
Per FORD bulletin (TSB 16-0057) this transmission needs to be removed and rebuilt.

CORRECTION
Removed transmission from vehicle and sent transmission to be repaired. Received transmission back from the transmission shop and installed transmission back onto vehicle with a new torque converter. Filled transmission with approximately 16qts of transmission fluid. Erased engine light. Test drove and re-checked fluid level. Transmission is shifting properly and the check engine light did not come on.

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Jan-19	AMRIT TEEMAL,VISHNU	4	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 04-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Jan 4, 2019 7:22:39 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Jan 4, 2019 7:22:39 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Jan 4, 2019 7:22:39 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Jan 4, 2019 7:22:39 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Jan 4, 2019 7:22:39 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Jan 4, 2019 7:22:39 PM	No	
20 - Miles			VAMRITTEEMAL	Jan 4, 2019 7:22:39 PM	No	
30 - Kilometers			VAMRITTEEMAL	Jan 4, 2019 7:22:39 PM	No	
40 - Hours			VAMRITTEEMAL	Jan 4, 2019 7:22:39 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	4.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52047125
Invoice No. 55345 - 52047125

Client Department:
Department: 55345M
Work Order Description
Replaced transmission
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 150,048 - DH

Activity Header
Activity: 20 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 43 Weak
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Jan-19	7C3Z-7G387-B	CYLINDER, CLUTCH, TRANSMISSION	1	74.29	74.29
16-Jan-19	F81Z-7A527-AA	RING, SNAP, CLUTCH, TRANSMISSION	1	2.42	2.42
16-Jan-19	8C3Z-7C155-A	GASKET, BODY, VALVE, TRANSMISSION, 5R110	1	24.89	24.89
04-Jan-19	3C3Z-7G299-AA	RETAINER, GEAR, PLANETARY	1	9.03	9.03
04-Jan-19	19180251	TRANSMISSION, REMANUFACTURED	1	486.03	486.03
04-Jan-19	20021	FILTER, TRANSMISSION 20021	1	17.27	17.27
16-Jan-19	6C3Z-7A262-AA	CLUTCH, FORWARD, TRANSMISSION	1	21.58	21.58

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Jan-19	AMRIT TEEMAL,VISHNU	0.2666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: 55345 TRANSMISSION DTC P0751 SHIFT SOLENOID Performed by: VAMRITTEEMAL Performed on: 04-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - 55345 TRANSMISSION DTC P0751 SHIFT SOLENOID	Done		VAMRITTEEMAL	Jan 4, 2019 7:22:09 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	652.78
Labor:	0.00
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**652.78**

Work Order Footer

	Work Order 52047125 Total	
	Parts:	652.78
	Labor:	0.00
	Labor Hours:	4.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**652.78**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52033695
Invoice No. 55345 - 52033695

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Spark plugs		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	149,623 - DH

Chronology		
Reported	Dec 31, 2018 8:19:19 AM	Dec 31, 2018 8:19:19 AM
Started	Dec 31, 2018 12:00:00 AM	
Completed	Dec 31, 2018 10:13:56 AM	Dec 31, 2018 10:13:56 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:spark plugs

Cause: Preventive Maintenance

Correction:replaced spark plugs and boots and clean throttle body

Parts:
10 spark plugs ap103
10 boots 357006

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 31-DEC-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Dec 31, 2018 8:25:25 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Dec 31, 2018 8:25:25 AM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Dec 31, 2018 8:25:25 AM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Dec 31, 2018 8:25:25 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Dec 31, 2018 8:25:25 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Dec 31, 2018 8:25:25 AM	No	
20 - Miles			JAPEREZ	Dec 31, 2018 8:25:25 AM	No	
30 - Kilometers			JAPEREZ	Dec 31, 2018 8:25:25 AM	No	
40 - Hours			JAPEREZ	Dec 31, 2018 8:25:25 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52033695
Invoice No. 55345 - 52033695

Client Department:
Department: 55345M
Work Order Description
Spark plugs
Requested By: JAPEREZ
Created By: JAPEREZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 149,623 - DH

Activity Header
Activity: 15 033 IGNITION
Activity Note: Spark plugs
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
31-Dec-18	357006	BOOT, COIL-ON-PLUG, IGNITION	10	3.95	39.5
31-Dec-18	AP103	PLUG, SPARK	10	2.9	29

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Dec-18	Perez,Javier	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	68.50
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**68.50**

Work Order Footer

Work Order 52033695 Total	
Parts:	68.50
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**68.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51914011
Invoice No. 55345 - 51914011

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM C		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	148,403 - DH

Chronology		
Reported	Dec 18, 2018 8:27:30 AM	Dec 18, 2018 8:27:30 AM
Started	Dec 18, 2018 12:00:00 AM	
Completed	Dec 19, 2018 8:59:00 AM	Dec 19, 2018 8:59:00 AM
Down Time		

Work Order Notes

Line 10 PMC

Preventive maintenance

Perform service lube all Pivoting Points cross Rotate Tires completed

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Dec-18	Pierre,Hubert J	7	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 18-DEC-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
10,100 - Safety Inspection	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,140 - Check Service Brakes	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
11,152 - Decelerometer Results Test 1	FEET	N/A	HPIERRE	Dec 18, 2018 1:57:17 PM	No	
11,154 - Decelerometer Results Test 2	FEET	N/A	HPIERRE	Dec 18, 2018 1:57:17 PM	No	
11,156 - Decelerometer Results Test 3	FEET	N/A	HPIERRE	Dec 18, 2018 1:57:17 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	Dec 18, 2018 1:57:17 PM	No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	Dec 18, 2018 1:57:17 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
20,260 - Check Stop Request System	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Dec 18, 2018 1:57:17 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Dec 18, 2018 1:57:17 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
40,420 - Check Hood	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Dec 18, 2018 1:57:17 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Dec 18, 2018 1:57:17 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Dec 18, 2018 1:57:17 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Dec 18, 2018 1:57:17 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Dec 18, 2018 1:57:17 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Dec 18, 2018 1:57:17 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Dec 18, 2018 1:57:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
60,631 - Tread Depth RF	6 32nds of an inch		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
60,632 - Tread Depth LF	6 32nds of an inch		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
60,634 - Tread Depth RRI	5 32nds of an inch		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
60,635 - Tread Depth LRI	5 32nds of an inch		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
60,636 - Tread Depth LRO	5 32nds of an inch		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
60,670 - Check Dual Mating With Square	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
77,135 - Brake Rotor LF	1.5 Inch		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
77,136 - Brake Rotor RF	1.5 Inch		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
77,137 - Brake Rotor LR	1.6 Inch		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
77,138 - Brake Rotor RR	1.6 Inch		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Dec 18, 2018 1:57:17 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Dec 18, 2018 1:57:17 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	7.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51914011
Invoice No. 55345 - 51914011

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 148,403 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Dec-18	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: HPIERRE Performed on: 18-DEC-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Dec 18, 2018 1:59:44 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Dec 18, 2018 1:59:44 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Dec 18, 2018 1:59:44 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Dec 18, 2018 1:59:44 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Dec 18, 2018 1:59:44 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Dec 18, 2018 1:59:44 PM	No	
107,000 - FRA Change Primary Fuel Filter	Done		HPIERRE	Dec 18, 2018 1:59:44 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Dec 18, 2018 1:59:44 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		HPIERRE	Dec 18, 2018 1:59:44 PM	No	
201,000 - Service Crankcase Breather	Done		HPIERRE	Dec 18, 2018 1:59:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	Yes		HPIERRE	Dec 18, 2018 1:59:44 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		HPIERRE	Dec 18, 2018 1:59:44 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		HPIERRE	Dec 18, 2018 1:59:44 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		HPIERRE	Dec 18, 2018 1:59:44 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		HPIERRE	Dec 18, 2018 1:59:44 PM	No	
302,000 - Check Toe-In and Record Reading	-	N/A	HPIERRE	Dec 18, 2018 1:59:44 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	N/A	HPIERRE	Dec 18, 2018 1:59:44 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No	N/A	HPIERRE	Dec 18, 2018 1:59:44 PM	No	
305,000 - FRA Change Differential Fluid	Yes		HPIERRE	Dec 18, 2018 1:59:44 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51914011
Invoice No. 55345 - 51914011

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM C		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	148,403 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Dec-18	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 18-DEC-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Dec 18, 2018 2:00:26 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Dec 18, 2018 2:00:26 PM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Dec 18, 2018 2:00:26 PM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Dec 18, 2018 2:00:26 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Dec 18, 2018 2:00:26 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Dec 18, 2018 2:00:26 PM	No	
20 - Miles			HPIERRE	Dec 18, 2018 2:00:26 PM	No	
30 - Kilometers	3		HPIERRE	Dec 18, 2018 2:00:26 PM	No	
40 - Hours	7		HPIERRE	Dec 18, 2018 2:00:26 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 51914011 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	7.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51971170
Invoice No. 55345 - 51971170

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Spark plugs		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	146,368 - DH

Chronology		
Reported	Dec 6, 2018 2:20:23 PM	Dec 6, 2018 2:20:23 PM
Started	Dec 6, 2018 12:00:00 AM	
Completed	Dec 7, 2018 9:29:47 AM	Dec 7, 2018 9:29:47 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:spark plugs

Cause: preventive maintenance

Correction: Replaced all spark plugs and coil boots. While replacing spark plugs found serpentine belt is cracked. Replaced belt

Parts:
8 new spark plugs
8 coil boots
1 new belt

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 06-DEC-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Dec 6, 2018 2:29:25 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Dec 6, 2018 2:29:25 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Dec 6, 2018 2:29:25 PM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Dec 6, 2018 2:29:25 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Dec 6, 2018 2:29:25 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Dec 6, 2018 2:29:25 PM	No	
20 - Miles			JAPEREZ	Dec 6, 2018 2:29:25 PM	No	
30 - Kilometers			JAPEREZ	Dec 6, 2018 2:29:25 PM	No	
40 - Hours			JAPEREZ	Dec 6, 2018 2:29:25 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51971170
Invoice No. 55345 - 51971170

Client Department:
Department: 55345M
Work Order Description
Spark plugs
Requested By: JAPEREZ
Created By: JAPEREZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 146,368 - DH

Activity Header
Activity: 15 033 IGNITION
Activity Note: Spark plugs
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Dec-18	357006	BOOT, COIL-ON-PLUG, IGNITION	10	3.95	39.5
06-Dec-18	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	22.2	22.2
06-Dec-18	AP103	PLUG, SPARK	10	2.9	29

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Dec-18	Perez,Javier	3.25	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	90.70
Labor:	0.00
Labor Hours:	3.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**90.70**

Work Order Footer

Work Order 51971170 Total	
Parts:	90.70
Labor:	0.00
Labor Hours:	3.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**90.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51929907
Invoice No. 55345 - 51929907

Client Department:
Department: 55345M
Work Order Description
W/C lift buckle
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 144,383 - DH

Chronology		
Reported	Nov 21, 2018 3:36:17 PM	Nov 21, 2018 3:36:17 PM
Started	Nov 21, 2018 12:00:00 AM	
Completed	Nov 21, 2018 3:51:00 PM	Nov 21, 2018 3:51:00 PM
Down Time		

Work Order Notes

Line 10 Replaced W/C lift buckle

Activity Header
Activity: 10 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: Replaced W/C lift buckle
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Nov-18	28983	BUCKLE, SAFETY, W/C, BRAUN	1	21.8	21.8

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Nov-18	AMRIT TEEMAL,VISHNU	0.2666666	0	0
21-Nov-18	AMRIT TEEMAL,VISHNU	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	21.80
Labor:	0.00
Labor Hours:	0.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**21.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51929907
Invoice No. 55345 - 51929907

Client Department:
Department: 55345M
Work Order Description
W/C lift buckle
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 144,383 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 21-NOV-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Nov 21, 2018 3:51:09 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Nov 21, 2018 3:51:09 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Nov 21, 2018 3:51:09 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Nov 21, 2018 3:51:09 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Nov 21, 2018 3:51:09 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Nov 21, 2018 3:51:09 PM	No	
20 - Miles			VAMRITTEEMAL	Nov 21, 2018 3:51:09 PM	No	
30 - Kilometers			VAMRITTEEMAL	Nov 21, 2018 3:51:09 PM	No	
40 - Hours			VAMRITTEEMAL	Nov 21, 2018 3:51:09 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 51929907 Total	
Parts:	21.80
Labor:	0.00
Labor Hours:	0.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**21.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51922084
Invoice No. 55345 - 51922084

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Engine is low on coolant		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	144,092 - DH

Chronology		
Reported	Nov 19, 2018 2:30:39 PM	Nov 19, 2018 2:30:39 PM
Started	Nov 19, 2018 12:00:00 AM	
Completed	Nov 20, 2018 2:14:23 PM	Nov 20, 2018 2:14:23 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:engine is low on coolant

Cause: pressure test coolant system found coolant is burn through the head gasket

Correction:flush coolant system to install stop leak, retest and road test vehicle ok at this time

Part:
1 stop leak

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 19-NOV-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Nov 19, 2018 2:38:36 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Nov 19, 2018 2:38:36 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Nov 19, 2018 2:38:36 PM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Nov 19, 2018 2:38:36 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Nov 19, 2018 2:38:36 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Nov 19, 2018 2:38:36 PM	No	
20 - Miles			JAPEREZ	Nov 19, 2018 2:38:36 PM	No	
30 - Kilometers			JAPEREZ	Nov 19, 2018 2:38:36 PM	No	
40 - Hours			JAPEREZ	Nov 19, 2018 2:38:36 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51922084
Invoice No. 55345 - 51922084

Client Department:
Department: 55345M
Work Order Description
Engine is low on coolant
Requested By: JAPEREZ
Created By: JAPEREZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 144,092 - DH

Activity Header
Activity: 15 042 COOLING SYSTEM
Activity Note: Engine is low on coolant
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Nov-18	38386	TREATMENT, SEALER, COOLANT	1	65.73	65.73

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Nov-18	Perez,Javier	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	65.73
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**65.73**

Work Order Footer

Work Order 51922084 Total	
Parts:	65.73
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**65.73**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51836586
Invoice No. 55345 - 51836586

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	143,885 - DH

Chronology		
Reported	Nov 15, 2018 12:00:00 AM	Nov 15, 2018 12:00:00 AM
Started	Nov 15, 2018 12:00:00 AM	
Completed	Nov 15, 2018 7:54:00 PM	Nov 15, 2018 7:54:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA Service

CAUSE: preventive maintenance

CORRECTION: Performed and completed
Replaced air filter

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Nov-18	AMRIT TEEMAL,VISHNU	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: VAMRITTEEMAL Performed on: 15-NOV-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
10,100 - Safety Inspection	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
10,140 - Check Service Brakes	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
10,160 - FRA Check Instruments and Horns	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
10,170 - Check Fast Idle	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
10,180 - Check Starter Protection Circuit	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
10,190 - Check Reverse Warning System	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
11,100 - Check Parking Brake	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
11,150 - Perform Brake Test	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
11,152 - Decelerometer Results Test 1	FEET	n/a	VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
11,154 - Decelerometer Results Test 2	FEET	n/a	VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
11,156 - Decelerometer Results Test 3	FEET	n/a	VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
11,170 - FRA Check Door Operation	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
20,210 - Check Condition of Operator's Area	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
20,240 - FRA Check Interior Lights	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	n/a	VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
22,110 - Check Emergency Hatches	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
22,120 - Check All Safety Equipment	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
30,310 - Check Passenger Doors	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
30,360 - Check for Physical Damage and Decals	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
30,380 - Check Exterior Compartment Doors	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
33,100 - Check Lights and Reflectors	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
40,420 - Check Hood	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
44,130 - FRA Check Exhaust System	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
44,140 - FRA Check Intake System	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
44,180 - FRA Check for Leaks	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
44,190 - FRA Perform Battery Inspection	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
50,510 - Check Entire Steering System	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	70 Pounds per Square Inch		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
60,620 - Check Valve Stems and Caps	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
60,630 - Check and Record Tread Depth	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
60,631 - Tread Depth RF	12 32nds of an inch		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
60,650 - Check Sidewall Wear	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
60,660 - Inspect for Cuts and Tears	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
70,710 - Check Vibration Damper	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
70,730 - FRA Check Starter	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
70,770 - FRA Check Exhaust System	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
77,110 - FRA Check Fuel Tank	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
77,120 - Check Suspension Components	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
77,133 - Brake Pad Thickness LR	4 Inch		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
77,134 - Brake Pad Thickness RR	4 Inch		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
77,135 - Brake Rotor LF	39.91 Inch		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
77,136 - Brake Rotor RF	39.9 Inch		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
77,137 - Brake Rotor LR	35.84 Inch		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
77,138 - Brake Rotor RR	35.89 Inch		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
77,140 - FRA Check Brake Hoses	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
77,150 - Check King Pins	-	n/a	VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
80,810 - Completion of PMI Report	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		VAMRITTEEMAL	Nov 15, 2018 7:40:23 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51913998
Invoice No. 55345 - 51913998

Client Department:
Department: 55345M
Work Order Description
Rear brakes
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 143,885 - DH

Chronology

Reported	Nov 15, 2018 7:41:14 PM	Nov 15, 2018 7:41:14 PM
Started	Nov 15, 2018 12:00:00 AM	
Completed	Nov 15, 2018 7:54:00 PM	Nov 15, 2018 7:54:00 PM
Down Time		

Work Order Notes

Line 10 Replaced rear brakes

Activity Header
Activity: 10 013/000/000 BRAKES
Activity Note: Rear brakes
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Nov-18	8C2Z-2V200-C	PADS, BRAKE, DISC, REAR	1	47.81	47.81

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Nov-18	AMRIT TEEMAL,VISHNU	1.75	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	47.81
Labor:	0.00
Labor Hours:	1.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**47.81**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51836586
Invoice No. 55345 - 51836586

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 143,885 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Nov-18	PA4075	FILTER, AIR SEE P546597	1	5.27	5.27
15-Nov-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Nov-18	AMRIT TEEMAL,VISHNU	1	0	0
15-Nov-18	AMRIT TEEMAL,VISHNU	0.2666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: VAMRITTEEMAL Performed on: 15-NOV-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		VAMRITTEEMAL	Nov 15, 2018 7:41:01 PM	No	
101,000 - FRA Change Oil Filters	Yes		VAMRITTEEMAL	Nov 15, 2018 7:41:01 PM	No	
102,000 - FRA Drain Engine Oil	Yes		VAMRITTEEMAL	Nov 15, 2018 7:41:01 PM	No	
103,000 - FRA Check Transmission Fluid	Done		VAMRITTEEMAL	Nov 15, 2018 7:41:01 PM	No	
104,000 - Lubricate Chassis	Done		VAMRITTEEMAL	Nov 15, 2018 7:41:01 PM	No	
105,000 - Replace or Clean A/C Filters	Done		VAMRITTEEMAL	Nov 15, 2018 7:41:01 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	VAMRITTEEMAL	Nov 15, 2018 7:41:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
108,000 - Lube all pivoting Mechanisms	Done		VAMRITTEEMAL	Nov 15, 2018 7:41:01 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	7.23
Labor:	0.00
Labor Hours:	1.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.23**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51913998
Invoice No. 55345 - 51913998

Client Department:
Department: 55345M
Work Order Description
Rear brakes
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 143,885 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Nov-18	AMRIT TEEMAL,VISHNU	0.2666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 15-NOV-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Nov 15, 2018 7:49:22 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Nov 15, 2018 7:49:22 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Nov 15, 2018 7:49:22 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Nov 15, 2018 7:49:22 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Nov 15, 2018 7:49:22 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Nov 15, 2018 7:49:22 PM	No	
20 - Miles			VAMRITTEEMAL	Nov 15, 2018 7:49:22 PM	No	
30 - Kilometers			VAMRITTEEMAL	Nov 15, 2018 7:49:22 PM	No	
40 - Hours			VAMRITTEEMAL	Nov 15, 2018 7:49:22 PM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 51913998 Total	
Parts:	47.81
Labor:	0.00
Labor Hours:	2.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**47.81**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51836586
Invoice No. 55345 - 51836586

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	143,885 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 15-NOV-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Nov 15, 2018 7:25:48 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Nov 15, 2018 7:25:48 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Nov 15, 2018 7:25:48 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Nov 15, 2018 7:25:48 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Nov 15, 2018 7:25:48 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Nov 15, 2018 7:25:48 PM	No	
20 - Miles			VAMRITTEEMAL	Nov 15, 2018 7:25:48 PM	No	
30 - Kilometers			VAMRITTEEMAL	Nov 15, 2018 7:25:48 PM	No	
40 - Hours			VAMRITTEEMAL	Nov 15, 2018 7:25:48 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 51836586 Total	
Parts:	7.23
Labor:	0.00
Labor Hours:	2.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.23**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51874841
Invoice No. 55345 - 51874841

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Tires		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	141,582 - DH

Chronology		
Reported	Nov 4, 2018 3:36:32 PM	Nov 4, 2018 3:36:32 PM
Started	Nov 4, 2018 12:00:00 AM	
Completed	Nov 5, 2018 9:17:35 AM	Nov 5, 2018 9:17:35 AM
Down Time		

Work Order Notes

Line 10 Replaced Front Tire (1)

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Nov-18	Delva,Terry	0.7166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 04-NOV-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Nov 4, 2018 3:40:59 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Nov 4, 2018 3:40:59 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Nov 4, 2018 3:40:59 PM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Nov 4, 2018 3:40:59 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Nov 4, 2018 3:40:59 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Nov 4, 2018 3:40:59 PM	No	
20 - Miles			TDELVA	Nov 4, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:40:59 PM		
30 - Kilometers			TDELVA	Nov 4, 2018 3:40:59 PM	No	
40 - Hours			TDELVA	Nov 4, 2018 3:40:59 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51874841
Invoice No. 55345 - 51874841

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Tires		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	141,582 - DH

Activity Header
Activity: 20 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note: Tires
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Nov-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	1	103.44	103.44

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Nov-18	Delva,Terry	1.4833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	103.44
Labor:	0.00
Labor Hours:	1.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**103.44**

Work Order Footer

Work Order 51874841 Total	
Parts:	103.44
Labor:	0.00
Labor Hours:	2.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**103.44**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51844882
Invoice No. 55345 - 51844882

Client Department:
Department: 55345M
Work Order Description
Needs inner and outter bearings in right side wheel
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 139,681 - DH

Chronology		
Reported	Oct 24, 2018 11:12:38 PM	Oct 24, 2018 11:12:38 PM
Started	Oct 24, 2018 12:00:00 AM	
Completed	Oct 25, 2018 9:24:34 AM	Oct 25, 2018 9:24:34 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:driver complaints right front wheel making noise

Needs bearings

Correction: replaced inner and outer bearings seal repack bearings
Inner part number LM102949 Qty1
Outer TM 15101 Qty1
Seal CR24000 Qty1
Torque wheel 140 lbs second torque 140 lbs

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Oct-18	Gaspard,Ronald	0.1333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 24-OCT-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Oct 24, 2018 11:19:40 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Oct 24, 2018 11:19:40 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Oct 24, 2018 11:19:40 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Oct 24, 2018 11:19:40 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Oct 24, 2018 11:19:40 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Oct 24, 2018 11:19:40 PM	No	
20 - Miles			RGASPARD	Oct 24, 2018 11:19:40 PM	No	
30 - Kilometers			RGASPARD	Oct 24, 2018 11:19:40 PM	No	
40 - Hours			RGASPARD	Oct 24, 2018 11:19:40 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51844882
Invoice No. 55345 - 51844882

Client Department:
Department: 55345M
Work Order Description
Needs inner and outter bearings in right side wheel
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 139,681 - DH

Activity Header
Activity: 15 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Right side wheel needs bearings
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Oct-18	Gaspard,Ronald	1.05	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51844882
Invoice No. 55345 - 51844882

Client Department:
Department: 55345M
Work Order Description
Needs inner and outter bearings in right side wheel
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 139,681 - DH

Activity Header
Activity: 25 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Oct-18	CR24000	SEAL, WHEEL, HUB, FRONT	2	6.92	13.84
25-Oct-18	LM102949	BEARING, WHEEL, INNER, FRONT, TAPERED	2	7.44	14.88
25-Oct-18	TM15101	BEARING, WHEEL, OUTER, CONE, ROLLER, TAPERED	2	8.16	16.32

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	45.04
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**45.04**

Work Order Footer

Work Order 51844882 Total	
Parts:	45.04
Labor:	0.00
Labor Hours:	1.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**45.04**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51836579
Invoice No. 55345 - 51836579

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Needs 2 front tires		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	139,253 - DH

Chronology		
Reported	Oct 23, 2018 12:20:45 AM	Oct 23, 2018 12:20:45 AM
Started	Oct 23, 2018 12:00:00 AM	
Completed	Oct 24, 2018 12:15:00 AM	Oct 24, 2018 12:15:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction:

Line 20 Needs 2 front tires
Wear
2 new tires mounted and balance
Torque wheels 140 lbs second torque 140 lbs
Part number 189752 qty2

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Oct-18	Gaspard,Ronald	0.1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 23-OCT-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Oct 23, 2018 6:20:43 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Oct 23, 2018 6:20:43 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Oct 23, 2018 6:20:43 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Oct 23, 2018 6:20:43 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Oct 23, 2018 6:20:43 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Oct 23, 2018 6:20:43 PM	No	
20 - Miles			RGASPARD	Oct 23, 2018 6:20:43 PM	No	
30 - Kilometers			RGASPARD	Oct 23, 2018 6:20:43 PM	No	
40 - Hours			RGASPARD	Oct 23, 2018 6:20:43 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51836579
Invoice No. 55345 - 51836579

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Needs 2 front tires		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	139,253 - DH

Activity Header
Activity: 15 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note: Needs 2 front tires
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Oct-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	103.44	206.88

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Oct-18	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	206.88
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**206.88**

Work Order Footer

Work Order 51836579 Total	
Parts:	206.88
Labor:	0.00
Labor Hours:	1.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**206.88**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51766081
Invoice No. 55345 - 51766081

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 139,253 - DH

Chronology		
Reported	Oct 22, 2018 1:36:29 PM	Oct 22, 2018 1:36:29 PM
Started	Oct 23, 2018 12:00:00 AM	
Completed	Oct 23, 2018 12:30:00 AM	Oct 23, 2018 12:30:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE: Service

CORRECTION:Perform pmA Service
Oil filter B329 Qty1
Engine oil 5w20 Qts 7

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Oct-18	Gaspard,Ronald	1.5666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 23-OCT-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
10,100 - Safety Inspection	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	RGASPARD	Oct 23, 2018 12:16:58 AM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	RGASPARD	Oct 23, 2018 12:16:58 AM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	RGASPARD	Oct 23, 2018 12:16:58 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	RGASPARD	Oct 23, 2018 12:16:58 AM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	RGASPARD	Oct 23, 2018 12:16:58 AM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	RGASPARD	Oct 23, 2018 12:16:58 AM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	RGASPARD	Oct 23, 2018 12:16:58 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	RGASPARD	Oct 23, 2018 12:16:58 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
40,420 - Check Hood	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	RGASPARD	Oct 23, 2018 12:16:58 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	RGASPARD	Oct 23, 2018 12:16:58 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	RGASPARD	Oct 23, 2018 12:16:58 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	RGASPARD	Oct 23, 2018 12:16:58 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	RGASPARD	Oct 23, 2018 12:16:58 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
44,150 - FRA Inspect Turbocharger	-	NA	RGASPARD	Oct 23, 2018 12:16:58 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Oct 23, 2018 12:16:58 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
60,631 - Tread Depth RF	7 32nds of an inch		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
60,632 - Tread Depth LF	7 32nds of an inch		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
60,633 - Tread Depth RRO	4 32nds of an inch		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
60,634 - Tread Depth RRI	4 32nds of an inch		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
60,635 - Tread Depth LRI	5 32nds of an inch		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
60,636 - Tread Depth LRO	4 32nds of an inch		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
77,131 - Brake Pad Thickness LF	6 Inch		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
77,132 - Brake Pad Thickness RF	6 Inch		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
77,133 - Brake Pad Thickness LR	8 Inch		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
77,134 - Brake Pad Thickness RR	8 Inch		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
77,137 - Brake Rotor LR	40 Inch		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
77,138 - Brake Rotor RR	40 Inch		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
77,150 - Check King Pins	-	NA	RGASPARD	Oct 23, 2018 12:16:58 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Oct 23, 2018 12:16:58 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51766081
Invoice No. 55345 - 51766081

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 139,253 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Oct-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Oct-18	Gaspard,Ronald	1.1166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 23-OCT-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Oct 23, 2018 12:17:32 AM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Oct 23, 2018 12:17:32 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Oct 23, 2018 12:17:32 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Oct 23, 2018 12:17:32 AM	No	
104,000 - Lubricate Chassis	Done		RGASPARD	Oct 23, 2018 12:17:32 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Oct 23, 2018 12:17:32 AM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		RGASPARD	Oct 23, 2018 12:17:32 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Oct 23, 2018 12:17:32 AM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	1.12
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51766081
Invoice No. 55345 - 51766081

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	139,253 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Oct-18	Gaspard,Ronald	0.2666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 23-OCT-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Oct 23, 2018 12:18:02 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Oct 23, 2018 12:18:02 AM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Oct 23, 2018 12:18:02 AM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Oct 23, 2018 12:18:02 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Oct 23, 2018 12:18:02 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Oct 23, 2018 12:18:02 AM	No	
20 - Miles			RGASPARD	Oct 23, 2018 12:18:02 AM	No	
30 - Kilometers			RGASPARD	Oct 23, 2018 12:18:02 AM	No	
40 - Hours			RGASPARD	Oct 23, 2018 12:18:02 AM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 51766081 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51807065
Invoice No. 55345 - 51807065

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Wheel chair		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	137,494 - DH

Chronology		
Reported	Oct 12, 2018 8:04:10 AM	Oct 12, 2018 8:04:10 AM
Started	Oct 12, 2018 12:00:00 AM	
Completed	Oct 12, 2018 11:54:00 AM	Oct 12, 2018 11:54:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:wheel chair

Cause: wheel chair seat belt latch is broken

Correction:Replaced latch

Part:
1 new latch 28983

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 12-OCT-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Oct 12, 2018 8:31:05 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Oct 12, 2018 8:31:05 AM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Oct 12, 2018 8:31:05 AM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Oct 12, 2018 8:31:05 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Oct 12, 2018 8:31:05 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Oct 12, 2018 8:31:05 AM	No	
20 - Miles			JAPEREZ	Oct 12, 2018 8:31:05 AM	No	
30 - Kilometers			JAPEREZ	Oct 12, 2018 8:31:05 AM	No	
40 - Hours			JAPEREZ	Oct 12, 2018 8:31:05 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51807065
Invoice No. 55345 - 51807065

Client Department:
Department: 55345M
Work Order Description
Wheel chair
Requested By: JAPEREZ
Created By: JAPEREZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 137,494 - DH

Activity Header
Activity: 15 055 HANDLING, CARGO RESTRAINT & LIFT SYSTEM (POWER UNITS, TRAILERS)
Activity Note: Wheel chair
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Oct-18	28983	BUCKLE, SAFETY, W/C, BRAUN	1	21.33	21.33

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Oct-18	Perez,Javier	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	21.33
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**21.33**

Work Order Footer

Work Order 51807065 Total	
Parts:	21.33
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**21.33**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51682519
Invoice No. 55345 - 51682519

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 135,010 - DH

Chronology		
Reported	Sep 28, 2018 11:43:36 AM	Sep 28, 2018 11:43:36 AM
Started	Sep 29, 2018 12:00:00 AM	
Completed	Sep 29, 2018 12:28:00 AM	Sep 29, 2018 12:28:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmB

CAUSE: Service

CORRECTION:Perform pmB Service
Oil filter B329 Qty1
Engine oil 5w20 qty 7 Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Sep-18	Gaspard,Ronald	1.55	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 28-SEP-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	RGASPARD	Sep 28, 2018 11:56:05 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	RGASPARD	Sep 28, 2018 11:56:05 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	RGASPARD	Sep 28, 2018 11:56:05 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	RGASPARD	Sep 28, 2018 11:56:05 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	RGASPARD	Sep 28, 2018 11:56:05 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	RGASPARD	Sep 28, 2018 11:56:05 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	RGASPARD	Sep 28, 2018 11:56:05 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	RGASPARD	Sep 28, 2018 11:56:05 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
40,420 - Check Hood	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	RGASPARD	Sep 28, 2018 11:56:05 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	RGASPARD	Sep 28, 2018 11:56:05 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	RGASPARD	Sep 28, 2018 11:56:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	RGASPARD	Sep 28, 2018 11:56:05 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	RGASPARD	Sep 28, 2018 11:56:05 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	RGASPARD	Sep 28, 2018 11:56:05 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Sep 28, 2018 11:56:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
77,137 - Brake Rotor LR	40 Inch		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
77,138 - Brake Rotor RR	40 Inch		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
77,150 - Check King Pins	-	NA	RGASPARD	Sep 28, 2018 11:56:05 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Sep 28, 2018 11:56:05 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51682519
Invoice No. 55345 - 51682519

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 135,010 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Sep-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Sep-18	Gaspard,Ronald	1.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: RGASPARD Performed on: 28-SEP-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Sep 28, 2018 11:59:37 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Sep 28, 2018 11:59:37 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Sep 28, 2018 11:59:37 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Sep 28, 2018 11:59:37 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Sep 28, 2018 11:59:37 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Sep 28, 2018 11:59:37 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Sep 28, 2018 11:59:37 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Sep 28, 2018 11:59:37 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		RGASPARD	Sep 28, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				11:59:37 PM		
201,000 - Service Crankcase Breather	Done		RGASPARD	Sep 28, 2018 11:59:37 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Sep 28, 2018 11:59:37 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Sep 28, 2018 11:59:37 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Sep 28, 2018 11:59:37 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	1.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51682519
Invoice No. 55345 - 51682519

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM B		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	135,010 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Sep-18	Gaspard,Ronald	0.2666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 29-SEP-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Sep 29, 2018 12:00:05 AM	No	
20 - Miles			RGASPARD	Sep 29, 2018 12:00:05 AM	No	
30 - Kilometers			RGASPARD	Sep 29, 2018 12:00:05 AM	No	
40 - Hours			RGASPARD	Sep 29, 2018 12:00:05 AM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51682519 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.87

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51575820
Invoice No. 55345 - 51575820

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 130,917 - DH

Chronology		
Reported	Aug 31, 2018 11:31:32 AM	Aug 31, 2018 11:31:32 AM
Started	Sep 4, 2018 12:00:00 AM	
Completed	Sep 4, 2018 10:35:00 AM	Sep 4, 2018 10:35:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PM A

CAUSE: Service due

CORRECTION: Performed and completed pmA....
Changed engine oil and replaced engine oil filter
Lube all Pivoting Points

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Sep-18	Delva,Terry	0.5666666	0	0
04-Sep-18	Delva,Terry	1.1833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: TDELVA Performed on: 04-SEP-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
10,100 - Safety Inspection	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,120 - FRA Check All Warning Lights and Alarms	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
10,140 - Check Service Brakes	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
10,160 - FRA Check Instruments and Horns	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
10,170 - Check Fast Idle	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
10,180 - Check Starter Protection Circuit	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
10,190 - Check Reverse Warning System	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
11,100 - Check Parking Brake	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
11,150 - Perform Brake Test	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	TDELVA	Sep 4, 2018 9:09:03 AM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	TDELVA	Sep 4, 2018 9:09:03 AM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	TDELVA	Sep 4, 2018 9:09:03 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	TDELVA	Sep 4, 2018 9:09:03 AM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	TDELVA	Sep 4, 2018 9:09:03 AM	No	
11,170 - FRA Check Door Operation	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
20,210 - Check Condition of Operator's Area	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
20,240 - FRA Check Interior Lights	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,250 - FRA Check Interior Electrical Panels	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
20,260 - Check Stop Request System	-	NA	TDELVA	Sep 4, 2018 9:09:03 AM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	TDELVA	Sep 4, 2018 9:09:03 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
22,110 - Check Emergency Hatches	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
22,120 - Check All Safety Equipment	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
30,310 - Check Passenger Doors	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	TDELVA	Sep 4, 2018 9:09:03 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
30,360 - Check for Physical Damage and Decals	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
30,380 - Check Exterior Compartment Doors	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
33,100 - Check Lights and Reflectors	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
40,420 - Check Hood	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	TDELVA	Sep 4, 2018 9:09:03 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	TDELVA	Sep 4, 2018 9:09:03 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,442 - Freeze Point	Degree Fahrenheit	NA	TDELVA	Sep 4, 2018 9:09:03 AM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	TDELVA	Sep 4, 2018 9:09:03 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	TDELVA	Sep 4, 2018 9:09:03 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	-	NA	TDELVA	Sep 4, 2018 9:09:03 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
44,130 - FRA Check Exhaust System	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
44,140 - FRA Check Intake System	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
44,150 - FRA Inspect Turbocharger	-	NA	TDELVA	Sep 4, 2018 9:09:03 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
44,180 - FRA Check for Leaks	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
44,190 - FRA Perform Battery Inspection	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
50,510 - Check Entire Steering System	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		TDELVA	Sep 4, 2018 9:09:03 AM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		TDELVA	Sep 4, 2018 9:09:03 AM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		TDELVA	Sep 4, 2018 9:09:03 AM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		TDELVA	Sep 4, 2018 9:09:03 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,615 - Air Pressure LRI	65 Pounds per Square Inch		TDELVA	Sep 4, 2018 9:09:03 AM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		TDELVA	Sep 4, 2018 9:09:03 AM	No	
60,620 - Check Valve Stems and Caps	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
60,630 - Check and Record Tread Depth	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
60,631 - Tread Depth RF	10 32nds of an inch		TDELVA	Sep 4, 2018 9:09:03 AM	No	
60,632 - Tread Depth LF	10 32nds of an inch		TDELVA	Sep 4, 2018 9:09:03 AM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		TDELVA	Sep 4, 2018 9:09:03 AM	No	
60,634 - Tread Depth RRI	9 32nds of an inch		TDELVA	Sep 4, 2018 9:09:03 AM	No	
60,635 - Tread Depth LRI	9 32nds of an inch		TDELVA	Sep 4, 2018 9:09:03 AM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		TDELVA	Sep 4, 2018 9:09:03 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
60,650 - Check Sidewall Wear	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
60,660 - Inspect for Cuts and Tears	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
60,670 - Check Dual Mating With Square	-	NA	TDELVA	Sep 4, 2018 9:09:03 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
70,710 - Check Vibration Damper	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
70,730 - FRA Check Starter	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
70,770 - FRA Check Exhaust System	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,790 - Check All Body Mounts and Chassis Frame	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
77,110 - FRA Check Fuel Tank	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
77,120 - Check Suspension Components	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
77,131 - Brake Pad Thickness LF	8 Inch		TDELVA	Sep 4, 2018 9:09:03 AM	No	
77,132 - Brake Pad Thickness RF	8 Inch		TDELVA	Sep 4, 2018 9:09:03 AM	No	
77,133 - Brake Pad Thickness LR	8 Inch		TDELVA	Sep 4, 2018 9:09:03 AM	No	
77,134 - Brake Pad Thickness RR	8 Inch		TDELVA	Sep 4, 2018 9:09:03 AM	No	
77,135 - Brake Rotor LF	39.7 Inch		TDELVA	Sep 4, 2018 9:09:03 AM	No	
77,136 - Brake Rotor RF	39.7 Inch		TDELVA	Sep 4, 2018 9:09:03 AM	No	
77,137 - Brake Rotor LR	37.8 Inch		TDELVA	Sep 4, 2018 9:09:03 AM	No	
77,138 - Brake Rotor RR	37.8 Inch		TDELVA	Sep 4, 2018 9:09:03 AM	No	
77,140 - FRA Check Brake Hoses	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
77,150 - Check King Pins	-	NA	TDELVA	Sep 4, 2018 9:09:03 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
80,810 - Completion of PMI Report	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		TDELVA	Sep 4, 2018 9:09:03 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51575820
Invoice No. 55345 - 51575820

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 130,917 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Sep-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Sep-18	Delva,Terry	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: TDELVA Performed on: 04-SEP-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		TDELVA	Sep 4, 2018 9:02:29 AM	No	
101,000 - FRA Change Oil Filters	Yes		TDELVA	Sep 4, 2018 9:02:29 AM	No	
102,000 - FRA Drain Engine Oil	Yes		TDELVA	Sep 4, 2018 9:02:29 AM	No	
103,000 - FRA Check Transmission Fluid	Done		TDELVA	Sep 4, 2018 9:02:29 AM	No	
104,000 - Lubricate Chassis	Done		TDELVA	Sep 4, 2018 9:02:29 AM	No	
105,000 - Replace or Clean A/C Filters	Done		TDELVA	Sep 4, 2018 9:02:29 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	TDELVA	Sep 4, 2018 9:02:29 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		TDELVA	Sep 4, 2018 9:02:29 AM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	1.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51575820
Invoice No. 55345 - 51575820

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	130,917 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Sep-18	Delva,Terry	0.2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 04-SEP-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Sep 4, 2018 9:02:51 AM	No	
20 - Miles			TDELVA	Sep 4, 2018 9:02:51 AM	No	
30 - Kilometers			TDELVA	Sep 4, 2018 9:02:51 AM	No	
40 - Hours			TDELVA	Sep 4, 2018 9:02:51 AM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51575820 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.95

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51575807
Invoice No. 55345 - 51575807

Client Department:
Department: 55345M
Work Order Description
Needs 2 new tires and front brakes job
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 126,411 - DH

Chronology		
Reported	Aug 7, 2018 12:03:43 AM	Aug 7, 2018 12:03:43 AM
Started		
Completed	Aug 7, 2018 12:24:00 AM	Aug 7, 2018 12:24:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs front brakes job and 2 tires

Cause: wear

Correction:replaced front brake pads and lubed guide pins
2 new tires mounted and balance rotate tires
Brake part number BRSD1328 Qty1
Tires part number 189752 qty 2
Torque wheels 140 lbs second torque wheels 140 lbs

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 07-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Aug 7, 2018 12:08:05 AM	No	
20 - Miles			RGASPARD	Aug 7, 2018 12:08:05 AM	No	
30 - Kilometers			RGASPARD	Aug 7, 2018 12:08:05 AM	No	
40 - Hours			RGASPARD	Aug 7, 2018 12:08:05 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51575807
Invoice No. 55345 - 51575807

Client Department:
Department: 55345M
Work Order Description
Needs 2 new tires and front brakes job
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 126,411 - DH

Activity Header
Activity: 15 013/000/000 BRAKES
Activity Note: Needs 2 new tires and front brakes job
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Aug-18	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	48.87	48.87
07-Aug-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	103.44	206.88

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	255.75
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**255.75**

Work Order Footer

Work Order 51575807 Total	
Parts:	255.75
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**255.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51506289
Invoice No. 55345 - 51506289

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	126,411 - DH

Chronology		
Reported	Aug 6, 2018 11:00:12 AM	Aug 6, 2018 11:00:12 AM
Started	Aug 7, 2018 12:00:00 AM	
Completed	Aug 7, 2018 12:23:00 AM	Aug 7, 2018 12:23:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PmA

CAUSE:Service

CORRECTION:perform PmA Service
Oil filter B329 qty 1
Engine oil 5w20 qty 7 qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Aug-18	Gaspard,Ronald	1.55	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 07-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
10,100 - Safety Inspection	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Aug 7, 2018 12:00:06 AM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Aug 7, 2018 12:00:06 AM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Aug 7, 2018 12:00:06 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Aug 7, 2018 12:00:06 AM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Aug 7, 2018 12:00:06 AM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	na	RGASPARD	Aug 7, 2018 12:00:06 AM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Aug 7, 2018 12:00:06 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
30,320 - Inspect Step-well and Hand Rails	-	na	RGASPARD	Aug 7, 2018 12:00:06 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Aug 7, 2018 12:00:06 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
40,420 - Check Hood	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Aug 7, 2018 12:00:06 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Aug 7, 2018 12:00:06 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Aug 7, 2018 12:00:06 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Aug 7, 2018 12:00:06 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Aug 7, 2018 12:00:06 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Aug 7, 2018 12:00:06 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Aug 7, 2018 12:00:06 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
60,631 - Tread Depth RF	7 32nds of an inch		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
60,632 - Tread Depth LF	8 32nds of an inch		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
60,635 - Tread Depth LRI	3 32nds of an inch		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
60,636 - Tread Depth LRO	3 32nds of an inch		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
77,131 - Brake Pad Thickness LF	3 Inch		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
77,132 - Brake Pad Thickness RF	3 Inch		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
77,133 - Brake Pad Thickness LR	10 Inch		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
77,134 - Brake Pad Thickness RR	10 Inch		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
77,137 - Brake Rotor LR	40 Inch		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
77,138 - Brake Rotor RR	40 Inch		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
77,150 - Check King Pins	-	na	RGASPARD	Aug 7, 2018 12:00:06 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Aug 7, 2018 12:00:06 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51506289
Invoice No. 55345 - 51506289

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	126,411 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Aug-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Aug-18	Gaspard,Ronald	1.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 07-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Aug 7, 2018 12:00:49 AM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Aug 7, 2018 12:00:49 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Aug 7, 2018 12:00:49 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Aug 7, 2018 12:00:49 AM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Aug 7, 2018 12:00:49 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Aug 7, 2018 12:00:49 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Aug 7, 2018 12:00:49 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Aug 7, 2018 12:00:49 AM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	1.05
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51506289
Invoice No. 55345 - 51506289

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	126,411 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Aug-18	Gaspard,Ronald	0.25	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 07-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Aug 7, 2018 12:01:08 AM	No	
20 - Miles			RGASPARD	Aug 7, 2018 12:01:08 AM	No	
30 - Kilometers			RGASPARD	Aug 7, 2018 12:01:08 AM	No	
40 - Hours			RGASPARD	Aug 7, 2018 12:01:08 AM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51506289 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.85

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51411404
Invoice No. 55345 - 51411404

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM C		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	122,054 - DH

Chronology

Reported	Jul 12, 2018 11:49:05 AM	Jul 12, 2018 11:49:05 AM
Started	Jul 12, 2018 12:00:00 AM	
Completed	Jul 13, 2018 8:57:00 AM	Jul 13, 2018 8:57:00 AM
Down Time		

Work Order Notes

Line 10 PMC
Service
Perform pmc Service
Oil filter B329 qty1
Engine oil 5w20 qty 7 Qts
Transmission filter 20021 qty1
Transmission fluid 10 Qts
Gear oil 80w90 qty 5 Qts
Replaced AC filter
Air filter PA4075 qty1

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Jul-18	Gaspard,Ronald	1.5833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 12-JUL-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
10,110 - FRA Check Drivers Pre-trip or	Done		RGASPARD	Jul 12, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
DVIR/EVIR & Authorization Forms				11:09:28 PM		
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Jul 12, 2018 11:09:28 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Jul 12, 2018 11:09:28 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Jul 12, 2018 11:09:28 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Jul 12, 2018 11:09:28 PM	No	
11,162 - FRA Check/Record Water Temperature	0 Degree Fahrenheit	na	RGASPARD	Jul 12, 2018 11:09:28 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Jul 12, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:09:28 PM		
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Jul 12, 2018 11:09:28 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Jul 12, 2018 11:09:28 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Jul 12, 2018 11:09:28 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
40,420 - Check Hood	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Jul 12, 2018 11:09:28 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate	No	na	RGASPARD	Jul 12, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
with a Yes or No)				11:09:28 PM		
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Jul 12, 2018 11:09:28 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Jul 12, 2018 11:09:28 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Jul 12, 2018 11:09:28 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Jul 12, 2018 11:09:28 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
60,614 - Air Pressure RRI	65 Pounds per		RGASPARD	Jul 12, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			11:09:28 PM		
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
60,631 - Tread Depth RF	7 32nds of an inch		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
60,635 - Tread Depth LRI	5 32nds of an inch		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
60,636 - Tread Depth LRO	4 32nds of an inch		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
70,780 - Check Driveline, U-joint and Slip	Done		RGASPARD	Jul 12, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Yokes				11:09:28 PM		
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
77,131 - Brake Pad Thickness LF	6 Inch		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
77,132 - Brake Pad Thickness RF	6 Inch		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
77,133 - Brake Pad Thickness LR	11 Inch		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
77,134 - Brake Pad Thickness RR	11 Inch		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
77,137 - Brake Rotor LR	40 Inch		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
77,138 - Brake Rotor RR	40 Inch		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Jul 12, 2018 11:09:28 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Jul 12, 2018 11:09:28 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51411404
Invoice No. 55345 - 51411404

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 122,054 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Jul-18	20021	FILTER, TRANSMISSION 20021	1	17.26	17.26
12-Jul-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Jul-18	Gaspard,Ronald	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: RGASPARD Performed on: 12-JUL-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jul 12, 2018 11:10:55 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jul 12, 2018 11:10:55 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jul 12, 2018 11:10:55 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jul 12, 2018 11:10:55 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Jul 12, 2018 11:10:55 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jul 12, 2018 11:10:55 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	na	RGASPARD	Jul 12, 2018 11:10:55 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jul 12, 2018 11:10:55 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Jul 12, 2018 11:10:55 PM	No	
201,000 - Service Crankcase Breather	Done		RGASPARD	Jul 12, 2018 11:10:55 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		RGASPARD	Jul 12, 2018 11:10:55 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Jul 12, 2018 11:10:55 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Jul 12, 2018 11:10:55 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		RGASPARD	Jul 12, 2018 11:10:55 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		RGASPARD	Jul 12, 2018 11:10:55 PM	No	
302,000 - Check Toe-In and Record Reading	-	na	RGASPARD	Jul 12, 2018 11:10:55 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	na	RGASPARD	Jul 12, 2018 11:10:55 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		RGASPARD	Jul 12, 2018 11:10:55 PM	No	
305,000 - FRA Change Differential Fluid	Yes		RGASPARD	Jul 12, 2018 11:10:55 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	19.22
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**19.22**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51411404
Invoice No. 55345 - 51411404

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM C		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	122,054 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Jul-18	Gaspard,Ronald	0.2666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 12-JUL-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jul 12, 2018 11:11:27 PM	No	
20 - Miles			RGASPARD	Jul 12, 2018 11:11:27 PM	No	
30 - Kilometers			RGASPARD	Jul 12, 2018 11:11:27 PM	No	
40 - Hours			RGASPARD	Jul 12, 2018 11:11:27 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51411404 Total	
Parts:	19.22
Labor:	0.00
Labor Hours:	4.35

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**19.22**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51441945
Invoice No. 55345 - 51441945

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Outer barrier shocks are bad		Ford E450 Champion Challenger	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	118,778 - DH

Chronology		
Reported	Jun 19, 2018 10:52:57 AM	Jun 19, 2018 10:52:57 AM
Started	Jun 19, 2018 12:00:00 AM	
Completed	Jun 19, 2018 11:37:23 AM	Jun 19, 2018 11:37:23 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:
Outer barrier shocks are bad

Cause:
the lift only works intermittently

Correction:
Replace the right side outer barrier shock

Line 20 .

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 19-JUN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Jun 19, 2018 11:09:16 AM	No	
20 - Miles			EDTORRES	Jun 19, 2018 11:09:16 AM	No	
30 - Kilometers			EDTORRES	Jun 19, 2018 11:09:16 AM	No	
40 - Hours			EDTORRES	Jun 19, 2018 11:09:16 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51441945
Invoice No. 55345 - 51441945

Client Department:
Department: 55345M
Work Order Description
Outer barrier shocks are bad
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 118,778 - DH

Activity Header
Activity: 15 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: Outer barrier shocks are bad
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Jun-18	Torres,Edwin	0.7833333	0	0
19-Jun-18	Torres,Edwin	0.7166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51441945 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51411389
Invoice No. 55345 - 51411389

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Needs rear brakes job		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	117,958 - DH

Chronology		
Reported	Jun 8, 2018 7:29:34 PM	Jun 8, 2018 7:29:34 PM
Started	Jun 8, 2018 12:00:00 AM	
Completed	Jun 8, 2018 7:41:00 PM	Jun 8, 2018 7:41:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs rear brakes job

Cause: wear

Correction:Replaced rear brake pads and lube guide pins
Torque wheels 140 lbs second torque 140 lbs
Part number BRSD1330 qty1

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Jun-18	Gaspard,Ronald	0.1333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 08-JUN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jun 8, 2018 7:31:29 PM	No	
20 - Miles			RGASPARD	Jun 8, 2018 7:31:29 PM	No	
30 - Kilometers			RGASPARD	Jun 8, 2018 7:31:29 PM	No	
40 - Hours			RGASPARD	Jun 8, 2018 7:31:29 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51333873
Invoice No. 55345 - 51333873

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	117,958 - DH

Chronology		
Reported	Jun 7, 2018 11:57:31 AM	Jun 7, 2018 11:57:31 AM
Started	Jun 8, 2018 12:00:00 AM	
Completed	Jun 8, 2018 7:41:00 PM	Jun 8, 2018 7:41:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:Service

CORRECTION:Perform pmA Service
Oil filter B329 qty1
Engine oil 5w20 qty 7 Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Jun-18	Gaspard,Ronald	1.5333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 08-JUN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Jun 8, 2018 7:24:25 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Jun 8, 2018 7:24:25 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Jun 8, 2018 7:24:25 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Jun 8, 2018 7:24:25 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Jun 8, 2018 7:24:25 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	na	RGASPARD	Jun 8, 2018 7:24:25 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Jun 8, 2018 7:24:25 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Jun 8, 2018 7:24:25 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
40,420 - Check Hood	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Jun 8, 2018 7:24:25 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Jun 8, 2018 7:24:25 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Jun 8, 2018 7:24:25 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Jun 8, 2018 7:24:25 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Jun 8, 2018 7:24:25 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Jun 8, 2018 7:24:25 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Jun 8, 2018 7:24:25 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
77,133 - Brake Pad Thickness LR	4 Inch		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
77,134 - Brake Pad Thickness RR	4 Inch		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
77,137 - Brake Rotor LR	40 Inch		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
77,138 - Brake Rotor RR	40 Inch		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Jun 8, 2018 7:24:25 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Jun 8, 2018 7:24:25 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51411389
Invoice No. 55345 - 51411389

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Needs rear brakes job		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	117,958 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Jun-18	BRSD-1330	PADS, BRAKE, DISC, REAR, FORD SAME AS PFH133020	1	43.06	43.06

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Jun-18	Gaspard,Ronald	1.7666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	43.06
Labor:	0.00
Labor Hours:	1.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.06**

Work Order Footer

Work Order 51411389 Total	
Parts:	43.06
Labor:	0.00
Labor Hours:	1.90
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.06**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51333873
Invoice No. 55345 - 51333873

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 117,958 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Jun-18	B329	FILTER, OIL, SPIN-ON SEE P550965	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Jun-18	Gaspard,Ronald	1.0333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 08-JUN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jun 8, 2018 7:25:09 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jun 8, 2018 7:25:09 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jun 8, 2018 7:25:09 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jun 8, 2018 7:25:09 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Jun 8, 2018 7:25:09 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jun 8, 2018 7:25:09 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Jun 8, 2018 7:25:09 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jun 8, 2018 7:25:09 PM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	1.96
	Labor:	0.00
	Labor Hours:	1.03
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51333873
Invoice No. 55345 - 51333873

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	117,958 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Jun-18	Gaspard,Ronald	0.25	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 08-JUN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jun 8, 2018 7:25:40 PM	No	
20 - Miles			RGASPARD	Jun 8, 2018 7:25:40 PM	No	
30 - Kilometers			RGASPARD	Jun 8, 2018 7:25:40 PM	No	
40 - Hours			RGASPARD	Jun 8, 2018 7:25:40 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51333873 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.82

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51369877
Invoice No. 55345 - 51369877

Client Department:
Department: 55345M
Work Order Description
Driver step is broken. Passenger side liding window is broken.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 116,394 - DH

Chronology		
Reported	May 24, 2018 7:31:51 AM	May 24, 2018 7:31:51 AM
Started	May 24, 2018 12:00:00 AM	
Completed	May 29, 2018 8:56:00 AM	May 29, 2018 8:56:00 AM
Down Time		

Work Order Notes

Line 10 Driver step is broken. Passenger side liding window is broken

Repaired driver side step, one of the bolts for the rear step bracket snapped through the metal that it was holding onto.

Replaced the back window on the passenger side because the sliding window was broken. The cause of the broken window is unknown. Hard drive was pulled by David K. And he took it to PTC for reviewing.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 24-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	May 24, 2018 7:37:28 AM	No	
20 - Miles			EDTORRES	May 24, 2018 7:37:28 AM	No	
30 - Kilometers			EDTORRES	May 24, 2018 7:37:28 AM	No	
40 - Hours			EDTORRES	May 24, 2018 7:37:28 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51369877
Invoice No. 55345 - 51369877

Client Department:
Department: 55345M
Work Order Description
Driver step is broken. Passenger side liding window is broken.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 116,394 - DH

Activity Header
Activity:20 174/000/000 BODY, BUS
Activity Note: Driver step is broken. Passenger side liding window is broken
Reason for Repair: 41 Abuse of Equipment
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-May-18	Torres,Edwin	3.2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51369877 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51204840
Invoice No. 55345 - 51204840

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	113,919 - DH

Chronology		
Reported	May 8, 2018 11:14:44 AM	May 8, 2018 11:14:44 AM
Started	May 8, 2018 12:00:00 AM	
Completed	May 9, 2018 12:22:00 AM	May 9, 2018 12:22:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:Service

CORRECTION:Perform pmA Service
Oil filter B329 qty1
Engine oil 5w20 qty 7 Qts
Rotate tires washed rims
Torque wheels 140 lbs second torque 140 lbs

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-May-18	Gaspard,Ronald	1.8333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 08-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	RGASPARD	May 8, 2018 11:48:23 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	RGASPARD	May 8, 2018 11:48:23 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	RGASPARD	May 8, 2018 11:48:23 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	RGASPARD	May 8, 2018 11:48:23 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	RGASPARD	May 8, 2018 11:48:23 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
20,260 - Check Stop Request System	-	NA	RGASPARD	May 8, 2018 11:48:23 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	RGASPARD	May 8, 2018 11:48:23 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	RGASPARD	May 8, 2018 11:48:23 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
40,420 - Check Hood	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	RGASPARD	May 8, 2018 11:48:23 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	RGASPARD	May 8, 2018 11:48:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,442 - Freeze Point	Degree Fahrenheit	NA	RGASPARD	May 8, 2018 11:48:23 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	RGASPARD	May 8, 2018 11:48:23 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	RGASPARD	May 8, 2018 11:48:23 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	RGASPARD	May 8, 2018 11:48:23 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	May 8, 2018 11:48:23 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	May 8, 2018 11:48:23 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	May 8, 2018 11:48:23 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	May 8, 2018 11:48:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	May 8, 2018 11:48:23 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	May 8, 2018 11:48:23 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
60,631 - Tread Depth RF	5 32nds of an inch		RGASPARD	May 8, 2018 11:48:23 PM	No	
60,632 - Tread Depth LF	6 32nds of an inch		RGASPARD	May 8, 2018 11:48:23 PM	No	
60,633 - Tread Depth RRO	11 32nds of an inch		RGASPARD	May 8, 2018 11:48:23 PM	No	
60,634 - Tread Depth RRI	11 32nds of an inch		RGASPARD	May 8, 2018 11:48:23 PM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		RGASPARD	May 8, 2018 11:48:23 PM	No	
60,636 - Tread Depth LRO	11 32nds of an inch		RGASPARD	May 8, 2018 11:48:23 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		RGASPARD	May 8, 2018 11:48:23 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		RGASPARD	May 8, 2018 11:48:23 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		RGASPARD	May 8, 2018 11:48:23 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		RGASPARD	May 8, 2018 11:48:23 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	May 8, 2018 11:48:23 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	May 8, 2018 11:48:23 PM	No	
77,137 - Brake Rotor LR	40 Inch		RGASPARD	May 8, 2018 11:48:23 PM	No	
77,138 - Brake Rotor RR	40 Inch		RGASPARD	May 8, 2018 11:48:23 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
77,150 - Check King Pins	-	NA	RGASPARD	May 8, 2018 11:48:23 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	May 8, 2018 11:48:23 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51204840
Invoice No. 55345 - 51204840

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 113,919 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-May-18	F75Z-6730-BA	PLUG, DRAIN, OIL, ENGINE, 3.0L	1	6.66	6.66
08-May-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-May-18	Gaspard,Ronald	1.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 08-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	May 8, 2018 11:49:10 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	May 8, 2018 11:49:10 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	May 8, 2018 11:49:10 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	May 8, 2018 11:49:10 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	May 8, 2018 11:49:10 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	May 8, 2018 11:49:10 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	May 8, 2018 11:49:10 PM	No	
108,000 - Lube all pivoting	Done		RGASPARD	May 8, 2018 11:49:10	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Mechanisms				PM		

Activity Sub Total

Activity 20 Sub Total	
Parts:	8.62
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.62**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51204840
Invoice No. 55345 - 51204840

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	113,919 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-May-18	Gaspard,Ronald	0.2666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 08-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	May 8, 2018 11:49:33 PM	No	
20 - Miles			RGASPARD	May 8, 2018 11:49:33 PM	No	
30 - Kilometers			RGASPARD	May 8, 2018 11:49:33 PM	No	
40 - Hours			RGASPARD	May 8, 2018 11:49:33 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51204840 Total	
Parts:	8.62
Labor:	0.00
Labor Hours:	3.18

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**8.62**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51333843
Invoice No. 55345 - 51333843

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Needs 2 front shoks		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	113,919 - DH

Chronology		
Reported	May 8, 2018 11:57:41 PM	May 8, 2018 11:57:41 PM
Started	May 9, 2018 12:00:00 AM	
Completed	May 9, 2018 12:21:00 AM	May 9, 2018 12:21:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs front shocks

Cause: wear

Correction:replaced front shocks and bushings
Part number ASH-1154 qty2
Part number bushings AD 1034 qty2

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-May-18	Gaspard,Ronald	0.1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 08-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	May 8, 2018 11:59:10 PM	No	
20 - Miles			RGASPARD	May 8, 2018 11:59:10 PM	No	
30 - Kilometers			RGASPARD	May 8, 2018 11:59:10 PM	No	
40 - Hours			RGASPARD	May 8, 2018 11:59:10 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51333843
Invoice No. 55345 - 51333843

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Needs 2 front shoks		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	113,919 - DH

Activity Header
Activity: 15 016/000/000 SUSPENSION
Activity Note: REPLACE FRONNT SHOCKS
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-May-18	AD1034	BUSHING, ABSORBER, SHOCK, UPPER, FRONT, ECONOLINE SAME AS 6C3Z-18197-AA	2	3.65	7.3
09-May-18	ASH1154	ABSORBER, SHOCK, FRONT, E450 SAME AS 8C2Z-18124-D	2	34.68	69.36

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-May-18	Gaspard,Ronald	1.5666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	76.66
Labor:	0.00
Labor Hours:	1.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**76.66**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51333843
Invoice No. 55345 - 51333843

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Needs 2 front shoks		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	113,919 - DH

Activity Header
Activity: 25 016/000/000 SUSPENSION
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51333843 Total	
Parts:	76.66
Labor:	0.00
Labor Hours:	1.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**76.66**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51202312
Invoice No. 55345 - 51202312

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Wiper and Wiper Motor Clip		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	109,587 - DH

Chronology		
Reported	Apr 9, 2018 12:28:11 PM	Apr 9, 2018 12:28:11 PM
Started		
Completed	Apr 9, 2018 10:42:00 PM	Apr 9, 2018 10:42:00 PM
Down Time		

Work Order Notes

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 09-APR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Apr 9, 2018 10:41:20 PM	No	
20 - Miles			CKARLENS	Apr 9, 2018 10:41:20 PM	No	
30 - Kilometers			CKARLENS	Apr 9, 2018 10:41:20 PM	No	
40 - Hours			CKARLENS	Apr 9, 2018 10:41:20 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51202312
Invoice No. 55345 - 51202312

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Wiper and Wiper Motor Clip		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	109,587 - DH

Activity Header
Activity: 20 050 GROUP, ACCESSORIES
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Apr-18	40520	BLADE, WIPER, WINDSHIELD, 20"	2	4.17	8.34

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	8.34
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.34**

Work Order Footer

Work Order 51202312 Total	
Parts:	8.34
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.34**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51091516
Invoice No. 55345 - 51091516

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM B		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	109,587 - DH

Chronology		
Reported	Apr 9, 2018 11:39:41 AM	Apr 9, 2018 11:39:41 AM
Started	Apr 9, 2018 12:00:00 AM	
Completed	Apr 9, 2018 10:41:00 PM	Apr 9, 2018 10:41:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PM-B

CAUSE: Preventive Maintenance

CORRECTION: Tech Performed PM-B

Parts used
Oil filter Qty:1 part#B329
Oil Qty:6qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Apr-18	KARLENS,Cyrius	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: CKARLENS Performed on: 09-APR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
10,100 - Safety Inspection	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,120 - FRA Check All Warning Lights and Alarms	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
10,140 - Check Service Brakes	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
10,160 - FRA Check Instruments and Horns	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
10,170 - Check Fast Idle	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
10,180 - Check Starter Protection Circuit	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
10,190 - Check Reverse Warning System	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
11,100 - Check Parking Brake	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
11,150 - Perform Brake Test	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	CKARLENS	Apr 9, 2018 10:15:01 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	CKARLENS	Apr 9, 2018 10:15:01 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	CKARLENS	Apr 9, 2018 10:15:01 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	CKARLENS	Apr 9, 2018 10:15:01 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	CKARLENS	Apr 9, 2018 10:15:01 PM	No	
11,170 - FRA Check Door Operation	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
20,210 - Check Condition of Operator's Area	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
20,240 - FRA Check Interior Lights	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,250 - FRA Check Interior Electrical Panels	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
20,260 - Check Stop Request System	-	NA	CKARLENS	Apr 9, 2018 10:15:01 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	CKARLENS	Apr 9, 2018 10:15:01 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
22,110 - Check Emergency Hatches	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
22,120 - Check All Safety Equipment	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
30,310 - Check Passenger Doors	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	CKARLENS	Apr 9, 2018 10:15:01 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
30,360 - Check for Physical Damage and Decals	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
30,380 - Check Exterior Compartment Doors	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
33,100 - Check Lights and Reflectors	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
40,420 - Check Hood	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	CKARLENS	Apr 9, 2018 10:15:01 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		CKARLENS	Apr 9, 2018 10:15:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,442 - Freeze Point	0 Degree Fahrenheit	NA	CKARLENS	Apr 9, 2018 10:15:01 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	CKARLENS	Apr 9, 2018 10:15:01 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	CKARLENS	Apr 9, 2018 10:15:01 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
44,130 - FRA Check Exhaust System	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
44,140 - FRA Check Intake System	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	CKARLENS	Apr 9, 2018 10:15:01 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
44,180 - FRA Check for Leaks	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
44,190 - FRA Perform Battery Inspection	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
50,510 - Check Entire Steering System	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		CKARLENS	Apr 9, 2018 10:15:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,615 - Air Pressure LRI	70 Pounds per Square Inch		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
60,620 - Check Valve Stems and Caps	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
60,630 - Check and Record Tread Depth	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
60,633 - Tread Depth RRO	13 32nds of an inch		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
60,634 - Tread Depth RRI	13 32nds of an inch		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
60,635 - Tread Depth LRI	13 32nds of an inch		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
60,636 - Tread Depth LRO	13 32nds of an inch		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
60,650 - Check Sidewall Wear	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
60,660 - Inspect for Cuts and Tears	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
60,670 - Check Dual Mating With Square	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
70,710 - Check Vibration Damper	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
70,730 - FRA Check Starter	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
70,770 - FRA Check Exhaust System	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,790 - Check All Body Mounts and Chassis Frame	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
77,110 - FRA Check Fuel Tank	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
77,120 - Check Suspension Components	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
77,135 - Brake Rotor LF	39.8 Inch		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
77,136 - Brake Rotor RF	39.8 Inch		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
77,137 - Brake Rotor LR	41.8 Inch		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
77,138 - Brake Rotor RR	41.8 Inch		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
77,140 - FRA Check Brake Hoses	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
77,150 - Check King Pins	-	NA	CKARLENS	Apr 9, 2018 10:15:01 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
80,810 - Completion of PMI Report	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		CKARLENS	Apr 9, 2018 10:15:01 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51091516
Invoice No. 55345 - 51091516

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 109,587 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Apr-18	F757-6730-BA	PLUG, DRAIN, OIL, ENGINE	1	6.66	6.66
09-Apr-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Apr-18	KARLENS,Cyrius	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: CKARLENS Performed on: 09-APR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		CKARLENS	Apr 9, 2018 10:05:18 PM	No	
101,000 - FRA Change Oil Filters	Yes		CKARLENS	Apr 9, 2018 10:05:18 PM	No	
102,000 - FRA Drain Engine Oil	Yes		CKARLENS	Apr 9, 2018 10:05:18 PM	No	
103,000 - FRA Check Transmission Fluid	Done		CKARLENS	Apr 9, 2018 10:05:18 PM	No	
104,000 - Lubricate Chassis	Done		CKARLENS	Apr 9, 2018 10:05:18 PM	No	
105,000 - Replace or Clean A/C Filters	Done		CKARLENS	Apr 9, 2018 10:05:18 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	CKARLENS	Apr 9, 2018 10:05:18 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		CKARLENS	Apr 9, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:05:18 PM		
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		CKARLENS	Apr 9, 2018 10:05:18 PM	No	
201,000 - Service Crankcase Breather	Done		CKARLENS	Apr 9, 2018 10:05:18 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		CKARLENS	Apr 9, 2018 10:05:18 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	Yes		CKARLENS	Apr 9, 2018 10:05:18 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		CKARLENS	Apr 9, 2018 10:05:18 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	8.62
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.62**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51091516
Invoice No. 55345 - 51091516

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM B		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	109,587 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Apr-18	KARLENS,Cyrius	0.3166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 09-APR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Apr 9, 2018 10:04:39 PM	No	
20 - Miles			CKARLENS	Apr 9, 2018 10:04:39 PM	No	
30 - Kilometers			CKARLENS	Apr 9, 2018 10:04:39 PM	No	
40 - Hours			CKARLENS	Apr 9, 2018 10:04:39 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51091516 Total	
Parts:	8.62
Labor:	0.00
Labor Hours:	4.32

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**8.62**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51198760
Invoice No. 55345 - 51198760

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
L/R inner tire Flet		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	109,357 - DH

Chronology		
Reported	Apr 8, 2018 6:31:06 PM	Apr 8, 2018 6:31:06 PM
Started	Apr 8, 2018 12:00:00 AM	
Completed	Apr 8, 2018 6:39:00 PM	Apr 8, 2018 6:39:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: L/R inner Flat

Cause: Large metal in tire

Correction: mount & Balance .Tire& Replace on L/R inner.
Parts# 189752 Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Apr-18	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 08-APR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 8, 2018 6:33:08 PM	No	
20 - Miles			DARTHURS	Apr 8, 2018 6:33:08 PM	No	
30 - Kilometers			DARTHURS	Apr 8, 2018 6:33:08 PM	No	
40 - Hours			DARTHURS	Apr 8, 2018 6:33:08 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51198760
Invoice No. 55345 - 51198760

Client Department:
Department: 55345M
Work Order Description
L/R inner tire Flet
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 109,357 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Replace L/R inner Tire
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Apr-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	1	103.44	103.44

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Apr-18	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	103.44
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**103.44**

Work Order Footer

Work Order 51198760 Total	
Parts:	103.44
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**103.44**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51089965
Invoice No. 55345 - 51089965

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Rear tires near min. specs.		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	105,193 - DH

Chronology		
Reported	Mar 11, 2018 6:09:42 AM	Mar 11, 2018 6:09:42 AM
Started	Mar 11, 2018 12:00:00 AM	
Completed	Mar 12, 2018 11:45:00 AM	Mar 12, 2018 11:45:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear tires near min. specs.

Cause: normal wear

Correction:removed and replaced rear tires(4) torque and retorque (140 f/p). Road test, all okay at this time.

Part: 4 tires # 189752.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 11-MAR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Mar 11, 2018 12:20:42 PM	No	
20 - Miles			RAURODRIGUEZ	Mar 11, 2018 12:20:42 PM	No	
30 - Kilometers			RAURODRIGUEZ	Mar 11, 2018 12:20:42 PM	No	
40 - Hours			RAURODRIGUEZ	Mar 11, 2018 12:20:42 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51089965
Invoice No. 55345 - 51089965

Client Department:
Department: 55345M
Work Order Description
Rear tires near min. specs.
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 105,193 - DH

Activity Header
Activity: 15 017 TIRES, TUBES, LINERS & VALVES
Activity Note: Rear tires near min. specs.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Mar-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	4	103.44	413.76

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Mar-18	Rodriguez,Raul	1.45	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	413.76
Labor:	0.00
Labor Hours:	1.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**413.76**

Work Order Footer

Work Order 51089965 Total	
Parts:	413.76
Labor:	0.00
Labor Hours:	1.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**413.76**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51027484
Invoice No. 55345 - 51027484

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	105,433 - DH

Chronology		
Reported	Mar 9, 2018 12:04:48 PM	Mar 9, 2018 12:04:48 PM
Started	Mar 12, 2018 12:00:00 AM	
Completed	Mar 12, 2018 11:44:00 AM	Mar 12, 2018 11:44:00 AM
Down Time		

Work Order Notes

Line 10 PM A

CAUSE:
PM

CORRECTION:
Perform pmA service, lube front end, tire rotation, torque and re torque tires (140 f/p), R&R engine oil and filter, road test, all okay at this time.

Parts. Engine oil filter part # B329 qty 1
engine oil. 5W20 Qty 6 qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Mar-18	Rodriguez,Raul	1.7166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RAURODRIGUEZ Performed on: 12-MAR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
10,100 - Safety Inspection	Done		RAURODRIGUEZ	Mar 12, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:44:35 AM		
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
10,140 - Check Service Brakes	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
10,160 - FRA Check Instruments and Horns	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
10,170 - Check Fast Idle	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
10,180 - Check Starter Protection Circuit	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
10,190 - Check Reverse Warning System	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
11,100 - Check Parking Brake	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
11,150 - Perform Brake Test	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
11,170 - FRA Check Door Operation	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
20,210 - Check Condition of Operator's Area	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		RAURODRIGUEZ	Mar 12, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:44:35 AM		
20,240 - FRA Check Interior Lights	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
20,260 - Check Stop Request System	-	na	RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
22,110 - Check Emergency Hatches	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
22,120 - Check All Safety Equipment	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
30,310 - Check Passenger Doors	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
30,360 - Check for Physical Damage and Decals	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
30,380 - Check Exterior Compartment Doors	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
33,100 - Check Lights and Reflectors	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
40,420 - Check Hood	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
40,440 - Test Coolant System Using Test	-	na	RAURODRIGUEZ	Mar 12, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Strips and Record Results				11:44:35 AM		
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
44,130 - FRA Check Exhaust System	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
44,140 - FRA Check Intake System	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
44,150 - FRA Inspect Turbocharger	-	na	RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
44,180 - FRA Check for Leaks	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
44,190 - FRA Perform Battery Inspection	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
50,510 - Check Entire Steering System	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
60,613 - Air Pressure RRO	65 Pounds per		RAURODRIGUEZ	Mar 12, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			11:44:35 AM		
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
60,620 - Check Valve Stems and Caps	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
60,630 - Check and Record Tread Depth	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
60,631 - Tread Depth RF	10 32nds of an inch		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
60,632 - Tread Depth LF	10 32nds of an inch		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
60,633 - Tread Depth RRO	4 32nds of an inch		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
60,634 - Tread Depth RRI	3 32nds of an inch		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
60,635 - Tread Depth LRI	4 32nds of an inch		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
60,636 - Tread Depth LRO	4 32nds of an inch		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
60,650 - Check Sidewall Wear	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
60,660 - Inspect for Cuts and Tears	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
60,670 - Check Dual Mating With Square	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
70,710 - Check Vibration Damper	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
70,730 - FRA Check Starter	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
70,770 - FRA Check Exhaust System	Done		RAURODRIGUEZ	Mar 12, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:44:35 AM		
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
77,110 - FRA Check Fuel Tank	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
77,120 - Check Suspension Components	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
77,131 - Brake Pad Thickness LF	Inch	9mm	RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
77,132 - Brake Pad Thickness RF	Inch	9mm	RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
77,133 - Brake Pad Thickness LR	Inch	8mm	RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
77,134 - Brake Pad Thickness RR	Inch	8mm	RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
77,135 - Brake Rotor LF	Inch	39.6mm	RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
77,136 - Brake Rotor RF	Inch	39.6mm	RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
77,137 - Brake Rotor LR	Inch	35.7mm	RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
77,138 - Brake Rotor RR	Inch	35.7mm	RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
77,140 - FRA Check Brake Hoses	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
77,150 - Check King Pins	-	na	RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
80,810 - Completion of PMI Report	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		RAURODRIGUEZ	Mar 12, 2018 11:44:35 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51027484
Invoice No. 55345 - 51027484

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 105,433 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Mar-18	B329	FILTER, OIL, SPIN-ON SEE P550965	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Mar-18	Rodriguez,Raul	0.65	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RAURODRIGUEZ Performed on: 12-MAR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RAURODRIGUEZ	Mar 12, 2018 11:37:19 AM	No	
101,000 - FRA Change Oil Filters	Yes		RAURODRIGUEZ	Mar 12, 2018 11:37:19 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RAURODRIGUEZ	Mar 12, 2018 11:37:19 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RAURODRIGUEZ	Mar 12, 2018 11:37:19 AM	No	
104,000 - Lubricate Chassis	Done		RAURODRIGUEZ	Mar 12, 2018 11:37:19 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RAURODRIGUEZ	Mar 12, 2018 11:37:19 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RAURODRIGUEZ	Mar 12, 2018 11:37:19 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RAURODRIGUEZ	Mar 12, 2018 11:37:19 AM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	1.96
	Labor:	0.00
	Labor Hours:	0.65
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51027484
Invoice No. 55345 - 51027484

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	105,433 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 12-MAR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Mar 12, 2018 11:36:29 AM	No	
20 - Miles			RAURODRIGUEZ	Mar 12, 2018 11:36:29 AM	No	
30 - Kilometers			RAURODRIGUEZ	Mar 12, 2018 11:36:29 AM	No	
40 - Hours			RAURODRIGUEZ	Mar 12, 2018 11:36:29 AM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51027484 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.37
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 50961757
Invoice No. 55345 - 50961757

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	101,063 - DH

Chronology		
Reported	Feb 6, 2018 10:15:38 AM	Feb 6, 2018 10:15:38 AM
Started	Feb 6, 2018 12:00:00 AM	
Completed	Feb 6, 2018 11:52:00 PM	Feb 6, 2018 11:52:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:Service

CORRECTION:perform pmA Service
Oil filter B329 qty 1
Engine oil 5w20 qty 7 Qts
Rotate tires cleaned rims
Torque wheels 140 lbs second torque 140 lbs

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Feb-18	Gaspard,Ronald	1.5333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 06-FEB-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Feb 6, 2018 11:24:36 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Feb 6, 2018 11:24:36 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Feb 6, 2018 11:24:36 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Feb 6, 2018 11:24:36 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Feb 6, 2018 11:24:36 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Feb 6, 2018 11:24:36 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Feb 6, 2018 11:24:36 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Feb 6, 2018 11:24:36 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
40,420 - Check Hood	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Feb 6, 2018 11:24:36 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Feb 6, 2018 11:24:36 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Feb 6, 2018 11:24:36 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Feb 6, 2018 11:24:36 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Feb 6, 2018 11:24:36 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Feb 6, 2018 11:24:36 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Feb 6, 2018 11:24:36 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
60,631 - Tread Depth RF	9 32nds of an inch		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
60,634 - Tread Depth RRI	5 32nds of an inch		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
77,131 - Brake Pad Thickness LF	12 Inch		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
77,132 - Brake Pad Thickness RF	12 Inch		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
77,137 - Brake Rotor LR	40 Inch		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
77,138 - Brake Rotor RR	40 Inch		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Feb 6, 2018 11:24:36 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Feb 6, 2018 11:24:36 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 50961757
Invoice No. 55345 - 50961757

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	101,063 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Feb-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Feb-18	Gaspard,Ronald	1.25	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 06-FEB-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Feb 6, 2018 11:25:26 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Feb 6, 2018 11:25:26 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Feb 6, 2018 11:25:26 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Feb 6, 2018 11:25:26 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Feb 6, 2018 11:25:26 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Feb 6, 2018 11:25:26 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Feb 6, 2018 11:25:26 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Feb 6, 2018 11:25:26 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	1.25
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 50961757
Invoice No. 55345 - 50961757

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	101,063 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Feb-18	Gaspard,Ronald	0.2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 06-FEB-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Feb 6, 2018 11:25:51 PM	No	
20 - Miles			RGASPARD	Feb 6, 2018 11:25:51 PM	No	
30 - Kilometers			RGASPARD	Feb 6, 2018 11:25:51 PM	No	
40 - Hours			RGASPARD	Feb 6, 2018 11:25:51 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 50961757
Invoice No. 55345 - 50961757

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	101,063 - DH

Activity Header
Activity: 40 999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 50961757 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.98
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 48371043
Invoice No. 55345 - 48371043

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 96,839 - DH

Chronology		
Reported	Dec 21, 2017 3:50:58 PM	Dec 21, 2017 3:50:58 PM
Started	Dec 22, 2017 12:00:00 AM	
Completed	Dec 22, 2017 11:04:00 PM	Dec 22, 2017 11:04:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINTS: PM C

CAUSE: Service due

CORRECTION: Performed and completed PM C...
Changed engine oil and replaced engine oil filter
Changed transmission fluid and replaced transmission filter
Replaced rear A/C filter
Drained /Replaced differential fluid
Part #PA4075. Qty1
B329. Qty1
#20021. Qty1

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Dec-17	PA4075	OUT OF SERVICE DO NOT ORDER FILTER, AIR, PAPER SAME AS AF25590	1	5.18	5.18
22-Dec-17	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Dec-17	Delva,Terry	3	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
10 Desc: Light Medium Duty PMI Task: First Transit Light-Medium Duty PMI Performed by: TDELVA Performed on: 22-DEC-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
10,100 - Safety Inspection	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
10,140 - Check Service Brakes	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
10,160 - FRA Check Instruments and Horns	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
10,170 - Check Fast Idle	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
10,180 - Check Starter Protection Circuit	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
10,190 - Check Reverse Warning System	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
11,100 - Check Parking Brake	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
11,150 - Perform Brake Test	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
11,152 - Decelerometer Results Test 1	FEET	n/a	TDELVA	Dec 22, 2017 10:55:53 PM	No	
11,154 - Decelerometer Results Test 2	FEET	n/a	TDELVA	Dec 22, 2017 10:55:53 PM	No	
11,156 - Decelerometer Results Test 3	FEET	n/a	TDELVA	Dec 22, 2017 10:55:53 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	TDELVA	Dec 22, 2017 10:55:53 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	TDELVA	Dec 22, 2017 10:55:53 PM	No	
11,170 - FRA Check Door Operation	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done	n/a	TDELVA	Dec 22, 2017 10:55:53 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
20,210 - Check Condition of Operator's Area	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,220 - Check Accelerator and Brake Pedals	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
20,240 - FRA Check Interior Lights	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
20,260 - Check Stop Request System	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	TDELVA	Dec 22, 2017 10:55:53 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
22,110 - Check Emergency Hatches	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
22,120 - Check All Safety Equipment	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
30,310 - Check Passenger Doors	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	TDELVA	Dec 22, 2017 10:55:53 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
30,360 - Check for Physical Damage and Decals	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
30,380 - Check Exterior Compartment Doors	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
33,100 - Check Lights and Reflectors	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
40,420 - Check Hood	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,430 - Check Fan, Shroud and Radiator	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	TDELVA	Dec 22, 2017 10:55:53 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	TDELVA	Dec 22, 2017 10:55:53 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	TDELVA	Dec 22, 2017 10:55:53 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	TDELVA	Dec 22, 2017 10:55:53 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	TDELVA	Dec 22, 2017 10:55:53 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	-	n/a	TDELVA	Dec 22, 2017 10:55:53 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
44,130 - FRA Check Exhaust System	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
44,140 - FRA Check Intake System	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	TDELVA	Dec 22, 2017 10:55:53 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
44,180 - FRA Check for Leaks	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
44,190 - FRA Perform Battery Inspection	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
50,510 - Check Entire Steering System	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		TDELVA	Dec 22, 2017 10:55:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,612 - Air Pressure LF	65 Pounds per Square Inch		TDELVA	Dec 22, 2017 10:55:53 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		TDELVA	Dec 22, 2017 10:55:53 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		TDELVA	Dec 22, 2017 10:55:53 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		TDELVA	Dec 22, 2017 10:55:53 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		TDELVA	Dec 22, 2017 10:55:53 PM	No	
60,620 - Check Valve Stems and Caps	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
60,630 - Check and Record Tread Depth	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
60,631 - Tread Depth RF	13 32nds of an inch		TDELVA	Dec 22, 2017 10:55:53 PM	No	
60,632 - Tread Depth LF	14 32nds of an inch		TDELVA	Dec 22, 2017 10:55:53 PM	No	
60,633 - Tread Depth RRO	10 32nds of an inch		TDELVA	Dec 22, 2017 10:55:53 PM	No	
60,634 - Tread Depth RRI	11 32nds of an inch		TDELVA	Dec 22, 2017 10:55:53 PM	No	
60,635 - Tread Depth LRI	9 32nds of an inch		TDELVA	Dec 22, 2017 10:55:53 PM	No	
60,636 - Tread Depth LRO	10 32nds of an inch		TDELVA	Dec 22, 2017 10:55:53 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
60,650 - Check Sidewall Wear	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
60,660 - Inspect for Cuts and Tears	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
60,670 - Check Dual Mating With Square	-		TDELVA	Dec 22, 2017 10:55:53 PM	Yes	50961753
60,680 - Check Wheels for Cracks and Loose Lugs	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
70,710 - Check Vibration Damper	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
70,730 - FRA Check Starter	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,760 - FRA Check Differential Breather and Fluid	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
70,770 - FRA Check Exhaust System	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
77,110 - FRA Check Fuel Tank	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
77,120 - Check Suspension Components	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
77,131 - Brake Pad Thickness LF	3 Inch	Front Brakes	TDELVA	Dec 22, 2017 10:55:53 PM	Yes	50961753
77,132 - Brake Pad Thickness RF	5 Inch		TDELVA	Dec 22, 2017 10:55:53 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		TDELVA	Dec 22, 2017 10:55:53 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		TDELVA	Dec 22, 2017 10:55:53 PM	No	
77,135 - Brake Rotor LF	39.5 Inch		TDELVA	Dec 22, 2017 10:55:53 PM	No	
77,136 - Brake Rotor RF	39.6 Inch		TDELVA	Dec 22, 2017 10:55:53 PM	No	
77,137 - Brake Rotor LR	35.8 Inch		TDELVA	Dec 22, 2017 10:55:53 PM	No	
77,138 - Brake Rotor RR	35.6 Inch		TDELVA	Dec 22, 2017 10:55:53 PM	No	
77,140 - FRA Check Brake Hoses	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
77,150 - Check King Pins	-	n/a	TDELVA	Dec 22, 2017 10:55:53 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
80,810 - Completion of PMI Report	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		TDELVA	Dec 22, 2017 10:55:53 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**7.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 50961753
Invoice No. 55345 - 50961753

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FollowUp=====>Front Brakes		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	96,839 - DH

Chronology		
Reported	Dec 22, 2017 10:55:53 PM	Dec 22, 2017 10:55:53 PM
Started	Dec 22, 2017 12:00:00 AM	
Completed	Dec 22, 2017 11:04:00 PM	Dec 22, 2017 11:04:00 PM
Down Time		

Work Order Notes

Line 10 Replaced front brake pads
Part#BRSD-1328. Qty1

Activity Header
Activity: 10 050/000 GROUP, ACCESSORIES
Activity Note: Air Cleaner
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 14 Install
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Dec-17	Delva,Terry	0.5666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 48371043
Invoice No. 55345 - 48371043

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 96,839 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Dec-17	20021	FILTER, TRANSMISSION 20021	1	16.93	16.93

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Dec-17	Delva,Terry	0.5333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: TDELVA Performed on: 22-DEC-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		TDELVA	Dec 22, 2017 10:47:49 PM	No	
101,000 - FRA Change Oil Filters	Yes		TDELVA	Dec 22, 2017 10:47:49 PM	No	
102,000 - FRA Drain Engine Oil	Yes		TDELVA	Dec 22, 2017 10:47:49 PM	No	
103,000 - FRA Check Transmission Fluid	Done		TDELVA	Dec 22, 2017 10:47:49 PM	No	
104,000 - Lubricate Chassis	Done		TDELVA	Dec 22, 2017 10:47:49 PM	No	
105,000 - Replace or Clean A/C Filters	Done		TDELVA	Dec 22, 2017 10:47:49 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	n/a	TDELVA	Dec 22, 2017 10:47:49 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		TDELVA	Dec 22, 2017 10:47:49 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		TDELVA	Dec 22, 2017 10:47:49 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
201,000 - Service Crankcase Breather	Done		TDELVA	Dec 22, 2017 10:47:49 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		TDELVA	Dec 22, 2017 10:47:49 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	Yes		TDELVA	Dec 22, 2017 10:47:49 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		TDELVA	Dec 22, 2017 10:47:49 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		TDELVA	Dec 22, 2017 10:47:49 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		TDELVA	Dec 22, 2017 10:47:49 PM	No	
302,000 - Check Toe-In and Record Reading	-	n/a	TDELVA	Dec 22, 2017 10:47:49 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	n/a	TDELVA	Dec 22, 2017 10:47:49 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	Yes		TDELVA	Dec 22, 2017 10:47:49 PM	No	
305,000 - FRA Change Differential Fluid	Yes		TDELVA	Dec 22, 2017 10:47:49 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	16.93
Labor:	0.00
Labor Hours:	0.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**16.93**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 50961753
Invoice No. 55345 - 50961753

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FollowUp=====>Front Brakes		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	96,839 - DH

Activity Header
Activity: 20 013 BRAKES
Activity Note: Front Brakes
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Dec-17	Delva,Terry	0.2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 48371043
Invoice No. 55345 - 48371043

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM C		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	96,839 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Dec-17	Delva,Terry	0.65	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 22-DEC-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Dec 22, 2017 10:45:41 PM	No	
20 - Miles			TDELVA	Dec 22, 2017 10:45:41 PM	No	
30 - Kilometers			TDELVA	Dec 22, 2017 10:45:41 PM	No	
40 - Hours			TDELVA	Dec 22, 2017 10:45:41 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 48371043 Total	
Parts:	24.03
Labor:	0.00
Labor Hours:	4.18

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**24.03**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 50961753
Invoice No. 55345 - 50961753

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FollowUp=====>Front Brakes		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	96,839 - DH

Activity Header
Activity: 30 999/999/999 TOTAL VEHICLE
Activity Note: Prameter
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Dec-17	BRSD-1328	PADS, BRAKE, DISC, FRONT	1	50.32	50.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Dec-17	Delva,Terry	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: Prameter
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 22-DEC-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Dec 22, 2017 10:59:41 PM	No	
20 - Miles			TDELVA	Dec 22, 2017 10:59:41 PM	No	
30 - Kilometers			TDELVA	Dec 22, 2017 10:59:41 PM	No	
40 - Hours			TDELVA	Dec 22, 2017 10:59:41 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	50.32
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**50.32**

Work Order Footer

Work Order 50961753 Total	
Parts:	50.32

	Labor:	0.00
	Labor Hours:	2.77
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**50.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 48721487
Invoice No. 55345 - 48721487

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Signal Light		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	93,145 - DH

Chronology		
Reported	Nov 20, 2017 5:51:48 PM	Nov 20, 2017 5:51:48 PM
Started	Nov 20, 2017 12:00:00 AM	
Completed	Nov 20, 2017 5:55:00 PM	Nov 20, 2017 5:55:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: Front Left Signal out

CAUSE: Bad bulb

CORRECTION: Replaced front Right Bulb
Part used #3157NA. Qty:1

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Nov-17	Delva,Terry	0.3666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 20-NOV-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Nov 20, 2017 5:55:38 PM	No	
20 - Miles			TDELVA	Nov 20, 2017 5:55:38 PM	No	
30 - Kilometers			TDELVA	Nov 20, 2017 5:55:38 PM	No	
40 - Hours			TDELVA	Nov 20, 2017 5:55:38 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 48721487
Invoice No. 55345 - 48721487

Client Department:
Department: 55345M
Work Order Description
Signal Light
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 93,145 - DH

Activity Header
Activity: 15 050/000 GROUP, ACCESSORIES
Activity Note: Signal bulb
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 14 Install
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Nov-17	3157NA	LAMP, MINIATURE, WEDGE-MOUNT, AMBER SAME AS GE3157NA	1	0.85	0.85

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Nov-17	Delva,Terry	0.7333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.85
Labor:	0.00
Labor Hours:	0.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.85**

Work Order Footer

Work Order 48721487 Total	
Parts:	0.85
Labor:	0.00
Labor Hours:	1.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.85**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 45403375
Invoice No. 55345 - 45403375

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	92,899 - DH

Chronology		
Reported	Nov 16, 2017 2:48:45 PM	Nov 16, 2017 2:48:45 PM
Started	Nov 16, 2017 12:00:00 AM	
Completed	Nov 17, 2017 12:14:00 AM	Nov 17, 2017 12:14:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:Service

CORRECTION:perform pmA service
Oil filter B329 qty 1
Engine oil 5w20 qty 7 Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Nov-17	Gaspard,Ronald	1.5333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 16-NOV-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Nov 16, 2017 11:56:57 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Nov 16, 2017 11:56:57 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Nov 16, 2017 11:56:57 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Nov 16, 2017 11:56:57 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Nov 16, 2017 11:56:57 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	na	RGASPARD	Nov 16, 2017 11:56:57 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Nov 16, 2017 11:56:57 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Nov 16, 2017 11:56:57 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
40,420 - Check Hood	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Nov 16, 2017 11:56:57 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Nov 16, 2017 11:56:57 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Nov 16, 2017 11:56:57 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Nov 16, 2017 11:56:57 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Nov 16, 2017 11:56:57 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Nov 16, 2017 11:56:57 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Nov 16, 2017 11:56:57 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
60,631 - Tread Depth RF	3 32nds of an inch	needs front tires	RGASPARD	Nov 16, 2017 11:56:57 PM	Yes	48369826
60,632 - Tread Depth LF	3 32nds of an inch		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
77,133 - Brake Pad Thickness LR	4 Inch		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
77,134 - Brake Pad Thickness RR	4 Inch	needs rear brakes job	RGASPARD	Nov 16, 2017 11:56:57 PM	Yes	48369826
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
77,137 - Brake Rotor LR	38 Inch		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
77,138 - Brake Rotor RR	38 Inch		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Nov 16, 2017 11:56:57 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Nov 16, 2017 11:56:57 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 45403375
Invoice No. 55345 - 45403375

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 92,899 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Nov-17	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Nov-17	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 16-NOV-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Nov 16, 2017 11:57:30 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Nov 16, 2017 11:57:30 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Nov 16, 2017 11:57:30 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Nov 16, 2017 11:57:30 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Nov 16, 2017 11:57:30 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Nov 16, 2017 11:57:30 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Nov 16, 2017 11:57:30 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Nov 16, 2017 11:57:30 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.92
	Labor:	0.00
	Labor Hours:	1.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 45403375
Invoice No. 55345 - 45403375

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	92,899 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Nov-17	Gaspard,Ronald	0.2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 16-NOV-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Nov 16, 2017 11:57:47 PM	No	
20 - Miles			RGASPARD	Nov 16, 2017 11:57:47 PM	No	
30 - Kilometers			RGASPARD	Nov 16, 2017 11:57:47 PM	No	
40 - Hours			RGASPARD	Nov 16, 2017 11:57:47 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 45403375 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.73

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 48369826
Invoice No. 55345 - 48369826

Client Department:
Department: 55345M
Work Order Description
Followup--------> needs rear brakes job and front tires
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 92,899 - DH

Chronology		
Reported	Nov 16, 2017 11:56:57 PM	Nov 16, 2017 11:56:57 PM
Started	Nov 17, 2017 12:00:00 AM	
Completed	Nov 17, 2017 12:12:00 AM	Nov 17, 2017 12:12:00 AM
Down Time		

Work Order Notes

Line 10 Needs rear brakes job and front tires
Wear
Replaced rear brake pads and lubed guide pins
2 front tires mounted and balance
Tires part number 189752 qty 2
Brakes part number BRSD1330 qty 1
Torque wheels 140 lbs second torque 140 lbs

Activity Header
Activity: 10 017 TIRES, TUBES, LINERS & VALVES
Activity Note: needs front tires
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Nov-17	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	106.72	213.44

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Nov-17	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	213.44
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**213.44**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 48369826
Invoice No. 55345 - 48369826

Client Department:
Department: 55345M
Work Order Description
Followup--------> needs rear brakes job and front tires
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 92,899 - DH

Activity Header
Activity: 20 013/002 REAR BRAKES & DRUMS
Activity Note: needs rear brakes job
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Nov-17	BRSD-1330	PADS, BRAKE, DISC, REAR, FORD SAME AS PFH133020	1	43.15	43.15

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Nov-17	Gaspard,Ronald	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	43.15
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.15**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 48369826
Invoice No. 55345 - 48369826

Client Department:
Department: 55345M
Work Order Description
Followup--------> needs rear brakes job and front tires
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 92,899 - DH

Activity Header
Activity: 30 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Nov-17	Gaspard,Ronald	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc:
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 17-NOV-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Nov 17, 2017 12:01:19 AM	No	
20 - Miles			RGASPARD	Nov 17, 2017 12:01:19 AM	No	
30 - Kilometers			RGASPARD	Nov 17, 2017 12:01:19 AM	No	
40 - Hours			RGASPARD	Nov 17, 2017 12:01:19 AM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 48369826 Total	
Parts:	256.59
Labor:	0.00
Labor Hours:	3.08

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**256.59**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 42205035
Invoice No. 55345 - 42205035

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 88,966 - DH

Chronology		
Reported	Oct 16, 2017 9:29:52 AM	Oct 16, 2017 9:29:52 AM
Started	Oct 16, 2017 12:00:00 AM	
Completed	Oct 17, 2017 7:06:00 AM	Oct 17, 2017 7:06:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA

CAUSE: preventive maintenance

CORRECTION:perform service lube all Pivoting points cross rotate tires completed
Parts #B329 qty 1
Oil5w20 #6

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Oct-17	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.92	1.92
16-Oct-17	3973291	LAMP, LED, CLEAR, 4". SOUND-OFF	1	42.76	42.76

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Oct-17	Pierre,Hubert J	5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 16-OCT-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
10,100 - Safety Inspection	Done		HPIERRE	Oct 16, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				2:56:37 PM		
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
11,152 - Decelerometer Results Test 1	FEET	N/A	HPIERRE	Oct 16, 2017 2:56:37 PM	No	
11,154 - Decelerometer Results Test 2	FEET	N/A	HPIERRE	Oct 16, 2017 2:56:37 PM	No	
11,156 - Decelerometer Results Test 3	FEET	N/A	HPIERRE	Oct 16, 2017 2:56:37 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	Oct 16, 2017 2:56:37 PM	No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	Oct 16, 2017 2:56:37 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Oct 16, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				2:56:37 PM		
20,240 - FRA Check Interior Lights	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Oct 16, 2017 2:56:37 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Oct 16, 2017 2:56:37 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Oct 16, 2017 2:56:37 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
40,420 - Check Hood	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
40,440 - Test Coolant System Using Test Strips	-	N/A	HPIERRE	Oct 16, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
and Record Results				2:56:37 PM		
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Oct 16, 2017 2:56:37 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Oct 16, 2017 2:56:37 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Oct 16, 2017 2:56:37 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Oct 16, 2017 2:56:37 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Oct 16, 2017 2:56:37 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
60,613 - Air Pressure RRO	70 Pounds per		HPIERRE	Oct 16, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			2:56:37 PM		
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
60,631 - Tread Depth RF	6 32nds of an inch		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
60,632 - Tread Depth LF	6 32nds of an inch		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
60,633 - Tread Depth RRO	10 32nds of an inch		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
60,635 - Tread Depth LRI	10 32nds of an inch		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
60,636 - Tread Depth LRO	10 32nds of an inch		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Oct 16, 2017 2:56:37 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Oct 16, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				2:56:37 PM		
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
77,135 - Brake Rotor LF	1.5 Inch		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
77,136 - Brake Rotor RF	1.5 Inch		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
77,137 - Brake Rotor LR	1.6 Inch		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
77,138 - Brake Rotor RR	1.6 Inch		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Oct 16, 2017 2:56:37 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Oct 16, 2017 2:56:37 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	44.68
Labor:	0.00
Labor Hours:	5.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**44.68**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 42205035
Invoice No. 55345 - 42205035

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	88,966 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Oct-17	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 16-OCT-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Oct 16, 2017 2:57:51 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Oct 16, 2017 2:57:51 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Oct 16, 2017 2:57:51 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Oct 16, 2017 2:57:51 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Oct 16, 2017 2:57:51 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Oct 16, 2017 2:57:51 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Oct 16, 2017 2:57:51 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Oct 16, 2017 2:57:51 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 42205035
Invoice No. 55345 - 42205035

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 88,966 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Oct-17	F75Z-6730-BA	PLUG, DRAIN, OIL, ENGINE, 3.0L	1	6.66	6.66

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Oct-17	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 16-OCT-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Oct 16, 2017 3:00:34 PM	No	
20 - Miles			HPIERRE	Oct 16, 2017 3:00:34 PM	No	
30 - Kilometers			HPIERRE	Oct 16, 2017 3:00:34 PM	No	
40 - Hours			HPIERRE	Oct 16, 2017 3:00:34 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	6.66
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**6.66**

Work Order Footer

Work Order 42205035 Total	
Parts:	51.34

	Labor:	0.00
	Labor Hours:	5.50
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**51.34**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 43486327
Invoice No. 55345 - 43486327

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Driver said front A/C not working		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	86,010 - DH

Chronology		
Reported	Sep 27, 2017 12:03:32 PM	Sep 27, 2017 12:03:32 PM
Started	Sep 27, 2017 12:00:00 AM	
Completed	Sep 27, 2017 2:26:00 PM	Sep 27, 2017 2:26:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: Driver said front A/C not working

CAUSE: leaking evaporator

CORRECTION: replace evaporator orifice tube and add freon completed
Part# evaporator U.K.-211 -6C2Z-19860-C qty 1
Orifice tube #3411885 qty 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Sep-17	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 27-SEP-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Sep 27, 2017 12:16:30 PM	No	
20 - Miles			HPIERRE	Sep 27, 2017 12:16:30 PM	No	
30 - Kilometers			HPIERRE	Sep 27, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:16:30 PM		
40 - Hours			HPIERRE	Sep 27, 2017 12:16:30 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 43486327
Invoice No. 55345 - 43486327

Client Department:
Department: 55345M
Work Order Description
Driver said front A/C not working
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 86,010 - DH

Activity Header
Activity: 15 001/001/000 AIR CONDITIONING
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: C PM Level C
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Sep-17	3411885	TUBE, ORIFICE, A/C, FORD	1	0.75	0.75
27-Sep-17	YK211	CORE, EVAPORATOR, A/C	1	150.45	150.45

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Sep-17	Pierre,Hubert J	5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List						
15 Desc: Task: ELECTRICAL SYSTEM Performed by: HPIERRE Performed on: 27-SEP-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - A/C SYSTEM CHECK	Done		HPIERRE	Sep 27, 2017 12:19:34 PM	No	

Activity Sub Total

Activity 15 Sub Total	
Parts:	151.20
Labor:	0.00
Labor Hours:	5.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**151.20**

Work Order Footer

Work Order 43486327 Total	
Parts:	151.20
Labor:	0.00
Labor Hours:	5.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**151.20**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 36878909
Invoice No. 55345 - 36878909

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 84,783 - DH

Chronology		
Reported	Sep 14, 2017 11:37:11 AM	Sep 14, 2017 11:37:11 AM
Started	Sep 14, 2017 12:00:00 AM	
Completed	Sep 14, 2017 11:04:00 PM	Sep 14, 2017 11:04:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmB

CAUSE:service

CORRECTION:perform pmB
Oil filter B329 qty 1
Engine oil 5w20 qty 7 Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Sep-17	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 14-SEP-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Sep 14, 2017 4:42:34 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Sep 14, 2017 4:42:34 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Sep 14, 2017 4:42:34 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Sep 14, 2017 4:42:34 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Sep 14, 2017 4:42:34 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	na	RGASPARD	Sep 14, 2017 4:42:34 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Sep 14, 2017 4:42:34 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Sep 14, 2017 4:42:34 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
40,420 - Check Hood	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Sep 14, 2017 4:42:34 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Sep 14, 2017 4:42:34 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Sep 14, 2017 4:42:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Sep 14, 2017 4:42:34 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Sep 14, 2017 4:42:34 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Sep 14, 2017 4:42:34 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Sep 14, 2017 4:42:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
60,631 - Tread Depth RF	6 32nds of an inch		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
60,633 - Tread Depth RRO	9 32nds of an inch		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
60,636 - Tread Depth LRO	12 32nds of an inch		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
77,137 - Brake Rotor LR	38 Inch		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
77,138 - Brake Rotor RR	38 Inch		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Sep 14, 2017 4:42:34 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Sep 14, 2017 4:42:34 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 36878909
Invoice No. 55345 - 36878909

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 84,783 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Sep-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Sep-17	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: RGASPARD Performed on: 14-SEP-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Sep 14, 2017 4:43:37 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Sep 14, 2017 4:43:37 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Sep 14, 2017 4:43:37 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Sep 14, 2017 4:43:37 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Sep 14, 2017 4:43:37 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Sep 14, 2017 4:43:37 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Sep 14, 2017 4:43:37 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Sep 14, 2017 4:43:37 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		RGASPARD	Sep 14, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				4:43:37 PM		
201,000 - Service Crankcase Breather	Done		RGASPARD	Sep 14, 2017 4:43:37 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Sep 14, 2017 4:43:37 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Sep 14, 2017 4:43:37 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Sep 14, 2017 4:43:37 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 36878909
Invoice No. 55345 - 36878909

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM B		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	84,783 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Sep-17	Gaspard,Ronald	0.1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 14-SEP-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Sep 14, 2017 4:44:11 PM	No	
20 - Miles			RGASPARD	Sep 14, 2017 4:44:11 PM	No	
30 - Kilometers			RGASPARD	Sep 14, 2017 4:44:11 PM	No	
40 - Hours			RGASPARD	Sep 14, 2017 4:44:11 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 36878909 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.60

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 39273699
Invoice No. 55345 - 39273699

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Battery		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	81,918 - DH

Chronology		
Reported	Aug 15, 2017 4:08:05 PM	Aug 15, 2017 4:08:05 PM
Started	Aug 15, 2017 12:00:00 AM	
Completed	Aug 15, 2017 6:20:00 PM	Aug 15, 2017 6:20:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Had to jump start the car

CAUSE: Bad Battery

CORRECTION: Replaced two batteries..
Parts Used #24M-XHD Qty:2

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Aug-17	MTP-24S	OUT OF SERVICE BATTERY	1	79.75	79.75

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Aug-17	Delva,Terry	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 15-AUG-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Aug 15, 2017 4:16:21 PM	No	
20 - Miles			TDELVA	Aug 15, 2017 4:16:21 PM	No	
30 - Kilometers			TDELVA	Aug 15, 2017 4:16:21 PM	No	
40 - Hours			TDELVA	Aug 15, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				4:16:21 PM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	79.75
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**79.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 39273699
Invoice No. 55345 - 39273699

Client Department:
Department: 55345M
Work Order Description
Battery
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 81,918 - DH

Activity Header
Activity: 15 031/005/000 CHARGER, BATTERY, ON-BOARD, VEHICLES, PROPELLED, ELECTRICALLY
Activity Note: Battery
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure: 43 Weak
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Aug-17	24M-XHD	BATTERY, 800CCA, 12V	1	80.96	80.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Aug-17	Delva,Terry	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	80.96
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**80.96**

Work Order Footer

Work Order 39273699 Total	
Parts:	160.71
Labor:	0.00
Labor Hours:	1.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**160.71**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 34945865
Invoice No. 55345 - 34945865

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	80,520 - DH

Chronology		
Reported	Jul 21, 2017 11:57:07 AM	Jul 21, 2017 11:57:07 AM
Started	Jul 21, 2017 12:00:00 AM	
Completed	Jul 21, 2017 4:40:00 PM	Jul 21, 2017 4:40:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pm-A Inspection due

CAUSE: miles

CORRECTION: Completed pm-A Inspection. Replace oil and oil filter. Replaced 2 left rear tires. Torqued to 140 ft pounds. Road test torque 2 time . Replaced 2 block terminals. Pole single.

Parts used. 6 quarts oil. 5 w20. 1 oil filter. B329. 2 tires. Firestone. 189752. 2 block terminals 10210201

Replaced. Drivers mirror. Curb side. Under warranty. Qty. 1. 718708.

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Jul-17	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	105.25	210.5
21-Jul-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92
21-Jul-17	10210201	BLOCK, TERMINAL, POLE, SINGLE	2	10.86	21.72

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jul-17	Capazzoli,Louis	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
10 Desc: Light Medium Duty PMI Task: First Transit Light-Medium Duty PMI Performed by: LCAPAZZOLI Performed on: 21-JUL-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
10,100 - Safety Inspection	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
10,140 - Check Service Brakes	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
10,160 - FRA Check Instruments and Horns	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
10,170 - Check Fast Idle	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
10,180 - Check Starter Protection Circuit	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
10,190 - Check Reverse Warning System	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
11,100 - Check Parking Brake	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
11,150 - Perform Brake Test	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
11,152 - Decelerometer Results Test 1	FEET	n/a	LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
11,154 - Decelerometer Results Test 2	FEET	n/a	LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
11,156 - Decelerometer Results Test 3	FEET	n/a	LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
11,170 - FRA Check Door Operation	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
20,210 - Check Condition of Operator's Area	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,220 - Check Accelerator and Brake Pedals	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
20,240 - FRA Check Interior Lights	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
20,260 - Check Stop Request System	-	n/a	LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
22,110 - Check Emergency Hatches	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
22,120 - Check All Safety Equipment	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
30,310 - Check Passenger Doors	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
30,360 - Check for Physical Damage and Decals	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
30,380 - Check Exterior Compartment Doors	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
33,100 - Check Lights and Reflectors	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
40,420 - Check Hood	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,430 - Check Fan, Shroud and Radiator	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
44,130 - FRA Check Exhaust System	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
44,140 - FRA Check Intake System	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
44,180 - FRA Check for Leaks	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
44,190 - FRA Perform Battery Inspection	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
50,510 - Check Entire Steering System	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,612 - Air Pressure LF	70 Pounds per Square Inch		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
60,620 - Check Valve Stems and Caps	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
60,630 - Check and Record Tread Depth	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
60,631 - Tread Depth RF	12 32nds of an inch		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
60,633 - Tread Depth RRO	12 32nds of an inch		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
60,636 - Tread Depth LRO	12 32nds of an inch		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
60,650 - Check Sidewall Wear	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
60,660 - Inspect for Cuts and Tears	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
70,710 - Check Vibration Damper	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
70,730 - FRA Check Starter	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,760 - FRA Check Differential Breather and Fluid	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
70,770 - FRA Check Exhaust System	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
77,110 - FRA Check Fuel Tank	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
77,120 - Check Suspension Components	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
77,131 - Brake Pad Thickness LF	Inch	10 mm	LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
77,132 - Brake Pad Thickness RF	Inch	10 mm	LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
77,133 - Brake Pad Thickness LR	Inch	10 mm	LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
77,134 - Brake Pad Thickness RR	Inch	10 mm	LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
77,135 - Brake Rotor LF	Inch	40	LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
77,136 - Brake Rotor RF	Inch	40	LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
77,137 - Brake Rotor LR	Inch	40	LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
77,138 - Brake Rotor RR	Inch	40	LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
77,140 - FRA Check Brake Hoses	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
77,150 - Check King Pins	-	n/a	LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
80,810 - Completion of PMI Report	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		LCAPAZZOLI	Jul 21, 2017 3:41:25 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	234.14
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**234.14**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 36876042
Invoice No. 55345 - 36876042

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Replace both left rear tires		Ford E450 Champion Challenger	
Requested By:	LCAPAZZOLI	**Status:**	40 - Closed (40)
Created By:	LCAPAZZOLI	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	80,520 - DH

Chronology		
Reported	Jul 21, 2017 3:56:06 PM	Jul 21, 2017 3:56:06 PM
Started		
Completed	Jul 21, 2017 4:40:00 PM	Jul 21, 2017 4:40:00 PM
Down Time		

Work Order Notes

Line 10 Replaced both left rear tires. Torque to 140 ft pounds. Road test. Torque 2 nd. Time

Parts used. 2. Firestone tires. 189752

Activity Header
Activity: 10 017 TIRES, TUBES, LINERS & VALVES
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Jul-17	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	105.25	210.5

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	210.50
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**210.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 34945865
Invoice No. 55345 - 34945865

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 80,520 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jul-17	Capazzoli,Louis	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: LCAPAZZOLI Performed on: 21-JUL-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		LCAPAZZOLI	Jul 21, 2017 3:41:59 PM	No	
101,000 - FRA Change Oil Filters	Yes		LCAPAZZOLI	Jul 21, 2017 3:41:59 PM	No	
102,000 - FRA Drain Engine Oil	Yes		LCAPAZZOLI	Jul 21, 2017 3:41:59 PM	No	
103,000 - FRA Check Transmission Fluid	Done		LCAPAZZOLI	Jul 21, 2017 3:41:59 PM	No	
104,000 - Lubricate Chassis	Done		LCAPAZZOLI	Jul 21, 2017 3:41:59 PM	No	
105,000 - Replace or Clean A/C Filters	Done		LCAPAZZOLI	Jul 21, 2017 3:41:59 PM	No	
107,000 - FRA Change Primary Fuel Filter	No		LCAPAZZOLI	Jul 21, 2017 3:41:59 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		LCAPAZZOLI	Jul 21, 2017 3:41:59 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.50
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 36876042
Invoice No. 55345 - 36876042

Client Department:
Department: 55345M
Work Order Description
Replace both left rear tires
Requested By: LCAPAZZOLI
Created By: LCAPAZZOLI
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 80,520 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 21-JUL-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Jul 21, 2017 4:01:39 PM	No	
20 - Miles			LCAPAZZOLI	Jul 21, 2017 4:01:39 PM	No	
30 - Kilometers			LCAPAZZOLI	Jul 21, 2017 4:01:39 PM	No	
40 - Hours			LCAPAZZOLI	Jul 21, 2017 4:01:39 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 36876042 Total	
Parts:	210.50
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**210.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 34945865
Invoice No. 55345 - 34945865

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 80,520 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jul-17	Capazzoli,Louis	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 21-JUL-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Jul 21, 2017 3:32:32 PM	No	
20 - Miles			LCAPAZZOLI	Jul 21, 2017 3:32:32 PM	No	
30 - Kilometers			LCAPAZZOLI	Jul 21, 2017 3:32:32 PM	No	
40 - Hours			LCAPAZZOLI	Jul 21, 2017 3:32:32 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34945865 Total	
Parts:	234.14
Labor:	0.00
Labor Hours:	1.58

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**234.14**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34998020
Invoice No. 55345 - 34998020

Client Department:
Department: 55345M
Work Order Description
Manufacturer recommended spark plug service by mileage
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 78,536 - DH

Chronology		
Reported	Jun 29, 2017 11:32:07 AM	Jun 29, 2017 11:32:07 AM
Started	Jun 29, 2017 12:00:00 AM	
Completed	Jun 29, 2017 1:36:00 PM	Jun 29, 2017 1:36:00 PM
Down Time		

Work Order Notes

Line 10 Spark plug

COMPLAINT:
Manufacturer recommended spark plug service by mileage

CAUSE:
Normal wear.

CORRECTION:
Removed all spark plugs and spark plug boots. Replaced them with new spark plugs and spark plug boots. Applied dielectric grease to the the spring inside the spark plug boot.

PARTS
Qty 10 Boot WR-6128
Qty 10 spark plug SP521

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 29-JUN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Jun 29, 2017 11:53:27 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			EDTORRES	Jun 29, 2017 11:53:27 AM	No	
30 - Kilometers			EDTORRES	Jun 29, 2017 11:53:27 AM	No	
40 - Hours			EDTORRES	Jun 29, 2017 11:53:27 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34998020
Invoice No. 55345 - 34998020

Client Department:
Department: 55345M
Work Order Description
Manufacturer recommended spark plug service by mileage
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 78,536 - DH

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Manufacturer recommended spark plug service by mileage
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Jun-17	SP521	PLUG, SPARK, 5.4L, FORD	10	4.15	41.5
29-Jun-17	WR6128	BOOT, PLUG, SPARK	10	5.43	54.3

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Jun-17	Torres,Edwin	3.4	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	95.80
Labor:	0.00
Labor Hours:	3.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**95.80**

Work Order Footer

Work Order 34998020 Total	
Parts:	95.80
Labor:	0.00
Labor Hours:	3.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**95.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34955683
Invoice No. 55345 - 34955683

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Wiper motor clip		Ford E450 Champion Challenger	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	76,992 - DH

Chronology		
Reported	Jun 12, 2017 12:43:38 PM	Jun 12, 2017 12:43:38 PM
Started	Jun 12, 2017 12:00:00 AM	
Completed	Jun 12, 2017 2:32:00 PM	Jun 12, 2017 2:32:00 PM
Down Time		

Work Order Notes

Line 10 Wiper motor linkage clip

CAUSE:
Found that the pressure clip that holds the linkage onto the motor doesn't have enough pressure to retain the linkage onto the motor over time.

CORRECTION:
Removed the bad pressure clip and installed a new pressure clip and mounted the linkage back onto the wiper motor.

Qty 1 wiper motor/pressure clip E3TZ-17531-A

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 12-JUN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Jun 12, 2017 12:46:15 PM	No	
20 - Miles			EDTORRES	Jun 12, 2017 12:46:15 PM	No	
30 - Kilometers			EDTORRES	Jun 12, 2017 12:46:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			EDTORRES	Jun 12, 2017 12:46:15 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34955683
Invoice No. 55345 - 34955683

Client Department:
Department: 55345M
Work Order Description
Wiper motor clip
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 76,992 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note: Wiper motor clip
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Jun-17	E3TZ-17531-A	CLIP, ARM, WPER	1	10.52	10.52

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Jun-17	Torres,Edwin	0.5166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	10.52
Labor:	0.00
Labor Hours:	0.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**10.52**

Work Order Footer

Work Order 34955683 Total	
Parts:	10.52
Labor:	0.00
Labor Hours:	0.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**10.52**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 34806490
Invoice No. 55345 - 34806490

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	76,744 - DH

Chronology		
Reported	Jun 6, 2017 10:25:18 AM	Jun 6, 2017 10:25:18 AM
Started	Jun 6, 2017 12:00:00 AM	
Completed	Jun 6, 2017 11:32:00 PM	Jun 6, 2017 11:32:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA

CAUSE:service

CORRECTION:perform PMA service
Oil filter B329 Qty 1
Engine oil 5W20Qty 7 Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jun-17	Gaspard,Ronald	1	0	0
06-Jun-17	Gaspard,Ronald	1.5333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 06-JUN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Jun 6, 2017 11:32:27 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Jun 6, 2017 11:32:27 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Jun 6, 2017 11:32:27 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Jun 6, 2017 11:32:27 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Jun 6, 2017 11:32:27 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Jun 6, 2017 11:32:27 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Jun 6, 2017 11:32:27 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
30,340 - FRA Check Destination Sign and Run Box	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
40,420 - Check Hood	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Jun 6, 2017 11:32:27 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Jun 6, 2017 11:32:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Jun 6, 2017 11:32:27 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Jun 6, 2017 11:32:27 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Jun 6, 2017 11:32:27 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Jun 6, 2017 11:32:27 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Jun 6, 2017 11:32:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
60,631 - Tread Depth RF	11 32nds of an inch		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
60,632 - Tread Depth LF	11 32nds of an inch		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
60,633 - Tread Depth RRO	2 32nds of an inch	needs 2 right rear tires	RGASPARD	Jun 6, 2017 11:32:27 PM	Yes	34945392
60,634 - Tread Depth RRI	3 32nds of an inch		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
60,636 - Tread Depth LRO	5 32nds of an inch		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
77,137 - Brake Rotor LR	38 Inch		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
77,138 - Brake Rotor RR	38 Inch		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Jun 6, 2017 11:32:27 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Jun 6, 2017 11:32:27 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 34806490
Invoice No. 55345 - 34806490

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 76,744 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Jun-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jun-17	Gaspard,Ronald	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 06-JUN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jun 6, 2017 9:17:40 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jun 6, 2017 9:17:40 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jun 6, 2017 9:17:40 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jun 6, 2017 9:17:40 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Jun 6, 2017 9:17:40 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jun 6, 2017 9:17:40 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Jun 6, 2017 9:17:40 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jun 6, 2017 9:17:40 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.92
	Labor:	0.00
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 34806490
Invoice No. 55345 - 34806490

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 76,744 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jun-17	Gaspard,Ronald	0.1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 06-JUN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jun 6, 2017 9:18:13 PM	No	
20 - Miles			RGASPARD	Jun 6, 2017 9:18:13 PM	No	
30 - Kilometers			RGASPARD	Jun 6, 2017 9:18:13 PM	No	
40 - Hours			RGASPARD	Jun 6, 2017 9:18:13 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34806490 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.72

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34945392
Invoice No. 55345 - 34945392

Client Department:
Department: 55345M
Work Order Description
Followup----------> needs 2 right rear tires
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 76,744 - DH

Chronology		
Reported	Jun 6, 2017 9:16:59 PM	Jun 6, 2017 9:16:59 PM
Started	Jun 6, 2017 12:00:00 AM	
Completed	Jun 6, 2017 11:30:00 PM	Jun 6, 2017 11:30:00 PM
Down Time		

Work Order Notes

Line 10 Needs 2 right rear tires
Wear
2 new tires mounted and balanced
Torque wheels 140 lbs second torque 140 lbs
Part number 189752 qty 2

Activity Header
Activity: 10 017 TIRES, TUBES, LINERS & VALVES
Activity Note: needs 2 right rear tires
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Jun-17	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	105.25	210.5

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jun-17	Gaspard,Ronald	1.05	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	210.50
Labor:	0.00
Labor Hours:	1.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**210.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34945392
Invoice No. 55345 - 34945392

Client Department:
Department: 55345M
Work Order Description
Followup----------> needs 2 right rear tires
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 76,744 - DH

Activity Header
Activity: 20 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Needs 2 right rear tires
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jun-17	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Needs 2 right rear tires
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 06-JUN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jun 6, 2017 9:24:02 PM	No	
20 - Miles			RGASPARD	Jun 6, 2017 9:24:02 PM	No	
30 - Kilometers			RGASPARD	Jun 6, 2017 9:24:02 PM	No	
40 - Hours			RGASPARD	Jun 6, 2017 9:24:02 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34945392 Total	
Parts:	210.50
Labor:	0.00
Labor Hours:	1.12

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**210.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34843888
Invoice No. 55345 - 34843888

Client Department:
Department: 55345M
Work Order Description
Driverside mirror arm broken
Requested By: LCAPAZZOLI
Created By: LCAPAZZOLI
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 74,492 - DH

Chronology		
Reported	May 19, 2017 3:02:56 PM	May 19, 2017 3:02:56 PM
Started	May 19, 2017 12:00:00 AM	
Completed	May 23, 2017 7:34:00 AM	May 23, 2017 7:34:00 AM
Down Time		

Work Order Notes

Line 10 Replaced driverside mirror arm.

1. Under warranty Line 20 updated velvac driver side mirror arm replaced.

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-May-17	Capazzoli,Louis	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 19-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	May 19, 2017 5:18:18 PM	No	
20 - Miles			LCAPAZZOLI	May 19, 2017 5:18:18 PM	No	
30 - Kilometers			LCAPAZZOLI	May 19, 2017 5:18:18 PM	No	
40 - Hours			LCAPAZZOLI	May 19, 2017 5:18:18 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00

	Labor Hours:	0.50
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34843888
Invoice No. 55345 - 34843888

Client Department:
Department: 55345M
Work Order Description
Driverside mirror arm broken
Requested By: LCAPAZZOLI
Created By: LCAPAZZOLI
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 74,492 - DH

Activity Header
Activity: 20 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-May-17	Capazzoli,Louis	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34843888 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 34736858
Invoice No. 55345 - 34736858

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 72,584 - DH

Chronology		
Reported	May 3, 2017 9:50:50 AM	May 3, 2017 9:50:50 AM
Started	May 3, 2017 12:00:00 AM	
Completed	May 3, 2017 9:46:00 PM	May 3, 2017 9:46:00 PM
Down Time		

Work Order Notes

Line 10 Perform PMC Service Change Oil& Filter, Lube all Pivoting Points, Check brakes, clean batteries, Perform transmission service, replace transmission filter& Perform differential service replace air filter,
Parts# B329 Qty (1)
Parts# ,PA4075 Qty (1)
Parts# 20021 Qty (1)
Oil 5W20 Qty (7) Qts
Transmission fluid Qty (10) Qts
Differential fluid Qty (3) Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-May-17	Arthurs,Durvin	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 03-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
10,120 - FRA Check All Warning Lights and	Done		DARTHURS	May 3, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				8:14:49 PM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	May 3, 2017 8:14:49 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	May 3, 2017 8:14:49 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	May 3, 2017 8:14:49 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	May 3, 2017 8:14:49 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	May 3, 2017 8:14:49 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
20,250 - FRA Check Interior Electrical	Done		DARTHURS	May 3, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Panels				8:14:49 PM		
20,260 - Check Stop Request System	-	NA	DARTHURS	May 3, 2017 8:14:49 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	May 3, 2017 8:14:49 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	May 3, 2017 8:14:49 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
33,100 - Check Lights and Reflectors	-	Front center clearance Light	DARTHURS	May 3, 2017 8:14:49 PM	Yes	34806404
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
40,420 - Check Hood	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	May 3, 2017 8:14:49 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	May 3, 2017 8:14:49 PM	No	
40,442 - Freeze Point	Degree	NA	DARTHURS	May 3, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			8:14:49 PM		
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	May 3, 2017 8:14:49 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	May 3, 2017 8:14:49 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	May 3, 2017 8:14:49 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	May 3, 2017 8:14:49 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	May 3, 2017 8:14:49 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	May 3, 2017 8:14:49 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	May 3, 2017 8:14:49 PM	No	
60,615 - Air Pressure LRI	65 Pounds per		DARTHURS	May 3, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			8:14:49 PM		
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	May 3, 2017 8:14:49 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
60,631 - Tread Depth RF	12 32nds of an inch		DARTHURS	May 3, 2017 8:14:49 PM	No	
60,632 - Tread Depth LF	13 32nds of an inch		DARTHURS	May 3, 2017 8:14:49 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		DARTHURS	May 3, 2017 8:14:49 PM	No	
60,634 - Tread Depth RRI	5 32nds of an inch		DARTHURS	May 3, 2017 8:14:49 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		DARTHURS	May 3, 2017 8:14:49 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		DARTHURS	May 3, 2017 8:14:49 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	May 3, 2017 8:14:49 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
70,790 - Check All Body Mounts and	Done		DARTHURS	May 3, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Chassis Frame				8:14:49 PM		
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
77,131 - Brake Pad Thickness LF	9 Inch		DARTHURS	May 3, 2017 8:14:49 PM	No	
77,132 - Brake Pad Thickness RF	9 Inch		DARTHURS	May 3, 2017 8:14:49 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		DARTHURS	May 3, 2017 8:14:49 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		DARTHURS	May 3, 2017 8:14:49 PM	No	
77,135 - Brake Rotor LF	1.567 Inch		DARTHURS	May 3, 2017 8:14:49 PM	No	
77,136 - Brake Rotor RF	1.568 Inch		DARTHURS	May 3, 2017 8:14:49 PM	No	
77,137 - Brake Rotor LR	1.646 Inch		DARTHURS	May 3, 2017 8:14:49 PM	No	
77,138 - Brake Rotor RR	1.647 Inch		DARTHURS	May 3, 2017 8:14:49 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	May 3, 2017 8:14:49 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	May 3, 2017 8:14:49 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 34736858
Invoice No. 55345 - 34736858

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 72,584 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-May-17	PA4075	OUT OF SERVICE DO NOT ORDER FILTER, AIR, PAPER SAME AS AF25590	1	5.18	5.18
03-May-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92
03-May-17	20021	FILTER, TRANSMISSION 20021	1	16.94	16.94

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-May-17	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: DARTHURS Performed on: 03-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	May 3, 2017 8:16:45 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	May 3, 2017 8:16:45 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	May 3, 2017 8:16:45 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	May 3, 2017 8:16:45 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	May 3, 2017 8:16:45 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	May 3, 2017 8:16:45 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	NA	DARTHURS	May 3, 2017 8:16:45 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	May 3, 2017 8:16:45 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	May 3, 2017 8:16:45 PM	No	
201,000 - Service Crankcase Breather	-	NA	DARTHURS	May 3, 2017 8:16:45 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		DARTHURS	May 3, 2017 8:16:45 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	May 3, 2017 8:16:45 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	May 3, 2017 8:16:45 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		DARTHURS	May 3, 2017 8:16:45 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		DARTHURS	May 3, 2017 8:16:45 PM	No	
302,000 - Check Toe-In and Record Reading	-	NA	DARTHURS	May 3, 2017 8:16:45 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	NA	DARTHURS	May 3, 2017 8:16:45 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		DARTHURS	May 3, 2017 8:16:45 PM	No	
305,000 - FRA Change Differential Fluid	Yes		DARTHURS	May 3, 2017 8:16:45 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	24.04
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**24.04**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 34736858
Invoice No. 55345 - 34736858

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 72,584 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-May-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 03-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	May 3, 2017 8:17:17 PM	No	
20 - Miles			DARTHURS	May 3, 2017 8:17:17 PM	No	
30 - Kilometers			DARTHURS	May 3, 2017 8:17:17 PM	No	
40 - Hours			DARTHURS	May 3, 2017 8:17:17 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34736858 Total	
Parts:	24.04
Labor:	0.00
Labor Hours:	3.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**24.04**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34806404
Invoice No. 55345 - 34806404

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
FTLMPMI_FOLLOWUP		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	72,584 - DH

Chronology

Reported	May 3, 2017 8:14:49 PM	May 3, 2017 8:14:49 PM
Started	May 3, 2017 12:00:00 AM	
Completed	May 3, 2017 9:45:00 PM	May 3, 2017 9:45:00 PM
Down Time		

Work Order Notes

Line 10 Remove&Replace bad front center clearance Light,
Parts under shop supply Qty (1)

Activity Header

Activity: 10 034/000/000 LIGHTING SYSTEM
Activity Note: Front center clearance Light
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-May-17	Arthurs,Durvin	0.5	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34806404
Invoice No. 55345 - 34806404

Client Department:
Department: 55345M
Work Order Description
FTLMPMI_FOLLOWUP
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 72,584 - DH

Activity Header
Activity: 20 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 01 Breakdown
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-May-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 03-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	May 3, 2017 8:29:37 PM	No	
20 - Miles			DARTHURS	May 3, 2017 8:29:37 PM	No	
30 - Kilometers			DARTHURS	May 3, 2017 8:29:37 PM	No	
40 - Hours			DARTHURS	May 3, 2017 8:29:37 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34806404 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.58

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34785211
Invoice No. 55345 - 34785211

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Tires		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	71,250 - DH

Chronology		
Reported	Apr 24, 2017 3:51:51 PM	Apr 24, 2017 3:51:51 PM
Started	Apr 25, 2017 12:00:00 AM	
Completed	Apr 26, 2017 7:47:00 AM	Apr 26, 2017 7:47:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Tire issues

CAUSE:Low treads

CORRECTION:Tires replacement

Two (2) tires replaced by two old good ones

No new parts used

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 26-APR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Apr 26, 2017 7:46:37 AM	No	
20 - Miles			FSIMON	Apr 26, 2017 7:46:37 AM	No	
30 - Kilometers			FSIMON	Apr 26, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				7:46:37 AM		
40 - Hours			FSIMON	Apr 26, 2017 7:46:37 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34785211
Invoice No. 55345 - 34785211

Client Department:
Department: 55345M
Work Order Description
Tires
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 71,250 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Apr-17	Simon,Fritz	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34785211 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34748091
Invoice No. 55345 - 34748091

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Left rearTire		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	69,451 - DH

Chronology		
Reported	Apr 9, 2017 2:22:12 PM	Apr 9, 2017 2:22:12 PM
Started	Apr 9, 2017 12:00:00 AM	
Completed	Apr 9, 2017 2:30:00 PM	Apr 9, 2017 2:30:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: L/R Tire

CAUSE: Tire Worn

CORRECTION: Mount& Balance both L/R tire rotate to Front & two Front to L/R
Parts#189752Qty (2)

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Apr-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 09-APR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 9, 2017 2:23:35 PM	No	
20 - Miles			DARTHURS	Apr 9, 2017 2:23:35 PM	No	
30 - Kilometers			DARTHURS	Apr 9, 2017 2:23:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			DARTHURS	Apr 9, 2017 2:23:35 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34748091
Invoice No. 55345 - 34748091

Client Department:
Department: 55345M
Work Order Description
Left rearTire
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 69,451 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Both L/R Tire
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Apr-17	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	99.72	199.44
14-Apr-17	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	-2	102.88	-205.76
14-Apr-17	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	104.82	209.64

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Apr-17	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	203.32
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**203.32**

Work Order Footer

Work Order 34748091 Total	
Parts:	203.32
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**203.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34742241
Invoice No. 55345 - 34742241

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
W/C LIFT INSPECTION		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	69,003 - DH

Chronology		
Reported	Apr 4, 2017 9:19:49 PM	Apr 4, 2017 9:19:49 PM
Started		
Completed	Apr 5, 2017 12:52:00 PM	Apr 5, 2017 12:52:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT:

CAUSE:

CORRECTION:

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 05-APR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Apr 5, 2017 8:31:46 AM	No	
20 - Miles			HPIERRE	Apr 5, 2017 8:31:46 AM	No	
30 - Kilometers			HPIERRE	Apr 5, 2017 8:31:46 AM	No	
40 - Hours			HPIERRE	Apr 5, 2017 8:31:46 AM	No	

Activity Sub Total

	Activity 5 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34742241
Invoice No. 55345 - 34742241

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
W/C LIFT INSPECTION		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	69,003 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

15 Desc:
Task: Braun Wheelchair Lift Inspection Performed by: HPIERRE Performed on: 05-APR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Record Lift Model in Notes	Done	NCL954FIB3454HB-2	HPIERRE	Apr 5, 2017 8:37:51 AM	No	
200 - Record Serial # in Notes	Done	GA-01049	HPIERRE	Apr 5, 2017 8:37:51 AM	No	
300 - Cycle Count	3323 Cycles		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
10,000 - A - GENERAL INSPECTION	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
10,100 - Lift Battery, Circuit Breaker & Cable	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
10,200 - Lift Ground & Secondary Ground	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
10,300 - Vehicle Interlock Power	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
10,400 - Vehicle Interlock Prohits Vehicle Movement	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
10,500 - Lift Door Condition	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
10,600 - Hand Pendant Codition/Function	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
10,700 - Inspect Mounting Components	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,000 - B - CYCLE CHECK	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
20,100 - General Operation Throug Comple Cycle	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
20,200 - Main, Handrail, OB & IB Bumper Adjustments	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
20,300 - Floor Level Adjustment	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
20,400 - Platform Angle Adjustment	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
20,500 - Outer Barrier Interlock	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
20,600 - Inner Barrier Interlock	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
20,700 - Threshold Warning Interlock	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
20,800 - 50 Pound Fold Interlock	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
20,900 - Platform Lights	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
21,000 - Anti-Skid	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
21,100 - Operation & Warning Decals	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
21,200 - Back Pump Handdle Location	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
21,300 - Manual Override/Back-up System Function	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
30,000 - C - MECHANICAL COMPONENTS	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
30,100 - Base Plate, Tower, Arm & Platform Welds	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
30,200 - Outer Barrier Pins, Gas Springs & Fasteners	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
30,300 - Inner Barrier Pins, Gas Springs & Fasteners	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
30,400 - Pivot Pin Fasteners	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
30,500 - Pivot Pins & Bushing Condition	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
30,600 - Handrails	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
30,700 - Lift-Tite System	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
40,000 - D - HYDRAULIC COMPONENT CHECKS	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
40,100 - Leaks	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
40,200 - Hoses & Harness Routing/Condition (pump,parallel-vertical arms,platform)	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
40,300 - Remove Pump Cover & Check Fluid Level	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,400 - Fluid Condition	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
40,500 - LiftPump Motor Cables/Connections	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	
40,600 - Lift Pump Harnesses/Fuses/Electrical Components	Done		HPIERRE	Apr 5, 2017 8:37:51 AM	No	

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34742241 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 34609177
Invoice No. 55345 - 34609177

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	68,549 - DH

Chronology		
Reported	Mar 31, 2017 10:34:34 AM	Mar 31, 2017 10:34:34 AM
Started	Mar 31, 2017 12:00:00 AM	
Completed	Mar 31, 2017 11:58:00 PM	Mar 31, 2017 11:58:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA

CAUSE:service

CORRECTION:perform PMA service
Oil filter B329 qty 1
Engine oil 5w20 qty 7 qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Apr-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Mar-17	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 31-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Mar 31, 2017 10:58:32 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Mar 31, 2017 10:58:32 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Mar 31, 2017 10:58:32 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Mar 31, 2017 10:58:32 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Mar 31, 2017 10:58:32 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,240 - FRA Check Interior Lights	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Mar 31, 2017 10:58:32 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Mar 31, 2017 10:58:32 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Mar 31, 2017 10:58:32 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
40,420 - Check Hood	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Mar 31, 2017 10:58:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Mar 31, 2017 10:58:32 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Mar 31, 2017 10:58:32 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Mar 31, 2017 10:58:32 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Mar 31, 2017 10:58:32 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Mar 31, 2017 10:58:32 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Mar 31, 2017 10:58:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
60,631 - Tread Depth RF	7 32nds of an inch		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
60,632 - Tread Depth LF	7 32nds of an inch		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
60,633 - Tread Depth RRO	4 32nds of an inch		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
60,634 - Tread Depth RRI	5 32nds of an inch		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
60,635 - Tread Depth LRI	4 32nds of an inch		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
60,636 - Tread Depth LRO	4 32nds of an inch		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
77,133 - Brake Pad Thickness LR	12 Inch		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
77,134 - Brake Pad Thickness RR	12 Inch		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
77,137 - Brake Rotor LR	38 Inch		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
77,138 - Brake Rotor RR	38 Inch		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Mar 31, 2017 10:58:32 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Mar 31, 2017 10:58:32 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 34609177
Invoice No. 55345 - 34609177

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	68,549 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Mar-17	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 31-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Mar 31, 2017 10:59:30 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Mar 31, 2017 10:59:30 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Mar 31, 2017 10:59:30 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Mar 31, 2017 10:59:30 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Mar 31, 2017 10:59:30 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Mar 31, 2017 10:59:30 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Mar 31, 2017 10:59:30 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Mar 31, 2017 10:59:30 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	1.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 34609177
Invoice No. 55345 - 34609177

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DCARTER
Created By: DCARTER
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 68,549 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Mar-17	Gaspard,Ronald	0.1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 31-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Mar 31, 2017 11:00:46 PM	No	
20 - Miles			RGASPARD	Mar 31, 2017 11:00:46 PM	No	
30 - Kilometers			RGASPARD	Mar 31, 2017 11:00:46 PM	No	
40 - Hours			RGASPARD	Mar 31, 2017 11:00:46 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34609177 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.60

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34730776
Invoice No. 55345 - 34730776

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Driver's side mirror arm		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	68,048 - DH

Chronology		
Reported	Mar 28, 2017 1:51:23 PM	Mar 28, 2017 1:51:23 PM
Started	Mar 28, 2017 12:00:00 AM	
Completed	Mar 28, 2017 2:02:00 PM	Mar 28, 2017 2:02:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Loose driver's side mirror

CAUSE:Normal wear

CORRECTION:Driver's side mirror replacement

Driver's side mirror replaced by an updated one

Part used:
One driver's side updated mirror (under warranty).

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 28-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Mar 28, 2017 1:55:33 PM	No	
20 - Miles			FSIMON	Mar 28, 2017 1:55:33 PM	No	
30 - Kilometers			FSIMON	Mar 28, 2017 1:55:33 PM	No	
40 - Hours			FSIMON	Mar 28, 2017 1:55:33 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34730776
Invoice No. 55345 - 34730776

Client Department:
Department: 55345M
Work Order Description
Driver's side mirror arm
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 68,048 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Mar-17	Simon,Fritz	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34730776 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34628366
Invoice No. 55345 - 34628366

Client Department:
Department: 55345M
Work Order Description
REAR AC NOT COOLING PROPERLY
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 64,706 - DH

Chronology		
Reported	Feb 27, 2017 1:52:00 PM	Feb 27, 2017 1:52:00 PM
Started		
Completed	Feb 27, 2017 2:23:00 PM	Feb 27, 2017 2:23:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: REAR AC NOT COOLING PROPERLY

CAUSE:SISTEM LEAK

CORRECTION: UNIT WAS SENT TO ATLANTIC BUS SALES,THE FOLLOWING REPAIRS WAS PERFORMED PER INVOICE

#16286.

CHECK FREON LEAK AT CONDENSOR ,NOT LEAK FOUND,LEAK WAS FOUND AT DRIER & REPLACED WITH NEW STYLE.

EVACUATE & RECHARGE SISTEM.

UNIT RETURNED TO SERVICE

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	
30 - Kilometers					No	
40 - Hours					No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34628366
Invoice No. 55345 - 34628366

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
REAR AC NOT COOLING PROPERLY		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	64,706 - DH

Activity Header
Activity: 15 001/001/000 AIR CONDITIONING
Activity Note: REAR AC NOT COOLING PROPERLY
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34628366 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 34609135
Invoice No. 55345 - 34609135

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
ReaR brakes FTLMPMI_FOLLOWUP		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	64,471 - DH

Chronology		
Reported	Feb 22, 2017 2:13:26 PM	Feb 22, 2017 2:13:26 PM
Started	Feb 22, 2017 12:00:00 AM	
Completed	Feb 23, 2017 3:52:38 PM	Feb 23, 2017 3:52:38 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT:worn Rear brake pads

CAUSE:Normal wear

CORRECTION:Rear brake pads replacement

Rear brake pads found out of specs
Rear brake pads replaced

Parts used:
One (1) brake pads#BRSD1330 Line 20 REAR AC LEAK DETECTED ,UNIT WAS SENT TO ATLANTIC BUS SALES FOR UNDER WARRANTY AC REPAIRS.

F/SUPPRESSION SISTEM LEAK DETECTED DURING INSPECTION, ISSUE REPORTED TO KAREN
(CREATIVE BUS SALES WARRANTY REPRESENTATIVE) FOG MAKER TECHNICIAN CONTACTED.

Activity Header
Activity:10 013/002 REAR BRAKES & DRUMS
Activity Note: 3mm
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
10 Desc: 3mm Task: PRA and Meter Readings Performed by: FSIMON Performed on: 22-FEB-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Feb 22, 2017 3:14:23 PM	No	
20 - Miles			FSIMON	Feb 22, 2017 3:14:23 PM	No	
30 - Kilometers			FSIMON	Feb 22, 2017 3:14:23 PM	No	
40 - Hours			FSIMON	Feb 22, 2017 3:14:23 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 34609135
Invoice No. 55345 - 34609135

Client Department:
Department: 55345M
Work Order Description
ReaR brakes FTLMPMI_FOLLOWUP
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 64,471 - DH

Activity Header
Activity: 20
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Feb-17	BRSD-1330	PADS, BRAKE, DISC, REAR, FORD SAME AS PFH133020	1	43.15	43.15

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Feb-17	Simon,Fritz	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	43.15
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.15**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 34609135
Invoice No. 55345 - 34609135

Client Department:
Department: 55345M
Work Order Description
ReaR brakes FTLMPMI_FOLLOWUP
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 64,471 - DH

Activity Header
Activity: 30 001/001/000 AIR CONDITIONING
Activity Note: REAR AC LEAK DETECTED.
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 34609135
Invoice No. 55345 - 34609135

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
ReaR brakes FTLMPMI_FOLLOWUP		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	64,471 - DH

Activity Header
Activity: 40 050/000 GROUP, ACCESSORIES
Activity Note: F/SUPPRESSION SISTEM LEAK DETECTED UNDER PM INSPECTION.
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34609135 Total	
Parts:	43.15
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.15**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 32991037
Invoice No. 55345 - 32991037

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	64,471 - DH

Chronology		
Reported	Feb 22, 2017 7:05:53 AM	Feb 22, 2017 7:05:53 AM
Started	Feb 22, 2017 12:00:00 AM	
Completed	Feb 22, 2017 2:44:07 PM	Feb 22, 2017 2:44:07 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA

CAUSE:PMA due

CORRECTION:PMA completion

PMA performed
Engine oil filter changed
Engine oil changed
Grease fittings lubricated

NB:Fire suppression leaking
Rear A/C lines leaking

Parts used:
One (1) oil filter #B329
Six(6) quarts of oil 5w20

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Feb-17	Simon,Fritz	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
10 Desc: Light Medium Duty PMI Task: First Transit Light-Medium Duty PMI Performed by: FSIMON Performed on: 22-FEB-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
10,100 - Safety Inspection	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
10,140 - Check Service Brakes	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
10,160 - FRA Check Instruments and Horns	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
10,170 - Check Fast Idle	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
10,180 - Check Starter Protection Circuit	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
10,190 - Check Reverse Warning System	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
11,100 - Check Parking Brake	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
11,150 - Perform Brake Test	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	FSIMON	Feb 22, 2017 2:13:26 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	FSIMON	Feb 22, 2017 2:13:26 PM	No	
11,170 - FRA Check Door Operation	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
20,210 - Check Condition of Operator's Area	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
20,240 - FRA Check Interior Lights	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,250 - FRA Check Interior Electrical Panels	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
20,260 - Check Stop Request System	-	NA	FSIMON	Feb 22, 2017 2:13:26 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	FSIMON	Feb 22, 2017 2:13:26 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
22,110 - Check Emergency Hatches	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
22,120 - Check All Safety Equipment	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
30,310 - Check Passenger Doors	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	FSIMON	Feb 22, 2017 2:13:26 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
30,360 - Check for Physical Damage and Decals	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
30,380 - Check Exterior Compartment Doors	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
33,100 - Check Lights and Reflectors	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
40,420 - Check Hood	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	FSIMON	Feb 22, 2017 2:13:26 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	FSIMON	Feb 22, 2017 2:13:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,442 - Freeze Point	Degree Fahrenheit	NA	FSIMON	Feb 22, 2017 2:13:26 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	FSIMON	Feb 22, 2017 2:13:26 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	FSIMON	Feb 22, 2017 2:13:26 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
44,130 - FRA Check Exhaust System	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
44,140 - FRA Check Intake System	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	FSIMON	Feb 22, 2017 2:13:26 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
44,180 - FRA Check for Leaks	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
44,190 - FRA Perform Battery Inspection	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
50,510 - Check Entire Steering System	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		FSIMON	Feb 22, 2017 2:13:26 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		FSIMON	Feb 22, 2017 2:13:26 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		FSIMON	Feb 22, 2017 2:13:26 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		FSIMON	Feb 22, 2017 2:13:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,615 - Air Pressure LRI	65 Pounds per Square Inch		FSIMON	Feb 22, 2017 2:13:26 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		FSIMON	Feb 22, 2017 2:13:26 PM	No	
60,620 - Check Valve Stems and Caps	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
60,630 - Check and Record Tread Depth	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
60,631 - Tread Depth RF	99 32nds of an inch		FSIMON	Feb 22, 2017 2:13:26 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch		FSIMON	Feb 22, 2017 2:13:26 PM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		FSIMON	Feb 22, 2017 2:13:26 PM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		FSIMON	Feb 22, 2017 2:13:26 PM	No	
60,635 - Tread Depth LRI	5 32nds of an inch		FSIMON	Feb 22, 2017 2:13:26 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		FSIMON	Feb 22, 2017 2:13:26 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
60,650 - Check Sidewall Wear	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
60,660 - Inspect for Cuts and Tears	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
60,670 - Check Dual Mating With Square	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
70,710 - Check Vibration Damper	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
70,730 - FRA Check Starter	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
70,770 - FRA Check Exhaust System	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,790 - Check All Body Mounts and Chassis Frame	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
77,110 - FRA Check Fuel Tank	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
77,120 - Check Suspension Components	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
77,131 - Brake Pad Thickness LF	Inch	10mm	FSIMON	Feb 22, 2017 2:13:26 PM	No	
77,132 - Brake Pad Thickness RF	Inch	10mm	FSIMON	Feb 22, 2017 2:13:26 PM	No	
77,133 - Brake Pad Thickness LR	Inch	3mm	FSIMON	Feb 22, 2017 2:13:26 PM	Yes	34609135
77,134 - Brake Pad Thickness RR	Inch	4mm	FSIMON	Feb 22, 2017 2:13:26 PM	No	
77,135 - Brake Rotor LF	Inch	40mm	FSIMON	Feb 22, 2017 2:13:26 PM	No	
77,136 - Brake Rotor RF	Inch	40mm	FSIMON	Feb 22, 2017 2:13:26 PM	No	
77,137 - Brake Rotor LR	Inch	40mm	FSIMON	Feb 22, 2017 2:13:26 PM	No	
77,138 - Brake Rotor RR	Inch	40mm	FSIMON	Feb 22, 2017 2:13:26 PM	No	
77,140 - FRA Check Brake Hoses	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
77,150 - Check King Pins	-	NA	FSIMON	Feb 22, 2017 2:13:26 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
80,810 - Completion of PMI Report	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		FSIMON	Feb 22, 2017 2:13:26 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 32991037
Invoice No. 55345 - 32991037

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 64,471 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Feb-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Feb-17	Simon,Fritz	0.25	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: FSIMON Performed on: 22-FEB-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		FSIMON	Feb 22, 2017 1:39:50 PM	No	
101,000 - FRA Change Oil Filters	Yes		FSIMON	Feb 22, 2017 1:39:50 PM	No	
102,000 - FRA Drain Engine Oil	Yes		FSIMON	Feb 22, 2017 1:39:50 PM	No	
103,000 - FRA Check Transmission Fluid	Done		FSIMON	Feb 22, 2017 1:39:50 PM	No	
104,000 - Lubricate Chassis	Done		FSIMON	Feb 22, 2017 1:39:50 PM	No	
105,000 - Replace or Clean A/C Filters	Done		FSIMON	Feb 22, 2017 1:39:50 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	FSIMON	Feb 22, 2017 1:39:50 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		FSIMON	Feb 22, 2017 1:39:50 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	3.84
	Labor:	0.00
	Labor Hours:	0.50
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**3.84**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 32991037
Invoice No. 55345 - 32991037

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 64,471 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	
30 - Kilometers					No	
40 - Hours					No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 32991037 Total	
Parts:	3.84
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**3.84**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 29319222
Invoice No. 55345 - 29319222

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM B		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	60,424 - DH

Chronology		
Reported	Jan 19, 2017 1:52:54 PM	Jan 19, 2017 1:52:54 PM
Started	Jan 19, 2017 12:00:00 AM	
Completed	Jan 20, 2017 12:12:00 AM	Jan 20, 2017 12:12:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMB Service

CAUSE: Service due by Mileage

CORRECTION: Change Oil& Filter Lube all Pivoting Points clean A/C Filter Clean Batteries Check Brakes all is ok a this time replace lift arm stop rubber
Lift stop rubber Qty (1) Shop Supply
Parts# B329 Qty (1)
Oil 5w20 Qty (7) Qt

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Jan-17	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 19-JAN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Jan 19, 2017 9:58:42 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Jan 19, 2017 9:58:42 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
20,260 - Check Stop Request System	-	NA	DARTHURS	Jan 19, 2017 9:58:42 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Jan 19, 2017 9:58:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
30,330 - Check Wheelchair Lift Operation	Done	replace lift arm stop rubber	DARTHURS	Jan 19, 2017 9:58:42 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Jan 19, 2017 9:58:42 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
40,420 - Check Hood	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Jan 19, 2017 9:58:42 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Jan 19, 2017 9:58:42 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Jan 19, 2017 9:58:42 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Jan 19, 2017 9:58:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Jan 19, 2017 9:58:42 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Jan 19, 2017 9:58:42 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
60,611 - Air Pressure RF	75 Pounds per Square Inch		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
60,612 - Air Pressure LF	75 Pounds per Square Inch		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,630 - Check and Record Tread Depth	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
60,631 - Tread Depth RF	7 32nds of an inch		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
60,633 - Tread Depth RRO	3 32nds of an inch		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
60,634 - Tread Depth RRI	3 32nds of an inch	both R/R tire	DARTHURS	Jan 19, 2017 9:58:42 PM	Yes	32989612
60,635 - Tread Depth LRI	6 32nds of an inch		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
60,636 - Tread Depth LRO	5 32nds of an inch		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Jan 19, 2017 9:58:42 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,120 - Check Suspension Components	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
77,131 - Brake Pad Thickness LF	11 Inch		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
77,132 - Brake Pad Thickness RF	11 Inch		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
77,135 - Brake Rotor LF	1.576 Inch		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
77,136 - Brake Rotor RF	1.574 Inch		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
77,137 - Brake Rotor LR	1.624 Inch		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
77,138 - Brake Rotor RR	1.632 Inch		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Jan 19, 2017 9:58:42 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Jan 19, 2017 9:58:42 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 29319222
Invoice No. 55345 - 29319222

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 60,424 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Jan-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Jan-17	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: DARTHURS Performed on: 19-JAN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Jan 19, 2017 9:59:59 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Jan 19, 2017 9:59:59 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Jan 19, 2017 9:59:59 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Jan 19, 2017 9:59:59 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Jan 19, 2017 9:59:59 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Jan 19, 2017 9:59:59 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Jan 19, 2017 9:59:59 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Jan 19, 2017 9:59:59 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	Jan 19, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:59:59 PM		
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Jan 19, 2017 9:59:59 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		DARTHURS	Jan 19, 2017 9:59:59 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Jan 19, 2017 9:59:59 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Jan 19, 2017 9:59:59 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 29319222
Invoice No. 55345 - 29319222

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 60,424 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Jan-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 19-JAN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jan 19, 2017 10:00:25 PM	No	
20 - Miles			DARTHURS	Jan 19, 2017 10:00:25 PM	No	
30 - Kilometers			DARTHURS	Jan 19, 2017 10:00:25 PM	No	
40 - Hours			DARTHURS	Jan 19, 2017 10:00:25 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 29319222 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 32989612
Invoice No. 55345 - 32989612

Client Department:
Department: 55345M
Work Order Description
PMB Follow up>>>>>>>Rear Tire
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 60,424 - DH

Chronology

Reported	Jan 19, 2017 9:58:42 PM	Jan 19, 2017 9:58:42 PM
Started	Jan 19, 2017 12:00:00 AM	
Completed	Jan 20, 2017 12:11:00 AM	Jan 20, 2017 12:11:00 AM
Down Time		

Work Order Notes

Line 10 Mount&Balance Both R/R Tire Rotate both front tire to R/R & both New tire to Front,
Parts# 050017 Qty(2) kenda

Activity Header
Activity: 10 017 TIRES, TUBES, LINERS & VALVES
Activity Note: both R/R tire
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Jan-17	050017	OUT OF SERVICE TIRE, LT225/75R16, KRO5, KENDA	2	82.26	164.52

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Jan-17	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	164.52
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**164.52**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 32989612
Invoice No. 55345 - 32989612

Client Department:
Department: 55345M
Work Order Description
PMB Follow up>>>>>>>Rear Tire
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 60,424 - DH

Activity Header
Activity: 20 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 01 Breakdown
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Jan-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 19-JAN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jan 19, 2017 10:10:58 PM	No	
20 - Miles			DARTHURS	Jan 19, 2017 10:10:58 PM	No	
30 - Kilometers			DARTHURS	Jan 19, 2017 10:10:58 PM	No	
40 - Hours			DARTHURS	Jan 19, 2017 10:10:58 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 32989612 Total	
Parts:	164.52
Labor:	0.00
Labor Hours:	1.08

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**164.52**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 32913975
Invoice No. 55345 - 32913975

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Tires		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	59,179 - DH

Chronology		
Reported	Jan 10, 2017 3:09:46 PM	Jan 10, 2017 3:09:46 PM
Started	Jan 10, 2017 12:00:00 AM	
Completed	Jan 11, 2017 8:22:00 AM	Jan 11, 2017 8:22:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Flat tire

CAUSE:Tire punctured

CORRECTION:Tire replacement

Tire replaced by a good old one
Lugs nuts tightened 140ft/lb

No part used

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 10-JAN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Jan 10, 2017 3:35:31 PM	No	
20 - Miles			FSIMON	Jan 10, 2017 3:35:31 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30 - Kilometers			FSIMON	Jan 10, 2017 3:35:31 PM	No	
40 - Hours			FSIMON	Jan 10, 2017 3:35:31 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 32913975
Invoice No. 55345 - 32913975

Client Department:
Department: 55345M
Work Order Description
Tires
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 59,179 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Jan-17	Simon,Fritz	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 32913975 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 32106238
Invoice No. 55345 - 32106238

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Check rear Tires		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	58,317 - DH

Chronology		
Reported	Dec 30, 2016 1:48:02 PM	Dec 30, 2016 1:48:02 PM
Started	Dec 30, 2016 12:00:00 AM	
Completed	Jan 2, 2017 8:06:18 AM	Jan 2, 2017 8:06:18 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Flat tire

CAUSE:Tire punctured

CORRECTION:Tire replacement
Complaint identified
Outer right tire found flat
Tire replaced by a good (old)one.

No part to be charged

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 30-DEC-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Dec 30, 2016 3:16:51 PM	No	
20 - Miles			FSIMON	Dec 30, 2016 3:16:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30 - Kilometers			FSIMON	Dec 30, 2016 3:16:51 PM	No	
40 - Hours			FSIMON	Dec 30, 2016 3:16:51 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 32106238
Invoice No. 55345 - 32106238

Client Department:
Department: 55345M
Work Order Description
Check rear Tires
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 58,317 - DH

Activity Header
Activity: 15
Activity Note: Tire
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Dec-16	Simon,Fritz	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 32106238 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 30824350
Invoice No. 55345 - 30824350

Client Department:
Department: 55345M
Work Order Description
Manufacturer recommended transmission service by mileage
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 57,498 - DH

Chronology		
Reported	Dec 20, 2016 11:03:09 AM	Dec 20, 2016 11:03:09 AM
Started	Dec 20, 2016 12:00:00 AM	
Completed	Dec 20, 2016 1:00:15 PM	Dec 20, 2016 1:00:15 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT:
Manufacturer recommended transmission service by mileage

CAUSE:
Normal wear

CORRECTION:
Removed and replaced transmission fluid and filter

Part: 1 transmission filter # 8c3z-7a098-d

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 20-DEC-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Dec 20, 2016 11:22:41 AM	No	
20 - Miles			RAURODRIGUEZ	Dec 20, 2016 11:22:41 AM	No	
30 - Kilometers			RAURODRIGUEZ	Dec 20, 2016 11:22:41 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			RAURODRIGUEZ	Dec 20, 2016 11:22:41 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 30824350
Invoice No. 55345 - 30824350

Client Department:
Department: 55345M
Work Order Description
Manufacturer recommended transmission service by mileage
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 57,498 - DH

Activity Header
Activity: 15 027 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: Manufacturer recommended transmission service by mileage
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Dec-16	8C3Z-7A098-D	FILTER, TRANSMISSION	1	42.31	42.31

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Dec-16	Rodriguez,Raul	1.45	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	42.31
Labor:	0.00
Labor Hours:	1.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**42.31**

Work Order Footer

Work Order 30824350 Total	
Parts:	42.31
Labor:	0.00
Labor Hours:	1.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**42.31**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 29308892
Invoice No. 55345 - 29308892

Client Department:

Department: 55345M

Work Order Description
FOLLOWUP---------->Replace front pads Repack bearings grease

Requested By: LCAPAZZOLI
Created By: LCAPAZZOLI
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 56,203 - DH

Chronology		
Reported	Dec 5, 2016 2:21:08 PM	Dec 5, 2016 2:21:08 PM
Started	Dec 5, 2016 12:00:00 AM	
Completed	Dec 5, 2016 4:51:00 PM	Dec 5, 2016 4:51:00 PM
Down Time		

Work Order Notes

Line 10 Replace front brake pads. And inner seals

Parts used. 1 set front pads. Brsd1328. And inner seals. 2 qty. cr2400

Activity Header
Activity: 10 013/001 BRAKES & DRUMS, FRONT
Activity Note: 4mm. Needs front brakes
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Dec-16	BRSD-1328	PADS, BRAKE, DISC, FRONT	1	50.32	50.32
05-Dec-16	CR24000	SEAL, WHEEL, HUB, FRONT	2	7.53	15.06

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Dec-16	Capazzoli,Louis	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	65.38
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**65.38**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 29308892
Invoice No. 55345 - 29308892

Client Department:

Department: 55345M

Work Order Description
FOLLOWUP---------->Replace front pads Repack bearings grease

Requested By: LCAPAZZOLI
Created By: LCAPAZZOLI
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 56,203 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 05-DEC-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Dec 5, 2016 2:47:41 PM	No	
20 - Miles			LCAPAZZOLI	Dec 5, 2016 2:47:41 PM	No	
30 - Kilometers			LCAPAZZOLI	Dec 5, 2016 2:47:41 PM	No	
40 - Hours			LCAPAZZOLI	Dec 5, 2016 2:47:41 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 29308892 Total	
Parts:	65.38
Labor:	0.00
Labor Hours:	2.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**65.38**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27733654
Invoice No. 55345 - 27733654

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 56,203 - DH

Chronology		
Reported	Dec 5, 2016 11:57:17 AM	Dec 5, 2016 11:57:17 AM
Started	Dec 5, 2016 12:00:00 AM	
Completed	Dec 5, 2016 4:50:00 PM	Dec 5, 2016 4:50:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pm-A inspection due

CAUSE: mileage

CORRECTION: Completed pm-A inspection. Replace oil and oil filter replace air filter Line 20 Parts used 5w-20. 6 quarts. 1 oil filter br329. 1 air filter. Pa 4075

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Dec-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92
05-Dec-16	PA4075	OUT OF SERVICE DO NOT ORDER FILTER, AIR, PAPER SAME AS AF25590	1	5.18	5.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Dec-16	Capazzoli,Louis	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: LCAPAZZOLI Performed on: 05-DEC-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive	Done		LCAPAZZOLI	Dec 5, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
On (In Lot) Inspection				2:21:08 PM		
10,100 - Safety Inspection	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
10,140 - Check Service Brakes	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
10,160 - FRA Check Instruments and Horns	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
10,170 - Check Fast Idle	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
10,180 - Check Starter Protection Circuit	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
10,190 - Check Reverse Warning System	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
11,100 - Check Parking Brake	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
11,150 - Perform Brake Test	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
11,170 - FRA Check Door Operation	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
20,210 - Check Condition of Operator's Area	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
20,240 - FRA Check Interior Lights	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
20,250 - FRA Check Interior Electrical	Done		LCAPAZZOLI	Dec 5, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Panels				2:21:08 PM		
20,260 - Check Stop Request System	-	n/a	LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
22,110 - Check Emergency Hatches	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
22,120 - Check All Safety Equipment	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
30,310 - Check Passenger Doors	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
30,360 - Check for Physical Damage and Decals	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
30,380 - Check Exterior Compartment Doors	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
33,100 - Check Lights and Reflectors	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
40,420 - Check Hood	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
40,442 - Freeze Point	Degree	n/a	LCAPAZZOLI	Dec 5, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			2:21:08 PM		
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
44,130 - FRA Check Exhaust System	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
44,140 - FRA Check Intake System	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
44,180 - FRA Check for Leaks	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
44,190 - FRA Perform Battery Inspection	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
50,510 - Check Entire Steering System	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
60,615 - Air Pressure LRI	70 Pounds per		LCAPAZZOLI	Dec 5, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			2:21:08 PM		
60,616 - Air Pressure LRO	70 Pounds per Square Inch		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
60,620 - Check Valve Stems and Caps	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
60,630 - Check and Record Tread Depth	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
60,631 - Tread Depth RF	12 32nds of an inch		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
60,634 - Tread Depth RRI	4 32nds of an inch		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
60,635 - Tread Depth LRI	4 32nds of an inch		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
60,650 - Check Sidewall Wear	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
60,660 - Inspect for Cuts and Tears	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
70,710 - Check Vibration Damper	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
70,730 - FRA Check Starter	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
70,770 - FRA Check Exhaust System	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
70,790 - Check All Body Mounts and	Done		LCAPAZZOLI	Dec 5, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Chassis Frame				2:21:08 PM		
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
77,110 - FRA Check Fuel Tank	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
77,120 - Check Suspension Components	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
77,131 - Brake Pad Thickness LF	Inch	4mm. Needs front brakes	LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	Yes	29308892
77,132 - Brake Pad Thickness RF	Inch	4 mm	LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
77,133 - Brake Pad Thickness LR	Inch	9 mm	LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
77,134 - Brake Pad Thickness RR	Inch	9 mm	LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
77,135 - Brake Rotor LF	Inch	40	LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
77,136 - Brake Rotor RF	Inch	40	LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
77,137 - Brake Rotor LR	Inch	40	LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
77,138 - Brake Rotor RR	Inch	40	LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
77,140 - FRA Check Brake Hoses	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
77,150 - Check King Pins	-	n/a	LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
80,810 - Completion of PMI Report	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		LCAPAZZOLI	Dec 5, 2016 2:21:08 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27733654
Invoice No. 55345 - 27733654

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 56,203 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Dec-16	Capazzoli,Louis	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: LCAPAZZOLI Performed on: 05-DEC-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		LCAPAZZOLI	Dec 5, 2016 2:21:41 PM	No	
101,000 - FRA Change Oil Filters	Yes		LCAPAZZOLI	Dec 5, 2016 2:21:41 PM	No	
102,000 - FRA Drain Engine Oil	Yes		LCAPAZZOLI	Dec 5, 2016 2:21:41 PM	No	
103,000 - FRA Check Transmission Fluid	Done		LCAPAZZOLI	Dec 5, 2016 2:21:41 PM	No	
104,000 - Lubricate Chassis	Done		LCAPAZZOLI	Dec 5, 2016 2:21:41 PM	No	
105,000 - Replace or Clean A/C Filters	Done		LCAPAZZOLI	Dec 5, 2016 2:21:41 PM	No	
107,000 - FRA Change Primary Fuel Filter	No		LCAPAZZOLI	Dec 5, 2016 2:21:41 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		LCAPAZZOLI	Dec 5, 2016 2:21:41 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.50
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27733654
Invoice No. 55345 - 27733654

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	56,203 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Dec-16	Capazzoli,Louis	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 05-DEC-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Dec 5, 2016 2:21:58 PM	No	
20 - Miles			LCAPAZZOLI	Dec 5, 2016 2:21:58 PM	No	
30 - Kilometers			LCAPAZZOLI	Dec 5, 2016 2:21:58 PM	No	
40 - Hours			LCAPAZZOLI	Dec 5, 2016 2:21:58 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27733654 Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	2.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**7.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27411628
Invoice No. 55345 - 27411628

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	52,134 - DH

Chronology		
Reported	Oct 18, 2016 2:14:41 PM	Oct 18, 2016 2:14:41 PM
Started	Oct 18, 2016 12:00:00 AM	
Completed	Oct 19, 2016 12:29:00 AM	Oct 19, 2016 12:29:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:service

CORRECTION:perform pmA service
Oil filter B329 qty 1
Engine oil 5w20 qty 7qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Oct-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Oct-16	Gaspard,Ronald	1.5166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 18-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Oct 18, 2016 11:12:15 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Oct 18, 2016 11:12:15 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Oct 18, 2016 11:12:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Oct 18, 2016 11:12:15 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Oct 18, 2016 11:12:15 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
40,420 - Check Hood	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Oct 18, 2016 11:12:15 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Oct 18, 2016 11:12:15 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Oct 18, 2016 11:12:15 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Oct 18, 2016 11:12:15 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Oct 18, 2016 11:12:15 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Oct 18, 2016 11:12:15 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	Oct 18, 2016 11:12:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
60,631 - Tread Depth RF	3 32nds of an inch	needs front tires	RGASPARD	Oct 18, 2016 11:12:15 PM	Yes	27733461
60,632 - Tread Depth LF	4 32nds of an inch		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
77,137 - Brake Rotor LR	38 Inch		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
77,138 - Brake Rotor RR	38 Inch		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Oct 18, 2016 11:12:15 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Oct 18, 2016 11:12:15 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27733461
Invoice No. 55345 - 27733461

Client Department:
Department: 55345M
Work Order Description
Followup----------> needs 2 front tires
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 52,134 - DH

Chronology		
Reported	Oct 18, 2016 11:12:15 PM	Oct 18, 2016 11:12:15 PM
Started	Oct 18, 2016 12:00:00 AM	
Completed	Oct 19, 2016 12:29:00 AM	Oct 19, 2016 12:29:00 AM
Down Time		

Work Order Notes

Line 10 Needs 2 front tires
Low tread
Replaced front tires mounted balanced.
Torque tires 140 lbs second torque 140 lbs
Part number 050017 qty 2

Activity Header
Activity: 10 017 TIRES, TUBES, LINERS & VALVES
Activity Note: needs front tires
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Oct-16	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27411628
Invoice No. 55345 - 27411628

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	52,134 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Oct-16	Gaspard,Ronald	1.1333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 18-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Oct 18, 2016 11:12:54 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Oct 18, 2016 11:12:54 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Oct 18, 2016 11:12:54 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Oct 18, 2016 11:12:54 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Oct 18, 2016 11:12:54 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Oct 18, 2016 11:12:54 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Oct 18, 2016 11:12:54 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Oct 18, 2016 11:12:54 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	1.13
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27733461
Invoice No. 55345 - 27733461

Client Department:
Department: 55345M
Work Order Description
Followup----------> needs 2 front tires
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 52,134 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: Needs 2 front tire
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Oct-16	050017	OUT OF SERVICE TIRE, LT225/75R16, KRO5, KENDA	2	81.5	163

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Oct-16	Gaspard,Ronald	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Needs 2 front tire
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 18-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Oct 18, 2016 11:38:47 PM	No	
20 - Miles			RGASPARD	Oct 18, 2016 11:38:47 PM	No	
30 - Kilometers			RGASPARD	Oct 18, 2016 11:38:47 PM	No	
40 - Hours			RGASPARD	Oct 18, 2016 11:38:47 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	163.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**163.00**

Work Order Footer

Work Order 27733461 Total	
Parts:	163.00

	Labor:	0.00
	Labor Hours:	1.05
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**163.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27411628
Invoice No. 55345 - 27411628

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	52,134 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Oct-16	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 18-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Oct 18, 2016 11:13:16 PM	No	
20 - Miles			RGASPARD	Oct 18, 2016 11:13:16 PM	No	
30 - Kilometers			RGASPARD	Oct 18, 2016 11:13:16 PM	No	
40 - Hours			RGASPARD	Oct 18, 2016 11:13:16 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27411628 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.72

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27571698
Invoice No. 55345 - 27571698

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Check fuel gauge		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	50,867 - DH

Chronology		
Reported	Oct 7, 2016 5:35:20 PM	Oct 7, 2016 5:35:20 PM
Started	Oct 10, 2016 12:00:00 AM	
Completed	Oct 14, 2016 9:39:00 AM	Oct 14, 2016 9:39:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Fuel gauge reading full all the time

CAUSE:FLIM suspected defective

CORRECTION:Replace FLIM and fuel sender unit

Complaint verified
Flim and Fuel sender unit replaced

Parts used
One (1) FLIM (under warranty)
One (1) Fuel sender Unit (under warranty)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 14-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Oct 14, 2016 9:34:08 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			FSIMON	Oct 14, 2016 9:34:08 AM	No	
30 - Kilometers			FSIMON	Oct 14, 2016 9:34:08 AM	No	
40 - Hours			FSIMON	Oct 14, 2016 9:34:08 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27571698
Invoice No. 55345 - 27571698

Client Department:
Department: 55345M
Work Order Description
Check fuel gauge
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 50,867 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Oct-16	Simon,Fritz	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27571698 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27513651
Invoice No. 55345 - 27513651

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
External fuel filter replacement		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	50,753 - DH

Chronology		
Reported	Oct 3, 2016 3:18:12 PM	Oct 3, 2016 3:18:12 PM
Started	Oct 3, 2016 12:00:00 AM	
Completed	Oct 4, 2016 2:10:00 PM	Oct 4, 2016 2:10:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT:External filter (service)

CAUSE:Preventive maintenance

CORRECTION:External filter replacement

External fuel filter replaced

Part used
One (1) fuel filter p11bb-9155-ab

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 03-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Oct 3, 2016 3:32:51 PM	No	
20 - Miles			FSIMON	Oct 3, 2016 3:32:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30 - Kilometers			FSIMON	Oct 3, 2016 3:32:51 PM	No	
40 - Hours			FSIMON	Oct 3, 2016 3:32:51 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27513651
Invoice No. 55345 - 27513651

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
External fuel filter replacement		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	50,753 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Oct-16	P11BB-9155-AB	FILTER, FUEL, ROUSH NO CROSS	1	78.94	78.94

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Oct-16	Simon,Fritz	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	78.94
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**78.94**

Work Order Footer

Work Order 27513651 Total	
Parts:	78.94
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**78.94**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27460351
Invoice No. 55345 - 27460351

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Steering Box		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	49,982 - DH

Chronology		
Reported	Sep 23, 2016 5:31:33 PM	Sep 23, 2016 5:31:33 PM
Started	Sep 23, 2016 12:00:00 AM	
Completed	Sep 23, 2016 5:50:00 PM	Sep 23, 2016 5:50:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: Steering box

CAUSE: Steering box Leaking

CORRECTION: Remove& Replace Steering box
Parts#AC2Z3504A Qty (1)

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Sep-16	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 23-SEP-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Sep 23, 2016 5:33:30 PM	No	
20 - Miles			DARTHURS	Sep 23, 2016 5:33:30 PM	No	
30 - Kilometers			DARTHURS	Sep 23, 2016 5:33:30 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			DARTHURS	Sep 23, 2016 5:33:30 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27460351
Invoice No. 55345 - 27460351

Client Department:
Department: 55345M
Work Order Description
Steering Box
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 49,982 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Steering box Leaking
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Mar-17	AC2Z-3504-A-COR	CORE, BOX, GEAR, STEERING, E450 REPLACED BY GU2Z-3504-A	-2	225	-450
17-Jul-17	AC2Z-3504-A-COR	CORE, BOX, GEAR, STEERING, E450 REPLACED BY GU2Z-3504-A	-6	225	-1,350
06-Feb-17	AC2Z-3504-A-COR	CORE, BOX, GEAR, STEERING, E450 REPLACED BY GU2Z-3504-A	-1	225	-225
26-Sep-16	AC2Z-3504-A	BOX, GEAR, STEERING, E450, '08-'10 REPLACED BY GU2Z-3504-A	1	469.28	469.28
23-Mar-17	AC2Z-3504-A-COR	CORE, BOX, GEAR, STEERING, E450 REPLACED BY GU2Z-3504-A	8	225	1,800
26-Sep-16	AC2Z-3504-A-COR	CORE, BOX, GEAR, STEERING, E450 REPLACED BY GU2Z-3504-A	1	225	225

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Sep-16	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	469.28
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**469.28**

Work Order Footer

Work Order 27460351 Total	
Parts:	469.28

	Labor:	0.00
	Labor Hours:	1.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**469.28**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27205560
Invoice No. 55345 - 27205560

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: DCARTER
Created By: DCARTER
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 47,869 - DH

Chronology		
Reported	Aug 29, 2016 2:02:50 PM	Aug 29, 2016 2:02:50 PM
Started	Aug 29, 2016 12:00:00 AM	
Completed	Aug 30, 2016 11:44:00 AM	Aug 30, 2016 11:44:00 AM
Down Time		

Work Order Notes

Line 10 Complaint. Pm-c inspection due.

Cause. Miles

Correction. Completed pm-C inspection. Replace oil and oil filter. Service crankcase breather. Clear all codes.

Parts used. 5 W-20 6 quarts oil 1 oil filter B-329

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Aug-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Aug-16	Capazzoli,Louis	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: LCAPAZZOLI Performed on: 29-AUG-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
10,100 - Safety Inspection	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
10,140 - Check Service Brakes	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
10,160 - FRA Check Instruments and Horns	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
10,170 - Check Fast Idle	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
10,180 - Check Starter Protection Circuit	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
10,190 - Check Reverse Warning System	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
11,100 - Check Parking Brake	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
11,150 - Perform Brake Test	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
11,170 - FRA Check Door Operation	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
20,210 - Check Condition of Operator's Area	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
20,240 - FRA Check Interior Lights	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
20,260 - Check Stop Request System	-	n/a	LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
22,110 - Check Emergency Hatches	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
22,120 - Check All Safety Equipment	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
30,310 - Check Passenger Doors	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
30,360 - Check for Physical Damage and Decals	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
30,380 - Check Exterior Compartment Doors	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
33,100 - Check Lights and Reflectors	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
40,420 - Check Hood	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
44,130 - FRA Check Exhaust System	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
44,140 - FRA Check Intake System	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
44,180 - FRA Check for Leaks	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
44,190 - FRA Perform Battery Inspection	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
50,510 - Check Entire Steering System	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
60,630 - Check and Record Tread Depth	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
60,650 - Check Sidewall Wear	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
60,660 - Inspect for Cuts and Tears	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
70,710 - Check Vibration Damper	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
70,730 - FRA Check Starter	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
70,770 - FRA Check Exhaust System	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
77,120 - Check Suspension Components	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
77,131 - Brake Pad Thickness LF	Inch	9 mm	LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
77,132 - Brake Pad Thickness RF	Inch	9 mm	LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
77,133 - Brake Pad Thickness LR	Inch	12 mm	LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
77,134 - Brake Pad Thickness RR	Inch	12 mm	LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
77,135 - Brake Rotor LF	Inch	40	LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
77,136 - Brake Rotor RF	Inch	40	LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
77,137 - Brake Rotor LR	Inch	40	LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
77,138 - Brake Rotor RR	Inch	40	LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
77,140 - FRA Check Brake Hoses	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
77,150 - Check King Pins	-	n/a	LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
80,810 - Completion of PMI Report	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		LCAPAZZOLI	Aug 29, 2016 2:40:47 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27205560
Invoice No. 55345 - 27205560

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: DCARTER
Created By: DCARTER
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 47,869 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Aug-16	Capazzoli,Louis	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: LCAPAZZOLI Performed on: 29-AUG-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		LCAPAZZOLI	Aug 29, 2016 4:03:57 PM	No	
101,000 - FRA Change Oil Filters	Yes		LCAPAZZOLI	Aug 29, 2016 4:03:57 PM	No	
102,000 - FRA Drain Engine Oil	Yes		LCAPAZZOLI	Aug 29, 2016 4:03:57 PM	No	
103,000 - FRA Check Transmission Fluid	Done		LCAPAZZOLI	Aug 29, 2016 4:03:57 PM	No	
104,000 - Lubricate Chassis	Done		LCAPAZZOLI	Aug 29, 2016 4:03:57 PM	No	
105,000 - Replace or Clean A/C Filters	Done		LCAPAZZOLI	Aug 29, 2016 4:03:57 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	n/a	LCAPAZZOLI	Aug 29, 2016 4:03:57 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		LCAPAZZOLI	Aug 29, 2016 4:03:57 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		LCAPAZZOLI	Aug 29, 2016 4:03:57 PM	No	
201,000 - Service Crankcase Breather	Done		LCAPAZZOLI	Aug 29, 2016 4:03:57 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	No	n/a	LCAPAZZOLI	Aug 29, 2016 4:03:57 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No	n/a	LCAPAZZOLI	Aug 29, 2016 4:03:57 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		LCAPAZZOLI	Aug 29, 2016 4:03:57 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		LCAPAZZOLI	Aug 29, 2016 4:03:57 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		LCAPAZZOLI	Aug 29, 2016 4:03:57 PM	No	
302,000 - Check Toe-In and Record Reading	-	n/a	LCAPAZZOLI	Aug 29, 2016 4:03:57 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	n/a	LCAPAZZOLI	Aug 29, 2016 4:03:57 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No	n/a	LCAPAZZOLI	Aug 29, 2016 4:03:57 PM	No	
305,000 - FRA Change Differential Fluid	No		LCAPAZZOLI	Aug 29, 2016 4:03:57 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27205560
Invoice No. 55345 - 27205560

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: DCARTER
Created By: DCARTER
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 47,869 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Aug-16	Capazzoli,Louis	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 29-AUG-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Aug 29, 2016 2:46:32 PM	No	
20 - Miles			LCAPAZZOLI	Aug 29, 2016 2:46:32 PM	No	
30 - Kilometers			LCAPAZZOLI	Aug 29, 2016 2:46:32 PM	No	
40 - Hours			LCAPAZZOLI	Aug 29, 2016 2:46:32 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27205560 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.08

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27254408
Invoice No. 55345 - 27254408

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
A/C		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	44,379 - DH

Chronology		
Reported	Jul 21, 2016 10:18:01 PM	Jul 21, 2016 10:18:01 PM
Started	Jul 21, 2016 12:00:00 AM	
Completed	Jul 21, 2016 10:44:00 PM	Jul 21, 2016 10:44:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: No Front Air Coming From Vent

CAUSE:Reservoir Leaking

CORRECTION: Replace Reservoir/Check Valve,
Parts#YC2Z-19A566-AA Qty (1)
Parts#D70Z-19 Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jul-16	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 21-JUL-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 21, 2016 10:19:32 PM	No	
20 - Miles			DARTHURS	Jul 21, 2016 10:19:32 PM	No	
30 - Kilometers			DARTHURS	Jul 21, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:19:32 PM		
40 - Hours			DARTHURS	Jul 21, 2016 10:19:32 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27254408
Invoice No. 55345 - 27254408

Client Department:
Department: 55345M
Work Order Description
A/C
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 44,379 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: NoAir Blowing Through Vent,
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Jul-16	YC2Z-19A566-AA	RESERVOIR, VACUUM W/BRACKET	1	25.81	25.81
22-Jul-16	YK211	CORE, EVAPORATOR, A/C	1	150.45	150.45
22-Jul-16	YG193	VALVE, CHECK, VACUUM, A/C SAME AS D7OZ-19A563-A	1	4.59	4.59
22-Jul-16	YK211	CORE, EVAPORATOR, A/C	-1	150.45	-150.45

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jul-16	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	30.40
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**30.40**

Work Order Footer

Work Order 27254408 Total	
Parts:	30.40
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**30.40**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27227622
Invoice No. 55345 - 27227622

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Fuel gauge check		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	44,249 - DH

Chronology		
Reported	Jul 5, 2016 11:31:19 AM	Jul 5, 2016 11:31:19 AM
Started	Jul 5, 2016 12:00:00 AM	
Completed	Jul 12, 2016 2:01:00 PM	Jul 12, 2016 2:01:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Fuel gauge read full all the time

CAUSE:

CORRECTION:Fuel gauge system check

Complaint cannot be verified
Fuel system connectors cleaned
Parts related to fuel gauge tested ok
FLIM is suspected

No part used

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 08-JUL-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Jul 8, 2016 4:03:43 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			FSIMON	Jul 8, 2016 4:03:43 PM	No	
30 - Kilometers			FSIMON	Jul 8, 2016 4:03:43 PM	No	
40 - Hours			FSIMON	Jul 8, 2016 4:03:43 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27227622
Invoice No. 55345 - 27227622

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Fuel gauge check		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	44,249 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jul-16	Simon,Fritz	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27227622 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27205412
Invoice No. 55345 - 27205412

Client Department:
Department: 55345M
Work Order Description
PM Followup --------> REAR BRAKES
Requested By: DCARTER
Created By: DCARTER
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 43,680 - DH

Chronology		
Reported	Jun 21, 2016 1:39:00 PM	Jun 21, 2016 1:39:00 PM
Started	Jun 21, 2016 12:00:00 AM	
Completed	Jun 21, 2016 3:27:00 PM	Jun 21, 2016 3:27:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========. Rear brakes low to spec. Replaced rear brakes. Torque all rear tires. Road test . Torque 2 nd time.

Parts used. 1 set rear shoes. Part number. BRSD. -1330

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: RISK ASSESSMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jun-16	Capazzoli,Louis	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 21-JUN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Jun 21, 2016 3:26:00 PM	No	
20 - Miles			LCAPAZZOLI	Jun 21, 2016 3:26:00 PM	No	
30 - Kilometers			LCAPAZZOLI	Jun 21, 2016 3:26:00 PM	No	
40 - Hours			LCAPAZZOLI	Jun 21, 2016 3:26:00 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27205412
Invoice No. 55345 - 27205412

Client Department:
Department: 55345M
Work Order Description
PM Followup --------> REAR BRAKES
Requested By: DCARTER
Created By: DCARTER
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 43,680 - DH

Activity Header
Activity: 15 013/002/000 REAR BRAKES & DRUMS
Activity Note: REAR BRAKES
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Jun-16	BRSD-1330	PADS, BRAKE, DISC, REAR, FORD SAME AS PFH133020	1	43.15	43.15

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jun-16	Capazzoli,Louis	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	43.15
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.15**

Work Order Footer

Work Order 27205412 Total	
Parts:	43.15
Labor:	0.00
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.15**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27099180
Invoice No. 55345 - 27099180

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 43,680 - DH

Chronology		
Reported	Jun 21, 2016 11:45:39 AM	Jun 21, 2016 11:45:39 AM
Started	Jun 21, 2016 12:00:00 AM	
Completed	Jun 21, 2016 3:26:35 PM	Jun 21, 2016 3:26:35 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pm-A Due for Inspection

CAUSE: miles

CORRECTION: Completed pm -A inspection. Replace oil and oil filter

Parts used. 6 quarts oil. 5-w20. 1 oil filter. B-329.

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Jun-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jun-16	Capazzoli,Louis	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: LCAPAZZOLI Performed on: 21-JUN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
10,100 - Safety Inspection	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
10,140 - Check Service Brakes	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
10,160 - FRA Check Instruments and Horns	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
10,170 - Check Fast Idle	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
10,180 - Check Starter Protection Circuit	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
10,190 - Check Reverse Warning System	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
11,100 - Check Parking Brake	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
11,150 - Perform Brake Test	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
11,170 - FRA Check Door Operation	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
20,210 - Check Condition of Operator's Area	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
20,240 - FRA Check Interior Lights	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
20,260 - Check Stop Request System	-	n/a	LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
22,110 - Check Emergency Hatches	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
22,120 - Check All Safety Equipment	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
30,310 - Check Passenger Doors	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
30,360 - Check for Physical Damage and Decals	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
30,380 - Check Exterior Compartment Doors	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
33,100 - Check Lights and Reflectors	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
40,420 - Check Hood	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
44,130 - FRA Check Exhaust System	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
44,140 - FRA Check Intake System	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
44,180 - FRA Check for Leaks	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
44,190 - FRA Perform Battery Inspection	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
50,510 - Check Entire Steering System	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
60,630 - Check and Record Tread Depth	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
60,633 - Tread Depth RRO	4 32nds of an inch		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
60,636 - Tread Depth LRO	4 32nds of an inch		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
60,650 - Check Sidewall Wear	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
60,660 - Inspect for Cuts and Tears	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
70,710 - Check Vibration Damper	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
70,730 - FRA Check Starter	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
70,770 - FRA Check Exhaust System	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
77,120 - Check Suspension Components	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
77,131 - Brake Pad Thickness LF	Inch	9 mm	LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
77,132 - Brake Pad Thickness RF	Inch	9 mm	LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
77,133 - Brake Pad Thickness LR	Inch	12 mm	LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
77,134 - Brake Pad Thickness RR	Inch	12 mm	LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
77,135 - Brake Rotor LF	Inch	40	LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
77,136 - Brake Rotor RF	Inch	40	LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
77,137 - Brake Rotor LR	Inch	40	LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
77,138 - Brake Rotor RR	Inch	40	LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
77,140 - FRA Check Brake Hoses	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
77,150 - Check King Pins	-	n/a	LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
80,810 - Completion of PMI Report	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		LCAPAZZOLI	Jun 21, 2016 3:08:15 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27099180
Invoice No. 55345 - 27099180

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 43,680 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jun-16	Capazzoli,Louis	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: LCAPAZZOLI Performed on: 21-JUN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		LCAPAZZOLI	Jun 21, 2016 3:08:59 PM	No	
101,000 - FRA Change Oil Filters	Yes		LCAPAZZOLI	Jun 21, 2016 3:08:59 PM	No	
102,000 - FRA Drain Engine Oil	Yes		LCAPAZZOLI	Jun 21, 2016 3:08:59 PM	No	
103,000 - FRA Check Transmission Fluid	Done		LCAPAZZOLI	Jun 21, 2016 3:08:59 PM	No	
104,000 - Lubricate Chassis	Done		LCAPAZZOLI	Jun 21, 2016 3:08:59 PM	No	
105,000 - Replace or Clean A/C Filters	Done		LCAPAZZOLI	Jun 21, 2016 3:08:59 PM	No	
107,000 - FRA Change Primary Fuel Filter	No		LCAPAZZOLI	Jun 21, 2016 3:08:59 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		LCAPAZZOLI	Jun 21, 2016 3:08:59 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.50
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27099180
Invoice No. 55345 - 27099180

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 43,680 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jun-16	Capazzoli,Louis	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 21-JUN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Jun 21, 2016 3:09:42 PM	No	
20 - Miles			LCAPAZZOLI	Jun 21, 2016 3:09:42 PM	No	
30 - Kilometers			LCAPAZZOLI	Jun 21, 2016 3:09:42 PM	No	
40 - Hours			LCAPAZZOLI	Jun 21, 2016 3:09:42 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27099180 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.08

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27082067
Invoice No. 55345 - 27082067

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 39,420 - DH

Chronology		
Reported	May 6, 2016 11:52:51 AM	May 6, 2016 11:52:51 AM
Started	May 6, 2016 12:00:00 AM	
Completed	May 6, 2016 2:58:00 PM	May 6, 2016 2:58:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PM B

CAUSE: preventive maintenance

CORRECTION: perform service,lube all pivoting point and cross rotate front tires completed
Parts #oil filter B329 qty1
Oil#5w20 qts 6

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-May-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-May-16	Pierre,Hubert J	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 06-MAY-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
10,100 - Safety Inspection	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
10,140 - Check Service Brakes	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	0 Pounds per Square Inch	N/A	HPIERRE	May 6, 2016 12:30:33 PM	No	
11,162 - FRA Check/Record Water Temperature	0 Degree Fahrenheit	N/A	HPIERRE	May 6, 2016 12:30:33 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	May 6, 2016 12:30:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	May 6, 2016 12:30:33 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	May 6, 2016 12:30:33 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
40,420 - Check Hood	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	May 6, 2016 12:30:33 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	May 6, 2016 12:30:33 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	May 6, 2016 12:30:33 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	May 6, 2016 12:30:33 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	May 6, 2016 12:30:33 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	May 6, 2016 12:30:33 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	May 6, 2016 12:30:33 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	May 6, 2016 12:30:33 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	May 6, 2016 12:30:33 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	May 6, 2016 12:30:33 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	May 6, 2016 12:30:33 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	May 6, 2016 12:30:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		HPIERRE	May 6, 2016 12:30:33 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		HPIERRE	May 6, 2016 12:30:33 PM	No	
60,633 - Tread Depth RRO	11 32nds of an inch		HPIERRE	May 6, 2016 12:30:33 PM	No	
60,634 - Tread Depth RRI	11 32nds of an inch		HPIERRE	May 6, 2016 12:30:33 PM	No	
60,635 - Tread Depth LRI	11 32nds of an inch		HPIERRE	May 6, 2016 12:30:33 PM	No	
60,636 - Tread Depth LRO	11 32nds of an inch		HPIERRE	May 6, 2016 12:30:33 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	May 6, 2016 12:30:33 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
77,120 - Check Suspension Components	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		HPIERRE	May 6, 2016 12:30:33 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		HPIERRE	May 6, 2016 12:30:33 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		HPIERRE	May 6, 2016 12:30:33 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		HPIERRE	May 6, 2016 12:30:33 PM	No	
77,135 - Brake Rotor LF	1.8 Inch		HPIERRE	May 6, 2016 12:30:33 PM	No	
77,136 - Brake Rotor RF	1.8 Inch		HPIERRE	May 6, 2016 12:30:33 PM	No	
77,137 - Brake Rotor LR	1.6 Inch		HPIERRE	May 6, 2016 12:30:33 PM	No	
77,138 - Brake Rotor RR	1.6 Inch		HPIERRE	May 6, 2016 12:30:33 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	May 6, 2016 12:30:33 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	May 6, 2016 12:30:33 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27082067
Invoice No. 55345 - 27082067

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 39,420 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-May-16	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 06-MAY-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	May 6, 2016 1:12:51 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	May 6, 2016 1:12:51 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	May 6, 2016 1:12:51 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	May 6, 2016 1:12:51 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	May 6, 2016 1:12:51 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	May 6, 2016 1:12:51 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	May 6, 2016 1:12:51 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	May 6, 2016 1:12:51 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27082067
Invoice No. 55345 - 27082067

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 39,420 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-May-16	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 06-MAY-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	May 6, 2016 1:16:36 PM	No	
20 - Miles			HPIERRE	May 6, 2016 1:16:36 PM	No	
30 - Kilometers			HPIERRE	May 6, 2016 1:16:36 PM	No	
40 - Hours			HPIERRE	May 6, 2016 1:16:36 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27082067 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27082901
Invoice No. 55345 - 27082901

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Left front headlight check		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	38,807 - DH

Chronology		
Reported	Apr 29, 2016 5:35:11 AM	Apr 29, 2016 5:35:11 AM
Started		
Completed	Apr 29, 2016 4:25:00 PM	Apr 29, 2016 4:25:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Left front headlight. Not glowing

CAUSE:Defective headlight bulb

CORRECTION:Left head light replacement

Left headlight bulb replaced

Part used:
One (1) headlight bulb #H13

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DKNOTT Performed on: 06-MAY-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DKNOTT	May 6, 2016 10:55:59 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			DKNOTT	May 6, 2016 10:55:59 AM	No	
30 - Kilometers			DKNOTT	May 6, 2016 10:55:59 AM	No	
40 - Hours			DKNOTT	May 6, 2016 10:55:59 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27082901
Invoice No. 55345 - 27082901

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Left front headlight check		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	38,807 - DH

Activity Header
Activity: 15 030 ELECTRICAL GROUP
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Apr-16	9008	BULB, HEADLAMP, HALOGEN, 12V	1	5.79	5.79

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	5.79
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.79**

Work Order Footer

Work Order 27082901 Total	
Parts:	5.79
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27006323
Invoice No. 55345 - 27006323

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 38,707 - DH

Chronology		
Reported	Apr 27, 2016 11:04:42 AM	Apr 27, 2016 11:04:42 AM
Started	Apr 27, 2016 12:00:00 AM	
Completed	Apr 28, 2016 7:32:00 AM	Apr 28, 2016 7:32:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pm due

CAUSE: miles

CORRECTION: Completed. Pm. Replaced oil and oil filter. Service crankcase breather. Clear all codes

Parts used. 6 quarts oil. 5 w-20. 1 oil filter B-329.

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Apr-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Apr-16	Capazzoli,Louis	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: LCAPAZZOLI Performed on: 28-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
10,100 - Safety Inspection	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
10,140 - Check Service Brakes	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
10,160 - FRA Check Instruments and Horns	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
10,170 - Check Fast Idle	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
10,180 - Check Starter Protection Circuit	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
10,190 - Check Reverse Warning System	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
11,100 - Check Parking Brake	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
11,150 - Perform Brake Test	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
11,170 - FRA Check Door Operation	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
20,210 - Check Condition of Operator's Area	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
20,240 - FRA Check Interior Lights	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
20,260 - Check Stop Request System	-	n/a	LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
22,110 - Check Emergency Hatches	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
22,120 - Check All Safety Equipment	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
30,310 - Check Passenger Doors	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
30,360 - Check for Physical Damage and Decals	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
30,380 - Check Exterior Compartment Doors	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
33,100 - Check Lights and Reflectors	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
40,420 - Check Hood	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
44,130 - FRA Check Exhaust System	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
44,140 - FRA Check Intake System	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
44,180 - FRA Check for Leaks	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
44,190 - FRA Perform Battery Inspection	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
50,510 - Check Entire Steering System	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
60,630 - Check and Record Tread Depth	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
60,650 - Check Sidewall Wear	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
60,660 - Inspect for Cuts and Tears	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
70,710 - Check Vibration Damper	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
70,730 - FRA Check Starter	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
70,770 - FRA Check Exhaust System	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
77,120 - Check Suspension Components	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
77,131 - Brake Pad Thickness LF	Inch	9 mm	LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
77,132 - Brake Pad Thickness RF	Inch	9 mm	LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
77,133 - Brake Pad Thickness LR	Inch	10 mm	LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
77,134 - Brake Pad Thickness RR	Inch	10 mm	LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
77,135 - Brake Rotor LF	Inch	40	LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
77,136 - Brake Rotor RF	Inch	40	LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
77,137 - Brake Rotor LR	Inch	40	LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
77,138 - Brake Rotor RR	Inch	40	LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
77,140 - FRA Check Brake Hoses	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
77,150 - Check King Pins	-	n/a	LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
80,810 - Completion of PMI Report	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		LCAPAZZOLI	Apr 28, 2016 2:03:03 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27006323
Invoice No. 55345 - 27006323

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 38,707 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Apr-16	Capazzoli,Louis	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: LCAPAZZOLI Performed on: 28-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		LCAPAZZOLI	Apr 28, 2016 2:24:00 PM	No	
101,000 - FRA Change Oil Filters	Yes		LCAPAZZOLI	Apr 28, 2016 2:24:00 PM	No	
102,000 - FRA Drain Engine Oil	Yes		LCAPAZZOLI	Apr 28, 2016 2:24:00 PM	No	
103,000 - FRA Check Transmission Fluid	Done		LCAPAZZOLI	Apr 28, 2016 2:24:00 PM	No	
104,000 - Lubricate Chassis	Done		LCAPAZZOLI	Apr 28, 2016 2:24:00 PM	No	
105,000 - Replace or Clean A/C Filters	Done		LCAPAZZOLI	Apr 28, 2016 2:24:00 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	LCAPAZZOLI	Apr 28, 2016 2:24:00 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		LCAPAZZOLI	Apr 28, 2016 2:24:00 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		LCAPAZZOLI	Apr 28, 2016 2:24:00 PM	No	
201,000 - Service Crankcase Breather	Done		LCAPAZZOLI	Apr 28, 2016 2:24:00 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	No	n/a	LCAPAZZOLI	Apr 28, 2016 2:24:00 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No	n/a	LCAPAZZOLI	Apr 28, 2016 2:24:00 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		LCAPAZZOLI	Apr 28, 2016 2:24:00 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27006323
Invoice No. 55345 - 27006323

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM B		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	38,707 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Apr-16	Capazzoli,Louis	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 27-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Apr 27, 2016 3:23:38 PM	No	
20 - Miles			LCAPAZZOLI	Apr 27, 2016 3:23:38 PM	No	
30 - Kilometers			LCAPAZZOLI	Apr 27, 2016 3:23:38 PM	No	
40 - Hours			LCAPAZZOLI	Apr 27, 2016 3:23:38 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27006323 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.08

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27014051
Invoice No. 55345 - 27014051

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Check fuel gauge for bad reading		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	35,123 - DH

Chronology		
Reported	Mar 23, 2016 1:48:28 PM	Mar 23, 2016 1:48:28 PM
Started	Mar 23, 2016 12:00:00 AM	
Completed	Mar 23, 2016 3:15:00 PM	Mar 23, 2016 3:15:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: Fuel gauge needle staying on full

CAUSE:Fuel gauge issue cannot be verified

CORRECTION:Fuel gauge issue cannot be duplicated

Complaint cannot be duplicated
Fuel gauge sending unit tested ok
Bus returned to service

No parts utilized

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 23-MAR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Mar 23, 2016 3:25:25 PM	No	
20 - Miles			FSIMON	Mar 23, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:25:25 PM		
30 - Kilometers			FSIMON	Mar 23, 2016 3:25:25 PM	No	
40 - Hours			FSIMON	Mar 23, 2016 3:25:25 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27014051
Invoice No. 55345 - 27014051

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Check fuel gauge for bad reading		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	35,123 - DH

Activity Header
Activity: 15 044 FUEL SYSTEM
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Mar-16	Simon,Fritz	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27014051 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26879132
Invoice No. 55345 - 26879132

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 34,330 - DH

Chronology		
Reported	Mar 16, 2016 3:12:53 PM	Mar 16, 2016 3:12:53 PM
Started	Mar 16, 2016 12:00:00 AM	
Completed	Mar 16, 2016 10:31:00 PM	Mar 16, 2016 10:31:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE: regular maintenance

CORRECTION: perform service,lube all pivoting point and cross rotate front tires completed
Parts #oil filter B329 qty1
Oil#5w20 qt6
Air filter #pa4075 qt 1

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Mar-16	PA4075	OUT OF SERVICE DO NOT ORDER FILTER, AIR, PAPER SAME AS AF25590	1	5.18	5.18
17-Mar-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Mar-16	Pierre,Hubert J	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 16-MAR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,100 - Safety Inspection	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	N/A	HPIERRE	Mar 16, 2016 10:29:41 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	N/A	HPIERRE	Mar 16, 2016 10:29:41 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	N/A	HPIERRE	Mar 16, 2016 10:29:41 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Mar 16, 2016 10:29:41 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Mar 16, 2016 10:29:41 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
40,420 - Check Hood	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Mar 16, 2016 10:29:41 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Mar 16, 2016 10:29:41 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Mar 16, 2016 10:29:41 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Mar 16, 2016 10:29:41 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Mar 16, 2016 10:29:41 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Mar 16, 2016 10:29:41 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Mar 16, 2016 10:29:41 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
60,631 - Tread Depth RF	9 32nds of an inch		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
60,633 - Tread Depth RRO	11 32nds of an inch		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
60,634 - Tread Depth RRI	11 32nds of an inch		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
60,635 - Tread Depth LRI	11 32nds of an inch		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
60,636 - Tread Depth LRO	11 32nds of an inch		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Mar 16, 2016 10:29:41 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
77,135 - Brake Rotor LF	42 Inch		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
77,136 - Brake Rotor RF	42 Inch		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
77,137 - Brake Rotor LR	40 Inch		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
77,138 - Brake Rotor RR	40 Inch		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Mar 16, 2016 10:29:41 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Mar 16, 2016 10:29:41 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26879132
Invoice No. 55345 - 26879132

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 34,330 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Mar-16	Pierre,Hubert J	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 16-MAR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Mar 16, 2016 3:46:31 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Mar 16, 2016 3:46:31 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Mar 16, 2016 3:46:31 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Mar 16, 2016 3:46:31 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Mar 16, 2016 3:46:31 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Mar 16, 2016 3:46:31 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Mar 16, 2016 3:46:31 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Mar 16, 2016 3:46:31 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.50
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26879132
Invoice No. 55345 - 26879132

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 34,330 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Mar-16	Pierre,Hubert J	0.1666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 16-MAR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Mar 16, 2016 3:46:56 PM	No	
20 - Miles			HPIERRE	Mar 16, 2016 3:46:56 PM	No	
30 - Kilometers			HPIERRE	Mar 16, 2016 3:46:56 PM	No	
40 - Hours			HPIERRE	Mar 16, 2016 3:46:56 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26879132 Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	2.67

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**7.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26954603
Invoice No. 55345 - 26954603

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
left front tire low specs.		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	33,558 - DH

Chronology		
Reported	Mar 9, 2016 2:21:00 PM	Mar 9, 2016 2:21:00 PM
Started	Mar 9, 2016 12:00:00 AM	
Completed	Mar 10, 2016 2:25:00 PM	Mar 10, 2016 2:25:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: tire worn

CAUSE: tire wear

CORRECTION: Replaced left front tire. Torqued to 140 ft pounds road test torqued 2 nd time

Parts used 1 tire. Bridgestone. 206361

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Mar-16	Capazzoli,Louis	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 10-MAR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Mar 10, 2016 1:23:10 PM	No	
20 - Miles			LCAPAZZOLI	Mar 10, 2016 1:23:10 PM	No	
30 - Kilometers			LCAPAZZOLI	Mar 10, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				1:23:10 PM		
40 - Hours			LCAPAZZOLI	Mar 10, 2016 1:23:10 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26954603
Invoice No. 55345 - 26954603

Client Department:
Department: 55345M
Work Order Description
left front tire low specs.
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 33,558 - DH

Activity Header
Activity: 15 017/001/000 TIRE, PNEUMATIC
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Mar-16	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	1	112.55	112.55

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Mar-16	Capazzoli,Louis	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	112.55
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**112.55**

Work Order Footer

Work Order 26954603 Total	
Parts:	112.55
Labor:	0.00
Labor Hours:	1.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**112.55**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26924653
Invoice No. 55345 - 26924653

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Check lift		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	32,280 - DH

Chronology		
Reported	Feb 24, 2016 12:18:55 PM	Feb 24, 2016 12:18:55 PM
Started	Feb 26, 2016 12:00:00 AM	
Completed	Mar 2, 2016 9:40:00 AM	Mar 2, 2016 9:40:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT: Lift not working properly

CAUSE:lift Cylinder issues

CORRECTION: Bus under warranty needs to be sent to the vendor for repair

Complaint verified
W/C lift check
W/C lift found going down by itself
W/C lift cylinders need to be replaced
W/C lift (under warranty) sent to the vendor for repair.
MobilityWorks technician replaced lift cylinders

No parts charged
Lift cylinders (under warranty)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 26-FEB-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Feb 26, 2016 7:57:03 AM	No	
20 - Miles			FSIMON	Feb 26, 2016 7:57:03 AM	No	
30 - Kilometers			FSIMON	Feb 26, 2016 7:57:03 AM	No	
40 - Hours			FSIMON	Feb 26, 2016 7:57:03 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26924653
Invoice No. 55345 - 26924653

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Check lift		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	32,280 - DH

Activity Header
Activity: 15 055 HANDLING, CARGO RESTRAINT & LIFT SYSTEM (POWER UNITS, TRAILERS)
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Feb-16	Simon,Fritz	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26924653 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26891046
Invoice No. 55345 - 26891046

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Fuel gauge issues		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	31,514 - DH

Chronology		
Reported	Feb 15, 2016 9:31:50 AM	Feb 15, 2016 9:31:50 AM
Started	Feb 15, 2016 12:00:00 AM	
Completed	Feb 18, 2016 1:51:00 PM	Feb 18, 2016 1:51:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Fuel gauge stuck in full

CAUSE:Fuel gauge

CORRECTION:

Driver's complaint verified
Continuity checked ok between
1-Fuel level sender and SRM
2-SRM and Fuel level Indicator Module
3-SRM and FRPCM
Fuel electrical Connectors cleaned and tightened
Fuel gauge working
Vehicle returned in service

NB: FLIM and SRM are suspected working intermittently (defective)

No parts utilized

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 15-FEB-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Feb 15, 2016 10:16:07 AM	No	
20 - Miles			FSIMON	Feb 15, 2016 10:16:07 AM	No	
30 - Kilometers			FSIMON	Feb 15, 2016 10:16:07 AM	No	
40 - Hours			FSIMON	Feb 15, 2016 10:16:07 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26891046
Invoice No. 55345 - 26891046

Client Department:
Department: 55345M
Work Order Description
Fuel gauge issues
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 31,514 - DH

Activity Header
Activity: 15 044 FUEL SYSTEM
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Jun-20	11395002	MODULE, INTERFACE, LEVEL, FUEL, GASEOUS	2	141.55	283.1
17-Jun-20	11395002	MODULE, INTERFACE, LEVEL, FUEL, GASEOUS	1	141.55	141.55

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Feb-16	Simon,Fritz	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	424.65
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**424.65**

Work Order Footer

Work Order 26891046 Total	
Parts:	424.65
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**424.65**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26886508
Invoice No. 55345 - 26886508

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Driver headlight		Ford E450 Champion Challenger	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	30,844 - DH

Chronology		
Reported	Feb 11, 2016 9:53:37 AM	Feb 11, 2016 9:53:37 AM
Started	Feb 11, 2016 12:00:00 AM	
Completed	Feb 11, 2016 2:31:00 PM	Feb 11, 2016 2:31:00 PM
Down Time		

Work Order Notes

Line 10 Headlight

COMPLAINT:
Driver complained of bad headlight bulb on driver side.

CAUSE:
Normal wear.

CORRECTION: replaced headlight bulb. Head light is working properly at this time.

Part- ford headlamp part number H13 qty 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 11-FEB-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Feb 11, 2016 12:01:58 PM	No	
20 - Miles			EDTORRES	Feb 11, 2016 12:01:58 PM	No	
30 - Kilometers			EDTORRES	Feb 11, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:01:58 PM		
40 - Hours			EDTORRES	Feb 11, 2016 12:01:58 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26886508
Invoice No. 55345 - 26886508

Client Department:
Department: 55345M
Work Order Description
Driver headlight
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 30,844 - DH

Activity Header
Activity: 15 034 LIGHTING SYSTEM
Activity Note: Bad headlight on driver side
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Feb-16	H13	BULB, CAPSULE, HEADLAMP, HALOGEN	1	7.86	7.86

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Feb-16	Torres,Edwin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	7.86
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.86**

Work Order Footer

Work Order 26886508 Total	
Parts:	7.86
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.86**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26708784
Invoice No. 55345 - 26708784

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 30,028 - DH

Chronology		
Reported	Feb 5, 2016 12:00:00 AM	Feb 5, 2016 12:00:00 AM
Started	Feb 5, 2016 12:00:00 AM	
Completed	Feb 5, 2016 11:15:00 PM	Feb 5, 2016 11:15:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:service

CORRECTION:perform pmA service
Oil filter B329 qty1
Engine oil 5w20 qty 6qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Feb-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Feb-16	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 05-FEB-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Feb 5, 2016 11:11:42 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Feb 5, 2016 11:11:42 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Feb 5, 2016 11:11:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Feb 5, 2016 11:11:42 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Feb 5, 2016 11:11:42 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
40,420 - Check Hood	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Feb 5, 2016 11:11:42 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Feb 5, 2016 11:11:42 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Feb 5, 2016 11:11:42 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Feb 5, 2016 11:11:42 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Feb 5, 2016 11:11:42 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Feb 5, 2016 11:11:42 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	Feb 5, 2016 11:11:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
60,631 - Tread Depth RF	9 32nds of an inch		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
60,633 - Tread Depth RRO	11 32nds of an inch		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
60,635 - Tread Depth LRI	10 32nds of an inch		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
60,636 - Tread Depth LRO	12 32nds of an inch		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
60,670 - Check Dual Mating With Square	-	na	RGASPARD	Feb 5, 2016 11:11:42 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
77,131 - Brake Pad Thickness LF	12 Inch		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
77,132 - Brake Pad Thickness RF	12 Inch		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
77,135 - Brake Rotor LF	37 Inch		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
77,136 - Brake Rotor RF	37 Inch		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
77,137 - Brake Rotor LR	34 Inch		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
77,138 - Brake Rotor RR	34 Inch		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Feb 5, 2016 11:11:42 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Feb 5, 2016 11:11:42 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26708784
Invoice No. 55345 - 26708784

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 30,028 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Feb-16	Gaspard,Ronald	0.6666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 05-FEB-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Feb 5, 2016 11:12:34 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Feb 5, 2016 11:12:34 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Feb 5, 2016 11:12:34 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Feb 5, 2016 11:12:34 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Feb 5, 2016 11:12:34 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Feb 5, 2016 11:12:34 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Feb 5, 2016 11:12:34 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Feb 5, 2016 11:12:34 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.67
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26708784
Invoice No. 55345 - 26708784

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	30,028 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Feb-16	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 05-FEB-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Feb 5, 2016 11:12:56 PM	No	
20 - Miles			RGASPARD	Feb 5, 2016 11:12:56 PM	No	
30 - Kilometers			RGASPARD	Feb 5, 2016 11:12:56 PM	No	
40 - Hours			RGASPARD	Feb 5, 2016 11:12:56 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26708784 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.23

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26708779
Invoice No. 55345 - 26708779

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
REPLACE FRONT BRAKES		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	25,372 - DH

Chronology		
Reported	Dec 14, 2015 11:15:55 PM	Dec 14, 2015 11:15:55 PM
Started	Dec 14, 2015 12:00:00 AM	
Completed	Dec 14, 2015 11:39:00 PM	Dec 14, 2015 11:39:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT: needs front brakes job.

CAUSE:normal wear.

CORRECTION: perform front brakes job.
Replaced front brake pads ,lubed guide pins
Part number BRSD 1328
Torque tires 140lbs second torque 140lbs

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Dec-15	Gaspard,Ronald	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 14-DEC-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Dec 14, 2015 11:33:02 PM	No	
20 - Miles			RGASPARD	Dec 14, 2015 11:33:02 PM	No	
30 - Kilometers			RGASPARD	Dec 14, 2015 11:33:02 PM	No	
40 - Hours			RGASPARD	Dec 14, 2015 11:33:02 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26708779
Invoice No. 55345 - 26708779

Client Department:
Department: 55345M
Work Order Description
REPLACE FRONT BRAKES
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 25,372 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: REPLACE FRONT BRAKES
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Dec-15	BRSD-1328	PADS, BRAKE, DISC, FRONT	1	50.32	50.32
22-Dec-15	BRSD-1328	PADS, BRAKE, DISC, FRONT	-1	50.32	-50.32
15-Dec-15	BRSD-1328	PADS, BRAKE, DISC, FRONT	1	50.32	50.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Dec-15	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	50.32
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**50.32**

Work Order Footer

Work Order 26708779 Total	
Parts:	50.32
Labor:	0.00
Labor Hours:	1.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**50.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26538732
Invoice No. 55345 - 26538732

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: LCAPAZZOLI
Created By: LCAPAZZOLI
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 227,254 - DH

Chronology

Reported	Dec 14, 2015 1:36:10 PM	Dec 14, 2015 1:36:10 PM
Started	Dec 14, 2015 12:00:00 AM	
Completed	Dec 14, 2015 11:32:00 PM	Dec 14, 2015 11:32:00 PM
Down Time		

Work Order Notes

Line 10 PmC
Service
Perform pmc service
Oil filter B329 qty1
Engine oil 5w20 qty 6qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Dec-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92
17-Jun-20	680709407	GLASS, MIRROR, VELVAC W/KIT	2	26.3	52.6

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Dec-15	Gaspard,Ronald	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 14-DEC-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
10,110 - FRA Check Drivers Pre-trip or	Done		RGASPARD	Dec 14, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
DVIR/EVIR & Authorization Forms				11:23:29 PM		
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Dec 14, 2015 11:23:29 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Dec 14, 2015 11:23:29 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Dec 14, 2015 11:23:29 PM	No	
20,270 - Check Fare Box Mounting (If	-	na	RGASPARD	Dec 14, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Applicable)				11:23:29 PM		
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Dec 14, 2015 11:23:29 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
40,420 - Check Hood	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Dec 14, 2015 11:23:29 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Dec 14, 2015 11:23:29 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Dec 14, 2015 11:23:29 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
40,460 - Record Antifreeze Protection Level	-	na	RGASPARD	Dec 14, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Using Refractometer				11:23:29 PM		
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Dec 14, 2015 11:23:29 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Dec 14, 2015 11:23:29 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Dec 14, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:23:29 PM		
60,630 - Check and Record Tread Depth	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
60,631 - Tread Depth RF	11 32nds of an inch		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
60,633 - Tread Depth RRO	11 32nds of an inch		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
60,636 - Tread Depth LRO	11 32nds of an inch		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
60,670 - Check Dual Mating With Square	-	na	RGASPARD	Dec 14, 2015 11:23:29 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Dec 14, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:23:29 PM		
77,120 - Check Suspension Components	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
77,131 - Brake Pad Thickness LF	4 Inch		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
77,132 - Brake Pad Thickness RF	4 Inch		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
77,137 - Brake Rotor LR	34 Inch		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
77,138 - Brake Rotor RR	34 Inch		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Dec 14, 2015 11:23:29 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Dec 14, 2015 11:23:29 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	54.52
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**54.52**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26538732
Invoice No. 55345 - 26538732

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: LCAPAZZOLI
Created By: LCAPAZZOLI
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 227,254 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Dec-15	Gaspard,Ronald	0.6666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: RGASPARD Performed on: 14-DEC-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Dec 14, 2015 11:25:17 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Dec 14, 2015 11:25:17 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Dec 14, 2015 11:25:17 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Dec 14, 2015 11:25:17 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Dec 14, 2015 11:25:17 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Dec 14, 2015 11:25:17 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	na	RGASPARD	Dec 14, 2015 11:25:17 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Dec 14, 2015 11:25:17 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Dec 14, 2015 11:25:17 PM	No	
201,000 - Service Crankcase Breather	Done		RGASPARD	Dec 14, 2015 11:25:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Dec 14, 2015 11:25:17 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Dec 14, 2015 11:25:17 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Dec 14, 2015 11:25:17 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		RGASPARD	Dec 14, 2015 11:25:17 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		RGASPARD	Dec 14, 2015 11:25:17 PM	No	
302,000 - Check Toe-In and Record Reading	-	na	RGASPARD	Dec 14, 2015 11:25:17 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	na	RGASPARD	Dec 14, 2015 11:25:17 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		RGASPARD	Dec 14, 2015 11:25:17 PM	No	
305,000 - FRA Change Differential Fluid	No		RGASPARD	Dec 14, 2015 11:25:17 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26538732
Invoice No. 55345 - 26538732

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM C		Ford E450 Champion Challenger	
Requested By:	LCAPAZZOLI	**Status:**	40 - Closed (40)
Created By:	LCAPAZZOLI	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	227,254 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Dec-15	Gaspard,Ronald	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 14-DEC-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Dec 14, 2015 11:25:43 PM	No	
20 - Miles			RGASPARD	Dec 14, 2015 11:25:43 PM	No	
30 - Kilometers			RGASPARD	Dec 14, 2015 11:25:43 PM	No	
40 - Hours			RGASPARD	Dec 14, 2015 11:25:43 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26538732 Total	
Parts:	54.52
Labor:	0.00
Labor Hours:	2.72

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**54.52**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26601136
Invoice No. 55345 - 26601136

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Engine shaking check		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	23,395 - DH

Chronology		
Reported	Nov 19, 2015 9:17:15 AM	Nov 19, 2015 9:17:15 AM
Started	Nov 19, 2015 12:07:00 PM	
Completed	Nov 19, 2015 12:09:00 PM	Nov 19, 2015 12:09:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT:Bus shaking when on drive

CAUSE:Unknown

CORRECTION:Engine checked
Vehicle diagnosed
Driver's complaint cannot be verified
Vehicle road test drive performed OK.
Vehicle returned to its spot.

No part utilized

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 19-NOV-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Nov 19, 2015 12:06:05 PM	No	
20 - Miles			FSIMON	Nov 19, 2015 12:06:05 PM	No	
30 - Kilometers			FSIMON	Nov 19, 2015 12:06:05 PM	No	
40 - Hours			FSIMON	Nov 19, 2015 12:06:05 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26601136
Invoice No. 55345 - 26601136

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Engine shaking check		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	23,395 - DH

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Nov-15	Simon,Fritz	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26601136 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26565941
Invoice No. 55345 - 26565941

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Check Fuel gauge		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	21,998 - DH

Chronology		
Reported	Oct 30, 2015 12:59:16 PM	Oct 30, 2015 12:59:16 PM
Started		
Completed	Nov 2, 2015 2:57:00 PM	Nov 2, 2015 2:57:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT:Fuel gauge stuck on full

CAUSE:Unknown

CORRECTION:sending unit cleaned

Driver's complaint verified
Sending unit checked and cleaned
Sending unit Working OK.

No parts utilized

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Oct-15	Simon,Fritz	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 02-NOV-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Nov 2, 2015 2:56:47 PM	No	
20 - Miles			FSIMON	Nov 2, 2015 2:56:47 PM	No	
30 - Kilometers			FSIMON	Nov 2, 2015 2:56:47 PM	No	
40 - Hours			FSIMON	Nov 2, 2015 2:56:47 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26565941
Invoice No. 55345 - 26565941

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
Check Fuel gauge		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	21,998 - DH

Activity Header
Activity: 15 044 FUEL SYSTEM
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26565941 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26563585
Invoice No. 55345 - 26563585

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
per driver brakes squeak		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	21,774 - DH

Chronology		
Reported	Oct 29, 2015 8:19:00 AM	Oct 29, 2015 8:19:00 AM
Started	Oct 29, 2015 9:26:00 AM	
Completed	Oct 29, 2015 11:16:00 AM	Oct 29, 2015 11:16:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT: Driver notes in the DVI sheet "brakes are sgreenings".

CAUSE:

CORRECTION: Brakes cleaned

Vehicle road test drive ok
Brakes Visual inspection performed ,Brakes pads under specifications.
Front brakes cleaned
Front tires lugs nuts torqued 140ft/lb
Lugs nuts indicators reinstalled
Vehicle road test drive again ok.

NB :We need more clarification from the driver about his complaint.

No part utilized

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Oct-15	Simon,Fritz	1.82	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 29-OCT-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Oct 29, 2015 10:01:37 AM	No	
20 - Miles			FSIMON	Oct 29, 2015 10:01:37 AM	No	
30 - Kilometers			FSIMON	Oct 29, 2015 10:01:37 AM	No	
40 - Hours			FSIMON	Oct 29, 2015 10:01:37 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.82
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26563585
Invoice No. 55345 - 26563585

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
per driver brakes squeak		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	21,774 - DH

Activity Header
Activity: 15 013 BRAKES
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26563585 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.82
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26269892
Invoice No. 55345 - 26269892

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 20,920 - DH

Chronology		
Reported	Oct 9, 2015 11:04:16 AM	Oct 9, 2015 11:04:16 AM
Started	Oct 9, 2015 12:00:00 AM	
Completed	Oct 9, 2015 1:24:00 PM	Oct 9, 2015 1:24:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: performed. Pm. A

CAUSE:

CORRECTION: Replaced oil and oil filter

Parts used. 6 quarts. Oil. B329. 1 oil filter. B329

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: LIGHT MEDIUM DUTY PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Oct-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.52	1.52

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Oct-15	Capazzoli,Louis	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: LIGHT MEDIUM DUTY PMI
Task: First Transit Light-Medium Duty PMI Performed by: LCAPAZZOLI Performed on: 09-OCT-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
10,100 - Safety Inspection	Done		LCAPAZZOLI	Oct 9, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				1:20:05 PM		
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
10,140 - Check Service Brakes	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
10,160 - FRA Check Instruments and Horns	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
10,170 - Check Fast Idle	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
10,180 - Check Starter Protection Circuit	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
10,190 - Check Reverse Warning System	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
11,100 - Check Parking Brake	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
11,150 - Perform Brake Test	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
11,170 - FRA Check Door Operation	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
20,210 - Check Condition of Operator's Area	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
20,240 - FRA Check Interior Lights	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
20,260 - Check Stop Request System	-	n/a	LCAPAZZOLI	Oct 9, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				1:20:05 PM		
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
22,110 - Check Emergency Hatches	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
22,120 - Check All Safety Equipment	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
30,310 - Check Passenger Doors	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
30,360 - Check for Physical Damage and Decals	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
30,380 - Check Exterior Compartment Doors	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
33,100 - Check Lights and Reflectors	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
40,420 - Check Hood	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
40,450 - FRA Check Coolant Recovery System	Done		LCAPAZZOLI	Oct 9, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Condition & for Leaks				1:20:05 PM		
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	-	n/a	LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
44,130 - FRA Check Exhaust System	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
44,140 - FRA Check Intake System	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
44,180 - FRA Check for Leaks	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
44,190 - FRA Perform Battery Inspection	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
50,510 - Check Entire Steering System	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
60,616 - Air Pressure LRO	70 Pounds per		LCAPAZZOLI	Oct 9, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			1:20:05 PM		
60,620 - Check Valve Stems and Caps	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
60,630 - Check and Record Tread Depth	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
60,631 - Tread Depth RF	12 32nds of an inch		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
60,633 - Tread Depth RRO	12 32nds of an inch		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
60,636 - Tread Depth LRO	12 32nds of an inch		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
60,650 - Check Sidewall Wear	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
60,660 - Inspect for Cuts and Tears	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
70,710 - Check Vibration Damper	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
70,730 - FRA Check Starter	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
70,770 - FRA Check Exhaust System	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
77,100 - FRA Check Security, Integrity and	Done		LCAPAZZOLI	Oct 9, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Length of Ground Straps				1:20:05 PM		
77,110 - FRA Check Fuel Tank	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
77,120 - Check Suspension Components	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
77,133 - Brake Pad Thickness LR	12 Inch		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
77,134 - Brake Pad Thickness RR	12 Inch		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
77,135 - Brake Rotor LF	Inch	n/a	LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
77,136 - Brake Rotor RF	Inch	n/a	LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
77,137 - Brake Rotor LR	Inch	n/a	LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
77,138 - Brake Rotor RR	Inch	n/a	LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
77,140 - FRA Check Brake Hoses	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
77,150 - Check King Pins	-	n/a	LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
80,810 - Completion of PMI Report	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		LCAPAZZOLI	Oct 9, 2015 1:20:05 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.52
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.52**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26269892
Invoice No. 55345 - 26269892

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	20,920 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: LCAPAZZOLI Performed on: 09-OCT-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		LCAPAZZOLI	Oct 9, 2015 1:21:16 PM	No	
101,000 - FRA Change Oil Filters	Yes		LCAPAZZOLI	Oct 9, 2015 1:21:16 PM	No	
102,000 - FRA Drain Engine Oil	Yes		LCAPAZZOLI	Oct 9, 2015 1:21:16 PM	No	
103,000 - FRA Check Transmission Fluid	Done		LCAPAZZOLI	Oct 9, 2015 1:21:16 PM	No	
104,000 - Lubricate Chassis	Done		LCAPAZZOLI	Oct 9, 2015 1:21:16 PM	No	
105,000 - Replace or Clean A/C Filters	Done		LCAPAZZOLI	Oct 9, 2015 1:21:16 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	LCAPAZZOLI	Oct 9, 2015 1:21:16 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		LCAPAZZOLI	Oct 9, 2015 1:21:16 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00

	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26269892
Invoice No. 55345 - 26269892

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	20,920 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment and Meter Reading
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: Personal Risk Assessment and Meter Reading
Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 09-OCT-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Oct 9, 2015 12:57:22 PM	No	
20 - Miles			LCAPAZZOLI	Oct 9, 2015 12:57:22 PM	No	
30 - Kilometers			LCAPAZZOLI	Oct 9, 2015 12:57:22 PM	No	
40 - Hours			LCAPAZZOLI	Oct 9, 2015 12:57:22 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26269892 Total	
Parts:	1.52
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**1.52**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26535332
Invoice No. 55345 - 26535332

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
REPLACE ALL REAR TIRES		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	20,920 - DH

Chronology		
Reported	Oct 8, 2015 5:00:14 PM	Oct 8, 2015 5:00:14 PM
Started	Oct 8, 2015 5:08:00 PM	
Completed	Oct 8, 2015 5:27:00 PM	Oct 8, 2015 5:27:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT: All rear tires out of spec

CAUSE:

CORRECTION: replaced all rear tires Torqued to 140 ft pounds. Road test. Torqued 2 nd time

Part number. 192659. Qty. 4

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 08-OCT-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Oct 8, 2015 5:03:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			LCAPAZZOLI	Oct 8, 2015 5:03:32 PM	No	
30 - Kilometers			LCAPAZZOLI	Oct 8, 2015 5:03:32 PM	No	
40 - Hours			LCAPAZZOLI	Oct 8, 2015 5:03:32 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26535332
Invoice No. 55345 - 26535332

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
REPLACE ALL REAR TIRES		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	20,920 - DH

Activity Header
Activity: 15 017 TIRES, TUBES, LINERS & VALVES
Activity Note: REPLACE ALL REAR TIRES
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Oct-15	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	4	115.03	460.12

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Oct-15	Capazzoli,Louis	0.32	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	460.12
Labor:	0.00
Labor Hours:	0.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**460.12**

Work Order Footer

Work Order 26535332 Total	
Parts:	460.12
Labor:	0.00
Labor Hours:	0.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**460.12**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26534810
Invoice No. 55345 - 26534810

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
REAR BRAKE JOB		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	20,920 - DH

Chronology		
Reported	Oct 8, 2015 2:08:00 PM	Oct 8, 2015 2:08:00 PM
Started	Oct 8, 2015 12:00:00 AM	
Completed	Oct 8, 2015 4:20:00 PM	Oct 8, 2015 4:20:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT: Rear brakes out of spec

CAUSE:

CORRECTION: Replace rear brakes

Parts used Rear brakes. 8c2z2200- A

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 08-OCT-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Oct 8, 2015 3:43:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			LCAPAZZOLI	Oct 8, 2015 3:43:46 PM	No	
30 - Kilometers			LCAPAZZOLI	Oct 8, 2015 3:43:46 PM	No	
40 - Hours			LCAPAZZOLI	Oct 8, 2015 3:43:46 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26534810
Invoice No. 55345 - 26534810

Client Department:
Department: 55345M
Work Order Description
REAR BRAKE JOB
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 20,920 - DH

Activity Header
Activity: 15 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Oct-15	8C2Z-2200-A	PADS, BRAKE, DISC, REAR, E350, '08	1	43.98	43.98

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Oct-15	Capazzoli,Louis	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	43.98
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.98**

Work Order Footer

Work Order 26534810 Total	
Parts:	43.98
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.98**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26476835
Invoice No. 55345 - 26476835

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
REPLACE FRONT TIRES		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	19,435 - DH

Chronology		
Reported	Sep 16, 2015 4:31:58 PM	Sep 16, 2015 4:31:58 PM
Started	Sep 16, 2015 5:04:00 PM	
Completed	Sep 16, 2015 6:13:00 PM	Sep 16, 2015 6:13:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT: needs 2 front tires .

CAUSE:under spec.

CORRECTION: dismounted ,mounted 2new tires and balanced. First torque 140lbs second 140lbs
PARTS#206361

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Sep-15	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 16-SEP-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the	Done		RGASPARD	Sep 16, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				6:05:59 PM		
20 - Miles			RGASPARD	Sep 16, 2015 6:05:59 PM	No	
30 - Kilometers			RGASPARD	Sep 16, 2015 6:05:59 PM	No	
40 - Hours			RGASPARD	Sep 16, 2015 6:05:59 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26476835
Invoice No. 55345 - 26476835

Client Department:
Department: 55345M
Work Order Description
REPLACE FRONT TIRES
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 19,435 - DH

Activity Header
Activity: 15 017 TIRES, TUBES, LINERS & VALVES
Activity Note: Replace Front Tires
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Sep-15	206361	TIRE, LT225/75R16, BSW, R250, DURAVIS, BRIDGESTONE	2	151.66	303.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Sep-15	Gaspard,Ronald	0.13	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	303.32
Labor:	0.00
Labor Hours:	0.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**303.32**

Work Order Footer

Work Order 26476835 Total	
Parts:	303.32
Labor:	0.00
Labor Hours:	1.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**303.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26094043
Invoice No. 55345 - 26094043

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DCARTER
Created By: DCARTER
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 16,427 - DH

Chronology		
Reported	Aug 20, 2015 12:00:00 AM	Aug 20, 2015 12:00:00 AM
Started	Aug 20, 2015 12:00:00 AM	
Completed	Aug 20, 2015 9:48:00 PM	Aug 20, 2015 9:48:00 PM
Down Time		

Work Order Notes

Line 10 Oil filter ....B329...1
Engine oil .....5w20....6qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: LIGHT MEDIUM DUTY PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Aug-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.26	1.26

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Aug-15	Gaspard,Ronald	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: LIGHT MEDIUM DUTY PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 21-AUG-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
10,130 - FRA Check Automatic Transmission	Done		RGASPARD	Aug 21, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Neutral Start Operation				4:09:54 PM		
10,140 - Check Service Brakes	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Aug 21, 2015 4:09:54 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Aug 21, 2015 4:09:54 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
20,260 - Check Stop Request System	Done	na	RGASPARD	Aug 21, 2015 4:09:54 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	Done	na	RGASPARD	Aug 21, 2015 4:09:54 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
20,290 - Check for Physical Damage, Water	Done		RGASPARD	Aug 21, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Leaks, and Graffiti				4:09:54 PM		
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
30,340 - FRA Check Destination Sign and Run Box	Done	na	RGASPARD	Aug 21, 2015 4:09:54 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
40,420 - Check Hood	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Aug 21, 2015 4:09:54 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Aug 21, 2015 4:09:54 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Aug 21, 2015 4:09:54 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Aug 21, 2015 4:09:54 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Aug 21, 2015 4:09:54 PM	No	
40,470 - Pressure Test Cooling System and	Done		RGASPARD	Aug 21, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Check for Leaks				4:09:54 PM		
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Aug 21, 2015 4:09:54 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
60,631 - Tread Depth RF	12 32nds of an		RGASPARD	Aug 21, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	inch			4:09:54 PM		
60,632 - Tread Depth LF	12 32nds of an inch		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
60,633 - Tread Depth RRO	13 32nds of an inch		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
60,634 - Tread Depth RRI	13 32nds of an inch		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
60,635 - Tread Depth LRI	13 32nds of an inch		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
60,636 - Tread Depth LRO	13 32nds of an inch		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
60,670 - Check Dual Mating With Square	-	na	RGASPARD	Aug 21, 2015 4:09:54 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
77,130 - FRA Check Brake Pad Thickness and	Done		RGASPARD	Aug 21, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Rotor for Wear				4:09:54 PM		
77,131 - Brake Pad Thickness LF	12 Inch		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
77,132 - Brake Pad Thickness RF	12 Inch		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
77,137 - Brake Rotor LR	Inch	na	RGASPARD	Aug 21, 2015 4:09:54 PM	No	
77,138 - Brake Rotor RR	Inch	na	RGASPARD	Aug 21, 2015 4:09:54 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Aug 21, 2015 4:09:54 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Aug 21, 2015 4:09:54 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.26
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26094043
Invoice No. 55345 - 26094043

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	16,427 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A SERVICE
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A SERVICE
Task: PM A SERVICE Performed by: RGASPARD Performed on: 21-AUG-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Aug 21, 2015 4:08:51 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Aug 21, 2015 4:08:51 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Aug 21, 2015 4:08:51 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Aug 21, 2015 4:08:51 PM	No	
104,000 - Lubricate Chassis	Done	na	RGASPARD	Aug 21, 2015 4:08:51 PM	No	
105,000 - Replace or Clean A/C Filters	Done	na	RGASPARD	Aug 21, 2015 4:08:51 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes	na	RGASPARD	Aug 21, 2015 4:08:51 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Aug 21, 2015 4:08:51 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00

	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26094043
Invoice No. 55345 - 26094043

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DCARTER
Created By: DCARTER
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 16,427 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 20-AUG-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Aug 20, 2015 8:32:58 PM	No	
20 - Miles			RGASPARD	Aug 20, 2015 8:32:58 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26094043 Total	
Parts:	1.26
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 25887537
Invoice No. 55345 - 25887537

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM B		Ford E450 Champion Challenger	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	11,721 - DH

Chronology		
Reported	Jun 23, 2015 12:00:00 AM	Jun 23, 2015 12:00:00 AM
Started	Jun 23, 2015 12:00:00 AM	
Completed	Jun 30, 2015 12:56:14 PM	Jun 30, 2015 12:56:14 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION: Line 20 PM-B SERVICE PERFORM
CHECK BRAKES, CHESCK TIRES, LUBRICATE CHASSIS

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: PM B INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Jun-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.18	1.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jun-15	Owens,Arthur	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.18
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.18**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 25887537
Invoice No. 55345 - 25887537

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM B		Ford E450 Champion Challenger	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	11,721 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B SERVICE
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 25887537
Invoice No. 55345 - 25887537

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM B		Ford E450 Champion Challenger	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	11,721 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 25887537 Total	
Parts:	1.18
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.18**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 25734781
Invoice No. 55345 - 25734781

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DCARTER
Created By: DCARTER
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4516-P
VIN: 1FDFE4FS0EDB17178
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 7,114 - DH

Chronology		
Reported	Apr 20, 2015 12:00:00 AM	Apr 20, 2015 12:00:00 AM
Started	Apr 20, 2015 12:00:00 AM	
Completed	Apr 21, 2015 8:55:19 AM	Apr 21, 2015 8:55:19 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION: Line 20 Replaced Oil Filter
Changed Engine Oil
Rotate and Torque Tires to Spec.
Washed Fluid Added.

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: PM A INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Apr-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.63	1.63

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Apr-15	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.63
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.63**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 25734781
Invoice No. 55345 - 25734781

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	7,114 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A SERVICE
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 25734781
Invoice No. 55345 - 25734781

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	7,114 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 25734781 Total	
Parts:	1.63
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.63**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 24687415
Invoice No. 55345 - 24687415

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	2,514 - DH

Chronology		
Reported	Feb 20, 2015 12:00:00 AM	Feb 20, 2015 12:00:00 AM
Started	Feb 20, 2015 12:00:00 AM	
Completed	Mar 16, 2015 6:23:30 PM	Mar 16, 2015 6:23:30 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION:

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: PM A INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Feb-15	Owens,Arthur	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 24687415
Invoice No. 55345 - 24687415

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	2,514 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A SERVICE
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 24687415
Invoice No. 55345 - 24687415

Client Department:			
Department:	55345M	**Equipment No.:**	4516-P
Work Order Description		**VIN:**	1FDFE4FS0EDB17178
PM A		Ford E450 Champion Challenger	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	2,514 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 24687415 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

WorkOrder: 51333873
Invoice Number: 55345-51333873

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
PM A		**VIN:**	1FDFE4FS0EDB17178
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jun 7, 2018	11:57 AM
Started	Jun 8, 2018	
Completed	Jun 8, 2018	7:41 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	117,958	DH
System	117,958	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA CAUSE:Service CORRECTION:Perform pmA Service Oil filter B329 qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
08-Jun-18	Gaspard,Ronald	1.53	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.53	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
08-Jun-18	B329		FILTER, OIL (USE FGA0000399/FSC0000399)	1.00	1.96	1.96

WorkOrder: 51333873
Invoice Number: 55345-51333873

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
PM A		**VIN:**	1FDFE4FS0EDB17178
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Labor Posted

Date	Technician	Hours	Rate	Extended
08-Jun-18	Gaspard,Ronald	1.03	0.00	0.00

Activity 20 Sub Total

Parts:	1.96
Labor:	0.00
Labor Hours: 1.03	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Activity: 30 **999 TOTAL VEHICLE**

Activity Note: PRAMETER
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
08-Jun-18	Gaspard,Ronald	0.25	0.00	0.00

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.25	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

WorkOrder 51333873 Grand Total

Parts:	1.96
Labor:	0.00
Labor Hours: 2.82	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	**1.96**

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
51411389	8-Jun-18	117,958	WO	Needs rear brakes job
51333873	8-Jun-18	117,958	WO	PM A

WorkOrder: 51333873
Invoice Number: 55345-51333873

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
PM A		**VIN:**	1FDFE4FS0EDB17178
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

WorkOrder	Date Completed	Life Meter	Class	Description
51204840	9-May-18	113,919	WO	PM A
51333843	9-May-18	113,919	WO	Needs 2 front shoks

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
51089965	11-Mar-18	105,193	WO	Rear tires near min. specs.

PH: Work Order: 51333873 Desc: PM A
Equip: 4516-P Desc: Ford E450 Champion Challenger VIN: 1FDFE4FS0EDB17178

LH: 10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 08-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Jun 8, 2018 7:23:52 PM	No	
10,100	Safety Inspection	Done		RGASPARD	Jun 8, 2018 7:23:52 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jun 8, 2018 7:23:52 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		RGASPARD	Jun 8, 2018 7:23:52 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Jun 8, 2018 7:23:53 PM	No	
10,140	Check Service Brakes	Done		RGASPARD	Jun 8, 2018 7:23:53 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Jun 8, 2018 7:23:53 PM	No	
10,160	FRA Check Instruments and Horns	Done		RGASPARD	Jun 8, 2018 7:23:53 PM	No	
10,170	Check Fast Idle	Done		RGASPARD	Jun 8, 2018 7:23:53 PM	No	
10,180	Check Starter Protection Circuit	Done		RGASPARD	Jun 8, 2018 7:23:53 PM	No	
10,190	Check Reverse Warning System	Done		RGASPARD	Jun 8, 2018 7:23:54 PM	No	
11,100	Check Parking Brake	Done		RGASPARD	Jun 8, 2018 7:23:54 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		RGASPARD	Jun 8, 2018 7:23:54 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Jun 8, 2018 7:23:54 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		RGASPARD	Jun 8, 2018 7:23:54 PM	No	
11,140	Road Test: Check for Proper Operation	Done		RGASPARD	Jun 8, 2018 7:23:54 PM	No	
11,150	Perform Brake Test	Done		RGASPARD	Jun 8, 2018 7:23:54 PM	No	
11,152	Decelerometer Results Test 1	FEET	na	RGASPARD	Jun 8, 2018 7:23:54 PM	No	
11,154	Decelerometer Results Test 2	FEET	na	RGASPARD	Jun 8, 2018 7:23:55 PM	No	
11,156	Decelerometer Results Test 3	FEET	na	RGASPARD	Jun 8, 2018 7:23:54 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Jun 8, 2018 7:23:54 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Jun 8, 2018 7:23:55 PM	No	
11,170	FRA Check Door Operation	Done		RGASPARD	Jun 8, 2018 7:23:55 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		RGASPARD	Jun 8, 2018 7:23:55 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		RGASPARD	Jun 8, 2018 7:23:55 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		RGASPARD	Jun 8, 2018 7:23:56 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		RGASPARD	Jun 8, 2018 7:23:56 PM	No	
20,230	FRA Check Wiring Under Dash	Done		RGASPARD	Jun 8, 2018 7:23:56 PM	No	
20,240	FRA Check Interior Lights	Done		RGASPARD	Jun 8, 2018 7:23:56 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		RGASPARD	Jun 8, 2018 7:23:56 PM	No	
20,260	Check Stop Request System	-	na	RGASPARD	Jun 8, 2018 7:23:56 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Jun 8, 2018 7:23:56 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Jun 8, 2018 7:23:56 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Jun 8, 2018 7:23:57 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		RGASPARD	Jun 8, 2018 7:23:57 PM	No	
22,110	Check Emergency Hatches	Done		RGASPARD	Jun 8, 2018 7:23:57 PM	No	
22,120	Check All Safety Equipment	Done		RGASPARD	Jun 8, 2018 7:23:57 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Jun 8, 2018 7:23:57 PM	No	
30,310	Check Passenger Doors	Done		RGASPARD	Jun 8, 2018 7:23:57 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		RGASPARD	Jun 8, 2018 7:23:57 PM	No	
30,330	Check Wheelchair Lift Operation	Done		RGASPARD	Jun 8, 2018 7:23:57 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	na	RGASPARD	Jun 8, 2018 7:23:58 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		RGASPARD	Jun 8, 2018 7:23:58 PM	No	
30,360	Check for Physical Damage and Decals	Done		RGASPARD	Jun 8, 2018 7:23:58 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		RGASPARD	Jun 8, 2018 7:23:58 PM	No	
30,380	Check Exterior Compartment Doors	Done		RGASPARD	Jun 8, 2018 7:23:58 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		RGASPARD	Jun 8, 2018 7:23:58 PM	No	
33,100	Check Lights and Reflectors	Done		RGASPARD	Jun 8, 2018 7:23:58 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Jun 8, 2018 7:23:58 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Jun 8, 2018 7:23:59 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Jun 8, 2018 7:23:58 PM	No	
40,420	Check Hood	Done		RGASPARD	Jun 8, 2018 7:23:59 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		RGASPARD	Jun 8, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					7:23:59 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Jun 8, 2018 7:23:59 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Jun 8, 2018 7:23:59 PM	No	
40,442	Freeze Point	Degree Fahrenheit	na	RGASPARD	Jun 8, 2018 7:23:59 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Jun 8, 2018 7:24:00 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Jun 8, 2018 7:24:00 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Jun 8, 2018 7:23:59 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Jun 8, 2018 7:24:00 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		RGASPARD	Jun 8, 2018 7:24:00 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		RGASPARD	Jun 8, 2018 7:24:00 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Jun 8, 2018 7:24:00 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Jun 8, 2018 7:24:00 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Jun 8, 2018 7:24:00 PM	No	
44,130	FRA Check Exhaust System	Done		RGASPARD	Jun 8, 2018 7:24:00 PM	No	
44,140	FRA Check Intake System	Done		RGASPARD	Jun 8, 2018 7:24:01 PM	No	
44,150	FRA Inspect Turbocharger	-	na	RGASPARD	Jun 8, 2018 7:24:01 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Jun 8, 2018 7:24:01 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Jun 8, 2018 7:24:01 PM	No	
44,180	FRA Check for Leaks	Done		RGASPARD	Jun 8, 2018 7:24:01 PM	No	
44,190	FRA Perform Battery Inspection	Done		RGASPARD	Jun 8, 2018 7:24:01 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Jun 8, 2018 7:24:01 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		RGASPARD	Jun 8, 2018 7:24:02 PM	No	
50,510	Check Entire Steering System	Done		RGASPARD	Jun 8, 2018 7:24:02 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Jun 8, 2018 7:24:02 PM	No	
60,610	FRA Check and Record Air Pressure	Done		RGASPARD	Jun 8, 2018 7:24:02 PM	No	
60,611	Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Jun 8, 2018 7:24:02 PM	No	
60,612	Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Jun 8, 2018 7:24:02 PM	No	
60,613	Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Jun 8, 2018 7:24:02 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Jun 8, 2018 7:24:03 PM	No	
60,615	Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Jun 8, 2018 7:24:03 PM	No	
60,616	Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Jun 8, 2018 7:24:03 PM	No	
60,620	Check Valve Stems and Caps	Done		RGASPARD	Jun 8, 2018 7:24:03 PM	No	
60,630	Check and Record Tread Depth	Done		RGASPARD	Jun 8, 2018 7:24:04 PM	No	
60,631	Tread Depth RF	8 32nds of an inch		RGASPARD	Jun 8, 2018 7:24:03 PM	No	
60,632	Tread Depth LF	9 32nds of an inch		RGASPARD	Jun 8, 2018 7:24:03 PM	No	
60,633	Tread Depth RRO	7 32nds of an inch		RGASPARD	Jun 8, 2018 7:24:03 PM	No	
60,634	Tread Depth RRI	8 32nds of an inch		RGASPARD	Jun 8, 2018 7:24:03 PM	No	
60,635	Tread Depth LRI	7 32nds of an inch		RGASPARD	Jun 8, 2018 7:24:04 PM	No	
60,636	Tread Depth LRO	6 32nds of an inch		RGASPARD	Jun 8, 2018 7:24:04 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		RGASPARD	Jun 8, 2018 7:24:04 PM	No	
60,650	Check Sidewall Wear	Done		RGASPARD	Jun 8, 2018 7:24:04 PM	No	
60,660	Inspect for Cuts and Tears	Done		RGASPARD	Jun 8, 2018 7:24:05 PM	No	
60,670	Check Dual Mating With Square	Done		RGASPARD	Jun 8, 2018 7:24:04 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Jun 8, 2018 7:24:05 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Jun 8, 2018 7:24:05 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		RGASPARD	Jun 8, 2018 7:24:05 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Jun 8, 2018 7:24:05 PM	No	
70,710	Check Vibration Damper	Done		RGASPARD	Jun 8, 2018 7:24:05 PM	No	
70,720	Check Engine and Transmission Mounts	Done		RGASPARD	Jun 8, 2018 7:24:05 PM	No	
70,730	FRA Check Starter	Done		RGASPARD	Jun 8, 2018 7:24:05 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Jun 8, 2018 7:24:05 PM	No	
70,750	FRA Check Transmission for Leaks	Done		RGASPARD	Jun 8, 2018 7:24:06 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		RGASPARD	Jun 8, 2018 7:24:06 PM	No	
70,770	FRA Check Exhaust System	Done		RGASPARD	Jun 8, 2018 7:24:06 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Jun 8, 2018 7:24:06 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		RGASPARD	Jun 8, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					7:24:06 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Jun 8, 2018 7:24:07 PM	No	
77,110	FRA Check Fuel Tank	Done		RGASPARD	Jun 8, 2018 7:24:07 PM	No	
77,120	Check Suspension Components	Done		RGASPARD	Jun 8, 2018 7:24:07 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Jun 8, 2018 7:24:07 PM	No	
77,131	Brake Pad Thickness LF	8 Inch		RGASPARD	Jun 8, 2018 7:24:08 PM	No	
77,132	Brake Pad Thickness RF	8 Inch		RGASPARD	Jun 8, 2018 7:24:08 PM	No	
77,133	Brake Pad Thickness LR	4 Inch		RGASPARD	Jun 8, 2018 7:24:08 PM	No	
77,134	Brake Pad Thickness RR	4 Inch		RGASPARD	Jun 8, 2018 7:24:08 PM	No	
77,135	Brake Rotor LF	38 Inch		RGASPARD	Jun 8, 2018 7:24:08 PM	No	
77,136	Brake Rotor RF	38 Inch		RGASPARD	Jun 8, 2018 7:24:08 PM	No	
77,137	Brake Rotor LR	40 Inch		RGASPARD	Jun 8, 2018 7:24:09 PM	No	
77,138	Brake Rotor RR	40 Inch		RGASPARD	Jun 8, 2018 7:24:09 PM	No	
77,140	FRA Check Brake Hoses	Done		RGASPARD	Jun 8, 2018 7:24:09 PM	No	
77,150	Check King Pins	-	na	RGASPARD	Jun 8, 2018 7:24:09 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Jun 8, 2018 7:24:09 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		RGASPARD	Jun 8, 2018 7:24:09 PM	No	
80,810	Completion of PMI Report	Done		RGASPARD	Jun 8, 2018 7:24:09 PM	No	
90,000	SECTION 9 Completion of PMI	Done		RGASPARD	Jun 8, 2018 7:24:09 PM	No	
90,910	Vehicle Returned to predetermined location	Done		RGASPARD	Jun 8, 2018 7:24:10 PM	No	

LH: 20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 08-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		RGASPARD	Jun 8, 2018 7:24:53 PM	No	
101,000	FRA Change Oil Filters	Yes		RGASPARD	Jun 8, 2018 7:24:54 PM	No	
102,000	FRA Drain Engine Oil	Yes		RGASPARD	Jun 8, 2018 7:24:53 PM	No	
103,000	FRA Check Transmission Fluid	Done		RGASPARD	Jun 8, 2018 7:24:54 PM	No	
104,000	Lubricate Chassis	-	na	RGASPARD	Jun 8, 2018 7:24:53 PM	No	
105,000	Replace or Clean A/C Filters	Done		RGASPARD	Jun 8, 2018 7:24:54 PM	No	
107,000	FRA Change Primary Fuel Filter	No	na	RGASPARD	Jun 8, 2018 7:24:54 PM	No	
108,000	Lube all pivoting Mechanisms	Done		RGASPARD	Jun 8, 2018 7:24:54 PM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 08-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jun 8, 2018 7:25:27 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51506289
Invoice Number: 55345-51506289

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
PM A		**VIN:**	1FDFE4FS0EDB17178
Requested By:	CVERGARA	**Status:**	40
Created By:	CVERGARA	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Aug 6, 2018	11:00 AM
Started	Aug 7, 2018	
Completed	Aug 7, 2018	12:23 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	126,411	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PmA CAUSE:Service CORRECTION:perform PmA Service Oil filter B329 qty 1 Engine oil 5w20 qty 7 qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
07-Aug-18	Gaspard,Ronald	1.55	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.55	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
07-Aug-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51575820
Invoice Number: 55345-51575820

Client Department:			
MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
PM A		**VIN:**	1FDFE4FS0EDB17178
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Aug 31, 2018	11:31 AM
Started	Sep 4, 2018	
Completed	Sep 4, 2018	10:35 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	130,917	DH
System	130,917	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PM A CAUSE: Service due CORRECTION: Performed and completed pmA.... Changed engine oil and replaced engine oil filter Lube all Pivoting Points

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
04-Sep-18	Delva,Terry	0.57	0.00	0.00
04-Sep-18	Delva,Terry	1.18	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.75	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51766081
Invoice Number: 55345-51766081

Client Department:
MRC: 55345M
WO Desc:
PM A
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4516-P
Ford E450 Champion Challenger
VIN: 1FDFE4FS0EDB17178
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Oct 22, 2018	1:36 PM
Started	Oct 23, 2018	
Completed	Oct 23, 2018	12:30 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	139,253	DH
System	139,459	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA CAUSE: Service CORRECTION:Perform pmA Service Oil filter B329 Qty1 Engine oil 5w20 Qts 7

Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
23-Oct-18	Gaspard,Ronald	1.57	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.57	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
23-Oct-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51836586
Invoice Number: 55345-51836586

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
PM A		**VIN:**	1FDFE4FS0EDB17178
Requested By:	RGASPARD	**Status:**	32
Created By:	RGASPARD	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Nov 15, 2018	12:00 AM
Started	Nov 15, 2018	
Completed	Nov 15, 2018	7:54 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	143,885	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service CAUSE: preventive maintenance CORRECTION: Performed and completed Replaced air filter

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
15-Nov-18	AMRIT TEEMAL,VISHNU	1.50	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
15-Nov-18	PA4075		FILTER, AIR, PAPER SAME AS AF25590	1.00	5.27	5.27

1/23/2019

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52009321
Invoice Number: 55345-52009321

Client Department:			
MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
PM A		**VIN:**	1FDFE4FS0EDB17178
Requested By:	CVERGARA	**Status:**	40
Created By:	CVERGARA	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jan 23, 2019	1:01 PM
Started	Jan 23, 2019	
Completed	Jan 23, 2019	11:00 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	152,700	DH
System	152,920	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service CAUSE: Service Due by Mileage CORRECTION: Change Oil& Filter. Lube all Pivoting Points Clean batteries. Check brakes .Replace. A/C filter replace Oil drain plugs. Parts# B329 Qty (1) Oil 5W20QTY (7.0) Qt Parts#65266 Qty (1)

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
23-Jan-19	Arthurs,Durvin	1.50	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52106636
Invoice Number: 55345-52106636

Client Department:			
MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
PM A		**VIN:**	1FDFE4FS0EDB17178
Requested By:	DARTHURS	**Status:**	40
Created By:	DARTHURS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Feb 20, 2019	5:13 PM
Started	Feb 20, 2019	
Completed	Feb 20, 2019	11:56 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	157,049	DH
System	157,273	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA CAUSE: Service CORRECTION:Perform pmA Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
20-Feb-19	Gaspard,Ronald	1.60	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.60	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
20-Feb-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase
by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52252405
Invoice Number: 55345-52252405

Client Department:
MRC: 55345M
WO Desc:
PM A
Requested By: CVERGARA
Created By: CVERGARA
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4516-P
Ford E450 Champion Challenger
VIN: 1FDFE4FS0EDB17178
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Apr 9, 2019	3:30 PM
Started	Apr 9, 2019	
Completed	Apr 9, 2019	11:53 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	165,535	DH
System	165,773	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:
	CAUSE:
	CORRECTION:

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
09-Apr-19	Arthurs,Durvin	1.50	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
09-Apr-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52329366
Invoice Number: 55345-52329366

Client Department:			
MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
PM A		**VIN:**	1FDFE4FS0EDB17178
Requested By:	DARTHURS	**Status:**	40
Created By:	DARTHURS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	May 9, 2019	12:00 AM
Started	May 9, 2019	
Completed	May 9, 2019	11:57 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	170,103	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service CAUSE: Service due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points .check brakes Clean batteries. Parts # B329 Qty (1) Oil 5W20 Qty (7.0) Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
09-May-19	Arthurs,Durvin	1.50	65.00	97.50

Activity 10 Sub Total

Parts:	0.00
Labor:	97.50
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
09-May-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase
by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52493511
Invoice Number: 55345-52493511

Client Department:
MRC: 55345M
WO Desc:
PM A
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4516-P
Ford E450 Champion Challenger
VIN: 1FDFE4FS0EDB17178
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Jul 1, 2019	12:55 PM
Started	Jul 2, 2019	
Completed	Jul 2, 2019	5:22 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	178,701	DH
System	178,701	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PM A service. CAUSE: Due by Mileage. CORRECTION: LOF engine oil and filter. Performed tire and brake inspection.

Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
02-Jul-19	Earl Johnson	1.50	65.00	97.50

Activity 10 Sub Total

Parts:	0.00
Labor:	97.50
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
02-Jul-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52570674
Invoice Number: 55345-52570674

Client Department:
MRC: 55345M
WO Desc:
PM A
Requested By: EARJOHNSON
Created By: EARJOHNSON
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4516-P
Ford E450 Champion Challenger
VIN: 1FDFE4FS0EDB17178
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Aug 2, 2019	12:31 PM
Started	Aug 3, 2019	
Completed	Aug 3, 2019	12:08 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	183,066	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMA Service CAUSE: Service due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check Brakes. clean batteries Parts# B329 Qty (1) Oil 5w20 Qty (7.0) Qt

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
03-Aug-19	Arthurs,Durvin	1.50	65.00	97.50

Activity 10 Sub Total

Parts:	0.00
Labor:	97.50
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
03-Aug-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52857818
Invoice Number: 55345-52857818

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
PM A		**VIN:**	1FDFE4FS0EDB17178
Requested By:	DARTHURS	**Status:**	40
Created By:	DARTHURS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Oct 30, 2019	12:00 AM
Started	Oct 31, 2019	
Completed	Oct 31, 2019	12:23 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	196,547	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service CAUSE: Service due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check brakes . Clean batteries. Parts # B329 Qty (1) Oil 5W20 Qty (7.0) Qt

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
31-Oct-19	Arthurs,Durvin	1.50	65.00	97.50

Activity 10 Sub Total

Parts:	0.00
Labor:	97.50
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
31-Oct-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53039638
Invoice Number: 55345-53039638

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
PM A		**VIN:**	1FDFE4FS0EDB17178
Requested By:	RRENE	**Status:**	40
Created By:	RRENE	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Dec 20, 2019	8:59 AM
Started		
Completed	Dec 22, 2019	11:19 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	205,096	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA service CAUSE: preventive maintenance CORRECTION: perform PmA Service lube all Pivoting Points

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
22-Dec-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53119478
Invoice Number: 55345-53119478

Client Department:
MRC: 55345M
WO Desc:
PM A
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4516-P
Ford E450 Champion Challenger
VIN: 1FDFE4FS0EDB17178
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Jan 22, 2020	10:33 AM
Started	Jan 22, 2020	
Completed	Jan 22, 2020	8:48 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	209,304	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA SERVICE CAUSE: PREVENTIVE MAINTENANCE CORRECTION: PERFORM AND COMPLETED PMA SERVICE REPLACED AIR FILTER REPLACED DRAIN PLUG

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
22-Jan-20	AMRIT TEEMAL,VISHNU	1.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
22-Jan-20	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53306991
Invoice Number: 55345-53306991

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
PM A		**VIN:**	1FDFE4FS0EDB17178
Requested By:	AOWENS	**Status:**	40
Created By:	AOWENS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Mar 16, 2020	11:59 AM
Started	Mar 16, 2020	
Completed	Mar 16, 2020	8:37 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	217,598	DH
System	217,746	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA SERVICE CAUSE: PREVENTIVE MAINTENANCE CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
16-Mar-20	AMRIT TEEMAL,VISHNU	0.83	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.83	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
16-Mar-20	B329(F)		FILTER, OIL, SPIN-ON	1.00	1.96	1.96

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53390670
Invoice Number: 55345-53390670

Client Department:
MRC: 55345M
WO Desc:
PM A
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4516-P
Ford E450 Champion Challenger
VIN: 1FDFE4FS0EDB17178
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Apr 24, 2020	11:28 AM
Started	Apr 26, 2020	
Completed	Apr 26, 2020	11:54 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	221,618	DH
System	221,798	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA service CAUSE: preventive maintenance CORRECTION: perform pmA service and lube all Pivoting Points

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
26-Apr-20	NELSON PIERRE-LOUIS	3.02	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 3.02	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
26-Apr-20	B329(F)		FILTER, OIL, SPIN-ON SEE BALDWIN B329	1.00	1.96	1.96

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53604388
Invoice Number: 55345-53604388

Client Department:
MRC: 55345M
WO Desc:
55345-LIGHT DUTY PMA
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4516-P
Ford E450 Champion Challenger
VIN: 1FDFE4FS0EDB17178
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Chronology		
Reported	Jul 17, 2020	11:15 AM
Started	Jul 17, 2020	
Completed	Jul 17, 2020	11:43 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	230,240	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMA Service CAUSE: Service Due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points. check brakes. Clean batteries. Replace A/C Filter. Parts # B329 Qty (1) Oil 10W30 Qty(7.0) Qt

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53707699
Invoice Number: 55345-53707699

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
55345-LIGHT DUTY PMA		**VIN:**	1FDFE4FS0EDB17178
Requested By:	DARTHURS	**Status:**	40
Created By:	DARTHURS	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Sep 15, 2020	12:00 AM
Started	Sep 15, 2020	
Completed	Sep 16, 2020	12:47 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	234,691	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA CAUSE: service CORRECTION: perform PMA service Oil filter B329 qty1 Engine oil 10w30 qty 7 qts

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53987879
Invoice Number: 55345-53987879

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
55345-LIGHT DUTY PMA		**VIN:**	1FDFE4FS0EDB17178
Requested By:	DARTHURS	**Status:**	40
Created By:	DARTHURS	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Nov 25, 2020	12:00 AM
Started	Nov 26, 2020	
Completed	Nov 26, 2020	9:02 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	243,450	DH
System	243,450	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PM A service. CAUSE: Due by Mileage. CORRECTION: LOF engine oil and filter. Performed tire and brake inspection.

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
26-Nov-20	Earl Johnson	0.20	0.00	0.00

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.20	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 54087992
Invoice Number: 55345-54087992

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
55345-LIGHT DUTY PMA		**VIN:**	1FDFE4FS0EDB17178
Requested By:	EARJOHNSON	**Status:**	40
Created By:	EARJOHNSON	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Dec 31, 2020	8:58 AM
Started	Jan 1, 2021	
Completed	Jan 1, 2021	1:49 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	247,562	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMA CAUSE: preventive maintenance CORRECTION: Performed service lube all pivoting point cross tires completed

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10

Activity Note: Light Duty PMI
Reason for Repair: -
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 54264468
Invoice Number: 55345-54264468

Client Department:
MRC: 55345M
Equipment: 4516-P
WO Desc:
55345-LIGHT DUTY PMA
Ford E450 Champion Challenger
VIN: 1FDFE4FS0EDB17178
Requested By: RGASPARD
Status: 40
Created By: RGASPARD
Priority: 3
Class: WO
Driver:
Arrangement: Unassigned
Phone:
Potential Warranty: No
ETA:

Chronology		
Reported	Apr 16, 2021	12:00 AM
Started	Apr 16, 2021	
Completed	Apr 16, 2021	3:58 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	255,946	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Vehicle came in for service CAUSE: Time for service CORRECTION: Job complete. Muffler has a small hole might¿ve been in the back

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
16-Apr-21	Junior Hurst	0.02	0.00	0.00

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.02	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **020 GROUP, DRIVETRAIN**

Activity Note: Light Duty PMI
Reason for Repair: 11 - Routine
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
16-Apr-21	B329(F)		SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1.00	1.98	1.98

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 54476337
Invoice Number: 55345-54476337

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
55345-LIGHT DUTY PMA		**VIN:**	1FDFE4FS0EDB17178
Requested By:	JUHURST	**Status:**	40
Created By:	JUHURST	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Mar 23, 2022	12:00 AM
Started	Mar 24, 2022	
Completed	Mar 25, 2022	12:42 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	260,709	DH
System	260,709	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMA CAUSE:Service CORRECTION:Perform PMA Service oil filter B329 qty1 engine oil 10w30 qty 7 qts clean AC filter clean batteries

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note:	PERSONAL RISK ASSESSMENT
Reason for Repair:	SW - Shop Work Order
Work Accomplished:	06 - Inspect
Part Failure:	00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**

Activity Note:	Light Duty PMI
Reason for Repair:	05 - Inspection, Routine
Work Accomplished:	-
Part Failure:	-

Activity Comments

Parts Issued

WorkOrder: 54476337
Invoice Number: 55345-54476337

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
55345-LIGHT DUTY PMA		**VIN:**	1FDFE4FS0EDB17178
Requested By:	JUHURST	**Status:**	40
Created By:	JUHURST	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Date	Part Number		Description	Qty.	Each	Extended
24-Mar-22	B329		FILTER, OIL, SPIN-ON	1.00	1.99	1.99

Labor Posted

Date	Technician	Hours	Rate	Extended
24-Mar-22	Gaspard,Ronald	1.00	0.00	0.00
25-Mar-22	Gaspard,Ronald	0.67	0.00	0.00

Activity 10 Sub Total

Parts:	1.99
Labor:	0.00
Labor Hours: 1.67	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.99**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

WorkOrder 54476337 Grand Total

Parts:	1.99
Labor:	0.00
Labor Hours: 1.67	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	**1.99**

Recent Repair History

WorkOrder: 54476337
Invoice Number: 55345-54476337

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
55345-LIGHT DUTY PMA		**VIN:**	1FDFE4FS0EDB17178
Requested By:	JUHURST	**Status:**	40
Created By:	JUHURST	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

WorkOrder	Date Completed	Life Meter	Class	Description
54476337	25-Mar-22	260,709	WO	55345-LIGHT DUTY PMA
55459490	24-Mar-22	260,435	WO	55345 PER DVIR (Check Transmission)
55399390	9-Mar-22	259,862	WO	PREPARE BUS FOR P.T.C ANNUAL INSPECTION.
55030820	27-Oct-21	259,861	WO	INSPECT BUS
53558161	14-Jun-21	259,861	WO	55345-A/C INSPECTION
53557977	14-Jun-21	259,861	WO	55345-FIRE SAFETY INSPECTION
53557801	14-Jun-21	259,861	WO	55345-PTC INSPECTION
53544613	14-Jun-21	259,861	WO	QCC FLEET INSPECTION

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description

PH: Work Order: 54476337 Desc: 55345-LIGHT DUTY PMA
Equip: 4516-P Desc: Ford E450 Champion Challenger VIN: 1FDFE4FS0EDB17178

LH: 10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: KIVEY Performed on: 25-MAR-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		RGASPARD	Mar 24, 2022 11:39:50 PM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Mar 24, 2022 11:39:54 PM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		RGASPARD	Mar 24, 2022 11:39:59 PM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Mar 24, 2022 11:40:03 PM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Mar 24, 2022 11:40:08 PM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Mar 24, 2022 11:40:12 PM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Mar 24, 2022 11:40:17 PM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done	TAG LIGHT INOP	KIVEY	Mar 25, 2022 7:52:54 AM	Yes	55463524
10,800	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Mar 24, 2022 11:40:26 PM	No	
10,900	INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Mar 24, 2022 11:40:31 PM	No	
11,100	INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Mar 24, 2022 11:40:35 PM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Mar 24, 2022 11:40:40 PM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Mar 24, 2022 11:40:45 PM	No	
20,200	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Mar 24, 2022 11:40:49 PM	No	
20,300	*RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Mar 24, 2022 11:40:54 PM	No	
20,400	PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Mar 24, 2022 11:40:59 PM	No	
20,500	*RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Mar 24, 2022 11:41:03 PM	No	
20,600	*RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Mar 24,	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					2022 11:41:11 PM		
20,700	INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Mar 24, 2022 11:41:16 PM	No	
20,800	INSPECT_High Idle Control	Done		RGASPARD	Mar 24, 2022 11:41:21 PM	No	
20,900	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Mar 24, 2022 11:42:36 PM	No	
21,000	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Mar 24, 2022 11:42:41 PM	No	
21,100	INSPECT_Parking Brake Operation	Done		RGASPARD	Mar 24, 2022 11:42:45 PM	No	
21,200	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Mar 24, 2022 11:42:50 PM	No	
21,300	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Mar 24, 2022 11:42:55 PM	No	
21,400	*RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Mar 24, 2022 11:42:59 PM	No	
21,500	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Mar 24, 2022 11:43:04 PM	No	
21,550	INSPECT_Driver Floor Area for Rust/Water Leaks	Done		RGASPARD	Mar 24, 2022 11:43:09 PM	No	
21,600	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Mar 24, 2022 11:43:13 PM	No	
21,700	INSPECT_Engine Fault Codes	Done		RGASPARD	Mar 24, 2022 11:43:18 PM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Mar 24, 2022 11:43:22 PM	No	
31,000	SSF (Street Side Front)	Done		RGASPARD	Mar 24, 2022 11:43:27 PM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Mar 24, 2022 11:43:31 PM	No	
31,020	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Mar 24, 2022 11:43:36 PM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Mar 24, 2022 11:43:41 PM	No	
31,040	INSPECT_Wiper Blades, Arms	Done		RGASPARD	Mar 24, 2022 11:43:45 PM	No	
32,000	Engine Inspection	Done		RGASPARD	Mar 24, 2022 11:43:50 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
32,010	INSPECT_Hood, Springs and Props	Done		RGASPARD	Mar 24, 2022 11:43:55 PM	No	
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Mar 24, 2022 11:43:59 PM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done	WATER PUMP LEAK	KIVEY	Mar 25, 2022 7:52:18 AM	Yes	55463524
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	Mar 24, 2022 11:44:20 PM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Mar 24, 2022 11:44:30 PM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Mar 24, 2022 11:44:35 PM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Mar 24, 2022 11:44:41 PM	No	
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Mar 24, 2022 11:44:45 PM	No	
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Mar 24, 2022 11:44:50 PM	No	
32,100	INSPECT_Intake System	Done		RGASPARD	Mar 24, 2022 11:44:54 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Mar 24, 2022 11:45:03 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Mar 24, 2022 11:45:25 PM	No	
33,010	CSF (Curb Side Front)	Done		RGASPARD	Mar 24, 2022 11:45:30 PM	No	
33,020	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Mar 24, 2022 11:45:34 PM	No	
33,030	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Mar 24, 2022 11:45:39 PM	No	
33,040	INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Mar 24, 2022 11:45:43 PM	No	
33,050	INSPECT_Wiper Blades, Arms	Done		RGASPARD	Mar 24, 2022 11:45:48 PM	No	
33,060	!FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	Mar 24, 2022 11:45:52 PM	No	
33,070	*RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	RGASPARD	Mar 24, 2022 11:46:02 PM	No	
33,080	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Mar 24, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:46:06 PM		
40,000	SECTION 4 - Interior Inspection	Done		RGASPARD	Mar 24, 2022 11:46:11 PM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Mar 24, 2022 11:46:15 PM	No	
40,200	INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RGASPARD	Mar 24, 2022 11:46:20 PM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Mar 24, 2022 11:46:24 PM	No	
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	Mar 24, 2022 11:46:29 PM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Mar 24, 2022 11:46:33 PM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Mar 24, 2022 11:46:38 PM	No	
40,700	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Mar 24, 2022 11:46:43 PM	No	
40,800	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Mar 24, 2022 11:46:47 PM	No	
40,900	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Mar 24, 2022 11:46:52 PM	No	
41,000	INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Mar 24, 2022 11:46:56 PM	No	
41,100	INSPECT_CLEAN_AC Filter	Done		RGASPARD	Mar 24, 2022 11:47:05 PM	No	
41,200	INSPECT_ Emergency Windows,Hatches,Doors,Alarms/ Lights;CHECK_for Leaks	Done		RGASPARD	Mar 24, 2022 11:47:09 PM	No	
41,300	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Mar 24, 2022 11:47:14 PM	No	
41,400	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Mar 24, 2022 11:47:19 PM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Mar 24, 2022 11:47:23 PM	No	
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Mar 24, 2022 11:47:28 PM	No	
50,200	INSPECT_Ball Joint Play	Done		RGASPARD	Mar 24, 2022 11:47:33 PM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Mar 24, 2022 11:47:38 PM	No	
50,400	LUBE_All Chassis Components	Done	na	RGASPARD	Mar 24,	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					2022 11:47:45 PM		
50,500	!FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Mar 24, 2022 11:47:49 PM	No	
50,700	INSPECT_Tire Condition	Done		RGASPARD	Mar 24, 2022 11:47:54 PM	No	
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Mar 24, 2022 11:47:58 PM	No	
50,900	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Mar 24, 2022 11:48:03 PM	No	
51,000	RECORD_LF-Tire Tread Depth (32nds)	3 32nds of an inch	FRONT TIRE BELOW SPEC NEED TO CHANGE	KIVEY	Mar 25, 2022 7:52:18 AM	Yes	55463524
51,100	RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Mar 24, 2022 11:49:24 PM	No	
51,200	RECORD_RF-Tire Tread Depth (32nds)	4 32nds of an inch	BELOW SPEC NEED TO CHANGE	KIVEY	Mar 25, 2022 7:52:18 AM	No	
51,300	RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Mar 24, 2022 11:49:44 PM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Mar 24, 2022 11:49:48 PM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Mar 24, 2022 11:50:22 PM	No	
51,600	!FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Mar 24, 2022 11:50:27 PM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	Mar 24, 2022 11:50:32 PM	No	
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	Mar 24, 2022 11:50:38 PM	No	
51,900	INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	38 Inch		RGASPARD	Mar 24, 2022 11:50:45 PM	No	
52,000	INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	38 Inch		RGASPARD	Mar 24, 2022 11:50:51 PM	No	
52,100	INSPECT_Vibration Damper	Done		RGASPARD	Mar 24, 2022 11:50:55 PM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Mar 24, 2022 11:51:00 PM	No	
52,400	!FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Mar 24, 2022 11:51:04 PM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Mar 24, 2022 11:51:09 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
52,700	INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Mar 24, 2022 11:51:14 PM	No	
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Mar 24, 2022 11:51:18 PM	No	
52,900	INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Mar 24, 2022 11:51:23 PM	No	
53,000	!FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Mar 24, 2022 11:51:27 PM	No	
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Mar 24, 2022 11:51:32 PM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Mar 24, 2022 11:51:37 PM	No	
53,300	*RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Mar 24, 2022 11:51:41 PM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Mar 24, 2022 11:51:46 PM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Mar 24, 2022 11:51:50 PM	No	
53,600	INSPECT_Tire Condition	Done		RGASPARD	Mar 24, 2022 11:51:55 PM	No	
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Mar 24, 2022 11:52:00 PM	No	
53,800	INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Mar 24, 2022 11:52:05 PM	No	
53,900	INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Mar 24, 2022 11:52:10 PM	No	
54,000	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Mar 24, 2022 11:52:14 PM	No	
54,100	INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Mar 24, 2022 11:52:19 PM	No	
54,200	RECORD_RRO-Tire Tread Depth (32nds)	2 32nds of an inch	REAR TIRE BELOW SPEC NEEDS TO BE CHANGED	KIVEY	Mar 25, 2022 7:52:18 AM	Yes	55463524
54,300	RECORD_RRI-Tire Tread Depth (32nds)	3 32nds of an inch	BELOW SPEC NEEDS TO BE CHANGED	KIVEY	Mar 25, 2022 7:52:18 AM	No	
54,400	RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Mar 24, 2022 11:52:43 PM	No	
54,500	RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Mar 24, 2022 11:52:49 PM	No	
54,600	RECORD_LRO-Tire Tread Depth (32nds)	5 32nds of an inch	BELOW SPEC NEEDS TO BE CHANGED	KIVEY	Mar 25, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					7:52:18 AM		
54,700	RECORD_LRI-Tire Tread Depth (32nds)	5 32nds of an inch	BELOW SPEC NEEDS TO BE CHANGED	KIVEY	Mar 25, 2022 7:52:19 AM	No	
54,800	RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Mar 24, 2022 11:53:06 PM	No	
54,900	RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Mar 24, 2022 11:53:12 PM	No	
55,000	!FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Mar 24, 2022 11:53:16 PM	No	
55,100	!FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Mar 24, 2022 11:53:21 PM	No	
55,200	!FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Mar 24, 2022 11:53:25 PM	No	
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		RGASPARD	Mar 24, 2022 11:53:34 PM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		RGASPARD	Mar 24, 2022 11:53:39 PM	No	
55,500	INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	Mar 24, 2022 11:53:47 PM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	Mar 24, 2022 11:53:52 PM	No	
55,700	!FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Mar 24, 2022 11:53:57 PM	No	
55,800	*RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Mar 24, 2022 11:54:05 PM	No	
55,900	*RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Mar 24, 2022 11:54:10 PM	No	
60,000	SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Mar 24, 2022 11:54:14 PM	No	
60,100	RECORD_Wheelchair Cycle Count	12458 Cycles		RGASPARD	Mar 24, 2022 11:54:21 PM	No	
60,200	CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Mar 24, 2022 11:54:25 PM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Mar 24, 2022 11:54:30 PM	No	
60,400	OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	Mar 24, 2022 11:54:35 PM	No	
60,500	INSPECT_ Bridgeplate Operation	Done		RGASPARD	Mar 24, 2022 11:54:39 PM	No	
60,600	INSPECT_All Pivot Points for Wear and	Done		RGASPARD	Mar 24,	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Looseness				2022 11:54:44 PM		
60,700	INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Mar 24, 2022 11:54:50 PM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Mar 24, 2022 11:54:54 PM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Mar 24, 2022 11:54:59 PM	No	
61,000	INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Mar 24, 2022 11:55:03 PM	No	
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Mar 24, 2022 11:55:08 PM	No	
61,200	INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Mar 24, 2022 11:55:13 PM	No	
61,300	INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Mar 24, 2022 11:55:17 PM	No	
61,400	INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Mar 24, 2022 11:55:22 PM	No	
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Mar 24, 2022 11:55:27 PM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Mar 24, 2022 11:55:32 PM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Mar 24, 2022 11:55:37 PM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Mar 24, 2022 11:55:41 PM	No	
61,900	CLEAN_Linkages and Mechanisms	Done		RGASPARD	Mar 24, 2022 11:55:47 PM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Mar 24, 2022 11:55:51 PM	No	
62,100	INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Mar 24, 2022 11:55:56 PM	No	
62,200	INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Mar 24, 2022 11:56:01 PM	No	
62,300	INSPECT_Bridgeplate Hinge	Done		RGASPARD	Mar 24, 2022 11:56:05 PM	No	
62,400	INSPECT_All Pivot Points	Done		RGASPARD	Mar 24, 2022 11:56:10 PM	No	
62,500	INSPECT_Cams and Slots	Done		RGASPARD	Mar 24, 2022 11:56:15 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
62,600	INSPECT_Rollers	Done		RGASPARD	Mar 24, 2022 11:56:19 PM	No	
62,700	INSPECT_All Linkages	Done		RGASPARD	Mar 24, 2022 11:56:24 PM	No	
70,000	SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		RGASPARD	Mar 24, 2022 11:56:29 PM	No	
70,300	INSPECT_Condition of Fuel Pressure Gauge	Done		RGASPARD	Mar 24, 2022 11:56:33 PM	No	
70,400	PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		RGASPARD	Mar 24, 2022 11:56:38 PM	No	
70,500	INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		RGASPARD	Mar 24, 2022 11:56:43 PM	No	
70,600	INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		RGASPARD	Mar 24, 2022 11:56:47 PM	No	
70,700	INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		RGASPARD	Mar 24, 2022 11:56:52 PM	No	
70,800	INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		RGASPARD	Mar 24, 2022 11:56:58 PM	No	
80,000	SECTION 8 - PMI Report Completion	Done		RGASPARD	Mar 24, 2022 11:57:02 PM	No	
80,100	COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Mar 24, 2022 11:57:07 PM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Mar 24, 2022 11:57:12 PM	No	

LH: 20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 25-MAR-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		RGASPARD	Mar 25, 2022 12:32:55 AM	No	
101,000	FRA Change Oil Filters	Yes		RGASPARD	Mar 25, 2022 12:32:59 AM	No	
102,000	FRA Drain Engine Oil	Yes		RGASPARD	Mar 25, 2022 12:33:03 AM	No	
103,000	FRA Check Transmission Fluid	Done		RGASPARD	Mar 25, 2022 12:33:08 AM	No	
104,000	Lubricate Chassis	-	na	RGASPARD	Mar 25, 2022 12:33:15 AM	No	
105,000	Replace or Clean A/C Filters	Done		RGASPARD	Mar 25, 2022 12:33:20 AM	No	
107,000	FRA Change Primary Fuel Filter	No	na	RGASPARD	Mar 25, 2022 12:33:28 AM	No	
108,000	Lube all pivoting Mechanisms	Done		RGASPARD	Mar 25, 2022 12:33:35 AM	No	

LH: 5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 24-MAR-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		RGASPARD	Mar 24, 2022 10:59:46 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Mar 24, 2022 10:59:51 PM	No	
4	Are you wearing the appropriate PPE?	Done		RGASPARD	Mar 24, 2022 10:59:55 PM	No	
7	Have you performed the proper LOTO?	Done		RGASPARD	Mar 24, 2022 11:00:00 PM	No	
10	Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Mar 24, 2022 11:00:04 PM	No	
11	Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Mar 24, 2022 11:00:09 PM	No	

FIRSTstudent
First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 55696310
Invoice Number: 55345-55696310

Client Department:
MRC: 55345M
WO Desc:
55345-LIGHT DUTY PMA
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4516-P
Ford E450 Champion Challenger
VIN: 1FDFE4FS0EDB17178
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Chronology		
Reported	Jul 26, 2022	12:00 AM
Started	Jul 28, 2022	
Completed	Jul 28, 2022	9:28 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	270,368	DH
System	270,000	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMA CAUSE:Service CORRECTION:Perform PMA Service oil filter B329 qty1 engine oil 10w30 qty 7 qts add washer fluid washed batteries

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**

Activity Note: Light Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

WorkOrder: 55696310
Invoice Number: 55345-55696310

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
55345-LIGHT DUTY PMA		**VIN:**	1FDFE4FS0EDB17178
Requested By:	DARTHURS	**Status:**	40
Created By:	DARTHURS	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Labor Posted

Date	Technician	Hours	Rate	Extended
28-Jul-22	Gaspard,Ronald	1.42	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.42	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
29-Jul-22	B329		FILTER, OIL, SPIN-ON	1.00	2.19	2.19

Labor Posted

Date	Technician	Hours	Rate	Extended
28-Jul-22	Gaspard,Ronald	0.35	0.00	0.00

Activity 20 Sub Total

Parts:	2.19
Labor:	0.00
Labor Hours: 0.35	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.19**

WorkOrder 55696310 Grand Total

Parts:	2.19
Labor:	0.00
Labor Hours: 1.77	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	**2.19**

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
55696310	28-Jul-22	270,368	WO	55345-LIGHT DUTY PMA

WorkOrder: 55696310
Invoice Number: 55345-55696310

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
55345-LIGHT DUTY PMA		**VIN:**	1FDFE4FS0EDB17178
Requested By:	DARTHURS	**Status:**	40
Created By:	DARTHURS	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

WorkOrder	Date Completed	Life Meter	Class	Description
55789907	21-Jul-22	269,345	WO	WHEEL CHAIR LIFT
55786645	19-Jul-22	269,227	WO	Left Head Light
55767527	14-Jul-22	268,767	WO	CHECK WHEEL CHAIR LIFT FOR PROPER OPERATION

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
55812636	28-Jul-22	270,368	WO	FOLLOWUP-FT Light Duty

PH: Work Order: 55696310 Desc: 55345-LIGHT DUTY PMA
Equip: 4516-P Desc: Ford E450 Champion Challenger VIN: 1FDFE4FS0EDB17178

LH: 10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 28-JUL-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		RGASPARD	Jul 28, 2022 8:25:35 PM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Jul 28, 2022 8:25:39 PM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		RGASPARD	Jul 28, 2022 8:25:44 PM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Jul 28, 2022 8:25:49 PM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Jul 28, 2022 8:25:53 PM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Jul 28, 2022 8:25:58 PM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jul 28, 2022 8:26:02 PM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Jul 28, 2022 8:26:07 PM	No	
10,800	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Jul 28, 2022 8:26:12 PM	No	
10,900	INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Jul 28, 2022 8:26:17 PM	No	
11,100	INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Jul 28, 2022 8:26:22 PM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Jul 28, 2022 8:26:27 PM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Jul 28, 2022 8:26:32 PM	No	
20,200	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Jul 28, 2022 8:26:36 PM	No	
20,300	*RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Jul 28, 2022 8:26:41 PM	No	
20,400	PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Jul 28, 2022 8:26:47 PM	No	
20,500	*RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Jul 28, 2022 8:26:52 PM	No	
20,600	*RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Jul 28, 2022 8:26:56 PM	No	
20,700	INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Jul 28, 2022 8:27:01 PM	No	
20,800	INSPECT_High Idle Control	Done		RGASPARD	Jul 28, 2022 8:27:09 PM	No	
20,900	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Jul 28, 2022 8:27:14 PM	No	
21,000	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Jul 28, 2022 8:27:18 PM	No	
21,100	INSPECT_Parking Brake Operation	Done		RGASPARD	Jul 28, 2022 8:27:23 PM	No	
21,200	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Jul 28, 2022 8:27:28 PM	No	
21,300	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Jul 28, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					8:27:32 PM		
21,400	*RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Jul 28, 2022 8:27:45 PM	No	
21,500	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Jul 28, 2022 8:27:50 PM	No	
21,550	INSPECT_Driver Floor Area for Rust/Water Leaks	Done		RGASPARD	Jul 28, 2022 8:27:55 PM	No	
21,600	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Jul 28, 2022 8:28:00 PM	No	
21,700	INSPECT_Engine Fault Codes	Done		RGASPARD	Jul 28, 2022 8:28:04 PM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Jul 28, 2022 8:28:10 PM	No	
31,000	SSF (Street Side Front)	Done		RGASPARD	Jul 28, 2022 8:28:15 PM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Jul 28, 2022 8:28:20 PM	No	
31,020	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Jul 28, 2022 8:28:25 PM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jul 28, 2022 8:28:30 PM	No	
31,040	INSPECT_Wiper Blades, Arms	Done		RGASPARD	Jul 28, 2022 8:28:35 PM	No	
32,000	Engine Inspection	Done		RGASPARD	Jul 28, 2022 8:28:39 PM	No	
32,010	INSPECT_Hood, Springs and Props	Done		RGASPARD	Jul 28, 2022 8:28:47 PM	No	
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Jul 28, 2022 8:28:52 PM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Jul 28, 2022 8:28:56 PM	No	
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	na	RGASPARD	Jul 28, 2022 8:29:07 PM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Jul 28, 2022 8:29:18 PM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Jul 28, 2022 8:29:31 PM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Jul 28, 2022 8:29:35 PM	No	
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Jul 28, 2022 8:29:41 PM	No	
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Jul 28, 2022 8:29:54 PM	No	
32,100	INSPECT_Intake System	Done		RGASPARD	Jul 28, 2022 8:30:18 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Jul 28, 2022 8:30:54 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Jul 28, 2022 8:30:35 PM	No	
33,010	CSF (Curb Side Front)	Done		RGASPARD	Jul 28, 2022 8:30:59 PM	No	
33,020	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Jul 28, 2022 8:31:03 PM	No	
33,030	*RPT*INSPECT_ FRONT Springs, Shocks, Spring	Done		RGASPARD	Jul 28, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Shackles				8:31:21 PM		
33,040	INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jul 28, 2022 8:31:30 PM	No	
33,050	INSPECT_Wiper Blades, Arms	Done		RGASPARD	Jul 28, 2022 8:31:35 PM	No	
33,060	!FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	Jul 28, 2022 8:31:40 PM	No	
33,070	*RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	RGASPARD	Jul 28, 2022 8:31:49 PM	No	
33,080	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Jul 28, 2022 8:31:54 PM	No	
40,000	SECTION 4 - Interior Inspection	Done		RGASPARD	Jul 28, 2022 8:31:58 PM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Jul 28, 2022 8:32:03 PM	No	
40,200	INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		RGASPARD	Jul 28, 2022 8:32:19 PM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Jul 28, 2022 8:32:25 PM	No	
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	Jul 28, 2022 8:32:29 PM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Jul 28, 2022 8:32:40 PM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Jul 28, 2022 8:32:50 PM	No	
40,700	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Jul 28, 2022 8:32:55 PM	No	
40,800	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Jul 28, 2022 8:32:59 PM	No	
40,900	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Jul 28, 2022 8:33:04 PM	No	
41,000	INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Jul 28, 2022 8:41:17 PM	No	
41,100	INSPECT_CLEAN_AC Filter	Done	needs rear AC filter	RGASPARD	Jul 28, 2022 8:41:37 PM	Yes	55812636
41,200	INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		RGASPARD	Jul 28, 2022 8:41:51 PM	No	
41,300	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Jul 28, 2022 8:41:55 PM	No	
41,400	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Jul 28, 2022 8:42:00 PM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Jul 28, 2022 8:42:22 PM	No	
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Jul 28, 2022 8:42:27 PM	No	
50,200	INSPECT_Ball Joint Play	Done		RGASPARD	Jul 28, 2022 8:42:54 PM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Jul 28, 2022 8:42:59 PM	No	
50,400	LUBE_All Chassis Components	Done	na	RGASPARD	Jul 28, 2022 8:43:07 PM	No	
50,500	!FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Jul 28, 2022 8:43:11 PM	No	
50,700	INSPECT_Tire Condition	Done		RGASPARD	Jul 28, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					8:43:16 PM		
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Jul 28, 2022 8:43:21 PM	No	
50,900	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Jul 28, 2022 8:43:28 PM	No	
51,000	RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Jul 28, 2022 8:50:29 PM	No	
51,100	RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Jul 28, 2022 8:50:37 PM	No	
51,200	RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Jul 28, 2022 8:50:41 PM	No	
51,300	RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Jul 28, 2022 8:50:46 PM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Jul 28, 2022 8:50:51 PM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Jul 28, 2022 8:50:55 PM	No	
51,600	!FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Jul 28, 2022 8:51:00 PM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Jul 28, 2022 8:51:05 PM	No	
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Jul 28, 2022 8:51:11 PM	No	
51,900	INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	37 Inch		RGASPARD	Jul 28, 2022 8:51:19 PM	No	
52,000	INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	37 Inch		RGASPARD	Jul 28, 2022 8:51:27 PM	No	
52,100	INSPECT_Vibration Damper	Done		RGASPARD	Jul 28, 2022 8:51:31 PM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Jul 28, 2022 8:51:36 PM	No	
52,400	!FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Jul 28, 2022 8:51:41 PM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Jul 28, 2022 8:51:46 PM	No	
52,700	INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Jul 28, 2022 8:51:50 PM	No	
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Jul 28, 2022 8:51:55 PM	No	
52,900	INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Jul 28, 2022 8:52:00 PM	No	
53,000	!FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Jul 28, 2022 8:52:04 PM	No	
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Jul 28, 2022 8:52:09 PM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Jul 28, 2022 8:52:14 PM	No	
53,300	*RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Jul 28, 2022 8:52:19 PM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Jul 28, 2022 8:52:23 PM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Jul 28, 2022 8:52:28 PM	No	
53,600	INSPECT_Tire Condition	Done		RGASPARD	Jul 28, 2022 8:52:33 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Jul 28, 2022 8:52:37 PM	No	
53,800	INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Jul 28, 2022 8:52:42 PM	No	
53,900	INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Jul 28, 2022 8:52:48 PM	No	
54,000	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Jul 28, 2022 8:52:53 PM	No	
54,100	INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jul 28, 2022 8:52:57 PM	No	
54,200	RECORD_RRO-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Jul 28, 2022 8:57:11 PM	No	
54,300	RECORD_RRI-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Jul 28, 2022 8:57:17 PM	No	
54,400	RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jul 28, 2022 8:57:22 PM	No	
54,500	RECORD_RRI-Air Pressure (psi)	35 Pounds per Square Inch	right rear inside flat	RGASPARD	Jul 28, 2022 8:58:01 PM	Yes	55812636
54,600	RECORD_LRO-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Jul 28, 2022 8:58:48 PM	No	
54,700	RECORD_LRI-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Jul 28, 2022 8:58:53 PM	No	
54,800	RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jul 28, 2022 8:58:58 PM	No	
54,900	RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jul 28, 2022 8:59:03 PM	No	
55,000	!FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Jul 28, 2022 8:59:08 PM	No	
55,100	!FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Jul 28, 2022 8:59:13 PM	No	
55,200	!FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Jul 28, 2022 8:59:17 PM	No	
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	Jul 28, 2022 8:59:24 PM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	Jul 28, 2022 8:59:28 PM	No	
55,500	INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	Jul 28, 2022 8:59:35 PM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	Jul 28, 2022 8:59:40 PM	No	
55,700	!FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Jul 28, 2022 8:59:45 PM	No	
55,800	*RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Jul 28, 2022 8:59:49 PM	No	
55,900	*RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Jul 28, 2022 8:59:54 PM	No	
60,000	SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Jul 28, 2022 8:59:59 PM	No	
60,100	RECORD_Wheelchair Cycle Count	10845 Cycles		RGASPARD	Jul 28, 2022 9:01:31 PM	No	
60,200	CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Jul 28, 2022 9:01:36 PM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Jul 28, 2022 9:01:40 PM	No	
60,400	OPERATE_Lift thru Complete	Done		RGASPARD	Jul 28, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down				9:01:45 PM		
60,500	INSPECT_ Bridgeplate Operation	Done		RGASPARD	Jul 28, 2022 9:01:50 PM	No	
60,600	INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Jul 28, 2022 9:01:54 PM	No	
60,700	INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Jul 28, 2022 9:01:59 PM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Jul 28, 2022 9:02:04 PM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Jul 28, 2022 9:02:08 PM	No	
61,000	INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Jul 28, 2022 9:02:13 PM	No	
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Jul 28, 2022 9:02:18 PM	No	
61,200	INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Jul 28, 2022 9:02:23 PM	No	
61,300	INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Jul 28, 2022 9:02:28 PM	No	
61,400	INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Jul 28, 2022 9:02:32 PM	No	
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Jul 28, 2022 9:02:37 PM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Jul 28, 2022 9:02:42 PM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Jul 28, 2022 9:02:53 PM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Jul 28, 2022 9:03:04 PM	No	
61,900	CLEAN_Linkages and Mechanisms	Done		RGASPARD	Jul 28, 2022 9:03:09 PM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Jul 28, 2022 9:03:13 PM	No	
62,100	INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Jul 28, 2022 9:03:18 PM	No	
62,200	INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Jul 28, 2022 9:03:23 PM	No	
62,300	INSPECT_Bridgeplate Hinge	Done		RGASPARD	Jul 28, 2022 9:03:28 PM	No	
62,400	INSPECT_All Pivot Points	Done		RGASPARD	Jul 28, 2022 9:03:33 PM	No	
62,500	INSPECT_Cams and Slots	Done		RGASPARD	Jul 28, 2022 9:03:37 PM	No	
62,600	INSPECT_Rollers	Done		RGASPARD	Jul 28, 2022 9:03:42 PM	No	
62,700	INSPECT_All Linkages	Done		RGASPARD	Jul 28, 2022 9:03:47 PM	No	
70,000	SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		RGASPARD	Jul 28, 2022 9:03:51 PM	No	
70,300	INSPECT_Condition of Fuel Pressure Gauge	Done		RGASPARD	Jul 28, 2022 9:03:56 PM	No	
70,400	PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		RGASPARD	Jul 28, 2022 9:04:01 PM	No	
70,500	INSPECT_Tank test date, labels-Reference-ST.4	Done		RGASPARD	Jul 28, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	FMMVSS 304 & ANSI-CSA NGV2				9:04:05 PM		
70,600	INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		RGASPARD	Jul 28, 2022 9:04:10 PM	No	
70,700	INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		RGASPARD	Jul 28, 2022 9:04:15 PM	No	
70,800	INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		RGASPARD	Jul 28, 2022 9:04:19 PM	No	
80,000	SECTION 8 - PMI Report Completion	Done		RGASPARD	Jul 28, 2022 9:04:24 PM	No	
80,100	COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Jul 28, 2022 9:04:29 PM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Jul 28, 2022 9:04:34 PM	No	

LH: 20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 28-JUL-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		RGASPARD	Jul 28, 2022 9:06:23 PM	No	
101,000	FRA Change Oil Filters	Yes		RGASPARD	Jul 28, 2022 9:06:28 PM	No	
102,000	FRA Drain Engine Oil	Yes		RGASPARD	Jul 28, 2022 9:06:33 PM	No	
103,000	FRA Check Transmission Fluid	Done		RGASPARD	Jul 28, 2022 9:06:38 PM	No	
104,000	Lubricate Chassis	-	na	RGASPARD	Jul 28, 2022 9:06:43 PM	No	
105,000	Replace or Clean A/C Filters	Done		RGASPARD	Jul 28, 2022 9:06:48 PM	No	
107,000	FRA Change Primary Fuel Filter	No	na	RGASPARD	Jul 28, 2022 9:06:54 PM	No	
108,000	Lube all pivoting Mechanisms	Done		RGASPARD	Jul 28, 2022 9:06:58 PM	No	

LH: 5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 28-JUL-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		RGASPARD	Jul 28, 2022 7:39:10 PM	No	
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Jul 28, 2022 7:39:15 PM	No	
4	Are you wearing the appropriate PPE?	Done		RGASPARD	Jul 28, 2022 7:39:33 PM	No	
7	Have you performed the proper LOTO?	Done		RGASPARD	Jul 28, 2022 7:39:41 PM	No	
10	Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Jul 28, 2022 7:40:07 PM	No	
11	Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jul 28, 2022 7:40:15 PM	No	

FIRSTstudent
First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 55812645
Invoice Number: 55345-55812645

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
55345-LIGHT DUTY PMA		**VIN:**	1FDFE4FS0EDB17178
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Sep 2, 2022	12:00 AM
Started	Sep 7, 2022	
Completed	Sep 8, 2022	12:11 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	275,288	DH
System	275,096	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMA CAUSE:Service CORRECTION:Perform PMA Service oil filter B329 qty1 engine oil 10w30 qty 7qts add washer fluid check inflate tires to spec air filter PA4075 qty1

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note:	PERSONAL RISK ASSESSMENT
Reason for Repair:	SW - Shop Work Order
Work Accomplished:	06 - Inspect
Part Failure:	00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**

Activity Note:	Light Duty PMI
Reason for Repair:	05 - Inspection, Routine
Work Accomplished:	-
Part Failure:	-

Activity Comments

Parts Issued

WorkOrder: 55812645
Invoice Number: 55345-55812645

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
55345-LIGHT DUTY PMA		**VIN:**	1FDFE4FS0EDB17178
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Date	Part Number		Description	Qty.	Each	Extended
07-Sep-22	B329		FILTER, OIL, SPIN-ON	1.00	7.57	7.57
07-Sep-22	PA4075		FILTER, AIR	1.00	6.69	6.69

Labor Posted

Date	Technician	Hours	Rate	Extended
07-Sep-22	Gaspard,Ronald	1.80	0.00	0.00

Activity 10 Sub Total

Parts:	14.26
Labor:	0.00
Labor Hours: 1.80	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**14.26**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
08-Sep-22	Gaspard,Ronald	0.15	0.00	0.00
07-Sep-22	Gaspard,Ronald	0.22	0.00	0.00

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.37	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

WorkOrder 55812645 Grand Total

Parts:	14.26
Labor:	0.00
Labor Hours: 2.17	
Sublet Parts:	0.00
Sublet Labor:	0.00

WorkOrder: 55812645
Invoice Number: 55345-55812645

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
55345-LIGHT DUTY PMA		**VIN:**	1FDFE4FS0EDB17178
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

WorkOrder Grand Total **14.26**

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
55812645	8-Sep-22	275,288	WO	55345-LIGHT DUTY PMA
55907130	1-Sep-22	274,462	WO	driver side mirror broke
55854844	15-Aug-22	271,866	WO	WINDSHIELD WIPERS NOT MOVING
55829976	8-Aug-22	271,288	WO	Check Wheel Chair Lift

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
55907130	1-Sep-22	274,462	WO	driver side mirror broke

PH: Work Order: 55812645 Desc: 55345-LIGHT DUTY PMA
Equip: 4516-P Desc: Ford E450 Champion Challenger VIN: 1FDFE4FS0EDB17178

LH: 10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 07-SEP-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		RGASPARD	Sep 7, 2022 11:00:55 PM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Sep 7, 2022 11:00:59 PM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		RGASPARD	Sep 7, 2022 11:01:04 PM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Sep 7, 2022 11:01:09 PM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Sep 7, 2022 11:01:14 PM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Sep 7, 2022 11:01:19 PM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Sep 7, 2022 11:01:24 PM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Sep 7, 2022 11:01:29 PM	No	
10,800	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Sep 7, 2022 11:01:34 PM	No	
10,900	INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Sep 7, 2022 11:01:39 PM	No	
11,100	INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Sep 7, 2022 11:01:44 PM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Sep 7, 2022 11:01:50 PM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Sep 7, 2022 11:01:56 PM	No	
20,200	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Sep 7, 2022 11:02:00 PM	No	
20,300	*RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Sep 7, 2022 11:02:06 PM	No	
20,400	PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Sep 7, 2022 11:02:11 PM	No	
20,500	*RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Sep 7, 2022 11:02:18 PM	No	
20,600	*RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Sep 7, 2022 11:02:23 PM	No	
20,700	INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Sep 7, 2022 11:02:28 PM	No	
20,800	INSPECT_High Idle Control	Done		RGASPARD	Sep 7, 2022 11:04:03 PM	No	
20,900	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Sep 7, 2022 11:04:15 PM	No	
21,000	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Sep 7, 2022 11:04:20 PM	No	
21,100	INSPECT_Parking Brake Operation	Done		RGASPARD	Sep 7, 2022 11:04:26 PM	No	
21,200	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Sep 7, 2022 11:04:31 PM	No	
21,300	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Sep 7, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:04:37 PM		
21,400	*RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Sep 7, 2022 11:04:42 PM	No	
21,500	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Sep 7, 2022 11:04:50 PM	No	
21,550	INSPECT_Driver Floor Area for Rust/Water Leaks	Done		RGASPARD	Sep 7, 2022 11:04:55 PM	No	
21,600	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Sep 7, 2022 11:05:00 PM	No	
21,700	INSPECT_Engine Fault Codes	Done		RGASPARD	Sep 7, 2022 11:05:05 PM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Sep 7, 2022 11:05:10 PM	No	
31,000	SSF (Street Side Front)	Done		RGASPARD	Sep 7, 2022 11:05:15 PM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Sep 7, 2022 11:05:20 PM	No	
31,020	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Sep 7, 2022 11:05:55 PM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Sep 7, 2022 11:05:59 PM	No	
31,040	INSPECT_Wiper Blades, Arms	Done		RGASPARD	Sep 7, 2022 11:06:04 PM	No	
32,000	Engine Inspection	Done		RGASPARD	Sep 7, 2022 11:06:09 PM	No	
32,010	INSPECT_Hood, Springs and Props	Done		RGASPARD	Sep 7, 2022 11:06:14 PM	No	
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Sep 7, 2022 11:06:20 PM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Sep 7, 2022 11:06:24 PM	No	
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	Sep 7, 2022 11:06:55 PM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Sep 7, 2022 11:07:06 PM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Sep 7, 2022 11:07:11 PM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Sep 7, 2022 11:07:15 PM	No	
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Sep 7, 2022 11:07:21 PM	No	
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Sep 7, 2022 11:07:38 PM	No	
32,100	INSPECT_Intake System	Done		RGASPARD	Sep 7, 2022 11:07:43 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Sep 7, 2022 11:10:12 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Sep 7, 2022 11:07:52 PM	No	
33,010	CSF (Curb Side Front)	Done		RGASPARD	Sep 7, 2022 11:10:21 PM	No	
33,020	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Sep 7, 2022 11:10:28 PM	No	
33,030	*RPT*INSPECT_ FRONT Springs, Shocks, Spring	Done		RGASPARD	Sep 7, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Shackles				11:10:34 PM		
33,040	INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Sep 7, 2022 11:10:40 PM	No	
33,050	INSPECT_Wiper Blades, Arms	Done		RGASPARD	Sep 7, 2022 11:10:46 PM	No	
33,060	!FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	Sep 7, 2022 11:10:52 PM	No	
33,070	*RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	RGASPARD	Sep 7, 2022 11:11:04 PM	No	
33,080	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Sep 7, 2022 11:11:09 PM	No	
40,000	SECTION 4 - Interior Inspection	Done		RGASPARD	Sep 7, 2022 11:11:15 PM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Sep 7, 2022 11:11:21 PM	No	
40,200	INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		RGASPARD	Sep 7, 2022 11:11:26 PM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Sep 7, 2022 11:11:33 PM	No	
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	Sep 7, 2022 11:11:39 PM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Sep 7, 2022 11:11:45 PM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Sep 7, 2022 11:11:51 PM	No	
40,700	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Sep 7, 2022 11:11:58 PM	No	
40,800	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Sep 7, 2022 11:12:04 PM	No	
40,900	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Sep 7, 2022 11:12:10 PM	No	
41,000	INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Sep 7, 2022 11:12:15 PM	No	
41,100	INSPECT_CLEAN_AC Filter	Done		RGASPARD	Sep 7, 2022 11:12:23 PM	No	
41,200	INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		RGASPARD	Sep 7, 2022 11:12:30 PM	No	
41,300	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Sep 7, 2022 11:13:30 PM	No	
41,400	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Sep 7, 2022 11:13:35 PM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Sep 7, 2022 11:13:40 PM	No	
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Sep 7, 2022 11:13:45 PM	No	
50,200	INSPECT_Ball Joint Play	Done		RGASPARD	Sep 7, 2022 11:13:50 PM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Sep 7, 2022 11:13:55 PM	No	
50,400	LUBE_All Chassis Components	Done	na	RGASPARD	Sep 7, 2022 11:14:08 PM	No	
50,500	!FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Sep 7, 2022 11:14:14 PM	No	
50,700	INSPECT_Tire Condition	Done		RGASPARD	Sep 7, 2022 11:14:19 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Sep 7, 2022 11:14:25 PM	No	
50,900	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Sep 7, 2022 11:14:30 PM	No	
51,000	RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Sep 7, 2022 11:14:47 PM	No	
51,100	RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Sep 7, 2022 11:14:53 PM	No	
51,200	RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Sep 7, 2022 11:15:03 PM	No	
51,300	RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Sep 7, 2022 11:15:13 PM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Sep 7, 2022 11:15:17 PM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Sep 7, 2022 11:15:22 PM	No	
51,600	!FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Sep 7, 2022 11:15:27 PM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Sep 7, 2022 11:15:36 PM	No	
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Sep 7, 2022 11:15:41 PM	No	
51,900	INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	37 Inch		RGASPARD	Sep 7, 2022 11:15:48 PM	No	
52,000	INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	37 Inch		RGASPARD	Sep 7, 2022 11:15:53 PM	No	
52,100	INSPECT_Vibration Damper	Done		RGASPARD	Sep 7, 2022 11:15:58 PM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Sep 7, 2022 11:16:02 PM	No	
52,400	!FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Sep 7, 2022 11:16:07 PM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Sep 7, 2022 11:16:12 PM	No	
52,700	INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Sep 7, 2022 11:16:17 PM	No	
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Sep 7, 2022 11:16:22 PM	No	
52,900	INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Sep 7, 2022 11:16:26 PM	No	
53,000	!FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Sep 7, 2022 11:16:35 PM	No	
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Sep 7, 2022 11:16:45 PM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Sep 7, 2022 11:16:49 PM	No	
53,300	*RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Sep 7, 2022 11:18:36 PM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Sep 7, 2022 11:18:42 PM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Sep 7, 2022 11:18:47 PM	No	
53,600	INSPECT_Tire Condition	Done		RGASPARD	Sep 7, 2022 11:18:52 PM	No	
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Sep 7, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:18:58 PM		
53,800	INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Sep 7, 2022 11:19:04 PM	No	
53,900	INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Sep 7, 2022 11:19:10 PM	No	
54,000	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Sep 7, 2022 11:19:16 PM	No	
54,100	INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Sep 7, 2022 11:19:22 PM	No	
54,200	RECORD_RRO-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Sep 7, 2022 11:19:34 PM	No	
54,300	RECORD_RRI-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Sep 7, 2022 11:19:45 PM	No	
54,400	RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Sep 7, 2022 11:19:54 PM	No	
54,500	RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Sep 7, 2022 11:20:01 PM	No	
54,600	RECORD_LRO-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Sep 7, 2022 11:20:11 PM	No	
54,700	RECORD_LRI-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Sep 7, 2022 11:20:22 PM	No	
54,800	RECORD_LRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Sep 7, 2022 11:20:28 PM	No	
54,900	RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Sep 7, 2022 11:20:40 PM	No	
55,000	!FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Sep 7, 2022 11:20:44 PM	No	
55,100	!FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Sep 7, 2022 11:20:49 PM	No	
55,200	!FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Sep 7, 2022 11:20:54 PM	No	
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Sep 7, 2022 11:21:00 PM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Sep 7, 2022 11:21:05 PM	No	
55,500	INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	39 Inch		RGASPARD	Sep 7, 2022 11:21:22 PM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	39 Inch		RGASPARD	Sep 7, 2022 11:21:28 PM	No	
55,700	!FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Sep 7, 2022 11:21:33 PM	No	
55,800	*RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Sep 7, 2022 11:21:38 PM	No	
55,900	*RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Sep 7, 2022 11:21:43 PM	No	
60,000	SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Sep 7, 2022 11:21:47 PM	No	
60,100	RECORD_Wheelchair Cycle Count	11243 Cycles		RGASPARD	Sep 7, 2022 11:22:45 PM	No	
60,200	CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Sep 7, 2022 11:22:52 PM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Sep 7, 2022 11:22:56 PM	No	
60,400	OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	Sep 7, 2022 11:23:04 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,500	INSPECT_ Bridgeplate Operation	Done		RGASPARD	Sep 7, 2022 11:23:09 PM	No	
60,600	INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Sep 7, 2022 11:23:17 PM	No	
60,700	INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Sep 7, 2022 11:23:22 PM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Sep 7, 2022 11:23:29 PM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Sep 7, 2022 11:23:34 PM	No	
61,000	INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Sep 7, 2022 11:23:40 PM	No	
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Sep 7, 2022 11:24:21 PM	No	
61,200	INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Sep 7, 2022 11:24:31 PM	No	
61,300	INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Sep 7, 2022 11:24:36 PM	No	
61,400	INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Sep 7, 2022 11:24:41 PM	No	
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Sep 7, 2022 11:24:47 PM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Sep 7, 2022 11:24:52 PM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Sep 7, 2022 11:25:01 PM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Sep 7, 2022 11:25:06 PM	No	
61,900	CLEAN_Linkages and Mechanisms	Done		RGASPARD	Sep 7, 2022 11:25:11 PM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Sep 7, 2022 11:25:16 PM	No	
62,100	INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Sep 7, 2022 11:25:21 PM	No	
62,200	INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Sep 7, 2022 11:25:26 PM	No	
62,300	INSPECT_Bridgeplate Hinge	Done		RGASPARD	Sep 7, 2022 11:25:34 PM	No	
62,400	INSPECT_All Pivot Points	Done		RGASPARD	Sep 7, 2022 11:25:40 PM	No	
62,500	INSPECT_Cams and Slots	Done		RGASPARD	Sep 7, 2022 11:25:45 PM	No	
62,600	INSPECT_Rollers	Done		RGASPARD	Sep 7, 2022 11:25:50 PM	No	
62,700	INSPECT_All Linkages	Done		RGASPARD	Sep 7, 2022 11:25:55 PM	No	
70,000	SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		RGASPARD	Sep 7, 2022 11:26:00 PM	No	
70,300	INSPECT_Condition of Fuel Pressure Gauge	Done		RGASPARD	Sep 7, 2022 11:26:05 PM	No	
70,400	PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		RGASPARD	Sep 7, 2022 11:26:11 PM	No	
70,500	INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		RGASPARD	Sep 7, 2022 11:26:16 PM	No	
70,600	INSPECT_ Tank Lines to Ensure Secure Mounting,	Done		RGASPARD	Sep 7, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Insulation Against Vibration				11:26:21 PM		
70,700	INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		RGASPARD	Sep 7, 2022 11:26:26 PM	No	
70,800	INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		RGASPARD	Sep 7, 2022 11:26:31 PM	No	
80,000	SECTION 8 - PMI Report Completion	Done		RGASPARD	Sep 7, 2022 11:26:36 PM	No	
80,100	COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Sep 7, 2022 11:26:41 PM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Sep 7, 2022 11:26:46 PM	No	

LH: 20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 07-SEP-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		RGASPARD	Sep 7, 2022 11:47:19 PM	No	
101,000	FRA Change Oil Filters	Yes		RGASPARD	Sep 7, 2022 11:47:24 PM	No	
102,000	FRA Drain Engine Oil	Yes		RGASPARD	Sep 7, 2022 11:47:29 PM	No	
103,000	FRA Check Transmission Fluid	Done		RGASPARD	Sep 7, 2022 11:47:34 PM	No	
104,000	Lubricate Chassis	-	na	RGASPARD	Sep 7, 2022 11:47:41 PM	No	
105,000	Replace or Clean A/C Filters	Done		RGASPARD	Sep 7, 2022 11:47:46 PM	No	
107,000	FRA Change Primary Fuel Filter	No	na	RGASPARD	Sep 7, 2022 11:47:51 PM	No	
108,000	Lube all pivoting Mechanisms	Done		RGASPARD	Sep 7, 2022 11:47:58 PM	No	

LH: 5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 07-SEP-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		RGASPARD	Sep 7, 2022 9:57:37 PM	No	
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Sep 7, 2022 9:57:41 PM	No	
4	Are you wearing the appropriate PPE?	Done		RGASPARD	Sep 7, 2022 9:57:46 PM	No	
7	Have you performed the proper LOTO?	Done		RGASPARD	Sep 7, 2022 9:57:51 PM	No	
10	Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Sep 7, 2022 9:57:56 PM	No	
11	Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Sep 7, 2022 9:58:01 PM	No	

FIRSTstudent
First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 56255196
Invoice Number: 55345-56255196

Client Department:
MRC: 55345M
WO Desc:
55345-MEDIUM DUTY PMA
Requested By: TDELVA
Created By: TDELVA
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4516-P
Ford E450 Champion Challenger
VIN: 1FDFE4FS0EDB17178
Status: 32
Priority: 3
Driver:
Phone:
ETA:

Chronology		
Reported	Apr 17, 2023	12:00 AM
Started	Apr 19, 2023	
Completed	Apr 19, 2023	8:21 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	283,956	DH
System	283,956	DH

WorkOrder Notes

Line	Comment
10	Pma Preventive maintenance Performed PMA completed

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: Personal Risk Assessment
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
19-Apr-23	B329		FILTER, OIL, SPIN-ON SEE P550965	1.00	2.51	2.51

Labor Posted

WorkOrder: 56255196
Invoice Number: 55345-56255196

Client Department:
MRC: 55345M
WO Desc:
55345-MEDIUM DUTY PMA
Requested By: TDELVA
Created By: TDELVA
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4516-P
Ford E450 Champion Challenger
VIN: 1FDFE4FS0EDB17178
Status: 32
Priority: 3
Driver:
Phone:
ETA:

Date	Technician	Hours	Rate	Extended
19-Apr-23	Pierre,Hubert J	1.78	65.00	115.70
19-Apr-23	Pierre,Hubert J	0.40	65.00	26.00

Activity 10 Sub Total

Parts:	2.51
Labor:	141.70
Labor Hours: 2.18	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**144.21**

Activity: 20 **999/999/999 TOTAL VEHICLE**

Activity Note: Medium Duty PMA Service
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
19-Apr-23	Pierre,Hubert J	0.37	65.00	24.05

Activity 20 Sub Total

Parts:	0.00
Labor:	24.05
Labor Hours: 0.37	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**24.05**

WorkOrder 56255196 Grand Total

Parts:	2.51
Labor:	165.75
Labor Hours: 2.55	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	**168.26**

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
56255196	19-Apr-23	283,956	WO	55345-MEDIUM DUTY PMA
56608747	11-Apr-23	283,157	WO	BLOWER MOTOR NOT BLOWING ON ANY MODE. LOST POWER

WorkOrder: 56255196
Invoice Number: 55345-56255196

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
55345-MEDIUM DUTY PMA		**VIN:**	1FDFE4FS0EDB17178
Requested By:	TDELVA	**Status:**	32
Created By:	TDELVA	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

WorkOrder	Date Completed	Life Meter	Class	Description
56550372	29-Mar-23	281,262	WO	Scheduled
56546920	28-Mar-23	281,052	WO	Scheduled

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description

PH: Work Order: 56255196 Desc: 55345-MEDIUM DUTY PMA
Equip: 4516-P Desc: Ford E450 Champion Challenger VIN: 1FDFE4FS0EDB17178

LH: 10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: HPIERRE Performed on: 19-APR-23

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		HPIERRE	Apr 19, 2023 7:50:43 AM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		HPIERRE	Apr 19, 2023 7:50:43 AM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		HPIERRE	Apr 19, 2023 7:50:43 AM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		HPIERRE	Apr 19, 2023 7:50:42 AM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		HPIERRE	Apr 19, 2023 7:50:42 AM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		HPIERRE	Apr 19, 2023 7:50:44 AM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Apr 19, 2023 7:50:43 AM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		HPIERRE	Apr 19, 2023 7:50:43 AM	No	
10,800	CHECK_All Destination Signage	Done		HPIERRE	Apr 19, 2023 7:50:43 AM	No	
10,900	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		HPIERRE	Apr 19, 2023 7:37:59 AM	No	
11,000	INSPECT_Fuel Tank Cap, and Doors	Done		HPIERRE	Apr 19, 2023 7:50:43 AM	No	
11,200	INSPECT_License Plate, Bracket, Bumpers	Done		HPIERRE	Apr 19, 2023 7:50:43 AM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		HPIERRE	Apr 19, 2023 7:50:44 AM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		HPIERRE	Apr 19, 2023 7:50:44 AM	No	
20,200	CHECK_Public Address System	Done		HPIERRE	Apr 19, 2023 7:50:44 AM	No	
20,300	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		HPIERRE	Apr 19, 2023 7:50:44 AM	No	
20,400	*RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		HPIERRE	Apr 19, 2023 7:38:15 AM	No	
20,500	PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		HPIERRE	Apr 19, 2023 7:50:44 AM	No	
20,600	RECORD_Brake Performance Test E.T.	60 Second*		HPIERRE	Apr 19, 2023 7:50:44 AM	No	
20,700	RECORD_Brake Performance Test Speed	60 Miles per Hour		HPIERRE	Apr 19, 2023 7:50:44 AM	No	
20,800	RECORD_Brake Performance Test Distance	6 FEET		HPIERRE	Apr 19, 2023 7:50:44 AM	No	
20,900	RECORD_Brake Performance Test Adj Distance (20mph)	6 FEET		HPIERRE	Apr 19, 2023 7:50:44 AM	No	
21,000	RECORD_Brake Performance Test Ave GX	90 Gravitational Force		HPIERRE	Apr 19, 2023 7:50:44 AM	No	
21,100	ADD_Image of Brake Test Results to PM Work Order	Done		HPIERRE	Apr 19, 2023 7:50:44 AM	No	
21,200	*RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		HPIERRE	Apr 19, 2023	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					7:39:32 AM		
21,300	*RPT*INSPECT_Windshields, Sun Visors	Done		HPIERRE	Apr 19, 2023 7:39:41 AM	No	
21,400	INSPECT_Wiper/Washer Operation, Condition	Done		HPIERRE	Apr 19, 2023 7:50:44 AM	No	
21,500	INSPECT_High Idle Control	Done		HPIERRE	Apr 19, 2023 7:50:44 AM	No	
21,600	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		HPIERRE	Apr 19, 2023 7:39:48 AM	No	
21,700	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		HPIERRE	Apr 19, 2023 7:39:54 AM	No	
21,800	INSPECT_Parking Brake Operation	Done		HPIERRE	Apr 19, 2023 7:50:45 AM	No	
21,900	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		HPIERRE	Apr 19, 2023 7:50:45 AM	No	
22,000	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		HPIERRE	Apr 19, 2023 7:50:45 AM	No	
22,100	*RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		HPIERRE	Apr 19, 2023 7:40:54 AM	No	
22,200	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		HPIERRE	Apr 19, 2023 7:50:45 AM	No	
22,250	INSPECT_Driver Floor Area for Water Leaks	Done		HPIERRE	Apr 19, 2023 7:50:46 AM	No	
22,300	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		HPIERRE	Apr 19, 2023 7:41:39 AM	No	
22,400	INSPECT_Engine Fault Codes	Done		HPIERRE	Apr 19, 2023 7:50:46 AM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION	Done		HPIERRE	Apr 19, 2023 7:50:46 AM	No	
31,000	SSF (Street Side Front)	Done		HPIERRE	Apr 19, 2023 7:50:47 AM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Apr 19, 2023 7:41:47 AM	No	
31,020	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Apr 19, 2023 7:41:51 AM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Apr 19, 2023 7:50:47 AM	No	
31,040	INSPECT_Wiper Blades, Arms	Done		HPIERRE	Apr 19, 2023 7:50:49 AM	No	
32,000	Engine Inspection	Done		HPIERRE	Apr 19, 2023 7:50:49 AM	No	
32,010	INSPECT_Hood, Springs and Props	Done		HPIERRE	Apr 19, 2023 7:50:49 AM	No	
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		HPIERRE	Apr 19, 2023 7:50:49 AM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done		HPIERRE	Apr 19, 2023 7:50:49 AM	No	
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		HPIERRE	Apr 19, 2023 7:50:49 AM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	190 Degree Fahrenheit		HPIERRE	Apr 19, 2023 7:50:50 AM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		HPIERRE	Apr 19, 2023 7:50:50 AM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		HPIERRE	Apr 19, 2023 7:42:27 AM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		HPIERRE	Apr 19, 2023 7:42:31 AM	No	
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		HPIERRE	Apr 19, 2023 7:42:35 AM	No	
32,100	INSPECT_Intake System	Done		HPIERRE	Apr 19, 2023 7:50:50 AM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12 Volt*		HPIERRE	Apr 19, 2023 7:42:48 AM	No	
33,000	CSF (Curb Side Front)	Done		HPIERRE	Apr 19, 2023 7:50:50 AM	No	
33,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Apr 19, 2023 7:42:55 AM	No	
33,020	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Apr 19, 2023 7:42:58 AM	No	
33,030	INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Apr 19, 2023 7:50:50 AM	No	
33,040	INSPECT_Wiper Blades, Arms	Done		HPIERRE	Apr 19, 2023 7:50:50 AM	No	
33,050	!FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		HPIERRE	Apr 19, 2023 7:50:51 AM	No	
33,060	*RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	12 Volt*		HPIERRE	Apr 19, 2023 7:43:10 AM	No	
33,070	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		HPIERRE	Apr 19, 2023 7:50:51 AM	No	
40,000	SECTION 4 - Interior Inspection	Done		HPIERRE	Apr 19, 2023 7:50:51 AM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		HPIERRE	Apr 19, 2023 7:43:18 AM	No	
40,200	INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		HPIERRE	Apr 19, 2023 7:50:51 AM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		HPIERRE	Apr 19, 2023 7:50:51 AM	No	
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		HPIERRE	Apr 19, 2023 7:50:51 AM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		HPIERRE	Apr 19, 2023 7:50:51 AM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		HPIERRE	Apr 19, 2023 7:50:51 AM	No	
40,700	CHECK_Passenger Stop Request System	Done		HPIERRE	Apr 19, 2023 7:50:51 AM	No	
40,800	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		HPIERRE	Apr 19, 2023 7:44:21 AM	No	
40,900	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		HPIERRE	Apr 19, 2023 7:44:25 AM	No	
41,000	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		HPIERRE	Apr 19, 2023 7:50:51 AM	No	
41,100	INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		HPIERRE	Apr 19, 2023 7:50:52 AM	No	
41,200	INSPECT_CLEAN_AC Filter	Done		HPIERRE	Apr 19, 2023 7:50:51 AM	No	
41,300	INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		HPIERRE	Apr 19, 2023 7:50:52 AM	No	
41,400	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done		HPIERRE	Apr 19, 2023 7:44:35 AM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
41,500	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done		HPIERRE	Apr 19, 2023 7:44:40 AM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done		HPIERRE	Apr 19, 2023 7:50:52 AM	No	
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		HPIERRE	Apr 19, 2023 7:44:45 AM	No	
50,200	INSPECT_Ball Joint Play	Done		HPIERRE	Apr 19, 2023 7:50:52 AM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		HPIERRE	Apr 19, 2023 7:50:52 AM	No	
50,400	LUBE_All Chassis Components	Done		HPIERRE	Apr 19, 2023 7:50:52 AM	No	
50,500	!FRA!CHANGE_Engine oil,filters	Done		HPIERRE	Apr 19, 2023 7:50:52 AM	No	
50,700	INSPECT_Tire Condition	Done		HPIERRE	Apr 19, 2023 7:57:13 AM	No	
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done	need rotate	HPIERRE	Apr 19, 2023 7:50:52 AM	Yes	56634077
50,900	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Apr 19, 2023 7:50:52 AM	No	
51,000	RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		HPIERRE	Apr 19, 2023 7:50:53 AM	No	
51,100	RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Apr 19, 2023 7:50:53 AM	No	
51,200	RECORD_RF-Tire Tread Depth (32nds)	7 32nds of an inch		HPIERRE	Apr 19, 2023 7:50:53 AM	No	
51,300	RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Apr 19, 2023 7:50:54 AM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		HPIERRE	Apr 19, 2023 7:50:54 AM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		HPIERRE	Apr 19, 2023 7:50:55 AM	No	
51,600	!FRA!INSPECT_ Front Brake Assemblies	Done		HPIERRE	Apr 19, 2023 7:50:55 AM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	Apr 19, 2023 7:50:56 AM	No	
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	Apr 19, 2023 7:50:56 AM	No	
51,900	INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	20 Inch		HPIERRE	Apr 19, 2023 7:50:56 AM	No	
52,000	INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	20 Inch		HPIERRE	Apr 19, 2023 7:50:56 AM	No	
52,100	INSPECT_Vibration Damper	Done		HPIERRE	Apr 19, 2023 7:50:56 AM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		HPIERRE	Apr 19, 2023 7:50:56 AM	No	
52,400	!FRA!INSPECT_ Starter Mounting	Done		HPIERRE	Apr 19, 2023 7:50:57 AM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		HPIERRE	Apr 19, 2023 7:50:57 AM	No	
52,700	INSPECT_ Engine, Transmission Mounts	Done		HPIERRE	Apr 19, 2023 7:52:28 AM	No	
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		HPIERRE	Apr 19, 2023 7:50:57 AM	No	
52,900	INSPECT_ Shift Cable Adjustment - All Transmissions	Done		HPIERRE	Apr 19, 2023	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					7:50:57 AM		
53,000	!FRA!INSPECT_ Transmission Breather and Clean	Done		HPIERRE	Apr 19, 2023 7:50:57 AM	No	
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		HPIERRE	Apr 19, 2023 7:47:48 AM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		HPIERRE	Apr 19, 2023 7:47:54 AM	No	
53,300	*RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		HPIERRE	Apr 19, 2023 7:47:58 AM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		HPIERRE	Apr 19, 2023 7:48:01 AM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		HPIERRE	Apr 19, 2023 7:50:57 AM	No	
53,600	INSPECT_Tire Condition	Done		HPIERRE	Apr 19, 2023 7:50:57 AM	No	
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Apr 19, 2023 7:50:58 AM	No	
53,800	INSPECT_ Mismatched Tire Tread, Casing Design	Done		HPIERRE	Apr 19, 2023 7:50:58 AM	No	
53,900	INSPECT_Dual Mating Tires w/Square	Done		HPIERRE	Apr 19, 2023 7:50:58 AM	No	
54,000	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Apr 19, 2023 7:50:58 AM	No	
54,100	INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Apr 19, 2023 7:50:58 AM	No	
54,200	RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Apr 19, 2023 7:50:58 AM	No	
54,300	RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Apr 19, 2023 7:50:58 AM	No	
54,400	RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Apr 19, 2023 7:50:58 AM	No	
54,500	RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Apr 19, 2023 7:50:58 AM	No	
54,600	RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Apr 19, 2023 7:50:59 AM	No	
54,700	RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Apr 19, 2023 7:50:59 AM	No	
54,800	RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Apr 19, 2023 7:50:59 AM	No	
54,900	RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Apr 19, 2023 7:50:59 AM	No	
55,000	!FRA!INSPECT_ REAR Brake Assemblies	Done		HPIERRE	Apr 19, 2023 7:50:59 AM	No	
55,100	!FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		HPIERRE	Apr 19, 2023 7:50:59 AM	No	
55,200	!FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		HPIERRE	Apr 19, 2023 7:50:59 AM	No	
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		HPIERRE	Apr 19, 2023 7:50:59 AM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		HPIERRE	Apr 19, 2023 7:50:59 AM	No	
55,500	INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	22 Inch		HPIERRE	Apr 19, 2023 7:50:59 AM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	22 Inch		HPIERRE	Apr 19, 2023 7:51:00 AM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
55,700	CHECK_Spring Brake Inversion Valve	Done		HPIERRE	Apr 19, 2023 7:51:00 AM	No	
55,800	CHECK_Double Check Valve - Primary, Secondary	Done		HPIERRE	Apr 19, 2023 7:51:00 AM	No	
55,900	!FRA!INSPECT_ Under Body Exhaust System	Done		HPIERRE	Apr 19, 2023 7:51:00 AM	No	
56,000	*RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		HPIERRE	Apr 19, 2023 7:49:30 AM	No	
56,100	*RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		HPIERRE	Apr 19, 2023 7:51:00 AM	No	
60,000	SECTION 6 - Wheelchair Inspection	Done		HPIERRE	Apr 19, 2023 7:51:00 AM	No	
60,100	RECORD_Wheelchair Cycle Count	33352 Cycles		HPIERRE	Apr 19, 2023 7:51:00 AM	No	
60,200	CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		HPIERRE	Apr 19, 2023 7:51:00 AM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		HPIERRE	Apr 19, 2023 7:51:00 AM	No	
60,400	OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		HPIERRE	Apr 19, 2023 7:51:00 AM	No	
60,500	INSPECT_ Bridgeplate Operation	Done		HPIERRE	Apr 19, 2023 7:51:00 AM	No	
60,600	INSPECT_All Pivot Points for Wear and Looseness	Done		HPIERRE	Apr 19, 2023 7:51:01 AM	No	
60,700	INSPECT_Rollers for Wear and Smooth Rotation	Done		HPIERRE	Apr 19, 2023 7:51:01 AM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	Done		HPIERRE	Apr 19, 2023 7:51:01 AM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	Done		HPIERRE	Apr 19, 2023 7:51:01 AM	No	
61,000	INSPECT_Cable Condition (If Applicable)	Done		HPIERRE	Apr 19, 2023 7:51:01 AM	No	
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		HPIERRE	Apr 19, 2023 7:51:01 AM	No	
61,200	INSPECT_Electrical Connections and Routing of Wires and Cables	Done		HPIERRE	Apr 19, 2023 7:51:01 AM	No	
61,300	INSPECT_Operation and Adjustment of All Safety Switches	Done		HPIERRE	Apr 19, 2023 7:51:01 AM	No	
61,400	INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		HPIERRE	Apr 19, 2023 7:51:02 AM	No	
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		HPIERRE	Apr 19, 2023 7:51:02 AM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		HPIERRE	Apr 19, 2023 7:51:02 AM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		HPIERRE	Apr 19, 2023 7:51:02 AM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		HPIERRE	Apr 19, 2023 7:51:02 AM	No	
61,900	CLEAN_Linkages and Mechanisms	Done		HPIERRE	Apr 19, 2023 7:51:02 AM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		HPIERRE	Apr 19, 2023 7:51:02 AM	No	
62,100	INSPECT_Emergency Platform Release Mechanism	Done		HPIERRE	Apr 19, 2023 7:51:02 AM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
62,200	INSPECT_Platform Barrier Latch Mechanism	Done		HPIERRE	Apr 19, 2023 7:51:03 AM	No	
62,300	INSPECT_Bridgeplate Hinge	Done		HPIERRE	Apr 19, 2023 7:51:04 AM	No	
62,400	INSPECT_All Pivot Points	Done		HPIERRE	Apr 19, 2023 7:51:04 AM	No	
62,500	INSPECT_Cams and Slots	Done		HPIERRE	Apr 19, 2023 7:51:04 AM	No	
62,600	INSPECT_Rollers	Done		HPIERRE	Apr 19, 2023 7:51:04 AM	No	
62,700	INSPECT_All Linkages	Done		HPIERRE	Apr 19, 2023 7:51:04 AM	No	
70,000	SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		HPIERRE	Apr 19, 2023 7:51:04 AM	No	
70,300	INSPECT_Condition of Fuel Pressure Gauge	Done		HPIERRE	Apr 19, 2023 7:51:04 AM	No	
70,400	PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		HPIERRE	Apr 19, 2023 7:51:04 AM	No	
70,500	INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		HPIERRE	Apr 19, 2023 7:51:04 AM	No	
70,600	INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		HPIERRE	Apr 19, 2023 7:51:04 AM	No	
70,700	INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		HPIERRE	Apr 19, 2023 7:51:04 AM	No	
70,800	INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		HPIERRE	Apr 19, 2023 7:51:04 AM	No	
80,000	SECTION 8 - PMI Report Completion	Done		HPIERRE	Apr 19, 2023 7:51:05 AM	No	
80,100	COMPLETE_PM Report; Follow-ups	Done		HPIERRE	Apr 19, 2023 7:51:05 AM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		HPIERRE	Apr 19, 2023 7:51:05 AM	No	

LH: 20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: HPIERRE Performed on: 19-APR-23

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		HPIERRE	Apr 19, 2023 7:36:29 AM	No	
101,000	FRA Change Oil Filters	Yes		HPIERRE	Apr 19, 2023 7:36:33 AM	No	
102,000	FRA Drain Engine Oil	Yes		HPIERRE	Apr 19, 2023 7:36:33 AM	No	
103,000	FRA Check Transmission Fluid	Done		HPIERRE	Apr 19, 2023 7:36:33 AM	No	
104,000	Lubricate Chassis	Done		HPIERRE	Apr 19, 2023 7:36:33 AM	No	
105,000	Replace or Clean A/C Filters	Done		HPIERRE	Apr 19, 2023 7:36:33 AM	No	
106,000	Drain Water from Fuel Water Separator (where applicable)	Done		HPIERRE	Apr 19, 2023 7:36:33 AM	No	
107,000	FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Apr 19, 2023 7:36:33 AM	No	
108,000	Lube all pivoting Mechanisms	Done		HPIERRE	Apr 19, 2023 7:36:33 AM	No	

LH: 5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 19-APR-23

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		HPIERRE	Apr 19, 2023 7:35:12 AM	No	
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Apr 19, 2023 7:35:20 AM	No	
4	Are you wearing the appropriate PPE?	Done		HPIERRE	Apr 19, 2023 7:35:20 AM	No	
7	Have you performed the proper LOTO?	Done		HPIERRE	Apr 19, 2023 7:35:20 AM	No	
10	Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Apr 19, 2023 7:35:20 AM	No	
11	Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Apr 19, 2023 7:35:20 AM	No	

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52765954
Invoice Number: 55345-52765954

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
PM A		**VIN:**	1FDFE4FS0EDB17178
Requested By:	DARTHURS	**Status:**	40
Created By:	DARTHURS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Oct 2, 2019	2:22 PM
Started	Oct 3, 2019	
Completed	Oct 3, 2019	12:13 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	191,713	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service CAUSE: Service due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check Brakes. Clean batteries. Parts # B329 Qty (1) Oil 5W20 Qty (7.0) Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
03-Oct-19	Arthurs,Durvin	1.50	65.00	97.50

Activity 10 Sub Total

Parts:	0.00
Labor:	97.50
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
03-Oct-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51682519
Invoice Number: 55345-51682519

Client Department:			
MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
PM B		**VIN:**	1FDFE4FS0EDB17178
Requested By:	CVERGARA	**Status:**	32
Created By:	CVERGARA	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Sep 28, 2018	11:43 AM
Started	Sep 29, 2018	
Completed	Sep 29, 2018	12:28 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	135,010	DH
System	135,229	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmB CAUSE: Service CORRECTION:Perform pmB Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
29-Sep-18	Gaspard,Ronald	1.55	0.00	0.00

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 1.55	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
29-Sep-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52188896
Invoice Number: 55345-52188896

Client Department:
MRC: 55345M
Equipment: 4516-P
WO Desc:
PM B
Ford E450 Champion Challenger
VIN: 1FDFE4FS0EDB17178
Requested By: RGASPARD
Status: 32
Created By: RGASPARD
Priority: 1
Class: WO
Driver:
Arrangement: Unassigned
Phone:
Potential Warranty: No
ETA:

Chronology		
Reported	Mar 13, 2019	9:46 AM
Started	Mar 13, 2019	
Completed	Mar 14, 2019	10:00 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	161,324	DH
System	161,324	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMB CAUSE: Service due CORRECTION: Performed and completed pmB Changed engine oil and replaced engine oil filter Lube all Pivoting Points

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
13-Mar-19	Delva,Terry	1.65	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.65	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
13-Mar-19	B329		FILTER, OIL (FGA0000399/FSC0000399)	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52658763
Invoice Number: 55345-52658763

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
PM B		**VIN:**	1FDFE4FS0EDB17178
Requested By:	DARTHURS	**Status:**	40
Created By:	DARTHURS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Sep 6, 2019	11:44 AM
Started	Sep 6, 2019	
Completed	Sep 7, 2019	12:00 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	187,381	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMB Service CAUSE: Service due by Mileage. CORRECTION: Change Oil & Filter Lube all Pivoting Points Check Brakes . Clean batteries. Parts # B329 Qty (1) Oil 5W20 Qty (7.0) Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
06-Sep-19	Arthurs,Durvin	2.00	65.00	130.00

Activity 10 Sub Total

Parts:	0.00
Labor:	130.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**130.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
06-Sep-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53206482
Invoice Number: 55345-53206482

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
PM B		**VIN:**	1FDFE4FS0EDB17178
Requested By:	VAMRITTEEMAL	**Status:**	40
Created By:	VAMRITTEEMAL	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Feb 20, 2020	10:14 AM
Started	Feb 20, 2020	
Completed	Feb 20, 2020	7:08 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	213,570	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMB SERVICE CAUSE: PREVENTIVE MAINTENANCE CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
20-Feb-20	AMRIT TEEMAL,VISHNU	0.43	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.43	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
20-Feb-20	P9600		FILTER, OIL	1.00	3.45	3.45
20-Feb-20	P9600		FILTER, OIL	-1.00	3.45	-3.45

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53876299
Invoice Number: 55345-53876299

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
55345-LIGHT DUTY PMB		**VIN:**	1FDFE4FS0EDB17178
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Oct 22, 2020	12:00 AM
Started	Oct 22, 2020	
Completed	Oct 22, 2020	11:11 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	239,014	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMB Service CAUSE: Service Due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points . Check brakes. Clean batteries.. replace air filter. Parts # B329 Qty (1) Parts # PA 4075 Qty (1) Oil 10W20 Qty (7) Qt

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note:	PERSONAL RISK ASSESSMENT
Reason for Repair:	SW - Shop Work Order
Work Accomplished:	06 - Inspect
Part Failure:	00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note:	Light Duty PMI
Reason for Repair:	08 - Preventive Maintenance
Work Accomplished:	-
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

FIRSTstudent
First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 55463093
Invoice Number: 55345-55463093

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
55345-LIGHT DUTY PMB		**VIN:**	1FDFE4FS0EDB17178
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jun 9, 2022	12:00 AM
Started	Jun 15, 2022	
Completed	Jun 15, 2022	10:07 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	265,639	DH
System	265,109	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMB Service CAUSE: Service due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check Brakes. Clean Batteries parts # B329 Qty (1) Oil 10W30 Qty (7,0) Qt

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**

Activity Note: Light Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder: 55463093
Invoice Number: 55345-55463093

Client Department:
MRC: 55345M
Equipment: 4516-P
WO Desc:
55345-LIGHT DUTY PMB
Ford E450 Champion Challenger
VIN: 1FDFE4FS0EDB17178
Requested By: RGASPARD
Status: 40
Created By: RGASPARD
Priority: 3
Class: WO
Driver:
Arrangement: Unassigned
Phone:
Potential Warranty: No
ETA:

Date	Technician	Hours	Rate	Extended
15-Jun-22	Arthurs,Durvin	1.88	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.88	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
15-Jun-22	B329		FILTER, OIL, SPIN-ON	1.00	2.14	2.14

Labor Posted

Date	Technician	Hours	Rate	Extended
15-Jun-22	Arthurs,Durvin	0.40	0.00	0.00

Activity 20 Sub Total

Parts:	2.14
Labor:	0.00
Labor Hours: 0.40	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.14**

WorkOrder 55463093 Grand Total

Parts:	2.14
Labor:	0.00
Labor Hours: 2.28	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	**2.14**

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
55463093	15-Jun-22	265,639	WO	55345-LIGHT DUTY PMB
55688557	13-Jun-22	265,315	WO	REAR AC NOT WORKING

WorkOrder: 55463093
Invoice Number: 55345-55463093

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
55345-LIGHT DUTY PMB		**VIN:**	1FDFE4FS0EDB17178
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

WorkOrder	Date Completed	Life Meter	Class	Description
55657525	2-Jun-22	264,137	WO	Wheelchair Lift
55641798	27-May-22	263,542	WO	55345 PER DVIR (Check Rear AC)
54648786	19-May-22	262,738	WO	QCC FLEET INSPECTION
55603843	15-May-22	262,318	WO	TRANSMISSION NOT SHIFTING PROPERLY

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description

PH: Work Order: 55463093 Desc: 55345-LIGHT DUTY PMB
Equip: 4516-P Desc: Ford E450 Champion Challenger VIN: 1FDFE4FS0EDB17178

LH: 10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: DARTHURS Performed on: 15-JUN-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		DARTHURS	Jun 15, 2022 9:08:27 PM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		DARTHURS	Jun 15, 2022 9:08:32 PM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		DARTHURS	Jun 15, 2022 9:08:37 PM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		DARTHURS	Jun 15, 2022 9:08:41 PM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		DARTHURS	Jun 15, 2022 9:08:57 PM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		DARTHURS	Jun 15, 2022 9:09:05 PM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jun 15, 2022 9:09:09 PM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		DARTHURS	Jun 15, 2022 9:09:18 PM	No	
10,800	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		DARTHURS	Jun 15, 2022 9:09:24 PM	No	
10,900	INSPECT_Fuel Tank Cap, and Doors	Done		DARTHURS	Jun 15, 2022 9:09:29 PM	No	
11,100	INSPECT_License Plate, Bracket, Bumpers	Done		DARTHURS	Jun 15, 2022 9:09:34 PM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		DARTHURS	Jun 15, 2022 9:09:39 PM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		DARTHURS	Jun 15, 2022 9:09:45 PM	No	
20,200	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		DARTHURS	Jun 15, 2022 9:09:50 PM	No	
20,300	*RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		DARTHURS	Jun 15, 2022 9:09:58 PM	No	
20,400	PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		DARTHURS	Jun 15, 2022 9:10:04 PM	No	
20,500	*RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		DARTHURS	Jun 15, 2022 9:10:09 PM	No	
20,600	*RPT*INSPECT_Windshields, Sun Visors	Done		DARTHURS	Jun 15, 2022 9:10:14 PM	No	
20,700	INSPECT_Wiper/Washer Operation, Condition	Done	Washer inop not Spraying	DARTHURS	Jun 15, 2022 9:11:08 PM	No	
20,800	INSPECT_High Idle Control	Done		DARTHURS	Jun 15, 2022 9:11:13 PM	No	
20,900	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		DARTHURS	Jun 15, 2022 9:11:19 PM	No	
21,000	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		DARTHURS	Jun 15, 2022 9:11:25 PM	No	
21,100	INSPECT_Parking Brake Operation	Done		DARTHURS	Jun 15, 2022 9:11:30 PM	No	
21,200	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		DARTHURS	Jun 15, 2022 9:11:35 PM	No	
21,300	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		DARTHURS	Jun 15, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					9:11:40 PM		
21,400	*RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		DARTHURS	Jun 15, 2022 9:11:49 PM	No	
21,500	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		DARTHURS	Jun 15, 2022 9:11:56 PM	No	
21,550	INSPECT_Driver Floor Area for Rust/Water Leaks	Done		DARTHURS	Jun 15, 2022 9:12:01 PM	No	
21,600	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		DARTHURS	Jun 15, 2022 9:12:11 PM	No	
21,700	INSPECT_Engine Fault Codes	Done		DARTHURS	Jun 15, 2022 9:12:17 PM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION - Front	Done		DARTHURS	Jun 15, 2022 9:12:21 PM	No	
31,000	SSF (Street Side Front)	Done		DARTHURS	Jun 15, 2022 9:12:26 PM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		DARTHURS	Jun 15, 2022 9:12:31 PM	No	
31,020	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		DARTHURS	Jun 15, 2022 9:12:37 PM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Jun 15, 2022 9:12:42 PM	No	
31,040	INSPECT_Wiper Blades, Arms	Done		DARTHURS	Jun 15, 2022 9:12:47 PM	No	
32,000	Engine Inspection	Done		DARTHURS	Jun 15, 2022 9:12:52 PM	No	
32,010	INSPECT_Hood, Springs and Props	Done		DARTHURS	Jun 15, 2022 9:12:59 PM	No	
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		DARTHURS	Jun 15, 2022 9:13:05 PM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done		DARTHURS	Jun 15, 2022 9:13:10 PM	No	
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	NA	DARTHURS	Jun 15, 2022 9:40:57 PM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	DARTHURS	Jun 15, 2022 9:13:34 PM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		DARTHURS	Jun 15, 2022 9:13:39 PM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		DARTHURS	Jun 15, 2022 9:13:46 PM	No	
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		DARTHURS	Jun 15, 2022 9:13:55 PM	No	
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		DARTHURS	Jun 15, 2022 9:14:02 PM	No	
32,100	INSPECT_Intake System	Done		DARTHURS	Jun 15, 2022 9:14:07 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	0 Volt*		DARTHURS	Jun 15, 2022 9:14:19 PM	No	
33,010	CSF (Curb Side Front)	Done		DARTHURS	Jun 15, 2022 9:14:24 PM	No	
33,020	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		DARTHURS	Jun 15, 2022 9:14:31 PM	No	
33,030	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		DARTHURS	Jun 15, 2022 9:14:36 PM	No	
33,040	INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Jun 15, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					9:14:41 PM		
33,050	INSPECT_Wiper Blades, Arms	Done		DARTHURS	Jun 15, 2022 9:14:47 PM	No	
33,060	!FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		DARTHURS	Jun 15, 2022 9:14:53 PM	No	
33,070	*RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	13.98 Volt*		DARTHURS	Jun 15, 2022 9:15:06 PM	No	
33,070	*RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	13.98 Volt*		DARTHURS	Jun 15, 2022 9:42:02 PM	No	
33,080	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		DARTHURS	Jun 15, 2022 9:15:29 PM	No	
40,000	SECTION 4 - Interior Inspection	Done		DARTHURS	Jun 15, 2022 9:15:34 PM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		DARTHURS	Jun 15, 2022 9:15:39 PM	No	
40,200	INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		DARTHURS	Jun 15, 2022 9:15:44 PM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		DARTHURS	Jun 15, 2022 9:15:49 PM	No	
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		DARTHURS	Jun 15, 2022 9:15:53 PM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		DARTHURS	Jun 15, 2022 9:15:59 PM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		DARTHURS	Jun 15, 2022 9:16:04 PM	No	
40,700	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		DARTHURS	Jun 15, 2022 9:16:10 PM	No	
40,800	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		DARTHURS	Jun 15, 2022 9:16:16 PM	No	
40,900	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		DARTHURS	Jun 15, 2022 9:16:21 PM	No	
41,000	INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		DARTHURS	Jun 15, 2022 9:16:26 PM	No	
41,100	INSPECT_CLEAN_AC Filter	Done		DARTHURS	Jun 15, 2022 9:16:34 PM	No	
41,200	INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		DARTHURS	Jun 15, 2022 9:16:39 PM	No	
41,300	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done		DARTHURS	Jun 15, 2022 9:16:46 PM	No	
41,400	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done		DARTHURS	Jun 15, 2022 9:16:53 PM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done		DARTHURS	Jun 15, 2022 9:17:00 PM	No	
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		DARTHURS	Jun 15, 2022 9:17:05 PM	No	
50,200	INSPECT_Ball Joint Play	Done		DARTHURS	Jun 15, 2022 9:17:10 PM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		DARTHURS	Jun 15, 2022 9:17:15 PM	No	
50,400	LUBE_All Chassis Components	Done		DARTHURS	Jun 15, 2022 9:17:19 PM	No	
50,500	!FRA!CHANGE_Engine oil,filters	Done		DARTHURS	Jun 15, 2022 9:17:24 PM	No	
50,700	INSPECT_Tire Condition	Done		DARTHURS	Jun 15, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					9:17:28 PM		
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done		DARTHURS	Jun 15, 2022 9:17:33 PM	No	
50,900	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		DARTHURS	Jun 15, 2022 9:17:38 PM	No	
51,000	RECORD_LF-Tire Tread Depth (32nds)	12 32nds of an inch		DARTHURS	Jun 15, 2022 9:20:05 PM	No	
51,100	RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		DARTHURS	Jun 15, 2022 9:20:19 PM	No	
51,200	RECORD_RF-Tire Tread Depth (32nds)	12 32nds of an inch		DARTHURS	Jun 15, 2022 9:20:28 PM	No	
51,300	RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		DARTHURS	Jun 15, 2022 9:20:36 PM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		DARTHURS	Jun 15, 2022 9:20:42 PM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		DARTHURS	Jun 15, 2022 9:20:47 PM	No	
51,600	!FRA!INSPECT_ Front Brake Assemblies	Done		DARTHURS	Jun 15, 2022 9:20:51 PM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		DARTHURS	Jun 15, 2022 9:21:05 PM	No	
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		DARTHURS	Jun 15, 2022 9:21:12 PM	No	
51,900	INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.554 Inch		DARTHURS	Jun 15, 2022 9:21:29 PM	No	
52,000	INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.554 Inch		DARTHURS	Jun 15, 2022 9:21:39 PM	No	
52,100	INSPECT_Vibration Damper	Done		DARTHURS	Jun 15, 2022 9:21:49 PM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		DARTHURS	Jun 15, 2022 9:21:55 PM	No	
52,400	!FRA!INSPECT_ Starter Mounting	Done		DARTHURS	Jun 15, 2022 9:21:59 PM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		DARTHURS	Jun 15, 2022 9:22:04 PM	No	
52,700	INSPECT_ Engine, Transmission Mounts	Done		DARTHURS	Jun 15, 2022 9:22:09 PM	No	
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		DARTHURS	Jun 15, 2022 9:22:13 PM	No	
52,900	INSPECT_ Shift Cable Adjustment - All Transmissions	Done		DARTHURS	Jun 15, 2022 9:22:18 PM	No	
53,000	!FRA!INSPECT_ Transmission Breather and Clean	Done		DARTHURS	Jun 15, 2022 9:22:23 PM	No	
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		DARTHURS	Jun 15, 2022 9:22:31 PM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		DARTHURS	Jun 15, 2022 9:22:36 PM	No	
53,300	*RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		DARTHURS	Jun 15, 2022 9:22:46 PM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		DARTHURS	Jun 15, 2022 9:22:53 PM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		DARTHURS	Jun 15, 2022 9:23:04 PM	No	
53,600	INSPECT_Tire Condition	Done		DARTHURS	Jun 15, 2022 9:23:10 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		DARTHURS	Jun 15, 2022 9:23:16 PM	No	
53,800	INSPECT_ Mismatched Tire Tread, Casing Design	Done		DARTHURS	Jun 15, 2022 9:23:21 PM	No	
53,900	INSPECT_Dual Mating Tires w/Square	Done		DARTHURS	Jun 15, 2022 9:23:27 PM	No	
54,000	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		DARTHURS	Jun 15, 2022 9:23:31 PM	No	
54,100	INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Jun 15, 2022 9:23:36 PM	No	
54,200	RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		DARTHURS	Jun 15, 2022 9:23:49 PM	No	
54,300	RECORD_RRI-Tire Tread Depth (32nds)	10 32nds of an inch		DARTHURS	Jun 15, 2022 9:23:58 PM	No	
54,400	RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		DARTHURS	Jun 15, 2022 9:24:06 PM	No	
54,500	RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		DARTHURS	Jun 15, 2022 9:24:12 PM	No	
54,600	RECORD_LRO-Tire Tread Depth (32nds)	7 32nds of an inch		DARTHURS	Jun 15, 2022 9:24:22 PM	No	
54,700	RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		DARTHURS	Jun 15, 2022 9:24:30 PM	No	
54,800	RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		DARTHURS	Jun 15, 2022 9:24:35 PM	No	
54,900	RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		DARTHURS	Jun 15, 2022 9:24:40 PM	No	
55,000	!FRA!INSPECT_ REAR Brake Assemblies	Done		DARTHURS	Jun 15, 2022 9:24:48 PM	No	
55,100	!FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		DARTHURS	Jun 15, 2022 9:24:56 PM	No	
55,200	!FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		DARTHURS	Jun 15, 2022 9:25:04 PM	No	
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	11 32nds of an inch		DARTHURS	Jun 15, 2022 9:25:16 PM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	11 32nds of an inch		DARTHURS	Jun 15, 2022 9:25:23 PM	No	
55,500	INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	1.665 Inch		DARTHURS	Jun 15, 2022 9:25:47 PM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	1.665 Inch		DARTHURS	Jun 15, 2022 9:25:55 PM	No	
55,700	!FRA!INSPECT_ Under Body Exhaust System	Done		DARTHURS	Jun 15, 2022 9:25:59 PM	No	
55,800	*RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		DARTHURS	Jun 15, 2022 9:26:07 PM	No	
55,900	*RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		DARTHURS	Jun 15, 2022 9:26:15 PM	No	
60,000	SECTION 6 - Wheelchair Inspection	Done		DARTHURS	Jun 15, 2022 9:26:21 PM	No	
60,100	RECORD_Wheelchair Cycle Count	15.554 Cycles		DARTHURS	Jun 15, 2022 9:26:31 PM	No	
60,200	CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		DARTHURS	Jun 15, 2022 9:26:39 PM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		DARTHURS	Jun 15, 2022 9:26:46 PM	No	
60,400	OPERATE_Lift thru Complete	Done		DARTHURS	Jun 15, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down				9:26:51 PM		
60,500	INSPECT_ Bridgeplate Operation	Done		DARTHURS	Jun 15, 2022 9:26:55 PM	No	
60,600	INSPECT_All Pivot Points for Wear and Looseness	Done		DARTHURS	Jun 15, 2022 9:27:00 PM	No	
60,700	INSPECT_Rollers for Wear and Smooth Rotation	Done		DARTHURS	Jun 15, 2022 9:27:05 PM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	Done		DARTHURS	Jun 15, 2022 9:27:11 PM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	Done		DARTHURS	Jun 15, 2022 9:27:16 PM	No	
61,000	INSPECT_Cable Condition (If Applicable)	Done		DARTHURS	Jun 15, 2022 9:27:21 PM	No	
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		DARTHURS	Jun 15, 2022 9:27:25 PM	No	
61,200	INSPECT_Electrical Connections and Routing of Wires and Cables	Done		DARTHURS	Jun 15, 2022 9:27:31 PM	No	
61,300	INSPECT_Operation and Adjustment of All Safety Switches	Done		DARTHURS	Jun 15, 2022 9:27:40 PM	No	
61,400	INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		DARTHURS	Jun 15, 2022 9:27:47 PM	No	
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		DARTHURS	Jun 15, 2022 9:27:53 PM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		DARTHURS	Jun 15, 2022 9:28:03 PM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		DARTHURS	Jun 15, 2022 9:28:10 PM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		DARTHURS	Jun 15, 2022 9:28:17 PM	No	
61,900	CLEAN_Linkages and Mechanisms	Done		DARTHURS	Jun 15, 2022 9:28:22 PM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		DARTHURS	Jun 15, 2022 9:28:29 PM	No	
62,100	INSPECT_Emergency Platform Release Mechanism	Done		DARTHURS	Jun 15, 2022 9:28:34 PM	No	
62,200	INSPECT_Platform Barrier Latch Mechanism	Done		DARTHURS	Jun 15, 2022 9:28:42 PM	No	
62,300	INSPECT_Bridgeplate Hinge	Done		DARTHURS	Jun 15, 2022 9:28:46 PM	No	
62,400	INSPECT_All Pivot Points	Done		DARTHURS	Jun 15, 2022 9:28:51 PM	No	
62,500	INSPECT_Cams and Slots	Done		DARTHURS	Jun 15, 2022 9:28:57 PM	No	
62,600	INSPECT_Rollers	Done		DARTHURS	Jun 15, 2022 9:29:02 PM	No	
62,700	INSPECT_All Linkages	Done		DARTHURS	Jun 15, 2022 9:29:08 PM	No	
70,000	SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		DARTHURS	Jun 15, 2022 9:29:12 PM	No	
70,300	INSPECT_Condition of Fuel Pressure Gauge	Done		DARTHURS	Jun 15, 2022 9:29:17 PM	No	
70,400	PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		DARTHURS	Jun 15, 2022 9:29:24 PM	No	
70,500	INSPECT_Tank test date, labels-Reference-ST.4	Done		DARTHURS	Jun 15, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	FMMVSS 304 & ANSI-CSA NGV2				9:29:28 PM		
70,600	INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		DARTHURS	Jun 15, 2022 9:29:34 PM	No	
70,700	INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		DARTHURS	Jun 15, 2022 9:29:39 PM	No	
70,800	INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		DARTHURS	Jun 15, 2022 9:29:45 PM	No	
80,000	SECTION 8 - PMI Report Completion	Done		DARTHURS	Jun 15, 2022 9:29:49 PM	No	
80,100	COMPLETE_PM Report; Follow-ups	Done		DARTHURS	Jun 15, 2022 9:29:54 PM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		DARTHURS	Jun 15, 2022 9:29:59 PM	No	

LH: 20 Desc: PM B
Task: PM B SERVICE Performed by: DARTHURS Performed on: 15-JUN-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		DARTHURS	Jun 15, 2022 9:43:10 PM	No	
101,000	FRA Change Oil Filters	Yes		DARTHURS	Jun 15, 2022 9:43:15 PM	No	
102,000	FRA Drain Engine Oil	Yes		DARTHURS	Jun 15, 2022 9:43:20 PM	No	
103,000	FRA Check Transmission Fluid	Done		DARTHURS	Jun 15, 2022 9:43:27 PM	No	
104,000	Lubricate Chassis	Done		DARTHURS	Jun 15, 2022 9:43:31 PM	No	
105,000	Replace or Clean A/C Filters	Done		DARTHURS	Jun 15, 2022 9:43:36 PM	No	
107,000	FRA Change Primary Fuel Filter	No	NA	DARTHURS	Jun 15, 2022 9:43:48 PM	No	
108,000	Lube all pivoting Mechanisms	Done		DARTHURS	Jun 15, 2022 9:43:57 PM	No	
200,000	"B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	Jun 15, 2022 9:44:03 PM	No	
201,000	Service Crankcase Breather	-	NA	DARTHURS	Jun 15, 2022 9:44:17 PM	No	
203,000	FRA Change Automatic Transmission Fluid	No		DARTHURS	Jun 15, 2022 9:44:24 PM	No	
204,000	FRA Change Power Steering Fluid and Filter	No		DARTHURS	Jun 15, 2022 9:44:29 PM	No	
205,000	Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Jun 15, 2022 9:44:34 PM	No	

LH: 5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 15-JUN-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		DARTHURS	Jun 15, 2022 9:46:04 PM	No	
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jun 15, 2022 9:46:08 PM	No	
4	Are you wearing the appropriate PPE?	Done		DARTHURS	Jun 15, 2022 9:46:14 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
7	Have you performed the proper LOTO?	Done		DARTHURS	Jun 15, 2022 9:46:18 PM	No	
10	Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jun 15, 2022 9:46:23 PM	No	
11	Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jun 15, 2022 9:46:28 PM	No	

FIRSTstudent
First Transit

WorkOrder
55345 Palm Tran Connection
v 2.2

WorkOrder: 56195702
Invoice Number: 55345-56195702

Client Department:
MRC: 55345M
WO Desc:
55345-MEDIUM DUTY PMB
Requested By: SPACE
Created By: SPACE
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4516-P
Ford E450 Champion Challenger
VIN: 1FDFE4FS0EDB17178
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Chronology		
Reported	Dec 23, 2022	12:00 AM
Started	Dec 25, 2022	
Completed	Dec 25, 2022	6:34 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	280,068	DH

WorkOrder Notes

Line	Comment
10	Complaint: PMB cause: service due Correction: Performed and completed PMB

Activity: 5 **999/999/999 TOTAL VEHICLE**
Activity Note: Personal Risk Assessment
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder: 56195702
Invoice Number: 55345-56195702

Client Department:
MRC: 55345M
WO Desc:
55345-MEDIUM DUTY PMB
Requested By: SPACE
Created By: SPACE
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4516-P
Ford E450 Champion Challenger
VIN: 1FDFE4FS0EDB17178
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Date	Technician	Hours	Rate	Extended
25-Dec-22	Delva,Terry	2.67	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 2.67	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999/999/999 TOTAL VEHICLE**

Activity Note: Medium Duty PMB Service
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
25-Dec-22	B329		FILTER, OIL, SPIN-ON	1.00	3.05	3.05

Labor Posted

Date	Technician	Hours	Rate	Extended
25-Dec-22	Delva,Terry	1.68	0.00	0.00

Activity 20 Sub Total

Parts:	3.05
Labor:	0.00
Labor Hours: 1.68	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**3.05**

WorkOrder 56195702 Grand Total

Parts:	3.05
Labor:	0.00
Labor Hours: 4.35	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	**3.05**

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
56195702	25-Dec-22	280,068	WO	55345-MEDIUM DUTY PMB
56175660	15-Dec-22	277,961	WO	55345 PER DVIR (Check Brakes)

WorkOrder: 56195702
Invoice Number: 55345-56195702

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
55345-MEDIUM DUTY PMB		**VIN:**	1FDFE4FS0EDB17178
Requested By:	SPACE	**Status:**	40
Created By:	SPACE	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

WorkOrder	Date Completed	Life Meter	Class	Description
56179339	30-Nov-22	277,961	WO	55345 PER DVIR (Check Rear AC)
56164632	24-Nov-22	277,961	WO	front A/C issue

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description

PH: Work Order: 56195702 Desc: 55345-MEDIUM DUTY PMB
Equip: 4516-P Desc: Ford E450 Champion Challenger VIN: 1FDFE4FS0EDB17178

LH: 10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: TDELVA Performed on: 25-DEC-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		TDELVA	Dec 25, 2022 6:05:06 PM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		TDELVA	Dec 25, 2022 6:05:07 PM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		TDELVA	Dec 25, 2022 6:05:07 PM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		TDELVA	Dec 25, 2022 6:05:08 PM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		TDELVA	Dec 25, 2022 6:05:08 PM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		TDELVA	Dec 25, 2022 6:05:09 PM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	Dec 25, 2022 6:05:10 PM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		TDELVA	Dec 25, 2022 6:05:11 PM	No	
10,800	CHECK_All Destination Signage	Done		TDELVA	Dec 25, 2022 6:05:11 PM	No	
10,900	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		TDELVA	Dec 25, 2022 6:05:11 PM	No	
11,000	INSPECT_Fuel Tank Cap, and Doors	Done		TDELVA	Dec 25, 2022 6:05:12 PM	No	
11,200	INSPECT_License Plate, Bracket, Bumpers	Done		TDELVA	Dec 25, 2022 6:05:12 PM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		TDELVA	Dec 25, 2022 6:05:13 PM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		TDELVA	Dec 25, 2022 6:05:13 PM	No	
20,200	CHECK_Public Address System	Done		TDELVA	Dec 25, 2022 6:05:14 PM	No	
20,300	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		TDELVA	Dec 25, 2022 6:05:15 PM	No	
20,400	*RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		TDELVA	Dec 25, 2022 6:05:16 PM	No	
20,500	PERFORM_Brake Test (Apply hard enough to	Done		TDELVA	Dec 25,	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	check wheel pull and Application)				2022 6:05:16 PM		
20,600	RECORD_Brake Performance Test E.T.	0 Second*		TDELVA	Dec 25, 2022 6:05:17 PM	No	
20,700	RECORD_Brake Performance Test Speed	0 Miles per Hour		TDELVA	Dec 25, 2022 6:05:17 PM	No	
20,800	RECORD_Brake Performance Test Distance	0 FEET		TDELVA	Dec 25, 2022 6:05:18 PM	No	
20,900	RECORD_Brake Performance Test Adj Distance (20mph)	0 FEET		TDELVA	Dec 25, 2022 6:05:18 PM	No	
21,000	RECORD_Brake Performance Test Ave GX	0 Gravitational Force		TDELVA	Dec 25, 2022 6:05:19 PM	No	
21,100	ADD_Image of Brake Test Results to PM Work Order	Done		TDELVA	Dec 25, 2022 6:05:20 PM	No	
21,200	*RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		TDELVA	Dec 25, 2022 6:05:20 PM	No	
21,300	*RPT*INSPECT_Windshields, Sun Visors	Done		TDELVA	Dec 25, 2022 6:05:21 PM	No	
21,400	INSPECT_Wiper/Washer Operation, Condition	Done	Winshield Washer line leaks	TDELVA	Dec 25, 2022 4:43:53 PM	Yes	56255191
21,500	INSPECT_High Idle Control	Done		TDELVA	Dec 25, 2022 6:05:21 PM	No	
21,600	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		TDELVA	Dec 25, 2022 6:05:22 PM	No	
21,700	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		TDELVA	Dec 25, 2022 6:05:22 PM	No	
21,800	INSPECT_Parking Brake Operation	Done	Vehicle come out of park while e-brake apply	TDELVA	Dec 25, 2022 4:45:15 PM	Yes	56255191
21,900	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		TDELVA	Dec 25, 2022 6:05:23 PM	No	
22,000	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		TDELVA	Dec 25, 2022 6:05:23 PM	No	
22,100	*RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		TDELVA	Dec 25, 2022 6:05:24 PM	No	
22,200	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done	under dash wire need to be secure	TDELVA	Dec 25, 2022 4:46:12 PM	Yes	56255191
22,250	INSPECT_Driver Floor Area for Water Leaks	Done		TDELVA	Dec 25, 2022 6:05:25 PM	No	
22,300	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		TDELVA	Dec 25, 2022 6:05:25 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
22,400	INSPECT_Engine Fault Codes	Done		TDELVA	Dec 25, 2022 6:05:26 PM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION	Done		TDELVA	Dec 25, 2022 6:05:26 PM	No	
31,000	SSF (Street Side Front)	Done		TDELVA	Dec 25, 2022 6:05:27 PM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		TDELVA	Dec 25, 2022 6:05:27 PM	No	
31,020	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		TDELVA	Dec 25, 2022 6:05:28 PM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done		TDELVA	Dec 25, 2022 6:05:28 PM	No	
31,040	INSPECT_Wiper Blades, Arms	Done	Wiper blades	TDELVA	Dec 25, 2022 6:02:36 PM	Yes	56255191
32,000	Engine Inspection	Done		TDELVA	Dec 25, 2022 6:05:29 PM	No	
32,010	INSPECT_Hood, Springs and Props	Done		TDELVA	Dec 25, 2022 6:05:29 PM	No	
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		TDELVA	Dec 25, 2022 6:05:30 PM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done	Power steering leaks	TDELVA	Dec 25, 2022 6:03:37 PM	No	
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		TDELVA	Dec 25, 2022 6:05:30 PM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	0 Degree Fahrenheit		TDELVA	Dec 25, 2022 6:05:31 PM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		TDELVA	Dec 25, 2022 6:05:31 PM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		TDELVA	Dec 25, 2022 6:05:32 PM	No	
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		TDELVA	Dec 25, 2022 6:05:32 PM	No	
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		TDELVA	Dec 25, 2022 6:05:33 PM	No	
32,100	INSPECT_Intake System	Done		TDELVA	Dec 25, 2022 6:05:33 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	0 Volt*		TDELVA	Dec 25, 2022 6:05:34 PM	No	
33,000	CSF (Curb Side Front)	Done		TDELVA	Dec 25, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					6:05:35 PM		
33,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		TDELVA	Dec 25, 2022 6:05:35 PM	No	
33,020	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		TDELVA	Dec 25, 2022 6:05:36 PM	No	
33,030	INSPECT_Mud Flaps, Brackets	Done		TDELVA	Dec 25, 2022 6:05:36 PM	No	
33,040	INSPECT_Wiper Blades, Arms	Done		TDELVA	Dec 25, 2022 6:05:37 PM	No	
33,050	!FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		TDELVA	Dec 25, 2022 6:05:37 PM	No	
33,060	*RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	13.8 Volt*		TDELVA	Dec 25, 2022 6:04:59 PM	No	
33,060	*RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	13.5 Volt*		TDELVA	Dec 25, 2022 6:08:13 PM	No	
33,070	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		TDELVA	Dec 25, 2022 6:08:14 PM	No	
40,000	SECTION 4 - Interior Inspection	Done		TDELVA	Dec 25, 2022 6:08:14 PM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		TDELVA	Dec 25, 2022 6:08:15 PM	No	
40,200	INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		TDELVA	Dec 25, 2022 6:08:15 PM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		TDELVA	Dec 25, 2022 6:08:16 PM	No	
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		TDELVA	Dec 25, 2022 6:08:16 PM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		TDELVA	Dec 25, 2022 6:08:17 PM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		TDELVA	Dec 25, 2022 6:08:17 PM	No	
40,700	CHECK_Passenger Stop Request System	Done		TDELVA	Dec 25, 2022 6:08:18 PM	No	
40,800	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		TDELVA	Dec 25, 2022 6:08:18 PM	No	
40,900	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		TDELVA	Dec 25, 2022 6:08:19 PM	No	
41,000	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		TDELVA	Dec 25, 2022 6:08:19 PM	No	
41,100	INSPECT_All ADA Equip (Lift Seat Belt, floor	Done	Floor hold downs.	TDELVA	Dec 25,	Yes	56255191

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	hold Downs, Belts, Cover, Alarms)				2022 6:08:20 PM		
41,200	INSPECT_CLEAN_AC Filter	Done		TDELVA	Dec 25, 2022 6:19:53 PM	No	
41,300	INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		TDELVA	Dec 25, 2022 6:19:54 PM	No	
41,400	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done		TDELVA	Dec 25, 2022 6:19:54 PM	No	
41,500	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done		TDELVA	Dec 25, 2022 6:19:55 PM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done		TDELVA	Dec 25, 2022 6:19:56 PM	No	
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		TDELVA	Dec 25, 2022 6:19:56 PM	No	
50,200	INSPECT_Ball Joint Play	Done		TDELVA	Dec 25, 2022 6:19:57 PM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		TDELVA	Dec 25, 2022 6:19:57 PM	No	
50,400	LUBE_All Chassis Components	Done		TDELVA	Dec 25, 2022 6:19:58 PM	No	
50,500	!FRA!CHANGE_Engine oil,filters	Done		TDELVA	Dec 25, 2022 6:19:58 PM	No	
50,700	INSPECT_Tire Condition	Done		TDELVA	Dec 25, 2022 6:19:59 PM	No	
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done		TDELVA	Dec 25, 2022 6:19:59 PM	No	
50,900	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		TDELVA	Dec 25, 2022 6:20:00 PM	No	
51,000	RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		TDELVA	Dec 25, 2022 6:20:00 PM	No	
51,100	RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		TDELVA	Dec 25, 2022 6:20:01 PM	No	
51,200	RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		TDELVA	Dec 25, 2022 6:20:01 PM	No	
51,300	RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		TDELVA	Dec 25, 2022 6:20:02 PM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		TDELVA	Dec 25, 2022 6:20:03 PM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		TDELVA	Dec 25, 2022 6:20:03 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
51,600	!FRA!INSPECT_ Front Brake Assemblies	Done		TDELVA	Dec 25, 2022 6:20:04 PM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch	Front brakes	TDELVA	Dec 25, 2022 6:10:41 PM	Yes	56255191
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch		TDELVA	Dec 25, 2022 6:20:05 PM	No	
51,900	INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	36.8 Inch		TDELVA	Dec 25, 2022 6:20:05 PM	No	
52,000	INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	36.8 Inch		TDELVA	Dec 25, 2022 6:20:06 PM	No	
52,100	INSPECT_Vibration Damper	Done		TDELVA	Dec 25, 2022 6:20:06 PM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		TDELVA	Dec 25, 2022 6:20:07 PM	No	
52,400	!FRA!INSPECT_ Starter Mounting	Done		TDELVA	Dec 25, 2022 6:20:07 PM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		TDELVA	Dec 25, 2022 6:20:08 PM	No	
52,700	INSPECT_ Engine, Transmission Mounts	Done		TDELVA	Dec 25, 2022 6:20:08 PM	No	
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		TDELVA	Dec 25, 2022 6:20:09 PM	No	
52,900	INSPECT_ Shift Cable Adjustment - All Transmissions	Done		TDELVA	Dec 25, 2022 6:20:10 PM	No	
53,000	!FRA!INSPECT_ Transmission Breather and Clean	Done		TDELVA	Dec 25, 2022 6:20:10 PM	No	
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		TDELVA	Dec 25, 2022 6:20:11 PM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		TDELVA	Dec 25, 2022 6:20:11 PM	No	
53,300	*RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		TDELVA	Dec 25, 2022 6:20:12 PM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		TDELVA	Dec 25, 2022 6:20:12 PM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		TDELVA	Dec 25, 2022 6:20:13 PM	No	
53,600	INSPECT_Tire Condition	Done		TDELVA	Dec 25, 2022 6:20:13 PM	No	
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		TDELVA	Dec 25, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					6:20:14 PM		
53,800	INSPECT_ Mismatched Tire Tread, Casing Design	Done		TDELVA	Dec 25, 2022 6:20:14 PM	No	
53,900	INSPECT_Dual Mating Tires w/Square	-	na	TDELVA	Dec 25, 2022 6:20:15 PM	No	
54,000	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		TDELVA	Dec 25, 2022 6:20:15 PM	No	
54,100	INSPECT_Mud Flaps, Brackets	Done		TDELVA	Dec 25, 2022 6:20:16 PM	No	
54,200	RECORD_RRO-Tire Tread Depth (32nds)	9 32nds of an inch		TDELVA	Dec 25, 2022 6:20:16 PM	No	
54,300	RECORD_RRI-Tire Tread Depth (32nds)	9 32nds of an inch		TDELVA	Dec 25, 2022 6:20:17 PM	No	
54,400	RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		TDELVA	Dec 25, 2022 6:20:18 PM	No	
54,500	RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		TDELVA	Dec 25, 2022 6:20:18 PM	No	
54,600	RECORD_LRO-Tire Tread Depth (32nds)	3 32nds of an inch	Rear Left tires	TDELVA	Dec 25, 2022 6:13:13 PM	Yes	56255191
54,700	RECORD_LRI-Tire Tread Depth (32nds)	4 32nds of an inch		TDELVA	Dec 25, 2022 6:20:19 PM	No	
54,800	RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		TDELVA	Dec 25, 2022 6:20:19 PM	No	
54,900	RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		TDELVA	Dec 25, 2022 6:20:20 PM	No	
55,000	!FRA!INSPECT_ REAR Brake Assemblies	Done		TDELVA	Dec 25, 2022 6:20:20 PM	No	
55,100	!FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		TDELVA	Dec 25, 2022 6:20:21 PM	No	
55,200	!FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		TDELVA	Dec 25, 2022 6:20:22 PM	No	
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	Dec 25, 2022 6:20:22 PM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	Dec 25, 2022 6:20:23 PM	No	
55,500	INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	38.6 Inch		TDELVA	Dec 25, 2022 6:20:23 PM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	38.6 Inch		TDELVA	Dec 25, 2022 6:20:24 PM	No	
55,700	CHECK_Spring Brake Inversion Valve	Done		TDELVA	Dec 25,	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					2022 6:20:25 PM		
55,800	CHECK_Double Check Valve - Primary, Secondary	Done		TDELVA	Dec 25, 2022 6:20:25 PM	No	
55,900	!FRA!INSPECT_ Under Body Exhaust System	Done		TDELVA	Dec 25, 2022 6:20:26 PM	No	
56,000	*RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		TDELVA	Dec 25, 2022 6:20:26 PM	No	
56,100	*RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done	Right rear rubber mount	TDELVA	Dec 25, 2022 6:14:46 PM	Yes	56255191
60,000	SECTION 6 - Wheelchair Inspection	Done		TDELVA	Dec 25, 2022 6:20:27 PM	No	
60,100	RECORD_Wheelchair Cycle Count	16357 Cycles		TDELVA	Dec 25, 2022 6:20:28 PM	No	
60,200	CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		TDELVA	Dec 25, 2022 6:20:28 PM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		TDELVA	Dec 25, 2022 6:20:29 PM	No	
60,400	OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done	Lift jerky	TDELVA	Dec 25, 2022 6:20:29 PM	Yes	56255191
60,500	INSPECT_ Bridgeplate Operation	Done		TDELVA	Dec 25, 2022 6:22:36 PM	No	
60,600	INSPECT_All Pivot Points for Wear and Looseness	Done		TDELVA	Dec 25, 2022 6:22:36 PM	No	
60,700	INSPECT_Rollers for Wear and Smooth Rotation	Done		TDELVA	Dec 25, 2022 6:22:37 PM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	Done		TDELVA	Dec 25, 2022 6:22:37 PM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	Done		TDELVA	Dec 25, 2022 6:22:38 PM	No	
61,000	INSPECT_Cable Condition (If Applicable)	Done		TDELVA	Dec 25, 2022 6:22:38 PM	No	
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		TDELVA	Dec 25, 2022 6:22:39 PM	No	
61,200	INSPECT_Electrical Connections and Routing of Wires and Cables	Done		TDELVA	Dec 25, 2022 6:22:39 PM	No	
61,300	INSPECT_Operation and Adjustment of All Safety Switches	Done		TDELVA	Dec 25, 2022 6:22:40 PM	No	
61,400	INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		TDELVA	Dec 25, 2022 6:22:40 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		TDELVA	Dec 25, 2022 6:22:41 PM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		TDELVA	Dec 25, 2022 6:22:42 PM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		TDELVA	Dec 25, 2022 6:24:20 PM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		TDELVA	Dec 25, 2022 6:22:42 PM	No	
61,900	CLEAN_Linkages and Mechanisms	Done		TDELVA	Dec 25, 2022 6:22:43 PM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		TDELVA	Dec 25, 2022 6:22:43 PM	No	
62,100	INSPECT_Emergency Platform Release Mechanism	Done		TDELVA	Dec 25, 2022 6:22:44 PM	No	
62,200	INSPECT_Platform Barrier Latch Mechanism	Done		TDELVA	Dec 25, 2022 6:22:45 PM	No	
62,300	INSPECT_Bridgeplate Hinge	Done		TDELVA	Dec 25, 2022 6:22:45 PM	No	
62,400	INSPECT_All Pivot Points	Done		TDELVA	Dec 25, 2022 6:22:46 PM	No	
62,500	INSPECT_Cams and Slots	Done		TDELVA	Dec 25, 2022 6:22:46 PM	No	
62,600	INSPECT_Rollers	Done		TDELVA	Dec 25, 2022 6:22:47 PM	No	
62,700	INSPECT_All Linkages	Done		TDELVA	Dec 25, 2022 6:22:47 PM	No	
70,000	SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		TDELVA	Dec 25, 2022 6:22:48 PM	No	
70,300	INSPECT_Condition of Fuel Pressure Gauge	Done		TDELVA	Dec 25, 2022 6:22:48 PM	No	
70,400	PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		TDELVA	Dec 25, 2022 6:22:49 PM	No	
70,500	INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		TDELVA	Dec 25, 2022 6:22:49 PM	No	
70,600	INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		TDELVA	Dec 25, 2022 6:22:50 PM	No	
70,700	INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		TDELVA	Dec 25, 2022 6:22:50 PM	No	
70,800	INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		TDELVA	Dec 25, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					6:22:51 PM		
80,000	SECTION 8 - PMI Report Completion	Done		TDELVA	Dec 25, 2022 6:22:51 PM	No	
80,100	COMPLETE_PM Report; Follow-ups	Done		TDELVA	Dec 25, 2022 6:22:52 PM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		TDELVA	Dec 25, 2022 6:22:52 PM	No	

LH: 20 Desc: Medium Duty PMB Service
Task: 55345-Medium Duty PMB Inspection Performed by: TDELVA Performed on: 25-DEC-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		TDELVA	Dec 25, 2022 3:01:36 PM	No	
101,000	FRA Change Oil Filters	Yes		TDELVA	Dec 25, 2022 3:01:37 PM	No	
102,000	FRA Drain Engine Oil	Yes		TDELVA	Dec 25, 2022 3:01:38 PM	No	
103,000	FRA Check Transmission Fluid	Done		TDELVA	Dec 25, 2022 3:01:40 PM	No	
104,000	Lubricate Chassis	Done		TDELVA	Dec 25, 2022 3:01:39 PM	No	
105,000	Replace or Clean A/C Filters	Done		TDELVA	Dec 25, 2022 3:01:01 PM	No	
106,000	Drain Water from Fuel Water Separator (where applicable)	-	na	TDELVA	Dec 25, 2022 3:01:32 PM	No	
107,000	FRA Change Primary Fuel Filter	No		TDELVA	Dec 25, 2022 3:01:34 PM	No	
108,000	Lube all pivoting Mechanisms	Done		TDELVA	Dec 25, 2022 3:02:17 PM	No	
200,000	"B" PMI SERVICING ITEMS (12 MONTH)	Done		TDELVA	Dec 25, 2022 3:01:35 PM	No	
201,000	Service Crankcase Breather	Done		TDELVA	Dec 25, 2022 3:01:30 PM	No	
202,000	FRA Change Water Separator ¿ Secondary Fuel Filters	No		TDELVA	Dec 25, 2022 3:01:03 PM	No	
203,000	FRA Change Automatic Transmission Fluid	No		TDELVA	Dec 25, 2022 3:01:07 PM	No	
204,000	FRA Change Power Steering Fluid and Filter	No		TDELVA	Dec 25, 2022 3:01:28 PM	No	
205,000	Complete Engine Diagnostics and Clear Codes when Completed	Done		TDELVA	Dec 25, 2022 3:01:29 PM	No	

LH: 5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 25-DEC-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		TDELVA	Dec 25, 2022 2:35:30 PM	No	
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Dec 25, 2022 2:35:32 PM	No	
4	Are you wearing the appropriate PPE?	Done		TDELVA	Dec 25, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					2:35:35 PM		
7	Have you performed the proper LOTO?	Done		TDELVA	Dec 25, 2022 2:35:38 PM	No	
10	Are you aware of the potential risks of performing this repair?	Done		TDELVA	Dec 25, 2022 2:35:41 PM	No	
11	Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Dec 25, 2022 2:35:44 PM	No	

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51411404
Invoice Number: 55345-51411404

Client Department:			
MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
PM C		**VIN:**	1FDFE4FS0EDB17178
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jul 12, 2018	11:49 AM
Started	Jul 12, 2018	
Completed	Jul 13, 2018	8:57 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	122,054	DH
System	122,314	DH

WorkOrder Notes

Line	Comment
10	PMC Service Perform pmc Service Oil filter B329 qty1 Engine oil 5w20 qty 7 Qts Transmission filter 20021 qty1 Transmission fluid 10 Qts Gear oil 80w90 qty 5 Qts Replaced AC filter Air filter PA4075 qty1

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
12-Jul-18	Gaspard,Ronald	1.58	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.58	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51914011
Invoice Number: 55345-51914011

Client Department:
MRC: 55345M
Equipment: 4516-P
Ford E450 Champion Challenger
WO Desc:
PM C
VIN: 1FDFE4FS0EDB17178
Requested By: VAMRITTEEMAL
Status: 40
Created By: VAMRITTEEMAL
Priority: 1
Class: WO
Driver:
Arrangement: Unassigned
Phone:
Potential Warranty: No
ETA:

Chronology		
Reported	Dec 18, 2018	8:27 AM
Started	Dec 18, 2018	
Completed	Dec 19, 2018	8:59 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	148,403	DH
System	148,403	DH

WorkOrder Notes

Line	Comment
10	PMC Preventive maintenance Perform service lube all Pivoting Points cross Rotate Tires completed

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
18-Dec-18	Pierre,Hubert J	7.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 7.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

FirstBase
by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52418255
Invoice Number: 55345-52418255

Client Department:
MRC: 55345M
WO Desc:
PM C
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4516-P
Ford E450 Champion Challenger
VIN: 1FDFE4FS0EDB17178
Status: 32
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Jun 5, 2019	11:59 AM
Started	Jun 5, 2019	
Completed	Jun 6, 2019	12:04 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	174,297	DH
System	174,515	DH

WorkOrder Notes

Line	Comment
10	Perform PMC Service. Change Oil & Filter. Lube all Pivoting Points. Check Brakes .clean batteries. Replace A/C Filter.perform Transmission Service drain & Fill & Replace Filter. Perform differential service drain & Fill Swap L/R inner tire. Parts# B329 Qty (1) Oil 5W20 Qty (7) Qt Parts# 20021 Qty (1) ATF Fluid Qty (9.0) Qt Gear Oil 80W90 Qty (3) Qt

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
05-Jun-19	Arthurs,Durvin	3.50	65.00	227.50

Activity 10 Sub Total

Parts:	0.00
Labor:	227.50
Labor Hours: 3.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**227.50**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
05-Jun-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52951492
Invoice Number: 55345-52951492

Client Department:
MRC: 55345M
WO Desc:
PM C
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4516-P
Ford E450 Champion Challenger
VIN: 1FDFE4FS0EDB17178
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Nov 25, 2019	12:04 PM
Started	Nov 25, 2019	
Completed	Nov 26, 2019	7:46 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	200,808	DH

WorkOrder Notes

Line	Comment
10	PMC SERVICE PREVENTIVE MAINTENANCE PERFORM AND COMPLETED PMC SERVICE

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
25-Nov-19	AMRIT TEEMAL,VISHNU	1.50	65.00	97.50

Activity 10 Sub Total

Parts:	0.00
Labor:	97.50
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
25-Nov-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53558500
Invoice Number: 55345-53558500

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
55345-LIGHT DUTY PMC		**VIN:**	1FDFE4FS0EDB17178
Requested By:	NSTOLFO	**Status:**	40
Created By:	NSTOLFO	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jun 5, 2020	12:00 AM
Started	Jun 7, 2020	
Completed	Jun 7, 2020	2:04 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	226,010	DH
System	226,151	DH

WorkOrder Notes

Line	Comment
10	Complaint: PMC Service Cause: preventive maintenance Correction: perform PMC Service and lube all Pivoting Points,and Rear end Service replaced 2 passenger side rear tires

Activity: 5 **999/999/999 TOTAL VEHICLE**
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 54173847
Invoice Number: 55345-54173847

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
55345-LIGHT DUTY PMC		**VIN:**	1FDFE4FS0EDB17178
Requested By:	HPIERRE	**Status:**	40
Created By:	HPIERRE	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Feb 2, 2021	12:16 PM
Started	Feb 2, 2021	
Completed	Feb 2, 2021	9:23 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	251,680	DH

WorkOrder Notes

Line	Comment
10	PMC Service Perform PMC service Oil filter B329 Qty1 Engine oil 10w30 qty 7 qts Replaced AC filter Replaced drain plug oil 65266 Qty1

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**

Activity Note: Light Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder: 51204840
Invoice Number: 55345-51204840

Client Department:
MRC: 55345M
WO Desc:
PM A
Requested By: CKARLENS
Created By: CKARLENS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4516-P
Ford E450 Champion Challenger
VIN: 1FDFE4FS0EDB17178
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Date	Part Number		Description	Qty.	Each	Extended
08-May-18	F75Z-6730-BA		PLUG, DRAIN, OIL, ENGINE, 3.0L	1.00	6.66	6.66
08-May-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted

Date	Technician	Hours	Rate	Extended
08-May-18	Gaspard,Ronald	1.08	0.00	0.00

Activity 20 Sub Total

Parts:	8.62
Labor:	0.00
Labor Hours: 1.08	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.62**

Activity: 30 **999 TOTAL VEHICLE**

Activity Note: PRAMETER
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
08-May-18	Gaspard,Ronald	0.27	0.00	0.00

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.27	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

WorkOrder 51204840 Grand Total

Parts:	8.62
Labor:	0.00
Labor Hours: 3.18	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	**8.62**

WorkOrder: 51204840
Invoice Number: 55345-51204840

Client Department:

MRC:	55345M	**Equipment:**	4516-P
WO Desc:			Ford E450 Champion Challenger
PM A		**VIN:**	1FDFE4FS0EDB17178
Requested By:	CKARLENS	**Status:**	40
Created By:	CKARLENS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
51204840	9-May-18	113,919	WO	PM A
51333843	9-May-18	113,919	WO	Needs 2 front shoks
51091516	9-Apr-18	109,587	WO	PM B
51198760	8-Apr-18	109,357	WO	L/R inner tire Flet

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
51089965	11-Mar-18	105,193	WO	Rear tires near min. specs.

PH: Work Order: 51204840 Desc: PM A
Equip: 4516-P Desc: Ford E450 Champion Challenger VIN: 1FDFE4FS0EDB17178

LH: 10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 08-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	May 8, 2018 11:47:51 PM	No	
10,100	Safety Inspection	Done		RGASPARD	May 8, 2018 11:47:51 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	May 8, 2018 11:47:51 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		RGASPARD	May 8, 2018 11:47:51 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	May 8, 2018 11:47:51 PM	No	
10,140	Check Service Brakes	Done		RGASPARD	May 8, 2018 11:47:51 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	May 8, 2018 11:47:51 PM	No	
10,160	FRA Check Instruments and Horns	Done		RGASPARD	May 8, 2018 11:47:51 PM	No	
10,170	Check Fast Idle	Done		RGASPARD	May 8, 2018 11:47:52 PM	No	
10,180	Check Starter Protection Circuit	Done		RGASPARD	May 8, 2018 11:47:52 PM	No	
10,190	Check Reverse Warning System	Done		RGASPARD	May 8, 2018 11:47:52 PM	No	
11,100	Check Parking Brake	Done		RGASPARD	May 8, 2018 11:47:52 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		RGASPARD	May 8, 2018 11:47:52 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	May 8, 2018 11:47:52 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		RGASPARD	May 8, 2018 11:47:52 PM	No	
11,140	Road Test: Check for Proper Operation	Done		RGASPARD	May 8, 2018 11:47:52 PM	No	
11,150	Perform Brake Test	Done		RGASPARD	May 8, 2018 11:47:52 PM	No	
11,152	Decelerometer Results Test 1	FEET	NA	RGASPARD	May 8, 2018 11:47:53 PM	No	
11,154	Decelerometer Results Test 2	FEET	NA	RGASPARD	May 8, 2018 11:47:53 PM	No	
11,156	Decelerometer Results Test 3	FEET	NA	RGASPARD	May 8, 2018 11:47:53 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	RGASPARD	May 8, 2018 11:47:53 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	NA	RGASPARD	May 8, 2018 11:47:53 PM	No	
11,170	FRA Check Door Operation	Done		RGASPARD	May 8, 2018 11:47:53 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		RGASPARD	May 8, 2018 11:47:53 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		RGASPARD	May 8, 2018 11:47:53 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		RGASPARD	May 8, 2018 11:47:54 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		RGASPARD	May 8, 2018 11:47:54 PM	No	
20,230	FRA Check Wiring Under Dash	Done		RGASPARD	May 8, 2018 11:47:54 PM	No	
20,240	FRA Check Interior Lights	Done		RGASPARD	May 8, 2018 11:47:54 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		RGASPARD	May 8, 2018 11:47:54 PM	No	
20,260	Check Stop Request System	-	NA	RGASPARD	May 8, 2018 11:47:54 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	NA	RGASPARD	May 8, 2018 11:47:54 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	May 8, 2018 11:47:54 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	May 8, 2018 11:47:54 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		RGASPARD	May 8, 2018 11:47:54 PM	No	
22,110	Check Emergency Hatches	Done		RGASPARD	May 8, 2018 11:47:55 PM	No	
22,120	Check All Safety Equipment	Done		RGASPARD	May 8, 2018 11:47:55 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		RGASPARD	May 8, 2018 11:47:55 PM	No	
30,310	Check Passenger Doors	Done		RGASPARD	May 8, 2018 11:47:55 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		RGASPARD	May 8, 2018 11:47:55 PM	No	
30,330	Check Wheelchair Lift Operation	Done		RGASPARD	May 8, 2018 11:47:55 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	NA	RGASPARD	May 8, 2018 11:47:55 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		RGASPARD	May 8, 2018 11:47:55 PM	No	
30,360	Check for Physical Damage and Decals	Done		RGASPARD	May 8, 2018 11:47:56 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		RGASPARD	May 8, 2018 11:47:56 PM	No	
30,380	Check Exterior Compartment Doors	Done		RGASPARD	May 8, 2018 11:47:56 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		RGASPARD	May 8, 2018 11:47:56 PM	No	
33,100	Check Lights and Reflectors	Done		RGASPARD	May 8, 2018 11:47:56 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	May 8, 2018 11:47:56 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		RGASPARD	May 8, 2018 11:47:56 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	May 8, 2018 11:47:56 PM	No	
40,420	Check Hood	Done		RGASPARD	May 8, 2018 11:47:56 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		RGASPARD	May 8, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:47:56 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	NA	RGASPARD	May 8, 2018 11:47:57 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	RGASPARD	May 8, 2018 11:47:57 PM	No	
40,442	Freeze Point	Degree Fahrenheit	NA	RGASPARD	May 8, 2018 11:47:57 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	May 8, 2018 11:47:57 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	NA	RGASPARD	May 8, 2018 11:47:57 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	NA	RGASPARD	May 8, 2018 11:47:57 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	May 8, 2018 11:47:58 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		RGASPARD	May 8, 2018 11:47:58 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		RGASPARD	May 8, 2018 11:47:58 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	May 8, 2018 11:47:58 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		RGASPARD	May 8, 2018 11:47:58 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	May 8, 2018 11:47:58 PM	No	
44,130	FRA Check Exhaust System	Done		RGASPARD	May 8, 2018 11:47:58 PM	No	
44,140	FRA Check Intake System	Done		RGASPARD	May 8, 2018 11:47:58 PM	No	
44,150	FRA Inspect Turbocharger	-	NA	RGASPARD	May 8, 2018 11:47:59 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	May 8, 2018 11:47:59 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		RGASPARD	May 8, 2018 11:47:59 PM	No	
44,180	FRA Check for Leaks	Done		RGASPARD	May 8, 2018 11:47:59 PM	No	
44,190	FRA Perform Battery Inspection	Done		RGASPARD	May 8, 2018 11:47:59 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	May 8, 2018 11:47:59 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		RGASPARD	May 8, 2018 11:47:59 PM	No	
50,510	Check Entire Steering System	Done		RGASPARD	May 8, 2018 11:47:59 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	May 8, 2018 11:48:00 PM	No	
60,610	FRA Check and Record Air Pressure	Done		RGASPARD	May 8, 2018 11:48:00 PM	No	
60,611	Air Pressure RF	70 Pounds per Square Inch		RGASPARD	May 8, 2018 11:48:00 PM	No	
60,612	Air Pressure LF	70 Pounds per Square Inch		RGASPARD	May 8, 2018 11:48:00 PM	No	
60,613	Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	May 8, 2018 11:48:00 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	May 8, 2018 11:48:00 PM	No	
60,615	Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	May 8, 2018 11:48:00 PM	No	
60,616	Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	May 8, 2018 11:48:01 PM	No	
60,620	Check Valve Stems and Caps	Done		RGASPARD	May 8, 2018 11:48:01 PM	No	
60,630	Check and Record Tread Depth	Done		RGASPARD	May 8, 2018 11:48:01 PM	No	
60,631	Tread Depth RF	5 32nds of an inch		RGASPARD	May 8, 2018 11:48:01 PM	No	
60,632	Tread Depth LF	6 32nds of an inch		RGASPARD	May 8, 2018 11:48:01 PM	No	
60,633	Tread Depth RRO	11 32nds of an inch		RGASPARD	May 8, 2018 11:48:02 PM	No	
60,634	Tread Depth RRI	11 32nds of an inch		RGASPARD	May 8, 2018 11:48:01 PM	No	
60,635	Tread Depth LRI	12 32nds of an inch		RGASPARD	May 8, 2018 11:48:02 PM	No	
60,636	Tread Depth LRO	11 32nds of an inch		RGASPARD	May 8, 2018 11:48:02 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		RGASPARD	May 8, 2018 11:48:02 PM	No	
60,650	Check Sidewall Wear	Done		RGASPARD	May 8, 2018 11:48:02 PM	No	
60,660	Inspect for Cuts and Tears	Done		RGASPARD	May 8, 2018 11:48:02 PM	No	
60,670	Check Dual Mating With Square	Done		RGASPARD	May 8, 2018 11:48:02 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	May 8, 2018 11:48:03 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		RGASPARD	May 8, 2018 11:48:03 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		RGASPARD	May 8, 2018 11:48:03 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		RGASPARD	May 8, 2018 11:48:03 PM	No	
70,710	Check Vibration Damper	Done		RGASPARD	May 8, 2018 11:48:03 PM	No	
70,720	Check Engine and Transmission Mounts	Done		RGASPARD	May 8, 2018 11:48:03 PM	No	
70,730	FRA Check Starter	Done		RGASPARD	May 8, 2018 11:48:03 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	May 8, 2018 11:48:03 PM	No	
70,750	FRA Check Transmission for Leaks	Done		RGASPARD	May 8, 2018 11:48:04 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		RGASPARD	May 8, 2018 11:48:04 PM	No	
70,770	FRA Check Exhaust System	Done		RGASPARD	May 8, 2018 11:48:04 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	May 8, 2018 11:48:04 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		RGASPARD	May 8, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:48:04 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	May 8, 2018 11:48:04 PM	No	
77,110	FRA Check Fuel Tank	Done		RGASPARD	May 8, 2018 11:48:05 PM	No	
77,120	Check Suspension Components	Done		RGASPARD	May 8, 2018 11:48:05 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	May 8, 2018 11:48:05 PM	No	
77,131	Brake Pad Thickness LF	8 Inch		RGASPARD	May 8, 2018 11:48:05 PM	No	
77,132	Brake Pad Thickness RF	8 Inch		RGASPARD	May 8, 2018 11:48:05 PM	No	
77,133	Brake Pad Thickness LR	8 Inch		RGASPARD	May 8, 2018 11:48:05 PM	No	
77,134	Brake Pad Thickness RR	8 Inch		RGASPARD	May 8, 2018 11:48:05 PM	No	
77,135	Brake Rotor LF	38 Inch		RGASPARD	May 8, 2018 11:48:05 PM	No	
77,136	Brake Rotor RF	38 Inch		RGASPARD	May 8, 2018 11:48:06 PM	No	
77,137	Brake Rotor LR	40 Inch		RGASPARD	May 8, 2018 11:48:06 PM	No	
77,138	Brake Rotor RR	40 Inch		RGASPARD	May 8, 2018 11:48:06 PM	No	
77,140	FRA Check Brake Hoses	Done		RGASPARD	May 8, 2018 11:48:06 PM	No	
77,150	Check King Pins	-	NA	RGASPARD	May 8, 2018 11:48:06 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	May 8, 2018 11:48:06 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		RGASPARD	May 8, 2018 11:48:07 PM	No	
80,810	Completion of PMI Report	Done		RGASPARD	May 8, 2018 11:48:07 PM	No	
90,000	SECTION 9 Completion of PMI	Done		RGASPARD	May 8, 2018 11:48:07 PM	No	
90,910	Vehicle Returned to predetermined location	Done		RGASPARD	May 8, 2018 11:48:07 PM	No	

LH: 20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 08-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		RGASPARD	May 8, 2018 11:48:55 PM	No	
101,000	FRA Change Oil Filters	Yes		RGASPARD	May 8, 2018 11:48:56 PM	No	
102,000	FRA Drain Engine Oil	Yes		RGASPARD	May 8, 2018 11:48:56 PM	No	
103,000	FRA Check Transmission Fluid	Done		RGASPARD	May 8, 2018 11:48:56 PM	No	
104,000	Lubricate Chassis	-	NA	RGASPARD	May 8, 2018 11:48:56 PM	No	
105,000	Replace or Clean A/C Filters	Done		RGASPARD	May 8, 2018 11:48:56 PM	No	
107,000	FRA Change Primary Fuel Filter	No	NA	RGASPARD	May 8, 2018 11:48:56 PM	No	
108,000	Lube all pivoting Mechanisms	Done		RGASPARD	May 8, 2018 11:48:56 PM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 08-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	May 8, 2018 11:49:19 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	