Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57172682
Invoice No. 55345 - 57172682

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FIRST TRANSIT AC INSPECTION		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	315,373 -

Chronology		
Reported	Feb 12, 2025 11:13:13 AM	Feb 12, 2025 11:13:13 AM
Started		
Completed	Feb 12, 2025 11:29:33 AM	Feb 12, 2025 11:29:33 AM
Down Time		

Work Order Notes

Line 10 VEHICLE RETIRED

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: VEHICLE RETIRED¿
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57172682
Invoice No. 55345 - 57172682

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FIRST TRANSIT AC INSPECTION		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	315,373 -

Activity Header
Activity: 10 001/001/001 AIR CONDITIONING
Activity Note: VEHICLE RETIRED¿
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57172682 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 57533130
Invoice No. 55345 - 57533130

Client Department:
Department: 55345M
Work Order Description
Road Call- tow truck service
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 315,373 - DH

Chronology		
Reported	Oct 25, 2024 3:12:00 PM	Oct 25, 2024 3:12:00 PM
Started		
Completed	Nov 25, 2024 7:25:00 AM	Nov 25, 2024 7:25:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint :VEHICLE DOES NOT START

Cause: BATTERY DEAD

Correction: VEHICLE TOWED FROM 821 SOUTHERN BLVD TO KELLY'S DRIVE

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL-VEHICLE HAS NOT START CONDITION TOWED BY GARDENS
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Oct-24	DSP-TOWING	DIRECT PURCHASES FOR SERVICES TOWING	1	247.5	247.5

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	247.50
Labor:	0.00
Labor Hours:	0.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**247.50**

Work Order Footer

Work Order 57533130 Total	
Parts:	247.50
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**247.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57455631
Invoice No. 55345 - 57455631

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Rear AC malfunction.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	315,155 - DH

Chronology		
Reported	Jul 23, 2024 7:55:00 PM	Jul 23, 2024 7:55:00 PM
Started	Jul 23, 2024 7:57:00 PM	
Completed	Jul 23, 2024 8:42:00 PM	Jul 23, 2024 8:42:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear AC malfunction.

Cause: Unknown.

Correction: Checked vehicles rear AC system, blows cold on all fan speeds. Could not duplicate AC issue.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 23-JUL-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jul 23, 2024 8:42:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		EARJOHNSON	Jul 23, 2024 8:42:27 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jul 23, 2024 8:42:27 PM	No	
400 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jul 23, 2024 8:42:27 PM	No	
700 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jul 23, 2024 8:42:27 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jul 23, 2024 8:42:27 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jul 23, 2024 8:42:27 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57455631
Invoice No. 55345 - 57455631

Client Department:
Department: 55345M
Work Order Description
Rear AC malfunction.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 315,155 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear AC malfunction.
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jul-24	Earl Johnson	0.73	65	47.45

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	47.45
Labor Hours:	0.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**47.45**

Work Order Footer

Work Order 57455631 Total	
Parts:	0.00
Labor:	47.45
Labor Hours:	0.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**47.45**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 57448590
Invoice No. 55345 - 57448590

Client Department:
Department: 55345M
Work Order Description
Road Call- BATTERY LIGHT COMING ON/OFF
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 314,805 - DH

Chronology		
Reported	Jul 15, 2024 11:31:00 AM	Jul 15, 2024 11:31:00 AM
Started	Jul 15, 2024 11:50:00 AM	
Completed	Jul 16, 2024 10:42:00 AM	Jul 16, 2024 10:42:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction: Line 20 Battery Lights flashing on /Off. Remove & Replace Alternator & Replace Serpentine belts. Swap Radiator Cap.upper hose was kinking up .
Parts # KO61360 Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: PRAMETER Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 15-JUL-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		DARTHURS	Jul 15, 2024 11:50:44 AM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		DARTHURS	Jul 15, 2024 11:50:44 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jul 15, 2024 11:50:44 AM	No	
400 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jul 15, 2024 11:50:44 AM	No	
700 - Have you performed the proper LOTO?	Done		DARTHURS	Jul 15, 2024 11:50:44 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jul 15, 2024 11:50:44 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 15, 2024 11:50:44 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 57448590
Invoice No. 55345 - 57448590

Client Department:
Department: 55345M
Work Order Description
Road Call- BATTERY LIGHT COMING ON/OFF
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 314,805 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 57448590
Invoice No. 55345 - 57448590

Client Department:
Department: 55345M
Work Order Description
Road Call- BATTERY LIGHT COMING ON/OFF
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 314,805 - DH

Activity Header
Activity:20 032/001/001 BATTERY
Activity Note: PER DRIVER BATTERY LIGHT KEEPS COMING ON/FF
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Jul-24	K061360	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	30.88	30.88
15-Jul-24	GC2Z-10346-C	ALTERNATOR, 6.8L, E350	1	345.03	345.03

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Jul-24	Arthurs,Durvin	0.87	65	56.55

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	375.91
Labor:	56.55
Labor Hours:	0.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**432.46**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 57448590
Invoice No. 55345 - 57448590

Client Department:
Department: 55345M
Work Order Description
Road Call- BATTERY LIGHT COMING ON/OFF
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 314,805 - DH

Activity Header
Activity: 30 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: NOISE COMING OUT REAC AC SYSTEM
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Jul-24	Arthurs,Durvin	1.2	65	78
15-Jul-24	Arthurs,Durvin	1.15	65	74.75

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	152.75
Labor Hours:	2.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**152.75**

Work Order Footer

Work Order 57448590 Total	
Parts:	375.91
Labor:	209.30
Labor Hours:	3.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**585.21**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 57441682
Invoice No. 55345 - 57441682

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	314,367 - DH

Chronology

Reported	Jul 5, 2024 5:12:04 PM	Jul 5, 2024 5:12:04 PM
Started	Jul 5, 2024 5:46:00 PM	
Completed	Jul 5, 2024 6:51:00 PM	Jul 5, 2024 6:51:00 PM
Down Time		

Work Order Notes

Line 10 Vehicle came for battery issues check found battery need replacement. Installed two new battery to unit part # 652.250 F now working properly return unit back to service line

Activity Header

Activity: 10 032/001/001 BATTERY
Activity Note: BATTERY NEED REPLACE
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Jul-24	65-AGM	BATTERY, GROUP-65, 750CCA, 120MIN-RESERVE	2	165.45	330.9

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jul-24	Junior Hurst	1.08	65	70.2

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	330.90
Labor:	70.20
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**401.10**

Work Order Footer

Work Order 57441682 Total	
Parts:	330.90
Labor:	70.20
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**401.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57316477
Invoice No. 55345 - 57316477

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-MEDIUM DUTY PMA		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	314,367 - DH

Chronology		
Reported	Jul 5, 2024 12:00:00 AM	Jul 5, 2024 12:00:00 AM
Started	Jul 5, 2024 1:49:00 PM	
Completed	Jul 5, 2024 5:42:00 PM	Jul 5, 2024 5:42:00 PM
Down Time		

Work Order Notes

Line 10 SHUTTLE UNIT FROM KELLY DR. TO SHOP FOR SERVICE DUE BY MILEAGE CHANGE OIL FILTER PART B 329

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 05-JUL-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		JUHURST	Jul 5, 2024 5:22:03 PM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		JUHURST	Jul 5, 2024 5:22:03 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Jul 5, 2024 5:22:03 PM	No	
400 - Are you wearing the appropriate PPE?	Done		JUHURST	Jul 5, 2024 5:22:03 PM	No	
700 - Have you performed the proper LOTO?	Done		JUHURST	Jul 5, 2024 5:22:03 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Jul 5, 2024 5:22:03 PM	No	
1,100 - Have you successfully completed the Personal Risk	Done		JUHURST	Jul 5, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Assessment?				5:22:03 PM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57316477
Invoice No. 55345 - 57316477

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-MEDIUM DUTY PMA		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	314,367 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jul-24	Junior Hurst	3.4	65	221

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: JUHURST Performed on: 05-JUL-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
10,800 - CHECK_All Destination Signage	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
10,900 - *RPT*INSPECT_Body Damage,	Done		JUHURST	Jul 5, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Corrosion;DOCUMENT_Issues				5:12:39 PM		
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
20,200 - CHECK_Public Address System	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	80 Second*		JUHURST	Jul 5, 2024 5:12:39 PM	No	
20,700 - RECORD_Brake Performance Test Speed	30 Miles per Hour		JUHURST	Jul 5, 2024 5:12:39 PM	No	
20,800 - RECORD_Brake Performance Test Distance	50 FEET		JUHURST	Jul 5, 2024 5:12:39 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	50 FEET		JUHURST	Jul 5, 2024 5:12:39 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	80 Gravitational Force		JUHURST	Jul 5, 2024 5:12:39 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
21,500 - INSPECT_High Idle Control	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
32,000 - Engine Inspection	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Jul 5, 2024 5:12:39 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*	BATTERY NEED REPLACE	JUHURST	Jul 5, 2024 5:12:39 PM	Yes	57441682
33,000 - CSF (Curb Side Front)	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
33,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
33,050 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
33,060 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	14 Volt*		JUHURST	Jul 5, 2024 5:12:39 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
40,700 - CHECK_Passenger Stop Request System	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
50,400 - LUBE_All Chassis Components	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,700 - INSPECT_Tire Condition	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Jul 5, 2024 5:12:39 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Jul 5, 2024 5:12:39 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Jul 5, 2024 5:12:39 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Jul 5, 2024 5:12:39 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		JUHURST	Jul 5, 2024 5:12:39 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		JUHURST	Jul 5, 2024 5:12:39 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.3 Inch		JUHURST	Jul 5, 2024 5:12:39 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.3 Inch		JUHURST	Jul 5, 2024 5:12:39 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Jul 5, 2024 5:12:39 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Jul 5, 2024 5:12:39 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Jul 5, 2024 5:12:39 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Jul 5, 2024 5:12:39 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Jul 5, 2024 5:12:39 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Jul 5, 2024 5:12:39 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Jul 5, 2024 5:12:39 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Jul 5, 2024 5:12:39 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		JUHURST	Jul 5, 2024 5:12:39 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		JUHURST	Jul 5, 2024 5:12:39 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	1.3 Inch		JUHURST	Jul 5, 2024 5:12:39 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	1.3 Inch		JUHURST	Jul 5, 2024 5:12:39 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		JUHURST	Jul 5, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				5:12:39 PM		
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	2891 Cycles		JUHURST	Jul 5, 2024 5:12:39 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
62,400 - INSPECT_All Pivot Points	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
62,500 - INSPECT_Cams and Slots	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
62,600 - INSPECT_Rollers	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
62,700 - INSPECT_All Linkages	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	Jul 5, 2024 5:12:39 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	221.00
Labor Hours:	3.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**221.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57316477
Invoice No. 55345 - 57316477

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-MEDIUM DUTY PMA		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	314,367 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Jul-24	75050	OIL, ENGINE, 5W/30	1	2.73	2.73
05-Jul-24	75050	OIL, ENGINE, 5W/30	7	2.73	19.11
05-Jul-24	LF16424	FILTER, OIL SUPERSEDES P9600	1	6.22	6.22

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jul-24	Junior Hurst	0.03	65	1.95
05-Jul-24	Junior Hurst	0.22	65	14.3

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: JUHURST Performed on: 05-JUL-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		JUHURST	Jul 5, 2024 5:18:16 PM	No	
101,000 - FRA Change Oil Filters	Yes		JUHURST	Jul 5, 2024 5:18:16 PM	No	
102,000 - FRA Drain Engine Oil	Yes		JUHURST	Jul 5, 2024 5:18:16 PM	No	
103,000 - FRA Check Transmission Fluid	Done		JUHURST	Jul 5, 2024 5:18:16 PM	No	
104,000 - Lubricate Chassis	Done		JUHURST	Jul 5, 2024 5:18:16 PM	No	
105,000 - Replace or Clean A/C Filters	Done		JUHURST	Jul 5, 2024 5:18:16 PM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	Done		JUHURST	Jul 5, 2024 5:18:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
107,000 - FRA Change Primary Fuel Filter	No		JUHURST	Jul 5, 2024 5:18:16 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		JUHURST	Jul 5, 2024 5:18:16 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	28.06
Labor:	16.25
Labor Hours:	0.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**44.31**

Work Order Footer

Work Order 57316477 Total	
Parts:	28.06
Labor:	237.25
Labor Hours:	3.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**265.31**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57395683
Invoice No. 55345 - 57395683

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
VEHICLE NOT STARTING		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	313,158 - DH

Chronology		
Reported	May 12, 2024 12:45:00 PM	May 12, 2024 12:45:00 PM
Started		
Completed	May 28, 2024 10:21:54 AM	May 28, 2024 10:21:54 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: VEHICLE WOULD NOT START

Cause: ALTERNATOR POSITIVE LUG BURNED

Correction: REPLACE ALTERNATOR AND REPLACE POSITIVE LUG TO ALTERNATOR.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57395683
Invoice No. 55345 - 57395683

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
VEHICLE NOT STARTING		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	313,158 - DH

Activity Header
Activity: 15 031 CHARGING
Activity Note: ALTERNATOR
Reason for Repair: 04 Driver's Report
Work Accomplished: 34 Charge / Discharge
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-May-24	DSP-TOWING	DIRECT PURCHASES FOR SERVICES TOWING	1	408.1	408.1
12-May-24	GL8946	ALTERNATOR, 5.4L, E450	1	311.04	311.04

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	719.14
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**719.14**

Work Order Footer

Work Order 57395683 Total	
Parts:	719.14
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**719.14**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 13

Work Order No. 57317817
Invoice No. 55345 - 57317817

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,556 - DH

Chronology		
Reported	Feb 13, 2024 12:50:01 PM	Feb 13, 2024 12:50:01 PM
Started		
Completed	Mar 13, 2024 12:57:00 AM	Mar 13, 2024 12:57:00 AM
Down Time		

Work Order Notes

Line 10 ***VOID***

Activity Header
Activity: 10
Activity Note: interior lights out x3
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 13

Work Order No. 57317817
Invoice No. 55345 - 57317817

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,556 - DH

Activity Header
Activity:20
Activity Note: battery door needs adjustemnt
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 13

Work Order No. 57317817
Invoice No. 55345 - 57317817

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,556 - DH

Activity Header
Activity: 30
Activity Note: exhaust tail pipe hanger missing
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 13

Work Order No. 57317817
Invoice No. 55345 - 57317817

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,556 - DH

Activity Header
Activity:40
Activity Note: windshield washer inop
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 13

Work Order No. 57317817
Invoice No. 55345 - 57317817

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,556 - DH

Activity Header
Activity: 50
Activity Note: driver seat needs a new cushiong and cover
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 50 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 6 of 13

Work Order No. 57317817
Invoice No. 55345 - 57317817

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,556 - DH

Activity Header
Activity:60
Activity Note: shifter rod has play +shifter cable needed
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 60 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 7 of 13

Work Order No. 57317817
Invoice No. 55345 - 57317817

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,556 - DH

Activity Header
Activity: 70
Activity Note: w/c lift needs adjustment
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 70 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 8 of 13

Work Order No. 57317817
Invoice No. 55345 - 57317817

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,556 - DH

Activity Header
Activity: 80
Activity Note: rear ac bad temperature controller
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 80 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 9 of 13

Work Order No. 57317817
Invoice No. 55345 - 57317817

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,556 - DH

Activity Header
Activity: 90
Activity Note: passenger side heat cover loose
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 90 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 10 of 13

Work Order No. 57317817
Invoice No. 55345 - 57317817

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,556 - DH

Activity Header
Activity: 100
Activity Note: first aid and body fluid kit needed
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 100 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 11 of 13

Work Order No. 57317817
Invoice No. 55345 - 57317817

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,556 - DH

Activity Header
Activity: 110
Activity Note: right front lower ball joint has play
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 110 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 12 of 13

Work Order No. 57317817
Invoice No. 55345 - 57317817

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,556 - DH

Activity Header
Activity: 120
Activity Note: oil leak by front of the engine area
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 120 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 13 of 13

Work Order No. 57317817
Invoice No. 55345 - 57317817

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,556 - DH

Activity Header
Activity: 130 999 TOTAL VEHICLE
Activity Note: Fire extenguisher not signed.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 130 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57317817 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57263919
Invoice No. 55345 - 57263919

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
QCC FLEET INSPECTION		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,556 -

Chronology

Reported	Feb 13, 2024 10:07:40 AM	Feb 13, 2024 10:07:40 AM
Started		
Completed	Feb 13, 2024 12:53:00 PM	Feb 13, 2024 12:53:00 PM
Down Time		

Work Order Notes

Line 10 QCC INSPECTION PERFORMED

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: CVERGARA Performed on: 13-FEB-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		CVERGARA	Feb 13, 2024 12:32:12 PM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		CVERGARA	Feb 13, 2024 12:32:12 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		CVERGARA	Feb 13, 2024 12:32:12 PM	No	
400 - Are you wearing the appropriate PPE?	Done		CVERGARA	Feb 13, 2024 12:32:12 PM	No	
700 - Have you performed the proper LOTO?	Done		CVERGARA	Feb 13, 2024 12:32:12 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		CVERGARA	Feb 13, 2024 12:32:12 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		CVERGARA	Feb 13, 2024 12:32:12 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57263919
Invoice No. 55345 - 57263919

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
QCC FLEET INSPECTION		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,556 -

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: QCC FLEET INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: QCC FLEET INSPECTION
Task: 55345 QCC FLEET INSPECTION Performed by: CVERGARA Performed on: 13-FEB-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - EXTERIOR CIRCLE INSPECTION	Done		CVERGARA	Feb 13, 2024 12:51:26 PM	No	
20 - Cleanliness		unit needs to be cleaned	CVERGARA	Feb 13, 2024 12:51:26 PM	No	
30 - Entrance Door Operation/Seals/Glass			CVERGARA	Feb 13, 2024 12:51:26 PM	No	
40 - Body/Fenders/Bumpers		scratches al around the body	CVERGARA	Feb 13, 2024 12:51:26 PM	No	
50 - Tires/Wheels/Lugs			CVERGARA	Feb 13, 2024 12:51:26 PM	No	
60 - Mirrors and Attachments			CVERGARA	Feb 13, 2024 12:51:26 PM	No	
70 - Lights and Accessories		interior lights out x3	CVERGARA	Feb 13, 2024 12:51:26 PM	Yes	57317817
80 - Compartment Doors			CVERGARA	Feb 13, 2024 12:51:26 PM	No	
90 - Battery Compartment		battery door needs adjustemnt	CVERGARA	Feb 13, 2024 12:51:26 PM	Yes	57317817
100 - Check All Fluids			CVERGARA	Feb 13, 2024 12:51:26 PM	No	
110 - Belt Drives			CVERGARA	Feb 13, 2024 12:51:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
120 - Air Induction		n/a	CVERGARA	Feb 13, 2024 12:51:26 PM	No	
130 - Exhaust System		exhaust tail pipe hanger missing	CVERGARA	Feb 13, 2024 12:51:26 PM	Yes	57317817
140 - Engine Compartmetn Wiring			CVERGARA	Feb 13, 2024 12:51:26 PM	No	
150 - DRIVERS AREA INSPECTION	Done		CVERGARA	Feb 13, 2024 12:51:26 PM	No	
160 - Air System		n/a	CVERGARA	Feb 13, 2024 12:51:26 PM	No	
170 - Audible Warnings			CVERGARA	Feb 13, 2024 12:51:26 PM	No	
180 - Dash and Gauges			CVERGARA	Feb 13, 2024 12:51:26 PM	No	
190 - Accessory components			CVERGARA	Feb 13, 2024 12:51:26 PM	No	
200 - Exit Door Operation			CVERGARA	Feb 13, 2024 12:51:26 PM	No	
210 - Exit Door Interlock			CVERGARA	Feb 13, 2024 12:51:26 PM	No	
220 - Fare box and ticket cutter.		n/a	CVERGARA	Feb 13, 2024 12:51:26 PM	No	
230 - Fast Idle			CVERGARA	Feb 13, 2024 12:51:26 PM	No	
240 - Glass & Mirrors		windshield washer inop	CVERGARA	Feb 13, 2024 12:51:26 PM	Yes	57317817
250 - Floor Covering			CVERGARA	Feb 13, 2024 12:51:26 PM	No	
260 - Horn and Lamps			CVERGARA	Feb 13, 2024 12:51:26 PM	No	
270 - Start Function			CVERGARA	Feb 13, 2024 12:51:26 PM	No	
280 - PA System		n/a	CVERGARA	Feb 13, 2024 12:51:26 PM	No	
290 - Pedal Condition and Adjustment			CVERGARA	Feb 13, 2024 12:51:26 PM	No	
300 - Reverse System			CVERGARA	Feb 13, 2024 12:51:26 PM	No	
310 - Seat		driver seat needs a new cushiong and cover	CVERGARA	Feb 13, 2024 12:51:26 PM	Yes	57317817
320 - Steering Wheel & Column		shifter rod has play +shifter cable needed	CVERGARA	Feb 13, 2024 12:51:26 PM	Yes	57317817
330 - Sun Visor			CVERGARA	Feb 13, 2024 12:51:26 PM	No	
340 - Turn Signals Switch			CVERGARA	Feb 13, 2024 12:51:26 PM	No	
350 - Electrical Compartment			CVERGARA	Feb 13, 2024 12:51:26 PM	No	
360 - Wheel Chair Operation		w/c lift needs adjustment	CVERGARA	Feb 13, 2024 12:51:26 PM	Yes	57317817
370 - INTERIOR CIRCLE	-		CVERGARA	Feb 13, 2024 12:51:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
380 - Cleanliness			CVERGARA	Feb 13, 2024 12:51:26 PM	No	
390 - HVAC		rear ac bad temperature controller	CVERGARA	Feb 13, 2024 12:51:26 PM	Yes	57317817
400 - Interior Passenger Area		passenger side heat cover loose	CVERGARA	Feb 13, 2024 12:51:26 PM	Yes	57317817
410 - Stop Request			CVERGARA	Feb 13, 2024 12:51:26 PM	No	
420 - Safety Equipment		first aid and body fluid kit needed	CVERGARA	Feb 13, 2024 12:51:26 PM	Yes	57317817
430 - UNDERCARRIAGE	Done		CVERGARA	Feb 13, 2024 12:51:26 PM	No	
440 - Air System		n/a	CVERGARA	Feb 13, 2024 12:51:26 PM	No	
450 - Steering components		right front lower ball joint has play	CVERGARA	Feb 13, 2024 12:51:26 PM	Yes	57317817
460 - Brake Inspection			CVERGARA	Feb 13, 2024 12:51:26 PM	No	
470 - Suspension Components			CVERGARA	Feb 13, 2024 12:51:26 PM	No	
480 - Frame			CVERGARA	Feb 13, 2024 12:51:26 PM	No	
490 - Fluid Leakage		oil leak by front of the engine area	CVERGARA	Feb 13, 2024 12:51:26 PM	Yes	57317817
500 - Fuel System			CVERGARA	Feb 13, 2024 12:51:26 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57263919 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 57316190
Invoice No. 55345 - 57316190

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,556 - DH

Chronology		
Reported	Feb 11, 2024 10:27:04 AM	Feb 11, 2024 10:27:04 AM
Started	Feb 11, 2024 11:40:00 AM	
Completed	Feb 12, 2024 4:40:00 AM	Feb 12, 2024 4:40:00 AM
Down Time		

Work Order Notes

Line 10 Replaced passenger side rear inner tire

Activity Header

Activity: 10 017/003/001 TIRE, CUSHION W/TREAD
Activity Note:
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Feb-24	NELSON PIERRE-LOUIS	1.18	65	76.7

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	76.70
Labor Hours:	1.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**76.70**

Work Order Footer

Work Order 57316190 Total	
Parts:	0.00
Labor:	76.70
Labor Hours:	1.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**76.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57263797
Invoice No. 55345 - 57263797

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-MEDIUM DUTY PMC		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,556 - DH

Chronology		
Reported	Feb 7, 2024 12:00:00 AM	Feb 7, 2024 12:00:00 AM
Started	Feb 11, 2024 6:22:00 AM	
Completed	Feb 12, 2024 4:39:00 AM	Feb 12, 2024 4:39:00 AM
Down Time		

Work Order Notes

Line 10 Complaint: PMC service

Cause: preventive maintenance

Correction: perform maintenance PMC service and lube rear end service

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 11-FEB-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Feb 11, 2024 8:06:23 AM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		NPIERRE-LOUIS	Feb 11, 2024 8:06:23 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Feb 11, 2024 8:06:23 AM	No	
400 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Feb 11, 2024 8:06:23 AM	No	
700 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Feb 11, 2024 8:06:23 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,000 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Feb 11, 2024 8:06:23 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Feb 11, 2024 8:06:23 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57263797
Invoice No. 55345 - 57263797

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-MEDIUM DUTY PMC		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,556 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Feb-24	NELSON PIERRE-LOUIS	2.07	65	134.55

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS Performed on: 11-FEB-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
10,800 - CHECK_All Destination Signage	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
10,900 - *RPT*INSPECT_Body Damage,	Done		NPIERRE-	Feb 11, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Corrosion;DOCUMENT_Issues			LOUIS	1:08:44 PM		
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
20,200 - CHECK_Public Address System	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	0 Second*		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
20,700 - RECORD_Brake Performance Test Speed	0 Miles per Hour		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
20,800 - RECORD_Brake Performance Test Distance	0 FEET		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	0 FEET		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	0 Gravitational Force		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
21,500 - INSPECT_High Idle Control	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
31,000 - SSF (Street Side Front)	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
32,000 - Engine Inspection	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	0 Degree Fahrenheit		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
32,100 - INSPECT_Intake System	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	13.5 Volt*		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
33,000 - CSF (Curb Side Front)	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-	Feb 11, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	1:08:44 PM		
33,050 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
33,060 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	13.2 Volt*		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
40,700 - CHECK_Passenger Stop Request System	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
50,400 - LUBE_All Chassis Components	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,700 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	11 32nds of an inch		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	76 Pounds per Square Inch		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	11 32nds of an inch		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	78 Pounds per Square Inch		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	35.5 Inch		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	35.5 Inch		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
52,100 - INSPECT_Vibration Damper	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
53,600 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	4 32nds of an inch		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	Yes	57316190
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	5 32nds of an inch		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	76 Pounds per Square Inch		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	76 Pounds per Square Inch		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	11 32nds of an inch		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	11 32nds of an inch		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	78 Pounds per Square Inch		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	77 Pounds per Square Inch		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	25.5 Inch		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	25.5 Inch		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	2000 Cycles		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		NPIERRE-	Feb 11, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	1:08:44 PM		
62,400 - INSPECT_All Pivot Points	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
62,500 - INSPECT_Cams and Slots	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
62,600 - INSPECT_Rollers	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
62,700 - INSPECT_All Linkages	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	Feb 11, 2024 1:08:44 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	134.55
Labor Hours:	2.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**134.55**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57263797
Invoice No. 55345 - 57263797

Client Department:
Department: 55345M
Work Order Description
55345-MEDIUM DUTY PMC
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 310,556 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM C Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Feb-24	75050	OIL, ENGINE, 5W/30	8	2.73	21.84
11-Feb-24	20021	FILTER, TRANSMISSION 20021	1	36.01	36.01

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Feb-24	NELSON PIERRE-LOUIS	1.45	65	94.25

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PM C Service
Task: 55345-Medium Duty PMC Inspection Performed by: NPIERRE-LOUIS Performed on: 11-FEB-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Feb 11, 2024 8:13:13 AM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Feb 11, 2024 8:13:13 AM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Feb 11, 2024 8:13:13 AM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Feb 11, 2024 8:13:13 AM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Feb 11, 2024 8:13:13 AM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Feb 11, 2024 8:13:13 AM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	Done		NPIERRE-LOUIS	Feb 11, 2024 8:13:13 AM	No	
107,000 - FRA Change Primary Fuel Filter	Done		NPIERRE-LOUIS	Feb 11, 2024 8:13:13 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-	Feb 11, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	8:13:13 AM		
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		NPIERRE-LOUIS	Feb 11, 2024 8:13:13 AM	No	
201,000 - Service Crankcase Breather	Done		NPIERRE-LOUIS	Feb 11, 2024 8:13:13 AM	No	
202,000 - FRA Change Water Separator ¿ Secondary Fuel Filters	No		NPIERRE-LOUIS	Feb 11, 2024 8:13:13 AM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		NPIERRE-LOUIS	Feb 11, 2024 8:13:13 AM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		NPIERRE-LOUIS	Feb 11, 2024 8:13:13 AM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		NPIERRE-LOUIS	Feb 11, 2024 8:13:13 AM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		NPIERRE-LOUIS	Feb 11, 2024 8:13:13 AM	No	
301,000 - Check and Lubricate Door Linkages	Done		NPIERRE-LOUIS	Feb 11, 2024 8:13:13 AM	No	
302,000 - Check Toe-In and Record Reading	Done		NPIERRE-LOUIS	Feb 11, 2024 8:13:13 AM	No	
302,001 - Record Toe-In Reading	0 Inches, fraction-actual		NPIERRE-LOUIS	Feb 11, 2024 8:13:13 AM	No	
303,000 - FRA Service Davco Type Water Separators (Secondary Fuel Filter)	Done		NPIERRE-LOUIS	Feb 11, 2024 8:13:13 AM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		NPIERRE-LOUIS	Feb 11, 2024 8:13:13 AM	No	
305,000 - FRA Change Differential Fluid	No		NPIERRE-LOUIS	Feb 11, 2024 8:13:13 AM	No	
306,000 - Change Spark Plugs	Done		NPIERRE-LOUIS	Feb 11, 2024 8:13:13 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	57.85
Labor:	94.25
Labor Hours:	1.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**152.10**

Work Order Footer

Work Order 57263797 Total	
Parts:	57.85
Labor:	228.80
Labor Hours:	3.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**286.65**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57298209
Invoice No. 55345 - 57298209

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Chec engine light illuminated.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,215 - DH

Chronology		
Reported	Jan 21, 2024 9:59:00 AM	Jan 21, 2024 9:59:00 AM
Started	Jan 21, 2024 10:01:00 AM	
Completed	Jan 24, 2024 3:29:00 PM	Jan 24, 2024 3:29:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Wrench light illuminated.

Cause: Transmission fault P0713 DTC.

Correction: Noted for repair. Out of service for trans temp sensor and valve body harness replacement.

Replaced transmission temperature sensor,valve body harness,test drive the vehicle everything ok at this time

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 24-JAN-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Jan 24, 2024 3:25:33 PM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		NPIERRE-LOUIS	Jan 24, 2024 3:25:33 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Jan 24, 2024 3:25:33 PM	No	
400 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Jan 24, 2024 3:25:33 PM	No	
700 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Jan 24, 2024 3:25:33 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Jan 24, 2024 3:25:33 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Jan 24, 2024 3:25:33 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57298209
Invoice No. 55345 - 57298209

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Chec engine light illuminated.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,215 - DH

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Check engine light illuminated.
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Jan-24	8C3Z-7C155-A	GASKET, BODY, VALVE, TRANSMISSION, 5R110	1	13.87	13.87
24-Jan-24	BC3Z-7H141-A	SENSOR, TEMPERATURE, TRANSMISSION	1	23.8	23.8
24-Jan-24	4C3Z-7G276-AA	HARNESS, SOLENOID, INTERNAL, TRANSMISSION, 5R110W	1	211.17	211.17

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jan-24	Earl Johnson	1.6	65	104

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	248.84
Labor:	104.00
Labor Hours:	1.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**352.84**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57298209
Invoice No. 55345 - 57298209

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Chec engine light illuminated.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,215 - DH

Activity Header
Activity:25 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: Check engine light on p0713
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Jan-24	20021	FILTER, TRANSMISSION 20021	1	36.01	36.01

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Jan-24	NELSON PIERRE-LOUIS	3.87	65	251.55

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	36.01
Labor:	251.55
Labor Hours:	3.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**287.56**

Work Order Footer

Work Order 57298209 Total	
Parts:	284.85
Labor:	355.55
Labor Hours:	5.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**640.40**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57297808
Invoice No. 55345 - 57297808

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
LF tire flat		Ford E450 Champion Challenger	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,215 - DH

Chronology		
Reported	Jan 20, 2024 9:56:00 AM	Jan 20, 2024 9:56:00 AM
Started	Jan 20, 2024 12:16:00 PM	
Completed	Jan 20, 2024 1:36:00 PM	Jan 20, 2024 1:36:00 PM
Down Time		

Work Order Notes

Line 10 LF tire patched

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: NBARRETO Performed on: 20-JAN-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		NBARRETO	Jan 20, 2024 9:58:20 AM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		NBARRETO	Jan 20, 2024 9:58:20 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NBARRETO	Jan 20, 2024 9:58:20 AM	No	
400 - Are you wearing the appropriate PPE?	Done		NBARRETO	Jan 20, 2024 9:58:20 AM	No	
700 - Have you performed the proper LOTO?	Done		NBARRETO	Jan 20, 2024 9:58:20 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,000 - Are you aware of the potential risks of performing this repair?	Done		NBARRETO	Jan 20, 2024 9:58:20 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		NBARRETO	Jan 20, 2024 9:58:20 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57297808
Invoice No. 55345 - 57297808

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
LF tire flat		Ford E450 Champion Challenger	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,215 - DH

Activity Header
Activity: 20 017/001/000 TIRE, PNEUMATIC
Activity Note: FRONT TIRES
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jan-24	Nicolas Barreto	1.32	65	85.8

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	85.80
Labor Hours:	1.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**85.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57297808
Invoice No. 55345 - 57297808

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
LF tire flat		Ford E450 Champion Challenger	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,215 - DH

Activity Header
Activity:30 017/001/000 TIRE, PNEUMATIC
Activity Note: REAR TIRES
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57297808 Total	
Parts:	0.00
Labor:	85.80
Labor Hours:	1.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**85.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57284350
Invoice No. 55345 - 57284350

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Check drivers seat.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	308,446 - DH

Chronology		
Reported	Jan 3, 2024 9:39:00 PM	Jan 3, 2024 9:39:00 PM
Started	Jan 3, 2024 9:43:00 PM	
Completed	Jan 3, 2024 10:30:00 PM	Jan 3, 2024 10:30:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Check drivers seat.

Cause: Unknown.

Correction: Driver complained seat is ¿uncomfortable ¿, checked vehicles seat and found no unusual defects.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 03-JAN-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jan 3, 2024 10:27:58 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		EARJOHNSON	Jan 3, 2024 10:27:58 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jan 3, 2024 10:27:58 PM	No	
400 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jan 3, 2024 10:27:58 PM	No	
700 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jan 3, 2024 10:27:58 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jan 3, 2024 10:27:58 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jan 3, 2024 10:27:58 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57284350
Invoice No. 55345 - 57284350

Client Department:
Department: 55345M
Work Order Description
Check drivers seat.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 308,446 - DH

Activity Header
Activity: 15 174 BODY, BUS
Activity Note: Check drivers seat.
Reason for Repair: 04 Driver's Report
Work Accomplished: 13 Other Mnt Repair
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jan-24	Earl Johnson	0.47	65	30.55

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	30.55
Labor Hours:	0.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**30.55**

Work Order Footer

Work Order 57284350 Total	
Parts:	0.00
Labor:	30.55
Labor Hours:	0.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**30.55**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57280813
Invoice No. 55345 - 57280813

Client Department:
Department: 55345M
Work Order Description
Bus won¿t move
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 308,434 - DH

Chronology		
Reported	Dec 29, 2023 5:40:12 AM	Dec 29, 2023 5:40:12 AM
Started	Dec 29, 2023 5:43:00 AM	
Completed	Dec 29, 2023 8:21:00 AM	Dec 29, 2023 8:21:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:Driver road call driver said bus won¿t start

Cause: nothing wrong with it

Correction: Driver didn¿t want to drive the bus completed

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 29-DEC-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		HPIERRE	Dec 29, 2023 8:20:42 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		HPIERRE	Dec 29, 2023 8:20:42 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Dec 29, 2023 8:20:42 AM	No	
400 - Are you wearing the appropriate PPE?	Done		HPIERRE	Dec 29, 2023 8:20:42 AM	No	
700 - Have you performed the proper LOTO?	Done		HPIERRE	Dec 29, 2023 8:20:42 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Dec 29, 2023 8:20:42 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Dec 29, 2023 8:20:42 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57280813
Invoice No. 55345 - 57280813

Client Department:
Department: 55345M
Work Order Description
Bus won¿t move
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 308,434 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Dec-23	Pierre,Hubert J	2.63	65	170.95

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	170.95
Labor Hours:	2.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**170.95**

Work Order Footer

Work Order 57280813 Total	
Parts:	0.00
Labor:	170.95
Labor Hours:	2.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**170.95**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57272877
Invoice No. 55345 - 57272877

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Front AC malfunction.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	307,882 - DH

Chronology		
Reported	Dec 18, 2023 9:05:02 PM	Dec 18, 2023 9:05:02 PM
Started	Dec 18, 2023 9:06:00 PM	
Completed	Dec 20, 2023 10:37:00 AM	Dec 20, 2023 10:37:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Front AC not working.

Cause: Front charge pressure low (evaporator).

Correction: Added PAG oil and recharged front AC to spec. Front evaporator seeping, will need to be replaced. Line 20 Lubricated WC lift pivot points. Roll stop opens closes as intended. Ran lift thru 4 consecutive cycles, weighted without any issues. Line 30 Front Evaporator Leaking. Remove &Replace Front Evaporator. Replace Accumulator. Replace Orifice tube. Charge A/C (1.88) Lbs Add (4,0) Oz Pag Oil. All is good at this time.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 20-DEC-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		DARTHURS	Dec 20, 2023 10:37:31 AM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		DARTHURS	Dec 20, 2023 10:37:31 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Dec 20, 2023 10:37:31 AM	No	
400 - Are you wearing the appropriate PPE?	Done		DARTHURS	Dec 20, 2023 10:37:31 AM	No	
700 - Have you performed the proper LOTO?	Done		DARTHURS	Dec 20, 2023 10:37:31 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Dec 20, 2023 10:37:31 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Dec 20, 2023 10:37:31 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57272877
Invoice No. 55345 - 57272877

Client Department:
Department: 55345M
Work Order Description
Front AC malfunction.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 307,882 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Front AC malfunction.
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Dec-23	YF-37655	ACCUMULATOR, A/C	1	59.97	59.97
20-Dec-23	3411885	TUBE, ORIFICE, A/C, FORD	1	0.9	0.9
20-Dec-23	6C2Z-19860-C	CORE, EVAPORATOR, A/C	1	91.61	91.61

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Dec-23	Earl Johnson	1.57	65	102.05
19-Dec-23	Arthurs,Durvin	1.82	65	118.3

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	152.48
Labor:	220.35
Labor Hours:	3.39
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**372.83**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57272877
Invoice No. 55345 - 57272877

Client Department:
Department: 55345M
Work Order Description
Front AC malfunction.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 307,882 - DH

Activity Header
Activity: 25 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: WC lift malfunction.
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Dec-23	Earl Johnson	1.25	65	81.25

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	0.00
Labor:	81.25
Labor Hours:	1.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**81.25**

Work Order Footer

Work Order 57272877 Total	
Parts:	152.48
Labor:	301.60
Labor Hours:	4.64
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**454.08**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57266741
Invoice No. 55345 - 57266741

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Check brakes.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	306,989 - DH

Chronology		
Reported	Dec 11, 2023 10:11:19 PM	Dec 11, 2023 10:11:19 PM
Started	Dec 11, 2023 10:12:00 PM	
Completed	Dec 12, 2023 12:29:00 AM	Dec 12, 2023 12:29:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Check brakes (squeaking).

Cause: Unknown.

Correction: Racked vehicle and checked vehicles brakes. Front and rear pads have been recently replaced. Front pads at(11mm) rear pads at (11mm). Not defects found durng visual inspection. Road tested vehicle without any issues.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 12-DEC-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		EARJOHNSON	Dec 12, 2023 12:23:44 AM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		EARJOHNSON	Dec 12, 2023 12:23:44 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Dec 12, 2023 12:23:44 AM	No	
400 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Dec 12, 2023 12:23:44 AM	No	
700 - Have you performed the proper LOTO?	Done		EARJOHNSON	Dec 12, 2023 12:23:44 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Dec 12, 2023 12:23:44 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Dec 12, 2023 12:23:44 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57266741
Invoice No. 55345 - 57266741

Client Department:
Department: 55345M
Work Order Description
Check brakes.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 306,989 - DH

Activity Header
Activity: 15 013/000/000 BRAKES
Activity Note: Check brakes.
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Dec-23	Earl Johnson	1.28	65	83.2

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	83.20
Labor Hours:	1.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**83.20**

Work Order Footer

Work Order 57266741 Total	
Parts:	0.00
Labor:	83.20
Labor Hours:	1.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**83.20**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 57263775
Invoice No. 55345 - 57263775

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	306,924 - DH

Chronology		
Reported	Dec 7, 2023 4:00:38 PM	Dec 7, 2023 4:00:38 PM
Started		
Completed	Dec 10, 2023 5:37:37 PM	Dec 10, 2023 5:37:37 PM
Down Time		

Work Order Notes

Activity Header
Activity: 10
Activity Note: leaking oil from crunk area
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57263775 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 6

Work Order No. 57263910
Invoice No. 55345 - 57263910

Client Department:
Department: 55345M
Work Order Description
FOLLOW UP TO QCC INSP
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 306,924 - DH

Chronology		
Reported	Dec 7, 2023 7:12:37 PM	Dec 7, 2023 7:12:37 PM
Started	Dec 7, 2023 7:50:00 PM	
Completed	Dec 8, 2023 9:32:00 PM	Dec 8, 2023 9:32:00 PM
Down Time		

Work Order Notes

Line 10 Change L A. D LIGHT. ONE PART #. 3976389 lamp now working perfect Line 20 Replace T. Junction windshield washer now working asdesign Line 30 Replace tag for fire extinguisher Line 40 Need two master shocks for lift door part # 762 Q-009N also front and rear brakes for NEXT DAY Line 50 Removed and replace front brakes part # 8C2Z-2001 Line 60 Start on the rear. Brakes replace part # 8C2Z 2V200-C after test drive unit working perfect Line 70 First aid kit replace. Job complete

Activity Header
Activity: 10
Activity Note: interior LED light not glowing
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Dec-23	3976389	LAMP, INTERIOR, LED	1	21.42	21.42

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Dec-23	Junior Hurst	0.65	65	42.25

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	21.42
Labor:	42.25
Labor Hours:	0.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**63.67**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 6

Work Order No. 57263910
Invoice No. 55345 - 57263910

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	306,924 - DH

Activity Header
Activity:20
Activity Note: Windshield wipers fluid
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Dec-23	Junior Hurst	1.3	65	84.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	84.50
Labor Hours:	1.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**84.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 6

Work Order No. 57263910
Invoice No. 55345 - 57263910

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	306,924 - DH

Activity Header
Activity:30
Activity Note: First Aid kit expired items.
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Dec-23	Junior Hurst	0.85	65	55.25

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	55.25
Labor Hours:	0.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**55.25**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 6

Work Order No. 57263910
Invoice No. 55345 - 57263910

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	306,924 - DH

Activity Header
Activity:40
Activity Note: Fire extinguisher inspection card
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 6

Work Order No. 57263910
Invoice No. 55345 - 57263910

Client Department:
Department: 55345M
Work Order Description
FOLLOW UP TO QCC INSP
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 306,924 - DH

Activity Header
Activity: 50
Activity Note: Front and rear brake pads
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Dec-23	BRSD1330B	PADS, BRAKE, DISC, REAR SAME AS 8C2Z-2V200-C	1	55.79	55.79
08-Dec-23	8C2Z-2001-C	PADS, BRAKE, DISC, FRONT SAME AS PFH132820	1	67.43	67.43

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Dec-23	Junior Hurst	4.17	65	271.05

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 50 Sub Total	
Parts:	123.22
Labor:	271.05
Labor Hours:	4.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**394.27**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 6 of 6

Work Order No. 57263910
Invoice No. 55345 - 57263910

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	306,924 - DH

Activity Header
Activity:60
Activity Note: Front engine cover oil leak.
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 60 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57263910 Total	
Parts:	144.64
Labor:	453.05
Labor Hours:	6.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**597.69**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57255438
Invoice No. 55345 - 57255438

Client Department:
Department: 55345M
Work Order Description
Road Call
Requested By: NBARRETO
Created By: NBARRETO
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 306,462 - DH

Chronology		
Reported	Nov 28, 2023 2:50:01 PM	Nov 28, 2023 2:50:01 PM
Started	Nov 28, 2023 2:51:00 PM	
Completed	Dec 8, 2023 1:20:00 PM	Dec 8, 2023 1:20:00 PM
Down Time		

Work Order Notes

Line 10 Engine shutting off 3 times while coming back, no check engine light Line 20 VEHICLE HAS BEEN INSPECTED FOR THIS ISSUE, PLEASE SEE WORK ORDER 57255620

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: NBARRETO Performed on: 28-NOV-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		NBARRETO	Nov 28, 2023 2:50:56 PM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		NBARRETO	Nov 28, 2023 2:50:56 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NBARRETO	Nov 28, 2023 2:50:56 PM	No	
400 - Are you wearing the appropriate PPE?	Done		NBARRETO	Nov 28, 2023 2:50:56 PM	No	
700 - Have you performed the proper LOTO?	Done		NBARRETO	Nov 28, 2023 2:50:56 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,000 - Are you aware of the potential risks of performing this repair?	Done		NBARRETO	Nov 28, 2023 2:50:56 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		NBARRETO	Nov 28, 2023 2:50:56 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57255438
Invoice No. 55345 - 57255438

Client Department:
Department: 55345M
Work Order Description
Road Call
Requested By: NBARRETO
Created By: NBARRETO
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 306,462 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Nov-23	Nicolas Barreto	1.95	65	126.75

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	126.75
Labor Hours:	1.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**126.75**

Work Order Footer

Work Order 57255438 Total	
Parts:	0.00
Labor:	126.75
Labor Hours:	1.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**126.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56161190
Invoice No. 55345 - 56161190

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
QCC FLEET INSPECTION		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	306,924 -

Chronology		
Reported	Dec 7, 2023 5:09:17 PM	Dec 7, 2023 5:09:17 PM
Started		
Completed	Dec 7, 2023 7:25:00 PM	Dec 7, 2023 7:25:00 PM
Down Time		

Work Order Notes

Line 10 QCC INSPECTION COMPLETED
One interior LED light not glowing
Windshield wipers fluid
Electrical wires exposed
W/C lift door gas spring
Front and rear brake pads closed to the specs need to be replaced.
Engine oil leak at the front engine cover

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 07-DEC-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		FSIMON	Dec 7, 2023 5:17:22 PM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		FSIMON	Dec 7, 2023 5:17:22 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		FSIMON	Dec 7, 2023 5:17:22 PM	No	
400 - Are you wearing the appropriate PPE?	Done		FSIMON	Dec 7, 2023 5:17:22 PM	No	
700 - Have you performed the proper LOTO?	Done		FSIMON	Dec 7, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				5:17:22 PM		
1,000 - Are you aware of the potential risks of performing this repair?	Done		FSIMON	Dec 7, 2023 5:17:22 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Dec 7, 2023 5:17:22 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56161190
Invoice No. 55345 - 56161190

Client Department:
Department: 55345M
Work Order Description
QCC FLEET INSPECTION
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 306,924 -

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: QCC FLEET INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: QCC FLEET INSPECTION
Task: 55345 QCC FLEET INSPECTION Performed by: FSIMON Performed on: 07-DEC-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - EXTERIOR CIRCLE INSPECTION	Done		FSIMON	Dec 7, 2023 7:12:29 PM	No	
20 - Cleanliness	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
30 - Entrance Door Operation/Seals/Glass	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
40 - Body/Fenders/Bumpers	A	scratches	FSIMON	Dec 7, 2023 7:12:29 PM	No	
50 - Tires/Wheels/Lugs	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
60 - Mirrors and Attachments	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
70 - Lights and Accessories	B	interior LED light not glowing	FSIMON	Dec 7, 2023 7:12:29 PM	Yes	57263910
80 - Compartment Doors	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
90 - Battery Compartment	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
100 - Check All Fluids	B	Windshield wipers fluid	FSIMON	Dec 7, 2023 7:12:29 PM	Yes	57263910
110 - Belt Drives	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
120 - Air Induction	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
130 - Exhaust System	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
140 - Engine Compartmetn Wiring	B	Wires exposed	FSIMON	Dec 7, 2023 7:12:29 PM	No	
150 - DRIVERS AREA INSPECTION	Done		FSIMON	Dec 7, 2023 7:12:29 PM	No	
160 - Air System	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
170 - Audible Warnings	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
180 - Dash and Gauges	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
190 - Accessory components	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
200 - Exit Door Operation	B	W/C lift door not opening properly	FSIMON	Dec 7, 2023 7:12:29 PM	No	
210 - Exit Door Interlock	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
220 - Fare box and ticket cutter.	E		FSIMON	Dec 7, 2023 7:12:29 PM	No	
230 - Fast Idle	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
240 - Glass & Mirrors	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
250 - Floor Covering	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
260 - Horn and Lamps	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
270 - Start Function	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
280 - PA System	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
290 - Pedal Condition and Adjustment	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
300 - Reverse System	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
310 - Seat	B	Driver¿s seat small cut	FSIMON	Dec 7, 2023 7:12:29 PM	No	
320 - Steering Wheel & Column	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
330 - Sun Visor	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
340 - Turn Signals Switch	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
350 - Electrical Compartment	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
360 - Wheel Chair Operation	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
370 - INTERIOR CIRCLE	Done	First Aid kit expired items.	FSIMON	Dec 7, 2023 7:12:29 PM	Yes	57263910

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
380 - Cleanliness	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
390 - HVAC	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
400 - Interior Passenger Area	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
410 - Stop Request	E		FSIMON	Dec 7, 2023 7:12:29 PM	No	
420 - Safety Equipment	B	Fire extinguisher inspection card	FSIMON	Dec 7, 2023 7:12:29 PM	Yes	57263910
430 - UNDERCARRIAGE	Done		FSIMON	Dec 7, 2023 7:12:29 PM	No	
440 - Air System	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
450 - Steering components	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
460 - Brake Inspection	B	Front and rear brake pads	FSIMON	Dec 7, 2023 7:12:29 PM	Yes	57263910
470 - Suspension Components	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
480 - Frame	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	
490 - Fluid Leakage	B	Front engine cover oil leak.	FSIMON	Dec 7, 2023 7:12:29 PM	Yes	57263910
500 - Fuel System	A		FSIMON	Dec 7, 2023 7:12:29 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 56161190 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57210713
Invoice No. 55345 - 57210713

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-MEDIUM DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	306,924 - DH

Chronology		
Reported	Dec 7, 2023 12:00:00 AM	Dec 7, 2023 12:00:00 AM
Started	Dec 7, 2023 1:23:00 PM	
Completed	Dec 7, 2023 4:26:00 PM	Dec 7, 2023 4:26:00 PM
Down Time		

Work Order Notes

Line 10 Vehicle came in for service due by mileage change oil filter part # LF3681 Unit leaking oil between front cover lower left side Also road test unit for ten miles and the unit never cut off working perfect unit back to work

Activity Header

Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 07-DEC-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		JUHURST	Dec 7, 2023 1:22:57 PM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		JUHURST	Dec 7, 2023 1:22:57 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Dec 7, 2023 1:22:57 PM	No	
400 - Are you wearing the appropriate PPE?	Done		JUHURST	Dec 7, 2023 1:22:57 PM	No	
700 - Have you performed the proper LOTO?	Done		JUHURST	Dec 7, 2023 1:22:57 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Dec 7, 2023 1:22:57 PM	No	
1,100 - Have you successfully completed the Personal Risk	Done		JUHURST	Dec 7, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Assessment?				1:22:57 PM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57210713
Invoice No. 55345 - 57210713

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-MEDIUM DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	306,924 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Dec-23	Junior Hurst	1.38	65	89.7

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: JUHURST Performed on: 07-DEC-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
10,800 - CHECK_All Destination Signage	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
10,900 - *RPT*INSPECT_Body Damage,	Done		JUHURST	Dec 7, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Corrosion;DOCUMENT_Issues				4:26:15 PM		
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
20,200 - CHECK_Public Address System	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	80 Second*		JUHURST	Dec 7, 2023 4:26:15 PM	No	
20,700 - RECORD_Brake Performance Test Speed	30 Miles per Hour		JUHURST	Dec 7, 2023 4:26:15 PM	No	
20,800 - RECORD_Brake Performance Test Distance	50 FEET		JUHURST	Dec 7, 2023 4:26:15 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	50 FEET		JUHURST	Dec 7, 2023 4:26:15 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	80 Gravitational Force		JUHURST	Dec 7, 2023 4:26:15 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
21,500 - INSPECT_High Idle Control	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
32,000 - Engine Inspection	Done	leaking oil from crunk area	JUHURST	Dec 7, 2023 4:26:15 PM	Yes	57263775
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Dec 7, 2023 4:26:15 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Dec 7, 2023 4:26:15 PM	No	
33,000 - CSF (Curb Side Front)	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
33,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
33,050 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
33,060 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	14 Volt*		JUHURST	Dec 7, 2023 4:26:15 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
40,700 - CHECK_Passenger Stop Request System	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
50,400 - LUBE_All Chassis Components	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,700 - INSPECT_Tire Condition	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Dec 7, 2023 4:26:15 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Dec 7, 2023 4:26:15 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Dec 7, 2023 4:26:15 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Dec 7, 2023 4:26:15 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		JUHURST	Dec 7, 2023 4:26:15 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		JUHURST	Dec 7, 2023 4:26:15 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.2699 Inch		JUHURST	Dec 7, 2023 4:26:15 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.2699 Inch		JUHURST	Dec 7, 2023 4:26:15 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Dec 7, 2023 4:26:15 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	11 32nds of an inch		JUHURST	Dec 7, 2023 4:26:15 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Dec 7, 2023 4:26:15 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Dec 7, 2023 4:26:15 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Dec 7, 2023 4:26:15 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Dec 7, 2023 4:26:15 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Dec 7, 2023 4:26:15 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Dec 7, 2023 4:26:15 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Dec 7, 2023 4:26:15 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Dec 7, 2023 4:26:15 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	1.2699 Inch		JUHURST	Dec 7, 2023 4:26:15 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	1.2699 Inch		JUHURST	Dec 7, 2023 4:26:15 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		JUHURST	Dec 7, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				4:26:15 PM		
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	15846 Cycles		JUHURST	Dec 7, 2023 4:26:15 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
62,400 - INSPECT_All Pivot Points	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
62,500 - INSPECT_Cams and Slots	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
62,600 - INSPECT_Rollers	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
62,700 - INSPECT_All Linkages	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	Dec 7, 2023 4:26:15 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	89.70
Labor Hours:	1.38
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**89.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57210713
Invoice No. 55345 - 57210713

Client Department:
Department: 55345M
Work Order Description
55345-MEDIUM DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 306,924 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Dec-23	LF3681	FILTER, OIL, SPIN-ON SEE P550965	-1	5.47	-5.47
07-Dec-23	LF3681	FILTER, OIL, SPIN-ON SEE P550965	1	5.47	5.47
08-Dec-23	LF16424	FILTER, OIL SUPERSEDES P9600	1	7.92	7.92
08-Dec-23	75050	OIL, ENGINE, 5W/30	8	2.73	21.84

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Dec-23	Junior Hurst	1.63	65	105.95

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: JUHURST Performed on: 07-DEC-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		JUHURST	Dec 7, 2023 3:00:59 PM	No	
101,000 - FRA Change Oil Filters	Yes		JUHURST	Dec 7, 2023 3:00:59 PM	No	
102,000 - FRA Drain Engine Oil	Yes		JUHURST	Dec 7, 2023 3:00:59 PM	No	
103,000 - FRA Check Transmission Fluid	Done		JUHURST	Dec 7, 2023 3:00:59 PM	No	
104,000 - Lubricate Chassis	Done		JUHURST	Dec 7, 2023 3:00:59 PM	No	
105,000 - Replace or Clean A/C Filters	Done		JUHURST	Dec 7, 2023 3:00:59 PM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	Done		JUHURST	Dec 7, 2023 3:00:59 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
107,000 - FRA Change Primary Fuel Filter	Yes		JUHURST	Dec 7, 2023 3:00:59 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		JUHURST	Dec 7, 2023 3:00:59 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	29.76
Labor:	105.95
Labor Hours:	1.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**135.71**

Work Order Footer

Work Order 57210713 Total	
Parts:	29.76
Labor:	195.65
Labor Hours:	3.01
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**225.41**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 57255620
Invoice No. 55345 - 57255620

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Engine stalled.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	306,462 - DH

Chronology		
Reported	Nov 28, 2023 6:22:49 PM	Nov 28, 2023 6:22:49 PM
Started	Nov 28, 2023 6:24:00 PM	
Completed	Dec 4, 2023 3:49:00 PM	Dec 4, 2023 3:49:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Vehicle stalled.

Cause: Engine has a misfire (cyl 2).

Correction: Noted for heater hoses to be replaced and cyl 2 ignition coil to be replaced. Line 20 Check Misfire Found Code PO (302) / (Code PO (307) / PO (310) Remove & Replace # (2) / # (7) & # (10) Coil. Remove & Replace Both Heater hose.
Parts #BC2Z-18472-CA Qty (1)
Parts #BC2Z-18472-DA Qty (1)
Parts #DG508. Qty (3)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 29-NOV-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		EARJOHNSON	Nov 29, 2023 1:01:14 AM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		EARJOHNSON	Nov 29, 2023 1:01:14 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Nov 29, 2023 1:01:14 AM	No	
400 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Nov 29, 2023 1:01:14 AM	No	
700 - Have you performed the proper LOTO?	Done		EARJOHNSON	Nov 29, 2023 1:01:14 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Nov 29, 2023 1:01:14 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Nov 29, 2023 1:01:14 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 57255620
Invoice No. 55345 - 57255620

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Engine stalled.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	306,462 - DH

Activity Header
Activity: 15 045 POWER PLANT
Activity Note: Vehicles engine stalled.
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Dec-23	Arthurs,Durvin	0.68	65	44.2
28-Nov-23	Earl Johnson	2.6	65	169

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	213.20
Labor Hours:	3.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**213.20**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 57255620
Invoice No. 55345 - 57255620

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Engine stalled.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	306,462 - DH

Activity Header
Activity: 25 042 COOLING SYSTEM
Activity Note: COOLING HOSES
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Dec-23	BC2Z-18472-DA	TUBE, HEATER, WATER	1	56.91	56.91

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Dec-23	Arthurs,Durvin	3.17	65	206.05
04-Dec-23	Arthurs,Durvin	1.48	65	96.2

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	56.91
Labor:	302.25
Labor Hours:	4.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**359.16**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 57255620
Invoice No. 55345 - 57255620

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Engine stalled.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	306,462 - DH

Activity Header
Activity: 35 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: MULTIPLE CYLINDERS MISFIRE
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 24 Repair
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Dec-23	DG508	COIL, IGNITION SAME AS 3W7Z-12029-AA	2	44.52	89.04
04-Dec-23	DG508	COIL, IGNITION SAME AS 3W7Z-12029-AA	1	44.52	44.52

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 35 Sub Total	
Parts:	133.56
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**133.56**

Work Order Footer

Work Order 57255620 Total	
Parts:	190.47
Labor:	515.45
Labor Hours:	7.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**705.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57244527
Invoice No. 55345 - 57244527

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Check Engine Light on		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	305,508 - DH

Chronology		
Reported	Nov 15, 2023 9:07:23 AM	Nov 15, 2023 9:07:23 AM
Started	Nov 15, 2023 9:09:00 AM	
Completed	Nov 15, 2023 2:13:00 PM	Nov 15, 2023 2:13:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Check Engine Light on

Cause: Code PO 340 /PO 300 CamShaft sensor / Random Misfire

Correction: Perform Compression Test . OK . #(6) / # (1) Misfire. Replace #(1) Spark plugs & # (6).Secure Cam Shaft Sensor wire.Wire was disconnected. Clear Code Road test all is Ok at this time.
Parts # SP521 Qty (2)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 15-NOV-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		DARTHURS	Nov 15, 2023 9:09:49 AM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		DARTHURS	Nov 15, 2023 9:09:49 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Nov 15, 2023 9:09:49 AM	No	
400 - Are you wearing the appropriate PPE?	Done		DARTHURS	Nov 15, 2023 9:09:49 AM	No	
700 - Have you performed the proper LOTO?	Done		DARTHURS	Nov 15, 2023 9:09:49 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Nov 15, 2023 9:09:49 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Nov 15, 2023 9:09:49 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57244527
Invoice No. 55345 - 57244527

Client Department:
Department: 55345M
Work Order Description
Check Engine Light on
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 305,508 - DH

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Nov-23	SP521	PLUG, SPARK, 5.4L, FORD	2	4.14	8.28

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Nov-23	Arthurs,Durvin	0.23	65	14.95
15-Nov-23	Arthurs,Durvin	3.67	65	238.55

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	8.28
Labor:	253.50
Labor Hours:	3.90
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**261.78**

Work Order Footer

Work Order 57244527 Total	
Parts:	8.28
Labor:	253.50
Labor Hours:	3.90
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**261.78**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 57210649
Invoice No. 55345 - 57210649

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	303,273 - DH

Chronology

Reported	Oct 25, 2023 7:11:07 PM	Oct 25, 2023 7:11:07 PM
Started	Oct 25, 2023 8:01:00 PM	
Completed	Oct 25, 2023 8:29:00 PM	Oct 25, 2023 8:29:00 PM
Down Time		

Work Order Notes

Line 10 Needs air filter
Bad
Replace air filter
Part number AF25590 qty1

Activity Header
Activity: 10 041 INTAKE, AIR
Activity Note: needs air filter
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Oct-23	AF25590	FILTER, AIR SEE P546597	1	12.9	12.9

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Oct-23	Gaspard,Ronald	0.43	65	27.95

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	12.90
Labor:	27.95
Labor Hours:	0.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**40.85**

Work Order Footer

Work Order 57210649 Total	
Parts:	12.90
Labor:	27.95
Labor Hours:	0.43

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**40.85**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56752099
Invoice No. 55345 - 56752099

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-MEDIUM DUTY PMA		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	303,273 - DH

Chronology		
Reported	Oct 25, 2023 12:00:00 AM	Oct 25, 2023 12:00:00 AM
Started	Oct 25, 2023 5:35:00 PM	
Completed	Oct 25, 2023 8:01:00 PM	Oct 25, 2023 8:01:00 PM
Down Time		

Work Order Notes

Line 10 PMA
Service
Perform PMA service
Oil filter LF3681 qty1
Engine oil 10w30 qty 8 qts
Add washer fluid
Replace air filter AF25590 qty1

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 25-OCT-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		RGASPARD	Oct 25, 2023 5:35:05 PM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		RGASPARD	Oct 25, 2023 5:35:05 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Oct 25, 2023 5:35:05 PM	No	
400 - Are you wearing the appropriate PPE?	Done		RGASPARD	Oct 25, 2023 5:35:05 PM	No	
700 - Have you performed the proper LOTO?	Done		RGASPARD	Oct 25, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				5:35:05 PM		
1,000 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Oct 25, 2023 5:35:05 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Oct 25, 2023 5:35:05 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56752099
Invoice No. 55345 - 56752099

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-MEDIUM DUTY PMA		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	303,273 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Oct-23	Gaspard,Ronald	1.77	65	115.05

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 25-OCT-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
10,800 - CHECK_All Destination Signage	Done	NA	RGASPARD	Oct 25, 2023 7:11:04 PM	No	
10,900 - *RPT*INSPECT_Body Damage,	Done		RGASPARD	Oct 25, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Corrosion;DOCUMENT_Issues				7:11:04 PM		
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
20,200 - CHECK_Public Address System	Done	NA	RGASPARD	Oct 25, 2023 7:11:04 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	NA	RGASPARD	Oct 25, 2023 7:11:04 PM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	NA	RGASPARD	Oct 25, 2023 7:11:04 PM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	NA	RGASPARD	Oct 25, 2023 7:11:04 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	NA	RGASPARD	Oct 25, 2023 7:11:04 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	NA	RGASPARD	Oct 25, 2023 7:11:04 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done	NA	RGASPARD	Oct 25, 2023 7:11:04 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
21,500 - INSPECT_High Idle Control	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
32,000 - Engine Inspection	Done	needs air filter	RGASPARD	Oct 25, 2023 7:11:04 PM	Yes	57210649
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	NA	RGASPARD	Oct 25, 2023 7:11:04 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	RGASPARD	Oct 25, 2023 7:11:04 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
33,000 - CSF (Curb Side Front)	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Oct 25, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				7:11:04 PM		
33,050 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
33,060 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	14.1 Volt*		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
40,700 - CHECK_Passenger Stop Request System	Done	NA	RGASPARD	Oct 25, 2023 7:11:04 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
50,400 - LUBE_All Chassis Components	Done	NA	RGASPARD	Oct 25, 2023 7:11:04 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	38 Inch		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	38 Inch		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	39 Inch		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	39 Inch		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done	NA	RGASPARD	Oct 25, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				7:11:04 PM		
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done	NA	RGASPARD	Oct 25, 2023 7:11:04 PM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	2759 Cycles		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Oct 25, 2023 7:11:04 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	115.05
Labor Hours:	1.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**115.05**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56752099
Invoice No. 55345 - 56752099

Client Department:
Department: 55345M
Work Order Description
55345-MEDIUM DUTY PMA
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 303,273 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Oct-23	75050	OIL, ENGINE, 5W/30	8	2.73	21.84
25-Oct-23	LF16424	FILTER, OIL SUPERSEDES P9600	1	7.92	7.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Oct-23	Gaspard,Ronald	0.62	65	40.3

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: RGASPARD Performed on: 25-OCT-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Oct 25, 2023 7:23:20 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Oct 25, 2023 7:23:20 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Oct 25, 2023 7:23:20 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Oct 25, 2023 7:23:20 PM	No	
104,000 - Lubricate Chassis	Done	NA	RGASPARD	Oct 25, 2023 7:23:20 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Oct 25, 2023 7:23:20 PM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	-	NA	RGASPARD	Oct 25, 2023 7:23:20 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Oct 25, 2023 7:23:20 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Oct 25, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				7:23:20 PM		

Activity Sub Total

Activity 20 Sub Total	
Parts:	29.76
Labor:	40.30
Labor Hours:	0.62
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**70.06**

Work Order Footer

Work Order 56752099 Total	
Parts:	29.76
Labor:	155.35
Labor Hours:	2.39
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**185.11**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56945504
Invoice No. 55345 - 56945504

Client Department:
Department: 55345M
Work Order Description
FIRST TRANSIT AC INSPECTION
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 302,201 -

Chronology		
Reported	Oct 13, 2023 2:16:56 PM	Oct 13, 2023 2:16:56 PM
Started	Oct 13, 2023 2:20:00 PM	
Completed	Oct 13, 2023 5:05:00 PM	Oct 13, 2023 5:05:00 PM
Down Time		

Work Order Notes

Line 10 Vehicle came in for AC issue after checking AC front and rear puting out 61 at the vent i also call my supervisor to have alook whit me on the AC UNIT Is woking asdesign can¿t duplicate issue at this time Will monitor return unit back to work

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assesment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assesment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 13-OCT-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		JUHURST	Oct 13, 2023 5:05:03 PM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		JUHURST	Oct 13, 2023 5:05:03 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Oct 13, 2023 5:05:03 PM	No	
400 - Are you wearing the appropriate PPE?	Done		JUHURST	Oct 13, 2023 5:05:03 PM	No	
700 - Have you performed the proper LOTO?	Done		JUHURST	Oct 13, 2023 5:05:03 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Oct 13, 2023 5:05:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Oct 13, 2023 5:05:03 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56945504
Invoice No. 55345 - 56945504

Client Department:
Department: 55345M
Work Order Description
FIRST TRANSIT AC INSPECTION
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 302,201 -

Activity Header
Activity: 10 001/001/001 AIR CONDITIONING
Activity Note: FIRST TRANSIT AC INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Oct-23	Junior Hurst	1.88	65	122.2

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: FIRST TRANSIT AC INSPECTION
Task: FIRST TRANSIT AC INSPECTION Performed by: JUHURST Performed on: 13-OCT-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 VISUAL INSPECTION	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
10,100 - CHECK PHYSICAL DAMAGE, MISSING PARTS	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
10,200 - CHECK REFRIGERANT HOSES FOR CHAFING	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
10,300 - CHECK EVAPORATOR AND CONDENSER FOR OBSTRUCTIONS	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
10,400 - CHECK OPERATION OF FAST IDLE	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
20,000 - SECTION 2 DIAGNOSE THE SYSTEM CONDITION	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
20,100 - ATTACH GAUGES AND RUN SYSTEM 10 MINUTES	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
20,200 - CHECK FOR EVEN AIR DISTRIBUTION	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
20,300 - CHECK FOR PROPER OPERATION OF ALL HVAC MODES	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
20,400 - CHECK DRIVERS A/C SYSTEM	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,500 - RECORD AMBIENT TEMPERATURE BEFORE	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
20,600 - RECORD DISCHARGE PRESSURE BEFORE	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
20,700 - RECORD SUCTION PRESSURE BEFORE	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
20,710 - RECORD OUTLET TEMPERATURE BEFORE	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
20,800 - CHECK HIGH AND LOW PRESSURE CUTOUT SWITCHES FOR LEAKS	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
30,000 - SECTION 3 COMPRESSOR OPERATIONAL INSPCTION	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
30,100 - CHECK FOR UNUSUAL NOISES	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
30,200 - CHECK CLUTCH RESISTANCE READING	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
30,300 - CHECK AIR GAP IN COMPRESSOR CLUTCH	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
30,400 - CHECK COMPRESSOR MOUNTING AND ALIGHMENT	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
30,500 - INSPECT COMPRESSOR BELT(S) OR DRIVE SYSTEM	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
30,600 - CHECK FOR CRACKS AND WEAR	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
30,700 - CHECK FOR PROPER WIDTH AND LENGTH	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
30,800 - CHECK FOR PROPER ALIGNMENT	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
40,000 - SECTION 4 LEAK TEST SYSTEM	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
40,100 - CHICK A/C LINES WITH AN ELECTRONIC LEAK DETECTOR	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
40,200 - CHECK HOSES, FITTINGS, VALVES AND COMPRESSOR SHAFT SEAL	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
40,300 - CHECK HEATER HOSES FOR LEAKS	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
50,000 - SECTION 5 SYSTEM CONTAMINATION	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
50,100 - CHECK INLINE DRIER	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
50,200 - CHECK ACCUMULATOR	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
60,000 - SECTION 6 CHARGE SYSTEM	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
60,100 - IF CHARGING IS REQUIRED, CHARGE BY WEIGHT	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
60,200 - CHECK FOR LEAKS AFTER CHARGING	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
70,000 - SECTION 7 FAN MOTORS	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
70,100 - CHECK SEALED MOTORS FOR PROPER OPERATION	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,200 - INSPECT BLOWER WHEELS	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
70,300 - CHECK ELECTRICAL WIRING & CONNECTIONS	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
80,000 - SECTION 8 OPERATE SYSTEM	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
80,100 - CHECK FOR PROPER HEATING & COOLING	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
80,200 - CHECK TEMPERATURE CONTROLS	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
80,300 - CHECK DEFROST MODE	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
90,000 - SECTION 9 PERFORMANCE TEST READINGS	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
90,100 - RECORD AMBIENT TEMPERATURE READINGS AFTER	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
90,200 - RECORD DISCHARGE PRESSURE AFTER	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
90,300 - RECORD SUCTION PRESSURE AFTER	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
90,400 - RECORD OUTLET TEMPERATURE	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
100,000 - SECTION 10 RESTORE SYSTEM	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
100,100 - DISCONNECT GAUGES	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	
100,200 - CLOSE ALL PANELS, DOOR, ETC.	Done		JUHURST	Oct 13, 2023 3:37:26 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	122.20
Labor Hours:	1.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**122.20**

Work Order Footer

Work Order 56945504 Total	
Parts:	0.00
Labor:	122.20
Labor Hours:	1.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**122.20**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57123629
Invoice No. 55345 - 57123629

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PER DRIVER BUS STALLIG		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	301,843 - DH

Chronology		
Reported	Sep 27, 2023 4:45:28 PM	Sep 27, 2023 4:45:28 PM
Started	Oct 9, 2023 1:23:00 PM	
Completed	Oct 9, 2023 4:34:59 PM	Oct 9, 2023 4:34:59 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: vehicle came stater issue

Cause: worn stater
Also road test unit and NO issue found

Removed and replace new stater unit working perfect return unit back to work.
Correction:
Note W.O created by mistake

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 09-OCT-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		JUHURST	Oct 9, 2023 4:10:13 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		JUHURST	Oct 9, 2023 4:10:13 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Oct 9, 2023 4:10:13 PM	No	
400 - Are you wearing the appropriate PPE?	Done		JUHURST	Oct 9, 2023 4:10:13 PM	No	
700 - Have you performed the proper LOTO?	Done		JUHURST	Oct 9, 2023 4:10:13 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Oct 9, 2023 4:10:13 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Oct 9, 2023 4:10:13 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57123629
Invoice No. 55345 - 57123629

Client Department:
Department: 55345M
Work Order Description
PER DRIVER BUS STALLIG
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 301,843 - DH

Activity Header
Activity: 20 045 POWER PLANT
Activity Note: PER DRIVER BUS STALLING & IT DOES NOT WANT TO START
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Oct-23	DL3Z-11002-A	STARTER, E350, '14	1	148.8	148.8

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Oct-23	Junior Hurst	2.83	65	183.95

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	148.80
Labor:	183.95
Labor Hours:	2.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**332.75**

Work Order Footer

Work Order 57123629 Total	
Parts:	148.80
Labor:	183.95
Labor Hours:	2.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**332.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 7

Work Order No. 56925130
Invoice No. 55345 - 56925130

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Low engine compressions		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	300,385 - DH

Chronology		
Reported	Jul 25, 2023 11:33:11 PM	Jul 25, 2023 11:33:11 PM
Started	Jul 28, 2023 12:00:00 PM	
Completed	Oct 6, 2023 3:36:00 PM	Oct 6, 2023 3:36:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Check batteries.

Cause: Unknown.

Correction: Isolated batteries and checked each,both batteries good. Upon isolating found that 1 positive battery terminal was loose. Reconnected batteries and checked charging system, no issues found. Will monitor Line 20 Belt Squeaking / Exhaust Hanger. Engine Misfire. Code PO 304 / PO300 Random Misfire /# 4 MisfireReplace Exhaust hanger Replace belts
Parts #1360K6 Qty (1) Line 30 Check Compression On # (4) Cylinder.Compression(20) Psi Compression Low. No Water Leaks found Line 40 Remove & Replace Cylinder Head. Replace both head gasket. Replace bothintake gasket. Replace Sparks plugs.Replace Front Cover Seal. Replacetensioner & Tensioner Rail.. Line 50 Remove & Replace Serpentine belts & Idler Pulley. Replace Exhaust Hanger. Shop supply
Parts #1360K6 Qty (1)
Parts #89026 Qty (1) Line 60 Replace Rear Circuit Board & Evacuate & Recharge front A/C. Add (3.0) Oz Pag Oil & Recharge (1.88) Lbs Freon.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 26-JUL-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jul 26, 2023 12:06:04 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jul 26, 2023 12:06:04 AM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jul 26, 2023 12:06:04 AM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jul 26, 2023 12:06:04 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jul 26, 2023 12:06:04 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jul 26, 2023 12:06:04 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 7

Work Order No. 56925130
Invoice No. 55345 - 56925130

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Low engine compressions		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	300,385 - DH

Activity Header
Activity: 15 031/005/000 CHARGER, BATTERY, ON-BOARD, VEHICLES, PROPELLED, ELECTRICALLY
Activity Note: Check battery.
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure: 43 Weak
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 7

Work Order No. 56925130
Invoice No. 55345 - 56925130

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Low engine compressions		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	300,385 - DH

Activity Header
Activity: 25 045 POWER PLANT
Activity Note: PER DRIVER BUS HESITATES ON ACELERATION
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Jul-23	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	47.16	47.16

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Jul-23	Arthurs,Durvin	1.28	65	83.2
31-Jul-23	Arthurs,Durvin	3	65	195
28-Jul-23	Arthurs,Durvin	0.97	65	63.05
06-Oct-23	Arthurs,Durvin	1.23	65	79.95
28-Jul-23	Arthurs,Durvin	1.37	65	89.05
28-Jul-23	Arthurs,Durvin	1.55	65	100.75

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	47.16
Labor:	611.00
Labor Hours:	9.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**658.16**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 7

Work Order No. 56925130
Invoice No. 55345 - 56925130

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Low engine compressions		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	300,385 - DH

Activity Header
Activity: 35 002 CAB & SHEET METAL
Activity Note: PER DRIVER WATER LEAK BY TOP LEFT CORNER OF VEHICLE
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Sep-23	800-404	CONNECTOR, HOSE, HEATER, 3/4"	6	10.1	60.6

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Oct-23	Arthurs,Durvin	1.32	65	85.8

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 35 Sub Total	
Parts:	60.60
Labor:	85.80
Labor Hours:	1.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**146.40**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 7

Work Order No. 56925130
Invoice No. 55345 - 56925130

Client Department:
Department: 55345M
Work Order Description
Low engine compressions
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 300,385 - DH

Activity Header
Activity: 45 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Remove & Replace Cylinder Head
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Oct-23	SP521	PLUG, SPARK, 5.4L, FORD	10	4.17	41.7
26-Sep-23	F85Z-6M274-AA	ARM, TENSIONER, CHAIN, TIMMING, 5.4L	1	16.1	16.1
18-Oct-23	SP521	PLUG, SPARK, 5.4L, FORD	1	4.17	4.17
01-Nov-23	DSP-ENGINE	DIRECT PURCHASE FOR SERVICES ENGINE	1	150	150
26-Sep-23	1L3Z-6L266-AA	TENSIONER, CHAIN, TIMING	1	21.93	21.93
06-Oct-23	89026	PULLEY, IDLER, SMOOTH	1	17.49	17.49
26-Sep-23	XL1Z-6L266-AA	TENSIONER, CHAIN, TIMING	1	40.6	40.6
26-Sep-23	4L3Z-6M256-AA	GUIDE, CHAIN, TIMING, RH	1	19.13	19.13
30-Oct-23	PW494	PUMP, WATER	1	90.02	90.02
02-Oct-23	8L3Z-6G004-A	SENSOR, TEMPERATURE, COOLANT	1	24.97	24.97
26-Sep-23	2L1Z-6K297-AA	GUIDE, CHAIN, TIMING, LH	1	15.75	15.75
26-Sep-23	4C2Z-9461-BA	GASKET, MANIFOLD, INTAKE, 6.8L	8	2.9	23.2
26-Sep-23	4C2Z-9461-AA	GASKET, MANIFOLD, INTAKE	1	11.28	11.28
06-Oct-23	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	47.16	47.16
30-Nov-23	F75Z-6020-AA	GASKET, COVER, TIMING	1	3.78	3.78
26-Sep-23	2FKLP	HEAD, CYLINDER, REMANUFACTURED	1	505.09	505.09
02-Oct-23	F7UZ-6A303-BA	SPROCKET, CAMSHAFT, 6.8L	1	45.27	45.27
02-Oct-23	XL3Z-14A411-AA	HARNESS, WIRE, JUMPER, SENSOR, TEMPERATURE	1	38.49	38.49
26-Sep-23	1L3Z-6L266-AA	TENSIONER, CHAIN, TIMING	1	36.28	36.28
22-Sep-23	HS26304PT	GASKET, HEAD, CYLINDER, LH, 6.8L, E450, '06	1	188.09	188.09
22-Sep-23	ES72798-1	BOLT, HEAD, CYLINDER	2	72.71	145.42

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Sep-23	Arthurs,Durvin	2.67	65	173.55
05-Oct-23	Arthurs,Durvin	5.22	65	339.3

Booked Date	Technician	Hours	Shop Rate	Extended
26-Sep-23	Arthurs,Durvin	3.27	65	212.55
22-Sep-23	Arthurs,Durvin	3.25	65	211.25
04-Oct-23	Arthurs,Durvin	2.08	65	135.2
27-Sep-23	Arthurs,Durvin	3.3	65	214.5
26-Sep-23	Arthurs,Durvin	3.22	65	209.3
25-Sep-23	Arthurs,Durvin	8.17	65	531.05
06-Oct-23	Arthurs,Durvin	1.65	65	107.25
06-Oct-23	Arthurs,Durvin	2.63	65	170.95
05-Oct-23	Arthurs,Durvin	2.3	65	149.5
26-Sep-23	Arthurs,Durvin	0.78	65	50.7
22-Sep-23	Arthurs,Durvin	2	65	130

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 45 Sub Total	
Parts:	1,485.92
Labor:	2,635.10
Labor Hours:	40.54
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4,121.02**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 6 of 7

Work Order No. 56925130
Invoice No. 55345 - 56925130

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Low engine compressions		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	300,385 - DH

Activity Header
Activity: 55 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Front A/C blown Warm.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Oct-23	Arthurs,Durvin	1.18	65	76.7

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 55 Sub Total	
Parts:	0.00
Labor:	76.70
Labor Hours:	1.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**76.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 7 of 7

Work Order No. 56925130
Invoice No. 55345 - 56925130

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Low engine compressions		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	300,385 - DH

Activity Header
Activity: 65 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: CYLINDER HEAD EXCHANGE PERFORMED WELDING
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Nov-23	357006	BOOT, COIL-ON-PLUG, IGNITION	1	6.72	6.72
01-Nov-23	DSP-ENGINE	DIRECT PURCHASE FOR SERVICES ENGINE	1	100	100

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 65 Sub Total	
Parts:	106.72
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**106.72**

Work Order Footer

Work Order 56925130 Total	
Parts:	1,700.40
Labor:	3,408.60
Labor Hours:	52.44
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5,109.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56109041
Invoice No. 55345 - 56109041

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FIRST TRANSIT AC INSPECTION		Ford E450 Champion Challenger	
Requested By:	SPACE	**Status:**	40 - Closed (40)
Created By:	SPACE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	300,796 -

Chronology		
Reported	Aug 2, 2023 9:35:42 AM	Aug 2, 2023 9:35:42 AM
Started	Aug 2, 2023 9:54:00 AM	
Completed	Aug 2, 2023 11:08:00 AM	Aug 2, 2023 11:08:00 AM
Down Time		

Work Order Notes

Line 10
AC Inspection
Inspected allelectrical components. Ok
Inspected all lines and hoses. Ok
Inspected both AC compressors. Ok
Inpected both condensers. Ok
Inspected all fans and blows on every speed. Ok
No leaks.
Front AC temp. 56
Rear AC temp. 58
Outside temp. 81
Returned to services

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assesment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assesment
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 02-AUG-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Aug 2, 2023 10:30:38 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Aug 2, 2023 10:30:38 AM	No	
4 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Aug 2, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:30:38 AM		
7 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Aug 2, 2023 10:30:38 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Aug 2, 2023 10:30:38 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Aug 2, 2023 10:30:38 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56109041
Invoice No. 55345 - 56109041

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FIRST TRANSIT AC INSPECTION		Ford E450 Champion Challenger	
Requested By:	SPACE	**Status:**	40 - Closed (40)
Created By:	SPACE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	300,796 -

Activity Header
Activity: 10 001/001/001 AIR CONDITIONING
Activity Note: FIRST TRANSIT AC INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Aug-23	Rodriguez,Raul	1.07	65	69.55

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: FIRST TRANSIT AC INSPECTION
Task: FIRST TRANSIT AC INSPECTION Performed by: RAURODRIGUEZ Performed on: 02-AUG-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 VISUAL INSPECTION	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
10,100 - CHECK PHYSICAL DAMAGE, MISSING PARTS	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
10,200 - CHECK REFRIGERANT HOSES FOR CHAFING	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
10,300 - CHECK EVAPORATOR AND CONDENSER FOR OBSTRUCTIONS	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
10,400 - CHECK OPERATION OF FAST IDLE	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
20,000 - SECTION 2 DIAGNOSE THE SYSTEM CONDITION	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
20,100 - ATTACH GAUGES AND RUN SYSTEM 10 MINUTES	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
20,200 - CHECK FOR EVEN AIR DISTRIBUTION	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
20,300 - CHECK FOR PROPER OPERATION OF ALL HVAC MODES	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
20,400 - CHECK DRIVERS A/C SYSTEM	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,500 - RECORD AMBIENT TEMPERATURE BEFORE	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
20,600 - RECORD DISCHARGE PRESSURE BEFORE	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
20,700 - RECORD SUCTION PRESSURE BEFORE	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
20,710 - RECORD OUTLET TEMPERATURE BEFORE	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
20,800 - CHECK HIGH AND LOW PRESSURE CUTOUT SWITCHES FOR LEAKS	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
30,000 - SECTION 3 COMPRESSOR OPERATIONAL INSPCTION	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
30,100 - CHECK FOR UNUSUAL NOISES	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
30,200 - CHECK CLUTCH RESISTANCE READING	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
30,300 - CHECK AIR GAP IN COMPRESSOR CLUTCH	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
30,400 - CHECK COMPRESSOR MOUNTING AND ALIGHMENT	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
30,500 - INSPECT COMPRESSOR BELT(S) OR DRIVE SYSTEM	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
30,600 - CHECK FOR CRACKS AND WEAR	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
30,700 - CHECK FOR PROPER WIDTH AND LENGTH	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
30,800 - CHECK FOR PROPER ALIGNMENT	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
40,000 - SECTION 4 LEAK TEST SYSTEM	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
40,100 - CHICK A/C LINES WITH AN ELECTRONIC LEAK DETECTOR	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
40,200 - CHECK HOSES, FITTINGS, VALVES AND COMPRESSOR SHAFT SEAL	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
40,300 - CHECK HEATER HOSES FOR LEAKS	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
50,000 - SECTION 5 SYSTEM CONTAMINATION	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
50,100 - CHECK INLINE DRIER	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
50,200 - CHECK ACCUMULATOR	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
60,000 - SECTION 6 CHARGE SYSTEM	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
60,100 - IF CHARGING IS REQUIRED, CHARGE BY WEIGHT	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
60,200 - CHECK FOR LEAKS AFTER CHARGING	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
70,000 - SECTION 7 FAN MOTORS	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
70,100 - CHECK SEALED MOTORS FOR PROPER OPERATION	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,200 - INSPECT BLOWER WHEELS	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
70,300 - CHECK ELECTRICAL WIRING & CONNECTIONS	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
80,000 - SECTION 8 OPERATE SYSTEM	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
80,100 - CHECK FOR PROPER HEATING & COOLING	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
80,200 - CHECK TEMPERATURE CONTROLS	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
80,300 - CHECK DEFROST MODE	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
90,000 - SECTION 9 PERFORMANCE TEST READINGS	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
90,100 - RECORD AMBIENT TEMPERATURE READINGS AFTER	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
90,200 - RECORD DISCHARGE PRESSURE AFTER	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
90,300 - RECORD SUCTION PRESSURE AFTER	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
90,400 - RECORD OUTLET TEMPERATURE	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
100,000 - SECTION 10 RESTORE SYSTEM	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
100,100 - DISCONNECT GAUGES	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	
100,200 - CLOSE ALL PANELS, DOOR, ETC.	Done		RAURODRIGUEZ	Aug 2, 2023 11:08:37 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	69.55
Labor Hours:	1.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**69.55**

Work Order Footer

Work Order 56109041 Total	
Parts:	0.00
Labor:	69.55
Labor Hours:	1.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**69.55**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56913916
Invoice No. 55345 - 56913916

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Engine Belt		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	300,000 - DH

Chronology		
Reported	Jul 21, 2023 8:27:21 AM	Jul 21, 2023 8:27:21 AM
Started	Jul 21, 2023 8:28:00 AM	
Completed	Jul 28, 2023 11:11:00 AM	Jul 28, 2023 11:11:00 AM
Down Time		

Work Order Notes

Line 10 Engine making noise

Bad pulleys

Removed and replaced pulleys, test drive, all okay at this time

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 28-JUL-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Jul 28, 2023 11:11:20 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Jul 28, 2023 11:11:20 AM	No	
4 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Jul 28, 2023 11:11:20 AM	No	
7 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Jul 28, 2023 11:11:20 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Jul 28, 2023 11:11:20 AM	No	
11 - Have you successfully completed the	Done		RAURODRIGUEZ	Jul 28, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				11:11:20 AM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56913916
Invoice No. 55345 - 56913916

Client Department:
Department: 55345M
Work Order Description
Engine Belt
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 300,000 - DH

Activity Header
Activity: 20 045/000/000 POWER PLANT
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Jul-23	89026	PULLEY, IDLER, SMOOTH	1	14.6	14.6
21-Jul-23	419610	PULLEY, IDLER, 76MM	1	12.95	12.95

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jul-23	Rodriguez,Raul	1.43	65	92.95

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	27.55
Labor:	92.95
Labor Hours:	1.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**120.50**

Work Order Footer

Work Order 56913916 Total	
Parts:	27.55
Labor:	92.95
Labor Hours:	1.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**120.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56836426
Invoice No. 55345 - 56836426

Client Department:
Department: 55345M
Work Order Description
Road Call PER DRIVER BUS NOT RUNNUING RIGHT
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 300,000 - DH

Chronology		
Reported	Jun 21, 2023 12:09:00 PM	Jun 21, 2023 12:09:00 PM
Started	Jun 21, 2023 12:00:00 AM	
Completed	Jul 13, 2023 6:48:00 AM	Jul 13, 2023 6:48:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: vehicle was shaking

Cause: n/a

Correction: drive test the vehicle and put it on the lift to check front end ,nothing was found ,everything was ok at this time ,vehicle was back in service

Activity Header
Activity:20 999 TOTAL VEHICLE
Activity Note: BUS TOWED BACK TO BASE BY GARDENS TOWING
Reason for Repair: TW Towing
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet

PO No.	ACD Code	Supplier No.	SUPPLIER	Order Date	Received Value
4752705	181,439,885	1005999	PALM BEACH GARDENS TOWING CORP,FL,RIVIERA BEACH,3525 AVE K	Jun 21, 2023 12:00:00 AM	487.3

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	487.30
	Sublet Labor:	0.00
	Activity Sub Total	**487.30**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56836426
Invoice No. 55345 - 56836426

Client Department:
Department: 55345M
Work Order Description
Road Call PER DRIVER BUS NOT RUNNUING RIGHT
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 300,000 - DH

Activity Header
Activity: 30 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc:
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 13-JUL-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Jul 13, 2023 6:48:28 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Jul 13, 2023 6:48:28 AM	No	
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Jul 13, 2023 6:48:28 AM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Jul 13, 2023 6:48:28 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Jul 13, 2023 6:48:28 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Jul 13, 2023 6:48:28 AM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56836426
Invoice No. 55345 - 56836426

Client Department:
Department: 55345M
Work Order Description
Road Call PER DRIVER BUS NOT RUNNUING RIGHT
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 300,000 - DH

Activity Header
Activity: 40 999 TOTAL VEHICLE
Activity Note: PER DRIVER BUS NO RUNNING RIGHT
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 56836426 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	487.30
Sublet Labor:	0.00
Activity Sub Total	**487.30**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56787841
Invoice No. 55345 - 56787841

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Ford Body Parts		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	300,000 - DH

Chronology		
Reported	Jun 5, 2023 10:25:37 AM	Jun 5, 2023 10:25:37 AM
Started	Jun 5, 2023 10:26:00 AM	
Completed	Jun 7, 2023 6:12:00 AM	Jun 7, 2023 6:12:00 AM
Down Time		

Work Order Notes

Line 10 Complaint. Front top roof damage

Cause. Driver hit

Correction. Repair damaged area and replace the metal molding base, sealing with silicone

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 07-JUN-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Jun 7, 2023 6:04:00 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Jun 7, 2023 6:04:00 AM	No	
4 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Jun 7, 2023 6:04:00 AM	No	
7 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Jun 7, 2023 6:04:00 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Jun 7, 2023 6:04:00 AM	No	
11 - Have you successfully completed the	Done		RAURODRIGUEZ	Jun 7, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				6:04:00 AM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56787841
Invoice No. 55345 - 56787841

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Ford Body Parts		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	300,000 - DH

Activity Header
Activity: 20 002/000/000 CAB & SHEET METAL
Activity Note: FORD BODY REPAIR
Reason for Repair: 41 Abuse of Equipment
Work Accomplished: 15 Paint Prep, & Repaint
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jun-23	Rodriguez,Raul	1.97	65	128.05

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	128.05
Labor Hours:	1.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**128.05**

Work Order Footer

Work Order 56787841 Total	
Parts:	0.00
Labor:	128.05
Labor Hours:	1.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**128.05**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 56752090
Invoice No. 55345 - 56752090

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Follow up Medium Duty PMB		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	299,452 - DH

Chronology

Reported	May 23, 2023 9:08:09 AM	May 23, 2023 9:08:09 AM
Started	May 23, 2023 9:17:00 AM	
Completed	May 23, 2023 12:24:00 PM	May 23, 2023 12:24:00 PM
Down Time		

Work Order Notes

Line 10 Pmb follow up code p0713

Wire hanses

Replaced wire harness gasket and add fluids completed

Activity Header
Activity: 10 027 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: code po713 need wire harness
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-May-23	BC3Z-7H141-A	SENSOR, TEMPERATURE, TRANSMISSION	1	12.86	12.86
23-May-23	20021	FILTER, TRANSMISSION 20021	1	21.59	21.59
23-May-23	4C3Z-7G276-AA	HARNESS, SOLENOID, INTERNAL, TRANSMISSION, 5R110W	1	154	154

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-May-23	Pierre,Hubert J	2.97	65	193.05

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	188.45
Labor:	193.05
Labor Hours:	2.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**381.50**

Work Order Footer

	Work Order 56752090 Total	
	Parts:	188.45
	Labor:	193.05
	Labor Hours:	2.97
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**381.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 56752087
Invoice No. 55345 - 56752087

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	299,452 - DH

Chronology

Reported	May 23, 2023 9:07:56 AM	May 23, 2023 9:07:56 AM
Started		
Completed	May 23, 2023 12:20:00 PM	May 23, 2023 12:20:00 PM
Down Time		

Work Order Notes

Line 10 Pmb follow up need tire

Preventive Maintenance

Replaced tire with a good use one completed

Activity Header
Activity: 10 017/003/001 TIRE, CUSHION W/TREAD
Activity Note: need rear tire
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 56752087 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56747715
Invoice No. 55345 - 56747715

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Driver said check engine light is on		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	299,000 - DH

Chronology		
Reported	May 22, 2023 6:10:03 AM	May 22, 2023 6:10:03 AM
Started	May 22, 2023 6:12:00 AM	
Completed	May 23, 2023 9:17:00 AM	May 23, 2023 9:17:00 AM
Down Time		

Work Order Notes

Line 10 Driver said engine light is on

Code p0713

Replaced transmission wire completed everything on the follow up completed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 23-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	May 23, 2023 9:16:59 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	May 23, 2023 9:16:59 AM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	May 23, 2023 9:16:59 AM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	May 23, 2023 9:16:59 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	May 23, 2023 9:16:59 AM	No	
11 - Have you successfully completed the Personal	Done		HPIERRE	May 23, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				9:16:59 AM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56747715
Invoice No. 55345 - 56747715

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Driver said check engine light is on		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	299,000 - DH

Activity Header
Activity: 20 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-May-23	Pierre,Hubert J	0.32	65	20.8
22-May-23	Pierre,Hubert J	0.48	65	31.2

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	52.00
Labor Hours:	0.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**52.00**

Work Order Footer

Work Order 56747715 Total	
Parts:	0.00
Labor:	52.00
Labor Hours:	0.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**52.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56199954
Invoice No. 55345 - 56199954

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-MEDIUM DUTY PMB		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	299,452 - DH

Chronology		
Reported	May 22, 2023 12:00:00 AM	May 22, 2023 12:00:00 AM
Started	May 23, 2023 6:10:00 AM	
Completed	May 23, 2023 9:09:00 AM	May 23, 2023 9:09:00 AM
Down Time		

Work Order Notes

Line 10 Pmb

Preventive maintenance

Perform maintenance service completed

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 23-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	May 23, 2023 8:58:23 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	May 23, 2023 8:58:23 AM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	May 23, 2023 8:58:23 AM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	May 23, 2023 8:58:23 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	May 23, 2023 8:58:23 AM	No	
11 - Have you successfully completed the Personal	Done		HPIERRE	May 23, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				8:58:23 AM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56199954
Invoice No. 55345 - 56199954

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-MEDIUM DUTY PMB		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	299,452 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-May-23	Pierre,Hubert J	2.78	65	180.7

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: HPIERRE Performed on: 23-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
10,800 - CHECK_All Destination Signage	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
10,900 - *RPT*INSPECT_Body Damage,	Done		HPIERRE	May 23, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Corrosion;DOCUMENT_Issues				9:07:53 AM		
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
20,200 - CHECK_Public Address System	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	60 Second*		HPIERRE	May 23, 2023 9:07:53 AM	No	
20,700 - RECORD_Brake Performance Test Speed	60 Miles per Hour		HPIERRE	May 23, 2023 9:07:53 AM	No	
20,800 - RECORD_Brake Performance Test Distance	6 FEET		HPIERRE	May 23, 2023 9:07:53 AM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	6 FEET		HPIERRE	May 23, 2023 9:07:53 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	90 Gravitational Force		HPIERRE	May 23, 2023 9:07:53 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
21,500 - INSPECT_High Idle Control	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
21,800 - INSPECT_Parking Brake Operation	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
31,000 - SSF (Street Side Front)	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
32,000 - Engine Inspection	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	190 Degree Fahrenheit		HPIERRE	May 23, 2023 9:07:53 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
32,100 - INSPECT_Intake System	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12 Volt*		HPIERRE	May 23, 2023 9:07:53 AM	No	
33,000 - CSF (Curb Side Front)	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	May 23, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:07:53 AM		
33,050 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
33,060 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	12 Volt*		HPIERRE	May 23, 2023 9:07:53 AM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
40,700 - CHECK_Passenger Stop Request System	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
50,400 - LUBE_All Chassis Components	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,700 - INSPECT_Tire Condition	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	10 32nds of an inch		HPIERRE	May 23, 2023 9:07:53 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	May 23, 2023 9:07:53 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	10 32nds of an inch		HPIERRE	May 23, 2023 9:07:53 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	May 23, 2023 9:07:53 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		HPIERRE	May 23, 2023 9:07:53 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		HPIERRE	May 23, 2023 9:07:53 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	22 Inch		HPIERRE	May 23, 2023 9:07:53 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	222 Inch		HPIERRE	May 23, 2023 9:07:53 AM	No	
52,100 - INSPECT_Vibration Damper	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
53,600 - INSPECT_Tire Condition	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	4 32nds of an inch	need rear tire	HPIERRE	May 23, 2023 9:07:53 AM	Yes	56752087
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	May 23, 2023 9:07:53 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	May 23, 2023 9:07:53 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	May 23, 2023 9:07:53 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	May 23, 2023 9:07:53 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	May 23, 2023 9:07:53 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	May 23, 2023 9:07:53 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	May 23, 2023 9:07:53 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	May 23, 2023 9:07:53 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	May 23, 2023 9:07:53 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	22 Inch		HPIERRE	May 23, 2023 9:07:53 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	22 Inch		HPIERRE	May 23, 2023 9:07:53 AM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
60,100 - RECORD_Wheelchair Cycle Count	190 Cycles		HPIERRE	May 23, 2023 9:07:53 AM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
62,400 - INSPECT_All Pivot Points	Done		HPIERRE	May 23, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:07:53 AM		
62,500 - INSPECT_Cams and Slots	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
62,600 - INSPECT_Rollers	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
62,700 - INSPECT_All Linkages	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		HPIERRE	May 23, 2023 9:07:53 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	180.70
Labor Hours:	2.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**180.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56199954
Invoice No. 55345 - 56199954

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-MEDIUM DUTY PMB		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	299,452 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMB Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-May-23	B329	FILTER, OIL, SPIN-ON SEE P550965	1	2.51	2.51

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	2.51
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.51**

Work Order Footer

Work Order 56199954 Total	
Parts:	2.51
Labor:	180.70
Labor Hours:	2.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**183.21**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56750975
Invoice No. 55345 - 56750975

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
CHECK ENGINE LIGHT ON		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	299,452 - DH

Chronology		
Reported	May 22, 2023 7:09:30 PM	May 22, 2023 7:09:30 PM
Started	May 22, 2023 7:11:00 PM	
Completed	May 23, 2023 2:03:00 AM	May 23, 2023 2:03:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:Check Engine Light on

Cause: Cylinder #4 and 5 misfiring and Transmission Fluid Temperature Sensor A circuit

Correction:Cyl #4 Low Compression cyl4&5 sparks Plugs replaced ,Transmissions issues fixed

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 22-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		FSIMON	May 22, 2023 7:12:19 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		FSIMON	May 22, 2023 7:12:19 PM	No	
4 - Are you wearing the appropriate PPE?	Done		FSIMON	May 22, 2023 7:12:19 PM	No	
7 - Have you performed the proper LOTO?	Done		FSIMON	May 22, 2023 7:12:19 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		FSIMON	May 22, 2023 7:12:19 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	May 22, 2023 7:12:19 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56751262
Invoice No. 55345 - 56751262

Client Department:
Department: 55345M
Work Order Description
CATALYTIC CONVERTER THEFT DETERRENT KIT INSTALLATION
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 299,452 - DH

Chronology		
Reported	May 23, 2023 1:06:18 AM	May 23, 2023 1:06:18 AM
Started	May 23, 2023 1:10:00 AM	
Completed	May 23, 2023 2:03:00 AM	May 23, 2023 2:03:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction:

CATALYTIC CONVERTER THEFT DETERRENT KIT INSTALLED

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 23-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		FSIMON	May 23, 2023 1:11:26 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		FSIMON	May 23, 2023 1:11:26 AM	No	
4 - Are you wearing the appropriate PPE?	Done		FSIMON	May 23, 2023 1:11:26 AM	No	
7 - Have you performed the proper LOTO?	Done		FSIMON	May 23, 2023 1:11:26 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		FSIMON	May 23, 2023 1:11:26 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	May 23, 2023 1:11:26 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56750975
Invoice No. 55345 - 56750975

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
CHECK ENGINE LIGHT ON		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	299,452 - DH

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: CHECK ENGIE LIGHT DIAGNOSIS
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-May-23	Fritz Simon	4.27	65	277.55

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	277.55
Labor Hours:	4.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**277.55**

Work Order Footer

Work Order 56750975 Total	
Parts:	0.00
Labor:	277.55
Labor Hours:	4.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**277.55**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56751262
Invoice No. 55345 - 56751262

Client Department:
Department: 55345M
Work Order Description
CATALYTIC CONVERTER THEFT DETERRENT KIT INSTALLATION
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 299,452 - DH

Activity Header
Activity: 15 043/001/030 CONVERTER, CATALYTIC
Activity Note: CATALYTIC CONVERTER THEFT DETERRENT KIT INSTALLATION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-May-23	Fritz Simon	0.88	65	57.2

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	57.20
Labor Hours:	0.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**57.20**

Work Order Footer

Work Order 56751262 Total	
Parts:	0.00
Labor:	57.20
Labor Hours:	0.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**57.20**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56740788
Invoice No. 55345 - 56740788

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
CHECK ENGINE LIGHT ON		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	99 - Cancelled (99)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	299,000 - DH

Chronology		
Reported	May 18, 2023 7:07:21 PM	May 18, 2023 7:07:21 PM
Started	May 18, 2023 7:09:00 PM	
Completed	May 19, 2023 1:58:00 AM	May 19, 2023 1:58:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction:

W.O. Created by mistake instead of 4514

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 18-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		FSIMON	May 18, 2023 7:09:35 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		FSIMON	May 18, 2023 7:09:35 PM	No	
4 - Are you wearing the appropriate PPE?	Done		FSIMON	May 18, 2023 7:09:35 PM	No	
7 - Have you performed the proper LOTO?	Done		FSIMON	May 18, 2023 7:09:35 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		FSIMON	May 18, 2023 7:09:35 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	May 18, 2023 7:09:35 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56740788
Invoice No. 55345 - 56740788

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
CHECK ENGINE LIGHT ON		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	99 - Cancelled (99)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	299,000 - DH

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: CHECK ENGINE LIGHT ON
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-May-23	Fritz Simon	2.02	65	131.3

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	131.30
Labor Hours:	2.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**131.30**

Work Order Footer

Work Order 56740788 Total	
Parts:	0.00
Labor:	131.30
Labor Hours:	2.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**131.30**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56676404
Invoice No. 55345 - 56676404

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
NOISE UNDER THE HOOD WHEN TURNING ON AC		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	298,426 - DH

Chronology		
Reported	May 2, 2023 5:13:07 PM	May 2, 2023 5:13:07 PM
Started	May 2, 2023 5:15:00 PM	
Completed	May 3, 2023 2:21:00 AM	May 3, 2023 2:21:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:Loud noise under the hood

Cause:Defective idler pulley and tensioner and AC system

Correction:Idler pulley Bearing replaced ,tensioner replaced by a good old one,A/C recover orifice tube replaced vacuum leak test and recharge done .

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 03-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		FSIMON	May 3, 2023 2:21:26 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		FSIMON	May 3, 2023 2:21:26 AM	No	
4 - Are you wearing the appropriate PPE?	Done		FSIMON	May 3, 2023 2:21:26 AM	No	
7 - Have you performed the proper LOTO?	Done		FSIMON	May 3, 2023 2:21:26 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		FSIMON	May 3, 2023 2:21:26 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	May 3, 2023 2:21:26 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56676404
Invoice No. 55345 - 56676404

Client Department:
Department: 55345M
Work Order Description
NOISE UNDER THE HOOD WHEN TURNING ON AC
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 298,426 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: AC SYSTEM
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-May-23	3411885	TUBE, ORIFICE, A/C, FORD	1	1.06	1.06

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-May-23	Fritz Simon	6.03	65	391.95

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	1.06
Labor:	391.95
Labor Hours:	6.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**393.01**

Work Order Footer

Work Order 56676404 Total	
Parts:	1.06
Labor:	391.95
Labor Hours:	6.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**393.01**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56671318
Invoice No. 55345 - 56671318

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Check eng light on		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	298,426 - DH

Chronology		
Reported	May 1, 2023 1:14:42 PM	May 1, 2023 1:14:42 PM
Started	May 1, 2023 1:19:00 PM	
Completed	May 1, 2023 8:09:00 PM	May 1, 2023 8:09:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: From driver eng light on

Cause: system too leam P2098

Correction: CHANGE 02 sensor part # 17321 / Gu2Z-9G444-A8F9Z-9F472-J. Also check compression on cylinder # 4 and the p s i. Is 90. Too low Line 20 Please can you charge it two of the sensors for me. # 17321 / # GU-9G444-A Thank you return unit back to work

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 01-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	May 1, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:08:21 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	May 1, 2023 8:08:21 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	May 1, 2023 8:08:21 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	May 1, 2023 8:08:21 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	May 1, 2023 8:08:21 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	May 1, 2023 8:08:21 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56671318
Invoice No. 55345 - 56671318

Client Department:
Department: 55345M
Work Order Description
Check eng light on
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 298,426 - DH

Activity Header
Activity: 15 020 GROUP, DRIVETRAIN
Activity Note: Check eng light
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-May-23	DY1193	SENSOR, OXYGEN	1	84.57	84.57
03-May-23	17321	SENSOR, OXYGEN, POS-1, BANK-1, E450, '13	1	63.38	63.38

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-May-23	Junior Hurst	0.27	65	17.55
01-May-23	Junior Hurst	5.93	65	385.45

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	147.95
Labor:	403.00
Labor Hours:	6.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**550.95**

Work Order Footer

Work Order 56671318 Total	
Parts:	147.95
Labor:	403.00
Labor Hours:	6.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**550.95**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 5

Work Order No. 56664430
Invoice No. 55345 - 56664430

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Lift issue		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	298,426 - DH

Chronology		
Reported	Apr 28, 2023 1:03:22 PM	Apr 28, 2023 1:03:22 PM
Started	Apr 28, 2023 1:09:00 PM	
Completed	Apr 30, 2023 6:32:00 PM	Apr 30, 2023 6:32:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: from driver lift issue

Cause: Retractor broken

Correction: removed new retractor part # 31579KS LIFT NOW WORKING ASDESIGN Line 20 Vehicle also came in for check eng light on check and found the system too lean check all vacuum. and clean throttle body clear cord P 2098 unit working Good Line 30 Replace new oil filler tube part # 9C2Z-6763 -C Line 40 REMOVED BOOSTER FROM UNIT WILL REPLACE NEXT SHIFT Line 50 Install new Booster tounit Part # DC2Z-2005- A working perfect no leak Line 60 Removed and replace new marker L E D LAMP AMBER. TO RIGHT FRONT PART #3974688 Line 70 Repair Power cable for rear A/C compressor

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: JUHURST Performed on: 30-APR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Apr 30, 2023 6:32:19 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Apr 30, 2023 6:32:19 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Apr 30, 2023 6:32:19 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Apr 30, 2023 6:32:19 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Apr 30, 2023 6:32:19 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Apr 30, 2023 6:32:19 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 5

Work Order No. 56664430
Invoice No. 55345 - 56664430

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Lift issue		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	298,426 - DH

Activity Header
Activity: 15 030 ELECTRICAL GROUP
Activity Note: Lift issue
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Apr-23	9C2Z-6763-C	TUBE, FILLER, OIL, 6.8L	1	27.75	27.75

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Apr-23	Junior Hurst	3.88	65	252.2

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	27.75
Labor:	252.20
Labor Hours:	3.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**279.95**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 5

Work Order No. 56664430
Invoice No. 55345 - 56664430

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Lift issue		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	298,426 - DH

Activity Header
Activity: 25 020 GROUP, DRIVETRAIN
Activity Note: Check engine light on
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Apr-23	31579KS	BELT, W/C	1	71.69	71.69

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Apr-23	Junior Hurst	1.58	65	102.7

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	71.69
Labor:	102.70
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**174.39**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 5

Work Order No. 56664430
Invoice No. 55345 - 56664430

Client Department:
Department: 55345M
Work Order Description
Lift issue
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 298,426 - DH

Activity Header
Activity: 35 049 TRAIN, POWER, HYDRAULIC, HYBRID
Activity Note: Hydro Booster
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Apr-23	DC2Z-2005-A	BOOSTER, BRAKE, POWER, HYDRAULIC SAME AS BRB-103	1	204.91	204.91

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Apr-23	Junior Hurst	2.08	65	135.2
30-Apr-23	Junior Hurst	3.93	65	255.45

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 35 Sub Total	
Parts:	204.91
Labor:	390.65
Labor Hours:	6.01
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**595.56**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 5

Work Order No. 56664430
Invoice No. 55345 - 56664430

Client Department:
Department: 55345M
Work Order Description
Lift issue
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 298,426 - DH

Activity Header
Activity: 45 030 ELECTRICAL GROUP
Activity Note: Marker light out right side
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Apr-23	3974688	LAMP, LED, AMBER	1	8.9	8.9

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Apr-23	Junior Hurst	1.07	65	69.55

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 45 Sub Total	
Parts:	8.90
Labor:	69.55
Labor Hours:	1.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**78.45**

Work Order Footer

Work Order 56664430 Total	
Parts:	313.25
Labor:	815.10
Labor Hours:	12.54
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1,128.35**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 56607681
Invoice No. 55345 - 56607681

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Change two front tires		Ford E450 Champion Challenger	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	297,792 - DH

Chronology		
Reported	Apr 11, 2023 1:56:42 PM	Apr 11, 2023 1:56:42 PM
Started	Apr 11, 2023 12:00:00 AM	
Completed	Apr 11, 2023 4:28:00 PM	Apr 11, 2023 4:28:00 PM
Down Time		

Work Order Notes

Line 10 Two new front tires installed

Side plastic from lift changed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: NBARRETO Performed on: 11-APR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NBARRETO	Apr 11, 2023 1:57:56 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NBARRETO	Apr 11, 2023 1:57:56 PM	No	
4 - Are you wearing the appropriate PPE?	Done		NBARRETO	Apr 11, 2023 1:57:56 PM	No	
7 - Have you performed the proper LOTO?	Done		NBARRETO	Apr 11, 2023 1:57:56 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NBARRETO	Apr 11, 2023 1:57:56 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		NBARRETO	Apr 11, 2023 1:57:56 PM	No	

Activity Sub Total

	Activity 10 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 56607681
Invoice No. 55345 - 56607681

Client Department:
Department: 55345M
Work Order Description
Change two front tires
Requested By: NBARRETO
Created By: NBARRETO
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 297,792 - DH

Activity Header
Activity: 20 017/001/000 TIRE, PNEUMATIC
Activity Note: FRONT TIRES
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Apr-23	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	141.06	282.12
11-Apr-23	28983	BUCKLE, SAFETY, W/C, BRAUN	1	27.75	27.75

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Apr-23	Nicolas Barreto	2.5	65	162.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	309.87
Labor:	162.50
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**472.37**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 56607681
Invoice No. 55345 - 56607681

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Change two front tires		Ford E450 Champion Challenger	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	297,792 - DH

Activity Header
Activity:30 017/001/000 TIRE, PNEUMATIC
Activity Note: REAR TIRES
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 56607681
Invoice No. 55345 - 56607681

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Change two front tires		Ford E450 Champion Challenger	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	297,792 - DH

Activity Header
Activity: 40 016 SUSPENSION
Activity Note: VEHICLE SENT TO ELPEX FOR ALIGNMENT
Reason for Repair: 21 Capital Improvement
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet

PO No.	ACD Code	Supplier No.	SUPPLIER	Order Date	Received Value
4698180	179,606,376	72882	MIAMI TIRESOLES, ELPEX,FL,DEERFIELD BEACH,dba MIAMI TIRESOLES ELPEX	Apr 14, 2023 12:00:00 AM	125

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	125.00
Sublet Labor:	0.00
Activity Sub Total	**125.00**

Work Order Footer

Work Order 56607681 Total	
Parts:	309.87
Labor:	162.50
Labor Hours:	2.50
Sublet Parts:	125.00
Sublet Labor:	0.00
Activity Sub Total	**597.37**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 6

Work Order No. 56539192
Invoice No. 55345 - 56539192

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Check Lift		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	297,652 - DH

Chronology		
Reported	Mar 24, 2023 4:44:00 PM	Mar 24, 2023 4:44:00 PM
Started	Mar 24, 2023 5:41:00 PM	
Completed	Apr 10, 2023 9:53:00 AM	Apr 10, 2023 9:53:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Vehicle. Came in for lift issue

Cause: pump not olden pressure. At floor level Need new pump. Also need one shock for door

Correction: Line 20 This unit need water pump Itis leaking Line 30 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:Water pump is leaking

Cause: Defective water pump

Correction:Water pump replaced Line 40 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:Lift is not working properly

Cause:Defective outer barrier shocks gas spring and upper arm cylinders.

Correction: removed and replaced lift pump and motor

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 10-APR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Apr 10, 2023 9:47:45 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Apr 10, 2023 9:47:45 AM	No	
4 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Apr 10, 2023 9:47:45 AM	No	
7 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Apr 10, 2023 9:47:45 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Apr 10, 2023 9:47:45 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Apr 10, 2023 9:47:45 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 6

Work Order No. 56539192
Invoice No. 55345 - 56539192

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Check Lift		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	297,652 - DH

Activity Header
Activity: 15 055/023/000 LIFT, WHEELCHAIR, PASSENGER
Activity Note: check lift for proper Operation
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Mar-23	Fritz Simon	1.28	65	83.2
24-Mar-23	Junior Hurst	2.33	65	151.45

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	234.65
Labor Hours:	3.61
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**234.65**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 6

Work Order No. 56539192
Invoice No. 55345 - 56539192

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Check Lift		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	297,652 - DH

Activity Header
Activity: 25 042/004/000 PUMP, WATER
Activity Note: WATER PUMP LEAKING
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 18 Leaking
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Mar-23	PW494	PUMP, WATER	1	106.48	106.48

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Mar-23	Fritz Simon	1.75	65	113.75
25-Mar-23	Fritz Simon	1.23	65	79.95
24-Mar-23	Fritz Simon	0.22	65	14.3

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	106.48
Labor:	208.00
Labor Hours:	3.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**314.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 6

Work Order No. 56539192
Invoice No. 55345 - 56539192

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Check Lift		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	297,652 - DH

Activity Header
Activity: 35 174 BODY, BUS
Activity Note: Door shock one
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 35 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 6

Work Order No. 56539192
Invoice No. 55345 - 56539192

Client Department:
Department: 55345M
Work Order Description
Check Lift
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 297,652 - DH

Activity Header
Activity: 45 055/023 LIFT, WHEELCHAIR, PASSENGER
Activity Note: WC LIFT O.B SHOCKS REPL.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Mar-23	Fritz Simon	2	65	130
28-Mar-23	Fritz Simon	4.18	65	271.7

Activity Sublet
No Data Available

Activity Checklist

Check List

45 Desc: WC LIFT O.B SHOCKS REPL.
Task: Braun Wheelchair Lift Inspection Performed by: RAURODRIGUEZ Performed on: 10-APR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Record Lift Model in Notes	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
200 - Record Serial # in Notes	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
300 - Cycle Count	Cycles	na	RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
10,000 - A - GENERAL INSPECTION	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
10,100 - Lift Battery, Circuit Breaker & Cable	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
10,200 - Lift Ground & Secondary Ground	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
10,300 - Vehicle Interlock Power	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
10,400 - Vehicle Interlock Prohits Vehicle Movement	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
10,500 - Lift Door Condition	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,600 - Hand Pendant Codition/Function	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
10,700 - Inspect Mounting Components	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
20,000 - B - CYCLE CHECK	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
20,100 - General Operation Throug Comple Cycle	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
20,200 - Main, Handrail, OB & IB Bumper Adjustments	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
20,300 - Floor Level Adjustment	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
20,400 - Platform Angle Adjustment	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
20,500 - Outer Barrier Interlock	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
20,600 - Inner Barrier Interlock	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
20,700 - Threshold Warning Interlock	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
20,800 - 50 Pound Fold Interlock	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
20,900 - Platform Lights	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
21,000 - Anti-Skid	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
21,100 - Operation & Warning Decals	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
21,200 - Back Pump Handdle Location	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
21,300 - Manual Override/Back-up System Function	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
30,000 - C - MECHANICAL COMPONENTS	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
30,100 - Base Plate, Tower, Arm & Platform Welds	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
30,200 - Outer Barrier Pins, Gas Springs & Fasteners	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
30,300 - Inner Barrier Pins, Gas Springs & Fasteners	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
30,400 - Pivot Pin Fasteners	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
30,500 - Pivot Pins & Bushing Condition	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
30,600 - Handrails	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
30,700 - Lift-Tite System	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
40,000 - D - HYDRAULIC COMPONENT CHECKS	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
40,100 - Leaks	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,200 - Hoses & Harness Routing/Condition (pump,parallel-vertical arms,platform)	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
40,300 - Remove Pump Cover & Check Fluid Level	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
40,400 - Fluid Condition	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
40,500 - LiftPump Motor Cables/Connections	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	
40,600 - Lift Pump Harnesses/Fuses/Electrical Components	Done		RAURODRIGUEZ	Apr 10, 2023 9:53:02 AM	No	

Activity Sub Total

Activity 45 Sub Total	
Parts:	0.00
Labor:	401.70
Labor Hours:	6.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**401.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 6 of 6

Work Order No. 56539192
Invoice No. 55345 - 56539192

Client Department:
Department: 55345M
Work Order Description
Check Lift
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 297,652 - DH

Activity Header
Activity: 55 055/023/000 LIFT, WHEELCHAIR, PASSENGER
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Apr-23	Rodriguez,Raul	3.35	65	217.75
07-Apr-23	Rodriguez,Raul	5.05	65	328.25
05-Apr-23	Rodriguez,Raul	0.48	65	31.2

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 55 Sub Total	
Parts:	0.00
Labor:	577.20
Labor Hours:	8.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**577.20**

Work Order Footer

Work Order 56539192 Total	
Parts:	106.48
Labor:	1,421.55
Labor Hours:	21.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1,528.03**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56506325
Invoice No. 55345 - 56506325

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Replace Batteries		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	297,359 - DH

Chronology		
Reported	Mar 14, 2023 8:33:00 PM	Mar 14, 2023 8:33:00 PM
Started	Mar 14, 2023 8:34:00 PM	
Completed	Mar 16, 2023 4:26:00 PM	Mar 16, 2023 4:26:00 PM
Down Time		

Work Order Notes

Line 10

Complaint: Vehicle will not start

Cause: Batteries

Correction: Remove old batteries and reinstall new batteries both batteries are good at this time.

Part# 34 AGM Qty 2 Need to Charge Part Out None in stock

Please charge part out of stock

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
10 Desc: PERSONAL RISK ASSESMENT Task: PRA and Meter Readings Performed by: AOWENS Performed on: 16-MAR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		AOWENS	Mar 16, 2023 4:26:28 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		AOWENS	Mar 16, 2023 4:26:28 PM	No	
4 - Are you wearing the appropriate PPE?	Done		AOWENS	Mar 16, 2023 4:26:28 PM	No	
7 - Have you performed the proper LOTO?	Done		AOWENS	Mar 16, 2023 4:26:28 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	Mar 16, 2023 4:26:28 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Mar 16, 2023 4:26:28 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56506325
Invoice No. 55345 - 56506325

Client Department:
Department: 55345M
Work Order Description
Replace Batteries
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 297,359 - DH

Activity Header
Activity: 20 032/001/001 BATTERY
Activity Note: Replace Batteries
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure: 43 Weak
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Mar-23	34AGM	BATTERY, AGM, GROUP-34	2	166.95	333.9

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Mar-23	Owens,Arthur	1.13	65	73.45

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	333.90
Labor:	73.45
Labor Hours:	1.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**407.35**

Work Order Footer

Work Order 56506325 Total	
Parts:	333.90
Labor:	73.45
Labor Hours:	1.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**407.35**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56488106
Invoice No. 55345 - 56488106

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
REAR AC SYSTEM		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	297,102 - DH

Chronology		
Reported	Mar 9, 2023 7:26:27 AM	Mar 9, 2023 7:26:27 AM
Started	Mar 9, 2023 12:00:00 AM	
Completed	Mar 14, 2023 7:14:00 AM	Mar 14, 2023 7:14:00 AM
Down Time		

Work Order Notes

Line 10 PERFORM REGULAR MAINTENANCE FROM AND REAR AC

RETURN VEHICLE TO SERVICE

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 14-MAR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Mar 14, 2023 7:12:32 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Mar 14, 2023 7:12:32 AM	No	
4 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Mar 14, 2023 7:12:32 AM	No	
7 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Mar 14, 2023 7:12:32 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Mar 14, 2023 7:12:32 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Mar 14, 2023 7:12:32 AM	No	

Activity Sub Total

	Activity 10 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56488106
Invoice No. 55345 - 56488106

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
REAR AC SYSTEM		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	297,102 - DH

Activity Header
Activity: 20 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: REAR AC DIAG
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Mar-23	Rodriguez,Raul	1.7333333	65	112.6666645

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	112.67
Labor Hours:	1.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**112.67**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56488106
Invoice No. 55345 - 56488106

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
REAR AC SYSTEM		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	297,102 - DH

Activity Header
Activity: 30 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Mar-23	Rodriguez,Raul	1.5333333	65	99.6666645

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	99.67
Labor Hours:	1.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**99.67**

Work Order Footer

Work Order 56488106 Total	
Parts:	0.00
Labor:	212.33
Labor Hours:	3.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**212.33**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56492023
Invoice No. 55345 - 56492023

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
ROAD call		Ford E450 Champion Challenger	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	297,102 - DH

Chronology		
Reported	Mar 10, 2023 9:46:03 AM	Mar 10, 2023 9:46:03 AM
Started	Mar 10, 2023 9:49:00 AM	
Completed	Mar 10, 2023 11:51:00 AM	Mar 10, 2023 11:51:00 AM
Down Time		

Work Order Notes

Line 10 ROAD call cancel

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: NBARRETO Performed on: 10-MAR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NBARRETO	Mar 10, 2023 11:51:05 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NBARRETO	Mar 10, 2023 11:51:05 AM	No	
4 - Are you wearing the appropriate PPE?	Done		NBARRETO	Mar 10, 2023 11:51:05 AM	No	
7 - Have you performed the proper LOTO?	Done		NBARRETO	Mar 10, 2023 11:51:05 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NBARRETO	Mar 10, 2023 11:51:05 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		NBARRETO	Mar 10, 2023 11:51:05 AM	No	

Activity Sub Total

Activity 5 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56492023
Invoice No. 55345 - 56492023

Client Department:
Department: 55345M
Work Order Description
ROAD call
Requested By: NBARRETO
Created By: NBARRETO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 297,102 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Mar-23	28983	BUCKLE, SAFETY, W/C, BRAUN	1	21.63	21.63

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Mar-23	Nicolas Barreto	2.02	65	131.3

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	21.63
Labor:	131.30
Labor Hours:	2.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**152.93**

Work Order Footer

Work Order 56492023 Total	
Parts:	21.63
Labor:	131.30
Labor Hours:	2.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**152.93**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56315497
Invoice No. 55345 - 56315497

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
CANCELLED WORK ORDER		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	99 - Cancelled (99)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	296,944 - DH

Chronology		
Reported	Jan 17, 2023 12:03:42 PM	Jan 17, 2023 12:03:42 PM
Started		
Completed	Jan 24, 2023 2:56:22 PM	Jan 24, 2023 2:56:22 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction:

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	-				No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	-				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
4 - Are you wearing the appropriate PPE?	-				No	
7 - Have you performed the proper LOTO?	-				No	
10 - Are you aware of the potential risks of performing this repair?	-				No	
11 - Have you successfully completed the Personal Risk Assessment?	-				No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56315497
Invoice No. 55345 - 56315497

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
CANCELLED WORK ORDER		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	99 - Cancelled (99)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	296,944 - DH

Activity Header
Activity: 15 010 CHASSIS GROUP
Activity Note: more ride
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 56315497 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56199808
Invoice No. 55345 - 56199808

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP-FT Medium Duty
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 295,516 - DH

Chronology		
Reported	Dec 7, 2022 11:38:50 AM	Dec 7, 2022 11:38:50 AM
Started	Dec 22, 2022 10:01:00 PM	
Completed	Jan 11, 2023 2:34:00 PM	Jan 11, 2023 2:34:00 PM
Down Time		

Work Order Notes

Line 10 Installed 2 motor mounts Line 20 pleaee charge Right motor mount Line 30 fire suppression system alarm on

detector bottle low

removed and replaced detector bottle

w/c lift inspection, all okay at this time

Activity Header
Activity: 10 027/001/013 HARDWARE, MOUNTING, CASE, TRANSMISSION, AUTOMATIC APFI - 027-001-001
Activity Note: Engine mounts
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Jan-23	F7UZ-6038-EB	INSULATOR, SUPPORT, ENGINE, FRONT, LH	1	34.07	34.07
11-Jan-23	5U9Z-6038-AA	MOUNT, ENGINE, RH	1	42.54	42.54

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Jan-23	Delva,Terry	2.2	65	143
10-Jan-23	Delva,Terry	1.15	65	74.75

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	76.61
Labor:	217.75
Labor Hours:	3.35
Sublet Parts:	0.00

	Sublet Labor:	0.00
	Activity Sub Total	**294.36**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56199808
Invoice No. 55345 - 56199808

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	295,516 - DH

Activity Header
Activity: 20 051/007/000 SUPPRESSION, FIRE
Activity Note: fire suppression system alarm on
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Jan-23	Rodriguez,Raul	1.45	65	94.25

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	94.25
Labor Hours:	1.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**94.25**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56199808
Invoice No. 55345 - 56199808

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP-FT Medium Duty
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 295,516 - DH

Activity Header
Activity: 30 055/023/000 LIFT, WHEELCHAIR, PASSENGER
Activity Note: check wheel chair lift proper operation
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Jan-23	Rodriguez,Raul	1.2166666	65	79.083329

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	79.08
Labor Hours:	1.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**79.08**

Work Order Footer

Work Order 56199808 Total	
Parts:	76.61
Labor:	391.08
Labor Hours:	6.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**467.69**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 56199724
Invoice No. 55345 - 56199724

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	295,516 - DH

Chronology		
Reported	Dec 7, 2022 11:27:12 AM	Dec 7, 2022 11:27:12 AM
Started	Dec 7, 2022 1:13:00 PM	
Completed	Dec 8, 2022 12:40:00 PM	Dec 8, 2022 12:40:00 PM
Down Time		

Work Order Notes

Line 10 c. parking brakes no holding

c. shoes in spec, need to be adjust

c. adjusted parking brakes

Activity Header

Activity: 10 013/003/002 HARDWARE, MOUNTING, LEVER, PEDAL& SECTOR, BRAKE, PARKING APFI - 013-003-001
Activity Note: parking brake
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Dec-22	Rodriguez,Raul	1.97	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 56199724 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.97

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 56199827
Invoice No. 55345 - 56199827

Client Department:

Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	295,516 - DH

Chronology		
Reported	Dec 7, 2022 11:42:38 AM	Dec 7, 2022 11:42:38 AM
Started	Dec 7, 2022 12:06:00 PM	
Completed	Dec 8, 2022 12:37:00 PM	Dec 8, 2022 12:37:00 PM
Down Time		

Work Order Notes

Line 10 c. left rear inner tire near min specs

c. normal wear

c. replaced tire with used good one. (9/32)

Activity Header
Activity: 10 017/008/004 CAP, VALVE, TIRE
Activity Note: left rear inner tire
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Dec-22	Rodriguez,Raul	1.12	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 56199827 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.12
Sublet Parts:	0.00

	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56195699
Invoice No. 55345 - 56195699

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-MEDIUM DUTY PMA		Ford E450 Champion Challenger	
Requested By:	SPACE	**Status:**	40 - Closed (40)
Created By:	SPACE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	295,516 - DH

Chronology		
Reported	Dec 7, 2022 8:58:52 AM	Dec 7, 2022 8:58:52 AM
Started	Dec 7, 2022 9:29:00 AM	
Completed	Dec 7, 2022 12:04:00 PM	Dec 7, 2022 12:04:00 PM
Down Time		

Work Order Notes

Line 10 PERFORM PMA SERVICE

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 07-DEC-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Dec 7, 2022 11:15:23 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Dec 7, 2022 11:15:23 AM	No	
4 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Dec 7, 2022 11:15:23 AM	No	
7 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Dec 7, 2022 11:15:23 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Dec 7, 2022 11:15:23 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Dec 7, 2022 11:15:23 AM	No	

Activity Sub Total

Activity 5 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56195699
Invoice No. 55345 - 56195699

Client Department:
Department: 55345M
Work Order Description
55345-MEDIUM DUTY PMA
Requested By: SPACE
Created By: SPACE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 295,516 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Dec-22	B329	FILTER, OIL, SPIN-ON SEE P550965	1	4.11	4.11

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Dec-22	Rodriguez,Raul	2.57	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: RAURODRIGUEZ Performed on: 07-DEC-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR &	Done		RAURODRIGUEZ	Dec 7, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Authorization Forms				11:49:49 AM		
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
10,800 - CHECK_All Destination Signage	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
20,200 - CHECK_Public Address System	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	na	RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	na	RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	na	RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	na	RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	na	RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	-	na	RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
21,500 - INSPECT_High Idle Control	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
21,800 - INSPECT_Parking Brake Operation	Done	parking brake	RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	Yes	56199724
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
31,000 - SSF (Street Side Front)	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,000 - Engine Inspection	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
32,100 - INSPECT_Intake System	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	13.8 Volt*		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
33,000 - CSF (Curb Side Front)	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
33,050 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
33,060 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	13.8 Volt*		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	-	na	RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
40,700 - CHECK_Passenger Stop Request System	-	na	RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
50,100 - *RPT*INSPECT_Steering components- Drag Link, Tie Rods ends and Steering Damper	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,200 - INSPECT_Ball Joint Play	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
50,400 - LUBE_All Chassis Components	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
50,700 - INSPECT_Tire Condition	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	9 32nds of an inch		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	9 32nds of an inch		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	32nds of an inch	8mm	RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	32nds of an inch	8mm	RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	Inch	39.4mm	RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	Inch	39.4mm	RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
52,100 - INSPECT_Vibration Damper	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done	Engine mounts	RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	Yes	56199808
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
53,600 - INSPECT_Tire Condition	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	10 32nds of an inch		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	10 32nds of an inch		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	9 32nds of an inch		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	3 32nds of an inch	tire near min specs	RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	Yes	56199827
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	32nds of an inch	11mm	RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	32nds of an inch	11mm	RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	Inch	39.7mm	RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	Inch	39.7mm	RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,000 - SECTION 6 - Wheelchair Inspection	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
60,100 - RECORD_Wheelchair Cycle Count	Cycles	na	RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	-	na	RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
61,900 - CLEAN_Linkages and Mechanisms	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
62,400 - INSPECT_All Pivot Points	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
62,500 - INSPECT_Cams and Slots	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
62,600 - INSPECT_Rollers	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
62,700 - INSPECT_All Linkages	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RAURODRIGUEZ	Dec 7, 2022 11:49:49 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	4.11
Labor:	0.00
Labor Hours:	2.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.11**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56195699
Invoice No. 55345 - 56195699

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-MEDIUM DUTY PMA		Ford E450 Champion Challenger	
Requested By:	SPACE	**Status:**	40 - Closed (40)
Created By:	SPACE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	295,516 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: RAURODRIGUEZ Performed on: 07-DEC-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RAURODRIGUEZ	Dec 7, 2022 11:51:43 AM	No	
101,000 - FRA Change Oil Filters	Yes		RAURODRIGUEZ	Dec 7, 2022 11:51:43 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RAURODRIGUEZ	Dec 7, 2022 11:51:43 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RAURODRIGUEZ	Dec 7, 2022 11:51:43 AM	No	
104,000 - Lubricate Chassis	Done		RAURODRIGUEZ	Dec 7, 2022 11:51:43 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RAURODRIGUEZ	Dec 7, 2022 11:51:43 AM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	-	na	RAURODRIGUEZ	Dec 7, 2022 11:51:43 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RAURODRIGUEZ	Dec 7, 2022 11:51:43 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RAURODRIGUEZ	Dec 7, 2022 11:51:43 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 56195699 Total	
Parts:	4.11
Labor:	0.00
Labor Hours:	2.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.11**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55871913
Invoice No. 55345 - 55871913

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	99 - Cancelled (99)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	295,516 - DH

Chronology		
Reported	Nov 16, 2022 12:00:00 AM	Nov 16, 2022 12:00:00 AM
Started		
Completed	Dec 7, 2022 11:19:56 AM	Dec 7, 2022 11:19:56 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION:

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	-				No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	-				No	
4 - Are you wearing the appropriate PPE?	-				No	
7 - Have you performed the proper LOTO?	-				No	
10 - Are you aware of the potential risks of performing this repair?	-				No	
11 - Have you successfully completed the Personal Risk Assessment?	-				No	

Activity Sub Total

	Activity 5 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55871913
Invoice No. 55345 - 55871913

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	99 - Cancelled (99)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	295,516 - DH

Activity Header
Activity: 10
Activity Note: Light Duty PMI
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	-				No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	-				No	
10,200 - !FRA!INSPECT_Starter Operation	-				No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	-				No	
10,400 - !FRA!INSPECT_Back Up Alarm	-				No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	-				No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	-				No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	-				No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	-				No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	-				No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	-				No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	-				No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	-				No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive	-				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
into Shop						
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	-				No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	-				No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	-				No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	-				No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	-				No	
20,800 - INSPECT_High Idle Control	-				No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	-				No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	-				No	
21,100 - INSPECT_Parking Brake Operation	-				No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	-				No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	-				No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	-				No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	-				No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	-				No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	-				No	
21,700 - INSPECT_Engine Fault Codes	-				No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	-				No	
31,000 - SSF (Street Side Front)	-				No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	-				No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	-				No	
31,030 - INSPECT_Mud Flaps, Brackets	-				No	
31,040 - INSPECT_Wiper Blades, Arms	-				No	
32,000 - Engine Inspection	-				No	
32,010 - INSPECT_Hood, Springs and Props	-				No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	-				No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	-				No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-				No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit				No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	-				No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	-				No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	-				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	-				No	
32,100 - INSPECT_Intake System	-				No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	Volt*				No	
33,010 - CSF (Curb Side Front)	-				No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	-				No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	-				No	
33,040 - INSPECT_Mud Flaps, Brackets	-				No	
33,050 - INSPECT_Wiper Blades, Arms	-				No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	-				No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*				No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	-				No	
40,000 - SECTION 4 - Interior Inspection	-				No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	-				No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	-				No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	-				No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	-				No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	-				No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	-				No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	-				No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	-				No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	-				No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	-				No	
41,100 - INSPECT_CLEAN_AC Filter	-				No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	-				No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	-				No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	-				No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	-				No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	-				No	
50,200 - INSPECT_Ball Joint Play	-				No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	-				No	
50,400 - LUBE_All Chassis Components	-				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,500 - !FRA!CHANGE_Engine oil,filters	-				No	
50,700 - INSPECT_Tire Condition	-				No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	-				No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	-				No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	32nds of an inch				No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	Pounds per Square Inch				No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	32nds of an inch				No	
51,300 - RECORD_RF-Air Pressure (psi)	Pounds per Square Inch				No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	-				No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	-				No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	-				No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	32nds of an inch				No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	32nds of an inch				No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	Inch				No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	Inch				No	
52,100 - INSPECT_Vibration Damper	-				No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	-				No	
52,400 - !FRA!INSPECT_ Starter Mounting	-				No	
52,500 - !FRA!INSPECT_Engine Exhaust System	-				No	
52,700 - INSPECT_ Engine, Transmission Mounts	-				No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	-				No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	-				No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	-				No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	-				No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	-				No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	-				No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	-				No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	-				No	
53,600 - INSPECT_Tire Condition	-				No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	-				No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	-				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,900 - INSPECT_Dual Mating Tires w/Square	-				No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	-				No	
54,100 - INSPECT_Mud Flaps, Brackets	-				No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	32nds of an inch				No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	32nds of an inch				No	
54,400 - RECORD_RRO-Air Pressure (psi)	Pounds per Square Inch				No	
54,500 - RECORD_RRI-Air Pressure (psi)	Pounds per Square Inch				No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	32nds of an inch				No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	32nds of an inch				No	
54,800 - RECORD_LRO-Air Pressure (psi)	Pounds per Square Inch				No	
54,900 - RECORD_LRI-Air Pressure (psi)	Pounds per Square Inch				No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	-				No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	-				No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	-				No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	32nds of an inch				No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	32nds of an inch				No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	Inch				No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	Inch				No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	-				No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	-				No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	-				No	
60,000 - SECTION 6 - Wheelchair Inspection	-				No	
60,100 - RECORD_Wheelchair Cycle Count	Cycles				No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	-				No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	-				No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	-				No	
60,500 - INSPECT_ Bridgeplate Operation	-				No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	-				No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	-				No	
60,800 - INSPECT_Operation of Platform Barrier	-				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Mechanism						
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	-				No	
61,000 - INSPECT_Cable Condition (If Applicable)	-				No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	-				No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	-				No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	-				No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	-				No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	-				No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	-				No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	-				No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	-				No	
61,900 - CLEAN_Linkages and Mechanisms	-				No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	-				No	
62,100 - INSPECT_Emergency Platform Release Mechanism	-				No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	-				No	
62,300 - INSPECT_Bridgeplate Hinge	-				No	
62,400 - INSPECT_All Pivot Points	-				No	
62,500 - INSPECT_Cams and Slots	-				No	
62,600 - INSPECT_Rollers	-				No	
62,700 - INSPECT_All Linkages	-				No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	-				No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	-				No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	-				No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	-				No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	-				No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	-				No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	-				No	
80,000 - SECTION 8 - PMI Report Completion	-				No	
80,100 - COMPLETE_PM Report; Follow-ups	-				No	
80,200 - RETURN_Vehicle to Predetermined Location	-				No	

Activity Sub Total

Activity 10 Sub Total

Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55871913
Invoice No. 55345 - 55871913

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	99 - Cancelled (99)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	295,516 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	-				No	
101,000 - FRA Change Oil Filters	No				No	
102,000 - FRA Drain Engine Oil	No				No	
103,000 - FRA Check Transmission Fluid	-				No	
104,000 - Lubricate Chassis	-				No	
105,000 - Replace or Clean A/C Filters	-				No	
107,000 - FRA Change Primary Fuel Filter	No				No	
108,000 - Lube all pivoting Mechanisms	-				No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55871913 Total	
Parts:	0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56192968
Invoice No. 55345 - 56192968

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
lift not workimg		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	295,481 - DH

Chronology		
Reported	Dec 5, 2022 4:13:16 PM	Dec 5, 2022 4:13:16 PM
Started	Dec 5, 2022 4:41:00 PM	
Completed	Dec 7, 2022 9:07:00 AM	Dec 7, 2022 9:07:00 AM
Down Time		

Work Order Notes

Line 10 Rear A/C Blower Motor Not Working On Medium Speed Remove Evap Housing Found Low Speed Yellow Wire no Voltage. found Connector not making Contact Secure Connector all is good at this time. Line 20 complaint. w/c lift isn't working properly

Cause. bad inner plate shoks

Correction. removed and replaced inner plate shoks, all okay at this time

Activity Header

Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 07-DEC-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Dec 7, 2022 9:02:16 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Dec 7, 2022 9:02:16 AM	No	
4 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Dec 7, 2022 9:02:16 AM	No	
7 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Dec 7, 2022 9:02:16 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Dec 7, 2022 9:02:16 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Dec 7, 2022 9:02:16 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56192968
Invoice No. 55345 - 56192968

Client Department:
Department: 55345M
Work Order Description
lift not workimg
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 295,481 - DH

Activity Header
Activity: 15 030 ELECTRICAL GROUP
Activity Note: lift not working
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Dec-22	32601	SPRING, ASSIST, GAS	1	15.57	15.57

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Dec-22	Junior Hurst	1.85	0	0
07-Dec-22	Rodriguez,Raul	1.83	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	15.57
Labor:	0.00
Labor Hours:	3.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**15.57**

Work Order Footer

Work Order 56192968 Total	
Parts:	15.57
Labor:	0.00
Labor Hours:	3.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**15.57**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56183284
Invoice No. 55345 - 56183284

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check LED Interior Lights)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 295,128 - DH

Chronology		
Reported	Dec 1, 2022 11:02:00 PM	Dec 1, 2022 11:02:00 PM
Started	Dec 1, 2022 11:03:00 PM	
Completed	Dec 2, 2022 12:33:00 AM	Dec 2, 2022 12:33:00 AM
Down Time		

Work Order Notes

Line 10 Complaint: Interior light stays on.

Cause: Door light switch was "on".

Correction: Turned off dome light switch, lght went out shortly after.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 02-DEC-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Dec 2, 2022 12:29:30 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Dec 2, 2022 12:29:30 AM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Dec 2, 2022 12:29:30 AM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Dec 2, 2022 12:29:30 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Dec 2, 2022 12:29:30 AM	No	
11 - Have you successfully completed the	Done		EARJOHNSON	Dec 2, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				12:29:30 AM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56183284
Invoice No. 55345 - 56183284

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check LED Interior Lights)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 295,128 - DH

Activity Header
Activity:20 174/024/001 HARNESS, WIRING, BODY, BUS, MAIN
Activity Note: Check Interior Light
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Dec-22	Earl Johnson	0.45	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 56183284 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 54679615
Invoice No. 55345 - 54679615

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
QCC FLEET INSPECTION		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	295,128 -

Chronology		
Reported	Jul 13, 2022 12:41:09 PM	Jul 13, 2022 12:41:09 PM
Started		
Completed	Nov 22, 2022 11:00:48 PM	Nov 22, 2022 11:00:48 PM
Down Time		

Work Order Notes

Activity Header
Activity:0
Activity Note:
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 0 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56127489
Invoice No. 55345 - 56127489

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Wheelchair Lift		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	294,450 - DH

Chronology		
Reported	Nov 11, 2022 1:00:00 PM	Nov 11, 2022 1:00:00 PM
Started	Nov 11, 2022 1:28:00 PM	
Completed	Nov 11, 2022 2:54:00 PM	Nov 11, 2022 2:54:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Check wheelchair lift, wire under the dashboard

Cause: preventive maintenance

Correction: zip ties and secured wires under dashboard and lube the wheelchair lift Check and clean everything ok at time

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 11-NOV-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Nov 11, 2022 1:29:10 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Nov 11, 2022 1:29:10 PM	No	
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Nov 11, 2022 1:29:10 PM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Nov 11, 2022 1:29:10 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Nov 11, 2022 1:29:10 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Nov 11, 2022 1:29:10 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56127489
Invoice No. 55345 - 56127489

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Wheelchair Lift		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	294,450 - DH

Activity Header
Activity: 20 055/023/000 LIFT, WHEELCHAIR, PASSENGER
Activity Note: WheelChair Lift
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Nov-22	NELSON PIERRE-LOUIS	1.43	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 56127489 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56077636
Invoice No. 55345 - 56077636

Client Department:
Department: 55345M
Work Order Description
CHECK BUS FOR STALLING CONDITION
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 294,110 - DH

Chronology		
Reported	Oct 27, 2022 10:18:00 AM	Oct 27, 2022 10:18:00 AM
Started	Oct 27, 2022 11:19:00 AM	
Completed	Oct 28, 2022 12:07:00 PM	Oct 28, 2022 12:07:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:engine is stalling

Cause: Check computer system found codes for engine misfire on cylinders 3 and 4, removed coils and spark plugs to inspect it

Correction:replaced one ignition coil and 3 spark plugs retest and road test vehicle ok no stalling at this time

part:
1 ignition coil dg508
3 spark plug sp521

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 28-OCT-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Oct 28, 2022 11:23:13 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Oct 28, 2022 11:23:13 AM	No	
4 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Oct 28, 2022 11:23:13 AM	No	
7 - Have you performed the proper LOTO?	Done		JAPEREZ	Oct 28, 2022 11:23:13 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Oct 28, 2022 11:23:13 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Oct 28, 2022 11:23:13 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56077636
Invoice No. 55345 - 56077636

Client Department:
Department: 55345M
Work Order Description
CHECK BUS FOR STALLING CONDITION
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 294,110 - DH

Activity Header
Activity: 15 045 POWER PLANT
Activity Note: CHECK FOR STALLING CONDITION
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Oct-22	DG508	COIL, IGNITION SAME AS 3W7Z-12029-AA	1	35.92	35.92
28-Oct-22	SP521	PLUG, SPARK, 5.4L, FORD	3	4.92	14.76

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Oct-22	Perez,Javier	4.52	0	0
27-Oct-22	Perez,Javier	4.27	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	50.68
Labor:	0.00
Labor Hours:	8.79
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**50.68**

Work Order Footer

Work Order 56077636 Total	
Parts:	50.68
Labor:	0.00
Labor Hours:	8.79
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**50.68**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56033747
Invoice No. 55345 - 56033747

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
TIRES		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	294,011 - DH

Chronology		
Reported	Oct 13, 2022 7:36:00 AM	Oct 13, 2022 7:36:00 AM
Started	Oct 13, 2022 8:08:00 AM	
Completed	Oct 13, 2022 11:23:00 AM	Oct 13, 2022 11:23:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PASSENGER side rear tires low spec

Cause: preventive maintenance

Correction: replaced 2 PASSENGER side rear tires with used good ones mount and balance

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 13-OCT-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Oct 13, 2022 11:21:08 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Oct 13, 2022 11:21:08 AM	No	
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Oct 13, 2022 11:21:08 AM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Oct 13, 2022 11:21:08 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Oct 13, 2022 11:21:08 AM	No	
11 - Have you successfully completed the Personal	Done		NPIERRE-	Oct 13, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	11:21:08 AM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56033747
Invoice No. 55345 - 56033747

Client Department:
Department: 55345M
Work Order Description
TIRES
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 294,011 - DH

Activity Header
Activity: 20 017/001/000 TIRE, PNEUMATIC
Activity Note: TIRES
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Oct-22	NELSON PIERRE-LOUIS	2.35	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 56033747 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55918505
Invoice No. 55345 - 55918505

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
front A/C not cool		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	291,209 - DH

Chronology		
Reported	Sep 6, 2022 2:58:41 PM	Sep 6, 2022 2:58:41 PM
Started	Sep 6, 2022 12:00:00 AM	
Completed	Oct 5, 2022 4:27:00 PM	Oct 5, 2022 4:27:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Vehicle came in for front A/C not cooling

Cause: High side line from compressor leaking part order

Correction: Installed new front AC high pressure hose

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: front A/C not working
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Sep-22	Junior Hurst	3	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: front A/C not working
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 03-OCT-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Oct 3, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:18:30 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Oct 3, 2022 12:18:30 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Oct 3, 2022 12:18:30 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Oct 3, 2022 12:18:30 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Oct 3, 2022 12:18:30 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Oct 3, 2022 12:18:30 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55918505
Invoice No. 55345 - 55918505

Client Department:
Department: 55345M
Work Order Description
front A/C not cool
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 291,209 - DH

Activity Header
Activity: 15 001/001 AIR CONDITIONING
Activity Note: AC DISCHARGE HOSE LEAKING
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Oct-22	CC2Z-19972-A	MANIFOLD, DISCHARGE, A/C	1	122.44	122.44

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Oct-22	Delva,Terry	2.87	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	122.44
Labor:	0.00
Labor Hours:	2.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**122.44**

Work Order Footer

Work Order 55918505 Total	
Parts:	122.44
Labor:	0.00
Labor Hours:	5.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**122.44**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 55841126
Invoice No. 55345 - 55841126

Client Department:
Department: 55345M
Work Order Description
check engine light on
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 290,835 - DH

Chronology		
Reported	Aug 9, 2022 1:57:00 PM	Aug 9, 2022 1:57:00 PM
Started	Aug 9, 2022 3:26:00 PM	
Completed	Aug 26, 2022 1:22:00 PM	Aug 26, 2022 1:22:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: Check engine light is on and wrench light is on

Cause: Cyl #4 misfire and bad transmission external harness
low compression in #4 cylinder <100psi

Correction:Replaced cyl #4 spark plug and ignition coil.
Replaced transmission external harness
replaced overflow coolant tank Line 20 Front AC compressor click on/off
Recovered Front AC system .73lbs of freon
Vacuum system and no leaks found in system.....
Charged AC system

Activity Header
Activity: 10 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: check engine light on
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Aug-22	AP103	PLUG, SPARK	1	3.5	3.5

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Aug-22	Delva,Terry	0.15	0	0
09-Aug-22	Delva,Terry	1.33	0	0
16-Aug-22	Delva,Terry	1.05	0	0
10-Aug-22	Delva,Terry	0.6	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total

	Parts:	3.50
	Labor:	0.00
	Labor Hours:	3.13
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**3.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 55841126
Invoice No. 55345 - 55841126

Client Department:
Department: 55345M
Work Order Description
check engine light on
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 290,835 - DH

Activity Header
Activity: 20 032/000/000 CRANKING
Activity Note: Starter
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Aug-22	Delva,Terry	2.08	0	0
17-Aug-22	Delva,Terry	0.87	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 55841126
Invoice No. 55345 - 55841126

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
check engine light on		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	290,835 - DH

Activity Header
Activity: 30 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: transmission harness
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Aug-22	DC2Z-7C078-S	HARNESS, TRANSMISSION, EXTERNAL, E450	1	73.14	73.14
17-Aug-22	DG508	COIL, IGNITION SAME AS 3W7Z-12029-AA	1	35.92	35.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Aug-22	Delva,Terry	3.13	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	109.06
Labor:	0.00
Labor Hours:	3.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**109.06**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 55841126
Invoice No. 55345 - 55841126

Client Department:
Department: 55345M
Work Order Description
check engine light on
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 290,835 - DH

Activity Header
Activity: 40 042/002/009 TANK, SURGE, COOLANT
Activity Note: COOLANT RESERVOIR LEAKING
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Aug-22	603-811	TANK, OVERFLOW, COOLANT	1	78.36	78.36

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Aug-22	Delva,Terry	1.2166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	78.36
Labor:	0.00
Labor Hours:	1.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**78.36**

Work Order Footer

Work Order 55841126 Total	
Parts:	190.92
Labor:	0.00
Labor Hours:	10.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**190.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55741515
Invoice No. 55345 - 55741515

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	290,835 - DH

Chronology		
Reported	Aug 4, 2022 12:00:00 AM	Aug 4, 2022 12:00:00 AM
Started	Aug 19, 2022 10:45:00 AM	
Completed	Aug 19, 2022 6:22:00 PM	Aug 19, 2022 6:22:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA

CAUSE: service due

CORRECTION: Performed and completed PMA

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 19-AUG-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Aug 19, 2022 6:21:47 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Aug 19, 2022 6:21:47 PM	No	
4 - Are you wearing the appropriate PPE?	Done		TDELVA	Aug 19, 2022 6:21:47 PM	No	
7 - Have you performed the proper LOTO?	Done		TDELVA	Aug 19, 2022 6:21:47 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Aug 19, 2022 6:21:47 PM	No	
11 - Have you successfully completed the Personal	Done		TDELVA	Aug 19, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				6:21:47 PM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55741515
Invoice No. 55345 - 55741515

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 290,835 - DH

Activity Header
Activity: 10
Activity Note: Light Duty PMI
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Aug-22	B329	FILTER, OIL, SPIN-ON SEE P550965	1	7.57	7.57

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Aug-22	Delva,Terry	1.2	0	0
19-Aug-22	Delva,Terry	0.77	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: TDELVA Performed on: 19-AUG-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
10,800 - *RPT*INSPECT_Body Damage,	Done		TDELVA	Aug 19, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Corrosion;DOCUMENT_Issues				6:22:04 PM		
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
20,800 - INSPECT_High Idle Control	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
31,000 - SSF (Street Side Front)	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	Aug 19, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				6:22:04 PM		
31,040 - INSPECT_Wiper Blades, Arms	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
32,000 - Engine Inspection	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	TDELVA	Aug 19, 2022 6:22:04 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
32,100 - INSPECT_Intake System	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	0 Volt*		TDELVA	Aug 19, 2022 6:22:04 PM	No	
33,010 - CSF (Curb Side Front)	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	13.8 Volt*		TDELVA	Aug 19, 2022 6:22:04 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
50,400 - LUBE_All Chassis Components	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
50,700 - INSPECT_Tire Condition	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	9 32nds of an inch		TDELVA	Aug 19, 2022 6:22:04 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		TDELVA	Aug 19, 2022 6:22:04 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	9 32nds of an inch		TDELVA	Aug 19, 2022 6:22:04 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		TDELVA	Aug 19, 2022 6:22:04 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	Aug 19, 2022 6:22:04 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	Aug 19, 2022 6:22:04 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	36.8 Inch		TDELVA	Aug 19, 2022 6:22:04 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	36.8 Inch		TDELVA	Aug 19, 2022 6:22:04 PM	No	
52,100 - INSPECT_Vibration Damper	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
53,600 - INSPECT_Tire Condition	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	-	na	TDELVA	Aug 19, 2022 6:22:04 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		TDELVA	Aug 19, 2022 6:22:04 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		TDELVA	Aug 19, 2022 6:22:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		TDELVA	Aug 19, 2022 6:22:04 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		TDELVA	Aug 19, 2022 6:22:04 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		TDELVA	Aug 19, 2022 6:22:04 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		TDELVA	Aug 19, 2022 6:22:04 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		TDELVA	Aug 19, 2022 6:22:04 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		TDELVA	Aug 19, 2022 6:22:04 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	Aug 19, 2022 6:22:04 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	Aug 19, 2022 6:22:04 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	38.6 Inch		TDELVA	Aug 19, 2022 6:22:04 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	38.6 Inch		TDELVA	Aug 19, 2022 6:22:04 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	0 Cycles		TDELVA	Aug 19, 2022 6:22:04 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
61,000 - INSPECT_Cable Condition (If Applicable)	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
62,400 - INSPECT_All Pivot Points	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
62,500 - INSPECT_Cams and Slots	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
62,600 - INSPECT_Rollers	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
62,700 - INSPECT_All Linkages	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST. 4 FMMVSS 304 & ANSI-CSA NGV2	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,100 - COMPLETE_PM Report; Follow-ups	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		TDELVA	Aug 19, 2022 6:22:04 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	7.57
Labor:	0.00
Labor Hours:	1.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.57**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55741515
Invoice No. 55345 - 55741515

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 290,835 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Aug-22	Delva,Terry	1.53	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: TDELVA Performed on: 19-AUG-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		TDELVA	Aug 19, 2022 6:22:22 PM	No	
101,000 - FRA Change Oil Filters	No		TDELVA	Aug 19, 2022 6:22:22 PM	No	
102,000 - FRA Drain Engine Oil	No		TDELVA	Aug 19, 2022 6:22:22 PM	No	
103,000 - FRA Check Transmission Fluid	Done		TDELVA	Aug 19, 2022 6:22:22 PM	No	
104,000 - Lubricate Chassis	Done		TDELVA	Aug 19, 2022 6:22:22 PM	No	
105,000 - Replace or Clean A/C Filters	Done		TDELVA	Aug 19, 2022 6:22:22 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	TDELVA	Aug 19, 2022 6:22:22 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		TDELVA	Aug 19, 2022 6:22:22 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	1.53
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 55741515 Total	
Parts:	7.57
Labor:	0.00
Labor Hours:	3.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.57**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 55856878
Invoice No. 55345 - 55856878

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
enginy light on		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	290,835 - DH

Chronology		
Reported	Aug 15, 2022 1:14:16 PM	Aug 15, 2022 1:14:16 PM
Started		
Completed	Aug 15, 2022 3:46:00 PM	Aug 15, 2022 3:46:00 PM
Down Time		

Work Order Notes

Line 10 VEHICLE CAME IN FOR CHECK ENGINE LIGHT ON Line 20 COMPLAINT per driver check engine light on check unit and found injector # 9 cable was loose reconnected. unit now working return vehicle back to work

Activity Header
Activity:0
Activity Note:
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 0 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55754291
Invoice No. 55345 - 55754291

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
WIPERS NOT WORKING		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	286,862 - DH

Chronology		
Reported	Jul 7, 2022 7:07:00 AM	Jul 7, 2022 7:07:00 AM
Started	Jul 7, 2022 7:45:00 AM	
Completed	Jul 7, 2022 10:14:00 AM	Jul 7, 2022 10:14:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: wiper not working

Cause: the wiper linkage broken

Correction: replace windshield wiper linkages vompleted

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 07-JUL-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Jul 7, 2022 10:14:25 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Jul 7, 2022 10:14:25 AM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Jul 7, 2022 10:14:25 AM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Jul 7, 2022 10:14:25 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Jul 7, 2022 10:14:25 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Jul 7, 2022 10:14:25 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55754291
Invoice No. 55345 - 55754291

Client Department:
Department: 55345M
Work Order Description
WIPERS NOT WORKING
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 286,862 - DH

Activity Header
Activity: 15 002/035 WIPER & WASHER, WINDSHIELD
Activity Note: WIPER ARMS NOT WORKING
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Jul-22	1C2Z-17566-AA	LINKAGE, WIPER, WINDSHIELD	1	45.18	45.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Jul-22	Pierre,Hubert J	2.4	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	45.18
Labor:	0.00
Labor Hours:	2.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**45.18**

Work Order Footer

Work Order 55754291 Total	
Parts:	45.18
Labor:	0.00
Labor Hours:	2.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**45.18**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55642054
Invoice No. 55345 - 55642054

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMB		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	285,990 - DH

Chronology		
Reported	Jun 28, 2022 12:00:00 AM	Jun 28, 2022 12:00:00 AM
Started	Jun 30, 2022 3:46:00 PM	
Completed	Jul 1, 2022 12:31:00 AM	Jul 1, 2022 12:31:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMB

CAUSE:service

CORRECTION:Perform PMB Service
oil filter B329 qty1
engine oil 10w30 qty 7 qts
washed batteries
add washer fluid
check inflate tires to spec..

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 30-JUN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Jun 30, 2022 8:20:06 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Jun 30, 2022 8:20:06 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RGASPARD	Jun 30, 2022 8:20:06 PM	No	
7 - Have you performed the proper LOTO?	Done		RGASPARD	Jun 30, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:20:06 PM		
10 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Jun 30, 2022 8:20:06 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jun 30, 2022 8:20:06 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55642054
Invoice No. 55345 - 55642054

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMB		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	285,990 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Jun-22	B329	FILTER, OIL, SPIN-ON SEE P550965	1	2.19	2.19

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Jun-22	Gaspard,Ronald	1.67	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 30-JUN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
20,800 - INSPECT_High Idle Control	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	Jun 30, 2022 9:39:02 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Jun 30, 2022 9:39:02 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
33,010 - CSF (Curb Side Front)	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	RGASPARD	Jun 30, 2022 9:39:02 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		RGASPARD	Jun 30, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression				9:39:02 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done	needs rear AC filter	RGASPARD	Jun 30, 2022 9:39:02 PM	Yes	55741420
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
50,400 - LUBE_All Chassis Components	Done	na	RGASPARD	Jun 30, 2022 9:39:02 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	38 Inch		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	38 Inch		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Jun 30, 2022 9:39:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	4 32nds of an inch	needs rear brakes job.	RGASPARD	Jun 30, 2022 9:39:02 PM	Yes	55741420
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	4 32nds of an inch		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	13254 Cycles		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Jun 30, 2022 9:39:02 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	2.19
Labor:	0.00
Labor Hours:	1.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.19**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55642054
Invoice No. 55345 - 55642054

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMB
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 285,990 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Jun-22	Gaspard,Ronald	0.48	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: RGASPARD Performed on: 30-JUN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jun 30, 2022 10:02:11 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jun 30, 2022 10:02:11 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jun 30, 2022 10:02:11 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jun 30, 2022 10:02:11 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Jun 30, 2022 10:02:11 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jun 30, 2022 10:02:11 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Jun 30, 2022 10:02:11 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jun 30, 2022 10:02:11 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Jun 30, 2022 10:02:11 PM	No	
201,000 - Service Crankcase Breather	Done		RGASPARD	Jun 30, 2022 10:02:11 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Jun 30, 2022 10:02:11 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Jun 30, 2022 10:02:11 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Jun 30, 2022 10:02:11 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55642054 Total	
Parts:	2.19
Labor:	0.00
Labor Hours:	2.15
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.19**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55741420
Invoice No. 55345 - 55741420

Client Department:

Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	285,990 - DH

Chronology		
Reported	Jun 30, 2022 9:49:52 PM	Jun 30, 2022 9:49:52 PM
Started	Jun 30, 2022 9:51:00 PM	
Completed	Jul 1, 2022 12:30:00 AM	Jul 1, 2022 12:30:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========
To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.
==========

Complaint:needs rear AC filter and rear brakes job

Cause: AC filter bad ,rear brakes low spec

Correction: replace AC filter , replace rear brake pads and lube guide pins
torque wheels 140 lbs second torque 140 lbs
part number 8C2Z-2200-B qty1

Activity Header
Activity: 10 001/001 AIR CONDITIONING
Activity Note: needs rear AC filter
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Jun-22	Gaspard,Ronald	0.48	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55741420
Invoice No. 55345 - 55741420

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP-FT Light Duty
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 285,990 - DH

Activity Header
Activity: 20 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: needs rear brakes job.
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Jul-22	8C2Z-2200-B	PADS, BRAKE, DISC, REAR, E450 SAME AS PFH133020	1	67.32	67.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Jul-22	Gaspard,Ronald	0.5	0	0
30-Jun-22	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	67.32
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**67.32**

Work Order Footer

Work Order 55741420 Total	
Parts:	67.32
Labor:	0.00
Labor Hours:	1.98
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**67.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55710024
Invoice No. 55345 - 55710024

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
inspect roof for damages		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	284,551 - DH

Chronology		
Reported	Jun 21, 2022 2:11:00 PM	Jun 21, 2022 2:11:00 PM
Started	Jun 21, 2022 2:15:00 PM	
Completed	Jun 21, 2022 3:40:00 PM	Jun 21, 2022 3:40:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: Roof top Hatch Damage

Cause: Damage

Correction: Replaced Roof top Hatch
part# 55-08792-003. Qty:1
part is not in system
please charge part----------

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 21-JUN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jun 21, 2022 3:39:29 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jun 21, 2022 3:39:29 PM	No	
4 - Are you wearing the appropriate PPE?	Done		TDELVA	Jun 21, 2022 3:39:29 PM	No	
7 - Have you performed the proper LOTO?	Done		TDELVA	Jun 21, 2022 3:39:29 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jun 21, 2022 3:39:29 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jun 21, 2022 3:39:29 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55710024
Invoice No. 55345 - 55710024

Client Department:
Department: 55345M
Work Order Description
inspect roof for damages
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 284,551 - DH

Activity Header
Activity: 15 002 CAB & SHEET METAL
Activity Note: inspect and repair roof area
Reason for Repair: 04 Driver's Report
Work Accomplished: 15 Paint Prep, & Repaint
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jun-22	Delva,Terry	1.4	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55710024 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55661583
Invoice No. 55345 - 55661583

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
check battery compatment		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	282,016 - DH

Chronology		
Reported	Jun 3, 2022 10:15:00 AM	Jun 3, 2022 10:15:00 AM
Started	Jun 3, 2022 11:27:00 AM	
Completed	Jun 3, 2022 12:13:00 PM	Jun 3, 2022 12:13:00 PM
Down Time		

Work Order Notes

Line 10 complaint. battery compartment door no lock

Cause. missing lock spring

Correction. installed new spring and adjust battery door.

part . shop supply

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 03-JUN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Jun 3, 2022 12:12:33 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Jun 3, 2022 12:12:33 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Jun 3, 2022 12:12:33 PM	No	
7 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Jun 3, 2022 12:12:33 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Jun 3, 2022 12:12:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Jun 3, 2022 12:12:33 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55661583
Invoice No. 55345 - 55661583

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
check battery compatment		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	282,016 - DH

Activity Header
Activity: 20 014/005/058 SLIDER, TRAY, BOX, BATTERY
Activity Note: CHECK BATTERY COMPARTMENT
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jun-22	Rodriguez,Raul	0.65	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55661583 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 55642020
Invoice No. 55345 - 55642020

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	281,196 - DH

Chronology		
Reported	May 26, 2022 10:58:27 PM	May 26, 2022 10:58:27 PM
Started	May 26, 2022 10:59:00 PM	
Completed	May 27, 2022 12:04:00 AM	May 27, 2022 12:04:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.

==========

To file warranty be sure to do the following:

1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:batteries tray lock not working

Cause: spring came off the latch

Correction:took off batteries and adjusted the spring

Activity Header
Activity:10 032/001/001 BATTERY
Activity Note: batteries tray lock broken
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-May-22	Gaspard,Ronald	0.47	0	0
27-May-22	Gaspard,Ronald	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55642020 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55537053
Invoice No. 55345 - 55537053

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	281,196 - DH

Chronology		
Reported	May 24, 2022 12:00:00 AM	May 24, 2022 12:00:00 AM
Started	May 26, 2022 3:45:00 PM	
Completed	May 26, 2022 11:32:00 PM	May 26, 2022 11:32:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA

CAUSE:Service

CORRECTION:Perform PMA Service
oil filter B329 qty1
engine oil 10w30 qty 7 qts
add washer fluid
wash batteries
check inflate tires to spec

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 26-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	May 26, 2022 9:29:54 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	May 26, 2022 9:29:54 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RGASPARD	May 26, 2022 9:29:54 PM	No	
7 - Have you performed the proper LOTO?	Done		RGASPARD	May 26, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:29:54 PM		
10 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	May 26, 2022 9:29:54 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	May 26, 2022 9:29:54 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55537053
Invoice No. 55345 - 55537053

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 281,196 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-May-22	B329	FILTER, OIL, SPIN-ON SEE P550965	1	2.14	2.14

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-May-22	Gaspard,Ronald	1.4	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 26-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
20,800 - INSPECT_High Idle Control	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	May 26, 2022 10:54:03 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	May 26, 2022 10:54:03 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	May 26, 2022 10:54:03 PM	No	
33,010 - CSF (Curb Side Front)	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done	batteries tray lock broken	RGASPARD	May 26, 2022 10:54:03 PM	Yes	55642020
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	RGASPARD	May 26, 2022 10:54:03 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
50,400 - LUBE_All Chassis Components	Done	na	RGASPARD	May 26, 2022 10:54:03 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	May 26, 2022 10:54:03 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	May 26, 2022 10:54:03 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	May 26, 2022 10:54:03 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	May 26, 2022 10:54:03 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings,	Done		RGASPARD	May 26, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Sensors, Routing of Cables				10:54:03 PM		
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	May 26, 2022 10:54:03 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	May 26, 2022 10:54:03 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	38 Inch		RGASPARD	May 26, 2022 10:54:03 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	38 Inch		RGASPARD	May 26, 2022 10:54:03 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	May 26, 2022 10:54:03 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	May 26, 2022 10:54:03 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	May 26, 2022 10:54:03 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	May 26, 2022 10:54:03 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	May 26, 2022 10:54:03 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	May 26, 2022 10:54:03 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	May 26, 2022 10:54:03 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	May 26, 2022 10:54:03 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	May 26, 2022 10:54:03 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	May 26, 2022 10:54:03 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	May 26, 2022 10:54:03 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	May 26, 2022 10:54:03 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	13143 Cycles		RGASPARD	May 26, 2022 10:54:03 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	May 26, 2022 10:54:03 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	2.14
Labor:	0.00
Labor Hours:	1.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.14**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55537053
Invoice No. 55345 - 55537053

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 281,196 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-May-22	Gaspard,Ronald	0.62	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 26-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	May 26, 2022 10:55:31 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	May 26, 2022 10:55:31 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	May 26, 2022 10:55:31 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	May 26, 2022 10:55:31 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	May 26, 2022 10:55:31 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	May 26, 2022 10:55:31 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	May 26, 2022 10:55:31 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	May 26, 2022 10:55:31 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.62
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 55537053 Total	
Parts:	2.14
Labor:	0.00
Labor Hours:	2.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.14**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55638654
Invoice No. 55345 - 55638654

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Door Handle)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 280,980 - DH

Chronology		
Reported	May 25, 2022 8:59:00 PM	May 25, 2022 8:59:00 PM
Started	May 25, 2022 9:00:00 PM	
Completed	May 25, 2022 10:43:00 PM	May 25, 2022 10:43:00 PM
Down Time		

Work Order Notes

Line 10 needs lift door handle
broken
replace lif door handle and adjust the latch
lart number 4940268 qty1

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 25-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	May 25, 2022 9:46:12 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	May 25, 2022 9:46:12 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RGASPARD	May 25, 2022 9:46:12 PM	No	
7 - Have you performed the proper LOTO?	Done		RGASPARD	May 25, 2022 9:46:12 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	May 25, 2022 9:46:12 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	May 25, 2022 9:46:12 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55638654
Invoice No. 55345 - 55638654

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Door Handle)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 280,980 - DH

Activity Header
Activity: 20 174/011/000 COMPONENTS, DOOR, ENTRANCE, OPENING, OUTWARD, BUS
Activity Note: Check Door Handle
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-May-22	4940268	HANDLE, DOOR, W/C, RH	1	63.82	63.82

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-May-22	Gaspard,Ronald	0.93	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	63.82
Labor:	0.00
Labor Hours:	0.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**63.82**

Work Order Footer

Work Order 55638654 Total	
Parts:	63.82
Labor:	0.00
Labor Hours:	0.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**63.82**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55609411
Invoice No. 55345 - 55609411

Client Department:
Department: 55345M
Work Order Description
WHEEL CHAIR LIFT NOT WORKING
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 279,435 - DH

Chronology		
Reported	May 16, 2022 8:05:00 AM	May 16, 2022 8:05:00 AM
Started	May 16, 2022 8:51:00 AM	
Completed	May 16, 2022 12:23:00 PM	May 16, 2022 12:23:00 PM
Down Time		

Work Order Notes

Line 10 wheel chair lift not working

harness rollstop broken

replace harness rollstop and adjusted the lift completed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 16-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	May 16, 2022 12:23:31 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	May 16, 2022 12:23:31 PM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	May 16, 2022 12:23:31 PM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	May 16, 2022 12:23:31 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	May 16, 2022 12:23:31 PM	No	
11 - Have you successfully completed the Personal	Done		HPIERRE	May 16, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				12:23:31 PM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55609411
Invoice No. 55345 - 55609411

Client Department:
Department: 55345M
Work Order Description
WHEEL CHAIR LIFT NOT WORKING
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 279,435 - DH

Activity Header
Activity: 20 055/023/000 LIFT, WHEELCHAIR, PASSENGER
Activity Note: CHECK WHEEL CHAIR LIFT FOR PROPER OPERATION
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-May-22	33775AKS	HARNESS, ROLL, STOP, W/C, BRAUN	1	53.37	53.37

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-May-22	Pierre,Hubert J	3.32	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	53.37
Labor:	0.00
Labor Hours:	3.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**53.37**

Work Order Footer

Work Order 55609411 Total	
Parts:	53.37
Labor:	0.00
Labor Hours:	3.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**53.37**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 5

Work Order No. 55543138
Invoice No. 55345 - 55543138

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PER DRIVER BUS PULLING		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	276,301 - DH

Chronology		
Reported	Apr 22, 2022 7:36:00 AM	Apr 22, 2022 7:36:00 AM
Started	Apr 22, 2022 9:45:00 AM	
Completed	May 3, 2022 1:18:30 PM	May 3, 2022 1:18:30 PM
Down Time		

Work Order Notes

Line 10 Complaint: Bus pulling

cause: Defective left front Ball joints

Correction: Replaced left front upper and lower ball joints..
please charge part #8C2Z-3050-A. Line 20 replace the inner lh right inner and both outer tie rod completed

done by HUbert Line 30 TECHNICIAN REPLACED INNER AND OUTER TIE ROD ENDS CENTER AND DRAG LINK THEN UNIT WAS SENT TO ELPEX GOOD YEAR ,THE PIVOT BUSHINGS WERE REPLACED AND WHEEL ALIGNAMENT PERFORMED .

UNIT RETURNED TO SERVICE.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: KIVEY Performed on: 03-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		KIVEY	May 3, 2022 1:18:23 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		KIVEY	May 3, 2022 1:18:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
4 - Are you wearing the appropriate PPE?	Done		KIVEY	May 3, 2022 1:18:23 PM	No	
7 - Have you performed the proper LOTO?	Done		KIVEY	May 3, 2022 1:18:23 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		KIVEY	May 3, 2022 1:18:23 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		KIVEY	May 3, 2022 1:18:23 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 5

Work Order No. 55543138
Invoice No. 55345 - 55543138

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PER DRIVER BUS PULLING		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	276,301 - DH

Activity Header
Activity:20
Activity Note: VERIFY COMPLAINT
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Apr-22	Delva,Terry	2.67	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 5

Work Order No. 55543138
Invoice No. 55345 - 55543138

Client Department:
Department: 55345M
Work Order Description
PER DRIVER BUS PULLING
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 276,301 - DH

Activity Header
Activity: 30 016/000/000 SUSPENSION
Activity Note: ball joints
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Apr-22	8C2Z-3050-A	JOINT, BALL, LOWER	1	42.9	42.9
22-Apr-22	8C3Z-3049-B	JOINT, BALL, UPPER	1	35.8	35.8

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Apr-22	Delva,Terry	0.88	0	0
22-Apr-22	Delva,Terry	2.62	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	78.70
Labor:	0.00
Labor Hours:	3.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**78.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 5

Work Order No. 55543138
Invoice No. 55345 - 55543138

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PER DRIVER BUS PULLING		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	276,301 - DH

Activity Header
Activity: 40 015/004/045 TIE-ROD, STEERING
Activity Note: DRAG LINK ,INNER AND OUTER TIRE ROD ENDS REPLACEMENT
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Apr-22	8C2Z-3A131-D	END, TIE-ROD, OUTER, RH, ECONOLINE	1	40.27	40.27

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Apr-22	Pierre,Hubert J	3.42	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	40.27
Labor:	0.00
Labor Hours:	3.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**40.27**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 5

Work Order No. 55543138
Invoice No. 55345 - 55543138

Client Department:
Department: 55345M
Work Order Description
PER DRIVER BUS PULLING
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 276,301 - DH

Activity Header
Activity: 50 015/004 LINKAGE, STEERING
Activity Note: WHEEL ALIGNAMENT performed by elpex good year
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Apr-22	8C2Z-3304-C	LINK, DRAG, STEERING	1	78.8	78.8
26-Apr-22	DSP-OUTSIDESERV	DIRECT PURCHASE FOR OUTSIDE SERV GL54354	1	507.59	507.59
25-Apr-22	8C2Z-3A131-C	TIE-ROD, OUTER, LH	1	38.5	38.5
26-Apr-22	8C2Z-3A131-C	TIE-ROD, OUTER, LH	-1	38.5	-38.5
25-Apr-22	8C2Z-3A130-D	END, TIE-ROD, INNER, LH	1	44.78	44.78

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 50 Sub Total	
Parts:	669.67
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**669.67**

Work Order Footer

Work Order 55543138 Total	
Parts:	788.64
Labor:	0.00
Labor Hours:	9.59
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**788.64**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55556708
Invoice No. 55345 - 55556708

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Wheelchair Lift issue		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	276,639 - DH

Chronology		
Reported	Apr 27, 2022 10:20:00 AM	Apr 27, 2022 10:20:00 AM
Started	Apr 27, 2022 12:41:00 PM	
Completed	Apr 29, 2022 12:18:00 PM	Apr 29, 2022 12:18:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Vehicle came in for lift issue

Cause: unknown

Correction: check lift and could not duplicate the issue return Vehicle back to work

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 29-APR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Apr 29, 2022 12:17:34 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		JUHURST	Apr 29, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				12:17:34 PM		
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Apr 29, 2022 12:17:34 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Apr 29, 2022 12:17:34 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Apr 29, 2022 12:17:34 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Apr 29, 2022 12:17:34 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55556708
Invoice No. 55345 - 55556708

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Wheelchair Lift issue		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	276,639 - DH

Activity Header
Activity: 20 055/023/000 LIFT, WHEELCHAIR, PASSENGER
Activity Note: CHECK WHEEL CHAIR LIFT FOR PROPER OPERATION
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Apr-22	33659KS	PENDANT, CONTROL, W/C, BRAUN	1	184.89	184.89

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Apr-22	Junior Hurst	2.18	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	184.89
Labor:	0.00
Labor Hours:	2.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**184.89**

Work Order Footer

Work Order 55556708 Total	
Parts:	184.89
Labor:	0.00
Labor Hours:	2.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**184.89**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55534813
Invoice No. 55345 - 55534813

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	276,300 - DH

Chronology		
Reported	Apr 19, 2022 1:54:05 PM	Apr 19, 2022 1:54:05 PM
Started	Apr 19, 2022 3:45:00 PM	
Completed	Apr 20, 2022 3:18:00 PM	Apr 20, 2022 3:18:00 PM
Down Time		

Work Order Notes

Line 10 Replaced front brakes
fix WC lift
replaced wc lift rubber bumper
replaced 1 ignition coild an spark plug
replaced interior amber light (3)-----(shop supply)

Activity Header
Activity: 10 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: Front Brakes
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Apr-22	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	46.46	46.46

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Apr-22	Delva,Terry	1.27	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	46.46
Labor:	0.00
Labor Hours:	1.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**46.46**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55534813
Invoice No. 55345 - 55534813

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	276,300 - DH

Activity Header
Activity: 20 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Misfire
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Apr-22	DG508	COIL, IGNITION SAME AS 3W7Z-12029-AA	1	65.89	65.89
20-Apr-22	AP103	PLUG, SPARK	1	3.5	3.5

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Apr-22	Delva,Terry	1.9	0	0
20-Apr-22	Delva,Terry	0.02	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	69.39
Labor:	0.00
Labor Hours:	1.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**69.39**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55534813
Invoice No. 55345 - 55534813

Client Department:

Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	276,300 - DH

Activity Header
Activity: 30 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: lift no power
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Apr-22	32408	BUMPER, RUBBER, W/C, BRAUN SAME AS 32408-10KS	2	2	4

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Apr-22	Delva,Terry	1.5666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	4.00
Labor:	0.00
Labor Hours:	1.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.00**

Work Order Footer

Work Order 55534813 Total	
Parts:	119.85
Labor:	0.00
Labor Hours:	4.76
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**119.85**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55235317
Invoice No. 55345 - 55235317

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	276,300 - DH

Chronology		
Reported	Apr 15, 2022 12:00:00 AM	Apr 15, 2022 12:00:00 AM
Started	Apr 19, 2022 9:32:00 AM	
Completed	Apr 20, 2022 9:48:00 AM	Apr 20, 2022 9:48:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA

CAUSE: service due

CORRECTION: Performed and completed PMA

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 19-APR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Apr 19, 2022 1:38:27 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Apr 19, 2022 1:38:27 PM	No	
4 - Are you wearing the appropriate PPE?	Done		TDELVA	Apr 19, 2022 1:38:27 PM	No	
7 - Have you performed the proper LOTO?	Done		TDELVA	Apr 19, 2022 1:38:27 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Apr 19, 2022 1:38:27 PM	No	
11 - Have you successfully completed the Personal	Done		TDELVA	Apr 19, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				1:38:27 PM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55235317
Invoice No. 55345 - 55235317

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	276,300 - DH

Activity Header
Activity: 10
Activity Note: Light Duty PMI
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Apr-22	B329	FILTER, OIL, SPIN-ON SEE P550965	1	1.99	1.99

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Apr-22	Delva,Terry	1.22	0	0
19-Apr-22	Delva,Terry	0.92	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: TDELVA Performed on: 19-APR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
20,800 - INSPECT_High Idle Control	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
31,000 - SSF (Street Side Front)	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,030 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
32,000 - Engine Inspection	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	TDELVA	Apr 19, 2022 1:53:54 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
32,100 - INSPECT_Intake System	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	Volt*	na	TDELVA	Apr 19, 2022 1:53:54 PM	No	
33,010 - CSF (Curb Side Front)	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	13.89 Volt*		TDELVA	Apr 19, 2022 1:53:54 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	14 Volt*		TDELVA	Apr 19, 2022 1:53:54 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory	Done		TDELVA	Apr 19, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Forms Dates				1:53:54 PM		
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
50,400 - LUBE_All Chassis Components	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
50,700 - INSPECT_Tire Condition	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	11 32nds of an inch		TDELVA	Apr 19, 2022 1:53:54 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		TDELVA	Apr 19, 2022 1:53:54 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	11 32nds of an inch		TDELVA	Apr 19, 2022 1:53:54 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		TDELVA	Apr 19, 2022 1:53:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	3 32nds of an inch	Front Brakes	TDELVA	Apr 19, 2022 1:53:54 PM	Yes	55534813
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch		TDELVA	Apr 19, 2022 1:53:54 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	36.5 Inch		TDELVA	Apr 19, 2022 1:53:54 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	36.3 Inch		TDELVA	Apr 19, 2022 1:53:54 PM	No	
52,100 - INSPECT_Vibration Damper	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
53,600 - INSPECT_Tire Condition	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	-	na	TDELVA	Apr 19, 2022 1:53:54 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		TDELVA	Apr 19, 2022 1:53:54 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		TDELVA	Apr 19, 2022 1:53:54 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		TDELVA	Apr 19, 2022 1:53:54 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		TDELVA	Apr 19, 2022 1:53:54 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		TDELVA	Apr 19, 2022 1:53:54 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		TDELVA	Apr 19, 2022 1:53:54 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		TDELVA	Apr 19, 2022 1:53:54 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		TDELVA	Apr 19, 2022 1:53:54 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	Apr 19, 2022 1:53:54 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	Apr 19, 2022 1:53:54 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	35.6 Inch		TDELVA	Apr 19, 2022 1:53:54 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	35.6 Inch		TDELVA	Apr 19, 2022 1:53:54 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	0 Cycles		TDELVA	Apr 19, 2022 1:53:54 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth	Done		TDELVA	Apr 19, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Rotation				1:53:54 PM		
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
62,400 - INSPECT_All Pivot Points	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
62,500 - INSPECT_Cams and Slots	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
62,600 - INSPECT_Rollers	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
62,700 - INSPECT_All Linkages	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		TDELVA	Apr 19, 2022 1:53:54 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.99
Labor:	0.00
Labor Hours:	2.14
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.99**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55235317
Invoice No. 55345 - 55235317

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	276,300 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Apr-22	Delva,Terry	0.98	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: TDELVA Performed on: 19-APR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		TDELVA	Apr 19, 2022 1:37:48 PM	No	
101,000 - FRA Change Oil Filters	No		TDELVA	Apr 19, 2022 1:37:48 PM	No	
102,000 - FRA Drain Engine Oil	No		TDELVA	Apr 19, 2022 1:37:48 PM	No	
103,000 - FRA Check Transmission Fluid	Done		TDELVA	Apr 19, 2022 1:37:48 PM	No	
104,000 - Lubricate Chassis	Done		TDELVA	Apr 19, 2022 1:37:48 PM	No	
105,000 - Replace or Clean A/C Filters	Done		TDELVA	Apr 19, 2022 1:37:48 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	TDELVA	Apr 19, 2022 1:37:48 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		TDELVA	Apr 19, 2022 1:37:48 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.98
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 55235317 Total	
Parts:	1.99
Labor:	0.00
Labor Hours:	3.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.99**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55486866
Invoice No. 55345 - 55486866

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
WC lift malfunction.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	273,579 - DH

Chronology		
Reported	Apr 3, 2022 11:17:14 AM	Apr 3, 2022 11:17:14 AM
Started	Apr 3, 2022 11:21:00 AM	
Completed	Apr 3, 2022 5:32:00 PM	Apr 3, 2022 5:32:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: WC lift malfunction.

Cause: Roll stop not operating properly.

Correction: Remove and replaced 1 rollstop gas spring.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 03-APR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Apr 3, 2022 1:49:49 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		EARJOHNSON	Apr 3, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				1:49:49 PM		
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Apr 3, 2022 1:49:49 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Apr 3, 2022 1:49:49 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Apr 3, 2022 1:49:49 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Apr 3, 2022 1:49:49 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55486866
Invoice No. 55345 - 55486866

Client Department:
Department: 55345M
Work Order Description
WC lift malfunction.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 273,579 - DH

Activity Header
Activity: 15 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: WC lift malfunction.
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Apr-22	32831	SPRING, SHOCK, GAS, W/C	1	27.26	27.26

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Apr-22	Earl Johnson	1.1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	27.26
Labor:	0.00
Labor Hours:	1.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**27.26**

Work Order Footer

Work Order 55486866 Total	
Parts:	27.26
Labor:	0.00
Labor Hours:	1.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**27.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55479531
Invoice No. 55345 - 55479531

Client Department:
Department: 55345M
Work Order Description
Drive Ability (Test Drive Of MisFire)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 273,053 - DH

Chronology		
Reported	Mar 30, 2022 11:26:00 PM	Mar 30, 2022 11:26:00 PM
Started	Mar 30, 2022 11:27:00 PM	
Completed	Mar 31, 2022 10:45:00 AM	Mar 31, 2022 10:45:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Misfire.

Cause: TBD.

Correction: Road tested vehicle without any issues. No Check engine light illuminated. Will monitor.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 31-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Mar 31, 2022 12:32:02 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Mar 31, 2022 12:32:02 AM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Mar 31, 2022 12:32:02 AM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Mar 31, 2022 12:32:02 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Mar 31, 2022 12:32:02 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Mar 31, 2022 12:32:02 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55479531
Invoice No. 55345 - 55479531

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Drive Ability (Test Drive Of MisFire)		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	273,053 - DH

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Test Drive For MisFire
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55479531 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 55240825
Invoice No. 55345 - 55240825

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
per driver bus shakes		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	271,396 - DH

Chronology		
Reported	Mar 10, 2022 3:00:00 PM	Mar 10, 2022 3:00:00 PM
Started	Mar 10, 2022 3:00:00 PM	
Completed	Mar 11, 2022 12:33:00 PM	Mar 11, 2022 12:33:00 PM
Down Time		

Work Order Notes

Line 30 ROAD CALL VEHICLE CAME IN FOR FRONT AND REAR A/ C NOT WORKING Line 40 front and rear A/C not working

front a/c was going on in of
front a/c was low on freon rear a/c was working properly
vacuum and recharge performed leaking test vehicle passed it
Mount and balance 2 front tires completed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 07-JAN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Jan 7, 2022 10:01:57 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Jan 7, 2022 10:01:57 AM	No	
4 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Jan 7, 2022 10:01:57 AM	No	
7 - Have you performed the proper LOTO?	Done		JAPEREZ	Jan 7, 2022 10:01:57 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Jan 7, 2022 10:01:57 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Jan 7, 2022 10:01:57 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 55240825
Invoice No. 55345 - 55240825

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
per driver bus shakes		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	271,396 - DH

Activity Header
Activity: 20 045/007/000 HEAD, CYLINDER
Activity Note: PER DRIVER VEHICLE SHAKES
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Mar-22	Junior Hurst	1.35	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 55240825
Invoice No. 55345 - 55240825

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
per driver bus shakes		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	271,396 - DH

Activity Header
Activity: 30 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: CHECK FRONT AND REAR AC
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Mar-22	Pierre,Hubert J	1.27	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 55240825
Invoice No. 55345 - 55240825

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
per driver bus shakes		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	271,396 - DH

Activity Header
Activity:40 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Mar-22	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	135.26	270.52

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	270.52
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**270.52**

Work Order Footer

Work Order 55240825 Total	
Parts:	270.52
Labor:	0.00
Labor Hours:	2.62
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**270.52**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55398176
Invoice No. 55345 - 55398176

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Perform Tire Inspection		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	99 - Cancelled (99)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	272,200 - DH

Chronology		
Reported	Mar 2, 2022 6:02:00 PM	Mar 2, 2022 6:02:00 PM
Started	Mar 2, 2022 6:03:00 PM	
Completed	Mar 2, 2022 7:02:46 PM	Mar 2, 2022 7:02:46 PM
Down Time		

Work Order Notes

Line 10
Complaint:

Cause:

Correction:

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	-				No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	-				No	
4 - Are you wearing the appropriate PPE?	-				No	
7 - Have you performed the proper LOTO?	-				No	
10 - Are you aware of the potential risks of performing	-				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
this repair?						
11 - Have you successfully completed the Personal Risk Assessment?	-				No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55398176
Invoice No. 55345 - 55398176

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Perform Tire Inspection		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	99 - Cancelled (99)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	272,200 - DH

Activity Header
Activity: 20 017/001/000 TIRE, PNEUMATIC
Activity Note: FRONT TIRES
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Mar-22	Arthurs,Durvin	0.35	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55398176
Invoice No. 55345 - 55398176

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Perform Tire Inspection		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	99 - Cancelled (99)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	272,200 - DH

Activity Header
Activity: 30 017/001/000 TIRE, PNEUMATIC
Activity Note: REAR TIRES
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55398176 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55278592
Invoice No. 55345 - 55278592

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
CHECK FUEL PUMP		Ford E450 Champion Challenger	
Requested By:	KIVEY	**Status:**	99 - Cancelled (99)
Created By:	KIVEY	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	272,200 - DH

Chronology		
Reported	Jan 21, 2022 9:03:00 AM	Jan 21, 2022 9:03:00 AM
Started		
Completed	Jan 21, 2022 9:11:19 AM	Jan 21, 2022 9:11:19 AM
Down Time		

Work Order Notes

Activity Header
Activity: 10 044/003/000 PUMP, FUEL
Activity Note: FUEL PUMP INOP
Reason for Repair: 01 Breakdown
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55278592
Invoice No. 55345 - 55278592

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
CHECK FUEL PUMP		Ford E450 Champion Challenger	
Requested By:	KIVEY	**Status:**	99 - Cancelled (99)
Created By:	KIVEY	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	272,200 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PRA
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	-				No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	-				No	
4 - Are you wearing the appropriate PPE?	-				No	
7 - Have you performed the proper LOTO?	-				No	
10 - Are you aware of the potential risks of performing this repair?	-				No	
11 - Have you successfully completed the Personal Risk Assessment?	-				No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55278592 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55231404
Invoice No. 55345 - 55231404

Client Department:
Department: 55345M
Work Order Description
driver step broke
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 271,395 - DH

Chronology		
Reported	Jan 4, 2022 9:28:00 AM	Jan 4, 2022 9:28:00 AM
Started	Jan 4, 2022 4:00:00 PM	
Completed	Jan 5, 2022 1:50:00 PM	Jan 5, 2022 1:50:00 PM
Down Time		

Work Order Notes

Line 10 Repair Driver Step..

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 04-JAN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jan 4, 2022 4:26:34 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jan 4, 2022 4:26:34 PM	No	
4 - Are you wearing the appropriate PPE?	Done		TDELVA	Jan 4, 2022 4:26:34 PM	No	
7 - Have you performed the proper LOTO?	Done		TDELVA	Jan 4, 2022 4:26:34 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jan 4, 2022 4:26:34 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jan 4, 2022 4:26:34 PM	No	

Activity Sub Total

Activity 10 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55231404
Invoice No. 55345 - 55231404

Client Department:
Department: 55345M
Work Order Description
driver step broke
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 271,395 - DH

Activity Header
Activity:20 174/000/000 BODY, BUS
Activity Note:
Reason for Repair: 41 Abuse of Equipment
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Jan-22	Delva,Terry	0.95	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55231404 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55098054
Invoice No. 55345 - 55098054

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMC		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	271,395 - DH

Chronology		
Reported	Dec 28, 2021 12:00:00 AM	Dec 28, 2021 12:00:00 AM
Started	Dec 29, 2021 7:31:00 AM	
Completed	Jan 5, 2022 11:34:00 AM	Jan 5, 2022 11:34:00 AM
Down Time		

Work Order Notes

Line 10 Complaint : PMC service

Cause: preventive maintnance

Correction: perform pmc service and lube ,transmission service,rear end ,replaced all 6 tires with 6 good used ones

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 29-DEC-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Dec 29, 2021 1:46:49 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Dec 29, 2021 1:46:49 PM	No	
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Dec 29, 2021 1:46:49 PM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Dec 29, 2021 1:46:49 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Dec 29, 2021 1:46:49 PM	No	
11 - Have you successfully completed the Personal	Done		NPIERRE-	Dec 29, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	1:46:49 PM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55098054
Invoice No. 55345 - 55098054

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMC
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 271,395 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Dec-21	40520	BLADE, WIPER, WINDSHIELD, 20"	2	4.4	8.8

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Dec-21	NELSON PIERRE-LOUIS	4.63	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS Performed on: 05-JAN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
20,800 - INSPECT_High Idle Control	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
21,100 - INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
21,700 - INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
31,000 - SSF (Street Side Front)	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
32,000 - Engine Inspection	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	0 Degree Fahrenheit		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
32,100 - INSPECT_Intake System	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	13.2 Volt*		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
33,010 - CSF (Curb Side Front)	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	13.1 Volt*		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		NPIERRE-	Jan 5, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression			LOUIS	10:24:37 AM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
50,400 - LUBE_All Chassis Components	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
50,700 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	67 Pounds per Square Inch		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	33.5 Inch		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	33.5 Inch		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
52,100 - INSPECT_Vibration Damper	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
53,600 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	69 Pounds per Square Inch		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	67 Pounds per Square Inch		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	68 Pounds per Square Inch		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	69 Pounds per Square Inch		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	29.5 Inch		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	29.5 Inch		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
60,100 - RECORD_Wheelchair Cycle Count	0 Cycles		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper	Done		NPIERRE-	Jan 5, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alignment			LOUIS	10:24:37 AM		
61,000 - INSPECT_Cable Condition (If Applicable)	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
62,400 - INSPECT_All Pivot Points	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
62,500 - INSPECT_Cams and Slots	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
62,600 - INSPECT_Rollers	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
62,700 - INSPECT_All Linkages	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,000 - SECTION 8 - PMI Report Completion	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	Jan 5, 2022 10:24:37 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	8.80
Labor:	0.00
Labor Hours:	4.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55098054
Invoice No. 55345 - 55098054

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMC
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 271,395 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Dec-21	B7449	FILTER, OIL, SPIN-ON SEE P577066	1	2.73	2.73
29-Dec-21	20021	FILTER, TRANSMISSION 20021	1	17.44	17.44

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: NPIERRE-LOUIS Performed on: 29-DEC-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Dec 29, 2021 1:47:40 PM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Dec 29, 2021 1:47:40 PM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Dec 29, 2021 1:47:40 PM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Dec 29, 2021 1:47:40 PM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Dec 29, 2021 1:47:40 PM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Dec 29, 2021 1:47:40 PM	No	
107,000 - FRA Change Primary Fuel Filter	Done		NPIERRE-LOUIS	Dec 29, 2021 1:47:40 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Dec 29, 2021 1:47:40 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		NPIERRE-LOUIS	Dec 29, 2021 1:47:40 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
201,000 - Service Crankcase Breather	Done		NPIERRE-LOUIS	Dec 29, 2021 1:47:40 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		NPIERRE-LOUIS	Dec 29, 2021 1:47:40 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	Yes		NPIERRE-LOUIS	Dec 29, 2021 1:47:40 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		NPIERRE-LOUIS	Dec 29, 2021 1:47:40 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		NPIERRE-LOUIS	Dec 29, 2021 1:47:40 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		NPIERRE-LOUIS	Dec 29, 2021 1:47:40 PM	No	
302,000 - Check Toe-In and Record Reading	Done		NPIERRE-LOUIS	Dec 29, 2021 1:47:40 PM	No	
302,001 - Record Toe-In Reading	0 Inches, fraction-actual		NPIERRE-LOUIS	Dec 29, 2021 1:47:40 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	Yes		NPIERRE-LOUIS	Dec 29, 2021 1:47:40 PM	No	
305,000 - FRA Change Differential Fluid	Yes		NPIERRE-LOUIS	Dec 29, 2021 1:47:40 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	20.17
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**20.17**

Work Order Footer

Work Order 55098054 Total	
Parts:	28.97
Labor:	0.00
Labor Hours:	4.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**28.97**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55095291
Invoice No. 55345 - 55095291

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
DAMAGES BY TRANSIT DOOR		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	270,755 - DH

Chronology		
Reported	Nov 16, 2021 7:51:00 AM	Nov 16, 2021 7:51:00 AM
Started	Dec 31, 2021 12:00:00 AM	
Completed	Dec 31, 2021 11:28:00 AM	Dec 31, 2021 11:28:00 AM
Down Time		

Work Order Notes

Line 10 Complaint. DAMAGES BY TRANSIT DOOR

Cause. Unnokw

Correction. Fixed with body filler.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 31-DEC-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Dec 31, 2021 11:20:51 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Dec 31, 2021 11:20:51 AM	No	
4 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Dec 31, 2021 11:20:51 AM	No	
7 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Dec 31, 2021 11:20:51 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Dec 31, 2021 11:20:51 AM	No	
11 - Have you successfully completed the	Done		RAURODRIGUEZ	Dec 31, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				11:20:51 AM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55095291
Invoice No. 55345 - 55095291

Client Department:
Department: 55345M
Work Order Description
DAMAGES BY TRANSIT DOOR
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 270,755 - DH

Activity Header
Activity:20 174/000/000 BODY, BUS
Activity Note:
Reason for Repair: 41 Abuse of Equipment
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Dec-21	Rodriguez,Raul	4.0166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	4.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55095291 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	4.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55210403
Invoice No. 55345 - 55210403

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Road call lift not working		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	270,531 - DH

Chronology		
Reported	Dec 23, 2021 6:52:58 AM	Dec 23, 2021 6:52:58 AM
Started	Dec 23, 2021 12:33:00 PM	
Completed	Dec 23, 2021 1:46:00 PM	Dec 23, 2021 1:46:00 PM
Down Time		

Work Order Notes

Line 10 Road call lift not working

No power in it

Fix the lift completed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 23-DEC-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Dec 23, 2021 1:20:58 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Dec 23, 2021 1:20:58 PM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Dec 23, 2021 1:20:58 PM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Dec 23, 2021 1:20:58 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Dec 23, 2021 1:20:58 PM	No	
11 - Have you successfully completed the Personal	Done		HPIERRE	Dec 23, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				1:20:58 PM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55210403
Invoice No. 55345 - 55210403

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Road call lift not working		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	270,531 - DH

Activity Header
Activity: 20 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: WheelChair Lift
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Dec-21	Pierre,Hubert J	1.2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55210403 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55137595
Invoice No. 55345 - 55137595

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Rear Bumper		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	267,000 - DH

Chronology		
Reported	Dec 1, 2021 10:32:41 AM	Dec 1, 2021 10:32:41 AM
Started	Dec 1, 2021 10:33:00 AM	
Completed	Dec 1, 2021 3:34:00 PM	Dec 1, 2021 3:34:00 PM
Down Time		

Work Order Notes

Line 10 Repair rear bumper¿

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 01-DEC-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Dec 1, 2021 11:44:02 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Dec 1, 2021 11:44:02 AM	No	
4 - Are you wearing the appropriate PPE?	Done		TDELVA	Dec 1, 2021 11:44:02 AM	No	
7 - Have you performed the proper LOTO?	Done		TDELVA	Dec 1, 2021 11:44:02 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Dec 1, 2021 11:44:02 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Dec 1, 2021 11:44:02 AM	No	

Activity Sub Total

Activity 10 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55137595
Invoice No. 55345 - 55137595

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Rear Bumper		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	267,000 - DH

Activity Header
Activity:20
Activity Note: VERIFY COMPLAINT
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Dec-21	Delva,Terry	1.18	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55137595 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54870759
Invoice No. 55345 - 54870759

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	266,587 - DH

Chronology		
Reported	Nov 16, 2021 12:00:00 AM	Nov 16, 2021 12:00:00 AM
Started	Nov 16, 2021 2:11:00 PM	
Completed	Nov 16, 2021 4:45:00 PM	Nov 16, 2021 4:45:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Vehicle came in for service

CAUSE: Service by miles

CORRECTION: Job complete also oil filter replace part B329 return vehicle back to work

Activity Header

Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Nov-21	Junior Hurst	0.03	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 16-NOV-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Nov 16, 2021 2:11:51 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Nov 16, 2021 2:11:51 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Nov 16, 2021 2:11:51 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Nov 16, 2021 2:11:51 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Nov 16, 2021 2:11:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Nov 16, 2021 2:11:51 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54870759
Invoice No. 55345 - 54870759

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 266,587 - DH

Activity Header
Activity: 10 020 GROUP, DRIVETRAIN
Activity Note: Light Duty PMI
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Nov-21	Junior Hurst	2.23	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: JUHURST Performed on: 16-NOV-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Nov 16, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				4:25:07 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
20,800 - INSPECT_High Idle Control	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
32,000 - Engine Inspection	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Nov 16, 2021 4:25:07 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Nov 16, 2021 4:25:07 PM	No	
33,010 - CSF (Curb Side Front)	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	14 Volt*		JUHURST	Nov 16, 2021 4:25:07 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		JUHURST	Nov 16, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression				4:25:07 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
50,400 - LUBE_All Chassis Components	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
50,700 - INSPECT_Tire Condition	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Nov 16, 2021 4:25:07 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Nov 16, 2021 4:25:07 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Nov 16, 2021 4:25:07 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Nov 16, 2021 4:25:07 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Nov 16, 2021 4:25:07 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Nov 16, 2021 4:25:07 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.2299 Inch		JUHURST	Nov 16, 2021 4:25:07 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.2299 Inch		JUHURST	Nov 16, 2021 4:25:07 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Nov 16, 2021 4:25:07 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Nov 16, 2021 4:25:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Nov 16, 2021 4:25:07 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Nov 16, 2021 4:25:07 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Nov 16, 2021 4:25:07 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Nov 16, 2021 4:25:07 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Nov 16, 2021 4:25:07 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Nov 16, 2021 4:25:07 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		JUHURST	Nov 16, 2021 4:25:07 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		JUHURST	Nov 16, 2021 4:25:07 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	1.299 Inch		JUHURST	Nov 16, 2021 4:25:07 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	1.299 Inch		JUHURST	Nov 16, 2021 4:25:07 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	12620 Cycles		JUHURST	Nov 16, 2021 4:25:07 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper	Done		JUHURST	Nov 16, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alignment				4:25:07 PM		
61,000 - INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
62,400 - INSPECT_All Pivot Points	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
62,500 - INSPECT_Cams and Slots	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
62,600 - INSPECT_Rollers	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
62,700 - INSPECT_All Linkages	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	Nov 16, 2021 4:25:07 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54870759
Invoice No. 55345 - 54870759

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 266,587 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Nov-21	B329	FILTER, OIL, SPIN-ON SEE P550965	1	2.06	2.06

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: JUHURST Performed on: 16-NOV-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		JUHURST	Nov 16, 2021 4:38:13 PM	No	
101,000 - FRA Change Oil Filters	Yes		JUHURST	Nov 16, 2021 4:38:13 PM	No	
102,000 - FRA Drain Engine Oil	Yes		JUHURST	Nov 16, 2021 4:38:13 PM	No	
103,000 - FRA Check Transmission Fluid	Done		JUHURST	Nov 16, 2021 4:38:13 PM	No	
104,000 - Lubricate Chassis	Done		JUHURST	Nov 16, 2021 4:38:13 PM	No	
105,000 - Replace or Clean A/C Filters	Done		JUHURST	Nov 16, 2021 4:38:13 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		JUHURST	Nov 16, 2021 4:38:13 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		JUHURST	Nov 16, 2021 4:38:13 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	2.06
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**2.06**

Work Order Footer

Work Order 54870759 Total	
Parts:	2.06
Labor:	0.00
Labor Hours:	2.26
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.06**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55013591
Invoice No. 55345 - 55013591

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Rear AC malfunction.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	262,953 - DH

Chronology		
Reported	Oct 21, 2021 11:46:29 PM	Oct 21, 2021 11:46:29 PM
Started	Oct 21, 2021 11:47:00 PM	
Completed	Oct 27, 2021 11:33:00 PM	Oct 27, 2021 11:33:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:***VOID***

Cause:

Correction:

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 27-OCT-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Oct 27, 2021 11:33:46 PM	No	
2 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Oct 27, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				11:33:46 PM		
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Oct 27, 2021 11:33:46 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Oct 27, 2021 11:33:46 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Oct 27, 2021 11:33:46 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Oct 27, 2021 11:33:46 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55013591
Invoice No. 55345 - 55013591

Client Department:
Department: 55345M
Work Order Description
Rear AC malfunction.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 262,953 - DH

Activity Header
Activity: 15 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear AC malfunction.
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 51 Inoperative
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Oct-21	Earl Johnson	0.6	0	0
21-Oct-21	Earl Johnson	0.22	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.82
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55013591 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.82
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54894330
Invoice No. 55345 - 54894330

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
ENGINE CYLINDER HEADS		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	262,891 - DH

Chronology		
Reported	Sep 13, 2021 11:33:00 AM	Sep 13, 2021 11:33:00 AM
Started	Sep 13, 2021 11:36:00 AM	
Completed	Sep 28, 2021 8:10:00 AM	Sep 28, 2021 8:10:00 AM
Down Time		

Work Order Notes

Line 10 C: vehicle shakes

C: check computer system found codes for engine misfire on cylinders #2,#7,and #10 further test indicated that cylinders has low compression

C: remove and replace cylinder heads retest system and road test vehicle, engine has a shake due to low compression on cylinder #4

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 28-SEP-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Sep 28, 2021 8:09:34 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Sep 28, 2021 8:09:34 AM	No	
4 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Sep 28, 2021 8:09:34 AM	No	
7 - Have you performed the proper LOTO?	Done		JAPEREZ	Sep 28, 2021 8:09:34 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Sep 28, 2021 8:09:34 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Sep 28, 2021 8:09:34 AM	No	
20 - Miles			JAPEREZ	Sep 28, 2021 8:09:34 AM	No	
30 - Kilometers			JAPEREZ	Sep 28, 2021 8:09:34 AM	No	
40 - Hours			JAPEREZ	Sep 28, 2021 8:09:34 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54894330
Invoice No. 55345 - 54894330

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
ENGINE CYLINDER HEADS		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	262,891 - DH

Activity Header
Activity: 20 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: VERIFY COMPLAINT
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Sep-21	Perez,Javier	7.72	0	0
13-Sep-21	Perez,Javier	0.97	0	0
17-Sep-21	Perez,Javier	4.53	0	0
23-Sep-21	Perez,Javier	7.55	0	0
22-Sep-21	Perez,Javier	6.83	0	0
24-Sep-21	Perez,Javier	7.62	0	0
27-Sep-21	Perez,Javier	7.63	0	0
14-Sep-21	Perez,Javier	6.45	0	0
20-Sep-21	Perez,Javier	7.18	0	0
16-Sep-21	Perez,Javier	7.72	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	64.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54894330
Invoice No. 55345 - 54894330

Client Department:
Department: 55345M
Work Order Description
ENGINE CYLINDER HEADS
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 262,891 - DH

Activity Header
Activity: 30 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: CILYNDER HEADS REPLACEMENT
Reason for Repair: 39 Natural Causes
Work Accomplished: 04 Replace Rebuilt
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Sep-21	4C3Z-6051-AA	GASKET, HEAD, CYLINDER	1	43.16	43.16
30-Nov-23	W704593-S100	SEAL, O-RING	1	5.38	5.38
28-Sep-21	4C3Z-6051-BA	GASKET, HEAD, CYLINDER	1	43.95	43.95
28-Sep-21	F85Z-6K255-AA	ARM, TENSIONER, CHAIN, TIMING	1	14.26	14.26
28-Sep-21	W704593-S100	SEAL, O-RING	2	5.38	10.76
23-Sep-21	1L3Z-6L266-AA	TENSIONER, CHAIN, TIMING	1	26.86	26.86
28-Sep-21	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	21	21
23-Sep-21	4L3Z-6M256-AA	GUIDE, CHAIN, TIMING, RH	1	18.26	18.26
23-Sep-21	9C3Z-6049-F	HEAD, CYLINDER, 6.8L, CNG	1	827.4	827.4
28-Sep-21	2FKLP	HEAD, CYLINDER, REMANUFACTURED	1	505.09	505.09
28-Sep-21	F85Z-6M274-AA	ARM, TENSIONER, CHAIN, TIMMING, 5.4L	1	14.88	14.88
28-Sep-21	XL1Z-6L266-AA	TENSIONER, CHAIN, TIMING	1	27.15	27.15
23-Sep-21	SP-521	PLUG, SPARK, 5.4L, FORD	10	4.37	43.7
23-Sep-21	4C3Z-6051-BA	GASKET, HEAD, CYLINDER	1	43.95	43.95
28-Sep-21	2L1Z-6K297-AA	GUIDE, CHAIN, TIMING, LH	1	15.92	15.92

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	1,661.72
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00

	Sublet Labor:	0.00
	Activity Sub Total	**1,661.72**

Work Order Footer

Work Order 54894330 Total	
Parts:	1,661.72
Labor:	0.00
Labor Hours:	64.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1,661.72**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54880247
Invoice No. 55345 - 54880247

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Rear A/C		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	262,394 - DH

Chronology		
Reported	Sep 8, 2021 1:51:23 PM	Sep 8, 2021 1:51:23 PM
Started	Sep 8, 2021 1:53:00 PM	
Completed	Sep 8, 2021 5:28:00 PM	Sep 8, 2021 5:28:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: rear A/C

Cause: broken valve

Correction: Replace low side valve part# 11127540A also one office. 3411885 please charge out the part for me can¿t fine thank you return vehicle back to work

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Sep-21	Junior Hurst	0.02	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: JUHURST Performed on: 08-SEP-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Sep 8, 2021 5:23:52 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Sep 8, 2021 5:23:52 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Sep 8, 2021 5:23:52 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Sep 8, 2021 5:23:52 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Sep 8, 2021 5:23:52 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Sep 8, 2021 5:23:52 PM	No	
20 - Miles			JUHURST	Sep 8, 2021 5:23:52 PM	No	
30 - Kilometers			JUHURST	Sep 8, 2021 5:23:52 PM	No	
40 - Hours			JUHURST	Sep 8, 2021 5:23:52 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54880247
Invoice No. 55345 - 54880247

Client Department:
Department: 55345M
Work Order Description
Rear A/C
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 262,394 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear A/C
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Sep-21	Junior Hurst	3.45	0	0
08-Sep-21	Junior Hurst	0.02	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54880247 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.49
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 54870671
Invoice No. 55345 - 54870671

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	262,215 - DH

Chronology		
Reported	Sep 3, 2021 4:03:34 PM	Sep 3, 2021 4:03:34 PM
Started		
Completed	Sep 3, 2021 7:55:00 PM	Sep 3, 2021 7:55:00 PM
Down Time		

Work Order Notes

Activity Header
Activity: 10 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: rear brakes low need replaced l
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54870671 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 54870524
Invoice No. 55345 - 54870524

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	262,215 - DH

Chronology

Reported	Sep 3, 2021 3:36:12 PM	Sep 3, 2021 3:36:12 PM
Started	Sep 3, 2021 4:28:00 PM	
Completed	Sep 3, 2021 7:54:00 PM	Sep 3, 2021 7:54:00 PM
Down Time		

Work Order Notes

Line 10 Removed and replaced rear brakes part #8C2Z-2V200C also two set back pin part # BC2Z-2C150 -B after return vehicle back to work Please charge the part out for me the System won¿t allow me

Activity Header

Activity: 10 053/999/105 STRIPS, TEST, COOLANT
Activity Note:
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Sep-21	8C2Z-2V200-C	PADS, BRAKE, DISC, REAR	1	52.49	52.49

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Sep-21	Junior Hurst	3.28	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	52.49
Labor:	0.00
Labor Hours:	3.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**52.49**

Work Order Footer

Work Order 54870524 Total	
Parts:	52.49
Labor:	0.00
Labor Hours:	3.28
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**52.49**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54789085
Invoice No. 55345 - 54789085

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	262,215 - DH

Chronology		
Reported	Sep 3, 2021 12:00:00 AM	Sep 3, 2021 12:00:00 AM
Started	Sep 3, 2021 2:44:00 PM	
Completed	Sep 3, 2021 4:27:00 PM	Sep 3, 2021 4:27:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Vehicle came in for service

CAUSE: Service by miles

CORRECTION: replace drain plug and one oil filter. B329.

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Sep-21	Junior Hurst	0.07	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 03-SEP-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Sep 3, 2021 2:47:06 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Sep 3, 2021 2:47:06 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Sep 3, 2021 2:47:06 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Sep 3, 2021 2:47:06 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Sep 3, 2021 2:47:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Sep 3, 2021 2:47:06 PM	No	
20 - Miles			JUHURST	Sep 3, 2021 2:47:06 PM	No	
30 - Kilometers			JUHURST	Sep 3, 2021 2:47:06 PM	No	
40 - Hours			JUHURST	Sep 3, 2021 2:47:06 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54789085
Invoice No. 55345 - 54789085

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 262,215 - DH

Activity Header
Activity: 10
Activity Note: Light Duty PMI
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Sep-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.98	1.98
03-Sep-21	65266	PLUG, DRAIN, OIL, ENGINE	1	4.25	4.25

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Sep-21	Junior Hurst	1.28	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: JUHURST Performed on: 03-SEP-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until	Done		JUHURST	Sep 3, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Completion of this section)				4:04:14 PM		
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
20,800 - INSPECT_High Idle Control	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
32,000 - Engine Inspection	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Sep 3, 2021 4:04:14 PM	Yes	54870524
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Sep 3, 2021 4:04:14 PM	No	
33,010 - CSF (Curb Side Front)	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	14 Volt*		JUHURST	Sep 3, 2021 4:04:14 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
40,200 - INSPECT_Insurance/Registration/	Done		JUHURST	Sep 3, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Regulatory Forms Dates				4:04:14 PM		
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
50,400 - LUBE_All Chassis Components	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
50,700 - INSPECT_Tire Condition	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Sep 3, 2021 4:04:14 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Sep 3, 2021 4:04:14 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Sep 3, 2021 4:04:14 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds		JUHURST	Sep 3, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	per Square Inch			4:04:14 PM		
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Sep 3, 2021 4:04:14 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Sep 3, 2021 4:04:14 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.2299 Inch		JUHURST	Sep 3, 2021 4:04:14 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.2299 Inch		JUHURST	Sep 3, 2021 4:04:14 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Sep 3, 2021 4:04:14 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Sep 3, 2021 4:04:14 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Sep 3, 2021 4:04:14 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Sep 3, 2021 4:04:14 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	5 32nds of an inch		JUHURST	Sep 3, 2021 4:04:14 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Sep 3, 2021 4:04:14 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Sep 3, 2021 4:04:14 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Sep 3, 2021 4:04:14 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch	rear brakes low need replaced l	JUHURST	Sep 3, 2021 4:04:14 PM	Yes	54870671
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch		JUHURST	Sep 3, 2021 4:04:14 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.722 Inch		JUHURST	Sep 3, 2021 4:04:14 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.722 Inch		JUHURST	Sep 3, 2021 4:04:14 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	12419 Cycles		JUHURST	Sep 3, 2021 4:04:14 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
60,400 - OPERATE_Lift thru Complete	Done		JUHURST	Sep 3, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down				4:04:14 PM		
60,500 - INSPECT_ Bridgeplate Operation	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
62,400 - INSPECT_All Pivot Points	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
62,500 - INSPECT_Cams and Slots	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
62,600 - INSPECT_Rollers	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
62,700 - INSPECT_All Linkages	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	Sep 3, 2021 4:04:14 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	6.23
Labor:	0.00
Labor Hours:	1.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**6.23**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54789085
Invoice No. 55345 - 54789085

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	262,215 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Sep-21	Junior Hurst	0.33	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: JUHURST Performed on: 03-SEP-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		JUHURST	Sep 3, 2021 4:08:18 PM	No	
101,000 - FRA Change Oil Filters	Yes		JUHURST	Sep 3, 2021 4:08:18 PM	No	
102,000 - FRA Drain Engine Oil	Yes		JUHURST	Sep 3, 2021 4:08:18 PM	No	
103,000 - FRA Check Transmission Fluid	Done		JUHURST	Sep 3, 2021 4:08:18 PM	No	
104,000 - Lubricate Chassis	Done		JUHURST	Sep 3, 2021 4:08:18 PM	No	
105,000 - Replace or Clean A/C Filters	Done		JUHURST	Sep 3, 2021 4:08:18 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		JUHURST	Sep 3, 2021 4:08:18 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		JUHURST	Sep 3, 2021 4:08:18 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.33
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 54789085 Total	
Parts:	6.23
Labor:	0.00
Labor Hours:	1.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**6.23**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54836032
Invoice No. 55345 - 54836032

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Rear bumper damage.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,419 - DH

Chronology		
Reported	Aug 23, 2021 7:26:28 PM	Aug 23, 2021 7:26:28 PM
Started	Aug 23, 2021 7:28:00 PM	
Completed	Aug 24, 2021 12:10:00 AM	Aug 24, 2021 12:10:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: LR Bumper detached.

Cause: Damaged during operation.

Correction: Remove screws and reattached LR Bumper cover.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 23-AUG-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Aug 23, 2021 10:40:43 PM	No	
2 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Aug 23, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				10:40:43 PM		
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Aug 23, 2021 10:40:43 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Aug 23, 2021 10:40:43 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Aug 23, 2021 10:40:43 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Aug 23, 2021 10:40:43 PM	No	
20 - Miles			EARJOHNSON	Aug 23, 2021 10:40:43 PM	No	
30 - Kilometers			EARJOHNSON	Aug 23, 2021 10:40:43 PM	No	
40 - Hours			EARJOHNSON	Aug 23, 2021 10:40:43 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54836032
Invoice No. 55345 - 54836032

Client Department:
Department: 55345M
Work Order Description
Rear bumper damage.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 260,419 - DH

Activity Header
Activity: 15 010 CHASSIS GROUP
Activity Note: Rear bumper damaged.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Aug-21	Earl Johnson	3.2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54836032 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54797113
Invoice No. 55345 - 54797113

Client Department:
Department: 55345M
Work Order Description
Road Call
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 258,210 - DH

Chronology		
Reported	Aug 9, 2021 3:29:27 PM	Aug 9, 2021 3:29:27 PM
Started	Aug 9, 2021 3:30:00 PM	
Completed	Aug 9, 2021 5:51:00 PM	Aug 9, 2021 5:51:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Take unit 9936 to a driver and switch Vehicle

Cause: Fuel issue

Correction: return to shop and correct the problem change fuel gauge after return vehicle back to work

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 09-AUG-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Aug 9, 2021 5:46:17 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		JUHURST	Aug 9, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				5:46:17 PM		
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Aug 9, 2021 5:46:17 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Aug 9, 2021 5:46:17 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Aug 9, 2021 5:46:17 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Aug 9, 2021 5:46:17 PM	No	
20 - Miles			JUHURST	Aug 9, 2021 5:46:17 PM	No	
30 - Kilometers			JUHURST	Aug 9, 2021 5:46:17 PM	No	
40 - Hours			JUHURST	Aug 9, 2021 5:46:17 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54797113
Invoice No. 55345 - 54797113

Client Department:
Department: 55345M
Work Order Description
Road Call
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 258,210 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Aug-21	Junior Hurst	2.27	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54797113 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54675781
Invoice No. 55345 - 54675781

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMB
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 257,861 - DH

Chronology		
Reported	Aug 5, 2021 12:00:00 AM	Aug 5, 2021 12:00:00 AM
Started	Aug 5, 2021 8:27:00 PM	
Completed	Aug 6, 2021 12:07:00 AM	Aug 6, 2021 12:07:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMB

CAUSE: Service

CORRECTION:Perform PMB Service
Oil filter B329 qty1
Engine oil 10w30 qty 7 qts

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 05-AUG-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Aug 5, 2021 8:27:02 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Aug 5, 2021 8:27:02 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Aug 5, 2021 8:27:02 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Aug 5, 2021 8:27:02 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Aug 5, 2021 8:27:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Aug 5, 2021 8:27:02 PM	No	
20 - Miles			RGASPARD	Aug 5, 2021 8:27:02 PM	No	
30 - Kilometers			RGASPARD	Aug 5, 2021 8:27:02 PM	No	
40 - Hours			RGASPARD	Aug 5, 2021 8:27:02 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54675781
Invoice No. 55345 - 54675781

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMB
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 257,861 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Aug-21	Gaspard,Ronald	1.2	0	0
05-Aug-21	Gaspard,Ronald	0.43	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 05-AUG-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
20,800 - INSPECT_High Idle Control	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	Aug 5, 2021 9:12:20 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Aug 5, 2021 9:12:20 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.24 Volt*		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
33,010 - CSF (Curb Side Front)	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	RGASPARD	Aug 5, 2021 9:12:20 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		RGASPARD	Aug 5, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression				9:12:20 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
50,400 - LUBE_All Chassis Components	Done	na	RGASPARD	Aug 5, 2021 9:12:20 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	37 Inch		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	37 Inch		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Aug 5, 2021 9:12:20 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	17485 Cycles		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper	Done		RGASPARD	Aug 5, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alignment				9:12:20 PM		
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Aug 5, 2021 9:12:20 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54675781
Invoice No. 55345 - 54675781

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMB
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 257,861 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Aug-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.98	1.98

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Aug-21	Gaspard,Ronald	0.3	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: RGASPARD Performed on: 05-AUG-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Aug 5, 2021 10:25:05 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Aug 5, 2021 10:25:05 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Aug 5, 2021 10:25:05 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Aug 5, 2021 10:25:05 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Aug 5, 2021 10:25:05 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Aug 5, 2021 10:25:05 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Aug 5, 2021 10:25:05 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Aug 5, 2021 10:25:05 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		RGASPARD	Aug 5, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				10:25:05 PM		
201,000 - Service Crankcase Breather	Done		RGASPARD	Aug 5, 2021 10:25:05 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Aug 5, 2021 10:25:05 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Aug 5, 2021 10:25:05 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Aug 5, 2021 10:25:05 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.98
Labor:	0.00
Labor Hours:	0.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.98**

Work Order Footer

Work Order 54675781 Total	
Parts:	1.98
Labor:	0.00
Labor Hours:	1.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.98**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54719224
Invoice No. 55345 - 54719224

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Tire Light On		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	255,625 - DH

Chronology		
Reported	Jul 11, 2021 7:23:55 PM	Jul 11, 2021 7:23:55 PM
Started	Jul 11, 2021 7:25:00 PM	
Completed	Jul 11, 2021 8:32:00 PM	Jul 11, 2021 8:32:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: R/R inner Tire Flat.

Cause: Tire Has A Nail.

Correction: Remove R/R Inner Tire Patch Balance & Retrain TPMS Sensor

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 11-JUL-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jul 11, 2021 8:32:07 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		DARTHURS	Jul 11, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				8:32:07 PM		
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jul 11, 2021 8:32:07 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jul 11, 2021 8:32:07 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jul 11, 2021 8:32:07 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 11, 2021 8:32:07 PM	No	
20 - Miles			DARTHURS	Jul 11, 2021 8:32:07 PM	No	
30 - Kilometers			DARTHURS	Jul 11, 2021 8:32:07 PM	No	
40 - Hours			DARTHURS	Jul 11, 2021 8:32:07 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54719224
Invoice No. 55345 - 54719224

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Tire Light On		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	255,625 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Tire Light On
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Jul-21	Arthurs,Durvin	1.12	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54719224 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54718885
Invoice No. 55345 - 54718885

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
R/R Tire . Nail & Tire depth low		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	255,625 - DH

Chronology		
Reported	Jul 11, 2021 3:19:45 PM	Jul 11, 2021 3:19:45 PM
Started	Jul 11, 2021 3:22:00 PM	
Completed	Jul 11, 2021 7:23:00 PM	Jul 11, 2021 7:23:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Right Rear Outer Tire

Cause: Tire has a Nail & Worn

Correction: Swap all four Tire from bus (5716) Replace On Bus (4515)

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 11-JUL-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jul 11, 2021 3:22:47 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		DARTHURS	Jul 11, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				3:22:47 PM		
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jul 11, 2021 3:22:47 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jul 11, 2021 3:22:47 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jul 11, 2021 3:22:47 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 11, 2021 3:22:47 PM	No	
20 - Miles			DARTHURS	Jul 11, 2021 3:22:47 PM	No	
30 - Kilometers			DARTHURS	Jul 11, 2021 3:22:47 PM	No	
40 - Hours			DARTHURS	Jul 11, 2021 3:22:47 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54718885
Invoice No. 55345 - 54718885

Client Department:
Department: 55345M
Work Order Description
R/R Tire . Nail & Tire depth low
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 255,625 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Swap Rear Tire
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Jul-21	Arthurs,Durvin	1.72	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54718885 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53544612
Invoice No. 55345 - 53544612

Client Department:
Department: 55345M
Work Order Description
QCC FLEET INSPECTION
Requested By: RBOOTH
Created By: RBOOTH
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 253,714 -

Chronology		
Reported	Jun 23, 2021 11:09:34 AM	Jun 23, 2021 11:09:34 AM
Started		
Completed	Jun 24, 2021 5:19:00 PM	Jun 24, 2021 5:19:00 PM
Down Time		

Work Order Notes

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 24-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		AOWENS	Jun 24, 2021 5:07:49 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		AOWENS	Jun 24, 2021 5:07:49 PM	No	
3 - Are you wearing the appropriate PPE?	Done		AOWENS	Jun 24, 2021 5:07:49 PM	No	
4 - Have you performed the proper LOTO?	Done		AOWENS	Jun 24, 2021 5:07:49 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	Jun 24, 2021 5:07:49 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Jun 24, 2021 5:07:49 PM	No	
20 - Miles			AOWENS	Jun 24, 2021 5:07:49 PM	No	
30 - Kilometers			AOWENS	Jun 24, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				5:07:49 PM		
40 - Hours			AOWENS	Jun 24, 2021 5:07:49 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53544612
Invoice No. 55345 - 53544612

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
QCC FLEET INSPECTION		Ford E450 Champion Challenger	
Requested By:	RBOOTH	**Status:**	40 - Closed (40)
Created By:	RBOOTH	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	253,714 -

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: QCC FLEET INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53544612 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53557800
Invoice No. 55345 - 53557800

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-PTC INSPECTION		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	**Status:**	40 - Closed (40)
Created By:	NSTOLFO	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	253,608 -

Chronology

Reported	Jun 23, 2021 11:09:34 AM	Jun 23, 2021 11:09:34 AM
Started	Jun 23, 2021 4:08:00 PM	
Completed	Jun 23, 2021 5:07:00 PM	Jun 23, 2021 5:07:00 PM
Down Time		

Work Order Notes

Line 10 Inspection was performed and this unit. P T C

Activity Header

Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jun-21	Junior Hurst	0.03	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 23-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Jun 23, 2021 4:09:37 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Jun 23, 2021 4:09:37 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Jun 23, 2021 4:09:37 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Jun 23, 2021 4:09:37 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Jun 23, 2021 4:09:37 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Jun 23, 2021 4:09:37 PM	No	
20 - Miles			JUHURST	Jun 23, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				4:09:37 PM		
30 - Kilometers			JUHURST	Jun 23, 2021 4:09:37 PM	No	
40 - Hours			JUHURST	Jun 23, 2021 4:09:37 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53557800
Invoice No. 55345 - 53557800

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-PTC INSPECTION		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	**Status:**	40 - Closed (40)
Created By:	NSTOLFO	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	253,608 -

Activity Header
Activity: 15 999 TOTAL VEHICLE
Activity Note: PTC INSPECTION
Reason for Repair: 11 Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jun-21	Junior Hurst	0.92	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53557800 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53557976
Invoice No. 55345 - 53557976

Client Department:
Department: 55345M
Work Order Description
55345-FIRE SAFETY INSPECTION
Requested By: NSTOLFO
Created By: NSTOLFO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 253,608 -

Chronology		
Reported	Jun 23, 2021 11:09:34 AM	Jun 23, 2021 11:09:34 AM
Started	Jun 23, 2021 3:36:00 PM	
Completed	Jun 23, 2021 4:00:00 PM	Jun 23, 2021 4:00:00 PM
Down Time		

Work Order Notes

Line 10 Fire safety check was performed all components working

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 23-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Jun 23, 2021 3:37:59 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Jun 23, 2021 3:37:59 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Jun 23, 2021 3:37:59 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Jun 23, 2021 3:37:59 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Jun 23, 2021 3:37:59 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Jun 23, 2021 3:37:59 PM	No	
20 - Miles			JUHURST	Jun 23, 2021 3:37:59 PM	No	
30 - Kilometers			JUHURST	Jun 23, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:37:59 PM		
40 - Hours			JUHURST	Jun 23, 2021 3:37:59 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53557976
Invoice No. 55345 - 53557976

Client Department:
Department: 55345M
Work Order Description
55345-FIRE SAFETY INSPECTION
Requested By: NSTOLFO
Created By: NSTOLFO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 253,608 -

Activity Header
Activity: 15 999 TOTAL VEHICLE
Activity Note: ANNUAL FIRE SAFETY INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jun-21	Junior Hurst	0.4	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53557976 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53558160
Invoice No. 55345 - 53558160

Client Department:
Department: 55345M
Work Order Description
55345-A/C INSPECTION
Requested By: NSTOLFO
Created By: NSTOLFO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 253,608 -

Chronology		
Reported	Jun 23, 2021 11:09:33 AM	Jun 23, 2021 11:09:33 AM
Started	Jun 23, 2021 3:05:00 PM	
Completed	Jun 23, 2021 3:24:00 PM	Jun 23, 2021 3:24:00 PM
Down Time		

Work Order Notes

Line 10 Annual inspection perform for the air condition

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 23-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Jun 23, 2021 3:13:41 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Jun 23, 2021 3:13:41 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Jun 23, 2021 3:13:41 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Jun 23, 2021 3:13:41 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Jun 23, 2021 3:13:41 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Jun 23, 2021 3:13:41 PM	No	
20 - Miles			JUHURST	Jun 23, 2021 3:13:41 PM	No	
30 - Kilometers			JUHURST	Jun 23, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:13:41 PM		
40 - Hours			JUHURST	Jun 23, 2021 3:13:41 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53558160
Invoice No. 55345 - 53558160

Client Department:
Department: 55345M
Work Order Description
55345-A/C INSPECTION
Requested By: NSTOLFO
Created By: NSTOLFO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 253,608 -

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: ANNUAL A/C INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jun-21	Junior Hurst	0.15	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.15
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53558160 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.15
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54567342
Invoice No. 55345 - 54567342

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	253,608 - DH

Chronology		
Reported	Jun 23, 2021 12:00:00 AM	Jun 23, 2021 12:00:00 AM
Started	Jun 23, 2021 12:45:00 PM	
Completed	Jun 23, 2021 3:03:00 PM	Jun 23, 2021 3:03:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION:

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jun-21	Junior Hurst	0.28	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 23-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Jun 23, 2021 1:02:17 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Jun 23, 2021 1:02:17 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Jun 23, 2021 1:02:17 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Jun 23, 2021 1:02:17 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Jun 23, 2021 1:02:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Jun 23, 2021 1:02:17 PM	No	
20 - Miles			JUHURST	Jun 23, 2021 1:02:17 PM	No	
30 - Kilometers			JUHURST	Jun 23, 2021 1:02:17 PM	No	
40 - Hours			JUHURST	Jun 23, 2021 1:02:17 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54567342
Invoice No. 55345 - 54567342

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	253,608 - DH

Activity Header
Activity: 10
Activity Note: Light Duty PMI
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Jun-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.98	1.98
23-Jun-21	PA4075	FILTER, AIR SEE P546597	1	5.32	5.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jun-21	Junior Hurst	1.8	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: JUHURST Performed on: 23-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
20,800 - INSPECT_High Idle Control	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
32,000 - Engine Inspection	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Jun 23, 2021 2:50:08 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Jun 23, 2021 2:50:08 PM	No	
33,010 - CSF (Curb Side Front)	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	14 Volt*		JUHURST	Jun 23, 2021 2:50:08 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
50,400 - LUBE_All Chassis Components	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
50,700 - INSPECT_Tire Condition	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Jun 23, 2021 2:50:08 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Jun 23, 2021 2:50:08 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Jun 23, 2021 2:50:08 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Jun 23, 2021 2:50:08 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Jun 23, 2021 2:50:08 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Jun 23, 2021 2:50:08 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.2299 Inch		JUHURST	Jun 23, 2021 2:50:08 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.2299 Inch		JUHURST	Jun 23, 2021 2:50:08 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	5 32nds of an inch		JUHURST	Jun 23, 2021 2:50:08 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	5 32nds of an inch		JUHURST	Jun 23, 2021 2:50:08 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Jun 23, 2021 2:50:08 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Jun 23, 2021 2:50:08 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	5 32nds of an inch		JUHURST	Jun 23, 2021 2:50:08 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	5 32nds of an inch		JUHURST	Jun 23, 2021 2:50:08 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Jun 23, 2021 2:50:08 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Jun 23, 2021 2:50:08 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Jun 23, 2021 2:50:08 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Jun 23, 2021 2:50:08 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.722 Inch		JUHURST	Jun 23, 2021 2:50:08 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.722 Inch		JUHURST	Jun 23, 2021 2:50:08 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	11950 Cycles		JUHURST	Jun 23, 2021 2:50:08 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
61,000 - INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
62,400 - INSPECT_All Pivot Points	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
62,500 - INSPECT_Cams and Slots	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
62,600 - INSPECT_Rollers	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
62,700 - INSPECT_All Linkages	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	Jun 23, 2021 2:50:08 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	7.30
Labor:	0.00
Labor Hours:	1.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.30**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54567342
Invoice No. 55345 - 54567342

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 253,608 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jun-21	Junior Hurst	0.17	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: JUHURST Performed on: 23-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		JUHURST	Jun 23, 2021 2:52:30 PM	No	
101,000 - FRA Change Oil Filters	Yes		JUHURST	Jun 23, 2021 2:52:30 PM	No	
102,000 - FRA Drain Engine Oil	Yes		JUHURST	Jun 23, 2021 2:52:30 PM	No	
103,000 - FRA Check Transmission Fluid	Done		JUHURST	Jun 23, 2021 2:52:30 PM	No	
104,000 - Lubricate Chassis	Done		JUHURST	Jun 23, 2021 2:52:30 PM	No	
105,000 - Replace or Clean A/C Filters	Done		JUHURST	Jun 23, 2021 2:52:30 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		JUHURST	Jun 23, 2021 2:52:30 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		JUHURST	Jun 23, 2021 2:52:30 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.17
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 54567342 Total	
Parts:	7.30
Labor:	0.00
Labor Hours:	2.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.30**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54567320
Invoice No. 55345 - 54567320

Client Department:

Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOWUP-Replace rear Brakes		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	249,352 - DH

Chronology		
Reported	May 14, 2021 11:00:57 PM	May 14, 2021 11:00:57 PM
Started	May 14, 2021 11:08:00 PM	
Completed	Jun 22, 2021 5:21:00 PM	Jun 22, 2021 5:21:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========
To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.
==========

Complaint:needs rear brakes job

Cause: wear

Correction:replaced rear brake pads and lubed guide pins
Torque wheels 140 lbs second torque 140 lbs
Part number 8C2Z-2V00-C Qty1

Activity Header
Activity: 10 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: needs front brakes
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

	Activity 10 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54567320
Invoice No. 55345 - 54567320

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP-Replace rear Brakes
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 249,352 - DH

Activity Header
Activity: 20 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: needs front brakes
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Jun-21	8C2Z-2V200-C	PADS, BRAKE, DISC, REAR	1	53.34	53.34

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-May-21	Gaspard,Ronald	0.87	0	0
15-May-21	Gaspard,Ronald	0.33	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	53.34
Labor:	0.00
Labor Hours:	1.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**53.34**

Work Order Footer

Work Order 54567320 Total	
Parts:	53.34
Labor:	0.00
Labor Hours:	1.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**53.34**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54654077
Invoice No. 55345 - 54654077

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Ford Body Parts		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	252,933 - DH

Chronology		
Reported	Jun 16, 2021 7:04:24 AM	Jun 16, 2021 7:04:24 AM
Started	Jun 16, 2021 7:05:00 AM	
Completed	Jun 18, 2021 9:07:00 AM	Jun 18, 2021 9:07:00 AM
Down Time		

Work Order Notes

Line 10 Complaint. Vehicle body damage driver side lower panel

Cause. Driver hit a pole

Correction. Removed panel and fix

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Jun-21	Rodriguez,Raul	1.6833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 18-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Jun 18, 2021 8:57:48 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Jun 18, 2021 8:57:48 AM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Jun 18, 2021 8:57:48 AM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Jun 18, 2021 8:57:48 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Jun 18, 2021 8:57:48 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Jun 18, 2021 8:57:48 AM	No	
20 - Miles			RAURODRIGUEZ	Jun 18, 2021 8:57:48 AM	No	
30 - Kilometers			RAURODRIGUEZ	Jun 18, 2021 8:57:48 AM	No	
40 - Hours			RAURODRIGUEZ	Jun 18, 2021 8:57:48 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54654077
Invoice No. 55345 - 54654077

Client Department:
Department: 55345M
Work Order Description
Ford Body Parts
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 252,933 - DH

Activity Header
Activity: 20 174/000/000 BODY, BUS
Activity Note:
Reason for Repair: 41 Abuse of Equipment
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Jun-21	40520	BLADE, WIPER, WINDSHIELD, 20"	2	4.4	8.8

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jun-21	Rodriguez,Raul	7.83	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	8.80
Labor:	0.00
Labor Hours:	7.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.80**

Work Order Footer

Work Order 54654077 Total	
Parts:	8.80
Labor:	0.00
Labor Hours:	9.51
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54546640
Invoice No. 55345 - 54546640

Client Department:
Department: 55345M
Work Order Description
FIRST TRANSIT - NORTH AMERICA - CONSPICUITY
Requested By: DGALLAGHER
Created By: DGALLAGHER
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 248,817 - DH

Chronology		
Reported	May 11, 2021 2:27:17 PM	May 11, 2021 2:27:17 PM
Started		
Completed	Jun 18, 2021 8:54:00 AM	Jun 18, 2021 8:54:00 AM
Down Time		

Work Order Notes

Activity Header
Activity: 10 999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: CVERGARA Performed on: 18-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		CVERGARA	Jun 18, 2021 8:46:40 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		CVERGARA	Jun 18, 2021 8:46:40 AM	No	
3 - Are you wearing the appropriate PPE?	Done		CVERGARA	Jun 18, 2021 8:46:40 AM	No	
4 - Have you performed the proper LOTO?	Done		CVERGARA	Jun 18, 2021 8:46:40 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		CVERGARA	Jun 18, 2021 8:46:40 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		CVERGARA	Jun 18, 2021 8:46:40 AM	No	
20 - Miles			CVERGARA	Jun 18, 2021 8:46:40 AM	No	
30 - Kilometers			CVERGARA	Jun 18, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:46:40 AM		
40 - Hours			CVERGARA	Jun 18, 2021 8:46:40 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54546640
Invoice No. 55345 - 54546640

Client Department:
Department: 55345M
Work Order Description
FIRST TRANSIT - NORTH AMERICA - CONSPICUITY
Requested By: DGALLAGHER
Created By: DGALLAGHER
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 248,817 - DH

Activity Header
Activity:20 053/005/018 TAPE, REFLECTIVE
Activity Note: FIRST TRANSIT - NORTH AMERICA - CONSPICUITY
Reason for Repair: IC Internal Campaign
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: FIRST TRANSIT - NORTH AMERICA - CONSPICUITY
Task: FIRST TRANSIT - NORTH AMERICA - CONSPICUITY Performed by: CVERGARA Performed on: 18-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Inspect Conspicuity tape:	FTTA		CVERGARA	Jun 18, 2021 8:47:16 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54546640 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54645029
Invoice No. 55345 - 54645029

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Coolant Leak		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	252,562 - DH

Chronology		
Reported	Jun 13, 2021 1:00:08 PM	Jun 13, 2021 1:00:08 PM
Started	Jun 13, 2021 1:02:00 PM	
Completed	Jun 13, 2021 4:21:00 PM	Jun 13, 2021 4:21:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Coolant Leak.

Cause: Water Pump & Radiator Leaking.

Correction: Remove&Replace Water Pump & Remove&Replace Radiator. added (4) Gallon Coolant to Refill
Parts# G1000449250CSF Qty (1)
Parts # 4C3Z-8501-B. Qty (1)
Coolant Qty (4) Gallon

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 13-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jun 13, 2021 4:14:25 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jun 13, 2021 4:14:25 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jun 13, 2021 4:14:25 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jun 13, 2021 4:14:25 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jun 13, 2021 4:14:25 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jun 13, 2021 4:14:25 PM	No	
20 - Miles			DARTHURS	Jun 13, 2021 4:14:25 PM	No	
30 - Kilometers			DARTHURS	Jun 13, 2021 4:14:25 PM	No	
40 - Hours			DARTHURS	Jun 13, 2021 4:14:25 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54645029
Invoice No. 55345 - 54645029

Client Department:
Department: 55345M
Work Order Description
Coolant Leak
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 252,562 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Check Coolant Leak
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Jun-21	4C3Z-8501-B	PUMP, WATER, 6.8L	1	92.35	92.35
13-Jun-21	G1000449250CSF	RADIATOR	1	142.08	142.08

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Jun-21	Arthurs,Durvin	3.32	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	234.43
Labor:	0.00
Labor Hours:	3.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**234.43**

Work Order Footer

Work Order 54645029 Total	
Parts:	234.43
Labor:	0.00
Labor Hours:	3.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**234.43**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54594012
Invoice No. 55345 - 54594012

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Left rear tire flat		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	250,491 - DH

Chronology		
Reported	May 24, 2021 8:28:19 PM	May 24, 2021 8:28:19 PM
Started	May 25, 2021 12:39:00 PM	
Completed	May 25, 2021 2:56:00 PM	May 25, 2021 2:56:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Vehicle came in for rear tire flat

Cause: nail in tire

Correction: Repair tire and return vehicle back to work

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 25-MAY-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	May 25, 2021 2:26:58 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		JUHURST	May 25, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				2:26:58 PM		
3 - Are you wearing the appropriate PPE?	Done		JUHURST	May 25, 2021 2:26:58 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	May 25, 2021 2:26:58 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	May 25, 2021 2:26:58 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	May 25, 2021 2:26:58 PM	No	
20 - Miles			JUHURST	May 25, 2021 2:26:58 PM	No	
30 - Kilometers			JUHURST	May 25, 2021 2:26:58 PM	No	
40 - Hours			JUHURST	May 25, 2021 2:26:58 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54594012
Invoice No. 55345 - 54594012

Client Department:
Department: 55345M
Work Order Description
Left rear tire flat
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 250,491 - DH

Activity Header
Activity: 15 017 TIRES, TUBES, LINERS & VALVES
Activity Note: Flat tire in the rear
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-May-21	Junior Hurst	1.83	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54594012
Invoice No. 55345 - 54594012

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Left rear tire flat		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	250,491 - DH

Activity Header
Activity: 25 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54594012 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54576661
Invoice No. 55345 - 54576661

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Front AC malfunction.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	249,629 - DH

Chronology		
Reported	May 18, 2021 7:59:47 PM	May 18, 2021 7:59:47 PM
Started	May 18, 2021 8:00:00 PM	
Completed	May 18, 2021 10:23:00 PM	May 18, 2021 10:23:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Front AC malfunction.

Cause: Front blower motor faulty.

Correction: Remove and replaced faulty blower.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-May-21	Earl Johnson	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 18-MAY-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	May 18, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:17:20 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	May 18, 2021 10:17:20 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	May 18, 2021 10:17:20 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	May 18, 2021 10:17:20 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	May 18, 2021 10:17:20 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	May 18, 2021 10:17:20 PM	No	
20 - Miles			EARJOHNSON	May 18, 2021 10:17:20 PM	No	
30 - Kilometers			EARJOHNSON	May 18, 2021 10:17:20 PM	No	
40 - Hours			EARJOHNSON	May 18, 2021 10:17:20 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54576661
Invoice No. 55345 - 54576661

Client Department:
Department: 55345M
Work Order Description
Front AC malfunction.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 249,629 - DH

Activity Header
Activity: 15 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Front AC blower motor.
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-May-21	XC2Z-19805-BA	MOTOR, BLOWER SAME AS MM-840	1	36.91	36.91

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-May-21	Earl Johnson	2.27	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	36.91
Labor:	0.00
Labor Hours:	2.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**36.91**

Work Order Footer

Work Order 54576661 Total	
Parts:	36.91
Labor:	0.00
Labor Hours:	2.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**36.91**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54452182
Invoice No. 55345 - 54452182

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	249,352 - DH

Chronology		
Reported	May 14, 2021 10:24:02 AM	May 14, 2021 10:24:02 AM
Started	May 14, 2021 3:49:00 PM	
Completed	May 15, 2021 12:04:00 AM	May 15, 2021 12:04:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PmA

CAUSE: Service

CORRECTION: perform PmA Service
Oil filter B329 Qty1
Engine oil 10w30 qty 7 qts

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 14-MAY-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	May 14, 2021 9:11:04 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	May 14, 2021 9:11:04 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	May 14, 2021 9:11:04 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	May 14, 2021 9:11:04 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	May 14, 2021 9:11:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	May 14, 2021 9:11:04 PM	No	
20 - Miles			RGASPARD	May 14, 2021 9:11:04 PM	No	
30 - Kilometers			RGASPARD	May 14, 2021 9:11:04 PM	No	
40 - Hours			RGASPARD	May 14, 2021 9:11:04 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54452182
Invoice No. 55345 - 54452182

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	249,352 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-May-21	Gaspard,Ronald	1.68	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 14-MAY-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	May 14, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:22:50 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
20,800 - INSPECT_High Idle Control	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	May 14, 2021 10:22:50 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	-	na	RGASPARD	May 14, 2021 10:22:50 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.24 Volt*		RGASPARD	May 14, 2021 10:22:50 PM	No	
33,010 - CSF (Curb Side Front)	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	RGASPARD	May 14, 2021 10:22:50 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		RGASPARD	May 14, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression				10:22:50 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
50,400 - LUBE_All Chassis Components	Done	na	RGASPARD	May 14, 2021 10:22:50 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		RGASPARD	May 14, 2021 10:22:50 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	May 14, 2021 10:22:50 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		RGASPARD	May 14, 2021 10:22:50 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	May 14, 2021 10:22:50 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	May 14, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:22:50 PM		
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	3 32nds of an inch	needs front brakes	RGASPARD	May 14, 2021 10:22:50 PM	Yes	54567320
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	3 32nds of an inch	needs front brakes	RGASPARD	May 14, 2021 10:22:50 PM	Yes	54567320
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	37 Inch		RGASPARD	May 14, 2021 10:22:50 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	37 Inch		RGASPARD	May 14, 2021 10:22:50 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	4 32nds of an		RGASPARD	May 14, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	inch			10:22:50 PM		
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	May 14, 2021 10:22:50 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	May 14, 2021 10:22:50 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	May 14, 2021 10:22:50 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	May 14, 2021 10:22:50 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	May 14, 2021 10:22:50 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	May 14, 2021 10:22:50 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	May 14, 2021 10:22:50 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	May 14, 2021 10:22:50 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	May 14, 2021 10:22:50 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	May 14, 2021 10:22:50 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	May 14, 2021 10:22:50 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	18742 Cycles		RGASPARD	May 14, 2021 10:22:50 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	May 14, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:22:50 PM		
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	May 14, 2021 10:22:50 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54452182
Invoice No. 55345 - 54452182

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 249,352 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-May-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.98	1.98

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-May-21	Gaspard,Ronald	0.23	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 14-MAY-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	May 14, 2021 10:53:38 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	May 14, 2021 10:53:38 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	May 14, 2021 10:53:38 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	May 14, 2021 10:53:38 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	May 14, 2021 10:53:38 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	May 14, 2021 10:53:38 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	May 14, 2021 10:53:38 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	May 14, 2021 10:53:38 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.98
Labor:	0.00
Labor Hours:	0.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.98**

Work Order Footer

Work Order 54452182 Total	
Parts:	1.98
Labor:	0.00
Labor Hours:	1.91
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.98**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54455134
Invoice No. 55345 - 54455134

Client Department:
Department: 55345M
Work Order Description
Road Call
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 245,366 - DH

Chronology		
Reported	Apr 9, 2021 3:27:57 PM	Apr 9, 2021 3:27:57 PM
Started	Apr 9, 2021 3:28:00 PM	
Completed	Apr 14, 2021 9:46:00 AM	Apr 14, 2021 9:46:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: battery light flashing

Cause: bad battery

Correction: replaced batteries (2)

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 14-APR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Apr 14, 2021 9:46:15 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Apr 14, 2021 9:46:15 AM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Apr 14, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:46:15 AM		
4 - Have you performed the proper LOTO?	Done		TDELVA	Apr 14, 2021 9:46:15 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Apr 14, 2021 9:46:15 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Apr 14, 2021 9:46:15 AM	No	
20 - Miles			TDELVA	Apr 14, 2021 9:46:15 AM	No	
30 - Kilometers			TDELVA	Apr 14, 2021 9:46:15 AM	No	
40 - Hours			TDELVA	Apr 14, 2021 9:46:15 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54455134
Invoice No. 55345 - 54455134

Client Department:
Department: 55345M
Work Order Description
Road Call
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 245,366 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Apr-21	Delva,Terry	3.33	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54455134
Invoice No. 55345 - 54455134

Client Department:
Department: 55345M
Work Order Description
Road Call
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 245,366 - DH

Activity Header
Activity: 20 031/005/000 CHARGER, BATTERY, ON-BOARD, VEHICLES, PROPELLED, ELECTRICALLY
Activity Note: Replaced Battery
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure: 43 Weak
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Apr-21	34FT2	BATTERY	1	115.74	115.74

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Apr-21	Delva,Terry	1.68	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	115.74
Labor:	0.00
Labor Hours:	1.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**115.74**

Work Order Footer

Work Order 54455134 Total	
Parts:	115.74
Labor:	0.00
Labor Hours:	5.01
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**115.74**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54455540
Invoice No. 55345 - 54455540

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Alternator		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	245,366 - DH

Chronology		
Reported	Apr 9, 2021 3:59:25 PM	Apr 9, 2021 3:59:25 PM
Started	Apr 9, 2021 5:02:00 PM	
Completed	Apr 9, 2021 5:56:00 PM	Apr 9, 2021 5:56:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: vehicle came in from road call

Cause: alternator worn out

Correction: remove and replace new alternator to unit now working as design return vehicle back to work

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Apr-21	Junior Hurst	0.02	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 09-APR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Apr 9, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				5:54:10 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Apr 9, 2021 5:54:10 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Apr 9, 2021 5:54:10 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Apr 9, 2021 5:54:10 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Apr 9, 2021 5:54:10 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Apr 9, 2021 5:54:10 PM	No	
20 - Miles			JUHURST	Apr 9, 2021 5:54:10 PM	No	
30 - Kilometers			JUHURST	Apr 9, 2021 5:54:10 PM	No	
40 - Hours			JUHURST	Apr 9, 2021 5:54:10 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54455540
Invoice No. 55345 - 54455540

Client Department:
Department: 55345M
Work Order Description
Alternator
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 245,366 - DH

Activity Header
Activity: 15 020 GROUP, DRIVETRAIN
Activity Note: Alternator
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Apr-21	GC2Z-10346-C	ALTERNATOR, 6.8L, E350	1	203.37	203.37

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Apr-21	Junior Hurst	0.88	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	203.37
Labor:	0.00
Labor Hours:	0.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**203.37**

Work Order Footer

Work Order 54455540 Total	
Parts:	203.37
Labor:	0.00
Labor Hours:	0.90
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**203.37**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54345048
Invoice No. 55345 - 54345048

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMC		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	245,154 - DH

Chronology		
Reported	Apr 8, 2021 12:00:00 AM	Apr 8, 2021 12:00:00 AM
Started	Apr 8, 2021 10:08:00 PM	
Completed	Apr 9, 2021 12:12:00 AM	Apr 9, 2021 12:12:00 AM
Down Time		

Work Order Notes

Line 10 PMC
Service
Perform PMC service
Oil filter B329 Qty1
Engine oil 10w30 qty 7 qts
Gear Oil 80w90 qty 5 qts

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 08-APR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Apr 8, 2021 10:08:46 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Apr 8, 2021 10:08:46 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Apr 8, 2021 10:08:46 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Apr 8, 2021 10:08:46 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Apr 8, 2021 10:08:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Apr 8, 2021 10:08:46 PM	No	
20 - Miles			RGASPARD	Apr 8, 2021 10:08:46 PM	No	
30 - Kilometers			RGASPARD	Apr 8, 2021 10:08:46 PM	No	
40 - Hours			RGASPARD	Apr 8, 2021 10:08:46 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54345048
Invoice No. 55345 - 54345048

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMC
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 245,154 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Apr-21	Gaspard,Ronald	1.6	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 08-APR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Apr 8, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:27:58 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
20,800 - INSPECT_High Idle Control	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	Apr 8, 2021 11:27:58 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Apr 8, 2021 11:27:58 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.24 Volt*		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
33,010 - CSF (Curb Side Front)	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	RGASPARD	Apr 8, 2021 11:27:58 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		RGASPARD	Apr 8, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression				11:27:58 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
50,400 - LUBE_All Chassis Components	Done	na	RGASPARD	Apr 8, 2021 11:27:58 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	37 Inch		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	37 Inch		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Apr 8, 2021 11:27:58 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done	na	RGASPARD	Apr 8, 2021 11:27:58 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	13142 Cycles		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper	Done		RGASPARD	Apr 8, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alignment				11:27:58 PM		
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Apr 8, 2021 11:27:58 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54345048
Invoice No. 55345 - 54345048

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMC
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 245,154 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Apr-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.98	1.98

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Apr-21	Gaspard,Ronald	0.17	0	0
08-Apr-21	Gaspard,Ronald	0.27	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: RGASPARD Performed on: 08-APR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Apr 8, 2021 11:45:56 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Apr 8, 2021 11:45:56 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Apr 8, 2021 11:45:56 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Apr 8, 2021 11:45:56 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Apr 8, 2021 11:45:56 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Apr 8, 2021 11:45:56 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	na	RGASPARD	Apr 8, 2021 11:45:56 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Apr 8, 2021 11:45:56 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Apr 8, 2021 11:45:56 PM	No	
201,000 - Service Crankcase Breather	Done		RGASPARD	Apr 8, 2021 11:45:56 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Apr 8, 2021 11:45:56 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Apr 8, 2021 11:45:56 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Apr 8, 2021 11:45:56 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		RGASPARD	Apr 8, 2021 11:45:56 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		RGASPARD	Apr 8, 2021 11:45:56 PM	No	
302,000 - Check Toe-In and Record Reading	-	na	RGASPARD	Apr 8, 2021 11:45:56 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	na	RGASPARD	Apr 8, 2021 11:45:56 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	Yes		RGASPARD	Apr 8, 2021 11:45:56 PM	No	
305,000 - FRA Change Differential Fluid	Yes		RGASPARD	Apr 8, 2021 11:45:56 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.98
Labor:	0.00
Labor Hours:	0.44
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.98**

Work Order Footer

Work Order 54345048 Total	
Parts:	1.98
Labor:	0.00
Labor Hours:	2.04
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.98**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54356166
Invoice No. 55345 - 54356166

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345 TIRES		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	241,298 - DH

Chronology		
Reported	Mar 7, 2021 10:59:32 AM	Mar 7, 2021 10:59:32 AM
Started	Mar 7, 2021 11:00:00 AM	
Completed	Mar 7, 2021 1:14:00 PM	Mar 7, 2021 1:14:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: low Tires

Cause: preventive maintenance

Correction: replaced 2 front tires

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 07-MAR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Mar 7, 2021 1:11:24 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Mar 7, 2021 1:11:24 PM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Mar 7, 2021 1:11:24 PM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Mar 7, 2021 1:11:24 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Mar 7, 2021 1:11:24 PM	No	
10 - Have you successfully completed the Personal	Done		NPIERRE-	Mar 7, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	1:11:24 PM		
20 - Miles			NPIERRE-LOUIS	Mar 7, 2021 1:11:24 PM	No	
30 - Kilometers			NPIERRE-LOUIS	Mar 7, 2021 1:11:24 PM	No	
40 - Hours			NPIERRE-LOUIS	Mar 7, 2021 1:11:24 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54356166
Invoice No. 55345 - 54356166

Client Department:
Department: 55345M
Work Order Description
55345 TIRES
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 241,298 - DH

Activity Header
Activity: 20 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Mar-21	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	117.57	235.14

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Mar-21	NELSON PIERRE-LOUIS	2.17	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	235.14
Labor:	0.00
Labor Hours:	2.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**235.14**

Work Order Footer

Work Order 54356166 Total	
Parts:	235.14
Labor:	0.00
Labor Hours:	2.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**235.14**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 54344985
Invoice No. 55345 - 54344985

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP- Replace Rear Brakes
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 240,809 - DH

Chronology		
Reported	Mar 2, 2021 11:16:24 PM	Mar 2, 2021 11:16:24 PM
Started	Mar 2, 2021 11:19:00 PM	
Completed	Mar 3, 2021 4:27:00 PM	Mar 3, 2021 4:27:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========
To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.
==========

Complaint:needs rear brakes job and caliper

Cause: cease

Correction:Replaced rear brake pads, right rear caliper and pins
Brakes part number:8C2Z-2V200-C qty1
Pins:8C2Z-2C150-B qty1
Caliper BC2Z-2552-B qty1

Activity Header
Activity: 10 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: needs rear brakes job
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Mar-21	8C2Z-2V200-C	PADS, BRAKE, DISC, REAR	1	45.63	45.63
09-Mar-21	8C2Z-2C150-C	PIN, CALIPER, BRAKE, DISC, FRONT SAME AS BKCOE10	2	9.49	18.98
09-Mar-21	BC2Z-2552-B	CALIPER, BRAKE, DISC, REAR, RH, E450	1	85.14	85.14

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Mar-21	Gaspard,Ronald	0.68	0	0
03-Mar-21	Gaspard,Ronald	0.32	0	0
02-Mar-21	Gaspard,Ronald	0.68	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	149.75
Labor:	0.00
Labor Hours:	1.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**149.75**

Work Order Footer

Work Order 54344985 Total	
Parts:	149.75
Labor:	0.00
Labor Hours:	1.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**149.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54234246
Invoice No. 55345 - 54234246

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	240,809 - DH

Chronology		
Reported	Mar 2, 2021 12:00:00 AM	Mar 2, 2021 12:00:00 AM
Started	Mar 2, 2021 8:58:00 PM	
Completed	Mar 3, 2021 12:41:00 AM	Mar 3, 2021 12:41:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA

CAUSE: service

CORRECTION: perform PMA service
Oil filter B329 qty1
Engine oil 10w30 qty 7 qts

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 02-MAR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Mar 2, 2021 8:58:37 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Mar 2, 2021 8:58:37 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Mar 2, 2021 8:58:37 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Mar 2, 2021 8:58:37 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Mar 2, 2021 8:58:37 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Mar 2, 2021 8:58:37 PM	No	
20 - Miles			RGASPARD	Mar 2, 2021 8:58:37 PM	No	
30 - Kilometers			RGASPARD	Mar 2, 2021 8:58:37 PM	No	
40 - Hours			RGASPARD	Mar 2, 2021 8:58:37 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54234246
Invoice No. 55345 - 54234246

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 240,809 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Mar-21	Gaspard,Ronald	1.63	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 02-MAR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Mar 2, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:15:56 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
20,800 - INSPECT_High Idle Control	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	Mar 2, 2021 10:15:56 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Mar 2, 2021 10:15:56 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.24 Volt*		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
33,010 - CSF (Curb Side Front)	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	RGASPARD	Mar 2, 2021 10:15:56 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		RGASPARD	Mar 2, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression				10:15:56 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
50,400 - LUBE_All Chassis Components	Done	na	RGASPARD	Mar 2, 2021 10:15:56 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	2 32nds of an inch		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Mar 2, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:15:56 PM		
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	37 Inch		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	37 Inch		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Mar 2, 2021 10:15:56 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done	na	RGASPARD	Mar 2, 2021 10:15:56 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	3 32nds of an inch	needs rear brakes job	RGASPARD	Mar 2, 2021 10:15:56 PM	Yes	54344985
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	3 32nds of an inch		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	13453 Cycles		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Mar 2, 2021 10:15:56 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54234246
Invoice No. 55345 - 54234246

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 240,809 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Mar-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Mar-21	Gaspard,Ronald	0.68	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 02-MAR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Mar 2, 2021 10:37:29 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Mar 2, 2021 10:37:29 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Mar 2, 2021 10:37:29 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Mar 2, 2021 10:37:29 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Mar 2, 2021 10:37:29 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Mar 2, 2021 10:37:29 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Mar 2, 2021 10:37:29 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Mar 2, 2021 10:37:29 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order Footer

Work Order 54234246 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.31
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54272111
Invoice No. 55345 - 54272111

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Right rear outer flat		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	237,640 - DH

Chronology		
Reported	Feb 4, 2021 9:04:35 PM	Feb 4, 2021 9:04:35 PM
Started	Feb 4, 2021 9:06:00 PM	
Completed	Feb 4, 2021 11:33:00 PM	Feb 4, 2021 11:33:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:right rear outer tire flat

Cause: puncture

Correction:patched tire mount and balance
Torque wheels 140 lbs second torque 140 lbs

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 04-FEB-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Feb 4, 2021 9:06:26 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Feb 4, 2021 9:06:26 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Feb 4, 2021 9:06:26 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Feb 4, 2021 9:06:26 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Feb 4, 2021 9:06:26 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Feb 4, 2021 9:06:26 PM	No	
20 - Miles			RGASPARD	Feb 4, 2021 9:06:26 PM	No	
30 - Kilometers			RGASPARD	Feb 4, 2021 9:06:26 PM	No	
40 - Hours			RGASPARD	Feb 4, 2021 9:06:26 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54272111
Invoice No. 55345 - 54272111

Client Department:
Department: 55345M
Work Order Description
Right rear outer flat
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 237,640 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Right rear outer tire flat
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Feb-21	Gaspard,Ronald	0.78	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54272111 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54234228
Invoice No. 55345 - 54234228

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP-----> Replace Serpertine Belt And Motor Mount
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 236,381 - DH

Chronology		
Reported	Jan 22, 2021 11:47:42 PM	Jan 22, 2021 11:47:42 PM
Started	Jan 22, 2021 11:58:00 PM	
Completed	Jan 25, 2021 6:40:00 PM	Jan 25, 2021 6:40:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========
To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.
==========

Complaint:needs serpentine belt and right side motor mount

Cause: cracked

Correction: replaced serpentine belt and motor mount
Part number Belt:1360K6 Qty1
Pulley:89006 Qty1
Motor mount:5U9Z-6038-AA Qty1

Activity Header
Activity: 10 042/004 PUMP, WATER
Activity Note: needs Serpentine belt.
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Jan-21	89006	PULLEY, IDLER, GM	1	17.35	17.35
25-Jan-21	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	21	21

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Jan-21	Gaspard,Ronald	0.03	0	0

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jan-21	Gaspard,Ronald	0.57	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	38.35
Labor:	0.00
Labor Hours:	0.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**38.35**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54234228
Invoice No. 55345 - 54234228

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP-----> Replace Serpertine Belt And Motor Mount
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 236,381 - DH

Activity Header
Activity:20 027/001/013 HARDWARE, MOUNTING, CASE, TRANSMISSION, AUTOMATIC APFI - 027-001-001
Activity Note: needs right side motor mount.
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Jan-21	5U9Z-6038-AA	MOUNT, ENGINE, RH	1	54.47	54.47

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	54.47
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**54.47**

Work Order Footer

Work Order 54234228 Total	
Parts:	92.82
Labor:	0.00
Labor Hours:	0.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**92.82**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54123589
Invoice No. 55345 - 54123589

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	236,381 - DH

Chronology		
Reported	Jan 22, 2021 12:00:00 AM	Jan 22, 2021 12:00:00 AM
Started	Jan 22, 2021 10:07:00 PM	
Completed	Jan 23, 2021 12:33:00 AM	Jan 23, 2021 12:33:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE: Service

CORRECTION: Perform pmA Service
Oil filter B329 qty1
Engine oil 10w30 qty 7 qts

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 22-JAN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Jan 22, 2021 10:07:38 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Jan 22, 2021 10:07:38 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Jan 22, 2021 10:07:38 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Jan 22, 2021 10:07:38 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Jan 22, 2021 10:07:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jan 22, 2021 10:07:38 PM	No	
20 - Miles			RGASPARD	Jan 22, 2021 10:07:38 PM	No	
30 - Kilometers			RGASPARD	Jan 22, 2021 10:07:38 PM	No	
40 - Hours			RGASPARD	Jan 22, 2021 10:07:38 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54123589
Invoice No. 55345 - 54123589

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	236,381 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Jan-21	Gaspard,Ronald	1.43	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 22-JAN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Jan 22, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:32:04 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
20,800 - INSPECT_High Idle Control	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	Jan 22, 2021 11:32:04 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Jan 22, 2021 11:32:04 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done	needs Serpentine belt.	RGASPARD	Jan 22, 2021 11:32:04 PM	Yes	54234228
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	13.9 Volt*		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
33,010 - CSF (Curb Side Front)	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	RGASPARD	Jan 22, 2021 11:32:04 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		RGASPARD	Jan 22, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression				11:32:04 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
50,400 - LUBE_All Chassis Components	Done	na	RGASPARD	Jan 22, 2021 11:32:04 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Jan 22, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:32:04 PM		
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	37 Inch		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	37 Inch		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done	needs right side motor mount.	RGASPARD	Jan 22, 2021 11:32:04 PM	Yes	54234228
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Jan 22, 2021 11:32:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	12233 Cycles		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
70,500 - INSPECT_Tank test date, labels-	Done		RGASPARD	Jan 22, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2				11:32:04 PM		
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Jan 22, 2021 11:32:04 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54123589
Invoice No. 55345 - 54123589

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 236,381 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Jan-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Jan-21	Gaspard,Ronald	0.4	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 22-JAN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jan 22, 2021 11:57:31 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jan 22, 2021 11:57:31 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jan 22, 2021 11:57:31 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jan 22, 2021 11:57:31 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Jan 22, 2021 11:57:31 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jan 22, 2021 11:57:31 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Jan 22, 2021 11:57:31 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jan 22, 2021 11:57:31 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order Footer

Work Order 54123589 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	1.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54157015
Invoice No. 55345 - 54157015

Client Department:
Department: 55345M
Work Order Description
Replace Wheel Chair Strut
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 233,315 - DH

Chronology		
Reported	Dec 22, 2020 9:38:00 PM	Dec 22, 2020 9:38:00 PM
Started	Dec 22, 2020 9:48:00 PM	
Completed	Dec 22, 2020 11:26:00 PM	Dec 22, 2020 11:26:00 PM
Down Time		

Work Order Notes

Line 10 WC lift door gas shock bracket detached. Reattached gas door shock bracket and shock.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 22-DEC-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Dec 22, 2020 11:13:01 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Dec 22, 2020 11:13:01 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Dec 22, 2020 11:13:01 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Dec 22, 2020 11:13:01 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Dec 22, 2020 11:13:01 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Dec 22, 2020 11:13:01 PM	No	
20 - Miles			EARJOHNSON	Dec 22, 2020 11:13:01 PM	No	
30 - Kilometers			EARJOHNSON	Dec 22, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:13:01 PM		
40 - Hours			EARJOHNSON	Dec 22, 2020 11:13:01 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54157015
Invoice No. 55345 - 54157015

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Replace Wheel Chair Strut		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	233,315 - DH

Activity Header
Activity: 20 010 CHASSIS GROUP
Activity Note: VERIFY COMPLAINT
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Dec-20	Earl Johnson	0.25	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54157015
Invoice No. 55345 - 54157015

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Replace Wheel Chair Strut		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	233,315 - DH

Activity Header
Activity: 30 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: Replace Wheel Chair Strut
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Dec-20	Earl Johnson	1.15	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.15
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54157015 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53981285
Invoice No. 55345 - 53981285

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMB		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	232,086 - DH

Chronology		
Reported	Dec 9, 2020 12:00:00 AM	Dec 9, 2020 12:00:00 AM
Started	Dec 10, 2020 10:27:00 AM	
Completed	Dec 10, 2020 1:53:00 PM	Dec 10, 2020 1:53:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION:

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 10-DEC-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Dec 10, 2020 1:25:12 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Dec 10, 2020 1:25:12 PM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Dec 10, 2020 1:25:12 PM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Dec 10, 2020 1:25:12 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Dec 10, 2020 1:25:12 PM	No	
10 - Have you successfully completed the Personal	Done		HPIERRE	Dec 10, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				1:25:12 PM		
20 - Miles			HPIERRE	Dec 10, 2020 1:25:12 PM	No	
30 - Kilometers	12		HPIERRE	Dec 10, 2020 1:25:12 PM	No	
40 - Hours	2		HPIERRE	Dec 10, 2020 1:25:12 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53981285
Invoice No. 55345 - 53981285

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMB
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 232,086 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Dec-20	Pierre,Hubert J	3.43	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: HPIERRE Performed on: 10-DEC-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
20,800 - INSPECT_High Idle Control	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
31,000 - SSF (Street Side Front)	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,000 - Engine Inspection	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	190 Degree Fahrenheit	N/A	HPIERRE	Dec 10, 2020 1:24:29 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
32,100 - INSPECT_Intake System	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12 Volt*		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
33,010 - CSF (Curb Side Front)	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	12 Volt*		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
50,400 - LUBE_All Chassis Components	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
50,700 - INSPECT_Tire Condition	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	10 32nds of an inch		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	10 32nds of an inch		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		HPIERRE	Dec 10, 2020 1:24:29 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.6 Inch		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.6 Inch		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
52,100 - INSPECT_Vibration Damper	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
53,600 - INSPECT_Tire Condition	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Dec 10, 2020 1:24:29 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	1.7 Inch		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	1.7 Inch		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	23312 Cycles		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
62,400 - INSPECT_All Pivot Points	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
62,500 - INSPECT_Cams and Slots	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
62,600 - INSPECT_Rollers	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
62,700 - INSPECT_All Linkages	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		HPIERRE	Dec 10, 2020 1:24:29 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53981285
Invoice No. 55345 - 53981285

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMB
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 232,086 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Dec-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: HPIERRE Performed on: 10-DEC-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Dec 10, 2020 1:26:01 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Dec 10, 2020 1:26:01 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Dec 10, 2020 1:26:01 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Dec 10, 2020 1:26:01 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Dec 10, 2020 1:26:01 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Dec 10, 2020 1:26:01 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		HPIERRE	Dec 10, 2020 1:26:01 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Dec 10, 2020 1:26:01 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		HPIERRE	Dec 10, 2020 1:26:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
201,000 - Service Crankcase Breather	Done		HPIERRE	Dec 10, 2020 1:26:01 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		HPIERRE	Dec 10, 2020 1:26:01 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		HPIERRE	Dec 10, 2020 1:26:01 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		HPIERRE	Dec 10, 2020 1:26:01 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order Footer

Work Order 53981285 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	3.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54121717
Invoice No. 55345 - 54121717

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345 PER DVIR		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	231,892 - DH

Chronology		
Reported	Dec 10, 2020 7:28:00 AM	Dec 10, 2020 7:28:00 AM
Started	Dec 10, 2020 7:49:00 AM	
Completed	Dec 10, 2020 9:54:00 AM	Dec 10, 2020 9:54:00 AM
Down Time		

Work Order Notes

Line 10 C: as per driver vehicle didn¿t moved

C: Check computer system found no codes inspect transmission fluid

C: Road test vehicle can¿t duplicate concern at this time

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 10-DEC-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Dec 10, 2020 9:53:29 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Dec 10, 2020 9:53:29 AM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Dec 10, 2020 9:53:29 AM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Dec 10, 2020 9:53:29 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Dec 10, 2020 9:53:29 AM	No	
10 - Have you successfully completed the Personal	Done		JAPEREZ	Dec 10, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				9:53:29 AM		
20 - Miles			JAPEREZ	Dec 10, 2020 9:53:29 AM	No	
30 - Kilometers			JAPEREZ	Dec 10, 2020 9:53:29 AM	No	
40 - Hours			JAPEREZ	Dec 10, 2020 9:53:29 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54121717
Invoice No. 55345 - 54121717

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345 PER DVIR		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	231,892 - DH

Activity Header
Activity: 20 027 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: VERIFY COMPLAINT
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Dec-20	Perez,Javier	2.03	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54121717 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54069887
Invoice No. 55345 - 54069887

Client Department:
Department: 55345M
Work Order Description
ELECTRICAL AND ELECTRONICS
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 229,867 - DH

Chronology		
Reported	Nov 19, 2020 12:37:00 PM	Nov 19, 2020 12:37:00 PM
Started	Nov 19, 2020 12:43:00 PM	
Completed	Nov 20, 2020 1:27:00 PM	Nov 20, 2020 1:27:00 PM
Down Time		

Work Order Notes

Line 10 C: vehicle intermittently shut off

C: vehicle has a electric concern

C: Replaced engine wire harness road test vehicle for 1 and half hours didn¿t die

Part:
1 new engine harness dc2z-9d930-wa

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 20-NOV-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Nov 20, 2020 1:26:27 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Nov 20, 2020 1:26:27 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Nov 20, 2020 1:26:27 PM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Nov 20, 2020 1:26:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Nov 20, 2020 1:26:27 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Nov 20, 2020 1:26:27 PM	No	
20 - Miles			JAPEREZ	Nov 20, 2020 1:26:27 PM	No	
30 - Kilometers			JAPEREZ	Nov 20, 2020 1:26:27 PM	No	
40 - Hours			JAPEREZ	Nov 20, 2020 1:26:27 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54069887
Invoice No. 55345 - 54069887

Client Department:
Department: 55345M
Work Order Description
ELECTRICAL AND ELECTRONICS
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 229,867 - DH

Activity Header
Activity: 20 030 ELECTRICAL GROUP
Activity Note:
Reason for Repair: 01 Breakdown
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Nov-20	DC2Z-9D930-WA	HARNESS, WIRING, ENGINE	1	161.87	161.87

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Nov-20	Perez,Javier	5.73	0	0
19-Nov-20	Perez,Javier	3.1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	161.87
Labor:	0.00
Labor Hours:	8.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**161.87**

Work Order Footer

Work Order 54069887 Total	
Parts:	161.87
Labor:	0.00
Labor Hours:	8.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**161.87**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 54001639
Invoice No. 55345 - 54001639

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Engine Light On)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 228,091 - DH

Chronology		
Reported	Oct 27, 2020 10:33:00 PM	Oct 27, 2020 10:33:00 PM
Started	Oct 27, 2020 11:43:00 PM	
Completed	Nov 12, 2020 2:03:00 PM	Nov 12, 2020 2:03:00 PM
Down Time		

Work Order Notes

Line 10 Check engine light on

Code PO751

Replaced transmission add fluid replace brake switch completed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 12-NOV-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Nov 12, 2020 2:03:20 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Nov 12, 2020 2:03:20 PM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Nov 12, 2020 2:03:20 PM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Nov 12, 2020 2:03:20 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Nov 12, 2020 2:03:20 PM	No	
10 - Have you successfully completed the Personal	Done		HPIERRE	Nov 12, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				2:03:20 PM		
20 - Miles			HPIERRE	Nov 12, 2020 2:03:20 PM	No	
30 - Kilometers	12		HPIERRE	Nov 12, 2020 2:03:20 PM	No	
40 - Hours	8		HPIERRE	Nov 12, 2020 2:03:20 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 54001639
Invoice No. 55345 - 54001639

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Engine Light On)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 228,091 - DH

Activity Header
Activity:20
Activity Note: VERIFY COMPLAINT
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Oct-20	Earl Johnson	0.18	0	0
27-Oct-20	Earl Johnson	0.28	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.46
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 54001639
Invoice No. 55345 - 54001639

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345 PER DVIR (Check Engine Light On)		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	228,091 - DH

Activity Header
Activity: 30 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Check Engine Light On
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 54001639
Invoice No. 55345 - 54001639

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Engine Light On)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 228,091 - DH

Activity Header
Activity: 40 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 43 Weak
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Nov-20	8T4Z-13480-A	SWITCH, INTERLOCK, BRAKE	1	23.96	23.96
12-Nov-20	5R110W	TRANSMISSION, 6.8L, E450	1	2,455	2,455

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Nov-20	Pierre,Hubert J	8.08	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List						
40 Desc: Task: 55345 TRANSMISSION DTC P0751 SHIFT SOLENOID Performed by: HPIERRE Performed on: 12-NOV-20						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - 55345 TRANSMISSION DTC P0751 SHIFT SOLENOID	Done		HPIERRE	Nov 12, 2020 2:02:21 PM	No	

Activity Sub Total

Activity 40 Sub Total	
Parts:	2,478.96
Labor:	0.00
Labor Hours:	8.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2,478.96**

Work Order Footer

Work Order 54001639 Total	
Parts:	2,478.96
Labor:	0.00
Labor Hours:	8.54
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2,478.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 53980773
Invoice No. 55345 - 53980773

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP---> Replace Front Brakes
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 227,564 - DH

Chronology		
Reported	Oct 20, 2020 10:50:41 PM	Oct 20, 2020 10:50:41 PM
Started	Oct 20, 2020 11:48:00 PM	
Completed	Oct 21, 2020 10:07:00 PM	Oct 21, 2020 10:07:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========
To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.
==========

Complaint:needs front brakes job

Cause: wear

Correction:Replaced front brake pads and lubed guide pins
Part number 8C2Z-2V001-D qty1
Torque wheels 149 lbs second torque 140 lbs

Activity Header
Activity: 10 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: needs front brakes job
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Oct-20	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	43.02	43.02

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Oct-20	Gaspard,Ronald	0.2	0	0
21-Oct-20	Gaspard,Ronald	0.48	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	43.02
Labor:	0.00
Labor Hours:	0.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.02**

Work Order Footer

Work Order 53980773 Total	
Parts:	43.02
Labor:	0.00
Labor Hours:	0.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.02**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53839562
Invoice No. 55345 - 53839562

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	227,564 - DH

Chronology		
Reported	Oct 20, 2020 12:00:00 AM	Oct 20, 2020 12:00:00 AM
Started	Oct 20, 2020 9:59:00 PM	
Completed	Oct 21, 2020 7:29:00 AM	Oct 21, 2020 7:29:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE:Service

CORRECTION:Perform pmA Service
Oil filter B329 qty1
Engine oil 10w30 qty 7 qts

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 20-OCT-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Oct 20, 2020 9:59:17 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Oct 20, 2020 9:59:17 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Oct 20, 2020 9:59:17 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Oct 20, 2020 9:59:17 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Oct 20, 2020 9:59:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Oct 20, 2020 9:59:17 PM	No	
20 - Miles			RGASPARD	Oct 20, 2020 9:59:17 PM	No	
30 - Kilometers			RGASPARD	Oct 20, 2020 9:59:17 PM	No	
40 - Hours			RGASPARD	Oct 20, 2020 9:59:17 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53839562
Invoice No. 55345 - 53839562

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	227,564 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Oct-20	Gaspard,Ronald	1.62	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.62
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53839562
Invoice No. 55345 - 53839562

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	227,564 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Oct-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Oct-20	Gaspard,Ronald	0.18	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 20-OCT-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Oct 20, 2020 11:37:28 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Oct 20, 2020 11:37:28 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Oct 20, 2020 11:37:28 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Oct 20, 2020 11:37:28 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Oct 20, 2020 11:37:28 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Oct 20, 2020 11:37:28 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		RGASPARD	Oct 20, 2020 11:37:28 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Oct 20, 2020 11:37:28 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order Footer

Work Order 53839562 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	1.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53958697
Invoice No. 55345 - 53958697

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345 PER DVIR		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	227,179 - DH

Chronology		
Reported	Oct 14, 2020 7:35:00 AM	Oct 14, 2020 7:35:00 AM
Started	Oct 14, 2020 7:49:00 AM	
Completed	Oct 20, 2020 9:02:00 AM	Oct 20, 2020 9:02:00 AM
Down Time		

Work Order Notes

Line 10 C:Vehicle stalls

C: Check computer system found no codes, inspect all systems found intermittent misfire found faulty ignition coil, vehicle come back with stalling condition as per driver

C: Replace PCM and SRM also replace one ignition coil, road test vehicle for 6 hours didn¿t stall at this time

Parts:
1 rebuild PCM
1 new SRM p13jc03p205ac
1 ignition coil 26326

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 20-OCT-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Oct 20, 2020 9:02:20 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Oct 20, 2020 9:02:20 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Oct 20, 2020 9:02:20 AM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Oct 20, 2020 9:02:20 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Oct 20, 2020 9:02:20 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Oct 20, 2020 9:02:20 AM	No	
20 - Miles			JAPEREZ	Oct 20, 2020 9:02:20 AM	No	
30 - Kilometers			JAPEREZ	Oct 20, 2020 9:02:20 AM	No	
40 - Hours			JAPEREZ	Oct 20, 2020 9:02:20 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53958697
Invoice No. 55345 - 53958697

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345 PER DVIR		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	227,179 - DH

Activity Header
Activity: 20 030 ELECTRICAL GROUP
Activity Note: VERIFY COMPLAINT
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Oct-20	P13JC03P205AC	MODULE, RELAY, SMART, PROPANE, ROUSH	1	472.31	472.31
20-Oct-20	26326	PLUG, COIL, IGNITION	1	28.12	28.12

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Oct-20	Perez,Javier	1.7	0	0
15-Oct-20	Perez,Javier	7.7	0	0
14-Oct-20	Perez,Javier	3.15	0	0
20-Oct-20	Perez,Javier	1.3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	500.43
Labor:	0.00
Labor Hours:	13.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**500.43**

Work Order Footer

Work Order 53958697 Total	
Parts:	500.43
Labor:	0.00
Labor Hours:	13.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**500.43**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53943239
Invoice No. 55345 - 53943239

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345 PER DVIR bus stalling		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	226,944 - DH

Chronology		
Reported	Oct 8, 2020 10:54:00 AM	Oct 8, 2020 10:54:00 AM
Started	Oct 8, 2020 11:26:00 AM	
Completed	Oct 9, 2020 3:02:00 PM	Oct 9, 2020 3:02:00 PM
Down Time		

Work Order Notes

Line 10 C:Vehicle is stalling

C:Check computer system found codes for lean condition, follow diagnostic test found fuel injectors extensions o-rings are damaged causing to leak vacuum

C: Replaced all o-rings and all spark plugs also one ignition coil bracket was broken so it needed to be replaced

Parts:
2 kits of o- rings f0pz-9229-a
10 spark plugs ap103
1 ignition coil 26326

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 09-OCT-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Oct 9, 2020 3:01:22 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		JAPEREZ	Oct 9, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				3:01:22 PM		
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Oct 9, 2020 3:01:22 PM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Oct 9, 2020 3:01:22 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Oct 9, 2020 3:01:22 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Oct 9, 2020 3:01:22 PM	No	
20 - Miles			JAPEREZ	Oct 9, 2020 3:01:22 PM	No	
30 - Kilometers			JAPEREZ	Oct 9, 2020 3:01:22 PM	No	
40 - Hours			JAPEREZ	Oct 9, 2020 3:01:22 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53943239
Invoice No. 55345 - 53943239

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR bus stalling
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 226,944 - DH

Activity Header
Activity: 20 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: VERIFY COMPLAINT
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Oct-20	AP103	PLUG, SPARK	10	3.17	31.7
09-Oct-20	FOPZ-9229-A	O-RING, SEAL, INJECTOR, FUEL SAME AS CM-4717	-7	14.9	-104.3
09-Oct-20	FOPZ-9229-A	O-RING, SEAL, INJECTOR, FUEL SAME AS CM-4717	9	14.9	134.1
09-Oct-20	26326	PLUG, COIL, IGNITION	1	28.12	28.12

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Oct-20	Perez,Javier	7.1	0	0
08-Oct-20	Perez,Javier	4.22	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	89.62
Labor:	0.00
Labor Hours:	11.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**89.62**

Work Order Footer

Work Order 53943239 Total	
Parts:	89.62
Labor:	0.00
Labor Hours:	11.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**89.62**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53934832
Invoice No. 55345 - 53934832

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345 PER DVIR bus stalling		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	226,503 - DH

Chronology		
Reported	Oct 6, 2020 7:52:00 AM	Oct 6, 2020 7:52:00 AM
Started	Oct 6, 2020 8:36:00 AM	
Completed	Oct 6, 2020 11:30:00 AM	Oct 6, 2020 11:30:00 AM
Down Time		

Work Order Notes

Line 10 C:Vehicle was stalling

C: Check computer system found codes for fuel delivery and lean condition

C: Perform test and road test vehicle can¿t duplicate concern at this time

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 06-OCT-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Oct 6, 2020 11:29:42 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Oct 6, 2020 11:29:42 AM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Oct 6, 2020 11:29:42 AM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Oct 6, 2020 11:29:42 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Oct 6, 2020 11:29:42 AM	No	
10 - Have you successfully completed the Personal	Done		JAPEREZ	Oct 6, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				11:29:42 AM		
20 - Miles			JAPEREZ	Oct 6, 2020 11:29:42 AM	No	
30 - Kilometers			JAPEREZ	Oct 6, 2020 11:29:42 AM	No	
40 - Hours			JAPEREZ	Oct 6, 2020 11:29:42 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53934832
Invoice No. 55345 - 53934832

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345 PER DVIR bus stalling		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	226,503 - DH

Activity Header
Activity: 20 030 ELECTRICAL GROUP
Activity Note: VERIFY COMPLAINT
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Oct-20	Perez,Javier	1.1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53934832 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53897624
Invoice No. 55345 - 53897624

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Wheelchair Lift		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	225,279 - DH

Chronology		
Reported	Sep 23, 2020 9:05:00 AM	Sep 23, 2020 9:05:00 AM
Started	Sep 23, 2020 9:10:00 AM	
Completed	Sep 24, 2020 12:36:00 PM	Sep 24, 2020 12:36:00 PM
Down Time		

Work Order Notes

Line 10 Complaint WC Lift Broken ramp.

Cause. Normal wear

Correction. Removed and replaced ramp with used good one

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 24-SEP-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Sep 24, 2020 12:32:22 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Sep 24, 2020 12:32:22 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Sep 24, 2020 12:32:22 PM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Sep 24, 2020 12:32:22 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Sep 24, 2020 12:32:22 PM	No	
10 - Have you successfully completed the	Done		RAURODRIGUEZ	Sep 24, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				12:32:22 PM		
20 - Miles			RAURODRIGUEZ	Sep 24, 2020 12:32:22 PM	No	
30 - Kilometers			RAURODRIGUEZ	Sep 24, 2020 12:32:22 PM	No	
40 - Hours			RAURODRIGUEZ	Sep 24, 2020 12:32:22 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53897624
Invoice No. 55345 - 53897624

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Wheelchair Lift		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	225,279 - DH

Activity Header
Activity: 20 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: WheelChair Lift
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Sep-20	Rodriguez,Raul	4.62	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	4.62
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53897624 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	4.62
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 53723315
Invoice No. 55345 - 53723315

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	223,308 - DH

Chronology		
Reported	Sep 2, 2020 12:00:00 AM	Sep 2, 2020 12:00:00 AM
Started	Sep 2, 2020 12:31:00 PM	
Completed	Sep 2, 2020 1:34:00 PM	Sep 2, 2020 1:34:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA SERVICE

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 02-SEP-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Sep 2, 2020 1:34:29 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Sep 2, 2020 1:34:29 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Sep 2, 2020 1:34:29 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Sep 2, 2020 1:34:29 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Sep 2, 2020 1:34:29 PM	No	
10 - Have you successfully completed the	Done		VAMRITTEEMAL	Sep 2, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				1:34:29 PM		
20 - Miles			VAMRITTEEMAL	Sep 2, 2020 1:34:29 PM	No	
30 - Kilometers			VAMRITTEEMAL	Sep 2, 2020 1:34:29 PM	No	
40 - Hours			VAMRITTEEMAL	Sep 2, 2020 1:34:29 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 53723315
Invoice No. 55345 - 53723315

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 223,308 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Sep-20	AMRIT TEEMAL,VISHNU	0.8	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 53723315
Invoice No. 55345 - 53723315

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 223,308 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Sep-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: VAMRITTEEMAL Performed on: 02-SEP-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		VAMRITTEEMAL	Sep 2, 2020 1:23:05 PM	No	
101,000 - FRA Change Oil Filters	Yes		VAMRITTEEMAL	Sep 2, 2020 1:23:05 PM	No	
102,000 - FRA Drain Engine Oil	Yes		VAMRITTEEMAL	Sep 2, 2020 1:23:05 PM	No	
103,000 - FRA Check Transmission Fluid	Done		VAMRITTEEMAL	Sep 2, 2020 1:23:05 PM	No	
104,000 - Lubricate Chassis	Done		VAMRITTEEMAL	Sep 2, 2020 1:23:05 PM	No	
105,000 - Replace or Clean A/C Filters	Done		VAMRITTEEMAL	Sep 2, 2020 1:23:05 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	VAMRITTEEMAL	Sep 2, 2020 1:23:05 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		VAMRITTEEMAL	Sep 2, 2020 1:23:05 PM	No	

Activity Sub Total

Activity 20 Sub Total
Parts: 1.96

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 53723315
Invoice No. 55345 - 53723315

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	223,308 - DH

Activity Header
Activity: 30 055/023 LIFT, WHEELCHAIR, PASSENGER
Activity Note: 55345-W/C LIFT INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: 55345-W/C LIFT INSPECTION
Task: First Transit Wheelchair Lift Inspection Performed by: VAMRITTEEMAL Performed on: 02-SEP-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Wheelchair Cycle Count	10361 Cycles		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
1,000 - A.1 Check Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
2,000 - A.2 Check Platform Emergency Release Mechanism for Ease of Operation	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
3,000 - Operate Lift Through Complete Cycle and Check for:	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
3,003 - A.3 Unusual Noises	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
3,004 - A.4 Jerky Operation	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
3,005 - A.5 Operated Too Slowly or Too Fast	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
3,006 - A.6 Drift Down	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
7,000 - A.7 Check Bridgeplate Operation	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
8,000 - A.8 Check All Pivot Points for Wear and Looseness	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
9,000 - A.9 Check Rollers for Wear and Smooth Rotation	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11,000 - A.11 Check Operation of Platform Barrier Mechanism	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
12,000 - A.12 Check Cam Slots for Wear and Proper Alignment	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
13,000 - A.13 Check Cable Condition (If Applicable)	-	n/a	VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
14,000 - A.14 Check Hydraulic Hoses for Leaks, Chafing or Cracks	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
15,000 - A.15 Check Electrical Connections and Routing of Wires and Cables	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
16,000 - A.16 Check Operation and Adjustment of All Safety Switches	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
17,000 - A.17 Check All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
18,000 - A.18 Check the Manual Back-up Raise/Lower System (If Applicable)	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
19,000 - A.19 Check HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
20,000 - A.20 Are Operator Decals in Place? Consult Service Manual for Information.	Yes		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
21,000 - A.21 Check WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
90,000 - Clean all Linkages and Mechanisms If Needed before Lubrication	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
91,000 - Lubricate (Don¿t OVER Lubricate)	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
100,000 - B.1 Emergency Platform Release Mechanism	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
200,000 - B.2 Platform Barrier Latch Mechanism	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
300,000 - B.3 Bridgeplate Hinge	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
400,000 - B.4 All Pivot Points	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
500,000 - B.5 Cams and Slots	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
600,000 - B.6 Rollers	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	
700,000 - B.7 All Linkages	Done		VAMRITTEEMAL	Sep 2, 2020 1:24:29 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53723315 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.80

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53826287
Invoice No. 55345 - 53826287

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Replace Coolant Tank		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	222,848 - DH

Chronology		
Reported	Aug 28, 2020 11:28:00 PM	Aug 28, 2020 11:28:00 PM
Started	Aug 31, 2020 12:08:00 PM	
Completed	Aug 31, 2020 1:01:00 PM	Aug 31, 2020 1:01:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:coolant tank was leaking and cover penal Lower dash broke

Cause: preventive maintenance

Correction: replaced coolant tank and added coolant,and lover cover dash

Parts: 603-811,9c2z,1504459-aa

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 31-AUG-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-	Aug 31, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	12:53:56 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Aug 31, 2020 12:53:56 PM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Aug 31, 2020 12:53:56 PM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Aug 31, 2020 12:53:56 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Aug 31, 2020 12:53:56 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Aug 31, 2020 12:53:56 PM	No	
20 - Miles			NPIERRE-LOUIS	Aug 31, 2020 12:53:56 PM	No	
30 - Kilometers			NPIERRE-LOUIS	Aug 31, 2020 12:53:56 PM	No	
40 - Hours			NPIERRE-LOUIS	Aug 31, 2020 12:53:56 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53826287
Invoice No. 55345 - 53826287

Client Department:
Department: 55345M
Work Order Description
Replace Coolant Tank
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 222,848 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Replace Coolant Tank
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
31-Aug-20	9C2Z-1504459-AA	COVER, PANEL, DASH, LOWER	1	82.72	82.72
31-Aug-20	603-811	TANK, OVERFLOW, COOLANT	1	73.31	73.31

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Aug-20	NELSON PIERRE-LOUIS	0.88	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	156.03
Labor:	0.00
Labor Hours:	0.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**156.03**

Work Order Footer

Work Order 53826287 Total	
Parts:	156.03
Labor:	0.00
Labor Hours:	0.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**156.03**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53754715
Invoice No. 55345 - 53754715

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
REAR AC SYSTEM		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	220,237 - DH

Chronology		
Reported	Aug 4, 2020 12:36:00 PM	Aug 4, 2020 12:36:00 PM
Started	Aug 4, 2020 5:13:00 PM	
Completed	Aug 5, 2020 7:49:00 PM	Aug 5, 2020 7:49:00 PM
Down Time		

Work Order Notes

Line 10 Rear ac malfunction. Found that the rear ac high pressure was leaking. Remove and replaced rear ac high pressure hose.

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Aug-20	Earl Johnson	0.0666666	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 04-AUG-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Aug 4, 2020 10:19:06 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Aug 4, 2020 10:19:06 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Aug 4, 2020 10:19:06 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Aug 4, 2020 10:19:06 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Aug 4, 2020 10:19:06 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Aug 4, 2020 10:19:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			EARJOHNSON	Aug 4, 2020 10:19:06 PM	No	
30 - Kilometers			EARJOHNSON	Aug 4, 2020 10:19:06 PM	No	
40 - Hours			EARJOHNSON	Aug 4, 2020 10:19:06 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53754715
Invoice No. 55345 - 53754715

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
REAR AC SYSTEM		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	220,237 - DH

Activity Header
Activity: 20 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear A/C Looses Vaccum
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 51 Inoperative
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Aug-20	GC2Z-19972-B	LINE, PRESSURE, HIGH, A/C, E450	1	98.45	98.45

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Aug-20	Earl Johnson	5.08	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	98.45
Labor:	0.00
Labor Hours:	5.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**98.45**

Work Order Footer

Work Order 53754715 Total	
Parts:	98.45
Labor:	0.00
Labor Hours:	5.15
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**98.45**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53740982
Invoice No. 55345 - 53740982

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Battery Light)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 219,701 - DH

Chronology		
Reported	Jul 29, 2020 9:40:00 PM	Jul 29, 2020 9:40:00 PM
Started	Jul 29, 2020 9:44:00 PM	
Completed	Jul 29, 2020 11:19:00 PM	Jul 29, 2020 11:19:00 PM
Down Time		

Work Order Notes

Line 10 Hard Cranking. Check Charging System before charging At(13.68) Check Batteries Found (1) Battery Bad. Replace batteries & Recheck Charging System now Charging At (14.16). Could not verify batteries Light. Replace batteries tray spring,
Parts # 0499252 Qty (1)
Parts # DieHard AGM 34 Qty (1)

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 29-JUL-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jul 29, 2020 10:54:20 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jul 29, 2020 10:54:20 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jul 29, 2020 10:54:20 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jul 29, 2020 10:54:20 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jul 29, 2020 10:54:20 PM	No	
10 - Have you successfully completed the Personal	Done		DARTHURS	Jul 29, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				10:54:20 PM		
20 - Miles			DARTHURS	Jul 29, 2020 10:54:20 PM	No	
30 - Kilometers			DARTHURS	Jul 29, 2020 10:54:20 PM	No	
40 - Hours			DARTHURS	Jul 29, 2020 10:54:20 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53740982
Invoice No. 55345 - 53740982

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Battery Light)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 219,701 - DH

Activity Header
Activity: 20 031/000/000 CHARGING
Activity Note: VERIFY COMPLAINT
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Jul-20	Arthurs,Durvin	0.35	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53740982
Invoice No. 55345 - 53740982

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Battery Light)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 219,701 - DH

Activity Header
Activity: 30 031/000/000 CHARGING
Activity Note: Battery Light On
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Jul-20	0499252	SPRING, TRAY, BATTERY	1	2.92	2.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Jul-20	Arthurs,Durvin	0.78	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	2.92
Labor:	0.00
Labor Hours:	0.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.92**

Work Order Footer

Work Order 53740982 Total	
Parts:	2.92
Labor:	0.00
Labor Hours:	1.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 53616686
Invoice No. 55345 - 53616686

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMC		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	219,028 - DH

Chronology		
Reported	Jul 22, 2020 12:00:00 AM	Jul 22, 2020 12:00:00 AM
Started	Jul 22, 2020 7:05:00 PM	
Completed	Jul 23, 2020 12:30:00 AM	Jul 23, 2020 12:30:00 AM
Down Time		

Work Order Notes

Line 10 PMC
Service
Perform PMC service
Oil filter B329 Qty1
Engine oil 10w30 qty 7 qts
Transmission filter 20021 Qty1
Transmission fluid 10 qts

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 22-JUL-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Jul 22, 2020 7:05:33 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Jul 22, 2020 7:05:33 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Jul 22, 2020 7:05:33 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Jul 22, 2020 7:05:33 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Jul 22, 2020 7:05:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jul 22, 2020 7:05:33 PM	No	
20 - Miles			RGASPARD	Jul 22, 2020 7:05:33 PM	No	
30 - Kilometers			RGASPARD	Jul 22, 2020 7:05:33 PM	No	
40 - Hours			RGASPARD	Jul 22, 2020 7:05:33 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 53616686
Invoice No. 55345 - 53616686

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMC		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	219,028 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Jul-20	Gaspard,Ronald	1.58	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 53616686
Invoice No. 55345 - 53616686

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMC
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 219,028 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Jul-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96
22-Jul-20	20021	FILTER, TRANSMISSION 20021	1	17.27	17.27

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Jul-20	Gaspard,Ronald	1.35	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: RGASPARD Performed on: 22-JUL-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jul 22, 2020 10:38:52 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jul 22, 2020 10:38:52 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jul 22, 2020 10:38:52 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jul 22, 2020 10:38:52 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Jul 22, 2020 10:38:52 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jul 22, 2020 10:38:52 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	na	RGASPARD	Jul 22, 2020 10:38:52 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jul 22, 2020 10:38:52 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Jul 22, 2020 10:38:52 PM	No	
201,000 - Service Crankcase Breather	Done		RGASPARD	Jul 22, 2020 10:38:52 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		RGASPARD	Jul 22, 2020 10:38:52 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Jul 22, 2020 10:38:52 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Jul 22, 2020 10:38:52 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		RGASPARD	Jul 22, 2020 10:38:52 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		RGASPARD	Jul 22, 2020 10:38:52 PM	No	
302,000 - Check Toe-In and Record Reading	-	na	RGASPARD	Jul 22, 2020 10:38:52 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	na	RGASPARD	Jul 22, 2020 10:38:52 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		RGASPARD	Jul 22, 2020 10:38:52 PM	No	
305,000 - FRA Change Differential Fluid	Yes		RGASPARD	Jul 22, 2020 10:38:52 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	19.23
Labor:	0.00
Labor Hours:	1.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**19.23**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 53616686
Invoice No. 55345 - 53616686

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMC
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 219,028 - DH

Activity Header
Activity: 30 055/023 LIFT, WHEELCHAIR, PASSENGER
Activity Note: 55345-W/C LIFT INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Jul-20	Gaspard,Ronald	0.55	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: 55345-W/C LIFT INSPECTION
Task: First Transit Wheelchair Lift Inspection Performed by: RGASPARD Performed on: 22-JUL-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Wheelchair Cycle Count	10102 Cycles		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
1,000 - A.1 Check Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
2,000 - A.2 Check Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
3,000 - Operate Lift Through Complete Cycle and Check for:	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
3,003 - A.3 Unusual Noises	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
3,004 - A.4 Jerky Operation	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
3,005 - A.5 Operated Too Slowly or Too Fast	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
3,006 - A.6 Drift Down	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
7,000 - A.7 Check Bridgeplate Operation	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
8,000 - A.8 Check All Pivot Points for Wear and Looseness	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
9,000 - A.9 Check Rollers for Wear and Smooth Rotation	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
11,000 - A.11 Check Operation of Platform Barrier Mechanism	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
12,000 - A.12 Check Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
13,000 - A.13 Check Cable Condition (If Applicable)	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
14,000 - A.14 Check Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
15,000 - A.15 Check Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
16,000 - A.16 Check Operation and Adjustment of All Safety Switches	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
17,000 - A.17 Check All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
18,000 - A.18 Check the Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
19,000 - A.19 Check HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
20,000 - A.20 Are Operator Decals in Place? Consult Service Manual for Information.	Yes		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
21,000 - A.21 Check WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
90,000 - Clean all Linkages and Mechanisms If Needed before Lubrication	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
91,000 - Lubricate (Don¿t OVER Lubricate)	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
100,000 - B.1 Emergency Platform Release Mechanism	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
200,000 - B.2 Platform Barrier Latch Mechanism	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
300,000 - B.3 Bridgeplate Hinge	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
400,000 - B.4 All Pivot Points	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
500,000 - B.5 Cams and Slots	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
600,000 - B.6 Rollers	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	
700,000 - B.7 All Linkages	Done		RGASPARD	Jul 22, 2020 10:04:44 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53616686 Total	
Parts:	19.23

	Labor:	0.00
	Labor Hours:	3.48
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**19.23**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53696239
Invoice No. 55345 - 53696239

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Wheelchair Lift		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	218,028 - DH

Chronology		
Reported	Jul 14, 2020 4:31:14 PM	Jul 14, 2020 4:31:14 PM
Started	Jul 14, 2020 12:00:00 AM	
Completed	Jul 14, 2020 4:35:00 PM	Jul 14, 2020 4:35:00 PM
Down Time		

Work Order Notes

Line 10 Replaced inner barrier Raised Switch

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 14-JUL-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jul 14, 2020 4:35:14 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jul 14, 2020 4:35:14 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Jul 14, 2020 4:35:14 PM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Jul 14, 2020 4:35:14 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jul 14, 2020 4:35:14 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jul 14, 2020 4:35:14 PM	No	
20 - Miles			TDELVA	Jul 14, 2020 4:35:14 PM	No	
30 - Kilometers			TDELVA	Jul 14, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				4:35:14 PM		
40 - Hours			TDELVA	Jul 14, 2020 4:35:14 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53696239
Invoice No. 55345 - 53696239

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Wheelchair Lift		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	218,028 - DH

Activity Header
Activity: 20 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: WheelChair Lift
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Jul-20	32519KS	SWITCH, RAISED, W/C	1	28.79	28.79
14-Jul-20	32408	BUMPER, RUBBER, W/C, BRAUN SAME AS 32408-10KS	2	1.31	2.62

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Jul-20	Delva,Terry	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	31.41
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**31.41**

Work Order Footer

Work Order 53696239 Total	
Parts:	31.41
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**31.41**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53693246
Invoice No. 55345 - 53693246

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Right Front Signal Dont Work)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 217,854 - DH

Chronology		
Reported	Jul 13, 2020 7:39:00 PM	Jul 13, 2020 7:39:00 PM
Started	Jul 13, 2020 10:26:00 PM	
Completed	Jul 14, 2020 12:25:00 AM	Jul 14, 2020 12:25:00 AM
Down Time		

Work Order Notes

Line 10 Driver complained of the RF turn signal not working. Remove and replaced turn signal bulb.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Jul-20	Earl Johnson	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 13-JUL-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jul 13, 2020 11:21:25 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jul 13, 2020 11:21:25 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jul 13, 2020 11:21:25 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jul 13, 2020 11:21:25 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jul 13, 2020 11:21:25 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jul 13, 2020 11:21:25 PM	No	
20 - Miles			EARJOHNSON	Jul 13, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:21:25 PM		
30 - Kilometers			EARJOHNSON	Jul 13, 2020 11:21:25 PM	No	
40 - Hours			EARJOHNSON	Jul 13, 2020 11:21:25 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53693246
Invoice No. 55345 - 53693246

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Right Front Signal Dont Work)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 217,854 - DH

Activity Header
Activity: 20 034 LIGHTING SYSTEM
Activity Note: VERIFY COMPLAINT
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Jul-20	Earl Johnson	0.9	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.90
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53693246 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53678766
Invoice No. 55345 - 53678766

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Brakes, Battery Light On)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 217,235 - DH

Chronology		
Reported	Jul 7, 2020 8:39:00 PM	Jul 7, 2020 8:39:00 PM
Started	Jul 8, 2020 12:26:00 AM	
Completed	Jul 8, 2020 12:32:00 AM	Jul 8, 2020 12:32:00 AM
Down Time		

Work Order Notes

Line 10 Road tested vehicle with no issues. Brakes work properly, no battery light illuminated. Could not duplicate issues. Will monitor.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Jul-20	Earl Johnson	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 08-JUL-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jul 8, 2020 12:27:08 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jul 8, 2020 12:27:08 AM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jul 8, 2020 12:27:08 AM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jul 8, 2020 12:27:08 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jul 8, 2020 12:27:08 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jul 8, 2020 12:27:08 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			EARJOHNSON	Jul 8, 2020 12:27:08 AM	No	
30 - Kilometers			EARJOHNSON	Jul 8, 2020 12:27:08 AM	No	
40 - Hours			EARJOHNSON	Jul 8, 2020 12:27:08 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53678766
Invoice No. 55345 - 53678766

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Brakes, Battery Light On)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 217,235 - DH

Activity Header
Activity: 20 013 BRAKES
Activity Note: VERIFY COMPLAINT
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Jul-20	Earl Johnson	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53678766 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53661014
Invoice No. 55345 - 53661014

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
REAR AC SYSTEM		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	216,488 - DH

Chronology		
Reported	Jun 30, 2020 2:06:00 PM	Jun 30, 2020 2:06:00 PM
Started	Jun 30, 2020 7:11:00 PM	
Completed	Jun 30, 2020 10:29:00 PM	Jun 30, 2020 10:29:00 PM
Down Time		

Work Order Notes

Line 10 Check Rear A/C & Found Low Side going into Vacuum .possible Blockage in Low Side. Evacuate. Replace Orifice tube & Recharge. All seem to be ok at this time.
Parts # 3411885 Qty (1)
Freon Qty(4.0) lbs add (2) Oz Oil.

Activity Header

Activity:	10 999/999/999 TOTAL VEHICLE
Activity Note:	
Reason for Repair:	SW Shop Work Order
Work Accomplished:	06 Inspect
Part Failure:	00 No Failure
Activity Comments:	

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 30-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jun 30, 2020 10:17:20 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jun 30, 2020 10:17:20 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jun 30, 2020 10:17:20 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jun 30, 2020 10:17:20 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jun 30, 2020 10:17:20 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jun 30, 2020 10:17:20 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			DARTHURS	Jun 30, 2020 10:17:20 PM	No	
30 - Kilometers			DARTHURS	Jun 30, 2020 10:17:20 PM	No	
40 - Hours			DARTHURS	Jun 30, 2020 10:17:20 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53661014
Invoice No. 55345 - 53661014

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
REAR AC SYSTEM		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	216,488 - DH

Activity Header
Activity: 20 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Check Rear A/C System
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Jun-20	3411885	TUBE, ORIFICE, A/C, FORD	1	0.75	0.75

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Jun-20	Arthurs,Durvin	3.27	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.75
Labor:	0.00
Labor Hours:	3.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.75**

Work Order Footer

Work Order 53661014 Total	
Parts:	0.75
Labor:	0.00
Labor Hours:	3.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53658589
Invoice No. 55345 - 53658589

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Washer Not Working)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 216,332 - DH

Chronology		
Reported	Jun 29, 2020 8:20:00 PM	Jun 29, 2020 8:20:00 PM
Started	Jun 29, 2020 8:24:00 PM	
Completed	Jun 29, 2020 8:26:00 PM	Jun 29, 2020 8:26:00 PM
Down Time		

Work Order Notes

Line 10

Replace Nozzle washer

part# 3W7Z-17603-AA QTY 1

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 29-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		AOWENS	Jun 29, 2020 8:26:28 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		AOWENS	Jun 29, 2020 8:26:28 PM	No	
3 - Are you wearing the appropriate PPE?	Done		AOWENS	Jun 29, 2020 8:26:28 PM	No	
4 - Have you performed the proper LOTO?	Done		AOWENS	Jun 29, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:26:28 PM		
5 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	Jun 29, 2020 8:26:28 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Jun 29, 2020 8:26:28 PM	No	
20 - Miles			AOWENS	Jun 29, 2020 8:26:28 PM	No	
30 - Kilometers			AOWENS	Jun 29, 2020 8:26:28 PM	No	
40 - Hours			AOWENS	Jun 29, 2020 8:26:28 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53658589
Invoice No. 55345 - 53658589

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345 PER DVIR (Washer Not Working)		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	216,332 - DH

Activity Header
Activity: 20 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: VERIFY COMPLAINT
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53658589
Invoice No. 55345 - 53658589

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Washer Not Working)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 216,332 - DH

Activity Header
Activity: 30 050 GROUP, ACCESSORIES
Activity Note: Replace Nozzle Washer
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Jun-20	3W7Z-17603-AA	NOZZLE, WASHER, WINDSHIELD	1	4.9	4.9

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Jun-20	Owens,Arthur	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	4.90
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.90**

Work Order Footer

Work Order 53658589 Total	
Parts:	4.90
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.90**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53647993
Invoice No. 55345 - 53647993

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Engine Light On) P0420 CAT
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 215,975 - DH

Chronology		
Reported	Jun 24, 2020 11:40:00 PM	Jun 24, 2020 11:40:00 PM
Started	Jun 24, 2020 12:00:00 AM	
Completed	Jun 26, 2020 7:53:00 AM	Jun 26, 2020 7:53:00 AM
Down Time		

Work Order Notes

Line 10 Engine light on

Catalytic converters

Replaced catalytic converters completed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 26-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Jun 26, 2020 7:53:32 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Jun 26, 2020 7:53:32 AM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Jun 26, 2020 7:53:32 AM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Jun 26, 2020 7:53:32 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Jun 26, 2020 7:53:32 AM	No	
10 - Have you successfully completed the Personal	Done		HPIERRE	Jun 26, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				7:53:32 AM		
20 - Miles			HPIERRE	Jun 26, 2020 7:53:32 AM	No	
30 - Kilometers	1		HPIERRE	Jun 26, 2020 7:53:32 AM	No	
40 - Hours			HPIERRE	Jun 26, 2020 7:53:32 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53647993
Invoice No. 55345 - 53647993

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Engine Light On) P0420 CAT
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 215,975 - DH

Activity Header
Activity: 20 030 ELECTRICAL GROUP
Activity Note: CATALYTIC CONVERTER REPLACED
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Jun-20	Pierre,Hubert J	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53647993 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53647798
Invoice No. 55345 - 53647798

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Engine Light On)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 215,975 - DH

Chronology		
Reported	Jun 24, 2020 7:34:00 PM	Jun 24, 2020 7:34:00 PM
Started		
Completed	Jun 25, 2020 12:01:00 AM	Jun 25, 2020 12:01:00 AM
Down Time		

Work Order Notes

Line 10 Driver complained of the check engine light being illuminated. Scanned vehicle and confirmed codeP0420.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 24-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jun 24, 2020 11:11:03 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jun 24, 2020 11:11:03 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jun 24, 2020 11:11:03 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jun 24, 2020 11:11:03 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jun 24, 2020 11:11:03 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jun 24, 2020 11:11:03 PM	No	
20 - Miles			EARJOHNSON	Jun 24, 2020 11:11:03 PM	No	
30 - Kilometers			EARJOHNSON	Jun 24, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:11:03 PM		
40 - Hours			EARJOHNSON	Jun 24, 2020 11:11:03 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53647798
Invoice No. 55345 - 53647798

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Engine Light On)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 215,975 - DH

Activity Header
Activity:20 043/000/000 EXHAUST SYSTEM
Activity Note: VERIFY COMPLAINT (Check Engine Light On)
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Jun-20	Earl Johnson	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53647798 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53633645
Invoice No. 55345 - 53633645

Client Department:
Department: 55345M
Work Order Description
Road Call (Wheel Chair Lift Loosing Power)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 215,391 - DH

Chronology		
Reported	Jun 18, 2020 4:20:00 PM	Jun 18, 2020 4:20:00 PM
Started	Jun 18, 2020 4:22:00 PM	
Completed	Jun 18, 2020 5:33:00 PM	Jun 18, 2020 5:33:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:driver complained lift not working

Cause: no problem

Correction:check the lift ; it works fine.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 18-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Jun 18, 2020 4:22:26 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		RGASPARD	Jun 18, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				4:22:26 PM		
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Jun 18, 2020 4:22:26 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Jun 18, 2020 4:22:26 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Jun 18, 2020 4:22:26 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jun 18, 2020 4:22:26 PM	No	
20 - Miles			RGASPARD	Jun 18, 2020 4:22:26 PM	No	
30 - Kilometers			RGASPARD	Jun 18, 2020 4:22:26 PM	No	
40 - Hours			RGASPARD	Jun 18, 2020 4:22:26 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53633645
Invoice No. 55345 - 53633645

Client Department:
Department: 55345M
Work Order Description
Road Call (Wheel Chair Lift Loosing Power)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 215,391 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Jun-20	Gaspard,Ronald	1.17	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53633645 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 53558499
Invoice No. 55345 - 53558499

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	**Status:**	40 - Closed (40)
Created By:	NSTOLFO	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	214,778 - DH

Chronology		
Reported	Jun 11, 2020 3:16:09 PM	Jun 11, 2020 3:16:09 PM
Started	Jun 11, 2020 8:22:00 PM	
Completed	Jun 12, 2020 12:31:00 AM	Jun 12, 2020 12:31:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE: Service

CORRECTION: perform pmA service
Oil filter B329 qty1
Engine oil 10w30 qty 7 Qts

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 11-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Jun 11, 2020 8:22:10 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Jun 11, 2020 8:22:10 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Jun 11, 2020 8:22:10 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Jun 11, 2020 8:22:10 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Jun 11, 2020 8:22:10 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jun 11, 2020 8:22:10 PM	No	
20 - Miles			RGASPARD	Jun 11, 2020 8:22:10 PM	No	
30 - Kilometers			RGASPARD	Jun 11, 2020 8:22:10 PM	No	
40 - Hours			RGASPARD	Jun 11, 2020 8:22:10 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 53558499
Invoice No. 55345 - 53558499

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	**Status:**	40 - Closed (40)
Created By:	NSTOLFO	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	214,778 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Jun-20	Gaspard,Ronald	1.77	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 53558499
Invoice No. 55345 - 53558499

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: NSTOLFO
Created By: NSTOLFO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 214,778 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Jun-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Jun-20	Gaspard,Ronald	0.38	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 11-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jun 11, 2020 10:09:07 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jun 11, 2020 10:09:07 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jun 11, 2020 10:09:07 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jun 11, 2020 10:09:07 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Jun 11, 2020 10:09:07 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jun 11, 2020 10:09:07 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Jun 11, 2020 10:09:07 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jun 11, 2020 10:09:07 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	0.38
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 53558499
Invoice No. 55345 - 53558499

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	**Status:**	40 - Closed (40)
Created By:	NSTOLFO	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	214,778 - DH

Activity Header
Activity: 30 055/023 LIFT, WHEELCHAIR, PASSENGER
Activity Note: 55345-W/C LIFT INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Jun-20	Gaspard,Ronald	0.43	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: 55345-W/C LIFT INSPECTION
Task: First Transit Wheelchair Lift Inspection Performed by: RGASPARD Performed on: 11-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Wheelchair Cycle Count	9902 Cycles		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
1,000 - A.1 Check Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
2,000 - A.2 Check Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
3,000 - Operate Lift Through Complete Cycle and Check for:	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
3,003 - A.3 Unusual Noises	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
3,004 - A.4 Jerky Operation	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
3,005 - A.5 Operated Too Slowly or Too Fast	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
3,006 - A.6 Drift Down	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
7,000 - A.7 Check Bridgeplate Operation	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
8,000 - A.8 Check All Pivot Points for Wear and Looseness	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
9,000 - A.9 Check Rollers for Wear and Smooth Rotation	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
11,000 - A.11 Check Operation of Platform Barrier Mechanism	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
12,000 - A.12 Check Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
13,000 - A.13 Check Cable Condition (If Applicable)	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
14,000 - A.14 Check Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
15,000 - A.15 Check Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
16,000 - A.16 Check Operation and Adjustment of All Safety Switches	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
17,000 - A.17 Check All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
18,000 - A.18 Check the Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
19,000 - A.19 Check HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
20,000 - A.20 Are Operator Decals in Place? Consult Service Manual for Information.	Yes		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
21,000 - A.21 Check WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
90,000 - Clean all Linkages and Mechanisms If Needed before Lubrication	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
91,000 - Lubricate (Don¿t OVER Lubricate)	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
100,000 - B.1 Emergency Platform Release Mechanism	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
200,000 - B.2 Platform Barrier Latch Mechanism	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
300,000 - B.3 Bridgeplate Hinge	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
400,000 - B.4 All Pivot Points	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
500,000 - B.5 Cams and Slots	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
600,000 - B.6 Rollers	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	
700,000 - B.7 All Linkages	Done		RGASPARD	Jun 11, 2020 10:34:25 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53558499 Total	
Parts:	1.96

	Labor:	0.00
	Labor Hours:	2.58
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53616323
Invoice No. 55345 - 53616323

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Wheel Chair Bags Ripped)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 214,778 - DH

Chronology		
Reported	Jun 11, 2020 5:18:00 PM	Jun 11, 2020 5:18:00 PM
Started		
Completed	Jun 11, 2020 5:26:00 PM	Jun 11, 2020 5:26:00 PM
Down Time		

Work Order Notes

Line 10

Complaint wheel chair bags ripped

Cause Normal wear and tear

Correction Replace 4 wheel chair bags

Parts# Q5-8522 Qty 4

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
10 Desc: PRA Task: PRA and Meter Readings Performed by: AOWENS Performed on: 11-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		AOWENS	Jun 11, 2020 5:26:15 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		AOWENS	Jun 11, 2020 5:26:15 PM	No	
3 - Are you wearing the appropriate PPE?	Done		AOWENS	Jun 11, 2020 5:26:15 PM	No	
4 - Have you performed the proper LOTO?	Done		AOWENS	Jun 11, 2020 5:26:15 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	Jun 11, 2020 5:26:15 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Jun 11, 2020 5:26:15 PM	No	
20 - Miles			AOWENS	Jun 11, 2020 5:26:15 PM	No	
30 - Kilometers			AOWENS	Jun 11, 2020 5:26:15 PM	No	
40 - Hours			AOWENS	Jun 11, 2020 5:26:15 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53616323
Invoice No. 55345 - 53616323

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Wheel Chair Bags Ripped)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 214,778 - DH

Activity Header
Activity: 20 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: VERIFY COMPLAINT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53616323
Invoice No. 55345 - 53616323

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Wheel Chair Bags Ripped)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 214,778 - DH

Activity Header
Activity: 30 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: Replace wheel chair bags
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Jun-20	Q5-8522	POUCH, STORAGE, Q-STRAINT, NYLON	4	33.37	133.48

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	133.48
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**133.48**

Work Order Footer

Work Order 53616323 Total	
Parts:	133.48
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**133.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53603726
Invoice No. 55345 - 53603726

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Both A/C Blow Warm & Bus Shakes At High Speed
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 214,184 - DH

Chronology		
Reported	Jun 5, 2020 10:37:00 PM	Jun 5, 2020 10:37:00 PM
Started	Jun 7, 2020 12:38:00 PM	
Completed	Jun 7, 2020 4:40:00 PM	Jun 7, 2020 4:40:00 PM
Down Time		

Work Order Notes

Line 10 Engine Misfire / Front &Rear A/C blown hot air Front A/C not Working Because of misfire. Scan bus found Code PO300 / PO 302 / PO305 Misfire Replace # (5) coil & Booth& Swap # (2) Coil.& Clear Code no misfire at this time Evacuate Rear A/C found rear Orifice tube clogged Replace Orifice tube. Vacuum Recharge System. Swap thermostat switch. Balance Both front tire & Road test. Cannot charge out coil.
Parts # 3411885,Qty (1)
Parts # 26326. Qty (1)
Freon Qty 4.0 lbs & add 4 Oz oil

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 07-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jun 7, 2020 4:40:29 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jun 7, 2020 4:40:29 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jun 7, 2020 4:40:29 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jun 7, 2020 4:40:29 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jun 7, 2020 4:40:29 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jun 7, 2020 4:40:29 PM	No	
20 - Miles			DARTHURS	Jun 7, 2020 4:40:29 PM	No	
30 - Kilometers			DARTHURS	Jun 7, 2020 4:40:29 PM	No	
40 - Hours			DARTHURS	Jun 7, 2020 4:40:29 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53603726
Invoice No. 55345 - 53603726

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Both A/C Blow Warm & Bus Shakes At High Speed
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 214,184 - DH

Activity Header
Activity: 20 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: VERIFY COMPLAINT
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Jun-20	3411885	TUBE, ORIFICE, A/C, FORD	1	0.75	0.75

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Jun-20	Arthurs,Durvin	3.72	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.75
Labor:	0.00
Labor Hours:	3.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.75**

Work Order Footer

Work Order 53603726 Total	
Parts:	0.75
Labor:	0.00
Labor Hours:	3.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53594691
Invoice No. 55345 - 53594691

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Bus Shakes While Driving Causes it to Stall)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 213,944 - DH

Chronology		
Reported	Jun 2, 2020 10:56:00 PM	Jun 2, 2020 10:56:00 PM
Started	Jun 3, 2020 8:37:00 AM	
Completed	Jun 4, 2020 5:16:00 AM	Jun 4, 2020 5:16:00 AM
Down Time		

Work Order Notes

Line 10
Spark plug

COMPLAINT:
Manufacturer recommended spark plug service by mileage

CAUSE:
Normal wear.

CORRECTION:
Removed all spark plugs and spark plug boots. Replaced them with new spark plugs and spark plug boots. Applied dielectric grease to the the spring inside the spark plug boot.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
10 Desc: PRA Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 03-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Jun 3, 2020 2:55:33 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Jun 3, 2020 2:55:33 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Jun 3, 2020 2:55:33 PM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Jun 3, 2020 2:55:33 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Jun 3, 2020 2:55:33 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Jun 3, 2020 2:55:33 PM	No	
20 - Miles			RAURODRIGUEZ	Jun 3, 2020 2:55:33 PM	No	
30 - Kilometers			RAURODRIGUEZ	Jun 3, 2020 2:55:33 PM	No	
40 - Hours			RAURODRIGUEZ	Jun 3, 2020 2:55:33 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53594691
Invoice No. 55345 - 53594691

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Bus Shakes While Driving Causes it to Stall)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 213,944 - DH

Activity Header
Activity: 20 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: VERIFY COMPLAINT
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jun-20	Delva,Terry	0.45	0	0
03-Jun-20	Rodriguez,Raul	2.23	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53594691
Invoice No. 55345 - 53594691

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Bus Shakes While Driving Causes it to Stall)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 213,944 - DH

Activity Header
Activity: 30 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Bad spark plug
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Jun-20	AP103	PLUG, SPARK	10	3.16	31.6
03-Jun-20	26326	PLUG, COIL, IGNITION	1	28.12	28.12
03-Jun-20	357006	BOOT, COIL-ON-PLUG, IGNITION	10	4.36	43.6

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jun-20	Rodriguez,Raul	3.47	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	103.32
Labor:	0.00
Labor Hours:	3.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**103.32**

Work Order Footer

Work Order 53594691 Total	
Parts:	103.32
Labor:	0.00
Labor Hours:	6.15
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**103.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 53511388
Invoice No. 55345 - 53511388

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP---> Replace 2 left Rear Tires
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 210,629 - DH

Chronology		
Reported	Apr 28, 2020 10:00:43 PM	Apr 28, 2020 10:00:43 PM
Started	Apr 28, 2020 10:04:00 PM	
Completed	Apr 28, 2020 10:55:00 PM	Apr 28, 2020 10:55:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========
To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.
==========

Complaint (3) Rear Tires

Cause: Tires Worn below Spec.

Correction: Mount &Balance (2) Tires & Replace On L/R Swap R/R inner tire with A good use tire tread depth 9/32.
Parts #192659 Qty (2)

Activity Header
Activity: 10 017/008/004 CAP, VALVE, TIRE
Activity Note: Replace (3) Rear tire
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Apr-20	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	117.62	235.24

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Apr-20	Arthurs,Durvin	0.85	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	235.24
Labor:	0.00
Labor Hours:	0.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**235.24**

Work Order Footer

Work Order 53511388 Total	
Parts:	235.24
Labor:	0.00
Labor Hours:	0.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**235.24**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53383450
Invoice No. 55345 - 53383450

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	210,629 - DH

Chronology		
Reported	Apr 28, 2020 11:00:34 AM	Apr 28, 2020 11:00:34 AM
Started	Apr 28, 2020 6:30:00 PM	
Completed	Apr 28, 2020 10:02:00 PM	Apr 28, 2020 10:02:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA Service

CAUSE: Service Due by Mileage.

CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check brakes . clean batteries . Replace batteries tray spring. Replace A/C filter.
Parts # B329 Qty (1)
Oil 5W20QTY (7.0) Qt

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Apr-20	Arthurs,Durvin	2.35	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53383450
Invoice No. 55345 - 53383450

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 210,629 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Apr-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Apr-20	Arthurs,Durvin	0.4	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 28-APR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Apr 28, 2020 8:53:19 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Apr 28, 2020 8:53:19 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Apr 28, 2020 8:53:19 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Apr 28, 2020 8:53:19 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Apr 28, 2020 8:53:19 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Apr 28, 2020 8:53:19 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Apr 28, 2020 8:53:19 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Apr 28, 2020 8:53:19 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	0.40
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53383450
Invoice No. 55345 - 53383450

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	210,629 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 28-APR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Apr 28, 2020 8:54:07 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Apr 28, 2020 8:54:07 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Apr 28, 2020 8:54:07 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Apr 28, 2020 8:54:07 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Apr 28, 2020 8:54:07 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 28, 2020 8:54:07 PM	No	
20 - Miles			DARTHURS	Apr 28, 2020 8:54:07 PM	No	
30 - Kilometers			DARTHURS	Apr 28, 2020 8:54:07 PM	No	
40 - Hours			DARTHURS	Apr 28, 2020 8:54:07 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53383450 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53506791
Invoice No. 55345 - 53506791

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Engine light is on		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	210,469 - DH

Chronology		
Reported	Apr 27, 2020 11:27:59 AM	Apr 27, 2020 11:27:59 AM
Started	Apr 27, 2020 11:29:00 AM	
Completed	Apr 27, 2020 1:09:00 PM	Apr 27, 2020 1:09:00 PM
Down Time		

Work Order Notes

Line 10 Engine light is on

P2197 02Sensor

Replace 02 Sensor completed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 27-APR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Apr 27, 2020 12:38:32 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Apr 27, 2020 12:38:32 PM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Apr 27, 2020 12:38:32 PM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Apr 27, 2020 12:38:32 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Apr 27, 2020 12:38:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Apr 27, 2020 12:38:32 PM	No	
20 - Miles			HPIERRE	Apr 27, 2020 12:38:32 PM	No	
30 - Kilometers	1		HPIERRE	Apr 27, 2020 12:38:32 PM	No	
40 - Hours	2		HPIERRE	Apr 27, 2020 12:38:32 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53506791
Invoice No. 55345 - 53506791

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Engine light is on		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	210,469 - DH

Activity Header
Activity:20 043/000/000 EXHAUST SYSTEM
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Apr-20	8F9Z-9F472-H	SENSOR, OXYGEN	1	64.39	64.39

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Apr-20	Pierre,Hubert J	1.67	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	64.39
Labor:	0.00
Labor Hours:	1.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**64.39**

Work Order Footer

Work Order 53506791 Total	
Parts:	64.39
Labor:	0.00
Labor Hours:	1.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**64.39**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53505129
Invoice No. 55345 - 53505129

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Rear ac.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	210,323 - DH

Chronology		
Reported	Apr 26, 2020 2:47:08 PM	Apr 26, 2020 2:47:08 PM
Started	Apr 26, 2020 2:49:00 PM	
Completed	Apr 26, 2020 4:58:00 PM	Apr 26, 2020 4:58:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear ac orifice tube.

Cause: Campaign.

Correction: Remove and replaced rear ac orifice tube.
Part# 3411885 Qty.(1).

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Apr-20	Earl Johnson	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 26-APR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Apr 26, 2020 4:57:17 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Apr 26, 2020 4:57:17 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Apr 26, 2020 4:57:17 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Apr 26, 2020 4:57:17 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Apr 26, 2020 4:57:17 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Apr 26, 2020 4:57:17 PM	No	
20 - Miles			EARJOHNSON	Apr 26, 2020 4:57:17 PM	No	
30 - Kilometers			EARJOHNSON	Apr 26, 2020 4:57:17 PM	No	
40 - Hours			EARJOHNSON	Apr 26, 2020 4:57:17 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53505129
Invoice No. 55345 - 53505129

Client Department:
Department: 55345M
Work Order Description
Rear ac.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 210,323 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 24 Special Study
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Apr-20	Earl Johnson	2.12	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53505129 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53386904
Invoice No. 55345 - 53386904

Client Department:
Department: 55345M
Work Order Description
Brake Booster
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 206,643 - DH

Chronology		
Reported	Mar 15, 2020 1:50:25 PM	Mar 15, 2020 1:50:25 PM
Started	Mar 15, 2020 12:00:00 AM	
Completed	Mar 15, 2020 4:04:00 PM	Mar 15, 2020 4:04:00 PM
Down Time		

Work Order Notes

Line 10 Replaced Brake Booster

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 15-MAR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Mar 15, 2020 4:04:43 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Mar 15, 2020 4:04:43 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Mar 15, 2020 4:04:43 PM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Mar 15, 2020 4:04:43 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Mar 15, 2020 4:04:43 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Mar 15, 2020 4:04:43 PM	No	
20 - Miles			TDELVA	Mar 15, 2020 4:04:43 PM	No	
30 - Kilometers			TDELVA	Mar 15, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				4:04:43 PM		
40 - Hours			TDELVA	Mar 15, 2020 4:04:43 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53386904
Invoice No. 55345 - 53386904

Client Department:
Department: 55345M
Work Order Description
Brake Booster
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 206,643 - DH

Activity Header
Activity: 20 013 BRAKES
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Mar-20	DC2Z-2005-A	BOOSTER, BRAKE, POWER, HYDRAULIC SAME AS BRB-103	1	188.55	188.55

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Mar-20	Delva,Terry	2.35	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	188.55
Labor:	0.00
Labor Hours:	2.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**188.55**

Work Order Footer

Work Order 53386904 Total	
Parts:	188.55
Labor:	0.00
Labor Hours:	2.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**188.55**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53287898
Invoice No. 55345 - 53287898

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM B		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	206,643 - DH

Chronology		
Reported	Mar 13, 2020 11:02:13 AM	Mar 13, 2020 11:02:13 AM
Started	Mar 13, 2020 12:00:00 AM	
Completed	Mar 13, 2020 3:15:00 PM	Mar 13, 2020 3:15:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMB SERVICE

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMB SERVICE
REPLACED AIR FILTER

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Mar-20	AMRIT TEEMAL,VISHNU	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53287898
Invoice No. 55345 - 53287898

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 206,643 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Mar-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: VAMRITTEEMAL Performed on: 13-MAR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		VAMRITTEEMAL	Mar 13, 2020 3:07:19 PM	No	
101,000 - FRA Change Oil Filters	Yes		VAMRITTEEMAL	Mar 13, 2020 3:07:19 PM	No	
102,000 - FRA Drain Engine Oil	Yes		VAMRITTEEMAL	Mar 13, 2020 3:07:19 PM	No	
103,000 - FRA Check Transmission Fluid	Done		VAMRITTEEMAL	Mar 13, 2020 3:07:19 PM	No	
104,000 - Lubricate Chassis	Done		VAMRITTEEMAL	Mar 13, 2020 3:07:19 PM	No	
105,000 - Replace or Clean A/C Filters	Done		VAMRITTEEMAL	Mar 13, 2020 3:07:19 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	VAMRITTEEMAL	Mar 13, 2020 3:07:19 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		VAMRITTEEMAL	Mar 13, 2020 3:07:19 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		VAMRITTEEMAL	Mar 13, 2020 3:07:19 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
201,000 - Service Crankcase Breather	-	n/a	VAMRITTEEMAL	Mar 13, 2020 3:07:19 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No	n/a	VAMRITTEEMAL	Mar 13, 2020 3:07:19 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No	n/a	VAMRITTEEMAL	Mar 13, 2020 3:07:19 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		VAMRITTEEMAL	Mar 13, 2020 3:07:19 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53287898
Invoice No. 55345 - 53287898

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM B		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	206,643 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Mar-20	PA4075	FILTER, AIR SEE P546597	1	5.28	5.28

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 13-MAR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Mar 13, 2020 3:06:01 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Mar 13, 2020 3:06:01 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Mar 13, 2020 3:06:01 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Mar 13, 2020 3:06:01 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Mar 13, 2020 3:06:01 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Mar 13, 2020 3:06:01 PM	No	
20 - Miles			VAMRITTEEMAL	Mar 13, 2020 3:06:01 PM	No	
30 - Kilometers			VAMRITTEEMAL	Mar 13, 2020 3:06:01 PM	No	
40 - Hours			VAMRITTEEMAL	Mar 13, 2020 3:06:01 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	5.28
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**5.28**

Work Order Footer

Work Order 53287898 Total	
Parts:	7.24
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.24**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53364194
Invoice No. 55345 - 53364194

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Worn on the. right front		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	205,670 - DH

Chronology		
Reported	Mar 8, 2020 2:42:17 PM	Mar 8, 2020 2:42:17 PM
Started		
Completed	Mar 8, 2020 6:13:00 PM	Mar 8, 2020 6:13:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Vehicle came for pulling to the right

Cause: Worn out tires

Correction: Check front end on After replace two new tires to front of vehicle take unit for road test now working as design return vehicle back to work

Line 20 UNIT WAS SENT TO ATLANTIC BUS SALES FOR WHEEL ALIGNAMENT

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: JUHURST Performed on: 08-MAR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Mar 8, 2020 6:12:51 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Mar 8, 2020 6:12:51 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Mar 8, 2020 6:12:51 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Mar 8, 2020 6:12:51 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Mar 8, 2020 6:12:51 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Mar 8, 2020 6:12:51 PM	No	
20 - Miles		N/A	JUHURST	Mar 8, 2020 6:12:51 PM	No	
30 - Kilometers		N/A	JUHURST	Mar 8, 2020 6:12:51 PM	No	
40 - Hours		N/A	JUHURST	Mar 8, 2020 6:12:51 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53364194
Invoice No. 55345 - 53364194

Client Department:
Department: 55345M
Work Order Description
Worn on the. right front
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 205,670 - DH

Activity Header
Activity: 15 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note: Worn tire right front
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Mar-20	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	117.62	235.24

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	235.24
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**235.24**

Work Order Footer

Work Order 53364194 Total	
Parts:	235.24
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**235.24**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53335030
Invoice No. 55345 - 53335030

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Blend Door Actuator		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	204,999 - DH

Chronology		
Reported	Feb 28, 2020 5:16:20 PM	Feb 28, 2020 5:16:20 PM
Started	Feb 28, 2020 5:28:00 PM	
Completed	Mar 6, 2020 10:01:00 AM	Mar 6, 2020 10:01:00 AM
Down Time		

Work Order Notes

Line 10 Complaint: No heat in front AC

Cause: defective blend door actuator

Correction: Replaced Blend door Actuator
Please charge part

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 28-FEB-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Feb 28, 2020 7:16:52 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Feb 28, 2020 7:16:52 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Feb 28, 2020 7:16:52 PM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Feb 28, 2020 7:16:52 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Feb 28, 2020 7:16:52 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Feb 28, 2020 7:16:52 PM	No	
20 - Miles			TDELVA	Feb 28, 2020 7:16:52 PM	No	
30 - Kilometers			TDELVA	Feb 28, 2020 7:16:52 PM	No	
40 - Hours			TDELVA	Feb 28, 2020 7:16:52 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53335030
Invoice No. 55345 - 53335030

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Blend Door Actuator		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	204,999 - DH

Activity Header
Activity: 20 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Mar-20	604-200	ACTUATOR, DOOR, BLEND	1	26.83	26.83

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Feb-20	Delva,Terry	0.4	0	0
28-Feb-20	Delva,Terry	0.1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	26.83
Labor:	0.00
Labor Hours:	0.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**26.83**

Work Order Footer

Work Order 53335030 Total	
Parts:	26.83
Labor:	0.00
Labor Hours:	0.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**26.83**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53345324
Invoice No. 55345 - 53345324

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Rear a/c compressor		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	205,235 - DH

Chronology		
Reported	Mar 3, 2020 9:42:56 AM	Mar 3, 2020 9:42:56 AM
Started	Mar 3, 2020 9:44:00 AM	
Completed	Mar 3, 2020 1:55:00 PM	Mar 3, 2020 1:55:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:Rear a/ c compressor

Cause: Check a/ c system found outside clutch balancers fell off causing the clutch to make noise

Correction: Replaced a/c compressor, retest system ok at this time

Part:
1 new a/c compressor 8025005

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 03-MAR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Mar 3, 2020 1:55:31 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Mar 3, 2020 1:55:31 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Mar 3, 2020 1:55:31 PM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Mar 3, 2020 1:55:31 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Mar 3, 2020 1:55:31 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Mar 3, 2020 1:55:31 PM	No	
20 - Miles			JAPEREZ	Mar 3, 2020 1:55:31 PM	No	
30 - Kilometers			JAPEREZ	Mar 3, 2020 1:55:31 PM	No	
40 - Hours			JAPEREZ	Mar 3, 2020 1:55:31 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53345324
Invoice No. 55345 - 53345324

Client Department:
Department: 55345M
Work Order Description
Rear a/c compressor
Requested By: JAPEREZ
Created By: JAPEREZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 205,235 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear a/c compressor
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Mar-20	8025005	COMPRESSOR, A/C, TM21	1	279.73	279.73

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Mar-20	Perez,Javier	4.12	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	279.73
Labor:	0.00
Labor Hours:	4.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**279.73**

Work Order Footer

Work Order 53345324 Total	
Parts:	279.73
Labor:	0.00
Labor Hours:	4.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**279.73**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53287899
Invoice No. 55345 - 53287899

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
55345 REAR BRAKE		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	202,692 - DH

Chronology		
Reported	Feb 16, 2020 1:37:24 PM	Feb 16, 2020 1:37:24 PM
Started	Feb 21, 2020 10:24:00 AM	
Completed	Feb 21, 2020 12:37:00 PM	Feb 21, 2020 12:37:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: low front brake pads

Cause: preventive maintenance

Correction: replaced front brake pads

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Feb-20	NELSON PIERRE-LOUIS	1.72	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 21-FEB-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Feb 21, 2020 12:04:53 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Feb 21, 2020 12:04:53 PM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Feb 21, 2020 12:04:53 PM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Feb 21, 2020 12:04:53 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Feb 21, 2020 12:04:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Feb 21, 2020 12:04:53 PM	No	
20 - Miles			NPIERRE-LOUIS	Feb 21, 2020 12:04:53 PM	No	
30 - Kilometers			NPIERRE-LOUIS	Feb 21, 2020 12:04:53 PM	No	
40 - Hours			NPIERRE-LOUIS	Feb 21, 2020 12:04:53 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53287899
Invoice No. 55345 - 53287899

Client Department:
Department: 55345M
Work Order Description
55345 REAR BRAKE
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 202,692 - DH

Activity Header
Activity: 20 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Feb-20	9C2Z-2V200-B	PADS, BRAKE, DISC, REAR SAME AS BRSD1329B	1	46.22	46.22

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Feb-20	NELSON PIERRE-LOUIS	0.47	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	46.22
Labor:	0.00
Labor Hours:	0.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**46.22**

Work Order Footer

Work Order 53287899 Total	
Parts:	46.22
Labor:	0.00
Labor Hours:	2.19
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**46.22**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53197158
Invoice No. 55345 - 53197158

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	202,692 - DH

Chronology		
Reported	Feb 14, 2020 11:00:51 AM	Feb 14, 2020 11:00:51 AM
Started		
Completed	Feb 16, 2020 1:37:00 PM	Feb 16, 2020 1:37:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PmA Service

CAUSE: preventive maintenance

CORRECTION: perform PmA Service lube all Pivoting Points

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53197158
Invoice No. 55345 - 53197158

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 202,692 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Feb-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: NPIERRE-LOUIS Performed on: 16-FEB-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Feb 16, 2020 1:35:58 PM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Feb 16, 2020 1:35:58 PM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Feb 16, 2020 1:35:58 PM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Feb 16, 2020 1:35:58 PM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Feb 16, 2020 1:35:58 PM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Feb 16, 2020 1:35:58 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		NPIERRE-LOUIS	Feb 16, 2020 1:35:58 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Feb 16, 2020 1:35:58 PM	No	

Activity Sub Total

Activity 20 Sub Total
Parts: 1.96

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53197158
Invoice No. 55345 - 53197158

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 202,692 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 16-FEB-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Feb 16, 2020 1:36:31 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Feb 16, 2020 1:36:31 PM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Feb 16, 2020 1:36:31 PM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Feb 16, 2020 1:36:31 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Feb 16, 2020 1:36:31 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Feb 16, 2020 1:36:31 PM	No	
20 - Miles			NPIERRE-LOUIS	Feb 16, 2020 1:36:31 PM	No	
30 - Kilometers			NPIERRE-LOUIS	Feb 16, 2020 1:36:31 PM	No	
40 - Hours			NPIERRE-LOUIS	Feb 16, 2020 1:36:31 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53197158 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 53197135
Invoice No. 55345 - 53197135

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP------->Replace Serptine Belt
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 198,459 - DH

Chronology		
Reported	Jan 20, 2020 10:08:43 PM	Jan 20, 2020 10:08:43 PM
Started	Jan 20, 2020 10:41:00 PM	
Completed	Jan 20, 2020 11:54:00 PM	Jan 20, 2020 11:54:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========
To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.
==========

Complaint:Needs serpentine belt

Cause: crack

Correction:Replaced serpentine belt
Part number 1360K6 qty1

Activity Header
Activity: 10 042/004 PUMP, WATER
Activity Note: needs Serpentine belt
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Jan-20	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	21	21

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jan-20	Gaspard,Ronald	1.2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	21.00
Labor:	0.00
Labor Hours:	1.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**21.00**

Work Order Footer

Work Order 53197135 Total	
Parts:	21.00
Labor:	0.00
Labor Hours:	1.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**21.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53111660
Invoice No. 55345 - 53111660

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	198,459 - DH

Chronology		
Reported	Jan 20, 2020 1:21:29 PM	Jan 20, 2020 1:21:29 PM
Started	Jan 20, 2020 8:22:00 PM	
Completed	Jan 20, 2020 10:40:00 PM	Jan 20, 2020 10:40:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA

CAUSE: Service

CORRECTION: Performed PMA Service
Oil filter B329 qty1
Engine oil 5W20Qty qty 7 Qts

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jan-20	Gaspard,Ronald	1.75	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53111660
Invoice No. 55345 - 53111660

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DKNOTT
Created By: DKNOTT
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 198,459 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Jan-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jan-20	Gaspard,Ronald	0.52	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 20-JAN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jan 20, 2020 10:11:15 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jan 20, 2020 10:11:15 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jan 20, 2020 10:11:15 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jan 20, 2020 10:11:15 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Jan 20, 2020 10:11:15 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jan 20, 2020 10:11:15 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Jan 20, 2020 10:11:15 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jan 20, 2020 10:11:15 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	0.52
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53111660
Invoice No. 55345 - 53111660

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	198,459 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 20-JAN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Jan 20, 2020 10:35:20 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Jan 20, 2020 10:35:20 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Jan 20, 2020 10:35:20 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Jan 20, 2020 10:35:20 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Jan 20, 2020 10:35:20 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jan 20, 2020 10:35:20 PM	No	
20 - Miles			RGASPARD	Jan 20, 2020 10:35:20 PM	No	
30 - Kilometers			RGASPARD	Jan 20, 2020 10:35:20 PM	No	
40 - Hours			RGASPARD	Jan 20, 2020 10:35:20 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53111660 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53110348
Invoice No. 55345 - 53110348

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM C		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	99 - Cancelled (99)
Created By:	TDELVA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	194,400 - DH

Chronology		
Reported	Dec 18, 2019 4:25:21 PM	Dec 18, 2019 4:25:21 PM
Started		
Completed	Dec 19, 2019 7:08:25 AM	Dec 19, 2019 7:08:25 AM
Down Time		

Work Order Notes

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53110348
Invoice No. 55345 - 53110348

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 99 - Cancelled (99)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 194,400 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	-				No	
101,000 - FRA Change Oil Filters	No				No	
102,000 - FRA Drain Engine Oil	No				No	
103,000 - FRA Check Transmission Fluid	-				No	
104,000 - Lubricate Chassis	-				No	
105,000 - Replace or Clean A/C Filters	-				No	
107,000 - FRA Change Primary Fuel Filter	-				No	
108,000 - Lube all pivoting Mechanisms	-				No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	-				No	
201,000 - Service Crankcase Breather	-				No	
203,000 - FRA Change Automatic Transmission Fluid	No				No	
204,000 - FRA Change Power Steering Fluid and Filter	No				No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	-				No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	-				No	
301,000 - Check and Lubricate Door Linkages	-				No	
302,000 - Check Toe-In and Record Reading	-				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
302,001 - Record Toe-In Reading	Inches, fraction-actual				No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No				No	
305,000 - FRA Change Differential Fluid	No				No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53110348
Invoice No. 55345 - 53110348

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM C		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	99 - Cancelled (99)
Created By:	TDELVA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	194,400 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	-				No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	-				No	
3 - Are you wearing the appropriate PPE?	-				No	
4 - Have you performed the proper LOTO?	-				No	
5 - Are you aware of the potential risks of performing this repair?	-				No	
10 - Have you successfully completed the Personal Risk Assessment?	-				No	
20 - Miles					No	
30 - Kilometers					No	
40 - Hours					No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53110348 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 53110305
Invoice No. 55345 - 53110305

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	194,400 - DH

Chronology

Reported	Dec 18, 2019 3:53:22 PM	Dec 18, 2019 3:53:22 PM
Started	Dec 18, 2019 4:42:00 PM	
Completed	Dec 18, 2019 7:51:00 PM	Dec 18, 2019 7:51:00 PM
Down Time		

Work Order Notes

Activity Header
Activity: 10 016 SUSPENSION
Activity Note: Rear Rubber Shock
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Dec-19	DSR108-075	RUBBER, SPRING, SHEAR, RUBBER, REAR, MOR/RYDE	2	152.75	305.5

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Dec-19	Delva,Terry	1.22	65	79.3

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	305.50
Labor:	79.30
Labor Hours:	1.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**384.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 53110305
Invoice No. 55345 - 53110305

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	194,400 - DH

Activity Header
Activity: 20 050 GROUP, ACCESSORIES
Activity Note: wiper blades
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Dec-19	40520	BLADE, WIPER, WINDSHIELD, 20"	6	4.07	24.42
18-Dec-19	40520	BLADE, WIPER, WINDSHIELD, 20"	2	4.07	8.14

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	32.56
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**32.56**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 53110305
Invoice No. 55345 - 53110305

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	194,400 - DH

Activity Header
Activity: 30 042/000/000 COOLING SYSTEM
Activity Note: Leaking Radiator
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Dec-19	G1000382282CSF	RADIATOR, E450	1	151.87	151.87

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Dec-19	Delva,Terry	1.92	65	124.8

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	151.87
Labor:	124.80
Labor Hours:	1.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**276.67**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 53110305
Invoice No. 55345 - 53110305

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	194,400 - DH

Activity Header
Activity: 40 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

40 Desc: PRA
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 18-DEC-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Dec 18, 2019 7:51:11 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Dec 18, 2019 7:51:11 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Dec 18, 2019 7:51:11 PM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Dec 18, 2019 7:51:11 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Dec 18, 2019 7:51:11 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Dec 18, 2019 7:51:11 PM	No	
20 - Miles			TDELVA	Dec 18, 2019 7:51:11 PM	No	
30 - Kilometers			TDELVA	Dec 18, 2019 7:51:11 PM	No	
40 - Hours			TDELVA	Dec 18, 2019 7:51:11 PM	No	

Activity Sub Total

Activity 40 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53110305 Total	
Parts:	489.93
Labor:	204.10
Labor Hours:	3.14
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**694.03**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53013360
Invoice No. 55345 - 53013360

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	RRENE	**Status:**	40 - Closed (40)
Created By:	RRENE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	194,400 - DH

Chronology		
Reported	Dec 18, 2019 12:00:00 AM	Dec 18, 2019 12:00:00 AM
Started	Dec 18, 2019 2:36:00 PM	
Completed	Dec 18, 2019 4:02:00 PM	Dec 18, 2019 4:02:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA

CAUSE: Service due

CORRECTION: Performed and completed PmA
Changed engine oil and replaced engine oil filter
Replaced air filter and Engine oil drain plug

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Dec-19	Delva,Terry	1.25	65	81.25

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	81.25
Labor Hours:	1.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**81.25**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53013360
Invoice No. 55345 - 53013360

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RRENE
Created By: RRENE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 194,400 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Dec-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96
18-Dec-19	65266	PLUG, DRAIN, OIL, ENGINE	1	4.26	4.26
18-Dec-19	PA4075	FILTER, AIR SEE P546597	2	5.28	10.56

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Dec-19	Delva,Terry	0.05	65	3.25

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: TDELVA Performed on: 18-DEC-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		TDELVA	Dec 18, 2019 3:52:53 PM	No	
101,000 - FRA Change Oil Filters	Yes		TDELVA	Dec 18, 2019 3:52:53 PM	No	
102,000 - FRA Drain Engine Oil	Yes		TDELVA	Dec 18, 2019 3:52:53 PM	No	
103,000 - FRA Check Transmission Fluid	Done		TDELVA	Dec 18, 2019 3:52:53 PM	No	
104,000 - Lubricate Chassis	Done		TDELVA	Dec 18, 2019 3:52:53 PM	No	
105,000 - Replace or Clean A/C Filters	Done		TDELVA	Dec 18, 2019 3:52:53 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	TDELVA	Dec 18, 2019 3:52:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
108,000 - Lube all pivoting Mechanisms	Done		TDELVA	Dec 18, 2019 3:52:53 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	21.04
Labor:	3.25
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**24.29**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53013360
Invoice No. 55345 - 53013360

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RRENE
Created By: RRENE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 194,400 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 18-DEC-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Dec 18, 2019 2:36:26 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Dec 18, 2019 2:36:26 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Dec 18, 2019 2:36:26 PM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Dec 18, 2019 2:36:26 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Dec 18, 2019 2:36:26 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Dec 18, 2019 2:36:26 PM	No	
20 - Miles			TDELVA	Dec 18, 2019 2:36:26 PM	No	
30 - Kilometers			TDELVA	Dec 18, 2019 2:36:26 PM	No	
40 - Hours			TDELVA	Dec 18, 2019 2:36:26 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53013360 Total	
Parts:	21.04
Labor:	84.50
Labor Hours:	1.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**105.54**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 53085581
Invoice No. 55345 - 53085581

Client Department:
Department: 55345M
Work Order Description
UNIT # 4515-P TOWING CHARGE
Requested By: DKNOTT
Created By: DKNOTT
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 193,261 - DH

Chronology		
Reported	Dec 11, 2019 11:56:00 AM	Dec 11, 2019 11:56:00 AM
Started		
Completed	Dec 11, 2019 2:56:02 PM	Dec 11, 2019 2:56:02 PM
Down Time		

Work Order Notes

Line 10 Ran out of propane

Activity Header
Activity: 10 044 FUEL SYSTEM
Activity Note: UNIT # 4515-P TOWING CHARGE
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Dec-19	DSP-TOWING	DIRECT PURCHASES FOR SERVICES TOWING	1	157	157

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	157.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**157.00**

Work Order Footer

Work Order 53085581 Total	
Parts:	157.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**157.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52919710
Invoice No. 55345 - 52919710

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	RRENE	**Status:**	40 - Closed (40)
Created By:	RRENE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	189,802 - DH

Chronology		
Reported	Nov 17, 2019 12:00:00 AM	Nov 17, 2019 12:00:00 AM
Started		
Completed	Nov 18, 2019 3:54:56 PM	Nov 18, 2019 3:54:56 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PmA service

CAUSE: preventive maintenance

CORRECTION: perform PmA Service

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: NPIERRE-LOUIS Performed on: 18-NOV-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
10,100 - Safety Inspection	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
10,140 - Check Service Brakes	Done		NPIERRE-	Nov 18, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	12:35:06 PM		
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
10,160 - FRA Check Instruments and Horns	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
10,170 - Check Fast Idle	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
10,180 - Check Starter Protection Circuit	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
10,190 - Check Reverse Warning System	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
11,100 - Check Parking Brake	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
11,150 - Perform Brake Test	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
11,152 - Decelerometer Results Test 1	0 FEET		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
11,154 - Decelerometer Results Test 2	0 FEET		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
11,156 - Decelerometer Results Test 3	0 FEET		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	0 Pounds per Square Inch		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
11,162 - FRA Check/Record Water Temperature	0 Degree Fahrenheit		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
11,170 - FRA Check Door Operation	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
20,210 - Check Condition of Operator's Area	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
20,240 - FRA Check Interior Lights	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
20,260 - Check Stop Request System	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
20,270 - Check Fare Box Mounting (If	Done		NPIERRE-	Nov 18, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Applicable)			LOUIS	12:35:06 PM		
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
22,110 - Check Emergency Hatches	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
22,120 - Check All Safety Equipment	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
30,310 - Check Passenger Doors	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
30,340 - FRA Check Destination Sign and Run Box	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
30,360 - Check for Physical Damage and Decals	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
30,380 - Check Exterior Compartment Doors	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
33,100 - Check Lights and Reflectors	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
40,420 - Check Hood	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
40,442 - Freeze Point	0 Degree Fahrenheit		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
40,460 - Record Antifreeze Protection Level	Done		NPIERRE-	Nov 18, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Using Refractometer			LOUIS	12:35:06 PM		
40,461 - Refractometer Reading	0 Degree Fahrenheit		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
44,130 - FRA Check Exhaust System	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
44,140 - FRA Check Intake System	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
44,150 - FRA Inspect Turbocharger	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
44,180 - FRA Check for Leaks	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
44,190 - FRA Perform Battery Inspection	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
50,510 - Check Entire Steering System	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
60,620 - Check Valve Stems and Caps	Done		NPIERRE-	Nov 18, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	12:35:06 PM		
60,630 - Check and Record Tread Depth	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
60,633 - Tread Depth RRO	9 32nds of an inch		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
60,634 - Tread Depth RRI	9 32nds of an inch		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
60,636 - Tread Depth LRO	9 32nds of an inch		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
60,650 - Check Sidewall Wear	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
60,660 - Inspect for Cuts and Tears	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
60,670 - Check Dual Mating With Square	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
70,710 - Check Vibration Damper	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
70,730 - FRA Check Starter	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
70,770 - FRA Check Exhaust System	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
77,110 - FRA Check Fuel Tank	Done		NPIERRE-	Nov 18, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	12:35:06 PM		
77,120 - Check Suspension Components	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
77,135 - Brake Rotor LF	41.9 Inch		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
77,136 - Brake Rotor RF	41.9 Inch		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
77,137 - Brake Rotor LR	35.9 Inch		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
77,138 - Brake Rotor RR	35.9 Inch		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
77,140 - FRA Check Brake Hoses	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
77,150 - Check King Pins	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
80,810 - Completion of PMI Report	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:06 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52919710
Invoice No. 55345 - 52919710

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RRENE
Created By: RRENE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 189,802 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Nov-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: NPIERRE-LOUIS Performed on: 18-NOV-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:51 PM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Nov 18, 2019 12:35:51 PM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Nov 18, 2019 12:35:51 PM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:51 PM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:51 PM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:51 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		NPIERRE-LOUIS	Nov 18, 2019 12:35:51 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Nov 18, 2019 12:35:51 PM	No	

Activity Sub Total

Activity 20 Sub Total
Parts: 1.96

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52919710
Invoice No. 55345 - 52919710

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	RRENE	**Status:**	40 - Closed (40)
Created By:	RRENE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	189,802 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 18-NOV-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Nov 18, 2019 12:26:07 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Nov 18, 2019 12:26:07 PM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Nov 18, 2019 12:26:07 PM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Nov 18, 2019 12:26:07 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Nov 18, 2019 12:26:07 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Nov 18, 2019 12:26:07 PM	No	
20 - Miles			NPIERRE-LOUIS	Nov 18, 2019 12:26:07 PM	No	
30 - Kilometers			NPIERRE-LOUIS	Nov 18, 2019 12:26:07 PM	No	
40 - Hours			NPIERRE-LOUIS	Nov 18, 2019 12:26:07 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 52919710 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53008125
Invoice No. 55345 - 53008125

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Slow hard to start		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	189,591 - DH

Chronology		
Reported	Nov 17, 2019 11:47:13 AM	Nov 17, 2019 11:47:13 AM
Started		
Completed	Nov 18, 2019 10:04:52 AM	Nov 18, 2019 10:04:52 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: the was hard to start

Cause: preventive maintenance old starter

Correction: replaced starter with a new one.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Nov-19	DL3Z-11002-A-COR	CORE, STARTER, E350, '14	-1	35	-35
17-Nov-19	DL3Z-11002-A-COR	CORE, STARTER, E350, '14	1	35	35

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 17-NOV-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Nov 17, 2019 11:59:44 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Nov 17, 2019 11:59:44 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Nov 17, 2019 11:59:44 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Nov 17, 2019 11:59:44 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Nov 17, 2019 11:59:44 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Nov 17, 2019 11:59:44 AM	No	
20 - Miles			NPIERRE-LOUIS	Nov 17, 2019 11:59:44 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Nov 17, 2019 11:59:44 AM	No	
40 - Hours			NPIERRE-LOUIS	Nov 17, 2019 11:59:44 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53008125
Invoice No. 55345 - 53008125

Client Department:
Department: 55345M
Work Order Description
Slow hard to start
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 189,591 - DH

Activity Header
Activity: 15 046 ELECTRICAL PROPULSION SYSTEM
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Nov-19	DL3Z-11002-A	STARTER, E350, '14	1	133.95	133.95
15-Jun-20	AP103	PLUG, SPARK	10	3.16	31.6

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	165.55
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**165.55**

Work Order Footer

Work Order 53008125 Total	
Parts:	165.55
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**165.55**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52820148
Invoice No. 55345 - 52820148

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM B		Ford E450 Champion Challenger	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	185,294 - DH

Chronology		
Reported	Oct 18, 2019 10:56:37 AM	Oct 18, 2019 10:56:37 AM
Started		
Completed	Oct 22, 2019 7:49:38 AM	Oct 22, 2019 7:49:38 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PmB service

CAUSE: preventive maintenance

CORRECTION: perform pmB

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: NPIERRE-LOUIS Performed on: 21-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
10,100 - Safety Inspection	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
10,140 - Check Service Brakes	Done		NPIERRE-	Oct 21, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	12:28:23 PM		
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
10,160 - FRA Check Instruments and Horns	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
10,170 - Check Fast Idle	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
10,180 - Check Starter Protection Circuit	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
10,190 - Check Reverse Warning System	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
11,100 - Check Parking Brake	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
11,150 - Perform Brake Test	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
11,152 - Decelerometer Results Test 1	0 FEET		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
11,154 - Decelerometer Results Test 2	0 FEET		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
11,156 - Decelerometer Results Test 3	0 FEET		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	0 Pounds per Square Inch		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
11,162 - FRA Check/Record Water Temperature	0 Degree Fahrenheit		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
11,170 - FRA Check Door Operation	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
20,210 - Check Condition of Operator's Area	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
20,240 - FRA Check Interior Lights	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
20,260 - Check Stop Request System	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
20,270 - Check Fare Box Mounting (If	Done		NPIERRE-	Oct 21, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Applicable)			LOUIS	12:28:23 PM		
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
22,110 - Check Emergency Hatches	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
22,120 - Check All Safety Equipment	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
30,310 - Check Passenger Doors	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
30,340 - FRA Check Destination Sign and Run Box	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
30,360 - Check for Physical Damage and Decals	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
30,380 - Check Exterior Compartment Doors	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
33,100 - Check Lights and Reflectors	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
40,420 - Check Hood	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
40,442 - Freeze Point	0 Degree Fahrenheit		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
40,460 - Record Antifreeze Protection Level	Done		NPIERRE-	Oct 21, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Using Refractometer			LOUIS	12:28:23 PM		
40,461 - Refractometer Reading	0 Degree Fahrenheit		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
44,130 - FRA Check Exhaust System	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
44,140 - FRA Check Intake System	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
44,150 - FRA Inspect Turbocharger	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
44,180 - FRA Check for Leaks	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
44,190 - FRA Perform Battery Inspection	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
50,510 - Check Entire Steering System	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
60,620 - Check Valve Stems and Caps	Done		NPIERRE-	Oct 21, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	12:28:23 PM		
60,630 - Check and Record Tread Depth	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
60,631 - Tread Depth RF	9 32nds of an inch		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
60,633 - Tread Depth RRO	9 32nds of an inch		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
60,636 - Tread Depth LRO	9 32nds of an inch		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
60,650 - Check Sidewall Wear	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
60,660 - Inspect for Cuts and Tears	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
60,670 - Check Dual Mating With Square	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
70,710 - Check Vibration Damper	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
70,730 - FRA Check Starter	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
70,770 - FRA Check Exhaust System	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
77,110 - FRA Check Fuel Tank	Done		NPIERRE-	Oct 21, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	12:28:23 PM		
77,120 - Check Suspension Components	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
77,131 - Brake Pad Thickness LF	5 Inch		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
77,132 - Brake Pad Thickness RF	5 Inch		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
77,135 - Brake Rotor LF	41.9 Inch		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
77,136 - Brake Rotor RF	41.9 Inch		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
77,137 - Brake Rotor LR	35.9 Inch		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
77,138 - Brake Rotor RR	35.9 Inch		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
77,140 - FRA Check Brake Hoses	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
77,150 - Check King Pins	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
80,810 - Completion of PMI Report	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		NPIERRE-LOUIS	Oct 21, 2019 12:28:23 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52820148
Invoice No. 55345 - 52820148

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: DKNOTT
Created By: DKNOTT
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 185,294 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Oct-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: NPIERRE-LOUIS Performed on: 21-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Oct 21, 2019 12:29:02 PM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Oct 21, 2019 12:29:02 PM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Oct 21, 2019 12:29:02 PM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Oct 21, 2019 12:29:02 PM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Oct 21, 2019 12:29:02 PM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Oct 21, 2019 12:29:02 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		NPIERRE-LOUIS	Oct 21, 2019 12:29:02 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Oct 21, 2019 12:29:02 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		NPIERRE-LOUIS	Oct 21, 2019 12:29:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
201,000 - Service Crankcase Breather	Done		NPIERRE-LOUIS	Oct 21, 2019 12:29:02 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		NPIERRE-LOUIS	Oct 21, 2019 12:29:02 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	Yes		NPIERRE-LOUIS	Oct 21, 2019 12:29:02 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		NPIERRE-LOUIS	Oct 21, 2019 12:29:02 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52820148
Invoice No. 55345 - 52820148

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: DKNOTT
Created By: DKNOTT
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 185,294 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 21-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Oct 21, 2019 12:22:42 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Oct 21, 2019 12:22:42 PM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Oct 21, 2019 12:22:42 PM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Oct 21, 2019 12:22:42 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Oct 21, 2019 12:22:42 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Oct 21, 2019 12:22:42 PM	No	
20 - Miles			NPIERRE-LOUIS	Oct 21, 2019 12:22:42 PM	No	
30 - Kilometers			NPIERRE-LOUIS	Oct 21, 2019 12:22:42 PM	No	
40 - Hours			NPIERRE-LOUIS	Oct 21, 2019 12:22:42 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 52820148 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52912264
Invoice No. 55345 - 52912264

Client Department:
Department: 55345M
Work Order Description
Front brakes job
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 185,095 - DH

Chronology		
Reported	Oct 20, 2019 1:05:01 PM	Oct 20, 2019 1:05:01 PM
Started		
Completed	Oct 21, 2019 9:05:33 AM	Oct 21, 2019 9:05:33 AM
Down Time		

Work Order Notes

Line 10 Complaint: Front Brakes was low

Cause: preventive maintenance

Correction: replaced front brake pads and caliper bracket

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 20-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Oct 20, 2019 1:16:22 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Oct 20, 2019 1:16:22 PM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Oct 20, 2019 1:16:22 PM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Oct 20, 2019 1:16:22 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Oct 20, 2019 1:16:22 PM	No	
10 - Have you successfully completed the Personal	Done		NPIERRE-	Oct 20, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	1:16:22 PM		
20 - Miles			NPIERRE-LOUIS	Oct 20, 2019 1:16:22 PM	No	
30 - Kilometers			NPIERRE-LOUIS	Oct 20, 2019 1:16:22 PM	No	
40 - Hours			NPIERRE-LOUIS	Oct 20, 2019 1:16:22 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52912264
Invoice No. 55345 - 52912264

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Front brakes job		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	185,095 - DH

Activity Header
Activity: 20 013/000/000 BRAKES
Activity Note: Front Brakes
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Oct-19	8C2Z-2B292-C	BRACKET, CALIPER, BRAKE, DISC, FRONT	1	76.12	76.12
20-Oct-19	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	48.87	48.87

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	124.99
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**124.99**

Work Order Footer

Work Order 52912264 Total	
Parts:	124.99
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**124.99**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52727213
Invoice No. 55345 - 52727213

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	181,038 - DH

Chronology		
Reported	Sep 20, 2019 5:06:58 PM	Sep 20, 2019 5:06:58 PM
Started		
Completed	Sep 23, 2019 10:22:55 AM	Sep 23, 2019 10:22:55 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PmA Service

CAUSE: preventive maintenance

CORRECTION: perform PmA Service

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: NPIERRE-LOUIS Performed on: 23-SEP-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
10,100 - Safety Inspection	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
10,140 - Check Service Brakes	Done		NPIERRE-	Sep 23, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	9:04:38 AM		
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
10,160 - FRA Check Instruments and Horns	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
10,170 - Check Fast Idle	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
10,180 - Check Starter Protection Circuit	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
10,190 - Check Reverse Warning System	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
11,100 - Check Parking Brake	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
11,150 - Perform Brake Test	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
11,152 - Decelerometer Results Test 1	0 FEET		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
11,154 - Decelerometer Results Test 2	0 FEET		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
11,156 - Decelerometer Results Test 3	0 FEET		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	0 Pounds per Square Inch		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
11,162 - FRA Check/Record Water Temperature	0 Degree Fahrenheit		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
11,170 - FRA Check Door Operation	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
20,210 - Check Condition of Operator's Area	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
20,240 - FRA Check Interior Lights	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
20,260 - Check Stop Request System	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
20,270 - Check Fare Box Mounting (If	Done		NPIERRE-	Sep 23, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Applicable)			LOUIS	9:04:38 AM		
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
22,110 - Check Emergency Hatches	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
22,120 - Check All Safety Equipment	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
30,310 - Check Passenger Doors	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
30,340 - FRA Check Destination Sign and Run Box	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
30,360 - Check for Physical Damage and Decals	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
30,380 - Check Exterior Compartment Doors	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
33,100 - Check Lights and Reflectors	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
40,420 - Check Hood	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
40,442 - Freeze Point	0 Degree Fahrenheit		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
40,460 - Record Antifreeze Protection Level	Done		NPIERRE-	Sep 23, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Using Refractometer			LOUIS	9:04:38 AM		
40,461 - Refractometer Reading	0 Degree Fahrenheit		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
44,130 - FRA Check Exhaust System	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
44,140 - FRA Check Intake System	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
44,150 - FRA Inspect Turbocharger	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
44,180 - FRA Check for Leaks	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
44,190 - FRA Perform Battery Inspection	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
50,510 - Check Entire Steering System	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
60,620 - Check Valve Stems and Caps	Done		NPIERRE-	Sep 23, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	9:04:38 AM		
60,630 - Check and Record Tread Depth	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
60,631 - Tread Depth RF	8 32nds of an inch		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
60,632 - Tread Depth LF	8 32nds of an inch		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
60,650 - Check Sidewall Wear	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
60,660 - Inspect for Cuts and Tears	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
60,670 - Check Dual Mating With Square	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
70,710 - Check Vibration Damper	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
70,730 - FRA Check Starter	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
70,770 - FRA Check Exhaust System	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
77,110 - FRA Check Fuel Tank	Done		NPIERRE-	Sep 23, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	9:04:38 AM		
77,120 - Check Suspension Components	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
77,131 - Brake Pad Thickness LF	6 Inch		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
77,132 - Brake Pad Thickness RF	6 Inch		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
77,133 - Brake Pad Thickness LR	7 Inch		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
77,134 - Brake Pad Thickness RR	7 Inch		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
77,135 - Brake Rotor LF	45.9 Inch		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
77,136 - Brake Rotor RF	45.9 Inch		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
77,137 - Brake Rotor LR	35.5 Inch		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
77,138 - Brake Rotor RR	35.5 Inch		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
77,140 - FRA Check Brake Hoses	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
77,150 - Check King Pins	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
80,810 - Completion of PMI Report	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		NPIERRE-LOUIS	Sep 23, 2019 9:04:38 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52727213
Invoice No. 55345 - 52727213

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DKNOTT
Created By: DKNOTT
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 181,038 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Sep-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: NPIERRE-LOUIS Performed on: 23-SEP-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Sep 23, 2019 9:05:23 AM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Sep 23, 2019 9:05:23 AM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Sep 23, 2019 9:05:23 AM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Sep 23, 2019 9:05:23 AM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Sep 23, 2019 9:05:23 AM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Sep 23, 2019 9:05:23 AM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		NPIERRE-LOUIS	Sep 23, 2019 9:05:23 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Sep 23, 2019 9:05:23 AM	No	

Activity Sub Total

Activity 20 Sub Total
Parts: 1.96

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52727213
Invoice No. 55345 - 52727213

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	181,038 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 23-SEP-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Sep 23, 2019 8:55:51 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Sep 23, 2019 8:55:51 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Sep 23, 2019 8:55:51 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Sep 23, 2019 8:55:51 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Sep 23, 2019 8:55:51 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Sep 23, 2019 8:55:51 AM	No	
20 - Miles			NPIERRE-LOUIS	Sep 23, 2019 8:55:51 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Sep 23, 2019 8:55:51 AM	No	
40 - Hours			NPIERRE-LOUIS	Sep 23, 2019 8:55:51 AM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

	Work Order 52727213 Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52725785
Invoice No. 55345 - 52725785

Client Department:
Department: 55345M
Work Order Description
Replaced 2 tires and 1 clearance light
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 176,812 - DH

Chronology		
Reported	Aug 26, 2019 12:24:42 PM	Aug 26, 2019 12:24:42 PM
Started	Aug 26, 2019 12:00:00 AM	
Completed	Aug 26, 2019 8:49:00 PM	Aug 26, 2019 8:49:00 PM
Down Time		

Work Order Notes

Line 10 Mount and balanced 2 front tires
Torqued wheels to 140ftlb test driven and retorqued
Replaced 1 top Clearance Light

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Aug-19	AMRIT TEEMAL,VISHNU	0.2666666	65	17.333329

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 26-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Aug 26, 2019 12:29:55 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Aug 26, 2019 12:29:55 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Aug 26, 2019 12:29:55 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Aug 26, 2019 12:29:55 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Aug 26, 2019 12:29:55 PM	No	
10 - Have you successfully completed the	Done		VAMRITTEEMAL	Aug 26, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				12:29:55 PM		
20 - Miles			VAMRITTEEMAL	Aug 26, 2019 12:29:55 PM	No	
30 - Kilometers			VAMRITTEEMAL	Aug 26, 2019 12:29:55 PM	No	
40 - Hours			VAMRITTEEMAL	Aug 26, 2019 12:29:55 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	17.33
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**17.33**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52725785
Invoice No. 55345 - 52725785

Client Department:
Department: 55345M
Work Order Description
Replaced 2 tires and 1 clearance light
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 176,812 - DH

Activity Header
Activity: 20 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Aug-19	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	120.48	240.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Aug-19	AMRIT TEEMAL,VISHNU	1	65	65

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	240.96
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**305.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52725785
Invoice No. 55345 - 52725785

Client Department:
Department: 55345M
Work Order Description
Replaced 2 tires and 1 clearance light
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 176,812 - DH

Activity Header
Activity: 30 034/003/000 LAMPS, SIGNAL, PARKING & BACKUP
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Aug-19	3974688	LAMP, LED, AMBER	1	7.57	7.57

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Aug-19	AMRIT TEEMAL,VISHNU	0.3333333	65	21.6666645

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	7.57
Labor:	21.67
Labor Hours:	0.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**29.24**

Work Order Footer

Work Order 52725785 Total	
Parts:	248.53
Labor:	104.00
Labor Hours:	1.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**352.53**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52643057
Invoice No. 55345 - 52643057

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	176,812 - DH

Chronology		
Reported	Aug 23, 2019 11:24:30 AM	Aug 23, 2019 11:24:30 AM
Started	Aug 26, 2019 12:00:00 AM	
Completed	Aug 26, 2019 4:27:25 PM	Aug 26, 2019 4:27:25 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA SERVICE

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Aug-19	AMRIT TEEMAL,VISHNU	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: VAMRITTEEMAL Performed on: 26-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
10,100 - Safety Inspection	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,140 - Check Service Brakes	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
10,160 - FRA Check Instruments and Horns	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
10,170 - Check Fast Idle	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
10,180 - Check Starter Protection Circuit	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
10,190 - Check Reverse Warning System	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
11,100 - Check Parking Brake	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
11,150 - Perform Brake Test	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
11,152 - Decelerometer Results Test 1	FEET	n/a	VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
11,154 - Decelerometer Results Test 2	FEET	n/a	VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
11,156 - Decelerometer Results Test 3	FEET	n/a	VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
11,170 - FRA Check Door Operation	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
20,210 - Check Condition of Operator's Area	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
20,240 - FRA Check Interior Lights	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
20,260 - Check Stop Request System	-	n/a	VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
22,110 - Check Emergency Hatches	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
22,120 - Check All Safety Equipment	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
30,310 - Check Passenger Doors	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
30,360 - Check for Physical Damage and Decals	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
30,380 - Check Exterior Compartment Doors	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
33,100 - Check Lights and Reflectors	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
40,420 - Check Hood	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
44,130 - FRA Check Exhaust System	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
44,140 - FRA Check Intake System	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
44,180 - FRA Check for Leaks	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
44,190 - FRA Perform Battery Inspection	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
50,510 - Check Entire Steering System	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
60,630 - Check and Record Tread Depth	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
60,631 - Tread Depth RF	4 32nds of an inch		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
60,632 - Tread Depth LF	4 32nds of an inch		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
60,635 - Tread Depth LRI	9 32nds of an inch		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
60,636 - Tread Depth LRO	9 32nds of an inch		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
60,650 - Check Sidewall Wear	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
60,660 - Inspect for Cuts and Tears	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
70,710 - Check Vibration Damper	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
70,730 - FRA Check Starter	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
70,770 - FRA Check Exhaust System	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
77,120 - Check Suspension Components	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
77,133 - Brake Pad Thickness LR	9 Inch		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
77,134 - Brake Pad Thickness RR	9 Inch		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
77,135 - Brake Rotor LF	39.91 Inch		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
77,136 - Brake Rotor RF	39.88 Inch		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
77,137 - Brake Rotor LR	35.89 Inch		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
77,138 - Brake Rotor RR	35.86 Inch		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
77,140 - FRA Check Brake Hoses	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
77,150 - Check King Pins	-	n/a	VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
80,810 - Completion of PMI Report	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		VAMRITTEEMAL	Aug 26, 2019 12:24:28 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52643057
Invoice No. 55345 - 52643057

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	176,812 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Aug-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Aug-19	AMRIT TEEMAL,VISHNU	1	65	65

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: VAMRITTEEMAL Performed on: 26-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		VAMRITTEEMAL	Aug 26, 2019 12:19:35 PM	No	
101,000 - FRA Change Oil Filters	Yes		VAMRITTEEMAL	Aug 26, 2019 12:19:35 PM	No	
102,000 - FRA Drain Engine Oil	Yes		VAMRITTEEMAL	Aug 26, 2019 12:19:35 PM	No	
103,000 - FRA Check Transmission Fluid	Done		VAMRITTEEMAL	Aug 26, 2019 12:19:35 PM	No	
104,000 - Lubricate Chassis	Done		VAMRITTEEMAL	Aug 26, 2019 12:19:35 PM	No	
105,000 - Replace or Clean A/C Filters	Done		VAMRITTEEMAL	Aug 26, 2019 12:19:35 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	VAMRITTEEMAL	Aug 26, 2019 12:19:35 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		VAMRITTEEMAL	Aug 26, 2019 12:19:35 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	65.00
	Labor Hours:	1.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**66.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52643057
Invoice No. 55345 - 52643057

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 176,812 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Aug-19	AMRIT TEEMAL,VISHNU	0.2666666	65	17.333329

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 26-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Aug 26, 2019 12:19:04 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Aug 26, 2019 12:19:04 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Aug 26, 2019 12:19:04 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Aug 26, 2019 12:19:04 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Aug 26, 2019 12:19:04 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Aug 26, 2019 12:19:04 PM	No	
20 - Miles			VAMRITTEEMAL	Aug 26, 2019 12:19:04 PM	No	
30 - Kilometers			VAMRITTEEMAL	Aug 26, 2019 12:19:04 PM	No	
40 - Hours			VAMRITTEEMAL	Aug 26, 2019 12:19:04 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	17.33
	Labor Hours:	0.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**17.33**

Work Order Footer

Work Order 52643057 Total	
Parts:	1.96
Labor:	179.83
Labor Hours:	2.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**181.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52694899
Invoice No. 55345 - 52694899

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Battery Light / Air filter		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	175,447 - DH

Chronology		
Reported	Aug 15, 2019 8:02:25 PM	Aug 15, 2019 8:02:25 PM
Started	Aug 15, 2019 12:00:00 AM	
Completed	Aug 15, 2019 11:17:00 PM	Aug 15, 2019 11:17:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Battery Light On

Cause: Bad Alternator

Correction: Remove & Replace Alternator Check charging system 14. 38 volts Replace Air Filter.
Alternator under warranty Qty (1)
Parts # PA4075 Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Aug-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 15-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Aug 15, 2019 11:07:39 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Aug 15, 2019 11:07:39 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Aug 15, 2019 11:07:39 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Aug 15, 2019 11:07:39 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Aug 15, 2019 11:07:39 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Aug 15, 2019 11:07:39 PM	No	
20 - Miles			DARTHURS	Aug 15, 2019 11:07:39 PM	No	
30 - Kilometers			DARTHURS	Aug 15, 2019 11:07:39 PM	No	
40 - Hours			DARTHURS	Aug 15, 2019 11:07:39 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	5.42
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.42**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52694899
Invoice No. 55345 - 52694899

Client Department:
Department: 55345M
Work Order Description
Battery Light / Air filter
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 175,447 - DH

Activity Header
Activity: 15 031/000/000 CHARGING
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Aug-19	PA4075	FILTER, AIR SEE P546597	1	5.28	5.28

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Aug-19	Arthurs,Durvin	1	65	65

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	5.28
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**70.28**

Work Order Footer

Work Order 52694899 Total	
Parts:	5.28
Labor:	70.42
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**75.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52683428
Invoice No. 55345 - 52683428

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Rear ac not cold.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	174,588 - DH

Chronology		
Reported	Aug 13, 2019 12:13:25 AM	Aug 13, 2019 12:13:25 AM
Started	Aug 13, 2019 12:00:00 AM	
Completed	Aug 13, 2019 12:25:00 AM	Aug 13, 2019 12:25:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear ac not cold.

Cause: 1 Faulty rear condenser fan.

Correction: Remove and replaced 1 rear condenser fan.

Part# 8050002 Qty. (1).

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Aug-19	Earl Johnson	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 13-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Aug 13, 2019 12:24:25 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Aug 13, 2019 12:24:25 AM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Aug 13, 2019 12:24:25 AM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Aug 13, 2019 12:24:25 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Aug 13, 2019 12:24:25 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Aug 13, 2019 12:24:25 AM	No	
20 - Miles			EARJOHNSON	Aug 13, 2019 12:24:25 AM	No	
30 - Kilometers			EARJOHNSON	Aug 13, 2019 12:24:25 AM	No	
40 - Hours			EARJOHNSON	Aug 13, 2019 12:24:25 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52683428
Invoice No. 55345 - 52683428

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Rear ac not cold.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	174,588 - DH

Activity Header
Activity: 15 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear ac not cold .
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 51 Inoperative
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Aug-19	8050002	FAN, CONDENSER, A/C, MOUNT, FLUSH, 14"	1	63.19	63.19

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Aug-19	Earl Johnson	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	63.19
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**160.69**

Work Order Footer

Work Order 52683428 Total	
Parts:	63.19
Labor:	195.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**258.19**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52652325
Invoice No. 55345 - 52652325

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Wc lift malfunction.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	173,111 - DH

Chronology		
Reported	Jul 31, 2019 11:57:56 PM	Jul 31, 2019 11:57:56 PM
Started	Aug 1, 2019 12:00:00 AM	
Completed	Aug 1, 2019 12:10:00 AM	Aug 1, 2019 12:10:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: wc lifts up function not working.

Cause: Faulty bridgeplate switch.

Correction: Remove and Replaced bridgeplate switch.

Part# 32519KS QTY (1).

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Aug-19	Earl Johnson	0.1166666	65	7.583329
01-Aug-19	Earl Johnson	0.0666666	65	4.333329

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 01-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Aug 1, 2019 12:07:04 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Aug 1, 2019 12:07:04 AM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Aug 1, 2019 12:07:04 AM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Aug 1, 2019 12:07:04 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Aug 1, 2019 12:07:04 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Aug 1, 2019 12:07:04 AM	No	
20 - Miles			EARJOHNSON	Aug 1, 2019 12:07:04 AM	No	
30 - Kilometers			EARJOHNSON	Aug 1, 2019 12:07:04 AM	No	
40 - Hours			EARJOHNSON	Aug 1, 2019 12:07:04 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	11.92
Labor Hours:	0.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**11.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52652325
Invoice No. 55345 - 52652325

Client Department:
Department: 55345M
Work Order Description
Wc lift malfunction.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 173,111 - DH

Activity Header
Activity: 15 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: Wc lift malfunction.
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Aug-19	32519KS	SWITCH, RAISED, W/C	1	29.26	29.26

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Aug-19	Earl Johnson	1	65	65

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	29.26
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**94.26**

Work Order Footer

Work Order 52652325 Total	
Parts:	29.26
Labor:	76.92
Labor Hours:	1.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**106.18**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52551228
Invoice No. 55345 - 52551228

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM C		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	172,699 - DH

Chronology		
Reported	Jul 26, 2019 11:04:17 AM	Jul 26, 2019 11:04:17 AM
Started	Jul 29, 2019 12:00:00 AM	
Completed	Jul 29, 2019 11:39:00 AM	Jul 29, 2019 11:39:00 AM
Down Time		

Work Order Notes

Line 10 Complaint: Performed PMC

Cause: preventive maintenance

Correction: PMC service performed

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: NPIERRE-LOUIS Performed on: 29-JUL-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
10,100 - Safety Inspection	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
10,140 - Check Service Brakes	Done		NPIERRE-	Jul 29, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	8:46:29 AM		
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
10,160 - FRA Check Instruments and Horns	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
10,170 - Check Fast Idle	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
10,180 - Check Starter Protection Circuit	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
10,190 - Check Reverse Warning System	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
11,100 - Check Parking Brake	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
11,150 - Perform Brake Test	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
11,152 - Decelerometer Results Test 1	FEET	na	NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
11,154 - Decelerometer Results Test 2	FEET	na	NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
11,156 - Decelerometer Results Test 3	FEET	na	NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
11,170 - FRA Check Door Operation	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
20,210 - Check Condition of Operator's Area	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
20,240 - FRA Check Interior Lights	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
20,260 - Check Stop Request System	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
20,270 - Check Fare Box Mounting (If	Done		NPIERRE-	Jul 29, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Applicable)			LOUIS	8:46:29 AM		
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
22,110 - Check Emergency Hatches	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
22,120 - Check All Safety Equipment	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
30,310 - Check Passenger Doors	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
30,340 - FRA Check Destination Sign and Run Box	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
30,360 - Check for Physical Damage and Decals	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
30,380 - Check Exterior Compartment Doors	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
33,100 - Check Lights and Reflectors	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
40,420 - Check Hood	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
40,460 - Record Antifreeze Protection Level	Done		NPIERRE-	Jul 29, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Using Refractometer			LOUIS	8:46:29 AM		
40,461 - Refractometer Reading	Degree Fahrenheit	na	NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
44,130 - FRA Check Exhaust System	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
44,140 - FRA Check Intake System	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
44,150 - FRA Inspect Turbocharger	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
44,180 - FRA Check for Leaks	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
44,190 - FRA Perform Battery Inspection	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
50,510 - Check Entire Steering System	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
60,620 - Check Valve Stems and Caps	Done		NPIERRE-	Jul 29, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	8:46:29 AM		
60,630 - Check and Record Tread Depth	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
60,631 - Tread Depth RF	9 32nds of an inch		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
60,632 - Tread Depth LF	9 32nds of an inch		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
60,650 - Check Sidewall Wear	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
60,660 - Inspect for Cuts and Tears	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
60,670 - Check Dual Mating With Square	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
70,710 - Check Vibration Damper	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
70,730 - FRA Check Starter	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
70,770 - FRA Check Exhaust System	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
77,110 - FRA Check Fuel Tank	Done		NPIERRE-	Jul 29, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	8:46:29 AM		
77,120 - Check Suspension Components	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
77,131 - Brake Pad Thickness LF	7 Inch		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
77,132 - Brake Pad Thickness RF	7 Inch		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
77,133 - Brake Pad Thickness LR	4 Inch		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
77,134 - Brake Pad Thickness RR	4 Inch		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
77,135 - Brake Rotor LF	45.5 Inch		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
77,136 - Brake Rotor RF	45.5 Inch		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
77,137 - Brake Rotor LR	35.5 Inch		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
77,138 - Brake Rotor RR	35.5 Inch		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
77,140 - FRA Check Brake Hoses	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
77,150 - Check King Pins	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
80,810 - Completion of PMI Report	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		NPIERRE-LOUIS	Jul 29, 2019 8:46:29 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52551228
Invoice No. 55345 - 52551228

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 172,699 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Jul-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96
29-Jul-19	20021	FILTER, TRANSMISSION 20021	1	17.27	17.27

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Jul-19	NELSON PIERRE-LOUIS	4	65	260

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: NPIERRE-LOUIS Performed on: 29-JUL-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Jul 29, 2019 8:37:18 AM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Jul 29, 2019 8:37:18 AM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Jul 29, 2019 8:37:18 AM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Jul 29, 2019 8:37:18 AM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Jul 29, 2019 8:37:18 AM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Jul 29, 2019 8:37:18 AM	No	
107,000 - FRA Change Primary Fuel Filter	Done		NPIERRE-LOUIS	Jul 29, 2019 8:37:18 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Jul 29, 2019 8:37:18 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		NPIERRE-LOUIS	Jul 29, 2019 8:37:18 AM	No	
201,000 - Service Crankcase Breather	Done		NPIERRE-LOUIS	Jul 29, 2019 8:37:18 AM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		NPIERRE-LOUIS	Jul 29, 2019 8:37:18 AM	No	
204,000 - FRA Change Power Steering Fluid and Filter	Yes		NPIERRE-LOUIS	Jul 29, 2019 8:37:18 AM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		NPIERRE-LOUIS	Jul 29, 2019 8:37:18 AM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		NPIERRE-LOUIS	Jul 29, 2019 8:37:18 AM	No	
301,000 - Check and Lubricate Door Linkages	Done		NPIERRE-LOUIS	Jul 29, 2019 8:37:18 AM	No	
302,000 - Check Toe-In and Record Reading	Done	na	NPIERRE-LOUIS	Jul 29, 2019 8:37:18 AM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	na	NPIERRE-LOUIS	Jul 29, 2019 8:37:18 AM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	Yes		NPIERRE-LOUIS	Jul 29, 2019 8:37:18 AM	No	
305,000 - FRA Change Differential Fluid	Yes		NPIERRE-LOUIS	Jul 29, 2019 8:37:18 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	19.23
Labor:	260.00
Labor Hours:	4.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**279.23**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52551228
Invoice No. 55345 - 52551228

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 172,699 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 29-JUL-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Jul 29, 2019 8:47:08 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Jul 29, 2019 8:47:08 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Jul 29, 2019 8:47:08 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Jul 29, 2019 8:47:08 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Jul 29, 2019 8:47:08 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Jul 29, 2019 8:47:08 AM	No	
20 - Miles			NPIERRE-LOUIS	Jul 29, 2019 8:47:08 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Jul 29, 2019 8:47:08 AM	No	
40 - Hours			NPIERRE-LOUIS	Jul 29, 2019 8:47:08 AM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 52551228 Total	
Parts:	19.23
Labor:	260.00
Labor Hours:	4.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**279.23**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52640045
Invoice No. 55345 - 52640045

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Rear brakes		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	172,519 - DH

Chronology		
Reported	Jul 28, 2019 8:19:23 AM	Jul 28, 2019 8:19:23 AM
Started	Jul 28, 2019 12:00:00 AM	
Completed	Jul 29, 2019 11:06:41 AM	Jul 29, 2019 11:06:41 AM
Down Time		

Work Order Notes

Line 10 Complaint: Rear Brakes was low
Cause: preventive care
Correction: Replaced Rear Brakes Pads
Part : 8c2z-2v200-c Rear Brake part

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 28-JUL-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Jul 28, 2019 8:30:57 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Jul 28, 2019 8:30:57 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Jul 28, 2019 8:30:57 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Jul 28, 2019 8:30:57 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Jul 28, 2019 8:30:57 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Jul 28, 2019 8:30:57 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			NPIERRE-LOUIS	Jul 28, 2019 8:30:57 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Jul 28, 2019 8:30:57 AM	No	
40 - Hours			NPIERRE-LOUIS	Jul 28, 2019 8:30:57 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52640045
Invoice No. 55345 - 52640045

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Rear brakes		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	172,519 - DH

Activity Header
Activity: 20 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Jul-19	8C2Z-2V200-C	PADS, BRAKE, DISC, REAR	1	44.89	44.89

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Jul-19	NELSON PIERRE-LOUIS	2	65	130

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	44.89
Labor:	130.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**174.89**

Work Order Footer

Work Order 52640045 Total	
Parts:	44.89
Labor:	130.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**174.89**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52577872
Invoice No. 55345 - 52577872

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Front AC		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	169,547 - DH

Chronology		
Reported	Jul 5, 2019 8:07:33 PM	Jul 5, 2019 8:07:33 PM
Started	Jul 5, 2019 12:00:00 AM	
Completed	Jul 8, 2019 10:04:13 AM	Jul 8, 2019 10:04:13 AM
Down Time		

Work Order Notes

Line 10 Replaced Front AC blower motor and resistor
Replaced Front Battery terminal block (2)

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jul-19	Delva,Terry	0.3333333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 05-JUL-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jul 5, 2019 8:11:18 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jul 5, 2019 8:11:18 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Jul 5, 2019 8:11:18 PM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Jul 5, 2019 8:11:18 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jul 5, 2019 8:11:18 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jul 5, 2019 8:11:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			TDELVA	Jul 5, 2019 8:11:18 PM	No	
30 - Kilometers			TDELVA	Jul 5, 2019 8:11:18 PM	No	
40 - Hours			TDELVA	Jul 5, 2019 8:11:18 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52577872
Invoice No. 55345 - 52577872

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Front AC		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	169,547 - DH

Activity Header
Activity: 20 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Jul-19	4C2Z-19A706-AA	RESISTOR, MOTOR, BLOWER SAME AS YH1697	1	13.46	13.46
05-Jul-19	XC2Z-19805-BA	MOTOR, BLOWER SAME AS MM-840	1	36.38	36.38
05-Jul-19	3940905	BLOCK, TERMINAL, BATTERY	2	13.81	27.62

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jul-19	Delva,Terry	1.6	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	77.46
Labor:	0.00
Labor Hours:	1.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**77.46**

Work Order Footer

Work Order 52577872 Total	
Parts:	77.46
Labor:	0.00
Labor Hours:	1.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**77.46**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52470513
Invoice No. 55345 - 52470513

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	RRENE	**Status:**	40 - Closed (40)
Created By:	RRENE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	168,221 - DH

Chronology		
Reported	Jun 25, 2019 4:12:42 PM	Jun 25, 2019 4:12:42 PM
Started	Jun 26, 2019 12:00:00 AM	
Completed	Jun 26, 2019 12:21:00 AM	Jun 26, 2019 12:21:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PmA

CAUSE: Service

CORRECTION:perform PmA Service
Oil filter B329 qty 1
Engine oil 5w20 qty 7 Qts
Drain plug oil 65266 Qty1

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Jun-19	Gaspard,Ronald	1.6166666	65	105.083329

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 26-JUN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
10,100 - Safety Inspection	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
10,120 - FRA Check All Warning Lights and	Done		RGASPARD	Jun 26, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				12:07:56 AM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Jun 26, 2019 12:07:56 AM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Jun 26, 2019 12:07:56 AM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Jun 26, 2019 12:07:56 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Jun 26, 2019 12:07:56 AM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Jun 26, 2019 12:07:56 AM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Jun 26, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:07:56 AM		
20,260 - Check Stop Request System	-	na	RGASPARD	Jun 26, 2019 12:07:56 AM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Jun 26, 2019 12:07:56 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Jun 26, 2019 12:07:56 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
40,420 - Check Hood	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Jun 26, 2019 12:07:56 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Jun 26, 2019 12:07:56 AM	No	
40,442 - Freeze Point	Degree	na	RGASPARD	Jun 26, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			12:07:56 AM		
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Jun 26, 2019 12:07:56 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Jun 26, 2019 12:07:56 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Jun 26, 2019 12:07:56 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
60,615 - Air Pressure LRI	65 Pounds per		RGASPARD	Jun 26, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			12:07:56 AM		
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
60,631 - Tread Depth RF	8 32nds of an inch		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
60,632 - Tread Depth LF	10 32nds of an inch		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
70,790 - Check All Body Mounts and Chassis	Done		RGASPARD	Jun 26, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Frame				12:07:56 AM		
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
77,131 - Brake Pad Thickness LF	8 Inch		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
77,132 - Brake Pad Thickness RF	8 Inch		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
77,133 - Brake Pad Thickness LR	7 Inch		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
77,134 - Brake Pad Thickness RR	7 Inch		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
77,137 - Brake Rotor LR	40 Inch		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
77,138 - Brake Rotor RR	40 Inch		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
77,150 - Check King Pins	-	na	RGASPARD	Jun 26, 2019 12:07:56 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Jun 26, 2019 12:07:56 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	105.08
Labor Hours:	1.62
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**105.08**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52470513
Invoice No. 55345 - 52470513

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RRENE
Created By: RRENE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 168,221 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Jun-19	65266	PLUG, DRAIN, OIL, ENGINE	1	4.54	4.54
26-Jun-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Jun-19	Gaspard,Ronald	1.1166666	65	72.583329

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 26-JUN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jun 26, 2019 12:08:31 AM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jun 26, 2019 12:08:31 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jun 26, 2019 12:08:31 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jun 26, 2019 12:08:31 AM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Jun 26, 2019 12:08:31 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jun 26, 2019 12:08:31 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Jun 26, 2019 12:08:31 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jun 26, 2019 12:08:31 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	6.50
Labor:	72.58
Labor Hours:	1.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**79.08**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52470513
Invoice No. 55345 - 52470513

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	RRENE	**Status:**	40 - Closed (40)
Created By:	RRENE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	168,221 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Jun-19	Gaspard,Ronald	0.25	65	16.25

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 26-JUN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Jun 26, 2019 12:08:53 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Jun 26, 2019 12:08:53 AM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Jun 26, 2019 12:08:53 AM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Jun 26, 2019 12:08:53 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Jun 26, 2019 12:08:53 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jun 26, 2019 12:08:53 AM	No	
20 - Miles			RGASPARD	Jun 26, 2019 12:08:53 AM	No	
30 - Kilometers			RGASPARD	Jun 26, 2019 12:08:53 AM	No	
40 - Hours			RGASPARD	Jun 26, 2019 12:08:53 AM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	16.25
	Labor Hours:	0.25
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**16.25**

Work Order Footer

Work Order 52470513 Total	
Parts:	6.50
Labor:	193.92
Labor Hours:	2.98
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**200.42**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52547345
Invoice No. 55345 - 52547345

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Check lft.		Ford E450 Champion Challenger	
Requested By:	EJACKSON	**Status:**	40 - Closed (40)
Created By:	EJACKSON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	167,983 - DH

Chronology		
Reported	Jun 24, 2019 10:35:02 PM	Jun 24, 2019 10:35:02 PM
Started	Jun 24, 2019 12:00:00 AM	
Completed	Jun 25, 2019 12:04:00 AM	Jun 25, 2019 12:04:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Check Lift.

Cause: Normal wear and tear.

Correction: Remove and Replaced 1 out board roll stop stabilizer shock.
Part# 32831 quantity (1).

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Jun-19	EARL JACKSON	0.0333333	65	2.1666645

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EJACKSON Performed on: 24-JUN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EJACKSON	Jun 24, 2019 11:09:56 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EJACKSON	Jun 24, 2019 11:09:56 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EJACKSON	Jun 24, 2019 11:09:56 PM	No	
4 - Have you performed the proper LOTO?	Done		EJACKSON	Jun 24, 2019 11:09:56 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EJACKSON	Jun 24, 2019 11:09:56 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EJACKSON	Jun 24, 2019 11:09:56 PM	No	
20 - Miles			EJACKSON	Jun 24, 2019 11:09:56 PM	No	
30 - Kilometers			EJACKSON	Jun 24, 2019 11:09:56 PM	No	
40 - Hours			EJACKSON	Jun 24, 2019 11:09:56 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	2.17
Labor Hours:	0.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.17**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52547345
Invoice No. 55345 - 52547345

Client Department:
Department: 55345M
Work Order Description
Check lft.
Requested By: EJACKSON
Created By: EJACKSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 167,983 - DH

Activity Header
Activity: 15 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: Check lift.
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Jun-19	32831	SPRING, SHOCK, GAS, W/C	2	26.58	53.16

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Jun-19	EARL JACKSON	0.25	65	16.25

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	53.16
Labor:	16.25
Labor Hours:	0.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**69.41**

Work Order Footer

Work Order 52547345 Total	
Parts:	53.16
Labor:	18.42
Labor Hours:	0.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**71.58**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52388770
Invoice No. 55345 - 52388770

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	163,933 - DH

Chronology		
Reported	May 28, 2019 1:06:31 PM	May 28, 2019 1:06:31 PM
Started		
Completed	May 29, 2019 10:10:17 AM	May 29, 2019 10:10:17 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PmA

CAUSE: preventive maintenance

CORRECTION: perform PmA Service lube all Pivoting Points cross Rotate Tires completed

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 28-MAY-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
10,100 - Safety Inspection	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
10,140 - Check Service Brakes	Done		HPIERRE	May 28, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				1:31:28 PM		
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
11,152 - Decelerometer Results Test 1	FEET	N/A	HPIERRE	May 28, 2019 1:31:28 PM	No	
11,154 - Decelerometer Results Test 2	FEET	N/A	HPIERRE	May 28, 2019 1:31:28 PM	No	
11,156 - Decelerometer Results Test 3	FEET	N/A	HPIERRE	May 28, 2019 1:31:28 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	May 28, 2019 1:31:28 PM	No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	May 28, 2019 1:31:28 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	May 28, 2019 1:31:28 PM	No	
20,270 - Check Fare Box Mounting (If	-	N/A	HPIERRE	May 28, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Applicable)				1:31:28 PM		
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	May 28, 2019 1:31:28 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
40,420 - Check Hood	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	May 28, 2019 1:31:28 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	May 28, 2019 1:31:28 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
40,460 - Record Antifreeze Protection Level	-	N/A	HPIERRE	May 28, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Using Refractometer				1:31:28 PM		
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	May 28, 2019 1:31:28 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	May 28, 2019 1:31:28 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	May 28, 2019 1:31:28 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	May 28, 2019 1:31:28 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	May 28, 2019 1:31:28 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	May 28, 2019 1:31:28 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	May 28, 2019 1:31:28 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	May 28, 2019 1:31:28 PM	No	
60,620 - Check Valve Stems and Caps	Done		HPIERRE	May 28, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				1:31:28 PM		
60,630 - Check and Record Tread Depth	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		HPIERRE	May 28, 2019 1:31:28 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		HPIERRE	May 28, 2019 1:31:28 PM	No	
60,633 - Tread Depth RRO	10 32nds of an inch		HPIERRE	May 28, 2019 1:31:28 PM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		HPIERRE	May 28, 2019 1:31:28 PM	No	
60,635 - Tread Depth LRI	10 32nds of an inch		HPIERRE	May 28, 2019 1:31:28 PM	No	
60,636 - Tread Depth LRO	10 32nds of an inch		HPIERRE	May 28, 2019 1:31:28 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	May 28, 2019 1:31:28 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
77,110 - FRA Check Fuel Tank	Done		HPIERRE	May 28, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				1:31:28 PM		
77,120 - Check Suspension Components	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		HPIERRE	May 28, 2019 1:31:28 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		HPIERRE	May 28, 2019 1:31:28 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		HPIERRE	May 28, 2019 1:31:28 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		HPIERRE	May 28, 2019 1:31:28 PM	No	
77,135 - Brake Rotor LF	1.6 Inch		HPIERRE	May 28, 2019 1:31:28 PM	No	
77,136 - Brake Rotor RF	1.6 Inch		HPIERRE	May 28, 2019 1:31:28 PM	No	
77,137 - Brake Rotor LR	1.7 Inch		HPIERRE	May 28, 2019 1:31:28 PM	No	
77,138 - Brake Rotor RR	1.7 Inch		HPIERRE	May 28, 2019 1:31:28 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	May 28, 2019 1:31:28 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	May 28, 2019 1:31:28 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52388770
Invoice No. 55345 - 52388770

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	163,933 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-May-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 28-MAY-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	May 28, 2019 1:33:27 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	May 28, 2019 1:33:27 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	May 28, 2019 1:33:27 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	May 28, 2019 1:33:27 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	May 28, 2019 1:33:27 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	May 28, 2019 1:33:27 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	May 28, 2019 1:33:27 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	May 28, 2019 1:33:27 PM	No	

Activity Sub Total

Activity 20 Sub Total
Parts: 1.96

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52388770
Invoice No. 55345 - 52388770

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	163,933 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 28-MAY-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	May 28, 2019 1:34:45 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	May 28, 2019 1:34:45 PM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	May 28, 2019 1:34:45 PM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	May 28, 2019 1:34:45 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	May 28, 2019 1:34:45 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	May 28, 2019 1:34:45 PM	No	
20 - Miles			HPIERRE	May 28, 2019 1:34:45 PM	No	
30 - Kilometers	6		HPIERRE	May 28, 2019 1:34:45 PM	No	
40 - Hours	4		HPIERRE	May 28, 2019 1:34:45 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 52388770 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52406431
Invoice No. 55345 - 52406431

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
REPLACE WIPER BLADES		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	160,315 - DH

Chronology		
Reported	May 6, 2019 10:53:00 PM	May 6, 2019 10:53:00 PM
Started	May 6, 2019 12:00:00 AM	
Completed	May 6, 2019 10:59:00 PM	May 6, 2019 10:59:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: WIPER BLADES

Cause: NORMAL USAGE NORMAL WEAR AND TEAR

Correction: REPLACE WIPER BLADES

PARTS# 40520 QTY 2

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-May-19	Owens,Arthur	0.2	65	13

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: AOWENS Performed on: 06-MAY-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		AOWENS	May 6, 2019 10:59:17 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		AOWENS	May 6, 2019 10:59:17 PM	No	
3 - Are you wearing the appropriate PPE?	Done		AOWENS	May 6, 2019 10:59:17 PM	No	
4 - Have you performed the proper LOTO?	Done		AOWENS	May 6, 2019 10:59:17 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	May 6, 2019 10:59:17 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	May 6, 2019 10:59:17 PM	No	
20 - Miles			AOWENS	May 6, 2019 10:59:17 PM	No	
30 - Kilometers			AOWENS	May 6, 2019 10:59:17 PM	No	
40 - Hours			AOWENS	May 6, 2019 10:59:17 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	13.00
Labor Hours:	0.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**13.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52406431
Invoice No. 55345 - 52406431

Client Department:
Department: 55345M
Work Order Description
REPLACE WIPER BLADES
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 160,315 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note: REPLACE WIPER BLADES
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-May-19	40520	BLADE, WIPER, WINDSHIELD, 20"	2	4.16	8.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-May-19	Owens,Arthur	0.3	65	19.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	8.32
Labor:	19.50
Labor Hours:	0.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**27.82**

Work Order Footer

Work Order 52406431 Total	
Parts:	8.32
Labor:	32.50
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**40.82**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52400674
Invoice No. 55345 - 52400674

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Front A/C		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	160,220 - DH

Chronology		
Reported	May 3, 2019 7:33:25 PM	May 3, 2019 7:33:25 PM
Started	May 3, 2019 12:00:00 AM	
Completed	May 3, 2019 11:33:00 PM	May 3, 2019 11:33:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Front A/C / Front Tires

Cause: A/C Evaporator Leaking / Front Tire Worn

Correction: evacuate AC to replace Evaporator & Orifice tube. Recharge A/C to (1.88) lb add (2) Oz Oil& Mount & Balance Front Tire & Replace on Front.
Parts# 3411885 Qty (1)
Parts# 192659 Qty (1)
Parts# 6C2Z-19860-C Qty (1)

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-May-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 03-MAY-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	May 3, 2019 11:12:05 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	May 3, 2019 11:12:05 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	May 3, 2019 11:12:05 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	May 3, 2019 11:12:05 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	May 3, 2019 11:12:05 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	May 3, 2019 11:12:05 PM	No	
20 - Miles			DARTHURS	May 3, 2019 11:12:05 PM	No	
30 - Kilometers			DARTHURS	May 3, 2019 11:12:05 PM	No	
40 - Hours			DARTHURS	May 3, 2019 11:12:05 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	5.42
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.42**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52400674
Invoice No. 55345 - 52400674

Client Department:
Department: 55345M
Work Order Description
Front A/C
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 160,220 - DH

Activity Header
Activity: 15 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-May-19	3411885	TUBE, ORIFICE, A/C, FORD	1	0.75	0.75
03-May-19	6C2Z-19860-C	CORE, EVAPORATOR, A/C	1	101.19	101.19

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-May-19	Arthurs,Durvin	3	65	195

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	101.94
Labor:	195.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**296.94**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52400674
Invoice No. 55345 - 52400674

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Front A/C		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	160,220 - DH

Activity Header
Activity:25 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-May-19	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	120.47	240.94

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-May-19	Arthurs,Durvin	1	65	65

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	240.94
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**305.94**

Work Order Footer

Work Order 52400674 Total	
Parts:	342.88
Labor:	265.42
Labor Hours:	4.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**608.30**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52284980
Invoice No. 55345 - 52284980

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM B		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	159,605 - DH

Chronology		
Reported	Apr 26, 2019 1:15:17 PM	Apr 26, 2019 1:15:17 PM
Started	Apr 30, 2019 12:00:00 AM	
Completed	Apr 30, 2019 4:51:00 PM	Apr 30, 2019 4:51:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PMB Service

CAUSE: Service due by Mileage

CORRECTION: Change Oil & Filter. Lube all Pivoting Points . Check Brakes Clean batteries.
Parts# B329 Qty (1)
Oil 5W20 Qty (7.0) Qt

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Apr-19	Arthurs,Durvin	2	65	130

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 30-APR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Apr 30, 2019 4:22:54 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Apr 30, 2019 4:22:54 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Apr 30, 2019 4:22:54 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Apr 30, 2019 4:22:54 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Apr 30, 2019 4:22:54 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	Apr 30, 2019 4:22:54 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Apr 30, 2019 4:22:54 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	-	NA	DARTHURS	Apr 30, 2019 4:22:54 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Apr 30, 2019 4:22:54 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
40,420 - Check Hood	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Apr 30, 2019 4:22:54 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Apr 30, 2019 4:22:54 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Apr 30, 2019 4:22:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Apr 30, 2019 4:22:54 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Apr 30, 2019 4:22:54 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Apr 30, 2019 4:22:54 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Apr 30, 2019 4:22:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
60,631 - Tread Depth RF	5 32nds of an inch		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
60,632 - Tread Depth LF	6 32nds of an inch		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
60,633 - Tread Depth RRO	9 32nds of an inch		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
60,635 - Tread Depth LRI	10 32nds of an inch		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
60,636 - Tread Depth LRO	9 32nds of an inch		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Apr 30, 2019 4:22:54 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
77,131 - Brake Pad Thickness LF	2 Inch		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
77,132 - Brake Pad Thickness RF	4 Inch		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
77,135 - Brake Rotor LF	1.553 Inch		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
77,136 - Brake Rotor RF	1.552 Inch		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
77,137 - Brake Rotor LR	1.412 Inch		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
77,138 - Brake Rotor RR	1.413 Inch		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Apr 30, 2019 4:22:54 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	-	NA	DARTHURS	Apr 30, 2019 4:22:54 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Apr 30, 2019 4:22:54 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	130.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**130.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52284980
Invoice No. 55345 - 52284980

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 159,605 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Apr-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96
29-Apr-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Apr-19	Arthurs,Durvin	0.4166666	65	27.083329

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: DARTHURS Performed on: 30-APR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Apr 30, 2019 4:25:04 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Apr 30, 2019 4:25:04 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Apr 30, 2019 4:25:04 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Apr 30, 2019 4:25:04 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Apr 30, 2019 4:25:04 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Apr 30, 2019 4:25:04 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Apr 30, 2019 4:25:04 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Apr 30, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				4:25:04 PM		
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	Apr 30, 2019 4:25:04 PM	No	
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Apr 30, 2019 4:25:04 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		DARTHURS	Apr 30, 2019 4:25:04 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Apr 30, 2019 4:25:04 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Apr 30, 2019 4:25:04 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	3.92
Labor:	27.08
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**31.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52284980
Invoice No. 55345 - 52284980

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM B		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	159,605 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Apr-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 30-APR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Apr 30, 2019 4:25:45 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Apr 30, 2019 4:25:45 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Apr 30, 2019 4:25:45 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Apr 30, 2019 4:25:45 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Apr 30, 2019 4:25:45 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 30, 2019 4:25:45 PM	No	
20 - Miles			DARTHURS	Apr 30, 2019 4:25:45 PM	No	
30 - Kilometers			DARTHURS	Apr 30, 2019 4:25:45 PM	No	
40 - Hours			DARTHURS	Apr 30, 2019 4:25:45 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	5.42
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**5.42**

Work Order Footer

Work Order 52284980 Total	
Parts:	3.92
Labor:	162.50
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**166.42**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52388699
Invoice No. 55345 - 52388699

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Front brakes/ Heater hose		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	159,605 - DH

Chronology		
Reported	Apr 30, 2019 4:30:12 PM	Apr 30, 2019 4:30:12 PM
Started	Apr 30, 2019 12:00:00 AM	
Completed	Apr 30, 2019 4:50:00 PM	Apr 30, 2019 4:50:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Front Brakes/ heater hose.

Cause: Front Brakes Low/ heater hose Leaking.

Correction: Remove& Replace heater hose & Remove& Replace Front Brakes Clean frozen slide. Lube & Replace.
Parts# 8C2Z-2V001-D Qty (1)
Parts# 8C2Z-18472-CA Qty (1)
Parts# BC2Z-18472-DA Qty-DA

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Apr-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 30-APR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Apr 30, 2019 4:31:50 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Apr 30, 2019 4:31:50 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Apr 30, 2019 4:31:50 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Apr 30, 2019 4:31:50 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Apr 30, 2019 4:31:50 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 30, 2019 4:31:50 PM	No	
20 - Miles			DARTHURS	Apr 30, 2019 4:31:50 PM	No	
30 - Kilometers			DARTHURS	Apr 30, 2019 4:31:50 PM	No	
40 - Hours			DARTHURS	Apr 30, 2019 4:31:50 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	5.42
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.42**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52388699
Invoice No. 55345 - 52388699

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Front brakes/ Heater hose		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	159,605 - DH

Activity Header
Activity: 15 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Apr-19	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	48.87	48.87

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Apr-19	Arthurs,Durvin	1	65	65

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	48.87
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**113.87**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52388699
Invoice No. 55345 - 52388699

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Front brakes/ Heater hose		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	159,605 - DH

Activity Header
Activity:25 042/000/000 COOLING SYSTEM
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Apr-19	BC2Z-18472-CA	TUBE, HEATER, WATER	1	59.54	59.54
30-Apr-19	BC2Z-18472-DA	TUBE, HEATER, WATER	1	56.59	56.59

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Apr-19	Arthurs,Durvin	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	116.13
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**213.63**

Work Order Footer

Work Order 52388699 Total	
Parts:	165.00
Labor:	167.92
Labor Hours:	2.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**332.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52198633
Invoice No. 55345 - 52198633

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	154,801 - DH

Chronology		
Reported	Mar 25, 2019 11:06:32 AM	Mar 25, 2019 11:06:32 AM
Started	Mar 25, 2019 12:00:00 AM	
Completed	Mar 26, 2019 8:27:00 AM	Mar 26, 2019 8:27:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA

CAUSE: preventive maintenance

CORRECTION: Perform PMA Service Lube all Pivoting Points Cross Rotate completed

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Mar-19	Pierre,Hubert J	6	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 25-MAR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
10,100 - Safety Inspection	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,140 - Check Service Brakes	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
11,152 - Decelerometer Results Test 1	FEET	N/A	HPIERRE	Mar 25, 2019 12:28:05 PM	No	
11,154 - Decelerometer Results Test 2	FEET	N/A	HPIERRE	Mar 25, 2019 12:28:05 PM	No	
11,156 - Decelerometer Results Test 3	FEET	N/A	HPIERRE	Mar 25, 2019 12:28:05 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	Mar 25, 2019 12:28:05 PM	No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	Mar 25, 2019 12:28:05 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Mar 25, 2019 12:28:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Mar 25, 2019 12:28:05 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Mar 25, 2019 12:28:05 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
30,380 - Check Exterior Compartment Doors	-	N/A	HPIERRE	Mar 25, 2019 12:28:05 PM	No	
30,390 - FRA Check Fuel Tank Cap	-	N/A	HPIERRE	Mar 25, 2019 12:28:05 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
40,420 - Check Hood	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Mar 25, 2019 12:28:05 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Mar 25, 2019 12:28:05 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Mar 25, 2019 12:28:05 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Mar 25, 2019 12:28:05 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Mar 25, 2019 12:28:05 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Mar 25, 2019 12:28:05 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Mar 25, 2019 12:28:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
60,633 - Tread Depth RRO	12 32nds of an inch		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
60,636 - Tread Depth LRO	12 32nds of an inch		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Mar 25, 2019 12:28:05 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
77,131 - Brake Pad Thickness LF	6 Inch		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
77,132 - Brake Pad Thickness RF	6 Inch		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
77,135 - Brake Rotor LF	1.6 Inch		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
77,136 - Brake Rotor RF	1.6 Inch		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
77,137 - Brake Rotor LR	1.7 Inch		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
77,138 - Brake Rotor RR	1.7 Inch		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Mar 25, 2019 12:28:05 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Mar 25, 2019 12:28:05 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	6.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52198633
Invoice No. 55345 - 52198633

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 154,801 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Mar-19	B329	FILTER, OIL, SPIN-ON SEE P550965	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Mar-19	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 25-MAR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Mar 25, 2019 12:29:07 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Mar 25, 2019 12:29:07 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Mar 25, 2019 12:29:07 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Mar 25, 2019 12:29:07 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Mar 25, 2019 12:29:07 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Mar 25, 2019 12:29:07 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Mar 25, 2019 12:29:07 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Mar 25, 2019 12:29:07 PM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	1.96
	Labor:	0.00
	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52198633
Invoice No. 55345 - 52198633

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	154,801 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Mar-19	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 25-MAR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Mar 25, 2019 12:29:51 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Mar 25, 2019 12:29:51 PM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Mar 25, 2019 12:29:51 PM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Mar 25, 2019 12:29:51 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Mar 25, 2019 12:29:51 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Mar 25, 2019 12:29:51 PM	No	
20 - Miles			HPIERRE	Mar 25, 2019 12:29:51 PM	No	
30 - Kilometers	6		HPIERRE	Mar 25, 2019 12:29:51 PM	No	
40 - Hours	6		HPIERRE	Mar 25, 2019 12:29:51 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 52198633 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	6.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52128027
Invoice No. 55345 - 52128027

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	150,368 - DH

Chronology		
Reported	Feb 25, 2019 8:07:00 AM	Feb 25, 2019 8:07:00 AM
Started	Feb 25, 2019 12:00:00 AM	
Completed	Feb 25, 2019 9:58:00 AM	Feb 25, 2019 9:58:00 AM
Down Time		

Work Order Notes

Line 10 PM.

Perform pmA service, lube front end, tire rotation, torque and re torque tires (140 f/p), R&R engine oil and filter, road test, all okay at this time.

Parts. Engine oil filter part # B329 qty 1
engine oil. 5W20 Qty 7 qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Feb-19	B329	FILTER, OIL, SPIN-ON SEE P550965	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Feb-19	Rodriguez,Raul	1.7666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RAURODRIGUEZ Performed on: 25-FEB-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
10,100 - Safety Inspection	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
10,110 - FRA Check Drivers Pre-trip or	Done		RAURODRIGUEZ	Feb 25, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
DVIR/EVIR & Authorization Forms				9:55:07 AM		
10,120 - FRA Check All Warning Lights and Alarms	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
10,140 - Check Service Brakes	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
10,160 - FRA Check Instruments and Horns	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
10,170 - Check Fast Idle	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
10,180 - Check Starter Protection Circuit	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
10,190 - Check Reverse Warning System	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
11,100 - Check Parking Brake	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
11,150 - Perform Brake Test	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
11,170 - FRA Check Door Operation	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
20,210 - Check Condition of Operator's Area	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
20,240 - FRA Check Interior Lights	Done		RAURODRIGUEZ	Feb 25, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:55:07 AM		
20,250 - FRA Check Interior Electrical Panels	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
20,260 - Check Stop Request System	-	na	RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
22,110 - Check Emergency Hatches	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
22,120 - Check All Safety Equipment	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
30,310 - Check Passenger Doors	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
30,360 - Check for Physical Damage and Decals	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
30,380 - Check Exterior Compartment Doors	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
33,100 - Check Lights and Reflectors	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
40,420 - Check Hood	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate	No	na	RAURODRIGUEZ	Feb 25, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
with a Yes or No)				9:55:07 AM		
40,442 - Freeze Point	Degree Fahrenheit	na	RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
44,130 - FRA Check Exhaust System	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
44,140 - FRA Check Intake System	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
44,150 - FRA Inspect Turbocharger	-	na	RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
44,180 - FRA Check for Leaks	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
44,190 - FRA Perform Battery Inspection	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
50,510 - Check Entire Steering System	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
60,614 - Air Pressure RRI	65 Pounds per		RAURODRIGUEZ	Feb 25, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			9:55:07 AM		
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
60,620 - Check Valve Stems and Caps	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
60,630 - Check and Record Tread Depth	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
60,631 - Tread Depth RF	10 32nds of an inch		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
60,632 - Tread Depth LF	10 32nds of an inch		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
60,633 - Tread Depth RRO	13 32nds of an inch		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
60,634 - Tread Depth RRI	13 32nds of an inch		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
60,635 - Tread Depth LRI	13 32nds of an inch		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
60,636 - Tread Depth LRO	13 32nds of an inch		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
60,650 - Check Sidewall Wear	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
60,660 - Inspect for Cuts and Tears	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
60,670 - Check Dual Mating With Square	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
70,710 - Check Vibration Damper	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
70,730 - FRA Check Starter	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
70,770 - FRA Check Exhaust System	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
70,780 - Check Driveline, U-joint and Slip	Done		RAURODRIGUEZ	Feb 25, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Yokes				9:55:07 AM		
70,790 - Check All Body Mounts and Chassis Frame	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
77,110 - FRA Check Fuel Tank	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
77,120 - Check Suspension Components	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
77,131 - Brake Pad Thickness LF	Inch	6mm	RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
77,132 - Brake Pad Thickness RF	Inch	6mm	RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
77,133 - Brake Pad Thickness LR	Inch	9mm	RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
77,134 - Brake Pad Thickness RR	Inch	9mm	RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
77,135 - Brake Rotor LF	Inch	39.4mm	RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
77,136 - Brake Rotor RF	Inch	39.4mm	RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
77,137 - Brake Rotor LR	Inch	38.8mm	RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
77,138 - Brake Rotor RR	Inch	38.8mm	RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
77,140 - FRA Check Brake Hoses	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
77,150 - Check King Pins	-	na	RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
80,810 - Completion of PMI Report	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		RAURODRIGUEZ	Feb 25, 2019 9:55:07 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	1.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52128027
Invoice No. 55345 - 52128027

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 150,368 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Feb-19	65266	PLUG, DRAIN, OIL, ENGINE	1	5.87	5.87

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Feb-19	Rodriguez,Raul	0.6333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RAURODRIGUEZ Performed on: 25-FEB-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RAURODRIGUEZ	Feb 25, 2019 9:56:50 AM	No	
101,000 - FRA Change Oil Filters	Yes		RAURODRIGUEZ	Feb 25, 2019 9:56:50 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RAURODRIGUEZ	Feb 25, 2019 9:56:50 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RAURODRIGUEZ	Feb 25, 2019 9:56:50 AM	No	
104,000 - Lubricate Chassis	Done		RAURODRIGUEZ	Feb 25, 2019 9:56:50 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RAURODRIGUEZ	Feb 25, 2019 9:56:50 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RAURODRIGUEZ	Feb 25, 2019 9:56:50 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RAURODRIGUEZ	Feb 25, 2019 9:56:50 AM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	5.87
	Labor:	0.00
	Labor Hours:	0.63
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**5.87**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52128027
Invoice No. 55345 - 52128027

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 150,368 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 25-FEB-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Feb 25, 2019 9:57:47 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Feb 25, 2019 9:57:47 AM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Feb 25, 2019 9:57:47 AM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Feb 25, 2019 9:57:47 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Feb 25, 2019 9:57:47 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Feb 25, 2019 9:57:47 AM	No	
20 - Miles			RAURODRIGUEZ	Feb 25, 2019 9:57:47 AM	No	
30 - Kilometers			RAURODRIGUEZ	Feb 25, 2019 9:57:47 AM	No	
40 - Hours			RAURODRIGUEZ	Feb 25, 2019 9:57:47 AM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 52128027 Total	
Parts:	7.83
Labor:	0.00
Labor Hours:	2.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.83**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52142933
Invoice No. 55345 - 52142933

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Rear a/c service		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	147,409 - DH

Chronology		
Reported	Feb 5, 2019 1:48:08 PM	Feb 5, 2019 1:48:08 PM
Started	Feb 5, 2019 12:00:00 AM	
Completed	Feb 6, 2019 10:25:14 AM	Feb 6, 2019 10:25:14 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:Rear a/c service

Cause: evacuate and recharge a/c

Correction:Replace orifice tube, evacuate and recharge a/c system retest ok at this time

Part:
1 new orifice tube 3411885

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 05-FEB-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Feb 5, 2019 1:54:21 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Feb 5, 2019 1:54:21 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Feb 5, 2019 1:54:21 PM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Feb 5, 2019 1:54:21 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Feb 5, 2019 1:54:21 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Feb 5, 2019 1:54:21 PM	No	
20 - Miles			JAPEREZ	Feb 5, 2019 1:54:21 PM	No	
30 - Kilometers			JAPEREZ	Feb 5, 2019 1:54:21 PM	No	
40 - Hours			JAPEREZ	Feb 5, 2019 1:54:21 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52142933
Invoice No. 55345 - 52142933

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Rear a/c service		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	147,409 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear a/c service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Feb-19	3411885	TUBE, ORIFICE, A/C, FORD	1	0.75	0.75

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Feb-19	Perez,Javier	2.3333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.75
Labor:	0.00
Labor Hours:	2.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.75**

Work Order Footer

Work Order 52142933 Total	
Parts:	0.75
Labor:	0.00
Labor Hours:	2.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52043033
Invoice No. 55345 - 52043033

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM C		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	146,575 - DH

Chronology		
Reported	Jan 30, 2019 1:16:28 PM	Jan 30, 2019 1:16:28 PM
Started		
Completed	Jan 31, 2019 9:02:00 AM	Jan 31, 2019 9:02:00 AM
Down Time		

Work Order Notes

Line 10 PMC

Preventive maintenance

Perform service lube all Pivoting Points cross Rotate Tires completed

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 31-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
10,100 - Safety Inspection	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Jan 31, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:09:11 AM		
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
11,152 - Decelerometer Results Test 1	FEET	N/A	HPIERRE	Jan 31, 2019 8:09:11 AM	No	
11,154 - Decelerometer Results Test 2	FEET	N/A	HPIERRE	Jan 31, 2019 8:09:11 AM	No	
11,156 - Decelerometer Results Test 3	FEET	N/A	HPIERRE	Jan 31, 2019 8:09:11 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	Jan 31, 2019 8:09:11 AM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	N/A	HPIERRE	Jan 31, 2019 8:09:11 AM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
20,260 - Check Stop Request System	-	N;/A	HPIERRE	Jan 31, 2019 8:09:11 AM	No	
20,270 - Check Fare Box Mounting (If	-	N/A	HPIERRE	Jan 31, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Applicable)				8:09:11 AM		
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Jan 31, 2019 8:09:11 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
40,420 - Check Hood	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Jan 31, 2019 8:09:11 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Jan 31, 2019 8:09:11 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Jan 31, 2019 8:09:11 AM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
40,460 - Record Antifreeze Protection Level	-	N/A	HPIERRE	Jan 31, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Using Refractometer				8:09:11 AM		
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Jan 31, 2019 8:09:11 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	-	N/A	HPIERRE	Jan 31, 2019 8:09:11 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Jan 31, 2019 8:09:11 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Jan 31, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:09:11 AM		
60,630 - Check and Record Tread Depth	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
60,631 - Tread Depth RF	10 32nds of an inch		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
60,632 - Tread Depth LF	10 32nds of an inch		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
60,633 - Tread Depth RRO	12 32nds of an inch		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
60,636 - Tread Depth LRO	12 32nds of an inch		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Jan 31, 2019 8:09:11 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Jan 31, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:09:11 AM		
77,120 - Check Suspension Components	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
77,131 - Brake Pad Thickness LF	12 Inch		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
77,132 - Brake Pad Thickness RF	12 Inch		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
77,133 - Brake Pad Thickness LR	12 Inch		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
77,134 - Brake Pad Thickness RR	12 Inch		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
77,135 - Brake Rotor LF	1.6 Inch		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
77,136 - Brake Rotor RF	1.6 Inch		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
77,137 - Brake Rotor LR	1.7 Inch		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
77,138 - Brake Rotor RR	1.7 Inch		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Jan 31, 2019 8:09:11 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Jan 31, 2019 8:09:11 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52043033
Invoice No. 55345 - 52043033

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 146,575 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
31-Jan-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: HPIERRE Performed on: 31-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Jan 31, 2019 8:12:12 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Jan 31, 2019 8:12:12 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Jan 31, 2019 8:12:12 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Jan 31, 2019 8:12:12 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Jan 31, 2019 8:12:12 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Jan 31, 2019 8:12:12 AM	No	
107,000 - FRA Change Primary Fuel Filter	Done		HPIERRE	Jan 31, 2019 8:12:12 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Jan 31, 2019 8:12:12 AM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		HPIERRE	Jan 31, 2019 8:12:12 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
201,000 - Service Crankcase Breather	Done		HPIERRE	Jan 31, 2019 8:12:12 AM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		HPIERRE	Jan 31, 2019 8:12:12 AM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		HPIERRE	Jan 31, 2019 8:12:12 AM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		HPIERRE	Jan 31, 2019 8:12:12 AM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		HPIERRE	Jan 31, 2019 8:12:12 AM	No	
301,000 - Check and Lubricate Door Linkages	Done		HPIERRE	Jan 31, 2019 8:12:12 AM	No	
302,000 - Check Toe-In and Record Reading	-	N/A	HPIERRE	Jan 31, 2019 8:12:12 AM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	N/A	HPIERRE	Jan 31, 2019 8:12:12 AM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		HPIERRE	Jan 31, 2019 8:12:12 AM	No	
305,000 - FRA Change Differential Fluid	Yes		HPIERRE	Jan 31, 2019 8:12:12 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52043033
Invoice No. 55345 - 52043033

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM C		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	146,575 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 31-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Jan 31, 2019 8:13:23 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Jan 31, 2019 8:13:23 AM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Jan 31, 2019 8:13:23 AM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Jan 31, 2019 8:13:23 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Jan 31, 2019 8:13:23 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Jan 31, 2019 8:13:23 AM	No	
20 - Miles			HPIERRE	Jan 31, 2019 8:13:23 AM	No	
30 - Kilometers	8		HPIERRE	Jan 31, 2019 8:13:23 AM	No	
40 - Hours	8		HPIERRE	Jan 31, 2019 8:13:23 AM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 52043033 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52116137
Invoice No. 55345 - 52116137

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Rear Tires/ Rear Brakes		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	145,911 - DH

Chronology		
Reported	Jan 27, 2019 5:26:28 PM	Jan 27, 2019 5:26:28 PM
Started	Jan 27, 2019 12:00:00 AM	
Completed	Jan 27, 2019 5:39:00 PM	Jan 27, 2019 5:39:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear Brakes& Rear Tires.

Cause: Rear brakes uneven wear / low .rear tires below spec.

Correction: Mount& Balance Rear Tires& Remove& Replace Rear Brakes. Replace tire on rear.
Parts# 002760 Qty (4)
Parts #8C2Z-2V200-C Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Jan-19	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 27-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jan 27, 2019 5:28:27 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jan 27, 2019 5:28:27 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jan 27, 2019 5:28:27 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jan 27, 2019 5:28:27 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jan 27, 2019 5:28:27 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jan 27, 2019 5:28:27 PM	No	
20 - Miles			DARTHURS	Jan 27, 2019 5:28:27 PM	No	
30 - Kilometers			DARTHURS	Jan 27, 2019 5:28:27 PM	No	
40 - Hours			DARTHURS	Jan 27, 2019 5:28:27 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52116137
Invoice No. 55345 - 52116137

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Rear Tires/ Rear Brakes		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	145,911 - DH

Activity Header
Activity: 15 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Jan-19	8C2Z-2V200-C	PADS, BRAKE, DISC, REAR	1	47.81	47.81

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Jan-19	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	47.81
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**47.81**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52116137
Invoice No. 55345 - 52116137

Client Department:
Department: 55345M
Work Order Description
Rear Tires/ Rear Brakes
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 145,911 - DH

Activity Header
Activity: 25 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Jan-19	002760	TIRE, 225/75R16, 10-PLY, BSW, HT2, TRANSFORCE, FIRESTONE	4	108.36	433.44

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Jan-19	Arthurs,Durvin	0.5	0	0
27-Jan-19	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	433.44
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**433.44**

Work Order Footer

Work Order 52116137 Total	
Parts:	481.25
Labor:	0.00
Labor Hours:	3.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**481.25**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52103415
Invoice No. 55345 - 52103415

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Vehicle wont crank		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	145,435 - DH

Chronology		
Reported	Jan 23, 2019 8:32:03 AM	Jan 23, 2019 8:32:03 AM
Started	Jan 23, 2019 12:00:00 AM	
Completed	Jan 23, 2019 1:00:14 PM	Jan 23, 2019 1:00:14 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:vehicle won¿t crank

Cause: check cranking system found both batteries internal failure

Correction:replaced batteries retest system ok at this time

Parts:
2 new batteries 34AGM

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 23-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Jan 23, 2019 8:38:50 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Jan 23, 2019 8:38:50 AM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Jan 23, 2019 8:38:50 AM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Jan 23, 2019 8:38:50 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Jan 23, 2019 8:38:50 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Jan 23, 2019 8:38:50 AM	No	
20 - Miles			JAPEREZ	Jan 23, 2019 8:38:50 AM	No	
30 - Kilometers			JAPEREZ	Jan 23, 2019 8:38:50 AM	No	
40 - Hours			JAPEREZ	Jan 23, 2019 8:38:50 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52103415
Invoice No. 55345 - 52103415

Client Department:
Department: 55345M
Work Order Description
Vehicle wont crank
Requested By: JAPEREZ
Created By: JAPEREZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 145,435 - DH

Activity Header
Activity: 15 032 CRANKING
Activity Note: Vehicle wont crank
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Jan-19	34AGM	BATTERY, AGM, GROUP-34	2	115.74	231.48

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jan-19	Perez,Javier	1.25	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	231.48
Labor:	0.00
Labor Hours:	1.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**231.48**

Work Order Footer

Work Order 52103415 Total	
Parts:	231.48
Labor:	0.00
Labor Hours:	1.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**231.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52077671
Invoice No. 55345 - 52077671

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Vehicle wont crank		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	143,955 - DH

Chronology		
Reported	Jan 14, 2019 2:53:47 PM	Jan 14, 2019 2:53:47 PM
Started	Jan 14, 2019 12:00:00 AM	
Completed	Jan 15, 2019 11:07:50 AM	Jan 15, 2019 11:07:50 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: vehicle won¿t crank

Cause: check cranking system found both batteries internal failure

Correction:replace batteries retest system ok at this time

Parts:
2 new batteries 34agm

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 14-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Jan 14, 2019 3:02:32 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Jan 14, 2019 3:02:32 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Jan 14, 2019 3:02:32 PM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Jan 14, 2019 3:02:32 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Jan 14, 2019 3:02:32 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Jan 14, 2019 3:02:32 PM	No	
20 - Miles			JAPEREZ	Jan 14, 2019 3:02:32 PM	No	
30 - Kilometers			JAPEREZ	Jan 14, 2019 3:02:32 PM	No	
40 - Hours			JAPEREZ	Jan 14, 2019 3:02:32 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52077671
Invoice No. 55345 - 52077671

Client Department:
Department: 55345M
Work Order Description
Vehicle wont crank
Requested By: JAPEREZ
Created By: JAPEREZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 143,955 - DH

Activity Header
Activity: 15 032 CRANKING
Activity Note: Vehicle wont crank
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Jan-19	34AGM	BATTERY, AGM, GROUP-34	2	114.99	229.98

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Jan-19	Perez,Javier	1.25	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	229.98
Labor:	0.00
Labor Hours:	1.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**229.98**

Work Order Footer

Work Order 52077671 Total	
Parts:	229.98
Labor:	0.00
Labor Hours:	1.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**229.98**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51968105
Invoice No. 55345 - 51968105

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	142,345 - DH

Chronology		
Reported	Jan 3, 2019 10:12:10 AM	Jan 3, 2019 10:12:10 AM
Started	Jan 3, 2019 12:00:00 AM	
Completed	Jan 3, 2019 4:43:00 PM	Jan 3, 2019 4:43:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA

CAUSE: Service due

CORRECTION: Performed and completed pmA Service
Changed engine oil and replaced engine oil filter

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jan-19	Delva,Terry	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: TDELVA Performed on: 03-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
10,100 - Safety Inspection	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
10,140 - Check Service Brakes	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
10,160 - FRA Check Instruments and Horns	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
10,170 - Check Fast Idle	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
10,180 - Check Starter Protection Circuit	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
10,190 - Check Reverse Warning System	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
11,100 - Check Parking Brake	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
11,150 - Perform Brake Test	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	TDELVA	Jan 3, 2019 4:20:36 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	TDELVA	Jan 3, 2019 4:20:36 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	TDELVA	Jan 3, 2019 4:20:36 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	TDELVA	Jan 3, 2019 4:20:36 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	TDELVA	Jan 3, 2019 4:20:36 PM	No	
11,170 - FRA Check Door Operation	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
20,210 - Check Condition of Operator's Area	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
20,240 - FRA Check Interior Lights	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	TDELVA	Jan 3, 2019 4:20:36 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	TDELVA	Jan 3, 2019 4:20:36 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
22,110 - Check Emergency Hatches	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
22,120 - Check All Safety Equipment	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
30,310 - Check Passenger Doors	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	TDELVA	Jan 3, 2019 4:20:36 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
30,360 - Check for Physical Damage and Decals	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
30,380 - Check Exterior Compartment Doors	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
33,100 - Check Lights and Reflectors	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
40,420 - Check Hood	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	TDELVA	Jan 3, 2019 4:20:36 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	TDELVA	Jan 3, 2019 4:20:36 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	TDELVA	Jan 3, 2019 4:20:36 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	TDELVA	Jan 3, 2019 4:20:36 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	TDELVA	Jan 3, 2019 4:20:36 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
44,130 - FRA Check Exhaust System	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
44,140 - FRA Check Intake System	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	TDELVA	Jan 3, 2019 4:20:36 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
44,180 - FRA Check for Leaks	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
44,190 - FRA Perform Battery Inspection	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
50,510 - Check Entire Steering System	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		TDELVA	Jan 3, 2019 4:20:36 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		TDELVA	Jan 3, 2019 4:20:36 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		TDELVA	Jan 3, 2019 4:20:36 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		TDELVA	Jan 3, 2019 4:20:36 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		TDELVA	Jan 3, 2019 4:20:36 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		TDELVA	Jan 3, 2019 4:20:36 PM	No	
60,620 - Check Valve Stems and Caps	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
60,630 - Check and Record Tread Depth	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		TDELVA	Jan 3, 2019 4:20:36 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		TDELVA	Jan 3, 2019 4:20:36 PM	No	
60,633 - Tread Depth RRO	9 32nds of an inch		TDELVA	Jan 3, 2019 4:20:36 PM	No	
60,634 - Tread Depth RRI	9 32nds of an inch		TDELVA	Jan 3, 2019 4:20:36 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		TDELVA	Jan 3, 2019 4:20:36 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		TDELVA	Jan 3, 2019 4:20:36 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
60,650 - Check Sidewall Wear	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
60,660 - Inspect for Cuts and Tears	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
60,670 - Check Dual Mating With Square	-	NA	TDELVA	Jan 3, 2019 4:20:36 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
70,710 - Check Vibration Damper	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
70,730 - FRA Check Starter	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
70,770 - FRA Check Exhaust System	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
77,110 - FRA Check Fuel Tank	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
77,120 - Check Suspension Components	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		TDELVA	Jan 3, 2019 4:20:36 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		TDELVA	Jan 3, 2019 4:20:36 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		TDELVA	Jan 3, 2019 4:20:36 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		TDELVA	Jan 3, 2019 4:20:36 PM	No	
77,135 - Brake Rotor LF	39.7 Inch		TDELVA	Jan 3, 2019 4:20:36 PM	No	
77,136 - Brake Rotor RF	39.7 Inch		TDELVA	Jan 3, 2019 4:20:36 PM	No	
77,137 - Brake Rotor LR	38.6 Inch		TDELVA	Jan 3, 2019 4:20:36 PM	No	
77,138 - Brake Rotor RR	38.6 Inch		TDELVA	Jan 3, 2019 4:20:36 PM	No	
77,140 - FRA Check Brake Hoses	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
77,150 - Check King Pins	-	NA	TDELVA	Jan 3, 2019 4:20:36 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
80,810 - Completion of PMI Report	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		TDELVA	Jan 3, 2019 4:20:36 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51968105
Invoice No. 55345 - 51968105

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 142,345 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Jan-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jan-19	Delva,Terry	0.8833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: TDELVA Performed on: 03-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		TDELVA	Jan 3, 2019 4:21:15 PM	No	
101,000 - FRA Change Oil Filters	Yes		TDELVA	Jan 3, 2019 4:21:15 PM	No	
102,000 - FRA Drain Engine Oil	Yes		TDELVA	Jan 3, 2019 4:21:15 PM	No	
103,000 - FRA Check Transmission Fluid	Done		TDELVA	Jan 3, 2019 4:21:15 PM	No	
104,000 - Lubricate Chassis	Done		TDELVA	Jan 3, 2019 4:21:15 PM	No	
105,000 - Replace or Clean A/C Filters	Done		TDELVA	Jan 3, 2019 4:21:15 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	TDELVA	Jan 3, 2019 4:21:15 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		TDELVA	Jan 3, 2019 4:21:15 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	0.88
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51968105
Invoice No. 55345 - 51968105

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	142,345 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jan-19	Delva,Terry	0.5	0	0
03-Jan-19	Delva,Terry	0.6	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 03-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jan 3, 2019 3:50:10 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jan 3, 2019 3:50:10 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Jan 3, 2019 3:50:10 PM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Jan 3, 2019 3:50:10 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jan 3, 2019 3:50:10 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jan 3, 2019 3:50:10 PM	No	
20 - Miles			TDELVA	Jan 3, 2019 3:50:10 PM	No	
30 - Kilometers			TDELVA	Jan 3, 2019 3:50:10 PM	No	
40 - Hours			TDELVA	Jan 3, 2019 3:50:10 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51968105 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.98
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51888541
Invoice No. 55345 - 51888541

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	138,153 - DH

Chronology		
Reported	Dec 5, 2018 10:49:52 AM	Dec 5, 2018 10:49:52 AM
Started	Dec 5, 2018 12:00:00 AM	
Completed	Dec 5, 2018 5:40:00 PM	Dec 5, 2018 5:40:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PM A

CAUSE: Service due

CORRECTION: Performed and completed pmA
Changed engine oil and replaced engine oil filter
Replaced rear AC filter

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Dec-18	Delva,Terry	1.35	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: TDELVA Performed on: 05-DEC-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
10,100 - Safety Inspection	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
10,140 - Check Service Brakes	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
10,160 - FRA Check Instruments and Horns	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
10,170 - Check Fast Idle	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
10,180 - Check Starter Protection Circuit	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
10,190 - Check Reverse Warning System	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
11,100 - Check Parking Brake	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
11,150 - Perform Brake Test	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	TDELVA	Dec 5, 2018 4:27:28 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	TDELVA	Dec 5, 2018 4:27:28 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	TDELVA	Dec 5, 2018 4:27:28 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	TDELVA	Dec 5, 2018 4:27:28 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	TDELVA	Dec 5, 2018 4:27:28 PM	No	
11,170 - FRA Check Door Operation	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
20,210 - Check Condition of Operator's Area	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
20,240 - FRA Check Interior Lights	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	na	TDELVA	Dec 5, 2018 4:27:28 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	TDELVA	Dec 5, 2018 4:27:28 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
22,110 - Check Emergency Hatches	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
22,120 - Check All Safety Equipment	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
30,310 - Check Passenger Doors	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	TDELVA	Dec 5, 2018 4:27:28 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
30,360 - Check for Physical Damage and Decals	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
30,380 - Check Exterior Compartment Doors	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
33,100 - Check Lights and Reflectors	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
40,420 - Check Hood	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	TDELVA	Dec 5, 2018 4:27:28 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	TDELVA	Dec 5, 2018 4:27:28 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	TDELVA	Dec 5, 2018 4:27:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	TDELVA	Dec 5, 2018 4:27:28 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	TDELVA	Dec 5, 2018 4:27:28 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
44,130 - FRA Check Exhaust System	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
44,140 - FRA Check Intake System	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	TDELVA	Dec 5, 2018 4:27:28 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
44,180 - FRA Check for Leaks	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
44,190 - FRA Perform Battery Inspection	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
50,510 - Check Entire Steering System	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		TDELVA	Dec 5, 2018 4:27:28 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		TDELVA	Dec 5, 2018 4:27:28 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		TDELVA	Dec 5, 2018 4:27:28 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		TDELVA	Dec 5, 2018 4:27:28 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		TDELVA	Dec 5, 2018 4:27:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		TDELVA	Dec 5, 2018 4:27:28 PM	No	
60,620 - Check Valve Stems and Caps	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
60,630 - Check and Record Tread Depth	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
60,631 - Tread Depth RF	11 32nds of an inch		TDELVA	Dec 5, 2018 4:27:28 PM	No	
60,632 - Tread Depth LF	11 32nds of an inch		TDELVA	Dec 5, 2018 4:27:28 PM	No	
60,633 - Tread Depth RRO	10 32nds of an inch		TDELVA	Dec 5, 2018 4:27:28 PM	No	
60,634 - Tread Depth RRI	9 32nds of an inch		TDELVA	Dec 5, 2018 4:27:28 PM	No	
60,635 - Tread Depth LRI	9 32nds of an inch		TDELVA	Dec 5, 2018 4:27:28 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		TDELVA	Dec 5, 2018 4:27:28 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
60,650 - Check Sidewall Wear	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
60,660 - Inspect for Cuts and Tears	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
60,670 - Check Dual Mating With Square	-	na	TDELVA	Dec 5, 2018 4:27:28 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
70,710 - Check Vibration Damper	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
70,730 - FRA Check Starter	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
70,770 - FRA Check Exhaust System	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
77,110 - FRA Check Fuel Tank	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
77,120 - Check Suspension Components	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		TDELVA	Dec 5, 2018 4:27:28 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		TDELVA	Dec 5, 2018 4:27:28 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		TDELVA	Dec 5, 2018 4:27:28 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		TDELVA	Dec 5, 2018 4:27:28 PM	No	
77,135 - Brake Rotor LF	38.9 Inch		TDELVA	Dec 5, 2018 4:27:28 PM	No	
77,136 - Brake Rotor RF	38.9 Inch		TDELVA	Dec 5, 2018 4:27:28 PM	No	
77,137 - Brake Rotor LR	37.6 Inch		TDELVA	Dec 5, 2018 4:27:28 PM	No	
77,138 - Brake Rotor RR	37.8 Inch		TDELVA	Dec 5, 2018 4:27:28 PM	No	
77,140 - FRA Check Brake Hoses	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
77,150 - Check King Pins	-	na	TDELVA	Dec 5, 2018 4:27:28 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
80,810 - Completion of PMI Report	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		TDELVA	Dec 5, 2018 4:27:28 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51888541
Invoice No. 55345 - 51888541

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 138,153 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Dec-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Dec-18	Delva,Terry	1.7333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: TDELVA Performed on: 05-DEC-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		TDELVA	Dec 5, 2018 4:28:26 PM	No	
101,000 - FRA Change Oil Filters	Yes		TDELVA	Dec 5, 2018 4:28:26 PM	No	
102,000 - FRA Drain Engine Oil	Yes		TDELVA	Dec 5, 2018 4:28:26 PM	No	
103,000 - FRA Check Transmission Fluid	Done		TDELVA	Dec 5, 2018 4:28:26 PM	No	
104,000 - Lubricate Chassis	Done		TDELVA	Dec 5, 2018 4:28:26 PM	No	
105,000 - Replace or Clean A/C Filters	Done		TDELVA	Dec 5, 2018 4:28:26 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	TDELVA	Dec 5, 2018 4:28:26 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		TDELVA	Dec 5, 2018 4:28:26 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	1.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51888541
Invoice No. 55345 - 51888541

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	138,153 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Dec-18	Delva,Terry	1.9	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 05-DEC-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Dec 5, 2018 4:18:11 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Dec 5, 2018 4:18:11 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Dec 5, 2018 4:18:11 PM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Dec 5, 2018 4:18:11 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Dec 5, 2018 4:18:11 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Dec 5, 2018 4:18:11 PM	No	
20 - Miles			TDELVA	Dec 5, 2018 4:18:11 PM	No	
30 - Kilometers			TDELVA	Dec 5, 2018 4:18:11 PM	No	
40 - Hours			TDELVA	Dec 5, 2018 4:18:11 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	1.90
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 51888541 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	4.98
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51888447
Invoice No. 55345 - 51888447

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Front tires		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	133,845 - DH

Chronology		
Reported	Nov 7, 2018 10:03:43 PM	Nov 7, 2018 10:03:43 PM
Started	Nov 7, 2018 12:00:00 AM	
Completed	Nov 7, 2018 11:41:00 PM	Nov 7, 2018 11:41:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Front Tires

Cause: Front Tire Worn below spec

Correction:Mount &Balance Tires new tire on front Rotate LF to LR inner .swap L/R outer tread depth 6/32 Parts#189752 Qty (2)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Nov-18	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 07-NOV-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Nov 7, 2018 10:06:07 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Nov 7, 2018 10:06:07 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Nov 7, 2018 10:06:07 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Nov 7, 2018 10:06:07 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Nov 7, 2018 10:06:07 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Nov 7, 2018 10:06:07 PM	No	
20 - Miles			DARTHURS	Nov 7, 2018 10:06:07 PM	No	
30 - Kilometers			DARTHURS	Nov 7, 2018 10:06:07 PM	No	
40 - Hours			DARTHURS	Nov 7, 2018 10:06:07 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51812907
Invoice No. 55345 - 51812907

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: DKNOTT
Created By: DKNOTT
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 133,845 - DH

Chronology		
Reported	Nov 7, 2018 11:37:09 AM	Nov 7, 2018 11:37:09 AM
Started	Nov 7, 2018 12:00:00 AM	
Completed	Nov 7, 2018 11:41:00 PM	Nov 7, 2018 11:41:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMB Service

CAUSE: Service due by Mileage.

CORRECTION: Change Oil& Filter. Lube all Pivoting Points. Check brakes. Clean batteries.replace A/C Filter.
Parts# B329 Qty (1)
Oil 5W20 Qty (7.0) Qt

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Nov-18	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 07-NOV-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Nov 7, 2018 11:39:07 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Nov 7, 2018 11:39:07 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Nov 7, 2018 11:39:07 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Nov 7, 2018 11:39:07 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Nov 7, 2018 11:39:07 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	Nov 7, 2018 11:39:07 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Nov 7, 2018 11:39:07 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Nov 7, 2018 11:39:07 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
40,420 - Check Hood	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Nov 7, 2018 11:39:07 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Nov 7, 2018 11:39:07 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Nov 7, 2018 11:39:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Nov 7, 2018 11:39:07 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Nov 7, 2018 11:39:07 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Nov 7, 2018 11:39:07 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Nov 7, 2018 11:39:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
60,631 - Tread Depth RF	3 32nds of an inch		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
60,632 - Tread Depth LF	6 32nds of an inch		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
60,634 - Tread Depth RRI	5 32nds of an inch		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
60,635 - Tread Depth LRI	3 32nds of an inch		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
60,636 - Tread Depth LRO	3 32nds of an inch		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Nov 7, 2018 11:39:07 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
77,133 - Brake Pad Thickness LR	9 Inch		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
77,134 - Brake Pad Thickness RR	9 Inch		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
77,135 - Brake Rotor LF	1.559 Inch		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
77,136 - Brake Rotor RF	1.559 Inch		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
77,137 - Brake Rotor LR	1.654 Inch		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
77,138 - Brake Rotor RR	1.653 Inch		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Nov 7, 2018 11:39:07 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Nov 7, 2018 11:39:07 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51888447
Invoice No. 55345 - 51888447

Client Department:
Department: 55345M
Work Order Description
Front tires
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 133,845 - DH

Activity Header
Activity: 15 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Nov-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	104.9	209.8

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Nov-18	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	209.80
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**209.80**

Work Order Footer

Work Order 51888447 Total	
Parts:	209.80
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**209.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51812907
Invoice No. 55345 - 51812907

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: DKNOTT
Created By: DKNOTT
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 133,845 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Nov-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Nov-18	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: DARTHURS Performed on: 07-NOV-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Nov 7, 2018 9:57:46 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Nov 7, 2018 9:57:46 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Nov 7, 2018 9:57:46 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Nov 7, 2018 9:57:46 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Nov 7, 2018 9:57:46 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Nov 7, 2018 9:57:46 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Nov 7, 2018 9:57:46 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Nov 7, 2018 9:57:46 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	Nov 7, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:57:46 PM		
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Nov 7, 2018 9:57:46 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		DARTHURS	Nov 7, 2018 9:57:46 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Nov 7, 2018 9:57:46 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Nov 7, 2018 9:57:46 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51812907
Invoice No. 55345 - 51812907

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM B		Ford E450 Champion Challenger	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	133,845 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Nov-18	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 07-NOV-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Nov 7, 2018 9:58:33 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Nov 7, 2018 9:58:33 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Nov 7, 2018 9:58:33 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Nov 7, 2018 9:58:33 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Nov 7, 2018 9:58:33 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Nov 7, 2018 9:58:33 PM	No	
20 - Miles			DARTHURS	Nov 7, 2018 9:58:33 PM	No	
30 - Kilometers			DARTHURS	Nov 7, 2018 9:58:33 PM	No	
40 - Hours			DARTHURS	Nov 7, 2018 9:58:33 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 51812907 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51862417
Invoice No. 55345 - 51862417

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Power Steering box		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	132,299 - DH

Chronology		
Reported	Oct 30, 2018 11:32:22 PM	Oct 30, 2018 11:32:22 PM
Started	Oct 30, 2018 12:00:00 AM	
Completed	Oct 30, 2018 11:53:00 PM	Oct 30, 2018 11:53:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Steering Box

Cause: Steering Box Leaking& Possible high pressure hose.

Correction: Remove&Replace Steering box. High pressure hose under monitoring.
Parts P/S box Shop Supply Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Oct-18	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 30-OCT-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Oct 30, 2018 11:35:46 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Oct 30, 2018 11:35:46 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Oct 30, 2018 11:35:46 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Oct 30, 2018 11:35:46 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Oct 30, 2018 11:35:46 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Oct 30, 2018 11:35:46 PM	No	
20 - Miles			DARTHURS	Oct 30, 2018 11:35:46 PM	No	
30 - Kilometers			DARTHURS	Oct 30, 2018 11:35:46 PM	No	
40 - Hours			DARTHURS	Oct 30, 2018 11:35:46 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51862417
Invoice No. 55345 - 51862417

Client Department:
Department: 55345M
Work Order Description
Power Steering box
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 132,299 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Replace Steering Box
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Nov-18	27-7632	GEAR, STEERING, E350	1	94.07	94.07

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Oct-18	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	94.07
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**94.07**

Work Order Footer

Work Order 51862417 Total	
Parts:	94.07
Labor:	0.00
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**94.07**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51736363
Invoice No. 55345 - 51736363

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	129,438 - DH

Chronology		
Reported	Oct 12, 2018 2:22:07 PM	Oct 12, 2018 2:22:07 PM
Started	Oct 14, 2018 12:00:00 AM	
Completed	Oct 15, 2018 11:17:19 AM	Oct 15, 2018 11:17:19 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA Service

CAUSE: Preventive Maintenance

CORRECTION: Performed and completed PmA Service
Part# B329 Qty1

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Oct-18	Delva,Terry	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: TDELVA Performed on: 14-OCT-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
10,100 - Safety Inspection	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
10,140 - Check Service Brakes	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
10,160 - FRA Check Instruments and Horns	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
10,170 - Check Fast Idle	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
10,180 - Check Starter Protection Circuit	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
10,190 - Check Reverse Warning System	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
11,100 - Check Parking Brake	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
11,150 - Perform Brake Test	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
11,152 - Decelerometer Results Test 1	FEET	n/a	TDELVA	Oct 14, 2018 8:11:53 PM	No	
11,154 - Decelerometer Results Test 2	FEET	n/a	TDELVA	Oct 14, 2018 8:11:53 PM	No	
11,156 - Decelerometer Results Test 3	FEET	n/a	TDELVA	Oct 14, 2018 8:11:53 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	TDELVA	Oct 14, 2018 8:11:53 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	TDELVA	Oct 14, 2018 8:11:53 PM	No	
11,170 - FRA Check Door Operation	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
20,210 - Check Condition of Operator's Area	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
20,240 - FRA Check Interior Lights	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	n/a	TDELVA	Oct 14, 2018 8:11:53 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	TDELVA	Oct 14, 2018 8:11:53 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
22,110 - Check Emergency Hatches	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
22,120 - Check All Safety Equipment	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
30,310 - Check Passenger Doors	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	TDELVA	Oct 14, 2018 8:11:53 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
30,360 - Check for Physical Damage and Decals	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
30,380 - Check Exterior Compartment Doors	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
33,100 - Check Lights and Reflectors	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
40,420 - Check Hood	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	TDELVA	Oct 14, 2018 8:11:53 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	TDELVA	Oct 14, 2018 8:11:53 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	TDELVA	Oct 14, 2018 8:11:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	TDELVA	Oct 14, 2018 8:11:53 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	TDELVA	Oct 14, 2018 8:11:53 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
44,130 - FRA Check Exhaust System	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
44,140 - FRA Check Intake System	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	TDELVA	Oct 14, 2018 8:11:53 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
44,180 - FRA Check for Leaks	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
44,190 - FRA Perform Battery Inspection	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
50,510 - Check Entire Steering System	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		TDELVA	Oct 14, 2018 8:11:53 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		TDELVA	Oct 14, 2018 8:11:53 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		TDELVA	Oct 14, 2018 8:11:53 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		TDELVA	Oct 14, 2018 8:11:53 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		TDELVA	Oct 14, 2018 8:11:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	70 Pounds per Square Inch		TDELVA	Oct 14, 2018 8:11:53 PM	No	
60,620 - Check Valve Stems and Caps	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
60,630 - Check and Record Tread Depth	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
60,631 - Tread Depth RF	7 32nds of an inch		TDELVA	Oct 14, 2018 8:11:53 PM	No	
60,632 - Tread Depth LF	7 32nds of an inch		TDELVA	Oct 14, 2018 8:11:53 PM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		TDELVA	Oct 14, 2018 8:11:53 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		TDELVA	Oct 14, 2018 8:11:53 PM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		TDELVA	Oct 14, 2018 8:11:53 PM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		TDELVA	Oct 14, 2018 8:11:53 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
60,650 - Check Sidewall Wear	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
60,660 - Inspect for Cuts and Tears	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	TDELVA	Oct 14, 2018 8:11:53 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
70,710 - Check Vibration Damper	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
70,730 - FRA Check Starter	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
70,770 - FRA Check Exhaust System	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
77,110 - FRA Check Fuel Tank	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
77,120 - Check Suspension Components	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		TDELVA	Oct 14, 2018 8:11:53 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		TDELVA	Oct 14, 2018 8:11:53 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		TDELVA	Oct 14, 2018 8:11:53 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		TDELVA	Oct 14, 2018 8:11:53 PM	No	
77,135 - Brake Rotor LF	39.91 Inch		TDELVA	Oct 14, 2018 8:11:53 PM	No	
77,136 - Brake Rotor RF	39.9 Inch		TDELVA	Oct 14, 2018 8:11:53 PM	No	
77,137 - Brake Rotor LR	35.97 Inch		TDELVA	Oct 14, 2018 8:11:53 PM	No	
77,138 - Brake Rotor RR	35.93 Inch		TDELVA	Oct 14, 2018 8:11:53 PM	No	
77,140 - FRA Check Brake Hoses	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
77,150 - Check King Pins	-	n/a	TDELVA	Oct 14, 2018 8:11:53 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
80,810 - Completion of PMI Report	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		TDELVA	Oct 14, 2018 8:11:53 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51736363
Invoice No. 55345 - 51736363

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 129,438 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Oct-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Oct-18	Delva,Terry	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: TDELVA Performed on: 14-OCT-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		TDELVA	Oct 14, 2018 8:14:28 PM	No	
101,000 - FRA Change Oil Filters	Yes		TDELVA	Oct 14, 2018 8:14:28 PM	No	
102,000 - FRA Drain Engine Oil	Yes		TDELVA	Oct 14, 2018 8:14:28 PM	No	
103,000 - FRA Check Transmission Fluid	Done		TDELVA	Oct 14, 2018 8:14:28 PM	No	
104,000 - Lubricate Chassis	Done		TDELVA	Oct 14, 2018 8:14:28 PM	No	
105,000 - Replace or Clean A/C Filters	Done		TDELVA	Oct 14, 2018 8:14:28 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	TDELVA	Oct 14, 2018 8:14:28 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		TDELVA	Oct 14, 2018 8:14:28 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	1.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51736363
Invoice No. 55345 - 51736363

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	129,438 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Oct-18	Delva,Terry	0.2666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 14-OCT-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Oct 14, 2018 8:14:16 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Oct 14, 2018 8:14:16 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Oct 14, 2018 8:14:16 PM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Oct 14, 2018 8:14:16 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Oct 14, 2018 8:14:16 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Oct 14, 2018 8:14:16 PM	No	
20 - Miles			TDELVA	Oct 14, 2018 8:14:16 PM	No	
30 - Kilometers			TDELVA	Oct 14, 2018 8:14:16 PM	No	
40 - Hours			TDELVA	Oct 14, 2018 8:14:16 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 51736363 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51736310
Invoice No. 55345 - 51736310

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Needs front and rear brakes job		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	125,136 - DH

Chronology		
Reported	Sep 19, 2018 11:27:00 PM	Sep 19, 2018 11:27:00 PM
Started	Sep 19, 2018 12:00:00 AM	
Completed	Sep 20, 2018 12:11:00 AM	Sep 20, 2018 12:11:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs front and rear brakes job

Cause: wear

Correction:replaced front and rear brake pads
Lubed sliding pins
Front brakes part number BRSD1328 Qty1
Rear brakes part number BRSD1330 Qty1
Torque wheels 140 lbs second torque 140 lbs

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Sep-18	Gaspard,Ronald	0.1333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 19-SEP-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Sep 19, 2018 11:35:09 PM	No	
20 - Miles			RGASPARD	Sep 19, 2018 11:35:09 PM	No	
30 - Kilometers			RGASPARD	Sep 19, 2018 11:35:09 PM	No	
40 - Hours			RGASPARD	Sep 19, 2018 11:35:09 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51736310
Invoice No. 55345 - 51736310

Client Department:
Department: 55345M
Work Order Description
Needs front and rear brakes job
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 125,136 - DH

Activity Header
Activity: 15 013/000/000 BRAKES
Activity Note: Needs front and rear brakes job
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Sep-18	Gaspard,Ronald	1.5	0	0
19-Sep-18	Gaspard,Ronald	1.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51736310
Invoice No. 55345 - 51736310

Client Department:
Department: 55345M
Work Order Description
Needs front and rear brakes job
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 125,136 - DH

Activity Header
Activity: 25 013/000/000 BRAKES
Activity Note: Needs rear brakes job
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Sep-18	Gaspard,Ronald	0.1333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51736310 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51657239
Invoice No. 55345 - 51657239

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	125,136 - DH

Chronology

Reported	Sep 19, 2018 9:41:27 AM	Sep 19, 2018 9:41:27 AM
Started	Sep 19, 2018 12:00:00 AM	
Completed	Sep 20, 2018 12:10:00 AM	Sep 20, 2018 12:10:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA

CAUSE:Service

CORRECTION:perform PMA Service
Oil filter B329 qty 1
Engine oil 5w20 qty 7 Qts
Fixed top lift door shock
Replaced tie down bag

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Sep-18	Gaspard,Ronald	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 19-SEP-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Sep 19, 2018 11:21:37 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Sep 19, 2018 11:21:37 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Sep 19, 2018 11:21:37 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Sep 19, 2018 11:21:37 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Sep 19, 2018 11:21:37 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Sep 19, 2018 11:21:37 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Sep 19, 2018 11:21:37 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Sep 19, 2018 11:21:37 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
40,420 - Check Hood	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Sep 19, 2018 11:21:37 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Sep 19, 2018 11:21:37 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Sep 19, 2018 11:21:37 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Sep 19, 2018 11:21:37 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Sep 19, 2018 11:21:37 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Sep 19, 2018 11:21:37 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Sep 19, 2018 11:21:37 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
60,631 - Tread Depth RF	7 32nds of an inch		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
60,635 - Tread Depth LRI	10 32nds of an inch		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
77,131 - Brake Pad Thickness LF	4 Inch		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
77,132 - Brake Pad Thickness RF	4 Inch		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
77,133 - Brake Pad Thickness LR	5 Inch		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
77,134 - Brake Pad Thickness RR	5 Inch		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
77,137 - Brake Rotor LR	40 Inch		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
77,138 - Brake Rotor RR	40 Inch		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Sep 19, 2018 11:21:37 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Sep 19, 2018 11:21:37 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51657239
Invoice No. 55345 - 51657239

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	125,136 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Sep-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Sep-18	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 19-SEP-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Sep 19, 2018 11:22:24 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Sep 19, 2018 11:22:24 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Sep 19, 2018 11:22:24 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Sep 19, 2018 11:22:24 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Sep 19, 2018 11:22:24 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Sep 19, 2018 11:22:24 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Sep 19, 2018 11:22:24 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Sep 19, 2018 11:22:24 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	1.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51657239
Invoice No. 55345 - 51657239

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	125,136 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Sep-18	Gaspard,Ronald	0.2666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 19-SEP-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Sep 19, 2018 11:22:49 PM	No	
20 - Miles			RGASPARD	Sep 19, 2018 11:22:49 PM	No	
30 - Kilometers			RGASPARD	Sep 19, 2018 11:22:49 PM	No	
40 - Hours			RGASPARD	Sep 19, 2018 11:22:49 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51657239 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	3.77

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51655192
Invoice No. 55345 - 51655192

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
REPLACE MOTOR MOUNT		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	121,030 - DH

Chronology		
Reported	Aug 24, 2018 11:30:01 PM	Aug 24, 2018 11:30:01 PM
Started		
Completed	Aug 27, 2018 7:47:00 AM	Aug 27, 2018 7:47:00 AM
Down Time		

Work Order Notes

Line 10 Tech replaced both motor mounts
Part# 5U9Z-6038-AA qty1
Part#F7UZ-6038-EB qty1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc:
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 24-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Aug 24, 2018 11:39:19 PM	No	
20 - Miles			CKARLENS	Aug 24, 2018 11:39:19 PM	No	
30 - Kilometers			CKARLENS	Aug 24, 2018 11:39:19 PM	No	
40 - Hours			CKARLENS	Aug 24, 2018 11:39:19 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51655192
Invoice No. 55345 - 51655192

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
REPLACE MOTOR MOUNT		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	121,030 - DH

Activity Header
Activity: 15 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: REPLACE MOTOR MOUNT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Aug-18	F7UZ-6038-EB	INSULATOR, SUPPORT, ENGINE, FRONT, LH	1	50.34	50.34
24-Aug-18	5U9Z-6038-AA	MOUNT, ENGINE, RH	1	54.47	54.47

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	104.81
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**104.81**

Work Order Footer

Work Order 51655192 Total	
Parts:	104.81
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**104.81**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51559624
Invoice No. 55345 - 51559624

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 121,030 - DH

Chronology		
Reported	Aug 24, 2018 12:00:49 PM	Aug 24, 2018 12:00:49 PM
Started	Aug 24, 2018 12:00:00 AM	
Completed	Aug 27, 2018 7:35:00 AM	Aug 27, 2018 7:35:00 AM
Down Time		

Work Order Notes

Line 10 Tech performed PM-C
Parts Used
Oil filter Qty:1 part#B329
Oil Qty:7qts
Transmission filter Qty:1 part#20022
Air filter qty1 part#PA4075

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Aug-18	KARLENS,Cyrius	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: CKARLENS Performed on: 24-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
10,100 - Safety Inspection	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
10,140 - Check Service Brakes	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
10,160 - FRA Check Instruments and Horns	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
10,170 - Check Fast Idle	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
10,180 - Check Starter Protection Circuit	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
10,190 - Check Reverse Warning System	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
11,100 - Check Parking Brake	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
11,150 - Perform Brake Test	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	CKARLENS	Aug 24, 2018 11:22:06 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	CKARLENS	Aug 24, 2018 11:22:06 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	CKARLENS	Aug 24, 2018 11:22:06 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	CKARLENS	Aug 24, 2018 11:22:06 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	CKARLENS	Aug 24, 2018 11:22:06 PM	No	
11,170 - FRA Check Door Operation	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
20,210 - Check Condition of Operator's Area	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
20,240 - FRA Check Interior Lights	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	CKARLENS	Aug 24, 2018 11:22:06 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	CKARLENS	Aug 24, 2018 11:22:06 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
22,110 - Check Emergency Hatches	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
22,120 - Check All Safety Equipment	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
30,310 - Check Passenger Doors	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	CKARLENS	Aug 24, 2018 11:22:06 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
30,360 - Check for Physical Damage and Decals	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
30,380 - Check Exterior Compartment Doors	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
33,100 - Check Lights and Reflectors	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
40,420 - Check Hood	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	CKARLENS	Aug 24, 2018 11:22:06 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	CKARLENS	Aug 24, 2018 11:22:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	CKARLENS	Aug 24, 2018 11:22:06 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	CKARLENS	Aug 24, 2018 11:22:06 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
44,130 - FRA Check Exhaust System	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
44,140 - FRA Check Intake System	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	CKARLENS	Aug 24, 2018 11:22:06 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
44,180 - FRA Check for Leaks	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
44,190 - FRA Perform Battery Inspection	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
50,510 - Check Entire Steering System	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		CKARLENS	Aug 24, 2018 11:22:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	70 Pounds per Square Inch		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
60,620 - Check Valve Stems and Caps	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
60,630 - Check and Record Tread Depth	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
60,650 - Check Sidewall Wear	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
60,660 - Inspect for Cuts and Tears	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
60,670 - Check Dual Mating With Square	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
70,710 - Check Vibration Damper	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
70,730 - FRA Check Starter	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
70,770 - FRA Check Exhaust System	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
77,110 - FRA Check Fuel Tank	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
77,120 - Check Suspension Components	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
77,131 - Brake Pad Thickness LF	6 Inch		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
77,132 - Brake Pad Thickness RF	6 Inch		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
77,133 - Brake Pad Thickness LR	9 Inch		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
77,134 - Brake Pad Thickness RR	9 Inch		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
77,135 - Brake Rotor LF	39.8 Inch		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
77,136 - Brake Rotor RF	39.8 Inch		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
77,137 - Brake Rotor LR	41.8 Inch		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
77,138 - Brake Rotor RR	41.8 Inch		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
77,140 - FRA Check Brake Hoses	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
77,150 - Check King Pins	-	NA	CKARLENS	Aug 24, 2018 11:22:06 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
80,810 - Completion of PMI Report	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		CKARLENS	Aug 24, 2018 11:22:06 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51559624
Invoice No. 55345 - 51559624

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 121,030 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Aug-18	PA4075	FILTER, AIR SEE P546597	1	5.23	5.23
24-Aug-18	20021	FILTER, TRANSMISSION 20021	1	17.27	17.27
24-Aug-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Aug-18	KARLENS,Cyrius	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: CKARLENS Performed on: 24-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		CKARLENS	Aug 24, 2018 11:24:12 PM	No	
101,000 - FRA Change Oil Filters	Yes		CKARLENS	Aug 24, 2018 11:24:12 PM	No	
102,000 - FRA Drain Engine Oil	Yes		CKARLENS	Aug 24, 2018 11:24:12 PM	No	
103,000 - FRA Check Transmission Fluid	Done		CKARLENS	Aug 24, 2018 11:24:12 PM	No	
104,000 - Lubricate Chassis	Done		CKARLENS	Aug 24, 2018 11:24:12 PM	No	
105,000 - Replace or Clean A/C Filters	Done		CKARLENS	Aug 24, 2018 11:24:12 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	NA	CKARLENS	Aug 24, 2018 11:24:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
108,000 - Lube all pivoting Mechanisms	Done		CKARLENS	Aug 24, 2018 11:24:12 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		CKARLENS	Aug 24, 2018 11:24:12 PM	No	
201,000 - Service Crankcase Breather	Done		CKARLENS	Aug 24, 2018 11:24:12 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		CKARLENS	Aug 24, 2018 11:24:12 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	Yes		CKARLENS	Aug 24, 2018 11:24:12 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		CKARLENS	Aug 24, 2018 11:24:12 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		CKARLENS	Aug 24, 2018 11:24:12 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		CKARLENS	Aug 24, 2018 11:24:12 PM	No	
302,000 - Check Toe-In and Record Reading	-	NA	CKARLENS	Aug 24, 2018 11:24:12 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	NA	CKARLENS	Aug 24, 2018 11:24:12 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	Yes		CKARLENS	Aug 24, 2018 11:24:12 PM	No	
305,000 - FRA Change Differential Fluid	Yes		CKARLENS	Aug 24, 2018 11:24:12 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	24.46
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**24.46**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51559624
Invoice No. 55345 - 51559624

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM C		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	121,030 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Aug-18	KARLENS,Cyrius	0.3333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 24-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Aug 24, 2018 11:24:57 PM	No	
20 - Miles			CKARLENS	Aug 24, 2018 11:24:57 PM	No	
30 - Kilometers			CKARLENS	Aug 24, 2018 11:24:57 PM	No	
40 - Hours			CKARLENS	Aug 24, 2018 11:24:57 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51559624 Total	
Parts:	24.46
Labor:	0.00
Labor Hours:	4.33

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**24.46**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51488561
Invoice No. 55345 - 51488561

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	116,913 - DH

Chronology		
Reported	Jul 31, 2018 12:46:05 PM	Jul 31, 2018 12:46:05 PM
Started	Aug 1, 2018 12:00:00 AM	
Completed	Aug 1, 2018 5:27:00 PM	Aug 1, 2018 5:27:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA

CAUSE: Service due

CORRECTION: Performed and completed PMA
Changed engine oil and replaced engine oil filter
Lube all Pivoting Points

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Aug-18	Delva,Terry	1.7833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: TDELVA Performed on: 01-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
10,100 - Safety Inspection	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
10,140 - Check Service Brakes	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
10,160 - FRA Check Instruments and Horns	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
10,170 - Check Fast Idle	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
10,180 - Check Starter Protection Circuit	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
10,190 - Check Reverse Warning System	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
11,100 - Check Parking Brake	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
11,150 - Perform Brake Test	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	TDELVA	Aug 1, 2018 4:56:25 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	TDELVA	Aug 1, 2018 4:56:25 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	TDELVA	Aug 1, 2018 4:56:25 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	TDELVA	Aug 1, 2018 4:56:25 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	TDELVA	Aug 1, 2018 4:56:25 PM	No	
11,170 - FRA Check Door Operation	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
20,210 - Check Condition of Operator's Area	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
20,240 - FRA Check Interior Lights	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	na	TDELVA	Aug 1, 2018 4:56:25 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	TDELVA	Aug 1, 2018 4:56:25 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
22,110 - Check Emergency Hatches	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
22,120 - Check All Safety Equipment	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
30,310 - Check Passenger Doors	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	TDELVA	Aug 1, 2018 4:56:25 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
30,360 - Check for Physical Damage and Decals	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
30,380 - Check Exterior Compartment Doors	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
33,100 - Check Lights and Reflectors	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
40,420 - Check Hood	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	TDELVA	Aug 1, 2018 4:56:25 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	TDELVA	Aug 1, 2018 4:56:25 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	TDELVA	Aug 1, 2018 4:56:25 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	TDELVA	Aug 1, 2018 4:56:25 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	TDELVA	Aug 1, 2018 4:56:25 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
44,130 - FRA Check Exhaust System	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
44,140 - FRA Check Intake System	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	TDELVA	Aug 1, 2018 4:56:25 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
44,180 - FRA Check for Leaks	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
44,190 - FRA Perform Battery Inspection	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
50,510 - Check Entire Steering System	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		TDELVA	Aug 1, 2018 4:56:25 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		TDELVA	Aug 1, 2018 4:56:25 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		TDELVA	Aug 1, 2018 4:56:25 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		TDELVA	Aug 1, 2018 4:56:25 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		TDELVA	Aug 1, 2018 4:56:25 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		TDELVA	Aug 1, 2018 4:56:25 PM	No	
60,620 - Check Valve Stems and Caps	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
60,630 - Check and Record Tread Depth	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
60,631 - Tread Depth RF	12 32nds of an inch		TDELVA	Aug 1, 2018 4:56:25 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		TDELVA	Aug 1, 2018 4:56:25 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		TDELVA	Aug 1, 2018 4:56:25 PM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		TDELVA	Aug 1, 2018 4:56:25 PM	No	
60,635 - Tread Depth LRI	10 32nds of an inch		TDELVA	Aug 1, 2018 4:56:25 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		TDELVA	Aug 1, 2018 4:56:25 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
60,650 - Check Sidewall Wear	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
60,660 - Inspect for Cuts and Tears	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
60,670 - Check Dual Mating With Square	-	na	TDELVA	Aug 1, 2018 4:56:25 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
70,710 - Check Vibration Damper	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
70,730 - FRA Check Starter	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
70,770 - FRA Check Exhaust System	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
77,110 - FRA Check Fuel Tank	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
77,120 - Check Suspension Components	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
77,131 - Brake Pad Thickness LF	6 Inch		TDELVA	Aug 1, 2018 4:56:25 PM	No	
77,132 - Brake Pad Thickness RF	6 Inch		TDELVA	Aug 1, 2018 4:56:25 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		TDELVA	Aug 1, 2018 4:56:25 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		TDELVA	Aug 1, 2018 4:56:25 PM	No	
77,135 - Brake Rotor LF	39.6 Inch		TDELVA	Aug 1, 2018 4:56:25 PM	No	
77,136 - Brake Rotor RF	39.6 Inch		TDELVA	Aug 1, 2018 4:56:25 PM	No	
77,137 - Brake Rotor LR	38.5 Inch		TDELVA	Aug 1, 2018 4:56:25 PM	No	
77,138 - Brake Rotor RR	38.5 Inch		TDELVA	Aug 1, 2018 4:56:25 PM	No	
77,140 - FRA Check Brake Hoses	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
77,150 - Check King Pins	-	na	TDELVA	Aug 1, 2018 4:56:25 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
80,810 - Completion of PMI Report	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		TDELVA	Aug 1, 2018 4:56:25 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51488561
Invoice No. 55345 - 51488561

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 116,913 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Aug-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Aug-18	Delva,Terry	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: TDELVA Performed on: 01-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		TDELVA	Aug 1, 2018 4:43:27 PM	No	
101,000 - FRA Change Oil Filters	Yes		TDELVA	Aug 1, 2018 4:43:27 PM	No	
102,000 - FRA Drain Engine Oil	Yes		TDELVA	Aug 1, 2018 4:43:27 PM	No	
103,000 - FRA Check Transmission Fluid	Done		TDELVA	Aug 1, 2018 4:43:27 PM	No	
104,000 - Lubricate Chassis	Done		TDELVA	Aug 1, 2018 4:43:27 PM	No	
105,000 - Replace or Clean A/C Filters	Done		TDELVA	Aug 1, 2018 4:43:27 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	TDELVA	Aug 1, 2018 4:43:27 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		TDELVA	Aug 1, 2018 4:43:27 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	2.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51488561
Invoice No. 55345 - 51488561

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	116,913 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Aug-18	Delva,Terry	0.75	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 01-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Aug 1, 2018 4:40:55 PM	No	
20 - Miles			TDELVA	Aug 1, 2018 4:40:55 PM	No	
30 - Kilometers			TDELVA	Aug 1, 2018 4:40:55 PM	No	
40 - Hours			TDELVA	Aug 1, 2018 4:40:55 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51488561 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	4.53

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51388302
Invoice No. 55345 - 51388302

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	112,468 - DH

Chronology		
Reported	Jul 6, 2018 9:56:56 AM	Jul 6, 2018 9:56:56 AM
Started	Jul 6, 2018 12:00:00 AM	
Completed	Jul 7, 2018 12:00:00 AM	Jul 7, 2018 12:00:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA Service

CAUSE: Service Due by Mileage

CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Clean batteries.Replace A/C Filter. Check brakes.
Parts# B329 Qty (1)
Oil 5W20QTY Qty (7.0) Qt

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jul-18	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 06-JUL-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
10,120 - FRA Check All Warning Lights and	Done		DARTHURS	Jul 6, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				11:15:56 PM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Jul 6, 2018 11:15:56 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Jul 6, 2018 11:15:56 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Jul 6, 2018 11:15:56 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Jul 6, 2018 11:15:56 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Jul 6, 2018 11:15:56 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Jul 6, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:15:56 PM		
20,260 - Check Stop Request System	-	NA	DARTHURS	Jul 6, 2018 11:15:56 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Jul 6, 2018 11:15:56 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Jul 6, 2018 11:15:56 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
40,420 - Check Hood	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Jul 6, 2018 11:15:56 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Jul 6, 2018 11:15:56 PM	No	
40,442 - Freeze Point	Degree	NA	DARTHURS	Jul 6, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			11:15:56 PM		
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Jul 6, 2018 11:15:56 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Jul 6, 2018 11:15:56 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Jul 6, 2018 11:15:56 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
60,615 - Air Pressure LRI	65 Pounds per		DARTHURS	Jul 6, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			11:15:56 PM		
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
60,631 - Tread Depth RF	6 32nds of an inch		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
60,632 - Tread Depth LF	7 32nds of an inch		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
60,633 - Tread Depth RRO	3 32nds of an inch		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
60,634 - Tread Depth RRI	4 32nds of an inch		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
60,635 - Tread Depth LRI	9 32nds of an inch		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Jul 6, 2018 11:15:56 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
70,790 - Check All Body Mounts and Chassis	Done		DARTHURS	Jul 6, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Frame				11:15:56 PM		
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
77,133 - Brake Pad Thickness LR	12 Inch		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
77,134 - Brake Pad Thickness RR	12 Inch		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
77,135 - Brake Rotor LF	1.555 Inch		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
77,136 - Brake Rotor RF	1.556 Inch		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
77,137 - Brake Rotor LR	1.645 Inch		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
77,138 - Brake Rotor RR	1.646 Inch		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Jul 6, 2018 11:15:56 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Jul 6, 2018 11:15:56 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51388302
Invoice No. 55345 - 51388302

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 112,468 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Jul-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jul-18	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 06-JUL-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Jul 6, 2018 11:17:06 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Jul 6, 2018 11:17:06 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Jul 6, 2018 11:17:06 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Jul 6, 2018 11:17:06 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Jul 6, 2018 11:17:06 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Jul 6, 2018 11:17:06 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Jul 6, 2018 11:17:06 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Jul 6, 2018 11:17:06 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51388302
Invoice No. 55345 - 51388302

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	112,468 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jul-18	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 06-JUL-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 6, 2018 11:17:31 PM	No	
20 - Miles			DARTHURS	Jul 6, 2018 11:17:31 PM	No	
30 - Kilometers			DARTHURS	Jul 6, 2018 11:17:31 PM	No	
40 - Hours			DARTHURS	Jul 6, 2018 11:17:31 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51388302 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51488539
Invoice No. 55345 - 51488539

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
R/R Tire		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	112,468 - DH

Chronology		
Reported	Jul 6, 2018 11:24:00 PM	Jul 6, 2018 11:24:00 PM
Started	Jul 6, 2018 12:00:00 AM	
Completed	Jul 6, 2018 11:59:00 PM	Jul 6, 2018 11:59:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:R/R Tire

Cause: Tires Worn

Correction: Mount& Balance Both R/R Tire.& Rotate to Front.rotate both front To R/R
Parts# 189752 Qty (2)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jul-18	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 06-JUL-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 6, 2018 11:30:12 PM	No	
20 - Miles			DARTHURS	Jul 6, 2018 11:30:12 PM	No	
30 - Kilometers			DARTHURS	Jul 6, 2018 11:30:12 PM	No	
40 - Hours			DARTHURS	Jul 6, 2018 11:30:12 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51488539
Invoice No. 55345 - 51488539

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
R/R Tire		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	112,468 - DH

Activity Header
Activity: 15 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Jul-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	103.44	206.88

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jul-18	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	206.88
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**206.88**

Work Order Footer

Work Order 51488539 Total	
Parts:	206.88
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**206.88**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 51441879
Invoice No. 55345 - 51441879

Client Department:
Department: 55345M
Work Order Description
Small round emergency light for emergency exits is out
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 110,320 - DH

Chronology		
Reported	Jun 19, 2018 10:42:10 AM	Jun 19, 2018 10:42:10 AM
Started	Jun 19, 2018 12:00:00 AM	
Completed	Jun 19, 2018 11:38:32 AM	Jun 19, 2018 11:38:32 AM
Down Time		

Work Order Notes

Line 10 Small round emergency light for emergency exit is out

Replaced the bad red emergency exit led light assembly for the rear hatch

Replaced right side headlight because it was out (low beam) Line 20

Lift is getting stuck.

Platform is not leveled and the outer barrier microswitches need adjustment.

Adjusted the micro switches and leveled platform. Line 30

Fire suppression detector bottle is below specs

Swapped out with one of our spare detector bottles, system is now within specs

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 19-JUN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the	Done		EDTORRES	Jun 19, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				10:52:41 AM		
20 - Miles			EDTORRES	Jun 19, 2018 10:52:41 AM	No	
30 - Kilometers			EDTORRES	Jun 19, 2018 10:52:41 AM	No	
40 - Hours			EDTORRES	Jun 19, 2018 10:52:41 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 51441879
Invoice No. 55345 - 51441879

Client Department:
Department: 55345M
Work Order Description
Small round emergency light for emergency exits is out
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 110,320 - DH

Activity Header
Activity: 20 034/003/000 LAMPS, SIGNAL, PARKING & BACKUP
Activity Note: Small round emergency light for emergency exits is out
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Jun-18	999-5038(F)	MISC SHOP SUPPLIES NUTS & BOLTS ETC GL/CODE 54337	1	177.87	177.87

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Jun-18	Torres,Edwin	0.4333333	0	0
19-Jun-18	Torres,Edwin	0.2333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	177.87
Labor:	0.00
Labor Hours:	0.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**177.87**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 51441879
Invoice No. 55345 - 51441879

Client Department:
Department: 55345M
Work Order Description
Small round emergency light for emergency exits is out
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 110,320 - DH

Activity Header
Activity: 30 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: Wheelchair lift is getting stuck
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Jun-18	Torres,Edwin	0.85	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 51441879
Invoice No. 55345 - 51441879

Client Department:
Department: 55345M
Work Order Description
Small round emergency light for emergency exits is out
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 110,320 - DH

Activity Header
Activity: 40 050/000 GROUP, ACCESSORIES
Activity Note: Fire surpression system detector bottle is below specs.
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 14 Install
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Jun-18	Torres,Edwin	0.7	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51441879 Total	
Parts:	177.87
Labor:	0.00
Labor Hours:	2.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**177.87**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51388233
Invoice No. 55345 - 51388233

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Rear Brakes & W/C Lift		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	108,361 - DH

Chronology		
Reported	Jun 1, 2018 10:19:11 PM	Jun 1, 2018 10:19:11 PM
Started	Jun 1, 2018 12:00:00 AM	
Completed	Jun 1, 2018 11:56:00 PM	Jun 1, 2018 11:56:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear Brakes& W/C Lift

Cause: Rear brakes uneven Wear./ wheel chair outer barrier flap won¿t close

Correction: Remove & Replace Rear Brakes& Lube slide pins.remove & Replace W/C Outer barrier shocks
Parts#BRSD 1330 Qty (1)
Parts# 32831 Qty (2)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Jun-18	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 01-JUN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jun 1, 2018 11:55:46 PM	No	
20 - Miles			DARTHURS	Jun 1, 2018 11:55:46 PM	No	
30 - Kilometers			DARTHURS	Jun 1, 2018 11:55:46 PM	No	
40 - Hours			DARTHURS	Jun 1, 2018 11:55:46 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51388233
Invoice No. 55345 - 51388233

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Rear Brakes & W/C Lift		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	108,361 - DH

Activity Header
Activity: 15 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Jun-18	BRSD-1330	PADS, BRAKE, DISC, REAR, FORD SAME AS PFH133020	1	43.06	43.06

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Jun-18	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	43.06
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.06**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51388233
Invoice No. 55345 - 51388233

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Rear Brakes & W/C Lift		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	108,361 - DH

Activity Header
Activity: 25 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Jun-18	32831	SPRING, SHOCK, GAS, W/C	2	26.38	52.76

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Jun-18	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	52.76
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**52.76**

Work Order Footer

Work Order 51388233 Total	
Parts:	95.82
Labor:	0.00
Labor Hours:	2.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**95.82**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51322374
Invoice No. 55345 - 51322374

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM B		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	108,361 - DH

Chronology		
Reported	Jun 1, 2018 11:00:03 AM	Jun 1, 2018 11:00:03 AM
Started	Jun 1, 2018 12:00:00 AM	
Completed	Jun 1, 2018 11:54:00 PM	Jun 1, 2018 11:54:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMB Service

CAUSE: Service due by Mileage

CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check brakes. Clean Batteries .replace A/C Filter Swap R/R outer tire with One 6/32.
Parts# B329 Qty (1)
Oil 5W20 Qty (7.0) Qt

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Jun-18	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 01-JUN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
10,120 - FRA Check All Warning Lights and	Done		DARTHURS	Jun 1, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				10:12:29 PM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Jun 1, 2018 10:12:29 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Jun 1, 2018 10:12:29 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Jun 1, 2018 10:12:29 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Jun 1, 2018 10:12:29 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Jun 1, 2018 10:12:29 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Jun 1, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:12:29 PM		
20,260 - Check Stop Request System	-	NA	DARTHURS	Jun 1, 2018 10:12:29 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Jun 1, 2018 10:12:29 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Jun 1, 2018 10:12:29 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
40,420 - Check Hood	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Jun 1, 2018 10:12:29 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Jun 1, 2018 10:12:29 PM	No	
40,442 - Freeze Point	Degree	NA	DARTHURS	Jun 1, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			10:12:29 PM		
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Jun 1, 2018 10:12:29 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Jun 1, 2018 10:12:29 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Jun 1, 2018 10:12:29 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
60,615 - Air Pressure LRI	65 Pounds per		DARTHURS	Jun 1, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			10:12:29 PM		
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
60,633 - Tread Depth RRO	4 32nds of an inch		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
60,635 - Tread Depth LRI	10 32nds of an inch		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
60,636 - Tread Depth LRO	10 32nds of an inch		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Jun 1, 2018 10:12:29 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
70,790 - Check All Body Mounts and Chassis	Done		DARTHURS	Jun 1, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Frame				10:12:29 PM		
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
77,133 - Brake Pad Thickness LR	5 Inch		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
77,134 - Brake Pad Thickness RR	4 Inch		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
77,135 - Brake Rotor LF	1.556 Inch		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
77,136 - Brake Rotor RF	1.557 Inch		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
77,137 - Brake Rotor LR	1.654 Inch		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
77,138 - Brake Rotor RR	1.655 Inch		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Jun 1, 2018 10:12:29 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Jun 1, 2018 10:12:29 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51322374
Invoice No. 55345 - 51322374

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 108,361 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Jun-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Jun-18	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: DARTHURS Performed on: 01-JUN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Jun 1, 2018 10:13:27 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Jun 1, 2018 10:13:27 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Jun 1, 2018 10:13:27 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Jun 1, 2018 10:13:27 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Jun 1, 2018 10:13:27 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Jun 1, 2018 10:13:27 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Jun 1, 2018 10:13:27 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Jun 1, 2018 10:13:27 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	Jun 1, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:13:27 PM		
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Jun 1, 2018 10:13:27 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		DARTHURS	Jun 1, 2018 10:13:27 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Jun 1, 2018 10:13:27 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Jun 1, 2018 10:13:27 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51322374
Invoice No. 55345 - 51322374

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM B		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	108,361 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Jun-18	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 01-JUN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jun 1, 2018 10:13:51 PM	No	
20 - Miles			DARTHURS	Jun 1, 2018 10:13:51 PM	No	
30 - Kilometers			DARTHURS	Jun 1, 2018 10:13:51 PM	No	
40 - Hours			DARTHURS	Jun 1, 2018 10:13:51 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51322374 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51177312
Invoice No. 55345 - 51177312

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	104,220 - DH

Chronology		
Reported	May 3, 2018 12:11:22 PM	May 3, 2018 12:11:22 PM
Started	May 3, 2018 12:00:00 AM	
Completed	May 3, 2018 11:01:00 PM	May 3, 2018 11:01:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PM-A

CAUSE: Preventive Maintenance

CORRECTION: Performed PmA
Parts used
Oil filter Qty:1
Oil Qty:6.5wts
Air filter Qty1 part# Pa4075

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-May-18	KARLENS,Cyrius	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: CKARLENS Performed on: 03-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
10,100 - Safety Inspection	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,120 - FRA Check All Warning Lights and Alarms	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
10,140 - Check Service Brakes	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
10,160 - FRA Check Instruments and Horns	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
10,170 - Check Fast Idle	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
10,180 - Check Starter Protection Circuit	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
10,190 - Check Reverse Warning System	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
11,100 - Check Parking Brake	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
11,150 - Perform Brake Test	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	CKARLENS	May 3, 2018 7:51:00 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	CKARLENS	May 3, 2018 7:51:00 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	CKARLENS	May 3, 2018 7:51:00 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	CKARLENS	May 3, 2018 7:51:00 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	CKARLENS	May 3, 2018 7:51:00 PM	No	
11,170 - FRA Check Door Operation	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
20,210 - Check Condition of Operator's Area	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
20,240 - FRA Check Interior Lights	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,250 - FRA Check Interior Electrical Panels	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
20,260 - Check Stop Request System	-	na	CKARLENS	May 3, 2018 7:51:00 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	CKARLENS	May 3, 2018 7:51:00 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
22,110 - Check Emergency Hatches	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
22,120 - Check All Safety Equipment	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
30,310 - Check Passenger Doors	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	CKARLENS	May 3, 2018 7:51:00 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
30,360 - Check for Physical Damage and Decals	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
30,380 - Check Exterior Compartment Doors	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
33,100 - Check Lights and Reflectors	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
40,420 - Check Hood	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	CKARLENS	May 3, 2018 7:51:00 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		CKARLENS	May 3, 2018 7:51:00 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,442 - Freeze Point	Degree Fahrenheit	na	CKARLENS	May 3, 2018 7:51:00 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	CKARLENS	May 3, 2018 7:51:00 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	CKARLENS	May 3, 2018 7:51:00 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
44,130 - FRA Check Exhaust System	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
44,140 - FRA Check Intake System	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	CKARLENS	May 3, 2018 7:51:00 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
44,180 - FRA Check for Leaks	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
44,190 - FRA Perform Battery Inspection	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
50,510 - Check Entire Steering System	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		CKARLENS	May 3, 2018 7:51:00 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		CKARLENS	May 3, 2018 7:51:00 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		CKARLENS	May 3, 2018 7:51:00 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		CKARLENS	May 3, 2018 7:51:00 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,615 - Air Pressure LRI	70 Pounds per Square Inch		CKARLENS	May 3, 2018 7:51:00 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		CKARLENS	May 3, 2018 7:51:00 PM	No	
60,620 - Check Valve Stems and Caps	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
60,630 - Check and Record Tread Depth	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
60,631 - Tread Depth RF	9 32nds of an inch		CKARLENS	May 3, 2018 7:51:00 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch		CKARLENS	May 3, 2018 7:51:00 PM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		CKARLENS	May 3, 2018 7:51:00 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		CKARLENS	May 3, 2018 7:51:00 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		CKARLENS	May 3, 2018 7:51:00 PM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		CKARLENS	May 3, 2018 7:51:00 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
60,650 - Check Sidewall Wear	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
60,660 - Inspect for Cuts and Tears	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
60,670 - Check Dual Mating With Square	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
70,710 - Check Vibration Damper	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
70,730 - FRA Check Starter	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
70,770 - FRA Check Exhaust System	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,790 - Check All Body Mounts and Chassis Frame	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
77,110 - FRA Check Fuel Tank	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
77,120 - Check Suspension Components	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
77,131 - Brake Pad Thickness LF	9 Inch		CKARLENS	May 3, 2018 7:51:00 PM	No	
77,132 - Brake Pad Thickness RF	9 Inch		CKARLENS	May 3, 2018 7:51:00 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		CKARLENS	May 3, 2018 7:51:00 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		CKARLENS	May 3, 2018 7:51:00 PM	No	
77,135 - Brake Rotor LF	39.8 Inch		CKARLENS	May 3, 2018 7:51:00 PM	No	
77,136 - Brake Rotor RF	39.8 Inch		CKARLENS	May 3, 2018 7:51:00 PM	No	
77,137 - Brake Rotor LR	41.8 Inch		CKARLENS	May 3, 2018 7:51:00 PM	No	
77,138 - Brake Rotor RR	41.8 Inch		CKARLENS	May 3, 2018 7:51:00 PM	No	
77,140 - FRA Check Brake Hoses	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
77,150 - Check King Pins	-	na	CKARLENS	May 3, 2018 7:51:00 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
80,810 - Completion of PMI Report	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		CKARLENS	May 3, 2018 7:51:00 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51321577
Invoice No. 55345 - 51321577

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Replaced wipers		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	104,220 - DH

Chronology		
Reported	May 3, 2018 2:48:15 PM	May 3, 2018 2:48:15 PM
Started	May 3, 2018 12:00:00 AM	
Completed	May 3, 2018 11:01:00 PM	May 3, 2018 11:01:00 PM
Down Time		

Work Order Notes

Line 10 Tech replace front wipers
Qty:2 part# 40520

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-May-18	KARLENS,Cyrius	0.3666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 03-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	May 3, 2018 7:42:25 PM	No	
20 - Miles			CKARLENS	May 3, 2018 7:42:25 PM	No	
30 - Kilometers			CKARLENS	May 3, 2018 7:42:25 PM	No	
40 - Hours			CKARLENS	May 3, 2018 7:42:25 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.37

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51177312
Invoice No. 55345 - 51177312

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 104,220 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-May-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96
03-May-18	PA4075	FILTER, AIR SEE P546597	1	5.28	5.28

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-May-18	KARLENS,Cyrius	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: CKARLENS Performed on: 03-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		CKARLENS	May 3, 2018 8:01:45 PM	No	
101,000 - FRA Change Oil Filters	Yes		CKARLENS	May 3, 2018 8:01:45 PM	No	
102,000 - FRA Drain Engine Oil	Yes		CKARLENS	May 3, 2018 8:01:45 PM	No	
103,000 - FRA Check Transmission Fluid	Done		CKARLENS	May 3, 2018 8:01:45 PM	No	
104,000 - Lubricate Chassis	Done		CKARLENS	May 3, 2018 8:01:45 PM	No	
105,000 - Replace or Clean A/C Filters	Done		CKARLENS	May 3, 2018 8:01:45 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	CKARLENS	May 3, 2018 8:01:45 PM	No	
108,000 - Lube all pivoting	Done		CKARLENS	May 3, 2018 8:01:45	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Mechanisms				PM		

Activity Sub Total

Activity 20 Sub Total	
Parts:	7.24
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.24**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51321577
Invoice No. 55345 - 51321577

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Replaced wipers		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	104,220 - DH

Activity Header
Activity: 20 050/000/000 GROUP, ACCESSORIES
Activity Note: Replace front wipers
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-May-18	40520	BLADE, WIPER, WINDSHIELD, 20"	2	4.17	8.34

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-May-18	KARLENS,Cyrius	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	8.34
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.34**

Work Order Footer

Work Order 51321577 Total	
Parts:	8.34
Labor:	0.00
Labor Hours:	0.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.34**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51177312
Invoice No. 55345 - 51177312

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	104,220 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-May-18	KARLENS,Cyrius	0.2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 03-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	May 3, 2018 8:14:26 PM	No	
20 - Miles			CKARLENS	May 3, 2018 8:14:26 PM	No	
30 - Kilometers			CKARLENS	May 3, 2018 8:14:26 PM	No	
40 - Hours			CKARLENS	May 3, 2018 8:14:26 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51177312 Total	
Parts:	7.24
Labor:	0.00
Labor Hours:	4.20

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**7.24**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51286037
Invoice No. 55345 - 51286037

Client Department:
Department: 55345M
Work Order Description
MDT not working. Spring on battery tray lock is broken.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 102,650 - DH

Chronology		
Reported	Apr 25, 2018 6:56:03 AM	Apr 25, 2018 6:56:03 AM
Started	Apr 25, 2018 12:00:00 AM	
Completed	May 1, 2018 11:39:51 AM	May 1, 2018 11:39:51 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:
MDT not working. Spring on battery tray lock is broken.

Correction:
Cleaned MDT screen. The digitizer for the screen was turn off. That¿s why it wasn¿t working. I was able to turn the digitizer back on.

I installed a new spring for the battery tray lock.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 25-APR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Apr 25, 2018 7:04:59 AM	No	
20 - Miles			EDTORRES	Apr 25, 2018 7:04:59 AM	No	
30 - Kilometers			EDTORRES	Apr 25, 2018 7:04:59 AM	No	
40 - Hours			EDTORRES	Apr 25, 2018 7:04:59 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51286037
Invoice No. 55345 - 51286037

Client Department:
Department: 55345M
Work Order Description
MDT not working. Spring on battery tray lock is broken.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 102,650 - DH

Activity Header
Activity: 15 050/000 GROUP, ACCESSORIES
Activity Note: MDT not working. Spring on battery tray lock is broken.
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 14 Install
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Apr-18	Torres,Edwin	0.8833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51286037 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51243700
Invoice No. 55345 - 51243700

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Vehicle wont start		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	101,870 - DH

Chronology		
Reported	Apr 17, 2018 11:54:46 AM	Apr 17, 2018 11:54:46 AM
Started	Apr 17, 2018 12:00:00 AM	
Completed	Apr 17, 2018 2:04:56 PM	Apr 17, 2018 2:04:56 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:vehicle won¿t start

Cause: fuel control bleed solenoid and fuel pump not working as is designed

Correction:replaced fuel control solenoids and fuel pump kit

Parts:
1 fuel control solenoids
1 fuel pump kit
2 o2 sensors

Line 20 C: vehicle has codes for o2sensors heaters

C:check o2 sensors system found both sides o2 sensors internal failure

C:replaced sensors retest system ok at this time

Parts:2 o2 sensors

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 17-APR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Apr 17, 2018 12:27:44 PM	No	
20 - Miles			JAPEREZ	Apr 17, 2018 12:27:44 PM	No	
30 - Kilometers			JAPEREZ	Apr 17, 2018 12:27:44 PM	No	
40 - Hours			JAPEREZ	Apr 17, 2018 12:27:44 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51243700
Invoice No. 55345 - 51243700

Client Department:
Department: 55345M
Work Order Description
Vehicle wont start
Requested By: JAPEREZ
Created By: JAPEREZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 101,870 - DH

Activity Header
Activity: 15 044 FUEL SYSTEM
Activity Note: Vehicle wont start
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Apr-18	DY1185	SENSOR, OXYGEN, UPSTREAM, F550	1	58.41	58.41
17-Apr-18	P13EB10E200AB	OUT OF SERVICE MODULE, CONTROL, PRESSURE, RAIL, FUEL	1	483.41	483.41

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Apr-18	Perez,Javier	7.3333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	541.82
Labor:	0.00
Labor Hours:	7.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**541.82**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51243700
Invoice No. 55345 - 51243700

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Vehicle wont start		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	101,870 - DH

Activity Header
Activity: 25 030 ELECTRICAL GROUP
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Apr-18	DY1193	SENSOR, OXYGEN	1	84.57	84.57

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	84.57
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**84.57**

Work Order Footer

Work Order 51243700 Total	
Parts:	626.39
Labor:	0.00
Labor Hours:	7.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**626.39**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51084716
Invoice No. 55345 - 51084716

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 100,146 - DH

Chronology		
Reported	Apr 3, 2018 7:56:38 PM	Apr 3, 2018 7:56:38 PM
Started	Apr 4, 2018 12:00:00 AM	
Completed	Apr 4, 2018 5:45:00 PM	Apr 4, 2018 5:45:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA Service

CAUSE: Service due by Mileage

CORRECTION: Change Oil& Filter .Lube all Pivoting Points. check Brakes. clean batteries.
Parts# B329 Qty (1)
Oil 5W20 Qty (7) Qty

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Apr-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Apr-18	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 04-APR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Apr 4, 2018 5:33:38 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Apr 4, 2018 5:33:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Apr 4, 2018 5:33:38 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Apr 4, 2018 5:33:38 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Apr 4, 2018 5:33:38 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Apr 4, 2018 5:33:38 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Apr 4, 2018 5:33:38 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Apr 4, 2018 5:33:38 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51084716
Invoice No. 55345 - 51084716

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	100,146 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Apr-18	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 04-APR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 4, 2018 5:32:48 PM	No	
20 - Miles			DARTHURS	Apr 4, 2018 5:32:48 PM	No	
30 - Kilometers			DARTHURS	Apr 4, 2018 5:32:48 PM	No	
40 - Hours			DARTHURS	Apr 4, 2018 5:32:48 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51084716
Invoice No. 55345 - 51084716

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	100,146 - DH

Activity Header
Activity: 40 999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Apr-18	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51084716 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 51084695
Invoice No. 55345 - 51084695

Client Department:
Department: 55345M
Work Order Description
Tech repalce driver rear tires and wiper,serpentine belt
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 96,121 - DH

Chronology		
Reported	Mar 8, 2018 10:45:03 PM	Mar 8, 2018 10:45:03 PM
Started	Mar 8, 2018 12:00:00 AM	
Completed	Mar 8, 2018 11:06:00 PM	Mar 8, 2018 11:06:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: replace driver rear tires, wipers and serp belt

Cause: wear and tear

Correction: tech replaced driver rear tire. Wipers. Serpentine belt

Belt Qty:1 part# 1360K6
Wiper blades Qty:2 part # 40520
Tires Qty:2 part # 189752

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Mar-18	KARLENS,Cyrius	0.3333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 08-MAR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Mar 8, 2018 10:58:57 PM	No	
20 - Miles			CKARLENS	Mar 8, 2018 10:58:57 PM	No	
30 - Kilometers			CKARLENS	Mar 8, 2018 10:58:57 PM	No	
40 - Hours			CKARLENS	Mar 8, 2018 10:58:57 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 51084695
Invoice No. 55345 - 51084695

Client Department:
Department: 55345M
Work Order Description
Tech repalce driver rear tires and wiper,serpentine belt
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 96,121 - DH

Activity Header
Activity: 15 050/000 GROUP, ACCESSORIES
Activity Note: Replace serpentine belt
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 14 Install
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Mar-18	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	23.51	23.51

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Mar-18	KARLENS,Cyrius	1.2833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	23.51
Labor:	0.00
Labor Hours:	1.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**23.51**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 51084695
Invoice No. 55345 - 51084695

Client Department:
Department: 55345M
Work Order Description
Tech repalce driver rear tires and wiper,serpentine belt
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 96,121 - DH

Activity Header
Activity:25 050/000 GROUP, ACCESSORIES
Activity Note: Reaplce driver rear tires
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 14 Install
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Mar-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	103.44	206.88

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Mar-18	KARLENS,Cyrius	1.1833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	206.88
Labor:	0.00
Labor Hours:	1.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**206.88**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 51084695
Invoice No. 55345 - 51084695

Client Department:
Department: 55345M
Work Order Description
Tech repalce driver rear tires and wiper,serpentine belt
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 96,121 - DH

Activity Header
Activity: 35 050/000 GROUP, ACCESSORIES
Activity Note: Replace wiper
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 14 Install
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Mar-18	40520	BLADE, WIPER, WINDSHIELD, 20"	2	4.28	8.56

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Mar-18	KARLENS,Cyrius	0.6833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 35 Sub Total	
Parts:	8.56
Labor:	0.00
Labor Hours:	0.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.56**

Work Order Footer

Work Order 51084695 Total	
Parts:	238.95
Labor:	0.00
Labor Hours:	3.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**238.95**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 51037856
Invoice No. 55345 - 51037856

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 96,121 - DH

Chronology		
Reported	Mar 8, 2018 1:43:06 PM	Mar 8, 2018 1:43:06 PM
Started	Mar 8, 2018 12:00:00 AM	
Completed	Mar 8, 2018 10:59:00 PM	Mar 8, 2018 10:59:00 PM
Down Time		

Work Order Notes

Line 10 Perform PM-C
Tech performed PM-C
Parts used
Oil filter Qty:1 part# B329
Oil Qty:6qts
Transmission filter Qty:1 part#20021

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Mar-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96
08-Mar-18	20021	FILTER, TRANSMISSION 20021	1	17.21	17.21

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Mar-18	KARLENS,Cyrius	3	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: CKARLENS Performed on: 08-MAR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
10,100 - Safety Inspection	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
10,140 - Check Service Brakes	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
10,160 - FRA Check Instruments and Horns	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
10,170 - Check Fast Idle	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
10,180 - Check Starter Protection Circuit	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
10,190 - Check Reverse Warning System	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
11,100 - Check Parking Brake	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
11,150 - Perform Brake Test	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	CKARLENS	Mar 8, 2018 10:44:27 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	CKARLENS	Mar 8, 2018 10:44:27 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	CKARLENS	Mar 8, 2018 10:44:27 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	CKARLENS	Mar 8, 2018 10:44:27 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	CKARLENS	Mar 8, 2018 10:44:27 PM	No	
11,170 - FRA Check Door Operation	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
20,210 - Check Condition of Operator's Area	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,240 - FRA Check Interior Lights	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
20,260 - Check Stop Request System	-	na	CKARLENS	Mar 8, 2018 10:44:27 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	CKARLENS	Mar 8, 2018 10:44:27 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
22,110 - Check Emergency Hatches	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
22,120 - Check All Safety Equipment	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
30,310 - Check Passenger Doors	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	CKARLENS	Mar 8, 2018 10:44:27 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
30,360 - Check for Physical Damage and Decals	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
30,380 - Check Exterior Compartment Doors	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
33,100 - Check Lights and Reflectors	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
40,420 - Check Hood	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	CKARLENS	Mar 8, 2018 10:44:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	CKARLENS	Mar 8, 2018 10:44:27 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	CKARLENS	Mar 8, 2018 10:44:27 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	CKARLENS	Mar 8, 2018 10:44:27 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
44,130 - FRA Check Exhaust System	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
44,140 - FRA Check Intake System	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	CKARLENS	Mar 8, 2018 10:44:27 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
44,180 - FRA Check for Leaks	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
44,190 - FRA Perform Battery Inspection	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
50,510 - Check Entire Steering System	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		CKARLENS	Mar 8, 2018 10:44:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,614 - Air Pressure RRI	70 Pounds per Square Inch		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
60,620 - Check Valve Stems and Caps	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
60,630 - Check and Record Tread Depth	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
60,631 - Tread Depth RF	12 32nds of an inch		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
60,633 - Tread Depth RRO	10 32nds of an inch		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
60,635 - Tread Depth LRI	3 32nds of an inch		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
60,636 - Tread Depth LRO	3 32nds of an inch		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
60,650 - Check Sidewall Wear	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
60,660 - Inspect for Cuts and Tears	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
60,670 - Check Dual Mating With Square	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
70,710 - Check Vibration Damper	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
70,730 - FRA Check Starter	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
70,770 - FRA Check Exhaust System	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,780 - Check Driveline, U-joint and Slip Yokes	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
77,110 - FRA Check Fuel Tank	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
77,120 - Check Suspension Components	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
77,133 - Brake Pad Thickness LR	9 Inch		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
77,134 - Brake Pad Thickness RR	9 Inch		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
77,135 - Brake Rotor LF	39.8 Inch		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
77,136 - Brake Rotor RF	39.8 Inch		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
77,137 - Brake Rotor LR	41.8 Inch		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
77,138 - Brake Rotor RR	41.8 Inch		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
77,140 - FRA Check Brake Hoses	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
77,150 - Check King Pins	-	na	CKARLENS	Mar 8, 2018 10:44:27 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
80,810 - Completion of PMI Report	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		CKARLENS	Mar 8, 2018 10:44:27 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	19.17
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**19.17**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 51037856
Invoice No. 55345 - 51037856

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 96,121 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Mar-18	KARLENS,Cyrius	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: CKARLENS Performed on: 08-MAR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		CKARLENS	Mar 8, 2018 10:23:50 PM	No	
101,000 - FRA Change Oil Filters	Yes		CKARLENS	Mar 8, 2018 10:23:50 PM	No	
102,000 - FRA Drain Engine Oil	Yes		CKARLENS	Mar 8, 2018 10:23:50 PM	No	
103,000 - FRA Check Transmission Fluid	Done		CKARLENS	Mar 8, 2018 10:23:50 PM	No	
104,000 - Lubricate Chassis	Done		CKARLENS	Mar 8, 2018 10:23:50 PM	No	
105,000 - Replace or Clean A/C Filters	Done		CKARLENS	Mar 8, 2018 10:23:50 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	na	CKARLENS	Mar 8, 2018 10:23:50 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		CKARLENS	Mar 8, 2018 10:23:50 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		CKARLENS	Mar 8, 2018 10:23:50 PM	No	
201,000 - Service Crankcase Breather	Done		CKARLENS	Mar 8, 2018 10:23:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	Yes		CKARLENS	Mar 8, 2018 10:23:50 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	Yes		CKARLENS	Mar 8, 2018 10:23:50 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		CKARLENS	Mar 8, 2018 10:23:50 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		CKARLENS	Mar 8, 2018 10:23:50 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		CKARLENS	Mar 8, 2018 10:23:50 PM	No	
302,000 - Check Toe-In and Record Reading	-	na	CKARLENS	Mar 8, 2018 10:23:50 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	na	CKARLENS	Mar 8, 2018 10:23:50 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	Yes		CKARLENS	Mar 8, 2018 10:23:50 PM	No	
305,000 - FRA Change Differential Fluid	Yes		CKARLENS	Mar 8, 2018 10:23:50 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 51037856
Invoice No. 55345 - 51037856

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM C		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	96,121 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Mar-18	KARLENS,Cyrius	0.3	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 08-MAR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Mar 8, 2018 10:22:10 PM	No	
20 - Miles			CKARLENS	Mar 8, 2018 10:22:10 PM	No	
30 - Kilometers			CKARLENS	Mar 8, 2018 10:22:10 PM	No	
40 - Hours			CKARLENS	Mar 8, 2018 10:22:10 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 51037856
Invoice No. 55345 - 51037856

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM C		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	96,121 - DH

Activity Header
Activity: 40 999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Mar-18	KARLENS,Cyrius	0.75	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51037856 Total	
Parts:	19.17
Labor:	0.00
Labor Hours:	6.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**19.17**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51037833
Invoice No. 55345 - 51037833

Client Department:
Department: 55345M
Work Order Description
FTLMPMI_FOLLOWUP Tech replace front brakes and tires
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 91,994 - DH

Chronology		
Reported	Feb 12, 2018 10:57:49 PM	Feb 12, 2018 10:57:49 PM
Started	Feb 12, 2018 12:00:00 AM	
Completed	Feb 12, 2018 11:29:00 PM	Feb 12, 2018 11:29:00 PM
Down Time		

Work Order Notes

Line 10 Tech replaced front tires Qty:2 part number 189752
Front brake pads Qty:1 part number BRSD-1328

Activity Header
Activity: 10 017/001/000 TIRE, PNEUMATIC
Activity Note: replace front tires
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Feb-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	103.44	206.88

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	206.88
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**206.88**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51037833
Invoice No. 55345 - 51037833

Client Department:
Department: 55345M
Work Order Description
FTLMPMI_FOLLOWUP Tech replace front brakes and tires
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 91,994 - DH

Activity Header
Activity: 20 013 BRAKES
Activity Note: replace front brake pads
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Feb-18	BRSD-1328	PADS, BRAKE, DISC, FRONT	1	51.66	51.66

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	51.66
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**51.66**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51037833
Invoice No. 55345 - 51037833

Client Department:
Department: 55345M
Work Order Description
FTLMPMI_FOLLOWUP Tech replace front brakes and tires
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 91,994 - DH

Activity Header
Activity: 30 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Feb-18	KARLENS,Cyrius	0.2833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc:
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 12-FEB-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Feb 12, 2018 11:27:38 PM	No	
20 - Miles			CKARLENS	Feb 12, 2018 11:27:38 PM	No	
30 - Kilometers			CKARLENS	Feb 12, 2018 11:27:38 PM	No	
40 - Hours			CKARLENS	Feb 12, 2018 11:27:38 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51037833 Total	
Parts:	258.54
Labor:	0.00
Labor Hours:	0.28

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**258.54**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 50975573
Invoice No. 55345 - 50975573

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	91,994 - DH

Chronology		
Reported	Feb 12, 2018 10:34:12 AM	Feb 12, 2018 10:34:12 AM
Started	Feb 12, 2018 12:00:00 AM	
Completed	Feb 12, 2018 11:16:00 PM	Feb 12, 2018 11:16:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PM-A

CAUSE: Preventive Maintenance

CORRECTION: Tech Performed PM-A

Parts used
Oil filter Qty:1 part# B329
Oil Qty:6qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Feb-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Feb-18	KARLENS,Cyrius	3	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: CKARLENS Performed on: 12-FEB-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
10,100 - Safety Inspection	Done		CKARLENS	Feb 12, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:52:12 PM		
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
10,140 - Check Service Brakes	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
10,160 - FRA Check Instruments and Horns	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
10,170 - Check Fast Idle	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
10,180 - Check Starter Protection Circuit	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
10,190 - Check Reverse Warning System	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
11,100 - Check Parking Brake	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
11,150 - Perform Brake Test	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	CKARLENS	Feb 12, 2018 10:52:12 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	CKARLENS	Feb 12, 2018 10:52:12 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	CKARLENS	Feb 12, 2018 10:52:12 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	CKARLENS	Feb 12, 2018 10:52:12 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	CKARLENS	Feb 12, 2018 10:52:12 PM	No	
11,170 - FRA Check Door Operation	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
20,210 - Check Condition of Operator's Area	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		CKARLENS	Feb 12, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:52:12 PM		
20,240 - FRA Check Interior Lights	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
20,260 - Check Stop Request System	-	NA	CKARLENS	Feb 12, 2018 10:52:12 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	CKARLENS	Feb 12, 2018 10:52:12 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
22,110 - Check Emergency Hatches	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
22,120 - Check All Safety Equipment	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
30,310 - Check Passenger Doors	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	CKARLENS	Feb 12, 2018 10:52:12 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
30,360 - Check for Physical Damage and Decals	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
30,380 - Check Exterior Compartment Doors	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
33,100 - Check Lights and Reflectors	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
40,420 - Check Hood	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
40,440 - Test Coolant System Using Test	-	NA	CKARLENS	Feb 12, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Strips and Record Results				10:52:12 PM		
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	CKARLENS	Feb 12, 2018 10:52:12 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	CKARLENS	Feb 12, 2018 10:52:12 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	CKARLENS	Feb 12, 2018 10:52:12 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	-	NA	CKARLENS	Feb 12, 2018 10:52:12 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
44,130 - FRA Check Exhaust System	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
44,140 - FRA Check Intake System	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	CKARLENS	Feb 12, 2018 10:52:12 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
44,180 - FRA Check for Leaks	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
44,190 - FRA Perform Battery Inspection	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
50,510 - Check Entire Steering System	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
60,613 - Air Pressure RRO	70 Pounds per		CKARLENS	Feb 12, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			10:52:12 PM		
60,614 - Air Pressure RRI	70 Pounds per Square Inch		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
60,620 - Check Valve Stems and Caps	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
60,630 - Check and Record Tread Depth	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
60,631 - Tread Depth RF	4 32nds of an inch	replace front tires	CKARLENS	Feb 12, 2018 10:52:12 PM	Yes	51037833
60,632 - Tread Depth LF	4 32nds of an inch		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
60,650 - Check Sidewall Wear	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
60,660 - Inspect for Cuts and Tears	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
60,670 - Check Dual Mating With Square	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
70,710 - Check Vibration Damper	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
70,730 - FRA Check Starter	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
70,770 - FRA Check Exhaust System	Done		CKARLENS	Feb 12, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:52:12 PM		
70,780 - Check Driveline, U-joint and Slip Yokes	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
77,110 - FRA Check Fuel Tank	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
77,120 - Check Suspension Components	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
77,131 - Brake Pad Thickness LF	3 Inch	replace front brake pads	CKARLENS	Feb 12, 2018 10:52:12 PM	Yes	51037833
77,132 - Brake Pad Thickness RF	5 Inch		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
77,133 - Brake Pad Thickness LR	9 Inch		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
77,134 - Brake Pad Thickness RR	9 Inch		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
77,135 - Brake Rotor LF	39.8 Inch		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
77,136 - Brake Rotor RF	39.8 Inch		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
77,137 - Brake Rotor LR	41.8 Inch		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
77,138 - Brake Rotor RR	41.8 Inch		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
77,140 - FRA Check Brake Hoses	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
77,150 - Check King Pins	-	NA	CKARLENS	Feb 12, 2018 10:52:12 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
80,810 - Completion of PMI Report	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		CKARLENS	Feb 12, 2018 10:52:12 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 50975573
Invoice No. 55345 - 50975573

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 91,994 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Feb-18	KARLENS,Cyrius	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: CKARLENS Performed on: 12-FEB-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		CKARLENS	Feb 12, 2018 10:45:30 PM	No	
101,000 - FRA Change Oil Filters	Yes		CKARLENS	Feb 12, 2018 10:45:30 PM	No	
102,000 - FRA Drain Engine Oil	Yes		CKARLENS	Feb 12, 2018 10:45:30 PM	No	
103,000 - FRA Check Transmission Fluid	Done		CKARLENS	Feb 12, 2018 10:45:30 PM	No	
104,000 - Lubricate Chassis	Done		CKARLENS	Feb 12, 2018 10:45:30 PM	No	
105,000 - Replace or Clean A/C Filters	Done		CKARLENS	Feb 12, 2018 10:45:30 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	CKARLENS	Feb 12, 2018 10:45:30 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		CKARLENS	Feb 12, 2018 10:45:30 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	2.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 50975573
Invoice No. 55345 - 50975573

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 91,994 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Feb-18	KARLENS,Cyrius	0.2833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 12-FEB-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Feb 12, 2018 10:45:02 PM	No	
20 - Miles			CKARLENS	Feb 12, 2018 10:45:02 PM	No	
30 - Kilometers			CKARLENS	Feb 12, 2018 10:45:02 PM	No	
40 - Hours			CKARLENS	Feb 12, 2018 10:45:02 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 50975573 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	5.28

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51017097
Invoice No. 55345 - 51017097

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Vehicle wont start		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	90,783 - DH

Chronology		
Reported	Jan 31, 2018 11:13:07 AM	Jan 31, 2018 11:13:07 AM
Started	Jan 31, 2018 12:00:00 AM	
Completed	Feb 1, 2018 9:14:00 AM	Feb 1, 2018 9:14:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:vehicle won't start

Cause: check cranking system found batteries are not good also batteries terminals are corroded

Correction:replace 2 new batteries and replaced both sides terminals with a used ones

Parts:

2 new batteries 34a6m

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 31-JAN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Jan 31, 2018 11:27:02 AM	No	
20 - Miles			JAPEREZ	Jan 31, 2018 11:27:02 AM	No	
30 - Kilometers			JAPEREZ	Jan 31, 2018 11:27:02 AM	No	
40 - Hours			JAPEREZ	Jan 31, 2018 11:27:02 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51017097
Invoice No. 55345 - 51017097

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Vehicle wont start		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	90,783 - DH

Activity Header
Activity: 15 032 CRANKING
Activity Note: Vehicle wont start
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
31-Jan-18	34AGM	BATTERY, AGM, GROUP-34	2	114.24	228.48

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Jan-18	Perez,Javier	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	228.48
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**228.48**

Work Order Footer

Work Order 51017097 Total	
Parts:	228.48
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**228.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51016288
Invoice No. 55345 - 51016288

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Needs batteries		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	90,783 - DH

Chronology		
Reported	Jan 30, 2018 11:26:56 PM	Jan 30, 2018 11:26:56 PM
Started	Jan 30, 2018 12:00:00 AM	
Completed	Jan 30, 2018 11:32:00 PM	Jan 30, 2018 11:32:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs batteries

Cause: bad

Correction:check and replaced batteries
Part number 34-AGM qty 2

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Jan-18	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 30-JAN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jan 30, 2018 11:29:14 PM	No	
20 - Miles			RGASPARD	Jan 30, 2018 11:29:14 PM	No	
30 - Kilometers			RGASPARD	Jan 30, 2018 11:29:14 PM	No	
40 - Hours			RGASPARD	Jan 30, 2018 11:29:14 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51016288
Invoice No. 55345 - 51016288

Client Department:
Department: 55345M
Work Order Description
Needs batteries
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 90,783 - DH

Activity Header
Activity: 15 031 CHARGING
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Jan-18	34AGM	BATTERY, AGM, GROUP-34	2	114.24	228.48

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Jan-18	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	228.48
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**228.48**

Work Order Footer

Work Order 51016288 Total	
Parts:	228.48
Labor:	0.00
Labor Hours:	1.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**228.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 50975493
Invoice No. 55345 - 50975493

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
FOLLOW UP PMA		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	87,719 - DH

Chronology		
Reported	Jan 3, 2018 9:42:22 PM	Jan 3, 2018 9:42:22 PM
Started		
Completed	Jan 4, 2018 9:44:00 PM	Jan 4, 2018 9:44:00 PM
Down Time		

Work Order Notes

Line 10 TECH CREATED ANOTHER WORK ORDER BY MISTAKE.

Activity Header
Activity: 10 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 50975493 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 49521794
Invoice No. 55345 - 49521794

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	87,719 - DH

Chronology		
Reported	Jan 3, 2018 12:44:32 PM	Jan 3, 2018 12:44:32 PM
Started	Jan 3, 2018 12:00:00 AM	
Completed	Jan 3, 2018 11:14:00 PM	Jan 3, 2018 11:14:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PM-A

CAUSE:Preventive maintenance

CORRECTION:Tech performed PM-A

Parts used.
Oil Qty:6 Qts
Oil filter Qty: 1 part number
Air filter. Qty1 part number Pa4075

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Jan-18	PA4075	FILTER, AIR SEE P546597	1	5.18	5.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jan-18	KARLENS,Cyrius	4.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: CKARLENS Performed on: 03-JAN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,100 - Safety Inspection	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
10,140 - Check Service Brakes	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
10,160 - FRA Check Instruments and Horns	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
10,170 - Check Fast Idle	-	na	CKARLENS	Jan 3, 2018 10:15:22 PM	No	
10,180 - Check Starter Protection Circuit	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
10,190 - Check Reverse Warning System	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
11,100 - Check Parking Brake	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
11,150 - Perform Brake Test	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	CKARLENS	Jan 3, 2018 10:15:22 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	CKARLENS	Jan 3, 2018 10:15:22 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	CKARLENS	Jan 3, 2018 10:15:22 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	CKARLENS	Jan 3, 2018 10:15:22 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	CKARLENS	Jan 3, 2018 10:15:22 PM	No	
11,170 - FRA Check Door Operation	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
20,210 - Check Condition of Operator's Area	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,230 - FRA Check Wiring Under Dash	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
20,240 - FRA Check Interior Lights	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
20,260 - Check Stop Request System	-	na	CKARLENS	Jan 3, 2018 10:15:22 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	CKARLENS	Jan 3, 2018 10:15:22 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
22,110 - Check Emergency Hatches	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
22,120 - Check All Safety Equipment	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
30,310 - Check Passenger Doors	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	CKARLENS	Jan 3, 2018 10:15:22 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
30,360 - Check for Physical Damage and Decals	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
30,380 - Check Exterior Compartment Doors	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
33,100 - Check Lights and Reflectors	-	replace upper left marker light	CKARLENS	Jan 3, 2018 10:15:22 PM	Yes	50975530
33,110 - Check License Plate, Permits and State Inspection Decals	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
40,420 - Check Hood	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	CKARLENS	Jan 3, 2018 10:15:22 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	CKARLENS	Jan 3, 2018 10:15:22 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	CKARLENS	Jan 3, 2018 10:15:22 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	CKARLENS	Jan 3, 2018 10:15:22 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
44,130 - FRA Check Exhaust System	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
44,140 - FRA Check Intake System	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	CKARLENS	Jan 3, 2018 10:15:22 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
44,180 - FRA Check for Leaks	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
44,190 - FRA Perform Battery Inspection	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
50,510 - Check Entire Steering System	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		CKARLENS	Jan 3, 2018 10:15:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,613 - Air Pressure RRO	70 Pounds per Square Inch		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
60,620 - Check Valve Stems and Caps	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
60,630 - Check and Record Tread Depth	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
60,631 - Tread Depth RF	7 32nds of an inch		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
60,632 - Tread Depth LF	7 32nds of an inch		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
60,633 - Tread Depth RRO	3 32nds of an inch	Replace Right Rear tires	CKARLENS	Jan 3, 2018 10:15:22 PM	Yes	50975530
60,634 - Tread Depth RRI	4 32nds of an inch		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
60,650 - Check Sidewall Wear	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
60,660 - Inspect for Cuts and Tears	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
60,670 - Check Dual Mating With Square	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
70,710 - Check Vibration Damper	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
70,730 - FRA Check Starter	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,770 - FRA Check Exhaust System	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
77,110 - FRA Check Fuel Tank	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
77,120 - Check Suspension Components	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
77,131 - Brake Pad Thickness LF	6 Inch		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
77,132 - Brake Pad Thickness RF	6 Inch		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
77,133 - Brake Pad Thickness LR	4 Inch		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
77,134 - Brake Pad Thickness RR	3 Inch	Replace brake pads	CKARLENS	Jan 3, 2018 10:15:22 PM	Yes	50975530
77,135 - Brake Rotor LF	39.7 Inch		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
77,136 - Brake Rotor RF	39.8 Inch		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
77,137 - Brake Rotor LR	41.7 Inch		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
77,138 - Brake Rotor RR	41.8 Inch		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
77,140 - FRA Check Brake Hoses	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
77,150 - Check King Pins	-	na	CKARLENS	Jan 3, 2018 10:15:22 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
80,810 - Completion of PMI Report	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		CKARLENS	Jan 3, 2018 10:15:22 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	5.18
Labor:	0.00
Labor Hours:	4.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.18**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 49521794
Invoice No. 55345 - 49521794

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 87,719 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Jan-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jan-18	KARLENS,Cyrius	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: CKARLENS Performed on: 03-JAN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		CKARLENS	Jan 3, 2018 11:12:41 PM	No	
101,000 - FRA Change Oil Filters	Yes		CKARLENS	Jan 3, 2018 11:12:41 PM	No	
102,000 - FRA Drain Engine Oil	Yes		CKARLENS	Jan 3, 2018 11:12:41 PM	No	
103,000 - FRA Check Transmission Fluid	Done		CKARLENS	Jan 3, 2018 11:12:41 PM	No	
104,000 - Lubricate Chassis	Done		CKARLENS	Jan 3, 2018 11:12:41 PM	No	
105,000 - Replace or Clean A/C Filters	Done		CKARLENS	Jan 3, 2018 11:12:41 PM	No	50975493
107,000 - FRA Change Primary Fuel Filter	No	n/a	CKARLENS	Jan 3, 2018 11:12:41 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		CKARLENS	Jan 3, 2018 11:12:41 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.92
	Labor:	0.00
	Labor Hours:	2.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 49521794
Invoice No. 55345 - 49521794

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	87,719 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jan-18	KARLENS,Cyrius	0.2833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 03-JAN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Jan 3, 2018 9:42:53 PM	No	
20 - Miles			CKARLENS	Jan 3, 2018 9:42:53 PM	No	
30 - Kilometers			CKARLENS	Jan 3, 2018 9:42:53 PM	No	
40 - Hours			CKARLENS	Jan 3, 2018 9:42:53 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 49521794 Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	6.78

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**7.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 50975530
Invoice No. 55345 - 50975530

Client Department:

Department: 55345M

Work Order Description
FOLLOWUP---------->BRAKES AND TIRES REPLACE TOP MARKER LIGHT

Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 87,719 - DH

Chronology		
Reported	Jan 3, 2018 10:15:22 PM	Jan 3, 2018 10:15:22 PM
Started	Jan 3, 2018 12:00:00 AM	
Completed	Jan 3, 2018 11:13:00 PM	Jan 3, 2018 11:13:00 PM
Down Time		

Work Order Notes

Line 10 Tech replaced 2 RR tires part number 189752 Qty2
Tech replaced rear brakes part number BRSD-1330-B
Tech replaced upper left marker light warranty

Activity Header
Activity: 10 034 LIGHTING SYSTEM
Activity Note: replace upper left marker light
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jan-18	KARLENS,Cyrius	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 50975530
Invoice No. 55345 - 50975530

Client Department:

Department: 55345M

Work Order Description
FOLLOWUP---------->BRAKES AND TIRES REPLACE TOP MARKER LIGHT

Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 87,719 - DH

Activity Header
Activity: 20 013 BRAKES
Activity Note: Replace brake pads
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Jan-18	BRSD-1330	PADS, BRAKE, DISC, REAR, FORD SAME AS PFH133020	1	43.15	43.15

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jan-18	KARLENS,Cyrius	1.1666666	0	0
03-Jan-18	KARLENS,Cyrius	4	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	43.15
Labor:	0.00
Labor Hours:	5.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.15**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 50975530
Invoice No. 55345 - 50975530

Client Department:

Department: 55345M

Work Order Description
FOLLOWUP---------->BRAKES AND TIRES REPLACE TOP MARKER LIGHT

Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 87,719 - DH

Activity Header
Activity: 30 017/001/000 TIRE, PNEUMATIC
Activity Note: Replace Right Rear tires
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Jan-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	103.44	206.88

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jan-18	KARLENS,Cyrius	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	206.88
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**206.88**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 50975530
Invoice No. 55345 - 50975530

Client Department:

Department: 55345M

Work Order Description
FOLLOWUP---------->BRAKES AND TIRES REPLACE TOP MARKER LIGHT

Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 87,719 - DH

Activity Header
Activity: 40 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jan-18	KARLENS,Cyrius	0.2833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

40 Desc:
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 03-JAN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Jan 3, 2018 10:39:00 PM	No	
20 - Miles			CKARLENS	Jan 3, 2018 10:39:00 PM	No	
30 - Kilometers			CKARLENS	Jan 3, 2018 10:39:00 PM	No	
40 - Hours			CKARLENS	Jan 3, 2018 10:39:00 PM	No	

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 50975530 Total	
Parts:	250.03

	Labor:	0.00
	Labor Hours:	8.95
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**250.03**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 46397292
Invoice No. 55345 - 46397292

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM B		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	83,756 - DH

Chronology		
Reported	Nov 28, 2017 9:41:53 AM	Nov 28, 2017 9:41:53 AM
Started	Nov 29, 2017 12:00:00 AM	
Completed	Nov 29, 2017 12:19:00 AM	Nov 29, 2017 12:19:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmB

CAUSE:Service

CORRECTION:perform pmB service
Oil filter B329 qty 1
Engine oil 5w20 qty 7 qts
Replaced drain plug oil F75Z-6730-BA qty 1

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Nov-17	Gaspard,Ronald	1.55	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 29-NOV-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
10,100 - Safety Inspection	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
10,120 - FRA Check All Warning Lights and	Done		RGASPARD	Nov 29, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				12:13:09 AM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Nov 29, 2017 12:13:09 AM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Nov 29, 2017 12:13:09 AM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Nov 29, 2017 12:13:09 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Nov 29, 2017 12:13:09 AM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Nov 29, 2017 12:13:09 AM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Nov 29, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:13:09 AM		
20,260 - Check Stop Request System	-	na	RGASPARD	Nov 29, 2017 12:13:09 AM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Nov 29, 2017 12:13:09 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Nov 29, 2017 12:13:09 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
40,420 - Check Hood	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Nov 29, 2017 12:13:09 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Nov 29, 2017 12:13:09 AM	No	
40,442 - Freeze Point	Degree	na	RGASPARD	Nov 29, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			12:13:09 AM		
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Nov 29, 2017 12:13:09 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Nov 29, 2017 12:13:09 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Nov 29, 2017 12:13:09 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
60,615 - Air Pressure LRI	65 Pounds per		RGASPARD	Nov 29, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			12:13:09 AM		
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
60,631 - Tread Depth RF	7 32nds of an inch		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
60,632 - Tread Depth LF	8 32nds of an inch		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
70,790 - Check All Body Mounts and Chassis	Done		RGASPARD	Nov 29, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Frame				12:13:09 AM		
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
77,131 - Brake Pad Thickness LF	7 Inch		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
77,132 - Brake Pad Thickness RF	7 Inch		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
77,133 - Brake Pad Thickness LR	7 Inch		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
77,134 - Brake Pad Thickness RR	7 Inch		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
77,137 - Brake Rotor LR	38 Inch		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
77,138 - Brake Rotor RR	38 Inch		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
77,150 - Check King Pins	-	na	RGASPARD	Nov 29, 2017 12:13:09 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Nov 29, 2017 12:13:09 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 46397292
Invoice No. 55345 - 46397292

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM B		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	83,756 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Nov-17	F75Z-6730-BA	PLUG, DRAIN, OIL, ENGINE, 3.0L	1	6.66	6.66
29-Nov-17	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Nov-17	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: RGASPARD Performed on: 29-NOV-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Nov 29, 2017 12:13:57 AM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Nov 29, 2017 12:13:57 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Nov 29, 2017 12:13:57 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Nov 29, 2017 12:13:57 AM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Nov 29, 2017 12:13:57 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Nov 29, 2017 12:13:57 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Nov 29, 2017 12:13:57 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Nov 29, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:13:57 AM		
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Nov 29, 2017 12:13:57 AM	No	
201,000 - Service Crankcase Breather	Done		RGASPARD	Nov 29, 2017 12:13:57 AM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Nov 29, 2017 12:13:57 AM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Nov 29, 2017 12:13:57 AM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Nov 29, 2017 12:13:57 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	8.58
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.58**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 46397292
Invoice No. 55345 - 46397292

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM B		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	83,756 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Nov-17	Gaspard,Ronald	0.1833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 29-NOV-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Nov 29, 2017 12:14:16 AM	No	
20 - Miles			RGASPARD	Nov 29, 2017 12:14:16 AM	No	
30 - Kilometers			RGASPARD	Nov 29, 2017 12:14:16 AM	No	
40 - Hours			RGASPARD	Nov 29, 2017 12:14:16 AM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 46397292 Total	
Parts:	8.58
Labor:	0.00
Labor Hours:	2.73

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**8.58**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 48008500
Invoice No. 55345 - 48008500

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Spark plugs.		Ford E450 Champion Challenger	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	81,971 - DH

Chronology		
Reported	Nov 13, 2017 6:15:07 AM	Nov 13, 2017 6:15:07 AM
Started	Nov 13, 2017 12:00:00 AM	
Completed	Nov 13, 2017 7:29:00 AM	Nov 13, 2017 7:29:00 AM
Down Time		

Work Order Notes

Line 10
Spark plug

COMPLAINT:
Manufacturer recommended spark plug service by mileage

CAUSE:
Normal wear.

CORRECTION:
Removed all spark plugs and spark plug boots. Replaced them with new spark plugs and spark plug boots. Applied dielectric grease to the the spring inside the spark plug boot.

PARTS
Qty 8 Boot WR-6128
Qty 8 spark plug SP521

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 13-NOV-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Nov 13, 2017 6:27:34 AM	No	
20 - Miles			EDTORRES	Nov 13, 2017 6:27:34 AM	No	
30 - Kilometers			EDTORRES	Nov 13, 2017 6:27:34 AM	No	
40 - Hours			EDTORRES	Nov 13, 2017 6:27:34 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 48008500
Invoice No. 55345 - 48008500

Client Department:
Department: 55345M
Work Order Description
Spark plugs.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 81,971 - DH

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Nov-17	WR6128	BOOT, PLUG, SPARK	10	5.48	54.8
13-Nov-17	SP521	PLUG, SPARK, 5.4L, FORD	10	4.15	41.5

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Nov-17	Torres,Edwin	3.2166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	96.30
Labor:	0.00
Labor Hours:	3.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**96.30**

Work Order Footer

Work Order 48008500 Total	
Parts:	96.30
Labor:	0.00
Labor Hours:	3.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**96.30**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 43025891
Invoice No. 55345 - 43025891

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	79,752 - DH

Chronology		
Reported	Oct 27, 2017 9:38:13 AM	Oct 27, 2017 9:38:13 AM
Started	Oct 27, 2017 12:00:00 AM	
Completed	Oct 27, 2017 3:00:00 PM	Oct 27, 2017 3:00:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE: preventive maintenance

CORRECTION: perform PM A service lube all Pivoting cross rotate tires completed
Parts #B329 qty1
Oil5w30 Qts 6

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Oct-17	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Oct-17	Pierre,Hubert J	5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 27-OCT-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
10,100 - Safety Inspection	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
11,152 - Decelerometer Results Test 1	FEET	N/A	HPIERRE	Oct 27, 2017 2:54:44 PM	No	
11,154 - Decelerometer Results Test 2	FEET	N/A	HPIERRE	Oct 27, 2017 2:54:44 PM	No	
11,156 - Decelerometer Results Test 3	FEET	N/A	HPIERRE	Oct 27, 2017 2:54:44 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	Oct 27, 2017 2:54:44 PM	No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	Oct 27, 2017 2:54:44 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
20,230 - FRA Check Wiring Under Dash	-	N/A	HPIERRE	Oct 27, 2017 2:54:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,240 - FRA Check Interior Lights	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Oct 27, 2017 2:54:44 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Oct 27, 2017 2:54:44 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Oct 27, 2017 2:54:44 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
40,420 - Check Hood	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Oct 27, 2017 2:54:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Oct 27, 2017 2:54:44 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Oct 27, 2017 2:54:44 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Oct 27, 2017 2:54:44 PM	No	
40,461 - Refractometer Reading	0 Degree Fahrenheit	N/A	HPIERRE	Oct 27, 2017 2:54:44 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Oct 27, 2017 2:54:44 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Oct 27, 2017 2:54:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Oct 27, 2017 2:54:44 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
77,135 - Brake Rotor LF	1.6 Inch		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
77,136 - Brake Rotor RF	1.6 Inch		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
77,137 - Brake Rotor LR	1.7 Inch		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
77,138 - Brake Rotor RR	1.7 Inch		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Oct 27, 2017 2:54:44 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Oct 27, 2017 2:54:44 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	5.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 43025891
Invoice No. 55345 - 43025891

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 79,752 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Oct-17	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 27-OCT-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Oct 27, 2017 2:56:30 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Oct 27, 2017 2:56:30 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Oct 27, 2017 2:56:30 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Oct 27, 2017 2:56:30 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Oct 27, 2017 2:56:30 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Oct 27, 2017 2:56:30 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Oct 27, 2017 2:56:30 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Oct 27, 2017 2:56:30 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 43025891
Invoice No. 55345 - 43025891

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	79,752 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Oct-17	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 27-OCT-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Oct 27, 2017 2:56:54 PM	No	
20 - Miles			HPIERRE	Oct 27, 2017 2:56:54 PM	No	
30 - Kilometers			HPIERRE	Oct 27, 2017 2:56:54 PM	No	
40 - Hours			HPIERRE	Oct 27, 2017 2:56:54 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 43025891 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	5.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 37890417
Invoice No. 55345 - 37890417

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	75,717 - DH

Chronology		
Reported	Sep 21, 2017 1:18:33 PM	Sep 21, 2017 1:18:33 PM
Started	Sep 22, 2017 12:00:00 AM	
Completed	Sep 22, 2017 5:39:00 PM	Sep 22, 2017 5:39:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA Service

CAUSE: Service due by Mileage

CORRECTION: Change Oil & Filter Lube all Pivoting Points ,Check Brakes, clean batteries.
Parts# B329 Qty (1)
Oil 5W20 Qty (7.0) Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Sep-17	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 22-SEP-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
10,120 - FRA Check All Warning Lights	Done		DARTHURS	Sep 22, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
and Alarms				5:05:11 PM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Sep 22, 2017 5:05:11 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Sep 22, 2017 5:05:11 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Sep 22, 2017 5:05:11 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Sep 22, 2017 5:05:11 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Sep 22, 2017 5:05:11 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
20,260 - Check Stop Request System	-	NA	DARTHURS	Sep 22, 2017 5:05:11 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Sep 22, 2017 5:05:11 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Sep 22, 2017 5:05:11 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
40,420 - Check Hood	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Sep 22, 2017 5:05:11 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Sep 22, 2017 5:05:11 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Sep 22, 2017 5:05:11 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Sep 22, 2017 5:05:11 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Sep 22, 2017 5:05:11 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Sep 22, 2017 5:05:11 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Sep 22, 2017 5:05:11 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
60,632 - Tread Depth LF	11 32nds of an inch		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
60,633 - Tread Depth RRO	3 32nds of an inch		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
60,634 - Tread Depth RRI	3 32nds of an inch	swap both R/R Tire tread depth 8/32 both	DARTHURS	Sep 22, 2017 5:05:11 PM	Yes	43023593
60,635 - Tread Depth LRI	8 32nds of an inch		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Sep 22, 2017 5:05:11 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
77,135 - Brake Rotor LF	1.564 Inch		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
77,136 - Brake Rotor RF	1.563 Inch		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
77,137 - Brake Rotor LR	1.651 Inch		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
77,138 - Brake Rotor RR	1.652 Inch		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Sep 22, 2017 5:05:11 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Sep 22, 2017 5:05:11 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 37890417
Invoice No. 55345 - 37890417

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	75,717 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Sep-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Sep-17	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 22-SEP-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Sep 22, 2017 5:06:16 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Sep 22, 2017 5:06:16 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Sep 22, 2017 5:06:16 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Sep 22, 2017 5:06:16 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Sep 22, 2017 5:06:16 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Sep 22, 2017 5:06:16 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Sep 22, 2017 5:06:16 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Sep 22, 2017 5:06:16 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.92
	Labor:	0.00
	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 37890417
Invoice No. 55345 - 37890417

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	75,717 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Sep-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 22-SEP-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Sep 22, 2017 5:06:40 PM	No	
20 - Miles			DARTHURS	Sep 22, 2017 5:06:40 PM	No	
30 - Kilometers			DARTHURS	Sep 22, 2017 5:06:40 PM	No	
40 - Hours			DARTHURS	Sep 22, 2017 5:06:40 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 37890417 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 43023593
Invoice No. 55345 - 43023593

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PMA Follow up>>>>>>R/R Tire		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	75,717 - DH

Chronology		
Reported	Sep 22, 2017 5:05:11 PM	Sep 22, 2017 5:05:11 PM
Started	Sep 22, 2017 12:00:00 AM	
Completed	Sep 22, 2017 5:38:00 PM	Sep 22, 2017 5:38:00 PM
Down Time		

Work Order Notes

Line 10 Remove both R/R Tire&Replace With (2) Use tire tread depth 8/32

Activity Header
Activity: 10 017 TIRES, TUBES, LINERS & VALVES
Activity Note: swap both R/R Tire tread depth 8/32 both
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Sep-17	Arthurs,Durvin	0.1666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 43023593
Invoice No. 55345 - 43023593

Client Department:
Department: 55345M
Work Order Description
PMA Follow up>>>>>>R/R Tire
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 75,717 - DH

Activity Header
Activity: 20 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 01 Breakdown
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Sep-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 22-SEP-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Sep 22, 2017 5:15:01 PM	No	
20 - Miles			DARTHURS	Sep 22, 2017 5:15:01 PM	No	
30 - Kilometers			DARTHURS	Sep 22, 2017 5:15:01 PM	No	
40 - Hours			DARTHURS	Sep 22, 2017 5:15:01 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 43023593 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.25

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 34964262
Invoice No. 55345 - 34964262

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 71,780 - DH

Chronology		
Reported	Jul 31, 2017 8:00:37 AM	Jul 31, 2017 8:00:37 AM
Started	Jul 31, 2017 12:00:00 AM	
Completed	Aug 1, 2017 7:24:00 AM	Aug 1, 2017 7:24:00 AM
Down Time		

Work Order Notes

Line 10 Pmc

Preventive maintenance

Perform service lube all Pivot point cross tires and replace air filter completed
Parts # PA 4075 qty 1 air filter
Oil#329 qt 1 oil 5w30 qts 6
Transmission filter 20021 qty 1

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
31-Jul-17	20021	FILTER, TRANSMISSION 20021	1	13.68	13.68
31-Jul-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92
31-Jul-17	PA4075	OUT OF SERVICE DO NOT ORDER FILTER, AIR, PAPER SAME AS AF25590	1	5.18	5.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Jul-17	Pierre,Hubert J	7	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
10 Desc: Light Medium Duty PMI Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 31-JUL-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
10,100 - Safety Inspection	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
11,152 - Decelerometer Results Test 1	FEET	N/A	HPIERRE	Jul 31, 2017 2:32:07 PM	No	
11,154 - Decelerometer Results Test 2	FEET	N/A	HPIERRE	Jul 31, 2017 2:32:07 PM	No	
11,156 - Decelerometer Results Test 3	FEET	N/A	HPIERRE	Jul 31, 2017 2:32:07 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	Jul 31, 2017 2:32:07 PM	No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	Jul 31, 2017 2:32:07 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
20,230 - FRA Check Wiring Under Dash	-	N/A	HPIERRE	Jul 31, 2017 2:32:07 PM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Jul 31, 2017 2:32:07 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Jul 31, 2017 2:32:07 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Jul 31, 2017 2:32:07 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
40,420 - Check Hood	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Jul 31, 2017 2:32:07 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Jul 31, 2017 2:32:07 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Jul 31, 2017 2:32:07 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Jul 31, 2017 2:32:07 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Jul 31, 2017 2:32:07 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Jul 31, 2017 2:32:07 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Jul 31, 2017 2:32:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
60,631 - Tread Depth RF	12 32nds of an inch		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Jul 31, 2017 2:32:07 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
77,135 - Brake Rotor LF	1.6 Inch		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
77,136 - Brake Rotor RF	1.6 Inch		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
77,137 - Brake Rotor LR	1.7 Inch		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
77,138 - Brake Rotor RR	1.7 Inch		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Jul 31, 2017 2:32:07 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Jul 31, 2017 2:32:07 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	20.78
Labor:	0.00
Labor Hours:	7.00
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**20.78**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 34964262
Invoice No. 55345 - 34964262

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 71,780 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Jul-17	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: HPIERRE Performed on: 31-JUL-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Jul 31, 2017 2:36:42 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Jul 31, 2017 2:36:42 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Jul 31, 2017 2:36:42 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Jul 31, 2017 2:36:42 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Jul 31, 2017 2:36:42 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Jul 31, 2017 2:36:42 PM	No	
107,000 - FRA Change Primary Fuel Filter	Done		HPIERRE	Jul 31, 2017 2:36:42 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Jul 31, 2017 2:36:42 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		HPIERRE	Jul 31, 2017 2:36:42 PM	No	
201,000 - Service Crankcase Breather	Done		HPIERRE	Jul 31, 2017 2:36:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	Yes		HPIERRE	Jul 31, 2017 2:36:42 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		HPIERRE	Jul 31, 2017 2:36:42 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		HPIERRE	Jul 31, 2017 2:36:42 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		HPIERRE	Jul 31, 2017 2:36:42 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		HPIERRE	Jul 31, 2017 2:36:42 PM	No	
302,000 - Check Toe-In and Record Reading	-	N/A	HPIERRE	Jul 31, 2017 2:36:42 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	N/A	HPIERRE	Jul 31, 2017 2:36:42 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		HPIERRE	Jul 31, 2017 2:36:42 PM	No	
305,000 - FRA Change Differential Fluid	Yes		HPIERRE	Jul 31, 2017 2:36:42 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 34964262
Invoice No. 55345 - 34964262

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 71,780 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Jul-17	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 31-JUL-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Jul 31, 2017 2:37:16 PM	No	
20 - Miles			HPIERRE	Jul 31, 2017 2:37:16 PM	No	
30 - Kilometers			HPIERRE	Jul 31, 2017 2:37:16 PM	No	
40 - Hours			HPIERRE	Jul 31, 2017 2:37:16 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34964262 Total	
Parts:	20.78
Labor:	0.00
Labor Hours:	7.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**20.78**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 37080799
Invoice No. 55345 - 37080799

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
L/R Tire		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	70,775 - DH

Chronology		
Reported	Jul 23, 2017 7:59:26 PM	Jul 23, 2017 7:59:26 PM
Started	Jul 23, 2017 12:00:00 AM	
Completed	Jul 23, 2017 8:07:00 PM	Jul 23, 2017 8:07:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: both L/R Tire

CAUSE: Both tire below Spec

CORRECTION: Swap Two Front Tire .From Bus 5429 both 10/32& Replace on Bus 5418 both tire 3/32

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jul-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 23-JUL-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 23, 2017 8:02:20 PM	No	
20 - Miles			DARTHURS	Jul 23, 2017 8:02:20 PM	No	
30 - Kilometers			DARTHURS	Jul 23, 2017 8:02:20 PM	No	
40 - Hours			DARTHURS	Jul 23, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:02:20 PM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 37080799
Invoice No. 55345 - 37080799

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
L/R Tire		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	70,775 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Replace both L/R Tire
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jul-17	Arthurs,Durvin	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 37080799 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 35721223
Invoice No. 55345 - 35721223

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Front tires near minimun specs		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	69,192 - DH

Chronology		
Reported	Jul 9, 2017 11:56:11 AM	Jul 9, 2017 11:56:11 AM
Started	Jul 9, 2017 12:00:00 AM	
Completed	Jul 10, 2017 9:32:00 AM	Jul 10, 2017 9:32:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:
Check front tires
¿
CAUSE:
Normal wear
¿
CORRECTION:
Mounted and balanced 2 tires. Set tires to 65 psi and placed them in the front. Torqued lug nuts to 140 LBS. Test drove. Re-torqued to 140 LBS.
¿

Parts. Firestone tires. Part # 189752 qty 2

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 09-JUL-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Jul 9, 2017 12:09:35 PM	No	
20 - Miles			RAURODRIGUEZ	Jul 9, 2017 12:09:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30 - Kilometers			RAURODRIGUEZ	Jul 9, 2017 12:09:35 PM	No	
40 - Hours			RAURODRIGUEZ	Jul 9, 2017 12:09:35 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 35721223
Invoice No. 55345 - 35721223

Client Department:
Department: 55345M
Work Order Description
Front tires near minimun specs
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 69,192 - DH

Activity Header
Activity: 15 017/001/000 TIRE, PNEUMATIC
Activity Note: Front tires near min. Specs
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Jul-17	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	105.25	210.5

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Jul-17	Rodriguez,Raul	1.2833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	210.50
Labor:	0.00
Labor Hours:	1.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**210.50**

Work Order Footer

Work Order 35721223 Total	
Parts:	210.50
Labor:	0.00
Labor Hours:	1.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**210.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34988354
Invoice No. 55345 - 34988354

Client Department:
Department: 55345M
Work Order Description
Driver said the lift is not working
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 68,326 - DH

Chronology		
Reported	Jun 23, 2017 1:14:14 PM	Jun 23, 2017 1:14:14 PM
Started	Jun 23, 2017 12:00:00 AM	
Completed	Jun 23, 2017 3:40:54 PM	Jun 23, 2017 3:40:54 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: driver said the lift not working

CAUSE:IB up switch bad

CORRECTION: replace IB up switch kit completed
Part under warranty qty1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jun-17	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 23-JUN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Jun 23, 2017 1:36:53 PM	No	
20 - Miles			HPIERRE	Jun 23, 2017 1:36:53 PM	No	
30 - Kilometers			HPIERRE	Jun 23, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				1:36:53 PM		
40 - Hours			HPIERRE	Jun 23, 2017 1:36:53 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34988354
Invoice No. 55345 - 34988354

Client Department:
Department: 55345M
Work Order Description
Driver said the lift is not working
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 68,326 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jun-17	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34988354 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 34835360
Invoice No. 55345 - 34835360

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	67,648 - DH

Chronology		
Reported	Jun 16, 2017 7:10:08 AM	Jun 16, 2017 7:10:08 AM
Started	Jun 16, 2017 12:00:00 AM	
Completed	Jun 16, 2017 4:32:00 PM	Jun 16, 2017 4:32:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PM A serviced

CAUSE: PMA Service Due

CORRECTION:Performed PMA
Changed Engine oil and engine oil filter
Parts# B329 Qty:1

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jun-17	Delva,Terry	4	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: TDELVA Performed on: 16-JUN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
10,100 - Safety Inspection	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
10,120 - FRA Check All Warning Lights and	Done		TDELVA	Jun 16, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				4:24:32 PM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
10,140 - Check Service Brakes	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
10,160 - FRA Check Instruments and Horns	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
10,170 - Check Fast Idle	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
10,180 - Check Starter Protection Circuit	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
10,190 - Check Reverse Warning System	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
11,100 - Check Parking Brake	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
11,150 - Perform Brake Test	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
11,152 - Decelerometer Results Test 1	FEET	N/A	TDELVA	Jun 16, 2017 4:24:32 PM	No	
11,154 - Decelerometer Results Test 2	FEET	N/A	TDELVA	Jun 16, 2017 4:24:32 PM	No	
11,156 - Decelerometer Results Test 3	FEET	N/A	TDELVA	Jun 16, 2017 4:24:32 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	0 Pounds per Square Inch	N/A	TDELVA	Jun 16, 2017 4:24:32 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	N/A	TDELVA	Jun 16, 2017 4:24:32 PM	No	
11,170 - FRA Check Door Operation	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
20,210 - Check Condition of Operator's Area	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
20,240 - FRA Check Interior Lights	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		TDELVA	Jun 16, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				4:24:32 PM		
20,260 - Check Stop Request System	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	TDELVA	Jun 16, 2017 4:24:32 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
22,110 - Check Emergency Hatches	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
22,120 - Check All Safety Equipment	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
30,310 - Check Passenger Doors	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	TDELVA	Jun 16, 2017 4:24:32 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
30,360 - Check for Physical Damage and Decals	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
30,380 - Check Exterior Compartment Doors	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
33,100 - Check Lights and Reflectors	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
40,420 - Check Hood	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	TDELVA	Jun 16, 2017 4:24:32 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	TDELVA	Jun 16, 2017 4:24:32 PM	No	
40,442 - Freeze Point	Degree	N/A	TDELVA	Jun 16, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			4:24:32 PM		
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	TDELVA	Jun 16, 2017 4:24:32 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	TDELVA	Jun 16, 2017 4:24:32 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
44,130 - FRA Check Exhaust System	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
44,140 - FRA Check Intake System	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	TDELVA	Jun 16, 2017 4:24:32 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
44,180 - FRA Check for Leaks	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
44,190 - FRA Perform Battery Inspection	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
50,510 - Check Entire Steering System	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		TDELVA	Jun 16, 2017 4:24:32 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		TDELVA	Jun 16, 2017 4:24:32 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		TDELVA	Jun 16, 2017 4:24:32 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		TDELVA	Jun 16, 2017 4:24:32 PM	No	
60,615 - Air Pressure LRI	65 Pounds per		TDELVA	Jun 16, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			4:24:32 PM		
60,616 - Air Pressure LRO	65 Pounds per Square Inch		TDELVA	Jun 16, 2017 4:24:32 PM	No	
60,620 - Check Valve Stems and Caps	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
60,630 - Check and Record Tread Depth	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
60,631 - Tread Depth RF	6 32nds of an inch		TDELVA	Jun 16, 2017 4:24:32 PM	No	
60,632 - Tread Depth LF	6 32nds of an inch		TDELVA	Jun 16, 2017 4:24:32 PM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		TDELVA	Jun 16, 2017 4:24:32 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		TDELVA	Jun 16, 2017 4:24:32 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		TDELVA	Jun 16, 2017 4:24:32 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		TDELVA	Jun 16, 2017 4:24:32 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
60,650 - Check Sidewall Wear	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
60,660 - Inspect for Cuts and Tears	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	TDELVA	Jun 16, 2017 4:24:32 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
70,710 - Check Vibration Damper	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
70,730 - FRA Check Starter	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
70,770 - FRA Check Exhaust System	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
70,790 - Check All Body Mounts and Chassis	Done		TDELVA	Jun 16, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Frame				4:24:32 PM		
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
77,110 - FRA Check Fuel Tank	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
77,120 - Check Suspension Components	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
77,131 - Brake Pad Thickness LF	Inch	9mm	TDELVA	Jun 16, 2017 4:24:32 PM	No	
77,132 - Brake Pad Thickness RF	Inch	9mm	TDELVA	Jun 16, 2017 4:24:32 PM	No	
77,133 - Brake Pad Thickness LR	0 Inch	10mm	TDELVA	Jun 16, 2017 4:24:32 PM	No	
77,134 - Brake Pad Thickness RR	Inch	10mm	TDELVA	Jun 16, 2017 4:24:32 PM	No	
77,135 - Brake Rotor LF	Inch	39mm	TDELVA	Jun 16, 2017 4:24:32 PM	No	
77,136 - Brake Rotor RF	Inch	39mm	TDELVA	Jun 16, 2017 4:24:32 PM	No	
77,137 - Brake Rotor LR	Inch	39mm	TDELVA	Jun 16, 2017 4:24:32 PM	No	
77,138 - Brake Rotor RR	Inch	39mm	TDELVA	Jun 16, 2017 4:24:32 PM	No	
77,140 - FRA Check Brake Hoses	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
77,150 - Check King Pins	-	N/A	TDELVA	Jun 16, 2017 4:24:32 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
80,810 - Completion of PMI Report	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		TDELVA	Jun 16, 2017 4:24:32 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	4.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 34835360
Invoice No. 55345 - 34835360

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 67,648 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Jun-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jun-17	Delva,Terry	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: TDELVA Performed on: 16-JUN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		TDELVA	Jun 16, 2017 4:24:11 PM	No	
101,000 - FRA Change Oil Filters	Yes		TDELVA	Jun 16, 2017 4:24:11 PM	No	
102,000 - FRA Drain Engine Oil	Yes		TDELVA	Jun 16, 2017 4:24:11 PM	No	
103,000 - FRA Check Transmission Fluid	Done		TDELVA	Jun 16, 2017 4:24:11 PM	No	
104,000 - Lubricate Chassis	Done		TDELVA	Jun 16, 2017 4:24:11 PM	No	
105,000 - Replace or Clean A/C Filters	Done		TDELVA	Jun 16, 2017 4:24:11 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		TDELVA	Jun 16, 2017 4:24:11 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		TDELVA	Jun 16, 2017 4:24:11 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.92
	Labor:	0.00
	Labor Hours:	0.50
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 34835360
Invoice No. 55345 - 34835360

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 67,648 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jun-17	Delva,Terry	0.1666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 16-JUN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jun 16, 2017 4:32:00 PM	No	
20 - Miles			TDELVA	Jun 16, 2017 4:32:00 PM	No	
30 - Kilometers			TDELVA	Jun 16, 2017 4:32:00 PM	No	
40 - Hours			TDELVA	Jun 16, 2017 4:32:00 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34835360 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	4.67

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34896570
Invoice No. 55345 - 34896570

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
R/R Tires		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	65,283 - DH

Chronology		
Reported	May 28, 2017 7:25:39 PM	May 28, 2017 7:25:39 PM
Started	May 28, 2017 12:00:00 AM	
Completed	May 28, 2017 7:35:00 PM	May 28, 2017 7:35:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: Tires

CAUSE:both R/R tire worn,

CORRECTION: Swap both R/R Tire 2/32 replace with 6/32 tread depth ,

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-May-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 28-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	May 28, 2017 7:30:09 PM	No	
20 - Miles			DARTHURS	May 28, 2017 7:30:09 PM	No	
30 - Kilometers			DARTHURS	May 28, 2017 7:30:09 PM	No	
40 - Hours			DARTHURS	May 28, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				7:30:09 PM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34896570
Invoice No. 55345 - 34896570

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
R/R Tires		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	65,283 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Both R/R Tire worn
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-May-17	Arthurs,Durvin	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34896570 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 34752187
Invoice No. 55345 - 34752187

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	63,764 - DH

Chronology		
Reported	May 16, 2017 8:04:10 AM	May 16, 2017 8:04:10 AM
Started	May 17, 2017 12:00:00 AM	
Completed	May 17, 2017 11:43:00 PM	May 17, 2017 11:43:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA

CAUSE:Service

CORRECTION:perform pmA service
Oil filter B329 qty 1
Engine oil 5w20 qty 7 qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-May-17	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 17-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	May 17, 2017 10:35:58 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	May 17, 2017 10:35:58 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	May 17, 2017 10:35:58 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	May 17, 2017 10:35:58 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	May 17, 2017 10:35:58 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	na	RGASPARD	May 17, 2017 10:35:58 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	May 17, 2017 10:35:58 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	May 17, 2017 10:35:58 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
40,420 - Check Hood	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	May 17, 2017 10:35:58 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	May 17, 2017 10:35:58 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	May 17, 2017 10:35:58 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	May 17, 2017 10:35:58 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	May 17, 2017 10:35:58 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	May 17, 2017 10:35:58 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	May 17, 2017 10:35:58 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	May 17, 2017 10:35:58 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	May 17, 2017 10:35:58 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	May 17, 2017 10:35:58 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	May 17, 2017 10:35:58 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	May 17, 2017 10:35:58 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
60,631 - Tread Depth RF	6 32nds of an inch		RGASPARD	May 17, 2017 10:35:58 PM	No	
60,632 - Tread Depth LF	7 32nds of an inch		RGASPARD	May 17, 2017 10:35:58 PM	No	
60,633 - Tread Depth RRO	4 32nds of an inch		RGASPARD	May 17, 2017 10:35:58 PM	No	
60,634 - Tread Depth RRI	5 32nds of an inch		RGASPARD	May 17, 2017 10:35:58 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		RGASPARD	May 17, 2017 10:35:58 PM	No	
60,636 - Tread Depth LRO	4 32nds of an inch		RGASPARD	May 17, 2017 10:35:58 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
77,131 - Brake Pad Thickness LF	12 Inch		RGASPARD	May 17, 2017 10:35:58 PM	No	
77,132 - Brake Pad Thickness RF	12 Inch		RGASPARD	May 17, 2017 10:35:58 PM	No	
77,133 - Brake Pad Thickness LR	12 Inch		RGASPARD	May 17, 2017 10:35:58 PM	No	
77,134 - Brake Pad Thickness RR	12 Inch		RGASPARD	May 17, 2017 10:35:58 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	May 17, 2017 10:35:58 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	May 17, 2017 10:35:58 PM	No	
77,137 - Brake Rotor LR	38 Inch		RGASPARD	May 17, 2017 10:35:58 PM	No	
77,138 - Brake Rotor RR	38 Inch		RGASPARD	May 17, 2017 10:35:58 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	May 17, 2017 10:35:58 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	May 17, 2017 10:35:58 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 34752187
Invoice No. 55345 - 34752187

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 63,764 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-May-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-May-17	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 17-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	May 17, 2017 10:36:43 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	May 17, 2017 10:36:43 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	May 17, 2017 10:36:43 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	May 17, 2017 10:36:43 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	May 17, 2017 10:36:43 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	May 17, 2017 10:36:43 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	May 17, 2017 10:36:43 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	May 17, 2017 10:36:43 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.92
	Labor:	0.00
	Labor Hours:	1.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 34752187
Invoice No. 55345 - 34752187

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	63,764 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-May-17	Gaspard,Ronald	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 17-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	May 17, 2017 10:37:10 PM	No	
20 - Miles			RGASPARD	May 17, 2017 10:37:10 PM	No	
30 - Kilometers			RGASPARD	May 17, 2017 10:37:10 PM	No	
40 - Hours			RGASPARD	May 17, 2017 10:37:10 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34752187 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.58

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34801581
Invoice No. 55345 - 34801581

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Wiper arm clip		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	61,414 - DH

Chronology		
Reported	May 1, 2017 11:54:37 AM	May 1, 2017 11:54:37 AM
Started	May 1, 2017 12:00:00 AM	
Completed	May 1, 2017 2:03:00 PM	May 1, 2017 2:03:00 PM
Down Time		

Work Order Notes

Line 10

COMPLAINT:
Preventative maintenance to prevent wiper failure.

CAUSE:
Found that the pressure clip that holds the linkage onto the motor didn't have enough pressure to retain the linkage onto the motor over time. Started a preventative maintenance Campaign fix this issue.

CORRECTION:
Removed the bad pressure clip and installed a new pressure clip and mounted the linkage back onto the wiper motor.

Qty 1 wiper motor/pressure clip E3TZ-17531-A

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 01-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	May 1, 2017 11:59:34 AM	No	
20 - Miles			RAURODRIGUEZ	May 1, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:59:34 AM		
30 - Kilometers			RAURODRIGUEZ	May 1, 2017 11:59:34 AM	No	
40 - Hours			RAURODRIGUEZ	May 1, 2017 11:59:34 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34801581
Invoice No. 55345 - 34801581

Client Department:
Department: 55345M
Work Order Description
Wiper arm clip
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 61,414 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note: Wiper arm clip
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-May-17	E3TZ-17531-A	CLIP, ARM, WPER	1	10.51	10.51

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-May-17	Rodriguez,Raul	0.7166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	10.51
Labor:	0.00
Labor Hours:	0.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**10.51**

Work Order Footer

Work Order 34801581 Total	
Parts:	10.51
Labor:	0.00
Labor Hours:	0.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**10.51**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 34633905
Invoice No. 55345 - 34633905

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM B		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	59,304 - DH

Chronology		
Reported	Apr 11, 2017 9:47:01 AM	Apr 11, 2017 9:47:01 AM
Started	Apr 11, 2017 12:00:00 AM	
Completed	Apr 11, 2017 5:41:00 PM	Apr 11, 2017 5:41:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pm-B Inspection due

CAUSE: mileage

CORRECTION: completed pm-B Inspection. Replace oil and oil filter. Clear all codes. Service crankcase breather

Parts used 6 quarts oil. 5w20. 1 oil filter B329

Activity Header

Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Apr-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Apr-17	Capazzoli,Louis	1	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: LCAPAZZOLI Performed on: 11-APR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
10,100 - Safety Inspection	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
10,140 - Check Service Brakes	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
10,160 - FRA Check Instruments and Horns	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
10,170 - Check Fast Idle	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
10,180 - Check Starter Protection Circuit	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
10,190 - Check Reverse Warning System	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
11,100 - Check Parking Brake	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
11,150 - Perform Brake Test	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
11,152 - Decelerometer Results Test 1	FEET	n/a	LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
11,154 - Decelerometer Results Test 2	FEET	n/a	LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
11,156 - Decelerometer Results Test 3	FEET	n/a	LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
11,170 - FRA Check Door Operation	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
20,210 - Check Condition of Operator's Area	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,240 - FRA Check Interior Lights	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
20,260 - Check Stop Request System	-	n/a	LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
22,110 - Check Emergency Hatches	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
22,120 - Check All Safety Equipment	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
30,310 - Check Passenger Doors	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
30,360 - Check for Physical Damage and Decals	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
30,380 - Check Exterior Compartment Doors	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
33,100 - Check Lights and Reflectors	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
40,420 - Check Hood	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
44,130 - FRA Check Exhaust System	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
44,140 - FRA Check Intake System	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
44,180 - FRA Check for Leaks	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
44,190 - FRA Perform Battery Inspection	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
50,510 - Check Entire Steering System	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,614 - Air Pressure RRI	65 Pounds per Square Inch		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
60,620 - Check Valve Stems and Caps	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
60,630 - Check and Record Tread Depth	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
60,650 - Check Sidewall Wear	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
60,660 - Inspect for Cuts and Tears	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
70,710 - Check Vibration Damper	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
70,730 - FRA Check Starter	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
70,770 - FRA Check Exhaust System	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,780 - Check Driveline, U-joint and Slip Yokes	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
77,110 - FRA Check Fuel Tank	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
77,120 - Check Suspension Components	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
77,131 - Brake Pad Thickness LF	Inch	4 mm Need front brakes	LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	Yes	34752116
77,132 - Brake Pad Thickness RF	Inch	4 mm	LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
77,133 - Brake Pad Thickness LR	Inch	4 mm needs rear brakes	LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	Yes	34752116
77,134 - Brake Pad Thickness RR	Inch	4 mm	LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
77,135 - Brake Rotor LF	Inch	40	LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
77,136 - Brake Rotor RF	Inch	40	LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
77,137 - Brake Rotor LR	Inch	40	LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
77,138 - Brake Rotor RR	Inch	40	LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
77,140 - FRA Check Brake Hoses	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
77,150 - Check King Pins	-	n/a	LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
80,810 - Completion of PMI Report	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		LCAPAZZOLI	Apr 11, 2017 5:40:27 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 34633905
Invoice No. 55345 - 34633905

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 59,304 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Apr-17	Capazzoli,Louis	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: LCAPAZZOLI Performed on: 11-APR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		LCAPAZZOLI	Apr 11, 2017 5:09:46 PM	No	
101,000 - FRA Change Oil Filters	Yes		LCAPAZZOLI	Apr 11, 2017 5:09:46 PM	No	
102,000 - FRA Drain Engine Oil	Yes		LCAPAZZOLI	Apr 11, 2017 5:09:46 PM	No	
103,000 - FRA Check Transmission Fluid	Done		LCAPAZZOLI	Apr 11, 2017 5:09:46 PM	No	
104,000 - Lubricate Chassis	Done		LCAPAZZOLI	Apr 11, 2017 5:09:46 PM	No	
105,000 - Replace or Clean A/C Filters	Done		LCAPAZZOLI	Apr 11, 2017 5:09:46 PM	No	
107,000 - FRA Change Primary Fuel Filter	No		LCAPAZZOLI	Apr 11, 2017 5:09:46 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		LCAPAZZOLI	Apr 11, 2017 5:09:46 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		LCAPAZZOLI	Apr 11, 2017 5:09:46 PM	No	
201,000 - Service Crankcase Breather	Done		LCAPAZZOLI	Apr 11, 2017 5:09:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	No		LCAPAZZOLI	Apr 11, 2017 5:09:46 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		LCAPAZZOLI	Apr 11, 2017 5:09:46 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		LCAPAZZOLI	Apr 11, 2017 5:09:46 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 34633905
Invoice No. 55345 - 34633905

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM B		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	59,304 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Apr-17	Capazzoli,Louis	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 11-APR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Apr 11, 2017 5:10:04 PM	No	
20 - Miles			LCAPAZZOLI	Apr 11, 2017 5:10:04 PM	No	
30 - Kilometers			LCAPAZZOLI	Apr 11, 2017 5:10:04 PM	No	
40 - Hours			LCAPAZZOLI	Apr 11, 2017 5:10:04 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34633905 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.58

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 34752116
Invoice No. 55345 - 34752116

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP---------->needs front brakes and rear brakes
Requested By: LCAPAZZOLI
Created By: LCAPAZZOLI
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 59,304 - DH

Chronology		
Reported	Apr 11, 2017 5:09:03 PM	Apr 11, 2017 5:09:03 PM
Started	Apr 11, 2017 12:00:00 AM	
Completed	Apr 11, 2017 5:40:00 PM	Apr 11, 2017 5:40:00 PM
Down Time		

Work Order Notes

Line 10 Replaced front and rear brakes brakes due to low specs. 4 mm. Torque all tires 140 ft pounds road test torque 2 nd time

Parts used. Front pads. 1 set BRSD 1328. Rear pads 1 set. BRSD 1330

Activity Header
Activity: 10 013/002 REAR BRAKES & DRUMS
Activity Note: 4 mm REPLACE REAR BRAKES
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Apr-17	BRSD-1328	PADS, BRAKE, DISC, FRONT	-1	50.32	-50.32
11-Apr-17	BRSD-1330	PADS, BRAKE, DISC, REAR, FORD SAME AS PFH133020	1	43.15	43.15
11-Apr-17	BRSD-1328	PADS, BRAKE, DISC, FRONT	1	50.32	50.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Apr-17	Capazzoli,Louis	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	43.15
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.15**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 34752116
Invoice No. 55345 - 34752116

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP---------->needs front brakes and rear brakes
Requested By: LCAPAZZOLI
Created By: LCAPAZZOLI
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 59,304 - DH

Activity Header
Activity: 20 013/001 BRAKES & DRUMS, FRONT
Activity Note: 4 mm Need front brakes
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Apr-17	BRSD-1328	PADS, BRAKE, DISC, FRONT	1	50.32	50.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Apr-17	Capazzoli,Louis	0.0833333	0	0
11-Apr-17	Capazzoli,Louis	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	50.32
Labor:	0.00
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**50.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 34752116
Invoice No. 55345 - 34752116

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP---------->needs front brakes and rear brakes
Requested By: LCAPAZZOLI
Created By: LCAPAZZOLI
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 59,304 - DH

Activity Header
Activity: 30 013 BRAKES
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Apr-17	Capazzoli,Louis	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc:
Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 11-APR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Apr 11, 2017 5:13:42 PM	No	
20 - Miles			LCAPAZZOLI	Apr 11, 2017 5:13:42 PM	No	
30 - Kilometers			LCAPAZZOLI	Apr 11, 2017 5:13:42 PM	No	
40 - Hours			LCAPAZZOLI	Apr 11, 2017 5:13:42 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34752116 Total	
Parts:	93.47
Labor:	0.00
Labor Hours:	2.67

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**93.47**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34730759
Invoice No. 55345 - 34730759

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Driver's side mirror arm		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	57,416 - DH

Chronology		
Reported	Mar 28, 2017 1:43:39 PM	Mar 28, 2017 1:43:39 PM
Started	Mar 28, 2017 12:00:00 AM	
Completed	Mar 28, 2017 1:57:00 PM	Mar 28, 2017 1:57:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Loose driver's side mirror

CAUSE:Normal wear

CORRECTION:Driver's side mirror replacement

Driver's side mirror replaced by an updated one

Part used:
One driver's side updated mirror (under warranty).

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 28-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Mar 28, 2017 1:51:09 PM	No	
20 - Miles			FSIMON	Mar 28, 2017 1:51:09 PM	No	
30 - Kilometers			FSIMON	Mar 28, 2017 1:51:09 PM	No	
40 - Hours			FSIMON	Mar 28, 2017 1:51:09 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34730759
Invoice No. 55345 - 34730759

Client Department:
Department: 55345M
Work Order Description
Driver's side mirror arm
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 57,416 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Mar-17	Simon,Fritz	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34730759 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34728680
Invoice No. 55345 - 34728680

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
W/C LIFT INSPECTION		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	57,163 - DH

Chronology		
Reported	Mar 27, 2017 9:50:00 AM	Mar 27, 2017 9:50:00 AM
Started		
Completed	Mar 28, 2017 7:16:00 AM	Mar 28, 2017 7:16:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Lift Inspection

CAUSE:Lift Inspection required

CORRECTION:Lift inspection completion
Lift Inspection performed

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 27-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Mar 27, 2017 3:55:43 PM	No	
20 - Miles			FSIMON	Mar 27, 2017 3:55:43 PM	No	
30 - Kilometers			FSIMON	Mar 27, 2017 3:55:43 PM	No	
40 - Hours			FSIMON	Mar 27, 2017 3:55:43 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34728680
Invoice No. 55345 - 34728680

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
W/C LIFT INSPECTION		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	57,163 - DH

Activity Header
Activity: 15 055/023 LIFT, WHEELCHAIR, PASSENGER
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

15 Desc:
Task: Braun Wheelchair Lift Inspection Performed by: FSIMON Performed on: 28-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Record Lift Model in Notes	Done	NCL954FIB3454HB-2	FSIMON	Mar 28, 2017 10:32:28 AM	No	
200 - Record Serial # in Notes	Done	GA-01042	FSIMON	Mar 28, 2017 10:32:28 AM	No	
300 - Cycle Count	Cycles	2558 cycles	FSIMON	Mar 28, 2017 10:32:28 AM	No	
10,000 - A - GENERAL INSPECTION	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
10,100 - Lift Battery, Circuit Breaker & Cable	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
10,200 - Lift Ground & Secondary Ground	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
10,300 - Vehicle Interlock Power	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
10,400 - Vehicle Interlock Prohits Vehicle Movement	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
10,500 - Lift Door Condition	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
10,600 - Hand Pendant Codition/Function	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
10,700 - Inspect Mounting Components	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,000 - B - CYCLE CHECK	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
20,100 - General Operation Throug Comple Cycle	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
20,200 - Main, Handrail, OB & IB Bumper Adjustments	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
20,300 - Floor Level Adjustment	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
20,400 - Platform Angle Adjustment	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
20,500 - Outer Barrier Interlock	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
20,600 - Inner Barrier Interlock	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
20,700 - Threshold Warning Interlock	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
20,800 - 50 Pound Fold Interlock	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
20,900 - Platform Lights	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
21,000 - Anti-Skid	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
21,100 - Operation & Warning Decals	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
21,200 - Back Pump Handdle Location	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
21,300 - Manual Override/Back-up System Function	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
30,000 - C - MECHANICAL COMPONENTS	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
30,100 - Base Plate, Tower, Arm & Platform Welds	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
30,200 - Outer Barrier Pins, Gas Springs & Fasteners	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
30,300 - Inner Barrier Pins, Gas Springs & Fasteners	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
30,400 - Pivot Pin Fasteners	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
30,500 - Pivot Pins & Bushing Condition	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
30,600 - Handrails	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
30,700 - Lift-Tite System	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
40,000 - D - HYDRAULIC COMPONENT CHECKS	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
40,100 - Leaks	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
40,200 - Hoses & Harness Routing/Condition (pump,parallel-vertical arms,platform)	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
40,300 - Remove Pump Cover & Check Fluid Level	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,400 - Fluid Condition	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
40,500 - LiftPump Motor Cables/Connections	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	
40,600 - Lift Pump Harnesses/Fuses/Electrical Components	Done		FSIMON	Mar 28, 2017 10:32:28 AM	No	

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34728680 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34659640
Invoice No. 55345 - 34659640

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Front A/C		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	55,532 - DH

Chronology		
Reported	Mar 10, 2017 10:08:33 AM	Mar 10, 2017 10:08:33 AM
Started	Mar 10, 2017 12:00:00 AM	
Completed	Mar 13, 2017 8:44:00 AM	Mar 13, 2017 8:44:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Front A/C not blowing cold

CAUSE:Leaky Evaporator

CORRECTION:Evaporator replacement

Complaint verified
Visual inspection performed
Front Evaporator found leaking
Evaporator replaced
Vacuum and leak test performed,oil added and recharge completed.
Front A/C blowing cold

Parts used:
One (1) evaporator#YK-211
One (1) orifice tube #YG380
One (1)battery bloc terminal#3940905

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: FSIMON Performed on: 10-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Mar 10, 2017 2:32:56 PM	No	
20 - Miles			FSIMON	Mar 10, 2017 2:32:56 PM	No	
30 - Kilometers			FSIMON	Mar 10, 2017 2:32:56 PM	No	
40 - Hours			FSIMON	Mar 10, 2017 2:32:56 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34659640
Invoice No. 55345 - 34659640

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Front A/C		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	55,532 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Mar-17	YK211	CORE, EVAPORATOR, A/C	1	150.45	150.45
10-Mar-17	3940905	BLOCK, TERMINAL, BATTERY	1	13.72	13.72
10-Mar-17	YG-380	TUBE, ORIFICE, A/C	1	4.36	4.36

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Mar-17	Simon,Fritz	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	168.53
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**168.53**

Work Order Footer

Work Order 34659640 Total	
Parts:	168.53
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**168.53**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 33053747
Invoice No. 55345 - 33053747

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	55,206 - DH

Chronology		
Reported	Mar 2, 2017 10:08:16 AM	Mar 2, 2017 10:08:16 AM
Started	Mar 2, 2017 12:00:00 AM	
Completed	Mar 2, 2017 6:58:00 PM	Mar 2, 2017 6:58:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA Service

CAUSE:Service Due By Mileage

CORRECTION: Change Oil & Filter Lube all Pivoting Points Check Brakes Replace lift handle stop rubber ,replace Air filter, Replace L/Front clearance Light,
Lift arm stop rubber Qty (2) shop supply
Clearance Light Qty (1) Shop Supply,
Parts# B329 Qty (1)
Parts# PA 4075 Qty (1)

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Mar-17	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 02-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
10,110 - FRA Check Drivers Pre-trip or	Done		DARTHURS	Mar 2, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
DVIR/EVIR & Authorization Forms				6:47:41 PM		
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Mar 2, 2017 6:47:41 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Mar 2, 2017 6:47:41 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
20,260 - Check Stop Request System	-	NA	DARTHURS	Mar 2, 2017 6:47:41 PM	No	
20,270 - Check Fare Box Mounting (If	-	NA	DARTHURS	Mar 2, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Applicable)				6:47:41 PM		
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Mar 2, 2017 6:47:41 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
40,420 - Check Hood	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Mar 2, 2017 6:47:41 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Mar 2, 2017 6:47:41 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Mar 2, 2017 6:47:41 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
40,460 - Record Antifreeze Protection Level	-	NA	DARTHURS	Mar 2, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Using Refractometer				6:47:41 PM		
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Mar 2, 2017 6:47:41 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Mar 2, 2017 6:47:41 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Mar 2, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				6:47:41 PM		
60,630 - Check and Record Tread Depth	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
60,631 - Tread Depth RF	9 32nds of an inch		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
60,633 - Tread Depth RRO	4 32nds of an inch		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
60,634 - Tread Depth RRI	4 32nds of an inch		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
60,635 - Tread Depth LRI	4 32nds of an inch		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
60,636 - Tread Depth LRO	4 32nds of an inch		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Mar 2, 2017 6:47:41 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Mar 2, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				6:47:41 PM		
77,120 - Check Suspension Components	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
77,131 - Brake Pad Thickness LF	6 Inch		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
77,132 - Brake Pad Thickness RF	6 Inch		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
77,135 - Brake Rotor LF	1.568 Inch		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
77,136 - Brake Rotor RF	1.569 Inch		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
77,137 - Brake Rotor LR	1.647 Inch		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
77,138 - Brake Rotor RR	1.647 Inch		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Mar 2, 2017 6:47:41 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Mar 2, 2017 6:47:41 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 33053747
Invoice No. 55345 - 33053747

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 55,206 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Mar-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92
02-Mar-17	PA4075	OUT OF SERVICE DO NOT ORDER FILTER, AIR, PAPER SAME AS AF25590	1	5.18	5.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Mar-17	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 02-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Mar 2, 2017 6:48:27 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Mar 2, 2017 6:48:27 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Mar 2, 2017 6:48:27 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Mar 2, 2017 6:48:27 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Mar 2, 2017 6:48:27 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Mar 2, 2017 6:48:27 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Mar 2, 2017 6:48:27 PM	No	
108,000 - Lube all pivoting	Done		DARTHURS	Mar 2, 2017 6:48:27	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Mechanisms				PM		

Activity Sub Total

Activity 20 Sub Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 33053747
Invoice No. 55345 - 33053747

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	55,206 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Mar-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 02-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Mar 2, 2017 6:48:52 PM	No	
20 - Miles			DARTHURS	Mar 2, 2017 6:48:52 PM	No	
30 - Kilometers			DARTHURS	Mar 2, 2017 6:48:52 PM	No	
40 - Hours			DARTHURS	Mar 2, 2017 6:48:52 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 33053747 Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	2.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**7.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 34632500
Invoice No. 55345 - 34632500

Client Department:
Department: 55345M
Work Order Description
Flat Tire
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 54,999 - DH

Chronology		
Reported	Mar 1, 2017 11:33:46 PM	Mar 1, 2017 11:33:46 PM
Started	Mar 1, 2017 12:00:00 AM	
Completed	Mar 1, 2017 11:45:00 PM	Mar 1, 2017 11:45:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Flat Tire

CAUSE: Nail in Tire&Tire Separated

CORRECTION Remove& Replace R/R inner Tire with Use One tread dept 4/32

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Mar-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 01-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Mar 1, 2017 11:35:05 PM	No	
20 - Miles			DARTHURS	Mar 1, 2017 11:35:05 PM	No	
30 - Kilometers			DARTHURS	Mar 1, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:35:05 PM		
40 - Hours			DARTHURS	Mar 1, 2017 11:35:05 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 34632500
Invoice No. 55345 - 34632500

Client Department:
Department: 55345M
Work Order Description
Flat Tire
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 54,999 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Mar-17	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 34632500
Invoice No. 55345 - 34632500

Client Department:
Department: 55345M
Work Order Description
Flat Tire
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 54,999 - DH

Activity Header
Activity: 20 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Nail intire &Seperated tire
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Mar-17	Arthurs,Durvin	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34632500 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34612941
Invoice No. 55345 - 34612941

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Passenger headlight is out		Ford E450 Champion Challenger	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	54,435 - DH

Chronology		
Reported	Feb 24, 2017 12:12:20 PM	Feb 24, 2017 12:12:20 PM
Started	Feb 24, 2017 12:00:00 AM	
Completed	Feb 24, 2017 2:30:00 PM	Feb 24, 2017 2:30:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT:

CAUSE:

CORRECTION:

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 24-FEB-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Feb 24, 2017 12:14:06 PM	No	
20 - Miles			EDTORRES	Feb 24, 2017 12:14:06 PM	No	
30 - Kilometers			EDTORRES	Feb 24, 2017 12:14:06 PM	No	
40 - Hours			EDTORRES	Feb 24, 2017 12:14:06 PM	No	

Activity Sub Total

	Activity 5 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34612941
Invoice No. 55345 - 34612941

Client Department:
Department: 55345M
Work Order Description
Passenger headlight is out
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 54,435 - DH

Activity Header
Activity: 15 034 LIGHTING SYSTEM
Activity Note: Passenger side headlight is out
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Feb-17	Torres,Edwin	0.4	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34612941 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 32948458
Invoice No. 55345 - 32948458

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
External fuel filter replacement		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	50,754 - DH

Chronology		
Reported	Jan 16, 2017 9:45:09 AM	Jan 16, 2017 9:45:09 AM
Started		
Completed	Feb 8, 2017 1:40:00 PM	Feb 8, 2017 1:40:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: External fuel filter (service)

CAUSE:Preventive maintenance

CORRECTION:External Fuel filter replacement

NB:External fuel filter line bleeding process cannot be performed.
Tank valve stuck open suspected.
Bus must be scheduled for tank valve issues.(under warranty).

Creatives Bus Sales Technician replaced valve and external filter.

Parts used
One (1) fuel tank valve (under warranty).
One (1) fuel filter # P11BB-9155-AB

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 08-FEB-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Feb 8, 2017 10:17:24 AM	No	
20 - Miles			FSIMON	Feb 8, 2017 10:17:24 AM	No	
30 - Kilometers			FSIMON	Feb 8, 2017 10:17:24 AM	No	
40 - Hours			FSIMON	Feb 8, 2017 10:17:24 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 32948458
Invoice No. 55345 - 32948458

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
External fuel filter replacement		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	50,754 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Feb-17	P11BB-9155-AB	FILTER, FUEL, ROUSH NO CROSS	1	78.94	78.94

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	78.94
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**78.94**

Work Order Footer

Work Order 32948458 Total	
Parts:	78.94
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**78.94**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 28446626
Invoice No. 55345 - 28446626

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: LCAPAZZOLI
Created By: LCAPAZZOLI
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 51,254 - DH

Chronology		
Reported	Jan 23, 2017 11:57:54 AM	Jan 23, 2017 11:57:54 AM
Started	Jan 23, 2017 12:00:00 AM	
Completed	Jan 23, 2017 11:54:00 PM	Jan 23, 2017 11:54:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA

CAUSE:service

CORRECTION:perform pmA
Oil filter B329 qty 1
Engine oil 5w20 qty 7 qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jan-17	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 23-JAN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Jan 23, 2017 10:22:27 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Jan 23, 2017 10:22:27 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Jan 23, 2017 10:22:27 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Jan 23, 2017 10:22:27 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
40,420 - Check Hood	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Jan 23, 2017 10:22:27 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Jan 23, 2017 10:22:27 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Jan 23, 2017 10:22:27 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Jan 23, 2017 10:22:27 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Jan 23, 2017 10:22:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Jan 23, 2017 10:22:27 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,631 - Tread Depth RF	9 32nds of an inch		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
60,633 - Tread Depth RRO	9 32nds of an inch		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
77,137 - Brake Rotor LR	32 Inch		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
77,138 - Brake Rotor RR	32 Inch		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Jan 23, 2017 10:22:27 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Jan 23, 2017 10:22:27 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 28446626
Invoice No. 55345 - 28446626

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: LCAPAZZOLI
Created By: LCAPAZZOLI
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 51,254 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Jan-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jan-17	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 23-JAN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jan 23, 2017 10:23:23 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jan 23, 2017 10:23:23 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jan 23, 2017 10:23:23 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jan 23, 2017 10:23:23 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Jan 23, 2017 10:23:23 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jan 23, 2017 10:23:23 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Jan 23, 2017 10:23:23 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jan 23, 2017 10:23:23 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.92
	Labor:	0.00
	Labor Hours:	1.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 28446626
Invoice No. 55345 - 28446626

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	LCAPAZZOLI	**Status:**	40 - Closed (40)
Created By:	LCAPAZZOLI	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	51,254 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jan-17	Gaspard,Ronald	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 23-JAN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jan 23, 2017 10:23:53 PM	No	
20 - Miles			RGASPARD	Jan 23, 2017 10:23:53 PM	No	
30 - Kilometers			RGASPARD	Jan 23, 2017 10:23:53 PM	No	
40 - Hours			RGASPARD	Jan 23, 2017 10:23:53 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 28446626 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.58

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 32899335
Invoice No. 55345 - 32899335

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Flat tires		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	50,114 - DH

Chronology		
Reported	Jan 5, 2017 9:21:14 AM	Jan 5, 2017 9:21:14 AM
Started	Jan 5, 2017 12:00:00 AM	
Completed	Jan 5, 2017 3:57:12 PM	Jan 5, 2017 3:57:12 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Left rear flat tires

CAUSE:Tire punctured

CORRECTION:Tires replacement and rotation

Complaint verified
Front tires rotated to the left rear side
Two (2) new tires installed in the front
Rims cleaned

Parts used:
Two(2) tires 225/75R16 #050017

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 05-JAN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal	Done		FSIMON	Jan 5, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				9:41:25 AM		
20 - Miles			FSIMON	Jan 5, 2017 9:41:25 AM	No	
30 - Kilometers			FSIMON	Jan 5, 2017 9:41:25 AM	No	
40 - Hours			FSIMON	Jan 5, 2017 9:41:25 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 32899335
Invoice No. 55345 - 32899335

Client Department:
Department: 55345M
Work Order Description
Flat tires
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 50,114 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Jan-17	050017	OUT OF SERVICE TIRE, LT225/75R16, KRO5, KENDA	2	89.9	179.8

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jan-17	Simon,Fritz	1.25	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	179.80
Labor:	0.00
Labor Hours:	1.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**179.80**

Work Order Footer

Work Order 32899335 Total	
Parts:	179.80
Labor:	0.00
Labor Hours:	1.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**179.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27515809
Invoice No. 55345 - 27515809

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 47,159 - DH

Chronology		
Reported	Nov 23, 2016 11:42:04 AM	Nov 23, 2016 11:42:04 AM
Started	Nov 23, 2016 12:00:00 AM	
Completed	Nov 23, 2016 6:09:00 PM	Nov 23, 2016 6:09:00 PM
Down Time		

Work Order Notes

Line 10 Complaint . Pm-c inspection due

Cause. mileage

Correction . Completed pm -c inspection. Replace oil and oil filter. Service crank case breather. Clear all active codes

Parts used. 6 quarts oil. 5 w20. 1 oil filter. B329

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Nov-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Nov-16	Capazzoli,Louis	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List						
10 Desc: Light Medium Duty PMI Task: First Transit Light-Medium Duty PMI Performed by: LCAPAZZOLI Performed on: 23-NOV-16						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
10,100 - Safety Inspection	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
10,140 - Check Service Brakes	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
10,160 - FRA Check Instruments and Horns	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
10,170 - Check Fast Idle	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
10,180 - Check Starter Protection Circuit	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
10,190 - Check Reverse Warning System	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
11,100 - Check Parking Brake	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
11,150 - Perform Brake Test	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
11,170 - FRA Check Door Operation	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
20,210 - Check Condition of Operator's Area	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
20,240 - FRA Check Interior Lights	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
20,260 - Check Stop Request System	-	n/a	LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
22,110 - Check Emergency Hatches	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
22,120 - Check All Safety Equipment	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
30,310 - Check Passenger Doors	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
30,360 - Check for Physical Damage and Decals	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
30,380 - Check Exterior Compartment Doors	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
33,100 - Check Lights and Reflectors	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
40,420 - Check Hood	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
44,130 - FRA Check Exhaust System	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
44,140 - FRA Check Intake System	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
44,180 - FRA Check for Leaks	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
44,190 - FRA Perform Battery Inspection	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
50,510 - Check Entire Steering System	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
60,630 - Check and Record Tread Depth	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
60,634 - Tread Depth RRI	4 32nds of an inch		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
60,650 - Check Sidewall Wear	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
60,660 - Inspect for Cuts and Tears	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
70,710 - Check Vibration Damper	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
70,730 - FRA Check Starter	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
70,770 - FRA Check Exhaust System	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
77,120 - Check Suspension Components	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
77,131 - Brake Pad Thickness LF	Inch	10 mm	LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
77,132 - Brake Pad Thickness RF	Inch	10 mm	LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
77,133 - Brake Pad Thickness LR	Inch	10 mm	LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
77,134 - Brake Pad Thickness RR	Inch	10 mm	LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
77,135 - Brake Rotor LF	Inch	40	LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
77,136 - Brake Rotor RF	Inch	40	LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
77,137 - Brake Rotor LR	Inch	40	LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
77,138 - Brake Rotor RR	Inch	40	LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
77,140 - FRA Check Brake Hoses	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
77,150 - Check King Pins	-	n/a	LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
80,810 - Completion of PMI Report	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		LCAPAZZOLI	Nov 23, 2016 3:23:00 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27515809
Invoice No. 55345 - 27515809

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 47,159 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Nov-16	Capazzoli,Louis	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: LCAPAZZOLI Performed on: 23-NOV-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		LCAPAZZOLI	Nov 23, 2016 3:24:32 PM	No	
101,000 - FRA Change Oil Filters	Yes		LCAPAZZOLI	Nov 23, 2016 3:24:32 PM	No	
102,000 - FRA Drain Engine Oil	Yes		LCAPAZZOLI	Nov 23, 2016 3:24:32 PM	No	
103,000 - FRA Check Transmission Fluid	Done		LCAPAZZOLI	Nov 23, 2016 3:24:32 PM	No	
104,000 - Lubricate Chassis	Done		LCAPAZZOLI	Nov 23, 2016 3:24:32 PM	No	
105,000 - Replace or Clean A/C Filters	Done		LCAPAZZOLI	Nov 23, 2016 3:24:32 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	n/a	LCAPAZZOLI	Nov 23, 2016 3:24:32 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		LCAPAZZOLI	Nov 23, 2016 3:24:32 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		LCAPAZZOLI	Nov 23, 2016 3:24:32 PM	No	
201,000 - Service Crankcase Breather	Done		LCAPAZZOLI	Nov 23, 2016 3:24:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	No		LCAPAZZOLI	Nov 23, 2016 3:24:32 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		LCAPAZZOLI	Nov 23, 2016 3:24:32 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		LCAPAZZOLI	Nov 23, 2016 3:24:32 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		LCAPAZZOLI	Nov 23, 2016 3:24:32 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		LCAPAZZOLI	Nov 23, 2016 3:24:32 PM	No	
302,000 - Check Toe-In and Record Reading	-	n/a	LCAPAZZOLI	Nov 23, 2016 3:24:32 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	n/a	LCAPAZZOLI	Nov 23, 2016 3:24:32 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		LCAPAZZOLI	Nov 23, 2016 3:24:32 PM	No	
305,000 - FRA Change Differential Fluid	No		LCAPAZZOLI	Nov 23, 2016 3:24:32 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27515809
Invoice No. 55345 - 27515809

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM C		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	47,159 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Nov-16	Capazzoli,Louis	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 23-NOV-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Nov 23, 2016 3:24:48 PM	No	
20 - Miles			LCAPAZZOLI	Nov 23, 2016 3:24:48 PM	No	
30 - Kilometers			LCAPAZZOLI	Nov 23, 2016 3:24:48 PM	No	
40 - Hours			LCAPAZZOLI	Nov 23, 2016 3:24:48 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27515809 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.08

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27390494
Invoice No. 55345 - 27390494

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 42,928 - DH

Chronology		
Reported	Oct 3, 2016 2:23:58 PM	Oct 3, 2016 2:23:58 PM
Started	Oct 3, 2016 12:00:00 AM	
Completed	Oct 3, 2016 8:26:00 PM	Oct 3, 2016 8:26:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA

CAUSE: preventive maintenance

CORRECTION:perform service lube all pivoting points and cross rotate front tires completed
Parts #B329 oil filter qty 1
Oil 5w20 qts 6

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Oct-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Oct-16	Pierre,Hubert J	4	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 03-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
10,100 - Safety Inspection	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1400 Pounds per Square Inch	N/A	HPIERRE	Oct 3, 2016 6:50:04 PM	No	
11,162 - FRA Check/Record Water Temperature	90 Degree Fahrenheit	N/A	HPIERRE	Oct 3, 2016 6:50:04 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Oct 3, 2016 6:50:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Oct 3, 2016 6:50:04 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Oct 3, 2016 6:50:04 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
40,420 - Check Hood	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Oct 3, 2016 6:50:04 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Oct 3, 2016 6:50:04 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Oct 3, 2016 6:50:04 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Oct 3, 2016 6:50:04 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Oct 3, 2016 6:50:04 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Oct 3, 2016 6:50:04 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Oct 3, 2016 6:50:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
60,631 - Tread Depth RF	7 32nds of an inch		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
60,632 - Tread Depth LF	7 32nds of an inch		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
60,633 - Tread Depth RRO	10 32nds of an inch		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
60,635 - Tread Depth LRI	10 32nds of an inch		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
60,636 - Tread Depth LRO	10 32nds of an inch		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Oct 3, 2016 6:50:04 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
77,131 - Brake Pad Thickness LF	9 Inch		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
77,132 - Brake Pad Thickness RF	9 Inch		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
77,135 - Brake Rotor LF	1.7 Inch		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
77,136 - Brake Rotor RF	1.7 Inch		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
77,137 - Brake Rotor LR	1.8 Inch		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
77,138 - Brake Rotor RR	1.8 Inch		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Oct 3, 2016 6:50:04 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Oct 3, 2016 6:50:04 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	4.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27390494
Invoice No. 55345 - 27390494

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 42,928 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Oct-16	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 03-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Oct 3, 2016 6:50:43 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Oct 3, 2016 6:50:43 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Oct 3, 2016 6:50:43 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Oct 3, 2016 6:50:43 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Oct 3, 2016 6:50:43 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Oct 3, 2016 6:50:43 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Oct 3, 2016 6:50:43 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Oct 3, 2016 6:50:43 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27390494
Invoice No. 55345 - 27390494

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	42,928 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Oct-16	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 03-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Oct 3, 2016 6:50:57 PM	No	
20 - Miles			HPIERRE	Oct 3, 2016 6:50:57 PM	No	
30 - Kilometers			HPIERRE	Oct 3, 2016 6:50:57 PM	No	
40 - Hours			HPIERRE	Oct 3, 2016 6:50:57 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27390494 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	4.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27445433
Invoice No. 55345 - 27445433

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Headlight and Front A/C blowing check		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	41,971 - DH

Chronology		
Reported	Sep 16, 2016 11:57:08 AM	Sep 16, 2016 11:57:08 AM
Started	Sep 16, 2016 12:00:00 AM	
Completed	Sep 19, 2016 8:50:00 AM	Sep 19, 2016 8:50:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Right headlight not glowing

CAUSE:Defective Headlight bulb

CORRECTION: Headlight bulb replacement

Complaint verified
Headlight bulb replaced

Part used:
One (1) headlight bulb #9008 Line 20
COMPLAINT:Front A/C not blowing normally

CAUSE:Defective vacuum reservoir

CORRECTION: Vacuum reservoir replacement

Complaint verified
Vacuum reservoir replaced
Front A/C retested (ok)

Parts used:
One (1) vacuum reservoir#YC2Z-19A566-AA
One (1) valve asy #D7OZ-19A563-A

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 16-SEP-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Sep 16, 2016 2:51:34 PM	No	
20 - Miles			FSIMON	Sep 16, 2016 2:51:34 PM	No	
30 - Kilometers			FSIMON	Sep 16, 2016 2:51:34 PM	No	
40 - Hours			FSIMON	Sep 16, 2016 2:51:34 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27445433
Invoice No. 55345 - 27445433

Client Department:
Department: 55345M
Work Order Description
Headlight and Front A/C blowing check
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 41,971 - DH

Activity Header
Activity: 15 034 LIGHTING SYSTEM
Activity Note: Headlight
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Sep-16	9008	BULB, HEADLAMP, HALOGEN, 12V	1	5.79	5.79

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Sep-16	Simon,Fritz	0.25	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	5.79
Labor:	0.00
Labor Hours:	0.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27445433
Invoice No. 55345 - 27445433

Client Department:
Department: 55345M
Work Order Description
Headlight and Front A/C blowing check
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 41,971 - DH

Activity Header
Activity: 25 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Vacuum reservoir
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Sep-16	YC2Z-19A566-AA	RESERVOIR, VACUUM W/BRACKET	1	25.81	25.81
19-Sep-16	D7OZ-19A563-A	VALVE, SUCTION, A/C	1	4.9	4.9

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Sep-16	Simon,Fritz	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	30.71
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**30.71**

Work Order Footer

Work Order 27445433 Total	
Parts:	36.50
Labor:	0.00
Labor Hours:	1.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**36.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27435108
Invoice No. 55345 - 27435108

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Rear Right Outer tire is flat.		Ford E450 Champion Challenger	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	41,212 - DH

Chronology		
Reported	Sep 9, 2016 4:27:15 AM	Sep 9, 2016 4:27:15 AM
Started	Sep 9, 2016 12:00:00 AM	
Completed	Sep 9, 2016 8:03:00 AM	Sep 9, 2016 8:03:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:
Right rear outer tire is flat

CAUSE:
Unknown.

CORRECTION:
Removed flat tire and replaced tire with a used but in good condition tire that has 6/32 of thread.

No new parts used.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 09-SEP-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Sep 9, 2016 8:01:46 AM	No	
20 - Miles			EDTORRES	Sep 9, 2016 8:01:46 AM	No	
30 - Kilometers			EDTORRES	Sep 9, 2016 8:01:46 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			EDTORRES	Sep 9, 2016 8:01:46 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27435108
Invoice No. 55345 - 27435108

Client Department:
Department: 55345M
Work Order Description
Rear Right Outer tire is flat.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 41,212 - DH

Activity Header
Activity: 15 017 TIRES, TUBES, LINERS & VALVES
Activity Note: Right rear outer tire is flat.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Sep-16	Torres,Edwin	0.85	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27435108 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27169504
Invoice No. 55345 - 27169504

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 38,747 - DH

Chronology		
Reported	Aug 18, 2016 9:28:22 AM	Aug 18, 2016 9:28:22 AM
Started	Aug 18, 2016 12:00:00 AM	
Completed	Aug 18, 2016 11:03:00 PM	Aug 18, 2016 11:03:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:service

CORRECTION:perform pmA service
Oil filter B329 qty1
Engine oil 5w20 qty 7 qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Aug-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Aug-16	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 18-AUG-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Aug 18, 2016 10:34:18 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Aug 18, 2016 10:34:18 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Aug 18, 2016 10:34:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Aug 18, 2016 10:34:18 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Aug 18, 2016 10:34:18 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
40,420 - Check Hood	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Aug 18, 2016 10:34:18 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Aug 18, 2016 10:34:18 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Aug 18, 2016 10:34:18 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Aug 18, 2016 10:34:18 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Aug 18, 2016 10:34:18 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Aug 18, 2016 10:34:18 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	Aug 18, 2016 10:34:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
60,631 - Tread Depth RF	7 32nds of an inch		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
60,634 - Tread Depth RRI	9 32nds of an inch		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
60,635 - Tread Depth LRI	9 32nds of an inch		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
77,135 - Brake Rotor LF	37 Inch		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
77,136 - Brake Rotor RF	37 Inch		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
77,137 - Brake Rotor LR	34 Inch		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
77,138 - Brake Rotor RR	34 Inch		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Aug 18, 2016 10:34:18 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Aug 18, 2016 10:34:18 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27169504
Invoice No. 55345 - 27169504

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	38,747 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Aug-16	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 18-AUG-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Aug 18, 2016 10:35:05 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Aug 18, 2016 10:35:05 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Aug 18, 2016 10:35:05 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Aug 18, 2016 10:35:05 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Aug 18, 2016 10:35:05 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Aug 18, 2016 10:35:05 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Aug 18, 2016 10:35:05 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Aug 18, 2016 10:35:05 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	1.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27169504
Invoice No. 55345 - 27169504

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	38,747 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Aug-16	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 18-AUG-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Aug 18, 2016 10:35:25 PM	No	
20 - Miles			RGASPARD	Aug 18, 2016 10:35:25 PM	No	
30 - Kilometers			RGASPARD	Aug 18, 2016 10:35:25 PM	No	
40 - Hours			RGASPARD	Aug 18, 2016 10:35:25 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27169504 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.57

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27200916
Invoice No. 55345 - 27200916

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Bus check for shutting of		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	35,299 - DH

Chronology		
Reported	Jun 17, 2016 12:33:29 PM	Jun 17, 2016 12:33:29 PM
Started	Jun 17, 2016 12:00:00 AM	
Completed	Jun 17, 2016 2:24:00 PM	Jun 17, 2016 2:24:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Bus shutting of

CAUSE:

CORRECTION:Connections and fuel system pressures check

Complaint cannot be verified
Fuel system pressures within specs
Connections tightened

Road test performed ok
No part used

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 17-JUN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Jun 17, 2016 12:57:45 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			FSIMON	Jun 17, 2016 12:57:45 PM	No	
30 - Kilometers			FSIMON	Jun 17, 2016 12:57:45 PM	No	
40 - Hours			FSIMON	Jun 17, 2016 12:57:45 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27200916
Invoice No. 55345 - 27200916

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Bus check for shutting of		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	35,299 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Jun-16	Simon,Fritz	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27200916 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27076901
Invoice No. 55345 - 27076901

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: DCARTER
Created By: DCARTER
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 34,421 - DH

Chronology		
Reported	Jun 2, 2016 10:41:15 AM	Jun 2, 2016 10:41:15 AM
Started	Jun 2, 2016 12:00:00 AM	
Completed	Jun 3, 2016 7:57:00 AM	Jun 3, 2016 7:57:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pm- B. Due

CAUSE: miles

CORRECTION: Completed pm- B inspection

Replace oil and oil filter. Service crankcase breather. Clear all codes

Parts used 6 quarts oil 5 w-20. 1 oil filter B-329

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Jun-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jun-16	Capazzoli,Louis	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: LCAPAZZOLI Performed on: 02-JUN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
10,100 - Safety Inspection	Done		LCAPAZZOLI	Jun 2, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:05:14 PM		
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
10,140 - Check Service Brakes	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
10,160 - FRA Check Instruments and Horns	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
10,170 - Check Fast Idle	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
10,180 - Check Starter Protection Circuit	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
10,190 - Check Reverse Warning System	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
11,100 - Check Parking Brake	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
11,150 - Perform Brake Test	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
11,170 - FRA Check Door Operation	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
20,210 - Check Condition of Operator's Area	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
20,240 - FRA Check Interior Lights	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
20,260 - Check Stop Request System	-	n/a	LCAPAZZOLI	Jun 2, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:05:14 PM		
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
22,110 - Check Emergency Hatches	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
22,120 - Check All Safety Equipment	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
30,310 - Check Passenger Doors	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
30,360 - Check for Physical Damage and Decals	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
30,380 - Check Exterior Compartment Doors	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
33,100 - Check Lights and Reflectors	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
40,420 - Check Hood	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
40,450 - FRA Check Coolant Recovery System	Done		LCAPAZZOLI	Jun 2, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Condition & for Leaks				3:05:14 PM		
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
44,130 - FRA Check Exhaust System	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
44,140 - FRA Check Intake System	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
44,180 - FRA Check for Leaks	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
44,190 - FRA Perform Battery Inspection	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
50,510 - Check Entire Steering System	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
60,616 - Air Pressure LRO	70 Pounds per		LCAPAZZOLI	Jun 2, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			3:05:14 PM		
60,620 - Check Valve Stems and Caps	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
60,630 - Check and Record Tread Depth	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
60,650 - Check Sidewall Wear	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
60,660 - Inspect for Cuts and Tears	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
70,710 - Check Vibration Damper	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
70,730 - FRA Check Starter	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
70,770 - FRA Check Exhaust System	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
77,100 - FRA Check Security, Integrity and	Done		LCAPAZZOLI	Jun 2, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Length of Ground Straps				3:05:14 PM		
77,110 - FRA Check Fuel Tank	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
77,120 - Check Suspension Components	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
77,131 - Brake Pad Thickness LF	Inch	12 mm	LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
77,132 - Brake Pad Thickness RF	Inch	12 mm	LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
77,133 - Brake Pad Thickness LR	Inch	12 mm	LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
77,134 - Brake Pad Thickness RR	Inch	12 mm	LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
77,135 - Brake Rotor LF	Inch	40	LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
77,136 - Brake Rotor RF	Inch	40	LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
77,137 - Brake Rotor LR	Inch	40	LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
77,138 - Brake Rotor RR	Inch	40 mm	LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
77,140 - FRA Check Brake Hoses	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
77,150 - Check King Pins	-	n/a	LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
80,810 - Completion of PMI Report	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		LCAPAZZOLI	Jun 2, 2016 3:05:14 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27076901
Invoice No. 55345 - 27076901

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: DCARTER
Created By: DCARTER
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 34,421 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jun-16	Capazzoli,Louis	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: LCAPAZZOLI Performed on: 02-JUN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		LCAPAZZOLI	Jun 2, 2016 3:06:07 PM	No	
101,000 - FRA Change Oil Filters	Yes		LCAPAZZOLI	Jun 2, 2016 3:06:07 PM	No	
102,000 - FRA Drain Engine Oil	Yes		LCAPAZZOLI	Jun 2, 2016 3:06:07 PM	No	
103,000 - FRA Check Transmission Fluid	Done		LCAPAZZOLI	Jun 2, 2016 3:06:07 PM	No	
104,000 - Lubricate Chassis	Done		LCAPAZZOLI	Jun 2, 2016 3:06:07 PM	No	
105,000 - Replace or Clean A/C Filters	Done		LCAPAZZOLI	Jun 2, 2016 3:06:07 PM	No	
107,000 - FRA Change Primary Fuel Filter	No		LCAPAZZOLI	Jun 2, 2016 3:06:07 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		LCAPAZZOLI	Jun 2, 2016 3:06:07 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		LCAPAZZOLI	Jun 2, 2016 3:06:07 PM	No	
201,000 - Service Crankcase Breather	Done		LCAPAZZOLI	Jun 2, 2016 3:06:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	No		LCAPAZZOLI	Jun 2, 2016 3:06:07 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		LCAPAZZOLI	Jun 2, 2016 3:06:07 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		LCAPAZZOLI	Jun 2, 2016 3:06:07 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27076901
Invoice No. 55345 - 27076901

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM B		Ford E450 Champion Challenger	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	34,421 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jun-16	Capazzoli,Louis	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 02-JUN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Jun 2, 2016 3:06:26 PM	No	
20 - Miles			LCAPAZZOLI	Jun 2, 2016 3:06:26 PM	No	
30 - Kilometers			LCAPAZZOLI	Jun 2, 2016 3:06:26 PM	No	
40 - Hours			LCAPAZZOLI	Jun 2, 2016 3:06:26 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27076901 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.08

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27046260
Invoice No. 55345 - 27046260

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 30,131 - DH

Chronology		
Reported	Apr 25, 2016 11:39:32 AM	Apr 25, 2016 11:39:32 AM
Started	Apr 25, 2016 12:00:00 AM	
Completed	Apr 25, 2016 1:34:00 PM	Apr 25, 2016 1:34:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA

CAUSE: preventive maintenance

CORRECTION: perform service,lube all pivoting point and cross rotate front tires complete
Parts #oil filter B329 qty1
Oil #5w20 qts 6
Marker lights #168# 2
Replace both marker lights too

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Apr-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Apr-16	Pierre,Hubert J	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 25-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,100 - Safety Inspection	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
11,150 - Perform Brake Test	Done	N/A	HPIERRE	Apr 25, 2016 12:52:42 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	0 Pounds per Square Inch	N/A	HPIERRE	Apr 25, 2016 12:52:42 PM	No	
11,162 - FRA Check/Record Water Temperature	0 Degree Fahrenheit	N/A	HPIERRE	Apr 25, 2016 12:52:42 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	N/A	HPIERRE	Apr 25, 2016 12:52:42 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Apr 25, 2016 12:52:42 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Apr 25, 2016 12:52:42 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
40,420 - Check Hood	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Apr 25, 2016 12:52:42 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Apr 25, 2016 12:52:42 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Apr 25, 2016 12:52:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Apr 25, 2016 12:52:42 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Apr 25, 2016 12:52:42 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Apr 25, 2016 12:52:42 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Apr 25, 2016 12:52:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
60,631 - Tread Depth RF	11 32nds of an inch		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
60,632 - Tread Depth LF	11 32nds of an inch		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
60,633 - Tread Depth RRO	9 32nds of an inch		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
60,635 - Tread Depth LRI	9 32nds of an inch		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
60,636 - Tread Depth LRO	9 32nds of an inch		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Apr 25, 2016 12:52:42 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
77,131 - Brake Pad Thickness LF	11 Inch		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
77,132 - Brake Pad Thickness RF	11 Inch		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
77,135 - Brake Rotor LF	40 Inch		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
77,136 - Brake Rotor RF	40 Inch		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
77,137 - Brake Rotor LR	38 Inch		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
77,138 - Brake Rotor RR	38 Inch		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Apr 25, 2016 12:52:42 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Apr 25, 2016 12:52:42 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27046260
Invoice No. 55345 - 27046260

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 30,131 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Apr-16	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 25-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Apr 25, 2016 12:53:28 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Apr 25, 2016 12:53:28 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Apr 25, 2016 12:53:28 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Apr 25, 2016 12:53:28 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Apr 25, 2016 12:53:28 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Apr 25, 2016 12:53:28 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Apr 25, 2016 12:53:28 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Apr 25, 2016 12:53:28 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27046260
Invoice No. 55345 - 27046260

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 30,131 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Apr-16	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 25-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Apr 25, 2016 12:53:45 PM	No	
20 - Miles			HPIERRE	Apr 25, 2016 12:53:45 PM	No	
30 - Kilometers			HPIERRE	Apr 25, 2016 12:53:45 PM	No	
40 - Hours			HPIERRE	Apr 25, 2016 12:53:45 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27046260 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26717678
Invoice No. 55345 - 26717678

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 28,760 - DH

Chronology		
Reported	Apr 11, 2016 9:03:43 AM	Apr 11, 2016 9:03:43 AM
Started	Apr 11, 2016 12:00:00 AM	
Completed	Apr 11, 2016 2:31:00 PM	Apr 11, 2016 2:31:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA

CAUSE:preventive maintenance

CORRECTION: perform service,all pivoting point cross rotate front tires and replace air filter complete
Parts #oil filter B329 qty1
Oil#5w20 qts6
Air filter # pa4075qty 1

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Apr-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92
11-Apr-16	PA4075	OUT OF SERVICE DO NOT ORDER FILTER, AIR, PAPER SAME AS AF25590	1	5.18	5.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Apr-16	Pierre,Hubert J	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 11-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,100 - Safety Inspection	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	N/A	HPIERRE	Apr 11, 2016 12:30:51 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	N/A	HPIERRE	Apr 11, 2016 12:30:51 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	N/A	HPIERRE	Apr 11, 2016 12:30:51 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Apr 11, 2016 12:30:51 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Apr 11, 2016 12:30:51 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
40,420 - Check Hood	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Apr 11, 2016 12:30:51 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Apr 11, 2016 12:30:51 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Apr 11, 2016 12:30:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Apr 11, 2016 12:30:51 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Apr 11, 2016 12:30:51 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Apr 11, 2016 12:30:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
60,631 - Tread Depth RF	12 32nds of an inch		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
60,633 - Tread Depth RRO	11 32nds of an inch		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
60,634 - Tread Depth RRI	11 32nds of an inch		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
60,635 - Tread Depth LRI	11 32nds of an inch		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
60,636 - Tread Depth LRO	11 32nds of an inch		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Apr 11, 2016 12:30:51 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
77,131 - Brake Pad Thickness LF	4 Inch		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
77,132 - Brake Pad Thickness RF	4 Inch	need front brake pads	HPIERRE	Apr 11, 2016 12:30:51 PM	No	
77,133 - Brake Pad Thickness LR	5 Inch		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
77,134 - Brake Pad Thickness RR	4 Inch	need brake pads	HPIERRE	Apr 11, 2016 12:30:51 PM	No	
77,135 - Brake Rotor LF	1.8 Inch		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
77,136 - Brake Rotor RF	1.8 Inch		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
77,137 - Brake Rotor LR	1.6 Inch		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
77,138 - Brake Rotor RR	1.6 Inch		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Apr 11, 2016 12:30:51 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Apr 11, 2016 12:30:51 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26717678
Invoice No. 55345 - 26717678

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 28,760 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Apr-16	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 11-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Apr 11, 2016 12:31:34 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Apr 11, 2016 12:31:34 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Apr 11, 2016 12:31:34 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Apr 11, 2016 12:31:34 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Apr 11, 2016 12:31:34 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Apr 11, 2016 12:31:34 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Apr 11, 2016 12:31:34 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Apr 11, 2016 12:31:34 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26717678
Invoice No. 55345 - 26717678

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	28,760 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Apr-16	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 11-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Apr 11, 2016 12:31:54 PM	No	
20 - Miles			HPIERRE	Apr 11, 2016 12:31:54 PM	No	
30 - Kilometers			HPIERRE	Apr 11, 2016 12:31:54 PM	No	
40 - Hours			HPIERRE	Apr 11, 2016 12:31:54 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26717678 Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	2.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**7.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27046042
Invoice No. 55345 - 27046042

Client Department:
Department: 55345M
Work Order Description
PMA follow up ---------->bus need front brake and rear brake pads
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 28,760 - DH

Chronology		
Reported	Apr 11, 2016 12:38:34 PM	Apr 11, 2016 12:38:34 PM
Started	Apr 11, 2016 12:00:00 AM	
Completed	Apr 11, 2016 2:13:00 PM	Apr 11, 2016 2:13:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: bus need front brake and rear brake pads

CAUSE:below spect 4 mmm left on both

CORRECTION: replace front brake and rear brake torque driver and re- torque to 140 ft pounds complete
Parts #rear brake pads 1330Qty1
Front brake pad 1328 qty 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Apr-16	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 11-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Apr 11, 2016 2:12:18 PM	No	
20 - Miles			HPIERRE	Apr 11, 2016 2:12:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30 - Kilometers			HPIERRE	Apr 11, 2016 2:12:18 PM	No	
40 - Hours			HPIERRE	Apr 11, 2016 2:12:18 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27046042
Invoice No. 55345 - 27046042

Client Department:
Department: 55345M
Work Order Description
PMA follow up ---------->bus need front brake and rear brake pads
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 28,760 - DH

Activity Header
Activity: 15 013 BRAKES
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Apr-16	BRSD-1330	PADS, BRAKE, DISC, REAR, FORD SAME AS PFH133020	1	43.15	43.15
12-Apr-16	BRSD-1328	PADS, BRAKE, DISC, FRONT	1	50.32	50.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Apr-16	Pierre,Hubert J	3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	93.47
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**93.47**

Work Order Footer

Work Order 27046042 Total	
Parts:	93.47
Labor:	0.00
Labor Hours:	3.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**93.47**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27002680
Invoice No. 55345 - 27002680

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Bus need rear bumper sensor and	Wheel chair door shock	Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	26,812 - DH

Chronology		
Reported	Mar 14, 2016 3:09:52 PM	Mar 14, 2016 3:09:52 PM
Started	Mar 14, 2016 12:00:00 AM	
Completed	Mar 14, 2016 5:05:00 PM	Mar 14, 2016 5:05:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: check wheelchair door shock and rear bumper sensors

CAUSE:wheelchair shock and sensors are bad

CORRECTION: replace two rear bumper sensors and one wheelchair door shock completed
Parts# rear bumper sensors N02900102AXA qty 2
Wheelchair shock#1

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Mar-16	Pierre,Hubert J	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 14-MAR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Mar 14, 2016 3:13:41 PM	No	
20 - Miles			HPIERRE	Mar 14, 2016 3:13:41 PM	No	
30 - Kilometers			HPIERRE	Mar 14, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:13:41 PM		
40 - Hours			HPIERRE	Mar 14, 2016 3:13:41 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27002680
Invoice No. 55345 - 27002680

Client Department:
Department: 55345M
Work Order Description
Bus need rear bumper sensor and Wheel chair door shock
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 26,812 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Mar-16	(N)02900102AXA	OUT OF SERVICE SENSOR, BUMPER	2	99.68	199.36
03-May-16	1016426	STRUT, GAS, DOOR	-1	27.38	-27.38
03-May-16	1016426	STRUT, GAS, DOOR	1	27.38	27.38
15-Mar-16	1016426	STRUT, GAS, DOOR	1	27.38	27.38

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Mar-16	Pierre,Hubert J	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	226.74
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**226.74**

Work Order Footer

Work Order 27002680 Total	
Parts:	226.74
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**226.74**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26790107
Invoice No. 55345 - 26790107

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Fuel gauge check		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	24,693 - DH

Chronology		
Reported	Jan 13, 2016 3:51:07 PM	Jan 13, 2016 3:51:07 PM
Started	Jan 13, 2016 12:00:00 AM	
Completed	Jan 18, 2016 11:07:37 AM	Jan 18, 2016 11:07:37 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further

Complaint: Fuel gauge issues

CAUSE:Bad connections

CORRECTION:Fuel system bad connections

Complaint verified
All connectors cleaned,lubricated and tightened
Road test performed ok
Bus returned to its spot for utilization

No parts used

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Jan-16	Simon,Fritz	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	-				No	
20 - Miles					No	
30 - Kilometers					No	
40 - Hours					No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26790107
Invoice No. 55345 - 26790107

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Fuel gauge check		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	24,693 - DH

Activity Header
Activity: 15 044 FUEL SYSTEM
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26790107 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26506923
Invoice No. 55345 - 26506923

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM C		Ford E450 Champion Challenger	
Requested By:	LCAPAZZOLI	**Status:**	40 - Closed (40)
Created By:	LCAPAZZOLI	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	24,462 - DH

Chronology		
Reported	Dec 21, 2015 2:42:50 PM	Dec 21, 2015 2:42:50 PM
Started		
Completed	Dec 21, 2015 5:59:00 PM	Dec 21, 2015 5:59:00 PM
Down Time		

Work Order Notes

Line 10 PMA
Regular maintenance

Perform service lube all pivoting point and cross rotate front tires completed
Parts # oil filter B329 qty1
Oil 5w20 qt 6

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Dec-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92
22-Dec-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	-1	1.92	-1.92

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 21-DEC-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
10,100 - Safety Inspection	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
10,110 - FRA Check Drivers Pre-trip or	Done		HPIERRE	Dec 21, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
DVIR/EVIR & Authorization Forms				5:59:12 PM		
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	N/A	HPIERRE	Dec 21, 2015 5:59:12 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	N/A	HPIERRE	Dec 21, 2015 5:59:12 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Dec 21, 2015 5:59:12 PM	No	
20,270 - Check Fare Box Mounting (If	-	N/A	HPIERRE	Dec 21, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Applicable)				5:59:12 PM		
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Dec 21, 2015 5:59:12 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
40,420 - Check Hood	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Dec 21, 2015 5:59:12 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Dec 21, 2015 5:59:12 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Dec 21, 2015 5:59:12 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
40,460 - Record Antifreeze Protection Level	Done		HPIERRE	Dec 21, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Using Refractometer				5:59:12 PM		
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Dec 21, 2015 5:59:12 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Dec 21, 2015 5:59:12 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Dec 21, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				5:59:12 PM		
60,630 - Check and Record Tread Depth	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
60,631 - Tread Depth RF	14 32nds of an inch		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
60,632 - Tread Depth LF	14 32nds of an inch		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
60,633 - Tread Depth RRO	13 32nds of an inch		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
60,634 - Tread Depth RRI	13 32nds of an inch		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
60,635 - Tread Depth LRI	13 32nds of an inch		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
60,636 - Tread Depth LRO	13 32nds of an inch		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Dec 21, 2015 5:59:12 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Dec 21, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				5:59:12 PM		
77,120 - Check Suspension Components	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
77,135 - Brake Rotor LF	40 Inch		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
77,136 - Brake Rotor RF	40 Inch		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
77,137 - Brake Rotor LR	38 Inch		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
77,138 - Brake Rotor RR	38 Inch		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Dec 21, 2015 5:59:12 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Dec 21, 2015 5:59:12 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26506923
Invoice No. 55345 - 26506923

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: LCAPAZZOLI
Created By: LCAPAZZOLI
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 24,462 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: HPIERRE Performed on: 21-DEC-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Dec 21, 2015 4:55:49 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Dec 21, 2015 4:55:49 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Dec 21, 2015 4:55:49 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Dec 21, 2015 4:55:49 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Dec 21, 2015 4:55:49 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Dec 21, 2015 4:55:49 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	N/A	HPIERRE	Dec 21, 2015 4:55:49 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Dec 21, 2015 4:55:49 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		HPIERRE	Dec 21, 2015 4:55:49 PM	No	
201,000 - Service Crankcase Breather	Done		HPIERRE	Dec 21, 2015 4:55:49 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		HPIERRE	Dec 21, 2015 4:55:49 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
204,000 - FRA Change Power Steering Fluid and Filter	No		HPIERRE	Dec 21, 2015 4:55:49 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		HPIERRE	Dec 21, 2015 4:55:49 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		HPIERRE	Dec 21, 2015 4:55:49 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		HPIERRE	Dec 21, 2015 4:55:49 PM	No	
302,000 - Check Toe-In and Record Reading	-	N/A	HPIERRE	Dec 21, 2015 4:55:49 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	N/A	HPIERRE	Dec 21, 2015 4:55:49 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		HPIERRE	Dec 21, 2015 4:55:49 PM	No	
305,000 - FRA Change Differential Fluid	No		HPIERRE	Dec 21, 2015 4:55:49 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26506923
Invoice No. 55345 - 26506923

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM C		Ford E450 Champion Challenger	
Requested By:	LCAPAZZOLI	**Status:**	40 - Closed (40)
Created By:	LCAPAZZOLI	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	24,462 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 21-DEC-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Dec 21, 2015 4:56:08 PM	No	
20 - Miles			HPIERRE	Dec 21, 2015 4:56:08 PM	No	
30 - Kilometers			HPIERRE	Dec 21, 2015 4:56:08 PM	No	
40 - Hours			HPIERRE	Dec 21, 2015 4:56:08 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26506923 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26594282
Invoice No. 55345 - 26594282

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
NEEDED REAR TIRES		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	22,208 - DH

Chronology		
Reported	Nov 16, 2015 9:06:00 AM	Nov 16, 2015 9:06:00 AM
Started	Nov 16, 2015 9:40:00 AM	
Completed	Nov 16, 2015 10:10:00 AM	Nov 16, 2015 10:10:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT: Worn tires

CAUSE:Normal wear.

CORRECTION:Rear tires replacement

Tires visually inspected and gauged
Rear tires found out of specifications
Four(4) rear tires replaced
Rear tires inflated 70ft/lb
Lugs nuts torqued 140 psi
Lugs nuts indicators reinstalled

Parts utilized:
Four (4) tires 225/75R16 #192659

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 16-NOV-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Nov 16, 2015 10:03:54 AM	No	
20 - Miles			FSIMON	Nov 16, 2015 10:03:54 AM	No	
30 - Kilometers			FSIMON	Nov 16, 2015 10:03:54 AM	No	
40 - Hours			FSIMON	Nov 16, 2015 10:03:54 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26594282
Invoice No. 55345 - 26594282

Client Department:
Department: 55345M
Work Order Description
NEEDED REAR TIRES
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 22,208 - DH

Activity Header
Activity: 15 017 TIRES, TUBES, LINERS & VALVES
Activity Note: TIRES
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Nov-15	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	4	116.94	467.76

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Nov-15	Simon,Fritz	0.47	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	467.76
Labor:	0.00
Labor Hours:	0.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**467.76**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26594282
Invoice No. 55345 - 26594282

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
NEEDED REAR TIRES		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	22,208 - DH

Activity Header
Activity: 25 044 FUEL SYSTEM
Activity Note: PROPANE
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:
Line 10 Complaint:Vehicle smelling fuel
Inspection and drive test performed
Complaint cannot be verified
Vehicle returned to its spot.

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Nov-15	Simon,Fritz	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26594282 Total	
Parts:	467.76
Labor:	0.00
Labor Hours:	1.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**467.76**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26555895
Invoice No. 55345 - 26555895

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Fuel gauge check		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	21,442 - DH

Chronology		
Reported	Oct 23, 2015 4:53:11 AM	Oct 23, 2015 4:53:11 AM
Started		
Completed	Oct 26, 2015 9:09:00 AM	Oct 26, 2015 9:09:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT:Fuel gauge not displaying full after being refilled

CAUSE. Fuel electrical circuit parasitic resistance

CORRECTION:Fuel electrical circuit cleaned

Fuel system diagnosed
Driver's complaint verified
Fuel electrical circuit cleaned
Gauge reading ok.

No parts utilized

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 26-OCT-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Oct 26, 2015 8:58:53 AM	No	
20 - Miles			FSIMON	Oct 26, 2015 8:58:53 AM	No	
30 - Kilometers			FSIMON	Oct 26, 2015 8:58:53 AM	No	
40 - Hours			FSIMON	Oct 26, 2015 8:58:53 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26555895
Invoice No. 55345 - 26555895

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
Fuel gauge check		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	21,442 - DH

Activity Header
Activity: 15 044 FUEL SYSTEM
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26555895 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26543495
Invoice No. 55345 - 26543495

Client Department:
Department: 55345M
Work Order Description
Driver complaint of small crack in windshield, low tire tread and lock
Requested By: RMANZINO
Created By: RMANZINO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 20,579 - DH

Chronology		
Reported	Oct 14, 2015 6:37:53 AM	Oct 14, 2015 6:37:53 AM
Started	Oct 14, 2015 12:00:00 AM	
Completed	Oct 14, 2015 9:20:00 AM	Oct 14, 2015 9:20:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT: Driver complaint of small crack in windshield and wheel chair door wont lock

CAUSE: confirmed complaint and found the windshield has already been repaired.
Wheel chair door lock binds.

CORRECTION: no action required for windshield
Wheel chair door lock is a non serviceable item and can not be taken apart to attempt repair.
I lubricated the lock tumbler and attempted to free it many times but could not.
A new door lock will need to be ordered for repair or leave it as is.
Line 20 Inspected all tires and found the front two tires and right rear two tires at or below minimum spec.
Front tires (both 5/32) were removed and installed in the right rear position.
Two new tires were installed in the front.
Set all tires at recommended psi. 65 front, 70 rear.
Torqued lug nuts to 140 ft lbs.
Washed all newly installed wheels.
Test drove then retorqued lug nuts to 140 ft lbs.
Vehicle returned to service. Line 30 192659 (2) qty bridgestone tires

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Oct-15	Manzino,Robert C	0.1666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RMANZINO Performed on: 14-OCT-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RMANZINO	Oct 14, 2015 6:47:12 AM	No	
20 - Miles			RMANZINO	Oct 14, 2015 6:47:12 AM	No	
30 - Kilometers			RMANZINO	Oct 14, 2015 6:47:12 AM	No	
40 - Hours			RMANZINO	Oct 14, 2015 6:47:12 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26543495
Invoice No. 55345 - 26543495

Client Department:
Department: 55345M
Work Order Description
Driver complaint of small crack in windshield, low tire tread and lock
Requested By: RMANZINO
Created By: RMANZINO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 20,579 - DH

Activity Header
Activity: 15 002 CAB & SHEET METAL
Activity Note: Driver complaint of small crack in windshield and wheel chair door wont lock
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Oct-15	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	115.03	230.06

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Oct-15	Manzino,Robert C	0.75	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	230.06
Labor:	0.00
Labor Hours:	0.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**230.06**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26543495
Invoice No. 55345 - 26543495

Client Department:
Department: 55345M
Work Order Description
Driver complaint of small crack in windshield, low tire tread and lock
Requested By: RMANZINO
Created By: RMANZINO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 20,579 - DH

Activity Header
Activity: 25 017 TIRES, TUBES, LINERS & VALVES
Activity Note: Check tire tread depth
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Oct-15	Manzino,Robert C	0.5	0	0
14-Oct-15	Manzino,Robert C	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26543495 Total	
Parts:	230.06
Labor:	0.00
Labor Hours:	2.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**230.06**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26260104
Invoice No. 55345 - 26260104

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RMANZINO
Created By: RMANZINO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 20,198 - DH

Chronology		
Reported	Aug 27, 2015 3:09:36 PM	Aug 27, 2015 3:09:36 PM
Started	Sep 24, 2015 12:00:00 AM	
Completed	Sep 24, 2015 2:09:00 PM	Sep 24, 2015 2:09:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform. Pm. Oil and filter change

CAUSE:

CORRECTION:

Parts used. 6 quarts oil. 5-w20. 1oil filter. B329 Line 20 WAITING FOR MILEAGES TO GET TO PM NEAR TO CLOSE PM

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: LIGHT MEDIUM DUTY PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Sep-15	Capazzoli,Louis	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: LIGHT MEDIUM DUTY PMI
Task: First Transit Light-Medium Duty PMI Performed by: LCAPAZZOLI Performed on: 24-SEP-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
10,100 - Safety Inspection	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
10,110 - FRA Check Drivers Pre-trip or	Done		LCAPAZZOLI	Sep 24, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
DVIR/EVIR & Authorization Forms				2:04:37 PM		
10,120 - FRA Check All Warning Lights and Alarms	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
10,140 - Check Service Brakes	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
10,160 - FRA Check Instruments and Horns	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
10,170 - Check Fast Idle	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
10,180 - Check Starter Protection Circuit	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
10,190 - Check Reverse Warning System	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
11,100 - Check Parking Brake	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
11,150 - Perform Brake Test	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
11,170 - FRA Check Door Operation	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
20,210 - Check Condition of Operator's Area	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
20,240 - FRA Check Interior Lights	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
20,260 - Check Stop Request System	-	n/a	LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
20,270 - Check Fare Box Mounting (If	-	n/a	LCAPAZZOLI	Sep 24, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Applicable)				2:04:37 PM		
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
22,110 - Check Emergency Hatches	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
22,120 - Check All Safety Equipment	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
30,310 - Check Passenger Doors	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
30,360 - Check for Physical Damage and Decals	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
30,380 - Check Exterior Compartment Doors	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
33,100 - Check Lights and Reflectors	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
40,420 - Check Hood	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
40,460 - Record Antifreeze Protection Level	-	n/a	LCAPAZZOLI	Sep 24, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Using Refractometer				2:04:37 PM		
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	-	n/a	LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
44,130 - FRA Check Exhaust System	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
44,140 - FRA Check Intake System	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
44,180 - FRA Check for Leaks	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
44,190 - FRA Perform Battery Inspection	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
50,510 - Check Entire Steering System	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
60,620 - Check Valve Stems and Caps	Done		LCAPAZZOLI	Sep 24, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				2:04:37 PM		
60,630 - Check and Record Tread Depth	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
60,631 - Tread Depth RF	6 32nds of an inch		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
60,632 - Tread Depth LF	5 32nds of an inch		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
60,633 - Tread Depth RRO	4 32nds of an inch		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
60,634 - Tread Depth RRI	4 32nds of an inch		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
60,635 - Tread Depth LRI	4 32nds of an inch		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
60,636 - Tread Depth LRO	4 32nds of an inch		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	-	n/a	LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
60,650 - Check Sidewall Wear	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
60,660 - Inspect for Cuts and Tears	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
70,710 - Check Vibration Damper	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
70,730 - FRA Check Starter	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
70,770 - FRA Check Exhaust System	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
77,110 - FRA Check Fuel Tank	Done		LCAPAZZOLI	Sep 24, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				2:04:37 PM		
77,120 - Check Suspension Components	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
77,135 - Brake Rotor LF	Inch	n/a	LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
77,136 - Brake Rotor RF	Inch	n/a	LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
77,137 - Brake Rotor LR	Inch	n/a	LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
77,138 - Brake Rotor RR	Inch	n/a	LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
77,140 - FRA Check Brake Hoses	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
77,150 - Check King Pins	-	n/a	LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
80,810 - Completion of PMI Report	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		LCAPAZZOLI	Sep 24, 2015 2:04:37 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26260104
Invoice No. 55345 - 26260104

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RMANZINO
Created By: RMANZINO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 20,198 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Sep-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.52	1.52

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: LCAPAZZOLI Performed on: 24-SEP-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		LCAPAZZOLI	Sep 24, 2015 2:06:08 PM	No	
101,000 - FRA Change Oil Filters	Yes		LCAPAZZOLI	Sep 24, 2015 2:06:08 PM	No	
102,000 - FRA Drain Engine Oil	Yes		LCAPAZZOLI	Sep 24, 2015 2:06:08 PM	No	
103,000 - FRA Check Transmission Fluid	Done		LCAPAZZOLI	Sep 24, 2015 2:06:08 PM	No	
104,000 - Lubricate Chassis	Done		LCAPAZZOLI	Sep 24, 2015 2:06:08 PM	No	
105,000 - Replace or Clean A/C Filters	Done		LCAPAZZOLI	Sep 24, 2015 2:06:08 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	LCAPAZZOLI	Sep 24, 2015 2:06:08 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		LCAPAZZOLI	Sep 24, 2015 2:06:08 PM	No	

Activity Sub Total

Activity 20 Sub Total
Parts: 1.52

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.52**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26260104
Invoice No. 55345 - 26260104

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	RMANZINO	**Status:**	40 - Closed (40)
Created By:	RMANZINO	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	20,198 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 24-SEP-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Sep 24, 2015 2:07:42 PM	No	
20 - Miles			LCAPAZZOLI	Sep 24, 2015 2:07:42 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26260104 Total	
Parts:	1.52
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.52**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26068673
Invoice No. 55345 - 26068673

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DCARTER
Created By: DCARTER
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 15,934 - DH

Chronology		
Reported	Aug 13, 2015 9:35:27 AM	Aug 13, 2015 9:35:27 AM
Started	Aug 13, 2015 11:33:00 AM	
Completed	Aug 13, 2015 1:59:00 PM	Aug 13, 2015 1:59:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION: Line 20 B329 oil filter (1) qty

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: light medium duty inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Aug-15	Manzino,Robert C	1.38	0	0
13-Aug-15	Manzino,Robert C	0.47	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: light medium duty inspection
Task: First Transit Light-Medium Duty PMI Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done				No	
10,100 - Safety Inspection	Done				No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done				No	
10,120 - FRA Check All Warning Lights and Alarms	Done				No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,140 - Check Service Brakes	Done				No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done				No	
10,160 - FRA Check Instruments and Horns	Done				No	
10,170 - Check Fast Idle	Done				No	
10,180 - Check Starter Protection Circuit	Done				No	
10,190 - Check Reverse Warning System	Done				No	
11,100 - Check Parking Brake	Done				No	
11,110 - Check HVAC Switches and Other Controls	Done				No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done				No	
11,130 - FRA Check Wiper and Washer Operation	Done				No	
11,140 - Road Test: Check for Proper Operation	Done				No	
11,150 - Perform Brake Test	Done				No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	50 Pounds per Square Inch				No	
11,162 - FRA Check/Record Water Temperature	50 Degree Fahrenheit				No	
11,170 - FRA Check Door Operation	Done				No	
11,180 - FRA Check Operation of All Other Accessories	Done				No	
20,000 - SECTION 2 Interior Circle Inspection	Done				No	
20,210 - Check Condition of Operator's Area	Done				No	
20,220 - Check Accelerator and Brake Pedals	Done				No	
20,230 - FRA Check Wiring Under Dash	Done				No	
20,240 - FRA Check Interior Lights	Done				No	
20,250 - FRA Check Interior Electrical Panels	Done				No	
20,260 - Check Stop Request System	Done	na			No	
20,270 - Check Fare Box Mounting (If Applicable)	Done	na			No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done				No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done				No	
22,100 - Check Emergency Windows and Glass Condition	Done				No	
22,110 - Check Emergency Hatches	Done				No	
22,120 - Check All Safety Equipment	Done				No	
30,000 - SECTION 3 Exterior Circle Inspection	Done				No	
30,310 - Check Passenger Doors	Done				No	
30,320 - Inspect Step-well and Hand Rails	Done				No	
30,330 - Check Wheelchair Lift Operation	Done				No	
30,340 - FRA Check Destination Sign and Run Box	Done	na			No	
30,350 - FRA Inspect Mirror and Mountings	Done				No	
30,360 - Check for Physical Damage and Decals	Done				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30,370 - Check Wiper Blade and Arm Condition	Done				No	
30,380 - Check Exterior Compartment Doors	Done				No	
30,390 - FRA Check Fuel Tank Cap	Done				No	
33,100 - Check Lights and Reflectors	Done				No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done				No	
40,000 - SECTION 4 Engine Compartment Inspection	Done				No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done				No	
40,420 - Check Hood	Done				No	
40,430 - Check Fan, Shroud and Radiator	Done				No	
40,440 - Test Coolant System Using Test Strips and Record Results	Done				No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes				No	
40,442 - Freeze Point	-40 Degree Fahrenheit				No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done				No	
40,460 - Record Antifreeze Protection Level Using Refractometer	Done				No	
40,461 - Refractometer Reading	-40 Degree Fahrenheit				No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done				No	
40,480 - FRA Check Coolant Hose Condition	Done				No	
40,490 - FRA Check Alternator Mount and Condition	Done				No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done				No	
44,110 - FRA Check Master Cylinder Fluid Level	Done				No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done				No	
44,130 - FRA Check Exhaust System	Done				No	
44,140 - FRA Check Intake System	Done				No	
44,150 - FRA Inspect Turbocharger	Done	na			No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done				No	
44,170 - FRA Check All Engine or Belt Driven Components	Done				No	
44,180 - FRA Check for Leaks	Done				No	
44,190 - FRA Perform Battery Inspection	Done				No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done				No	
50,000 - SECTION 5 Steering System Inspection	Done				No	
50,510 - Check Entire Steering System	Done				No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,610 - FRA Check and Record Air Pressure	Done				No	
60,611 - Air Pressure RF	65 Pounds per Square Inch				No	
60,612 - Air Pressure LF	65 Pounds per Square Inch				No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch				No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch				No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch				No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch				No	
60,620 - Check Valve Stems and Caps	Done				No	
60,630 - Check and Record Tread Depth	Done				No	
60,631 - Tread Depth RF	8 32nds of an inch				No	
60,632 - Tread Depth LF	8 32nds of an inch				No	
60,633 - Tread Depth RRO	6 32nds of an inch				No	
60,634 - Tread Depth RRI	5 32nds of an inch				No	
60,635 - Tread Depth LRI	6 32nds of an inch				No	
60,636 - Tread Depth LRO	6 32nds of an inch				No	
60,640 - Check for Mismatched Tread or Casing Design	Done				No	
60,650 - Check Sidewall Wear	Done				No	
60,660 - Inspect for Cuts and Tears	Done				No	
60,670 - Check Dual Mating With Square	Done				No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done				No	
60,690 - Check Tires for Irregular or Alignment Wear	Done				No	
66,100 - FRA Check Outer Hubs for Leaks	Done				No	
70,000 - SECTION 7 Under Vehicle Inspection	Done				No	
70,710 - Check Vibration Damper	Done				No	
70,720 - Check Engine and Transmission Mounts	Done				No	
70,730 - FRA Check Starter	Done				No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done				No	
70,750 - FRA Check Transmission for Leaks	Done				No	
70,760 - FRA Check Differential Breather and Fluid	Done				No	
70,770 - FRA Check Exhaust System	Done				No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done				No	
70,790 - Check All Body Mounts and Chassis Frame	Done				No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done				No	
77,110 - FRA Check Fuel Tank	Done				No	
77,120 - Check Suspension Components	Done				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done				No	
77,131 - Brake Pad Thickness LF	9 Inch	mm			No	
77,132 - Brake Pad Thickness RF	9 Inch	mm			No	
77,133 - Brake Pad Thickness LR	9 Inch	mm			No	
77,134 - Brake Pad Thickness RR	9 Inch	mm			No	
77,135 - Brake Rotor LF	1.5 Inch				No	
77,136 - Brake Rotor RF	1.5 Inch				No	
77,137 - Brake Rotor LR	1.4 Inch				No	
77,138 - Brake Rotor RR	1.4 Inch				No	
77,140 - FRA Check Brake Hoses	Done				No	
77,150 - Check King Pins	Done	na			No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done				No	
80,000 - SECTION 8 PMI Report Completion	Done				No	
80,810 - Completion of PMI Report	Done				No	
90,000 - SECTION 9 Completion of PMI	Done				No	
90,910 - Vehicle Returned to predetermined location	Done				No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26068673
Invoice No. 55345 - 26068673

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DCARTER
Created By: DCARTER
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4515-P
VIN: 1FDFE4FS9EDB17177
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 15,934 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A SERVICE
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Aug-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.26	1.26

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Aug-15	Manzino,Robert C	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A SERVICE
Task: PM A SERVICE Performed by: RMANZINO Performed on: 13-AUG-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RMANZINO	Aug 13, 2015 1:28:40 PM	No	
101,000 - FRA Change Oil Filters	Yes		RMANZINO	Aug 13, 2015 1:28:40 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RMANZINO	Aug 13, 2015 1:28:40 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RMANZINO	Aug 13, 2015 1:28:40 PM	No	
104,000 - Lubricate Chassis	Done		RMANZINO	Aug 13, 2015 1:28:40 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RMANZINO	Aug 13, 2015 1:28:40 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes	na yet	RMANZINO	Aug 13, 2015 1:28:40 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RMANZINO	Aug 13, 2015 1:28:40 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.26
	Labor:	0.00
	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26068673
Invoice No. 55345 - 26068673

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	15,934 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RMANZINO Performed on: 13-AUG-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RMANZINO	Aug 13, 2015 1:56:24 PM	No	
20 - Miles			RMANZINO	Aug 13, 2015 1:56:24 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26068673 Total	
Parts:	1.26
Labor:	0.00
Labor Hours:	2.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 25905941
Invoice No. 55345 - 25905941

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM B		Ford E450 Champion Challenger	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	11,651 - DH

Chronology		
Reported	Jun 16, 2015 12:00:00 AM	Jun 16, 2015 12:00:00 AM
Started	Jun 16, 2015 12:00:00 AM	
Completed	Jun 18, 2015 10:03:33 AM	Jun 18, 2015 10:03:33 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION: Line 20 PM-B SERVICE COMPLETED
REPLACED OIL FILTER
CHANGED ENGINE OIL
WASHER FLUID ADDED

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: PM B INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Jun-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.77	1.77

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jun-15	Gaspard,Ronald	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.77
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00

	Sublet Labor:	0.00
	Activity Sub Total	**1.77**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 25905941
Invoice No. 55345 - 25905941

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM B		Ford E450 Champion Challenger	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	11,651 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B SERVICE
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 25905941
Invoice No. 55345 - 25905941

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM B		Ford E450 Champion Challenger	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	11,651 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 25905941 Total	
Parts:	1.77
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.77**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 25738626
Invoice No. 55345 - 25738626

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	KCONCEPCION	**Status:**	40 - Closed (40)
Created By:	KCONCEPCION	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	7,059 - DH

Chronology		
Reported	Apr 27, 2015 12:00:00 AM	Apr 27, 2015 12:00:00 AM
Started	Apr 27, 2015 12:00:00 AM	
Completed	Apr 28, 2015 10:47:13 AM	Apr 28, 2015 10:47:13 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION: Line 20 REPLACED OIL FILTER. CHANGED ENGINE OIL. WASHER FLUID DOLDED. 2 NEW TIRES.

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: PM A INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Apr-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.71	1.71

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Apr-15	Gaspard,Ronald	3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.71
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.71**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 25738626
Invoice No. 55345 - 25738626

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	KCONCEPCION	**Status:**	40 - Closed (40)
Created By:	KCONCEPCION	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	7,059 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A SERVICE
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 25738626
Invoice No. 55345 - 25738626

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	KCONCEPCION	**Status:**	40 - Closed (40)
Created By:	KCONCEPCION	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	7,059 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 25738626 Total	
Parts:	1.71
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.71**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 24687414
Invoice No. 55345 - 24687414

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	2,465 - DH

Chronology		
Reported	Mar 17, 2015 4:12:56 PM	Mar 17, 2015 4:12:56 PM
Started	Mar 18, 2015 12:00:00 AM	
Completed	Mar 18, 2015 8:31:31 AM	Mar 18, 2015 8:31:31 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION:

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: PM A INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Mar-15	Capazzoli,Louis	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 24687414
Invoice No. 55345 - 24687414

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	2,465 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A SERVICE
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 24687414
Invoice No. 55345 - 24687414

Client Department:			
Department:	55345M	**Equipment No.:**	4515-P
Work Order Description		**VIN:**	1FDFE4FS9EDB17177
PM A		Ford E450 Champion Challenger	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	2,465 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 24687414 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**