

10/17/2025
10:28:31 AM

Palm Beach County Fleet Management Asset Maintenance History
10210385 2019 FORD F150 Pickup, 1/2 Ton

Total Hours: 82.20		Labor: 6,000.60		Parts: 4,352.68		Comm: 1,406.22		Charged: 11759.50	
Work Order: 1910961		Meter: 302				In Date: 10/23/2019		Closed: 10/24/2019	
Problem: pre delivery inspection									
Work Completed				Parts Issued		Quantity			
- pre delivery inspection				Shop Supplies		1.00			
- Shop Supplies									
Hours: 2.00		Comm: 0.00		Labor: 146.00		Parts: 4.00		Total: 150.00	
Work Order: 1910972		Meter: 308				In Date: 10/24/2019		Closed: 10/29/2019	
Problem: Install ignition power for radio .									
Work Completed				Parts Issued		Quantity			
- Fabricate and install ignition power for radio . Install floor mats and steering wheel cover .				Fab Loom-split Poly		20.00			
				Primary Wire		15.00			
- Shop Supplies				Micro Add A Circuit		1.00			
				Ford Triton Pvc Swc		1.00			
				2pc Hd Mat Set Blk		1.00			
				Shop Supplies		1.00			
Hours: 0.50		Comm: 0.00		Labor: 36.50		Parts: 91.59		Total: 128.09	
Work Order: 1911854		Meter: 1187				In Date: 11/15/2019		Closed: 11/25/2019	
Problem: NAIL IN TIRE									
Work Completed				Parts Issued		Quantity			
- Repair tire.				Shop Supplies		1.00			
- Shop Supplies									
Hours: 1.00		Comm: 0.00		Labor: 73.00		Parts: 4.00		Total: 77.00	

10/17/2025
10:28:31 AM

Palm Beach County Fleet Management Asset Maintenance History
10210385 2019 FORD F150 Pickup, 1/2 Ton

Work Order: 1912245 **Meter:** 4570 **In Date:** 11/27/2019 **Closed:** 01/30/2020
Problem: Install two side boxes in truck bed. P.M. service.

Work Completed

- Remove side tool boxes and replace them with front opening boxes .
- P.m. service.
- Replace cabin air filter and clean fresh air intake .
- Rotate and balance all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Side Boxes	2.00
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Air Freshener	1.00
Cabin Air Filter	1.00
Shop Supplies	1.00

Hours: 7.50

Comm: 0.00

Labor: 547.50

Parts: 1,137.00

Total: 1,684.50

Work Order: 2001456 **Meter:** 5253 **In Date:** 02/11/2020 **Closed:** 02/11/2020
Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00

Comm: 9.54

Labor: 0.00

Parts: 0.00

Total: 9.54

Work Order: 2004275 **Meter:** 11062 **In Date:** 04/29/2020 **Closed:** 05/07/2020
Problem: P.M. service.

Work Completed

- P.m. service.
- Balance and rotate all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Shop Supplies	1.00

Hours: 3.00

Comm: 0.00

Labor: 219.00

Parts: 33.73

Total: 252.73

10/17/2025
10:28:31 AM

Palm Beach County Fleet Management Asset Maintenance History
10210385 2019 FORD F150 Pickup, 1/2 Ton

Work Order: 2008659 **Meter:** 17379 **In Date:** 08/28/2020 **Closed:** 09/09/2020
Problem: PM Service, Wipers noisy, Wiper fluid.

Work Completed

- P.m. service.
- Replace cabin air filter and clean fresh air intake .
- Repair left rear tire . Rotate and balance all four tires . Nitrofill all .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Frshner	1.00
Cabin Air Filter	1.00
Shop Supplies	1.00

Hours: 4.50

Comm: 0.00

Labor: 328.50 Parts: 54.13 Total: 382.63

Work Order: 2102531 **Meter:** 26439 **In Date:** 03/05/2021 **Closed:** 03/11/2021
Problem: PM Service, Washer fluid

Work Completed

- Preventive Maint. Service
- Rotate and speed balance all, nitro fill
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 3.00

Comm: 0.00

Labor: 219.00 Parts: 48.78 Total: 267.78

10/17/2025
10:28:31 AM

Palm Beach County Fleet Management Asset Maintenance History
10210385 2019 FORD F150 Pickup, 1/2 Ton

Work Order: 2108809 **Meter:** 32983 **In Date:** 08/13/2021 **Closed:** 08/25/2021
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Balane And Rotate All Tires With Nitro Fill
- R&r Cabin Air Filter And Clean Fresh Air Intake
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
22" Wiper Blade	2.00
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Cabin Filter	1.00
A/fresh	1.00
Shop Supplies	1.00

Hours: 3.50

Comm: 0.00

Labor: 255.50 Parts: 56.21 Total: 311.71

Work Order: 2201057 **Meter:** 40115 **In Date:** 01/28/2022 **Closed:** 02/08/2022
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Rotate and balance tires, correct Nitrogen levels, re learn Tpms.
- Customers complaint right rear tail light is out. Replace lower right rear tail light bulb.
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Oil Filter	1.00
Motor Oil	6.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Boxed Miniatures	1.00
Shop Supplies	1.00

Hours: 3.50

Comm: 0.00

Labor: 255.50 Parts: 69.34 Total: 324.84

10/17/2025
10:28:31 AM

Palm Beach County Fleet Management Asset Maintenance History
10210385 2019 FORD F150 Pickup, 1/2 Ton

Work Order: 2206197 **Meter:** 46810 **In Date:** 06/13/2022 **Closed:** 06/23/2022
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Replace steering wheel cover.
- All 4 tires measure at 4/32nds. Replace all 4 tires below 4/32nds, balance and nitrogen fill tire. Reinstall on vehicle. Reset Tpms.
- C/s brake light comes on. Remove wheels, inspect brake system, scan & found code P059f, P0555 & P0556, perform diagnostic using flow chart & found leaking brake booster vacuum sensor. Replace vacuum sensor, grommet & clear codes.
- Replace how's my driving decal.
- Test drive before & after repair & verify all repairs are complete.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	6.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Steering Wheel Cover Large	1.00
Enr Elect Battery	1.00
245/70/17 Tire Mich	4.00
Brake Grommet	1.00
Sensor Assy	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 7.25

Comm: 0.00

Labor: 529.25

Parts: 911.23

Total: 1,440.48

Work Order: 2209042 **Meter:** 49956 **In Date:** 08/29/2022 **Closed:** 08/29/2022
Problem: Nail in tire

Work Completed

- Repair and balance right front tire.nitrogen fill and reset Tpms.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 2.65

Total: 75.65

10/17/2025
10:28:31 AM

Palm Beach County Fleet Management Asset Maintenance History
10210385 2019 FORD F150 Pickup, 1/2 Ton

Work Order: 2211746 **Meter:** 53395 **In Date:** 11/18/2022 **Closed:** 12/02/2022
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Clean A/c crawlspace & replace cabin air filter.
- Fill all tires with nitrogen, balance, rotate & reset Tpms.
- Replace how's my driving decal.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	6.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Tree Royal Pine 3pk	1.00
Cabin Filter	1.00
Cover Engine	1.00
Shop Supplies	1.00

Hours: 4.00

Comm: 0.00

Labor: 292.00

Parts: 154.89

Total: 446.89

Work Order: 2303524 **Meter:** 59820 **In Date:** 04/07/2023 **Closed:** 04/14/2023
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- clean debris from air cowl system and replaced dirty cabin filter
- rotate balanced 4 tires
- replaced missing how's my driving sticker
- service all three aux tool boxes lube and adjust latches to lock properly
- lock cylinder sticking. diagnose and replaced lock cylinder. re-keyed lock cylinder to fit key. Replaced sticking key tumbler cylinder assembly.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
Cabin Air Filter	1.00
Lock Cylinder Ign	1.00
Shop Supplies	1.00

Hours: 6.25

Comm: 0.00

Labor: 456.25

Parts: 132.68

Total: 588.93

10/17/2025
10:28:31 AM

Palm Beach County Fleet Management Asset Maintenance History
10210385 2019 FORD F150 Pickup, 1/2 Ton

Work Order: 2311372 **Meter:** 68197 **In Date:** 11/14/2023 **Closed:** 11/27/2023
Problem: PM Service. washer fluid.

Work Completed

- Preventive Maint. Service
- rear brake pads below min spec. Remove and replace brake pads with new. Service calipers rotors and brake caliper slides. Test Drive.
- rotate balanced 4 tires
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Non-chlor Brake Clnr	1.00
Permatex	1.00
Brake Pad	1.00
Shop Supplies	1.00

Hours: 5.00

Comm: 0.00

Labor: 365.00

Parts: 154.23

Total: 519.23

Work Order: 2403840 **Meter:** 77700 **In Date:** 04/18/2024 **Closed:** 04/29/2024
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- rotate and balance all 4 tires nitro fill all
- Battery failed load test and a diagnostic charged was performed. Battery was then test but still failed load test. Remove and replace battery reset Bsm using Ids.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
Battery	1.00
Shop Supplies	1.00

Hours: 4.50

Comm: 0.00

Labor: 328.50

Parts: 306.99

Total: 635.49

Work Order: 2404832 **Meter:** 77700 **In Date:** 04/25/2024 **Closed:** 05/14/2024
Problem: Damage-Damage to right door & cab side

Work Completed

- Damage-damage to right door & cab side

Hours: 0.00

Comm: 1,396.68

Labor: 0.00

Parts: 0.00

Total: 1,396.68

10/17/2025
10:28:31 AM

Palm Beach County Fleet Management Asset Maintenance History
10210385 2019 FORD F150 Pickup, 1/2 Ton

Work Order: 2407851 **Meter:** 83371 **In Date:** 08/14/2024 **Closed:** 08/21/2024
Problem: PM Service. Screws in Rear tires

Work Completed

- Performed P.m. Service & Inspection.
- Performed Flat Repair On Both Rear Tires Then Balance & Rotate All 4 Tires Add Nitro Fill Reset Tpms.
- Removed And Replaced Cabin Air Filter, Clean A/c Vents & Removed Debris Then Check.
- Performed Engine Decarb & Fuel Injection Flush Service, Removed Throttle Body & Clean.
- Performed Tune-up, Removed Intake & Replaced All 6 Spark Plugs. Then Test Drive And Check.
- Shop Supplies

Hours: 10.70

Comm: 0.00

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Wiper Blade	2.00
Cabin Air Filter	1.00
Motor Tune-up 16oz	1.00
Intake Cleaner Kit	1.00
Plenum Gskt Set	1.00
Spark Plug	6.00
Shop Supplies	1.00

Labor: 781.10

Parts: 134.54

Total: 915.64

Work Order: 2412227 **Meter:** 89575 **In Date:** 12/30/2024 **Closed:** 01/13/2025
Problem: PM Service

Work Completed

- Preventive Maint. Service
- Mount and balance 4 new tires. Nitrogen filled all tires.
- Performed full front end alignment. Road test
- Shop Supplies

Hours: 6.50

Comm: 0.00

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Wiper Blade	2.00
245/70r17xl Mich Def Ltx	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Labor: 474.50

Parts: 930.76

Total: 1,405.26

10/17/2025
10:28:31 AM

Palm Beach County Fleet Management Asset Maintenance History
10210385 2019 FORD F150 Pickup, 1/2 Ton

Work Order: 2504940 **Meter:** 97196 **In Date:** 05/28/2025 **Closed:** 06/17/2025
Problem: PM Service.

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Inspected Brakes, Front Brake Pads At Minimum Deapth Replace Front Pads, Resurface Rotors, Service And Bleed Calipers Test Drive
- Rotate And Balance Tires With Nitro Fill
- Shop Supplies

Napagold Oil Filter	1.00
Napa Quart 5w20	6.00
Wiper Blade	1.00
Used Fire X Refurbished	1.00
Brake Pad	1.00
Brk Fluid Dot 4-32oz	1.00
White Shepherd Stp Lk	1.00
Shop Supplies	1.00
Labor: 474.50	Parts: 125.94 Total: 600.44

Hours: 6.50 Comm: 0.00

Work Order: 2507816 **Meter:** 100702 **In Date:** 08/20/2025 **Closed:** 08/26/2025
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 82.20 Total Labor: 6,000.60 Total Comm: 1,406.22 Total Parts: 4,352.68