

10/17/2025
10:34:24 AM

Palm Beach County Fleet Management Asset Maintenance History
10210255 2020 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Total Hours: 192.80	Labor: 14,074.40	Parts: 13,878.70	Comm: 2,805.21	Charged: 30758.31
----------------------------	-------------------------	-------------------------	-----------------------	--------------------------

Work Order: 2003459	Meter: 328	In Date: 04/07/2020	Closed: 04/07/2020
Problem: pre delivery inspection			

Work Completed

- pre delivery inspection
- Shop Supplies

Hours: 2.00

Comm: 0.00

Parts Issued

Shop Supplies

Quantity

1.00

Labor: 146.00

Parts: 4.00

Total: 150.00

Work Order: 2003495	Meter: 330	In Date: 04/07/2020	Closed: 04/09/2020
Problem: Install radio ignition power .			

Work Completed

- Fabricate and install ignition power for radio . Install floor mats and steering wheel cover .
- Shop Supplies

Hours: 0.50

Comm: 0.00

Parts Issued

Primary Wire

20.00

Fab Loom-split Poly

10.00

Micro Add A Circuit

1.00

Ford Triton Pvc Swc

1.00

Floormat

1.00

Shop Supplies

1.00

Labor: 36.50

Parts: 85.24

Total: 121.74

Work Order: 2004950	Meter: 3070	In Date: 05/15/2020	Closed: 05/20/2020
Problem: Winch in not working.			

Work Completed

- Diagnose winch inop . Repair loose ground cable . Unwind winch and inspect and rewind all the way in .
- Shop Supplies

Hours: 1.00

Comm: 0.00

Parts Issued

Shop Supplies

Quantity

1.00

Labor: 73.00

Parts: 4.00

Total: 77.00

10/17/2025
10:34:24 AM

Palm Beach County Fleet Management Asset Maintenance History
10210255 2020 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2006378 **Meter:** 5799 **In Date:** 06/26/2020 **Closed:** 06/30/2020
Problem: PM Service, Detail.

Work Completed

- P.m. service.
- Replace missing pintle pin .
- Inspect and service winch .
- Balance and rotate all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Pintle Pin W/clip	1.00
Used Fire X Refurbished	1.00
22" Wiper Blade	2.00
Shop Supplies	1.00

Hours: 4.95

Comm: 0.00

Labor: 361.35

Parts: 61.24

Total: 422.59

Work Order: 2010520 **Meter:** 12002 **In Date:** 10/20/2020 **Closed:** 02/25/2021
Problem: Dist. 4 Steve, bad battery

Work Completed

- Jump start @ roads parking lot, Charge battery fully Test battery, battery failed load test . Replace battery.
- P.m. service.
- Replace two tires, rotate/balance & nitro service all.
- Service winch, Diagnose winch controller unit bad . Replace control unit and retest .
- Shop Supplies

Parts Issued

Quantity

Battery 65	1.00
Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Air Fltr	1.00
Lt 245/75/17titr Mic	2.00
Remote Kit	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00
Freight Charge	1.00

Hours: 7.75

Comm: 0.00

Labor: 565.75

Parts: 873.45

Total: 1,439.20

Work Order: 2011955 **Meter:** 11956 **In Date:** 10/27/2020 **Closed:** 12/01/2020
Problem: Damage to left front fender & driver's door

Work Completed

- Damage to left front fender & driver's door

Hours: 0.00

Comm: 2,136.55

Labor: 0.00

Parts: 0.00

Total: 2,136.55

10/17/2025
10:34:24 AM

Palm Beach County Fleet Management Asset Maintenance History
10210255 2020 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2102734 **Meter:** 16502 **In Date:** 03/10/2021 **Closed:** 03/11/2021
Problem: Dist.1 Terrence, truck has a nail in the rear Rt. tire

Work Completed

- Replace right rear tire and balance due to sidewall damage .
- Shop Supplies

Hours: 0.50

Comm: 0.00

Parts Issued

Quantity

Lt 245/75/17ttr Mic	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Labor: 36.50	Parts: 313.56	Total: 350.06
--------------	---------------	---------------

Work Order: 2104894 **Meter:** 19069 **In Date:** 04/30/2021 **Closed:** 05/06/2021
Problem: PM Service. Truck is over due will turn in today

Work Completed

- Preventive Maint. Service
- Mount Two New Tires; Nitrogen Fill, Rotate And Balance Four.
- R&r Broken Pintel Pin.
- R&r Faulty Winch Control Module And Service Winch.
- Shop Supplies

Hours: 5.95

Comm: 0.00

Parts Issued

Quantity

Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Used Fire X Refurbished	1.00
Lt 245/75/17ttr Mic	2.00
Pintle Pin W/clip	1.00
Steering Wheel Cover Large	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Labor: 434.35	Parts: 709.84	Total: 1,144.19
---------------	---------------	-----------------

10/17/2025
10:34:24 AM

Palm Beach County Fleet Management Asset Maintenance History
10210255 2020 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2109059 **Meter:** 24762 **In Date:** 08/20/2021 **Closed:** 09/10/2021
Problem: PM Service. will turn in today

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- check battery,charging system after fully charge it fails load test,replaced defective batery
- check,replaced cabin a/c filter
- inspect and service winch
- balance and rotate all 4 tires
- check,replaced defective trailer plug and fabricated wires as needed
- check,pin point test sop,replaced bth front defective strobe light by drilled new holes,fabricated wires as needed and verify normal operation
- Shop Supplies

Battery 65	1.00
22" Wiper Blade	2.00
Air Fltr	1.00
Napa Quart 5w30	8.00
Napagold Oil Filter	1.00
Cabin Filter	1.00
trailer plug	1.00
Electrical Tape	1.00
Permatex	1.00
Permatex	1.00
Mnt Conc Led Clear	2.00
Shop Supplies	1.00

Hours: 9.25

Comm: 0.00

Labor: 675.25 Parts: 400.92 Total: 1,076.17

10/17/2025
10:34:24 AM

Palm Beach County Fleet Management Asset Maintenance History
10210255 2020 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2200246 **Meter:** 32719 **In Date:** 01/07/2022 **Closed:** 01/18/2022
Problem: PM Service. will turn in tomorrow

Work Completed

Parts Issued

Quantity

- Performed P.m. Service & Inspection
- Mount 2 Tires Then Balance And Rotate All 4 Wheels, Reset Tpms.
- Performed Front Wheel Alignment. Road Test .
- Performed Service & Inspection On Winch, Removed And Replaced Frayed Winch Cable.
- Removed Front Brake Pads, Resurfaced Both Front Brake Rotors, Lubricate Caliper Slides, Replaced Brake Pads, Then Bleed & Flush Entire Brake System, Test Drove Burnish Brakes.
- Right Alley Light On Light Bar Inop, Dissassemble Light Bar Switch Assembly And Check For B+ & Ground. B+ & Ground Ok Found Switch Defective, Removed And Replaced Then Check. Working As Design.
- Shop Supplies

Motor Oil 5w30	8.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Lt 245/75/17titr Mic	2.00
Brk Fluid Dot 4-32oz	1.00
Non-chlor Brake Clnr	1.00
Brake Pad	1.00
Winch Cable	1.00
Rocker Switch	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 13.75

Comm: 0.00

Labor: 1,003.75 Parts: 1,031.73 Total: 2,035.48

Work Order: 2206166 **Meter:** 40814 **In Date:** 06/10/2022 **Closed:** 06/21/2022
Problem: PM Service. need window shades and detailed will turn in tomorrow

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Install Four New Window Vent Shades.
- Mount Two New Tires; Rotate, Balance Four And Relearn Tire Sensors.
- R&r Broken Pintel Pin.
- Inspect And Service Power Winch.
- Shop Supplies

Napagold Oil Filter	1.00
Napa Quart 5w20	7.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Lt 245/75/17titr Mic	2.00
trailer plug	1.00
Window Vet	1.00
Pintle Pin W/clip	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 6.95

Comm: 0.00

Labor: 507.35 Parts: 627.99 Total: 1,135.34

10/17/2025
10:34:24 AM

Palm Beach County Fleet Management Asset Maintenance History
10210255 2020 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2206433 **Meter:** 40825 **In Date:** 06/15/2022 **Closed:** 06/16/2022
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2206166 for: Ray Hiskell

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2206166 for: Ray Hiskell

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

Work Order: 2208424 **Meter:** 47619 **In Date:** 08/15/2022 **Closed:** 08/18/2022
Problem: commercial tow bill

Work Completed

- Towed By Outside Wrecker

- Shop Supplies

Parts Issued

Quantity

Comercial Towing 1.00

Shop Supplies 1.00

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 214.28 Total: 214.28

Work Order: 2208437 **Meter:** 47673 **In Date:** 08/15/2022 **Closed:** 08/23/2022
Problem: DUE FOR PM

Work Completed

- Preventive Maint. Service

- Rotated and balanced all 4 tires. Nitrogen filled all tires.

- Diagnose no start. Charged battery fully. Tested starting system and battery failed test. Replaced defective battery. Reset Bms.

- Reattached winch cable due to being extended too far. Inspect and serviced winch

- Transport to and from dealer for recall 22s09 and rear pinion seal

- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter 1.00

Napa Quart 5w30 8.00

Washer Fluid Concentr 1.00

22" Wiper Blade 2.00

Battery 1.00

Shop Supplies 1.00

Hours: 8.75 Comm: 0.00 Labor: 638.75 Parts: 200.64 Total: 839.39

Work Order: 2208561 **Meter:** 47619 **In Date:** 08/15/2022 **Closed:** 08/16/2022
Problem: DUE FOR PM

Work Completed

- Tow From: Sisters Towing Compound To: Lv Shop

Hours: 0.00 Comm: 113.00 Labor: 0.00 Parts: 0.00 Total: 113.00

10/17/2025
10:34:24 AM

Palm Beach County Fleet Management Asset Maintenance History
10210255 2020 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2211515 **Meter:** 53900 **In Date:** 11/15/2022 **Closed:** 11/23/2022
Problem: Dist.4 Les, light bar not working

Work Completed

- Diagnose and repair fuse and holder burned out. Replace holder, fuse and rewire.
- Shop Supplies

Hours: 1.00

Comm: 0.00

Parts Issued

Quantity

Electrical Tape	1.00
Fuse Holder	1.00
Shop Supplies	1.00
Labor: 73.00	Parts: 6.64
Total: 79.64	

Work Order: 2212164 **Meter:** 56081 **In Date:** 12/02/2022 **Closed:** 12/14/2022
Problem: PM Service. Dist.4 Poppa and detail

Work Completed

- Performed P.m. Service & Inspection.
- Mount 1 Tire Then Balance & Rotate All 4 Wheels, Add Nitro Fill Reset Tpms.
- Removed & Replaced Cabin Air Fiter, Clean A/c Vents And Check.
- Performed Inspection & Service On Winch, Found Winch Inop, Check Power & Ground. Power & Ground Ok, Found Motor Wire Short To Frame Causing External Damage To Solenoid. Dissassemble & Replaced With Known Good Solenoid.
- All 4 Brake Pads Where Below Manufac Specs. Removed All Front & Rear Brake Calipers And Pads, Resurface All 4 Brake Rotors, Replaced Calipers & Brake Pads, Lubricate Caliper Slide Then Bleed And Flush Entire Brake System, Test Drove & Burnish Brakes.
- Both Light Bar & Strobe Switch Inop, Check Power & Ground, Power Ground Ok. Switch Defective, Removed Then Relaced And Check.
- Shop Supplies

Hours: 16.55

Comm: 0.00

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Lt 245/75/17titr Mic	1.00
Cabin Filter Replaces Fp92	1.00
Caliper Washer	4.00
Non-chlor Brake Clnr	2.00
Brake Fl-dot 3-4 32oz	1.00
Bracketed Caliper	1.00
Bracketed Caliper	1.00
Brake Pads	1.00
Brake Pads	1.00
Led Rocker Switch Round	1.00
Elec Battery A23	1.00
Rocker Switch	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00
Labor: 1,208.15	Parts: 669.62
Total: 1,877.77	

10/17/2025
10:34:24 AM

Palm Beach County Fleet Management Asset Maintenance History
10210255 2020 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2212260 **Meter:** 54891 **In Date:** 12/07/2022 **Closed:** 12/07/2022
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2212164 for: Ray Hiskell

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2212164 for: Ray Hiskell

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

Work Order: 2305288 **Meter:** 67406 **In Date:** 05/26/2023 **Closed:** 06/01/2023
Problem: PM Service

Work Completed

- Preventive Maint. Service
- Mount Two New Tires, Rotate And Balance Four. Relearn Tire Sensors.
- Replace Broken Pintel Pin.
- Complete Front End Alignment And Road Test To Verify Repair.
- Diagnois Engine Misfire .r&r 16 Spark Plugs And Wires For V8 Tune-up. Power Balance Check Cylinders With Scan Tool.
- Perform Fuel Injection Service, Decarb Intake System And Clean Throttle Body. Clear Codes With Scan Tool.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Big G Degreaser 1 Gal	1.00
Steering Wheel Cover Large	1.00
Lt 245/75/17titr Mic	2.00
Pintle Pin W/clip	1.00
Spark Plug Wire	8.00
Spark Plug	16.00
Intake Cleaner Kit	1.00
Motor Tune-up 16oz	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 14.25 Comm: 0.00 Labor: 1,040.25 Parts: 888.89 Total: 1,929.14

Work Order: 2307814 **Meter:** 70844 **In Date:** 08/07/2023 **Closed:** 08/08/2023
Problem: battery

Work Completed

- Charge battery fully . Test battery and charging system . Battery failed load test . R&r defective battery .
- Shop Supplies

Parts Issued

Quantity

Battery	1.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 190.11 Total: 263.11

10/17/2025
10:34:24 AM

Palm Beach County Fleet Management Asset Maintenance History
10210255 2020 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2307958 **Meter:** 71177 **In Date:** 08/09/2023 **Closed:** 08/10/2023
Problem: Towed in for blown front right tire

Work Completed

Parts Issued

Quantity

- Repair right front tire and balance . Nitro fill all .reset Tpms .
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 2.65	Total: 75.65
-------------	------------	--------------	-------------	--------------

Work Order: 2308053 **Meter:** 71354 **In Date:** 08/11/2023 **Closed:** 08/16/2023
Problem: Dist.4 Les wrench cable needs to be rewind, with the work that's is being done on the wrench also needs a detail

Work Completed

Parts Issued

Quantity

- Remove and disassembly wench to remove broken keeper screw and respool and retest .
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 2.65	Total: 148.65
-------------	------------	---------------	-------------	---------------

Work Order: 2309321 **Meter:** 73860 **In Date:** 08/09/2023 **Closed:** 09/13/2023
Problem: blown front left tire

Work Completed

- Tow From: i95 Nb before wolbright on shoulder To: Fleet vista Lv

Hours: 0.00	Comm: 124.30	Labor: 0.00	Parts: 0.00	Total: 124.30
-------------	--------------	-------------	-------------	---------------

Work Order: 2312004 **Meter:** 79781 **In Date:** 12/01/2023 **Closed:** 12/05/2023
Problem: PM Service Dist.4 Les, will turn in tomorrow

Work Completed

Parts Issued

Quantity

- Performed P.m. Service & Inspection.
- Performed Tire Rotation Balance On All 4 Wheels, Reset Tpms.
- Performed Inspection & Service On Winch.
- Removed And Replaced The Cabin Air Filter, Clean A/c Vents & Check.
- Shop Supplies

Napagold Oil Filter	1.00
---------------------	------

Motor Oil 5w30	7.00
----------------	------

Wiper Blade	2.00
-------------	------

Cabin Air Filter	1.00
------------------	------

Shop Supplies	1.00
---------------	------

Hours: 5.25	Comm: 0.00	Labor: 383.25	Parts: 69.13	Total: 452.38
-------------	------------	---------------	--------------	---------------

10/17/2025
10:34:25 AM

Palm Beach County Fleet Management Asset Maintenance History
10210255 2020 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2401745 **Meter:** 84220 **In Date:** 02/15/2024 **Closed:** 02/26/2024
Problem: Dist.4 Les, wheel bearing are bad

Work Completed

- Diagnose noise from front end .replaced front Wheel bearings. Road test .
- Diagnose noise in rear of vehicle Replace rear differentia side bearings and races , seals and pinion bearings and races , crush sleeve and kit.
- Shop Supplies

Parts Issued

Quantity

Hub Asm	2.00
Dif Oil	3.00
Non-chlor Brake Clnr	2.00
Px Grey Rtv Silicone	1.00
Gear Differential Kit	1.00
Cup	2.00
Bearing	2.00
Shop Supplies	1.00

Hours: 12.60

Comm: 0.00

Labor: 919.80 Parts: 1,596.94 Total: 2,516.74

Work Order: 2402227 **Meter:** 84652 **In Date:** 03/01/2024 **Closed:** 03/05/2024
Problem: PM Service WILL TURN IN TOMORROW

Work Completed

- Performed P.m. Service & Inspection.
- Mount 2 Tires Then Balance & Rotate All 4 Tires, Add Nitro Fill Reset Tpms.
- Performed Service & Inspection On Winch.
- Front Brake Pads Where Below Manufac Specs, Removed Front Brake Pads And Calipers, Resurfaced Both Front Brake Rotors Then Install New Calipers & Brake Pads, Bleed And Flush Entire Brake System. Test Drove Vehicle & Burnish Brakes.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Air Fltr	1.00
Lt 245/75/17titr Mic	2.00
Brake Pad	1.00
Non-chlor Brake Clnr	1.00
Brake Fl-dot 3-4 32oz	1.00
Brake Caliper	1.00
Brake Caliper	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 9.75

Comm: 0.00

Labor: 711.75 Parts: 825.44 Total: 1,537.19

10/17/2025
10:34:25 AM

Palm Beach County Fleet Management Asset Maintenance History
10210255 2020 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2406764 **Meter:** 95248 **In Date:** 07/12/2024 **Closed:** 07/17/2024
Problem: PM Service

Work Completed

- Preventive Maint. Service
- Load test battery and charge fully. Retest battery and failed. R&r battery, diagnose current draw test with multimeter and found light bar wiring harness drawing 0.98 amps. Repair light bar harness and retest to verify draw now 0.35 amps.
- Mount two new tires, rotate and balance four. Relearn tire sensors.
- Inspect and service power winch
- R&r worn hood struts unable to support hood.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Macs Battery Cleaner	1.00
Battery	1.00
Lt 245/75/17titr Mic	2.00
Lift Support	1.00
Lift Support	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 7.75

Comm: 0.00

Labor: 565.75

Parts: 804.37

Total: 1,370.12

10/17/2025
10:34:25 AM

Palm Beach County Fleet Management Asset Maintenance History
10210255 2020 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2410537 **Meter:** 107390 **In Date:** 10/31/2024 **Closed:** 11/12/2024
Problem: PM Service Les D4, rear trail light is broken this truck is an on call truck can we have it back soon as possible Thank

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Diagnose engine light with scan tool Dtc P0496. Performed Evap system test and found purge valve stuck open. R&r failed purge valve, retest passed and clear code.
- Customer states left rear tail lamp broken. R&r broken left rear tail lamp assembly, fabricate to install strobe lamp bulb.
- R&r trailer socket due to right signal not functioning properly. R&r trailer socket has corrosion, retest and verify repair.
- Inspect and service power winch.
- Rotate and balance four tires.
- R&r auto transmission filter, and flush transmission system. Road test to verify service complete.
- Drain and fill transfer case.
- Shop Supplies

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Trailer Connector Truck Side	1.00
Valve Asm	1.00
Lamp Asy	1.00
Tram Filter	1.00
oil auto	16.00
oil auto	2.00
Shop Supplies	1.00

Hours: 12.75

Comm: 0.00

Labor: 930.75

Parts: 455.98

Total: 1,386.73

10/17/2025
10:34:25 AM

Palm Beach County Fleet Management Asset Maintenance History
10210255 2020 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2412015 **Meter:** 114307 **In Date:** 12/19/2024 **Closed:** 01/28/2025
Problem: D4 Les , the Rt. tail light is broken need to order please let me know when it comes in. P.M. Service Detail

Work Completed

Parts Issued

Quantity

- Removed And Replaced R/r Taillight Assembly, Modify For Strobe.
- Performed P.m. Service & Inspection.
- Mount 2 Tires Then Balance & Rotate All 4 Tires, Add Nitro Fill Reset Tpms.
- Performed Front Wheel Alignment & Test Drove Vehicle, Then Check.
- Performed Inspection Then Service On Winch.
- Left Alley Spotlight Inop, Check Power & Ground To Switch. Power & Ground Ok. Switch Defective Removed & Replaced The Check.
- Rear Brake Pads & Rotors Below Manufacture Specs, Removed Both Rear Brake Caliper, Pads & Rotors. Then Replaced Bleed Entire Brake System. Test Drove Vehicle & Check. Working As Design.
- Shop Supplies

Tail Lamp Asy Rh	1.00
Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Lt 245/75/17titr Mic	2.00
Bracketed Caliper	1.00
Bracketed Caliper	1.00
Rocker Switch	1.00
Brk Fluid Dot 4-32oz	1.00
Non-chlor Brake Clnr	1.00
Brake Pad	1.00
Brake Rotor	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 13.55

Comm: 0.00

Labor: 989.15

Parts: 1,321.07

Total: 2,310.22

Work Order: 2500898 **Meter:** 114307 **In Date:** 01/28/2025 **Closed:** 01/29/2025
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2412015 for: Ray Hiskell

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2412015 for: Ray Hiskell

Hours: 0.00

Comm: 86.40

Labor: 0.00

Parts: 0.00

Total: 86.40

10/17/2025
10:34:25 AM

Palm Beach County Fleet Management Asset Maintenance History
10210255 2020 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2502188 **Meter:** 116536 **In Date:** 03/06/2025 **Closed:** 03/10/2025
Problem: D4 Les, driving side rear tire needs replacing will bring it in

Work Completed

Parts Issued

Quantity

- Replace Left Rear Tire Due To Nail In Side Wall Not Repairable Balance With Nitro Fill
- Shop Supplies

Lt 245/75/17titr Mic	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 0.50	Comm: 0.00	Labor: 36.50	Parts: 287.68	Total: 324.18
-------------	------------	--------------	---------------	---------------

Work Order: 2502301 **Meter:** 116726 **In Date:** 03/05/2025 **Closed:** 03/11/2025
Problem: Tow-Flat driver rear

Work Completed

- Tow From: Congress N of clintmore, just past costco To: fleet vista Lv Shop

Hours: 0.00	Comm: 45.36	Labor: 0.00	Parts: 0.00	Total: 45.36
-------------	-------------	-------------	-------------	--------------

Work Order: 2503096 **Meter:** 118442 **In Date:** 04/02/2025 **Closed:** 04/02/2025
Problem: D4, Les, rear Rt. tire has a nail

Work Completed

Parts Issued

Quantity

- Repair right rear tire and balance .nitro fill all and reset Tpms
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 2.65	Total: 75.65
-------------	------------	--------------	-------------	--------------

10/17/2025
10:34:25 AM

Palm Beach County Fleet Management Asset Maintenance History
10210255 2020 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2504649 **Meter:** 121240 **In Date:** 05/19/2025 **Closed:** 05/22/2025
Problem: P.M. Service Wench on front of truck is broke. Needs fixed.

Work Completed

- Preventive Maint. Service
- Driver states winch is broke. R&i winch assembly to replace knotted and broken winch cable. Clean and lubricate winch gear assembly, and verify repair complete.
- R&r faulty high mount stop lamp bulb.
- Repair right and left rear tire flat, rotate and balance four.
- R&r broken pintel pin.
- Resurface front rotors, R&r front brake pads, clean and lube caliper slides. Flush and bleed contaminated brake fluid. Road test vehicle to burnish brakes.
- R&r Driver front top headlamp faulty.
- Shop Supplies

Hours: 12.95

Comm: 0.00

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Wiper Blade	2.00
Big G Degreaser 1 Gal	1.00
Used Fire X Refurbished	1.00
Winch Cable 3/8x90	1.00
Boxed Miniatures	1.00
Pintle Pin W/clip	1.00
Non-chlor Brake Clnr	1.00
Brake Fl-dot 3-4 32oz	1.00
Brake Pad	1.00
Boxed Capsules	1.00
Shop Supplies	1.00

Labor: 945.35

Parts: 312.39

Total: 1,257.74

10/17/2025
10:34:25 AM

Palm Beach County Fleet Management Asset Maintenance History
10210255 2020 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2506881 **Meter:** 127642 **In Date:** 07/25/2025 **Closed:** 07/31/2025

Problem: PM Service Tow- Busted radiator

Work Completed

- Performed P.m. Service & Inspection.
- Performed Tire Rotation And Balance On All 4 Tires, Add Nitro Fill Reset Tpms.
- Performed Inspection & Service On Winch.
- Passenger Side Headlamp Bulb Inop & Mirror Turn Signal Lens Crack Therefor Has Water Intrusion. Check Power And Ground To Headlamp Bulb. Power And Ground Ok. Bulb Filament Distorted. Removed & Replaced Bulb & Turn Sgnal Light On Mirror Assembly.
- Removed And Replaced The Cabin Air Filter, Clean A/c Vents And Check.
- Washer Fluid Pump Inop, Check Signal Power And Ground To Washer Pump. Power And Ground Ok. Pump Defective Removed And Replaced, Then Check. Working As Design.
- Pressure Test Cooling System, Found Radiator Leaking And Thermostat Closed. Removed And Replaced Radiator, Thermostat, Upper And Lower Radiator Hoses. Coolant Reservoir Contaminated Also Removed Then Replaced. Blled System & Check.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Air Fltr	1.00
Boxed Capsules	1.00
Cabin Air Filter	1.00
Wd40 Spr	1.00
Washer Pump	1.00
Coolent	2.00
Cap Assy	1.00
Seal	1.00
Thermostat	1.00
Rad Hose	1.00
Hose	1.00
Coolant Reservoir	1.00
Radiator Assy	1.00
Mirrrior Lamp	1.00
Tank Assy	1.00
Shop Supplies	1.00

Hours: 17.55

Comm: 0.00

Labor: 1,281.15

Parts: 1,912.96

Total: 3,194.11

Work Order: 2507280 **Meter:** 128463 **In Date:** 07/25/2025 **Closed:** 08/06/2025

Problem: Tow- Busted radiator

Work Completed

- Tow From: 11185 Palmetto Park Rd, Boca Raton 33428 To: Fleet Vista Lv Shop

Hours: 0.00

Comm: 118.80

Labor: 0.00

Parts: 0.00

Total: 118.80

10/17/2025
10:34:25 AM

Palm Beach County Fleet Management Asset Maintenance History
10210255 2020 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2509001 **Meter:** 132783 **In Date:** 09/23/2025 **Closed:** 10/02/2025
Problem: Transition Prep Charge

Work Completed		Parts Issued		Quantity
- Transition Prep Charge		Shop Supplies		1.00
- Shop Supplies				
Hours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 2.65	Total: 148.65
Total Hours: 192.80	Total Labor: 14,074.40	Total Comm: 2,805.21	Total Parts: 13,878.70	