

10/17/2025
10:35:32 AM

Palm Beach County Fleet Management Asset Maintenance History
10210256 2020 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Total Hours: 131.50		Labor: 9,599.50		Parts: 10,284.88		Comm: 272.60		Charged: 20156.98	
Work Order: 2003581		Meter: 302				In Date: 04/09/2020		Closed: 04/14/2020	
Problem: pre delivery inspection									
Work Completed				Parts Issued				Quantity	
- pre delivetry inspection & weld hitch sleeve				Shop Supplies				1.00	
- Shop Supplies									
Hours: 3.00		Comm: 0.00		Labor: 219.00		Parts: 4.00		Total: 223.00	
Work Order: 2007519		Meter: 6841				In Date: 07/31/2020		Closed: 08/19/2020	
Problem: PM Service, Need hitch insert adapter.									
Work Completed				Parts Issued				Quantity	
- P.m. service.				Reducer Sleeve				1.00	
- Install trailer hitch adapter .				Napa Quart 5w30				7.00	
- Rotate and balance all four tires . Nitrofill all and reset Tpms .				Napagold Oil Filter				1.00	
- Inspect and service winch .				Washer Fluid Concentr				1.00	
- Shop Supplies				Used Fire X Refurbished				1.00	
				Reducer Sleeve				1.00	
				Macs Chain Cable Lube				1.00	
				Shop Supplies				1.00	
Hours: 5.05		Comm: 0.00		Labor: 368.65		Parts: 123.75		Total: 492.40	
Work Order: 2012803		Meter: 17463				In Date: 12/23/2020		Closed: 12/23/2020	
Problem: Dist. 1 Roel, Rt. front tire has a nail in it									
Work Completed				Parts Issued				Quantity	
- Repair right front tire and balance . Nitro fill all.				Shop Supplies				1.00	
- Shop Supplies									
Hours: 1.00		Comm: 0.00		Labor: 73.00		Parts: 4.00		Total: 77.00	

10/17/2025
10:35:32 AM

Palm Beach County Fleet Management Asset Maintenance History
10210256 2020 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2100255 **Meter:** 18646 **In Date:** 01/08/2021 **Closed:** 02/18/2021
Problem: Dist.1 Terrence , P.M. service. truck needs steering wheel cover and check trailer warning on dash

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- inspect all tires. R & I four new tires, speed balance & nitro fill all
- check trailer message on dash, R & I new trailer hitch connector . Rewire as needed .
- Inspect and service winch
- Transport to and from dealer for rear pinon seal leaking .
- Perform front end alignment
- Shop Supplies

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
trailer plug	1.00
Steering Wheel Cover Large	1.00
Lt 245/75/17titr Mic	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 11.25

Comm: 0.00

Labor: 821.25

Parts: 1,706.54

Total: 2,527.79

Work Order: 2104651 **Meter:** 22254 **In Date:** 04/27/2021 **Closed:** 04/28/2021
Problem: Had to jump start .

Work Completed

Parts Issued

Quantity

- Charge battery fully . Test battery and charging system . Battery failed load test . R&r defective battery .
- Shop Supplies

Battery	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 192.82

Total: 265.82

Work Order: 2107451 **Meter:** 26140 **In Date:** 07/09/2021 **Closed:** 07/14/2021
Problem: PM Service. will turn in today

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Inspect and serviced winch.
- Rotated and balanced all 4 tires. Nitrogen filled all tires.
- Replaced cabin filter. Clean debris from fresh air intake.
- Shop Supplies

22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Napa Quart 5w30	8.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
Cabin Air Filter	1.00
Shop Supplies	1.00

Hours: 5.25

Comm: 0.00

Labor: 383.25

Parts: 57.34

Total: 440.59

10/17/2025
10:35:32 AM

Palm Beach County Fleet Management Asset Maintenance History
10210256 2020 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2111364 **Meter:** 32533 **In Date:** 10/21/2021 **Closed:** 10/26/2021
Problem: Dist.1 Eric, need a battery for the key fob. P.M. Service.

Work Completed

- Preventive Maint. Service
- R&r Faulty Battery For Key Remote.
- Resurface Front Brake Rotors, R&r Worn Front Brake Pads, Lube Caliper Slide Pins, Flush And Bleed Brake System. Road Test To Burnish Brakes.
- R&r Broken Pintel Pin.
- Inspect And Service Power Winch.
- Rotate And Balance Four Tires. Nitro Fill All .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Brake Pad	1.00
Non-chlor Brake Clnr	1.00
Brk Fluid Dot 4-32oz	1.00
Pintle Pin W/clip	1.00
Enr Elect Battery	1.00
Shop Supplies	1.00

Hours: 9.15

Comm: 0.00

Labor: 667.95

Parts: 134.53

Total: 802.48

Work Order: 2203028 **Meter:** 37812 **In Date:** 03/18/2022 **Closed:** 03/22/2022
Problem: PM Service. will turn in tomorrow

Work Completed

- Preventive Maint. Service
- Check akk, R & I four new, speed balance and nitro fill
- Inspect and service winches
- Perform front end alignment and road test .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Lt 245/75/17titr Mic	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 8.25

Comm: 0.00

Labor: 602.25

Parts: 1,031.23

Total: 1,633.48

10/17/2025
10:35:32 AM

Palm Beach County Fleet Management Asset Maintenance History
10210256 2020 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2206836 **Meter:** 42506 **In Date:** 06/29/2022 **Closed:** 06/30/2022
Problem: Dist.1 Cory, truck has a bad battery

Work Completed

Parts Issued

Quantity

- Test battery, replace battery perform starting and charging system analysis. Ok
- Shop Supplies

Battery	1.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 144.95 Total: 217.95

Work Order: 2208204 **Meter:** 45005 **In Date:** 08/05/2022 **Closed:** 08/15/2022
Problem: PM Service. Cold start long crank. Safety Recall 22S09.

Work Completed

Parts Issued

Quantity

- Performed P.m. Service & Inspection.
- Performed Tire Rotation Balance On All 4 Wheels, Reset Tpms.
- Performed Service & Inspection On Winch.
- L/r Turn Signal Inop, Check Signal Power & Ground. Power & Ground Ok., Bulb Filament Distorted, Removed And Replaced Then Check.
- Removed & Replaced The Cabin Air Filter, Clean A/c Vents & Check.
- Performed Fuel Injection Cleaning & Engine Decarb Service, Removed Throttle Body And Clean.
- Check Concern, Vehicle Runs Ruff & Misfiring, Plug In Scan Tool & Check For Faults, Found Fault Code P0300 Random Cylinder Misfire, Perform Diag & Found Ignition Coil Cyl 6 & 7 Defective, Perform Tune-up R & R Both Coils And All 16 Spark Plugs & 8 Wir
- Transport to and from dealer for recall 22s09
- Shop Supplies

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Used Fire X Refurbished	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Air Filter	1.00
Elec Battery A23	1.00
Boxed Miniatures	1.00
Proformer Cabin Fil	1.00
Motor Tune-up 16oz	1.00
Intake Cleaner Kit	1.00
Spark Plug	16.00
Spark Plug Wire	16.00
Ignition Coil	2.00
Ing Coil	1.00
Shop Supplies	1.00

Hours: 15.35 Comm: 0.00 Labor: 1,120.55 Parts: 751.00 Total: 1,871.55

10/17/2025
10:35:32 AM

Palm Beach County Fleet Management Asset Maintenance History
10210256 2020 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2300611 **Meter:** 53437 **In Date:** 01/23/2023 **Closed:** 01/25/2023
Problem: P.M. service.

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Test and replace defective left top brake light bulb and socket . Retest . Replace missing pintle pin .
- Replace two front tires and rotate and balance all four tires . Nitro fill all.
- Inspect and service winch .
- Shop Supplies

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Light Socket	1.00
Boxed Miniatures	1.00
Pintle Pin W/clip	1.00
Lt 245/75/17ttr Mic	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 6.75

Comm: 0.00

Labor: 492.75

Parts: 557.17

Total: 1,049.92

Work Order: 2302974 **Meter:** 57078 **In Date:** 03/23/2023 **Closed:** 03/23/2023
Problem: Dist.1 Willie, rear Lt. tire is low on air pressure

Work Completed

Parts Issued

Quantity

- Repair left rear tire and balance . Nitro fill all.
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 2.65

Total: 75.65

10/17/2025
10:35:32 AM

Palm Beach County Fleet Management Asset Maintenance History
10210256 2020 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2307174 **Meter:** 63914 **In Date:** 07/20/2023 **Closed:** 07/27/2023

Problem: PM Service also need to change tire to A.T. tires and has issue with the front wrench.

Work Completed

- Preventive Maint. Service
- R & I four new tires, speed balance nitro fill
- Perform front alignment, road test
- Inspect and service winches. Replace winch control and cable wires and retest
- Check & change cabin filter and clean fresh air intake
- Inspect & R & I new Front and rear brakes, Resurface all four rotors, R & I new front and rear calipers, Bleed & flush brake fluid Burnish rotors on road test
- Perform battery analyzing load & charging system test batt. failed, R & I new battery
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Used Fire X Refurbished	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Lt245/75r17 Bfg At Ko2 10ply	4.00
Cabin Filter Replaces Fp92	1.00
Brake Pads	1.00
Front Brake Pad	1.00
Non-chlor Brake Clnr	1.00
Brake Fl-dot 3-4 32oz	1.00
Battery	1.00
Brake Caliper	1.00
Brake Caliper	1.00
Brake Caliper	1.00
Brake Caliper	1.00
Brake Pad	1.00
Remote Cntrl Kit For Evo Winch	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00
Freight Charge	1.00

Hours: 18.05

Comm: 0.00

Labor: 1,317.65 Parts: 1,757.20 Total: 3,074.85

10/17/2025
10:35:32 AM

Palm Beach County Fleet Management Asset Maintenance History
10210256 2020 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2400933 **Meter:** 74967 **In Date:** 01/26/2024 **Closed:** 02/20/2024
Problem: PM Service and need to order and install visor safety lights and a detail, Long crank when starting, Brakes squealing

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service completed
- replaced two tires ,balance and rotate all 4 tires
- installed new pintle pin
- sop and installed two visor strobes light by fabricated wires as needed
- inspect and service winch
- Pressure test and inspect cooling system ,performed coolant ,flush & refill to spec also clean coolant reservoir
- check noise engine area and long crank ,sop and r&i defective throttle body assembly
- check,pin point during road test,sop and r&r both defective front shocks absorbers. R&r defective front steering stabilizer .
- check,pin point test,clean ,sand,lube brakes pads ,service all calipers,by r&i all necessary parts,then road test again to verify normal operation
- Shop Supplies

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
Steering Wheel Cover Large	1.00
Wiper Blade	2.00
Lt245/75r17 Bfg At Ko2 10ply	2.00
Pintle Pin W/clip	1.00
Coolent	2.00
Gasket	1.00
Throttle	1.00
Damper Asy	1.00
Excel-g Shock	2.00
9" Mini Led Bar Visor	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00
Freight Charge	1.00

Hours: 15.15

Comm: 0.00

Labor: 1,105.95

Parts: 1,342.02

Total: 2,447.97

Work Order: 2401473 **Meter:** 74954 **In Date:** 02/07/2024 **Closed:** 02/09/2024
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2400933 for: Ray Hiskell

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2400933 for: Ray Hiskell

Hours: 0.00

Comm: 90.40

Labor: 0.00

Parts: 0.00

Total: 90.40

10/17/2025
10:35:32 AM

Palm Beach County Fleet Management Asset Maintenance History
10210256 2020 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2406763 **Meter:** 83131 **In Date:** 07/12/2024 **Closed:** 07/16/2024
Problem: PM Service, AND DETAIL

Work Completed

- Preventive Maint. Service
- Replaced 2 tires. Rotated and balanced all 4 tires. Nitrogen filled all tires
- Replaced cabin filter and cleaned debris from fresh air intake.
- Inspect and serviced winch
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Cabin Air Filter	1.00
Lt245/75r17 Bfg At Ko2 10ply	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 6.25

Comm: 0.00

Labor: 456.25

Parts: 485.70

Total: 941.95

Work Order: 2406845 **Meter:** 83129 **In Date:** 07/16/2024 **Closed:** 07/16/2024
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2406763 for: Ray Hiskell

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2406763 for: Ray Hiskell

Hours: 0.00

Comm: 90.40

Labor: 0.00

Parts: 0.00

Total: 90.40

10/17/2025
10:35:32 AM

Palm Beach County Fleet Management Asset Maintenance History
10210256 2020 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2411708 **Meter:** 89762 **In Date:** 12/11/2024 **Closed:** 12/19/2024
Problem: PM Service will turn in to toady needs a detail. Battery goes dead. Chech roof light

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Inspect Lights Right Rear License Palte Light Blown Replace And Retest
- Pressure Tested Cooling System Found Radiator Leaking Drain Cooling System Replace Radiator And Thermostat And Vacuum Fill System And Retest
- Diagnose Left Rear Window Not Going Down Found Master Switch Circuit Corroded Replace And Retest
- Battery Dead Recharged Battery And Fail Load Test With Bad Cell R&r Battery And Recheck Charging System Program To Bcm With Ids
- Replace 2 Tires Balance All With Nitro Fill
- Shop Supplies

Drain Plug	1.00
Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Boxed Miniatures	1.00
Coolent	2.00
Battery	1.00
Radiator Assy	1.00
Hose	1.00
Thermostat	1.00
Seal	1.00
Rad Hose	1.00
Window Switch Assy	1.00
Tire	2.00
Battery	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 14.25

Comm: 0.00

Labor: 1,040.25 Parts: 1,714.96 Total: 2,755.21

Work Order: 2501710 **Meter:** 91912 **In Date:** 02/21/2025 **Closed:** 02/26/2025
Problem: D1 Cory, front window lights need mounting ,strobe light not coming on, BF Goodrick tire all Terrain

Work Completed

Parts Issued

Quantity

- Clean glue tape & reinstall windshield strobe Lamp, check circuit to strobe light switch, R & i new switch
- Shop Supplies

Led Rocker Switch Round	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00 Parts: 3.65 Total: 76.65

10/17/2025
10:35:32 AM

Palm Beach County Fleet Management Asset Maintenance History
10210256 2020 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2505594 **Meter:** 99009 **In Date:** 06/13/2025 **Closed:** 06/17/2025
Problem: PM Service and a detail will turn in tomorrow

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Rotated and balanced all 4 tires. Nitrogen filled all tires.
- Inspect and serviced winch
- Replaced cabin filter and clean debris from fresh air intake.
- Diagnose Lf marker light inop. R&r bad bulb. Replaced damaged left tail light assembly. Fabricate and install strobe into new light.
- Shop Supplies

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Wiper Blade	2.00
Air Fltr	1.00
Used Fire X Refurbished	1.00
Cabin Air Filter	1.00
Lamp Asy	1.00
Bulb	1.00
Shop Supplies	1.00

Hours: 6.75

Comm: 0.00

Labor: 492.75

Parts: 271.39

Total: 764.14

Work Order: 2505695 **Meter:** 98939 **In Date:** 06/17/2025 **Closed:** 06/17/2025
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2505594 for: Ray Hiskell

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2505594 for: Ray Hiskell

Hours: 0.00

Comm: 91.80

Labor: 0.00

Parts: 0.00

Total: 91.80

Work Order: 2508151 **Meter:** 102549 **In Date:** 08/28/2025 **Closed:** 09/05/2025
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 0.00

Total: 146.00

Total Hours: 131.50

Total Labor: 9,599.50

Total Comm: 272.60

Total Parts: 10,284.88