



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

L00030

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE CAPTAIN

Workorder: V15066

In Date: 05/14/2008

Meter Reading: 313.00

Close Date: 06/12/2008

Problem?

INSTALL GRAPHIC KIT, ESC-1

Task performed:

Install graphic kit ESC1 - Graphic Designs j

Parts

NO PARTS USED

Quantity

Vendor?: GRAPHIC DESIGNS

Workorder: V15870

In Date: 06/20/2008

Meter Reading:

Close Date: 07/08/2008

Problem?

PLEASE CHANGE THE EMERGENCY LIGHTS AND SIREN TO TURN OFF WITH THE IGNITION SWITCH

Task performed:

Esort DSS tech's from CS to ST81 for electrical modification to emer lights circuit; escort techs out of airport ST81. j

Parts

NO PARTS USED

Quantity

Workorder: V16400

In Date: 07/17/2008

Meter Reading:

Close Date: 07/30/2008

Problem?

INSTALL REAR COMMAND CENTER IN THIS VEHICLE esc1

Task performed:

1. Travel to CS from St81 w/Capt Boike to PU new ESC-1; then drove veh back to ST81.
 2. Measure command center & veh bed to make sure it wld fit.
 3. Install command center in new veh; measure/drill mounting holes; bolt down; straighten one safety pin.
- j

Parts

NO PARTS USED

Quantity



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

L00030

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE CAPTAIN

Workorder: V16642

In Date: 07/28/2008

Meter Reading:

Close Date: 08/04/2008

Problem?

Install handlight ESC-81

Task performed:

Parts

Quantity

Install & wire handlight in cab of veh ESC-1. j

NO PARTS USED

Workorder: V16734

In Date: 07/31/2008

Meter Reading:

Close Date: 08/04/2008

Problem?

New Escort 1, siren not working.

Task performed:

Parts

Quantity

1. Travel to ST81 from CS; travel to CS from ST81.
2. R/R siren head; no 12V to siren; trace wiring to power dist. panel; rep open ckt. j

NO PARTS USED

Workorder: V16930

In Date: 08/08/2008

Meter Reading:

Close Date: 08/18/2008

Problem?

Right rear tail light strobe package not working. Driver's side works fine. Passanger side not working. ESC 1

Task performed:

Parts

Quantity

1. tech meeting a.m.
2. diagnose r/r taillight strobe tube.
3. travel to st 81 and back to shop.
4. r&r r/r taillight lens. needs new lens, bad install.

S30HACSTROBE BULB

1

Workorder: V16143

In Date: 07/03/2008

Meter Reading:

Close Date: 09/08/2008

Problem?

COULD YOU INSTALL VANITY PLATE AND SEAT COVERS

Task performed:

Parts

Quantity

installed i.d. plate but was unable to install seat covers due to the wrong ones.

NO PARTS USED



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

L00030

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE CAPTAIN

Workorder: V17356

In Date: 08/27/2008

Close Date: 09/08/2008

Meter Reading:

Problem?

Lower rear light bar.

Task performed:

1. travel to and from shop to st81.
2. r/r 2 rear light bars. straighten and make new brackets mounting them in the lowest possible position.

Parts

NO PARTS USED

Quantity

Workorder: V17594

In Date: 09/09/2008

Close Date: 09/30/2008

Meter Reading: 2,697.00

Problem?

please put a map light in this vehicle

Task performed:

1. Install map Lt in Veh. Find suitable post ground in center console.
2. Travel to Sta-81 from C/S. Escort body shop tech from richtein to estimate body paint on D-1/D-5. Escort him out of Sta-81 when finished. Travel back to C/S from Sta-81.

Parts

LF18TS-LED MAP LIGHT LED 18 IN

1

(R.T.)

Workorder: V15871

In Date: 06/20/2008

Close Date: 10/01/2008

Meter Reading:

Problem?

REAR BED TOPPER LEAKS WATER COULD WE FIX PLEASE

Task performed:

1. Bring truck and trailer rep to Sta-81. To make for seat cover for 4 vehicles/then escort him out of airport.
2. Mount county tag + ID tag on this veh and F-150 airport Capt-1.

Parts

NO PARTS USED

Quantity

(R.T.)



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

L00030

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE CAPTAIN

Workorder: V17923

In Date: 09/24/2008

Close Date: 10/02/2008

Meter Reading:

Problem?

screw stuck in right front tire

Task performed:

1. Travel to Stn81 from C/S; travel to C/S from Stn81.
 2. Rem screw from R/F tire; soap test hole; no leak fnd.
- j

Parts

Quantity

NO PARTS USED

Workorder: V17777

In Date: 09/17/2008

Close Date: 10/03/2008

Meter Reading:

Problem?

Siren 10-7 ESC-1

Task performed:

1. test siren-all modes work.

(R.T.)

Parts

Quantity

NO PARTS USED

Workorder: V18511

In Date: 10/22/2008

Close Date: 11/03/2008

Meter Reading:

Problem?

Remove roof lightbar.

Task performed:

1. Measure cab windshield & get veh info; meet with Ed Woodland to order inside cab style light bar.
 2. Travel to St81 from C/S; travel to C/S from ST81.
 3. Rem light bar from veh with all associated wiring & cables; seal (5) holes in roof from mounting & cables; tape wire ends where neccessary.
- j

Parts

Quantity

NO PARTS USED

Workorder: V18668

In Date: 10/28/2008

Close Date: 11/03/2008

Meter Reading:

Problem?

rear light bar cable is hanging in rear bed. needs reattached.

Task performed:

Rem old adhesive from bed topper interior; install cable tie bases & tie wrap wiring harness to bases.

j

Parts

Quantity

NO PARTS USED



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

L00030

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE CAPTAIN

Workorder: V18849

In Date: 11/04/2008

Meter Reading:

Close Date: 11/04/2008

Problem?

Radio shop: Re-locate radio antenna from roof to fender

Task performed:

Parts

Quantity

REPORTED TO STEVEN LEE 11/4/08

NO PARTS USED

Workorder: V18991

In Date: 11/10/2008

Meter Reading:

Close Date: 11/20/2008

Problem?

all strobe lights out of service.

Task performed:

Parts

Quantity

All strobes inop; loose connector in panel & blown fuse;
rep wiring & installed new fuse. j

NO PARTS USED

Workorder: V18687

In Date: 10/29/2008

Meter Reading:

Close Date: 12/02/2008

Problem?

rotate the tires the front are showing wear on outside edges

Task performed:

Parts

Quantity

Rotate (4) tires. j

NO PARTS USED

Workorder: V19320

In Date: 11/25/2008

Meter Reading:

Close Date: 12/09/2008

Problem?

Lower tire warning. Screw found in driver front tire. esc1

Task performed:

Parts

Quantity

Lower tire warning; screw fnd in driver frnt tire - Callaghan
j

NO PARTS USED

Vendor?: CALLAGHAN



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

L00030

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE CAPTAIN

Workorder: V19398

In Date: 11/30/2008

Meter Reading:

Close Date: 12/16/2008

Problem?

Truck looks like it is due for a PM. No sticker in window for when due.

Task performed:

1. Trave to Stn81 from C/S; travel to C/S from St81.
 2. A-Inspection with oil/filter change; chk all fluids levels.
- j

Parts

51372OIL FILTER PH2

Quantity

1

Workorder: V19864

In Date: 12/19/2008

Meter Reading:

Close Date: 12/31/2008

Problem?

low pressure indicator light is on. a nail was removed from the right front tire.

Task performed:

1. Travel to Stn81 from C/S; travel to C/S from Stn81.
2. Chk veh; light not on; will monitor. j

Parts

NO PARTS USED

Quantity

Workorder: V20241

In Date: 01/08/2009

Meter Reading: 7,370.00

Close Date: 01/26/2009

Problem?

install new light bar on unit esc 1

Task performed:

- 1- Travel to st-81 to c/s and from c/s, and back to c/s.
- 2- Mount and install inside cab type light bar, run and connect all necessary wiring to swithes power grounds.

Parts

I12UFZ-TEN-LEDINNER EDGE LIGHT

Quantity

1

Workorder: V20335

In Date: 01/13/2009

Meter Reading: 8,035.00

Close Date: 02/06/2009

Problem?

install seat covers

Task performed:

1. Travel to St81 from C/S. travel to C/S from St81.
2. Install frt/rear seat covers. j

Parts

NO PARTS USED

Quantity



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

L00030

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE CAPTAIN

Workorder: V20612

In Date: 01/26/2009

Meter Reading:

Close Date: 02/06/2009

Problem?

several nuts missing from mike holder. esc 1

Task performed:

Install new attaching hardware.

j

Parts

Quantity

NO PARTS USED

Workorder: V20140

In Date: 01/05/2009

Meter Reading:

7,370.00

Close Date: 02/17/2009

Problem?

flat repair on R/R ESC1 (outside agency-Callaghan tire)

Task performed:

Flat repair on R/R ESC1 - Callaghan

j

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V19863

In Date: 12/19/2008

Meter Reading:

6,801.30

Close Date: 02/19/2009

Problem?

repair flat tire R/F and move to rear (outside agency-callaghan tire)

Task performed:

repair flat tire R/F & move to rear - Callaghan

j

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V20797

In Date: 02/02/2009

Meter Reading:

9,093.10

Close Date: 02/24/2009

Problem?

tire sensor warning light on ESC1

Task performed:

Set all tires to factory pressure; perform tire pressure monitoring sys; reset pressure for sys sensors.

j

Parts

Quantity

NO PARTS USED



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

L00030

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE CAPTAIN

Workorder: V20700

In Date: 01/29/2009

Meter Reading:

Close Date: 02/25/2009

Problem?

brake light/turn signal out. Driver rear.

Task performed:

Parts

Quantity

1. Travel to Stn81 from C/S; travel to C/S from Stn81.
2. R/R L/R tail light asy; R/R stop/turn bulb. j

NO PARTS USED

Workorder: V21339

In Date: 02/25/2009

Meter Reading:

Close Date: 02/28/2009

Problem?

Rear Cab shell is loose and hanging off the bed of the truck.

Task performed:

Parts

Quantity

1. Drive to Sn81 from C/S. drive to C/S frm Stn81.
2. Loosen all mntng clamps for pickup topper; reposition topper & tightene all clamps. j

NO PARTS USED

Workorder: V20139

In Date: 01/05/2009

Meter Reading:

Close Date: 03/02/2009

Problem?

slow leak in passenger rear tire. From screw.

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V21395

In Date: 02/27/2009

Meter Reading: 10,194.00

Close Date: 03/11/2009

Problem?

B inspection and related repairs ESC-1

Task performed:

Parts

Quantity

1. Travel to Stn81 from C/S; travel to C/S from Stn81.
2. B-Inspection j

51372OIL FILTER PH2

1



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

L00030

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE CAPTAIN

Workorder: V22126

In Date: 03/27/2009

Meter Reading: 11,407.00

Close Date: 04/13/2009

Problem?

replace tires at callaghan

Task performed:

Replace tires at - Callaghan j

Parts

NO PARTS USED

Quantity

Vendor?: CALLAGHAN

Workorder: V21278

In Date: 02/23/2009

Meter Reading:

Close Date: 05/11/2009

Problem?

WEAR BAR SHOWING ON TIRE

Task performed:

1. Inspect all tires, write down size; schedule with Ed Ehrke for tire replacement.
2. Called Callaghan Tire; does not have (4) tires this size in stock; have to call back Mon 3/2/09.
3. New tires installed at callaghan. j

Parts

NO PARTS USED

Quantity

Workorder: V23622

In Date: 05/28/2009

Meter Reading:

Close Date: 06/15/2009

Problem?

TAIL LIGHTS HALF FULL OF WATER. esc 1

Task performed:

1. Travel to Stn81 from C/S; travel to C/S frm Stn81.
2. R/R both tail lgiht asys; drain all water; leak is from DSS techs that cut wrong hole in hsng for strobe & put tape over hole; ordered (2) new tail light hsng asys.
3. R/R both tail lights asy; drill new holes for strobelights & seal lights. j

Parts

7C3Z13404ALAMP ASSY

7C3Z13405ALAMP ASSY

1

1



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

L00030

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE CAPTAIN

Workorder: V24351

In Date: 06/25/2009

Close Date: 07/06/2009

Meter Reading: 15,038.00

Problem?

B inspection and repairs

Task performed:

B-Inspection

2. R/R L/F strobe light in headlight asy; DSS made hole too big; fill surrounding area w/silicone; had to R/R L/F hdlight hsgn in order to change strobe. j

Parts

Quantity

01046301700S30HACP STROBE CLEAR

1

51372OIL FILTER PH2

1

15W40BSYN OIL BULK QTS

9

Workorder: V24808

In Date: 07/16/2009

Close Date: 08/04/2009

Meter Reading: 16,311.00

Problem?

Right brake light is out/nail in tire(driver rear).

Task performed:

1. R/R tail light lens; R/R bul.

2. Temp rep on tailpipe/exh sys; bent in auto accident; R/R tailpipe hanger; straighten/reinstall; add clamp to attach to tailpipe; need new exh sys; bent during veh accident. j

Parts

Quantity

NO PARTS USED

Workorder: V24868

In Date: 07/19/2009

Close Date: 08/04/2009

Meter Reading:

Problem?

vehicle brake light is out ESC1

Task performed:

This repair fixed on W/O 24808 j

Parts

Quantity

NO PARTS USED

Workorder: V25364

In Date: 08/06/2009

Close Date: 09/14/2009

Meter Reading: 16,598.50

Problem?

REPAIR BODY DAMAGE FROM ACCIDENT, ESC-1

Task performed:

Repair body damage from accident ESC-1 - Southeast Truck j

Vendor?: SOUTHEAST TRUCK

Parts

Quantity

NO PARTS USED



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

L00030

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE CAPTAIN

Workorder: V26216

In Date: 09/13/2009

Close Date: 09/14/2009

Meter Reading:

Problem?

bolt in left rear tire. ESC 1

Task performed:

sent unit to callaghan

Parts

Quantity

NO PARTS USED

Workorder: V26281

In Date: 09/16/2009

Close Date: 09/25/2009

Meter Reading: 16,598.50

Problem?

install tire ESC 1

Task performed:

1. Travel to Stn81 from C/S; travel to C/S from Stn81.
2. Install orig tire/whee onto veh; put spare tire back into cradle under rear of veh.

j

Parts

Quantity

NO PARTS USED

Workorder: V26263

In Date: 09/15/2009

Close Date: 09/28/2009

Meter Reading: 16,598.50

Problem?

repair tire ESC 1 (outside agency-Callaghan tire)

Task performed:

no charge

Parts

Quantity

NO PARTS USED

Workorder: V26461

In Date: 09/25/2009

Close Date: 10/14/2009

Meter Reading: 18,359.00

Problem?

REPLACE STRIPING ON RIGHT SIDE OF VEHICLE DUE TO ACCIDENT, ESC-1

Task performed:

replace striping on R/side of veh due to accident, ESC-1

Graphic Design j

Vendor?: GRAPHIC DEISNGS

Parts

Quantity

NO PARTS USED



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

L00030

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE CAPTAIN

Workorder: V27809

In Date: 11/19/2009

Close Date: 12/02/2009

Meter Reading: 18,913.10

Problem?

rotate tires ESC1

Task performed:

Rotate tires to even out tire wear; adj frnt/rear press; reprogram tire press monitoring sys on veh after tire rotation. j

Parts

NO PARTS USED

Quantity

Workorder: V27975

In Date: 11/29/2009

Close Date: 12/07/2009

Meter Reading:

Problem?

Right rear tail light strobe INOP. St81

Task performed:

1. Travel to Stn81 from C/S.
2. R/R R/rear tail light asy; R/R strobe tube. j

Parts

01046301700S30HACP STROBE CLEAR

1

Workorder: V28336

In Date: 12/14/2009

Close Date: 12/22/2009

Meter Reading: 18,913.10

Problem?

dead battery

Task performed:

1. Chk veh; load to frt on hookup charger.
2. R/R btry. j

Parts

65-72BXT65750 BATTERY

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

1

1

Workorder: V27255

In Date: 10/28/2009

Close Date: 01/27/2010

Meter Reading: 18,766.40

Problem?

make two new keys for uni al packer ford closed by nb 1.27.10 no invoice found by vendor

Task performed:

Parts

NO PARTS USED

Quantity



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

L00030

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE CAPTAIN

Workorder: V30872

In Date: 03/19/2010

Close Date: 04/08/2010

Meter Reading: 19,279.00

Problem?

Right front strobe INOP.

Task performed:

R/R R/F strobe in headlight hsng; reasel w/silicone. j

Parts

01046301700S30HACP STROBE CLEAR

Quantity

1

Workorder: V28787

In Date: 01/04/2010

Close Date: 04/14/2010

Meter Reading:

Problem?

Service past due by date on service sticker 09/2009. Please complete.

Task performed:

Parts

NO PARTS USED

Quantity

Workorder: V31369

In Date: 04/08/2010

Close Date: 05/01/2010

Meter Reading: 19,279.00

Problem?

ac1 battery found dead. key switch was not on. recurrent problem. tac

Task performed:

Unit is at airport; mech there will rep. j

Parts

NO PARTS USED

Quantity

Workorder: V31438

In Date: 04/11/2010

Close Date: 05/07/2010

Meter Reading: 19,279.00

Problem?

battery dead. recurrent problem. keys were not in ignition. tail lights were noted on although light swith was in the off position. tac

Task performed:

1. Chk btry & charging sys again; NPF; rem headlite frm charger; think handlite btry bad; will monitor. j

Parts

NO PARTS USED

Quantity



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

L00030

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE CAPTAIN

Workorder: V30766

In Date: 03/16/2010

Meter Reading: 19,279.00

Close Date: 05/24/2010

Problem?

Could we install a shore charging system in this vehicle like the ones used in the DC vehicles AC1

Task performed:

This veh ok; had a defective handlite btry causing veh
btry drain. j

Parts

NO PARTS USED

Quantity

Workorder: V32424

In Date: 05/25/2010

Meter Reading: 19,650.00

Close Date: 06/08/2010

Problem?

Mount new halatron extinguisher in vehicle AC1

Task performed:

Find stuiable lcn; drill/tap holes; mnt ext. j

Parts

NO PARTS USED

Quantity

Workorder: V33288

In Date: 07/01/2010

Meter Reading: 19,757.00

Close Date: 07/01/2010

Problem?

Ground radio has lots of static on the line. Unable to reduce the static in order to communicate with the tower.

Task performed:

reported to radio shop 07/01/10

Parts

NO PARTS USED

Quantity

Workorder: V31670

In Date: 04/20/2010

Meter Reading: 20,097.00

Close Date: 10/05/2010

Problem?

B inspection and repairs as needed AC 1

Task performed:

1. b inspection
2. r&r lens jab

Parts

51372OIL FILTER PH2
15W40BSYN OIL BULK QTS
01046301700S30HACP STROBE CLEAR

Quantity

1
9
1



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

L00030

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE CAPTAIN

Workorder: V37194

In Date: 12/16/2010

Meter Reading: 20,339.00

Close Date: 01/13/2011

Problem?

B inspection and repairs as needed AC 1

Task performed:

- B-Inspection
- Inflate all tires to correct press.
- R/R R/F strobe inheadlight hsng; dig out silicone to rem lite; install new strobe & silicone to seal.
- Trave to Stn81; R/R wiper blades.
- Mix/fill windshield washer reservoir.
- Svc 4WD t-case. j

Parts

Quantity

91-20WIPER BLADE 20 IN

2

01046301700S30HACP STROBE CLEAR

1

33243FUEL FILTER WPB

1

49883AIR FILTER WPB 7C3Z9601A

1

51372OIL FILTER PH2

1

15W40BSYN OIL BULK QTS

6

Workorder: V39046

In Date: 03/08/2011

Meter Reading: 20,588.00

Close Date: 03/28/2011

Problem?

STEERING VERY STIFF A/C 10-7 TIRE PRESSURE MONITOR

Task performed:

1. Travel to Boulevard Tire to PU veh; return to Stn81; rep TPMS warning It on at dash.

Parts

Quantity

NO PARTS USED

Veh was sent to Al Packer Ford for all other repairs - warranty. j

Workorder: V38845

In Date: 02/28/2011

Meter Reading: 16,598.50

Close Date: 04/20/2011

Problem?

replace all 4 tires ESC 1 (outside agency-Boulevard tire)

Task performed:

Replc all (4) tires ESC1 - Boulevard j

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

L00030

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE CAPTAIN

Workorder: V42707

In Date: 08/10/2011

Meter Reading: 21,221.00

Close Date: 08/15/2011

Problem?

B Inspection @ Al Packer

Task performed:

B Inspection @ Al Packer

Parts

Quantity

NO PARTS USED

Vendor?: AL PACKER

Workorder: V45909

In Date: 12/16/2011

Meter Reading:

Close Date: 12/20/2011

Problem?

Left headlight strobe INOP. Sta 81

Task performed:

REPAIRS DONE ON W.O. #V45954.

Parts

Quantity

NO PARTS USED

Workorder: V45954

In Date: 12/19/2011

Meter Reading:

Close Date: 12/20/2011

Problem?

Right front headlight strobe INOP in addition to front left already reported. Sta 81

Task performed:

CHECK HEAD LIGHT STROBES, RAN EMERGENCY LIGHTS - FOUND NO EXTERNAL STROBES IN HEAD LIGHTS. CHECK WIG-WAG- CHECK OK. R&R L. MARKER LIGHT - OK.

Parts

Quantity

NO PARTS USED

CHECK FOR NOT STARTING - FOUND STARTER GRINDING AND NOT TURNING ENGINE OVER - BARRED ENGINE OVER BY HAND - STARTED TRUCK - BROUGHT TRUCK TO SHOP - RETURN DRIVER TO STA 81 - RETURN TO SHOP.



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

L00030

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE CAPTAIN

Workorder: V46190

In Date: 12/31/2011

Meter Reading:

Close Date: 02/13/2012

Problem?

Left hi-beam INOP. Front headlight strobes INOP. Sta 81

Task performed:

REPLACED LEFT HEADLIGHT

Parts

Quantity

9008HEAD LAMP

1

01046301700S30HACP STROBE CLEAR

1

REPLACED FRONT HEADLIGHT STOBES, SILICONE STROBES IN HOUSING

S30TLBULB

1

TRAVEL TO AIRPORT AND BACK TO SHOP AND RESTOCK VEHICLE

Workorder: V48335

In Date: 04/01/2012

Meter Reading:

Close Date: 04/02/2012

Problem?

#1 GROUND RADIO NOT WORKING PROPERLY. LOTS OF NOISE. ESC1

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V49111

In Date: 05/05/2012

Meter Reading: 22,118.00

Close Date: 06/04/2012

Problem?

Front right hi-beam INOP. Right rear tail light strobe INOP. ESC 1

Task performed:

Parts

Quantity

1. REMOVED HEADLIGHT INSTALLED NEW BULB REINSTALLED HEADLIGHT CHECKED OK.

9008HEAD LAMP

1

2. FOUND LOOSE CONNECTION ON REAR LIGHT CORRECTED.

S30HACSTROBE BULB

2

BC3Z13404ACPLAMP TAIL R/H

1

3. WORK DONE ON 49395.

BC3Z13405ACPTAIL LIGHT L/H

1



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

L00030

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE CAPTAIN

Workorder: V49395

In Date: 05/16/2012

Meter Reading: 22,118.00

Close Date: 06/04/2012

Problem?

driver rear brake/blinker light out

Task performed:

REMOVED BROKEN TAIL LIGHT INSTALLED STROBE LIGHT IN HOUSING INSTALLED NEW ASSEMBLY FOUND STROBE LIGHT IN OTHER SIDE CHECKED OK.

Parts

NO PARTS USED

Quantity

Workorder: V52257

In Date: 09/08/2012

Meter Reading: 22,474.00

Close Date: 10/05/2012

Problem?

Left rear srobe in tail light INOP. AT 81

Task performed:

INSTALLED NEW STROBE LIGHT IN TAIL LIGHT ASSEMBLY.

Parts

01046301700S30HACP STROBE CLEAR

Quantity

1

Workorder: V53225

In Date: 10/20/2012

Meter Reading: 22,613.00

Close Date: 10/25/2012

Problem?

Right Rear tail light/turn signal INOP.

Task performed:

INSTALLED NEW BULB IN TAIL LIGHT.

Parts

3157TAIL LIGHT BULBS

Quantity

10

Workorder: V52441

In Date: 09/17/2012

Meter Reading: 22,591.00

Close Date: 11/02/2012

Problem?

B INSPECTION OIL CHANGE SERVICES

Task performed:

B inspection
oil and filters

Vendor?: OCS

Parts

NO PARTS USED

Quantity



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

L00030

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE CAPTAIN

Workorder: V57423

In Date: 05/02/2013

Close Date: 05/20/2013

Meter Reading:

Problem?

FRONT L HEADLIGHT

Task performed:

TRAVEL TO ST 81 R&R HEAD LIGHT AND SOCKET
AND REWIRE.

Parts

Quantity

9008HEAD LAMP

2

3U2Z14S411FKAEPITAIL SOCKET

1

Workorder: V58660

In Date: 06/24/2013

Close Date: 07/18/2013

Meter Reading: 23,489.00

Problem?

RIGHT TAIL LIGHT OUT

Task performed:

REPAIRED ON WORK ORDER #58777

Parts

Quantity

NO PARTS USED

Workorder: V58777

In Date: 06/29/2013

Close Date: 07/18/2013

Meter Reading: 23,489.00

Problem?

Right rear turn signal / emergency flasher INOP. AT 81

Task performed:

TRAVEL TO ST81 R&R TAIL LIGHT BULB.

Parts

Quantity

NO PARTS USED

Workorder: V59001

In Date: 07/11/2013

Close Date: 08/15/2013

Meter Reading: 23,560.00

Problem?

Low tire pressure light is on inside the cab.

Task performed:

1. CHECK OUT TAIL LIGHT OUT AGAIN. R&R BULB
SEAL UP CRACK IN LIGHT WATER GETTING IN.
2. FORD TRUCK NEEDS TPS RESET AT FORD LIKE
D/C TIRES FULL NO RESET AT STATION POSS BAD
SENSOR.

Parts

Quantity

NO PARTS USED



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

L00030

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE CAPTAIN

Workorder: V60445

In Date: 09/11/2013

Close Date: 10/25/2013

Meter Reading: 23,667.00

Problem?

B-inspection

Task performed:

1. B-INSPECTION.
2. R&R WINDSHIELD WIPER BLADES.
3. TURN LOW TIRE PRESSURE LIGHT OFF.
4. ASSIST.

Parts

Quantity

49883AIR FILTER WPB 7C3Z9601A

1

15W40QSYN OIL QT

12

Workorder: V65745

In Date: 04/15/2014

Close Date: 04/24/2014

Meter Reading:

Problem?

Air condition not working. ESC 1

Task performed:

CHECKED UNIT FOUND CLUTCH CYCLING ADDED
FREON OK.

Parts

Quantity

NO PARTS USED

Workorder: V70337

In Date: 10/21/2014

Close Date: 10/21/2014

Meter Reading: 25,109.00

Problem?

B-inspection

Task performed:

B-inspection
Replaced steering box
Vendor?: AL PACKER

Parts

Quantity

NO PARTS USED

Workorder: V72026

In Date: 01/04/2015

Close Date: 01/13/2015

Meter Reading:

Problem?

Ground radio's intermitatly will not work. could not transmit or recieve durring an emergency. Truck had to be shut down and restarted for it to work.

Task performed:

radio shop looked at

Parts

Quantity

NO PARTS USED



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

L00030

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE CAPTAIN

Workorder: V72063

In Date: 01/05/2015

Meter Reading:

Close Date: 01/16/2015

Problem?

Low voltage on alternator. Truck would not start after running.

Task performed:

Parts

Quantity

WORK REPAIRS AS REQUESTED.

NO PARTS USED

Vendor?: AL PACKER

Workorder: V72119

In Date: 01/08/2015

Meter Reading:

Close Date: 01/20/2015

Problem?

Left front strobe INOP.

Task performed:

Parts

Quantity

No problem found.

NO PARTS USED



Palm Beach County Fire Rescue

Fleet Maintenance Asset History

Asset: (L00030) 2008 - FORD F350 Truck Ems Or Rescue Captain Vehicle

L00030

CSHOP-2015-3429

Comments: **NAIL IN LR TIRE**

Date Opened 10-14-2015

Date Finished

10-20-2015

Meter 1 Reading:

26,627

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
TIRES & WHEELS

CSHOP-2015-3866

Comments: **SENT TO TIRESOLES**

Date Opened 11-9-2015

Date Finished

11-18-2015

Meter 1 Reading:

26,792

TASKS PERFORMED

NO PARTS USED

TIRES ALL

VENDOR? EARL COLVARD BOULEVARD TIRE

Service Requests:

11/09/2015

TIRES / 44: WORN / EXCHANGE - NEW

RIGHT REAR TIRE WORN WITH NAIL IN IT AND POSSIBLY LOSING AIR. LOW TIRE PRESSURE LIGHT ON. LEFT REAR TIRE WORN.

CSHOP-2015-945

Comments: **B INSPECTION WIPER BLADES BACK UP ALARM**

Date Opened 6-2-2015

Date Finished

6-2-2015

Meter 1 Reading:

26,025

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2016-2355

Comments: **B SERVICE**

Date Opened 5-17-2016

Date Finished

5-27-2016

Meter 1 Reading:

27,419

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

Asset Work Order History L00030**CSHOP-2016-4479**

Date Opened 9-14-2016

Date Finished

12-6-2016

Meter 1 Reading:

28,000

TASKS PERFORMED**Q PARTS**

TAIL LIGHTS

2 9IP; 3156 WAGNER BULB
2 BULB; TAIL LIGHT BULBS

Service Requests:

09/11/2016

LIGHTS / 12: BROKEN / REPAIR

VEHICLE LIGHTS NOT WORKING- RIGHT REAR TAIL LIGHT

CSHOP-2016-5570Comments: **ON-CALL AC1**

Date Opened 11-29-2016

Date Finished

12-1-2016

Meter 1 Reading:

28,273

TASKS PERFORMED**Q PARTS**

HEADLIGHTS LOW BEAM

1 LAMP; HEAD LAMP

Service Requests:

11/24/2016

LIGHTS / 12: BROKEN / REPAIR

DRIVER SIDE HEADLIGHT OUT

CSHOP-2017-1329

Date Opened 3-3-2017

Date Finished

3-7-2017

Meter 1 Reading:

28,741

TASKS PERFORMED**Q PARTS**

TAIL LIGHTS

1 9IP; TAIL LIGHT BULBS

CSHOP-2017-3336

Date Opened 6-6-2017

Date Finished

6-6-2017

Meter 1 Reading:

29,089

TASKS PERFORMED**NO PARTS USED**

PM SERVICE B LIGHT

VENDOR? AL PACKER

Asset Work Order History L00030

CSHOP-2017-5795

Date Opened 10-6-2017

Date Finished

10-31-2017

Meter 1 Reading:

29,876

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FUEL SYSTEM
BRAKE LIGHTS
HEADLIGHTS HIGH BEAM
ELECTRICAL
SUSPENSION
STROBE LIGHTS

2 1FD; TAIL LIGHT SOCKET
1 1FD; TAIL LAMP
1 1FD; TAIL LAMP
2 LMP; BULB
1 LMP; HALOGEN CAPSULE
3 9IP; S30HACP STROBE CLEAR

Service Requests:

10/06/2017 LIGHTS / 27: OVERHEATED / PREFORMED INSPECTION. FOUND TAIL LIGHT SOCKETS OVERHEATED
VEHICLE LIGHTS NOT WORKING: RIGHT REAR LIGHT AND BRAKE LIGHT ARE OUT

10/12/2017 SHOCKS / 44: WORN / TEST DROVE AND PREFORMED INSPECTION. ASSET BROUGHT TO DEALER
SHOCKS WORN OUT??? RIDING ROUGH YOU FEEL EVERY BUMP IN THE FRONT END. BUMP STOPS FOUND ON
GROUND ROTTED OFF.

10/12/2017 STARTER / 18: LEAKING / TOOK ASSET TO THE DEALER FOR DIAGNOSTICS AND REPAIR. REPAIR
INTERMITTENT DIFFICULT TO START. SEEMS LIKE FUEL PUMP LOOSES IT PRIME. POSSIBLE FUEL PUMP GOING BAD.
NOTICE IT MORE WHEN VEHICLE SITS FOR LONG PERIODS.

CSHOP-2017-6063

Date Opened 10-20-2017

Date Finished

10-25-2017

Meter 1 Reading:

29,876

TASKS PERFORMED

NO PARTS USED

SUSPENSION

VENDOR? AL PACKER

CSHOP-2017-7100

Date Opened 12-12-2017

Date Finished

2-9-2018

Meter 1 Reading:

30,448

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
DOOR PROP CYLINDER
BATTERY

2 5AH; SHOCK 20LBS
1 1AD; 65 SERIES BATTERY

Service Requests:

12/12/2017 WINDOW / 43: WEAK / VERIFIED CONCERN. ORDERED PROPS USING PART NUMBER ON THEM. /
REAR TRUCK BED TOPPER.....NEEDS NEW PROP (HYDRALIC) ARM THAT HOLD WINDOW UP WHEN ACCESSING BED
OF TRUCK. NEDDS 2 PLACED

Asset Work Order History L00030

CSHOP-2017-779

Date Opened 2-7-2017 Date Finished 2-9-2017 Meter 1 Reading: 28,564

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
CRANKING SYSTEM

1 9IP; BXT65750 BATTERY

Service Requests:

02/07/2017 STARTER / 43: WEAK / PREFORMED BATTERY, STARTING, AND CHARGING TESTS. BATTERY FAIL
VEHICLE WILL NOT START NEED NEW BATTERY

CSHOP-2018-1222

Date Opened 2-28-2018 Date Finished 2-28-2018 Meter 1 Reading: 30,802

TASKS PERFORMED

NO PARTS USED

TIRES ALL

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2018-1312

Date Opened 3-5-2018 Date Finished 3-13-2018 Meter 1 Reading: 30,832

TASKS PERFORMED

Q PARTS

FIRE FIGHTING EQUIPMENT

1 BK; FUSE HOLDER

Service Requests:

03/03/2018 SERVICE REQUEST / 29: PART OMITTED / INSTALLED 4 GAS CHARGER. FABRICATED HARNESSE
NEED CHARGER MOUNTED IN VEHICLE FOR DRAGER X-AM 2500 GAS METER

CSHOP-2018-2991

Comments: **WARNING LIGHT SWITCH BROKEN REVERSE LAMP OUT**

Date Opened 5-30-2018 Date Finished 6-1-2018 Meter 1 Reading: 31,383

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
BACK UP LIGHTS
STROBE LIGHTS

10 9IP; LIGHT BULB
2 NW; PROSOFTTOUCHSWITCH

Asset Work Order History L00030

CSHOP-2018-3146

Date Opened 6-6-2018

Date Finished

1-8-2019

Meter 1 Reading:

31,771

TASKS PERFORMED

Q PARTS

LIGHT BAR

1 9AP; LIGHTBAR INSTALLATION
1 1WL; GREEN AIRPORT LIGHT BAR
1 FRT

Service Requests:

06/05/2018

LIGHTS / 12: BROKEN / EXCHANGE - NEW

VEHICLE LIGHTS WOULD LIKE TO HAVE THE GREEN COMMAND LIGHT PERMANENTLY MOUNTED AND WIRED IT IS CURRENTLY A MAGNET TYPE WITH A PLUG THAT GOES INTO CIGARETTE LIGHTER. CAN WE AFFIX IT TO THE CENTER OF ROOF AND WIRE IT TO A SWITCH? THANKS

CSHOP-2018-5164

Comments: **FOUND A/C COMPRESSOR CLUTCH HAD FAILED CAUSING RATTILING SOUND AND LOSS OF A/C . REPAIRED AT PACKER**

Date Opened 9-11-2018

Date Finished

9-20-2018

Meter 1 Reading:

31,771

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

Service Requests:

09/11/2018

A/C / 12: BROKEN / INSPECT
A/C ISSUE NOT BLOWING COLD

09/11/2018

ENGINE / 12: BROKEN / INSPECT
ENGINE MAKING A RADDLING SOUND. MAYBE A LOOSE BELT

CSHOP-2018-5381

Date Opened 9-20-2018

Date Finished

9-20-2018

Meter 1 Reading:

31,771

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2018-5384

Date Opened 9-20-2018

Date Finished

10-5-2018

Meter 1 Reading:

0

TASKS PERFORMED

Q PARTS

SEAT FRONT

1 9AP; POLY SEAT COVERS
1 NONSTOCK; FREIGHT CHARGE

Asset Work Order History L00030

CSHOP-2018-6325

Date Opened 11-6-2018 Date Finished 11-6-2018 Meter 1 Reading: 31,771

TASKS PERFORMED

NO PARTS USED

TIRES ALL

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2018-964

Date Opened 2-14-2018 Date Finished 2-14-2018 Meter 1 Reading: 30,660

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2019-136

Comments: **BATTERY CHARGER FOR 81**

Date Opened 1-8-2019 Date Finished 1-25-2019 Meter 1 Reading: 31,771

TASKS PERFORMED

Q PARTS

ELECTRICAL

1 **SOR; WHEEL BATTERY CHARGER**

CSHOP-2019-5392

Date Opened 10-12-2019 Date Finished 10-16-2019 Meter 1 Reading: 33,546

TASKS PERFORMED

Q PARTS

BATTERY

1 **1AD; BATTERY GROUP 65**

CSHOP-2019-5482

Date Opened 10-24-2019 Date Finished 10-24-2019 Meter 1 Reading: 33,789

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2019-5644

Date Opened 10-26-2019 Date Finished 10-28-2019 Meter 1 Reading: 33,789

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
BATTERY

1 **1AD; BATTERY GROUP 65**

Asset Work Order History L00030

CSHOP-2019-5783

Date Opened 11-4-2019 Date Finished 11-14-2019 Meter 1 Reading: 33,878

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
CRANKING SYSTEM

1 6KU; AC2000 12V PLC TEN 8
1 BK; HI AMP FLUSH MOUNT
1 6KU; AUTO EJECT W STD YEL CVR

CSHOP-2020-176

Date Opened 1-12-2020 Date Finished 1-13-2020 Meter 1 Reading: 39,072

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
CRANKING SYSTEM

CSHOP-2020-1932

Date Opened 4-11-2020 Date Finished 4-11-2020 Meter 1 Reading: 34,662

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2020-2064

Date Opened 4-18-2020 Date Finished 4-18-2020 Meter 1 Reading: 34,688

TASKS PERFORMED

NO PARTS USED

SUSPENSION

VENDOR? AL PACKER

CSHOP-2020-4796

Date Opened 9-14-2020 Date Finished 10-7-2020 Meter 1 Reading: 35,533

TASKS PERFORMED

NO PARTS USED

TEMP GAUGE

Service Requests:

09/12/2020 TEMPERATURE / 49: CAN NOT DUPLICATE CONCERN / ATTEMPTED TO VERIFY CONCERN. TEST
TEMP GAUGE BAD MAYBE? SEEM TO BE FLUCTUATING

Asset Work Order History L00030

CSHOP-2020-5240

Date Opened 10-5-2020 Date Finished 10-19-2020 Meter 1 Reading: 35,533

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
BODY - WORK COMPARTMENT EMER
MOTOR

1 8GR; CAPACITOR 645 774UF 110 125VAC

Service Requests:

10/03/2020 SERVICE REQUEST / 19: LOOSE / VERIFIED CONCERN. REMOVED ALL GEAR FROM PULL OUT TF
BACK UTILITY TRAY HANDLE IS BROKEN OR NEED ADJUSTING. IT IS NOT ALLOWING THE TRAY TO ROLL OUT.

CSHOP-2020-624

Date Opened 2-5-2020 Date Finished 2-10-2020 Meter 1 Reading: 39,072

TASKS PERFORMED

NO PARTS USED

FIRE FIGHTING EQUIPMENT

Service Requests:

02/04/2020 SERVICE REQUEST / 43: WEAK / SPOKE WITH W. CHAMBERS IN THE WAREHOUSE. HE STATED I
NEED NEW BATTERIES AND POSSIBLY CHARGER FOR AC1 MILWAUKEE SAWSALL. UNSURE IF THIS IS AN
ASSETWORKS REQUEST BUT WILL ALSO SEND EMAIL TO SUPPORT SERVICES. CASE AND TOOLS ARE IN AC1 OFFICE.
THANKS

CSHOP-2020-761

Date Opened 2-10-2020 Date Finished 4-16-2020 Meter 1 Reading: 34,598

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
STROBE LIGHTS
HVAC SYSTEM

1 LMP; LAMP
2 1FD; SOCKET HEADLIGHT
1 1WL; HEADLIGHT FLASHER
2 1FD; O RING KIT
3 1MC; SHRADER VALVE
1 1FD; CONDENSER

Service Requests:

02/10/2020 LIGHTS / 38: SHORTED / INSTALLED, REWIRED WIG WAG MODULE AND PROGRAMED. REPLACE I
VEHICLE LIGHTS NOT WORKING RED STROBE LIGHT OUT OF FRONT BUMPER DRIVER SIDE

CSHOP-2021-1324

Date Opened 3-10-2021 Date Finished 3-25-2021 Meter 1 Reading: 36,558

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
TURN SIGNAL LIGHTS

2 LMP; LAMP
1 LMP; LAMP

Service Requests:

03/09/2021 LIGHTS / 12: BROKEN / REPLACED FAILED BULB.
VEHICLE LIGHTS NOT WORKING LEFT REAR BLINKER/HAZARD LIGHT NOT WORKING

Asset Work Order History L00030

CSHOP-2021-2171

Date Opened 4-22-2021 Date Finished 5-11-2021 Meter 1 Reading: 36,778

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2021-2934

Date Opened 5-27-2021 Date Finished 7-13-2021 Meter 1 Reading: 37,215

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
TURN SIGNAL LIGHTS
AIR SYSTEM

2 1FD; TAIL LIGHT SOCKET
10 LMP; LAMP
2 1ML; SOCKET FEMALE
2 NTH; COUPLER

Service Requests:

05/26/2021 LIGHTS / 27: OVERHEATED / VERIFIED CONCERN. INSPECTED TAIL LAMPS. FOUND BULB SOCKE
VEHICLE LIGHTS NOT WORKING-RIGHT REAR BLINKER/HAZARD NOT WORKING

CSHOP-2021-4019

Comments: **HEADLIGHT**

Date Opened 7-19-2021 Date Finished 8-5-2021 Meter 1 Reading: 37,354

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
HEADLIGHTS LOW BEAM

1 8AM; BULB SWITCHBACK PAIR
1 9ES; BULB LED HI LO

Service Requests:

07/18/2021 SERVICE REQUEST / 12: BROKEN / REPLACED HEADLAMPS AND TURN SIGNALS WITH LED LAMP
DRIVER LOW BEAM HEAD LIGHT/DAYTIME RUNNING LIGHT OUT. NEEDS REPLACED

CSHOP-2021-4398

Date Opened 8-5-2021 Date Finished 8-5-2021 Meter 1 Reading: 37,354

TASKS PERFORMED

NO PARTS USED

SHORELINE CHARGER

Service Requests:

08/05/2021 SERVICE REQUEST / 19: LOOSE / VERIFIED CONCERN. CHECKED THE STATUS LED'S. ALL LAMP
CHECK SHORELINE CHARGER. WILL ONLY FLASH 1 BAR ON CHARGING SCALE.

Asset Work Order History L00030

CSHOP-2021-6487

Comments: **ROAD**

Date Opened 11-23-2021 Date Finished 12-14-2021 Meter 1 Reading: 37,400

TASKS PERFORMED

NO PARTS USED

LIGHTING SYSTEM

Service Requests:

11/19/2021 LIGHTS / 14: CRACKED / REPAIRED
VEHICLE LIGHTS NOT WORKING LEFT REAR BRAKE LIGHT WORKS INTERMITTENTLY

CSHOP-2021-7001

Date Opened 12-25-2021 Date Finished 12-28-2021 Meter 1 Reading: 38,091

TASKS PERFORMED

Q PARTS

STARTER

1 1AD; BATTERY GROUP 65

CSHOP-2021-7047

Date Opened 12-28-2021 Date Finished 2-16-2022 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

Service Requests:

12/28/2021 TIRES / 18: LEAKING / EXCHANGE - NEW
BAD TIRES - NEED POSSIBLE REPLACEMENTS ALSO RIGHT FRONT TIRE HAS A SCREW IN IT. NOTICED WHEN TOW
TRUCK WAS PICKING IT UP TO GO TO SHOP SO IF SOMEONE CAN TAKE A LOOK AT IT. WE DIDNT PULL IT JUST IN
CASE IT STARTED TO LEAK. THANK YOU

CSHOP-2021-7103

Date Opened 12-30-2021 Date Finished 12-30-2021 Meter 1 Reading: 38,096

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

Asset Work Order History L00030

CSHOP-2022-1923

Comments: **SLIDE OUT TRAY**

Date Opened 4-7-2022

Date Finished

4-12-2022

Meter 1 Reading:

38,591

TASKS PERFORMED

NO PARTS USED

STORAGE CABINET EMERGENCY VEH
SHORELINE CHARGER

Service Requests:

04/06/2022

SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / OPERATED THE SLIDE OUT TOOL TRAY
SLIDE OUT TOOL TRAY HANDLE IN THE REAR OF VEHICLE IS HARD TO PULL. IT DOESN'T ALLOW THE TRAY TO PULL
OUT IN ORDER TO ACCESS EQUIPMENT. NEEDS REPAIR. ON AC1

CSHOP-2022-2810

Date Opened 5-24-2022

Date Finished

6-27-2022

Meter 1 Reading:

38,867

TASKS PERFORMED

NO PARTS USED

TRANSMISSION

VENDOR? AL PACKER

Service Requests:

05/23/2022

TRANSMISSION / 12: BROKEN / EXCHANGE - REBUILT
TRANSMISSION SEEMS TO "CLUNK" WHEN YOU START DRIVING FROM A STOP OR WHEN COASTING AND PUSH ON
ACCELERATOR.

CSHOP-2022-5566

Comments: **TURN SIGNAL**

Date Opened 10-17-2022

Date Finished

10-18-2022

Meter 1 Reading:

39,432

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
TURN SIGNAL LIGHTS

1 LMP; LAMP
1 1FD; LEFT TAILLIGHT ASSY

Service Requests:

10/15/2022

LIGHTS / 18: LEAKING / FOUND THE LEFT TAIL LAMP FULL OF WATER DUE TO A CRACK IN THE H
VEHICLE LIGHTS NOT WORKING-LEFT BLINKER OUT

CSHOP-2022-6506

Date Opened 12-13-2022

Date Finished

12-16-2022

Meter 1 Reading:

39,775

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

Asset Work Order History L00030

CSHOP-2023-151

Comments: **ARFF CAPT. TRANS AND LIGHT**

Date Opened 1-10-2023

Date Finished

3-13-2023

Meter 1 Reading:

40,058

TASKS PERFORMED

Q PARTS

TURN SIGNAL LIGHTS
TRANSMISSION

2 LMP; LAMP

Service Requests:

01/10/2023

TRANSMISSION / 12: BROKEN / REPAIR

TRANSMISSION BAD TRANSMISSION SLIP IN REVERSE. ALMOST NO POWER. ALSO DRIVER REAR BLINKER

CSHOP-2023-2409

Comments: **CHECK ENGINE LIGHT**

Date Opened 5-5-2023

Date Finished

11-14-2023

Meter 1 Reading:

40,455

TASKS PERFORMED

Q PARTS

FAULT CODE
TAIL LIGHTS

2 LMP; LAMP

Service Requests:

05/04/2023

LIGHTS / 12: FOUND FAILED TAIL LAMP BULB. / REPLACED BULB.

right side rear brake light and blinker not working....VEHICLE LIGHTS NOT WORKING

05/04/2023

ENGINE / 49: CAN NOT DUPLICATE CONCERN / DUPLICATE SERVICE REQUEST.

ENGINE

05/04/2023

ENGINE / 49: CODE FOR EVAP SYSTEM SMALL LEAK FOUND. / PREFORMED DIAGNOSTICS AND I

check engine light on....ENGINE

CSHOP-2023-5435

Comments: **SHORELINE CHARGER**

Date Opened 10-23-2023

Date Finished

11-15-2023

Meter 1 Reading:

41,550

TASKS PERFORMED

NO PARTS USED

SHORELINE CHARGER

Service Requests:

10/18/2023

SERVICE REQUEST / 19: found a loose connection at the charger display connection. / preformed diag

DESCRIBE ISSUE Shoreline charger not working.

Asset Work Order History L00030

CSHOP-2023-5973

Comments: TRUCK EMS OR RESCUE CAPTAIN VEHICLE: VEHICLE DOORS
Date Opened 11-27-2023 Date Finished 11-28-2023 Meter 1 Reading: 41,674

TASKS PERFORMED NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
DOOR

Service Requests:

11/16/2023	DOOR / 11: FOUND TAILGATE LATCHES DRY ON LUBRICANT AND OUT OF ADJUSTMENT. / REMOVED LUBRICANT AND ADJUSTED LATCHES. VEHICLE DOORS-TRUNK DOOR WON'T OPEN
------------	---

CSHOP-2024-242

Date Opened 1-14-2024 Date Finished 1-14-2024 Meter 1 Reading: 41,963

TASKS PERFORMED NO PARTS USED

BODY EXTERIOR

CSHOP-2024-3498

Comments: TRANSFER CASE
Date Opened 7-22-2024 Date Finished 7-31-2024 Meter 1 Reading: 44,005

TASKS PERFORMED NO PARTS USED

TRANSFER CASE

Service Requests:

07/16/2024	TRANSMISSION / 12: BROKEN / OVERHAUL TRANSMISSION ISSUE, Transfer case shifting lever cotter pin, moon clip came off. The lever from the shifter to the transfer case is not secured.
------------	--

CSHOP-2024-3502

Comments: AIR CONDITIONING
Date Opened 7-22-2024 Date Finished 7-31-2024 Meter 1 Reading: 44,005

TASKS PERFORMED NO PARTS USED

HVAC SYSTEM

Service Requests:

07/22/2024	A/C / 12: BROKEN / REPAIR AIR CONDITIONING ISSUE Not blowing cold
------------	--

Asset Work Order History L00030

CSHOP-2024-3503

Comments: TAIL LIGHT
Date Opened 7-22-2024 Date Finished 8-1-2024 Meter 1 Reading: 44,005

TASKS PERFORMED NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
TAIL LIGHTS

Service Requests:
07/22/2024 LIGHTS / 12: BROKEN / REPAIR
Tail lights right side out

CSHOP-2024-3605

Comments: BODY DAMAGE
Date Opened 7-29-2024 Date Finished 7-31-2024 Meter 1 Reading: 44,005

TASKS PERFORMED NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
BODY DAMAGE ACCIDENT

Service Requests:
07/27/2024 DOOR / 12: BROKEN / REPAIR
When driving out of the bay the vehicle charging cable accidentally hooked onto rear window latch pulling it causing the metal window frame to bend and screws to dislodge. This incident occurred on a previous day and was attempted to be repaired by crew members without success. No major damage was made but some little to minor repairs need to be made

CSHOP-2024-3812

Date Opened 8-9-2024 Date Finished 9-17-2024 Meter 1 Reading: 44,058

TASKS PERFORMED NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2024-440

Comments: TAIL LIGHT
Date Opened 1-23-2024 Date Finished 2-14-2024 Meter 1 Reading: 42,102

TASKS PERFORMED Q PARTS

BATTERY
4 LMP; LAMP
1 1AD; BATTERY GROUP 65

Service Requests:
01/22/2024 LIGHTS / 12: BROKEN / REPAIR
Right tail light out.

Asset Work Order History L00030

CSHOP-2024-4764

Comments: AIR CONDITIONING
Date Opened 10-1-2024 Date Finished 10-11-2024 Meter 1 Reading: 44,058

TASKS PERFORMED NO PARTS USED

HVAC SYSTEM

Service Requests:

09/24/2024 A/C / 38: SHORTED / INSPECTED
AIR CONDITIONING ISSUE and rear alarm sensor alarm activation when in park and drive.

CSHOP-2025-1034

Comments: STARTING ISSUE
Date Opened 3-4-2025 Date Finished 3-6-2025 Meter 1 Reading: 45,120

TASKS PERFORMED Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
CRANKING SYSTEM
1 1FD; REMAN STARTER
1 1AD; BATTERY, GROUP 65
1 1FD; CORE DEPOSIT
-1 1FD; CORE DEPOSIT

Service Requests:

03/04/2025 STARTER / 11: BINDS/STICKS / VERIFIED CONCERN. PREFORMED DIAGNOSTICS. FOUND A FAUL
VEHICLE WILL NOT START/ vehicle not starting, shore line was plugged in.
03/05/2025 STARTER / 49: BINDS/STICKS / DUPLICATE CONCERN.
VEHICLE WILL NOT START

CSHOP-2025-1113

Comments: HARD STARTING
Date Opened 3-10-2025 Date Finished 3-12-2025 Meter 1 Reading: 0

TASKS PERFORMED NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
BATTERY
CRANKING SYSTEM

Service Requests:

03/07/2025 STARTER / 12: BROKEN / REPAIR
Hard start, 2nd battery showing low on charging display.
03/10/2025 STARTER / 12: BROKEN / REPAIR
the vehicle will not start

CSHOP-2025-4431

Comments: PREP FOR AUCTION
Date Opened 10-9-2025 Date Finished 10-14-2025 Meter 1 Reading: 45,120

TASKS PERFORMED NO PARTS USED

SURPLUS PREP

Asset Work Order History L00030

CSHOP-2025-822

Date Opened 2-19-2025 Date Finished 3-12-2025 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

TIRES ALL

VENDOR? DAN CALLAGHAN ENTERPRISES

Service Requests:

02/18/2025 TIRES / 12: BROKEN / EXCHANGE - NEW
Nail in passenger rear. Truck really needs all 4 tires.

RADIO-2017-57

Comments: **CALLED AC-1 ON 1/31/17. RADIO IS WORKING TODAY. THEY WILL CALL IF IT FAILS AGAIN.**

Date Opened 1-31-2017 Date Finished 1-31-2017 Meter 1 Reading: 28,564

TASKS PERFORMED

NO PARTS USED

RADIO

Service Requests:

01/28/2017 RADIO / /
RADIO ISSUES, MOBILE AIRCRAFT RADIO DOES NOT WORK. THIS IS URGENT!!!!!!

RADIO-2020-425

Comments: **ANT REPLACED**

Date Opened 5-5-2020 Date Finished 5-5-2020 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

Service Requests:

05/04/2020 RADIO / /
ANTENNA ON TOP OF VEHICLE LOOSE AND RATTLING. LARGE ONE BEHIND LIGHT BAR

RADIO-2021-1030

Comments: **NPF**

Date Opened 11-15-2021 Date Finished 11-15-2021 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

Service Requests:

11/15/2021 RADIO / /
RADIO ISSUES ----GROUND RADIO CONTINUOUS SQUELCH

Asset Work Order History L00030

RADIO-2022-1

Comments: **NPF**

Date Opened 1-3-2022

Date Finished

1-4-2022

Meter 1 Reading:

0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

Service Requests:

12/25/2021

RADIO / /

RADIO ISSUES- ATCT RADIO TOO MUCH SQUELCH / STATIC - LOOK @ RADIO WHILE @ CSHOP AFTER NEW STARTER MOTOR INSTALLED.

RADIO-2022-480

Comments: **COMPLETED**

Date Opened 6-28-2022

Date Finished

6-28-2022

Meter 1 Reading:

0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

Service Requests:

05/24/2022

RADIO / /

ATCT ANTENNA NEEDS TO BE REMOUNTED TO TOP OF CAB. NOTED THAT IT CAME DISLODGED. TRUCK WILL BE COMING TO SHOP ON MAY 24, 2022 FOR OTHER REPAIRS MAYBE IT CAN BE DONE THEN. THANK YOU

RADIO-2023-445

Comments: **TRUCK EMS OR RESCUE CAPTAIN VEHICLE: RADIO ISSUES**

Date Opened 5-5-2023

Date Finished

5-5-2023

Meter 1 Reading:

0

TASKS PERFORMED

NO PARTS USED

RADIO

Service Requests:

05/04/2023

RADIO / /

both of the ATCT radios continue to have squelch issues and unable to reduce the static coming through no matter what squelch level is set at..RADIO ISSUES. Checked both radios and no trouble found. replaced one mic.

RADIO-2024-167

Comments: **CREATE AND DELIVER PAGER TO AC1.**

Date Opened 2-5-2024

Date Finished

2-5-2024

Meter 1 Reading:

0

TASKS PERFORMED

NO PARTS USED

RADIO

Service Requests:

02/04/2024

RADIO / /

AC1 pager. Change to new battery and still not powering on.

Asset Work Order History L00030

RADIO-2025-1108

Comments: **SURPLUS PREP ON L00030.**

Date Opened 10-6-2025

Date Finished

10-6-2025

Meter 1 Reading:

0

TASKS PERFORMED

NO PARTS USED

SURPLUS PREP

Service Requests:

10/06/2025

RADIO / /

Surplus prep on Escort 1.

RADIO-2025-113

Comments: **TRUCK EMS OR RESCUE CAPTAIN VEHICLE: RADIO ISSUES**

Date Opened 2-4-2025

Date Finished

2-4-2025

Meter 1 Reading:

0

TASKS PERFORMED

NO PARTS USED

RADIO

Service Requests:

01/31/2025

RADIO / /

RADIO ISSUES, ground radio static regardless of squelch setting making it difficult to hear the tower.

RADIO-2025-219

Comments: **TRUCK EMS OR RESCUE CAPTAIN VEHICLE: RADIO ISSUES**

Date Opened 3-3-2025

Date Finished

3-3-2025

Meter 1 Reading:

0

TASKS PERFORMED

NO PARTS USED

RADIO

Service Requests:

02/28/2025

RADIO / /

Ground radio static. Can not hear other units radio traffic. Usually can hear the ATC, but the issue depends on location of the airfield. Truck has been plugged in while in quarters

RADIO-2025-224

Comments: **TRUCK EMS OR RESCUE CAPTAIN VEHICLE: RADIO ISSUES**

Date Opened 3-4-2025

Date Finished

3-4-2025

Meter 1 Reading:

0

TASKS PERFORMED

NO PARTS USED

AM - FM RADIO

Service Requests:

03/03/2025

RADIO / /

Ground radio still not working correctly on emergency alerts on the air field

Asset Work Order History L00030

RADIO-2025-374

Comments: **TRUCK EMS OR RESCUE CAPTAIN VEHICLE: RADIO ISSUES**
Date Opened 4-11-2025 Date Finished 4-11-2025 Meter 1 Reading: 0

TASKS PERFORMED **NO PARTS USED**

RADIO

Service Requests: -----
04/09/2025 RADIO / /
RADIO ISSUES VHF Radio volume is not audible, wires exposed and bad reception.

SSHOP-2023-1573

Date Opened 12-6-2023 Date Finished 2-8-2024 Meter 1 Reading: 41,719

TASKS PERFORMED **NO PARTS USED**

PM SERVICE B LIGHT

VENDOR? AL PACKER

SSHOP-2025-179

Date Opened 2-18-2025 Date Finished 2-18-2025 Meter 1 Reading: 44,580

TASKS PERFORMED **NO PARTS USED**

HVAC SYSTEM

VENDOR? AL PACKER