



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V5034

In Date: 10/23/2006

Meter Reading:

Close Date: 10/30/2006

Problem?

DRIPPING WHAT APPEARS TO BE SOME TYPE OF GREASE FROM WHAT LOOKS LIKE A CARRIER BEARING NEAR REAR
END. TANKER-72

Task performed:

1. TRAVELED TO STN 72. INSPECTED EXCESS
U-JOINT GREASE DRIPPING OFF.

Parts

NO PARTS USED

Quantity

Workorder: V5095

In Date: 10/25/2006

Meter Reading:

Close Date: 11/14/2006

Problem?

needs left rear mud flap t72

Task performed:

1. install mud flap

Parts

2436A432436A43 MUD FLAP 24X36

Quantity

1

Workorder: V5627

In Date: 12/01/2006

Meter Reading: 4,150.00

Close Date: 12/04/2006

Problem?

REPLACE CARBURATOR ON FLOAT PUMP T72

Task performed:

1. replace carburator on float pump
2. replace fuel line and shut off valve

Parts

INLINEVALVE B & S 8HP

MODEL 195702BRIGGS & STRATTON 8HP

Quantity

1

1

Workorder: V6625

In Date: 02/05/2007

Meter Reading:

Close Date: 02/21/2007

Problem?

add number plates to the side of the tender. we have the numbers, we just need the brackets added. t72

Task performed:

1. INSTALLED PLACARD HOLDERS.

Parts

NO PARTS USED

Quantity



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V8136

In Date: 05/07/2007

Meter Reading:

Close Date: 05/22/2007

Problem?

air horn button on pump panel sticking

Task performed:

R/R horn button; test ok

Parts

25-358SWITCH COVER

Quantity

1

Workorder: V8175

In Date: 05/09/2007

Meter Reading:

4,150.00

Close Date: 05/22/2007

Problem?

MARKER LIGHTS INOP, T-72

Task performed:

replaced marker light bulbs

Parts

NO PARTS USED

Quantity



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V9543

In Date: 07/25/2007

Meter Reading: 4,150.00

Close Date: 08/07/2007

Problem?

B INSPECTION AND REPAIRS AS NEEDED T72

Task performed:

1. b service
2. dump & refill floor cleaner
3. r&r all battery
4. found 2 lines on autolab system with no comp.. sleeve installed
5. remove autolab res. to clean, install rev. & prime line
6. drain coolant & refill
7. drian & refill power steering & change filter
8. r and r belts, no belts in stock, order new, old belts look good reinstalled
9. installed preconnet net
10. replace velcro on hose bed cover

Parts

Quantity

BPR5ESSPARK PLUG 7734	1
0041BRACKET TOOL	2
23-11007-125SCREW - F PAD	4
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
R90PFILTER FUEL 33231	1
035000116 INCH BRACKET	1
373-1.5E-Z LOK BRACKET	5
CYBS24268011CYBS-2426-80-11 STRAP	2
AWMBAWMB AXE WALL BRACKET	2
S777COUPLING NIPPLE	2
EXO3AH00015SPUG RAD. DRAIN	1
373-2.5E-Z LOK BRACKET	5
TB510AX HOLDER ZA115101C	1
11-20807-000PAD TUF	1
11-25747-000CLAMP A	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
30852300003085230000 DOUBLE HORIZ.	2
23-09114-0005/8 IN. C07H13 WASHER	4
11-23463-000U-BOLT 25B03	2
23-00461-0055/8 - 18 C07H26 NUT	4
5008414CARTRIDGE DC100	1
PH7405 51971 OIL FILTER WIX	2
11-20809-000PAD SPRING	1
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
HP-31DBATTERY 950CCA HP-31D	4
PAPCAXE COVER PLASTIC W/CHAIN	1
3085-195-000HORIZ.MOUNT	3
5269LPVM-5 SM MOUNT	5



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V9705

In Date: 08/03/2007

Meter Reading: 4,150.00

Close Date: 08/07/2007

Problem?

REPLACE BROKEN SPRING HANGAR WRONG ONE INSTALLED FROM FACTORY T72

Task performed:

found broken spring hangar, new one did not fit.
contacted fraghtliner found right one. installed new,
torqued u bolts

Parts

NO PARTS USED

Quantity

Workorder: V11404

In Date: 11/02/2007

Meter Reading: 623.30

Close Date: 11/30/2007

Problem?

gasket leaking around dump chute. dumping some water on ground. T72

Task performed:

1. Drive to sta. check butterfly valve, work ok. Gasket
dose not hold water in tank. Will leak untill what left in
pipe is gone.

Parts

NO PARTS USED

Quantity

Workorder: V11868

In Date: 12/03/2007

Meter Reading: 6,772.00

Close Date: 12/04/2007

Problem?

LIGHT OUT T72

Task performed:

1. L/ headlight burnt out/ replaced bulb

Parts

H4656USE CV TYPE HEAD LIGHT

Quantity

1

Workorder: V11896

In Date: 12/04/2007

Meter Reading: 629.00

Close Date: 12/05/2007

Problem?

flojet pump leaking foam t72

Task performed:

1. replace flow jet pump
2. travel to statuion

Parts

4300-505PUMP FLOJET 12V

Quantity

1



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V9557

In Date: 07/26/2007

Meter Reading: 4,150.00

Close Date: 01/14/2008

Problem?

replace hose bed cover central auto trim t72

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V12874

In Date: 01/28/2008

Meter Reading: 7,155.00

Close Date: 02/05/2008

Problem?

b inspection and repairs as needed t72

Task performed:

Parts

Quantity

B-Inspection

2. Rem drivere's side cab step to svc batteries

1/29/08 1.0 hrs

1/30/08 1.0 hrs Total 2.0 hrs

3. Replc wiper blades

4. Replc T/S side lenses j

54-15 31-15 WIPER BLADE

91513AMBER LENS

R90PFILTER FUEL 33231

PH7405 51971 OIL FILTER WIX

P1147GFUEL FILTER 33120 WIX DELCO TP916

15W40BSYN OIL BULK QTS

2

2

1

1

1

40

Workorder: V13248

In Date: 02/14/2008

Meter Reading:

Close Date: 02/15/2008

Problem?

Door ajar light and alarm in cab will not shut off. All doors are secure and closed. t72

Task performed:

Parts

Quantity

1. Adjust door switch

NO PARTS USED

Workorder: V14658

In Date: 04/24/2008

Meter Reading: 750.30

Close Date: 05/02/2008

Problem?

1 of the 3 pump panel lights are out t72

Task performed:

Parts

Quantity

1. Repaired pump panel light

1141BULB

2



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V14721

In Date: 04/28/2008

Close Date: 06/17/2008

Meter Reading: 750.30

Problem?

primer leaking water bad t72

Task performed:

1. install new pimer valve-tested ok

Parts

538028052VALVE PRIMER PUMP W/HARDWARE

Quantity

1

Workorder: V15799

In Date: 06/17/2008

Close Date: 06/24/2008

Meter Reading: 10,355.00

Problem?

DOOR AJAR LIGHT AND ALARM ON, T-72

Task performed:

Drive to stn; go to fire scene; cab door loose & booster door bad; replc tank stwl; test ok. j

Parts

52-624SWITCH DOOR

Quantity

6

Workorder: V15498

In Date: 06/03/2008

Close Date: 07/01/2008

Meter Reading: 9,806.00

Problem?

water leak in pump area t72

Task performed:

1. drive to location. remove pump panel. replace fitting . test = ok look at foam system needs head cntrl.

Parts

361000014RELAY

H6054USE CV TYPE SEALED BEAM

Quantity

2

2

Workorder: V15100

In Date: 05/14/2008

Close Date: 08/04/2008

Meter Reading: 806.10

Problem?

Situation found on 5/13/08 while on a brush fire. The situation is the foam system is not working. A code that reads Lo A appears c the foam display. T-72

Task performed:

1. Manual valve at foam tank was closed; Tried sys; still no foam; foam pump not locked up power at foam pump; but doesn't run & doesn't show flow on sys head; needs more diagnosis.
2. Travel to CS from ST72.
3. Drive to Stn72; C/O foam sys; need manual for foam logic. j

Parts

168-0380-51USE 168-0380-56-0 OLD CONTROL UNIT HALE

Quantity

1



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V15855

In Date: 06/19/2008

Close Date: 10/23/2008

Meter Reading: 851.50

Problem?

Request a back up camera installed on tender 72. It is a safety concern and a single man unit. All other have them installed

Task performed:

Parts

Quantity

1. C-Inspection
2. R/R air cleaner
3. R/R air dryer & purge valve. j

NO PARTS USED

Workorder: V17938

In Date: 09/25/2008

Close Date: 10/23/2008

Meter Reading: 11,899.00

Problem?

the dump tank on t72 has 2-3 leaks at the seams of the tarp

Task performed:

Parts

Quantity

NO PARTS USED



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V17942

In Date: 09/30/2008

Close Date: 10/23/2008

Meter Reading: 11,899.00

Problem?

c inspection and repairs as needed

Task performed:

1. Svc trans.
 2. Svc cooling sys.
 3. Svc both diff.
 4. Svc T-case.
 5. Replc batrys.
 6. R/R belts.
 7. Start to install rear view camera sys.
 8. Finish camera install.
 9. C/O foam sys; rem bad power distribution box.
 10. install new powr distribution box.
 11. Rem broken gear cover on hose reel.
 12. Troubleshoot foam sys.
 13. Start rear camera install.
 14. Finish rear view camera install.
 15. Assist camera install.
 16. Electrical test.
 17. Troubleshoot voltage drop in starter sys; chk cables; cln all positiv e /neg cable connections.
 18. R/R tank to pump & ___ valves.
 19. Continue to troubleshoot foam sys; R/R control head.
- j

Parts

Quantity

109995PURGE VALVE KIT	1
GT4100502DFBELT	1
GT4080562DFBELT	1
372000084MARKER LIGHT	1
2002501500DISTRIBUTION BOX	1
91378905 VALVE KIT 2 IN AKRON	1
HP-31DBATTERY 950CCA HP-31D	4
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
194BULB	10
30055-1030055-10 CIRCUIT BREAKER	1
1156BULB	1
52-624SWITCH DOOR	1
91398907 VALVE KIT 3 IN AKRON	2
78R536078R5360M 2PK FILTER AIR COND	1
15W40BSYN OIL BULK QTS	40
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
PH7405 51971 OIL FILTER WIX	2
R90PFILTER FUEL 33231	1
5008414CARTRIDGE DC100	1
91388906 VALVE KIT 2.5 IN AKRON	1
168-0380-51USE 168-0380-56-0 OLD CONTROL UNIT HALE	1
29526898 29548988 TRANS FILTER ALLISON	1
42610AIR FILTER CA3517	1

Workorder: V18116

In Date: 10/03/2008

Close Date: 10/23/2008

Meter Reading: 11,899.00

Problem?

repair hose bed cover and portable tank (outside agency-Central Auto)

Task performed:

Repair hose bed cover & portaboe tank - Central Auto

j

Vendor?: CENTRAL AUTO

Parts

Quantity

NO PARTS USED



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V18967

In Date: 11/10/2008

Close Date: 12/04/2008

Meter Reading: 988.20

Problem?

right rear outside flat T-72 CALLAGHAN

Task performed:

Right rear outside flat T-72 Callaghan MG

Parts

NO PARTS USED

Quantity

Vendor?: CALLAGHAN

Workorder: V19943

In Date: 12/24/2008

Close Date: 01/06/2009

Meter Reading: 13,226.70

Problem?

slight leak approx 3-4 gallons of water on the bay floor this morning unknown source T-72

Task performed:

Drive to Stn72; C/O R2R primer valve. j

Parts

538028052VALVE PRIMER PUMP W/HARDWARE

Quantity

1

Workorder: V20460

In Date: 01/20/2009

Close Date: 02/09/2009

Meter Reading: 13,566.20

Problem?

DOOR AJAR ALARM, SIREN AMP INOP, T-72

Task performed:

1. Fnd right rear side door plunger bad; R/R plunger; tightened door asy; ck opn-ck ok.
2. Fnd siren control mnt brkn; rem center console; remnted cntrl asy; ck ok. j

Parts

52-624SWITCH DOOR

Quantity

1

Workorder: V19950

In Date: 12/24/2008

Close Date: 02/18/2009

Meter Reading: 13,226.70

Problem?

REPLACE 3,000 GALLON LINER FOR FOL-DA-TANK, T-72 (ELITE FIRE)

Task performed:

Replace 3000 gal liner for FOL-DA-TANK, T72 - Elite Fire j

Parts

NO PARTS USED

Quantity

Vendor?: ELITE FIRE



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V20920

In Date: 02/06/2009

Meter Reading: 1,041.30

Close Date: 02/23/2009

Problem?

there is a water leak at or above discharge1 T72

Task performed:

Rep on W/O V20921. j

Parts

NO PARTS USED

Quantity

Workorder: V20921

In Date: 02/06/2009

Meter Reading: 1,041.30

Close Date: 02/23/2009

Problem?

there is an alarm for the doors open and all the doors are secure T72

Task performed:

1. T-shoot & rep door alarm ckt; replcd door alarm switch
2. Rep water leak at #1 discharge. j

Parts

52-624SWITCH DOOR

Quantity

1

Workorder: V21631

In Date: 03/08/2009

Meter Reading: 1,077.70

Close Date: 03/13/2009

Problem?

door alarm wont shut off on tender 72

Task performed:

Chk alarm; alarm not going off; repositioned right side fold down door sw; ck alarm not going off. j

Parts

NO PARTS USED

Quantity

Workorder: V22120

In Date: 03/26/2009

Meter Reading: 14,307.70

Close Date: 04/01/2009

Problem?

REPAIR DOOR OPEN ALARM T 72

Task performed:

1. Ck for door ajar alarm going off; Rem all door switches; alarm still on; replc door switches; T-shoot & rep wet wiring; replcd "Y" connector; made/installed water shield for node; ck ok.
2. Assist check for door alarm going off - Hines. j

Parts

B2420LP-SMUD FLAP 24 X 24
DT043PP007DEUTSCH RECEPTACLE
52-624SWITCH DOOR

Quantity

1

1

7



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V22180

In Date: 03/30/2009

Meter Reading: 1,107.90

Close Date: 04/17/2009

Problem?

Need brackets mounted for signage. This is for the drowning prevention and other signs. T72

Task performed:

Cln off side of truck to install placker on side; install top on brkt. j

Parts

NO PARTS USED

Quantity

Workorder: V22692

In Date: 04/20/2009

Meter Reading: 14,698.30

Close Date: 04/27/2009

Problem?

DOOR LARM WONT SHUT OFF T72 AT TRAINING

Task performed:

Fnd door alarm going off; R/R (20 "Y" connectors; traced & t-shoot wet connectors; dried connectors; ck opn; ck ok. j

Parts

DT043PP007DEUTSCH RECEPTACLE

2

Workorder: V22896

In Date: 04/29/2009

Meter Reading: 115,932.00

Close Date: 05/20/2009

Problem?

Large amount of oil coming out of the muffler on the float-a-pump. Possibly due to beeing stored at an angle that puts the head of the motor downward from the oil pan. Lots of smoke upon start-up. T-72

Task performed:

Driver swapped brush truck, float pump & tanker; float pump to make it fit.

Parts

NO PARTS USED

Quantity

Pump too big for compt; driver will measure.

Workorder: V23636

In Date: 05/29/2009

Meter Reading: 1,181.60

Close Date: 06/12/2009

Problem?

air leak at compression fitting on drivers seat t72

Task performed:

Rep air leak under drivers seat. j

Parts

0R80-0615-00INTERFACE MODULE

Quantity

1



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V23951

In Date: 06/09/2009

Meter Reading: 16,251.60

Close Date: 06/20/2009

Problem?

B INSPECTION AND REPAIRS AS NEEDED T72

Task performed:

- B-Inspection
2. Rep center clearance light.
3. Foam sys inop; tried to correct issues; no luck; will bring to shop.
4. Travel to/frm Stn72.
5. Replcd frt/rear input pinion seals.
6. Rem trans accumulator & resealed; reinstalled accumulator.
7. Filled auto lube sys.
8. Greased drill line.
9. Replcd wiper blades/washer pump.
10. Replcd pump panel/clearance light.
11. Adj sensor for foam sys.
12. Replcd btry switch.
13. wired lighter; plug hot all the time for GPS; okayed by Scott & Ed O.
14. Rep bulbs in ign/btry lights.
15. Chkd shoot out light; fnd swtch on cyl bad; ordered parts. j

Parts

Quantity

1227D940NUT	1
A11205X2728OIL SEAL	1
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
PH7405 51971 OIL FILTER WIX	2
R90PFILTER FUEL 33231	1
15W40BSYN OIL BULK QTS	24
2952271729552377 VALVE ASSY.ACCUM	1
29535973ACCUM.KIT	1
KIT2638PINION NUT/WASHER	1
BSHO392003501WASHER PUMP	1
1893BULB	2
A1205Q2591OIL SEAL PINION A11205A2731 NEW #	1
15W40QSYN OIL QT	8

Workorder: V23677

In Date: 05/31/2009

Meter Reading: 1,181.60

Close Date: 06/22/2009

Problem?

drivers side low beam headlight 2A1 doesnt work T72

Task performed:

- Go to Stn72; replc left lo-beam headlamp. j

Parts

Quantity

H4656USE CV TYPE HEAD LIGHT	1
-----------------------------	---



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V24147

In Date: 06/17/2009

Meter Reading: 16,251.60

Close Date: 06/24/2009

Problem?

REPLACE BAD SWITCH FOR DUMP CHUTE T72 PARTS ORDERED 6/17

Task performed:

Replcd chute swtch; still no light; traced wiring off node & dash light to chk node book; nothing in nodes; rewired swtch & added relay ok. j

Parts

Quantity

87499RY48 RELAY

1

ED24000SWITCH

1

FREIGHTSHIPPING CHARGES

1

HG01320SOLENOID VALVE

1

N251N252 WHEEL COVERS FRONT + REAR FOR ENGINE!

1

6256RJN6256RJN NUT-OUTER/RIGHT

4

H1422TSX STUD

4

Workorder: V24087

In Date: 06/15/2009

Meter Reading: 16,251.60

Close Date: 07/08/2009

Problem?

REPLACE TIRES AT SHOP CALLAGHAN

Task performed:

Replace tire at shop - Callaghan j

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V24139

In Date: 06/16/2009

Meter Reading: 16,251.60

Close Date: 07/09/2009

Problem?

hose bed cover central auto trim

Task performed:

Hose bed cover - Central Auto Trim j

Parts

Quantity

NO PARTS USED

Vendor?: CENTRAL AUTO TRIM



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V26589

In Date: 10/01/2009

Meter Reading: 1,290.10

Close Date: 10/19/2009

Problem?

excessive water leak at the pump/ transfer case tender 72

Task performed:

1. C/O water leak on tender 72; chk under truck; fnd water leak at primer pump; valve bad on pump panel.
 2. R/R primer valve on pump panel lead stop ok.
- j

Parts

538028052VALVE PRIMER PUMP W/HARDWARE

Quantity

1

Workorder: V27414

In Date: 11/04/2009

Meter Reading: 1,290.10

Close Date: 11/04/2009

Problem?

One item not charged on previous work order nb

Task performed:

1. C/O water leak on tender 72; chk under truck; fnd water leak at primer pump; valve bad on pump panel.
 2. R/R primer valve on pump panel lead stop ok.
- j

Parts

CD3009CLY WATER DRAIN

Quantity

1

Workorder: V29544

In Date: 01/29/2010

Meter Reading: 1,401.60

Close Date: 02/11/2010

Problem?

DOOR ALARM GOING OFF. T72 "J U S T R E A L L Y L O U D !!!" THANKS DEREK

Task performed:

- Travel to Stn72 from C/S; dia door open alarm sys; R/R compt L-1 door sw & compt R-1 door sw. j

Parts

52-624SWITCH DOOR

Quantity

2

Workorder: V28884

In Date: 01/06/2010

Meter Reading: 1,381.20

Close Date: 03/03/2010

Problem?

back up audible alarm not working T72

Task performed:

1. Fnd back-up alarm very quiet; needs alarm.
2. R/R back-up alarm on T-22. j

Parts

575BACKUP ALARM ECCO 107 DEC

Quantity

1



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V30868

In Date: 03/19/2010

Meter Reading: 20,268.00

Close Date: 04/27/2010

Problem?

back up camera showing blue screen of death T72

Task performed:

Parts

Quantity

1. C/O - needs new cam kit installed; need parts at shop.
2. R/R cam completely; take all parts to shop to send to factory.

NO PARTS USED

Complete at shop at time of svc by Jeff.

Workorder: V28387

In Date: 12/15/2009

Meter Reading: 18,926.90

Close Date: 04/29/2010

Problem?

REPLACE AIR CYLINDER FOR DUMP PARTS ORDERED IN T 72

Task performed:

Parts

Quantity

Dia problem w/rear wtr shoot lite inop; fnd power wire brkn; rem center console & ran new wire; adj switch - ok

NO PARTS USED

Workorder: V31022

In Date: 03/25/2010

Meter Reading: 20,322.00

Close Date: 04/30/2010

Problem?

On call air leak T72

Task performed:

Parts

Quantity

C/O; fnd gas tank vent blocked; cln, runs ok at this time; had driver test pump; he advised that it is good; he did not see vent. j

FSC17492134NC SW PARK BK SPADE TYPE CONNECTOR

1

2. Went to Stn72; fnd air leak behind dash; fnd switch leaking; R/R switch; ran/ck for leak; ck ok; return home.

j



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: **V31332**

In Date: 04/07/2010

Close Date: 05/04/2010

Meter Reading: 20,521.50

Problem?

C INSPECTION AND REPAIRS AS NEEDED T72

Task performed:

Parts

Quantity



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

C-Inspection

2. Svc btrys; rep wire term.
3. Adj air press in all tires.
4. Svc float-a-pump.
5. Replcd float-a-pump throttle; fab brkt.
6. P/S svc.
7. T-case svc.
8. Replc belts.
9. Coolant svc.
10. Cut block of alum; drill/thrd holes for hose reel roller.
11. Add 4-qts trans fluid; add washer fluid.
12. Perform dry vac; failed; rebuild hose reel valve & adj tank to pump & deck gun; perform dry vac test again; passed.
13. Rem air dryer for svc; cld not rem cartridge; replc dryer unit/fittings.
14. Replc stripped L/footmans screws w/sheet metal screws; tighten left pole holder brkt bolts; tighten L-2 striker screws; R-3 striker screws; R-3 tool brkt screws.
15. Cln/secure R-1 weatherstrip.
16. Mov hose brkt to keep hose frm rubbing against alt bolts.
17. Protect air line R/side w/spiral hose protection.
18. Replc #3 discharge cap & various cap/plug chains.
19. Dia foam sys; fnd sys out of calibration; calibrate foam sys.
20. Calibrate foam sys.
21. Replcd siren box.
22. Dia wtr leak at rear of tank; rem rear cvrs; fnd leak at rear tank fill fitting; crack in tank; vendor rep.
23. Install msng ign/btry on bulbs; replc bad bulb for ok to pump.
24. Dia problem w/R-1 door alarm; fnd wire cut below due to wire improperly connected to a grnd; connect wire properly; heat shrink connector - test ok.
25. Replcd brkn R-1 brass catches w/___ hooks to support the weight; travel to Home Depot & back for parts.
26. Replcd L-2 compt bulb.
27. Adj air horns.
28. Install backup camera components that were sent out to chk; camera still does not work; fnd blown fuse in unit module; install fuse & grnd for unit; fab brkt lost in shipping.
29. Fab brkt & sec #3 discharge pipe.
30. Chk eng codes; inspect turbo, EGR valve sensor wiring; ok; erase codes & test drive; rechk for same codes-ok; lower air to 50 PSi & drive to chk for codes; ok.
31. Quality check of veh w/scott; cln floor.
32. Reinstall rear cvrs after tank repair. j

91368904 VALVE KIT 1 1/2 IN
GT4080562DFBELT
FG87904MFG3937557S FILTER P/S NEW STYLE
P1147GFUEL FILTER 33120 WIX DELCO TP916
PH7405 51971 OIL FILTER WIX
R90PFILTER FUEL 33231
15W40BSYN OIL BULK QTS
BPR5ESSPARK PLUG 7734
800887AD-SP DROP IN DRYER COMPLETE
GT4100502DFBELT

1
1
1
1
2
1
40
1
1
1



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V31541

In Date: 04/14/2010

Meter Reading: 20,521.50

Close Date: 05/12/2010

Problem?

HOSE BED COVER T 72 CENTRAL

Task performed:

Hose bed coveer T72 - Central j

Parts

NO PARTS USED

Quantity

Vendor?: CENTRAL AUTO

Workorder: V32070

In Date: 05/07/2010

Meter Reading: 20,957.70

Close Date: 05/24/2010

Problem?

The back roll out steps on tender 72 are not secure to stand on, The right step is less secure than the left. Will not hold large amount of weight.

Task performed:

1. Fnd left rear step back; rem it to take to shop & repair
2. R/R step on back of tender & replc other bearing on other step as needed; completed. j

Parts

203FFBEARING PULLEY

Quantity

4

Workorder: V32106

In Date: 05/10/2010

Meter Reading: 20,957.70

Close Date: 06/18/2010

Problem?

drivers side rear step not working properly. mechanic removed it and took the step to the shop T72

Task performed:

Installed one other bearing in step; ok at this time. j

Parts

203FFBEARING PULLEY

Quantity

4

Workorder: V34402

In Date: 08/20/2010

Meter Reading: 22,488.60

Close Date: 09/08/2010

Problem?

tender 72 wont start batteries were new 10-2008

Task performed:

C/O truck; chk btry; all have power; chk switch-all working; fnd bad solenoid on fire wall; replc w/new; all ok at this time. j

Parts

ESX120105112STARTER RELAY ESX-120-105112

Quantity

1



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V30438

In Date: 03/04/2010

Meter Reading: 19,988.90

Close Date: 10/04/2010

Problem?

Left rear lower warning light out (LED) T72

Task performed:

1. R&R L.E.D. light left rear light ass. top one of four lights out

Parts

60R00FRR600 SERIES RED LED W/O FLANGE
0106837849C8COMP LIGHT WHITE LED 200

Quantity

1
1

Workorder: V36522

In Date: 11/17/2010

Meter Reading: 23,395.70

Close Date: 12/01/2010

Problem?

Left front stroke in grille is out. T72

Task performed:

Go to Stn22; look at lights; fnd one grill light out; rep w/new wires; program flash; ok at this time. j

Parts

NO PARTS USED

Quantity

Workorder: V37884

In Date: 01/19/2011

Meter Reading: 24,223.00

Close Date: 01/28/2011

Problem?

rear axle tires tread low t72

Task performed:

Need tires in about (1) week or 2. j

Parts

NO PARTS USED

Quantity

Workorder: V37868

In Date: 01/18/2011

Meter Reading: 24,223.00

Close Date: 02/01/2011

Problem?

nader pin safety cover broken. t72

Task performed:

Replc left rear nader pin cover; drill out to fit to truck; ok at this time. j

Parts

NO PARTS USED

Quantity



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V37462

In Date: 01/20/2011

Meter Reading: 24,400.00

Close Date: 02/02/2011

Problem?

B INSPECTION OIL CHANGE SERVICES T 72

Task performed:

- B-inspection
2. Replc btrys.
3. Did AMP draw test on starter; fnd draw 1140 AMPS at startup; fnd only (1) pos & (1) grnd off btrys; added another pos & grnd & retested; starts good.
4. Sec/protected air line to rear tank.
5. Adj tire press.
6. Replcd L/lower LED light.
7. Replcd compt door hold opens.
8. Replc velcro strap tool holder.
9. Replc flag decals.
10. Rep lights.
11. Road tested & filled w/wtr. j

Parts

Quantity

HP-31DBATTERY 950CCA HP-31D	4
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
680-10LAMERICAN FLAG W UV CLEAR LEFT	1
680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
PH7405 51971 OIL FILTER WIX	2
R90PFILTER FUEL 33231	1
15W40BSYN OIL BULK QTS	24
372000084MARKER LIGHT	1
EAA-8350-60UGSS6557UP STRUT-LIFT	3
EAA-8350-90UGSS6558UK STRUT-LIFT	3
50R03ZCRLIGHT LED RED TIR 6	1
UMVS254411STRAP 46 IN	1

Workorder: V38093

In Date: 01/27/2011

Meter Reading: 24,223.00

Close Date: 02/08/2011

Problem?

REPLACE REAR TIRES T72

Task performed:

Replace rear tires T72 - Boulevard j

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD

Workorder: V38186

In Date: 02/01/2011

Meter Reading: 24,452.80

Close Date: 02/16/2011

Problem?

replace dump chute cylinder t72

Task performed:

Replc cyl to dump chute with new from shop; working ok at this time. j

Parts

Quantity

NO PARTS USED



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V38782

In Date: 02/25/2011

Meter Reading: 24,815.20

Close Date: 03/22/2011

Problem?

On the rear of the tender, there is a plate around the 2.5 direct intake. The plate is loose and the screw that secures the plate appears striped out. T72

Task performed:

Parts

Quantity

Travel to Stn72; C/O 2.5 cover; drill/tap plate; install new bolts. j

NO PARTS USED

Workorder: V41014

In Date: 06/01/2011

Meter Reading: 26,190.20

Close Date: 06/09/2011

Problem?

RESPONED TO BRUSH FIRE IN BELLE GLADE

Task performed:

Parts

Quantity

Went to brush fire; R/R spotlight bulb on _____; on stand-by for brush fire; return home. j

Q1500T3/CLLB-M15 240 V BULB

1

Workorder: V41425

In Date: 06/18/2011

Meter Reading: 26,267.70

Close Date: 06/30/2011

Problem?

need a new foam pump it takes about 10 minutes to load 5 gallons of foam

Task performed:

Parts

Quantity

Travel to 72; R/R foam tank, fill pump; mov pump to new spot to keep away frm wtr; replumb pump & rewire unit. j

4300-505PUMP FLOJET 12V

1

Workorder: V41893

In Date: 07/08/2011

Meter Reading: 26,267.70

Close Date: 07/13/2011

Problem?

float pump is out of service. the pump is making making a noise that sounds like it is ready to blow. for now we have the float pum from brush 72 T72

Task performed:

Parts

Quantity

Travel to Stn72; PU float-a-pump; bring back to shop for small eng repair. j

NO PARTS USED



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V42899

In Date: 08/18/2011

Meter Reading: 27,133.10

Close Date: 08/30/2011

Problem?

Pump shift light is out. The pump shift still works. Light is not working. Hand tightening with no success. T72

Task performed:

Parts

Quantity

travel to st 72 check out pump shift pump is working
check out -- syst relays, fuses, etc found broken wire
under the inframe rail to pump shift switch repair test ok
return to shoop

NO PARTS USED

Workorder: V44440

In Date: 10/17/2011

Meter Reading: 27,575.00

Close Date: 11/17/2011

Problem?

B INSPECTION OIL CHANGE SERVICES

Task performed:

Parts

Quantity

1. B inspection oil change services with oil change

NO PARTS USED

Vendor?: OIL CHANGE SEVICES

Workorder: V45279

In Date: 11/18/2011

Meter Reading: 27,807.10

Close Date: 11/28/2011

Problem?

Complete C list and finish repairs from B inspection.

Task performed:

Parts

Quantity

travel to st 72 r&r nonslip tape on pass side steps
remove old tape and clean

54-15 31-15 WIPER BLADE

2

r&r wiper blades

top off grease tank for auto greaser

check out trans leak rear output shaft seal weeping will
watch, repair stems on tire order new tires



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V45465

In Date: 11/28/2011

Meter Reading: 27,856.80

Close Date: 12/05/2011

Problem?

REPLACE 2 REAR TIRES

Task performed:

REPLACE 2 REAR TIRES.

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD

Workorder: V46514

In Date: 01/11/2012

Meter Reading: 28,210.00

Close Date: 01/18/2012

Problem?

Vent saw on the tender starts and idles but dies whenever you give it any throttle. Ran it completely out of fuel and replaced with fresh with no change. Tagged and in the bay at station 72

Task performed:

CHECK OUT SAW CLEAN OUT FUEL SYSTEM AND
FILTER GET RUNNING ADJUST CARB.

Parts

NO PARTS USED

Quantity

Workorder: V47013

In Date: 02/01/2012

Meter Reading: 28,469.30

Close Date: 02/14/2012

Problem?

back scene light on passenger side out.

Task performed:

TRAVEL TO ST 72 CHECK OUT REAR LIGHT CHECK
FOR POWER AND GROUND BAD GROUND ON LIGHT
REPAIR GROUND TEST OK.

Parts

9ECAPR9ECAPR END CAP RED

Quantity

1

Workorder: V47489

In Date: 02/22/2012

Meter Reading: 28,717.00

Close Date: 02/27/2012

Problem?

Drivers side front rear tires tread low. Drivers side front read low also.

Task performed:

DRIVERS SIDE FRONT REAR TIRES TREAD LOW.
DRIVERS SIDE FRONT READ LOW ALSO.

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD TIRE CENTE



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V48269

In Date: 03/28/2012

Meter Reading: 29,112.00

Close Date: 04/05/2012

Problem?

Front left tire has extreme wear and a piece of tire is missing. t72

Task performed:

Parts

Quantity

CHECK OUT TIRE ON TRUCK ORDER NEW TIRE,
DONE.

NO PARTS USED

Workorder: V48379

In Date: 04/02/2012

Meter Reading: 29,290.00

Close Date: 04/05/2012

Problem?

REPLACE FRONT TIRE T72

Task performed:

Parts

Quantity

REPLACE FRONT TIRE T72.

NO PARTS USED

Vendor?: BOULEVARD TIRE CENTE

Workorder: V48023

In Date: 03/16/2012

Meter Reading: 28,899.10

Close Date: 04/11/2012

Problem?

Primer motor failed while attempting annual pump test. Used primery three times, 30 sec. each (allowing to cool for several min. inbetween) and primer stopped working when switch is pulled

Task performed:

Parts

Quantity

DIAGNOSE PRIMER FAILURE - FOUND SOLENOID
FAILURE - REMOVE AND INSTALL NEW SOLENOID -
TEST OPERATE - UNIT OPERATING NORMAL.

2000071102000072100 SOLENOID HALE PRIMER

1

Workorder: V48417

In Date: 04/04/2012

Meter Reading: 29,290.00

Close Date: 05/02/2012

Problem?

Install extension hose to foam drain. see R. Levy

Task performed:

Parts

Quantity

TRAVEL TO ST 72 INSTALL FOAM DRAIN HOSE KIT IN
PUMP PANEL.

NO PARTS USED



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V49387

In Date: 05/15/2012

Meter Reading: 29,704.00

Close Date: 05/30/2012

Problem?

The left side, outside light bar strobe is inoperative. T72

Task performed:

TRAVEL TO ST 72 CHECK OUT STROBE ON LT BAR
R&R TWO CORNER STROBE ASSY.

Parts

02036273300 TURBO94 CORNERLINEAR REFLECTOR

Quantity

2

Workorder: V50392

In Date: 06/25/2012

Meter Reading: 30,010.50

Close Date: 06/27/2012

Problem?

The scba bottle is leaking at the air amount guage. taken off the rack and attached a repair tag.

Task performed:

REPORTED TO SCBA SHOP.

Parts

NO PARTS USED

Quantity

Workorder: V50407

In Date: 06/26/2012

Meter Reading: 30,010.50

Close Date: 06/28/2012

Problem?

the tarp needs to be replaced

Task performed:

CHECK OUT BED COVER WILL WAIT TO REPLACE
NEXT PM

Parts

NO PARTS USED

Quantity

Workorder: V51583

In Date: 08/14/2012

Meter Reading:

Close Date: 09/14/2012

Problem?

Dump chute rubber gasket torn missing half t72

Task performed:

TRVL TO ST 72 CHK CHUTE GASKET ORDER NEW
GASKET.

Parts

NO PARTS USED

Quantity



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V51902

In Date: 08/27/2012

Close Date: 09/24/2012

Problem?

C INSPECTION T 72

Meter Reading: 30,543.00

Task performed:

Parts

Quantity



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

1. C INSPECT
2. C INSPECT
3. C INSPECT
4. REMOVE HOSE BED COVER FOR REPAIR.
5. EXHAUST RUBBING ON DRAIN SHAFT AND HALE T-CASE-FOUND LOOSE SUPPLY BRACKET MISSING ALL NUTS AND BOLTS. REPLACE MISSING SUPPORT BRACKET NUTS AND BOLTS SECURE SUPPORT BRACKET.
6. REMOVE BAD FOAM TANK TO STRAINER HOSE-CLEAN FITTING-INTSTALL PEW HOSE AND SECURELY FASTEN FILL LINE AND CHK FOR LEAK.
7. NO ANOID IN PUMP- REMOVE COVER PLATES AND INSTALL 2 ANOID IN SYST. CLEAN ALL SURFACES.
8. BELTS SERVICE ENGINE AND ALTERNATOR/ A/C COMPRESSOR REMOVE AND INSTALL NEW LEAK.
9. POWER STEERING FLUID AND FILTER SERVICE.
10. RETORQUE BOTH REAR AXLE U BOLTS AND FRT AXLE U BOLTS.
11. REAR/ REAR LFT BRAKE SHIFT FILLING ADJUST-REMOVE TIRE, DISASSEM BRAKE AND INSTALL NEW BRAKE SHOE ADJUST BRAKES.
12. AIR DYER SYST SERVICE.
13. DRIVER STEP SUPPORT BRACKET LOOSE.
14. REMOVE BAD READIATOR HOSES AND CLAMPS-INSTALL NEW HOSES AND CLAMPS-REFILL RADIATOR WITH COOLANT AND SECURE TRANSMISSION COOLER.
15. OIL SAMPLE ON BOTH REAR DIFFERENTIAL CLEAN AND SECURE LOOSE VENT TUBES.
16. PUMP COOLANT FOR VALVES INTAKE DISCHARGE, DECK GUN AND RESET ROLE PINS LOOSE AND FALLING OUT, CUT NEW PINS INSTALL AND INSURE THERE IS NO SHARP EDGES.
17. BATT ON AND IGNITION ON INDICATOR INOP- FOUND BLOWN BULB REPLACE BULBS AND THEY BLOW WHEN POWER APPLIED. OPEN DASH FOUND WIRE PINCHED TO GROUND. REPAIR FAULTY BULBS.
18. L/REAR SIDE BAD MARKER LIGHT DIM- REMOVE LED AND DOUND GROUND BOLT CORRODED-CLEAN AND REASSEMBLED LED FULLY LIT.
19. L AND R FENDER MARKER INOP ASSEMBLE LENSE BROKEN-REPLACE LENSES AND SECURE BULBS.
20. R/ R FRT AXLE LEAK REMOVE SCRADER VALVE INSTALL NEW SCRADER VALVE AND TIRE TO ROPS
21. REPLACE BAD WIND SHIELD WIPER BLADES, ADD 3 BOTTLES BUG SOLVENT AND FILL RESEVOIR WITH FLUID.
22. PUMP ALARM GOING OFF- OPERATE PUMP- ALARM GOES OFF ON CHARG OF PUMP PRESSURE.

GT4080562DFBELT
FG87904MFG3937557S FILTER P/S NEW STYLE
FGQ79699GASKET-P/S FILTER NEW STYLE
P1147GFUEL FILTER 33120 WIX DELCO TP916
PH7405 51971 OIL FILTER WIX
R90PFILTER FUEL 33231
5008414CARTRIDGE DC100
50R00FRRFLASHER RED LED FLANGED
54-15 31-15 WIPER BLADE
440-33-11/16 VALVE EXT
529008000529-0080-10-0 1 1/4 ANODE KIT
42610AIR FILTER CA3517
1891BULB
91513AMBER LENS

2
1
1
1
2
1
1
1
2
1
7
2



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

23. NO ABS LIGHT ON DASH-ABS BULB
INOP-REMOVE DASH ACCESS AND REPLACE
BLOWN BULB.

24. Q.C TRUCK.

25. R&R RGHT LOWER CORNER WARNING RIGHT
MOUNTING SCREWS BROKEN, HAD TO DRILL OUT
BROKEN SCREWS.

Workorder: V52527

In Date: 09/20/2012

Meter Reading:

Close Date: 09/26/2012

Problem?

Steady drip of water from below the truck on the passenger side just behind the pump, appears to be running down the frame rail from the rear of the truck T72

Task performed:

TRVL TO ST 72 CHK OUT WATER LEAK FOUND TANK
CRACK ON RIGHT REAR COVER OF WATER TANK
CALL TO SET UP THE SWAP AND TANK REPAIR.

Parts

NO PARTS USED

Quantity

Workorder: V52378

In Date: 09/14/2012

Meter Reading: 30,749.00

Close Date: 11/08/2012

Problem?

replace trans cooler

Task performed:

1. REPLACE TRANS COOLER.
2. REPLACE TRANS COOLER.
3. REPLACE TRANS COOLER.
4. COOLANT PIPE TO COOLER STARTING TO RUST
OUT 1 REMOVED PIPE REMOVE RUST INSTALLED
RUST PREVENTIVE AND PAINTED TEST OK.
5. AIR LEAK IN DASH WHEN BRAKE PEDAL
DEPRESSED SWITCH LEAKING/REMOVED SWITCH
ORDERED NEW.
6. AIR LEAK/SWITCH FOR ALLISION IN DASH BAD/
INSTALLED SWITCHED HAS ADDITIONAL SWITCHES
LEAKING.
7. ENG FAN STAYS ON ALL THE TIME/ FAN
SOLENOID OPENING/ ORDERED NEW SOLENOID.
8. END FAN STAYS ON ALL THE TIME/ LOSS OF
GROUND TO FAN CONTROLER/ CHECK FOR OPEN
GROUND NEED WIRING DIAGNOSE.
9. COVER FOR WATER SHOOT LOOSE/THREADS
STRIPPED DRILLED NEW THREADS AND
RE-INSTALLED COVER.

Parts

1250E473PLUG DRAIN REAR END FREIGHTLINER
TRANSYNDALLISON TRANS FLUID GAL
ANTICOOLANT ANTIFREEZE GAL
29506478SENSOR PRESSURE
29511308SENSOR PRESSURE
14820-1-5TRANS COOLER
29511307SWITCH TRANS
A06-26631-000SWITCH

Quantity

1
3
3
1
1
1
2
1



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V53150

In Date: 10/17/2012

Meter Reading: 30,921.00

Close Date: 11/08/2012

Problem?

Inspect water tank for leak. Need serial number off tank and does it need to be removed for repair.

Task performed:

Parts

Quantity

1. REMOVE AIR TANK FOR ACCESS TO REPAIR WATER TANK DRAIN WATER FROM TANK LIFT UP TRUCK FOR TANK REPAIR.
2. TIGHTEN U-BOLTS FOR REAR BODY MOUNTS/ LOOSE TIGHTEN REAR BODY U-BOLTS.
3. RE-INSTALL AIR TANK AND REPLACED DEFECTIVE 90 DEGREE SWIVEL FILLED WATER TANK.
4. REPLACE 3 ALLISON SWITCHES IN DOG HOUSE/ LEAKING/ REPLACED SWITCHES TESTED OK.

NO PARTS USED

Workorder: V53549

In Date: 11/05/2012

Meter Reading: 53,542.00

Close Date: 11/09/2012

Problem?

remove hose bed t 72

Task performed:

Parts

Quantity

1. REMOVE HOSE BED FROM TANKER FILL AND DRAIN WATER.
2. REMOVE HOSE BED COVER.
3. FILL TANK CHECK FOR LEAKS, DRAIN TANK.
4. INSTAL HOSEBED DECKING AND 2.5 PIPE.
5. REINSTALLED HOSE BED COVER, PIPE, DIVIDERS AND COVERS FILL TANK.

7001-30ESEAL

1

Workorder: V53590

In Date: 11/07/2012

Meter Reading: 53,542.00

Close Date: 11/13/2012

Problem?

Door Open Alarm

Task performed:

Parts

Quantity

COMP DOOR ALARM GOING OFF- FOUND R/R DOOR OPEN SWITCH BAD-REMOVE AND INSTALL NEW SWITCH.

52-624SWITCH DOOR

2



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V53656

In Date: 11/09/2012

Meter Reading:

Close Date: 11/16/2012

Problem?

Rear dump valve has a slow leak dripping water

Task performed:

Parts

Quantity

1. WENT TO ST 72 FOUND REAR VALVE CHK OK OPERATOR HAD DEBRIS IN FLAP CHK OK.
2. REPAIR LINKAGE ON FLOAT-A-PUMP REMOVED THROTTLE LEVER REPAIRED LINKAGE-CHK OK.

NO PARTS USED

Workorder: V55177

In Date: 01/20/2013

Meter Reading: 32,049.00

Close Date: 01/23/2013

Problem?

Air leak below cab

Task performed:

Parts

Quantity

REPAIRED EXHAUST PIPE AND AIR LINE.

NO PARTS USED

Workorder: V56040

In Date: 02/27/2013

Meter Reading: 32,263.00

Close Date: 02/28/2013

Problem?

all four tires on rear axel of Tender 72 have very little tread left. (almost smooth in some areas)

Task performed:

Parts

Quantity

ALL FOUR TIRES ON REAR AXEL OF TENDER 72 HAVE VERY LITTLE TREAD LEFT. (ALMOST SMOOTH IN SOME AREAS)

NO PARTS USED

Vendor?: BOULEVARD TIRE CENTE

Workorder: V56479

In Date: 03/18/2013

Meter Reading: 32,308.00

Close Date: 03/25/2013

Problem?

Paint peeling off roof of cab. T72

Task performed:

Parts

Quantity

CHECKOUT CAB WILL HAVE TO PRINT OVER ON NEXT P.M.

NO PARTS USED



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V56746

In Date: 04/01/2013

Meter Reading: 32,468.00

Close Date: 04/09/2013

Problem?

the front passenger side tire is extremely close to the tire ware mark T-72

Task performed:

TRAVEL TO ST 72 CHECK TIRES OK FOR NOW.

Parts

NO PARTS USED

Quantity



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V58175

In Date: 06/03/2013

Close Date: 06/13/2013

Meter Reading: 33,105.00

Problem?

B inspection T72

Task performed:

Parts

Quantity



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

1. B INSPECTION.
2. L-1 TOOL HOLDER AND L-2 DOOR LOCK LOOSE - REMOVE HOLDER AND LOCK RETAP SCREW HOLES AND REASSEMBLE; BATTERY AND IGNITION ON INDICATOR INOP - FOUND BULBS MISSING REPLACE BULBS. LIGHT OPERATING NORMAL.
3. ENGINE COMP LIGHT HANGING - REMOVE LIGHT ASSEMBLY - RETAP SCREW HOLES AND MOUNT LIGHT ASSEMBLY.
4. AIR LEAK - DIAGNOSE FAULT FOUND WATER SHOOT AIR DISTRIBUTION VALVE AND PARK BRAKE VALVE LEAKING - REMOVE WATER SHOOT VALVE INSTALL NEW AIR CONTROL VALVE, REMOVE PARK BRAKE AIR QUICK CONNECT VALVE AND INSTALL NEW ONE.
5. HOSE BED COVER LOCKING STRAPS BROKEN - REMOVE AND INSTALL REPLACEMENT.
6. MARKER LIGHTS INOP - REMOVE LED ASSEMBLY - CLEAN CONTACT ON WIRE HARNESS AND GROUNDING POINT, INSTALL NEW LED.
7. BACK UP CAMERA INOP - CHECK CAMERA CONTROLLER POWER IN BOTH FUSE GOOD - TRACE WIRE HARNESS FOUND LOOSE GROUND TO CONTROLLER IN OVERHEAD - SECURE GROUND.
8. WATER SHOOT CYLINDER PIN MISSING - REMOVE NUT AND BOLT INSTALL ??? PIN, WASHER AND COTTER PIN TO SHOOT CYLINDER.
9. HAND CRANK FOR HOSE REEL MISSING - FOUND DNI HAND CRANK - FABRICATE HOLDER FOR CRANK, WELD PIPE AND SUPPORT DRILL TAP AND MOUNT HAND CRANK IN HOSE REEL COMPARTMENT.
10. ENGINE CODES - INACTIVE - CLEAR CODES AND OPERATE UNIT NO CODE REAPPEAR. ROAD TEST.
11. FOAM SYSTEM OPERATE INTERMITTING - CLEAN STRAINER, SYMILATE FLOW TEST GOOD, OPERATE AND FLOW FOAM - FLUSH PUMP AND TOP OFF WATER TANK.
12. LEFT FRONT SIDE WARNING INOP - DIAGNOSE FAULT FOUND WIRE HARNESS CONNECTION REVERSE - CONNECT FAULT.
13. REMOVE STATION # HOLDERS, CLEAN AND POLISH SURFACE ASSEMBLY AND INSTALL NEW PLACK HOLDER AND # PLATE.
14. SERVICE BOTH REAR DIFFERENTIAL OIL.
15. BACK OF TRANSMISSION OILY - CLEAN AREA - LOOK FOR LEAK. NONE FOUND AT THIS TIME.
16. COOLANT LOW - CODE - COOLANT RESERVIOR LOW - TOP OFF COOLANT RESERVOIR PSI TEST CAP - CAP FAIL REPLACE CAP - PSI COOLING SYSTEM, FOUND HOSE AT ENGINE LEAKING - SECURE AND RETEST NO LEAKS.
17. PUMP VALVE DISCHARGE CAP NO CHAINES INSTALL 4.

P1147GFUEL FILTER 33120 WIX DELCO TP916
PH7405 51971 OIL FILTER WIX
R90PFILTER FUEL 33231
KN3100090555396 VALVE PRESSURE PTOTECTED
05-17223-000CAP RADIATOR 10 LB
35200-RLIGHT MARKER LED RED
108-12FBEADED CHAIN W/CONN 12
1893BULB

1
2
1
1
1
2
4
2



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

18. Q.C. TRUCK.

Workorder: V58524

In Date: 06/18/2013 Meter Reading: 33,327.00
Close Date: 06/28/2013

Problem?

multiple holes in the bottom of the dump tank T72

Task performed:

Parts

Quantity

CHECK OUT TANK ORDER NEW TANK GET CHEIF TO OK.

NO PARTS USED

Workorder: V59325

In Date: 07/24/2013 Meter Reading: 33,718.80
Close Date: 07/31/2013

Problem?

The front officer/passenger side tire on T72 is at the wear bars of the tread. Tire needs to be replaced.

Task performed:

Parts

Quantity

THE FRONT OFFICER/PASSENGER SIDE TIRE ON T72 IS AT THE WEAR BARS OF THE TREAD. TIRE NEEDS TO BE REPLACED.

NO PARTS USED

Vendor?: BOULEARD TIRE CENTE

Workorder: V58639

In Date: 06/24/2013 Meter Reading: 33,952.00
Close Date: 08/26/2013

Problem?

the chargers for the hand lights dont charge

Task performed:

Parts

Quantity

REPAIR WIRES TO BATTERY WIRE WRONG TO BATTERY TROUBLESHOOT PROBLEM AND REPAIR.

NO PARTS USED

Workorder: V63362

In Date: 01/14/2014 Meter Reading: 35,217.20
Close Date: 01/15/2014

Problem?

c/e light and low power

Task performed:

Parts

Quantity

CHECK OUT, DRIVER OUT TO ST 72 TENDER WITH CHECK ENG, FOUND SRS CODE 42 CLEAN AND RETEST, CLEAN CODE AND DRIVE, PARTS ORDER.

23527338SRS SENSOR

1



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V63627

In Date: 01/22/2014

Meter Reading: 35,217.20

Close Date: 01/24/2014

Problem?

Box light on driver side does not work. T72

Task performed:

DRIVER COMPLAINT BOX LIGHT INOP R&R LIGHT.

Parts

NO PARTS USED

Quantity

Workorder: V64075

In Date: 02/08/2014

Meter Reading:

Close Date: 02/11/2014

Problem?

Check engine light came on and no power

Task performed:

WENT TO 72- CHK ENG CODES- CODE 87 LOW INPUT VOLTAGE ON FUEL INLET- CHK CONNECTION- R&R 2 FUEL FILTERS TEST DROVE WITH OPERATOR- CHK OK- RETURN HOME.

Parts

R90PFILTER FUEL 33231

P1147GFUEL FILTER 33120 WIX DELCO TP916

1

1

Workorder: V64282

In Date: 02/17/2014

Meter Reading:

Close Date: 02/19/2014

Problem?

Check engine light coming on engine loses power

Task performed:

1. DRIVE TO ST. CHECK FOR ENGINE LIGHT ON. FOUND CODES FOR FUEL SENSOR AND THROTTLE. SENSOR CODES WILL COME AND GO. UNABLE TO REPAIR AT ST DRIVE UNIT TO SHOP FOR REPAIRS AND DRAG.

Parts

NO PARTS USED

Quantity

Workorder: V64273

In Date: 02/17/2014

Meter Reading:

Close Date: 03/03/2014

Problem?

Fuel gauge on pump panel not working when in pump

Task performed:

TROUBLESHOOT FUEL GUAGE ON PUMP PANELS CHECK WIRES CLEAN CONNECTIONS ON SENDING UNIT, REPLACE GUAGE.

Parts

NO PARTS USED

Quantity



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V64314

In Date: 02/14/2014

Meter Reading: 35,283.00

Close Date: 03/03/2014

Problem?

T72 low power/ check engine light

Task performed:

START TROUBLESHOOT, HAD CODE 87 FOR PUMP TRANS, CHECK ALL WIRING TEST DROVE, COULD NOT DUPLICATE PROBLEM, ORDER PUMP PRESSURE SENSOR.

Parts

Quantity

23520795DISCHARG TRNDUCR

1

301-502301-104 FUEL GAUGE

1

Workorder: V64382

In Date: 02/20/2014

Meter Reading:

Close Date: 03/11/2014

Problem?

Check engine light coming on no power T72

Task performed:

1. CHECKED CODES FOUND FLASH 41 SRS COUNTS CHECKER ELECTRICAL SYSTEM- DIAGNOSED CIRCUITS TO TRS SENSOR REPLACED TEST DROVE.

2. TEST DROVE AGAIN CHECKED CODES OK.

Parts

Quantity

23527339TIMING REF SENSOR TRS

1

Workorder: V64690

In Date: 03/04/2014

Meter Reading:

Close Date: 03/17/2014

Problem?

Fuel gauge on pump panel shows empty when in pump and full when out of pump. T72

Task performed:

1. PUMP PANEL FUEL GUAGE, INFILTRATE, TESTED WIRES MAY HAVE WRONG GUAGE WILL TRY ANOTHER GUAGE.

2. REMOVE OLD GUAGES INSTALLED NEW ONE BATH READING FULL AT THE SAME TIME, GOOD.

Parts

Quantity

301-502301-104 FUEL GAUGE

1



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V65042

In Date: 03/19/2014

Meter Reading:

Close Date: 03/28/2014

Problem?

The chain saw won't start. I ran it, revved and it conked out and won't restart.

Task performed:

CHECK OUT SAW, NO START PUT PLUG IN; TRY, NO START CHECK STOP SWITCH REMOVE NO START, THINK IT MUST BE MAG BAD. GIVE TO REGAN TO FIX.

Parts

4626BPMR7A SPARK PLUG

Quantity

2

Workorder: V65172

In Date: 03/24/2014

Meter Reading: 36,068.40

Close Date: 03/31/2014

Problem?

C INSPECTION AND REPAIRS T 72

Task performed:

1. PERFORM C-INSPECTION.
2. WORK ON C-INSPECTION.
3. TRAVEL TO STA-72 CHECK COMPUTER FOR CODES. FOUND 2 CODES LOW VOLTAGE ON TPS SENSOR. CHECK WIRING. DROVE BACK TO SHOP FOR FURTHER DIAGNOSE.
4. DRIVE TO ST-72 CHECK FENDER FOR TROBLE. FOUND CODES FOR SENSOR. CHECK SENSORS AND ARE WORKING FINE. NEEDS TO BE WORKED ON AT SHOP
5. CHECK FOR CODES, FOLLOW T.SHOOTING STEPS ON ALL CENSORS AND ENGINE WIRE HARNESS. FOUND POOR GROUND WIRE CONNECTION AT STARTER MOTOR. REPAIR. CONNECTION CLEAR CODES TEST FOR OPERATION IS GOOD SO FAR.

Parts

120257100C2030-7110-30 CLEAR DOME STEP

91581CLEAR LENS

1142BULB

54-15 31-15 WIPER BLADE

PH7405 51971 OIL FILTER WIX

42610AIR FILTER CA3517

15W40BSYN OIL BULK QTS

5008414CARTRIDGE DC100

109995PURGE VALVE KIT

Quantity

1

1

1

2

2

1

43

1

1

Workorder: V65348

In Date: 04/01/2014

Meter Reading:

Close Date: 04/08/2014

Problem?

the dump tank has a tear on the bottom . i would like to see if we can patch it before it gets worse. their is no depth guard on the vent saw . T72

Task performed:

ADJUSTED CREW TO GET W/D/C FOR TANK REPAIRS AND SAW PARTS MUST GO THROUGH CHAMBERS.

Parts

NO PARTS USED

Quantity



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V67529

In Date: 06/28/2014

Meter Reading:

Close Date: 07/07/2014

Problem?

PA mic detached from the wires B 72

Task performed:

Driver complaint of PA mic broken. Replaced siren heac

Parts

295SLSA1SIREN

Quantity

1

Workorder: V65144

In Date: 03/24/2014

Meter Reading: 36,068.40

Close Date: 07/17/2014

Problem?

Check engine light on/running rough

Task performed:

repairs done in ticket v65172

Parts

NO PARTS USED

Quantity

Workorder: V68192

In Date: 07/26/2014

Meter Reading:

Close Date: 07/29/2014

Problem?

Turn signals out T72

Task performed:

travel to sta,72 no turn signal or 4 ways look for fuse in panel never found, harness for signal sw, unplugged and plugged back in working ok.

Parts

NO PARTS USED

Quantity

Workorder: V68556

In Date: 08/10/2014

Meter Reading: 37,974.00

Close Date: 08/18/2014

Problem?

Rear tires tread low T72

Task performed:

Checked tires, already replaced.

Parts

NO PARTS USED

Quantity



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V68960

In Date: 08/26/2014

Close Date: 08/28/2014

Meter Reading: 38,141.00

Problem?

replace rear tires on E72

Task performed:

Replace rear tires on E72.

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD TIRE CENTE

Workorder: V69026

In Date: 08/28/2014

Close Date: 09/02/2014

Meter Reading:

Problem?

Need new ignition key old one bent

Task performed:

shop drop off new keys

Parts

1669309C2KEY

Quantity

6

Workorder: V69389

In Date: 09/15/2014

Close Date: 09/17/2014

Meter Reading: 38,344.00

Problem?

float-a-pump pull start chord broken. Unit inoperable.

Task performed:

Flout a pump pull card broken disassemble engine from tank. Removed pull cord hosing rerouted cord and reassemble pump.

Parts

NO PARTS USED

Quantity

Workorder: V69251

In Date: 09/09/2014

Close Date: 09/22/2014

Meter Reading:

Problem?

Pull start rope on float a pump broken

Task performed:

replaced pull starter rope on pump motor.

Parts

NO PARTS USED

Quantity



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V70313

In Date: 10/21/2014

Meter Reading: 38,825.00

Close Date: 11/10/2014

Problem?

Need a new fuel cap for float a pump

Task performed:

Replaced fuel cap on front pump

Parts

07-02517620-ZL8-003 HONDA FUEL CAP

Quantity

1

Workorder: V71515

In Date: 12/09/2014

Meter Reading: 39,106.40

Close Date: 12/11/2014

Problem?

HOSEBED COVER DAMAGED.

Task performed:

central repaired cover

Parts

NO PARTS USED

Quantity

Vendor?: CENTRAL

Workorder: V71730

In Date: 12/18/2014

Meter Reading: 39,397.00

Close Date: 12/29/2014

Problem?

Replace dash knob

Task performed:

Replaced broken knob for wiper switch

Parts

22-23372-001KNOB

Quantity

1



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V71183

In Date: 11/25/2014

Close Date: 01/06/2015

Meter Reading: 39,106.40

Problem?

B inspection T72

Task performed:

Parts

Quantity



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Trouble shot radiator fan staying on. Could not determine cause. ECM pinout chart will be needed for further diagnostics.

1. "B" inspection
2. Diagnose digital pressure gauges inop. disassembled pump panel, checked sensors and calibrated. Checked wiring harness, pressure gauge display failed.
3. Fabricated pump gauge panel from a sheet of stainless steel.
4. Help cut out plate for water and foam gauge out of s/s, cut plate cutter
5. Repaired loose ladder compartment switch bracket. Bracket is loose and hanging-retapped all fastener threads and installed new fasteners.
6. Installed wiper blades and topped off washer fluid tank
7. Replaced missing, left intake and #2 discharge caps-installed missing or broken safety chains on 3 pump caps.
8. Removed campaign signs and metal brackets
9. Replaced missing battery on and ignition on dash lamp bulbs-replaced failed right rear underbody work lamp.
10. Adjusted tire pressure on 3 axles all tires 15-25 PSI low
11. Rear work steps and latches dragging/seized-lubricated wheels, bearings and slides to loosen rust. Cleaned and lubed all to allow proper operation.
12. P/S system overdue for service-drained and flushed system-refilled to spec and bled air.
13. Installed new digital pump intake and discharge gauges, transducers and wiring harness. Reassembled pump panel-calibrated transducers ran pump to verify proper operation.
14. Class 3 leak-found at transmission output seal. R&I driveshaft, replaced output shaft seal and o-ring. Service transmission and replaced filters-filled to specs.
15. Replaced worn anodes on right intake and rear discharge ports-installed anode kit on left intake.
16. Installed repaired hosebed cover and installed new rear tie down straps.
17. Repaired loose upper, rear grab bar-drilled, tapped and installed new fasteners.
18. Removed and cleaned old grease from chassis autoluber. Filled reservoir with correct lube, verified proper operation.
19. Found excessive overnight leak down in air system-using soapy water. Found leak at valve disconnects, replaced disconnects. Verified system holding pressure
20. Found radiator clutch fan always on-preformed initial diagnostic. Vehicle will return for further diag and repair.

1893BULB	2
621714 IN LIGHT	1
108-12FBEADED CHAIN W/CONN 12	3
54-15 31-15 WIPER BLADE	2
29526898 29548988 TRANS FILTER ALLISON	1
529008000529-0080-10-0 1 1/4 ANODE KIT	1
029-0511-00-0ANODE ONLY	2
PSISDIDITAL VACUUM GAUGE KIT	2
S777COUPLING NIPPLE	4
HO9932493282/993282 SOLENOID VALVE SUTPHEN	1
29552703REAR SEAL 4000EVS ALLISON	1
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
R90PFILTER FUEL 33231	1
PH7405 51971 OIL FILTER WIX	2
6.5-70-18XSTRAP U-JOINT	1



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154943

FLD 120 TENDER 72

Workorder: V72148

In Date: 01/09/2015

Close Date: 01/29/2015

Meter Reading: 39,591.00

Problem?

Replace Headlights T72

Task performed:

1. Installed headlights in T72.

Parts

Quantity

H4656CVH4656CVC1 LOW BEAM CRYSTAL VISION

2

Workorder: V72676

In Date: 01/28/2015

Close Date: 02/05/2015

Meter Reading:

Problem?

Air leak losing pressure within an hour

Task performed:

Travel to ST 72. Replaced several leaking fittings on air tanks.

Parts

Quantity

103385NDRAIN COCK

4

Workorder: V74745

In Date: 04/17/2015

Close Date: 04/17/2015

Meter Reading:

Problem?

backup camera not working

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V74571

In Date: 04/10/2015

Close Date: 09/08/2015

Meter Reading: 40,474.00

Problem?

trans not shifting

Task performed:

parts only

Parts

Quantity

29544139REAR SPEED SENSOR ALLISON

1

29543432INPUT SENSOR ALLISON

1



Palm Beach County Fire Rescue

Fleet Maintenance Asset History

Asset: (10154943) 2003 - FERRARA FLD120SD Tender St2

10154943

CSHOP-2015-129

Comments: BACK UP CAMERA INOP TENDER 72

Date Opened 4-17-2015

Date Finished

4-27-2015

Meter 1 Reading:

40,500

TASKS PERFORMED

NO PARTS USED

BACK UP CAMERA-MONITOR

CSHOP-2015-2350

Comments: CHECK ENG LIGHT COMES ON T72 DRIVER KEEPS ADDING COOLANT NO LEAKS SHOWING 8/22 COOLANT LOW AGAIN, ADDED 1/2 GALLON OF WATER

Date Opened 8-17-2015

Date Finished

8-25-2015

Meter 1 Reading:

40,500

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
COOLING SYSTEM

CSHOP-2015-3204

Comments: T72 LIGHT OUT

Date Opened 10-2-2015

Date Finished

10-8-2015

Meter 1 Reading:

42,718

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM

1 LIGHT; MARKER LIGHT

Service Requests:

10/02/2015

LIGHTS / 12: BROKEN / REPLACED MARKER LIGHT
TOP DRIVER SIDE SMALL RED LIGHT ON THE REAR OF VEHICLE IS NOT WORKING.

CSHOP-2015-3855

Comments: T72 TIRE CHANGED 11/7 CALLED IN BY JEFF

Date Opened 11-9-2015

Date Finished

12-10-2015

Meter 1 Reading:

44,636

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? EARL COLVARD BOULEVARD TIRE

Service Requests:

11/07/2015

TIRES / 18: LEAKING / EXCHANGE - NEW
FRONT DRIVER TIRE PAST WEAR BAR....NEEDS IMMEDIATE CHANGE

Asset Work Order History 10154943

CSHOP-2015-4050

Comments: **CHECK ENGINE LIGHT ON T72**

Date Opened 11-19-2015 Date Finished 11-20-2015 Meter 1 Reading: 43,584

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES

3 FLUID; 50-50 EXTENDED LIFE COOLANT GAL

CSHOP-2015-4217

Comments: **T72 CROSS LAY VALVE LEAKING THE VALVE TO OPEN THE DECK GUN IS EXTREMELY DIFFICULT TO OPERATE, SOMETIMES IMPOSSIBLE. WE HAVE DONE MAINTENANCE AT THE STATION LEVEL -IE: WD40. HOIWEVER, THIS SHOULD BE LOOKED AT IN FURTHER DETAIL .**

Date Opened 11-30-2015 Date Finished 12-10-2015 Meter 1 Reading: 44,636

TASKS PERFORMED

Q PARTS

CONTROL VALVE

2 VALVE; 8905 VALVE KIT 2 IN AKRON

Service Requests:

11/28/2015 SERVICE REQUEST / 18: LEAKING / EXCHANGE - NEW
CROSSLAY #1 VALVE LEAKING CHARGING HOSE ON EXTENEDED PUMPING OPERATIONS

CSHOP-2015-4300

Comments: **T72**

Date Opened 12-4-2015 Date Finished 12-23-2015 Meter 1 Reading: 44,988

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
INTAKE VALVE
DOOR

Service Requests:

12/03/2015 ALARMS / 12: BROKEN / REPAIRED DOOR AJAR SWITCH
DOOR AJAR BUZZER STAYS ON

12/03/2015 SERVICE REQUEST / 18: LEAKING / REBUILT DISCHARGE VALVE
I NEED AN INTERNAL GASKET FOR THE PISTON INTAKE VALVE ON THE TENDER AKRON 7890 PISTON INTAKE VALVE

CSHOP-2015-4546

Comments: **FOAM FROM ALL DISCHARGES T72**

Date Opened 12-18-2015 Date Finished 2-3-2016 Meter 1 Reading: 45,425

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FOAM SYSTEM
REAR TIRES

1 VALVE; CHECK VALVE INJECTOR HALE FOAM SYS.

Service Requests:

12/18/2015 SERVICE REQUEST / 18: LEAKING / EXCHANGE - NEW
PUMP FLOWING FOAM OUT OF ALL DISCHARGES.

01/15/2016 TIRES / 44: WORN / EXCHANGE - NEW REPLACE 4 REAR TIRES

Asset Work Order History 10154943

CSHOP-2015-882

Comments: **DOOR OPEN WARNING ON T72**

Date Opened 6-1-2015

Date Finished

6-3-2015

Meter 1 Reading:

40,500

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
REAR DOOR

CSHOP-2015-971

Comments: **LOCKS FOR CROSSLAYS NEEDS TO BE REPLACED T72**

Date Opened 6-3-2015

Date Finished

6-16-2015

Meter 1 Reading:

40,500

TASKS PERFORMED

NO PARTS USED

BODY EXTERIOR

CSHOP-2016-1145

Comments: **C-INSPECTION TENDER 72**

Date Opened 3-9-2016

Date Finished

3-24-2016

Meter 1 Reading:

46,200

TASKS PERFORMED

Q PARTS

PM SERVICE C

38 MOTOR; 15W40 MOTOR OIL NON SYN
1 FILTER; FUEL FILTER 33120 WIX DELCO TP916
2 FILTER; 51971 OIL FILTER WIX
1 FILTER; FILTER FUEL 33231

CSHOP-2016-1146

Comments: **TENDER 72 PM FOLLOW UPS POSSIBLE FOAM SYSTEM CHECK VALVE PROBLEM POSSIBLE EGR COOLERS LEAKING**

Date Opened 3-9-2016

Date Finished

7-27-2016

Meter 1 Reading:

48,050

TASKS PERFORMED

Q PARTS

FOAM SYSTEM
FIRE FIGHTING EQUIPMENT
FIRE PUMP CONTROLS
FIRE PUMP PLUMBING
PRIMING PUMP FIRE PUMP
WIPER BLADES
ENGINE AND ACCESSORIES
TURN SIGNAL LIGHTS
LIGHTING SYSTEM
TRANSMISSION
AIR SYSTEM
HOOD LATCH
BODY EXTERIOR
HVAC SYSTEM

1 MEDIC MASTER; HGR-1 HELMET HOOK
1 NEWPART; THROTTLE CATCH
1 SAW; SAW GAURD
1 NEWPART; SPRING LOCK TEMPEST
1 9IP; LENS AMBER
1 LIGHT; HALE RED INDICATOR LED
1 BULB; BULB
1 VALVE; VALVE PRIMER PUMP W/HARDWARE
1 BULB; BULB
2 NEWPART; LED SCENE
1 FLUID; ALLISON TRANS FLUID GAL
2 9IP; HOOD LATCH
1 LIGHT; 854213 LIGHT GUIDE BUMPER
4 LED SCENE
2 MOUNT; LG MOUNT
1 9IP; 1229 RESISTER BLOWER
1 NEWPART; LOUVER

Asset Work Order History 10154943

CSHOP-2016-229

Comments: **T72 DOOR ALARM INTERMITTENT**

Date Opened 1-19-2016

Date Finished

2-3-2016

Meter 1 Reading:

45,425

TASKS PERFORMED

NO PARTS USED

DOOR

Service Requests:

01/17/2016

ALARMS / 19: LOOSE / REPAIR

DOOR ALARM GOING OFF INTERMITTENTLY

CSHOP-2016-2635

Comments: **T72 LOW AIR FLOW THROUGH A/C VENTS**

Date Opened 6-2-2016

Date Finished

6-2-2016

Meter 1 Reading:

46,550

LOW AIR FLOW AT AC VENTS

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

CSHOP-2016-2811

Comments: **T72**

Date Opened 6-13-2016

Date Finished

6-21-2016

Meter 1 Reading:

46,777

AIR LEAKS DRIVER SEAT ECT CK, OUT

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
GROUND LIGHT BODY
AIR SYSTEM

3

9IP; 4 IN ROUND LED

1

9IP; BOS6222084001 KIT AIR

Service Requests:

06/13/2016

SEATS / 18: LEAKING / EXCHANGE - NEW

DRIVER SEAT LEAKING CAUSING AIR SYSTEM TO LEAK DOWN TO 50 PSI

CSHOP-2016-3261

Date Opened 7-6-2016

Date Finished

7-6-2016

Meter 1 Reading:

47,278

TASKS PERFORMED

NO PARTS USED

FIRE PUMP

Service Requests:

07/06/2016

SERVICE REQUEST / 18: LEAKING / ADJUST

PUMP LEAK

Asset Work Order History 10154943

CSHOP-2016-3494

Date Opened 7-21-2016 Date Finished 7-21-2016 Meter 1 Reading: 47,917

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

Service Requests:

07/21/2016 SERVICE REQUEST / 18: LEAKING / CORRECT A LEAKING FITTING STILL LOOSING AIR WHEN PAI
AIR LEAK LEAKING DOWN OVER A FEW HRS TO BELOW 50 PSI

CSHOP-2016-3578

Comments: I/O BOARD FOR LIGHT BAR PART IS HERE T72 VOLTAGE DROPS WHEN EMERGENCY LIGHTS ARE ON

Date Opened 7-27-2016 Date Finished 9-7-2016 Meter 1 Reading: 48,850

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
CHARGING SYSTEM
AIR SYSTEM
LIGHT BAR

1 MOUNT; 4949PA/4962 320 AMP UPGRADE SADDLE MOUNT
4 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY
4 BATTERY; BATTERY 950CCA HP-31D
1 VALVE; VALVE PARKING BRK.
-1 BOARD; IO BOARD
1 REFLECTOR; OBSOLETE 1/2016 TURBO94 CORNERLINEAR
REFLECTOR
1 BOARD; IO BOARD

CSHOP-2016-3820

Comments: T72 FOAM SYSTEM

Date Opened 8-5-2016 Date Finished 9-19-2016 Meter 1 Reading: 49,186

TASKS PERFORMED

NO PARTS USED

FOAM SYSTEM
EQUIPMENT MOUNTING BRACKETS
CHARGING SYSTEM
AIR SYSTEM

Service Requests:

08/05/2016 SERVICE REQUEST / 35: RUSTED/CORRODED / REPAIR
NIPPLE FOR FOAM SYSTEM CORRODED HOSE FELL OFF FOAM SYSTEM OOS

Asset Work Order History 10154943**CSHOP-2016-4507**

Date Opened 9-16-2016

Date Finished

10-21-2016

Meter 1 Reading:

50,289

TASKS PERFORMED**Q PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE FIGHTING EQUIPMENT
FIRE APPARATUS
AIR SYSTEM
DOOR HANDLES INSIDE-OUTSIDE

2 DRAIN; DRAIN COCK
1 HANDLE; DOOR HANDLE NON LOCKING

Service Requests:

08/17/2016 SERVICE REQUEST / 18: LEAKING / EXCHANGE - NEW
REAR SEAL OF CHUTE IS WORN BADLY. CAUSES CHUTE TO HAVE PROBLEMS COMING IN AND OUT. IT WILL GET STUCK ABOUT HALF WAY IN AND OUT. WITH A LITTLE PERSUASION IT WORKS.

09/15/2016 STARTER / 12: BROKEN / REPAIR
VEHICLE WILL NOT START, NEED TO INSTALL A SHORELINE SYSTEM TO KEEP TRUCK ON CHARGE. THE TRUCK DOES START, I JUST DID NOT HAVE A BATTERY OPTION TO PUT IT IN. THANKS AGAIN.

09/28/2016 SERVICE REQUEST / 18: LEAKING / REPAIR
SERVICE REQUEST MAJOR AIR LEAK

09/30/2016 DOOR / 12: BROKEN / NEW
PASSENGER REAR DOOR WONT OPEN LOOK IS PULLING AWAY FOR THE DOOR ITSELF AND WONT OPEN IF FORCE OPEN DOOR WONT BE ABLE TO LOCK

10/06/2016 SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW
SERVICE REQUEST- DOOR ON PASSENGER SIDE COMPARTMENT THAT ALLOWS ACCESS TO THE FRONT OF THE DUMP TANK WILL NOT OPEN. LOCK WONT RELEASE WHILE THE DOOR IS PULLING AWAY FROM THE MECHANISM.

CSHOP-2016-4614

Date Opened 9-23-2016

Date Finished

9-30-2016

Meter 1 Reading:

49,840

TASKS PERFORMED**NO PARTS USED**

ELECTRICAL
AIR SYSTEM

CSHOP-2016-5165Comments: **AIR LEAK**

Date Opened 10-31-2016

Date Finished

11-1-2016

Meter 1 Reading:

50,675

TASKS PERFORMED**Q PARTS**

WIPER BLADES
AIR SYSTEM

2 NEWPART; WIPER BLADE 15"

Service Requests:

10/31/2016 SERVICE REQUEST / 12: BROKEN / REPAIR
CAN WE REPLACE THE 1980'S YELLOW FOG LIGHTS WITH HID DRIVING LIGHTS

Asset Work Order History 10154943

CSHOP-2016-5314

Date Opened 11-14-2016 Date Finished 11-18-2016 Meter 1 Reading: 50,955

TASKS PERFORMED

Q PARTS

AIR SYSTEM
STROBE LIGHTS

1 LIGHT; 600 SERIES RED LED W/O FLANGE

Service Requests:

11/14/2016 ALARMS / 12: BROKEN / REPLACED WITH NEW
ALARM SIGNALS, FRONT GRILL LED WARNING LIGHTS NOT WORKING.

CSHOP-2016-545

Comments: E-72 SCENE LIGHT OUT

Date Opened 2-3-2016 Date Finished 3-3-2016 Meter 1 Reading: 46,116

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
QUARTZ LIGHT

1 LIGHT; SCENE LIGHT

Service Requests:

02/03/2016 LIGHTS / 12: BROKEN / REPLACED SCENE LIGHT
DRIVER SIDE REAR SCENE LIGHT NOT WORKING

CSHOP-2016-5529

Comments: BATTERY SWITCH FAULTY REAR OF TANK NEEDS TO BE REPAIRED

Date Opened 11-28-2016 Date Finished 12-8-2016 Meter 1 Reading: 51,567

TASKS PERFORMED

Q PARTS

FIRE PUMP PLUMBING
CRANKING SYSTEM

2 LIGHT; LOW BEAM LED
2 LIGHT; HIGH BEAM LED
1 SWITCH; SWITCH BATTERY MASTER 300A

Service Requests:

11/23/2016 SERVICE REQUEST / 12: BROKEN / REPAIR
SERVICE REQUEST SPARK PLUG CAP ON T72 FLOATER PUMP DAMAGED NEEDS REPLACING.

Asset Work Order History 10154943**CSHOP-2016-5839**Comments: **T72**

Date Opened 12-14-2016 Date Finished 12-21-2016 Meter 1 Reading: 51,942

TASKS PERFORMED**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE PUMP PLUMBING
AIR SYSTEM

Service Requests:

12/14/2016 SERVICE REQUEST / 18: LEAKING / REPAIR

12/16/2016 ENGINE / 12: BROKEN / EXCHANGE - USED
THE FLOAT-A-PUMP ON TENDER 72 IS NOT WORKING. IT IS UNABLE TO BE STARTED AND IS LEAKING OIL AND GAS.**CSHOP-2016-6019**Comments: **TENDER -72 WATER LEAK AND AIR LEAK**

Date Opened 12-27-2016 Date Finished 1-9-2017 Meter 1 Reading: 52,048

TASKS PERFORMED**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE PUMP PLUMBING
REAR TIRES

Service Requests:12/24/2016 SERVICE REQUEST / 18: LEAKING / INSPECT
SERVICE REQUEST, AIR PRESSURE LEAK, WATER LEAK UNDER PUMP12/30/2016 TIRES / 44: WORN / INSPECT
BAD TIRES ON REAR OF TENDER**CSHOP-2016-832**Comments: **T72**

Date Opened 2-22-2016 Date Finished 2-24-2016 Meter 1 Reading: 45,683

TASKS PERFORMED**Q PARTS**

SIDE COMPARTMENT BODY

1 SHELF; TURTLE TILE 12X12 BLACK

Service Requests:02/22/2016 SERVICE REQUEST / 19: LOOSE / EXCHANGE - NEW
DISCHARGE 2 AND DECK GUN VALVES LEAKING**CSHOP-2017-1077**

Date Opened 2-21-2017 Date Finished 3-3-2017 Meter 1 Reading: 53,369

TASKS PERFORMED**Q PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER
DOOR

1 9IP; DOOR HANDLE W/LOCK
1 9IP; LATCH ASSY. FOR D-PADDLE HANDLE

Asset Work Order History 10154943**CSHOP-2017-1249**

Date Opened 2-28-2017

Date Finished

5-8-2017

Meter 1 Reading:

54,577

TASKS PERFORMED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE FIGHTING EQUIPMENT
FIRE PUMP PLUMBING
PUMP PANEL
EQUIPMENT MOUNTING BRACKETS
HOSE BED BODY
SIDE COMPARTMENT BODY
FIRE APPARATUS
WASHER NOZZLE
SPOT LIGHTS
LIGHTING SYSTEM
CHARGING SYSTEM
SWITCH-ELECTRICAL
FLUID
AIR SYSTEM
LIGHT BAR
EMERGENCY EQUIPMENT

Q PARTS

1	5SC; O-RING
1	5SC; WEAR STRIP TFT
1	SWITCH; EXTENDA GUN SWITCH
1	NONSTOCK; FREIGHT CHARGE
1	5SC; O-RING
1	5SC; CUP SEAL TFT
1	HANDLE; 88301201 3 IN SLO-CLOZ W/R1 HANDLE
1	NONSTOCK; FREIGHT CHARGE
1	9AP; 9AP
3	5SC; THREADED TRUNNION 2"
3	5SC; FEILD SERVICE KIT 2.5
4	5SC; FEILD SERVICE KIT 2.5
1	5SC; TS ACTUATOR HANDLE 2.5 VALVE
1	9HW; 1/8 RIVETS
1	5SC; 3"
1	NEWPART; FUSE HOLDER
2	9IP; 2030-7110-30 CLEAR DOME STEP
2	NEWPART; FUSE HOLDER
1	6KU; AUTO EJECT 20A
1	5TN; AUTO CHAGRE 2000
1	ECH; SWITCH
1	STRUT; GSS6557UP STRUT-LIFT
1	VALVE; VALVE AIR CONTROL
1	5EF; 5EF
2	VALVE; VALVE AIR CONTROL
1	9LL; SPARE KIT AIR COMPRESSOR
1	NONSTOCK; FREIGHT CHARGE

Service Requests:

02/28/2017

SERVICE REQUEST / 41: TORN/PUNCTURED / REMOVE HOSE BED COVER FOR OUTSIDE REPAIR
NEEDS NEW HOSE BED COVER

CSHOP-2017-1319

Date Opened 3-3-2017

Date Finished

3-10-2017

Meter 1 Reading:

53,937

TASKS PERFORMED

PM SERVICE B

Q PARTS

1	FIL; NAPAGOLD AIR FILTER
1	FILTER; FUEL FILTER 33120 WIX DELCO TP916
38	9OC; SYN 15W40
1	FIL; NAPAGOLD FUEL FILTER
-1	FIL; NAPAGOLD OIL FILTER
2	FIL; NAPAGOLD OIL FILTER
1	FIL; NAPAGOLD OIL FILTER

Asset Work Order History 10154943

CSHOP-2017-1459

Date Opened 3-9-2017 Date Finished 4-27-2017 Meter 1 Reading: 53,369

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM

Service Requests:

03/08/2017 ENGINE / 49: CAN NOT DUPLICATE CONCERN / PREFORMED COOLING SYSTEM PERFORMANCE
ENGINE PUMP TEST TEST STOPPED AT 14:52 DUE TO ENGINE TEMP 220. HAD ENGINE COOLER ON BUT IT DIDNT
HELP. DISCHARGE 1,2, AND INTAKE 3" ON DRIVER SIDE AIR LEAK. FAILED DRY VAC TEST.

CSHOP-2017-1553

Date Opened 3-13-2017 Date Finished 3-13-2017 Meter 1 Reading: 53,369

TASKS PERFORMED

NO PARTS USED

REAR TIRES

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2017-1899

Comments: **NEXT A SHIFT, TRY TO MEET TANKER 72 ON TUESDAY 4-4-17 SERRANO 786-201-1969**

Date Opened 3-30-2017 Date Finished 5-11-2017 Meter 1 Reading: 54,577

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
EQUIPMENT MOUNTING BRACKETS
ENGINE AND ACCESSORIES

1 2IH; FAN CLUTCH

Service Requests:

03/29/2017 ENGINE / 12: BROKEN / INSPECT
FAILED PUMP TEST DUE TO OVERHEATING. ENGINE COOLER UNABLE TO KEEP THE TENDER FROM REACHING 220.

CSHOP-2017-2043

Date Opened 4-7-2017 Date Finished 4-19-2017 Meter 1 Reading: 54,233

TASKS PERFORMED

Q PARTS

STROBE LIGHTS

2 1WL; LENS
2 LIGHT; 600 SERIES RED LED W/O FLANGE
2 LIGHT; 600 SERIES RED LED W/O FLANGE
-1 LIGHT; 600 SERIES RED LED W/O FLANGE
1 LIGHT; 600 SERIES RED LED W/O FLANGE
-2 LIGHT; 600 SERIES RED LED W/O FLANGE

CSHOP-2017-2373

Comments: **ON-CALL COMP DOOR ALARM**

Date Opened 4-24-2017 Date Finished 5-8-2017 Meter 1 Reading: 54,577

TASKS PERFORMED

Q PARTS

DOOR ALARM OR OTHER WARNING

2 5TN; SWITCH DOOR DPST NC MOM

Asset Work Order History 10154943**CSHOP-2017-3165**Comments: **CHECK FOR OVERHEATING DURING PUMP TEST**

Date Opened 5-30-2017

Date Finished 12-8-2017

Meter 1 Reading: 58,252

TASKS PERFORMED

EQUIPMENT MOUNTING BRACKETS
FUEL SYSTEM
THERMOSTAT
FAN CLUTCH
COOLING SYSTEM
SERPENTINE BELT TENSIONER
HVAC SYSTEM

Q PARTS

1	9AP; QUICK LINKS
1	BK; AUTOMOTIVE GOOP
-1	9IP; STRAP 36IN
1	9IP; STRAP 36IN
2	9IP; STRAP 46 IN
-1	5SC; STRAP
1	5SC; STRAP
1	2AW; T-RING
1	2AW; VIB, ASSETWORKS
2	2DD; THERMOSTAT
1	NBH; TENSIONER-HEAVY DUTY
1	9AP; HAND SOAP PUM (TOTAL TRK)
1	2FL; COOLANT SENDING
1	2FL; COOLANT SENSOR TEMP
1	2FL; COOLANT SENSOR
1	TWD; VALVE 3 WAY
1	NBH; FLEETRUNNER BELT
1	NBH; FLEETRUNNER BELT
1	NBH; TENSIONER-HEAVY DUTY
60	9OC; COOLANT
-60	9OC; COOLANT
1	NCB; DEGREASER MULTI PURP
1	NCB; BLASTER PENETRANT
1	5FF; TRANS COOLER
1	5FF; RADIATOR
1	NONSTOCK; FREIGHT CHARGE
1	2FL; CHARGE AIR
1	2FL; RAD HOSE TOP
1	9HY; TURBO HOSE
1	9HY; TURBO HOSE
1	9IP; CAP RADIATOR 10 LB
60	FLUID; COOLANT ANTIFREEZE GAL
1	2FL; INSULATOR
2	NBH; SILICONE COOLANT HOSE
3	9XX; 134A 10194654

CSHOP-2017-3569Comments: **PRIMMER STUCK ON.**

Date Opened 6-16-2017

Date Finished 6-19-2017

Meter 1 Reading: 55,797

TASKS PERFORMED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE PUMP PLUMBING

Q PARTS

1	9IP; VALVE PRIMER PUMP W/HARDWARE
---	-----------------------------------

Service Requests:

06/16/2017

SERVICE REQUEST / 11: BINDS/STICKS / EXCHANGE - NEW
PUMP PRIMER STUCK ON HAD TO USE MALLET TO SHUT OFF

Asset Work Order History 10154943

CSHOP-2017-5405

Date Opened 9-18-2017 Date Finished 10-10-2017 Meter 1 Reading: 58,090

TASKS PERFORMED

NO PARTS USED

LIGHTING SYSTEM
DIAGNOSE ELECTRICAL

Service Requests:

09/17/2017 LIGHTS / 12: BROKEN / REPAIR
RIGHT REAR SCENE LIGHT NOT WORKING

CSHOP-2017-5663

Comments: **ALSO CHECK DUMP CHUTE DROPS WATER STRAIGHT DOWN CHECK A/C SWITCH**

Date Opened 9-29-2017 Date Finished 1-22-2018 Meter 1 Reading: 58,789

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE PUMP

Service Requests:

09/29/2017 SERVICE REQUEST / 12: BROKEN / INSPECT
SERVICE REQUEST FOAM SYSTEM NOT WORKING DISPLAY FLASHING "NO PR"

10/09/2017 SERVICE REQUEST / 12: BROKEN / INSPECT
SERVICE REQUEST, RIGHT REAR LED LIGHT NOT WORKING

CSHOP-2017-6711

Comments: **FILTERS ONLY**

Date Opened 11-21-2017 Date Finished 12-13-2017 Meter 1 Reading: 58,252

TASKS PERFORMED

Q PARTS

PM SERVICE C

1	FIL; NAPAGOLD FUEL FILTER
1	FIL; NAPAGOLD FUEL FILTER
-4	9OC; SYN 15W40
4	9OC; SYN 15W40
-3	9OC; BULK TRANS SYN
2	FIL; NAPAGOLD OIL FILTER
4	FLUID; SYN OIL BULK QTS
3	9OC; BULK TRANS SYN
3	9IP; ALLISON TRANS FLUID GAL

Asset Work Order History 10154943

CSHOP-2017-6825

Comments: **ALSO CHECK DUMP CHUTE DROPS WATER STRAIGHT DOWN CHECK A/C SWITCH**

Date Opened 11-29-2017 Date Finished 1-22-2018 Meter 1 Reading: 58,789

TASKS PERFORMED

	Q	PARTS
FIRE PUMP	2	NAF; NAPA ANTIFREEZE GAL
CAB	1	2FL; GAUGE
COOLING SYSTEM	1	GRO; SOCKET
ELECTRICAL	1	GRO; SOCKET
SEAT FRONT	1	5SC; RELAY 40A/30A 5PIN
HVAC SYSTEM	1	GRO; SWITCH
	1	ECH; RELAY (AR462)
	2	ECH; RELAY (AR462)
	1	9IP; 1272 KNOB

CSHOP-2017-945

Comments: **T72**

Date Opened 2-15-2017 Date Finished 2-21-2017 Meter 1 Reading: 53,246

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
DOOR

Service Requests:

02/14/2017 ALARMS / 23: NOT CONNECTED / ADJUST
ALARM SIGNALS,.....DOOR ALARM KEEPS BUZZING INTERMITTENTLY GETTING WORSE . TENDER 72

CSHOP-2018-1421

Date Opened 3-12-2018 Date Finished 3-15-2018 Meter 1 Reading: 59,984

TASKS PERFORMED

NO PARTS USED

WATER TANK LEVEL LIGHTS

Service Requests:

03/12/2018 LIGHTS / 23: NOT CONNECTED / REPAIR
VEHICLE LIGHTS NOT WORKING ON THE SIDE OF DRIVER AND PASSENGER SHOWING HOW MUCH WATER WE HAVE
CHRISTMAS TREE LIGHTS. THE LIGHT ON SPEEDO IS OUT AGAIN

CSHOP-2018-1782

Date Opened 3-29-2018 Date Finished 4-6-2018 Meter 1 Reading: 60,442

TASKS PERFORMED

	Q	PARTS
FIRE PUMP	1	5TN; THERMAL RELIEF VALVE

Service Requests:

03/29/2018 SERVICE REQUEST / 18: LEAKING / EXCHANGE - NEW
PUMP OVERHEAT HOSE LEAKING CONTINUALLY

Asset Work Order History 10154943

CSHOP-2018-1809

Date Opened 3-30-2018

Date Finished

4-12-2018

Meter 1 Reading:

60,512

TASKS PERFORMED

Q PARTS

STARTER

1 9IP; 8200433 39MT STARTER 6815
-1 9IP; 8200433 39MT STARTER 6815
1 TWD; STARTER, 39MT 12V

Service Requests:

03/30/2018

STARTER / 12: BROKEN / REPAIR

VEHICLE WILL NOT START, BAD STARTER. LOOSE OR DAMAGED CABLES, HAVE TO TAP STARTER WITH OBJECT AND
THAN TRUCK WILL START . MECHANIC CAME OUT AND LOOKED.

CSHOP-2018-1904

Date Opened 4-4-2018

Date Finished

4-6-2018

Meter 1 Reading:

60,442

TASKS PERFORMED

NO PARTS USED

AUTO-EJECT

Service Requests:

04/04/2018

SERVICE REQUEST / 38: SHORTED / REPAIR

AUTO EJECTOR FOR BATTERY CHARGER NOT WORKING.

CSHOP-2018-2050

Date Opened 4-12-2018

Date Finished

4-23-2018

Meter 1 Reading:

60,512

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM

1 2FL; NORM CLSD 2 WIRE PRES SW

CSHOP-2018-207

Date Opened 1-10-2018

Date Finished

2-22-2018

Meter 1 Reading:

59,273

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE PUMP PLUMBING
FIRE PUMP

1 9HY; 1" 90 FXF STEEL 4000 PSI SUPER SWL JT

Service Requests:

01/09/2018

SERVICE REQUEST / 18: LEAKING / EXCHANGE - NEW

WATER LEAK HOSE REEL WHERE PIPE ENTERS COMPARTMENT

01/11/2018

SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT

-WATER LEAKING FROM TAILBOARD AREA WHEN TRUCK IS IN PIMP SPEEDO AND WATER TEMP DASH LIGHTS NOT
WORKING

Asset Work Order History 10154943

CSHOP-2018-2344

Date Opened 4-30-2018

Date Finished

4-30-2018

Meter 1 Reading:

60,846

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR?

DAN CALLAGHAN ENTERPRISES

CSHOP-2018-2410

Comments: I ORDERED A SWITCH IN CASE YOU DON'T HAVE ONE. PICTURE ATTACHED TO "RELATED FILES"

Date Opened 5-2-2018

Date Finished

5-17-2018

Meter 1 Reading:

60,969

TASKS PERFORMED

Q PARTS

HVAC SYSTEM

1 2FL; SWITCH, AC DOUBLE STACKED

CSHOP-2018-2483

Date Opened 5-7-2018

Date Finished

5-25-2018

Meter 1 Reading:

60,969

TASKS PERFORMED

Q PARTS

INTAKE VALVE

1 5TN; PVG VALVE ASSY W/HANDLE

FIRE PUMP PLUMBING

1 BK; FUSE HOLDER

PRIMING PUMP FIRE PUMP

1 1DB; PUMP

PARK-CLEARANCE LIGHTS

2 5TN; KIT, PRIMER VALVE PVG SEALS/ORINGS

4 LIT; LED M C LAMP

Service Requests:

05/04/2018

SERVICE REQUEST / 11: BINDS/STICKS / LUBRICATE

TYPE PROBLEM INTO DESCRIPTION THE BLACK MAX PISTON VALVE ON THE PASSENGER SIDE IS LEAKING WATER AND IS MISSING THE INNER O-RING

05/06/2018

SERVICE REQUEST / 18: LEAKING / EXCHANGE - NEW

PUMP PRIMER LEAKING WATER

05/07/2018

ENGINE / 12: BROKEN / EXCHANGE - NEW

ENGINE, PRIME MOTOR NOT WORKING AT ALL DURING DRAFTING TRAINING.

CSHOP-2018-277

Date Opened 1-12-2018

Date Finished

2-21-2018

Meter 1 Reading:

59,273

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER

1 2FL; LAMP

TURN SIGNAL LIGHTS

1 2FL; LAMP

Service Requests:

01/12/2018

SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW

RT FRONT TURN SIGNAL BROKEN

Asset Work Order History 10154943**CSHOP-2018-3417**

Date Opened 6-18-2018

Date Finished

6-18-2018

Meter 1 Reading:

61,449

TASKS PERFORMED**NO PARTS USED**

TIRE

VENDOR?

DAN CALLAGHAN ENTERPRISES

CSHOP-2018-3480

Date Opened 6-21-2018

Date Finished

6-21-2018

Meter 1 Reading:

61,449

TASKS PERFORMED**NO PARTS USED**

TIRES ALL

VENDOR?

DAN CALLAGHAN ENTERPRISES

CSHOP-2018-3617

Date Opened 6-27-2018

Date Finished

7-20-2018

Meter 1 Reading:

61,449

TASKS PERFORMED**NO PARTS USED**TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM**Service Requests:**

06/26/2018

SERVICE REQUEST / 18: LEAKING / REPAIR
AIR LEAK WENT FROM 120 PSI TO BELOW 50 PSI IN 5 HRS**CSHOP-2018-5052**

Date Opened 9-6-2018

Date Finished

10-17-2018

Meter 1 Reading:

63,752

TASKS PERFORMED**Q PARTS**TRAVEL TO BE CHARGED TO WORK ORDER
THROTTLE CONTROLS

1	MMM; MARINE ADH FAST CURE
1	8GR; 1632 BATTERY
1	2FR; TOTAL CONTROL GAUGE

Service Requests:

09/06/2018

SERVICE REQUEST / 38: SHORTED / INSPECT
THROTTLE INCREASE BUTTON ON PUMP PANEL NOT WORKING.**CSHOP-2018-5760**

Date Opened 10-11-2018

Date Finished

10-17-2018

Meter 1 Reading:

63,752

TASKS PERFORMED**Q PARTS**PARK-CLEARANCE LIGHTS
AIR TANK

1	LIT; LED M C LAMP
---	-------------------

Asset Work Order History 10154943

CSHOP-2018-5885

Date Opened 10-17-2018 Date Finished 10-18-2018 Meter 1 Reading: 63,753

TASKS PERFORMED

	Q	PARTS
FIRE PUMP	1	1WL; 600 SERIES RED LED W/O FLANGE
PRE TRIP INSPECTION	2	LIT; LED M C LAMP
STROBE LIGHTS	1	1WL; LIGHT

CSHOP-2018-5912

Date Opened 10-18-2018 Date Finished 10-18-2018 Meter 1 Reading: 63,753

TASKS PERFORMED

	Q	PARTS
PM SERVICE B	1	FIL; NAPAGOLD FUEL FILTER
	2	FIL; NAPAGOLD OIL FILTER
	2	WIP; WIPER
	48	4PC; 15W40 PREMIUM BLUE OIL
	1	FIL; NAPAGOLD FUEL FILTER

CSHOP-2018-6377

Comments: PUMP TEST FOLLOW-UP REPAIRS FAILED VACUUM TEST, PRIMER VANES WORN AND RECOMMEND REPLACING PUMP DISCHARGE NOT ACCURATE TRANSMISSION TEMPERATURE GAUGE AT PUMP PANEL NOT ACCURATE FUEL GAUGE AT PUMP PANEL NOT WORKING

Date Opened 11-9-2018 Date Finished 1-15-2019 Meter 1 Reading: 65,611

TASKS PERFORMED

	Q	PARTS
TRAVEL TO BE CHARGED TO WORK ORDER	1	GRO; SWITCH
AIR HORN	1	9IP; 301-104 FUEL GAUGE
FUEL GAUGE		

Service Requests:

11/09/2018 SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW
AIRHORN BUTTON ON PUMP PANEL INOP. FUEL GAUGE ON PUMP PANEL INOP.

CSHOP-2018-6623

Date Opened 11-21-2018 Date Finished 11-26-2018 Meter 1 Reading: 64,573

TASKS PERFORMED

	Q	PARTS
AIR SYSTEM	2	2FL; NORM CLSD 2 WIRE PRES SW
	1	2FL; SWITCH, NORMAL OPEN

Asset Work Order History 10154943**CSHOP-2018-6928**

Date Opened 12-6-2018 Date Finished 1-9-2019 Meter 1 Reading: 65,325

TASKS PERFORMED**Q PARTS**TURN SIGNAL LIGHTS
PARK-CLEARANCE LIGHTS

1 LIT; LED M C LAMP

Service Requests:12/05/2018 LIGHTS / 12: BROKEN / REPAIR
TURN SIGNAL LIGHT MOUNTED ON RIGHT FRONT FENDER IS LOOSE12/06/2018 LIGHTS / 12: BROKEN / EXCHANGE - NEW
DRIVER SIDE REAR UPPER MARKER LIGHT MISSING/INOP**CSHOP-2018-7171**Comments: **REQUEST SENT TO CALLAGHAN**

Date Opened 12-18-2018 Date Finished 12-26-2018 Meter 1 Reading: 65,210

TASKS PERFORMED**NO PARTS USED**

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES**Service Requests:**12/18/2018 TIRES / 18: LEAKING / EXCHANGE - NEW
BAD TIRES FRONT REAR AXLES TIRES ARE PAST WEAR BARS (4) OF THEM 12/22.5R,**CSHOP-2018-7288**

Date Opened 12-26-2018 Date Finished 2-6-2019 Meter 1 Reading: 65,684

TASKS PERFORMED**NO PARTS USED**TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM**Service Requests:**12/23/2018 SERVICE REQUEST / 18: LEAKING / EXCHANGE - NEW
AIR LEAK BEHIND DASH BY A/C CONTROLS**CSHOP-2018-78**

Date Opened 1-4-2018 Date Finished 1-18-2018 Meter 1 Reading: 58,789

TASKS PERFORMED**Q PARTS**

LIGHTING SYSTEM

1 1WL; LED FLOOD/SCENE LIGHT

Asset Work Order History 10154943

CSHOP-2018-881

Date Opened 2-9-2018

Date Finished

2-27-2018

Meter 1 Reading:

59,273

TASKS PERFORMED

Q PARTS

STROBE LIGHTS

2 1WL; LIGHT LED RED TIR6

Service Requests:

02/09/2018

LIGHTS / 38: SHORTED / EXCHANGE - NEW

VEHICLE LIGHTS NOT WORKING, RT FRONTSIDE LIGHTBAR STROBE NOT WORKING, RIGHT REAR UPPER LED NOT WORKING.

CSHOP-2019-1754

Date Opened 4-4-2019

Date Finished

5-10-2019

Meter 1 Reading:

67,638

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

HOSE BED BODY

LIGHTING SYSTEM

Service Requests:

04/04/2019

SERVICE REQUEST / 41: TORN/PUNCTURED / EXCHANGE - REBUILT

NEEDS NEW HOSE BED COVER

CSHOP-2019-1912

Date Opened 4-12-2019

Date Finished

5-2-2019

Meter 1 Reading:

67,443

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER

FIRE PUMP

LIGHTING SYSTEM

1 5SC; TRVVALVE

1 5SC; TRVVALVE

Service Requests:

04/12/2019

SERVICE REQUEST / 18: LEAKING / EXCHANGE - NEW

PUMP OVERHEAT DRAIN LEAKING. PASSENGER SIDE REAR UPPER WARNING LIGHT INOP.

CSHOP-2019-2422

Date Opened 5-8-2019

Date Finished

5-10-2019

Meter 1 Reading:

67,638

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER

LIGHTING SYSTEM

1 9IP; NODE HERCULES V-MUX

Asset Work Order History 10154943**CSHOP-2019-2466**

Date Opened 5-10-2019 Date Finished 5-10-2019 Meter 1 Reading: 67,638

TASKS PERFORMED**NO PARTS USED**TRAVEL TO BE CHARGED TO WORK ORDER
DOOR ALARM OR OTHER WARNING**Service Requests:**05/10/2019 ALARMS / 12: BROKEN / REPAIR
EXTENDA GUN WARNING LIGHT AND BUZZER SOUNDING .**CSHOP-2019-2511**

Date Opened 5-13-2019 Date Finished 5-17-2019 Meter 1 Reading: 67,727

TASKS PERFORMED**NO PARTS USED**TRAVEL TO BE CHARGED TO WORK ORDER
WATER TANK LEVEL LIGHTS**Service Requests:**05/13/2019 SERVICE REQUEST / 38: SHORTED / REPAIR
BOOSTER TANK LEVEL GAUGE FOAM TANK LEVEL GAUGE NOT WORKING**CSHOP-2019-2658**

Date Opened 5-23-2019 Date Finished 6-28-2019 Meter 1 Reading: 68,464

TASKS PERFORMED**Q PARTS**TRAVEL TO BE CHARGED TO WORK ORDER
EQUIPMENT MOUNTING BRACKETS
LIGHTING SYSTEM
BATTERY1 GRO; FUSEHOLD
4 1AD; BATTERY 31 SERIES**CSHOP-2019-276**

Date Opened 1-15-2019 Date Finished 1-30-2019 Meter 1 Reading: 65,684

TASKS PERFORMED**Q PARTS**

ENGINE AND ACCESSORIES

1 2DD; DIPSTICK

CSHOP-2019-3198

Date Opened 6-20-2019 Date Finished 6-21-2019 Meter 1 Reading: 68,184

TASKS PERFORMED**NO PARTS USED**TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM**Service Requests:**06/20/2019 SERVICE REQUEST / 38: SHORTED / INSPECT
PUMP PANEL LIGHTS NOT TURNING ON

Asset Work Order History 10154943**CSHOP-2019-3363**

Date Opened 6-27-2019

Date Finished

6-27-2019

Meter 1 Reading:

68,238

TASKS PERFORMED**NO PARTS USED**

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2019-3599

Date Opened 7-10-2019

Date Finished

7-30-2019

Meter 1 Reading:

68,839

TASKS PERFORMED**Q PARTS**

SEAT BELTS

1 2FL; SEATBELT

CSHOP-2019-3612

Date Opened 7-11-2019

Date Finished

7-30-2019

Meter 1 Reading:

68,839

TASKS PERFORMED**NO PARTS USED**TRAVEL TO BE CHARGED TO WORK ORDER
SEAT BELTS**CSHOP-2019-4201**

Date Opened 8-10-2019

Date Finished

8-16-2019

Meter 1 Reading:

69,205

TASKS PERFORMED**NO PARTS USED**

FIRE APPARATUS

CSHOP-2019-4319

Date Opened 8-16-2019

Date Finished

10-16-2019

Meter 1 Reading:

69,276

TASKS PERFORMED**Q PARTS**CONTROL VALVE FIRE PUMP
FIRE APPARATUS
TANK-RESERVOIR1 9AM; LUBRICANT MOLYKOTE 55 300Z
2 LMP; LAMP
1 9HD; VALVE SEAT 8 NITRILE
1 9IP; SEAL
1 BK; NAPA SEALANT FOAM
1 PTX; PERMATEX**CSHOP-2019-5435**

Date Opened 10-15-2019

Date Finished

10-18-2019

Meter 1 Reading:

69,289

TASKS PERFORMED**Q PARTS**

PM SERVICE C

38 4PC; 4PC
1 FIL; FIL
1 FIL; NAPAGOLD FUEL FILTER
2 FIL; NAPAGOLD OIL FILTER
32 4PC; 15W40 PREMIUM BLUE OIL
-32 4PC; 4PC

Asset Work Order History 10154943**CSHOP-2019-5459**Comments: **PMC REPAIR WO**

Date Opened 10-16-2019

Date Finished

10-25-2019

Meter 1 Reading:

69,388

TASKS PERFORMED

GEAR BOX FIRE PUMP
AIR FILTER
LIGHTING SYSTEM
REPAIR FROM PM - POWER STEERING
REPAIR FROM PM - DIFFERENTIALS
REPAIR FROM PM - BELTS
U-BOLTS
REPAIR FROM PM - TRANSMISSION
AIR DRIER

Q PARTS

-5 4PC; GEAR OIL SYN BULK DELO
5 4PC; GEAR OIL SYN BULK DELO
1 FIL; NAPAGOLD AIR FILTER
1 FIL; NAPAGOLD AIR FILTER
2 LIT; LED M C LAMP
-1 FIL; NAPA HYDRAULIC FILTER
1 FIL; NAPA HYDRAULIC FILTER
36 9OC; GEAR OIL BULK
14 4PC; GEAR OIL SYN BULK DELO
1 NBH; FLEETRUNNER BELT
1 NBH; FLEETRUNNER BELT
37 9OC; BULK TRANS SYN
1 2DD; FILTER KIT TRANS SUMP 4
2 CRC; CLEAN R CARB 20OZ
-23 9OC; BULK TRANS SYN
23 9OC; BULK TRANS SYN
12 1CH; BRAKE CLEANER MOPAR
1 2BE; PURGE VALVE KIT
1 TWD; PURGE VALVE KIT
1 FIL; NAPAGOLD AIR FILTER

CSHOP-2019-5584

Date Opened 10-22-2019

Date Finished

10-22-2019

Meter 1 Reading:

69,205

TASKS PERFORMED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES**NO PARTS USED****CSHOP-2019-5875**

Date Opened 11-9-2019

Date Finished

11-14-2019

Meter 1 Reading:

69,557

TASKS PERFORMED

COMPARTMENT LIGHT BODY

NO PARTS USED**CSHOP-2019-6041**

Date Opened 11-18-2019

Date Finished

12-18-2019

Meter 1 Reading:

70,247

TASKS PERFORMED

LIGHTING SYSTEM

Q PARTS

1 1WL; 600 SERIES LED LOOSE LEAD

Service Requests:

11/18/2019

SERVICE REQUEST / 38: SHORTED / REPAIR

REAR LOWER EMERGENCY LIGHTS OUT BOTH SIDES AND RT SIDE MIDDLE LOWER LIGHT OUT

Asset Work Order History 10154943**CSHOP-2019-6251**

Date Opened 12-3-2019

Date Finished

12-18-2019

Meter 1 Reading:

70,247

TASKS PERFORMED**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER
TANK-RESERVOIR

Service Requests:

12/02/2019

SERVICE REQUEST / 18: LEAKING / INSPECT

WATER TANK IS LEAKING A DROP A SECOND FROM A CRACK ON THE REAR OF THE TRUCK

CSHOP-2019-6696

Date Opened 12-30-2019

Date Finished

1-9-2020

Meter 1 Reading:

70,415

TASKS PERFORMED**Q PARTS**

INSTRUMENTS-GAUGES-METERS

1 BK; GAUGE MOUNT PANEL
1 BK; BK
1 BK; GAUGE

Service Requests:

12/27/2019

WINDOW / 12: BROKEN / EXCHANGE - NEW

TRANSMISSION OIL GAUGE GLASS CAME OFF THE TRUCK ON THE PUMP PANNEL GAUGE STILL WORK.

CSHOP-2020-1035

Date Opened 2-23-2020

Date Finished

2-27-2020

Meter 1 Reading:

70,783

TASKS PERFORMED**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM
BRACKET

CSHOP-2020-1042

Date Opened 2-24-2020

Date Finished

3-4-2020

Meter 1 Reading:

71,012

TASKS PERFORMED**Q PARTS**

DIAGNOSE ELECTRICAL

1 CRC; QD ELECTRONIC CLEANER

Service Requests:

02/23/2020

LIGHTS / 38: SHORTED / REPLACED

VEHICLE LIGHTS NOT WORKING. LEFT TURN REAR SIGNAL NOT WORKING.

Asset Work Order History 10154943**CSHOP-2020-1711**

Date Opened 3-26-2020

Date Finished

3-30-2020

Meter 1 Reading:

71,747

TASKS PERFORMED**NO PARTS USED**TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM**Service Requests:**

03/26/2020

SERVICE REQUEST / 18: LEAKING / REPAIR

AIR LEAK UNDER DASH BY BRAKE PEDAL WENT FROM 120 PSI TO BELOW 50 IN AN HOUR

CSHOP-2020-2284

Date Opened 4-30-2020

Date Finished

5-14-2020

Meter 1 Reading:

72,647

TASKS PERFORMED**Q PARTS**TRAVEL TO BE CHARGED TO WORK ORDER
PARK-CLEARANCE LIGHTS
SEAT BELTS2 LMP; LAMP LED 168 194
1 2FL; SEAT BELT DRIVERS SIDE**CSHOP-2020-2681**

Date Opened 5-20-2020

Date Finished

7-1-2020

Meter 1 Reading:

72,647

TASKS PERFORMED**Q PARTS**QUALITY CHECK-REPAIRS
WATER TANK LEVEL LIGHTS
CONTROL VALVE FIRE PUMP
HOSE BED BODY
HANDLIGHT
LIGHTING SYSTEM
DOOR LOCKS
HEATING AND VENTILATION2 9HY; GASOLA THREAD SEALANT
1 5AB; 3 3 5 BALL KIT COMPOSITE
4 5SC; BUCKLE ASSY W STRAPS
1 LMP; LAMP
2 LMP; LAMP RO BLISTER PK
1 5PF; SWITCH DOOR DPST NC MOM
1 LIT; LEDKIT
1 5EF; HANDLE LOCKING
2 2FL; LOUVER A C**CSHOP-2020-301**

Date Opened 1-19-2020

Date Finished

1-27-2020

Meter 1 Reading:

70,709

TASKS PERFORMED**Q PARTS**

REAR DOOR LATCH ASSEMBLY

2 5EF; HANDLELOCKING

CSHOP-2020-3975Comments: **WILL LEAVE NODE ON SERVICE TRUCK 10192795**

Date Opened 8-3-2020

Date Finished

8-8-2020

Meter 1 Reading:

0

TASKS PERFORMED**Q PARTS**

LIGHTING SYSTEM

1 6WL; NODE HERCULES VMUX

Asset Work Order History 10154943

CSHOP-2020-503

Date Opened 1-30-2020 Date Finished 8-3-2020 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

FIRE APPARATUS
LIGHTING SYSTEM

5 GRO; REPLACEMENT LENS

Service Requests:

01/29/2020 SERVICE REQUEST / 44: WORN / EXCHANGE - NEW
EMERGENCY LIGHT ON THE DRIVERS SIDE, UPPER REAR CORNER OF THE TRUCK IS BROKEN OFF.

CSHOP-2020-5403

Date Opened 10-13-2020 Date Finished 10-15-2020 Meter 1 Reading: 73,047

TASKS PERFORMED

NO PARTS USED

PM SERVICE B

CSHOP-2020-5454

Comments: LUBE OIL / FUEL SERVICE FROM PM TICKET

Date Opened 10-15-2020 Date Finished 10-19-2020 Meter 1 Reading: 73,047

TASKS PERFORMED

Q PARTS

EQUIPMENT MOUNTING BRACKETS
WIPER BLADES
ENGINE AND ACCESSORIES
PARK-CLEARANCE LIGHTS
LIGHTING SYSTEM
VALVE STEM
AIR SYSTEM
EMERGENCY EQUIPMENT

2 WIP; WIPER
1 FIL; FIL
1 FIL; NAPAGOLD FUEL FILTER
30 4PC; 15W40 PREMIUM BLUE OIL
8 4PC; 15W40 PREMIUM BLUE OIL
2 FIL; NAPAGOLD OIL FILTER
1 9AP; OIL SAMPLE TEST KIT PETRO CANADA
1 LMP; LAMP
1 9IP; BULB
1 9IP; 440-3 3 11/16" VALVE EXT
2 1WL; TIR6 LIGHT CHROME BEZEL
1 1WL; 500TIR6CLEAR
1 1WL; LENS RED OPTIC LED

CSHOP-2020-564

Date Opened 2-3-2020 Date Finished 2-19-2020 Meter 1 Reading: 71,120

TASKS PERFORMED

Q PARTS

FIRE PUMP

3 5HP; VPS KPS PWR SHIFT AMP CNTRL KIT

Service Requests:

02/03/2020 ENGINE / 18: LEAKING / REPAIR
PUMP TRANSFER LEAKING AT TRANSFER CASE WHEN IN ROAD MODE. (NOT LEAKING AT SWITCH)

Asset Work Order History 10154943**CSHOP-2020-5756**

Date Opened 10-30-2020

Date Finished

11-24-2020

Meter 1 Reading:

73,112

TASKS PERFORMEDFUEL INJECTOR
AIR SYSTEM**Q****PARTS**

1	2DD; 2DD
1	2DD; 2DD
1	2DD; INJECTORS 6 PK
1	9AP; SORBENT PAD
1	2DD; CORE DEPOSIT
1	PTX; PERMATEX
1	2FL; CYLINDER DUAL SHAFT AIR
1	2FL; CYLINDER AIR

CSHOP-2020-934

Date Opened 2-18-2020

Date Finished

5-15-2020

Meter 1 Reading:

72,647

TASKS PERFORMED

CAP

Q**PARTS**

1	5TN; TEMPEST VENTMASTER FUEL CAP
---	----------------------------------

Service Requests:

02/14/2020

SERVICE REQUEST / 18: LEAKING / EXCHANGE - NEW

TYPE PROBLEM INTO DESCRIPTION- CHAIN SAW ON TENDER 72 NEEDS NEW FUEL CAP

CSHOP-2021-2487

Date Opened 5-4-2021

Date Finished

5-6-2021

Meter 1 Reading:

73,565

TASKS PERFORMED

THROTTLE CONTROLS

Q**PARTS**

1	2FL; THROTTLE POSITION SENSOR
1	CRC; QD ELECTRONIC CLEANER

CSHOP-2021-4521

Date Opened 8-11-2021

Date Finished

8-13-2021

Meter 1 Reading:

73,581

TASKS PERFORMED

INSPECTION

NO PARTS USED

Asset Work Order History 10154943**CSHOP-2021-4522**Comments: **REPAIRS FROM PM**

Date Opened 8-11-2021

Date Finished

8-17-2021

Meter 1 Reading:

73,581

TASKS PERFORMEDFOAM SYSTEM
CONTROL VALVE FIRE PUMP
ELECTRICAL
FILTER
TIRE**Q PARTS**

1	5HP; TANK LEVEL SENSOR
1	LMP; LAMP RO BLISTER PK
1	FIL; NAPA FUEL FILTER
1	FIL; OIL ANALYSIS KIT
1	FIL; NAPAGOLD FUEL FILTER
1	FREIGHT
1	FIL; NAPAGOLD FUEL FILTER
2	FIL; NAPAGOLD OIL FILTER
1	FIL; NAPAGOLD FUEL FILTER

CSHOP-2021-5662Comments: **AIR LEAK SPARE AT 42**

Date Opened 10-7-2021

Date Finished

10-13-2021

Meter 1 Reading:

73,581

TASKS PERFORMED

SEAT FRONT

Q PARTS

1	TWD; KIT 914 915 960 715 7
---	----------------------------

Service Requests:

10/07/2021

SEATS / 18: LEAKING / EXCHANGE - NEW

AIR LEAK ON DRIVER'S SEAT. AIR COMPLETELY EMPTIES EVERY FEW MINUTES. ALSO, DIESEL EXHAUST SMELL IN THE CAB

CSHOP-2021-5939

Date Opened 10-22-2021

Date Finished

11-5-2021

Meter 1 Reading:

74,067

TASKS PERFORMEDTRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM**Q PARTS**

2	9ES; PRESSURESWITCH60PSINC
---	----------------------------

CSHOP-2021-6741Comments: **PRE TRIP INSPECTION**

Date Opened 12-8-2021

Date Finished

12-14-2021

Meter 1 Reading:

74,067

TASKS PERFORMED

QUALITY CHECK-REPAIRS

NO PARTS USED

Asset Work Order History 10154943**CSHOP-2022-2070**

Date Opened 4-14-2022 Date Finished 5-18-2022 Meter 1 Reading: 75,675

NEEDS A QC

TASKS PERFORMED**NO PARTS USED**

QUALITY CHECK-REPAIRS

Service Requests:04/14/2022 ALARMS / 12: BROKEN / INSPECT
TENDER 14 , NO BACK UP ALARM**CSHOP-2022-3454**

Date Opened 6-27-2022 Date Finished 9-2-2022 Meter 1 Reading: 76,089

TASKS PERFORMED**NO PARTS USED**

QUALITY CHECK-REPAIRS

CSHOP-2022-3576

Date Opened 7-5-2022 Date Finished 7-18-2022 Meter 1 Reading: 75,675

TASKS PERFORMED**NO PARTS USED**TRAVEL TO BE CHARGED TO WORK ORDER
REAR TIRES**Service Requests:**07/04/2022 TIRES / 44: WORN / INSPECT
BAD TIRE RIGHT REAR TANDEM SHOWING WARE.**CSHOP-2022-3956**

Date Opened 7-26-2022 Date Finished 8-23-2022 Meter 1 Reading: 76,089

TASKS PERFORMED**Q PARTS**QUALITY CHECK-REPAIRS
FRONT TIRES
AIR DRIER

1 1FG; FILTER AIR BRAKE 4374

CSHOP-2022-4233Comments: **INSPECTION ONLY**

Date Opened 8-12-2022 Date Finished 8-15-2022 Meter 1 Reading: 76,089

TASKS PERFORMED**Q PARTS**

INSPECTION

1 LIT; LED M C LAMP
1 LIT; LED M C LAMP

Asset Work Order History 10154943

CSHOP-2022-4234

Date Opened 8-12-2022

Date Finished

9-27-2022

Meter 1 Reading:

76,089

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
HOOD
PARK-CLEARANCE LIGHTS
LIGHTING SYSTEM
AIR DRIER
AIR SYSTEM

1 5FF; HOOD SPRING

CSHOP-2022-4554

Comments: **CALLAGHAN TIRE**

Date Opened 8-30-2022

Date Finished

8-30-2022

Meter 1 Reading:

0

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2022-4684

Comments: **CALLAGHAN TIRE**

Date Opened 8-31-2022

Date Finished

8-31-2022

Meter 1 Reading:

0

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2022-5244

Comments: **SMALL ENG SPARK PLUGS**

Date Opened 9-27-2022

Date Finished

10-11-2022

Meter 1 Reading:

0

TASKS PERFORMED

Q PARTS

SMALL ENGINE REPAIR

6 BSH; SPARK PLUG
30 RPO; TRUEFUEL
10 BSH; SPAKPLUG

CSHOP-2023-4265

Date Opened 8-15-2023

Date Finished

8-15-2023

Meter 1 Reading:

77,123

TASKS PERFORMED

NO PARTS USED

INSPECTION

Asset Work Order History 10154943

CSHOP-2023-4266

Comments: **NOTED DURING INSPECTION**

Date Opened 8-15-2023

Date Finished

11-14-2023

Meter 1 Reading:

77,124

TASKS PERFORMED

FIRE PUMP CONTROLS
ENGINE AND ACCESSORIES
LIGHTING SYSTEM
BATTERY
DOOR LOCKS

Q PARTS

1	5HP; PUMP PUCH PULL SWIVEL
1	5HP; LOCKING PUSH PULL SWIVEL CONTROLL
1	FIL; NAPAGOLD FUEL FILTER
38	4PC; 15W40 PREMIUM BLUE OIL
1	FIL; NAPAGOLD FUEL FILTER
2	FIL; NAPAGOLD OIL FILTER
1	FIL; NAPAGOLD AIR FILTER
-1	1WL; LED FLOOD SCENE LIGHT
1	1WL; LED FLOOD SCENE LIGHT
4	1AD; 1000 CCA 31 SERIES BATTERY

CSHOP-2024-2122

Comments: **AIR HORN BUTTON spare tender at 22**

Date Opened 4-29-2024

Date Finished

6-12-2024

Meter 1 Reading:

77,124

TASKS PERFORMED

TRAVEL TO BE CHARGED TO WORK ORDER
TANK-RESERVOIR
AIR HORN

NO PARTS USED

Service Requests:

04/26/2024 ALARMS / 49: CAN NOT DUPLICATE CONCERN / INSPECT
while truck was sitting onscene with the lights on the air horn went off by it self and continued blowing until the floor button was hit a couple times. it repeated blowing again and hitting the button it wouldgo off.

05/24/2024 DOOR / 11: BINDS/STICKS / LUBRICATE
VEHICLE DOORS, Dump tank rear access door wont open. Handle is frozen in place. Unable to unload dump tank

CSHOP-2024-2606

Comments: **ON CALL CHECK ENGINE**

Date Opened 5-27-2024

Date Finished

6-24-2024

Meter 1 Reading:

77,124

TASKS PERFORMED

ENGINE AND ACCESSORIES

NO PARTS USED

CSHOP-2024-4011

Date Opened 8-20-2024

Date Finished

10-7-2024

Meter 1 Reading:

76,700

TASKS PERFORMED

INSPECTION

NO PARTS USED

Asset Work Order History 10154943

CSHOP-2024-4012

Comments: ST2 PM FOLLOW UPS
Date Opened 8-20-2024 Date Finished 10-7-2024 Meter 1 Reading: 0

TASKS PERFORMED	Q	PARTS
FIRE APPARATUS	1	FIL; NAPAGOLD OIL FILTER
ENGINE AND ACCESSORIES	1	FIL; NAPAGOLD FUEL FILTER
LIGHTING SYSTEM	1	FIL; NAPAGOLD FUEL FILTER
TRANSMISSION	2	WIP; WIPER
AIR DRIER	2	WIP; WIPER
BODY EXTERIOR	1	FIL; NAPAGOLD AIR FILTER
HVAC SYSTEM	1	FIL; NAPAGOLD OIL FILTER
	6	GRO; RUBBER GROMMET
	2	LMP; LAMP
	2	LMP; BULB
	6	GRO; LAMP
	1	2DD; FILTER KIT, TRANS, SUMP 4"
	1	MMM; PRNT TAPE 2090-48A-CP
	1	2TP; KIT, PURGE VALVE
	1	1FG; FILTER, AIR BRAKE (4374)

CSHOP-2024-4843

Date Opened 10-5-2024 Date Finished 10-7-2024 Meter 1 Reading: 78,457

TASKS PERFORMED	NO PARTS USED
DIAGNOSE ELECTRICAL	

CSHOP-2024-5221

Date Opened 10-28-2024 Date Finished 1-15-2025 Meter 1 Reading: 78,490

TASKS PERFORMED	NO PARTS USED
CONTROL VALVE	

Service Requests:

10/27/2024	SERVICE REQUEST / 11: BINDS/STICKS / INSPECT Tank fill lever detached from mechanism inside tender
------------	---

Asset Work Order History 10154943

CSHOP-2024-586

Comments: unit wont start needs batteries and possible starter motor
Date Opened 1-29-2024 Date Finished 4-3-2024 Meter 1 Reading: 77,124

TASKS PERFORMED	Q	PARTS
WIPER BLADES	2	WIP; WIPER
STARTER	1	TWD; STARTER 39MT 12V
BATTERY	4	1AD; 1000 CCA 31 SERIES BATTERY
ELECTRICAL	1	2FL; RELAY STARTER WHITE RODGERS
AIR SYSTEM	2	9AP; SQUARE AMBER RED FENDER LIGHT
BACK UP CAMERA-MONITOR	2	1WL; LIGHT STRIP TANK STATUS
	1	9AP; DIGITAL WIRELESS BACKUP CAMERA
	3	LMP; LAMP
	1	9AP; TAG LIGHT
	1	9HD; BUMPER POLE LIGHT
	1	LMP; LAMP
	1	BK; BACK UP ALARM

CSHOP-2025-231

Date Opened 1-15-2025 Date Finished 8-26-2025 Meter 1 Reading: 0

TASKS PERFORMED	Q	PARTS
QUALITY CHECK-REPAIRS	1	CRC; STARTING FLUID W LUB
WATER TANK LEVEL LIGHTS	1	CRC; CLEAN R CARB
HOSE BED BODY	1	2FL; COOLANT SENSOR
REPAIR FROM PM - FLOATAPUMP	1	2IH; SEAT AIR BAG
SEAT FRONT		
CHECK ENGINE LIGHT		

Service Requests:

10/28/2024	SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW T42 (spare tender) hose bed cover on tender is torn and turn lock clasp are missing and/or broken. the front of the bed cover is being held down by a ratchet tie down strap-on.
01/10/2025	SERVICE REQUEST / 12: BROKEN / NEED OUTSIDE REPAIR bed cover ripped off due to age, float a pump not working, water tank level light not working
01/13/2025	SERVICE REQUEST / 12: BROKEN / INSPECT check engine light is on

CSHOP-2025-4402

Date Opened 10-7-2025 Date Finished 10-14-2025 Meter 1 Reading: 80,654

TASKS PERFORMED	NO PARTS USED
SURPLUS PREP	

Asset Work Order History 10154943

CSHOP-2025-506

Comments: **TENDER ST2: ENGINE**

Date Opened 1-31-2025

Date Finished

5-1-2025

Meter 1 Reading:

80,654

TASKS PERFORMED

Q PARTS

FIRE PUMP PLUMBING

1

9AP; REVIEW MONITOR CAMERA

BACK UP CAMERA-MONITOR

1

9ES; MIRROR WIRELESS LICENSE PLATE BACKUP CAM

Service Requests:

01/30/2025

TIRES / 44: WORN / INSPECT
TIRE WEAR

01/30/2025

ALARMS / 49: CAN NOT DUPLICATE CONCERN / INSPECT
ALARM SIGNALS rear driver side emergency light missing

01/30/2025

ENGINE / 18: LEAKING / REPAIR
ENGINE multiple leaks from behind pump panel

CSHOP-2025-853

Comments: **CALLAGHAN`S TIRE**

Date Opened 2-20-2025

Date Finished

2-20-2025

Meter 1 Reading:

0

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR?

DAN CALLAGHAN ENTERPRISES

CSHOP-2025-967

Comments: **TENDER ST2: VEHICLE LIGHTS NOT WORKING SPARE AT 22**

Date Opened 2-27-2025

Date Finished

5-1-2025

Meter 1 Reading:

80,654

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
HEADLIGHTS LOW BEAM

1

9ES; LIGHT, FIRETECH HEADLIGHT KIT (4) H & L

Service Requests:

02/26/2025

LIGHTS / 43: WEAK / EXCHANGE - NEW
VEHICLE LIGHTS NOT WORKING Both sides headlights have water in them and need to be replaced. Blinkers and Hazzard lights do not work at all now. Engine belts are loose and squealing loudly. Tachometer not working correctly. Rear camera needs to be replaced.

RADIO-2019-529

Comments: **T72 MDC**

Date Opened 6-17-2019

Date Finished

6-17-2019

Meter 1 Reading:

0

TASKS PERFORMED

NO PARTS USED

PC RELATED

Service Requests:

06/17/2019

RADIO / /
INSTALL MDC

Asset Work Order History 10154943

SSHOP-2021-10

Date Opened 1-7-2021

Date Finished

1-26-2021

Meter 1 Reading:

73,275

TASKS PERFORMED

WIPER BLADES
HEADLIGHTS LOW BEAM
LIGHTING SYSTEM

Q PARTS

2 9IP; WIPER BLADE 15

SSHOP-2021-14

Comments: **AIR LEAK**

Date Opened 1-11-2021

Date Finished

2-11-2021

Meter 1 Reading:

73,275

TASKS PERFORMED

DIAGNOSTIC TEST
COOLANT
AIR SYSTEM

Q PARTS

1 2FL; SWITCH IGNITION POLLAK
1 TWD; SWROT2POSLEVER2STUDS
1 TWD; VELVAC
1 2FL; MANIFOLD
1 2FL; SWITCH
1 2FL; SWITCH NORMAL OPEN
1 2FL; SWITCH, NORMAL OPEN
1 2FL; NORM CLSD 2 WIRE PRES SW

SSHOP-2021-26

Date Opened 1-15-2021

Date Finished

1-15-2021

Meter 1 Reading:

73,275

TASKS PERFORMED

REAR WINDOW

NO PARTS USED

SSHOP-2021-82

Comments: **QC**

Date Opened 3-3-2021

Date Finished

4-7-2021

Meter 1 Reading:

73,564

TASKS PERFORMED

QUALITY CHECK-REPAIRS
DISCHARGE GAUGE
REPAIR FROM PM - FIRE PUMP SYS
BRAKES
STROBE LIGHTS

Q PARTS

1 LIT; LED M C LAMP
1 5CS; GAUGE 3 5 30 600 WH
1 1WL; LIGHT LED RED TIR6
2 LMP; LAMP
1 2FR; TOTAL CONTROL
1 NONSTOCK; FREIGHT CHARGE
1 5FR; SENSOR INTAKE 0 600 PSI
1 2FL; SWITCH

SSHOP-2024-1178

Comments: **QC REPAIRS**

Date Opened 9-20-2024

Date Finished

10-7-2024

Meter 1 Reading:

0

TASKS PERFORMED

QUALITY CHECK-REPAIRS
HVAC SYSTEM

Q PARTS

6 RPO; TRUEFUEL
2 8HD; STRAP, RATCHET (4 PACK)

Asset Work Order History 10154943

SSHOP-2024-1252

Comments: **BATTS**
Date Opened 10-7-2024 Date Finished 10-7-2024 Meter 1 Reading: 0

<u>TASKS PERFORMED</u>	<u>Q</u>	<u>PARTS</u>
BATTERY	4	1AD; 1000 CCA 31 SERIES BATTERY

SSHOP-2024-1257

Comments: **TIRE**
Date Opened 10-8-2024 Date Finished 10-30-2024 Meter 1 Reading: 0

<u>TASKS PERFORMED</u>	<u>NO PARTS USED</u>
------------------------	----------------------

TIRE

VENDOR? DAN CALLAGHAN ENTERPRISES

SSHOP-2024-1495

Date Opened 11-22-2024 Date Finished 11-22-2024 Meter 1 Reading: 78,750

<u>TASKS PERFORMED</u>	<u>NO PARTS USED</u>
------------------------	----------------------

FIRE PUMP

SSHOP-2025-109

Date Opened 1-28-2025 Date Finished 2-20-2025 Meter 1 Reading: 0

<u>TASKS PERFORMED</u>	<u>NO PARTS USED</u>
------------------------	----------------------

TIRE

SSHOP-2025-110

Comments: **TIRE**
Date Opened 1-28-2025 Date Finished 2-20-2025 Meter 1 Reading: 0

<u>TASKS PERFORMED</u>	<u>NO PARTS USED</u>
------------------------	----------------------

TIRE