

10/16/2025
3:06:10 PM

10210021 Palm Beach County Fleet Management Asset Maintenance History
2019 JOHN DEERE GATOR HPX815E Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Total Hours: 39.75	Labor: 2,889.75	Parts: 1,793.37	Comm: 0.00	Charged: 4683.12
---------------------------	------------------------	------------------------	-------------------	-------------------------

Work Order: 1903811	Meter: 1	In Date: 04/09/2019	Closed: 04/09/2019
----------------------------	-----------------	----------------------------	---------------------------

Problem: pre delivery inspection

Work Completed

- pre delivery inspection
- Shop Supplies

Parts Issued

Shop Supplies	1.00
---------------	------

Quantity

Hours: 2.00	Comm: 0.00	Labor: 134.00	Parts: 3.00	Total: 137.00
-------------	------------	---------------	-------------	---------------

Work Order: 2005285	Meter: 149	In Date: 05/27/2020	Closed: 06/03/2020
----------------------------	-------------------	----------------------------	---------------------------

Problem: Pm service.

Work Completed

- Pm Service
- Test drive before and after repairs.
- Clean and adjust parking brake.
- Shop Supplies

Parts Issued

Napagold Air Filter	1.00
Napagold Air Filter	1.00
Napagold Oil Filter	1.00
15w40 Bulk Tank Pahokee	4.00
Napagold Fuel Filter	1.00
Shop Supplies	1.00

Quantity

Hours: 5.75	Comm: 0.00	Labor: 419.75	Parts: 46.11	Total: 465.86
-------------	------------	---------------	--------------	---------------

Work Order: 2107163	Meter: 367	In Date: 06/29/2021	Closed: 07/09/2021
----------------------------	-------------------	----------------------------	---------------------------

Problem: PM Service.

Work Completed

- Preventive Maintenance Service
- Replace worn front tires. Nitro fill tires.
- Service winch and respool cable correctly
- Shop Supplies

Parts Issued

15w40 Bulk Tank Pahokee	4.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
Napagold Air Filter	1.00
24x9.5x10 At Tire	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Quantity

Hours: 6.00	Comm: 0.00	Labor: 438.00	Parts: 342.67	Total: 780.67
-------------	------------	---------------	---------------	---------------

10/16/2025
3:06:10 PM

10210021

Palm Beach County Fleet Management Asset Maintenance History
2019 JOHN DEERE GATOR HPX815E Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 2111083 **Meter:** 437 **In Date:** 10/14/2021 **Closed:**
Problem: PM Service.

Work Completed

- Preventive Maint. Service

Hours: 0.00

Comm: 0.00

Labor: 0.00

Parts: 0.00

Total: 0.00

Work Order: 2207979 **Meter:** 725 **In Date:** 08/02/2022 **Closed:** 08/18/2022
Problem: PM Service.

Work Completed

- Preventive Maint. Service

- replaced both front tires

- test drive

- Shop Supplies

Parts Issued

Quantity

Napagold Fuel Filter 1.00

Napagold Air Filter 1.00

Napagold Air Filter 1.00

15w40 Bulk Tank Pahokee 4.00

Napagold Oil Filter 1.00

24-1050-10b Nhs All Trail 2.00

Shop Supplies 1.00

Tire Disposal Fee 2.00

Hours: 5.00

Comm: 0.00

Labor: 365.00

Parts: 314.93

Total: 679.93

Work Order: 2310256 **Meter:** 1058 **In Date:** 10/10/2023 **Closed:** 10/26/2023
Problem: PM Service

Work Completed

- Pm Service.

- customer complaint horn and blinkers inop found missing fuse installed
fuses and checked for electrical draw none found

- test drive

- adjusted parking brake and inspected cables and pads

- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter 1.00

Napagold Air Filter 1.00

Napagold Fuel Filter 1.00

Napagold Oil Filter 1.00

15w40 Bulk Tank Pahokee 4.00

Shop Supplies 1.00

Hours: 7.00

Comm: 0.00

Labor: 511.00

Parts: 42.59

Total: 553.59

10/16/2025
3:06:10 PM

10210021

Palm Beach County Fleet Management Asset Maintenance History
2019 JOHN DEERE GATOR HPX815E Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 2410307 **Meter:** 1345 **In Date:** 10/28/2024 **Closed:** 12/10/2024
Problem: PM Service

Work Completed

- Pm service
- Replaced worn tires
- Right front fender damaged. R/r Rops, glove box, headlight mounts and mud flap. Installed new fender.
- Replaced damaged positive cable and respool winch cable correctly. Straight winch cable roller fairlead.
- Charge and load test battery, it failed. Installed new battery and checked charging system, it passed.
- Blinkers, hazards and horn does not work. Test wiring; found corrosion on power supply circuit and shorted flasher module. Cleaned wiring connections and installed new module.
- Engine bogs and will not rev. Found clogged spark arrest screen. R/r screen and clean.
- Shop Supplies

Parts Issued

Quantity

Napagold Fuel Filter	1.00
15w40 Bulk Tank Pahokee	4.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Non-chlor Brake Clnr	1.00
24x9.5-10 Tire	2.00
24x10.50-10 Tire	2.00
Fender Kit	1.00
Macs Chain Cable Lube	1.00
Battery	1.00
Flasher Relay	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 12.00 Comm: 0.00

Labor: 876.00 Parts: 1,044.09 Total: 1,920.09

Work Order: 2507432 **Meter:** 1471 **In Date:** 08/08/2025 **Closed:** 08/15/2025
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00

Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 39.75

Total Labor: 2,889.75

Total Comm: 0.00

Total Parts: 1,793.37