

10/16/2025
3:15:23 PM

Palm Beach County Fleet Management Asset Maintenance History
10214741 2020 SMITHCO SAND STAR Ballfield Groomer

Total Hours: 59.00		Labor: 4,307.00		Parts: 2,024.41		Comm: 0.00		Charged: 6331.41	
Work Order: 2003511		Meter: 1				In Date: 04/07/2020		Closed: 04/08/2020	
Problem: pre delivery inspection									
Work Completed				Parts Issued				Quantity	
- pre delivery inspection				Shop Supplies				1.00	
- Shop Supplies									
Hours: 2.00		Comm: 0.00		Labor: 146.00		Parts: 4.00		Total: 150.00	
Work Order: 2007521		Meter: 68				In Date: 07/31/2020		Closed: 10/30/2020	
Problem: Hard to steer.Slow on reverse.									
Work Completed				Parts Issued				Quantity	
- Customers complaint hard to steer. Found dowel pin broken and jamming				Shop Supplies				1.00	
gears, remove steering assembly repair and reinstall.									
- Customers complaint no reverse, adjust traction pedal linkage.									
- Shop Supplies									
Hours: 4.75		Comm: 0.00		Labor: 346.75		Parts: 4.00		Total: 350.75	
Work Order: 2010859		Meter: 70				In Date: 10/28/2020		Closed: 11/13/2020	
Problem: throttle cable/ jump start/ water in fuel tank									
Work Completed				Parts Issued				Quantity	
- Water in fuel,drain tank ,clean lines, replace filter, bleed fuel system				Non-chlor Brake Clnr				1.00	
- Load test and charge battery				Fuel Element				1.00	
- diagnose problem dealer to Fleet and warranty throttle cable				Shop Supplies				1.00	
- Shop Supplies									
Hours: 3.00		Comm: 0.00		Labor: 219.00		Parts: 13.77		Total: 232.77	

10/16/2025
3:15:23 PM

Palm Beach County Fleet Management Asset Maintenance History
10214741 2020 SMITHCO SAND STAR Ballfield Groomer

Work Order: 2102732 **Meter:** 171 **In Date:** 03/10/2021 **Closed:** 03/12/2021
Problem: Rake will not start.Had to drive to Colusa Park to bypass and start unit and transport to SR Shop for repairs.

Work Completed

- Customers complaint wont start. Remove panels found broken wire on starter motor. Repair wiring, reassemble, test run.
- Travel to Caloosa park to repair broken down ballfield groomer stuck on field.
- Shop Supplies

Parts Issued

	Quantity
Shop Supplies	1.00

Hours: 3.00	Comm: 0.00	Labor: 219.00	Parts: 4.00	Total: 223.00
-------------	------------	---------------	-------------	---------------

Work Order: 2103468 **Meter:** 182 **In Date:** 03/26/2021 **Closed:** 04/09/2021
Problem: Located at Caloosa Park. Due for PM Service - Also has a wire broken off the starter that needs repair. Thanks!

Work Completed

- Preventive Maint. Service
- Service hydraulic system, replace filter, correct fluid level.
- Customers complaint starter wire broke from vibration. Replace connections with heavy brass eye connectors.
- Wash equipment for service and repairs.
- Verify fuel tank is contaminated with water and debris, drain fuel tank, clean screen on pick up tube, replace filters and purge air from system.
- Shop Supplies

Parts Issued

	Quantity
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
15w40 Bulk South Reg	4.00
Napagold Oil Filter	1.00
Aw68 Bulk Sr	2.00
Hydraulic Filter	1.00
Battery Cable Lug	4.00
Fuel Element	1.00
Shop Supplies	1.00

Hours: 9.75	Comm: 0.00	Labor: 711.75	Parts: 88.69	Total: 800.44
-------------	------------	---------------	--------------	---------------

Work Order: 2105749 **Meter:** 225 **In Date:** 05/25/2021 **Closed:** 05/28/2021
Problem: Check for no start.

Work Completed

- Remove paneling to access battery. Battery tested bad, replace battery, check charging system.
- Shop Supplies

Parts Issued

	Quantity
Warranty	1.00
Shop Supplies	1.00

Hours: 1.25	Comm: 0.00	Labor: 91.25	Parts: 143.53	Total: 234.78
-------------	------------	--------------	---------------	---------------

10/16/2025
3:15:23 PM

Palm Beach County Fleet Management Asset Maintenance History
10214741 2020 SMITHCO SAND STAR Ballfield Groomer

Work Order: 2109139 **Meter:** 300 **In Date:** 08/23/2021 **Closed:** 09/15/2021
Problem: Needs tires.Goes into reverse after start.Adjust parking brake.

Work Completed

Parts Issued

Quantity

- Customers complaint rear tires are worn. Replace three tires and correct all Nitrogen levels to 8 Psi.

22x11.00-10 P322 Knobby 3.00

Shop Supplies 1.00

- Verify traction pedal bracket fell of shaft. Reinstall and test run.

Tire Disposal Fee 3.00

- Customers complaint parking break wont hold. Remove rear tires and adjust parking brake.

- Shop Supplies

Hours: 4.50

Comm: 0.00

Labor: 328.50

Parts: 226.15

Total: 554.65

Work Order: 2203364 **Meter:** 421 **In Date:** 03/29/2022 **Closed:** 04/01/2022
Problem: PM Service.

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service

Napagold Air Filter 1.00

- Service hydraulic system, replace filter, correct fluid level.

Napagold Air Filter 1.00

- Verify parking brake is not holding. Remove rear wheels, clean and adjust rear drum brake assemblies.

Fuel Element 1.00

15w40 Bulk South Reg 4.00

- Shop Supplies

Napagold Oil Filter 1.00

Napa Hydraulic Filtr 1.00

Aw68 Bulk Sr 4.00

Shop Supplies 1.00

Hours: 6.00

Comm: 0.00

Labor: 438.00

Parts: 52.37

Total: 490.37

Work Order: 2209713 **Meter:** 528 **In Date:** 09/19/2022 **Closed:** 09/22/2022
Problem: Needs new battery, requires jump start, slow start

Work Completed

Parts Issued

Quantity

- Battery failed load test, Replace battery.

Battery 1.00

- Shop Supplies

Shop Supplies 1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 116.19

Total: 189.19

10/16/2025
3:15:23 PM

Palm Beach County Fleet Management Asset Maintenance History
10214741 2020 SMITHCO SAND STAR Ballfield Groomer

Work Order: 2300374 **Meter:** 598 **In Date:** 01/12/2023 **Closed:** 02/03/2023

Problem: hours meter. Front tire. Hard start

Work Completed

- C/c Hour meter inoperable. Verify complaint replace hour meter at 600 hours.
- Customers complaint front tire. Replace front tire mount, correct all Nitrogen levels to 5 Psi.
- Customers complaint hard to start. Verify terminals are corroded, Replace terminals.
- Shop Supplies

Hours: 3.50

Comm: 0.00

Parts Issued

	Quantity
Hour Meter	1.00
22x11.00-10 P322 Knobby	1.00
Batt Cable Terminal	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00
Freight Charge	1.00

Labor: 255.50

Parts: 192.47

Total: 447.97

Work Order: 2307069 **Meter:** 725 **In Date:** 07/18/2023 **Closed:** 07/27/2023

Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Service hydraulic system, replace filter, correct fluid level.
- Verify rear tires are worn. Replace two rear tires, mount correct all nitrogen levels to 8 Psi.
- Shop Supplies

Hours: 6.50

Comm: 0.00

Parts Issued

	Quantity
Napagold Air Filter	1.00
Inner Air Filter Replaces 2845	1.00
Fuel Element	1.00
15w40 Bulk South Reg	4.00
Proformer Oil Filter	1.00
10w30 Bulk Sr	2.00
Napa Hydraulic Filtr	1.00
22x11.00-10 4ply Tire Knobby	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Labor: 474.50

Parts: 226.82

Total: 701.32

Work Order: 2307577 **Meter:** 725 **In Date:** 07/31/2023 **Closed:**

Problem: Throttle linkage

Work Completed

- Cab Miscellaneous

Hours: 0.00

Comm: 0.00

Labor: 0.00

Parts: 0.00

Total: 0.00

10/16/2025
3:15:23 PM

Palm Beach County Fleet Management Asset Maintenance History
10214741 2020 SMITHCO SAND STAR Ballfield Groomer

Work Order: 2307650 **Meter:** 730 **In Date:** 08/01/2023 **Closed:** 08/03/2023
Problem: throttle rod keeps popping out. Brakes

Work Completed

Parts Issued

Quantity

- C/c throttle keeps popping out. Verify ball joint fittings for traction pedal is broken, replace joint, adjust linkage, test run.

Shop Supplies

1.00

- C/c Brakes. Verify operator does not release parking brake when in use. Adjust parking brake shoes, install label on dash reminding to release parking brake.

- Shop Supplies

Hours: 3.00

Comm: 0.00

Labor: 219.00

Parts: 2.65

Total: 221.65

Work Order: 2310106 **Meter:** 730 **In Date:** 10/04/2023 **Closed:** 10/12/2023
Problem: Battery

Work Completed

Parts Issued

Quantity

- C/c battery. Verify complaint, replace battery after failed load test. Clean and repair corroded terminals and wires. Check charging system.

Battery

1.00

22x11.00-10 4ply Tire Knobby

1.00

- Verify needs tire. Mount, correct all Nitrogen levels to 8 Psi.

Shop Supplies

1.00

- Shop Supplies

Tire Disposal Fee

1.00

Hours: 1.75

Comm: 0.00

Labor: 127.75

Parts: 197.12

Total: 324.87

10/16/2025
3:15:23 PM

Palm Beach County Fleet Management Asset Maintenance History
10214741 2020 SMITHCO SAND STAR Ballfield Groomer

Work Order: 2407068 **Meter:** 348 **In Date:** 07/23/2024 **Closed:** 08/21/2024
Problem: PM Service.

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Napagold Air Filter	1.00
- Service hydraulic system, replace filter, correct fluid level. test run.	Napagold Air Filter	1.00
- C/c seat. Replace seat.	15w40 Bulk South Reg	4.00
- C/c front tire. Verify front tire is worn. Replace front tire, correct Nitrogen levels to 7 Psi.	Napagold Oil Filter	1.00
- Shop Supplies	Fuel Element	1.00
	10w30 Bulk Sr	2.00
	Napa Hydraulic Filtr	1.00
	22x11.00-10 4ply Tire Knobby	1.00
	Seat	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	1.00
	Freight Charge	1.00
Hours: 7.00 Comm: 0.00	Labor: 511.00 Parts: 752.66	Total: 1,263.66

Work Order: 2508716 **Meter:** 348 **In Date:** 09/16/2025 **Closed:** 09/17/2025
Problem: Transition Prep Charge

Work Completed				
- Transition Prep Charge				
Hours: 2.00 Comm: 0.00	Labor: 146.00	Parts: 0.00	Total: 146.00	

Total Hours: 59.00 Total Labor: 4,307.00 Total Comm: 0.00 Total Parts: 2,024.41