

12/18/2025
11:32:26 AM

Palm Beach County Fleet Management Asset Maintenance History
10181114 2010 FORD F150 Pickup, 1/2 Ton

Total Hours: 139.55		Labor: 9,173.90	Parts: 8,698.34	Comm: 1,479.80	Charged: 19352.04
Work Order: 1005128		Meter: 325	In Date: 05/17/2010 Closed: 05/24/2010		
Problem: install tool box					
Work Completed			Parts Issued		Quantity
- Install tool box secure ck ok			82194 Gray Silicone (permatex)		1.00
- Shop Supplies			Shop Supplies		1.00
			117 Used Tool Box Weather Guard Tool Box		1.00
Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 101.83	Total: 161.83
Work Order: 1005147		Meter: 0	In Date: 05/18/2010 Closed: 05/18/2010		
Problem: Pre Delivery Inspection					
Work Completed					
- Pre Delivery Inspection					
Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 0.00	Total: 120.00
Work Order: 1012131		Meter: 3053	In Date: 10/29/2010 Closed: 11/03/2010		
Problem: Pm service					
Work Completed			Parts Issued		Quantity
- Perform pm service.			Shop Supplies		1.00
- Shop Supplies			1372 Oil Filter Frm Ph2 Wix 51372		1.00
			5w20 Engine Oil		7.00
			Used Firex Refurbed Fire Extingshers		1.00
Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 31.39	Total: 151.39
Work Order: 1012359		Meter: 3053	In Date: 11/03/2010 Closed: 11/05/2010		
Problem: flash canceiver spot # 220					
Work Completed			Parts Issued		Quantity
- Flash Canceiver			Shop Supplies		1.00
- Shop Supplies					
Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.00	Total: 62.00

12/18/2025
11:32:26 AM

Palm Beach County Fleet Management Asset Maintenance History
10181114 2010 FORD F150 Pickup, 1/2 Ton

Work Order: 1105140 **Meter:** 6521 **In Date:** 05/13/2011 **Closed:** 05/19/2011
Problem: P.M. Service.

Work Completed

- Perform pm service.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
5w20 Engine Oil	7.00
31-22 Wiper Blades 22" Wiper Blade	2.00

Hours: 3.00

Comm: 0.00

Labor: 180.00

Parts: 30.75

Total: 210.75

Work Order: 1112986 **Meter:** 10477 **In Date:** 12/08/2011 **Closed:**
Problem: P.M. Service.

Work Completed

-

Hours: 0.00

Comm: 0.00

Labor: 0.00

Parts: 0.00

Total: 0.00

Work Order: 1113137 **Meter:** 10477 **In Date:** 12/14/2011 **Closed:** 12/16/2011
Problem: pm service/ check wipers

Work Completed

- Pm Service
- Rotate balance tires
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
5w20 Engine Oil	7.00
31-22 Wiper Blades 22" Wiper Blade	2.00
Used Firex Refurbed Fire Extingshers	1.00

Hours: 3.00

Comm: 0.00

Labor: 180.00

Parts: 51.14

Total: 231.14

Work Order: 1203735 **Meter:** 12346 **In Date:** 04/19/2012 **Closed:** 04/26/2012
Problem: need extra kek

Work Completed

- Make and program 1 extra key
- Shop Supplies

Parts Issued

Quantity

164-r8040 Ignition Key 2011- Newer (ford)	1.00
Shop Supplies	1.00

Hours: 0.50

Comm: 0.00

Labor: 30.00

Parts: 25.25

Total: 55.25

12/18/2025
11:32:26 AM

Palm Beach County Fleet Management Asset Maintenance History
10181114 2010 FORD F150 Pickup, 1/2 Ton

Work Order: 1206522 **Meter:** 13898 **In Date:** 07/12/2012 **Closed:** 07/23/2012
Problem: P.M. service.

Work Completed

- Perform pm service.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
Ca10262 Air Filter Mtc Fa1883 Wix 49883	1.00
5w20 Engine Oil	7.00
7090blk Frt Floor Mats (rubber Queen)	1.00
31-22 Wiper Blades 22" Wiper Blade	2.00

Hours: 3.00

Comm: 0.00

Labor: 180.00	Parts: 65.05	Total: 245.05
---------------	--------------	---------------

Work Order: 1301971 **Meter:** 17908 **In Date:** 02/26/2013 **Closed:** 03/12/2013
Problem: Pm service.

Work Completed

- P.m. Service.
- Rotate and balance all tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
1372 Oil Filter	1.00
31-22 Wiper Blades 22	2.00
Used Firex Refurbed F	1.00
Shop Supplies	1.00

Hours: 3.00

Comm: 0.00

Labor: 180.00	Parts: 53.90	Total: 233.90
---------------	--------------	---------------

Work Order: 1312755 **Meter:** 24120 **In Date:** 12/20/2013 **Closed:** 01/08/2014
Problem: Pm service and reset oil life message.

Work Completed

- Perform pm service.
- Test starting and charging system.battery failed loadtest after recharge.replace failed battery with new.
- Rotate and balance all four tires.
- Make up and replace missing front asset nunbers with new.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Battery	1.00
Shop Supplies	1.00

Hours: 4.50

Comm: 0.00

Labor: 270.00	Parts: 169.31	Total: 439.31
---------------	---------------	---------------

12/18/2025
11:32:26 AM

Palm Beach County Fleet Management Asset Maintenance History
10181114 2010 FORD F150 Pickup, 1/2 Ton

Work Order: 1411722 **Meter:** 31870 **In Date:** 11/19/2014 **Closed:** 12/09/2014
Problem: P.M. Service.

Work Completed

- Pm service.
- Replace and balance all four tires.
- Complete front end alignment.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Stg Wheel Cov - Ford	1.00
235 75r17 Adventure	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 6.50

Comm: 0.00

Labor: 390.00

Parts: 1,027.80

Total: 1,417.80

Work Order: 1500159 **Meter:** 31870 **In Date:** 12/04/2014 **Closed:** 01/06/2015
Problem: damage to frt bumper

Work Completed

- damage to frt bumper

Hours: 0.00

Comm: 886.04

Labor: 0.00

Parts: 0.00

Total: 886.04

Work Order: 1505704 **Meter:** 35381 **In Date:** 06/08/2015 **Closed:** 07/27/2015
Problem: Tow in,dead battery.P.M. Service.

Work Completed

- Pm service.
- Test starting and charging system.battery failed loadtest.replace defective battery.
- Computer diagnose for Abs warning light on.pinpoint test for no communication with Abs module.test and replace defective Abs module and Hcu then reprogram and bleed system.
- Resurface both front brake rotors due to brake pulsation.service front brakes and calipers.roadtest.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Wiper Blade	2.00
Wd40 16oz	1.00
Battery	1.00
Abc Module	1.00
Abs Module	1.00
Shop Supplies	1.00

Hours: 10.50

Comm: 0.00

Labor: 630.00

Parts: 2,113.00

Total: 2,743.00

12/18/2025
11:32:26 AM

Palm Beach County Fleet Management Asset Maintenance History
10181114 2010 FORD F150 Pickup, 1/2 Ton

Work Order: 1505727 **Meter:** 35309 **In Date:** 06/08/2015 **Closed:** 06/08/2015
Problem: no start

Work Completed

- Tow From: 8100 forest hill blvd To: lv shop

Hours: 0.00 Comm: 104.15 Labor: 0.00 Parts: 0.00 Total: 104.15

Work Order: 1507501 **Meter:** 35381 **In Date:** 07/28/2015 **Closed:** 07/31/2015
Problem: Radio works intermittently.

Work Completed

- Diagnose and replace defective radio assemble.

- Shop Supplies

Parts Issued

Quantity

Radio 1.00

Shop Supplies 1.00

Hours: 1.50 Comm: 0.00 Labor: 90.00 Parts: 173.60 Total: 263.60

Work Order: 1508763 **Meter:** 36077 **In Date:** 09/01/2015 **Closed:** 09/16/2015
Problem: Check engine light on.Transmission shifts hard.

Work Completed

- Computer diagnose for check engine light on.codes P0171 and P0174
Inspect for vacume leaks and secure intake air duct to throttle
body.reset.reset Kam and test drive.

- Shop Supplies

Parts Issued

Quantity

Shop Supplies 1.00

Hours: 2.25 Comm: 0.00 Labor: 135.00 Parts: 2.00 Total: 137.00

Work Order: 1600749 **Meter:** 38161 **In Date:** 01/22/2016 **Closed:** 02/04/2016
Problem: P.M. service.

Work Completed

- Pm service.

- Pressure test and cooling system check.reverse flush and refill system.

- Perform transmission fluid flush and refill.

- Rotate and balance all four tires.

- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil 7.00

Napagold Oil Filter 1.00

Used Fire X Refurbished 1.00

22" Wiper Blade 2.00

Washer Fluid Concentr 1.00

Coolant Ford Gold 2.00

Syn-atf Trans Fluid S 14.00

Shop Supplies 1.00

Hours: 6.50 Comm: 0.00 Labor: 390.00 Parts: 150.05 Total: 540.05

12/18/2025
11:32:26 AM

Palm Beach County Fleet Management Asset Maintenance History
10181114 2010 FORD F150 Pickup, 1/2 Ton

Work Order: 1604558 **Meter:** 39665 **In Date:** 04/29/2016 **Closed:** 05/11/2016
Problem: Brake squeals. Check rear suspension.

Work Completed

- Resurface all four rusted brake rotors,replace front and rear brake pads.service and lube front and rear calipers.flush and bleed system.
- Replace both rear shocks.
- Shop Supplies

Parts Issued

Quantity

Brake Pads Front	1.00
Brake Pad	1.00
Reflex Truck Shock	2.00
Brake Pad	1.00
Shop Supplies	1.00

Hours: 7.00

Comm: 0.00

Labor: 420.00	Parts: 336.32	Total: 756.32
---------------	---------------	---------------

Work Order: 1700835 **Meter:** 45091 **In Date:** 01/26/2017 **Closed:** 02/06/2017
Problem: P.M. service.

Work Completed

- P.m. Service.
- Replace and balance four new tires.
- Complete wheel alignment.test drive.
- Fabricate and treplace asset #s.
- Shop Supplies

Parts Issued

Quantity

Used Fire X Refurbished	1.00
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
235 75r17 Adventure	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 7.50

Comm: 0.00

Labor: 450.00	Parts: 899.91	Total: 1,349.91
---------------	---------------	-----------------

12/18/2025
11:32:26 AM

Palm Beach County Fleet Management Asset Maintenance History
10181114 2010 FORD F150 Pickup, 1/2 Ton

Work Order: 1708168 **Meter:** 48552 **In Date:** 08/18/2017 **Closed:** 08/31/2017
Problem: PM Service, TPMS light on.

Work Completed

- P.m. service.
- Replace failed Tpms sensor in left front tire.rotate and high speed balance all four tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
22" Wiper Blade	2.00
Tpms12 Sensor Tire Pr	1.00
Shop Supplies	1.00

Hours: 4.00

Comm: 0.00

Labor: 240.00 Parts: 130.07 Total: 370.07

Work Order: 1804290 **Meter:** 50740 **In Date:** 04/25/2018 **Closed:** 05/03/2018
Problem: P.M. service and left front door lock inop.

Work Completed

- P.m. service.
- Left front door lock inop.replace left front door lock cylinder .rekey lock cylinder to match lock set.
- Inspect and service rear differential.
- Rotate and high speed balance all four tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
B Fluid Dot 3-32oz	1.00
Friction Modifier	1.00
20" Wiper Blade	2.00
Used Fire X Refurbished	1.00
75w140 Ford Axle Lube	2.00
Lock Cylinder	1.00
Ford Triton Pvc Swc	1.00
2-pk 3in Spot Mirror	1.00
Shop Supplies	1.00

Hours: 5.50

Comm: 0.00

Labor: 330.00 Parts: 220.07 Total: 550.07

12/18/2025
11:32:26 AM

Palm Beach County Fleet Management Asset Maintenance History
10181114 2010 FORD F150 Pickup, 1/2 Ton

Work Order: 1804998 **Meter:** 50889 **In Date:** 05/14/2018 **Closed:** 05/14/2018
Problem: 3 - Wash ticket(s) issued

Work Completed

- 3 - Wash ticket(s) issued

Hours: 0.00 Comm: 28.62 Labor: 0.00 Parts: 0.00 Total: 28.62

Work Order: 1810528 **Meter:** 52229 **In Date:** 10/12/2018 **Closed:** 10/18/2018
Problem: P.M. service and send to SE shop for canceiver removal.

Work Completed

- P.m. service.

- Charge battery . Test battery and charging system . Battery failed load test
. R&r defective battery.

- Rotate and balance all four tires. Nitrogen fill and reset Tpms.

- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil 6.00

Napagold Oil Filter 1.00

22" Wiper Blade 2.00

2pc Hd Mat Set Blk 1.00

Battery 1.00

Shop Supplies 1.00

Hours: 4.00 Comm: 0.00 Labor: 268.00 Parts: 192.98 Total: 460.98

Work Order: 1810642 **Meter:** 52232 **In Date:** 10/16/2018 **Closed:** 10/18/2018
Problem: remove canceiver

Work Completed

- remove cancaiver

- Shop Supplies

Parts Issued

Quantity

Shop Supplies 1.00

Hours: 1.00 Comm: 0.00 Labor: 67.00 Parts: 3.00 Total: 70.00

12/18/2025
11:32:26 AM

Palm Beach County Fleet Management Asset Maintenance History
10181114 2010 FORD F150 Pickup, 1/2 Ton

Work Order: 1904921 **Meter:** 54093 **In Date:** 05/06/2019 **Closed:** 05/13/2019
Problem: P.M. service and detail .

Work Completed

- P.m. service.
- Rotate and high speed balance all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Drain Plug	1.00
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 3.00

Comm: 0.00

Labor: 201.00 Parts: 49.85 Total: 250.85

Work Order: 1912630 **Meter:** 56121 **In Date:** 12/10/2019 **Closed:** 12/19/2019
Problem: pm service

Work Completed

- pm service

Parts Issued

Quantity

Napagold Oil Filter	1.00
10w30 Motor Oil	6.00
22" Wiper Blade	2.00

Hours: 2.00

Comm: 0.00

Labor: 146.00 Parts: 21.74 Total: 167.74

Work Order: 2005327 **Meter:** 60981 **In Date:** 05/28/2020 **Closed:** 06/11/2020
Problem: pm service

Work Completed

- pm service
- replace all tail light and reverse bulbs

Parts Issued

Quantity

Used Fire X Refurbished	1.00
10w30 Motor Oil	6.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Boxed Miniatures	2.00
Boxed Miniatures	2.00
Boxed Miniatures	2.00

Hours: 3.00

Comm: 0.00

Labor: 219.00 Parts: 40.40 Total: 259.40

12/18/2025
11:32:26 AM

Palm Beach County Fleet Management Asset Maintenance History
10181114 2010 FORD F150 Pickup, 1/2 Ton

Work Order: 2007037 **Meter:** 62283 **In Date:** 07/20/2020 **Closed:** 08/10/2020
Problem: check engine light

Work Completed

Parts Issued

Quantity

- diagnose codes P0130, P0150 replace both upstream O2 sensors

Sensor	2.00
--------	------

Hours: 2.50

Comm: 0.00

Labor: 182.50

Parts: 439.89

Total: 622.39

Work Order: 2011803 **Meter:** 64005 **In Date:** 11/30/2020 **Closed:** 12/09/2020
Problem: pm service

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service

Battery	1.00
---------	------

- Check , Load test. Replace battery

Napa Quart 5w20	6.00
-----------------	------

Napagold Oil Filter	1.00
---------------------	------

Napagold Air Filter	1.00
---------------------	------

Washer Fluid Concentr	1.00
-----------------------	------

22" Wiper Blade	2.00
-----------------	------

Bat Term Protector	1.00
--------------------	------

Hours: 3.00

Comm: 0.00

Labor: 219.00

Parts: 197.13

Total: 416.13

Work Order: 2105656 **Meter:** 66221 **In Date:** 05/21/2021 **Closed:** 06/04/2021
Problem: pm service

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service

Napa Quart 5w20	6.00
-----------------	------

Napagold Oil Filter	1.00
---------------------	------

22" Wiper Blade	2.00
-----------------	------

Used Fire X Refurbished	1.00
-------------------------	------

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 51.66

Total: 197.66

Work Order: 2111405 **Meter:** 68519 **In Date:** 10/22/2021 **Closed:** 10/25/2021
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00

Comm: 90.40

Labor: 0.00

Parts: 0.00

Total: 90.40

12/18/2025
11:32:26 AM

Palm Beach County Fleet Management Asset Maintenance History
10181114 2010 FORD F150 Pickup, 1/2 Ton

Work Order: 2112228 **Meter:** 68519 **In Date:** 11/15/2021 **Closed:**
Problem: pm service

Work Completed

- Preventive Maint. Service

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

Work Order: 2112329 **Meter:** 68530 **In Date:** 11/18/2021 **Closed:** 11/23/2021
Problem: P.M. service.

Work Completed

- Preventive Maint. Service

- Inspect Front Brakes, Brake Pads At Minium Death, Rotors Warped And
Out Of Spec, Replace Front Brake Pads, And Rotors

- Inspect All Tires R&r All Tires Balaance With Nitro Fill

- Test Drive And Perform Front End Alignment Retest

Parts Issued

Quantity

Napagold Oil Filter 1.00

5w20 Engine Oil 6.00

Washer Fluid Concentr 1.00

22" Wiper Blade 2.00

Non-chlor Brake Clnr 1.00

Brake Pad Set 1.00

Brake Rotor 2.00

235 75r17 Adventure 4.00

Tire Disposal Fee 4.00

Hours: 10.00 Comm: 0.00 Labor: 730.00 Parts: 896.49 Total: 1,626.49

Work Order: 2205810 **Meter:** 72025 **In Date:** 06/01/2022 **Closed:**
Problem: pm service

Work Completed

- Preventive Maint. Service

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

12/18/2025
11:32:26 AM

Palm Beach County Fleet Management Asset Maintenance History
10181114 2010 FORD F150 Pickup, 1/2 Ton

Work Order: 2205892 **Meter:** 72025 **In Date:** 06/02/2022 **Closed:** 06/14/2022
Problem: P.M. service.

Work Completed

- Preventive Maint. Service
- Rotate and speed balance, nitro fill
- Inspect driver seat trim broken, Install new, hub cap missing

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Housing	1.00
Center Cap	1.00

Hours: 3.30

Comm: 0.00

Labor: 240.90

Parts: 154.12

Total: 395.02

Work Order: 2210989 **Meter:** 73340 **In Date:** 10/26/2022 **Closed:** 10/28/2022
Problem: NO START

Work Completed

- diagnose no start - replace fuel pump relay - scan for codes no codes found
- check charging system - charged and tested battery

Parts Issued

Quantity

Relay	1.00
Motor Tune-up 16oz	1.00

Hours: 2.50

Comm: 0.00

Labor: 182.50

Parts: 21.43

Total: 203.93

Work Order: 2211705 **Meter:** 73363 **In Date:** 10/26/2022 **Closed:** 11/14/2022
Problem: NO START

Work Completed

- Tow From: 345 S Congress Ave, Delray (next to fuel pumps) To: 2601 Vista Pkwy, West Palm Beach 33411(se Shop)

Hours: 0.00

Comm: 113.00

Labor: 0.00

Parts: 0.00

Total: 113.00

12/18/2025
11:32:26 AM

Palm Beach County Fleet Management Asset Maintenance History
10181114 2010 FORD F150 Pickup, 1/2 Ton

Work Order: 2211938 **Meter:** 73581 **In Date:** 11/28/2022 **Closed:** 12/08/2022
Problem: pm service

Work Completed

- Preventive Maint. Service
- Rotate & Balance Tires

Parts Issued

Quantity

Napa Quart 5w20	6.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
High Gloss Coating	1.00
Non-chlor Brake Clnr	2.00

Hours: 3.00

Comm: 0.00

Labor: 219.00

Parts: 54.32

Total: 273.32

Work Order: 2301673 **Meter:** 74111 **In Date:** 02/21/2023 **Closed:** 03/02/2023
Problem: AC inop

Work Completed

- Diag A/c, Check For Codes, Check Charge, Repair Wire In Bjb And Replace Relay

Parts Issued

Quantity

Relay	1.00
-------	------

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 16.19

Total: 162.19

Work Order: 2304186 **Meter:** 74341 **In Date:** 04/26/2023 **Closed:** 04/28/2023
Problem: had to start twice to keep running then died on road coming to fleet/ pm

Work Completed

- Preventive Maint. Service
- Diag Vehicle No Start, Found Bad Fuel Pump Relay, Replaced Relay
- Battery Failed Load Test, Replaced Battery

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	6.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Relay	2.00
Battery	1.00

Hours: 4.00

Comm: 0.00

Labor: 292.00

Parts: 214.48

Total: 506.48

Work Order: 2304850 **Meter:** 74341 **In Date:** 04/26/2023 **Closed:** 05/15/2023
Problem: Died on road

Work Completed

- Tow From: Okeechobee and Jog right in front of the Publix. To: 2601 Vista Pkwy, West Palm Beach 33411se Shop)

Hours: 0.00

Comm: 124.30

Labor: 0.00

Parts: 0.00

Total: 124.30

12/18/2025
11:32:26 AM

Palm Beach County Fleet Management Asset Maintenance History
10181114 2010 FORD F150 Pickup, 1/2 Ton

Work Order: 2310311 **Meter:** 76565 **In Date:** 10/11/2023 **Closed:** 10/18/2023
Problem: pm service

Work Completed

- Preventive Maint. Service
- Load Test And Replaced Bad Battery, Tested Charging System

Parts Issued

Quantity

Napa Quart 5w20	6.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Battery	1.00

Hours: 3.00 Comm: 0.00 Labor: 219.00 Parts: 166.62 Total: 385.62

Work Order: 2310491 **Meter:** 76561 **In Date:** 10/10/2023 **Closed:** 10/17/2023
Problem: 1 - Wash ticket(s) Issued to: Harold Murray

Work Completed

- 1 - Wash ticket(s) Issued to: Harold Murray

Hours: 0.00 Comm: 8.98 Labor: 0.00 Parts: 0.00 Total: 8.98

Work Order: 2401133 **Meter:** 78469 **In Date:** 01/31/2024 **Closed:** 02/01/2024
Problem: wont start, drop vehicle parking lot where tickets get signed

Work Completed

- Replaced Fuel Pump Relay And Performed Fuel Pump Fuse Relocation
- Fueled Up Vehicle

Parts Issued

Quantity

Fuse Relocate Kit	1.00
Relay	1.00

Hours: 2.50 Comm: 0.00 Labor: 182.50 Parts: 49.52 Total: 232.02

Work Order: 2401501 **Meter:** 78837 **In Date:** 01/31/2024 **Closed:** 02/09/2024
Problem: wont start, drop vehicle parking lot where tickets get signed

Work Completed

- Tow From: 13425 Ellison Wilson Rd, Juno Burt Winters park To: Fleet Vista, Dispatch parking lot (my Office)

Hours: 0.00 Comm: 124.30 Labor: 0.00 Parts: 0.00 Total: 124.30

12/18/2025
11:32:26 AM

Palm Beach County Fleet Management Asset Maintenance History
10181114 2010 FORD F150 Pickup, 1/2 Ton

Work Order: 2403336 **Meter:** 80145 **In Date:** 04/04/2024 **Closed:** 04/08/2024
Problem: pm service

Work Completed

- Preventive Maint. Service
- Replace Taillight Bulb

Parts Issued

Quantity

Napa Quart 5w20	6.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Non-chlor Brake Clnr	2.00
Boxed Miniatures	1.00

Hours: 2.50

Comm: 0.00

Labor: 182.50

Parts: 73.15

Total: 255.65

Work Order: 2403821 **Meter:** 80273 **In Date:** 04/17/2024 **Closed:** 04/22/2024
Problem: fuel tank door problems

Work Completed

- Replaced Fuel Door Housing

Hours: 1.00

Comm: 0.00

Parts Issued

Quantity

Fuel Housing	1.00
--------------	------

Labor: 73.00

Parts: 36.87

Total: 109.87

Work Order: 2404246 **Meter:** 80477 **In Date:** 04/29/2024 **Closed:** 04/30/2024
Problem: check engine light/ instruments sweep

Work Completed

- Scan For Codes Replace Coolant Thermostat

Hours: 2.00

Comm: 0.00

Parts Issued

Quantity

Coolant Ford Gold	1.00
Thermostat	1.00

Labor: 146.00

Parts: 39.35

Total: 185.35

12/18/2025
11:32:26 AM

Palm Beach County Fleet Management Asset Maintenance History
10181114 2010 FORD F150 Pickup, 1/2 Ton

Work Order: 2409221 **Meter:** 82014 **In Date:** 09/24/2024 **Closed:** 09/25/2024
Problem: pm service

Work Completed

- Preventive Maint. Service

Parts Issued

Quantity

Napa Quart 5w20	6.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
oil auto	1.00
Coolent	1.00
Non-chlor Brake Clnr	2.00
Used Fire X Refurbished	1.00
Wiper Blade	2.00

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 123.22

Total: 269.22

Work Order: 2410162 **Meter:** 82511 **In Date:** 10/23/2024 **Closed:** 10/25/2024
Problem: dead battery

Work Completed

- Load Test Battery, Install New Battery And Pcm Relay

Parts Issued

Quantity

Battery	1.00
Relay	1.00

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 146.92

Total: 292.92

Work Order: 2502317 **Meter:** 85185 **In Date:** 03/10/2025 **Closed:** 03/14/2025
Problem: pm service

Work Completed

- Preventive Maint. Service

- Install New Third Brake Light Assembly And Bulbs

Parts Issued

Quantity

Napa Quart 5w20	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Beam Wiper Blade	2.00
Lamp Assy	1.00
Boxed Miniatures	3.00

Hours: 3.00

Comm: 0.00

Labor: 219.00

Parts: 125.62

Total: 344.62

12/18/2025
11:32:26 AM

Palm Beach County Fleet Management Asset Maintenance History
10181114 2010 FORD F150 Pickup, 1/2 Ton

Work Order: 2509437	Meter: 86914	In Date: 10/06/2025	Closed:
Problem: tire pressure			
Work Completed			
-			
Hours: 0.00	Comm: 0.00	Labor: 0.00	Parts: 0.00 Total: 0.00
Work Order: 2509527	Meter: 86914	In Date: 10/08/2025	Closed: 10/08/2025
Problem: Transition Prep Charge			
Work Completed			
- Transition Prep Charge			
Hours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 0.00 Total: 146.00
Total Hours: 139.55	Total Labor: 9,173.90	Total Comm: 1,479.80	Total Parts: 8,698.34