

12/18/2025
11:37:49 AM

Palm Beach County Fleet Management Asset Maintenance History
10203965 2017 FORD F150 Pickup, 1/2 Ton, Ext Cab

Total Hours: 101.25		Labor: 7,229.50	Parts: 6,233.79	Comm: 16,320.49	Charged: 29783.77
Work Order: 1711520		Meter: 348		In Date: 11/22/2017	Closed: 11/22/2017
Problem: 1061 - Pre Delivery Inspection					
Work Completed					
- Pre Delivery Inspection					
Hours: 2.00		Comm: 0.00		Labor: 120.00	Parts: 0.00 Total: 120.00
Work Order: 1802112		Meter: 1102		In Date: 02/26/2018	Closed: 02/27/2018
Problem: Install ignition power source for radio.					
Work Completed				Parts Issued	Quantity
- Fabericate and install fuse tap for ignition power soource for radio.				Micro Add A Circuit	1.00
- Shop Supplies				Shop Supplies	1.00
Hours: 0.50		Comm: 0.00		Labor: 30.00	Parts: 23.11 Total: 53.11
Work Order: 1804723		Meter: 3538		In Date: 05/04/2018	Closed: 05/09/2018
Problem: PM Service.					
Work Completed				Parts Issued	Quantity
- P.m. service.				trailer plug	1.00
- Replace faulty trailer socket due to water corrosion .rewire harness and seal socket with silicone.				5w20 Engine Oil	7.00
				Napagold Oil Filter	1.00
- Rotate and balance four tires.				Washer Fluid Concentr	1.00
- Shop Supplies				22" Wiper Blade	2.00
				Floor Mat-2pc Rub Bk	1.00
				Shop Supplies	1.00
Hours: 4.25		Comm: 0.00		Labor: 255.00	Parts: 68.00 Total: 323.00

12/18/2025
11:37:49 AM

Palm Beach County Fleet Management Asset Maintenance History
10203965 2017 FORD F150 Pickup, 1/2 Ton, Ext Cab

Work Order: 1808252 **Meter:** 6919 **In Date:** 08/10/2018 **Closed:** 09/18/2018
Problem: Check right front tire.

Work Completed

- Replace right front bent rim . Balance assembly and nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Wheel Asy	1.00
Tire Pressure Monitoring System Sensor (	1.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 192.10 Total: 252.10

Work Order: 1809927 **Meter:** 7372 **In Date:** 09/26/2018 **Closed:** 09/27/2018
Problem: Right rear tire going flat.

Work Completed

- Repair right rear tire and balance . Nitrogen fill tires.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1812756 **Meter:** 9431 **In Date:** 12/14/2018 **Closed:** 12/18/2018
Problem: PM Service

Work Completed

- P.m. service.
- Rotate and balance all four tires. Nitrofill all and reset Tpms.
- Shop Supplies

Parts Issued

Quantity

Napa Quart 5w20	7.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
22" Wiper Blade	2.00
Ford Triton Pvc Swc	1.00
Mac Wite Lithium Gres	1.00
Shop Supplies	1.00

Hours: 3.00 Comm: 0.00 Labor: 201.00 Parts: 79.74 Total: 280.74

Work Order: 1900715 **Meter:** 10282 **In Date:** 01/17/2019 **Closed:** 01/22/2019
Problem: Screw in right rear tire.

Work Completed

- Repair right rear tire and balance . Nitro fill all.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00 Comm: 0.00 Labor: 67.00 Parts: 3.00 Total: 70.00

12/18/2025
11:37:49 AM

Palm Beach County Fleet Management Asset Maintenance History
10203965 2017 FORD F150 Pickup, 1/2 Ton, Ext Cab

Work Order: 1906522 **Meter:** 14316 **In Date:** 06/20/2019 **Closed:** 06/24/2019
Problem: P.M. Service.

Work Completed

- P.m. service.
- Balance and rotate all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
2pc Hd Mat Set Blk	1.00
Ford Triton Pvc Swc	1.00
Shop Supplies	1.00

Hours: 3.00

Comm: 0.00

Labor: 201.00

Parts: 84.00

Total: 285.00

Work Order: 1908867 **Meter:** 16114 **In Date:** 08/23/2019 **Closed:** 08/29/2019
Problem: Blow out, drivers front tire.

Work Completed

- Replace left and left rear bent rims and replace left front damaged tire .
- Balance both . Nitrofill all tires .
- Shop Supplies

Parts Issued

Quantity

Tire Pressure Monitoring System Sensor (	2.00
Wheel Asy	2.00
245/70/17 Tire Mich	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 1.00

Comm: 0.00

Labor: 67.00

Parts: 618.59

Total: 685.59

Work Order: 1908923 **Meter:** 15982 **In Date:** 08/26/2019 **Closed:** 08/26/2019
Problem: Towed in for Flat tire

Work Completed

- Tow From: 441 N of Okeehchobee Blvd To: Vista

Hours: 0.00

Comm: 96.00

Labor: 0.00

Parts: 0.00

Total: 96.00

Work Order: 1910407 **Meter:** 16239 **In Date:** 08/27/2019 **Closed:** 10/08/2019
Problem: Damage to right rear fender & rear bumper

Work Completed

- Damage to right rear fender & rear bumper

Hours: 0.00

Comm: 1,474.13

Labor: 0.00

Parts: 0.00

Total: 1,474.13

12/18/2025
11:37:49 AM

Palm Beach County Fleet Management Asset Maintenance History
10203965 2017 FORD F150 Pickup, 1/2 Ton, Ext Cab

Work Order: 1912324 **Meter:** 16616 **In Date:** 12/02/2019 **Closed:** 01/21/2020
Problem: P.M. service and left running board loose ,noise right front wheel .

Work Completed

Parts Issued

Quantity

- P.m. service.
- R&r broken left side running board .
- Mount new fire extinguisher bracket behind left front seat .
- Rotate and high speed balance all four tires . Nitrofill all.
- Transport to and from dealer for oil leak and noise from right wheel area .
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Fire Ext Mount Strap Style	1.00
Step Asy	1.00
Shop Supplies	1.00

Hours: 6.30

Comm: 0.00

Labor: 459.90

Parts: 475.26

Total: 935.16

Work Order: 1912367 **Meter:** 16553 **In Date:** 10/23/2019 **Closed:** 12/03/2019
Problem: : Damage to left side of bed, rear bumper, both tail lights, hood, front bumper grille & right fro

Work Completed

- : Damage to left side of bed, rear bumper, both tail lights, hood, front bumper grille & right fro

Hours: 0.00

Comm: 5,823.18

Labor: 0.00

Parts: 0.00

Total: 5,823.18

Work Order: 2003096 **Meter:** 18555 **In Date:** 03/26/2020 **Closed:** 03/30/2020
Problem: Dead battery,had to jump.

Work Completed

Parts Issued

Quantity

- Charge battery fully . Test battery and charging system . Battery failed load test . R&r defective battery . Hook up lds to reset Bsm .
- Shop Supplies

Battry Motorcraft	1.00
Shop Supplies	1.00

Hours: 1.50

Comm: 0.00

Labor: 109.50

Parts: 180.69

Total: 290.19

12/18/2025
11:37:49 AM

Palm Beach County Fleet Management Asset Maintenance History
10203965 2017 FORD F150 Pickup, 1/2 Ton, Ext Cab

Work Order: 2007825 **Meter:** 23656 **In Date:** 08/07/2020 **Closed:** 08/11/2020
Problem: PM Service

Work Completed

Parts Issued

Quantity

- P.m. service.
- Test and replace defective strobe light switch .
- Replace cabin air filter and clean fresh air intake .
- Replace two tires . Rotate and high speed balance all four wheels . Nitrofill all.
- Perform complete front end alignment and road test .
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Fire Ext Mount Strap Style	1.00
Used Fire X Refurbished	1.00
Ford Triton Pvc Swc	1.00
2pc Hd Mat Set Blk	1.00
Napagold Air Filter	1.00
Switch - Rocker	1.00
Cabin Air Filter	1.00
245/70/17tire Coop	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 7.50

Comm: 0.00

Labor: 547.50	Parts: 626.00	Total: 1,173.50
---------------	---------------	-----------------

Work Order: 2009817 **Meter:** 25261 **In Date:** 09/29/2020 **Closed:** 09/30/2020
Problem: Right front headlamp out.

Work Completed

Parts Issued

Quantity

- Test and replace right headlight bulb .
- Shop Supplies

Blister Pack Capsules	1.00
Shop Supplies	1.00

Hours: 0.50

Comm: 0.00

Labor: 36.50	Parts: 17.86	Total: 54.36
--------------	--------------	--------------

12/18/2025
11:37:49 AM

Palm Beach County Fleet Management Asset Maintenance History
10203965 2017 FORD F150 Pickup, 1/2 Ton, Ext Cab

Work Order: 2010698 **Meter:** 25960 **In Date:** 10/26/2020 **Closed:** 10/28/2020
Problem: right headlight inop .

Work Completed

Parts Issued

Quantity

- Diagnose right headlight inop . Replace burnt connector and bulb . Retest .
- Shop Supplies

Socket	1.00
Blister Pack Capsules	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 32.67

Total: 105.67

Work Order: 2101710 **Meter:** 29581 **In Date:** 02/12/2021 **Closed:** 02/22/2021
Problem: P.M. service.

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- replace two front tires , balance and rotate All 4 . Nitro fill all.
- Check ,pin Point Npoise From Front Wheel Area,sop,r@r Defective L/f Wheel @ Hub Bearing Assembly,then Road Test To Verify Repair
- Shop Supplies

22" Wiper Blade	2.00
Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Mac Wite Lithium Gres	1.00
245/70/17 Tire Mich	2.00
Hub Assy Wheel	1.00
245/70/17tire Coop	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 5.50

Comm: 0.00

Labor: 401.50

Parts: 1,431.04

Total: 1,832.54

Work Order: 2104268 **Meter:** 29581 **In Date:** 02/18/2021 **Closed:** 04/15/2021
Problem: : Damage to front & rear bumper, right tail light, right rear fender & tail gate.

Work Completed

- : Damage to front & rear bumper, right tail light, right rear fender & tail gate.

Hours: 0.00

Comm: 3,834.66

Labor: 0.00

Parts: 0.00

Total: 3,834.66

12/18/2025
11:37:50 AM

Palm Beach County Fleet Management Asset Maintenance History
10203965 2017 FORD F150 Pickup, 1/2 Ton, Ext Cab

Work Order: 2104958 **Meter:** 29581 **In Date:** 05/03/2021 **Closed:** 05/25/2021
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 2109064 **Meter:** 32936 **In Date:** 08/20/2021 **Closed:** 08/30/2021
Problem: PM Service. will turn in today

Work Completed

- Preventive Maint. Service
- Rotated and balanced all 4 tires. Nitrogen filled all tires.
- Replaced cabin filter. Cleaned debris from fresh air intake.
- Transport to and from dealer for oil leaking from pan .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Steering Wheel Cover Large	1.00
2pc Hd Mat Set Blk	1.00
Cabin Filter	1.00
Shop Supplies	1.00

Hours: 5.50 Comm: 0.00 Labor: 401.50 Parts: 93.47 Total: 494.97

Work Order: 2111719 **Meter:** 34942 **In Date:** 10/29/2021 **Closed:** 11/01/2021
Problem: tire low on air fleet repaired now

Work Completed

- Repair right rear tire, balance & nitro service
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 2.65 Total: 75.65

Work Order: 2112655 **Meter:** 35555 **In Date:** 11/16/2021 **Closed:** 11/30/2021
Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 8.98 Labor: 0.00 Parts: 0.00 Total: 8.98

12/18/2025
11:37:50 AM

Palm Beach County Fleet Management Asset Maintenance History
10203965 2017 FORD F150 Pickup, 1/2 Ton, Ext Cab

Work Order: 2202056 **Meter:** 37699 **In Date:** 02/24/2022 **Closed:** 02/28/2022
Problem: PM Service. will turn in today

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service	Napagold Oil Filter	1.00
- check , replaced defective trailer plug . rewire as needed	Motor Oil	6.00
- installed two missing tool box lid struts or stay open	22" Wiper Blade	2.00
- balance and rotate all 4 tires . Nitro fill all.	Used Fire X Refurbished	1.00
- completed front end alignment due to steering wheel off center,then road trailer plug		1.00
test	Support	2.00
- Shop Supplies	Shop Supplies	1.00
Hours: 7.00	Comm: 0.00	Labor: 511.00 Parts: 112.16 Total: 623.16

Work Order: 2204662 **Meter:** 38731 **In Date:** 04/22/2022 **Closed:** 04/29/2022
Problem: Transport Accident vehicle to BODYSHOP

Work Completed

- Tow From: Fleet Wpb "rear fence area To: Anthony's Bodyshop (1420 Forsythe Rd, Wpb)

Hours: 0.00 Comm: 113.00 Labor: 0.00 Parts: 0.00 Total: 113.00

Work Order: 2205141 **Meter:** 38731 **In Date:** 04/11/2022 **Closed:** 05/12/2022
Problem: Damage to front bumper, left side of bed, left tail light, left rear tite & rim.

Work Completed

- Damage to front bumper, left side of bed, left tail light, left rear tite & rim.

Hours: 0.00 Comm: 4,683.75 Labor: 0.00 Parts: 0.00 Total: 4,683.75

12/18/2025
11:37:50 AM

Palm Beach County Fleet Management Asset Maintenance History
10203965 2017 FORD F150 Pickup, 1/2 Ton, Ext Cab

Work Order: 2210264 **Meter:** 43888 **In Date:** 10/05/2022 **Closed:** 10/14/2022
Problem: P.M. service and screw in right rear tire

Work Completed

- Preventive Maint. Service
- repair 1 tire ,rotate and balance all 4-tires nitro fill all
- Inspect and service rear differential .remove and replace diff fluid and inspect differential components
- perform injector and throttle body cleaning service and engine air intake decarb .
- Diagnose engine misfire . replace all 6 spark plugs after fuel injection cleaner
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Dif Oil	3.00
Intake Cleaner Kit	1.00
Spark Plug	6.00
Shop Supplies	1.00

Hours: 11.20

Comm: 0.00

Labor: 817.60

Parts: 186.68

Total: 1,004.28

Work Order: 2303530 **Meter:** 48686 **In Date:** 04/07/2023 **Closed:** 04/11/2023
Problem: Bridge Scotty PM

Work Completed

- Preventive Maint. Service
- R & I worn tire, Rotate and speed balance, nitro fill
- Replace cabin filter and clean fresh air intake
- R & I rear brakes, resurface both rotors, service caliper slide pins, bleed brakes, road test
- Perform complete alignment, road test
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	2.00
22" Wiper Blade	2.00
Napagold Air Filter	1.00
2 Pc Dickies Black	1.00
245/70/17 Tire Mich	2.00
Cabin Filter	1.00
Non-chlor Brake Clnr	1.00
Brake Pad	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 10.50

Comm: 0.00

Labor: 766.50

Parts: 545.00

Total: 1,311.50

12/18/2025
11:37:50 AM

Palm Beach County Fleet Management Asset Maintenance History
10203965 2017 FORD F150 Pickup, 1/2 Ton, Ext Cab

Work Order: 2309414 **Meter:** 54267 **In Date:** 09/15/2023 **Closed:** 09/19/2023
Problem: PM Service and detail

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service completed
- balance and rotate all 4 tires . Nitro fill all.
- check battery,charging system after fully charge it fail lad test,r&r defective battery ad reset bms
- Shop Supplies

Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Battry Motorcraft	1.00
Shop Supplies	1.00

Hours: 4.50

Comm: 0.00

Labor: 328.50

Parts: 216.19

Total: 544.69

Work Order: 2309504 **Meter:** 54267 **In Date:** 09/18/2023 **Closed:** 09/19/2023
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2309414 for: Ray Hiskell

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2309414 for: Ray Hiskell

Hours: 0.00

Comm: 90.40

Labor: 0.00

Parts: 0.00

Total: 90.40

Work Order: 2312411 **Meter:** 57209 **In Date:** 12/15/2023 **Closed:** 12/19/2023
Problem: Bridge Scott, low or bad battery check light will turn in today

Work Completed

Parts Issued

Quantity

- Replace key Fob battery.

Enr Elect Battery	1.00
-------------------	------

Hours: 0.20

Comm: 0.00

Labor: 14.60

Parts: 6.75

Total: 21.35

12/18/2025
11:37:50 AM

Palm Beach County Fleet Management Asset Maintenance History
10203965 2017 FORD F150 Pickup, 1/2 Ton, Ext Cab

Work Order: 2402645 **Meter:** 59179 **In Date:** 03/14/2024 **Closed:** 03/20/2024
Problem: PM Service front tire and right rear tire is leaking air

Work Completed

- Preventive Maint. Service
- Replaced 2 tires. Rotated and balanced all 4 tires. Nitrogen filled all tires.
- Diagnose Air bag light on. Code b1404. Pinpoint test and found to have chaffed wire in driver seat. Repaired wire and moved to keep from future chaffing. Cleared code and test drove.
- Replaced cabin filter. Cleaned debris from fresh air intake.
- Shop Supplies

Hours: 6.30

Comm: 0.00

Parts Issued

Quantity

Prest Syn Oil Stp Lk	1.00
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Steering Wheel Cover Large	1.00
Non-chlor Brake Clnr	2.00
245/70r17 Gy Wrkhrse Ht	2.00
Cabin Air Filter	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Labor: 459.90

Parts: 359.88

Total: 819.78

Work Order: 2403207 **Meter:** 59792 **In Date:** 03/29/2024 **Closed:** 04/02/2024
Problem: Bridge Scott, rt. head light out

Work Completed

- Remove right front inner wheel well to test and replace right low beam headlight bulb and melted connector . retest .
- Shop Supplies

Hours: 1.00

Comm: 0.00

Parts Issued

Quantity

Wire Assy	1.00
Blister Pack Capsules	1.00
Shop Supplies	1.00

Labor: 73.00

Parts: 29.63

Total: 102.63

12/18/2025
11:37:50 AM

Palm Beach County Fleet Management Asset Maintenance History
10203965 2017 FORD F150 Pickup, 1/2 Ton, Ext Cab

Work Order: 2408188 **Meter:** 65079 **In Date:** 08/23/2024 **Closed:** 08/27/2024
Problem: PM Service and need a replacement key Fob

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Diagnose Air bag light with scan tool, code B1404:13. Pinpoint test driver seat side airbag circuit and found jump wire broken to airbag. Removed seatback to replace jump wire. Retest and clear code. Verify repair complete.
- Customer states key fob broken. R&r broken key fob and reprogram. Verified repair complete.
- Rotate and balance four tires. Relearn tire sensors.
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Enr Elect Battery	1.00
Wire Asy	1.00
Key	1.00
Shop Supplies	1.00

Hours: 5.50

Comm: 0.00

Labor: 401.50

Parts: 228.14

Total: 629.64

Work Order: 2500525 **Meter:** 68948 **In Date:** 01/09/2025 **Closed:** 01/17/2025
Problem: 1 - Wash ticket(s) Issued to: Scotty Cothes

Work Completed

- 1 - Wash ticket(s) Issued to: Scotty Cothes

Hours: 0.00

Comm: 8.59

Labor: 0.00

Parts: 0.00

Total: 8.59

12/18/2025
11:37:50 AM

Palm Beach County Fleet Management Asset Maintenance History
10203965 2017 FORD F150 Pickup, 1/2 Ton, Ext Cab

Work Order: 2504032 **Meter:** 72495 **In Date:** 04/30/2025 **Closed:** 05/12/2025
Problem: PM Service. Send for Detail.

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- R&r faulty trailer socket and rewire wiring harness. Found horn disconnected and grill shutter blade detached. Reconnected horn connector and reattach grill shutter blade. Verify horn and grill shutter working at this time.
- Mount two tires, rotate and balance four. Nitro fill all .
- R&r both rear folding seat latch release handles broken.
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Steering Wheel Cover Large	1.00
Trailer Connector Truck Side	1.00
245/70r17xl Mich Def Ltx	2.00
Handle	1.00
Handle/adjstr	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 6.50 Comm: 0.00 Labor: 474.50 Parts: 616.55 Total: 1,091.05

Work Order: 2504468 **Meter:** 72495 **In Date:** 05/09/2025 **Closed:** 05/14/2025
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2504032 for: Mike Kenney

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2504032 for: Mike Kenney

Hours: 0.00 Comm: 91.80 Labor: 0.00 Parts: 0.00 Total: 91.80

Work Order: 2505992 **Meter:** 73368 **In Date:** 06/26/2025 **Closed:** 06/27/2025
Problem: Bridge Mario, rear driver side tire has a screw in it

Work Completed

Parts Issued

Quantity

- Repair left rear tire and balance . nitro fill all and reset Tpms
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 2.65 Total: 75.65

12/18/2025
11:37:50 AM

Palm Beach County Fleet Management Asset Maintenance History
10203965 2017 FORD F150 Pickup, 1/2 Ton, Ext Cab

Work Order: 2509282 **Meter:** 75128 **In Date:** 09/30/2025 **Closed:** 11/04/2025
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 101.25 Total Labor: 7,229.50 Total Comm: 16,320.49 Total Parts: 6,233.79