

12/18/2025
11:57:12 AM

Palm Beach County Fleet Management Asset Maintenance History
10198320 2015 FORD F350 Utility Body, 13,700 Gvwr

Total Hours: 151.50	Labor: 10,504.00	Parts: 9,653.89	Comm: 0.00	Charged: 20157.89
----------------------------	-------------------------	------------------------	-------------------	--------------------------

Work Order: 1509900	Meter: 338	In Date: 09/30/2015	Closed: 09/30/2015
Problem: 1061 - Pre Delivery Inspection			

Work Completed

- Pre Delivery Inspection
- Make & Apply Decals. Check Fluids, Belts and Operation

Hours: 4.00	Comm: 0.00	Labor: 240.00	Parts: 0.00	Total: 240.00
-------------	------------	---------------	-------------	---------------

Work Order: 1603260	Meter: 2739	In Date: 03/29/2016	Closed: 04/06/2016
Problem: Pm service. Rear end making noise.			

Work Completed

- Pm service.
- Rotate and balance tires.
- Add floor mats.
- Rear axle making noise. Drain and remove rear cover. Check for damage, none found. Reinstall cover and refill with new oil and friction modifier per Ford Tsb. Problem not corrected. Sent to Ford under warranty.
- Test drive 2x's.
- Shop Supplies

Parts Issued

Quantity

Floor Mat-2pc Rub Bk	1.00
Friction Modifier	2.00
5w20 Oil Bulk	8.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
1qt Syngear Oil 75-90	3.00
Shop Supplies	1.00

Hours: 9.00	Comm: 0.00	Labor: 540.00	Parts: 117.98	Total: 657.98
-------------	------------	---------------	---------------	---------------

Work Order: 1611568	Meter: 6114	In Date: 11/09/2016	Closed: 11/14/2016
Problem: Pm service.			

Work Completed

- Pm service.
- Replace missing hitch pin.
- Rotate and balance tires.
- Test drive.
- Shop Supplies

Parts Issued

Quantity

Pintle Pin W/clip	1.00
5w20 Oil Bulk	8.00
Napagold Oil Filter	1.00
Syn-atf Trans Fluid S	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Shop Supplies	1.00

Hours: 6.50	Comm: 0.00	Labor: 390.00	Parts: 38.09	Total: 428.09
-------------	------------	---------------	--------------	---------------

12/18/2025
11:57:12 AM

Palm Beach County Fleet Management Asset Maintenance History
10198320 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 1706116 **Meter:** 10813 **In Date:** 06/21/2017 **Closed:** 06/26/2017
Problem: Pm service.

Work Completed

- Pm service.
- Rotate and balance tires.
- Test drive.
- Shop Supplies

Parts Issued

Quantity

5w20 Oil Bulk	8.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Napagold Air Filter	1.00
Shop Supplies	1.00

Hours: 6.00

Comm: 0.00

Labor: 360.00	Parts: 40.64	Total: 400.64
---------------	--------------	---------------

Work Order: 1802301 **Meter:** 15703 **In Date:** 03/01/2018 **Closed:** 03/06/2018
Problem: Pm service.

Work Completed

- Pm service.
- Rotate and balance tires.
- Test drive.
- Shop Supplies

Parts Issued

Quantity

5w20 Oil Bulk	8.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Napagold Air Filter	1.00
Shop Supplies	1.00

Hours: 6.00

Comm: 0.00

Labor: 360.00	Parts: 40.49	Total: 400.49
---------------	--------------	---------------

12/18/2025
11:57:12 AM

Palm Beach County Fleet Management Asset Maintenance History
10198320 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 1809106 **Meter:** 18990 **In Date:** 09/05/2018 **Closed:** 09/07/2018
Problem: Pm service.

Work Completed

- Pm service.
- Battery failed load test. Replace battery.
- Replace worn tires. Nitro fill and balance.
- Test drive.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Oil Bulk	8.00
Napagold Air Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Battery	1.00
179636492 Lt245-75r17	6.00
Shop Supplies	1.00
Tire Disposal Fee	6.00

Hours: 8.00

Comm: 0.00

Labor: 480.00

Parts: 1,512.16

Total: 1,992.16

Work Order: 1903020 **Meter:** 23238 **In Date:** 03/19/2019 **Closed:** 03/21/2019
Problem: Pm service.

Work Completed

- Pm service.
- Replace shorted rear brake lights and marker light.
- Wash .
- Shop Supplies

Parts Issued

Quantity

5w20 Oil Bulk	8.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Lamp Kit	2.00
Led M C Grommet Kit	1.00
Grommet Mount Kit	1.00
Shop Supplies	1.00

Hours: 7.00

Comm: 0.00

Labor: 469.00

Parts: 216.26

Total: 685.26

12/18/2025
11:57:12 AM

Palm Beach County Fleet Management Asset Maintenance History
10198320 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 1909641 **Meter:** 27820 **In Date:** 09/19/2019 **Closed:** 10/01/2019
Problem: Pm service.

Work Completed

- Pm service.
- Test drive.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Oil Bulk	8.00
Napagold Air Filter	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 4.50

Comm: 0.00

Labor: 328.50

Parts: 63.43

Total: 391.93

Work Order: 1913131 **Meter:** 29596 **In Date:** 12/30/2019 **Closed:** 12/31/2019
Problem: Flat tire.

Work Completed

- Replace dmamaged Ds front tire.
- Shop Supplies

Parts Issued

Quantity

Lt245/75r17 Mich Defend Ltx	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 258.08

Total: 331.08

Work Order: 2001516 **Meter:** 30568 **In Date:** 02/12/2020 **Closed:** 02/19/2020
Problem: Flat tire.

Work Completed

- Repair Lf tire.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 4.00

Total: 77.00

12/18/2025
11:57:12 AM

Palm Beach County Fleet Management Asset Maintenance History
10198320 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 2002571 **Meter:** 30879 **In Date:** 03/12/2020 **Closed:** 03/17/2020
Problem: Pm service.

Work Completed

- Pm service.
- Replace worn Rf tire.
- Replace shorted body marker lights on utility body.
- Shop Supplies

Parts Issued

Quantity

5w20 Oil Bulk	8.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Lt245/75r17 Mich Defend Ltx	1.00
Grommet Mount Kit	2.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 5.50

Comm: 0.00

Labor: 401.50 Parts: 323.76 Total: 725.26

Work Order: 2005279 **Meter:** 33206 **In Date:** 05/27/2020 **Closed:** 06/03/2020
Problem: Engine missing.

Work Completed

- Engine had multiple misfire codes.p0300.replace all 16 sparkplugs. 8 coils and ignition wires. Clear codes.
- Test drive before and after repairs.
- Shop Supplies

Parts Issued

Quantity

Coil	4.00
Coil	4.00
Spark Plug	16.00
Espak Plug Wire	4.00
Espak Plug Wire	4.00
Shop Supplies	1.00

Hours: 5.00

Comm: 0.00

Labor: 365.00 Parts: 1,359.10 Total: 1,724.10

12/18/2025
11:57:12 AM

Palm Beach County Fleet Management Asset Maintenance History
10198320 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 2009504 **Meter:** 35296 **In Date:** 09/22/2020 **Closed:** 09/24/2020
Problem: Pm service.

Work Completed

- Pm service.
- Rotate and balance tires.
- Test drive.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Oil Bulk	8.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 5.50

Comm: 0.00

Labor: 401.50

Parts: 65.73

Total: 467.23

Work Order: 2102760 **Meter:** 38133 **In Date:** 03/11/2021 **Closed:** 03/17/2021
Problem: PM service due. Staff will transport to Pahokee Fleet this morning.

Work Completed

- Pm Service
- plug wires arcing replaced wires and plugs
- rotate and balance
- test drive
- Shop Supplies

Parts Issued

Quantity

5w20 Oil Bulk	8.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napagold Air Filter	1.00
Espak Plug Wire	4.00
Espak Plug Wire	4.00
Spark Plug	16.00
Shop Supplies	1.00

Hours: 9.50

Comm: 0.00

Labor: 693.50

Parts: 277.42

Total: 970.92

12/18/2025
11:57:12 AM

Palm Beach County Fleet Management Asset Maintenance History
10198320 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 2112108 **Meter:** 41850 **In Date:** 11/10/2021 **Closed:** 11/18/2021
Problem: PM Service.

Work Completed

- Preventive Maintenance Service
- Test drive
- Remove all corroded and rotted body mounts. Install new body mounts.
- Rotate and balance all 6 tires
- Shop Supplies

Parts Issued

Quantity

5w20 Oil Bulk	8.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Body Mount Kit	4.00
Body Mount Kit	2.00
Shop Supplies	1.00

Hours: 10.00

Comm: 0.00

Labor: 730.00

Parts: 501.67

Total: 1,231.67

Work Order: 2206257 **Meter:** 44353 **In Date:** 06/14/2022 **Closed:** 06/21/2022
Problem: PM Service.

Work Completed

- Preventive Maintenance Service
- Test Drive
- Mount and balance all six tires.
- Shop Supplies

Parts Issued

Quantity

Used Fire X Refurbished	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
5w20 Oil Bulk	8.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Lt245/75r17 Mich Defend Ltx	6.00
Shop Supplies	1.00
Tire Disposal Fee	6.00

Hours: 6.50

Comm: 0.00

Labor: 474.50

Parts: 1,565.97

Total: 2,040.47

12/18/2025
11:57:12 AM

Palm Beach County Fleet Management Asset Maintenance History
10198320 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 2207106 **Meter:** 44538 **In Date:** 07/07/2022 **Closed:** 07/11/2022
Problem: Battery dies. Staff will deliver to Pahokee Fleet this afternoon.

Work Completed

- Battery failed load test replaced battery
- Shop Supplies

Hours: 1.00

Comm: 0.00

Parts Issued

Battery	1.00
Shop Supplies	1.00

Labor: 73.00 Parts: 119.98 Total: 192.98

Work Order: 2300613 **Meter:** 46930 **In Date:** 01/23/2023 **Closed:** 01/26/2023
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- rotate and balance
- test drive
- Shop Supplies

Hours: 5.50

Comm: 0.00

Parts Issued

Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napagold Oil Filter	1.00
5w20 Oil Bulk	8.00
Shop Supplies	1.00

Labor: 401.50 Parts: 41.23 Total: 442.73

Work Order: 2303544 **Meter:** 48258 **In Date:** 04/10/2023 **Closed:** 04/27/2023
Problem: Check engine light is on

Work Completed

- check engine light on and over temp light found wiring harness chewed by rats under intake manifold removed intakemanifold and replaced upper engine harness and temp/knock sensor jumper harness reinstalled intake and cleared codes
- abs light on checked sensor and wiring took for test drive found If speed sensor inop replaced sensor
- test drive to check all symptoms were eliminated
- Shop Supplies

Hours: 12.00

Comm: 0.00

Parts Issued

Engine Harness	1.00
Wire Assy	1.00
Abs Sensor	1.00
Shop Supplies	1.00

Labor: 876.00 Parts: 246.96 Total: 1,122.96

12/18/2025
11:57:12 AM

Palm Beach County Fleet Management Asset Maintenance History
10198320 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 2308326 **Meter:** 50129 **In Date:** 08/21/2023 **Closed:** 09/19/2023
Problem: PM Service

Work Completed

- Preventive Maintenance Service
- Test Drive
- Rotate and balance tires
- Replaced worn from brake pads, rotors, calipers, slide pins and wheel bearings. Flush contaminated brake fluid from system.
- Replaced shorted rear tail/stop light
- Brake lights stay on all the time. Follow pin point test. Replaced shorted Bcm, reprogram new Bcm.
- Front wheel bearing spindles damaged. Installed new steering knuckles on both sides.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Oil Bulk	8.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
Led Sup Mdl 44 42 Dio	2.00
Brk Caliper Kit	2.00
Brk Fluid Dot 4-32oz	2.00
Seal	2.00
Cap	2.00
Non-chlor Brake Clnr	2.00
Brake Caliper	1.00
Brake Caliper	1.00
Front Brake Pad Duty	1.00
Bearing	2.00
Cone	2.00
Hub/rotor Asm	2.00
Module Bcm	1.00
Spindle	1.00
Spindle	1.00
Shop Supplies	1.00

Hours: 18.00

Comm: 0.00

Labor: 1,314.00

Parts: 2,397.76

Total: 3,711.76

12/18/2025
11:57:12 AM

Palm Beach County Fleet Management Asset Maintenance History
10198320 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 2404225 **Meter:** 53639 **In Date:** 04/29/2024 **Closed:** 05/22/2024
Problem: PM

Work Completed

- Pm service
- Test Dive
- Rotate and balance all six tires
- Truck slow to start. Charge and load test battery it failed. Installed new battery and checked charging system
- Back camera does not functions. Pinpoint test wiring and found came shorted. Replacement camera Nla. Removed old camera wiring, camera, and rear view mirror. Installed new rearview mirror, camera wiring and camera.
- Shop Supplies

Hours: 11.00

Comm: 0.00

Parts Issued

Quantity

Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	2.00
5w20 Oil Bulk	8.00
Napagold Oil Filter	1.00
Battery	1.00
Backup Cam Kit w/mirror	1.00
Shop Supplies	1.00

Labor: 803.00

Parts: 388.45

Total: 1,191.45

Work Order: 2500182 **Meter:** 57873 **In Date:** 01/08/2025 **Closed:** 02/03/2025
Problem: PM Service

Work Completed

- Preventive Maint. Service
- Test Drive
- Rotate and balance six tires.
- Replaced missing/damage reflective tape. 2 yellow and 4 red.
- Shop Supplies

Hours: 7.00

Comm: 0.00

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Oil Bulk	8.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
Non-chlor Brake Clnr	1.00
Tape	4.00
Tape	2.00
Shop Supplies	1.00

Labor: 511.00

Parts: 74.76

Total: 585.76

12/18/2025
11:57:12 AM

Palm Beach County Fleet Management Asset Maintenance History
10198320 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 2510481 **Meter:** 62532 **In Date:** 11/05/2025 **Closed:** 11/06/2025
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge
Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 151.50 Total Labor: 10,504.00 Total Comm: 0.00 Total Parts: 9,653.89