

12/18/2025
12:03:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10196035 2015 FORD F550 Utility Body, 18,000 Gvwr, with Topper

Total Hours: 287.30	Labor: 20,247.90	Parts: 22,335.12	Comm: 20,242.69	Charged: 62825.71
----------------------------	-------------------------	-------------------------	------------------------	--------------------------

Work Order: 1502187	Meter: 311	In Date: 03/02/2015	Closed: 03/02/2015
Problem: 1061 - Pre Delivery Inspection			

Work Completed

- Pre Delivery Inspection

Hours: 4.00	Comm: 0.00	Labor: 240.00	Parts: 0.00	Total: 240.00
-------------	------------	---------------	-------------	---------------

Work Order: 1508095	Meter: 2265	In Date: 08/12/2015	Closed: 08/19/2015
Problem: PM			

Work Completed

- pm
- add def
- test run
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	13.00
Napagold Oil Filter	1.00
Fuel Filter Kit	1.00
Air Filter (gold), Air Panel	1.00
Used Fire X Refurbished	1.00
Wiper Blade	2.00
Washer Fluid Concentr	1.00
Wd40 16oz	1.00
Def Quart	12.00
Shop Supplies	1.00

Hours: 5.00	Comm: 0.00	Labor: 300.00	Parts: 221.32	Total: 521.32
-------------	------------	---------------	---------------	---------------

12/18/2025
12:03:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10196035 2015 FORD F550 Utility Body, 18,000 Gvwr, with Topper

Work Order: 1602254 **Meter:** 5967 **In Date:** 03/03/2016 **Closed:** 03/18/2016
Problem: PM

Work Completed

- pm
- add def
- road test
- Shop Supplies

Parts Issued

Quantity

Brake Cleaner	3.00
Napagold Oil Filter	1.00
Fuel Filter Kit	1.00
Air Filter (gold), Air Panel	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Def Quart	17.00
15-40 Oil	15.00
Shop Supplies	1.00

Hours: 5.00

Comm: 0.00

Labor: 300.00 Parts: 214.07 Total: 514.07

Work Order: 1609079 **Meter:** 8135 **In Date:** 08/31/2016 **Closed:** 09/12/2016
Problem: PM / CK eng light

Work Completed

- pm
- scan codes. P2002
- Tsb 15-0152 perform Pcm recalibration
- add Def
- repair loose connection on fan for cargo roof
- road test
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	15.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Air Filter (gold), Air Panel	1.00
22" Wiper Blade	2.00
Non-chlor Brake Clnr	2.00
Used Fire X Refurbished	1.00
Def Quart	9.00
Shop Supplies	1.00

Hours: 8.00

Comm: 0.00

Labor: 480.00 Parts: 159.35 Total: 639.35

12/18/2025
12:03:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10196035 2015 FORD F550 Utility Body, 18,000 Gvwr, with Topper

Work Order: 1702121 **Meter:** 12330 **In Date:** 03/01/2017 **Closed:** 03/27/2017
Problem: PM

Work Completed

Parts Issued

Quantity

- pm	15-40 Oil	15.00
- road test	Napagold Oil Filter	1.00
- add Def	Napagold Fuel Filter	1.00
- Shop Supplies	Air Filter (gold), Air Panel	1.00
	Wiper Blade	2.00
	Def Bulk Qts	16.00
	Shop Supplies	1.00
Hours: 5.00	Comm: 0.00	Labor: 300.00 Parts: 151.64 Total: 451.64

Work Order: 1702720 **Meter:** 12203 **In Date:** 03/17/2017 **Closed:** 03/20/2017
Problem: Front tires

Work Completed

- front tires		
Hours: 0.00	Comm: 724.36	Labor: 0.00 Parts: 0.00 Total: 724.36

Work Order: 1708557 **Meter:** 16403 **In Date:** 08/30/2017 **Closed:** 09/26/2017
Problem: pm

Work Completed

Parts Issued

Quantity

- pm	15-40 Oil	15.00
- check engine light. code p2002	Napagold Oil Filter	1.00
- def	Napagold Fuel Filter	1.00
- R&r 2 leaking batteries	Air Filter (gold), Air Panel	1.00
- to ford 2xs	Wiper Blade	2.00
- Shop Supplies	Used Fire X Refurbished	1.00
	Hw Pigmat 15x20 100ct	1.00
	Blue Df	1.00
	Battery 65	2.00
	Shop Supplies	1.00
Hours: 11.50	Comm: 0.00	Labor: 690.00 Parts: 623.50 Total: 1,313.50

12/18/2025
12:03:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10196035 2015 FORD F550 Utility Body, 18,000 Gvwr, with Topper

Work Order: 1712539 **Meter:** 17633 **In Date:** 12/20/2017 **Closed:** 01/03/2018
Problem: DEF

Work Completed

- Def
- Shop Supplies

Hours: 0.50

Comm: 0.00

Parts Issued

Quantity

Blue Df	2.00
Shop Supplies	1.00
Labor: 30.00	Parts: 29.12
Total: 59.12	

Work Order: 1803223 **Meter:** 19125 **In Date:** 03/28/2018 **Closed:** 04/17/2018
Problem: PM

Work Completed

- Pm
- Def
- Road test
- Shop Supplies

Hours: 5.00

Comm: 0.00

Parts Issued

Quantity

15-40 Oil	15.00
Non-chlor Brake Clnr	1.00
Gen Trim Adhv Clear	1.00
Stp	2.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Air Filter (gold), Air Panel	1.00
Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Blue Df	1.00
Shop Supplies	1.00
Labor: 300.00	Parts: 193.81
Total: 493.81	

12/18/2025
12:03:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10196035 2015 FORD F550 Utility Body, 18,000 Gvwr, with Topper

Work Order: 1810426 **Meter:** 23270 **In Date:** 10/10/2018 **Closed:** 10/30/2018
Problem: PM

Work Completed

- pm
- repair marker lights
- def
- test run
- Shop Supplies

Parts Issued

Quantity

Wiper Blade	2.00
Washer Fluid Concentr	1.00
15-40 Oil	15.00
Napagold Fuel Filter	1.00
Air Filter (gold), Air Panel	1.00
Napagold Oil Filter	1.00
Grommet Mount Kit	1.00
Blue Df	2.00
Shop Supplies	1.00

Hours: 8.00

Comm: 0.00

Labor: 536.00

Parts: 172.49

Total: 708.49

12/18/2025
12:03:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10196035 2015 FORD F550 Utility Body, 18,000 Gvwr, with Topper

Work Order: 1904443 **Meter:** 27230 **In Date:** 04/24/2019 **Closed:** 05/15/2019
Problem: pm a/c strobes

Work Completed

Parts Issued

Quantity

- pm
- check engine light on. pull codes. pull def tank and replace pump/heater assembly. clear codes and reset tank level
- R&r side markers and rewire
- top off def tank
- R&r batteries leaking and failed load test. clean terminals
- strobe light replace
- check Ac. test system. recharge
- test run
- clean engine bay
- Shop Supplies

15-40 Oil	15.00
Napagold Oil Filter	1.00
Air Filter (gold), Air Panel	1.00
Napagold Fuel Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Seal Spe	1.00
Reservoir	1.00
Fuel Cap Diesel	1.00
Lamp-grommet Kit	1.00
Lamp Kit	1.00
Blue Df	2.00
Battery 65	2.00
Mnt Conc Led Clear	1.00
Shop Supplies	1.00

Hours: 17.50

Comm: 0.00

Labor: 1,172.50

Parts: 1,074.98

Total: 2,247.48

Work Order: 1905129 **Meter:** 27190 **In Date:** 05/10/2019 **Closed:** 05/10/2019
Problem: RRO

Work Completed

- Tire Service He - Rro

Hours: 0.00

Comm: 347.30

Labor: 0.00

Parts: 0.00

Total: 347.30

Work Order: 1908387 **Meter:** 30207 **In Date:** 08/13/2019 **Closed:** 08/15/2019
Problem: 2 Fire exstingushers

Work Completed

Parts Issued

Quantity

- Fire Exstingushers

Used Fire X Refurbished	2.00
-------------------------	------

Hours: 0.00

Comm: 0.00

Labor: 0.00

Parts: 29.37

Total: 29.37

12/18/2025
12:03:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10196035 2015 FORD F550 Utility Body, 18,000 Gvwr, with Topper

Work Order: 1908972 **Meter:** 30711 **In Date:** 08/22/2019 **Closed:** 08/27/2019
Problem: Front Tires

Work Completed

- Tire Service He - Front Tires

Hours: 0.00 Comm: 51.56 Labor: 0.00 Parts: 0.00 Total: 51.56

Work Order: 1908975 **Meter:** 30711 **In Date:** 08/27/2019 **Closed:** 08/27/2019
Problem: Front tires

Work Completed

- Tire Service He - Front tires

Hours: 0.00 Comm: 646.85 Labor: 0.00 Parts: 0.00 Total: 646.85

Work Order: 1909069 **Meter:** 30711 **In Date:** 08/29/2019 **Closed:** 08/29/2019
Problem: LF tire

Work Completed

- Tire Service He - Lf tire

Hours: 0.00 Comm: 327.02 Labor: 0.00 Parts: 0.00 Total: 327.02

Work Order: 1911201 **Meter:** 33283 **In Date:** 10/29/2019 **Closed:** 12/04/2019
Problem: PM

Work Completed

- pm
- def
- R&r pintle chain
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	15.00
Napagold Fuel Filter	1.00
Air Filter (gold), Air Panel	1.00
Napagold Oil Filter	1.00
Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Blue Df	1.00
Pintle Pin W/clip	1.00
Shop Supplies	1.00

Hours: 6.00 Comm: 0.00 Labor: 438.00 Parts: 174.07 Total: 612.07

12/18/2025
12:03:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10196035 2015 FORD F550 Utility Body, 18,000 Gvwr, with Topper

Work Order: 1912402 **Meter:** 33285 **In Date:** 11/25/2019 **Closed:** 12/03/2019
Problem: rears 4

Work Completed

- Tire Service vista - rears 4

Hours: 0.00 Comm: 265.16 Labor: 0.00 Parts: 0.00 Total: 265.16

Work Order: 1912451 **Meter:** 33285 **In Date:** 12/04/2019 **Closed:** 12/06/2019
Problem: Tires

Work Completed

- Tires

- Shop Supplies

Parts Issued

Quantity

Invgs140182 1.00

Shop Supplies 1.00

Tire Disposal Fee 1.00

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 1,520.31 Total: 1,520.31

Work Order: 1912716 **Meter:** 33649 **In Date:** 12/12/2019 **Closed:** 12/17/2019
Problem: Wipers

Work Completed

- Wiper blades

Parts Issued

Quantity

Wiper Blade 2.00

Hours: 0.50 Comm: 0.00 Labor: 36.50 Parts: 9.90 Total: 46.40

12/18/2025
12:03:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10196035 2015 FORD F550 Utility Body, 18,000 Gvwr, with Topper

Work Order: 2005366 **Meter:** 37407 **In Date:** 05/28/2020 **Closed:** 06/15/2020
Problem: pm/lights and tires

Work Completed

- pm
- def
- R&r tail lights
- replace batteries
- test run
- R&r roof fan
- manual regen
- scan codes P2002
- Shop Supplies

Parts Issued

Quantity

Napagold Fuel Filter	1.00
Air Filter (gold), Air Panel	1.00
Fuel Filter	1.00
15-40 Oil	14.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Px Grey Rtv Silicone	1.00
Pm-22-a Additive Dies	1.00
Non-chlor Brake Clnr	4.00
Blue Df	2.00
Led S44 42 Diod S T T	2.00
Battery 65	2.00
Roof Vent Fan	1.00
1k Seam Sealer-white	1.00
Shop Supplies	1.00

Hours: 18.00

Comm: 0.00

Labor: 1,314.00

Parts: 1,065.24

Total: 2,379.24

12/18/2025
12:03:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10196035 2015 FORD F550 Utility Body, 18,000 Gvwr, with Topper

Work Order: 2012267 **Meter:** 42435 **In Date:** 12/09/2020 **Closed:** 12/23/2020
Problem: Do for PM check up.

Work Completed

- Preventive Maint. Service
- def service
- Road Test
- replaced rear vice
- topped off coolant tanks
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	15.00
Wiper Blade	2.00
Washer Fluid Concentr	2.00
Px Grey Rtv Silicone	1.00
Pm-22-a Additive Dies	1.00
Non-chlor Brake Clnr	2.00
Napagold Fuel Filter	1.00
Air Filter (gold), Air Panel	1.00
Napagold Oil Filter	1.00
ridgid vise handle	1.00
Shop Supplies	1.00

Hours: 7.50

Comm: 0.00

Labor: 547.50

Parts: 250.89

Total: 798.39

Work Order: 2100653 **Meter:** 43555 **In Date:** 01/20/2021 **Closed:** 01/21/2021
Problem: Need to replace front headlight bulbs will drive down. Thank you

Work Completed

- C/c both headlights out removed grill assembly to access headlight retaining bolts. removed headlight assemblies and checked for power at connector. replaced bulbs and tested before assembly. reinstalled headlights and grill assembly.
- Shop Supplies

Parts Issued

Quantity

Boxed Capsules	2.00
Shop Supplies	1.00

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 29.92

Total: 175.92

Work Order: 2106795 **Meter:** 47068 **In Date:** 06/22/2021 **Closed:** 08/12/2021
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Cab mounts rotted out. Torch out seized cab mounts. Replace mounts
- Add Def
- Battery terminals corroded. Clean terminals and deacidify.

Parts Issued

Quantity

Oil Plug	1.00
Napagold Oil Filter	1.00
15-40 Oil	15.00
Napagold Fuel Filter	1.00

12/18/2025
12:03:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10196035 2015 FORD F550 Utility Body, 18,000 Gvwr, with Topper

- Front end sloppy. Replace drag link, track bar, outer rod ends.
- Ball joints have excessive free play. R&r ball joints
- Left rear taillight out. R&r taillight
- Front brake pads worn and caliper seized. R&r front calipers, rotors, and pads. Bleed brake system
- To Weber for alignment
- Rear walk in door will not latch properly. Latch damaged. Remove latch assy. Repair latch and reinstall.
- Replace Lf Rf Rro Lro tires
- Roof vent broken. Replace roof vent assy.
- Test Run
- Alignment
- Shop Supplies

Parts Issued	Quantity
Air Filter (gold), Air Panel	1.00
Wiper Blade	2.00
Washer Fluid Concentr	2.00
New Pig	1.00
Non-chlor Brake Clnr	3.00
Pm-22-a Additive Dies	1.00
Used Fire X Refurbished	1.00
Body Mount Kit	4.00
Body Mount Kit	2.00
Blue Df	2.00
Nozzle	1.00
caulk gun	1.00
Marine Adh Seal Blk	2.00
Roof Vent Fan	1.00
Alignment / Parts	1.00
Damper	1.00
Tie Rod Sleeve	1.00
front bar	1.00
Tie Rod	1.00
Tie Rod	1.00
Rod	1.00
End Asy	1.00
Rod Asy	1.00
Link Asy	2.00
ball joint	2.00
Ball Joint	2.00
Ball Joint	1.00
Grommet Mount Kit	1.00
Front Brake Rotor	2.00
Brake Pads	1.00

12/18/2025
12:03:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10196035 2015 FORD F550 Utility Body, 18,000 Gvwr, with Topper

		Parts Issued		Quantity	
		B Fluid Dot 3-32oz		3.00	
		sleeve		1.00	
		Shop Supplies		1.00	
Hours: 48.50		Comm: 0.00		Labor: 3,540.50	Parts: 3,863.98 Total: 7,404.48
Work Order: 2107736		Meter: 47068		In Date: 07/13/2021	Closed: 07/15/2021
Problem: Front tires 2 rear					
Work Completed					
- Tire Service: He Problem: Front tires 2 rear					
Hours: 0.00		Comm: 249.70		Labor: 0.00	Parts: 0.00 Total: 249.70
Work Order: 2107737		Meter: 47068		In Date: 07/15/2021	Closed: 07/15/2021
Problem: 4 Tires					
Work Completed					
- Tire Service: He Problem: 4 Tires					
Hours: 0.00		Comm: 1,017.09		Labor: 0.00	Parts: 0.00 Total: 1,017.09
Work Order: 2108898		Meter: 47821		In Date: 08/17/2021	Closed: 08/26/2021
Problem: Turbo Boost hose broke loose under the hood, also a wiring harness pull apart underneath driver side .Please Check					
Work Completed		Parts Issued		Quantity	
- Air Intake System		Tube - Outlet		1.00	
- add def		Blue Df		2.00	
- Shop Supplies		Shop Supplies		1.00	
Hours: 2.50		Comm: 0.00		Labor: 182.50	Parts: 97.15 Total: 279.65

12/18/2025
12:03:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10196035 2015 FORD F550 Utility Body, 18,000 Gvwr, with Topper

Work Order: 2200330 **Meter:** 49993 **In Date:** 01/11/2022 **Closed:** 02/08/2022
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- add def
- test drive
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	15.00
15-40 Oil	15.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Air Filter	1.00
Used Fire X Refurbished	1.00
Non-chlor Brake Clnr	3.00
Wiper Blade	2.00
Washer Fluid Concentr	2.00
Blue Df	2.00
Shop Supplies	1.00

Hours: 5.50

Comm: 0.00

Labor: 401.50

Parts: 215.31

Total: 616.81

Work Order: 2201804 **Meter:** 50114 **In Date:** 02/17/2022 **Closed:** 02/24/2022
Problem: No Start

Work Completed

- No Start, Fail load test, Battery replacement, clean terminals
- To Traffic parking lot
- Shop Supplies

Parts Issued

Quantity

Battery	2.00
Shop Supplies	1.00

Hours: 2.50

Comm: 0.00

Labor: 182.50

Parts: 287.24

Total: 469.74

Work Order: 2201900 **Meter:** 50203 **In Date:** 02/04/2022 **Closed:** 02/18/2022
Problem: Front tires

Work Completed

- Tire Service: He Problem: Front tires

Hours: 0.00

Comm: 612.46

Labor: 0.00

Parts: 0.00

Total: 612.46

12/18/2025
12:03:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10196035 2015 FORD F550 Utility Body, 18,000 Gvwr, with Topper

Work Order: 2201905 **Meter:** 50203 **In Date:** 02/18/2022 **Closed:** 02/18/2022
Problem: RF LF

Work Completed

- Tire Service: He Problem: Rf Lf

Hours: 0.00 Comm: 266.57 Labor: 0.00 Parts: 0.00 Total: 266.57

Work Order: 2201908 **Meter:** 50203 **In Date:** 02/22/2022 **Closed:**
Problem: Needs battery's want start truck is in the back gate was recently PM. Please check Thank you

Work Completed

- Battery

Parts Issued

Quantity

Battery 2.00

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 274.24 Total: 274.24

Work Order: 2203319 **Meter:** 51046 **In Date:** 03/28/2022 **Closed:** 03/30/2022
Problem: leaking some fuel underneath the engine smells like diesel drips heavy please check and repair. Thank you

Work Completed

- Operator states fuel leaking. Found cracked fuel filter assy. R&r fuel filter.
- Unit covered in fuel. Wash unit
- Test Run
- Shop Supplies

Parts Issued

Quantity

Napagold Fuel Filter 1.00

Shop Supplies 1.00

Hours: 3.00 Comm: 0.00 Labor: 219.00 Parts: 39.56 Total: 258.56

Work Order: 2205939 **Meter:** 53224 **In Date:** 06/06/2022 **Closed:** 06/07/2022
Problem: Need a new fire extinguisher to replace the one that was use from this truck it was a 5lbs. Will come down to pick up

Work Completed

- replace fire exstingusher
- Shop Supplies

Parts Issued

Quantity

Used Fire X Refurbished 1.00

Shop Supplies 1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 15.01 Total: 88.01

12/18/2025
12:03:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10196035 2015 FORD F550 Utility Body, 18,000 Gvwr, with Topper

Work Order: 2210180 **Meter:** 56703 **In Date:** 10/04/2022 **Closed:** 12/12/2022
Problem: PM Service.

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Add Def
- A/c Service
- Rear Brake Lights, only few bulbs working on both sides
- Rear Marker Lights on bar functioning but dim
- Dpf Filter at %75, do a manual regen x2 and recheck percentage, now at %0
- Top off primary and secondary coolant tanks
- Top off power steering resivor
- Shop Supplies

15-40 Oil	15.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Washer Fluid Concentr	2.00
Wiper Blade	2.00
Non-chlor Brake Clnr	4.00
Used Fire X Refurbished	1.00
Blue Df	2.00
Air Filter (gold), Air Panel	1.00
Led Sup Mdl 44 42 Dio	2.00
Led M C Lamp	2.00
Distilled Water 1gal	1.00
oil auto	1.00
Wd40 Spr	1.00
Pintle Pin W/clip	1.00
Stick-on Rd Reflector	2.00
Shop Supplies	1.00

Hours: 11.50

Comm: 0.00

Labor: 839.50

Parts: 364.23

Total: 1,203.73

Work Order: 2302249 **Meter:** 58433 **In Date:** 03/06/2023 **Closed:** 03/07/2023
Problem: Right front head light needs a new blub will drive truck down for repair. Thank you

Work Completed

Parts Issued

Quantity

- Lighting, Other remove front grill to gain acces to headlights assemblies to replace both headlight bulbs
- Shop Supplies

Hdl/swit	1.00
Boxed Capsules	2.00
Shop Supplies	1.00

Hours: 2.50

Comm: 0.00

Labor: 182.50

Parts: 31.70

Total: 214.20

12/18/2025
12:03:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10196035 2015 FORD F550 Utility Body, 18,000 Gvwr, with Topper

Work Order: 2303662 **Meter:** 59420 **In Date:** 04/12/2023 **Closed:** 04/14/2023
Problem: Please check battery has to jump to start. Thank you

Work Completed

Parts Issued

Quantity

- operator states unit will not start. Load test batteries. Batteries failed load test. R&r batteries

Battery 2.00

Hdl/swit 1.00

- Driver headlight inop. Pigtail melted. R&r driver headlight bulb and pigtail

Boxed Capsules 1.00

- Shop Supplies

Shop Supplies 1.00

Hours: 3.50

Comm: 0.00

Labor: 255.50

Parts: 353.15

Total: 608.65

Work Order: 2305450 **Meter:** 60871 **In Date:** 06/02/2023 **Closed:** 06/07/2023
Problem: driver states fuel issues cant drive/ PM

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service

15-40 Oil 15.00

- Add Def

F75z6730ba Drain Plug 1.00

- Flush evaporator core do to excessive amount of dust in cab.

Wd40 Spr 1.00

- Under body Fuel leak, defective filters housings fine line hair cracks leaking fuel on engine bay going under body. Rr units

New Pig 1.00

Non-chlor Brake Clnr 4.00

- Test drives

Napagold Oil Filter 1.00

- Wash fuel under body of truck and engine bay.

Used Fire X Refurbished 1.00

- Shop Supplies

Fuel Filter Kit 1.00

Washer Fluid Concentr 2.00

Wiper Blade 2.00

Blue Df 2.00

Air Filter (gold), Air Panel 1.00

Motor Tune-up 16oz 2.00

Shop Supplies 1.00

Hours: 14.00

Comm: 0.00

Labor: 1,022.00

Parts: 370.49

Total: 1,392.49

12/18/2025
12:03:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10196035 2015 FORD F550 Utility Body, 18,000 Gvwr, with Topper

Work Order: 2305729 **Meter:** 60871 **In Date:** 06/02/2023 **Closed:** 06/08/2023
Problem: Tires: RFAI;LFAO;LFAI;RFAO; Wear. Replace Tire

Work Completed

- Tire Service: he Problem: Tires: Rfai;lfao;lfai;rfao; Wear. Replace Tire

Hours: 0.00 Comm: 1,582.59 Labor: 0.00 Parts: 0.00 Total: 1,582.59

Work Order: 2305813 **Meter:** 60871 **In Date:** 06/01/2023 **Closed:** 06/12/2023
Problem: driver states fuel issues cant drive

Work Completed

- Tow From: 441 Just N lantana rd, Sb To: vista center

Hours: 0.00 Comm: 226.00 Labor: 0.00 Parts: 0.00 Total: 226.00

Work Order: 2309520 **Meter:** 63766 **In Date:** 09/19/2023 **Closed:** 09/19/2023
Problem: 1 - Key(s) Issued

Work Completed

- 1 - Key(s) Issued

Hours: 0.30 Comm: 0.00 Labor: 21.90 Parts: 3.00 Total: 24.90

Parts Issued

Quantity

Duplicate Vehicle Keys 1.00

12/18/2025
12:03:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10196035 2015 FORD F550 Utility Body, 18,000 Gvwr, with Topper

Work Order: 2400728

Meter: 67029

In Date: 01/23/2024 **Closed:** 03/25/2024

Problem: PM Service

Work Completed

- Preventive Maint. Service
- Rr rear brakes seals and calipers .
- Rr 2 front wheels
- Add additive to fuel do to water trace in filter housing.
- Swap out to led headlights.
- Rr both taillights units led elements burned out .
- replace pintle pin
- Add Def
- Test runs X 2
- Brake fluid flush.
- Shop Supplies

Parts Issued

Quantity

Non-chlor Brake Clnr	4.00
New Pig	1.00
Hand Wipes	1.00
Washer Fluid Concentr	2.00
Wiper Blade	2.00
Napagold Oil Filter	1.00
Air Filter (gold), Air Panel	1.00
Fuel Filter	1.00
F75z6730ba Drain Plug	1.00
F81z1001ba Seal Ring	2.00
Brake Fl-dot 3-4 32oz	2.00
Lucas 85-140 Gear Oil	3.00
225/70r19.5 Mounted Gy Endurance	2.00
Hotshot	1.00
H13/9008 Led Light	1.00
Led Sup Mdl 44 42 Dio	2.00
Pintle Pin W/clip	1.00
Delvac 15w40 1 Ga	4.00
Used Fire X Refurbished	1.00
Oil Seal	2.00
Brake Rotor	2.00
Rear Brake Caliper	1.00
Front Brake Caliper	1.00
Brake Pads	1.00
Blue Df	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 17.00

Comm: 0.00

Labor: 1,241.00

Parts: 2,225.09

Total: 3,466.09

12/18/2025
12:03:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10196035 2015 FORD F550 Utility Body, 18,000 Gvwr, with Topper

Work Order: 2409560 **Meter:** 71773 **In Date:** 10/02/2024 **Closed:** 10/31/2024
Problem: PM Service, Drivers side seat belt broken need new wiper blades washer fluid container leaks, DEF fluid gauge is

Work Completed

- Preventive Maint. Service
- Add Def
- Replace Def sending unit with doser. Recalibrate Scr system.
- Replace driver seat assembly.
- Replace washer fluid tank and pump
- Service Ccv Filter.
- Replace trailer plug recptacle.
- Replace led markers.
- Test run.
- Shop Supplies

Parts Issued

Quantity

Wash Pump	1.00
Wiper Blade	2.00
Washer Fluid Concentr	2.00
Stiction Elimint 32oz	1.00
15-40 Oil	15.00
Non-chlor Brake Clnr	4.00
F75z6730ba Drain Plug	1.00
Used Fire X Refurbished	1.00
Napagold Oil Filter	1.00
Air Filter (gold), Air Panel	1.00
Blue Df	2.00
Reservoir	1.00
Injector	1.00
Def Injector	1.00
Tray Asy	1.00
oil separator	1.00
Trailer Connector Truck Side	1.00
Grommet Mount Kit	2.00
Shop Supplies	1.00

Hours: 17.50

Comm: 0.00

Labor: 1,277.50 Parts: 1,333.64 Total: 2,611.14

12/18/2025
12:03:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10196035 2015 FORD F550 Utility Body, 18,000 Gvwr, with Topper

Work Order: 2502815 **Meter:** 73444 **In Date:** 03/25/2025 **Closed:** 03/25/2025
Problem: marker lights inop

Work Completed

Parts Issued

Quantity

- diagnose marker lights inop. found open circuit in supply. remount tripple marker light bar in rear.

Shop Supplies

1.00

- Recall: 21e01 Customer Satisfaction Programs 21n02, 21n05, and 21n06 -
The on-board diagnostic system may not illuminate the Malfunction Indicator Light (mil)

- Shop Supplies

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 2.65

Total: 148.65

Work Order: 2502816 **Meter:** 73443 **In Date:** 03/25/2025 **Closed:**
Problem: marker lights inop

Work Completed

- Lighting, Other

- Recall: 21e01 Customer Satisfaction Programs 21n02, 21n05, and 21n06 -
The on-board diagnostic system may not illuminate the Malfunction Indicator Light (mil)

Hours: 0.00

Comm: 0.00

Labor: 0.00

Parts: 0.00

Total: 0.00

Work Order: 2504568 **Meter:** 74804 **In Date:** 05/15/2025 **Closed:** 07/16/2025
Problem: PM Service Please check rear cab marking lights

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service

Rotella T6 15w40 Ck4

4.00

- Recall: 21e01 Customer Satisfaction Programs 21n02, 21n05, and 21n06 -
The on-board diagnostic system may not illuminate the Malfunction Indicator Light (mil)

Used Fire X Refurbished

1.00

- repair by Ford

Non-chlor Brake Clnr

8.00

- to ford

Napagold Oil Filter

1.00

- service trans

Wiper Blade

2.00

- service cooling system

Washer Fluid Concentr

1.00

- service rear diff

oil separator

1.00

- replace front brakes

Battery

2.00

- replace bad steering parts

Fuel Filter

1.00

Air Filter (gold), Air Panel

1.00

12/18/2025
12:03:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10196035 2015 FORD F550 Utility Body, 18,000 Gvwr, with Topper

- fix rear marker light mounting
- ccv filter
- replace battery's, check charging system and clean battery trays
- service power steering
- test drive vehicle 2x
- add def
- replace front shocks
- replace rear shocks
- to weber
- alignment by weber
- replace windshield washer sprayer
- Shop Supplies

Parts Issued	Quantity
Stiction Elimint 32oz	1.00
trans pan gasket	1.00
Transmission Filter	1.00
Trans Pan	1.00
Mercon Lv Trans Fluid	12.00
Front Rotor	2.00
Tr New Car Scent 3pk	1.00
Blue Df	2.00
Insulator Nut	2.00
Front Shock Absorber	2.00
Shock Absorber Rear	2.00
Distilled Water 1gal	3.00
Coolent	3.00
75w140 Ford Axle Lube	12.00
Non-chlor Brake Clnr	4.00
B Fluid Dot 3-32oz	1.00
Rear Brake Caliper	1.00
Front Brake Caliper	1.00
Brake Pads	1.00
Nut	1.00
Nut	2.00
Rod	1.00
Damper Asy	1.00
Draglink	1.00
Tube Asm	1.00
Rod Asm	1.00
Tie Rod End	1.00
End Assy	1.00
Parts And Service Align Truck	1.00
Shop Supplies	1.00

12/18/2025
12:03:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10196035 2015 FORD F550 Utility Body, 18,000 Gvwr, with Topper

Hours: 35.50 Comm: 3,383.56 Labor: 2,591.50 Parts: 3,633.60 Total: 9,608.66

Work Order: 2506624 **Meter:** 75496 **In Date:** 07/17/2025 **Closed:** 10/06/2025
Problem: engine light, shaking steering noise, wind air squeaky noise

Work Completed

Parts Issued

Quantity

- 6 new wheels and tires
- Recall: 21e01 Customer Satisfaction Programs 21n02, 21n05, and 21n06 - The on-board diagnostic system may not illuminate the Malfunction Indicator Light (mil)
- replace steering gear box shaft has play, replace upper draglink joint has play, and do a full steering system bleed
- straighten bracket and resecure rear bumper with new hardware
- to Weber
- alignment
- Ford repair - Dpf
- to ford
- Shop Supplies

Wheel Assy	6.00
steering gear box	1.00
Draglink	1.00
Nut	1.00
Nut	1.00
oil auto	3.00
Parts And Service Weber	1.00
Shop Supplies	1.00

Hours: 15.00 Comm: 8,233.36 Labor: 1,095.00 Parts: 3,305.13 Total: 12,633.49

Work Order: 2506883 **Meter:** 75374 **In Date:** 07/18/2025 **Closed:** 07/25/2025
Problem: Tires: All Wear. Replace Tire

Work Completed

- Tire Service: he Problem: Tires: All Wear. Replace Tire

Hours: 0.00 Comm: 2,309.10 Labor: 0.00 Parts: 0.00 Total: 2,309.10

Work Order: 2510664 **Meter:** 76098 **In Date:** 11/12/2025 **Closed:** 11/13/2025
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 287.30 Total Labor: 20,247.90 Total Comm: 20,242.69 Total Parts: 22,335.12