Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 58147310
Invoice No. 55345 - 58147310

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Rear A/C		Ford Transit	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	250,075 - DH

Chronology		
Reported	Mar 27, 2026 2:27:00 PM	Mar 27, 2026 2:27:00 PM
Started	Mar 27, 2026 2:32:00 PM	
Completed	Mar 27, 2026 4:12:00 PM	Mar 27, 2026 4:12:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction: Line 20 Check Rear A/C for L/C A/C performing ok Pressure good. Perform Rear A/C Service evacuate System Change Rear dryer. Vacuum & Recharge 6.00) Lbs Freon & added (3.00) Oz Oil.
Parts # 1412015 Qy (1)

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 27-MAR-26

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		DARTHURS	Mar 27, 2026	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				2:31:48 PM		
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Mar 27, 2026 2:31:48 PM	No	
400 - Are you wearing the appropriate PPE?	Done		DARTHURS	Mar 27, 2026 2:31:48 PM	No	
700 - Have you performed the proper LOTO?	Done		DARTHURS	Mar 27, 2026 2:31:48 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Mar 27, 2026 2:31:48 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Mar 27, 2026 2:31:48 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 58147310
Invoice No. 55345 - 58147310

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Rear A/C		Ford Transit	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	250,075 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear A/C Flashing L/C
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Mar-26	1412015	ACCUMULATOR, A/C	1	17.49	17.49

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Mar-26	Arthurs,Durvin	1.65	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	17.49
Labor:	0.00
Labor Hours:	1.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**17.49**

Work Order Footer

Work Order 58147310 Total	
Parts:	17.49
Labor:	0.00
Labor Hours:	1.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**17.49**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 58146095
Invoice No. 55345 - 58146095

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Rear AC malfunction.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	249,873 - DH

Chronology		
Reported	Mar 26, 2026 9:24:00 PM	Mar 26, 2026 9:24:00 PM
Started	Mar 26, 2026 9:26:00 PM	
Completed	Mar 27, 2026 2:19:33 PM	Mar 27, 2026 2:19:33 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction: Line 20 Vehicle OOS for rear AC malfunction (LC).

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 26-MAR-26

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		EARJOHNSON	Mar 26, 2026 11:17:38 PM	No	
200 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Mar 26, 2026	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				11:17:38 PM		
400 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Mar 26, 2026 11:17:38 PM	No	
700 - Have you performed the proper LOTO?	Done		EARJOHNSON	Mar 26, 2026 11:17:38 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Mar 26, 2026 11:17:38 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Mar 26, 2026 11:17:38 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 58146095
Invoice No. 55345 - 58146095

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Rear AC malfunction.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	249,873 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear AC malfunction.
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Mar-26	Earl Johnson	1.87	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 58146095 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 58140787
Invoice No. 55345 - 58140787

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	249,533 - DH

Chronology		
Reported	Mar 24, 2026 12:36:14 AM	Mar 24, 2026 12:36:14 AM
Started	Mar 24, 2026 1:20:00 AM	
Completed	Mar 24, 2026 2:10:00 AM	Mar 24, 2026 2:10:00 AM
Down Time		

Work Order Notes

Line 10 Rear AC filter dirty and left rear inside tire low air pressure.
Filter needs to be clean, tire has a screw
Wash AC filter and reinstalled, fixed left rear inside tire and inflate tire to specs

Activity Header
Activity: 10 001/001 AIR CONDITIONING
Activity Note: rear AC filter dirty
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Mar-26	Gaspard,Ronald	0.3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 58140787
Invoice No. 55345 - 58140787

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	249,533 - DH

Activity Header
Activity:20 017/003/001 TIRE, CUSHION W/TREAD
Activity Note: low air pressure
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Mar-26	Gaspard,Ronald	0.53	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 58140787 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 58094916
Invoice No. 55345 - 58094916

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	249,533 - DH

Chronology		
Reported	Mar 23, 2026 12:00:00 AM	Mar 23, 2026 12:00:00 AM
Started	Mar 23, 2026 10:05:00 PM	
Completed	Mar 24, 2026 1:07:00 AM	Mar 24, 2026 1:07:00 AM
Down Time		

Work Order Notes

Line 10 PMA
Service
Perform PMA Service
Oil filter LF17531 qty1
Engine oil 10w30 qty6 QTs
Add washer fluid

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 23-MAR-26

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		RGASPARD	Mar 23, 2026 10:05:08 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Mar 23, 2026 10:05:08 PM	No	
400 - Are you wearing the appropriate PPE?	Done		RGASPARD	Mar 23, 2026 10:05:08 PM	No	
700 - Have you performed the proper LOTO?	Done		RGASPARD	Mar 23, 2026 10:05:08 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Mar 23, 2026 10:05:08 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Mar 23, 2026 10:05:08 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 58094916
Invoice No. 55345 - 58094916

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	249,533 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Mar-26	Gaspard,Ronald	0.6	0	0
23-Mar-26	Gaspard,Ronald	0.55	0	0
23-Mar-26	Gaspard,Ronald	0.82	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 24-MAR-26

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,800 - CHECK_All Destination Signage	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
20,200 - CHECK_Public Address System	-	NA	RGASPARD	Mar 24, 2026 12:36:40 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	NA	RGASPARD	Mar 24, 2026 12:36:40 AM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	NA	RGASPARD	Mar 24, 2026 12:36:40 AM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	NA	RGASPARD	Mar 24, 2026 12:36:40 AM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	NA	RGASPARD	Mar 24, 2026 12:36:40 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	NA	RGASPARD	Mar 24, 2026 12:36:40 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	-	NA	RGASPARD	Mar 24, 2026 12:36:40 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
21,500 - INSPECT_High Idle Control	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
21,800 - INSPECT_Parking Brake Operation	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
32,000 - Engine Inspection	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	NA	RGASPARD	Mar 24, 2026 12:36:40 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	RGASPARD	Mar 24, 2026 12:36:40 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	13.8 Volt*		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
33,000 - CSF (Curb Side Front)	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks,	Done		RGASPARD	Mar 24, 2026	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Spring Shackles				12:36:40 AM		
33,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
40,700 - CHECK_Passenger Stop Request System	-	NA	RGASPARD	Mar 24, 2026 12:36:40 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done	rear AC filter dirty	RGASPARD	Mar 24, 2026 12:36:40 AM	Yes	58140787
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
50,100 - *RPT*INSPECT_Steering components- Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
50,400 - LUBE_All Chassis Components	Done	NA	RGASPARD	Mar 24, 2026 12:36:40 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	9 32nds of an inch		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.229 Inch		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.229 Inch		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	40 Pounds per Square Inch	low air pressure	RGASPARD	Mar 24, 2026 12:36:40 AM	Yes	58140787
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.799 Inch		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.799 Inch		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
55,700 - CHECK_Spring Brake Inversion Valve	-	NA	RGASPARD	Mar 24, 2026	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:36:40 AM		
55,800 - CHECK_Double Check Valve - Primary, Secondary	-	NA	RGASPARD	Mar 24, 2026 12:36:40 AM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Mar 24, 2026 12:36:40 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 58094916
Invoice No. 55345 - 58094916

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	249,533 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Mar-26	75050	OIL, ENGINE, 5W/30	6	2.71	16.26
24-Mar-26	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	3.69	3.69

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Mar-26	Gaspard,Ronald	0.45	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: RGASPARD Performed on: 24-MAR-26

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Mar 24, 2026 1:07:21 AM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Mar 24, 2026 1:07:21 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Mar 24, 2026 1:07:21 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Mar 24, 2026 1:07:21 AM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Mar 24, 2026 1:07:21 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Mar 24, 2026 1:07:21 AM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	-	NA	RGASPARD	Mar 24, 2026 1:07:21 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Mar 24, 2026 1:07:21 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Mar 24, 2026	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				1:07:21 AM		

Activity Sub Total

Activity 20 Sub Total	
Parts:	19.95
Labor:	0.00
Labor Hours:	0.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**19.95**

Work Order Footer

Work Order 58094916 Total	
Parts:	19.95
Labor:	0.00
Labor Hours:	2.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**19.95**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 58094511
Invoice No. 55345 - 58094511

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	245,640 - DH

Chronology		
Reported	Feb 20, 2026 7:50:04 AM	Feb 20, 2026 7:50:04 AM
Started	Feb 20, 2026 7:51:00 AM	
Completed	Feb 21, 2026 2:20:00 PM	Feb 21, 2026 2:20:00 PM
Down Time		

Work Order Notes

Line 10 Replaced turbo line Line 20 Replaced radiator

Activity Header

Activity: 10 043/004/064 KIT, MOUNTING, TURBOCHARGER
Activity Note: leaking coolant turbo
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Feb-26	LK4Z-8005-F	RADIATOR, TRANSIT, 3.5L W/TURBO	1	241.32	241.32
20-Feb-26	BL3Z-6A968-C	CONNECTOR, LINE, OIL, TURBOCHARGER, RH, F350 HD	1	10.1	10.1

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Feb-26	NELSON PIERRE-LOUIS	4.18	0	0
20-Feb-26	Delva,Terry	2	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	251.42
Labor:	0.00
Labor Hours:	6.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**251.42**

Work Order Footer

Work Order 58094511 Total	
Parts:	251.42
Labor:	0.00
Labor Hours:	6.18

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**251.42**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 58094914
Invoice No. 55345 - 58094914

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	245,640 - DH

Chronology

Reported	Feb 20, 2026 12:14:41 PM	Feb 20, 2026 12:14:41 PM
Started	Feb 20, 2026 3:13:00 PM	
Completed	Feb 20, 2026 3:55:00 PM	Feb 20, 2026 3:55:00 PM
Down Time		

Work Order Notes

Line 10 Replaced coolant bypass hose

Activity Header

Activity: 10 002/002/056 FLAP, MUD, WHEEL, FRONT, REAR
Activity Note:
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Feb-26	KM5411	HOSE, COOLANT, RADIATOR	1	46.99	46.99

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Feb-26	Delva,Terry	0.7	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	46.99
Labor:	0.00
Labor Hours:	0.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**46.99**

Work Order Footer

Work Order 58094914 Total	
Parts:	46.99
Labor:	0.00
Labor Hours:	0.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**46.99**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 58045829
Invoice No. 55345 - 58045829

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	245,640 - DH

Chronology		
Reported	Feb 17, 2026 12:00:00 AM	Feb 17, 2026 12:00:00 AM
Started	Feb 20, 2026 5:43:00 AM	
Completed	Feb 20, 2026 12:15:00 PM	Feb 20, 2026 12:15:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: PMB service

Cause: preventive maintenance

Correction: perform PMB maintenance service and lube

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 20-FEB-26

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Feb 20, 2026 12:08:41 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Feb 20, 2026 12:08:41 PM	No	
400 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Feb 20, 2026 12:08:41 PM	No	
700 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Feb 20, 2026 12:08:41 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Feb 20, 2026 12:08:41 PM	No	
1,100 - Have you successfully completed the	Done		NPIERRE-	Feb 20, 2026	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?			LOUIS	12:08:41 PM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 58045829
Invoice No. 55345 - 58045829

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	245,640 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Feb-26	AF56065	FILTER, AIR, CABIN SUPERSEDES PA30000	1	10.35	10.35

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Feb-26	NELSON PIERRE-LOUIS	2.13	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS Performed on: 20-FEB-26

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
10,800 - CHECK_All Destination Signage	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
20,200 - CHECK_Public Address System	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	na	NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	na	NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	na	NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	na	NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	na	NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
21,500 - INSPECT_High Idle Control	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	-	na	NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
31,000 - SSF (Street Side Front)	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
32,000 - Engine Inspection	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
32,100 - INSPECT_Intake System	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done	leaking coolant turbo	NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	Yes	58094511
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.3 Volt*		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
33,000 - CSF (Curb Side Front)	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
33,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
40,700 - CHECK_Passenger Stop Request System	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
50,400 - LUBE_All Chassis Components	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
50,700 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	66 Pounds per Square Inch		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	67 Pounds per Square Inch		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	23.5 Inch		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	23.5 Inch		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
52,100 - INSPECT_Vibration Damper	-	na	NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,600 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	Yes	58094914
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	67 Pounds per Square Inch		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	66 Pounds per Square Inch		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	66 Pounds per Square Inch		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	17.5 Inch		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	17.5 Inch		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	Feb 20, 2026 12:10:58 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	10.35
Labor:	0.00
Labor Hours:	2.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**10.35**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 58045829
Invoice No. 55345 - 58045829

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	245,640 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMB Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Feb-26	75050	OIL, ENGINE, 5W/30	6	2.71	16.26
20-Feb-26	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	3.69	3.69

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMB Service
Task: 55345-Medium Duty PMB Inspection Performed by: NPIERRE-LOUIS Performed on: 20-FEB-26

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Feb 20, 2026 12:09:47 PM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Feb 20, 2026 12:09:47 PM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Feb 20, 2026 12:09:47 PM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Feb 20, 2026 12:09:47 PM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Feb 20, 2026 12:09:47 PM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Feb 20, 2026 12:09:47 PM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	Done		NPIERRE-LOUIS	Feb 20, 2026 12:09:47 PM	No	
107,000 - FRA Change Primary Fuel Filter	No		NPIERRE-LOUIS	Feb 20, 2026 12:09:47 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Feb 20, 2026 12:09:47 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		NPIERRE-LOUIS	Feb 20, 2026 12:09:47 PM	No	
201,000 - Service Crankcase Breather	Done		NPIERRE-LOUIS	Feb 20, 2026 12:09:47 PM	No	
202,000 - FRA Change Water Separator ¿ Secondary Fuel Filters	No		NPIERRE-LOUIS	Feb 20, 2026 12:09:47 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		NPIERRE-LOUIS	Feb 20, 2026 12:09:47 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		NPIERRE-LOUIS	Feb 20, 2026 12:09:47 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		NPIERRE-LOUIS	Feb 20, 2026 12:09:47 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	19.95
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**19.95**

Work Order Footer

Work Order 58045829 Total	
Parts:	30.30
Labor:	0.00
Labor Hours:	2.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**30.30**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 58064681
Invoice No. 55345 - 58064681

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
needs right front head light		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	242,967 - DH

Chronology		
Reported	Jan 31, 2026 1:52:00 AM	Jan 31, 2026 1:52:00 AM
Started	Jan 31, 2026 1:55:00 AM	
Completed	Jan 31, 2026 2:00:00 AM	Jan 31, 2026 2:00:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction:

Line 20 Needs right front head light Bulb
Bulb blew out
Replaced head light bulb #H11BP qty1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 31-JAN-26

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		RGASPARD	Jan 31, 2026 1:55:22 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Jan 31, 2026 1:55:22 AM	No	
400 - Are you wearing the appropriate PPE?	Done		RGASPARD	Jan 31, 2026 1:55:22 AM	No	
700 - Have you performed the proper LOTO?	Done		RGASPARD	Jan 31, 2026 1:55:22 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Jan 31, 2026 1:55:22 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jan 31, 2026 1:55:22 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 58064681
Invoice No. 55345 - 58064681

Client Department:
Department: 55345M
Work Order Description
needs right front head light
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 242,967 - DH

Activity Header
Activity: 15 034 LIGHTING SYSTEM
Activity Note: Needs right front head light
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
31-Jan-26	H11BP	BULB, HEADLAMP	1	7.45	7.45

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Jan-26	Gaspard,Ronald	0.08	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	7.45
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.45**

Work Order Footer

Work Order 58064681 Total	
Parts:	7.45
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.45**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 58051871
Invoice No. 55345 - 58051871

Client Department:
Department: 55345M
Work Order Description
WC seat belt retractor cover missing.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 242,064 - DH

Chronology		
Reported	Jan 21, 2026 11:43:00 PM	Jan 21, 2026 11:43:00 PM
Started	Jan 21, 2026 11:45:00 PM	
Completed	Jan 23, 2026 1:39:00 AM	Jan 23, 2026 1:39:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction: Line 20 Remove and replaced rear WC seat belt retractor.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 22-JAN-26

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jan 22, 2026 1:22:52 AM	No	
200 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Jan 22, 2026	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				1:22:52 AM		
400 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jan 22, 2026 1:22:52 AM	No	
700 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jan 22, 2026 1:22:52 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jan 22, 2026 1:22:52 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jan 22, 2026 1:22:52 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 58051871
Invoice No. 55345 - 58051871

Client Department:
Department: 55345M
Work Order Description
WC seat belt retractor cover missing.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 242,064 - DH

Activity Header
Activity: 15 002/011/003 BELT & RETAINER, SEAT
Activity Note: WC seat belt retractor cover missing.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Feb-26	13448	BELT, SEAT, UNDERSEAT, FOLDAWAY	1	72.82	72.82

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Jan-26	Earl Johnson	1.35	0	0
21-Jan-26	Earl Johnson	0.25	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	72.82
Labor:	0.00
Labor Hours:	1.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**72.82**

Work Order Footer

Work Order 58051871 Total	
Parts:	72.82
Labor:	0.00
Labor Hours:	1.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**72.82**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 5

Work Order No. 58045810
Invoice No. 55345 - 58045810

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	241,673 - DH

Chronology		
Reported	Jan 17, 2026 1:02:15 AM	Jan 17, 2026 1:02:15 AM
Started	Jan 17, 2026 1:36:00 AM	
Completed	Jan 17, 2026 2:32:00 AM	Jan 17, 2026 2:32:00 AM
Down Time		

Work Order Notes

Line 10 Remove and replaced LR clearance light. Line 20 Remove and replaced license plate light. Line 30 Removed and cleaned rear AC filter element. Line 40 Replaced driveshaft loop bolt.

Activity Header

Activity: 10 034/003/000 LAMPS, SIGNAL, PARKING & BACKUP
Activity Note: LR clearance light out. Tag light out.
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Jan-26	MCL12RK	LAMP, MARKER/CLEARANCE, RED	1	9.61	9.61
17-Jan-26	B168	LIGHT, LICENSE, PLATE	1	9.3	9.3

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	18.91
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**18.91**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 5

Work Order No. 58045810
Invoice No. 55345 - 58045810

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	241,673 - DH

Activity Header
Activity: 20 174/024/001 HARNESS, WIRING, BODY, BUS, MAIN
Activity Note: Wires hanging under dash.
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 5

Work Order No. 58045810
Invoice No. 55345 - 58045810

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	241,673 - DH

Activity Header
Activity: 30 001/001 AIR CONDITIONING
Activity Note: Rear AC filter dirty.
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 5

Work Order No. 58045810
Invoice No. 55345 - 58045810

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	241,673 - DH

Activity Header
Activity: 40 024/001/004 U-JOINT, DRIVESHAFT
Activity Note: Driveshaft safety loop missing bolt.
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Jan-26	Earl Johnson	0.9	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.90
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 5

Work Order No. 58045810
Invoice No. 55345 - 58045810

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	241,673 - DH

Activity Header
Activity: 50 018/003/005 NUT, WHEEL, SELF-LOOKING
Activity Note: Lug nut indicators faded.
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 50 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 58045810 Total	
Parts:	18.91
Labor:	0.00
Labor Hours:	0.90
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**18.91**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57993329
Invoice No. 55345 - 57993329

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	241,673 - DH

Chronology		
Reported	Jan 15, 2026 12:00:00 AM	Jan 15, 2026 12:00:00 AM
Started	Jan 16, 2026 11:51:00 PM	
Completed	Jan 17, 2026 1:34:00 AM	Jan 17, 2026 1:34:00 AM
Down Time		

Work Order Notes

Line 10 Complaint: PM A service.

Cause: Due by mileage.

Correction: LOF engine oil and filter. Performed tire and brake inspection.

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 17-JAN-26

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jan 17, 2026 1:05:39 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jan 17, 2026 1:05:39 AM	No	
400 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jan 17, 2026 1:05:39 AM	No	
700 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jan 17, 2026 1:05:39 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jan 17, 2026 1:05:39 AM	No	
1,100 - Have you successfully completed the	Done		EARJOHNSON	Jan 17, 2026	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				1:05:39 AM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57993329
Invoice No. 55345 - 57993329

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	241,673 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jan-26	Earl Johnson	0.15	0	0
17-Jan-26	Earl Johnson	0.7	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: EARJOHNSON Performed on: 17-JAN-26

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		EARJOHNSON	Jan 17, 2026	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				1:32:57 AM		
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done	LR clearance light out. Tag light out.	EARJOHNSON	Jan 17, 2026 1:32:57 AM	Yes	58045810
10,800 - CHECK_All Destination Signage	Done	NA	EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done	Minor scratches and scuffs.	EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done	Normal wear.	EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
20,200 - CHECK_Public Address System	Done	NA	EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	NA	EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	NA	EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	NA	EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	NA	EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	NA	EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done	NA	EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
21,300 - *RPT*INSPECT_Windshields, Sun	Done		EARJOHNSON	Jan 17,	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Visors				2026 1:32:57 AM		
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
21,500 - INSPECT_High Idle Control	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
21,800 - INSPECT_Parking Brake Operation	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done	Wires hanging under dash.	EARJOHNSON	Jan 17, 2026 1:32:57 AM	Yes	58045810
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
31,000 - SSF (Street Side Front)	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,000 - Engine Inspection	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	NA	EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
32,100 - INSPECT_Intake System	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.7 Volt*		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
33,000 - CSF (Curb Side Front)	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,000 - SECTION 4 - Interior Inspection	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
40,700 - CHECK_Passenger Stop Request System	Done	NA	EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done	Rear AC filter dirty.	EARJOHNSON	Jan 17, 2026 1:32:57 AM	Yes	58045810
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
50,400 - LUBE_All Chassis Components	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
50,700 - INSPECT_Tire Condition	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	9 32nds of an inch		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	9 32nds of an inch		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.124 Inch		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.124 Inch		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
52,100 - INSPECT_Vibration Damper	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
52,400 - !FRA!INSPECT_ Starter Mounting	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done	Driveshaft safety loop missing bolt.	EARJOHNSON	Jan 17, 2026 1:32:57 AM	Yes	58045810
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
53,600 - INSPECT_Tire Condition	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done	NA	EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done	Lug nut indicators faded.	EARJOHNSON	Jan 17, 2026 1:32:57 AM	Yes	58045810
54,100 - INSPECT_Mud Flaps, Brackets	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	9 32nds of an inch		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.688 Inch		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.686 Inch		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done	NA	EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done	NA	EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,100 - COMPLETE_PM Report; Follow-ups	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		EARJOHNSON	Jan 17, 2026 1:32:57 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57993329
Invoice No. 55345 - 57993329

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	241,673 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Jan-26	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	3.68	3.68
17-Jan-26	75050	OIL, ENGINE, 5W/30	6	2.71	16.26

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Jan-26	Earl Johnson	0.73	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: EARJOHNSON Performed on: 17-JAN-26

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		EARJOHNSON	Jan 17, 2026 1:28:08 AM	No	
101,000 - FRA Change Oil Filters	Yes		EARJOHNSON	Jan 17, 2026 1:28:08 AM	No	
102,000 - FRA Drain Engine Oil	Yes		EARJOHNSON	Jan 17, 2026 1:28:08 AM	No	
103,000 - FRA Check Transmission Fluid	Done		EARJOHNSON	Jan 17, 2026 1:28:08 AM	No	
104,000 - Lubricate Chassis	Done		EARJOHNSON	Jan 17, 2026 1:28:08 AM	No	
105,000 - Replace or Clean A/C Filters	Done		EARJOHNSON	Jan 17, 2026 1:28:08 AM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	Done	NA	EARJOHNSON	Jan 17, 2026 1:28:08 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	EARJOHNSON	Jan 17, 2026 1:28:08 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		EARJOHNSON	Jan 17, 2026	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				1:28:08 AM		

Activity Sub Total

Activity 20 Sub Total	
Parts:	19.94
Labor:	0.00
Labor Hours:	0.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**19.94**

Work Order Footer

Work Order 57993329 Total	
Parts:	19.94
Labor:	0.00
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**19.94**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 58028944
Invoice No. 55345 - 58028944

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOW UP TO QCC INSP		Ford Transit	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	240,117 - DH

Chronology		
Reported	Jan 5, 2026 11:06:53 PM	Jan 5, 2026 11:06:53 PM
Started	Jan 5, 2026 11:43:00 PM	
Completed	Jan 6, 2026 2:16:00 AM	Jan 6, 2026 2:16:00 AM
Down Time		

Work Order Notes

Line 10 Resecured the passenger side kick panel with new screws. Line 20 Passenger side rear AC blower motor lightly squeaks , intermittently. Still operates efficiently. Line 30 Turbo intercooler line detached. Resecured line and road tested without any issues. Line 40 Passenger windows secured.

Activity Header
Activity: 10 000 CAB, CLIMATE CONTROL, INSTRUMENTS & AERODYNAMIC DEVICES
Activity Note: Entrance black board missing screws
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jan-26	Earl Johnson	0.15	0	0
05-Jan-26	Earl Johnson	0.28	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 58028944
Invoice No. 55345 - 58028944

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOW UP TO QCC INSP		Ford Transit	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	240,117 - DH

Activity Header
Activity: 20 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: REAR AC BLOWER MOTOR NOISY
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jan-26	Earl Johnson	0.72	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 58028944
Invoice No. 55345 - 58028944

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOW UP TO QCC INSP		Ford Transit	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	240,117 - DH

Activity Header
Activity: 30 002 CAB & SHEET METAL
Activity Note: LEFT SECOND WINDOW LOOSE
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 58028944
Invoice No. 55345 - 58028944

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOW UP TO QCC INSP		Ford Transit	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	240,117 - DH

Activity Header
Activity: 40 020 GROUP, DRIVETRAIN
Activity Note: WEIRD WASHING NOISE WHEN ACCELERATING
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jan-26	Earl Johnson	1.38	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.38
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 58028944 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57584149
Invoice No. 55345 - 57584149

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
QCC FLEET INSPECTION		Ford Transit	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	240,117 -

Chronology		
Reported	Jan 5, 2026 9:13:55 AM	Jan 5, 2026 9:13:55 AM
Started		
Completed	Jan 5, 2026 11:08:00 PM	Jan 5, 2026 11:08:00 PM
Down Time		

Work Order Notes

Line 10 QCC INSPECTION COMPLETED.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 05-JAN-26

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		FSIMON	Jan 5, 2026 10:51:31 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		FSIMON	Jan 5, 2026 10:51:31 PM	No	
400 - Are you wearing the appropriate PPE?	Done		FSIMON	Jan 5, 2026 10:51:31 PM	No	
700 - Have you performed the proper LOTO?	Done		FSIMON	Jan 5, 2026 10:51:31 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		FSIMON	Jan 5, 2026 10:51:31 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Jan 5, 2026 10:51:31 PM	No	

Activity Sub Total

Activity 10 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57584149
Invoice No. 55345 - 57584149

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
QCC FLEET INSPECTION		Ford Transit	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	240,117 -

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: QCC FLEET INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: QCC FLEET INSPECTION
Task: 55345 QCC FLEET INSPECTION Performed by: FSIMON Performed on: 05-JAN-26

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - EXTERIOR CIRCLE INSPECTION	Done		FSIMON	Jan 5, 2026 11:07:18 PM	No	
20 - Cleanliness	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
30 - Entrance Door Operation/Seals/Glass	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
40 - Body/Fenders/Bumpers	B	Entrance black board missing screws	FSIMON	Jan 5, 2026 11:07:18 PM	Yes	58028944
50 - Tires/Wheels/Lugs	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
60 - Mirrors and Attachments	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
70 - Lights and Accessories	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
80 - Compartment Doors	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
90 - Battery Compartment	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
100 - Check All Fluids	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
110 - Belt Drives	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
120 - Air Induction	E		FSIMON	Jan 5, 2026 11:07:18 PM	No	
130 - Exhaust System	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
140 - Engine Compartmetn Wiring	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
150 - DRIVERS AREA INSPECTION	Done		FSIMON	Jan 5, 2026 11:07:18 PM	No	
160 - Air System	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
170 - Audible Warnings	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
180 - Dash and Gauges	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
190 - Accessory components	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
200 - Exit Door Operation	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
210 - Exit Door Interlock	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
220 - Fare box and ticket cutter.	E		FSIMON	Jan 5, 2026 11:07:18 PM	No	
230 - Fast Idle	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
240 - Glass & Mirrors	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
250 - Floor Covering	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
260 - Horn and Lamps	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
270 - Start Function	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
280 - PA System	E		FSIMON	Jan 5, 2026 11:07:18 PM	No	
290 - Pedal Condition and Adjustment	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
300 - Reverse System	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
310 - Seat	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
320 - Steering Wheel & Column	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
330 - Sun Visor	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
340 - Turn Signals Switch	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
350 - Electrical Compartment	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
360 - Wheel Chair Operation	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
370 - INTERIOR CIRCLE	Done		FSIMON	Jan 5, 2026 11:07:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
380 - Cleanliness	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
390 - HVAC	B	REAR AC BLOWER MOTOR NOISY	FSIMON	Jan 5, 2026 11:07:18 PM	Yes	58028944
400 - Interior Passenger Area	B	LEFT SECOND WINDOW LOOSE	FSIMON	Jan 5, 2026 11:07:18 PM	Yes	58028944
410 - Stop Request	E		FSIMON	Jan 5, 2026 11:07:18 PM	No	
420 - Safety Equipment	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
430 - UNDERCARRIAGE	Done		FSIMON	Jan 5, 2026 11:07:18 PM	No	
440 - Air System	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
450 - Steering components	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
460 - Brake Inspection	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
470 - Suspension Components	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
480 - Frame	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
490 - Fluid Leakage	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	
500 - Fuel System	A		FSIMON	Jan 5, 2026 11:07:18 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57584149 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57992991
Invoice No. 55345 - 57992991

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	237,846 - DH

Chronology		
Reported	Dec 8, 2025 7:59:11 AM	Dec 8, 2025 7:59:11 AM
Started	Dec 8, 2025 8:17:00 AM	
Completed	Dec 8, 2025 12:03:00 PM	Dec 8, 2025 12:03:00 PM
Down Time		

Work Order Notes

Line 10 Replaced RH connector line turbocharger

Replaced one TPMs

Activity Header
Activity: 10 043/004/064 KIT, MOUNTING, TURBOCHARGER
Activity Note: turbocharger leaking coolant
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Dec-25	BL3Z-6A968-JD	CONNECTOR, LINE, OIL, TURBOCHARGER, RH, F350 HD	1	11.75	11.75

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Dec-25	NELSON PIERRE-LOUIS	3.68	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	11.75
Labor:	0.00
Labor Hours:	3.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**11.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57992991
Invoice No. 55345 - 57992991

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	237,846 - DH

Activity Header
Activity: 20 017/009 INFLATION & MONITORING, PRESSURE, TIRE
Activity Note: front d/s tpms
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Dec-25	TPMS62	SENSOR, MONITORING, PRESSURE, TIRE	1	42.77	42.77

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	42.77
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**42.77**

Work Order Footer

Work Order 57992991 Total	
Parts:	54.52
Labor:	0.00
Labor Hours:	3.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**54.52**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57937705
Invoice No. 55345 - 57937705

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	237,846 - DH

Chronology		
Reported	Dec 8, 2025 5:58:37 AM	Dec 8, 2025 5:58:37 AM
Started	Dec 8, 2025 6:08:00 AM	
Completed	Dec 8, 2025 11:16:00 AM	Dec 8, 2025 11:16:00 AM
Down Time		

Work Order Notes

Line 10 Complaint: PMA service

Cause: preventive maintenance

Correction: perform PMA maintenance service and lube

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 08-DEC-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Dec 8, 2025 8:10:38 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Dec 8, 2025 8:10:38 AM	No	
400 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Dec 8, 2025 8:10:38 AM	No	
700 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Dec 8, 2025 8:10:38 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Dec 8, 2025 8:10:38 AM	No	
1,100 - Have you successfully completed the	Done		NPIERRE-	Dec 8, 2025	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?			LOUIS	8:10:38 AM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57937705
Invoice No. 55345 - 57937705

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	237,846 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Dec-25	NELSON PIERRE-LOUIS	2.15	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS Performed on: 08-DEC-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
10,800 - CHECK_All Destination Signage	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
10,900 - *RPT*INSPECT_Body Damage,	Done		NPIERRE-	Dec 8, 2025	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Corrosion;DOCUMENT_Issues			LOUIS	11:15:53 AM		
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
20,200 - CHECK_Public Address System	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	na	NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	na	NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	na	NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	na	NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	na	NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
21,500 - INSPECT_High Idle Control	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
21,800 - INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	-	na	NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
31,000 - SSF (Street Side Front)	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
32,000 - Engine Inspection	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
32,100 - INSPECT_Intake System	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done	turbocharger leaking coolant	NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	Yes	57992991
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.2 Volt*		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
33,000 - CSF (Curb Side Front)	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
33,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
40,700 - CHECK_Passenger Stop Request System	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
50,400 - LUBE_All Chassis Components	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
50,700 - INSPECT_Tire Condition	Done	front d/s tpms	NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	Yes	57992991

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	11 32nds of an inch		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	67 Pounds per Square Inch		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	11 32nds of an inch		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	66 Pounds per Square Inch		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	23.3 Inch		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	23.3 Inch		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
52,100 - INSPECT_Vibration Damper	-	na	NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
53,600 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	11 32nds of an inch		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	11 32nds of an inch		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	68 Pounds per Square Inch		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	67 Pounds per Square Inch		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	11 32nds of an inch		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	11 32nds of an inch		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	67 Pounds per Square Inch		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	66 Pounds per Square Inch		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	17.7 Inch		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	17.5 Inch		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
55,800 - CHECK_Double Check Valve - Primary,	Done		NPIERRE-	Dec 8, 2025	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Secondary			LOUIS	11:15:53 AM		
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
80,000 - SECTION 8 - PMI Report Completion	-		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	Dec 8, 2025 11:15:53 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.15
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57937705
Invoice No. 55345 - 57937705

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	237,846 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Dec-25	75050	OIL, ENGINE, 5W/30	6	2.71	16.26
08-Dec-25	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	3.65	3.65

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: NPIERRE-LOUIS Performed on: 08-DEC-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Dec 8, 2025 8:11:54 AM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Dec 8, 2025 8:11:54 AM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Dec 8, 2025 8:11:54 AM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Dec 8, 2025 8:11:54 AM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Dec 8, 2025 8:11:54 AM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Dec 8, 2025 8:11:54 AM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	Done		NPIERRE-LOUIS	Dec 8, 2025 8:11:54 AM	No	
107,000 - FRA Change Primary Fuel Filter	No		NPIERRE-LOUIS	Dec 8, 2025 8:11:54 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Dec 8, 2025 8:11:54 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	19.91
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**19.91**

Work Order Footer

Work Order 57937705 Total	
Parts:	19.91
Labor:	0.00
Labor Hours:	2.15
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**19.91**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57976674
Invoice No. 55345 - 57976674

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Road Call-tires		Ford Transit	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	237,293 - DH

Chronology		
Reported	Nov 25, 2025 2:36:00 PM	Nov 25, 2025 2:36:00 PM
Started		
Completed	Dec 2, 2025 8:47:00 AM	Dec 2, 2025 8:47:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction: Line 20 REAR FLAT TIRES REPLACED BY ELPEX

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57976674
Invoice No. 55345 - 57976674

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Road Call-tires		Ford Transit	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	237,293 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL-TIRES REPLACED BY ELPEX GOOD YEAR MOBILE SERVICE
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Nov-25	131196995	TIRE, 195/75R16, WORKHORSE, HTL, WRANGLER, GOODYEAR	2	120	240
28-Nov-25	YY164902	FEE, ENVIRONMENTAL	2	1	2
28-Nov-25	YY183320	TIRE CHANGE, LT - Dismount tire from vehicle, dismount tire from rim/wheel, mount tireon rim/wheel, mount tire on vehicle - outside dual	2	112.5	225
28-Nov-25	YY183330	FEE, TIRE DISPOSAL, LT	2	3	6

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	473.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**473.00**

Work Order Footer

Work Order 57976674 Total	
Parts:	473.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**473.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 57976719
Invoice No. 55345 - 57976719

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
w/c lift having issues with big scooters		Ford Transit	
Requested By:	VRAMOS	**Status:**	40 - Closed (40)
Created By:	VRAMOS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	237,293 - DH

Chronology		
Reported	Nov 25, 2025 3:06:00 PM	Nov 25, 2025 3:06:00 PM
Started	Nov 25, 2025 3:09:00 PM	
Completed	Nov 26, 2025 8:56:00 AM	Nov 26, 2025 8:56:00 AM
Down Time		

Work Order Notes

Line 10 Wheel chair lift needs deeper diag, possibly bad pump Line 20 Vehicle OOS W/C lift inoperative 50 pound solenoid out of range

Activity Header

Activity: 10 999 TOTAL VEHICLE
Activity Note: W/C lift having issues with big scooter
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Nov-25	Victor Ramos	0.57	0	0
26-Nov-25	Rodriguez,Raul	1.23	0	0
26-Nov-25	Rodriguez,Raul	0.17	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57976719 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.97
Sublet Parts:	0.00

	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 57956741
Invoice No. 55345 - 57956741

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
REAR AC SYSTEM		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	235,362 - DH

Chronology		
Reported	Nov 11, 2025 1:30:00 PM	Nov 11, 2025 1:30:00 PM
Started	Nov 11, 2025 1:31:00 PM	
Completed	Nov 12, 2025 9:05:00 AM	Nov 12, 2025 9:05:00 AM
Down Time		

Work Order Notes

Line 10 Rear ac flashing HA
Bad dryer
Removed and replaced dryer Line 20 Needs 4 rear tires
Low specs
4 new tires mounted and balance
Torque wheels 140 lbs second torque 140 lbs
Part #131196995 qty4 Line 30 Emergency exit lights off
Power wire touching ground
Repair and relocate power wire

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 11-NOV-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Nov 11, 2025 2:30:20 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Nov 11, 2025 2:30:20 PM	No	
400 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Nov 11, 2025 2:30:20 PM	No	
700 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Nov 11, 2025 2:30:20 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,000 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Nov 11, 2025 2:30:20 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Nov 11, 2025 2:30:20 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 57956741
Invoice No. 55345 - 57956741

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
REAR AC SYSTEM		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	235,362 - DH

Activity Header
Activity: 20 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: REAR AC DIAG
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Nov-25	1412015	ACCUMULATOR, A/C	1	15.79	15.79

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Nov-25	Rodriguez,Raul	0.98	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	15.79
Labor:	0.00
Labor Hours:	0.98
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**15.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 57956741
Invoice No. 55345 - 57956741

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
REAR AC SYSTEM		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	235,362 - DH

Activity Header
Activity: 30 017 TIRES, TUBES, LINERS & VALVES
Activity Note: check tires
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Nov-25	131196995	TIRE, 195/75R16, WORKHORSE, HTL, WRANGLER, GOODYEAR	4	120	480

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Nov-25	Gaspard,Ronald	1.42	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	480.00
Labor:	0.00
Labor Hours:	1.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**480.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 57956741
Invoice No. 55345 - 57956741

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
REAR AC SYSTEM		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	235,362 - DH

Activity Header
Activity: 40 034/000/000 LIGHTING SYSTEM
Activity Note: Emergency exit lights off
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Nov-25	Rodriguez,Raul	0.7	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57956741 Total	
Parts:	495.79
Labor:	0.00
Labor Hours:	3.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**495.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 9

Work Order No. 57937510
Invoice No. 55345 - 57937510

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	234,359 - DH

Chronology		
Reported	Nov 1, 2025 8:13:28 AM	Nov 1, 2025 8:13:28 AM
Started	Nov 1, 2025 8:37:00 AM	
Completed	Nov 4, 2025 7:55:00 AM	Nov 4, 2025 7:55:00 AM
Down Time		

Work Order Notes

Line 10 Replaced all belts
Replaced turbo line plug
Replaced ball joint
Replaced front brakes
Replaced top clearance light

Activity Header
Activity: 10 034/003/000 LAMPS, SIGNAL, PARKING & BACKUP
Activity Note: front top Clearance light
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Nov-25	MCL12AK	LAMP, MARKER/CLEARANCE, LED, AMBER	1	10.19	10.19

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	10.19
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**10.19**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 9

Work Order No. 57937510
Invoice No. 55345 - 57937510

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	234,359 - DH

Activity Header
Activity: 20 174/001/001 BODY, BUS, COMPLETE
Activity Note: Body Damage PTC letters peeling off
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 9

Work Order No. 57937510
Invoice No. 55345 - 57937510

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	234,359 - DH

Activity Header
Activity:30 043/004/064 KIT, MOUNTING, TURBOCHARGER
Activity Note: Rear left top turbo leaks
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Nov-25	BL3Z-6A968-C	CONNECTOR, LINE, OIL, TURBOCHARGER, RH, F350 HD	1	10.38	10.38

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Nov-25	Delva,Terry	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	10.38
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**10.38**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 9

Work Order No. 57937510
Invoice No. 55345 - 57937510

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	234,359 - DH

Activity Header
Activity:40 174/022/011 COVER, SEAT, SEAT, BUS
Activity Note: Need belts
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Nov-25	K040405	BELT, SERPENTINE, 4-RIB, 40.55"L X 0.54"W SAME AS 5040405	1	15.51	15.51
04-Nov-25	K060547	BELT, SERPENTINE, 6-RIB, 54.75"L X 0.82"W SAME AS 5060548	1	15.9	15.9
04-Nov-25	K040535	BELT, SERPENTINE, 4-RIB, 53.54"L X .054"W SAME AS 5040535	1	20.25	20.25

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Nov-25	Delva,Terry	1.3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	51.66
Labor:	0.00
Labor Hours:	1.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**51.66**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 9

Work Order No. 57937510
Invoice No. 55345 - 57937510

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	234,359 - DH

Activity Header
Activity: 50 034/004/083 LAMP, INTERIOR
Activity Note:
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 50 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 6 of 9

Work Order No. 57937510
Invoice No. 55345 - 57937510

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	234,359 - DH

Activity Header
Activity:60 034/004/083 LAMP, INTERIOR
Activity Note:
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Nov-25	Delva,Terry	0.28	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 60 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 7 of 9

Work Order No. 57937510
Invoice No. 55345 - 57937510

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	234,359 - DH

Activity Header
Activity: 70 016/001/006 SHAFT, ARM, CONTROL, LOWER
Activity Note: Left ball joint
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Nov-25	KK3Z-3050-B	JOINT, BALL, LOWER	1	65.45	65.45

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Nov-25	Delva,Terry	2.2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 70 Sub Total	
Parts:	65.45
Labor:	0.00
Labor Hours:	2.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**65.45**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 8 of 9

Work Order No. 57937510
Invoice No. 55345 - 57937510

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	234,359 - DH

Activity Header
Activity: 80 013/002/013 SHOE, BRAKE, REAR
Activity Note: Front brake
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Nov-25	BRF-1896	PADS, BRAKE, DISC, FRONT, TRANSIT	1	55.79	55.79

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 80 Sub Total	
Parts:	55.79
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**55.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 9 of 9

Work Order No. 57937510
Invoice No. 55345 - 57937510

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	234,359 - DH

Activity Header
Activity: 90 017/001 TIRE, PNEUMATIC
Activity Note: Rear Tires
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 90 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57937510 Total	
Parts:	193.47
Labor:	0.00
Labor Hours:	6.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**193.47**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57900497
Invoice No. 55345 - 57900497

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	234,359 - DH

Chronology		
Reported	Oct 31, 2025 8:12:53 AM	Oct 31, 2025 8:12:53 AM
Started	Nov 1, 2025 6:29:00 AM	
Completed	Nov 1, 2025 2:36:00 PM	Nov 1, 2025 2:36:00 PM
Down Time		

Work Order Notes

Line 10 PMB

Service due

Performed and completed B

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 01-NOV-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		TDELVA	Nov 1, 2025 6:30:22 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Nov 1, 2025 6:30:22 AM	No	
400 - Are you wearing the appropriate PPE?	Done		TDELVA	Nov 1, 2025 6:30:22 AM	No	
700 - Have you performed the proper LOTO?	Done		TDELVA	Nov 1, 2025 6:30:22 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Nov 1, 2025 6:30:22 AM	No	
1,100 - Have you successfully completed the Personal	Done		TDELVA	Nov 1, 2025	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				6:30:22 AM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57900497
Invoice No. 55345 - 57900497

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	234,359 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Nov-25	Delva,Terry	1.67	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: TDELVA Performed on: 01-NOV-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done	front top Clearance light	TDELVA	Nov 1, 2025 8:09:46 AM	Yes	57937510
10,800 - CHECK_All Destination Signage	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
10,900 - *RPT*INSPECT_Body Damage,	Done	Body Damage	TDELVA	Nov 1, 2025	Yes	57937510

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Corrosion;DOCUMENT_Issues		PTC letters peeling off		8:09:46 AM		
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
20,200 - CHECK_Public Address System	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	-	na	TDELVA	Nov 1, 2025 8:09:46 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	na	TDELVA	Nov 1, 2025 8:09:46 AM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	na	TDELVA	Nov 1, 2025 8:09:46 AM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	na	TDELVA	Nov 1, 2025 8:09:46 AM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	na	TDELVA	Nov 1, 2025 8:09:46 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	na	TDELVA	Nov 1, 2025 8:09:46 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	-	na	TDELVA	Nov 1, 2025 8:09:46 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
21,500 - INSPECT_High Idle Control	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
21,800 - INSPECT_Parking Brake Operation	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	-	na	TDELVA	Nov 1, 2025 8:09:46 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
31,000 - SSF (Street Side Front)	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
32,000 - Engine Inspection	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	na	TDELVA	Nov 1, 2025 8:09:46 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	TDELVA	Nov 1, 2025 8:09:46 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
32,100 - INSPECT_Intake System	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done	Rear left top turbo leaks	TDELVA	Nov 1, 2025 8:09:46 AM	Yes	57937510
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.89 Volt*		TDELVA	Nov 1, 2025 8:09:46 AM	No	
33,000 - CSF (Curb Side Front)	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	Nov 1, 2025	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:09:46 AM		
33,040 - INSPECT_Wiper Blades, Arms	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
40,700 - CHECK_Passenger Stop Request System	-	na	TDELVA	Nov 1, 2025 8:09:46 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done	needbets	TDELVA	Nov 1, 2025 8:09:46 AM	Yes	57937510
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		TDELVA	Nov 1, 2025 8:09:46 AM	Yes	57937510
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
50,100 - *RPT*INSPECT_Steering components- Drag Link, Tie Rods ends and Steering Damper	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
50,200 - INSPECT_Ball Joint Play	Done	Left ball joint	TDELVA	Nov 1, 2025 8:09:46 AM	Yes	57937510
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
50,400 - LUBE_All Chassis Components	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
50,700 - INSPECT_Tire Condition	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	9 32nds of an inch		TDELVA	Nov 1, 2025 8:09:46 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		TDELVA	Nov 1, 2025 8:09:46 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	9 32nds of an inch		TDELVA	Nov 1, 2025 8:09:46 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		TDELVA	Nov 1, 2025 8:09:46 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done	Front brake	TDELVA	Nov 1, 2025 8:09:46 AM	Yes	57937510
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch		TDELVA	Nov 1, 2025 8:09:46 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch		TDELVA	Nov 1, 2025 8:09:46 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.27 Inch		TDELVA	Nov 1, 2025 8:09:46 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.27 Inch		TDELVA	Nov 1, 2025 8:09:46 AM	No	
52,100 - INSPECT_Vibration Damper	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
53,600 - INSPECT_Tire Condition	Done	Rear Tires	TDELVA	Nov 1, 2025 8:09:46 AM	Yes	57937510
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	-	na	TDELVA	Nov 1, 2025 8:09:46 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	3 32nds of an inch		TDELVA	Nov 1, 2025 8:09:46 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	4 32nds of an inch		TDELVA	Nov 1, 2025 8:09:46 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		TDELVA	Nov 1, 2025 8:09:46 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		TDELVA	Nov 1, 2025 8:09:46 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	5 32nds of an inch		TDELVA	Nov 1, 2025 8:09:46 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	4 32nds of an inch		TDELVA	Nov 1, 2025 8:09:46 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		TDELVA	Nov 1, 2025 8:09:46 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		TDELVA	Nov 1, 2025 8:09:46 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		TDELVA	Nov 1, 2025 8:09:46 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		TDELVA	Nov 1, 2025 8:09:46 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.127 Inch		TDELVA	Nov 1, 2025 8:09:46 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.127 Inch		TDELVA	Nov 1, 2025 8:09:46 AM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
55,800 - CHECK_Double Check Valve - Primary,	Done		TDELVA	Nov 1, 2025	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Secondary				8:09:46 AM		
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		TDELVA	Nov 1, 2025 8:09:46 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57900497
Invoice No. 55345 - 57900497

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	234,359 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMB Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Nov-25	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	3.65	3.65
01-Nov-25	75050	OIL, ENGINE, 5W/30	6	2.71	16.26

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Nov-25	Delva,Terry	0.47	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMB Service
Task: 55345-Medium Duty PMB Inspection Performed by: TDELVA Performed on: 01-NOV-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		TDELVA	Nov 1, 2025 2:36:14 PM	No	
101,000 - FRA Change Oil Filters	Yes		TDELVA	Nov 1, 2025 2:36:14 PM	No	
102,000 - FRA Drain Engine Oil	Yes		TDELVA	Nov 1, 2025 2:36:14 PM	No	
103,000 - FRA Check Transmission Fluid	Done		TDELVA	Nov 1, 2025 2:36:14 PM	No	
104,000 - Lubricate Chassis	Done		TDELVA	Nov 1, 2025 2:36:14 PM	No	
105,000 - Replace or Clean A/C Filters	Done		TDELVA	Nov 1, 2025 2:36:14 PM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	-	na	TDELVA	Nov 1, 2025 2:36:14 PM	No	
107,000 - FRA Change Primary Fuel Filter	No		TDELVA	Nov 1, 2025 2:36:14 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		TDELVA	Nov 1, 2025	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				2:36:14 PM		
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		TDELVA	Nov 1, 2025 2:36:14 PM	No	
201,000 - Service Crankcase Breather	Done		TDELVA	Nov 1, 2025 2:36:14 PM	No	
202,000 - FRA Change Water Separator ¿ Secondary Fuel Filters	No		TDELVA	Nov 1, 2025 2:36:14 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		TDELVA	Nov 1, 2025 2:36:14 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		TDELVA	Nov 1, 2025 2:36:14 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		TDELVA	Nov 1, 2025 2:36:14 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	19.91
Labor:	0.00
Labor Hours:	0.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**19.91**

Work Order Footer

Work Order 57900497 Total	
Parts:	19.91
Labor:	0.00
Labor Hours:	2.14
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**19.91**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 57924115
Invoice No. 55345 - 57924115

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
check engine light		Ford Transit	
Requested By:	VRAMOS	**Status:**	40 - Closed (40)
Created By:	VRAMOS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	233,280 - DH

Chronology		
Reported	Oct 23, 2025 7:05:00 AM	Oct 23, 2025 7:05:00 AM
Started	Oct 23, 2025 8:11:00 AM	
Completed	Oct 23, 2025 11:20:00 AM	Oct 23, 2025 11:20:00 AM
Down Time		

Work Order Notes

Line 10 Got into vehicle check engine light was not on, scanned for codes, no codes present at this time Line 20 Road call driver said brake not working and engine light is on

No engine light on and brake good

Test driving bus over an hour no engine light on no brake problem
Unable to duplicate driver complaint at this time return vehicle back to service

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Check engine light
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Oct-25	Pierre,Hubert J	3.13	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57924115 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57923651
Invoice No. 55345 - 57923651

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
CEL iluminated.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	233,280 - DH

Chronology		
Reported	Oct 22, 2025 10:00:00 PM	Oct 22, 2025 10:00:00 PM
Started	Oct 22, 2025 10:03:00 PM	
Completed	Oct 23, 2025 2:16:00 AM	Oct 23, 2025 2:16:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: CEL illuminated.

Cause: Per driver.

Correction: Found no MIL illuminated. Scanned vehicle for DTCs, none present. However found the module underneath steering column not connected securely, resecured connector.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 23-OCT-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		EARJOHNSON	Oct 23, 2025 2:15:37 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Oct 23, 2025 2:15:37 AM	No	
400 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Oct 23, 2025 2:15:37 AM	No	
700 - Have you performed the proper LOTO?	Done		EARJOHNSON	Oct 23, 2025 2:15:37 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Oct 23, 2025 2:15:37 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Oct 23, 2025 2:15:37 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57923651
Invoice No. 55345 - 57923651

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
CEL iluminated.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	233,280 - DH

Activity Header
Activity: 15 045 POWER PLANT
Activity Note: CEL illuminated.
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Oct-25	Earl Johnson	0.85	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57923651 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57922511
Invoice No. 55345 - 57922511

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Wheelchair Lift		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	233,280 - DH

Chronology		
Reported	Oct 22, 2025 7:28:00 AM	Oct 22, 2025 7:28:00 AM
Started	Oct 22, 2025 7:30:00 AM	
Completed	Oct 22, 2025 12:30:00 PM	Oct 22, 2025 12:30:00 PM
Down Time		

Work Order Notes

Line 10 Lift has no power to lifting heavy weights

Defective pump

Removed and replaced main pump box with good spare part and high pressure hose (right side)

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 22-OCT-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Oct 22, 2025 12:24:19 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Oct 22, 2025 12:24:19 PM	No	
400 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Oct 22, 2025 12:24:19 PM	No	
700 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Oct 22, 2025 12:24:19 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Oct 22, 2025 12:24:19 PM	No	
1,100 - Have you successfully completed the	Done		RAURODRIGUEZ	Oct 22, 2025	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				12:24:19 PM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57922511
Invoice No. 55345 - 57922511

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Wheelchair Lift		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	233,280 - DH

Activity Header
Activity: 20 055/023/000 LIFT, WHEELCHAIR, PASSENGER
Activity Note: WheelChair Lift
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Oct-25	403367A086KS	HOSE, PRESSURE, HIGH, LIFT, W/C	1	83.05	83.05

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Oct-25	Rodriguez,Raul	4.4	0	0
22-Oct-25	Rodriguez,Raul	0.23	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	83.05
Labor:	0.00
Labor Hours:	4.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**83.05**

Work Order Footer

Work Order 57922511 Total	
Parts:	83.05
Labor:	0.00
Labor Hours:	4.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**83.05**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57900452
Invoice No. 55345 - 57900452

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	230,730 - DH

Chronology

Reported	Oct 7, 2025 12:17:47 AM	Oct 7, 2025 12:17:47 AM
Started	Oct 7, 2025 1:16:00 AM	
Completed	Oct 7, 2025 2:22:00 AM	Oct 7, 2025 2:22:00 AM
Down Time		

Work Order Notes

Line 10 Needs rear brakes job and cabin filter dirty
Brakes low specs, needs new filter
Replace rear brake pads and lube guide pins, replace cabin filter
Torque wheels 140 lbs second torque 140 lbs
Brakes #1551-2388-00 qty1
Filter # AF56065 qty1

Activity Header
Activity: 10 001/001 AIR CONDITIONING
Activity Note: needs cabin filter
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Oct-25	AF56065	FILTER, AIR, CABIN SUPERSEDES PA30000	1	9.63	9.63

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Oct-25	Gaspard,Ronald	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	9.63
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**9.63**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57900452
Invoice No. 55345 - 57900452

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	230,730 - DH

Activity Header
Activity:20 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: needs rear brakes job
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Oct-25	1551-2388-00	PADS, BRAKE, REAR	1	47.85	47.85

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Oct-25	Gaspard,Ronald	1.02	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	47.85
Labor:	0.00
Labor Hours:	1.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**47.85**

Work Order Footer

Work Order 57900452 Total	
Parts:	57.48
Labor:	0.00
Labor Hours:	1.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**57.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57872956
Invoice No. 55345 - 57872956

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	VRAMOS	**Status:**	40 - Closed (40)
Created By:	VRAMOS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	230,730 - DH

Chronology		
Reported	Oct 4, 2025 12:00:00 AM	Oct 4, 2025 12:00:00 AM
Started	Oct 6, 2025 11:24:00 PM	
Completed	Oct 7, 2025 1:15:00 AM	Oct 7, 2025 1:15:00 AM
Down Time		

Work Order Notes

Line 10 PMA
Service
Perform PMA service
Oil filter LF17531 qty1
Engine oil 10w30 qty 6 QTs
Add washer fluid

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 06-OCT-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		RGASPARD	Oct 6, 2025 11:24:41 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Oct 6, 2025 11:24:41 PM	No	
400 - Are you wearing the appropriate PPE?	Done		RGASPARD	Oct 6, 2025 11:24:41 PM	No	
700 - Have you performed the proper LOTO?	Done		RGASPARD	Oct 6, 2025 11:24:41 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Oct 6, 2025 11:24:41 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Oct 6, 2025 11:24:41 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57872956
Invoice No. 55345 - 57872956

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	VRAMOS	**Status:**	40 - Closed (40)
Created By:	VRAMOS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	230,730 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Oct-25	Gaspard,Ronald	0.83	0	0
06-Oct-25	Gaspard,Ronald	0.6	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 07-OCT-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
10,800 - CHECK_All Destination Signage	-	NA	RGASPARD	Oct 7, 2025 12:18:09 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
20,200 - CHECK_Public Address System	-	NA	RGASPARD	Oct 7, 2025 12:18:09 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	NA	RGASPARD	Oct 7, 2025 12:18:09 AM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	NA	RGASPARD	Oct 7, 2025 12:18:09 AM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	NA	RGASPARD	Oct 7, 2025 12:18:09 AM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	NA	RGASPARD	Oct 7, 2025 12:18:09 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	NA	RGASPARD	Oct 7, 2025 12:18:09 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	-	NA	RGASPARD	Oct 7, 2025 12:18:09 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
21,500 - INSPECT_High Idle Control	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
21,800 - INSPECT_Parking Brake Operation	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
32,000 - Engine Inspection	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	NA	RGASPARD	Oct 7, 2025 12:18:09 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	RGASPARD	Oct 7, 2025 12:18:09 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
33,000 - CSF (Curb Side Front)	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Oct 7, 2025	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:18:09 AM		
33,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
40,700 - CHECK_Passenger Stop Request System	-	NA	RGASPARD	Oct 7, 2025 12:18:09 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done	needs cabin filter	RGASPARD	Oct 7, 2025 12:18:09 AM	Yes	57900452
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
50,100 - *RPT*INSPECT_Steering components- Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
50,400 - LUBE_All Chassis Components	-	NA	RGASPARD	Oct 7, 2025 12:18:09 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	11 32nds of an inch		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	10 32nds of an inch		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.229 Inch		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.229 Inch		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	4 32nds of an inch	needs rear brakes job	RGASPARD	Oct 7, 2025 12:18:09 AM	Yes	57900452
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	4 32nds of an inch		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.799 Inch		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.799 Inch		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
55,700 - CHECK_Spring Brake Inversion Valve	-	NA	RGASPARD	Oct 7, 2025 12:18:09 AM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	-	NA	RGASPARD	Oct 7, 2025 12:18:09 AM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Oct 7, 2025 12:18:09 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57872956
Invoice No. 55345 - 57872956

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	VRAMOS	**Status:**	40 - Closed (40)
Created By:	VRAMOS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	230,730 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Oct-25	75050	OIL, ENGINE, 5W/30	6	2.71	16.26
07-Oct-25	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	3.64	3.64

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Oct-25	Gaspard,Ronald	0.4	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: RGASPARD Performed on: 07-OCT-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Oct 7, 2025 12:51:54 AM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Oct 7, 2025 12:51:54 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Oct 7, 2025 12:51:54 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Oct 7, 2025 12:51:54 AM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Oct 7, 2025 12:51:54 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Oct 7, 2025 12:51:54 AM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	-	NA	RGASPARD	Oct 7, 2025 12:51:54 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Oct 7, 2025 12:51:54 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Oct 7, 2025	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:51:54 AM		

Activity Sub Total

Activity 20 Sub Total	
Parts:	19.90
Labor:	0.00
Labor Hours:	0.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**19.90**

Work Order Footer

Work Order 57872956 Total	
Parts:	19.90
Labor:	0.00
Labor Hours:	1.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**19.90**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 57882945
Invoice No. 55345 - 57882945

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
service inspection		Ford Transit	
Requested By:	GJUGGERDEO	**Status:**	40 - Closed (40)
Created By:	GJUGGERDEO	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	228,325 - DH

Chronology		
Reported	Sep 23, 2025 10:24:00 AM	Sep 23, 2025 10:24:00 AM
Started	Sep 23, 2025 10:31:00 AM	
Completed	Sep 23, 2025 1:07:00 PM	Sep 23, 2025 1:07:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction: Line 20 Passenger windows making noise when driving

Bad seal

Removed windows and change seals

Activity Header
Activity: 10 050 GROUP, ACCESSORIES
Activity Note: Needs inspection
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Sep-25	Goonashwar Juggerdeo	0.28	0	0
23-Sep-25	Rodriguez,Raul	0.45	0	0
23-Sep-25	Rodriguez,Raul	1.35	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57882945 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 57872946
Invoice No. 55345 - 57872946

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	VRAMOS	**Status:**	40 - Closed (40)
Created By:	VRAMOS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	226,900 - DH

Chronology		
Reported	Sep 15, 2025 5:49:19 PM	Sep 15, 2025 5:49:19 PM
Started	Sep 15, 2025 6:08:00 PM	
Completed	Sep 15, 2025 8:09:00 PM	Sep 15, 2025 8:09:00 PM
Down Time		

Work Order Notes

Line 10 Heater hose connector replaced from part number KH-1142 HOSE Line 20 Driver rear brake light replaced Line 30 Rear ac filter cleaned Line 40 2tires installed in front

Activity Header

Activity: 10 003/001 GAUGES & WARNING DEVICES
Activity Note: driver rear brake light dim
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Sep-25	Victor Ramos	0.3	0	0
15-Sep-25	Victor Ramos	0.07	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 57872946
Invoice No. 55345 - 57872946

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	VRAMOS	**Status:**	40 - Closed (40)
Created By:	VRAMOS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	226,900 - DH

Activity Header
Activity: 20 001/001 AIR CONDITIONING
Activity Note: rear ac filter dirty
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Sep-25	Victor Ramos	0.2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 57872946
Invoice No. 55345 - 57872946

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	VRAMOS	**Status:**	40 - Closed (40)
Created By:	VRAMOS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	226,900 - DH

Activity Header
Activity: 30 017/009 INFLATION & MONITORING, PRESSURE, TIRE
Activity Note: needs 2 new tires
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Sep-25	131196995	TIRE, 195/75R16, WORKHORSE, HTL, WRANGLER, GOODYEAR	2	120.04	240.08

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Sep-25	Victor Ramos	0.85	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	240.08
Labor:	0.00
Labor Hours:	0.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**240.08**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 57872946
Invoice No. 55345 - 57872946

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	VRAMOS	**Status:**	40 - Closed (40)
Created By:	VRAMOS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	226,900 - DH

Activity Header
Activity: 40 999 TOTAL VEHICLE
Activity Note: Heater hose connector needed
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Sep-25	KH-1142	HOSE, HEATER, FORD	1	28.83	28.83

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	28.83
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**28.83**

Work Order Footer

Work Order 57872946 Total	
Parts:	268.91
Labor:	0.00
Labor Hours:	1.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**268.91**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57827460
Invoice No. 55345 - 57827460

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	VRAMOS	**Status:**	40 - Closed (40)
Created By:	VRAMOS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	226,900 - DH

Chronology

Reported	Sep 12, 2025 12:00:00 AM	Sep 12, 2025 12:00:00 AM
Started	Sep 15, 2025 3:16:00 PM	
Completed	Sep 15, 2025 6:03:00 PM	Sep 15, 2025 6:03:00 PM
Down Time		

Work Order Notes

Line 10 Oil and filter changed, PMA service performed

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: VRAMOS Performed on: 15-SEP-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		VRAMOS	Sep 15, 2025 3:16:39 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VRAMOS	Sep 15, 2025 3:16:39 PM	No	
400 - Are you wearing the appropriate PPE?	Done		VRAMOS	Sep 15, 2025 3:16:39 PM	No	
700 - Have you performed the proper LOTO?	Done		VRAMOS	Sep 15, 2025 3:16:39 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		VRAMOS	Sep 15, 2025 3:16:39 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		VRAMOS	Sep 15, 2025 3:16:39 PM	No	

Activity Sub Total

Activity 5 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57827460
Invoice No. 55345 - 57827460

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	VRAMOS	**Status:**	40 - Closed (40)
Created By:	VRAMOS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	226,900 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Sep-25	EJ7Z-6730-B	PLUG, DRAIN, OIL, FORD	1	4.6	4.6

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Sep-25	Victor Ramos	2.57	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: VRAMOS Performed on: 15-SEP-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done	driver rear brake light dim	VRAMOS	Sep 15, 2025 5:49:35 PM	Yes	57872946
10,400 - !FRA!INSPECT_Back Up Alarm	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
10,800 - CHECK_All Destination Signage	Done		VRAMOS	Sep 15, 2025	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				5:49:35 PM		
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
20,200 - CHECK_Public Address System	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	na	VRAMOS	Sep 15, 2025 5:49:35 PM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	na	VRAMOS	Sep 15, 2025 5:49:35 PM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	na	VRAMOS	Sep 15, 2025 5:49:35 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	na	VRAMOS	Sep 15, 2025 5:49:35 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	na	VRAMOS	Sep 15, 2025 5:49:35 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	-	na	VRAMOS	Sep 15, 2025 5:49:35 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
21,500 - INSPECT_High Idle Control	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
31,000 - SSF (Street Side Front)	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
32,000 - Engine Inspection	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	VRAMOS	Sep 15, 2025 5:49:35 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
32,100 - INSPECT_Intake System	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.6 Volt*		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
33,000 - CSF (Curb Side Front)	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks,	Done		VRAMOS	Sep 15, 2025	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Spring Shackles				5:49:35 PM		
33,030 - INSPECT_Mud Flaps, Brackets	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
40,700 - CHECK_Passenger Stop Request System	-	na	VRAMOS	Sep 15, 2025 5:49:35 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done	rear ac filter dirty	VRAMOS	Sep 15, 2025 5:49:35 PM	Yes	57872946
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
50,400 - LUBE_All Chassis Components	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,700 - INSPECT_Tire Condition	Done	needs 2 new tires	VRAMOS	Sep 15, 2025 5:49:35 PM	Yes	57872946
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	30 Inch		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	30 Inch		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
52,100 - INSPECT_Vibration Damper	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
53,600 - INSPECT_Tire Condition	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	6 32nds of an inch		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	4 32nds of an inch		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	4 32nds of an inch		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	30 Inch		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	30 Inch		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		VRAMOS	Sep 15, 2025 5:49:35 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	4.60
Labor:	0.00
Labor Hours:	2.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.60**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57827460
Invoice No. 55345 - 57827460

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	VRAMOS	**Status:**	40 - Closed (40)
Created By:	VRAMOS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	226,900 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Sep-25	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	3.64	3.64
15-Sep-25	75050	OIL, ENGINE, 5W/30	6	2.71	16.26

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: VRAMOS Performed on: 15-SEP-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		VRAMOS	Sep 15, 2025 5:52:51 PM	No	
101,000 - FRA Change Oil Filters	Yes		VRAMOS	Sep 15, 2025 5:52:51 PM	No	
102,000 - FRA Drain Engine Oil	Yes		VRAMOS	Sep 15, 2025 5:52:51 PM	No	
103,000 - FRA Check Transmission Fluid	Done		VRAMOS	Sep 15, 2025 5:52:51 PM	No	
104,000 - Lubricate Chassis	Done		VRAMOS	Sep 15, 2025 5:52:51 PM	No	
105,000 - Replace or Clean A/C Filters	Done		VRAMOS	Sep 15, 2025 5:52:51 PM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	Done		VRAMOS	Sep 15, 2025 5:52:51 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		VRAMOS	Sep 15, 2025 5:52:51 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		VRAMOS	Sep 15, 2025 5:52:51 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	19.90
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**19.90**

Work Order Footer

Work Order 57827460 Total	
Parts:	24.50
Labor:	0.00
Labor Hours:	2.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**24.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57860523
Invoice No. 55345 - 57860523

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
front right tire low air in the yard		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	225,505 - DH

Chronology		
Reported	Sep 6, 2025 1:21:00 AM	Sep 6, 2025 1:21:00 AM
Started	Sep 6, 2025 1:26:00 AM	
Completed	Sep 6, 2025 2:01:00 AM	Sep 6, 2025 2:01:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction:

Line 20 Right front tire flat in the yard (Kelly)
Puncture
Fixed right front tire and inflate tire to specs .i used the shop truck.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 06-SEP-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		RGASPARD	Sep 6, 2025 1:26:23 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Sep 6, 2025 1:26:23 AM	No	
400 - Are you wearing the appropriate PPE?	Done		RGASPARD	Sep 6, 2025 1:26:23 AM	No	
700 - Have you performed the proper LOTO?	Done		RGASPARD	Sep 6, 2025 1:26:23 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Sep 6, 2025 1:26:23 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Sep 6, 2025 1:26:23 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57860523
Invoice No. 55345 - 57860523

Client Department:
Department: 55345M
Work Order Description
front right tire low air in the yard
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 225,505 - DH

Activity Header
Activity: 15 017 TIRES, TUBES, LINERS & VALVES
Activity Note: Front right tire very low air in the yard
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Sep-25	Gaspard,Ronald	0.57	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57860523 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57853832
Invoice No. 55345 - 57853832

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Complain wheel chair lift not working		Ford Transit	
Requested By:	GJUGGERDEO	**Status:**	40 - Closed (40)
Created By:	GJUGGERDEO	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	224,868 - DH

Chronology		
Reported	Sep 1, 2025 7:35:00 AM	Sep 1, 2025 7:35:00 AM
Started	Sep 1, 2025 7:40:00 AM	
Completed	Sep 1, 2025 8:14:00 AM	Sep 1, 2025 8:14:00 AM
Down Time		

Work Order Notes

Line 10 Check out and operate the lift found no issues working fine

Activity Header

Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: GJUGGERDEO Performed on: 01-SEP-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		GJUGGERDEO	Sep 1, 2025 9:53:22 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		GJUGGERDEO	Sep 1, 2025 9:53:22 AM	No	
400 - Are you wearing the appropriate PPE?	Done		GJUGGERDEO	Sep 1, 2025 9:53:22 AM	No	
700 - Have you performed the proper LOTO?	Done		GJUGGERDEO	Sep 1, 2025 9:53:22 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		GJUGGERDEO	Sep 1, 2025 9:53:22 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		GJUGGERDEO	Sep 1, 2025 9:53:22 AM	No	

Activity Sub Total

Activity 5 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57853832
Invoice No. 55345 - 57853832

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Complain wheel chair lift not working		Ford Transit	
Requested By:	GJUGGERDEO	**Status:**	40 - Closed (40)
Created By:	GJUGGERDEO	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	224,868 - DH

Activity Header
Activity: 10 050 GROUP, ACCESSORIES
Activity Note: Needs to inspect
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Sep-25	Goonashwar Juggerdeo	0.55	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57853832 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57849838
Invoice No. 55345 - 57849838

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Rear A/C Flashing H/A		Ford Transit	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	224,382 - DH

Chronology		
Reported	Aug 28, 2025 8:21:00 AM	Aug 28, 2025 8:21:00 AM
Started	Aug 28, 2025 8:26:00 AM	
Completed	Aug 28, 2025 1:53:00 PM	Aug 28, 2025 1:53:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction: Line 20 Check Rear A/C Found high Side hose Leaking Evacuate System. to Replace Rear dryer. Replace high pressure hose & Service Port. add (5.0) Oz Oil & Charge (6.00) Lbs Freon.
Parts # 1412015 Qty (1)

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 28-AUG-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		DARTHURS	Aug 28, 2025	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:25:55 AM		
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Aug 28, 2025 8:25:55 AM	No	
400 - Are you wearing the appropriate PPE?	Done		DARTHURS	Aug 28, 2025 8:25:55 AM	No	
700 - Have you performed the proper LOTO?	Done		DARTHURS	Aug 28, 2025 8:25:55 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Aug 28, 2025 8:25:55 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Aug 28, 2025 8:25:55 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57849838
Invoice No. 55345 - 57849838

Client Department:
Department: 55345M
Work Order Description
Rear A/C Flashing H/A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 224,382 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear A/C Flashing H/A
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Aug-25	1412015	ACCUMULATOR, A/C	1	15.14	15.14

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Aug-25	Arthurs,Durvin	5.45	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	15.14
Labor:	0.00
Labor Hours:	5.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**15.14**

Work Order Footer

Work Order 57849838 Total	
Parts:	15.14
Labor:	0.00
Labor Hours:	5.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**15.14**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57837992
Invoice No. 55345 - 57837992

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Rear AC malfunction		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	223,953 - DH

Chronology		
Reported	Aug 19, 2025 11:12:00 PM	Aug 19, 2025 11:12:00 PM
Started	Aug 19, 2025 11:14:00 PM	
Completed	Aug 22, 2025 1:59:00 PM	Aug 22, 2025 1:59:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear AC malfunction.

Cause: Compressor cycling (HA) (LC).

Correction: Vehicle OOS to be transported to shop for repairs. Line 20 REAR AC MALFUNCTION REPAIRED, PLEASE SEE WORK ORDER 57840910

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 20-AUG-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		EARJOHNSON	Aug 20, 2025 1:56:51 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Aug 20, 2025 1:56:51 AM	No	
400 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Aug 20, 2025 1:56:51 AM	No	
700 - Have you performed the proper LOTO?	Done		EARJOHNSON	Aug 20, 2025 1:56:51 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Aug 20, 2025 1:56:51 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Aug 20, 2025 1:56:51 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57837992
Invoice No. 55345 - 57837992

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Rear AC malfunction		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	223,953 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear AC malfunction.
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Aug-25	Earl Johnson	0.77	0	0
20-Aug-25	Earl Johnson	1.47	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.24
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57837992 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.24
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57840910
Invoice No. 55345 - 57840910

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Rear AC "HA"		Ford Transit	
Requested By:	VRAMOS	**Status:**	40 - Closed (40)
Created By:	VRAMOS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	224,119 - DH

Chronology		
Reported	Aug 21, 2025 4:44:00 PM	Aug 21, 2025 4:44:00 PM
Started	Aug 21, 2025 4:48:00 PM	
Completed	Aug 22, 2025 1:35:00 PM	Aug 22, 2025 1:35:00 PM
Down Time		

Work Order Notes

Line 10 Found leak in high side hose, replaced hose Line 20 Low side port leaking from valve due to rusting, replaced low side valves with new clamps Line 30 Instead new fuel door to unit

Activity Header

Activity: 10 000 CAB, CLIMATE CONTROL, INSTRUMENTS & AERODYNAMIC DEVICES
Activity Note: Rear ac blowing hot
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Aug-25	Victor Ramos	3.98	0	0
22-Aug-25	Victor Ramos	1.38	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	5.36
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57840910
Invoice No. 55345 - 57840910

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Rear AC "HA"		Ford Transit	
Requested By:	VRAMOS	**Status:**	40 - Closed (40)
Created By:	VRAMOS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	224,119 - DH

Activity Header
Activity: 20 002 CAB & SHEET METAL
Activity Note: fuel door broke
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Aug-25	CK4Z-5427936-J	HOUSING, DOOR, FILLER, FUEL	1	52.24	52.24

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Aug-25	Junior Hurst	0.1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	52.24
Labor:	0.00
Labor Hours:	0.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**52.24**

Work Order Footer

Work Order 57840910 Total	
Parts:	52.24
Labor:	0.00
Labor Hours:	5.46
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**52.24**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57827432
Invoice No. 55345 - 57827432

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	VRAMOS	**Status:**	40 - Closed (40)
Created By:	VRAMOS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	222,917 - DH

Chronology		
Reported	Aug 12, 2025 1:17:58 PM	Aug 12, 2025 1:17:58 PM
Started	Aug 12, 2025 1:40:00 PM	
Completed	Aug 12, 2025 2:21:00 PM	Aug 12, 2025 2:21:00 PM
Down Time		

Work Order Notes

Line 10 Top left corner and top right marker lights replaced Line 20 Rear ac filter cleaned

Activity Header
Activity: 10 001/001 AIR CONDITIONING
Activity Note: rear ac filter dirty
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Aug-25	Victor Ramos	0.1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57827432
Invoice No. 55345 - 57827432

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	VRAMOS	**Status:**	40 - Closed (40)
Created By:	VRAMOS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	222,917 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: Top front marker lights out
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Aug-25	MCL12AK	LAMP, MARKER/CLEARANCE, LED, AMBER	2	9.91	19.82

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Aug-25	Victor Ramos	0.55	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	19.82
Labor:	0.00
Labor Hours:	0.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**19.82**

Work Order Footer

Work Order 57827432 Total	
Parts:	19.82
Labor:	0.00
Labor Hours:	0.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**19.82**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57790460
Invoice No. 55345 - 57790460

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	222,917 - DH

Chronology		
Reported	Aug 11, 2025 12:00:00 AM	Aug 11, 2025 12:00:00 AM
Started	Aug 12, 2025 12:10:00 PM	
Completed	Aug 12, 2025 1:38:00 PM	Aug 12, 2025 1:38:00 PM
Down Time		

Work Order Notes

Line 10 Oil and filter changed, PMB service performed

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: VRAMOS Performed on: 12-AUG-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		VRAMOS	Aug 12, 2025 12:10:35 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VRAMOS	Aug 12, 2025 12:10:35 PM	No	
400 - Are you wearing the appropriate PPE?	Done		VRAMOS	Aug 12, 2025 12:10:35 PM	No	
700 - Have you performed the proper LOTO?	Done		VRAMOS	Aug 12, 2025 12:10:35 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		VRAMOS	Aug 12, 2025 12:10:35 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		VRAMOS	Aug 12, 2025 12:10:35 PM	No	

Activity Sub Total

Activity 5 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57790460
Invoice No. 55345 - 57790460

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	222,917 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Aug-25	Victor Ramos	1.4	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: VRAMOS Performed on: 12-AUG-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
10,800 - CHECK_All Destination Signage	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
10,900 - *RPT*INSPECT_Body Damage,	Done		VRAMOS	Aug 12, 2025	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Corrosion;DOCUMENT_Issues				1:18:14 PM		
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
20,200 - CHECK_Public Address System	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	na	VRAMOS	Aug 12, 2025 1:18:14 PM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	na	VRAMOS	Aug 12, 2025 1:18:14 PM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	na	VRAMOS	Aug 12, 2025 1:18:14 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	na	VRAMOS	Aug 12, 2025 1:18:14 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	na	VRAMOS	Aug 12, 2025 1:18:14 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	-	na	VRAMOS	Aug 12, 2025 1:18:14 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
21,500 - INSPECT_High Idle Control	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
31,000 - SSF (Street Side Front)	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
32,000 - Engine Inspection	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	VRAMOS	Aug 12, 2025 1:18:14 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
32,100 - INSPECT_Intake System	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.6 Volt*		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
33,000 - CSF (Curb Side Front)	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		VRAMOS	Aug 12, 2025	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				1:18:14 PM		
33,040 - INSPECT_Wiper Blades, Arms	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
40,700 - CHECK_Passenger Stop Request System	-	na	VRAMOS	Aug 12, 2025 1:18:14 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done	rear ac filter dirty	VRAMOS	Aug 12, 2025 1:18:14 PM	Yes	57827432
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
50,400 - LUBE_All Chassis Components	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
50,700 - INSPECT_Tire Condition	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	30 Inch		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	30 Inch		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
52,100 - INSPECT_Vibration Damper	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,600 - INSPECT_Tire Condition	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	5 32nds of an inch		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	6 32nds of an inch		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	5 32nds of an inch		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	30 Inch		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	30 Inch		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,000 - SECTION 8 - PMI Report Completion	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		VRAMOS	Aug 12, 2025 1:18:14 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57790460
Invoice No. 55345 - 57790460

Client Department:
Department: 55345M
Work Order Description
55345-MEDIUM DUTY PMB
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 222,917 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMB Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Aug-25	75050	OIL, ENGINE, 5W/30	6	2.71	16.26
12-Aug-25	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	3.62	3.62
26-Aug-25	H11BP	BULB, HEADLAMP	1	5.18	5.18

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMB Service
Task: 55345-Medium Duty PMB Inspection Performed by: VRAMOS Performed on: 12-AUG-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		VRAMOS	Aug 12, 2025 1:38:04 PM	No	
101,000 - FRA Change Oil Filters	Yes		VRAMOS	Aug 12, 2025 1:38:04 PM	No	
102,000 - FRA Drain Engine Oil	Yes		VRAMOS	Aug 12, 2025 1:38:04 PM	No	
103,000 - FRA Check Transmission Fluid	Done		VRAMOS	Aug 12, 2025 1:38:04 PM	No	
104,000 - Lubricate Chassis	Done		VRAMOS	Aug 12, 2025 1:38:04 PM	No	
105,000 - Replace or Clean A/C Filters	Done		VRAMOS	Aug 12, 2025 1:38:04 PM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	Done		VRAMOS	Aug 12, 2025 1:38:04 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		VRAMOS	Aug 12, 2025 1:38:04 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		VRAMOS	Aug 12, 2025	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				1:38:04 PM		
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		VRAMOS	Aug 12, 2025 1:38:04 PM	No	
201,000 - Service Crankcase Breather	Done		VRAMOS	Aug 12, 2025 1:38:04 PM	No	
202,000 - FRA Change Water Separator ¿ Secondary Fuel Filters	Yes		VRAMOS	Aug 12, 2025 1:38:04 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		VRAMOS	Aug 12, 2025 1:38:04 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	Yes		VRAMOS	Aug 12, 2025 1:38:04 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		VRAMOS	Aug 12, 2025 1:38:04 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	25.06
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**25.06**

Work Order Footer

Work Order 57790460 Total	
Parts:	25.06
Labor:	0.00
Labor Hours:	1.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**25.06**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57759681
Invoice No. 55345 - 57759681

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	219,026 - DH

Chronology		
Reported	Jul 14, 2025 12:00:00 AM	Jul 14, 2025 12:00:00 AM
Started	Jul 14, 2025 2:13:00 PM	
Completed	Jul 14, 2025 5:20:00 PM	Jul 14, 2025 5:20:00 PM
Down Time		

Work Order Notes

Line 10 Vehicle came in for service due by mileage Also oil filter part LF17531 and wash rear AC filter after return unit back to service

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 14-JUL-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		JUHURST	Jul 14, 2025 5:20:30 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Jul 14, 2025 5:20:30 PM	No	
400 - Are you wearing the appropriate PPE?	Done		JUHURST	Jul 14, 2025 5:20:30 PM	No	
700 - Have you performed the proper LOTO?	Done		JUHURST	Jul 14, 2025 5:20:30 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Jul 14, 2025 5:20:30 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Jul 14, 2025 5:20:30 PM	No	

Activity Sub Total

Activity 5 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57759681
Invoice No. 55345 - 57759681

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	219,026 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Jul-25	Junior Hurst	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: JUHURST Performed on: 14-JUL-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
10,800 - CHECK_All Destination Signage	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
20,200 - CHECK_Public Address System	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	80 Second*		JUHURST	Jul 14, 2025 5:19:47 PM	No	
20,700 - RECORD_Brake Performance Test Speed	30 Miles per Hour		JUHURST	Jul 14, 2025 5:19:47 PM	No	
20,800 - RECORD_Brake Performance Test Distance	50 FEET		JUHURST	Jul 14, 2025 5:19:47 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	50 FEET		JUHURST	Jul 14, 2025 5:19:47 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	80 Gravitational Force		JUHURST	Jul 14, 2025 5:19:47 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
21,500 - INSPECT_High Idle Control	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
32,000 - Engine Inspection	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	20 Degree Fahrenheit		JUHURST	Jul 14, 2025 5:19:47 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Jul 14, 2025 5:19:47 PM	No	
33,000 - CSF (Curb Side Front)	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
40,700 - CHECK_Passenger Stop Request System	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
50,400 - LUBE_All Chassis Components	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
50,700 - INSPECT_Tire Condition	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,000 - RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Jul 14, 2025 5:19:47 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Jul 14, 2025 5:19:47 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Jul 14, 2025 5:19:47 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Jul 14, 2025 5:19:47 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Jul 14, 2025 5:19:47 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Jul 14, 2025 5:19:47 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.3 Inch		JUHURST	Jul 14, 2025 5:19:47 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.3 Inch		JUHURST	Jul 14, 2025 5:19:47 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Jul 14, 2025 5:19:47 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Jul 14, 2025 5:19:47 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Jul 14, 2025 5:19:47 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Jul 14, 2025 5:19:47 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Jul 14, 2025 5:19:47 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Jul 14, 2025 5:19:47 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Jul 14, 2025 5:19:47 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Jul 14, 2025 5:19:47 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Jul 14, 2025 5:19:47 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Jul 14, 2025 5:19:47 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.5 Inch		JUHURST	Jul 14, 2025 5:19:47 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.5 Inch		JUHURST	Jul 14, 2025 5:19:47 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	Jul 14, 2025 5:19:47 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57759681
Invoice No. 55345 - 57759681

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	219,026 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Jul-25	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	3.48	3.48
14-Jul-25	75050	OIL, ENGINE, 5W/30	6	2.71	16.26

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Jul-25	Junior Hurst	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: JUHURST Performed on: 14-JUL-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		JUHURST	Jul 14, 2025 5:14:22 PM	No	
101,000 - FRA Change Oil Filters	Yes		JUHURST	Jul 14, 2025 5:14:22 PM	No	
102,000 - FRA Drain Engine Oil	Yes		JUHURST	Jul 14, 2025 5:14:22 PM	No	
103,000 - FRA Check Transmission Fluid	Done		JUHURST	Jul 14, 2025 5:14:22 PM	No	
104,000 - Lubricate Chassis	Done		JUHURST	Jul 14, 2025 5:14:22 PM	No	
105,000 - Replace or Clean A/C Filters	Done		JUHURST	Jul 14, 2025 5:14:22 PM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	Done		JUHURST	Jul 14, 2025 5:14:22 PM	No	
107,000 - FRA Change Primary Fuel Filter	No		JUHURST	Jul 14, 2025 5:14:22 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		JUHURST	Jul 14, 2025	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				5:14:22 PM		

Activity Sub Total

Activity 20 Sub Total	
Parts:	19.74
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**19.74**

Work Order Footer

Work Order 57759681 Total	
Parts:	19.74
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**19.74**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 57781864
Invoice No. 55345 - 57781864

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
replace left side strut		Ford Transit	
Requested By:	VRAMOS	**Status:**	40 - Closed (40)
Created By:	VRAMOS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	217,769 - DH

Chronology		
Reported	Jul 7, 2025 1:47:00 PM	Jul 7, 2025 1:47:00 PM
Started	Jul 7, 2025 1:51:00 PM	
Completed	Jul 7, 2025 2:17:00 PM	Jul 7, 2025 2:17:00 PM
Down Time		

Work Order Notes

Line 10 Left side lift strut replaced

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Replaced left side strut
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Jul-25	32831	SPRING, SHOCK, GAS, W/C	1	29.3	29.3

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Jul-25	Victor Ramos	0.4	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	29.30
Labor:	0.00
Labor Hours:	0.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**29.30**

Work Order Footer

Work Order 57781864 Total	
Parts:	29.30
Labor:	0.00
Labor Hours:	0.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**29.30**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57448636
Invoice No. 55345 - 57448636

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FIRST TRANSIT AC INSPECTION		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	217,769 -

Chronology		
Reported	Jul 7, 2025 8:35:31 AM	Jul 7, 2025 8:35:31 AM
Started	Jul 7, 2025 12:05:00 PM	
Completed	Jul 7, 2025 1:37:00 PM	Jul 7, 2025 1:37:00 PM
Down Time		

Work Order Notes

Line 10 Ac inspection complete everything in working order, no leaks

Activity Header

Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assesment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assesment
Task: PRA and Meter Readings Performed by: VRAMOS Performed on: 07-JUL-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		VRAMOS	Jul 7, 2025 12:05:17 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VRAMOS	Jul 7, 2025 12:05:17 PM	No	
400 - Are you wearing the appropriate PPE?	Done		VRAMOS	Jul 7, 2025 12:05:17 PM	No	
700 - Have you performed the proper LOTO?	Done		VRAMOS	Jul 7, 2025 12:05:17 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		VRAMOS	Jul 7, 2025 12:05:17 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		VRAMOS	Jul 7, 2025 12:05:17 PM	No	

Activity Sub Total

Activity 5 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57448636
Invoice No. 55345 - 57448636

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FIRST TRANSIT AC INSPECTION		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	217,769 -

Activity Header
Activity: 10 001/001/001 AIR CONDITIONING
Activity Note: FIRST TRANSIT AC INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Jul-25	Victor Ramos	1.37	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: FIRST TRANSIT AC INSPECTION
Task: FIRST TRANSIT AC INSPECTION Performed by: VRAMOS Performed on: 07-JUL-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 VISUAL INSPECTION	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
10,100 - CHECK PHYSICAL DAMAGE, MISSING PARTS	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
10,200 - CHECK REFRIGERANT HOSES FOR CHAFING	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
10,300 - CHECK EVAPORATOR AND CONDENSER FOR OBSTRUCTIONS	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
10,400 - CHECK OPERATION OF FAST IDLE	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
20,000 - SECTION 2 DIAGNOSE THE SYSTEM CONDITION	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
20,100 - ATTACH GAUGES AND RUN SYSTEM 10 MINUTES	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
20,200 - CHECK FOR EVEN AIR DISTRIBUTION	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
20,300 - CHECK FOR PROPER OPERATION OF ALL HVAC MODES	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
20,400 - CHECK DRIVERS A/C SYSTEM	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,500 - RECORD AMBIENT TEMPERATURE BEFORE	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
20,600 - RECORD DISCHARGE PRESSURE BEFORE	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
20,700 - RECORD SUCTION PRESSURE BEFORE	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
20,710 - RECORD OUTLET TEMPERATURE BEFORE	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
20,800 - CHECK HIGH AND LOW PRESSURE CUTOUT SWITCHES FOR LEAKS	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
30,000 - SECTION 3 COMPRESSOR OPERATIONAL INSPCTION	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
30,100 - CHECK FOR UNUSUAL NOISES	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
30,200 - CHECK CLUTCH RESISTANCE READING	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
30,300 - CHECK AIR GAP IN COMPRESSOR CLUTCH	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
30,400 - CHECK COMPRESSOR MOUNTING AND ALIGHMENT	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
30,500 - INSPECT COMPRESSOR BELT(S) OR DRIVE SYSTEM	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
30,600 - CHECK FOR CRACKS AND WEAR	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
30,700 - CHECK FOR PROPER WIDTH AND LENGTH	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
30,800 - CHECK FOR PROPER ALIGNMENT	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
40,000 - SECTION 4 LEAK TEST SYSTEM	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
40,100 - CHICK A/C LINES WITH AN ELECTRONIC LEAK DETECTOR	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
40,200 - CHECK HOSES, FITTINGS, VALVES AND COMPRESSOR SHAFT SEAL	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
40,300 - CHECK HEATER HOSES FOR LEAKS	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
50,000 - SECTION 5 SYSTEM CONTAMINATION	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
50,100 - CHECK INLINE DRIER	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
50,200 - CHECK ACCUMULATOR	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
60,000 - SECTION 6 CHARGE SYSTEM	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
60,100 - IF CHARGING IS REQUIRED, CHARGE BY WEIGHT	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
60,200 - CHECK FOR LEAKS AFTER CHARGING	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
70,000 - SECTION 7 FAN MOTORS	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
70,100 - CHECK SEALED MOTORS FOR PROPER OPERATION	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,200 - INSPECT BLOWER WHEELS	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
70,300 - CHECK ELECTRICAL WIRING & CONNECTIONS	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
80,000 - SECTION 8 OPERATE SYSTEM	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
80,100 - CHECK FOR PROPER HEATING & COOLING	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
80,200 - CHECK TEMPERATURE CONTROLS	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
80,300 - CHECK DEFROST MODE	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
90,000 - SECTION 9 PERFORMANCE TEST READINGS	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
90,100 - RECORD AMBIENT TEMPERATURE READINGS AFTER	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
90,200 - RECORD DISCHARGE PRESSURE AFTER	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
90,300 - RECORD SUCTION PRESSURE AFTER	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
90,400 - RECORD OUTLET TEMPERATURE	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
100,000 - SECTION 10 RESTORE SYSTEM	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
100,100 - DISCONNECT GAUGES	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	
100,200 - CLOSE ALL PANELS, DOOR, ETC.	Done		VRAMOS	Jul 7, 2025 1:37:14 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57448636 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 57759619
Invoice No. 55345 - 57759619

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	215,105 - DH

Chronology		
Reported	Jun 18, 2025 9:52:29 AM	Jun 18, 2025 9:52:29 AM
Started	Jun 18, 2025 9:53:00 AM	
Completed	Jun 18, 2025 12:33:00 PM	Jun 18, 2025 12:33:00 PM
Down Time		

Work Order Notes

Line 10 Replaced right front ball joint
Rotate front left tire with rear left inner tire
Torques left rear wheel nut and both front wheels nuts

Activity Header
Activity: 10 174/001/001 BODY, BUS, COMPLETE
Activity Note: Body Damage
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 57759619
Invoice No. 55345 - 57759619

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	215,105 - DH

Activity Header
Activity: 20 015/000 STEERING
Activity Note: vehicle pulled right
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 57759619
Invoice No. 55345 - 57759619

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	215,105 - DH

Activity Header
Activity: 30 016/001/006 SHAFT, ARM, CONTROL, LOWER
Activity Note: Right ball joint play
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Jun-25	KK3Z-3050-B	JOINT, BALL, LOWER	1	88.86	88.86

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Jun-25	Delva,Terry	2.67	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	88.86
Labor:	0.00
Labor Hours:	2.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**88.86**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 57759619
Invoice No. 55345 - 57759619

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	215,105 - DH

Activity Header
Activity: 40 017/009 INFLATION & MONITORING, PRESSURE, TIRE
Activity Note: Front tire
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57759619 Total	
Parts:	88.86
Labor:	0.00
Labor Hours:	2.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**88.86**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57723996
Invoice No. 55345 - 57723996

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	215,105 - DH

Chronology		
Reported	Jun 18, 2025 7:54:31 AM	Jun 18, 2025 7:54:31 AM
Started	Jun 18, 2025 7:56:00 AM	
Completed	Jun 18, 2025 10:23:00 AM	Jun 18, 2025 10:23:00 AM
Down Time		

Work Order Notes

Line 10 PMA

Service due

Performed and completed PMA

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 18-JUN-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		TDELVA	Jun 18, 2025 7:56:48 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jun 18, 2025 7:56:48 AM	No	
400 - Are you wearing the appropriate PPE?	Done		TDELVA	Jun 18, 2025 7:56:48 AM	No	
700 - Have you performed the proper LOTO?	Done		TDELVA	Jun 18, 2025 7:56:48 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jun 18, 2025 7:56:48 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jun 18, 2025 7:56:48 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57723996
Invoice No. 55345 - 57723996

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	215,105 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Jun-25	PA10093	FILTER, AIR, PANEL SEE AF4283	1	11.77	11.77

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Jun-25	Delva,Terry	1.93	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: TDELVA Performed on: 18-JUN-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
10,800 - CHECK_All Destination Signage	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done	Body Damage	TDELVA	Jun 18, 2025 9:50:27 AM	Yes	57759619
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
20,200 - CHECK_Public Address System	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	-	na	TDELVA	Jun 18, 2025 9:50:27 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	na	TDELVA	Jun 18, 2025 9:50:27 AM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	na	TDELVA	Jun 18, 2025 9:50:27 AM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	na	TDELVA	Jun 18, 2025 9:50:27 AM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	na	TDELVA	Jun 18, 2025 9:50:27 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	na	TDELVA	Jun 18, 2025 9:50:27 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	-	na	TDELVA	Jun 18, 2025 9:50:27 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
21,500 - INSPECT_High Idle Control	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
21,800 - INSPECT_Parking Brake Operation	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	-	na	TDELVA	Jun 18, 2025 9:50:27 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
31,000 - SSF (Street Side Front)	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
32,000 - Engine Inspection	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	na	TDELVA	Jun 18, 2025 9:50:27 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	TDELVA	Jun 18, 2025 9:50:27 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
32,100 - INSPECT_Intake System	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.89 Volt*		TDELVA	Jun 18, 2025 9:50:27 AM	No	
33,000 - CSF (Curb Side Front)	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
33,040 - INSPECT_Wiper Blades, Arms	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
40,700 - CHECK_Passenger Stop Request System	-	na	TDELVA	Jun 18, 2025 9:50:27 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done	vehicle pulled right	TDELVA	Jun 18, 2025 9:50:27 AM	Yes	57759619
50,200 - INSPECT_Ball Joint Play	Done	Right ball joint play	TDELVA	Jun 18, 2025 9:50:27 AM	Yes	57759619
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
50,400 - LUBE_All Chassis Components	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
50,700 - INSPECT_Tire Condition	Done	Front tire	TDELVA	Jun 18, 2025 9:50:27 AM	Yes	57759619
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		TDELVA	Jun 18, 2025 9:50:27 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	64 Pounds per Square Inch		TDELVA	Jun 18, 2025 9:50:27 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		TDELVA	Jun 18, 2025 9:50:27 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	64 Pounds per Square Inch		TDELVA	Jun 18, 2025 9:50:27 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	Jun 18, 2025 9:50:27 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	Jun 18, 2025 9:50:27 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.27 Inch		TDELVA	Jun 18, 2025 9:50:27 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.27 Inch		TDELVA	Jun 18, 2025 9:50:27 AM	No	
52,100 - INSPECT_Vibration Damper	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
53,600 - INSPECT_Tire Condition	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	-	na	TDELVA	Jun 18, 2025 9:50:27 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		TDELVA	Jun 18, 2025 9:50:27 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		TDELVA	Jun 18, 2025 9:50:27 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	64 Pounds per Square Inch		TDELVA	Jun 18, 2025 9:50:27 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	64 Pounds per Square Inch		TDELVA	Jun 18, 2025 9:50:27 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		TDELVA	Jun 18, 2025 9:50:27 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		TDELVA	Jun 18, 2025 9:50:27 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	64 Pounds per Square Inch		TDELVA	Jun 18, 2025 9:50:27 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	64 Pounds per Square Inch		TDELVA	Jun 18, 2025 9:50:27 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		TDELVA	Jun 18, 2025 9:50:27 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		TDELVA	Jun 18, 2025 9:50:27 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.127 Inch		TDELVA	Jun 18, 2025 9:50:27 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.127 Inch		TDELVA	Jun 18, 2025 9:50:27 AM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,100 - COMPLETE_PM Report; Follow-ups	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		TDELVA	Jun 18, 2025 9:50:27 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	11.77
Labor:	0.00
Labor Hours:	1.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**11.77**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57723996
Invoice No. 55345 - 57723996

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	215,105 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Jun-25	75050	OIL, ENGINE, 5W/30	6	2.71	16.26
18-Jun-25	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	3.48	3.48

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Jun-25	Delva,Terry	0.02	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: TDELVA Performed on: 18-JUN-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		TDELVA	Jun 18, 2025 9:51:53 AM	No	
101,000 - FRA Change Oil Filters	Yes		TDELVA	Jun 18, 2025 9:51:53 AM	No	
102,000 - FRA Drain Engine Oil	Yes		TDELVA	Jun 18, 2025 9:51:53 AM	No	
103,000 - FRA Check Transmission Fluid	Done		TDELVA	Jun 18, 2025 9:51:53 AM	No	
104,000 - Lubricate Chassis	Done		TDELVA	Jun 18, 2025 9:51:53 AM	No	
105,000 - Replace or Clean A/C Filters	Done		TDELVA	Jun 18, 2025 9:51:53 AM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	-	na	TDELVA	Jun 18, 2025 9:51:53 AM	No	
107,000 - FRA Change Primary Fuel Filter	No		TDELVA	Jun 18, 2025 9:51:53 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		TDELVA	Jun 18, 2025	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:51:53 AM		

Activity Sub Total

Activity 20 Sub Total	
Parts:	19.74
Labor:	0.00
Labor Hours:	0.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**19.74**

Work Order Footer

Work Order 57723996 Total	
Parts:	31.51
Labor:	0.00
Labor Hours:	1.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**31.51**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57730458
Invoice No. 55345 - 57730458

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Check Engine Light on		Ford Transit	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	211,573 - DH

Chronology		
Reported	May 27, 2025 7:33:00 AM	May 27, 2025 7:33:00 AM
Started	May 27, 2025 7:37:00 AM	
Completed	May 27, 2025 11:56:00 AM	May 27, 2025 11:56:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction: Line 20 Check Engine Light on / Scan found code (P2240) O2 Sensor positive Current Control Open Bank (2) Sensor (1). Recommend bank (2) Sensor (1) Remove & Replace Bank (2) -Sensor (1). Road Test all is good at the time.
Parts # LK4Z-9F472-C Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 27-MAY-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		DARTHURS	May 27, 2025 7:38:43 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	May 27, 2025 7:38:43 AM	No	
400 - Are you wearing the appropriate PPE?	Done		DARTHURS	May 27, 2025 7:38:43 AM	No	
700 - Have you performed the proper LOTO?	Done		DARTHURS	May 27, 2025 7:38:43 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	May 27, 2025 7:38:43 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	May 27, 2025 7:38:43 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57730458
Invoice No. 55345 - 57730458

Client Department:
Department: 55345M
Work Order Description
Check Engine Light on
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 211,573 - DH

Activity Header
Activity: 15 020 GROUP, DRIVETRAIN
Activity Note: Check Engine Light
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-May-25	LK4Z-9F472-C	SENSOR, OXYGEN, UPSTREAM, BANK-TWO, TRANSIT	1	133.74	133.74

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-May-25	Arthurs,Durvin	4.32	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	133.74
Labor:	0.00
Labor Hours:	4.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**133.74**

Work Order Footer

Work Order 57730458 Total	
Parts:	133.74
Labor:	0.00
Labor Hours:	4.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**133.74**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 57726303
Invoice No. 55345 - 57726303

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Right front tire sensor not reading		Ford Transit	
Requested By:	GJUGGERDEO	**Status:**	40 - Closed (40)
Created By:	GJUGGERDEO	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	211,573 - DH

Chronology		
Reported	May 22, 2025 9:46:00 AM	May 22, 2025 9:46:00 AM
Started	May 22, 2025 9:49:00 AM	
Completed	May 22, 2025 11:41:00 AM	May 22, 2025 11:41:00 AM
Down Time		

Work Order Notes

Line 10 Complaint Driver reports right front tire sensor not functioning

Cause check found sensor not working

Correction Remove and replaced sensor with new TPMS62
Remove and replace cabin filter AF56065

Activity Header
Activity: 10 017 TIRES, TUBES, LINERS & VALVES
Activity Note: Right front tire sensor not working properly
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-May-25	131196995	TIRE, 195/75R16, WORKHORSE, HTL, WRANGLER, GOODYEAR	2	119.26	238.52
22-May-25	TPMS62	SENSOR, MONITORING, PRESSURE, TIRE	1	42.76	42.76
22-May-25	AF56065	FILTER, AIR, CABIN SUPERSEDES PA30000	1	8.83	8.83

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-May-25	Goonashwar Juggerdeo	1.85	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	290.11
Labor:	0.00
Labor Hours:	1.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**290.11**

Work Order Footer

Work Order 57726303 Total	
Parts:	290.11
Labor:	0.00
Labor Hours:	1.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**290.11**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 6

Work Order No. 57723904
Invoice No. 55345 - 57723904

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	211,573 - DH

Chronology		
Reported	May 20, 2025 2:58:51 PM	May 20, 2025 2:58:51 PM
Started	May 21, 2025 7:40:00 AM	
Completed	May 21, 2025 10:32:00 AM	May 21, 2025 10:32:00 AM
Down Time		

Work Order Notes

Line 10 Palm Tran written are missing letters Line 20 Replaced turbo coolant line connector

Activity Header
Activity: 10 174/001/001 BODY, BUS, COMPLETE
Activity Note: body damage
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 6

Work Order No. 57723904
Invoice No. 55345 - 57723904

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	211,573 - DH

Activity Header
Activity: 20 042/002/044 CAP, TANK, SURGE
Activity Note: Coolant leaks
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 6

Work Order No. 57723904
Invoice No. 55345 - 57723904

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	211,573 - DH

Activity Header
Activity: 30 043/004/064 KIT, MOUNTING, TURBOCHARGER
Activity Note: turbo line leaks
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-May-25	BL3Z-6A968-C	CONNECTOR, LINE, OIL, TURBOCHARGER, RH, F350 HD	1	9.57	9.57

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-May-25	Delva,Terry	2.87	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	9.57
Labor:	0.00
Labor Hours:	2.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**9.57**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 6

Work Order No. 57723904
Invoice No. 55345 - 57723904

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	211,573 - DH

Activity Header
Activity: 40 032/001/001 BATTERY
Activity Note:
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 6

Work Order No. 57723904
Invoice No. 55345 - 57723904

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	211,573 - DH

Activity Header
Activity: 50 018/003/005 NUT, WHEEL, SELF-LOOKING
Activity Note:
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 50 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 6 of 6

Work Order No. 57723904
Invoice No. 55345 - 57723904

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	211,573 - DH

Activity Header
Activity: 60 002/002/056 FLAP, MUD, WHEEL, FRONT, REAR
Activity Note:
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 60 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57723904 Total	
Parts:	9.57
Labor:	0.00
Labor Hours:	2.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**9.57**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57686018
Invoice No. 55345 - 57686018

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	211,573 - DH

Chronology		
Reported	May 20, 2025 12:00:00 AM	May 20, 2025 12:00:00 AM
Started	May 20, 2025 1:38:00 PM	
Completed	May 20, 2025 4:00:00 PM	May 20, 2025 4:00:00 PM
Down Time		

Work Order Notes

Line 10 PMB

Service due

Performed and completed PMB

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 20-MAY-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		TDELVA	May 20, 2025 1:38:00 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	May 20, 2025 1:38:00 PM	No	
400 - Are you wearing the appropriate PPE?	Done		TDELVA	May 20, 2025 1:38:00 PM	No	
700 - Have you performed the proper LOTO?	Done		TDELVA	May 20, 2025 1:38:00 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	May 20, 2025 1:38:00 PM	No	
1,100 - Have you successfully completed the	Done		TDELVA	May 20, 2025	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				1:38:00 PM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57686018
Invoice No. 55345 - 57686018

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	211,573 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-May-25	Delva,Terry	1.95	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: TDELVA Performed on: 20-MAY-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
10,800 - CHECK_All Destination Signage	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
10,900 - *RPT*INSPECT_Body Damage,	Done	body	TDELVA	May 20, 2025	Yes	57723904

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Corrosion;DOCUMENT_Issues		damage		2:58:45 PM		
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
20,200 - CHECK_Public Address System	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	-	na	TDELVA	May 20, 2025 2:58:45 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	na	TDELVA	May 20, 2025 2:58:45 PM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	na	TDELVA	May 20, 2025 2:58:45 PM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	na	TDELVA	May 20, 2025 2:58:45 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	na	TDELVA	May 20, 2025 2:58:45 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	na	TDELVA	May 20, 2025 2:58:45 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	-	na	TDELVA	May 20, 2025 2:58:45 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
21,500 - INSPECT_High Idle Control	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	-	na	TDELVA	May 20, 2025 2:58:45 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		TDELVA	May 20, 2025 2:58:45 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
31,000 - SSF (Street Side Front)	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
32,000 - Engine Inspection	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	na	TDELVA	May 20, 2025 2:58:45 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	TDELVA	May 20, 2025 2:58:45 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done	Coolant leaks	TDELVA	May 20, 2025 2:58:45 PM	Yes	57723904
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
32,100 - INSPECT_Intake System	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done	turbo line leaks	TDELVA	May 20, 2025 2:58:45 PM	Yes	57723904
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	0 Volt*		TDELVA	May 20, 2025 2:58:45 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	13.8 Volt*		TDELVA	May 20, 2025 2:58:45 PM	Yes	57723904
33,000 - CSF (Curb Side Front)	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks,	Done		TDELVA	May 20, 2025	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Spring Shackles				2:58:45 PM		
33,030 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
40,700 - CHECK_Passenger Stop Request System	-	na	TDELVA	May 20, 2025 2:58:45 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
50,400 - LUBE_All Chassis Components	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		TDELVA	May 20, 2025 2:58:45 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,700 - INSPECT_Tire Condition	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		TDELVA	May 20, 2025 2:58:45 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	63 Pounds per Square Inch		TDELVA	May 20, 2025 2:58:45 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		TDELVA	May 20, 2025 2:58:45 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	64 Pounds per Square Inch		TDELVA	May 20, 2025 2:58:45 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	May 20, 2025 2:58:45 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	May 20, 2025 2:58:45 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.27 Inch		TDELVA	May 20, 2025 2:58:45 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.27 Inch		TDELVA	May 20, 2025 2:58:45 PM	No	
52,100 - INSPECT_Vibration Damper	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		TDELVA	May 20, 2025 2:58:45 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
53,600 - INSPECT_Tire Condition	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	-	na	TDELVA	May 20, 2025 2:58:45 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		TDELVA	May 20, 2025 2:58:45 PM	Yes	57723904
54,100 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	May 20, 2025 2:58:45 PM	Yes	57723904
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		TDELVA	May 20, 2025 2:58:45 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	7 32nds of an inch		TDELVA	May 20, 2025 2:58:45 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	63 Pounds per Square Inch		TDELVA	May 20, 2025 2:58:45 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	63 Pounds per Square Inch		TDELVA	May 20, 2025 2:58:45 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	7 32nds of an inch		TDELVA	May 20, 2025 2:58:45 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		TDELVA	May 20, 2025 2:58:45 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	63 Pounds per Square Inch		TDELVA	May 20, 2025 2:58:45 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	Pounds per Square Inch	63	TDELVA	May 20, 2025 2:58:45 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		TDELVA	May 20, 2025 2:58:45 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		TDELVA	May 20, 2025 2:58:45 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.127 Inch		TDELVA	May 20, 2025 2:58:45 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.127 Inch		TDELVA	May 20, 2025 2:58:45 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		TDELVA	May 20, 2025 2:58:45 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		TDELVA	May 20, 2025 2:58:45 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		TDELVA	May 20, 2025 2:58:45 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57686018
Invoice No. 55345 - 57686018

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	211,573 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMB Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-May-25	75050	OIL, ENGINE, 5W/30	6	2.71	16.26
20-May-25	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	3.47	3.47

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-May-25	Delva,Terry	0.42	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMB Service
Task: 55345-Medium Duty PMB Inspection Performed by: TDELVA Performed on: 20-MAY-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		TDELVA	May 20, 2025 3:36:58 PM	No	
101,000 - FRA Change Oil Filters	Yes		TDELVA	May 20, 2025 3:36:58 PM	No	
102,000 - FRA Drain Engine Oil	Yes		TDELVA	May 20, 2025 3:36:58 PM	No	
103,000 - FRA Check Transmission Fluid	Done		TDELVA	May 20, 2025 3:36:58 PM	No	
104,000 - Lubricate Chassis	Done		TDELVA	May 20, 2025 3:36:58 PM	No	
105,000 - Replace or Clean A/C Filters	Done		TDELVA	May 20, 2025 3:36:58 PM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	-	na	TDELVA	May 20, 2025 3:36:58 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	TDELVA	May 20, 2025 3:36:58 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		TDELVA	May 20, 2025	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:36:58 PM		
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		TDELVA	May 20, 2025 3:36:58 PM	No	
201,000 - Service Crankcase Breather	Done		TDELVA	May 20, 2025 3:36:58 PM	No	
202,000 - FRA Change Water Separator ¿ Secondary Fuel Filters	No		TDELVA	May 20, 2025 3:36:58 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		TDELVA	May 20, 2025 3:36:58 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		TDELVA	May 20, 2025 3:36:58 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		TDELVA	May 20, 2025 3:36:58 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	19.73
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**19.73**

Work Order Footer

Work Order 57686018 Total	
Parts:	19.73
Labor:	0.00
Labor Hours:	2.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**19.73**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 57714797
Invoice No. 55345 - 57714797

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Front Air Conditioning System		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	210,637 - DH

Chronology		
Reported	May 13, 2025 8:58:00 AM	May 13, 2025 8:58:00 AM
Started	May 13, 2025 8:59:00 AM	
Completed	May 13, 2025 1:10:00 PM	May 13, 2025 1:10:00 PM
Down Time		

Work Order Notes

Line 10 Front blower motor no working

Front fuse box damage connector

Removed fuse box, repaired connector and installed back, all okay at this time Line 20 Installed gas cover used good one and 4 new clips Line 30 Installed better condition tire on rear and rotated driver outer rear to front

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 13-MAY-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	May 13, 2025 12:41:41 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	May 13, 2025 12:41:41 PM	No	
400 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	May 13, 2025 12:41:41 PM	No	
700 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	May 13, 2025 12:41:41 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	May 13, 2025 12:41:41 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	May 13, 2025 12:41:41 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 57714797
Invoice No. 55345 - 57714797

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Front Air Conditioning System		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	210,637 - DH

Activity Header
Activity: 20 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: FRONT AC DIAG
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-May-25	Rodriguez,Raul	1.35	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 57714797
Invoice No. 55345 - 57714797

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Front Air Conditioning System		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	210,637 - DH

Activity Header
Activity: 30 044/000/000 FUEL SYSTEM
Activity Note: Gas black cover missing
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-May-25	W716507-S300	CLIP, PANEL, SIDE,,BODY, TRANSIT	4	2.27	9.08

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-May-25	Rodriguez,Raul	0.47	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	9.08
Labor:	0.00
Labor Hours:	0.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**9.08**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 57714797
Invoice No. 55345 - 57714797

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Front Air Conditioning System		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	210,637 - DH

Activity Header
Activity: 40 017 TIRES, TUBES, LINERS & VALVES
Activity Note: tires
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57714797 Total	
Parts:	9.08
Labor:	0.00
Labor Hours:	1.82
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**9.08**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57702760
Invoice No. 55345 - 57702760

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
RR taillight dim.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	209,359 - DH

Chronology		
Reported	May 6, 2025 1:59:00 AM	May 6, 2025 1:59:00 AM
Started	May 6, 2025 2:00:00 AM	
Completed	May 6, 2025 2:26:00 AM	May 6, 2025 2:26:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: RR taillight dim.

Cause: Defective.

Correction: Remove and replaced RR taillight assembly. Line 20 Reconnected NFC unit. Functions as intended. Line 30 Checked Lytx Camera, found no issues. Has power. Performed manual download.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 06-MAY-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		EARJOHNSON	May 6, 2025 2:26:27 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	May 6, 2025 2:26:27 AM	No	
400 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	May 6, 2025 2:26:27 AM	No	
700 - Have you performed the proper LOTO?	Done		EARJOHNSON	May 6, 2025 2:26:27 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	May 6, 2025 2:26:27 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	May 6, 2025 2:26:27 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57702760
Invoice No. 55345 - 57702760

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
RR tailight dim.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	209,359 - DH

Activity Header
Activity: 15 034/003/000 LAMPS, SIGNAL, PARKING & BACKUP
Activity Note: RR tailight dim.
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-May-25	210855	LAMP, STOP/TAIL, LED, 7"	1	64.36	64.36

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-May-25	Earl Johnson	0.4	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	64.36
Labor:	0.00
Labor Hours:	0.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**64.36**

Work Order Footer

Work Order 57702760 Total	
Parts:	64.36
Labor:	0.00
Labor Hours:	0.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**64.36**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57698827
Invoice No. 55345 - 57698827

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Rear AC Malfunction.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	208,860 - DH

Chronology		
Reported	May 1, 2025 6:42:00 PM	May 1, 2025 6:42:00 PM
Started	May 1, 2025 6:44:00 PM	
Completed	May 1, 2025 7:48:00 PM	May 1, 2025 7:48:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear AC malfunction (LC).

Cause: Low system pressure.

Correction: Inspected Rear AC system components, visually found no defects or signs of leaks. Found that the systems pressure was somewhat low causing intermittent shutoff. Recharged system to spec and road tested vehicle without any issues. Let vehicle idle for another half hot without any issues. Rear AC operating as intended.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 01-MAY-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		EARJOHNSON	May 1, 2025	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				7:40:21 PM		
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	May 1, 2025 7:40:21 PM	No	
400 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	May 1, 2025 7:40:21 PM	No	
700 - Have you performed the proper LOTO?	Done		EARJOHNSON	May 1, 2025 7:40:21 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	May 1, 2025 7:40:21 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	May 1, 2025 7:40:21 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57698827
Invoice No. 55345 - 57698827

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Rear AC Malfunction.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	208,860 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear AC malfunction.
Reason for Repair: 24 Special Study
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-May-25	Earl Johnson	1.07	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57698827 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 5

Work Order No. 57698609
Invoice No. 55345 - 57698609

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
PTC RANDOM INSPECTION		Ford Transit	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	208,860 - DH

Chronology		
Reported	May 1, 2025 2:45:00 PM	May 1, 2025 2:45:00 PM
Started	May 1, 2025 4:06:00 PM	
Completed	May 1, 2025 4:43:00 PM	May 1, 2025 4:43:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction: Line 20 Driver rear inner TPMs sensor replaced and TPMs sensors relearned, all tire treads are within minimum spec, tire light is no longer on Line 30 Added one more safety strap to make 8 Line 40 Rear ac is working fine

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: VRAMOS Performed on: 01-MAY-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		VRAMOS	May 1, 2025	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				4:29:11 PM		
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VRAMOS	May 1, 2025 4:29:11 PM	No	
400 - Are you wearing the appropriate PPE?	Done		VRAMOS	May 1, 2025 4:29:11 PM	No	
700 - Have you performed the proper LOTO?	Done		VRAMOS	May 1, 2025 4:29:11 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		VRAMOS	May 1, 2025 4:29:11 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		VRAMOS	May 1, 2025 4:29:11 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 5

Work Order No. 57698609
Invoice No. 55345 - 57698609

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
PTC RANDOM INSPECTION		Ford Transit	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	208,860 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: REAR AC NOT WORKING LC
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 5

Work Order No. 57698609
Invoice No. 55345 - 57698609

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
PTC RANDOM INSPECTION		Ford Transit	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	208,860 - DH

Activity Header
Activity: 25 017 TIRES, TUBES, LINERS & VALVES
Activity Note: TIRE LIGHT ON - CHECK TIRES THEAD SPECS
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-May-25	TPMS62	SENSOR, MONITORING, PRESSURE, TIRE	1	42.72	42.72

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-May-25	Victor Ramos	0.3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	42.72
Labor:	0.00
Labor Hours:	0.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**42.72**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 5

Work Order No. 57698609
Invoice No. 55345 - 57698609

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
PTC RANDOM INSPECTION		Ford Transit	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	208,860 - DH

Activity Header
Activity: 35 078 TRIM & MISCELLANEOUS HARDWARE
Activity Note: MISSING WHEEL CHAIR BLUE STRAPS
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-May-25	Victor Ramos	0.1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 35 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 5

Work Order No. 57698609
Invoice No. 55345 - 57698609

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
PTC RANDOM INSPECTION		Ford Transit	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	208,860 - DH

Activity Header
Activity: 45 999 TOTAL VEHICLE
Activity Note: Missing trim below gas cap
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 45 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57698609 Total	
Parts:	42.72
Labor:	0.00
Labor Hours:	0.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**42.72**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57685985
Invoice No. 55345 - 57685985

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	207,928 - DH

Chronology

Reported	Apr 23, 2025 7:43:25 AM	Apr 23, 2025 7:43:25 AM
Started	Apr 23, 2025 8:19:00 AM	
Completed	Apr 23, 2025 9:34:00 AM	Apr 23, 2025 9:34:00 AM
Down Time		

Work Order Notes

Line 10 Removed and replaced clearance light Line 20 Adjusted w/c lift ramp switches Line 30 Secured transmission cooler lines

Activity Header

Activity: 10 034/003/000 LAMPS, SIGNAL, PARKING & BACKUP
Activity Note: rear right clearance light out
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Apr-25	MCL12RK	LAMP, MARKER/CLEARANCE, RED	1	9.36	9.36

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Apr-25	Rodriguez,Raul	0.63	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	9.36
Labor:	0.00
Labor Hours:	0.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**9.36**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57685985
Invoice No. 55345 - 57685985

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	207,928 - DH

Activity Header
Activity:20 174/032/066 RESTRAINT, OCCUPANT, TIE-DOWN, WHEELCHAIR
Activity Note: w/l lift ramp need adjust
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Apr-25	Rodriguez,Raul	0.32	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57685985
Invoice No. 55345 - 57685985

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	207,928 - DH

Activity Header
Activity: 30 045/009/003 BODY, PUMP, OIL, ENGINE
Activity Note: transmission cooler lines need secure
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Apr-25	Rodriguez,Raul	0.3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57685985 Total	
Parts:	9.36
Labor:	0.00
Labor Hours:	1.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**9.36**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57569395
Invoice No. 55345 - 57569395

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	207,928 - DH

Chronology		
Reported	Apr 23, 2025 6:42:21 AM	Apr 23, 2025 6:42:21 AM
Started	Apr 23, 2025 6:46:00 AM	
Completed	Apr 23, 2025 8:13:00 AM	Apr 23, 2025 8:13:00 AM
Down Time		

Work Order Notes

Line 10 PM.

Perform pmA service, lube front end, tire rotation, torque and re torque tires (140 f/p), R&R engine oil and filter, road test, all okay at this time.

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 23-APR-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Apr 23, 2025 7:27:56 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Apr 23, 2025 7:27:56 AM	No	
400 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Apr 23, 2025 7:27:56 AM	No	
700 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Apr 23, 2025 7:27:56 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Apr 23, 2025 7:27:56 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Apr 23, 2025 7:27:56 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57569395
Invoice No. 55345 - 57569395

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	207,928 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Apr-25	Rodriguez,Raul	0.97	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: RAURODRIGUEZ Performed on: 23-APR-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RAURODRIGUEZ	Apr 23, 2025	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				7:43:55 AM		
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done	rear right clearance light out	RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	Yes	57685985
10,800 - CHECK_All Destination Signage	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
20,200 - CHECK_Public Address System	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	na	RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	na	RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
20,800 - RECORD_Brake Performance Test	FEET	na	RAURODRIGUEZ	Apr 23,	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Distance				2025 7:43:55 AM		
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	na	RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	na	RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	-	na	RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
21,500 - INSPECT_High Idle Control	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
21,800 - INSPECT_Parking Brake Operation	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
31,000 - SSF (Street Side Front)	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
32,000 - Engine Inspection	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	-	na	RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
32,100 - INSPECT_Intake System	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.7 Volt*		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
33,000 - CSF (Curb Side Front)	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
40,700 - CHECK_Passenger Stop Request System	-	na	RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done	w/l lift ramp need adjust	RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	Yes	57685985
41,200 - INSPECT_CLEAN_AC Filter	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
50,400 - LUBE_All Chassis Components	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
50,700 - INSPECT_Tire Condition	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	32nds of an inch	8mm	RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	32nds of an inch	8mm	RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	Inch	30.7mm	RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	Inch	30.7mm	RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
52,100 - INSPECT_Vibration Damper	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done	transmission cooler lines need secure	RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	Yes	57685985
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
53,600 - INSPECT_Tire Condition	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	9 32nds of an inch		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	9 32nds of an inch		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	9 32nds of an inch		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	9 32nds of an inch		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	32nds of an inch	9mm	RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	32nds of an inch	9mm	RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	Inch	17.3mm	RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	Inch	17.3mm	RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,200 - RETURN_Vehicle to Predetermined Location	Done		RAURODRIGUEZ	Apr 23, 2025 7:43:55 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57569395
Invoice No. 55345 - 57569395

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	207,928 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Apr-25	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	3.45	3.45
23-Apr-25	75050	OIL, ENGINE, 5W/30	6	2.71	16.26

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Apr-25	Rodriguez,Raul	0.48	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: RAURODRIGUEZ Performed on: 23-APR-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RAURODRIGUEZ	Apr 23, 2025 7:45:22 AM	No	
101,000 - FRA Change Oil Filters	Yes		RAURODRIGUEZ	Apr 23, 2025 7:45:22 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RAURODRIGUEZ	Apr 23, 2025 7:45:22 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RAURODRIGUEZ	Apr 23, 2025 7:45:22 AM	No	
104,000 - Lubricate Chassis	Done		RAURODRIGUEZ	Apr 23, 2025 7:45:22 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RAURODRIGUEZ	Apr 23, 2025 7:45:22 AM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	-	na	RAURODRIGUEZ	Apr 23, 2025 7:45:22 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RAURODRIGUEZ	Apr 23, 2025 7:45:22 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RAURODRIGUEZ	Apr 23, 2025	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				7:45:22 AM		

Activity Sub Total

Activity 20 Sub Total	
Parts:	19.71
Labor:	0.00
Labor Hours:	0.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**19.71**

Work Order Footer

Work Order 57569395 Total	
Parts:	19.71
Labor:	0.00
Labor Hours:	1.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**19.71**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 5

Work Order No. 57653711
Invoice No. 55345 - 57653711

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
DRIVER REPORTED VEHICLE NOT STARTING		Ford Transit	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	207,597 - DH

Chronology		
Reported	Mar 18, 2025 10:46:00 AM	Mar 18, 2025 10:46:00 AM
Started	Apr 17, 2025 12:00:00 AM	
Completed	Apr 18, 2025 1:14:00 PM	Apr 18, 2025 1:14:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction: Line 20 UNIT TOWED BY PGA TOWING TO WAYNE AKERS DUE TO NOT STARTING Line 30 Inspected vehicle checked oil filter ac tire brakes

Pressure test for coolant leak wiper blades
And all is working properly

Front left ac vent broke next to door

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: GJUGGERDEO Performed on: 18-APR-25

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		GJUGGERDEO	Apr 18, 2025 11:40:06 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		GJUGGERDEO	Apr 18, 2025 11:40:06 AM	No	
400 - Are you wearing the appropriate PPE?	Done		GJUGGERDEO	Apr 18, 2025 11:40:06 AM	No	
700 - Have you performed the proper LOTO?	Done		GJUGGERDEO	Apr 18, 2025 11:40:06 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		GJUGGERDEO	Apr 18, 2025 11:40:06 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		GJUGGERDEO	Apr 18, 2025 11:40:06 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 5

Work Order No. 57653711
Invoice No. 55345 - 57653711

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
DRIVER REPORTED VEHICLE NOT STARTING		Ford Transit	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	207,597 - DH

Activity Header
Activity: 15 999 TOTAL VEHICLE
Activity Note: WAYNE AKERS FORD DIAG.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
31-Mar-25	LK4Z-12A650-C	MODULE, CONTROL, ENGINE, ELECTRONIC (ECM)	1	869.17	869.17

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	869.17
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**869.17**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 5

Work Order No. 57653711
Invoice No. 55345 - 57653711

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
DRIVER REPORTED VEHICLE NOT STARTING		Ford Transit	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	207,597 - DH

Activity Header
Activity: 25 999 TOTAL VEHICLE
Activity Note: UNIT TOWED BY PGA TOWING TO WAYNE AKERS DUE TO NOT STARTING
Reason for Repair: TW Towing
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Mar-25	DSP-TOWING	DIRECT PURCHASES FOR SERVICES TOWING	1	293.7	293.7

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	293.70
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**293.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 5

Work Order No. 57653711
Invoice No. 55345 - 57653711

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
DRIVER REPORTED VEHICLE NOT STARTING		Ford Transit	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	207,597 - DH

Activity Header
Activity: 35 999 TOTAL VEHICLE
Activity Note: IN SERVICE INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Apr-25	Goonashwar Juggerdeo	1.57	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 35 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 5

Work Order No. 57653711
Invoice No. 55345 - 57653711

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
DRIVER REPORTED VEHICLE NOT STARTING		Ford Transit	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	207,597 - DH

Activity Header
Activity: 45 999 TOTAL VEHICLE
Activity Note: UNIT SERVICED BY WAYNE AKERS
Reason for Repair: 01 Breakdown
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet

PO No.	ACD Code	Supplier No.	SUPPLIER	Order Date	Received Value
5135938	189,568,985	2405643	WAYNE AKERS FORD,FL,LAKE WORTH,2000 10TH AVE NORTH	Apr 23, 2025 12:00:00 AM	3,000

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 45 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	3,000.00
Sublet Labor:	0.00
Activity Sub Total	**3,000.00**

Work Order Footer

Work Order 57653711 Total	
Parts:	1,162.87
Labor:	0.00
Labor Hours:	1.57
Sublet Parts:	3,000.00
Sublet Labor:	0.00
Activity Sub Total	**4,162.87**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 6

Work Order No. 57584729
Invoice No. 55345 - 57584729

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Vehicle stalling.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	206,915 - DH

Chronology		
Reported	Dec 29, 2024 4:06:00 PM	Dec 29, 2024 4:06:00 PM
Started	Dec 29, 2024 4:09:00 PM	
Completed	Mar 16, 2025 2:50:57 PM	Mar 16, 2025 2:50:57 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Vehicle towed in for stalling.

Cause: Unknown.

Correction: Vehicle cranks but doesn¿t start. In shop for further diagnosis. Line 20 Bus Shut down No Start. Check Found Code PO08A /Low Fuel Rail Pressure / PO107A2A / PO 6A8 Sensor Reference Voltage -C- Circuit Range / Performance Check Found No Reference Voltage to fuel Rail Pressure Senser. Re flash PCM Bus Start up & Rungood at this time Need to Road . Road test brought back in Shop For Rear A/C Flashing H/A evacuate Replace Rear dryer Charge (6.00) lbs Freon add (4,0) Oz oil upon checking A/C bus Stall out again.
Parts #1412015 Qty (1) Line 30 UNIT 2076 WOULD NOT START Line 40 Check Bus for Stalling found Code UO(401) PCM Not Communicating With ABS Module. Suspect high Speed (CAN) Bus Or PCM replace Crank Shaft sensorBL3Z-6C315-B Qty (1)
Parts Line 50 Remove Body control module from one bus replace on bus (2076) and reprogram Line 60 Remove metal step plate for repair Line 70 Replace back BCM & Dash Panel. Line 80 UNIT 2076 WAS TOWED TO WAYNE ACKERS, WOULD NOT START Line 90 Replace new step on driver side part # 442695 Also replace switch for passenger door Line 100 Issue with the antilock system alarm goes off when lift door open Line 110 HARNESS WAS NOT SECURED. SECURED HARNESS TO OBND TWO PORT AND ALL IS WORKING AS NEEDED

Activity Header

Activity:	5 999 TOTAL VEHICLE
Activity Note:	Personal Risk Assessment
Reason for Repair:	SW Shop Work Order
Work Accomplished:	06 Inspect
Part Failure:	
Activity Comments:	

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List						
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 30-DEC-24						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		DARTHURS	Dec 30, 2024 7:39:28 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Dec 30, 2024 7:39:28 AM	No	
400 - Are you wearing the appropriate PPE?	Done		DARTHURS	Dec 30, 2024 7:39:28 AM	No	
700 - Have you performed the proper LOTO?	Done		DARTHURS	Dec 30, 2024 7:39:28 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Dec 30, 2024 7:39:28 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Dec 30, 2024 7:39:28 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 6

Work Order No. 57584729
Invoice No. 55345 - 57584729

Client Department:
Department: 55345M
Work Order Description
Vehicle stalling.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 206,915 - DH

Activity Header
Activity: 15 045 POWER PLANT
Activity Note: Vehicle stalling .
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jan-25	Arthurs,Durvin	0.65	0	0
10-Jan-25	Arthurs,Durvin	1.9	0	0
02-Jan-25	Arthurs,Durvin	1.42	0	0
09-Jan-25	Arthurs,Durvin	2.63	0	0
15-Jan-25	Arthurs,Durvin	6.32	0	0
03-Jan-25	Arthurs,Durvin	1.33	0	0
03-Jan-25	Arthurs,Durvin	2.57	0	0
30-Dec-24	Arthurs,Durvin	5.77	65	375.05
31-Dec-24	Arthurs,Durvin	3.1	65	201.5
10-Feb-25	Arthurs,Durvin	1.65	0	0
09-Jan-25	Arthurs,Durvin	0.55	0	0
13-Jan-25	Arthurs,Durvin	4.98	0	0
29-Dec-24	Earl Johnson	1.02	65	66.3
30-Dec-24	Arthurs,Durvin	2.42	65	157.3
14-Jan-25	Arthurs,Durvin	7.73	0	0
13-Jan-25	Arthurs,Durvin	2.98	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	800.15
Labor Hours:	47.02

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**800.15**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 6

Work Order No. 57584729
Invoice No. 55345 - 57584729

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Vehicle stalling.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	206,915 - DH

Activity Header
Activity: 25 030 ELECTRICAL GROUP
Activity Note: VEHICLE HAS A NO START CONDITION -TOWED BY GARDENS TOWING
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Feb-25	DSP-TOWING	DIRECT PURCHASES FOR SERVICES TOWING	1	306.9	306.9
03-Jan-25	DSP-TOWING	DIRECT PURCHASES FOR SERVICES TOWING	1	326.7	326.7

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	633.60
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**633.60**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 6

Work Order No. 57584729
Invoice No. 55345 - 57584729

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Vehicle stalling.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	206,915 - DH

Activity Header
Activity: 35 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear A/C Flashing H/A
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Jan-25	1412015	ACCUMULATOR, A/C	1	14.25	14.25
10-Jan-25	BL3Z-6C315-B	SENSOR, POSITION, CRANKSHAFT	1	31.56	31.56
13-Feb-25	BK3Z-14529-J	SWITCH, REGULATOR, WINDOW, TRANSIT, '19	1	107.88	107.88

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Mar-25	Junior Hurst	1.92	0	0
03-Jan-25	Arthurs,Durvin	0.93	0	0
03-Jan-25	Arthurs,Durvin	2.38	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 35 Sub Total	
Parts:	153.69
Labor:	0.00
Labor Hours:	5.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**153.69**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 6

Work Order No. 57584729
Invoice No. 55345 - 57584729

Client Department:
Department: 55345M
Work Order Description
Vehicle stalling.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 206,915 - DH

Activity Header
Activity: 45 999 TOTAL VEHICLE
Activity Note: Driver metal step
Reason for Repair: * Reason for repair code
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Mar-25	442695	STEP, ENTRY, ALUMINUM, TRANSIT	1	491.55	491.55

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Mar-25	Junior Hurst	2.28	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 45 Sub Total	
Parts:	491.55
Labor:	0.00
Labor Hours:	2.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**491.55**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 6 of 6

Work Order No. 57584729
Invoice No. 55345 - 57584729

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Vehicle stalling.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	206,915 - DH

Activity Header
Activity: 55 999 TOTAL VEHICLE
Activity Note: OUT SERVICE WAYNE ACKERS
Reason for Repair: 01 Breakdown
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Feb-25	DSP-OUTSIDESERV	DIRECT PURCHASE FOR OUTSIDE SERV GL 5850	1	1,150	1,150
26-Feb-25	LU5Z-12A581-A	HARNESS, WIRING, ENGINE, UPPER	1	406.67	406.67

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 55 Sub Total	
Parts:	1,556.67
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1,556.67**

Work Order Footer

Work Order 57584729 Total	
Parts:	2,835.51
Labor:	800.15
Labor Hours:	54.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**3,635.66**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 57584144
Invoice No. 55345 - 57584144

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOW UP TO QCC INSP		Ford Transit	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	206,915 - DH

Chronology		
Reported	Dec 27, 2024 10:27:17 PM	Dec 27, 2024 10:27:17 PM
Started	Dec 27, 2024 10:33:00 PM	
Completed	Dec 27, 2024 11:17:00 PM	Dec 27, 2024 11:17:00 PM
Down Time		

Work Order Notes

Line 10

Clean rear AC filter

Activity Header
Activity: 10 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: DIRTY REAR AC FILTER
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Dec-24	Goonashwar Juggerdeo	0.72	65	46.8

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	46.80
Labor Hours:	0.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**46.80**

Work Order Footer

Work Order 57584144 Total	
Parts:	0.00
Labor:	46.80
Labor Hours:	0.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**46.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56526044
Invoice No. 55345 - 56526044

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
QCC FLEET INSPECTION		Ford Transit	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	206,915 -

Chronology		
Reported	Dec 27, 2024 5:53:50 AM	Dec 27, 2024 5:53:50 AM
Started		
Completed	Dec 27, 2024 10:32:00 PM	Dec 27, 2024 10:32:00 PM
Down Time		

Work Order Notes

Line 10 QCC INSPECTION COMPLETED

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 27-DEC-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		FSIMON	Dec 27, 2024 9:35:17 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		FSIMON	Dec 27, 2024 9:35:17 PM	No	
400 - Are you wearing the appropriate PPE?	Done		FSIMON	Dec 27, 2024 9:35:17 PM	No	
700 - Have you performed the proper LOTO?	Done		FSIMON	Dec 27, 2024 9:35:17 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		FSIMON	Dec 27, 2024 9:35:17 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Dec 27, 2024 9:35:17 PM	No	

Activity Sub Total

Activity 10 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56526044
Invoice No. 55345 - 56526044

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
QCC FLEET INSPECTION		Ford Transit	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	206,915 -

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: QCC FLEET INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: QCC FLEET INSPECTION
Task: 55345 QCC FLEET INSPECTION Performed by: FSIMON Performed on: 27-DEC-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - EXTERIOR CIRCLE INSPECTION	Done		FSIMON	Dec 27, 2024 10:30:19 PM	No	
20 - Cleanliness	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
30 - Entrance Door Operation/Seals/Glass	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
40 - Body/Fenders/Bumpers	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
50 - Tires/Wheels/Lugs	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
60 - Mirrors and Attachments	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
70 - Lights and Accessories	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
80 - Compartment Doors	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
90 - Battery Compartment	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
100 - Check All Fluids	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
110 - Belt Drives	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
120 - Air Induction	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
130 - Exhaust System	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
140 - Engine Compartmetn Wiring	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
150 - DRIVERS AREA INSPECTION	Done		FSIMON	Dec 27, 2024 10:30:19 PM	No	
160 - Air System	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
170 - Audible Warnings	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
180 - Dash and Gauges	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
190 - Accessory components			FSIMON	Dec 27, 2024 10:30:19 PM	No	
200 - Exit Door Operation			FSIMON	Dec 27, 2024 10:30:19 PM	No	
210 - Exit Door Interlock	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
220 - Fare box and ticket cutter.	E		FSIMON	Dec 27, 2024 10:30:19 PM	No	
230 - Fast Idle	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
240 - Glass & Mirrors	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
250 - Floor Covering	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
260 - Horn and Lamps	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
270 - Start Function	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
280 - PA System	E		FSIMON	Dec 27, 2024 10:30:19 PM	No	
290 - Pedal Condition and Adjustment	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
300 - Reverse System	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
310 - Seat	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
320 - Steering Wheel & Column	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
330 - Sun Visor	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
340 - Turn Signals Switch	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
350 - Electrical Compartment	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
360 - Wheel Chair Operation	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
370 - INTERIOR CIRCLE	Done		FSIMON	Dec 27, 2024 10:30:19 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
380 - Cleanliness	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
390 - HVAC	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
400 - Interior Passenger Area	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
410 - Stop Request	E		FSIMON	Dec 27, 2024 10:30:19 PM	No	
420 - Safety Equipment	B	BODY FLUID CLEAN UP KIT	FSIMON	Dec 27, 2024 10:30:19 PM	Yes	57584144
430 - UNDERCARRIAGE	Done		FSIMON	Dec 27, 2024 10:30:19 PM	No	
440 - Air System	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
450 - Steering components	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
460 - Brake Inspection	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
470 - Suspension Components	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
480 - Frame	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
490 - Fluid Leakage	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	
500 - Fuel System	A		FSIMON	Dec 27, 2024 10:30:19 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 56526044 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57575147
Invoice No. 55345 - 57575147

Client Department:
Department: 55345M
Work Order Description
Road Call-BATTERY LIGHT ON
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 205,276 - DH

Chronology		
Reported	Dec 16, 2024 3:48:00 PM	Dec 16, 2024 3:48:00 PM
Started	Dec 16, 2024 4:07:00 PM	
Completed	Dec 16, 2024 9:19:00 PM	Dec 16, 2024 9:19:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction: Line 20 Unit came in from road call for battery light on check and found alternator worn out removed and installed new part# 1MZ-10346F components no working as design return unit back to service Line 30 Can you please change out part for me can¿t find thank you

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 16-DEC-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		JUHURST	Dec 16, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				4:07:04 PM		
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Dec 16, 2024 4:07:04 PM	No	
400 - Are you wearing the appropriate PPE?	Done		JUHURST	Dec 16, 2024 4:07:04 PM	No	
700 - Have you performed the proper LOTO?	Done		JUHURST	Dec 16, 2024 4:07:04 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Dec 16, 2024 4:07:04 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Dec 16, 2024 4:07:04 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57575147
Invoice No. 55345 - 57575147

Client Department:
Department: 55345M
Work Order Description
Road Call-BATTERY LIGHT ON
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 205,276 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL-BATTERY LIGHT ON
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Dec-24	Junior Hurst	5.18	65	336.7

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	336.70
Labor Hours:	5.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**336.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57575147
Invoice No. 55345 - 57575147

Client Department:
Department: 55345M
Work Order Description
Road Call-BATTERY LIGHT ON
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 205,276 - DH

Activity Header
Activity: 20 020 GROUP, DRIVETRAIN
Activity Note: Unit came in for battery light on
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Dec-24	L1MZ-10346-F	ALTERNATOR	1	747.72	747.72

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	747.72
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**747.72**

Work Order Footer

Work Order 57575147 Total	
Parts:	747.72
Labor:	336.70
Labor Hours:	5.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1,084.42**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 8

Work Order No. 57569354
Invoice No. 55345 - 57569354

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	204,455 - DH

Chronology		
Reported	Dec 9, 2024 10:05:58 PM	Dec 9, 2024 10:05:58 PM
Started	Dec 9, 2024 10:21:00 PM	
Completed	Dec 11, 2024 3:43:00 PM	Dec 11, 2024 3:43:00 PM
Down Time		

Work Order Notes

Line 10 Left side black molding installed Line 20 Right fog light installed Line 30 Front brake pads replaced Line 40 New gas cap installed Line 50 4 blue straps added Line 60 NFC geo tab connection repaired Line 70 NFC connection repaired Line 80 Both securement bags replaced with new Line 90 Lift interior step alarm repaired

Activity Header
Activity: 10 034/003/000 LAMPS, SIGNAL, PARKING & BACKUP
Activity Note: right fog light
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Dec-24	H8C1	BULB, HEADLAMP, HALOGEN,12V	1	6.58	6.58
18-Dec-24	PA30000	FILTER, AIR, CABIN SEE AF56065	1	11.79	11.79

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	18.37
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**18.37**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 8

Work Order No. 57569354
Invoice No. 55345 - 57569354

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	204,455 - DH

Activity Header
Activity: 20 044/001/002 CAP, TANK, FUEL
Activity Note: fuel cap
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 8

Work Order No. 57569354
Invoice No. 55345 - 57569354

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	204,455 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: left side black molding missing
Reason for Repair: * Reason for repair code
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 8

Work Order No. 57569354
Invoice No. 55345 - 57569354

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	204,455 - DH

Activity Header
Activity: 40 053/004/001 EXTINGUISHER, FIRE
Activity Note: 4 blue straps missing
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 8

Work Order No. 57569354
Invoice No. 55345 - 57569354

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	204,455 - DH

Activity Header
Activity: 50 034/004/155 MOUNTING, PANEL, FUSE
Activity Note: nfc not working
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 50 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 6 of 8

Work Order No. 57569354
Invoice No. 55345 - 57569354

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	204,455 - DH

Activity Header
Activity: 60 999 TOTAL VEHICLE
Activity Note: both securement bag
Reason for Repair: * Reason for repair code
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 60 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 7 of 8

Work Order No. 57569354
Invoice No. 55345 - 57569354

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	204,455 - DH

Activity Header
Activity: 70 174/032/066 RESTRAINT, OCCUPANT, TIE-DOWN, WHEELCHAIR
Activity Note: lift interior step plate ALARM
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 70 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 8 of 8

Work Order No. 57569354
Invoice No. 55345 - 57569354

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	204,455 - DH

Activity Header
Activity: 80 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: front brake pads
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Dec-24	BRF-1896	PADS, BRAKE, DISC, FRONT, TRANSIT	1	55.14	55.14

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Dec-24	Nicolas Barreto	1.43	65	92.95

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 80 Sub Total	
Parts:	55.14
Labor:	92.95
Labor Hours:	1.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**148.09**

Work Order Footer

Work Order 57569354 Total	
Parts:	73.51
Labor:	92.95
Labor Hours:	1.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**166.46**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57569736
Invoice No. 55345 - 57569736

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Wheelchair Lift		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	204,455 - DH

Chronology		
Reported	Dec 10, 2024 10:27:00 AM	Dec 10, 2024 10:27:00 AM
Started	Dec 10, 2024 10:28:00 AM	
Completed	Dec 11, 2024 2:00:00 PM	Dec 11, 2024 2:00:00 PM
Down Time		

Work Order Notes

Line 10 Act 20
Inner plate alarm no sound + w/c lift malfunction

All tower switches need adjustment

Adjusted all tower switches + 50 pound solenoid
And replaced top left light (lift) part: shop supply

Act. 30
Driver seat lower cover damage

Unknown

Removed and replaced cover seat

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 11-DEC-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Dec 11, 2024 1:59:45 PM	No	
200 - If task requires lifting, are lifts secured, are	Done		RAURODRIGUEZ	Dec 11, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				1:59:45 PM		
400 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Dec 11, 2024 1:59:45 PM	No	
700 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Dec 11, 2024 1:59:45 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Dec 11, 2024 1:59:45 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Dec 11, 2024 1:59:45 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57569736
Invoice No. 55345 - 57569736

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Wheelchair Lift		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	204,455 - DH

Activity Header
Activity: 20 055/023/000 LIFT, WHEELCHAIR, PASSENGER
Activity Note: WheelChair Lift
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Dec-24	Delva,Terry	0.48	65	31.2
11-Dec-24	Rodriguez,Raul	3.07	65	199.55

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	230.75
Labor Hours:	3.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**230.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57569736
Invoice No. 55345 - 57569736

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Wheelchair Lift		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	204,455 - DH

Activity Header
Activity: 30 050 GROUP, ACCESSORIES
Activity Note: Driver seat lower cover damage
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Dec-24	1000-799	COVER, CUSHION, DRIVER	1	97.63	97.63

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Dec-24	Rodriguez,Raul	1.72	65	111.8

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	97.63
Labor:	111.80
Labor Hours:	1.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**209.43**

Work Order Footer

Work Order 57569736 Total	
Parts:	97.63
Labor:	342.55
Labor Hours:	5.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**440.18**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57548609
Invoice No. 55345 - 57548609

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	204,455 - DH

Chronology		
Reported	Dec 9, 2024 12:00:00 AM	Dec 9, 2024 12:00:00 AM
Started	Dec 9, 2024 8:37:00 PM	
Completed	Dec 9, 2024 11:47:00 PM	Dec 9, 2024 11:47:00 PM
Down Time		

Work Order Notes

Line 10 Pm done, oil filter replaced

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: NBARRETO Performed on: 09-DEC-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		NBARRETO	Dec 9, 2024 9:51:00 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NBARRETO	Dec 9, 2024 9:51:00 PM	No	
400 - Are you wearing the appropriate PPE?	Done		NBARRETO	Dec 9, 2024 9:51:00 PM	No	
700 - Have you performed the proper LOTO?	Done		NBARRETO	Dec 9, 2024 9:51:00 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		NBARRETO	Dec 9, 2024 9:51:00 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		NBARRETO	Dec 9, 2024 9:51:00 PM	No	

Activity Sub Total

Activity 5 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57548609
Invoice No. 55345 - 57548609

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	204,455 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Dec-24	Nicolas Barreto	1.22	65	79.3

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: NBARRETO Performed on: 09-DEC-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	-	right fog light	NBARRETO	Dec 9, 2024 10:05:45 PM	Yes	57569354
10,800 - CHECK_All Destination Signage	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
10,900 - *RPT*INSPECT_Body Damage,	Done		NBARRETO	Dec 9, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Corrosion;DOCUMENT_Issues				10:05:45 PM		
11,000 - INSPECT_Fuel Tank Cap, and Doors	-	fuel cap	NBARRETO	Dec 9, 2024 10:05:45 PM	Yes	57569354
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
20,200 - CHECK_Public Address System	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	na	NBARRETO	Dec 9, 2024 10:05:45 PM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	na	NBARRETO	Dec 9, 2024 10:05:45 PM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	na	NBARRETO	Dec 9, 2024 10:05:45 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	na	NBARRETO	Dec 9, 2024 10:05:45 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	na	NBARRETO	Dec 9, 2024 10:05:45 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
21,500 - INSPECT_High Idle Control	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	-	left side black molding missing	NBARRETO	Dec 9, 2024 10:05:45 PM	Yes	57569354
31,000 - SSF (Street Side Front)	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
32,000 - Engine Inspection	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	NBARRETO	Dec 9, 2024 10:05:45 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
32,100 - INSPECT_Intake System	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.6 Volt*		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
33,000 - CSF (Curb Side Front)	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
33,030 - INSPECT_Mud Flaps, Brackets	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	-	4 blue straps missing	NBARRETO	Dec 9, 2024 10:05:45 PM	Yes	57569354
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	-	nfc not working	NBARRETO	Dec 9, 2024 10:05:45 PM	Yes	57569354
40,700 - CHECK_Passenger Stop Request System	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	-	both securement bag	NBARRETO	Dec 9, 2024 10:05:45 PM	Yes	57569354
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	-	lift interior step plate ALARM	NBARRETO	Dec 9, 2024 10:05:45 PM	Yes	57569354
41,200 - INSPECT_CLEAN_AC Filter	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
50,100 - *RPT*INSPECT_Steering components- Drag Link, Tie Rods ends and Steering Damper	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
50,400 - LUBE_All Chassis Components	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
50,700 - INSPECT_Tire Condition	Done		NBARRETO	Dec 9, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:05:45 PM		
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	7 32nds of an inch		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	4 32nds of an inch	front brake pads	NBARRETO	Dec 9, 2024 10:05:45 PM	Yes	57569354
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.5 Inch		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.5 Inch		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
52,100 - INSPECT_Vibration Damper	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and	Done		NBARRETO	Dec 9, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Chassis Frame for Corrosion, Cracks				10:05:45 PM		
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
53,600 - INSPECT_Tire Condition	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.5 Inch		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.5 Inch		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		NBARRETO	Dec 9, 2024 10:05:45 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	79.30
Labor Hours:	1.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**79.30**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57548609
Invoice No. 55345 - 57548609

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	204,455 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Dec-24	75050	OIL, ENGINE, 5W/30	6	2.81	16.86
09-Dec-24	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	3.4	3.4

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Dec-24	Nicolas Barreto	0.48	65	31.2

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: NBARRETO Performed on: 09-DEC-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NBARRETO	Dec 9, 2024 9:52:20 PM	No	
101,000 - FRA Change Oil Filters	Yes		NBARRETO	Dec 9, 2024 9:52:20 PM	No	
102,000 - FRA Drain Engine Oil	Yes		NBARRETO	Dec 9, 2024 9:52:20 PM	No	
103,000 - FRA Check Transmission Fluid	Done		NBARRETO	Dec 9, 2024 9:52:20 PM	No	
104,000 - Lubricate Chassis	Done		NBARRETO	Dec 9, 2024 9:52:20 PM	No	
105,000 - Replace or Clean A/C Filters	Done		NBARRETO	Dec 9, 2024 9:52:20 PM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	Done		NBARRETO	Dec 9, 2024 9:52:20 PM	No	
107,000 - FRA Change Primary Fuel Filter	No		NBARRETO	Dec 9, 2024 9:52:20 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		NBARRETO	Dec 9, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:52:20 PM		

Activity Sub Total

Activity 20 Sub Total	
Parts:	20.26
Labor:	31.20
Labor Hours:	0.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**51.46**

Work Order Footer

Work Order 57548609 Total	
Parts:	20.26
Labor:	110.50
Labor Hours:	1.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**130.76**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57560040
Invoice No. 55345 - 57560040

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
check bus for coolant leak		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	202,520 - DH

Chronology		
Reported	Nov 27, 2024 8:02:00 AM	Nov 27, 2024 8:02:00 AM
Started	Nov 27, 2024 8:07:00 AM	
Completed	Nov 28, 2024 1:23:00 PM	Nov 28, 2024 1:23:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction: Line 20 Coolant leaking

Tech found that both left turbo line plug leaking
Water pump leaking
Top right rear engine turbo line plug leaking

Replaced water pump
Replaced turbo line plugs
Pressure test cooling system for leaks
No leaks at this time Line 30 Replaced 2 rear top clearance marker light

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 28-NOV-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		TDELVA	Nov 28, 2024 1:22:41 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Nov 28, 2024 1:22:41 PM	No	
400 - Are you wearing the appropriate PPE?	Done		TDELVA	Nov 28, 2024 1:22:41 PM	No	
700 - Have you performed the proper LOTO?	Done		TDELVA	Nov 28, 2024 1:22:41 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Nov 28, 2024 1:22:41 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Nov 28, 2024 1:22:41 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57560040
Invoice No. 55345 - 57560040

Client Department:
Department: 55345M
Work Order Description
check bus for coolant leak
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 202,520 - DH

Activity Header
Activity: 15 043/006/078 LINE, COOLANT, DOSER
Activity Note: Check for coolant leak
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Nov-24	BL3Z-6A968-JD	CONNECTOR, LINE, OIL, TURBOCHARGER, RH, F350 HD	1	10.88	10.88
28-Nov-24	BL3Z-6A968-C	CONNECTOR, LINE, OIL, TURBOCHARGER, RH, F350 HD	2	8.88	17.76
28-Nov-24	MCL12RK	LAMP, MARKER/CLEARANCE, RED	2	9.31	18.62
28-Nov-24	LK4Z-8501-B	PUMP, WATER, TRANSIT, 350, 2021	1	162.62	162.62

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Nov-24	Delva,Terry	0.83	65	53.95
28-Nov-24	Delva,Terry	6.87	65	446.55
27-Nov-24	Delva,Terry	3.15	65	204.75
27-Nov-24	Pierre,Hubert J	1.6	65	104
28-Nov-24	Delva,Terry	0.78	65	50.7

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	209.88
Labor:	859.95
Labor Hours:	13.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1,069.83**

Work Order Footer

Work Order 57560040 Total	
Parts:	209.88
Labor:	859.95
Labor Hours:	13.23
Sublet Parts:	0.00

	Sublet Labor:	0.00
	Activity Sub Total	**1,069.83**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57552776
Invoice No. 55345 - 57552776

Client Department:
Department: 55345M
Work Order Description
needs all blue straps and first aid kit
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 201,209 - DH

Chronology		
Reported	Nov 19, 2024 12:51:00 AM	Nov 19, 2024 12:51:00 AM
Started	Nov 19, 2024 12:55:00 AM	
Completed	Nov 19, 2024 12:57:00 AM	Nov 19, 2024 12:57:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction:

Line 20 Needs all blue straps and first aid kit
Missing straps and kit expired
Replace straps and first aid kit

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 19-NOV-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		RGASPARD	Nov 19, 2024 12:54:56 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Nov 19, 2024 12:54:56 AM	No	
400 - Are you wearing the appropriate PPE?	Done		RGASPARD	Nov 19, 2024 12:54:56 AM	No	
700 - Have you performed the proper LOTO?	Done		RGASPARD	Nov 19, 2024 12:54:56 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Nov 19, 2024 12:54:56 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Nov 19, 2024 12:54:56 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57552776
Invoice No. 55345 - 57552776

Client Department:
Department: 55345M
Work Order Description
needs all blue straps and first aid kit
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 201,209 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note: Needs all blue straps and first aid kit
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Nov-24	Gaspard,Ronald	0.03	65	1.95

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	1.95
Labor Hours:	0.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.95**

Work Order Footer

Work Order 57552776 Total	
Parts:	0.00
Labor:	1.95
Labor Hours:	0.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.95**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 12

Work Order No. 57548562
Invoice No. 55345 - 57548562

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	200,566 - DH

Chronology		
Reported	Nov 13, 2024 4:13:45 PM	Nov 13, 2024 4:13:45 PM
Started		
Completed	Nov 15, 2024 8:18:15 AM	Nov 15, 2024 8:18:15 AM
Down Time		

Work Order Notes

Line 10 Replaced parking light indicators

Activity Header
Activity: 10 034/003/000 LAMPS, SIGNAL, PARKING & BACKUP
Activity Note: 1 front top clearance light and 2 top rear out
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 12

Work Order No. 57548562
Invoice No. 55345 - 57548562

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	200,566 - DH

Activity Header
Activity: 20 044/001/002 CAP, TANK, FUEL
Activity Note: fuel door cover missing
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 12

Work Order No. 57548562
Invoice No. 55345 - 57548562

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	200,566 - DH

Activity Header
Activity: 30 002/037/002 SEAT, COMPLETE
Activity Note: Driver seat cover And secure black panel near Seats
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 12

Work Order No. 57548562
Invoice No. 55345 - 57548562

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	200,566 - DH

Activity Header
Activity: 40 002/008/001 PANEL, DASH
Activity Note: Right front fog light
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 12

Work Order No. 57548562
Invoice No. 55345 - 57548562

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	200,566 - DH

Activity Header
Activity: 50 002/002/056 FLAP, MUD, WHEEL, FRONT, REAR
Activity Note: left side mud flap missing
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 50 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 6 of 12

Work Order No. 57548562
Invoice No. 55345 - 57548562

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	200,566 - DH

Activity Header
Activity: 60 174/012 COMPONENTS, DOOR, EMERGENCY, SIDE, BUS
Activity Note: Driver Door step need repair
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 60 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 7 of 12

Work Order No. 57548562
Invoice No. 55345 - 57548562

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	200,566 - DH

Activity Header
Activity: 70 174/032/066 RESTRAINT, OCCUPANT, TIE-DOWN, WHEELCHAIR
Activity Note: WC lift inner flat surface not beeping when step on it
Securement bags
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 70 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 8 of 12

Work Order No. 57548562
Invoice No. 55345 - 57548562

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	200,566 - DH

Activity Header
Activity: 80 174/001/033 POST, DOOR, EXIT, EMERGENCY, BUS
Activity Note: rear door switch
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 80 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 9 of 12

Work Order No. 57548562
Invoice No. 55345 - 57548562

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	200,566 - DH

Activity Header
Activity: 90 174/000 BODY, BUS
Activity Note: REAR DOOR LOWER GLASSS
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 90 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 10 of 12

Work Order No. 57548562
Invoice No. 55345 - 57548562

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	200,566 - DH

Activity Header
Activity: 100 017/009/016 VALVE, PROTECTION, PRESSURE, TIRE
Activity Note: no tire pressure indication in dash board
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 100 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 11 of 12

Work Order No. 57548562
Invoice No. 55345 - 57548562

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	200,566 - DH

Activity Header
Activity: 110 013/002/013 SHOE, BRAKE, REAR
Activity Note: Front Brake Pads
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 110 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 12 of 12

Work Order No. 57548562
Invoice No. 55345 - 57548562

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	200,566 - DH

Activity Header
Activity: 120 024/001/004 U-JOINT, DRIVESHAFT
Activity Note: secure drive shaft Bracket
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 120 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57548562 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 57548607
Invoice No. 55345 - 57548607

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Follow up Medium Duty PMC		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	200,566 - DH

Chronology		
Reported	Nov 13, 2024 5:04:14 PM	Nov 13, 2024 5:04:14 PM
Started	Nov 13, 2024 5:56:00 PM	
Completed	Nov 13, 2024 7:32:00 PM	Nov 13, 2024 7:32:00 PM
Down Time		

Work Order Notes

Line 10 All spark plus replaced Line 20 Middle clearance light replaced Line 30 Rear alarm installed,

Activity Header
Activity: 10 045 POWER PLANT
Activity Note: Tune Up
Reason for Repair: * Reason for repair code
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 57548607
Invoice No. 55345 - 57548607

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Follow up Medium Duty PMC		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	200,566 - DH

Activity Header
Activity: 20 045 POWER PLANT
Activity Note: need spark plugs
Reason for Repair: * Reason for repair code
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Nov-24	SP580	PLUG, SPARK	6	9.26	55.56

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Nov-24	Nicolas Barreto	1.58	65	102.7

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	55.56
Labor:	102.70
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**158.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 57548607
Invoice No. 55345 - 57548607

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Follow up Medium Duty PMC		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	200,566 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: UPPER CLEARANCE LIGHT OUT
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Nov-24	MCL12AK	LAMP, MARKER/CLEARANCE, LED, AMBER	1	9.36	9.36

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	9.36
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**9.36**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 57548607
Invoice No. 55345 - 57548607

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Follow up Medium Duty PMC		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	200,566 - DH

Activity Header
Activity: 40 999 TOTAL VEHICLE
Activity Note: Rear alarm switch missing
Reason for Repair: * Reason for repair code
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57548607 Total	
Parts:	64.92
Labor:	102.70
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**167.62**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57490399
Invoice No. 55345 - 57490399

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMC		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	200,566 - DH

Chronology		
Reported	Oct 8, 2024 8:14:49 AM	Oct 8, 2024 8:14:49 AM
Started	Nov 13, 2024 3:25:00 PM	
Completed	Nov 13, 2024 5:04:00 PM	Nov 13, 2024 5:04:00 PM
Down Time		

Work Order Notes

Line 10 PMC

Service due

Performed and completed PmC
Charge engine oil and filter

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 13-NOV-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		TDELVA	Nov 13, 2024 5:02:08 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Nov 13, 2024 5:02:08 PM	No	
400 - Are you wearing the appropriate PPE?	Done		TDELVA	Nov 13, 2024 5:02:08 PM	No	
700 - Have you performed the proper LOTO?	Done		TDELVA	Nov 13, 2024 5:02:08 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Nov 13, 2024 5:02:08 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Nov 13, 2024 5:02:08 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57490399
Invoice No. 55345 - 57490399

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMC		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	200,566 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Nov-24	Delva,Terry	0.82	65	53.3

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: TDELVA Performed on: 13-NOV-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done	1 front top clearance light and 2 top rear out	TDELVA	Nov 13, 2024 5:03:14 PM	Yes	57548562
10,800 - CHECK_All Destination Signage	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done	fuel door cover missing	TDELVA	Nov 13, 2024 5:03:14 PM	Yes	57548562
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done	Driver seat cover	TDELVA	Nov 13, 2024 5:03:14 PM	Yes	57548562
20,200 - CHECK_Public Address System	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	-	na	TDELVA	Nov 13, 2024 5:03:14 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	na	TDELVA	Nov 13, 2024 5:03:14 PM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	na	TDELVA	Nov 13, 2024 5:03:14 PM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	na	TDELVA	Nov 13, 2024 5:03:14 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	na	TDELVA	Nov 13, 2024 5:03:14 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	na	TDELVA	Nov 13, 2024 5:03:14 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	-	na	TDELVA	Nov 13, 2024 5:03:14 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done	Right front fog light	TDELVA	Nov 13, 2024 5:03:14 PM	Yes	57548562
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
21,500 - INSPECT_High Idle Control	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	-	na	TDELVA	Nov 13, 2024 5:03:14 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
31,000 - SSF (Street Side Front)	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done	lft side mud flap missing	TDELVA	Nov 13, 2024 5:03:14 PM	Yes	57548562
31,040 - INSPECT_Wiper Blades, Arms	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
32,000 - Engine Inspection	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,010 - INSPECT_Hood, Springs and Props	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	na	TDELVA	Nov 13, 2024 5:03:14 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	TDELVA	Nov 13, 2024 5:03:14 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
32,100 - INSPECT_Intake System	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.9 Volt*		TDELVA	Nov 13, 2024 5:03:14 PM	No	
33,000 - CSF (Curb Side Front)	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done	Driver Door step need repair	TDELVA	Nov 13, 2024 5:03:14 PM	Yes	57548562
40,000 - SECTION 4 - Interior Inspection	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
40,700 - CHECK_Passenger Stop Request System	-	na	TDELVA	Nov 13, 2024 5:03:14 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done	WC lift inner flat surface not beeping when step on it	TDELVA	Nov 13, 2024 5:03:14 PM	Yes	57548562
41,200 - INSPECT_CLEAN_AC Filter	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done	rear door switch	TDELVA	Nov 13, 2024 5:03:14 PM	Yes	57548562
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done	REAR DOOR LOWER GLASSS	TDELVA	Nov 13, 2024 5:03:14 PM	Yes	57548562
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,400 - LUBE_All Chassis Components	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
50,700 - INSPECT_Tire Condition	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		TDELVA	Nov 13, 2024 5:03:14 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	63 Pounds per Square Inch	no tire pressure indication in dash board	TDELVA	Nov 13, 2024 5:03:14 PM	Yes	57548562
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		TDELVA	Nov 13, 2024 5:03:14 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	63 Pounds per Square Inch		TDELVA	Nov 13, 2024 5:03:14 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done	Front Brake Pads	TDELVA	Nov 13, 2024 5:03:14 PM	Yes	57548562
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	4 32nds of an inch		TDELVA	Nov 13, 2024 5:03:14 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	4 32nds of an inch		TDELVA	Nov 13, 2024 5:03:14 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.27 Inch		TDELVA	Nov 13, 2024 5:03:14 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.27 Inch		TDELVA	Nov 13, 2024 5:03:14 PM	No	
52,100 - INSPECT_Vibration Damper	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done	secure drive shaft Bracket	TDELVA	Nov 13, 2024 5:03:14 PM	Yes	57548562
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
53,600 - INSPECT_Tire Condition	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	-	na	TDELVA	Nov 13, 2024 5:03:14 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	10 32nds of an inch		TDELVA	Nov 13, 2024 5:03:14 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	10 32nds of an inch		TDELVA	Nov 13, 2024 5:03:14 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	63 Pounds per Square Inch		TDELVA	Nov 13, 2024 5:03:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,500 - RECORD_RRI-Air Pressure (psi)	63 Pounds per Square Inch		TDELVA	Nov 13, 2024 5:03:14 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	10 32nds of an inch		TDELVA	Nov 13, 2024 5:03:14 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	10 32nds of an inch		TDELVA	Nov 13, 2024 5:03:14 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	63 Pounds per Square Inch		TDELVA	Nov 13, 2024 5:03:14 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	63 Pounds per Square Inch		TDELVA	Nov 13, 2024 5:03:14 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	Nov 13, 2024 5:03:14 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	Nov 13, 2024 5:03:14 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.127 Inch		TDELVA	Nov 13, 2024 5:03:14 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.127 Inch		TDELVA	Nov 13, 2024 5:03:14 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,200 - RETURN_Vehicle to Predetermined Location	Done		TDELVA	Nov 13, 2024 5:03:14 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	53.30
Labor Hours:	0.82
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**53.30**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57490399
Invoice No. 55345 - 57490399

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMC		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	200,566 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM C Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Nov-24	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	3.4	3.4
13-Nov-24	75050	OIL, ENGINE, 5W/30	6	2.81	16.86

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Nov-24	Delva,Terry	0.67	65	43.55

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PM C Service
Task: 55345-Medium Duty PMC Inspection Performed by: TDELVA Performed on: 13-NOV-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		TDELVA	Nov 13, 2024 5:02:40 PM	No	
101,000 - FRA Change Oil Filters	Yes		TDELVA	Nov 13, 2024 5:02:40 PM	No	
102,000 - FRA Drain Engine Oil	Yes		TDELVA	Nov 13, 2024 5:02:40 PM	No	
103,000 - FRA Check Transmission Fluid	Done		TDELVA	Nov 13, 2024 5:02:40 PM	No	
104,000 - Lubricate Chassis	Done		TDELVA	Nov 13, 2024 5:02:40 PM	No	
105,000 - Replace or Clean A/C Filters	Done		TDELVA	Nov 13, 2024 5:02:40 PM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	-	na	TDELVA	Nov 13, 2024 5:02:40 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	na	TDELVA	Nov 13, 2024 5:02:40 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		TDELVA	Nov 13, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				5:02:40 PM		
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		TDELVA	Nov 13, 2024 5:02:40 PM	No	
201,000 - Service Crankcase Breather	Done		TDELVA	Nov 13, 2024 5:02:40 PM	No	
202,000 - FRA Change Water Separator ¿ Secondary Fuel Filters	No	na	TDELVA	Nov 13, 2024 5:02:40 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No	na	TDELVA	Nov 13, 2024 5:02:40 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No	na	TDELVA	Nov 13, 2024 5:02:40 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		TDELVA	Nov 13, 2024 5:02:40 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		TDELVA	Nov 13, 2024 5:02:40 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		TDELVA	Nov 13, 2024 5:02:40 PM	No	
302,000 - Check Toe-In and Record Reading	Done		TDELVA	Nov 13, 2024 5:02:40 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	na	TDELVA	Nov 13, 2024 5:02:40 PM	No	
303,000 - FRA Service Davco Type Water Separators (Secondary Fuel Filter)	-	na	TDELVA	Nov 13, 2024 5:02:40 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No	Tune Up	TDELVA	Nov 13, 2024 5:02:40 PM	Yes	57548607
305,000 - FRA Change Differential Fluid	No		TDELVA	Nov 13, 2024 5:02:40 PM	No	
306,000 - Change Spark Plugs	Done	need spark plugs	TDELVA	Nov 13, 2024 5:02:40 PM	Yes	57548607

Activity Sub Total

Activity 20 Sub Total	
Parts:	20.26
Labor:	43.55
Labor Hours:	0.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**63.81**

Work Order Footer

Work Order 57490399 Total	
Parts:	20.26
Labor:	96.85
Labor Hours:	1.49
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**117.11**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 5

Work Order No. 57515790
Invoice No. 55345 - 57515790

Client Department:
Department: 55345M
Work Order Description
Road Call-BUS SHUTT OFF / NO START CONDITION
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 200,566 - DH

Chronology		
Reported	Oct 4, 2024 12:44:00 PM	Oct 4, 2024 12:44:00 PM
Started	Oct 4, 2024 12:46:00 PM	
Completed	Nov 13, 2024 2:39:00 PM	Nov 13, 2024 2:39:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction: Line 20 Road call tow truck bringing in no start

Replace fuel pump and throttle Body use bus still not start need to checkout batteries they have low voltage completed Line 30 Change right side turbo connector leaking

Replace both right side bottom connector completed Line 40 Trying to reprogram the pmc unable bus stills not start

Need to do some more diagnostic complete Line 50 Check For No Start. Check found code PO107 Map Sensor Circuit low & PO192 Fuel Rail Sensor Circuit Low B-1 & PO6-A-8 Sensor Reference Voltage -C- Circuit Range Performance Check PID- Read 0.57 volts Wiggle wire fuel Pressure Sensor wire harness PID signal Rise to (5.00) Reference volts Recommend. Fuel pressure Sensor. But intake have to remove But intake bolts are corroded. Line 60 Road call bus won¿t start

Diagnostic the found no fuel going to the fuel rail bad fuel rail switch

Replace fuel rail switch and test driving the bus completed

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 5

Work Order No. 57515790
Invoice No. 55345 - 57515790

Client Department:
Department: 55345M
Work Order Description
Road Call-BUS SHUTT OFF / NO START CONDITION
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 200,566 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL-VEHICLE TOWED FROM WEST PALM BEACH AREA
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:
Line 10 ROAD CALL-VEHICLE TOWED FROM WEST PALM BEACH AREA, PER DRIVER VEHICLE STALLED NOS START CONDITION.

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 5

Work Order No. 57515790
Invoice No. 55345 - 57515790

Client Department:
Department: 55345M
Work Order Description
Road Call-BUS SHUTT OFF / NO START CONDITION
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 200,566 - DH

Activity Header
Activity: 20 012 AXLE, NON-DRIVEN, REAR (POWER UNITS & TRAILERS)
Activity Note: No start
Reason for Repair: 39 Natural Causes
Work Accomplished: 04 Replace Rebuilt
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Oct-24	DSP-TOWING	DIRECT PURCHASES FOR SERVICES TOWING	1	306.9	306.9
11-Oct-24	DSP-TOWING	DIRECT PURCHASES FOR SERVICES TOWING	1	287.1	287.1
13-Nov-24	FEP648MF	BATTERY, GROUP-48, 680CCA, 120MIN-RESERVE, DEKA	2	123.12	246.24
15-Oct-24	DSP-TOWING	DIRECT PURCHASES FOR SERVICES TOWING	1	287.1	287.1
15-Oct-24	DSP-TOWING	DIRECT PURCHASES FOR SERVICES TOWING	1	320.1	320.1

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Oct-24	Pierre,Hubert J	6.12	65	397.8
13-Nov-24	Pierre,Hubert J	2.4	65	156
14-Oct-24	Arthurs,Durvin	0.07	65	4.55
15-Oct-24	Arthurs,Durvin	2.92	65	189.8
11-Oct-24	Arthurs,Durvin	2.03	65	131.95
04-Oct-24	Pierre,Hubert J	4.3	65	279.5
13-Nov-24	Pierre,Hubert J	2.47	65	160.55

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	873.24
Labor:	1,320.15
Labor Hours:	20.31
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2,193.39**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 5

Work Order No. 57515790
Invoice No. 55345 - 57515790

Client Department:
Department: 55345M
Work Order Description
Road Call-BUS SHUTT OFF / NO START CONDITION
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 200,566 - DH

Activity Header
Activity: 30 044 FUEL SYSTEM
Activity Note: INSPECT AND REPAIR DRIVABILITY CONDITION
Reason for Repair: 01 Breakdown
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Nov-24	TPMS62	SENSOR, MONITORING, PRESSURE, TIRE	1	42.77	42.77
21-Nov-24	CK4Z-9H307-F	PUMP, FUEL, TRANSIT	1	581.64	581.64

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Oct-24	Pierre,Hubert J	8.15	65	529.75
08-Oct-24	Pierre,Hubert J	0.02	65	1.3

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	624.41
Labor:	531.05
Labor Hours:	8.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1,155.46**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 5

Work Order No. 57515790
Invoice No. 55345 - 57515790

Client Department:
Department: 55345M
Work Order Description
Road Call-BUS SHUTT OFF / NO START CONDITION
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 200,566 - DH

Activity Header
Activity: 40 041 INTAKE, AIR
Activity Note: Remove &Replace intake manifold
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Nov-24	BL3Z-9F972-B	SENSOR, PRESSURE, FUEL, FOCUS	1	67.42	67.42

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Nov-24	Pierre,Hubert J	0.67	65	43.55
15-Oct-24	Arthurs,Durvin	2.28	65	148.2

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	67.42
Labor:	191.75
Labor Hours:	2.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**259.17**

Work Order Footer

Work Order 57515790 Total	
Parts:	1,565.07
Labor:	2,042.95
Labor Hours:	31.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**3,608.02**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57498814
Invoice No. 55345 - 57498814

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
all rear TIRES		Ford Transit	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	199,120 - DH

Chronology		
Reported	Sep 13, 2024 12:31:00 PM	Sep 13, 2024 12:31:00 PM
Started	Sep 13, 2024 1:00:00 PM	
Completed	Sep 13, 2024 7:15:00 PM	Sep 13, 2024 7:15:00 PM
Down Time		

Work Order Notes

Line 10 Tires thread was 3 and 4

Replaced all rear tires with new tires Line 20 Abs light came on, scanned for codes

Left and rear wheel speed sensor bad, wires were damaged/cut

Repaired both wheel speed sensors connection wires, abs light went off

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: NBARRETO Performed on: 13-SEP-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		NBARRETO	Sep 13, 2024 2:36:57 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NBARRETO	Sep 13, 2024 2:36:57 PM	No	
400 - Are you wearing the appropriate PPE?	Done		NBARRETO	Sep 13, 2024 2:36:57 PM	No	
700 - Have you performed the proper LOTO?	Done		NBARRETO	Sep 13, 2024 2:36:57 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		NBARRETO	Sep 13, 2024 2:36:57 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		NBARRETO	Sep 13, 2024 2:36:57 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57498814
Invoice No. 55345 - 57498814

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
all rear TIRES		Ford Transit	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	199,120 - DH

Activity Header
Activity:20 017/001/000 TIRE, PNEUMATIC
Activity Note: FRONT TIRES
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: FRONT TIRES
Task: FRONT TIRE Performed by: NBARRETO Performed on: 13-SEP-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - First Torque Tire Position		na	NBARRETO	Sep 13, 2024 7:15:26 PM	No	
110 - First Torque Date/Time		na	NBARRETO	Sep 13, 2024 7:15:26 PM	No	
120 - First Torque Tool ID		na	NBARRETO	Sep 13, 2024 7:15:26 PM	No	
130 - First Torque Applied	Foot Pounds	na	NBARRETO	Sep 13, 2024 7:15:26 PM	No	
140 - Second Torque Tire Position		na	NBARRETO	Sep 13, 2024 7:15:26 PM	No	
150 - Second Torque Date/Time		na	NBARRETO	Sep 13, 2024 7:15:26 PM	No	
160 - Second Torque Tool ID		na	NBARRETO	Sep 13, 2024 7:15:26 PM	No	
170 - Second Torque Applied	Foot Pounds	na	NBARRETO	Sep 13, 2024 7:15:26 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00

	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57498814
Invoice No. 55345 - 57498814

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
all rear TIRES		Ford Transit	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	199,120 - DH

Activity Header
Activity:30 017/001/000 TIRE, PNEUMATIC
Activity Note: REAR TIRES
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Sep-24	131196995	TIRE, 195/75R16, WORKHORSE, HTL, WRANGLER, GOODYEAR	4	120	480

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Sep-24	Nicolas Barreto	5.42	65	352.3

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: REAR TIRES
Task: REAR TIRE Performed by: NBARRETO Performed on: 13-SEP-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - First Torque Tire Position		na	NBARRETO	Sep 13, 2024 7:14:05 PM	No	
110 - First Torque Date/Time		na	NBARRETO	Sep 13, 2024 7:14:05 PM	No	
120 - First Torque Tool ID		na	NBARRETO	Sep 13, 2024 7:14:05 PM	No	
130 - First Torque Applied	Foot Pounds	na	NBARRETO	Sep 13, 2024 7:14:05 PM	No	
140 - Second Torque Tire Position		na	NBARRETO	Sep 13, 2024 7:14:05 PM	No	
150 - Second Torque Date/Time		na	NBARRETO	Sep 13, 2024 7:14:05 PM	No	
160 - Second Torque Tool ID		na	NBARRETO	Sep 13, 2024 7:14:05 PM	No	
170 - Second Torque Applied	Foot Pounds	na	NBARRETO	Sep 13, 2024 7:14:05 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	480.00
	Labor:	352.30
	Labor Hours:	5.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**832.30**

Work Order Footer

Work Order 57498814 Total	
Parts:	480.00
Labor:	352.30
Labor Hours:	5.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**832.30**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57490344
Invoice No. 55345 - 57490344

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	197,000 - DH

Chronology		
Reported	Sep 3, 2024 9:24:22 PM	Sep 3, 2024 9:24:22 PM
Started	Sep 3, 2024 10:42:00 PM	
Completed	Sep 8, 2024 10:26:42 PM	Sep 8, 2024 10:26:42 PM
Down Time		

Work Order Notes

Line 10 Needs wiper blades ,rear AC filter dirty
Wiper blades bad,AC filter needs to be clean
Replace wiper blades 20 CA, 28 CA
Clean AC filter and reinstalled

Activity Header
Activity: 10 002/035/015 BLADE, WIPER
Activity Note: needs wiper blades
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Sep-24	20CA	BLADE, WIPER, WINDSHIELD	1	6.62	6.62
03-Sep-24	28CA	BLADE, WIPER, WINDSHEILD	1	6.25	6.25

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Sep-24	Gaspard,Ronald	0.25	65	16.25

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	12.87
Labor:	16.25
Labor Hours:	0.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**29.12**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57490344
Invoice No. 55345 - 57490344

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	197,000 - DH

Activity Header
Activity: 20 001/001 AIR CONDITIONING
Activity Note: rear AC filter dirty
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57490344 Total	
Parts:	12.87
Labor:	16.25
Labor Hours:	0.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**29.12**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57463280
Invoice No. 55345 - 57463280

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	197,000 - DH

Chronology		
Reported	Sep 3, 2024 12:00:00 AM	Sep 3, 2024 12:00:00 AM
Started	Sep 3, 2024 8:12:00 PM	
Completed	Sep 3, 2024 10:37:00 PM	Sep 3, 2024 10:37:00 PM
Down Time		

Work Order Notes

Line 10 PMA
Service
Performed PMA service
Oil filter LF 17531 qty1
Engine oil 10w30 qty 6 QTs
Add washer fluid

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 03-SEP-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		RGASPARD	Sep 3, 2024 8:06:19 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Sep 3, 2024 8:06:19 PM	No	
400 - Are you wearing the appropriate PPE?	Done		RGASPARD	Sep 3, 2024 8:06:19 PM	No	
700 - Have you performed the proper LOTO?	Done		RGASPARD	Sep 3, 2024 8:06:19 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Sep 3, 2024 8:06:19 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Sep 3, 2024 8:06:19 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57463280
Invoice No. 55345 - 57463280

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	197,000 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Sep-24	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	3.4	3.4

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Sep-24	Gaspard,Ronald	1.7	65	110.5

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 03-SEP-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
10,800 - CHECK_All Destination Signage	-	NA	RGASPARD	Sep 3, 2024 9:24:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
20,200 - CHECK_Public Address System	-	NA	RGASPARD	Sep 3, 2024 9:24:51 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	-	NA	RGASPARD	Sep 3, 2024 9:24:51 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	NA	RGASPARD	Sep 3, 2024 9:24:51 PM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	NA	RGASPARD	Sep 3, 2024 9:24:51 PM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	NA	RGASPARD	Sep 3, 2024 9:24:51 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	NA	RGASPARD	Sep 3, 2024 9:24:51 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	NA	RGASPARD	Sep 3, 2024 9:24:51 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	-	NA	RGASPARD	Sep 3, 2024 9:24:51 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
21,500 - INSPECT_High Idle Control	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	-	NA	RGASPARD	Sep 3, 2024 9:24:51 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	NA	RGASPARD	Sep 3, 2024 9:24:51 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	RGASPARD	Sep 3, 2024 9:24:51 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
33,000 - CSF (Curb Side Front)	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Sep 3, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:24:51 PM		
33,040 - INSPECT_Wiper Blades, Arms	Done	needs wiper blades	RGASPARD	Sep 3, 2024 9:24:51 PM	Yes	57490344
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
40,700 - CHECK_Passenger Stop Request System	-	NA	RGASPARD	Sep 3, 2024 9:24:51 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done	rear AC filter dirty	RGASPARD	Sep 3, 2024 9:24:51 PM	Yes	57490344
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
50,400 - LUBE_All Chassis Components	-	NA	RGASPARD	Sep 3, 2024 9:24:51 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	40 Pounds per Square Inch		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	40 Pounds per Square Inch		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.229 Inch		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.229 Inch		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.799 Inch		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.799 Inch		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	-	NA	RGASPARD	Sep 3, 2024 9:24:51 PM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	-	NA	RGASPARD	Sep 3, 2024 9:24:51 PM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Sep 3, 2024 9:24:51 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	3.40
Labor:	110.50
Labor Hours:	1.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**113.90**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57463280
Invoice No. 55345 - 57463280

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	197,000 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Sep-24	75050	OIL, ENGINE, 5W/30	6	2.81	16.86

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Sep-24	Gaspard,Ronald	0.53	65	34.45

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: RGASPARD Performed on: 03-SEP-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Sep 3, 2024 9:56:38 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Sep 3, 2024 9:56:38 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Sep 3, 2024 9:56:38 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Sep 3, 2024 9:56:38 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Sep 3, 2024 9:56:38 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Sep 3, 2024 9:56:38 PM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	-	NA	RGASPARD	Sep 3, 2024 9:56:38 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Sep 3, 2024 9:56:38 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Sep 3, 2024 9:56:38 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	16.86
Labor:	34.45
Labor Hours:	0.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**51.31**

Work Order Footer

Work Order 57463280 Total	
Parts:	20.26
Labor:	144.95
Labor Hours:	2.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**165.21**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57485181
Invoice No. 55345 - 57485181

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
rear ac issue		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	195,709 - DH

Chronology		
Reported	Aug 27, 2024 8:46:00 PM	Aug 27, 2024 8:46:00 PM
Started	Aug 27, 2024 8:53:00 PM	
Completed	Aug 28, 2024 1:01:00 PM	Aug 28, 2024 1:01:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction: Line 20 Vehicle came in for AC issue. Check unit completed front and rear no problem found so I call my supervisor to look at it white me A C. Working properly at this time Line 30
AC system diagnosis reveals that Rear A/C flashing LC.

The NFC reader test shows that the NFC reader is working momentarily. The GEOTAB is good but NFC reader needs to be replaced. Line 40 Recover system and recharge with right amount of Pag oil and Freon, tested, all okay at this time Line 50 Removed and replaced Geotab reader

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 28-AUG-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Aug 28, 2024 12:59:47 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Aug 28, 2024 12:59:47 PM	No	
400 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Aug 28, 2024 12:59:47 PM	No	
700 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Aug 28, 2024 12:59:47 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Aug 28, 2024 12:59:47 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Aug 28, 2024 12:59:47 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57485181
Invoice No. 55345 - 57485181

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
rear ac issue		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	195,709 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear AC issue
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Aug-24	Junior Hurst	0.63	65	40.95
28-Aug-24	Rodriguez,Raul	1.82	65	118.3

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	159.25
Labor Hours:	2.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**159.25**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57485181
Invoice No. 55345 - 57485181

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
rear ac issue		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	195,709 - DH

Activity Header
Activity: 25 036 DEVICES, INFORMATION, SUPPLEMENTAL
Activity Note: Geotab reader
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Aug-24	Rodriguez,Raul	0.7	65	45.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	0.00
Labor:	45.50
Labor Hours:	0.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**45.50**

Work Order Footer

Work Order 57485181 Total	
Parts:	0.00
Labor:	204.75
Labor Hours:	3.15
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**204.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57465594
Invoice No. 55345 - 57465594

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
rear ac ha and tire light is on		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	193,000 - DH

Chronology		
Reported	Aug 5, 2024 8:02:00 AM	Aug 5, 2024 8:02:00 AM
Started	Aug 5, 2024 8:05:00 AM	
Completed	Aug 5, 2024 11:56:00 AM	Aug 5, 2024 11:56:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction: Line 20 Driver said rear ac not working and tire light is on

Ac need new dryer tire need a sensor

Replaced tire sensor reprogrammed tire and replaced dryer vacuum and recharge completed Line 30 189752 qty1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 05-AUG-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		HPIERRE	Aug 5, 2024 11:54:51 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Aug 5, 2024 11:54:51 AM	No	
400 - Are you wearing the appropriate PPE?	Done		HPIERRE	Aug 5, 2024 11:54:51 AM	No	
700 - Have you performed the proper LOTO?	Done		HPIERRE	Aug 5, 2024 11:54:51 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Aug 5, 2024 11:54:51 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Aug 5, 2024 11:54:51 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57465594
Invoice No. 55345 - 57465594

Client Department:
Department: 55345M
Work Order Description
rear ac ha and tire light is on
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 193,000 - DH

Activity Header
Activity: 15 174/000/000 BODY, BUS
Activity Note: Rear ac ah and tire light on
Reason for Repair: 41 Abuse of Equipment
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Aug-24	1412015	ACCUMULATOR, A/C	1	14.25	14.25
13-Aug-24	FR3Z-1A189-C	SENSOR, MONITOR, PRESSURE, TIRE	1	46.66	46.66

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Aug-24	Pierre,Hubert J	3.8	65	247

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	60.91
Labor:	247.00
Labor Hours:	3.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**307.91**

Work Order Footer

Work Order 57465594 Total	
Parts:	60.91
Labor:	247.00
Labor Hours:	3.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**307.91**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 5

Work Order No. 57450041
Invoice No. 55345 - 57450041

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
BUS IS NOT RUNNING RIGHT/ TRANSMISSION ISSUE		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	191,803 - DH

Chronology		
Reported	Jul 16, 2024 10:02:00 PM	Jul 16, 2024 10:02:00 PM
Started	Jul 16, 2024 10:05:00 PM	
Completed	Aug 2, 2024 11:44:00 AM	Aug 2, 2024 11:44:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Check transmission.

Cause: Unknown.

Correction: Road tested vehicle and found that the transmission shutters upon take off acceleration. OOS for further diagnosis. Line 20 Complaint Check Transmission. Road Test Bus keep down Shifting.. Perform transmission relearn bus neutral up no forward /No Reverse. Scan Found Code PO 751 Shift Solenoid A Stuck Off / P2700 Transmission. Friction Element A apply Time Range performance. Bad transmission. Line 30 Replaced turbo line connector Line 40 Replaced both front sway bar link Line 50 Replaced transmission and clear all codes Halt and Relearned transmission

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 17-JUL-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		DARTHURS	Jul 17, 2024 7:48:55 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jul 17, 2024 7:48:55 AM	No	
400 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jul 17, 2024 7:48:55 AM	No	
700 - Have you performed the proper LOTO?	Done		DARTHURS	Jul 17, 2024 7:48:55 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jul 17, 2024 7:48:55 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 17, 2024 7:48:55 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 5

Work Order No. 57450041
Invoice No. 55345 - 57450041

Client Department:
Department: 55345M
Work Order Description
BUS IS NOT RUNNING RIGHT/ TRANSMISSION ISSUE
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 191,803 - DH

Activity Header
Activity: 15 027 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: Check transmission.
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Aug-24	LK4Z-7000-DA	TRANSMISSION, AUTOMATIC, 10R80	1	4,528.9	4,528.9

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Jul-24	Arthurs,Durvin	1.35	65	87.75
16-Jul-24	Earl Johnson	0.78	65	50.7

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	4,528.90
Labor:	138.45
Labor Hours:	2.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4,667.35**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 5

Work Order No. 57450041
Invoice No. 55345 - 57450041

Client Department:
Department: 55345M
Work Order Description
BUS IS NOT RUNNING RIGHT/ TRANSMISSION ISSUE
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 191,803 - DH

Activity Header
Activity:25 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: TRANSMISSION REPLACEMENT
Reason for Repair: 01 Breakdown
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Jul-24	Delva,Terry	2	65	130
31-Jul-24	Delva,Terry	1.45	65	94.25
31-Jul-24	Delva,Terry	2.15	65	139.75
31-Jul-24	Delva,Terry	3	65	195

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	0.00
Labor:	559.00
Labor Hours:	8.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**559.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 5

Work Order No. 57450041
Invoice No. 55345 - 57450041

Client Department:
Department: 55345M
Work Order Description
BUS IS NOT RUNNING RIGHT/ TRANSMISSION ISSUE
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 191,803 - DH

Activity Header
Activity: 35 042/000/000 COOLING SYSTEM
Activity Note: Turbo line leaking
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
31-Jul-24	BL3Z-6A968-C	CONNECTOR, LINE, OIL, TURBOCHARGER, RH, F350 HD	1	9.49	9.49
31-Jul-24	BK2Z-5K484-C	LINK, BAR, SWAY, FRONT	2	24.42	48.84

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Jul-24	Delva,Terry	0.83	65	53.95

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 35 Sub Total	
Parts:	58.33
Labor:	53.95
Labor Hours:	0.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**112.28**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 5

Work Order No. 57450041
Invoice No. 55345 - 57450041

Client Department:
Department: 55345M
Work Order Description
BUS IS NOT RUNNING RIGHT/ TRANSMISSION ISSUE
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 191,803 - DH

Activity Header
Activity: 45 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear AC Flashing HA
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 51 Inoperative
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Aug-24	Delva,Terry	1.57	65	102.05

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 45 Sub Total	
Parts:	0.00
Labor:	102.05
Labor Hours:	1.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**102.05**

Work Order Footer

Work Order 57450041 Total	
Parts:	4,587.23
Labor:	853.45
Labor Hours:	13.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5,440.68**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57463258
Invoice No. 55345 - 57463258

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	193,000 - DH

Chronology		
Reported	Aug 1, 2024 1:17:07 PM	Aug 1, 2024 1:17:07 PM
Started		
Completed	Aug 1, 2024 3:04:00 PM	Aug 1, 2024 3:04:00 PM
Down Time		

Work Order Notes

Line 10 Replaced rear top clearance lights
Replaced black step-well light (charge part)*
Need MDT

Activity Header
Activity: 10 003/001 GAUGES & WARNING DEVICES
Activity Note: rear top clearance lights out
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Aug-24	MCL12RK	LAMP, MARKER/CLEARANCE, RED	2	8.82	17.64

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	17.64
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**17.64**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57463258
Invoice No. 55345 - 57463258

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	193,000 - DH

Activity Header
Activity: 20 034/003/000 LAMPS, SIGNAL, PARKING & BACKUP
Activity Note: Door Step light out
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Aug-24	445311	LAMP, ADA, HOUSING, BLACK	2	38.73	77.46

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	77.46
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**77.46**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57463258
Invoice No. 55345 - 57463258

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	193,000 - DH

Activity Header
Activity: 30 002/008/001 PANEL, DASH
Activity Note: Door open/close switch
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57463258 Total	
Parts:	95.10
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**95.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57435218
Invoice No. 55345 - 57435218

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	193,000 - DH

Chronology		
Reported	Aug 1, 2024 12:00:00 AM	Aug 1, 2024 12:00:00 AM
Started	Aug 1, 2024 11:07:00 AM	
Completed	Aug 1, 2024 1:28:00 PM	Aug 1, 2024 1:28:00 PM
Down Time		

Work Order Notes

Line 10 Pma

Service due

Performed and completed Pma

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 01-AUG-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		TDELVA	Aug 1, 2024 11:08:44 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Aug 1, 2024 11:08:44 AM	No	
400 - Are you wearing the appropriate PPE?	Done		TDELVA	Aug 1, 2024 11:08:44 AM	No	
700 - Have you performed the proper LOTO?	Done		TDELVA	Aug 1, 2024 11:08:44 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Aug 1, 2024 11:08:44 AM	No	
1,100 - Have you successfully completed the	Done		TDELVA	Aug 1, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				11:08:44 AM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57435218
Invoice No. 55345 - 57435218

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	193,000 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Aug-24	Delva,Terry	2.17	65	141.05

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: TDELVA Performed on: 01-AUG-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done	rear top clearance lights out	TDELVA	Aug 1, 2024 1:16:50 PM	Yes	57463258
10,400 - !FRA!INSPECT_Back Up Alarm	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done	Door Step light out	TDELVA	Aug 1, 2024 1:16:50 PM	Yes	57463258
10,800 - CHECK_All Destination Signage	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
20,200 - CHECK_Public Address System	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	-	na	TDELVA	Aug 1, 2024 1:16:50 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	na	TDELVA	Aug 1, 2024 1:16:50 PM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	na	TDELVA	Aug 1, 2024 1:16:50 PM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	na	TDELVA	Aug 1, 2024 1:16:50 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	na	TDELVA	Aug 1, 2024 1:16:50 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	na	TDELVA	Aug 1, 2024 1:16:50 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	-	na	TDELVA	Aug 1, 2024 1:16:50 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
21,500 - INSPECT_High Idle Control	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done	Door open/close switch	TDELVA	Aug 1, 2024 1:16:50 PM	Yes	57463258
21,800 - INSPECT_Parking Brake Operation	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	-	na	TDELVA	Aug 1, 2024 1:16:50 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for	Done		TDELVA	Aug 1, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Proper Routing/Chafing/Securement				1:16:50 PM		
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
31,000 - SSF (Street Side Front)	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
32,000 - Engine Inspection	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	na	TDELVA	Aug 1, 2024 1:16:50 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	TDELVA	Aug 1, 2024 1:16:50 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
32,100 - INSPECT_Intake System	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.9 Volt*		TDELVA	Aug 1, 2024 1:16:50 PM	No	
33,000 - CSF (Curb Side Front)	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
33,030 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
40,700 - CHECK_Passenger Stop Request System	-	na	TDELVA	Aug 1, 2024 1:16:50 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
50,400 - LUBE_All Chassis Components	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
50,700 - INSPECT_Tire Condition	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		TDELVA	Aug 1, 2024 1:16:50 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	60 Pounds per Square Inch		TDELVA	Aug 1, 2024 1:16:50 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		TDELVA	Aug 1, 2024 1:16:50 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	60 Pounds per Square Inch		TDELVA	Aug 1, 2024 1:16:50 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	Aug 1, 2024 1:16:50 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	Aug 1, 2024 1:16:50 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.27 Inch		TDELVA	Aug 1, 2024 1:16:50 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.27 Inch		TDELVA	Aug 1, 2024 1:16:50 PM	No	
52,100 - INSPECT_Vibration Damper	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,600 - INSPECT_Tire Condition	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	-	na	TDELVA	Aug 1, 2024 1:16:50 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	6 32nds of an inch		TDELVA	Aug 1, 2024 1:16:50 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	6 32nds of an inch		TDELVA	Aug 1, 2024 1:16:50 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	60 Pounds per Square Inch		TDELVA	Aug 1, 2024 1:16:50 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	60 Pounds per Square Inch		TDELVA	Aug 1, 2024 1:16:50 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	5 32nds of an inch		TDELVA	Aug 1, 2024 1:16:50 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	5 32nds of an inch		TDELVA	Aug 1, 2024 1:16:50 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	60 Pounds per Square Inch		TDELVA	Aug 1, 2024 1:16:50 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	60 Pounds per Square Inch		TDELVA	Aug 1, 2024 1:16:50 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	Aug 1, 2024 1:16:50 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	Aug 1, 2024 1:16:50 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.127 Inch		TDELVA	Aug 1, 2024 1:16:50 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.127 Inch		TDELVA	Aug 1, 2024 1:16:50 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		TDELVA	Aug 1, 2024 1:16:50 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	141.05
Labor Hours:	2.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**141.05**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57435218
Invoice No. 55345 - 57435218

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	193,000 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Aug-24	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	3.39	3.39
01-Aug-24	75050	OIL, ENGINE, 5W/30	6	2.81	16.86

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Aug-24	Delva,Terry	0.15	65	9.75

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: TDELVA Performed on: 01-AUG-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		TDELVA	Aug 1, 2024 1:21:48 PM	No	
101,000 - FRA Change Oil Filters	Yes		TDELVA	Aug 1, 2024 1:21:48 PM	No	
102,000 - FRA Drain Engine Oil	Yes		TDELVA	Aug 1, 2024 1:21:48 PM	No	
103,000 - FRA Check Transmission Fluid	Done		TDELVA	Aug 1, 2024 1:21:48 PM	No	
104,000 - Lubricate Chassis	Done		TDELVA	Aug 1, 2024 1:21:48 PM	No	
105,000 - Replace or Clean A/C Filters	Done		TDELVA	Aug 1, 2024 1:21:48 PM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	-	na	TDELVA	Aug 1, 2024 1:21:48 PM	No	
107,000 - FRA Change Primary Fuel Filter	No		TDELVA	Aug 1, 2024 1:21:48 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		TDELVA	Aug 1, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				1:21:48 PM		

Activity Sub Total

Activity 20 Sub Total	
Parts:	20.25
Labor:	9.75
Labor Hours:	0.15
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**30.00**

Work Order Footer

Work Order 57435218 Total	
Parts:	20.25
Labor:	150.80
Labor Hours:	2.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**171.05**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56798440
Invoice No. 55345 - 56798440

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FIRST TRANSIT AC INSPECTION		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	191,456 -

Chronology		
Reported	Jul 15, 2024 10:04:14 AM	Jul 15, 2024 10:04:14 AM
Started		
Completed	Jul 15, 2024 12:25:00 PM	Jul 15, 2024 12:25:00 PM
Down Time		

Work Order Notes

Line 10
- [ ] AC Inspection
- [ ] Inspected allelectrical components. Ok
- [ ] Inspected all lines and hoses. Ok
- [ ] Inspected both AC compressors. Ok
- [ ] Inpected both condensers. Ok
- [ ] Inspected all fans and blows on every speed. Ok
- [ ] No leaks.
- [ ] Front AC temp. 57
- [ ] Rear AC temp. 52
- [ ] Outside temp. 81
- [ ] Returned to services

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assesment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assesment
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 15-JUL-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Jul 15, 2024 12:19:28 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Jul 15, 2024 12:19:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
400 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Jul 15, 2024 12:19:28 PM	No	
700 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Jul 15, 2024 12:19:28 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Jul 15, 2024 12:19:28 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Jul 15, 2024 12:19:28 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56798440
Invoice No. 55345 - 56798440

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FIRST TRANSIT AC INSPECTION		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	191,456 -

Activity Header
Activity: 10 001/001/001 AIR CONDITIONING
Activity Note: FIRST TRANSIT AC INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: FIRST TRANSIT AC INSPECTION
Task: FIRST TRANSIT AC INSPECTION Performed by: NPIERRE-LOUIS Performed on: 15-JUL-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 VISUAL INSPECTION	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
10,100 - CHECK PHYSICAL DAMAGE, MISSING PARTS	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
10,200 - CHECK REFRIGERANT HOSES FOR CHAFING	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
10,300 - CHECK EVAPORATOR AND CONDENSER FOR OBSTRUCTIONS	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
10,400 - CHECK OPERATION OF FAST IDLE	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
20,000 - SECTION 2 DIAGNOSE THE SYSTEM CONDITION	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
20,100 - ATTACH GAUGES AND RUN SYSTEM 10 MINUTES	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
20,200 - CHECK FOR EVEN AIR DISTRIBUTION	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
20,300 - CHECK FOR PROPER OPERATION OF ALL HVAC MODES	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
20,400 - CHECK DRIVERS A/C SYSTEM	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
20,500 - RECORD AMBIENT TEMPERATURE BEFORE	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,600 - RECORD DISCHARGE PRESSURE BEFORE	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
20,700 - RECORD SUCTION PRESSURE BEFORE	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
20,710 - RECORD OUTLET TEMPERATURE BEFORE	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
20,800 - CHECK HIGH AND LOW PRESSURE CUTOUT SWITCHES FOR LEAKS	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
30,000 - SECTION 3 COMPRESSOR OPERATIONAL INSPCTION	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
30,100 - CHECK FOR UNUSUAL NOISES	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
30,200 - CHECK CLUTCH RESISTANCE READING	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
30,300 - CHECK AIR GAP IN COMPRESSOR CLUTCH	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
30,400 - CHECK COMPRESSOR MOUNTING AND ALIGHMENT	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
30,500 - INSPECT COMPRESSOR BELT(S) OR DRIVE SYSTEM	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
30,600 - CHECK FOR CRACKS AND WEAR	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
30,700 - CHECK FOR PROPER WIDTH AND LENGTH	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
30,800 - CHECK FOR PROPER ALIGNMENT	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
40,000 - SECTION 4 LEAK TEST SYSTEM	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
40,100 - CHICK A/C LINES WITH AN ELECTRONIC LEAK DETECTOR	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
40,200 - CHECK HOSES, FITTINGS, VALVES AND COMPRESSOR SHAFT SEAL	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
40,300 - CHECK HEATER HOSES FOR LEAKS	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
50,000 - SECTION 5 SYSTEM CONTAMINATION	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
50,100 - CHECK INLINE DRIER	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
50,200 - CHECK ACCUMULATOR	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
60,000 - SECTION 6 CHARGE SYSTEM	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
60,100 - IF CHARGING IS REQUIRED, CHARGE BY WEIGHT	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
60,200 - CHECK FOR LEAKS AFTER CHARGING	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
70,000 - SECTION 7 FAN MOTORS	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
70,100 - CHECK SEALED MOTORS FOR PROPER OPERATION	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
70,200 - INSPECT BLOWER WHEELS	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,300 - CHECK ELECTRICAL WIRING & CONNECTIONS	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
80,000 - SECTION 8 OPERATE SYSTEM	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
80,100 - CHECK FOR PROPER HEATING & COOLING	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
80,200 - CHECK TEMPERATURE CONTROLS	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
80,300 - CHECK DEFROST MODE	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
90,000 - SECTION 9 PERFORMANCE TEST READINGS	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
90,100 - RECORD AMBIENT TEMPERATURE READINGS AFTER	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
90,200 - RECORD DISCHARGE PRESSURE AFTER	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
90,300 - RECORD SUCTION PRESSURE AFTER	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
90,400 - RECORD OUTLET TEMPERATURE	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
100,000 - SECTION 10 RESTORE SYSTEM	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
100,100 - DISCONNECT GAUGES	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	
100,200 - CLOSE ALL PANELS, DOOR, ETC.	Done		NPIERRE-LOUIS	Jul 15, 2024 12:22:49 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 56798440 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57435214
Invoice No. 55345 - 57435214

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	189,348 - DH

Chronology		
Reported	Jun 27, 2024 10:46:41 AM	Jun 27, 2024 10:46:41 AM
Started	Jul 15, 2024 9:14:00 AM	
Completed	Jul 15, 2024 12:24:00 PM	Jul 15, 2024 12:24:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: front AC not blowing

Cause : front AC blower motor

Correction: replaced front AC blower motor everything ok at this time

Parts : BK3z- 19805-c please charge

Activity Header
Activity: 10 036/008/002 CAMERA, SYSTEM, SURVEILLANCE
Activity Note: Angel Trax camera system. Only work cam. 5
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57435214
Invoice No. 55345 - 57435214

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	189,348 - DH

Activity Header
Activity: 20 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: FRONT AC NOT BLOWING AIR
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Jul-24	NELSON PIERRE-LOUIS	3.17	65	206.05

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	206.05
Labor Hours:	3.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**206.05**

Work Order Footer

Work Order 57435214 Total	
Parts:	0.00
Labor:	206.05
Labor Hours:	3.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**206.05**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57411739
Invoice No. 55345 - 57411739

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	189,348 - DH

Chronology		
Reported	Jun 26, 2024 12:00:00 AM	Jun 26, 2024 12:00:00 AM
Started	Jun 27, 2024 7:52:00 AM	
Completed	Jun 27, 2024 10:48:00 AM	Jun 27, 2024 10:48:00 AM
Down Time		

Work Order Notes

Line 10 PM.

Perform pm B service, lube front end, tire rotation, torque and re torque tires (140 f/p), R&R engine oil and filter, road test, all okay at this time.

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 27-JUN-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Jun 27, 2024 10:15:36 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Jun 27, 2024 10:15:36 AM	No	
400 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Jun 27, 2024 10:15:36 AM	No	
700 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Jun 27, 2024 10:15:36 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Jun 27, 2024 10:15:36 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Jun 27, 2024 10:15:36 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57411739
Invoice No. 55345 - 57411739

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	189,348 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Jun-24	Rodriguez,Raul	2.32	65	150.8

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: RAURODRIGUEZ Performed on: 27-JUN-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RAURODRIGUEZ	Jun 27, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:47:37 AM		
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
10,800 - CHECK_All Destination Signage	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
20,200 - CHECK_Public Address System	-	na	RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	na	RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	na	RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
20,800 - RECORD_Brake Performance	FEET	na	RAURODRIGUEZ	Jun 27,	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Test Distance				2024 10:47:37 AM		
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	na	RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	na	RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	-	na	RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
21,500 - INSPECT_High Idle Control	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
21,800 - INSPECT_Parking Brake Operation	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	-		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
31,000 - SSF (Street Side Front)	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
32,000 - Engine Inspection	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	na	RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
32,050 - !FRA! INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
32,100 - INSPECT_Intake System	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	13.9 Volt*		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
33,000 - CSF (Curb Side Front)	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
40,000 - SECTION 4 - Interior Inspection	-		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done	Angel Trax camera system. Only work cam. 5	RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	Yes	57435214
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
40,700 - CHECK_Passenger Stop Request System	-	na	RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	-		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
50,400 - LUBE_All Chassis Components	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
50,700 - INSPECT_Tire Condition	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	10 32nds of an inch		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	10 32nds of an inch		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	32nds of an inch	8mm	RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	32nds of an inch	8mm	RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	Inch	30.7mm	RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	Inch	30.7mm	RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
52,100 - INSPECT_Vibration Damper	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
53,600 - INSPECT_Tire Condition	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	6 32nds of an inch		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	6 32nds of an inch		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	6 32nds of an inch		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	32nds of an inch	10mm	RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	32nds of an inch	10mm	RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	Inch	17.5mm	RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	Inch	17.5mm	RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
80,000 - SECTION 8 - PMI Report Completion	-		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,200 - RETURN_Vehicle to Predetermined Location	Done		RAURODRIGUEZ	Jun 27, 2024 10:47:37 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	150.80
Labor Hours:	2.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**150.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57411739
Invoice No. 55345 - 57411739

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	189,348 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMB Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Jun-24	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	3.39	3.39
27-Jun-24	75050	OIL, ENGINE, 5W/30	6	2.73	16.38

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Jun-24	Rodriguez,Raul	0.58	65	37.7

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMB Service
Task: 55345-Medium Duty PMB Inspection Performed by: RAURODRIGUEZ Performed on: 27-JUN-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RAURODRIGUEZ	Jun 27, 2024 10:14:20 AM	No	
101,000 - FRA Change Oil Filters	Yes		RAURODRIGUEZ	Jun 27, 2024 10:14:20 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RAURODRIGUEZ	Jun 27, 2024 10:14:20 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RAURODRIGUEZ	Jun 27, 2024 10:14:20 AM	No	
104,000 - Lubricate Chassis	Done		RAURODRIGUEZ	Jun 27, 2024 10:14:20 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RAURODRIGUEZ	Jun 27, 2024 10:14:20 AM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	-	na	RAURODRIGUEZ	Jun 27, 2024 10:14:20 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RAURODRIGUEZ	Jun 27, 2024 10:14:20 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RAURODRIGUEZ	Jun 27, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:14:20 AM		
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RAURODRIGUEZ	Jun 27, 2024 10:14:20 AM	No	
201,000 - Service Crankcase Breather	Done		RAURODRIGUEZ	Jun 27, 2024 10:14:20 AM	No	
202,000 - FRA Change Water Separator ¿ Secondary Fuel Filters	No	na	RAURODRIGUEZ	Jun 27, 2024 10:14:20 AM	No	
203,000 - FRA Change Automatic Transmission Fluid	No	na	RAURODRIGUEZ	Jun 27, 2024 10:14:20 AM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No	na	RAURODRIGUEZ	Jun 27, 2024 10:14:20 AM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RAURODRIGUEZ	Jun 27, 2024 10:14:20 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	19.77
Labor:	37.70
Labor Hours:	0.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**57.47**

Work Order Footer

Work Order 57411739 Total	
Parts:	19.77
Labor:	188.50
Labor Hours:	2.90
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**208.27**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57424061
Invoice No. 55345 - 57424061

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
No Start		Ford Transit	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	187,659 - DH

Chronology		
Reported	Jun 14, 2024 7:54:00 AM	Jun 14, 2024 7:54:00 AM
Started	Jun 14, 2024 7:57:00 AM	
Completed	Jun 19, 2024 10:41:00 AM	Jun 19, 2024 10:41:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction: Line 20 Bus tow in for now Start/ Scan Found Code PO (106) /PO (107) /PO(120) / PO(124) /PO(236)/(PO237) /PO(532) /PO6A8)/UO(606) /U210) TPP Sensor / Turbo boost sensor& PO6A8 Reference voltage low Check throttle position sensor clear Code code keep returning Swap acceleration pedal Road test code did not return, but transmission keep slamming in gear possible bad transmissions also feel like it locking up. Line 30 Code PO6A8 Keep Returning & PO124 / low Reference Voltage. Swap throttle body& relearned alternator road test Code did not return,

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 19-JUN-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		DARTHURS	Jun 19, 2024 10:40:45 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jun 19, 2024 10:40:45 AM	No	
400 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jun 19, 2024 10:40:45 AM	No	
700 - Have you performed the proper LOTO?	Done		DARTHURS	Jun 19, 2024 10:40:45 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jun 19, 2024 10:40:45 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jun 19, 2024 10:40:45 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57424061
Invoice No. 55345 - 57424061

Client Department:
Department: 55345M
Work Order Description
No Start
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 187,659 - DH

Activity Header
Activity: 15 003 INSTRUMENTS, GAUGES, WARNING & SHUT-DOWN DEVICES
Activity Note: No Start
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Jul-24	DSP-TOWING	DIRECT PURCHASES FOR SERVICES TOWING	1	326.7	326.7

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Jun-24	Arthurs,Durvin	7.25	65	471.25
19-Jun-24	Arthurs,Durvin	2.83	65	183.95
18-Jun-24	Arthurs,Durvin	4.38	65	284.7
14-Jun-24	Arthurs,Durvin	8.12	65	527.8

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	326.70
Labor:	1,467.70
Labor Hours:	22.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1,794.40**

Work Order Footer

Work Order 57424061 Total	
Parts:	326.70
Labor:	1,467.70
Labor Hours:	22.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1,794.40**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 57411728
Invoice No. 55345 - 57411728

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	185,508 - DH

Chronology		
Reported	May 30, 2024 3:30:59 PM	May 30, 2024 3:30:59 PM
Started	May 30, 2024 3:44:00 PM	
Completed	May 30, 2024 6:21:00 PM	May 30, 2024 6:21:00 PM
Down Time		

Work Order Notes

Line 10 Rotate front tires to rear outer and replace two new tires to front of unit size 195/75R16C. Also replace muffler hanger no part # .

Activity Header

Activity: 10 017/003/001 TIRE, CUSHION W/TREAD
Activity Note: REAR OUTER TIRES NEED REPLACE
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-May-24	131196995	TIRE, 195/75R16, WORKHORSE, HTL, WRANGLER, GOODYEAR	2	120	240

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-May-24	Junior Hurst	2.62	65	170.3

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	240.00
Labor:	170.30
Labor Hours:	2.62
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**410.30**

Work Order Footer

Work Order 57411728 Total	
Parts:	240.00
Labor:	170.30
Labor Hours:	2.62
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**410.30**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57391274
Invoice No. 55345 - 57391274

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	185,508 - DH

Chronology		
Reported	May 28, 2024 12:00:00 AM	May 28, 2024 12:00:00 AM
Started	May 30, 2024 1:09:00 PM	
Completed	May 30, 2024 3:41:00 PM	May 30, 2024 3:41:00 PM
Down Time		

Work Order Notes

Line 10 Vehicle came in for service due by mileage change oil filter part # LF17531 also wash rear AC FILTER. And blower out cabin air filter replace one signal light right front # 3157

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 30-MAY-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		JUHURST	May 30, 2024 1:09:02 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	May 30, 2024 1:09:02 PM	No	
400 - Are you wearing the appropriate PPE?	Done		JUHURST	May 30, 2024 1:09:02 PM	No	
700 - Have you performed the proper LOTO?	Done		JUHURST	May 30, 2024 1:09:02 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	May 30, 2024 1:09:02 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	May 30, 2024 1:09:02 PM	No	

Activity Sub Total

Activity 5 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57391274
Invoice No. 55345 - 57391274

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	185,508 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-May-24	Junior Hurst	2.37	65	154.05

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: JUHURST Performed on: 30-MAY-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	May 30, 2024 3:31:41 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
10,800 - CHECK_All Destination Signage	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
20,200 - CHECK_Public Address System	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	80 Second*		JUHURST	May 30, 2024 3:31:41 PM	No	
20,700 - RECORD_Brake Performance Test Speed	30 Miles per Hour		JUHURST	May 30, 2024 3:31:41 PM	No	
20,800 - RECORD_Brake Performance Test Distance	50 FEET		JUHURST	May 30, 2024 3:31:41 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	50 FEET		JUHURST	May 30, 2024 3:31:41 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	80 Gravitational Force		JUHURST	May 30, 2024 3:31:41 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	May 30, 2024 3:31:41 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
21,500 - INSPECT_High Idle Control	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
32,000 - Engine Inspection	Done		JUHURST	May 30, 2024 3:31:41 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	May 30, 2024 3:31:41 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	May 30, 2024 3:31:41 PM	No	
33,000 - CSF (Curb Side Front)	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	May 30, 2024 3:31:41 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
40,700 - CHECK_Passenger Stop Request System	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
50,100 - *RPT*INSPECT_Steering components- Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	May 30, 2024 3:31:41 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,400 - LUBE_All Chassis Components	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
50,700 - INSPECT_Tire Condition	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	May 30, 2024 3:31:41 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	May 30, 2024 3:31:41 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	May 30, 2024 3:31:41 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	May 30, 2024 3:31:41 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	May 30, 2024 3:31:41 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	May 30, 2024 3:31:41 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.3 Inch		JUHURST	May 30, 2024 3:31:41 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.3 Inch		JUHURST	May 30, 2024 3:31:41 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		JUHURST	May 30, 2024 3:31:41 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	4 32nds of an inch	REAR OUTER TIRES NEED REPLACE	JUHURST	May 30, 2024 3:31:41 PM	Yes	57411728
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	May 30, 2024 3:31:41 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	May 30, 2024 3:31:41 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,500 - RECORD_RRI-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	May 30, 2024 3:31:41 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	4 32nds of an inch		JUHURST	May 30, 2024 3:31:41 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	May 30, 2024 3:31:41 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	May 30, 2024 3:31:41 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	May 30, 2024 3:31:41 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	May 30, 2024 3:31:41 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	May 30, 2024 3:31:41 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.5 Inch		JUHURST	May 30, 2024 3:31:41 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.5 Inch		JUHURST	May 30, 2024 3:31:41 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	May 30, 2024 3:31:41 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	May 30, 2024 3:31:41 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	May 30, 2024 3:31:41 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	154.05
Labor Hours:	2.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**154.05**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57391274
Invoice No. 55345 - 57391274

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	185,508 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
31-May-24	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	3.35	3.35
31-May-24	75050	OIL, ENGINE, 5W/30	10	2.73	27.3

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-May-24	Junior Hurst	0.15	65	9.75

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: JUHURST Performed on: 30-MAY-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		JUHURST	May 30, 2024 3:35:48 PM	No	
101,000 - FRA Change Oil Filters	Yes		JUHURST	May 30, 2024 3:35:48 PM	No	
102,000 - FRA Drain Engine Oil	Yes		JUHURST	May 30, 2024 3:35:48 PM	No	
103,000 - FRA Check Transmission Fluid	Done		JUHURST	May 30, 2024 3:35:48 PM	No	
104,000 - Lubricate Chassis	Done		JUHURST	May 30, 2024 3:35:48 PM	No	
105,000 - Replace or Clean A/C Filters	Done		JUHURST	May 30, 2024 3:35:48 PM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	Done		JUHURST	May 30, 2024 3:35:48 PM	No	
107,000 - FRA Change Primary Fuel Filter	No		JUHURST	May 30, 2024 3:35:48 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		JUHURST	May 30, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:35:48 PM		

Activity Sub Total

Activity 20 Sub Total	
Parts:	30.65
Labor:	9.75
Labor Hours:	0.15
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**40.40**

Work Order Footer

Work Order 57391274 Total	
Parts:	30.65
Labor:	163.80
Labor Hours:	2.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**194.45**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 57391271
Invoice No. 55345 - 57391271

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	181,672 - DH

Chronology

Reported	May 7, 2024 10:38:19 AM	May 7, 2024 10:38:19 AM
Started	May 7, 2024 10:46:00 AM	
Completed	May 8, 2024 7:04:00 AM	May 8, 2024 7:04:00 AM
Down Time		

Work Order Notes

Line 10 PMA follow up tire light is on

Bad sensors

Replace 3 sensors completed

Activity Header
Activity: 10 017/003/001 TIRE, CUSHION W/TREAD
Activity Note: need tire sensors 3
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-May-24	FR3Z-1A189-C	SENSOR, MONITOR, PRESSURE, TIRE	3	42.77	128.31

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-May-24	Pierre,Hubert J	1.55	65	100.75

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	128.31
Labor:	100.75
Labor Hours:	1.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**229.06**

Work Order Footer

Work Order 57391271 Total	
Parts:	128.31
Labor:	100.75

	Labor Hours:	1.55
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**229.06**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57366897
Invoice No. 55345 - 57366897

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	181,672 - DH

Chronology		
Reported	May 6, 2024 12:00:00 AM	May 6, 2024 12:00:00 AM
Started	May 7, 2024 7:04:00 AM	
Completed	May 7, 2024 10:42:00 AM	May 7, 2024 10:42:00 AM
Down Time		

Work Order Notes

Line 10 Parts used

Front brake pads needs to be charged (Inventory =0)
One front tire #192659 charged Line 20 PMA

Preventive maintenance

Performed PMA maintenance completed Line 30 Use 6 quart of oil 1 oil filter not on stock

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 07-MAY-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		HPIERRE	May 7, 2024 8:34:26 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	May 7, 2024 8:34:26 AM	No	
400 - Are you wearing the appropriate PPE?	Done		HPIERRE	May 7, 2024 8:34:26 AM	No	
700 - Have you performed the proper LOTO?	Done		HPIERRE	May 7, 2024 8:34:26 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,000 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	May 7, 2024 8:34:26 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	May 7, 2024 8:34:26 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57366897
Invoice No. 55345 - 57366897

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	181,672 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-May-24	75050	OIL, ENGINE, 5W/30	1	2.74	2.74

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-May-24	Pierre,Hubert J	2.22	65	144.3

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: HPIERRE Performed on: 07-MAY-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
10,800 - CHECK_All Destination Signage	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
20,200 - CHECK_Public Address System	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	60 Second*		HPIERRE	May 7, 2024 10:38:11 AM	No	
20,700 - RECORD_Brake Performance Test Speed	60 Miles per Hour		HPIERRE	May 7, 2024 10:38:11 AM	No	
20,800 - RECORD_Brake Performance Test Distance	6 FEET		HPIERRE	May 7, 2024 10:38:11 AM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	6 FEET		HPIERRE	May 7, 2024 10:38:11 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	90 Gravitational Force		HPIERRE	May 7, 2024 10:38:11 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
21,500 - INSPECT_High Idle Control	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
21,800 - INSPECT_Parking Brake Operation	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for	Done		HPIERRE	May 7, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Proper Routing/Chafing/Securement				10:38:11 AM		
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
31,000 - SSF (Street Side Front)	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
32,000 - Engine Inspection	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	190 Degree Fahrenheit		HPIERRE	May 7, 2024 10:38:11 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
32,100 - INSPECT_Intake System	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12 Volt*		HPIERRE	May 7, 2024 10:38:11 AM	No	
33,000 - CSF (Curb Side Front)	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
33,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
40,700 - CHECK_Passenger Stop Request System	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
50,400 - LUBE_All Chassis Components	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
50,700 - INSPECT_Tire Condition	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch	need tire sensors 3	HPIERRE	May 7, 2024 10:38:11 AM	Yes	57391271
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	May 7, 2024 10:38:11 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	May 7, 2024 10:38:11 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	May 7, 2024 10:38:11 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	May 7, 2024 10:38:11 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	May 7, 2024 10:38:11 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	22 Inch		HPIERRE	May 7, 2024 10:38:11 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	22 Inch		HPIERRE	May 7, 2024 10:38:11 AM	No	
52,100 - INSPECT_Vibration Damper	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,600 - INSPECT_Tire Condition	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	May 7, 2024 10:38:11 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	May 7, 2024 10:38:11 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	May 7, 2024 10:38:11 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	May 7, 2024 10:38:11 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	May 7, 2024 10:38:11 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	May 7, 2024 10:38:11 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	May 7, 2024 10:38:11 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	May 7, 2024 10:38:11 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	May 7, 2024 10:38:11 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	May 7, 2024 10:38:11 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	22 Inch		HPIERRE	May 7, 2024 10:38:11 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	22 Inch		HPIERRE	May 7, 2024 10:38:11 AM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		HPIERRE	May 7, 2024 10:38:11 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	2.74
Labor:	144.30
Labor Hours:	2.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**147.04**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57366897
Invoice No. 55345 - 57366897

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	181,672 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: HPIERRE Performed on: 07-MAY-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	May 7, 2024 8:35:37 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	May 7, 2024 8:35:37 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	May 7, 2024 8:35:37 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	May 7, 2024 8:35:37 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	May 7, 2024 8:35:37 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	May 7, 2024 8:35:37 AM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	Done		HPIERRE	May 7, 2024 8:35:37 AM	No	
107,000 - FRA Change Primary Fuel Filter	No		HPIERRE	May 7, 2024 8:35:37 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	May 7, 2024 8:35:37 AM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 57366897 Total	
Parts:	2.74
Labor:	144.30
Labor Hours:	2.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**147.04**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57331117
Invoice No. 55345 - 57331117

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
SMALL FIBERGLASS BY RIGHT REAR TOP AREA		Ford Transit	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	171,086 - DH

Chronology		
Reported	Feb 29, 2024 9:10:00 AM	Feb 29, 2024 9:10:00 AM
Started	Mar 1, 2024 12:00:00 AM	
Completed	Apr 24, 2024 12:13:46 PM	Apr 24, 2024 12:13:46 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: SMALL FIBER GLASS DAMAGE BY RIGHT REAR TOP AREA REPAIRED BY EG LABOR PER INV# 949

Cause: UNKNOWN

Correction: REPAIRED BY EG LABOR PER INV# 949

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57331117
Invoice No. 55345 - 57331117

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
SMALL FIBERGLASS BY RIGHT REAR TOP AREA		Ford Transit	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	171,086 - DH

Activity Header
Activity: 15 002 CAB & SHEET METAL
Activity Note: SMALL FIBER GLASS DAMAGE BY RIGHT REAR TOP AREA REPAIRED BY EG LABOR PER INV# 949
Reason for Repair: 42 Physical Damage
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet

PO No.	ACD Code	Supplier No.	SUPPLIER	Order Date	Received Value
5029411	185,929,143	2398452	EG LABOR LLC,FL,ORLANDO,12431 NATURE EAST DR	Feb 29, 2024 12:00:00 AM	312

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	312.00
Sublet Labor:	0.00
Activity Sub Total	**312.00**

Work Order Footer

Work Order 57331117 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	312.00
Sublet Labor:	0.00
Activity Sub Total	**312.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57366869
Invoice No. 55345 - 57366869

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	177,894 - DH

Chronology		
Reported	Apr 9, 2024 12:26:45 AM	Apr 9, 2024 12:26:45 AM
Started	Apr 9, 2024 7:02:00 AM	
Completed	Apr 10, 2024 12:57:00 PM	Apr 10, 2024 12:57:00 PM
Down Time		

Work Order Notes

Line 10 PMA follow need rear brake pads

Preventive maintenance

Perform rear brake service completed

Activity Header
Activity: 10 042/002/044 CAP, TANK, SURGE
Activity Note: lower heater hose leaking
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Apr-24	Pierre,Hubert J	0.18	65	11.7

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	11.70
Labor Hours:	0.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**11.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57366869
Invoice No. 55345 - 57366869

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	177,894 - DH

Activity Header
Activity: 20 001/001 AIR CONDITIONING
Activity Note: Rear AC filter dirty
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57366869
Invoice No. 55345 - 57366869

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	177,894 - DH

Activity Header
Activity: 30 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: needs rear brakes job
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Apr-24	1551-2388-00	PADS, BRAKE, REAR	1	44.2	44.2

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Apr-24	Pierre,Hubert J	2.45	65	159.25

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	44.20
Labor:	159.25
Labor Hours:	2.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**203.45**

Work Order Footer

Work Order 57366869 Total	
Parts:	44.20
Labor:	170.95
Labor Hours:	2.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**215.15**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57345255
Invoice No. 55345 - 57345255

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	177,894 - DH

Chronology		
Reported	Apr 8, 2024 12:00:00 AM	Apr 8, 2024 12:00:00 AM
Started	Apr 8, 2024 11:52:00 PM	
Completed	Apr 9, 2024 1:23:00 AM	Apr 9, 2024 1:23:00 AM
Down Time		

Work Order Notes

Line 10 PMA
Service
Perform PMA Service
Oil filter LF17531 qty1
Engine oil 10w30 qty 6 QTs
Add washer fluid

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 08-APR-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		RGASPARD	Apr 8, 2024 11:52:49 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Apr 8, 2024 11:52:49 PM	No	
400 - Are you wearing the appropriate PPE?	Done		RGASPARD	Apr 8, 2024 11:52:49 PM	No	
700 - Have you performed the proper LOTO?	Done		RGASPARD	Apr 8, 2024 11:52:49 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Apr 8, 2024 11:52:49 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Apr 8, 2024 11:52:49 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57345255
Invoice No. 55345 - 57345255

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	177,894 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Apr-24	Gaspard,Ronald	0.82	65	53.3
08-Apr-24	Gaspard,Ronald	0.13	65	8.45

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 09-APR-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
10,800 - CHECK_All Destination Signage	-	NA	RGASPARD	Apr 9, 2024 12:27:11 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
20,200 - CHECK_Public Address System	-	NA	RGASPARD	Apr 9, 2024 12:27:11 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	NA	RGASPARD	Apr 9, 2024 12:27:11 AM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	NA	RGASPARD	Apr 9, 2024 12:27:11 AM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	NA	RGASPARD	Apr 9, 2024 12:27:11 AM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	NA	RGASPARD	Apr 9, 2024 12:27:11 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	NA	RGASPARD	Apr 9, 2024 12:27:11 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	-	NA	RGASPARD	Apr 9, 2024 12:27:11 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
21,500 - INSPECT_High Idle Control	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
21,800 - INSPECT_Parking Brake Operation	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
32,000 - Engine Inspection	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	NA	RGASPARD	Apr 9, 2024 12:27:11 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	RGASPARD	Apr 9, 2024 12:27:11 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done	lower heater hose leaking	RGASPARD	Apr 9, 2024 12:27:11 AM	Yes	57366869
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
33,000 - CSF (Curb Side Front)	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Apr 9, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:27:11 AM		
33,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
40,700 - CHECK_Passenger Stop Request System	-	NA	RGASPARD	Apr 9, 2024 12:27:11 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done	Rear AC filter dirty	RGASPARD	Apr 9, 2024 12:27:11 AM	Yes	57366869
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
50,100 - *RPT*INSPECT_Steering components- Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
50,400 - LUBE_All Chassis Components	-	NA	RGASPARD	Apr 9, 2024 12:27:11 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.229 Inch		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.229 Inch		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch	needs rear brakes job	RGASPARD	Apr 9, 2024 12:27:11 AM	Yes	57366869
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.799 Inch		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.799 Inch		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
55,700 - CHECK_Spring Brake Inversion Valve	-	NA	RGASPARD	Apr 9, 2024 12:27:11 AM	No	
55,800 - CHECK_Double Check Valve - Primary,	-	NA	RGASPARD	Apr 9, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Secondary				12:27:11 AM		
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Apr 9, 2024 12:27:11 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	61.75
Labor Hours:	0.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**61.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57345255
Invoice No. 55345 - 57345255

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	177,894 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMB Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Apr-24	75050	OIL, ENGINE, 5W/30	8	2.74	21.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Apr-24	Gaspard,Ronald	0.55	65	35.75

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMB Service
Task: 55345-Medium Duty PMB Inspection Performed by: RGASPARD Performed on: 09-APR-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Apr 9, 2024 12:52:13 AM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Apr 9, 2024 12:52:13 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Apr 9, 2024 12:52:13 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Apr 9, 2024 12:52:13 AM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Apr 9, 2024 12:52:13 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Apr 9, 2024 12:52:13 AM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	-	NA	RGASPARD	Apr 9, 2024 12:52:13 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Apr 9, 2024 12:52:13 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Apr 9, 2024 12:52:13 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Apr 9, 2024 12:52:13 AM	No	
201,000 - Service Crankcase Breather	Done		RGASPARD	Apr 9, 2024 12:52:13 AM	No	
202,000 - FRA Change Water Separator ¿ Secondary Fuel Filters	No	NA	RGASPARD	Apr 9, 2024 12:52:13 AM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Apr 9, 2024 12:52:13 AM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Apr 9, 2024 12:52:13 AM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Apr 9, 2024 12:52:13 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	21.92
Labor:	35.75
Labor Hours:	0.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**57.67**

Work Order Footer

Work Order 57345255 Total	
Parts:	21.92
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**119.42**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57357752
Invoice No. 55345 - 57357752

Client Department:
Department: 55345M
Work Order Description
Passenger side moulding detached.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 175,875 - DH

Chronology		
Reported	Mar 28, 2024 12:19:00 AM	Mar 28, 2024 12:19:00 AM
Started	Mar 28, 2024 12:22:00 AM	
Completed	Mar 28, 2024 1:24:00 AM	Mar 28, 2024 1:24:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Passenger side moulding detached.

Cause: Wear and tear.

Correction: Reattached moulding with screws.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 28-MAR-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		EARJOHNSON	Mar 28, 2024 1:23:50 AM	No	
200 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Mar 28, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				1:23:50 AM		
400 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Mar 28, 2024 1:23:50 AM	No	
700 - Have you performed the proper LOTO?	Done		EARJOHNSON	Mar 28, 2024 1:23:50 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Mar 28, 2024 1:23:50 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Mar 28, 2024 1:23:50 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57357752
Invoice No. 55345 - 57357752

Client Department:
Department: 55345M
Work Order Description
Passenger side moulding detached.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 175,875 - DH

Activity Header
Activity: 15 002 CAB & SHEET METAL
Activity Note: Passenger side moulding detached.
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Mar-24	Earl Johnson	1.03	65	66.95

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	66.95
Labor Hours:	1.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**66.95**

Work Order Footer

Work Order 57357752 Total	
Parts:	0.00
Labor:	66.95
Labor Hours:	1.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**66.95**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57348593
Invoice No. 55345 - 57348593

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Air purifier hanging.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	174,505 - DH

Chronology		
Reported	Mar 19, 2024 11:19:00 PM	Mar 19, 2024 11:19:00 PM
Started	Mar 19, 2024 11:21:00 PM	
Completed	Mar 20, 2024 12:46:00 AM	Mar 20, 2024 12:46:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Air purifier detached from wall.

Cause: Damaged during operation.

Correction: Cleaned and prepped both surfaces. Reattached air purifier to wall with new screws and 2 sided tape.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 20-MAR-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		EARJOHNSON	Mar 20, 2024 12:45:39 AM	No	
200 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Mar 20, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				12:45:39 AM		
400 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Mar 20, 2024 12:45:39 AM	No	
700 - Have you performed the proper LOTO?	Done		EARJOHNSON	Mar 20, 2024 12:45:39 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Mar 20, 2024 12:45:39 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Mar 20, 2024 12:45:39 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57348593
Invoice No. 55345 - 57348593

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Air purifier hanging.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	174,505 - DH

Activity Header
Activity: 15 053/004/000 SAFETY EQUIPMENT
Activity Note: Air purifier detached from wall.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Mar-24	Earl Johnson	0.75	65	48.75
19-Mar-24	Earl Johnson	0.65	65	42.25

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	91.00
Labor Hours:	1.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**91.00**

Work Order Footer

Work Order 57348593 Total	
Parts:	0.00
Labor:	91.00
Labor Hours:	1.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**91.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57347885
Invoice No. 55345 - 57347885

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
rear ac blower not blowing		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	174,316 - DH

Chronology		
Reported	Mar 19, 2024 9:29:00 AM	Mar 19, 2024 9:29:00 AM
Started	Mar 19, 2024 9:33:00 AM	
Completed	Mar 19, 2024 10:07:00 AM	Mar 19, 2024 10:07:00 AM
Down Time		

Work Order Notes

Line 20 Rear ac blowing one side not blowing

Unable to duplicate

Both side is blowing at this moment completed

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 19-MAR-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		HPIERRE	Mar 19, 2024 10:07:07 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Mar 19, 2024 10:07:07 AM	No	
400 - Are you wearing the appropriate PPE?	Done		HPIERRE	Mar 19, 2024 10:07:07 AM	No	
700 - Have you performed the proper LOTO?	Done		HPIERRE	Mar 19, 2024 10:07:07 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Mar 19, 2024 10:07:07 AM	No	
1,100 - Have you successfully completed the	Done		HPIERRE	Mar 19, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				10:07:07 AM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57347885
Invoice No. 55345 - 57347885

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
rear ac blower not blowing		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	174,316 - DH

Activity Header
Activity: 15 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear ac not one not working
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 51 Inoperative
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Mar-24	Pierre,Hubert J	0.55	65	35.75

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	35.75
Labor Hours:	0.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**35.75**

Work Order Footer

Work Order 57347885 Total	
Parts:	0.00
Labor:	35.75
Labor Hours:	0.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**35.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57345224
Invoice No. 55345 - 57345224

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	173,775 - DH

Chronology		
Reported	Mar 15, 2024 10:09:44 AM	Mar 15, 2024 10:09:44 AM
Started	Mar 15, 2024 10:35:00 AM	
Completed	Mar 15, 2024 12:06:00 PM	Mar 15, 2024 12:06:00 PM
Down Time		

Work Order Notes

Line 10 Front brake job was completed

Activity Header

Activity: 10 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: front brake job
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Mar-24	BRF-1896	PADS, BRAKE, DISC, FRONT, TRANSIT	1	55.76	55.76

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Mar-24	NELSON PIERRE-LOUIS	1.5	65	97.5

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	55.76
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**153.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57345224
Invoice No. 55345 - 57345224

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	173,775 - DH

Activity Header
Activity: 20 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note:
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57345224 Total	
Parts:	55.76
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**153.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57324244
Invoice No. 55345 - 57324244

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	174,006 - DH

Chronology		
Reported	Mar 14, 2024 12:00:00 AM	Mar 14, 2024 12:00:00 AM
Started	Mar 15, 2024 8:03:00 AM	
Completed	Mar 15, 2024 10:34:00 AM	Mar 15, 2024 10:34:00 AM
Down Time		

Work Order Notes

Line 10 Complaint: PMA service

Cause: preventive maintenance

Correction: perform maintenance PMA service and lube

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 15-MAR-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Mar 15, 2024 10:08:28 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Mar 15, 2024 10:08:28 AM	No	
400 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Mar 15, 2024 10:08:28 AM	No	
700 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Mar 15, 2024 10:08:28 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Mar 15, 2024 10:08:28 AM	No	
1,100 - Have you successfully completed the	Done		NPIERRE-	Mar 15, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?			LOUIS	10:08:28 AM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57324244
Invoice No. 55345 - 57324244

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	174,006 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Mar-24	NELSON PIERRE-LOUIS	2.38	65	154.7

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS Performed on: 15-MAR-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
10,800 - CHECK_All Destination Signage	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
10,900 - *RPT*INSPECT_Body Damage,	Done		NPIERRE-	Mar 15, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Corrosion;DOCUMENT_Issues			LOUIS	10:07:31 AM		
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
20,200 - CHECK_Public Address System	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	na	NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	na	NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	na	NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	na	NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	na	NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
21,500 - INSPECT_High Idle Control	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
21,800 - INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	-	na	NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
31,000 - SSF (Street Side Front)	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
32,000 - Engine Inspection	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
32,100 - INSPECT_Intake System	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	13.5 Volt*		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
33,000 - CSF (Curb Side Front)	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-	Mar 15, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	10:07:31 AM		
33,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
40,700 - CHECK_Passenger Stop Request System	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
50,400 - LUBE_All Chassis Components	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
50,700 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	10 32nds of an inch		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	Pounds per Square Inch	64	NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	4 32nds of an inch	front brake job	NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	Yes	57345224
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	32nds of an inch	4	NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	Inch	23.5	NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	Inch	23.5	NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
52,100 - INSPECT_Vibration Damper	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,600 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	63 Pounds per Square Inch		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	64 Pounds per Square Inch		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	64 Pounds per Square Inch		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	64 Pounds per Square Inch		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	Yes	57345224
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch	rear brake job	NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	17.5 Inch		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	17.5 Inch		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	Mar 15, 2024 10:07:31 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	154.70
Labor Hours:	2.38
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**154.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57324244
Invoice No. 55345 - 57324244

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	174,006 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Mar-24	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	5.12	5.12
15-Mar-24	75050	OIL, ENGINE, 5W/30	6	2.75	16.5

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: NPIERRE-LOUIS Performed on: 15-MAR-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Mar 15, 2024 10:09:25 AM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Mar 15, 2024 10:09:25 AM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Mar 15, 2024 10:09:25 AM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Mar 15, 2024 10:09:25 AM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Mar 15, 2024 10:09:25 AM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Mar 15, 2024 10:09:25 AM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	Done		NPIERRE-LOUIS	Mar 15, 2024 10:09:25 AM	No	
107,000 - FRA Change Primary Fuel Filter	No		NPIERRE-LOUIS	Mar 15, 2024 10:09:25 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Mar 15, 2024 10:09:25 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	21.62
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**21.62**

Work Order Footer

Work Order 57324244 Total	
Parts:	21.62
Labor:	154.70
Labor Hours:	2.38
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**176.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57324239
Invoice No. 55345 - 57324239

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	170,029 - DH

Chronology		
Reported	Feb 21, 2024 9:17:25 AM	Feb 21, 2024 9:17:25 AM
Started	Feb 21, 2024 9:22:00 AM	
Completed	Feb 25, 2024 6:47:00 PM	Feb 25, 2024 6:47:00 PM
Down Time		

Work Order Notes

Line 10 Installed new rear bumper sign Line 20 Replaced two makers light completed Line 30 Vehicle came in for motor mount replacement. Two mounts replaced to unit after test drive unit

Activity Header

Activity: 10 034/003/000 LAMPS, SIGNAL, PARKING & BACKUP
Activity Note: clearance lights front and rear
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Feb-24	Pierre,Hubert J	1.65	65	107.25

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	107.25
Labor Hours:	1.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**107.25**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57324239
Invoice No. 55345 - 57324239

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	170,029 - DH

Activity Header
Activity: 20 010 CHASSIS GROUP
Activity Note: rear bumper sign out
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Feb-24	Rodriguez,Raul	0.2	65	13

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	13.00
Labor Hours:	0.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**13.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57324239
Invoice No. 55345 - 57324239

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	170,029 - DH

Activity Header
Activity: 30 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Motor mount
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Feb-24	CK4Z-6096-D	SUPPORT, ENGINE	2	64.96	129.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Feb-24	Junior Hurst	4.38	65	284.7

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	129.92
Labor:	284.70
Labor Hours:	4.38
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**414.62**

Work Order Footer

Work Order 57324239 Total	
Parts:	129.92
Labor:	404.95
Labor Hours:	6.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**534.87**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57302925
Invoice No. 55345 - 57302925

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	170,029 - DH

Chronology		
Reported	Feb 19, 2024 12:00:00 AM	Feb 19, 2024 12:00:00 AM
Started	Feb 21, 2024 7:44:00 AM	
Completed	Feb 21, 2024 9:19:00 AM	Feb 21, 2024 9:19:00 AM
Down Time		

Work Order Notes

Line 10 PERFORMED PM A

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 21-FEB-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Feb 21, 2024 7:50:31 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Feb 21, 2024 7:50:31 AM	No	
400 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Feb 21, 2024 7:50:31 AM	No	
700 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Feb 21, 2024 7:50:31 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Feb 21, 2024 7:50:31 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Feb 21, 2024 7:50:31 AM	No	

Activity Sub Total

Activity 5 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57302925
Invoice No. 55345 - 57302925

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	170,029 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Feb-24	Rodriguez,Raul	0.95	65	61.75

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: RAURODRIGUEZ Performed on: 21-FEB-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done	clearance lights front and rear	RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	Yes	57324239
10,800 - CHECK_All Destination Signage	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
20,200 - CHECK_Public Address System	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	na	RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	na	RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	na	RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	na	RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	na	RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	-	na	RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
21,500 - INSPECT_High Idle Control	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
21,800 - INSPECT_Parking Brake Operation	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done	rear bumper sign out	RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	Yes	57324239
31,000 - SSF (Street Side Front)	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
32,000 - Engine Inspection	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,010 - INSPECT_Hood, Springs and Props	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	na	RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
32,100 - INSPECT_Intake System	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	13.8 Volt*		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
33,000 - CSF (Curb Side Front)	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
40,700 - CHECK_Passenger Stop Request System	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,400 - LUBE_All Chassis Components	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
50,700 - INSPECT_Tire Condition	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	10 32nds of an inch		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	10 32nds of an inch		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	32nds of an inch	6mm	RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	32nds of an inch	6mm	RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	Inch	30.6mm	RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	Inch	30.6mm	RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
52,100 - INSPECT_Vibration Damper	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
53,600 - INSPECT_Tire Condition	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	7 32nds of an inch		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	7 32nds of an inch		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	32nds of an inch	8mm	RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	32nds of an inch	8mm	RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	Inch	17.5mm	RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	Inch	17.5mm	RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,200 - RETURN_Vehicle to Predetermined Location	Done		RAURODRIGUEZ	Feb 21, 2024 9:18:48 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	61.75
Labor Hours:	0.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**61.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57302925
Invoice No. 55345 - 57302925

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	170,029 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Feb-24	75050	OIL, ENGINE, 5W/30	6	2.73	16.38
21-Feb-24	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	7.1	7.1

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Feb-24	Rodriguez,Raul	0.6	65	39

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: RAURODRIGUEZ Performed on: 21-FEB-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RAURODRIGUEZ	Feb 21, 2024 7:54:35 AM	No	
101,000 - FRA Change Oil Filters	Yes		RAURODRIGUEZ	Feb 21, 2024 7:54:35 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RAURODRIGUEZ	Feb 21, 2024 7:54:35 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RAURODRIGUEZ	Feb 21, 2024 7:54:35 AM	No	
104,000 - Lubricate Chassis	Done		RAURODRIGUEZ	Feb 21, 2024 7:54:35 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RAURODRIGUEZ	Feb 21, 2024 7:54:35 AM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	-	na	RAURODRIGUEZ	Feb 21, 2024 7:54:35 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RAURODRIGUEZ	Feb 21, 2024 7:54:35 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RAURODRIGUEZ	Feb 21, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				7:54:35 AM		

Activity Sub Total

Activity 20 Sub Total	
Parts:	23.48
Labor:	39.00
Labor Hours:	0.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**62.48**

Work Order Footer

Work Order 57302925 Total	
Parts:	23.48
Labor:	100.75
Labor Hours:	1.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**124.23**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 5

Work Order No. 57302605
Invoice No. 55345 - 57302605

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	165,896 - DH

Chronology

Reported	Jan 26, 2024 12:20:27 AM	Jan 26, 2024 12:20:27 AM
Started	Jan 31, 2024 6:36:00 AM	
Completed	Feb 1, 2024 9:20:00 AM	Feb 1, 2024 9:20:00 AM
Down Time		

Work Order Notes

Line 10 Replaced valve cover gaskets and 6 spark plugs,test drive the vehicle everything ok at this time

Activity Header

Activity: 10 003/001 GAUGES & WARNING DEVICES
Activity Note: cylinder 6 miss fire
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Feb-24	SP580	PLUG, SPARK	6	10.22	61.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Feb-24	NELSON PIERRE-LOUIS	2.7	65	175.5

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	61.32
Labor:	175.50
Labor Hours:	2.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**236.82**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 5

Work Order No. 57302605
Invoice No. 55345 - 57302605

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	165,896 - DH

Activity Header
Activity: 20 001/001 AIR CONDITIONING
Activity Note: rear AC filter dirty
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 5

Work Order No. 57302605
Invoice No. 55345 - 57302605

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	165,896 - DH

Activity Header
Activity: 30 027/001/013 HARDWARE, MOUNTING, CASE, TRANSMISSION, AUTOMATIC APFI - 027-001-001
Activity Note: needs motor mounts
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 5

Work Order No. 57302605
Invoice No. 55345 - 57302605

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	165,896 - DH

Activity Header
Activity:40 045/009/003 BODY, PUMP, OIL, ENGINE
Activity Note: valve cover gascket leaking
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
31-Jan-24	BR3Z-6C535-A	SEAL, TUBE, PLUG, SPARK	-2	7.75	-15.5
31-Jan-24	BR3Z-6C535-B	SEAL, COVER, VALVE, EDGE	6	8.99	53.94
31-Jan-24	BR3Z-6C535-A	SEAL, TUBE, PLUG, SPARK	6	7.75	46.5
31-Jan-24	BL3Z-6584-A	GASKET, COVER, VALVE	1	16.57	16.57

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Jan-24	NELSON PIERRE-LOUIS	4.93	65	320.45

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	101.51
Labor:	320.45
Labor Hours:	4.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**421.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 5

Work Order No. 57302605
Invoice No. 55345 - 57302605

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	165,896 - DH

Activity Header
Activity:50
Activity Note:
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 50 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57302605 Total	
Parts:	162.83
Labor:	495.95
Labor Hours:	7.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**658.78**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57302128
Invoice No. 55345 - 57302128

Client Department:
Department: 55345M
Work Order Description
Road Call-bus vibrates check engine light on
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 165,896 - DH

Chronology		
Reported	Jan 25, 2024 2:13:00 PM	Jan 25, 2024 2:13:00 PM
Started	Jan 25, 2024 2:16:00 PM	
Completed	Jan 26, 2024 10:03:00 PM	Jan 26, 2024 10:03:00 PM
Down Time		

Work Order Notes

Line 20 Road call for unit driver complain for vibration check and found ignition coil F. Control high P2316. Engine may need tuneup.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 26-JAN-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		JUHURST	Jan 26, 2024 9:59:47 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Jan 26, 2024 9:59:47 PM	No	
400 - Are you wearing the appropriate PPE?	Done		JUHURST	Jan 26, 2024 9:59:47 PM	No	
700 - Have you performed the proper LOTO?	Done		JUHURST	Jan 26, 2024 9:59:47 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Jan 26, 2024 9:59:47 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Jan 26, 2024 9:59:47 PM	No	

Activity Sub Total

Activity 5 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57302128
Invoice No. 55345 - 57302128

Client Department:
Department: 55345M
Work Order Description
Road Call-bus vibrates check engine light on
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 165,896 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:
Line 10 Road call for unit driver complain for vibration check and found ignition coil F. Control high P2316. Engine may need tuneup.

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Jan-24	Junior Hurst	0.93	65	60.45

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	60.45
Labor Hours:	0.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**60.45**

Work Order Footer

Work Order 57302128 Total	
Parts:	0.00
Labor:	60.45
Labor Hours:	0.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**60.45**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57283245
Invoice No. 55345 - 57283245

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	166,079 - DH

Chronology		
Reported	Jan 25, 2024 12:00:00 AM	Jan 25, 2024 12:00:00 AM
Started	Jan 25, 2024 9:23:00 PM	
Completed	Jan 26, 2024 10:24:52 AM	Jan 26, 2024 10:24:52 AM
Down Time		

Work Order Notes

Line 10 PMB
Service
Perform PMB service
Oil filter LF17531 qty 1
Engine oil 10w30 qty 6 QTs
Add washer fluid
Replace 1 tie down bag

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 25-JAN-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		RGASPARD	Jan 25, 2024 9:22:57 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Jan 25, 2024 9:22:57 PM	No	
400 - Are you wearing the appropriate PPE?	Done		RGASPARD	Jan 25, 2024 9:22:57 PM	No	
700 - Have you performed the proper LOTO?	Done		RGASPARD	Jan 25, 2024 9:22:57 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Jan 25, 2024 9:22:57 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jan 25, 2024 9:22:57 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57283245
Invoice No. 55345 - 57283245

Client Department:
Department: 55345M
Work Order Description
55345-MEDIUM DUTY PMB
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 166,079 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:
Line 10 PMB
Service
Perform PMB service
Oil filter LF17531 qty1
Engine oil 10w30 qty 6 QTs
Add washer fluid
Check inflate tires to spec

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Jan-24	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	5.92	5.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Jan-24	Gaspard,Ronald	0.18	65	11.7
26-Jan-24	Gaspard,Ronald	0.73	65	47.45
25-Jan-24	Gaspard,Ronald	1.83	65	118.95

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: CKARLENS Performed on: 26-JAN-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,400 - !FRA!INSPECT_Back Up Alarm	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
10,800 - CHECK_All Destination Signage	-	NA	CKARLENS	Jan 26, 2024 10:24:41 AM	No	
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
20,200 - CHECK_Public Address System	-	NA	CKARLENS	Jan 26, 2024 10:24:41 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	NA	CKARLENS	Jan 26, 2024 10:24:41 AM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	NA	CKARLENS	Jan 26, 2024 10:24:41 AM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	NA	CKARLENS	Jan 26, 2024 10:24:41 AM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	NA	CKARLENS	Jan 26, 2024 10:24:41 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	NA	CKARLENS	Jan 26, 2024 10:24:41 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done	NA	CKARLENS	Jan 26, 2024 10:24:41 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
21,500 - INSPECT_High Idle Control	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
21,800 - INSPECT_Parking Brake Operation	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done	cylinder 6 miss fire	CKARLENS	Jan 26, 2024 10:24:41 AM	Yes	57302605
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
31,000 - SSF (Street Side Front)	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
32,000 - Engine Inspection	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	NA	CKARLENS	Jan 26, 2024 10:24:41 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	CKARLENS	Jan 26, 2024 10:24:41 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
32,100 - INSPECT_Intake System	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting	Done		CKARLENS	Jan 26, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Condition				10:24:41 AM		
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
33,000 - CSF (Curb Side Front)	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
40,700 - CHECK_Passenger Stop Request System	-	NA	CKARLENS	Jan 26, 2024 10:24:41 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done	rear AC filter dirty	CKARLENS	Jan 26, 2024 10:24:41 AM	Yes	57302605
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
50,100 - *RPT*INSPECT_Steering components- Drag Link, Tie Rods ends and Steering Damper	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,200 - INSPECT_Ball Joint Play	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
50,400 - LUBE_All Chassis Components	Done	NA	CKARLENS	Jan 26, 2024 10:24:41 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
50,700 - INSPECT_Tire Condition	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.229 Inch		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.229 Inch		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
52,100 - INSPECT_Vibration Damper	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done	needs motor mounts	CKARLENS	Jan 26, 2024 10:24:41 AM	Yes	57302605
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done	valve cover gascket leaking	CKARLENS	Jan 26, 2024 10:24:41 AM	Yes	57302605
52,900 - INSPECT_ Shift Cable Adjustment - All	Done		CKARLENS	Jan 26, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Transmissions				10:24:41 AM		
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
53,600 - INSPECT_Tire Condition	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	60 Pounds per Square Inch		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	60 Pounds per Square Inch		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	60 Pounds per Square Inch		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	60 Pounds per Square Inch		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining,	6 32nds of an		CKARLENS	Jan 26, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Pad Thickness (32nds)	inch			10:24:41 AM		
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.799 Inch		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.799 Inch		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done	NA	CKARLENS	Jan 26, 2024 10:24:41 AM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done	NA	CKARLENS	Jan 26, 2024 10:24:41 AM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		CKARLENS	Jan 26, 2024 10:24:41 AM	No	57302605

Activity Sub Total

Activity 10 Sub Total	
Parts:	5.92
Labor:	178.10
Labor Hours:	2.74
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**184.02**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57283245
Invoice No. 55345 - 57283245

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	166,079 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMB Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Jan-24	75050	OIL, ENGINE, 5W/30	6	2.73	16.38

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Jan-24	Gaspard,Ronald	0.7	65	45.5

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMB Service
Task: 55345-Medium Duty PMB Inspection Performed by: RGASPARD Performed on: 26-JAN-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jan 26, 2024 12:47:30 AM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jan 26, 2024 12:47:30 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jan 26, 2024 12:47:30 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jan 26, 2024 12:47:30 AM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Jan 26, 2024 12:47:30 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jan 26, 2024 12:47:30 AM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	-	NA	RGASPARD	Jan 26, 2024 12:47:30 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Jan 26, 2024 12:47:30 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jan 26, 2024 12:47:30 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Jan 26, 2024 12:47:30 AM	No	
201,000 - Service Crankcase Breather	Done		RGASPARD	Jan 26, 2024 12:47:30 AM	No	
202,000 - FRA Change Water Separator ¿ Secondary Fuel Filters	No	NA	RGASPARD	Jan 26, 2024 12:47:30 AM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Jan 26, 2024 12:47:30 AM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Jan 26, 2024 12:47:30 AM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Jan 26, 2024 12:47:30 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	16.38
Labor:	45.50
Labor Hours:	0.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**61.88**

Work Order Footer

Work Order 57283245 Total	
Parts:	22.30
Labor:	223.60
Labor Hours:	3.44
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**245.90**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57283313
Invoice No. 55345 - 57283313

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Unscheduled Work		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	162,226 - DH

Chronology		
Reported	Jan 2, 2024 6:08:00 PM	Jan 2, 2024 6:08:00 PM
Started	Jan 2, 2024 6:10:00 PM	
Completed	Jan 2, 2024 6:53:00 PM	Jan 2, 2024 6:53:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: NFC not working.

Cause: Geotab main connector not secured.

Correction: Removed panel, checked and reconnected geotab main connector.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 02-JAN-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jan 2, 2024 6:52:03 PM	No	
200 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Jan 2, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				6:52:03 PM		
400 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jan 2, 2024 6:52:03 PM	No	
700 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jan 2, 2024 6:52:03 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jan 2, 2024 6:52:03 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jan 2, 2024 6:52:03 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57283313
Invoice No. 55345 - 57283313

Client Department:
Department: 55345M
Work Order Description
Unscheduled Work
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 162,226 - DH

Activity Header
Activity: 15 036 DEVICES, INFORMATION, SUPPLEMENTAL
Activity Note: NFC not working.
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 24 Repair
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jan-24	Earl Johnson	0.72	65	46.8

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	46.80
Labor Hours:	0.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**46.80**

Work Order Footer

Work Order 57283313 Total	
Parts:	0.00
Labor:	46.80
Labor Hours:	0.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**46.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 57283235
Invoice No. 55345 - 57283235

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	162,226 - DH

Chronology		
Reported	Jan 2, 2024 4:13:34 PM	Jan 2, 2024 4:13:34 PM
Started	Jan 2, 2024 4:20:00 PM	
Completed	Jan 2, 2024 6:05:00 PM	Jan 2, 2024 6:05:00 PM
Down Time		

Work Order Notes

Line 10 Rotate front tires to right rear of vehicle and replace two new good year tires to front of vehicle size 195 /75R16 also road test unit working perfect return unit back to work .

Activity Header

Activity: 10 017/003/001 TIRE, CUSHION W/TREAD
Activity Note: front tires rotate to right rear of unit
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Jan-24	131196995	TIRE, 195/75R16, WORKHORSE, HTL, WRANGLER, GOODYEAR	2	120	240

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jan-24	Junior Hurst	1.73	65	112.45

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	240.00
Labor:	112.45
Labor Hours:	1.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**352.45**

Work Order Footer

Work Order 57283235 Total	
Parts:	240.00
Labor:	112.45
Labor Hours:	1.73
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**352.45**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57264076
Invoice No. 55345 - 57264076

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	162,226 - DH

Chronology		
Reported	Jan 2, 2024 12:49:52 PM	Jan 2, 2024 12:49:52 PM
Started	Jan 2, 2024 1:33:00 PM	
Completed	Jan 2, 2024 4:19:00 PM	Jan 2, 2024 4:19:00 PM
Down Time		

Work Order Notes

Line 10 VEHICLE CAME FOR SERVICE DUE BY MILE AGE CHANGE OIL FILTER PART # 17531 also wash rear AC filter

Activity Header

Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 02-JAN-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		JUHURST	Jan 2, 2024 1:30:00 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Jan 2, 2024 1:30:00 PM	No	
400 - Are you wearing the appropriate PPE?	Done		JUHURST	Jan 2, 2024 1:30:00 PM	No	
700 - Have you performed the proper LOTO?	Done		JUHURST	Jan 2, 2024 1:30:00 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Jan 2, 2024 1:30:00 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Jan 2, 2024 1:30:00 PM	No	

Activity Sub Total

Activity 5 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57264076
Invoice No. 55345 - 57264076

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	162,226 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jan-24	Junior Hurst	0.57	65	37.05
02-Jan-24	Junior Hurst	1.6	65	104

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: JUHURST Performed on: 02-JAN-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
10,800 - CHECK_All Destination Signage	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
20,200 - CHECK_Public Address System	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	80 Second*		JUHURST	Jan 2, 2024 4:13:56 PM	No	
20,700 - RECORD_Brake Performance Test Speed	30 Miles per Hour		JUHURST	Jan 2, 2024 4:13:56 PM	No	
20,800 - RECORD_Brake Performance Test Distance	50 FEET		JUHURST	Jan 2, 2024 4:13:56 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	50 FEET		JUHURST	Jan 2, 2024 4:13:56 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	80 Gravitational Force		JUHURST	Jan 2, 2024 4:13:56 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
21,500 - INSPECT_High Idle Control	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for	Done		JUHURST	Jan 2, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Proper Routing/Chafing/Securement				4:13:56 PM		
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
32,000 - Engine Inspection	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Jan 2, 2024 4:13:56 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Jan 2, 2024 4:13:56 PM	No	
33,000 - CSF (Curb Side Front)	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
33,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
40,700 - CHECK_Passenger Stop Request System	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
50,100 - *RPT*INSPECT_Steering components- Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
50,400 - LUBE_All Chassis Components	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
50,700 - INSPECT_Tire Condition	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Jan 2, 2024 4:13:56 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Jan 2, 2024 4:13:56 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	9 32nds of an inch	front tires rotate to right rear of unit	JUHURST	Jan 2, 2024 4:13:56 PM	Yes	57283235
51,300 - RECORD_RF-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Jan 2, 2024 4:13:56 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Jan 2, 2024 4:13:56 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Jan 2, 2024 4:13:56 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.2699 Inch		JUHURST	Jan 2, 2024 4:13:56 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.2699 Inch		JUHURST	Jan 2, 2024 4:13:56 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and	Done		JUHURST	Jan 2, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Chassis Frame for Corrosion, Cracks				4:13:56 PM		
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	3 32nds of an inch		JUHURST	Jan 2, 2024 4:13:56 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	32nds of an inch	right rear tires replace from front	JUHURST	Jan 2, 2024 4:13:56 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Jan 2, 2024 4:13:56 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Jan 2, 2024 4:13:56 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Jan 2, 2024 4:13:56 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Jan 2, 2024 4:13:56 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Jan 2, 2024 4:13:56 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Jan 2, 2024 4:13:56 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Jan 2, 2024 4:13:56 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Jan 2, 2024 4:13:56 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.5 Inch		JUHURST	Jan 2, 2024 4:13:56 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.5 Inch		JUHURST	Jan 2, 2024 4:13:56 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	Jan 2, 2024 4:13:56 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	141.05
Labor Hours:	2.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**141.05**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57264076
Invoice No. 55345 - 57264076

Client Department:
Department: 55345M
Work Order Description
55345-MEDIUM DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 162,226 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Jan-24	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	4.33	4.33
04-Jan-24	75050	OIL, ENGINE, 5W/30	6	2.73	16.38

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jan-24	Junior Hurst	0.58	65	37.7

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: JUHURST Performed on: 02-JAN-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		JUHURST	Jan 2, 2024 3:41:23 PM	No	
101,000 - FRA Change Oil Filters	Yes		JUHURST	Jan 2, 2024 3:41:23 PM	No	
102,000 - FRA Drain Engine Oil	Yes		JUHURST	Jan 2, 2024 3:41:23 PM	No	
103,000 - FRA Check Transmission Fluid	Done		JUHURST	Jan 2, 2024 3:41:23 PM	No	
104,000 - Lubricate Chassis	Done		JUHURST	Jan 2, 2024 3:41:23 PM	No	
105,000 - Replace or Clean A/C Filters	Done		JUHURST	Jan 2, 2024 3:41:23 PM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	Done		JUHURST	Jan 2, 2024 3:41:23 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		JUHURST	Jan 2, 2024 3:41:23 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		JUHURST	Jan 2, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:41:23 PM		

Activity Sub Total

Activity 20 Sub Total	
Parts:	20.71
Labor:	37.70
Labor Hours:	0.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**58.41**

Work Order Footer

Work Order 57264076 Total	
Parts:	20.71
Labor:	178.75
Labor Hours:	2.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**199.46**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57278623
Invoice No. 55345 - 57278623

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
tpms light on		Ford Transit	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	161,461 - DH

Chronology		
Reported	Dec 26, 2023 8:41:00 PM	Dec 26, 2023 8:41:00 PM
Started	Dec 26, 2023 9:29:00 PM	
Completed	Dec 26, 2023 10:45:00 PM	Dec 26, 2023 10:45:00 PM
Down Time		

Work Order Notes

Line 10 TPMS SENSOR REPLACED ON RF TIRE

Sensors relearned

Tpms light off

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Dec-23	FR3Z-1A189-C	SENSOR, MONITOR, PRESSURE, TIRE	1	42.77	42.77

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: NBARRETO Performed on: 26-DEC-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		NBARRETO	Dec 26, 2023 8:50:06 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NBARRETO	Dec 26, 2023 8:50:06 PM	No	
400 - Are you wearing the appropriate PPE?	Done		NBARRETO	Dec 26, 2023 8:50:06 PM	No	
700 - Have you performed the proper LOTO?	Done		NBARRETO	Dec 26, 2023 8:50:06 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		NBARRETO	Dec 26, 2023 8:50:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		NBARRETO	Dec 26, 2023 8:50:06 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	42.77
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**42.77**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57278623
Invoice No. 55345 - 57278623

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
tpms light on		Ford Transit	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	161,461 - DH

Activity Header
Activity: 15 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note: Tpms sensor replacement
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Dec-23	Nicolas Barreto	1.27	65	82.55

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	82.55
Labor Hours:	1.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**82.55**

Work Order Footer

Work Order 57278623 Total	
Parts:	42.77
Labor:	82.55
Labor Hours:	1.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**125.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57274044
Invoice No. 55345 - 57274044

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Check rear tires.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	160,609 - DH

Chronology		
Reported	Dec 19, 2023 11:41:00 PM	Dec 19, 2023 11:41:00 PM
Started	Dec 19, 2023 11:43:00 PM	
Completed	Dec 20, 2023 1:17:00 AM	Dec 20, 2023 1:17:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Check replace rear tires.

Cause: Tread depth below spec.

Correction: Remove and replaced LR wheels with 2 good used units.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 20-DEC-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		EARJOHNSON	Dec 20, 2023 1:17:29 AM	No	
200 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Dec 20, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				1:17:29 AM		
400 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Dec 20, 2023 1:17:29 AM	No	
700 - Have you performed the proper LOTO?	Done		EARJOHNSON	Dec 20, 2023 1:17:29 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Dec 20, 2023 1:17:29 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Dec 20, 2023 1:17:29 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57274044
Invoice No. 55345 - 57274044

Client Department:
Department: 55345M
Work Order Description
Check rear tires.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 160,609 - DH

Activity Header
Activity: 15 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note: Check rear tires.
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Dec-23	Earl Johnson	0.28	65	18.2
20-Dec-23	Earl Johnson	1.27	65	82.55

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	100.75
Labor Hours:	1.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**100.75**

Work Order Footer

Work Order 57274044 Total	
Parts:	0.00
Labor:	100.75
Labor Hours:	1.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**100.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 57264056
Invoice No. 55345 - 57264056

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	158,663 - DH

Chronology

Reported	Dec 7, 2023 11:35:17 PM	Dec 7, 2023 11:35:17 PM
Started	Dec 8, 2023 12:05:00 AM	
Completed	Dec 8, 2023 1:23:00 AM	Dec 8, 2023 1:23:00 AM
Down Time		

Work Order Notes

Line 10 Needs 2 front tires
Low tread
2 new tires mount and balance
Part number 131196995 qty2

Activity Header
Activity: 10 017/003/001 TIRE, CUSHION W/TREAD
Activity Note: needs 2 front tires
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Dec-23	131196995	TIRE, 195/75R16, WORKHORSE, HTL, WRANGLER, GOODYEAR	2	120	240

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Dec-23	Gaspard,Ronald	1.3	65	84.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	240.00
Labor:	84.50
Labor Hours:	1.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**324.50**

Work Order Footer

Work Order 57264056 Total	
Parts:	240.00
Labor:	84.50
Labor Hours:	1.30

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**324.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57243051
Invoice No. 55345 - 57243051

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	158,663 - DH

Chronology		
Reported	Dec 6, 2023 12:00:00 AM	Dec 6, 2023 12:00:00 AM
Started	Dec 7, 2023 8:48:00 PM	
Completed	Dec 8, 2023 12:05:00 AM	Dec 8, 2023 12:05:00 AM
Down Time		

Work Order Notes

Line 10 PMA
Service
Perform PMA service
Oil filter LF17531 qty1
Engine oil 10w30 qty 6 qts
Add washer fluid

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 07-DEC-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		RGASPARD	Dec 7, 2023 8:47:59 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Dec 7, 2023 8:47:59 PM	No	
400 - Are you wearing the appropriate PPE?	Done		RGASPARD	Dec 7, 2023 8:47:59 PM	No	
700 - Have you performed the proper LOTO?	Done		RGASPARD	Dec 7, 2023 8:47:59 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Dec 7, 2023 8:47:59 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Dec 7, 2023 8:47:59 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57243051
Invoice No. 55345 - 57243051

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	158,663 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Dec-23	Gaspard,Ronald	0.07	65	4.55
07-Dec-23	Gaspard,Ronald	1.45	65	94.25

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 07-DEC-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
10,800 - CHECK_All Destination Signage	Done	NA	RGASPARD	Dec 7, 2023 11:35:13 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
20,200 - CHECK_Public Address System	Done	NA	RGASPARD	Dec 7, 2023 11:35:13 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	NA	RGASPARD	Dec 7, 2023 11:35:13 PM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	NA	RGASPARD	Dec 7, 2023 11:35:13 PM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	NA	RGASPARD	Dec 7, 2023 11:35:13 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	NA	RGASPARD	Dec 7, 2023 11:35:13 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	NA	RGASPARD	Dec 7, 2023 11:35:13 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done	NA	RGASPARD	Dec 7, 2023 11:35:13 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
21,500 - INSPECT_High Idle Control	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	NA	RGASPARD	Dec 7, 2023 11:35:13 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	RGASPARD	Dec 7, 2023 11:35:13 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
33,000 - CSF (Curb Side Front)	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Dec 7, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:35:13 PM		
33,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
40,700 - CHECK_Passenger Stop Request System	Done	NA	RGASPARD	Dec 7, 2023 11:35:13 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
50,400 - LUBE_All Chassis Components	Done	NA	RGASPARD	Dec 7, 2023 11:35:13 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	2 32nds of an inch	needs 2 front tires	RGASPARD	Dec 7, 2023 11:35:13 PM	Yes	57264056
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.229 Inch		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.229 Inch		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.799 Inch		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.799 Inch		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done	NA	RGASPARD	Dec 7, 2023 11:35:13 PM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done	NA	RGASPARD	Dec 7, 2023 11:35:13 PM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Dec 7, 2023 11:35:13 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	98.80
Labor Hours:	1.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**98.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57243051
Invoice No. 55345 - 57243051

Client Department:
Department: 55345M
Work Order Description
55345-MEDIUM DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 158,663 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Dec-23	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	4.32	4.32
07-Dec-23	75050	OIL, ENGINE, 5W/30	6	2.73	16.38

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Dec-23	Gaspard,Ronald	0.07	65	4.55
07-Dec-23	Gaspard,Ronald	0.4	65	26

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: RGASPARD Performed on: 07-DEC-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Dec 7, 2023 11:37:50 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Dec 7, 2023 11:37:50 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Dec 7, 2023 11:37:50 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Dec 7, 2023 11:37:50 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Dec 7, 2023 11:37:50 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Dec 7, 2023 11:37:50 PM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	-	NA	RGASPARD	Dec 7, 2023 11:37:50 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Dec 7, 2023 11:37:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Dec 7, 2023 11:37:50 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	20.70
Labor:	30.55
Labor Hours:	0.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**51.25**

Work Order Footer

Work Order 57243051 Total	
Parts:	20.70
Labor:	129.35
Labor Hours:	1.99
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**150.05**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57256996
Invoice No. 55345 - 57256996

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Right low beam		Ford Transit	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	157,156 - DH

Chronology		
Reported	Nov 29, 2023 10:19:40 PM	Nov 29, 2023 10:19:40 PM
Started	Nov 29, 2023 10:22:00 PM	
Completed	Nov 29, 2023 10:56:00 PM	Nov 29, 2023 10:56:00 PM
Down Time		

Work Order Notes

Line 10 RIGHT LOW BEAM REPLACED

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: NBARRETO Performed on: 29-NOV-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		NBARRETO	Nov 29, 2023 10:54:52 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NBARRETO	Nov 29, 2023 10:54:52 PM	No	
400 - Are you wearing the appropriate PPE?	Done		NBARRETO	Nov 29, 2023 10:54:52 PM	No	
700 - Have you performed the proper LOTO?	Done		NBARRETO	Nov 29, 2023 10:54:52 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		NBARRETO	Nov 29, 2023 10:54:52 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		NBARRETO	Nov 29, 2023 10:54:52 PM	No	

Activity Sub Total

Activity 5 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57256996
Invoice No. 55345 - 57256996

Client Department:
Department: 55345M
Work Order Description
Right low beam
Requested By: NBARRETO
Created By: NBARRETO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 157,156 - DH

Activity Header
Activity: 15 034/001/000 HEADLAMP
Activity Note: Right low beam bulb
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Nov-23	H11BP	BULB, HEADLAMP	3	6.46	19.38
29-Nov-23	H11BP	BULB, HEADLAMP	1	6.46	6.46

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Nov-23	Nicolas Barreto	0.53	65	34.45

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	25.84
Labor:	34.45
Labor Hours:	0.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**60.29**

Work Order Footer

Work Order 57256996 Total	
Parts:	25.84
Labor:	34.45
Labor Hours:	0.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**60.29**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57244764
Invoice No. 55345 - 57244764

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Driver said driver side turn signal not working		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	155,012 - DH

Chronology		
Reported	Nov 15, 2023 1:24:05 PM	Nov 15, 2023 1:24:05 PM
Started	Nov 15, 2023 1:25:00 PM	
Completed	Nov 15, 2023 1:51:00 PM	Nov 15, 2023 1:51:00 PM
Down Time		

Work Order Notes

Line 10 Driver said turn signal not working

Bad light bulb

Replace light bulb turn signal completed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 15-NOV-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		HPIERRE	Nov 15, 2023 1:50:41 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Nov 15, 2023 1:50:41 PM	No	
400 - Are you wearing the appropriate PPE?	Done		HPIERRE	Nov 15, 2023 1:50:41 PM	No	
700 - Have you performed the proper LOTO?	Done		HPIERRE	Nov 15, 2023 1:50:41 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Nov 15, 2023 1:50:41 PM	No	
1,100 - Have you successfully completed the	Done		HPIERRE	Nov 15, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				1:50:41 PM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57244764
Invoice No. 55345 - 57244764

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Driver said driver side turn signal not working		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	155,012 - DH

Activity Header
Activity:20 034/004/021 LAMP, MARKER (FORMERLY 034-001-019)
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Nov-23	Pierre,Hubert J	0.4	65	26

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	26.00
Labor Hours:	0.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**26.00**

Work Order Footer

Work Order 57244764 Total	
Parts:	0.00
Labor:	26.00
Labor Hours:	0.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**26.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 57243010
Invoice No. 55345 - 57243010

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	154,673 - DH

Chronology

Reported	Nov 13, 2023 10:34:58 PM	Nov 13, 2023 10:34:58 PM
Started	Nov 14, 2023 12:12:00 AM	
Completed	Nov 14, 2023 5:30:00 PM	Nov 14, 2023 5:30:00 PM
Down Time		

Work Order Notes

Line 10 Driver side passenger seat belt not working
Can¿t retracted
Pull seat belt and unwrap the belt ,check ok

Activity Header
Activity: 10 174/022/011 COVER, SEAT, SEAT, BUS
Activity Note: passenger seat belt on driver side not retract
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Nov-23	H11BP	BULB, HEADLAMP	1	6.39	6.39

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Nov-23	Gaspard,Ronald	0.87	65	56.55

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	6.39
Labor:	56.55
Labor Hours:	0.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**62.94**

Work Order Footer

Work Order 57243010 Total	
Parts:	6.39
Labor:	56.55
Labor Hours:	0.87
Sublet Parts:	0.00

	Sublet Labor:	0.00
	Activity Sub Total	**62.94**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57193181
Invoice No. 55345 - 57193181

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	154,673 - DH

Chronology		
Reported	Nov 13, 2023 12:00:00 AM	Nov 13, 2023 12:00:00 AM
Started	Nov 13, 2023 9:17:00 PM	
Completed	Nov 14, 2023 12:12:00 AM	Nov 14, 2023 12:12:00 AM
Down Time		

Work Order Notes

Line 10 PMB
Service
Perform PMB service
Oil filter LF17531 qty1
Engine oil 10w30 qty 6 qts
Add washer fluid

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 13-NOV-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		RGASPARD	Nov 13, 2023 9:17:12 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Nov 13, 2023 9:17:12 PM	No	
400 - Are you wearing the appropriate PPE?	Done		RGASPARD	Nov 13, 2023 9:17:12 PM	No	
700 - Have you performed the proper LOTO?	Done		RGASPARD	Nov 13, 2023 9:17:12 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Nov 13, 2023 9:17:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Nov 13, 2023 9:17:12 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57193181
Invoice No. 55345 - 57193181

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	154,673 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Nov-23	Gaspard,Ronald	1.73	65	112.45

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 13-NOV-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Nov 13, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:34:53 PM		
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
10,800 - CHECK_All Destination Signage	Done	NA	RGASPARD	Nov 13, 2023 10:34:53 PM	No	
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
20,200 - CHECK_Public Address System	Done	NA	RGASPARD	Nov 13, 2023 10:34:53 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	NA	RGASPARD	Nov 13, 2023 10:34:53 PM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	NA	RGASPARD	Nov 13, 2023 10:34:53 PM	No	
20,800 - RECORD_Brake Performance Test	FEET	NA	RGASPARD	Nov 13,	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Distance				2023 10:34:53 PM		
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	NA	RGASPARD	Nov 13, 2023 10:34:53 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	NA	RGASPARD	Nov 13, 2023 10:34:53 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done	NA	RGASPARD	Nov 13, 2023 10:34:53 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
21,500 - INSPECT_High Idle Control	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	NA	RGASPARD	Nov 13, 2023 10:34:53 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	RGASPARD	Nov 13, 2023 10:34:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
33,000 - CSF (Curb Side Front)	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
40,700 - CHECK_Passenger Stop Request System	Done	NA	RGASPARD	Nov 13, 2023 10:34:53 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done	passenger seat belt on driver side not retract	RGASPARD	Nov 13, 2023 10:34:53 PM	Yes	57243010
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
50,400 - LUBE_All Chassis Components	Done	NA	RGASPARD	Nov 13, 2023 10:34:53 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.229 Inch		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.229 Inch		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Nov 13, 2023 10:34:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,900 - RECORD_LRI-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.799 Inch		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.799 Inch		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done	NA	RGASPARD	Nov 13, 2023 10:34:53 PM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done	NA	RGASPARD	Nov 13, 2023 10:34:53 PM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Nov 13, 2023 10:34:53 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	112.45
Labor Hours:	1.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**112.45**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57193181
Invoice No. 55345 - 57193181

Client Department:
Department: 55345M
Work Order Description
55345-MEDIUM DUTY PMB
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 154,673 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMB Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Nov-23	75050	OIL, ENGINE, 5W/30	6	2.73	16.38
13-Nov-23	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	4.32	4.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Nov-23	Gaspard,Ronald	0.47	65	30.55
14-Nov-23	Gaspard,Ronald	0.18	65	11.7

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMB Service
Task: 55345-Medium Duty PMB Inspection Performed by: RGASPARD Performed on: 13-NOV-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Nov 13, 2023 11:35:42 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Nov 13, 2023 11:35:42 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Nov 13, 2023 11:35:42 PM	No	
103,000 - FRA Check Transmission Fluid	-	NA	RGASPARD	Nov 13, 2023 11:35:42 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Nov 13, 2023 11:35:42 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Nov 13, 2023 11:35:42 PM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	-	NA	RGASPARD	Nov 13, 2023 11:35:42 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Nov 13, 2023 11:35:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Nov 13, 2023 11:35:42 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Nov 13, 2023 11:35:42 PM	No	
201,000 - Service Crankcase Breather	Done		RGASPARD	Nov 13, 2023 11:35:42 PM	No	
202,000 - FRA Change Water Separator ¿ Secondary Fuel Filters	No	NA	RGASPARD	Nov 13, 2023 11:35:42 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Nov 13, 2023 11:35:42 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Nov 13, 2023 11:35:42 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Nov 13, 2023 11:35:42 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	20.70
Labor:	42.25
Labor Hours:	0.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**62.95**

Work Order Footer

Work Order 57193181 Total	
Parts:	20.70
Labor:	154.70
Labor Hours:	2.38
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**175.40**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57219075
Invoice No. 55345 - 57219075

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Check engine light illuminated.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	151,944 - DH

Chronology		
Reported	Oct 29, 2023 10:03:20 AM	Oct 29, 2023 10:03:20 AM
Started	Oct 29, 2023 10:05:00 AM	
Completed	Oct 30, 2023 4:53:00 PM	Oct 30, 2023 4:53:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:cylender5 misfire and vehicle smell burning oil chech engine light on

Cause: needs valve cover gasket

Correction: replaced both side valve cover gasket and change cylinder 5 coil to sylinder 2 ,no check Light on .everything ok at this time

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 30-OCT-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Oct 30, 2023 4:48:58 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Oct 30, 2023 4:48:58 PM	No	
400 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Oct 30, 2023 4:48:58 PM	No	
700 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Oct 30, 2023 4:48:58 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Oct 30, 2023 4:48:58 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Oct 30, 2023 4:48:58 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57219075
Invoice No. 55345 - 57219075

Client Department:
Department: 55345M
Work Order Description
Check engine light illuminated.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 151,944 - DH

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Check engine light illuminated.
Reason for Repair:
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Oct-23	Earl Johnson	0.12	65	7.8
30-Oct-23	NELSON PIERRE-LOUIS	1.37	65	89.05

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	96.85
Labor Hours:	1.49
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**96.85**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57219075
Invoice No. 55345 - 57219075

Client Department:
Department: 55345M
Work Order Description
Check engine light illuminated.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 151,944 - DH

Activity Header
Activity: 25 045/000 POWER PLANT
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Oct-23	VS50879R	GASKET, COVER, VALVE, ENGINE	1	67.66	67.66

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Oct-23	NELSON PIERRE-LOUIS	6.6	65	429

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	67.66
Labor:	429.00
Labor Hours:	6.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**496.66**

Work Order Footer

Work Order 57219075 Total	
Parts:	67.66
Labor:	525.85
Labor Hours:	8.09
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**593.51**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 57193146
Invoice No. 55345 - 57193146

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Follow up Medium Duty PMA		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	150,785 - DH

Chronology		
Reported	Oct 20, 2023 8:02:58 AM	Oct 20, 2023 8:02:58 AM
Started	Oct 20, 2023 8:11:00 AM	
Completed	Oct 20, 2023 8:32:00 AM	Oct 20, 2023 8:32:00 AM
Down Time		

Work Order Notes

Line 10 PMA follow up need ac filter

Preventive maintenance

Replace ac filter completed

Activity Header
Activity: 10 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Need ac filter
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Oct-23	PA30000	FILTER, AIR, CABIN SEE AF56065	1	11.1	11.1

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Oct-23	Pierre,Hubert J	0.35	65	22.75

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	11.10
Labor:	22.75
Labor Hours:	0.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**33.85**

Work Order Footer

Work Order 57193146 Total	
Parts:	11.10
Labor:	22.75

	Labor Hours:	0.35
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**33.85**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57124027
Invoice No. 55345 - 57124027

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	150,785 - DH

Chronology		
Reported	Oct 19, 2023 12:00:00 AM	Oct 19, 2023 12:00:00 AM
Started	Oct 20, 2023 6:49:00 AM	
Completed	Oct 20, 2023 8:11:00 AM	Oct 20, 2023 8:11:00 AM
Down Time		

Work Order Notes

Line 10 PMA

Preventive maintenance

Performed PMA service completed

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 20-OCT-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		HPIERRE	Oct 20, 2023 8:02:12 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Oct 20, 2023 8:02:12 AM	No	
400 - Are you wearing the appropriate PPE?	Done		HPIERRE	Oct 20, 2023 8:02:12 AM	No	
700 - Have you performed the proper LOTO?	Done		HPIERRE	Oct 20, 2023 8:02:12 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Oct 20, 2023 8:02:12 AM	No	
1,100 - Have you successfully completed the	Done		HPIERRE	Oct 20, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				8:02:12 AM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57124027
Invoice No. 55345 - 57124027

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	150,785 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Oct-23	Pierre,Hubert J	1.37	65	89.05

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: HPIERRE Performed on: 20-OCT-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
10,800 - CHECK_All Destination Signage	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
20,200 - CHECK_Public Address System	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	60 Second*		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
20,700 - RECORD_Brake Performance Test Speed	60 Miles per Hour		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
20,800 - RECORD_Brake Performance Test Distance	6 FEET		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	6 FEET		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	90 Gravitational Force		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
21,500 - INSPECT_High Idle Control	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
21,800 - INSPECT_Parking Brake Operation	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
31,000 - SSF (Street Side Front)	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
32,000 - Engine Inspection	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	190 Degree Fahrenheit		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
32,100 - INSPECT_Intake System	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12 Volt*		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
33,000 - CSF (Curb Side Front)	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
40,700 - CHECK_Passenger Stop Request System	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
50,400 - LUBE_All Chassis Components	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
50,700 - INSPECT_Tire Condition	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,000 - RECORD_LF-Tire Tread Depth (32nds)	5 32nds of an inch		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	5 32nds of an inch		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	22 Inch		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	22 Inch		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
52,100 - INSPECT_Vibration Damper	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
53,600 - INSPECT_Tire Condition	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	22 Inch		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	22 Inch		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,200 - RETURN_Vehicle to Predetermined Location	Done		HPIERRE	Oct 20, 2023 8:10:05 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	89.05
Labor Hours:	1.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**89.05**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57124027
Invoice No. 55345 - 57124027

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	150,785 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Oct-23	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	4.32	4.32
20-Oct-23	75050	OIL, ENGINE, 5W/30	6	2.73	16.38

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: HPIERRE Performed on: 20-OCT-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Oct 20, 2023 8:03:09 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Oct 20, 2023 8:03:09 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Oct 20, 2023 8:03:09 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Oct 20, 2023 8:03:09 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Oct 20, 2023 8:03:09 AM	No	
105,000 - Replace or Clean A/C Filters	-	Need ac filter	HPIERRE	Oct 20, 2023 8:03:09 AM	Yes	57193146
106,000 - Drain Water from Fuel Water Separator (where applicable)	Done		HPIERRE	Oct 20, 2023 8:03:09 AM	No	
107,000 - FRA Change Primary Fuel Filter	No		HPIERRE	Oct 20, 2023 8:03:09 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Oct 20, 2023 8:03:09 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	20.70
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**20.70**

Work Order Footer

Work Order 57124027 Total	
Parts:	20.70
Labor:	89.05
Labor Hours:	1.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**109.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 57123974
Invoice No. 55345 - 57123974

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	147,036 - DH

Chronology

Reported	Sep 27, 2023 6:43:16 PM	Sep 27, 2023 6:43:16 PM
Started	Sep 27, 2023 7:08:00 PM	
Completed	Sep 27, 2023 7:48:00 PM	Sep 27, 2023 7:48:00 PM
Down Time		

Work Order Notes

Line 10 Reattached passenger side moulding with 2 screws.

Activity Header
Activity: 10
Activity Note: Passenger side moulding detached.
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Sep-23	Earl Johnson	0.67	65	43.55

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	43.55
Labor Hours:	0.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.55**

Work Order Footer

Work Order 57123974 Total	
Parts:	0.00
Labor:	43.55
Labor Hours:	0.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.55**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57043396
Invoice No. 55345 - 57043396

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	147,036 - DH

Chronology		
Reported	Sep 26, 2023 12:00:00 AM	Sep 26, 2023 12:00:00 AM
Started	Sep 27, 2023 5:02:00 PM	
Completed	Sep 27, 2023 7:08:00 PM	Sep 27, 2023 7:08:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: PM A service.

Cause: Due by mileage.

Correction: LOF engine oil and filter. Performed tire and brake inspection.

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 27-SEP-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Sep 27, 2023 7:06:39 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Sep 27, 2023 7:06:39 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Sep 27, 2023 7:06:39 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Sep 27, 2023 7:06:39 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Sep 27, 2023 7:06:39 PM	No	
11 - Have you successfully completed the	Done		EARJOHNSON	Sep 27, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				7:06:39 PM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57043396
Invoice No. 55345 - 57043396

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	147,036 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Sep-23	Earl Johnson	1.72	65	111.8

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: EARJOHNSON Performed on: 27-SEP-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
10,800 - CHECK_All Destination Signage	-	NA	EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
20,200 - CHECK_Public Address System	-	NA	EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	NA	EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	NA	EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	NA	EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	NA	EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	NA	EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	-	NA	EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
21,500 - INSPECT_High Idle Control	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	-	Passenger side moulding detached.	EARJOHNSON	Sep 27, 2023 6:43:29 PM	Yes	57123974
31,000 - SSF (Street Side Front)	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
32,000 - Engine Inspection	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,010 - INSPECT_Hood, Springs and Props	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	NA	EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
32,100 - INSPECT_Intake System	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.7 Volt*		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
33,000 - CSF (Curb Side Front)	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
40,700 - CHECK_Passenger Stop Request System	-	NA	EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,400 - LUBE_All Chassis Components	-	NA	EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
50,700 - INSPECT_Tire Condition	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.144 Inch		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.144 Inch		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
52,100 - INSPECT_Vibration Damper	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
53,600 - INSPECT_Tire Condition	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	-	NA	EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	60 Pounds per Square Inch		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,500 - RECORD_RRI-Air Pressure (psi)	60 Pounds per Square Inch		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	7 32nds of an inch		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	60 Pounds per Square Inch		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	60 Pounds per Square Inch		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.689 Inch		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.688 Inch		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	-	NA	EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	-	NA	EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,200 - RETURN_Vehicle to Predetermined Location	Done		EARJOHNSON	Sep 27, 2023 6:43:29 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	111.80
Labor Hours:	1.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**111.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57043396
Invoice No. 55345 - 57043396

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	147,036 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Sep-23	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	4.32	4.32
27-Sep-23	75050	OIL, ENGINE, 5W/30	6	2.74	16.44

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Sep-23	Earl Johnson	0.38	65	24.7

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: EARJOHNSON Performed on: 27-SEP-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		EARJOHNSON	Sep 27, 2023 7:06:16 PM	No	
101,000 - FRA Change Oil Filters	Yes		EARJOHNSON	Sep 27, 2023 7:06:16 PM	No	
102,000 - FRA Drain Engine Oil	Yes		EARJOHNSON	Sep 27, 2023 7:06:16 PM	No	
103,000 - FRA Check Transmission Fluid	Done		EARJOHNSON	Sep 27, 2023 7:06:16 PM	No	
104,000 - Lubricate Chassis	-	NA	EARJOHNSON	Sep 27, 2023 7:06:16 PM	No	
105,000 - Replace or Clean A/C Filters	Done		EARJOHNSON	Sep 27, 2023 7:06:16 PM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	-	NA	EARJOHNSON	Sep 27, 2023 7:06:16 PM	No	
107,000 - FRA Change Primary Fuel Filter	No		EARJOHNSON	Sep 27, 2023 7:06:16 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		EARJOHNSON	Sep 27, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				7:06:16 PM		

Activity Sub Total

Activity 20 Sub Total	
Parts:	20.76
Labor:	24.70
Labor Hours:	0.38
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**45.46**

Work Order Footer

Work Order 57043396 Total	
Parts:	20.76
Labor:	136.50
Labor Hours:	2.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**157.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57041622
Invoice No. 55345 - 57041622

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	142,969 - DH

Chronology

Reported	Sep 3, 2023 9:16:04 AM	Sep 3, 2023 9:16:04 AM
Started	Sep 3, 2023 10:03:00 AM	
Completed	Sep 4, 2023 1:02:00 PM	Sep 4, 2023 1:02:00 PM
Down Time		

Work Order Notes

Line 10 Trans service and front brake job was done

Activity Header

Activity: 10 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note:
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Sep-23	BRF-1896	PADS, BRAKE, DISC, FRONT, TRANSIT	1	51.72	51.72

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Sep-23	NELSON PIERRE-LOUIS	2.12	65	137.8

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	51.72
Labor:	137.80
Labor Hours:	2.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**189.52**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57041622
Invoice No. 55345 - 57041622

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	142,969 - DH

Activity Header
Activity: 20 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Sep-23	LK4Z-7A098-A	FILTER, TRANSMISSION NO CROSS	1	70.06	70.06

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Sep-23	NELSON PIERRE-LOUIS	5.85	65	380.25

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	70.06
Labor:	380.25
Labor Hours:	5.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**450.31**

Work Order Footer

Work Order 57041622 Total	
Parts:	121.78
Labor:	518.05
Labor Hours:	7.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**639.83**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56964076
Invoice No. 55345 - 56964076

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMC		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	143,127 - DH

Chronology		
Reported	Sep 1, 2023 12:00:00 AM	Sep 1, 2023 12:00:00 AM
Started	Sep 1, 2023 11:43:00 PM	
Completed	Sep 4, 2023 1:00:00 PM	Sep 4, 2023 1:00:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: pmc service

Cause: preventive maintenance

Correction: perform pmc service and lube ,trans service ,front brake jod was done

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 03-SEP-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Sep 3, 2023 10:03:14 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Sep 3, 2023 10:03:14 AM	No	
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Sep 3, 2023 10:03:14 AM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Sep 3, 2023 10:03:14 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Sep 3, 2023 10:03:14 AM	No	
11 - Have you successfully completed the Personal	Done		NPIERRE-	Sep 3, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	10:03:14 AM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56964076
Invoice No. 55345 - 56964076

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMC		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	143,127 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Sep-23	NELSON PIERRE-LOUIS	2.3	65	149.5

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS Performed on: 04-SEP-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
10,800 - CHECK_All Destination Signage	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
10,900 - *RPT*INSPECT_Body Damage,	Done		NPIERRE-	Sep 4, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Corrosion;DOCUMENT_Issues			LOUIS	12:51:06 PM		
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
20,200 - CHECK_Public Address System	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	0 Second*		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
20,700 - RECORD_Brake Performance Test Speed	0 Miles per Hour		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
20,800 - RECORD_Brake Performance Test Distance	0 FEET		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	0 FEET		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	0 Gravitational Force		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
21,500 - INSPECT_High Idle Control	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
31,000 - SSF (Street Side Front)	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
32,000 - Engine Inspection	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	280 Degree Fahrenheit		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
32,100 - INSPECT_Intake System	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.2 Volt*		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
33,000 - CSF (Curb Side Front)	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-	Sep 4, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	12:51:06 PM		
33,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
40,700 - CHECK_Passenger Stop Request System	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
50,400 - LUBE_All Chassis Components	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
50,700 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	11 32nds of an inch		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	10 32nds of an inch		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	64 Pounds per Square Inch		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	4 32nds of an inch		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	Yes	57041622
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	4 32nds of an inch		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	23.5 Inch		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	23.5 Inch		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
52,100 - INSPECT_Vibration Damper	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,600 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	54 Pounds per Square Inch		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	63 Pounds per Square Inch		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	63 Pounds per Square Inch		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	64 Pounds per Square Inch		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	17.5 Inch		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	17.5 Inch		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	Sep 4, 2023 12:51:06 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	149.50
Labor Hours:	2.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**149.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56964076
Invoice No. 55345 - 56964076

Client Department:
Department: 55345M
Work Order Description
55345-MEDIUM DUTY PMC
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 143,127 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM C Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Sep-23	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	4.32	4.32
03-Sep-23	75050	OIL, ENGINE, 5W/30	6	2.71	16.26

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Sep-23	NELSON PIERRE-LOUIS	1.92	65	124.8

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	20.58
Labor:	124.80
Labor Hours:	1.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**145.38**

Work Order Footer

Work Order 56964076 Total	
Parts:	20.58
Labor:	274.30
Labor Hours:	4.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**294.88**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 57015875
Invoice No. 55345 - 57015875

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345 SAFETY EQUIPMENT		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	141,744 - DH

Chronology		
Reported	Aug 25, 2023 8:05:21 AM	Aug 25, 2023 8:05:21 AM
Started	Aug 25, 2023 8:29:00 AM	
Completed	Aug 29, 2023 8:39:00 AM	Aug 29, 2023 8:39:00 AM
Down Time		

Work Order Notes

Line 10 Check PTC camera system, all working fine

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 29-AUG-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Aug 29, 2023 8:35:13 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Aug 29, 2023 8:35:13 AM	No	
4 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Aug 29, 2023 8:35:13 AM	No	
7 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Aug 29, 2023 8:35:13 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Aug 29, 2023 8:35:13 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Aug 29, 2023 8:35:13 AM	No	

Activity Sub Total

Activity 10 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 57015875
Invoice No. 55345 - 57015875

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345 SAFETY EQUIPMENT		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	141,744 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 57015875
Invoice No. 55345 - 57015875

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345 SAFETY EQUIPMENT		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	141,744 - DH

Activity Header
Activity: 30 053/004/000 SAFETY EQUIPMENT
Activity Note: safety equipment, PTC camera
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Aug-23	Rodriguez,Raul	0.85	65	55.25

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	55.25
Labor Hours:	0.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**55.25**

Work Order Footer

Work Order 57015875 Total	
Parts:	0.00
Labor:	55.25
Labor Hours:	0.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**55.25**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 56963989
Invoice No. 55345 - 56963989

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	139,323 - DH

Chronology		
Reported	Aug 8, 2023 8:52:48 PM	Aug 8, 2023 8:52:48 PM
Started		
Completed	Aug 22, 2023 4:19:00 PM	Aug 22, 2023 4:19:00 PM
Down Time		

Work Order Notes

Line 10 Remove and replaced front clearance light.

Activity Header

Activity: 10 034/003/000 LAMPS, SIGNAL, PARKING & BACKUP
Activity Note: Front clearance light out.
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Aug-23	MCL12AK	LAMP, MARKER/CLEARANCE, LED, AMBER	1	8.83	8.83

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	8.83
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.83**

Work Order Footer

Work Order 56963989 Total	
Parts:	8.83
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.83**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56985656
Invoice No. 55345 - 56985656

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR(Has to Start Bus Twice)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 140,497 - DH

Chronology		
Reported	Aug 16, 2023 12:15:00 AM	Aug 16, 2023 12:15:00 AM
Started	Aug 16, 2023 12:16:00 AM	
Completed	Aug 17, 2023 11:06:00 AM	Aug 17, 2023 11:06:00 AM
Down Time		

Work Order Notes

Line 10 Driver said bus cutting of at 5he stop sign

Bad purge valve and starter

Replace starter and purge valve i removed the starter install by nelson completed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 17-AUG-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Aug 17, 2023 11:03:54 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Aug 17, 2023 11:03:54 AM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Aug 17, 2023 11:03:54 AM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Aug 17, 2023 11:03:54 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Aug 17, 2023 11:03:54 AM	No	
11 - Have you successfully completed the Personal	Done		HPIERRE	Aug 17, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				11:03:54 AM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56985656
Invoice No. 55345 - 56985656

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR(Has to Start Bus Twice)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 140,497 - DH

Activity Header
Activity: 20 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Has to Start Bus Twice
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Aug-23	BL3Z-9B325-C	VALVE, PURGE, VAPOR, FUEL	1	81.97	81.97
16-Aug-23	LK4Z-11002-C	MOTOR, STARTER	1	205.8	205.8

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Aug-23	Pierre,Hubert J	8.17	65	531.05

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	287.77
Labor:	531.05
Labor Hours:	8.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**818.82**

Work Order Footer

Work Order 56985656 Total	
Parts:	287.77
Labor:	531.05
Labor Hours:	8.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**818.82**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56890701
Invoice No. 55345 - 56890701

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	139,323 - DH

Chronology		
Reported	Aug 8, 2023 12:00:00 AM	Aug 8, 2023 12:00:00 AM
Started	Aug 8, 2023 5:02:00 PM	
Completed	Aug 8, 2023 9:56:00 PM	Aug 8, 2023 9:56:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: PM A service.

Cause: Due by mileage.

Correction: LOF engine oil and filter. Performed tire and brake inspection.

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 08-AUG-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Aug 8, 2023 9:55:29 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Aug 8, 2023 9:55:29 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Aug 8, 2023 9:55:29 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Aug 8, 2023 9:55:29 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Aug 8, 2023 9:55:29 PM	No	
11 - Have you successfully completed the	Done		EARJOHNSON	Aug 8, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				9:55:29 PM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56890701
Invoice No. 55345 - 56890701

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	139,323 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Aug-23	Earl Johnson	1.93	65	125.45

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: EARJOHNSON Performed on: 08-AUG-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	-	Front clearance light out.	EARJOHNSON	Aug 8, 2023 8:52:42 PM	Yes	56963989
10,800 - CHECK_All Destination Signage	-	NA	EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
20,200 - CHECK_Public Address System	-	NA	EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	NA	EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	NA	EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	NA	EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	NA	EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	NA	EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
21,500 - INSPECT_High Idle Control	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
31,000 - SSF (Street Side Front)	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
32,000 - Engine Inspection	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	NA	EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
32,100 - INSPECT_Intake System	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.7 Volt*		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
33,000 - CSF (Curb Side Front)	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		EARJOHNSON	Aug 8, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:52:42 PM		
33,040 - INSPECT_Wiper Blades, Arms	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
40,700 - CHECK_Passenger Stop Request System	-	NA	EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
50,100 - *RPT*INSPECT_Steering components- Drag Link, Tie Rods ends and Steering Damper	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
50,400 - LUBE_All Chassis Components	-	NA	EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
50,700 - INSPECT_Tire Condition	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	11 32nds of an inch		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	11 32nds of an inch		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.145 Inch		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.145 Inch		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
52,100 - INSPECT_Vibration Damper	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
53,600 - INSPECT_Tire Condition	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	-	NA	EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	7 32nds of an inch		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	60 Pounds per Square Inch		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	60 Pounds per Square Inch		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	7 32nds of an inch		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	60 Pounds per Square Inch		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	60 Pounds per Square Inch		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.689 Inch		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.688 Inch		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	-	NA	EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
55,800 - CHECK_Double Check Valve - Primary,	Done		EARJOHNSON	Aug 8, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Secondary				8:52:42 PM		
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		EARJOHNSON	Aug 8, 2023 8:52:42 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	125.45
Labor Hours:	1.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**125.45**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56890701
Invoice No. 55345 - 56890701

Client Department:
Department: 55345M
Work Order Description
55345-MEDIUM DUTY PMA
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 139,323 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Aug-23	75050	OIL, ENGINE, 5W/30	6	2.59	15.54
08-Aug-23	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	4.31	4.31

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Aug-23	Earl Johnson	1.02	65	66.3

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: EARJOHNSON Performed on: 08-AUG-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		EARJOHNSON	Aug 8, 2023 8:54:40 PM	No	
101,000 - FRA Change Oil Filters	Yes		EARJOHNSON	Aug 8, 2023 8:54:40 PM	No	
102,000 - FRA Drain Engine Oil	Yes		EARJOHNSON	Aug 8, 2023 8:54:40 PM	No	
103,000 - FRA Check Transmission Fluid	Done		EARJOHNSON	Aug 8, 2023 8:54:40 PM	No	
104,000 - Lubricate Chassis	-	NA	EARJOHNSON	Aug 8, 2023 8:54:40 PM	No	
105,000 - Replace or Clean A/C Filters	Done		EARJOHNSON	Aug 8, 2023 8:54:40 PM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	-	NA	EARJOHNSON	Aug 8, 2023 8:54:40 PM	No	
107,000 - FRA Change Primary Fuel Filter	No		EARJOHNSON	Aug 8, 2023 8:54:40 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		EARJOHNSON	Aug 8, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:54:40 PM		

Activity Sub Total

Activity 20 Sub Total	
Parts:	19.85
Labor:	66.30
Labor Hours:	1.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**86.15**

Work Order Footer

Work Order 56890701 Total	
Parts:	19.85
Labor:	191.75
Labor Hours:	2.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**211.60**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56955652
Invoice No. 55345 - 56955652

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Rear AC malfunction.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	138,764 - DH

Chronology		
Reported	Aug 6, 2023 11:10:57 AM	Aug 6, 2023 11:10:57 AM
Started	Aug 6, 2023 11:12:00 AM	
Completed	Aug 7, 2023 4:49:00 PM	Aug 7, 2023 4:49:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear AC malfunction.

Cause: Rear ambient temp sensor out of range (Recmmd replace).

Correction: Noted for repair. AWP. Line 20 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear A/C malfunction

Cause: Defective Evaporator Temperature Sensor

Correction: Evaporator Temperature Sensor replaced

Part
Temp.sensor #CON-022-1 Qty1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 06-AUG-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Aug 6, 2023 1:12:43 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Aug 6, 2023 1:12:43 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Aug 6, 2023 1:12:43 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Aug 6, 2023 1:12:43 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Aug 6, 2023 1:12:43 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Aug 6, 2023 1:12:43 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56955652
Invoice No. 55345 - 56955652

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Rear AC malfunction.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	138,764 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear AC malfunction.
Reason for Repair:
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Aug-23	Earl Johnson	2.05	65	133.25

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	133.25
Labor Hours:	2.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**133.25**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56955652
Invoice No. 55345 - 56955652

Client Department:
Department: 55345M
Work Order Description
Rear AC malfunction.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 138,764 - DH

Activity Header
Activity: 25 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Aug-23	CON-022-1	SENSOR, TEMPERATURE, AIR, AMBIENT	1	39.52	39.52

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Aug-23	Fritz Simon	2.23	65	144.95

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	39.52
Labor:	144.95
Labor Hours:	2.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**184.47**

Work Order Footer

Work Order 56955652 Total	
Parts:	39.52
Labor:	278.20
Labor Hours:	4.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**317.72**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56954283
Invoice No. 55345 - 56954283

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Clearence light		Ford Transit	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	138,764 - DH

Chronology		
Reported	Aug 4, 2023 9:22:28 PM	Aug 4, 2023 9:22:28 PM
Started	Aug 4, 2023 9:23:00 PM	
Completed	Aug 4, 2023 9:32:00 PM	Aug 4, 2023 9:32:00 PM
Down Time		

Work Order Notes

Line 10 One clerence light replaced

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Aug-23	MCL12AK	LAMP, MARKER/CLEARANCE, LED, AMBER	1	8.83	8.83

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: NBARRETO Performed on: 04-AUG-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NBARRETO	Aug 4, 2023 9:23:53 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NBARRETO	Aug 4, 2023 9:23:53 PM	No	
4 - Are you wearing the appropriate PPE?	Done		NBARRETO	Aug 4, 2023 9:23:53 PM	No	
7 - Have you performed the proper LOTO?	Done		NBARRETO	Aug 4, 2023 9:23:53 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NBARRETO	Aug 4, 2023 9:23:53 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		NBARRETO	Aug 4, 2023 9:23:53 PM	No	

Activity Sub Total

	Activity 10 Sub Total	
	Parts:	8.83
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**8.83**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56954283
Invoice No. 55345 - 56954283

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Clearence light		Ford Transit	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	138,764 - DH

Activity Header
Activity:20 034/004/021 LAMP, MARKER (FORMERLY 034-001-019)
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Aug-23	Nicolas Barreto	0.13	65	8.45

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	8.45
Labor Hours:	0.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.45**

Work Order Footer

Work Order 56954283 Total	
Parts:	8.83
Labor:	8.45
Labor Hours:	0.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**17.28**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56944022
Invoice No. 55345 - 56944022

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR(Replace wheel chair bag)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 138,420 - DH

Chronology		
Reported	Aug 1, 2023 8:49:00 PM	Aug 1, 2023 8:49:00 PM
Started	Aug 1, 2023 8:50:00 PM	
Completed	Aug 1, 2023 10:55:00 PM	Aug 1, 2023 10:55:00 PM
Down Time		

Work Order Notes

Line 10 Replace wheel chair securement bag

Qty 1
Part Q5-822

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 01-AUG-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		AOWENS	Aug 1, 2023 10:54:17 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		AOWENS	Aug 1, 2023 10:54:17 PM	No	
4 - Are you wearing the appropriate PPE?	Done		AOWENS	Aug 1, 2023 10:54:17 PM	No	
7 - Have you performed the proper LOTO?	Done		AOWENS	Aug 1, 2023 10:54:17 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	Aug 1, 2023 10:54:17 PM	No	
11 - Have you successfully completed the Personal	Done		AOWENS	Aug 1, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				10:54:17 PM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56944022
Invoice No. 55345 - 56944022

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR(Replace wheel chair bag)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 138,420 - DH

Activity Header
Activity:20 055/023/000 LIFT, WHEELCHAIR, PASSENGER
Activity Note: Replace wheel Chair Bag
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Aug-23	Owens,Arthur	0.92	65	59.8
01-Aug-23	Owens,Arthur	0.2	65	13

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	72.80
Labor Hours:	1.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**72.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56944022
Invoice No. 55345 - 56944022

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345 PER DVIR(Replace wheel chair bag)		Ford Transit	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	138,420 - DH

Activity Header
Activity: 30 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 56944022 Total	
Parts:	0.00
Labor:	72.80
Labor Hours:	1.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**72.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56890772
Invoice No. 55345 - 56890772

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Rear AC malfunction.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	135,671 - DH

Chronology		
Reported	Jul 12, 2023 9:25:47 PM	Jul 12, 2023 9:25:47 PM
Started	Jul 12, 2023 9:26:00 PM	
Completed	Jul 13, 2023 12:34:00 AM	Jul 13, 2023 12:34:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear AC malfunction.

Cause: BL Code.

Correction: Isolated and checked both batteries, both good. Remove batteries and tray, cleaned and resecured and wires in underseat fuse box. Visually inspected circuit board for hotspots or sign of melting, found none. Let AC run for an hour without any issues.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 13-JUL-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jul 13, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:33:52 AM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jul 13, 2023 12:33:52 AM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jul 13, 2023 12:33:52 AM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jul 13, 2023 12:33:52 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jul 13, 2023 12:33:52 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jul 13, 2023 12:33:52 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56890772
Invoice No. 55345 - 56890772

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Rear AC malfunction.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	135,671 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear AC malfunction.
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Jul-23	Earl Johnson	2.57	65	167.05
13-Jul-23	Earl Johnson	0.55	65	35.75

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	202.80
Labor Hours:	3.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**202.80**

Work Order Footer

Work Order 56890772 Total	
Parts:	0.00
Labor:	202.80
Labor Hours:	3.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**202.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 56890617
Invoice No. 55345 - 56890617

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	135,671 - DH

Chronology		
Reported	Jul 12, 2023 6:36:10 PM	Jul 12, 2023 6:36:10 PM
Started	Jul 12, 2023 8:05:00 PM	
Completed	Jul 12, 2023 9:25:00 PM	Jul 12, 2023 9:25:00 PM
Down Time		

Work Order Notes

Line 10 Remove and replaced 2 front tires. Mounted, balanced, installed and torqued to spec.

Activity Header

Activity: 10 017/009 INFLATION & MONITORING, PRESSURE, TIRE
Activity Note: Front tires worn unevenly.
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Jul-23	131196995	TIRE, 195/75R16, WORKHORSE, HTL, WRANGLER, GOODYEAR	2	121	242

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Jul-23	Earl Johnson	1.33	65	86.45

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	242.00
Labor:	86.45
Labor Hours:	1.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**328.45**

Work Order Footer

Work Order 56890617 Total	
Parts:	242.00
Labor:	86.45
Labor Hours:	1.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**328.45**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56822686
Invoice No. 55345 - 56822686

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	135,671 - DH

Chronology		
Reported	Jul 12, 2023 12:00:00 AM	Jul 12, 2023 12:00:00 AM
Started	Jul 12, 2023 4:26:00 PM	
Completed	Jul 12, 2023 8:05:00 PM	Jul 12, 2023 8:05:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: PM A service.

Cause: Due by Mileage.

Correction: LOF engine oil and filter. Performed tire and brake inspection.

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 12-JUL-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jul 12, 2023 8:01:48 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jul 12, 2023 8:01:48 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jul 12, 2023 8:01:48 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jul 12, 2023 8:01:48 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jul 12, 2023 8:01:48 PM	No	
11 - Have you successfully completed the	Done		EARJOHNSON	Jul 12, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				8:01:48 PM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56822686
Invoice No. 55345 - 56822686

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	135,671 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Jul-23	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	4.29	4.29

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Jul-23	Earl Johnson	2.12	65	137.8

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: EARJOHNSON Performed on: 12-JUL-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
10,800 - CHECK_All Destination Signage	-	NA	EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
20,200 - CHECK_Public Address System	-	NA	EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	NA	EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	NA	EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	NA	EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	NA	EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	NA	EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	-	NA	EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
21,500 - INSPECT_High Idle Control	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
31,000 - SSF (Street Side Front)	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
32,000 - Engine Inspection	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	NA	EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
32,100 - INSPECT_Intake System	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.7 Volt*		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
33,000 - CSF (Curb Side Front)	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		EARJOHNSON	Jul 12, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				6:36:22 PM		
33,040 - INSPECT_Wiper Blades, Arms	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
40,700 - CHECK_Passenger Stop Request System	-	NA	EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
50,100 - *RPT*INSPECT_Steering components- Drag Link, Tie Rods ends and Steering Damper	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
50,400 - LUBE_All Chassis Components	-	NA	EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
50,700 - INSPECT_Tire Condition	-	Front tires worn unevenly.	EARJOHNSON	Jul 12, 2023 6:36:22 PM	Yes	56890617

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	4 32nds of an inch		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	3 32nds of an inch		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.143 Inch		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.142 Inch		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
52,100 - INSPECT_Vibration Damper	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
53,600 - INSPECT_Tire Condition	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	-	NA	EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	9 32nds of an inch		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	60 Pounds per Square Inch		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	60 Pounds per Square Inch		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	9 32nds of an inch		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	60 Pounds per Square Inch		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	60 Pounds per Square Inch		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.696 Inch		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.691 Inch		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	-	NA	EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
55,800 - CHECK_Double Check Valve - Primary,	-	NA	EARJOHNSON	Jul 12, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Secondary				6:36:22 PM		
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		EARJOHNSON	Jul 12, 2023 6:36:22 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	4.29
Labor:	137.80
Labor Hours:	2.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**142.09**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56822686
Invoice No. 55345 - 56822686

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	135,671 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Jul-23	75050	OIL, ENGINE, 5W/30	6	2.11	12.66

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Jul-23	Earl Johnson	1.43	65	92.95

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: EARJOHNSON Performed on: 12-JUL-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		EARJOHNSON	Jul 12, 2023 8:03:11 PM	No	
101,000 - FRA Change Oil Filters	Yes		EARJOHNSON	Jul 12, 2023 8:03:11 PM	No	
102,000 - FRA Drain Engine Oil	Yes		EARJOHNSON	Jul 12, 2023 8:03:11 PM	No	
103,000 - FRA Check Transmission Fluid	Done		EARJOHNSON	Jul 12, 2023 8:03:11 PM	No	
104,000 - Lubricate Chassis	-	NA	EARJOHNSON	Jul 12, 2023 8:03:11 PM	No	
105,000 - Replace or Clean A/C Filters	Done		EARJOHNSON	Jul 12, 2023 8:03:11 PM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	-	NA	EARJOHNSON	Jul 12, 2023 8:03:11 PM	No	
107,000 - FRA Change Primary Fuel Filter	No		EARJOHNSON	Jul 12, 2023 8:03:11 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		EARJOHNSON	Jul 12, 2023 8:03:11 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	12.66
Labor:	92.95
Labor Hours:	1.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**105.61**

Work Order Footer

Work Order 56822686 Total	
Parts:	16.95
Labor:	230.75
Labor Hours:	3.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**247.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56866706
Invoice No. 55345 - 56866706

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Windows leaking		Ford Transit	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	134,471 - DH

Chronology		
Reported	Jul 3, 2023 1:15:00 PM	Jul 3, 2023 1:15:00 PM
Started	Jul 3, 2023 1:22:00 PM	
Completed	Jul 3, 2023 3:13:00 PM	Jul 3, 2023 3:13:00 PM
Down Time		

Work Order Notes

Line 10 Right side emergency window, sealed in all 4 sides

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: NBARRETO Performed on: 03-JUL-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NBARRETO	Jul 3, 2023 2:48:52 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NBARRETO	Jul 3, 2023 2:48:52 PM	No	
4 - Are you wearing the appropriate PPE?	Done		NBARRETO	Jul 3, 2023 2:48:52 PM	No	
7 - Have you performed the proper LOTO?	Done		NBARRETO	Jul 3, 2023 2:48:52 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NBARRETO	Jul 3, 2023 2:48:52 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		NBARRETO	Jul 3, 2023 2:48:52 PM	No	

Activity Sub Total

Activity 10 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56866706
Invoice No. 55345 - 56866706

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Windows leaking		Ford Transit	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	134,471 - DH

Activity Header
Activity:20 053/004/000 SAFETY EQUIPMENT
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jul-23	Nicolas Barreto	1.83	65	118.95

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	118.95
Labor Hours:	1.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**118.95**

Work Order Footer

Work Order 56866706 Total	
Parts:	0.00
Labor:	118.95
Labor Hours:	1.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**118.95**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56853843
Invoice No. 55345 - 56853843

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
REAR AC SYSTEM		Ford Transit	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	133,547 - DH

Chronology		
Reported	Jun 27, 2023 9:02:06 PM	Jun 27, 2023 9:02:06 PM
Started	Jun 27, 2023 9:03:00 PM	
Completed	Jun 27, 2023 10:34:00 PM	Jun 27, 2023 10:34:00 PM
Down Time		

Work Order Notes

Line 10 AC not cooling, code BL Line 20 Check rear ac found that the rear ac is blow at 37.0 degrees vehicle has no BL code at this time.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: NBARRETO Performed on: 27-JUN-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NBARRETO	Jun 27, 2023 9:11:32 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NBARRETO	Jun 27, 2023 9:11:32 PM	No	
4 - Are you wearing the appropriate PPE?	Done		NBARRETO	Jun 27, 2023 9:11:32 PM	No	
7 - Have you performed the proper LOTO?	Done		NBARRETO	Jun 27, 2023 9:11:32 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NBARRETO	Jun 27, 2023 9:11:32 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		NBARRETO	Jun 27, 2023 9:11:32 PM	No	

Activity Sub Total

Activity 10 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56853843
Invoice No. 55345 - 56853843

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
REAR AC SYSTEM		Ford Transit	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	133,547 - DH

Activity Header
Activity: 20 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: REAR AC DIAG
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Jun-23	Nicolas Barreto	0.47	65	30.55

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	30.55
Labor Hours:	0.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**30.55**

Work Order Footer

Work Order 56853843 Total	
Parts:	0.00
Labor:	30.55
Labor Hours:	0.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**30.55**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56840035
Invoice No. 55345 - 56840035

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Check engine light on		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	132,855 - DH

Chronology		
Reported	Jun 22, 2023 1:10:36 PM	Jun 22, 2023 1:10:36 PM
Started	Jun 22, 2023 5:45:00 PM	
Completed	Jun 22, 2023 9:18:00 PM	Jun 22, 2023 9:18:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: VEHICLE CAME IN FOR CHECK ENG LIGHT ON

Cause: MULTIPLE MISFIRE ON CYLINDERS

Correction: CHANGE ALL SPARK PLUGS PART # CYFS-12YT. AFTER ROAD TEST UNIT WORKING PERFECT RETURN UNIT BACK TO WORK

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 22-JUN-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Jun 22, 2023 9:17:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Jun 22, 2023 9:17:15 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Jun 22, 2023 9:17:15 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Jun 22, 2023 9:17:15 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Jun 22, 2023 9:17:15 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Jun 22, 2023 9:17:15 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56840035
Invoice No. 55345 - 56840035

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Check engine light on		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	132,855 - DH

Activity Header
Activity: 15 020 GROUP, DRIVETRAIN
Activity Note: Check engine light on
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Jul-23	CYFS-12YT-6	PLUG, SPARK	8	4	32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Jun-23	Junior Hurst	3.55	65	230.75

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	32.00
Labor:	230.75
Labor Hours:	3.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**262.75**

Work Order Footer

Work Order 56840035 Total	
Parts:	32.00
Labor:	230.75
Labor Hours:	3.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**262.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56821693
Invoice No. 55345 - 56821693

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	131,790 - DH

Chronology		
Reported	Jun 16, 2023 9:52:42 AM	Jun 16, 2023 9:52:42 AM
Started	Jun 16, 2023 9:56:00 AM	
Completed	Jun 16, 2023 3:02:00 PM	Jun 16, 2023 3:02:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: per ptc ,front camera in the bus appears to be pointing downwrd ,

Cause: front camera was loos from te braket

Correction: readjusted the lift ,and front camera , both ac working good at this time

Activity Header
Activity: 10 174/001/001 BODY, BUS, COMPLETE
Activity Note: Rear bumper
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Jun-23	445357	BUMPER, ALUMINUM, REAR, 10'	1	1,280.01	1,280.01

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jun-23	NELSON PIERRE-LOUIS	3.42	65	222.3

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	1,280.01
Labor:	222.30
Labor Hours:	3.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1,502.31**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56821693
Invoice No. 55345 - 56821693

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	131,790 - DH

Activity Header
Activity: 20 036/008/002 CAMERA, SYSTEM, SURVEILLANCE
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56821693
Invoice No. 55345 - 56821693

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	131,790 - DH

Activity Header
Activity: 30 055 HANDLING, CARGO RESTRAINT & LIFT SYSTEM (POWER UNITS, TRAILERS)
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jun-23	NELSON PIERRE-LOUIS	1.42	65	92.3

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	92.30
Labor Hours:	1.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**92.30**

Work Order Footer

Work Order 56821693 Total	
Parts:	1,280.01
Labor:	314.60
Labor Hours:	4.84
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1,594.61**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56759918
Invoice No. 55345 - 56759918

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	131,994 - DH

Chronology		
Reported	Jun 15, 2023 11:05:15 PM	Jun 15, 2023 11:05:15 PM
Started	Jun 15, 2023 11:05:00 PM	
Completed	Jun 16, 2023 1:24:00 PM	Jun 16, 2023 1:24:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: pmb service

Cause: preventive maitenance

Correction: preform pmb service and lube

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 16-JUN-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Jun 16, 2023 9:53:38 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Jun 16, 2023 9:53:38 AM	No	
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Jun 16, 2023 9:53:38 AM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Jun 16, 2023 9:53:38 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Jun 16, 2023 9:53:38 AM	No	
11 - Have you successfully completed the Personal	Done		NPIERRE-	Jun 16, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	9:53:38 AM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56759918
Invoice No. 55345 - 56759918

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	131,994 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jun-23	NELSON PIERRE-LOUIS	2.23	65	144.95

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS Performed on: 16-JUN-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
10,800 - CHECK_All Destination Signage	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
10,900 - *RPT*INSPECT_Body Damage,	Done		NPIERRE-	Jun 16, 2023	Yes	56821693

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Corrosion;DOCUMENT_Issues			LOUIS	1:23:32 PM		
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
20,200 - CHECK_Public Address System	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	0 Second*		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
20,700 - RECORD_Brake Performance Test Speed	0 Miles per Hour		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
20,800 - RECORD_Brake Performance Test Distance	0 FEET		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	0 FEET		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	0 Gravitational Force		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
21,500 - INSPECT_High Idle Control	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
31,000 - SSF (Street Side Front)	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
32,000 - Engine Inspection	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	280 Degree Fahrenheit		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
32,100 - INSPECT_Intake System	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.2 Volt*		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
33,000 - CSF (Curb Side Front)	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-	Jun 16, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	1:23:32 PM		
33,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
40,700 - CHECK_Passenger Stop Request System	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
50,400 - LUBE_All Chassis Components	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
50,700 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	10 32nds of an inch		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	66 Pounds per Square Inch		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	23.5 Inch		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	23.5 Inch		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
52,100 - INSPECT_Vibration Damper	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,600 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	67 Pounds per Square Inch		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	66 Pounds per Square Inch		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	17.5 Inch		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	17.5 Inch		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	Jun 16, 2023 1:23:32 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	144.95
Labor Hours:	2.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**144.95**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56759918
Invoice No. 55345 - 56759918

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	131,994 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMB Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Jun-23	75050	OIL, ENGINE, 5W/30	6	2.11	12.66
16-Jun-23	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	4.21	4.21

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jun-23	NELSON PIERRE-LOUIS	1	65	65

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	16.87
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**81.87**

Work Order Footer

Work Order 56759918 Total	
Parts:	16.87
Labor:	209.95
Labor Hours:	3.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**226.82**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56817595
Invoice No. 55345 - 56817595

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
WC lift malfunction		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	131,576 - DH

Chronology		
Reported	Jun 14, 2023 11:22:57 PM	Jun 14, 2023 11:22:57 PM
Started	Jun 14, 2023 11:25:00 PM	
Completed	Jun 15, 2023 12:29:00 AM	Jun 15, 2023 12:29:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: WC lift malfunction.

Cause: Faulty control pendant.

Correction: Remove and replaced WC lift control pendant with good used unit. Ran lift through 4 consecutive cycles without any issues.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 14-JUN-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jun 14, 2023 11:53:56 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jun 14, 2023 11:53:56 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jun 14, 2023 11:53:56 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jun 14, 2023 11:53:56 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jun 14, 2023 11:53:56 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jun 14, 2023 11:53:56 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56817595
Invoice No. 55345 - 56817595

Client Department:
Department: 55345M
Work Order Description
WC lift malfunction
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 131,576 - DH

Activity Header
Activity: 15 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: WC lift malfunction
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Jun-23	Earl Johnson	0.58	65	37.7
15-Jun-23	Earl Johnson	0.47	65	30.55

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	68.25
Labor Hours:	1.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**68.25**

Work Order Footer

Work Order 56817595 Total	
Parts:	0.00
Labor:	68.25
Labor Hours:	1.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**68.25**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56109002
Invoice No. 55345 - 56109002

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FIRST TRANSIT AC INSPECTION		Ford Transit	
Requested By:	SPACE	**Status:**	40 - Closed (40)
Created By:	SPACE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	130,323 -

Chronology		
Reported	Jun 7, 2023 4:27:50 PM	Jun 7, 2023 4:27:50 PM
Started	Jun 8, 2023 6:45:00 AM	
Completed	Jun 8, 2023 8:34:00 AM	Jun 8, 2023 8:34:00 AM
Down Time		

Work Order Notes

Line 10 Complainte: firt transir ac inspection

Cause : pre annual inspection

Correction: inspected all electrical component .ok

Inspected belts pulleys and tensioner.ok

Inspected all lines and hoses .ok

Inspected both AC compresors ,both condensers .ok

Inspeted all fans and blowers on every speed ok

No leaks no chaffing

Front ac temp 34 , rear ac temp 37,outside temp 90

Vehicle returned to service

Part.pa30000

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assesment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assesment

Check List

Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 08-JUN-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:38 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:38 AM	No	
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:38 AM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:38 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:38 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:38 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56109002
Invoice No. 55345 - 56109002

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FIRST TRANSIT AC INSPECTION		Ford Transit	
Requested By:	SPACE	**Status:**	40 - Closed (40)
Created By:	SPACE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	130,323 -

Activity Header
Activity: 10 001/001/001 AIR CONDITIONING
Activity Note: FIRST TRANSIT AC INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Jun-23	PA30000	FILTER, AIR, CABIN SEE AF56065	1	11.1	11.1

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Jun-23	NELSON PIERRE-LOUIS	1.65	65	107.25

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: FIRST TRANSIT AC INSPECTION
Task: FIRST TRANSIT AC INSPECTION Performed by: NPIERRE-LOUIS Performed on: 08-JUN-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 VISUAL INSPECTION	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
10,100 - CHECK PHYSICAL DAMAGE, MISSING PARTS	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
10,200 - CHECK REFRIGERANT HOSES FOR CHAFING	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
10,300 - CHECK EVAPORATOR AND CONDENSER FOR OBSTRUCTIONS	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
10,400 - CHECK OPERATION OF FAST IDLE	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
20,000 - SECTION 2 DIAGNOSE THE SYSTEM CONDITION	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
20,100 - ATTACH GAUGES AND RUN SYSTEM 10 MINUTES	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
20,200 - CHECK FOR EVEN AIR DISTRIBUTION	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
20,300 - CHECK FOR PROPER OPERATION OF ALL HVAC MODES	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,400 - CHECK DRIVERS A/C SYSTEM	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
20,500 - RECORD AMBIENT TEMPERATURE BEFORE	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
20,600 - RECORD DISCHARGE PRESSURE BEFORE	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
20,700 - RECORD SUCTION PRESSURE BEFORE	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
20,710 - RECORD OUTLET TEMPERATURE BEFORE	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
20,800 - CHECK HIGH AND LOW PRESSURE CUTOUT SWITCHES FOR LEAKS	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
30,000 - SECTION 3 COMPRESSOR OPERATIONAL INSPCTION	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
30,100 - CHECK FOR UNUSUAL NOISES	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
30,200 - CHECK CLUTCH RESISTANCE READING	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
30,300 - CHECK AIR GAP IN COMPRESSOR CLUTCH	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
30,400 - CHECK COMPRESSOR MOUNTING AND ALIGHMENT	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
30,500 - INSPECT COMPRESSOR BELT(S) OR DRIVE SYSTEM	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
30,600 - CHECK FOR CRACKS AND WEAR	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
30,700 - CHECK FOR PROPER WIDTH AND LENGTH	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
30,800 - CHECK FOR PROPER ALIGNMENT	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
40,000 - SECTION 4 LEAK TEST SYSTEM	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
40,100 - CHICK A/C LINES WITH AN ELECTRONIC LEAK DETECTOR	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
40,200 - CHECK HOSES, FITTINGS, VALVES AND COMPRESSOR SHAFT SEAL	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
40,300 - CHECK HEATER HOSES FOR LEAKS	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
50,000 - SECTION 5 SYSTEM CONTAMINATION	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
50,100 - CHECK INLINE DRIER	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
50,200 - CHECK ACCUMULATOR	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
60,000 - SECTION 6 CHARGE SYSTEM	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
60,100 - IF CHARGING IS REQUIRED, CHARGE BY WEIGHT	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
60,200 - CHECK FOR LEAKS AFTER CHARGING	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
70,000 - SECTION 7 FAN MOTORS	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,100 - CHECK SEALED MOTORS FOR PROPER OPERATION	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
70,200 - INSPECT BLOWER WHEELS	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
70,300 - CHECK ELECTRICAL WIRING & CONNECTIONS	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
80,000 - SECTION 8 OPERATE SYSTEM	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
80,100 - CHECK FOR PROPER HEATING & COOLING	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
80,200 - CHECK TEMPERATURE CONTROLS	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
80,300 - CHECK DEFROST MODE	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
90,000 - SECTION 9 PERFORMANCE TEST READINGS	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
90,100 - RECORD AMBIENT TEMPERATURE READINGS AFTER	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
90,200 - RECORD DISCHARGE PRESSURE AFTER	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
90,300 - RECORD SUCTION PRESSURE AFTER	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
90,400 - RECORD OUTLET TEMPERATURE	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
100,000 - SECTION 10 RESTORE SYSTEM	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
100,100 - DISCONNECT GAUGES	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	
100,200 - CLOSE ALL PANELS, DOOR, ETC.	Done		NPIERRE-LOUIS	Jun 8, 2023 8:12:07 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	11.10
Labor:	107.25
Labor Hours:	1.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**118.35**

Work Order Footer

Work Order 56109002 Total	
Parts:	11.10
Labor:	107.25
Labor Hours:	1.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**118.35**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56650428
Invoice No. 55345 - 56650428

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	128,163 - DH

Chronology		
Reported	May 23, 2023 12:00:00 AM	May 23, 2023 12:00:00 AM
Started	May 25, 2023 4:05:00 AM	
Completed	May 25, 2023 9:16:00 AM	May 25, 2023 9:16:00 AM
Down Time		

Work Order Notes

Line 10 Complaint:

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 25-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	May 25, 2023 7:42:57 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	May 25, 2023 7:42:57 AM	No	
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	May 25, 2023 7:42:57 AM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	May 25, 2023 7:42:57 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	May 25, 2023 7:42:57 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	May 25, 2023 7:42:57 AM	No	

Activity Sub Total

Activity 5 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56650428
Invoice No. 55345 - 56650428

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	128,163 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-May-23	NELSON PIERRE-LOUIS	2.7	65	175.5

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS Performed on: 25-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
10,800 - CHECK_All Destination Signage	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
20,200 - CHECK_Public Address System	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	0 Second*		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
20,700 - RECORD_Brake Performance Test Speed	0 Miles per Hour		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
20,800 - RECORD_Brake Performance Test Distance	0 FEET		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	0 FEET		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	0 Gravitational Force		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
21,500 - INSPECT_High Idle Control	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
21,800 - INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
31,000 - SSF (Street Side Front)	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
32,000 - Engine Inspection	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	280 Degree Fahrenheit		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
32,100 - INSPECT_Intake System	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.2 Volt*		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
33,000 - CSF (Curb Side Front)	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
40,700 - CHECK_Passenger Stop Request System	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
50,400 - LUBE_All Chassis Components	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
50,700 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,000 - RECORD_LF-Tire Tread Depth (32nds)	11 32nds of an inch		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	10 32nds of an inch		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	66 Pounds per Square Inch		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	23.3 Inch		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	23.3 Inch		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
52,100 - INSPECT_Vibration Damper	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
53,600 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	10 32nds of an inch		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	66 Pounds per Square Inch		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	10 32nds of an inch		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	67 Pounds per Square Inch		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	66 Pounds per Square Inch		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	17.5 Inch		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	17.5 Inch		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,200 - RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	May 25, 2023 7:53:56 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	175.50
Labor Hours:	2.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**175.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56650428
Invoice No. 55345 - 56650428

Client Department:
Department: 55345M
Work Order Description
55345-MEDIUM DUTY PMA
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 128,163 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-May-23	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	4.21	4.21
02-Jun-23	75050	OIL, ENGINE, 5W/30	6	2.11	12.66

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-May-23	NELSON PIERRE-LOUIS	1.22	65	79.3

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: NPIERRE-LOUIS Performed on: 25-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	May 25, 2023 7:43:45 AM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	May 25, 2023 7:43:45 AM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	May 25, 2023 7:43:45 AM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	May 25, 2023 7:43:45 AM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	May 25, 2023 7:43:45 AM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	May 25, 2023 7:43:45 AM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	Done		NPIERRE-LOUIS	May 25, 2023 7:43:45 AM	No	
107,000 - FRA Change Primary Fuel Filter	No		NPIERRE-LOUIS	May 25, 2023 7:43:45 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-	May 25, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	7:43:45 AM		

Activity Sub Total

Activity 20 Sub Total	
Parts:	16.87
Labor:	79.30
Labor Hours:	1.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**96.17**

Work Order Footer

Work Order 56650428 Total	
Parts:	16.87
Labor:	254.80
Labor Hours:	3.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**271.67**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56754380
Invoice No. 55345 - 56754380

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Lift road call		Ford Transit	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	127,916 - DH

Chronology		
Reported	May 23, 2023 4:27:11 PM	May 23, 2023 4:27:11 PM
Started	May 23, 2023 4:30:00 PM	
Completed	May 23, 2023 4:38:00 PM	May 23, 2023 4:38:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction: Line 20 Road call canceled, driver fixed lift, did not had to leave base

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: NBARRETO Performed on: 23-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NBARRETO	May 23, 2023 4:38:22 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		NBARRETO	May 23, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				4:38:22 PM		
4 - Are you wearing the appropriate PPE?	Done		NBARRETO	May 23, 2023 4:38:22 PM	No	
7 - Have you performed the proper LOTO?	Done		NBARRETO	May 23, 2023 4:38:22 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NBARRETO	May 23, 2023 4:38:22 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		NBARRETO	May 23, 2023 4:38:22 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56754380
Invoice No. 55345 - 56754380

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Lift road call		Ford Transit	
Requested By:	NBARRETO	**Status:**	40 - Closed (40)
Created By:	NBARRETO	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	127,916 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-May-23	Nicolas Barreto	0.12	65	7.8

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	7.80
Labor Hours:	0.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.80**

Work Order Footer

Work Order 56754380 Total	
Parts:	0.00
Labor:	7.80
Labor Hours:	0.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56751093
Invoice No. 55345 - 56751093

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Seat jam		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	127,707 - DH

Chronology		
Reported	May 22, 2023 9:07:26 PM	May 22, 2023 9:07:26 PM
Started	May 22, 2023 9:11:00 PM	
Completed	May 22, 2023 9:42:00 PM	May 22, 2023 9:42:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: unit came in for seat belt issue

Cause: belt was stuck

Correction: belt now working as design

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 22-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	May 22, 2023 9:40:46 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		JUHURST	May 22, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				9:40:46 PM		
4 - Are you wearing the appropriate PPE?	Done		JUHURST	May 22, 2023 9:40:46 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	May 22, 2023 9:40:46 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	May 22, 2023 9:40:46 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	May 22, 2023 9:40:46 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56751093
Invoice No. 55345 - 56751093

Client Department:
Department: 55345M
Work Order Description
Seat jam
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 127,707 - DH

Activity Header
Activity: 15 020 GROUP, DRIVETRAIN
Activity Note: Seat belt issue
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-May-23	Junior Hurst	0.5	65	32.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	32.50
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**32.50**

Work Order Footer

Work Order 56751093 Total	
Parts:	0.00
Labor:	32.50
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**32.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56736578
Invoice No. 55345 - 56736578

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
WC securement broke.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	127,080 - DH

Chronology		
Reported	May 17, 2023 11:18:55 PM	May 17, 2023 11:18:55 PM
Started	May 17, 2023 11:21:00 PM	
Completed	May 18, 2023 12:27:00 AM	May 18, 2023 12:27:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: WC securement broke.

Cause: Damaged during operation.

Correction: Remove WC securement, repaired. Reinstalled securement.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 18-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	May 18, 2023 12:04:05 AM	No	
2 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	May 18, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				12:04:05 AM		
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	May 18, 2023 12:04:05 AM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	May 18, 2023 12:04:05 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	May 18, 2023 12:04:05 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	May 18, 2023 12:04:05 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56736578
Invoice No. 55345 - 56736578

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
WC securement broke.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	127,080 - DH

Activity Header
Activity: 15 002/011/003 BELT & RETAINER, SEAT
Activity Note: WC securement broke.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-May-23	Earl Johnson	0.45	65	29.25
17-May-23	Earl Johnson	0.65	65	42.25

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	71.50
Labor Hours:	1.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**71.50**

Work Order Footer

Work Order 56736578 Total	
Parts:	0.00
Labor:	71.50
Labor Hours:	1.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**71.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56688495
Invoice No. 55345 - 56688495

Client Department:
Department: 55345M
Work Order Description
Road Call
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 125,320 - DH

Chronology		
Reported	May 7, 2023 12:24:53 PM	May 7, 2023 12:24:53 PM
Started	May 7, 2023 12:25:00 PM	
Completed	May 14, 2023 1:20:00 PM	May 14, 2023 1:20:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: vehicle overheathing

Cause: n/a

Correction: added water drive the bus to base for mire diagnostic

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 14-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	May 14, 2023 1:19:58 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		NPIERRE-	May 14, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?			LOUIS	1:19:58 PM		
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	May 14, 2023 1:19:58 PM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	May 14, 2023 1:19:58 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	May 14, 2023 1:19:58 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	May 14, 2023 1:19:58 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56688495
Invoice No. 55345 - 56688495

Client Department:
Department: 55345M
Work Order Description
Road Call
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 125,320 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-May-23	NELSON PIERRE-LOUIS	1.85	65	120.25

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	120.25
Labor Hours:	1.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**120.25**

Work Order Footer

Work Order 56688495 Total	
Parts:	0.00
Labor:	120.25
Labor Hours:	1.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**120.25**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56694031
Invoice No. 55345 - 56694031

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Window issue		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	125,553 - DH

Chronology		
Reported	May 8, 2023 4:30:10 PM	May 8, 2023 4:30:10 PM
Started	May 8, 2023 5:03:00 PM	
Completed	May 8, 2023 6:02:00 PM	May 8, 2023 6:02:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Window issue

Cause: parking worn out

Correction: replace new parking to window now it is perfect return unir back to work

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 08-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	May 8, 2023 6:01:23 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	May 8, 2023 6:01:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
4 - Are you wearing the appropriate PPE?	Done		JUHURST	May 8, 2023 6:01:23 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	May 8, 2023 6:01:23 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	May 8, 2023 6:01:23 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	May 8, 2023 6:01:23 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56694031
Invoice No. 55345 - 56694031

Client Department:
Department: 55345M
Work Order Description
Window issue
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 125,553 - DH

Activity Header
Activity: 15 010 CHASSIS GROUP
Activity Note: Window issue
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-May-23	Junior Hurst	0.98	65	63.7

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	63.70
Labor Hours:	0.98
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**63.70**

Work Order Footer

Work Order 56694031 Total	
Parts:	0.00
Labor:	63.70
Labor Hours:	0.98
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**63.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56693118
Invoice No. 55345 - 56693118

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Unit in for over heat		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	125,553 - DH

Chronology		
Reported	May 8, 2023 1:18:15 PM	May 8, 2023 1:18:15 PM
Started	May 8, 2023 1:21:00 PM	
Completed	May 8, 2023 5:02:00 PM	May 8, 2023 5:02:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Vehicle came in for over heat

Cause: Water hose broken

Correction: removed and replace new hose part # K4Z8A519-M also replace coolant unit now working asdesign

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 08-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	May 8, 2023 4:59:41 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		JUHURST	May 8, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				4:59:41 PM		
4 - Are you wearing the appropriate PPE?	Done		JUHURST	May 8, 2023 4:59:41 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	May 8, 2023 4:59:41 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	May 8, 2023 4:59:41 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	May 8, 2023 4:59:41 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56693118
Invoice No. 55345 - 56693118

Client Department:
Department: 55345M
Work Order Description
Unit in for over heat
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 125,553 - DH

Activity Header
Activity: 15 020 GROUP, DRIVETRAIN
Activity Note: Over heat
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-May-23	LK4Z-8A519-M	HOSE, OUTLET, COOLANT	1	25.2	25.2

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-May-23	Junior Hurst	3.67	65	238.55

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	25.20
Labor:	238.55
Labor Hours:	3.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**263.75**

Work Order Footer

Work Order 56693118 Total	
Parts:	25.20
Labor:	238.55
Labor Hours:	3.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**263.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 56671158
Invoice No. 55345 - 56671158

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Check A/C		Ford Transit	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	125,295 - DH

Chronology		
Reported	May 1, 2023 12:52:12 PM	May 1, 2023 12:52:12 PM
Started	May 1, 2023 12:54:00 PM	
Completed	May 4, 2023 12:24:00 PM	May 4, 2023 12:24:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear A/C / Coolant Reservoir / Front Condenser Fan.

Cause: Coolant Reservoir Leaking / Need Rear A/C high Pressure hose. leaking.

Correction: Remove & Replace Coolant Reservoir.
Parts #KK2Z-8A080-B Qty (1)

Line 20 Rear A/C High Pressure hose Leaking. Evacuate Rear A/C Remove High Pressure Hose & Replace. Replace dryer add (6.0) Oz Oil & Charge (.6.5) Lbs Freon.
Parts #14-00288-00 Qty (1) Line 30 Remove & Replace over Flow By pass tube.& Top Off coolant.
Parts #LK4Z-8075-D Qty (1) Line 40 One Radiator Fan inop. /Radiator. Fan Support bolt Broken. Drill broken bolts& Retap tread. to Replace bolt.Remove & Replace Radiator Fan.
Parts #LK4Z-8C607-E Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 01-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	May 1, 2023 12:55:31 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	May 1, 2023 12:55:31 PM	No	
4 - Are you wearing the appropriate PPE?	Done		DARTHURS	May 1, 2023 12:55:31 PM	No	
7 - Have you performed the proper LOTO?	Done		DARTHURS	May 1, 2023 12:55:31 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	May 1, 2023 12:55:31 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	May 1, 2023 12:55:31 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 56671158
Invoice No. 55345 - 56671158

Client Department:
Department: 55345M
Work Order Description
Check A/C
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 125,295 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Check A/C
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-May-23	14-00288-00	DRYER, FILTER, A/C, W/SIGHT GLASS	1	18.08	18.08

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-May-23	Arthurs,Durvin	1.58	65	102.7
02-May-23	Arthurs,Durvin	5.32	65	345.8

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	18.08
Labor:	448.50
Labor Hours:	6.90
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**466.58**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 56671158
Invoice No. 55345 - 56671158

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Check A/C		Ford Transit	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	125,295 - DH

Activity Header
Activity: 25 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Over Flow Tank Leaking
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-May-23	LK4Z-8075-D	HOSE, OVERFLOW, COOLANT	1	28.76	28.76
01-May-23	KK2Z-8A080-B	RESERVOIR, COOLANT	1	56.5	56.5

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-May-23	Arthurs,Durvin	0.93	65	60.45
01-May-23	Arthurs,Durvin	1.38	65	89.7

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	85.26
Labor:	150.15
Labor Hours:	2.31
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**235.41**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 56671158
Invoice No. 55345 - 56671158

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Check A/C		Ford Transit	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	125,295 - DH

Activity Header
Activity: 35 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Remove & Replace Condenser Fan
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-May-23	LK4Z-8C607-E	FAN, COOLING, ENGINE	1	274.09	274.09

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-May-23	Arthurs,Durvin	1.9	65	123.5
04-May-23	Arthurs,Durvin	4.32	65	280.8

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 35 Sub Total	
Parts:	274.09
Labor:	404.30
Labor Hours:	6.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**678.39**

Work Order Footer

Work Order 56671158 Total	
Parts:	377.43
Labor:	1,002.95
Labor Hours:	15.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1,380.38**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 56650343
Invoice No. 55345 - 56650343

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	124,221 - DH

Chronology

Reported	Apr 24, 2023 4:01:17 PM	Apr 24, 2023 4:01:17 PM
Started	Apr 24, 2023 4:28:00 PM	
Completed	Apr 24, 2023 8:20:00 PM	Apr 24, 2023 8:20:00 PM
Down Time		

Work Order Notes

Line 10 Replace rear brakes is was below specification part # 1551-23-88 Line 20 Replace four new tires to rear of unit size 195/75R16C after return unit back to work

Activity Header

Activity: 10 013 BRAKES
Activity Note: Rear tires need replace
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Apr-23	131196995	TIRE, 195/75R16, WORKHORSE, HTL, WRANGLER, GOODYEAR	4	121.01	484.04
24-Apr-23	1551-2388-00	PADS, BRAKE, REAR	1	44.2	44.2

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Apr-23	Junior Hurst	3.08	65	200.2

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	528.24
Labor:	200.20
Labor Hours:	3.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**728.44**

Work Order Footer

Work Order 56650343 Total	
Parts:	528.24
Labor:	200.20
Labor Hours:	3.08
Sublet Parts:	0.00

	Sublet Labor:	0.00
	Activity Sub Total	**728.44**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56538708
Invoice No. 55345 - 56538708

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	124,221 - DH

Chronology		
Reported	Apr 24, 2023 12:00:00 AM	Apr 24, 2023 12:00:00 AM
Started	Apr 24, 2023 1:32:00 PM	
Completed	Apr 24, 2023 4:24:00 PM	Apr 24, 2023 4:24:00 PM
Down Time		

Work Order Notes

Line 10 Vehicle came in for service due by mileage change oil filter part # LF17531 also wash rear ac filter

Activity Header

Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 24-APR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Apr 24, 2023 4:19:45 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Apr 24, 2023 4:19:45 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Apr 24, 2023 4:19:45 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Apr 24, 2023 4:19:45 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Apr 24, 2023 4:19:45 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Apr 24, 2023 4:19:45 PM	No	

Activity Sub Total

Activity 5 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56538708
Invoice No. 55345 - 56538708

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	124,221 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Apr-23	LF17531	FILTER, OIL, SPIN-ON SEE P577066	1	4.21	4.21

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Apr-23	Junior Hurst	0.5	65	32.5
24-Apr-23	Junior Hurst	1.73	65	112.45

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: JUHURST Performed on: 24-APR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,800 - CHECK_All Destination Signage	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
20,200 - CHECK_Public Address System	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	80 Second*		JUHURST	Apr 24, 2023 4:17:56 PM	No	
20,700 - RECORD_Brake Performance Test Speed	30 Miles per Hour		JUHURST	Apr 24, 2023 4:17:56 PM	No	
20,800 - RECORD_Brake Performance Test Distance	50 FEET		JUHURST	Apr 24, 2023 4:17:56 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	50 FEET		JUHURST	Apr 24, 2023 4:17:56 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	80 Gravitational Force		JUHURST	Apr 24, 2023 4:17:56 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
21,500 - INSPECT_High Idle Control	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges,	Done		JUHURST	Apr 24, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Handles, Controls and Panels				4:17:56 PM		
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
32,000 - Engine Inspection	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Apr 24, 2023 4:17:56 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Apr 24, 2023 4:17:56 PM	No	
33,000 - CSF (Curb Side Front)	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
40,700 - CHECK_Passenger Stop Request System	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
50,100 - *RPT*INSPECT_Steering components- Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
50,400 - LUBE_All Chassis Components	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,700 - INSPECT_Tire Condition	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	9 32nds of an inch		JUHURST	Apr 24, 2023 4:17:56 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Apr 24, 2023 4:17:56 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	9 32nds of an inch		JUHURST	Apr 24, 2023 4:17:56 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Apr 24, 2023 4:17:56 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Apr 24, 2023 4:17:56 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Apr 24, 2023 4:17:56 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.2299 Inch		JUHURST	Apr 24, 2023 4:17:56 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.2299 Inch		JUHURST	Apr 24, 2023 4:17:56 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	2 32nds of an inch	rear tires need to be replaced	JUHURST	Apr 24, 2023 4:17:56 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	0 32nds of an inch		JUHURST	Apr 24, 2023 4:17:56 PM	Yes	56650343
54,400 - RECORD_RRO-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Apr 24, 2023 4:17:56 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Apr 24, 2023 4:17:56 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	3 32nds of an inch		JUHURST	Apr 24, 2023 4:17:56 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	1 32nds of an inch		JUHURST	Apr 24, 2023 4:17:56 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Apr 24, 2023 4:17:56 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Apr 24, 2023 4:17:56 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch		JUHURST	Apr 24, 2023 4:17:56 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch	rear brakes need change	JUHURST	Apr 24, 2023 4:17:56 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	1.2699 Inch		JUHURST	Apr 24, 2023 4:17:56 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	1.2699 Inch		JUHURST	Apr 24, 2023 4:17:56 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		JUHURST	Apr 24, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				4:17:56 PM		
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	Apr 24, 2023 4:17:56 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	4.21
Labor:	144.95
Labor Hours:	2.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**149.16**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56538708
Invoice No. 55345 - 56538708

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	124,221 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Apr-23	Junior Hurst	1.13	65	73.45

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: JUHURST Performed on: 24-APR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		JUHURST	Apr 24, 2023 2:39:31 PM	No	
101,000 - FRA Change Oil Filters	Yes		JUHURST	Apr 24, 2023 2:39:31 PM	No	
102,000 - FRA Drain Engine Oil	Yes		JUHURST	Apr 24, 2023 2:39:31 PM	No	
103,000 - FRA Check Transmission Fluid	Done		JUHURST	Apr 24, 2023 2:39:31 PM	No	
104,000 - Lubricate Chassis	Done		JUHURST	Apr 24, 2023 2:39:31 PM	No	
105,000 - Replace or Clean A/C Filters	Done		JUHURST	Apr 24, 2023 2:39:31 PM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	Done		JUHURST	Apr 24, 2023 2:39:31 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		JUHURST	Apr 24, 2023 2:39:31 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		JUHURST	Apr 24, 2023 2:39:31 PM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	0.00
	Labor:	73.45
	Labor Hours:	1.13
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**73.45**

Work Order Footer

Work Order 56538708 Total	
Parts:	4.21
Labor:	218.40
Labor Hours:	3.36
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**222.61**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56627773
Invoice No. 55345 - 56627773

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
check engine light on -		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	123,082 - DH

Chronology		
Reported	Apr 17, 2023 11:06:24 AM	Apr 17, 2023 11:06:24 AM
Started	Apr 17, 2023 11:32:00 AM	
Completed	Apr 21, 2023 2:20:00 PM	Apr 21, 2023 2:20:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: check engine light on

Cause: tech found multiple cylinder misfire : p0301 ,cylider 1 ,p0303 cylinder 3 ,p0302 cylinder 2, p0455 Evap system large leak

Correction: Line 20 Complaint: Check Engine Light on

Cause: Code PO301/PO302/PO303 /PO455/PO4F0 Misfire / Evap code Interface module Loose.

Correction: Secure inter face module Clear Code. Road test To Verify Repair.all is good at this time.

Please see work order # 56630429

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List						
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 21-APR-23						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Apr 21, 2023 2:19:09 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Apr 21, 2023 2:19:09 PM	No	
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Apr 21, 2023 2:19:09 PM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Apr 21, 2023 2:19:09 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Apr 21, 2023 2:19:09 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Apr 21, 2023 2:19:09 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56627773
Invoice No. 55345 - 56627773

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
check engine light on -		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	123,082 - DH

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: CHECK ENGINE LIGTH
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Apr-23	NELSON PIERRE-LOUIS	2.65	65	172.25

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	172.25
Labor Hours:	2.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**172.25**

Work Order Footer

Work Order 56627773 Total	
Parts:	0.00
Labor:	172.25
Labor Hours:	2.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**172.25**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56630429
Invoice No. 55345 - 56630429

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Check Engine Light on		Ford Transit	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	123,082 - DH

Chronology		
Reported	Apr 18, 2023 7:31:29 AM	Apr 18, 2023 7:31:29 AM
Started	Apr 18, 2023 7:34:00 AM	
Completed	Apr 18, 2023 9:17:00 AM	Apr 18, 2023 9:17:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Check Engine Light on

Cause: Code PO301/PO302/PO303 /PO455/PO4F0 Misfire / Evap code Interface module Loose.

Correction: Secure inter face module Clear Code. Road test To Verify Repair.all is good at this time.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 18-APR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Apr 18, 2023 7:34:59 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Apr 18, 2023 7:34:59 AM	No	
4 - Are you wearing the appropriate PPE?	Done		DARTHURS	Apr 18, 2023 7:34:59 AM	No	
7 - Have you performed the proper LOTO?	Done		DARTHURS	Apr 18, 2023 7:34:59 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Apr 18, 2023 7:34:59 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 18, 2023 7:34:59 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56630429
Invoice No. 55345 - 56630429

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Check Engine Light on		Ford Transit	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	123,082 - DH

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Apr-23	Arthurs,Durvin	1.72	65	111.8

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	111.80
Labor Hours:	1.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**111.80**

Work Order Footer

Work Order 56630429 Total	
Parts:	0.00
Labor:	111.80
Labor Hours:	1.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**111.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 56550611
Invoice No. 55345 - 56550611

Client Department:
Department: 55345M
Work Order Description
Driver said bus leaking coolant
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 120,725 - DH

Chronology		
Reported	Mar 29, 2023 5:35:02 AM	Mar 29, 2023 5:35:02 AM
Started	Mar 29, 2023 8:55:00 AM	
Completed	Mar 29, 2023 5:06:00 PM	Mar 29, 2023 5:06:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Coolant leaks under the hood of vehicle

Cause: heater hose 4way connector leaks

Correction: Replaced 4way connector

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 29-MAR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Mar 29, 2023 5:05:28 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Mar 29, 2023 5:05:28 PM	No	
4 - Are you wearing the appropriate PPE?	Done		TDELVA	Mar 29, 2023 5:05:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
7 - Have you performed the proper LOTO?	Done		TDELVA	Mar 29, 2023 5:05:28 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Mar 29, 2023 5:05:28 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Mar 29, 2023 5:05:28 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 56550611
Invoice No. 55345 - 56550611

Client Department:
Department: 55345M
Work Order Description
Driver said bus leaking coolant
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 120,725 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 56550611
Invoice No. 55345 - 56550611

Client Department:
Department: 55345M
Work Order Description
Driver said bus leaking coolant
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 120,725 - DH

Activity Header
Activity: 20 042 COOLING SYSTEM
Activity Note: CHECK COOLING SYSTEM FOR LEAKS
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Mar-23	CK4Z-18472-KG	HOSE, HEATER, REAR, HD, F350	1	69.49	69.49

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Mar-23	Delva,Terry	2.87	65	186.55
29-Mar-23	Delva,Terry	0.08	65	5.2

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	69.49
Labor:	191.75
Labor Hours:	2.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**261.24**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 56550611
Invoice No. 55345 - 56550611

Client Department:
Department: 55345M
Work Order Description
Driver said bus leaking coolant
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 120,725 - DH

Activity Header
Activity: 30 044/001/011 LINE, FUEL
Activity Note: INSPECT FOR FUEL SMELL
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 56550611 Total	
Parts:	69.49
Labor:	191.75
Labor Hours:	2.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**261.24**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 56537766
Invoice No. 55345 - 56537766

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	120,265 - DH

Chronology

Reported	Mar 24, 2023 10:53:29 AM	Mar 24, 2023 10:53:29 AM
Started		
Completed	Mar 24, 2023 3:15:00 PM	Mar 24, 2023 3:15:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: front lift shock gas was bad
Correction: replaced spring gas shock ,wc

Activity Header
Activity: 10 055/023/000 LIFT, WHEELCHAIR, PASSENGER
Activity Note:
Reason for Repair: 01 Breakdown
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Mar-23	32831	SPRING, SHOCK, GAS, W/C	1	26.3	26.3

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	26.30
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**26.30**

Work Order Footer

Work Order 56537766 Total	
Parts:	26.30
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**26.30**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56457816
Invoice No. 55345 - 56457816

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	120,265 - DH

Chronology		
Reported	Mar 23, 2023 12:00:00 AM	Mar 23, 2023 12:00:00 AM
Started	Mar 24, 2023 10:11:00 AM	
Completed	Mar 24, 2023 2:38:00 PM	Mar 24, 2023 2:38:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: pmb service

Cause: perform pmb service and lube

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 24-MAR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Mar 24, 2023 10:31:40 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Mar 24, 2023 10:31:40 AM	No	
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Mar 24, 2023 10:31:40 AM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Mar 24, 2023 10:31:40 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Mar 24, 2023 10:31:40 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Mar 24, 2023 10:31:40 AM	No	

Activity Sub Total

	Activity 5 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56457816
Invoice No. 55345 - 56457816

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	120,265 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Mar-23	B7449	FILTER, OIL, SPIN-ON SEE P577066	1	4.59	4.59

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Mar-23	NELSON PIERRE-LOUIS	2.07	65	134.55

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS Performed on: 24-MAR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	Yes	56537766
10,200 - !FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
10,800 - CHECK_All Destination Signage	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
20,200 - CHECK_Public Address System	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	0 Second*		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
20,700 - RECORD_Brake Performance Test Speed	0 Miles per Hour		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
20,800 - RECORD_Brake Performance Test Distance	0 FEET		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	0 FEET		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	0 Gravitational Force		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
21,500 - INSPECT_High Idle Control	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
21,800 - INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
31,000 - SSF (Street Side Front)	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
32,000 - Engine Inspection	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	280 Degree Fahrenheit		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
32,100 - INSPECT_Intake System	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.2 Volt*		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
33,000 - CSF (Curb Side Front)	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-	Mar 24, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	10:53:50 AM		
33,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
40,700 - CHECK_Passenger Stop Request System	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
50,400 - LUBE_All Chassis Components	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
50,700 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	12 32nds of an inch		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	12 32nds of an inch		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	64 Pounds per Square Inch		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	23.5 Inch		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	25.5 Inch		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
52,100 - INSPECT_Vibration Damper	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,600 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	64 Pounds per Square Inch		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	5 32nds of an inch		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	64 Pounds per Square Inch		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	17.5 Inch		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	17.5 Inch		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	Mar 24, 2023 10:53:50 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	4.59
Labor:	134.55
Labor Hours:	2.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**139.14**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56457816
Invoice No. 55345 - 56457816

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	120,265 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMB Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Mar-23	NELSON PIERRE-LOUIS	0.97	65	63.05

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	63.05
Labor Hours:	0.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**63.05**

Work Order Footer

Work Order 56457816 Total	
Parts:	4.59
Labor:	197.60
Labor Hours:	3.04
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**202.19**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 6

Work Order No. 56526029
Invoice No. 55345 - 56526029

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOW UP TO QCC INSP		Ford Transit	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	119,629 - DH

Chronology		
Reported	Mar 21, 2023 8:29:03 AM	Mar 21, 2023 8:29:03 AM
Started	Mar 21, 2023 1:36:00 PM	
Completed	Mar 21, 2023 9:24:00 PM	Mar 21, 2023 9:24:00 PM
Down Time		

Work Order Notes

Line 10 See bottom Line 20 Vehicle came in for follow up inspection check Air condition and also. Brakes front and rear all working perfect Line 30 Wash rear AC filter also check cabin filter Line 40 Repair right rear outer tire Line 50 Replace two new tires to front of vehicle size 195/ 75R16C. Also removed HUB CAPS Line 60 Check shocks on lift working perfect Line 70 Check heater hose no leak

Activity Header
Activity: 10
Activity Note: RRO OUTER TIRE HAS NAIL
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 6

Work Order No. 56526029
Invoice No. 55345 - 56526029

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOW UP TO QCC INSP		Ford Transit	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	119,629 - DH

Activity Header
Activity: 20
Activity Note: REMOVE HUB CAP AND CLEAN RIMS
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 6

Work Order No. 56526029
Invoice No. 55345 - 56526029

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOW UP TO QCC INSP		Ford Transit	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	119,629 - DH

Activity Header
Activity: 30
Activity Note: SECURE HEATER HOSE CLAMPS BY FUEL TANK
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Mar-23	Junior Hurst	0.15	65	9.75
21-Mar-23	Junior Hurst	0.1	65	6.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	16.25
Labor Hours:	0.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**16.25**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 6

Work Order No. 56526029
Invoice No. 55345 - 56526029

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOW UP TO QCC INSP		Ford Transit	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	119,629 - DH

Activity Header
Activity:40
Activity Note: REPLACE FRONT TIRES, SWAP FRONT TO REAR
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Mar-23	131196995	TIRE, 195/75R16, WORKHORSE, HTL, WRANGLER, GOODYEAR	2	127.98	255.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Mar-23	Junior Hurst	1.22	65	79.3

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	255.96
Labor:	79.30
Labor Hours:	1.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**335.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 6

Work Order No. 56526029
Invoice No. 55345 - 56526029

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOW UP TO QCC INSP		Ford Transit	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	119,629 - DH

Activity Header
Activity: 50
Activity Note: REPLACE OUTER SHOCKS ON LIFT
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Mar-23	Junior Hurst	0.37	65	24.05

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 50 Sub Total	
Parts:	0.00
Labor:	24.05
Labor Hours:	0.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**24.05**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 6 of 6

Work Order No. 56526029
Invoice No. 55345 - 56526029

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOW UP TO QCC INSP		Ford Transit	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	119,629 - DH

Activity Header
Activity: 60 999 TOTAL VEHICLE
Activity Note: INSPECT REAR BRAKE PADS.REPLACE IF NEEDED.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Mar-23	Junior Hurst	4.13	65	268.45

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 60 Sub Total	
Parts:	0.00
Labor:	268.45
Labor Hours:	4.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**268.45**

Work Order Footer

Work Order 56526029 Total	
Parts:	255.96
Labor:	388.05
Labor Hours:	5.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**644.01**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55455658
Invoice No. 55345 - 55455658

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
QCC FLEET INSPECTION		Ford Transit	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	119,629 -

Chronology		
Reported	Mar 21, 2023 7:52:39 AM	Mar 21, 2023 7:52:39 AM
Started		
Completed	Mar 21, 2023 8:31:27 AM	Mar 21, 2023 8:31:27 AM
Down Time		

Work Order Notes

Line 10 COMPLTED.
REAR BRAKE PAD HAS TO BE INSPECTED.
REAR INNER TIRES ARE LOW. ROTATE FRONT TO REAR. INSTALL TWO NEW TIRE IN THE FRONT.
RRO HAS NAIL.
SECURE HEATER HOSE BY FUEL TANK.
RIMS CAP HAS TO BE REMOVE AND CLEAN.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 21-MAR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		CKARLENS	Mar 21, 2023 8:20:35 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		CKARLENS	Mar 21, 2023 8:20:35 AM	No	
4 - Are you wearing the appropriate PPE?	Done		CKARLENS	Mar 21, 2023 8:20:35 AM	No	
7 - Have you performed the proper LOTO?	Done		CKARLENS	Mar 21, 2023 8:20:35 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		CKARLENS	Mar 21, 2023 8:20:35 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Mar 21, 2023 8:20:35 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55455658
Invoice No. 55345 - 55455658

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
QCC FLEET INSPECTION		Ford Transit	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	119,629 -

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: QCC FLEET INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: QCC FLEET INSPECTION
Task: 55345 QCC FLEET INSPECTION Performed by: CKARLENS Performed on: 21-MAR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - EXTERIOR CIRCLE INSPECTION	Done	RRO OUTER TIRE HAS NAIL	CKARLENS	Mar 21, 2023 8:28:59 AM	Yes	56526029
20 - Cleanliness	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
30 - Entrance Door Operation/Seals/Glass	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
40 - Body/Fenders/ Bumpers	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
50 - Tires/Wheels/Lugs	D	REMOVE HUB CAP AND CLEAN RIMS	CKARLENS	Mar 21, 2023 8:28:59 AM	Yes	56526029
60 - Mirrors and Attachments	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
70 - Lights and Accessories	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
80 - Compartment Doors	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
90 - Battery Compartment	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
100 - Check All Fluids	B	SECURE HEATER HOSE CLAMPS BY FUEL TANK	CKARLENS	Mar 21, 2023 8:28:59 AM	Yes	56526029
110 - Belt Drives	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
120 - Air Induction	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
130 - Exhaust System	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
140 - Engine Compartmetn Wiring	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
150 - DRIVERS AREA INSPECTION	Done		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
160 - Air System	E		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
170 - Audible Warnings	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
180 - Dash and Gauges	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
190 - Accessory components	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
200 - Exit Door Operation	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
210 - Exit Door Interlock	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
220 - Fare box and ticket cutter.	E		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
230 - Fast Idle	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
240 - Glass & Mirrors	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
250 - Floor Covering	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
260 - Horn and Lamps	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
270 - Start Function	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
280 - PA System	E		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
290 - Pedal Condition and Adjustment	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
300 - Reverse System	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
310 - Seat	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
320 - Steering Wheel & Column	D	REPLACE FRONT TIRES, SWAP FRONT TO REAR	CKARLENS	Mar 21, 2023 8:28:59 AM	Yes	56526029
330 - Sun Visor	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
340 - Turn Signals Switch	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
350 - Electrical Compartment	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
360 - Wheel Chair Operation	D	REPLACE OUTER SHOCKS ON LIFT	CKARLENS	Mar 21, 2023 8:28:59 AM	Yes	56526029
370 - INTERIOR CIRCLE	Done		CKARLENS	Mar 21, 2023 8:28:59 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
380 - Cleanliness	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
390 - HVAC	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
400 - Interior Passenger Area	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
410 - Stop Request	E		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
420 - Safety Equipment	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
430 - UNDERCARRIAGE	Done		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
440 - Air System	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
450 - Steering components	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
460 - Brake Inspection	B	INSPECT REAR BRAKE PADS.	CKARLENS	Mar 21, 2023 8:28:59 AM	Yes	56526029
470 - Suspension Components	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
480 - Frame	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
490 - Fluid Leakage	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	
500 - Fuel System	A		CKARLENS	Mar 21, 2023 8:28:59 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55455658 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 56457815
Invoice No. 55345 - 56457815

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	116,382 - DH

Chronology		
Reported	Feb 28, 2023 6:37:15 PM	Feb 28, 2023 6:37:15 PM
Started		
Completed	Feb 28, 2023 7:26:00 PM	Feb 28, 2023 7:26:00 PM
Down Time		

Work Order Notes

Line 10 Replace one good used tire to rtght rear of unit after return unit back to work

Activity Header
Activity: 10 017/009/016 VALVE, PROTECTION, PRESSURE, TIRE
Activity Note:
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 56457815 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56389887
Invoice No. 55345 - 56389887

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	116,382 - DH

Chronology		
Reported	Feb 28, 2023 12:00:00 AM	Feb 28, 2023 12:00:00 AM
Started	Feb 28, 2023 3:54:00 PM	
Completed	Feb 28, 2023 6:37:00 PM	Feb 28, 2023 6:37:00 PM
Down Time		

Work Order Notes

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 28-FEB-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Feb 28, 2023 6:31:11 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Feb 28, 2023 6:31:11 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Feb 28, 2023 6:31:11 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Feb 28, 2023 6:31:11 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Feb 28, 2023 6:31:11 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Feb 28, 2023 6:31:11 PM	No	

Activity Sub Total

Activity 5 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56389887
Invoice No. 55345 - 56389887

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	116,382 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Feb-23	B7449	FILTER, OIL, SPIN-ON SEE P577066	1	7.86	7.86

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Feb-23	Junior Hurst	1.2	65	78

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: JUHURST Performed on: 28-FEB-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR &	Done		JUHURST	Feb 28,	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Authorization Forms				2023 6:22:06 PM		
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
10,800 - CHECK_All Destination Signage	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
20,200 - CHECK_Public Address System	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	80 Second*		JUHURST	Feb 28, 2023 6:22:06 PM	No	
20,700 - RECORD_Brake Performance Test Speed	30 Miles per Hour		JUHURST	Feb 28, 2023 6:22:06 PM	No	
20,800 - RECORD_Brake Performance Test Distance	50 FEET		JUHURST	Feb 28, 2023 6:22:06 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	50 FEET		JUHURST	Feb 28, 2023 6:22:06 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	80 Gravitational Force		JUHURST	Feb 28, 2023 6:22:06 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
21,500 - INSPECT_High Idle Control	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,000 - Engine Inspection	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Feb 28, 2023 6:22:06 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Feb 28, 2023 6:22:06 PM	No	
33,000 - CSF (Curb Side Front)	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
40,700 - CHECK_Passenger Stop Request System	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
50,100 - *RPT*INSPECT_Steering components- Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
50,400 - LUBE_All Chassis Components	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
50,700 - INSPECT_Tire Condition	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Feb 28, 2023 6:22:06 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Feb 28, 2023 6:22:06 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	9 32nds of an inch		JUHURST	Feb 28, 2023 6:22:06 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Feb 28, 2023 6:22:06 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Feb 28, 2023 6:22:06 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Feb 28, 2023 6:22:06 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	.5 Inch		JUHURST	Feb 28, 2023 6:22:06 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	.5 Inch		JUHURST	Feb 28, 2023 6:22:06 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
52,400 - !FRA!INSPECT_ Starter Mounting	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	5 32nds of an inch		JUHURST	Feb 28, 2023 6:22:06 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	5 32nds of an inch		JUHURST	Feb 28, 2023 6:22:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Feb 28, 2023 6:22:06 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Feb 28, 2023 6:22:06 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	3 32nds of an inch		JUHURST	Feb 28, 2023 6:22:06 PM	Yes	56457815
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	3 32nds of an inch	one left rear tire need replace	JUHURST	Feb 28, 2023 6:22:06 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Feb 28, 2023 6:22:06 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Feb 28, 2023 6:22:06 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Feb 28, 2023 6:22:06 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Feb 28, 2023 6:22:06 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.5 Inch		JUHURST	Feb 28, 2023 6:22:06 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.5 Inch		JUHURST	Feb 28, 2023 6:22:06 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	Feb 28, 2023 6:22:06 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	7.86
Labor:	78.00
Labor Hours:	1.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**85.86**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56389887
Invoice No. 55345 - 56389887

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	116,382 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Feb-23	Junior Hurst	1.38	65	89.7

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: JUHURST Performed on: 28-FEB-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		JUHURST	Feb 28, 2023 5:16:46 PM	No	
101,000 - FRA Change Oil Filters	Yes		JUHURST	Feb 28, 2023 5:16:46 PM	No	
102,000 - FRA Drain Engine Oil	Yes		JUHURST	Feb 28, 2023 5:16:46 PM	No	
103,000 - FRA Check Transmission Fluid	Done		JUHURST	Feb 28, 2023 5:16:46 PM	No	
104,000 - Lubricate Chassis	Done		JUHURST	Feb 28, 2023 5:16:46 PM	No	
105,000 - Replace or Clean A/C Filters	Done		JUHURST	Feb 28, 2023 5:16:46 PM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	Done		JUHURST	Feb 28, 2023 5:16:46 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		JUHURST	Feb 28, 2023 5:16:46 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		JUHURST	Feb 28, 2023 5:16:46 PM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	0.00
	Labor:	89.70
	Labor Hours:	1.38
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**89.70**

Work Order Footer

Work Order 56389887 Total	
Parts:	7.86
Labor:	167.70
Labor Hours:	2.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**175.56**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56415005
Invoice No. 55345 - 56415005

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Nail on the passenger rear tire		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	113,979 - DH

Chronology		
Reported	Feb 15, 2023 12:32:21 PM	Feb 15, 2023 12:32:21 PM
Started		
Completed	Feb 16, 2023 5:36:00 AM	Feb 16, 2023 5:36:00 AM
Down Time		

Work Order Notes

Line 10 Nail on the rear passenger side tire

Nail

Mount and balance one use tire completed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 16-FEB-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Feb 16, 2023 5:36:33 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Feb 16, 2023 5:36:33 AM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Feb 16, 2023 5:36:33 AM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Feb 16, 2023 5:36:33 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Feb 16, 2023 5:36:33 AM	No	
11 - Have you successfully completed the Personal	Done		HPIERRE	Feb 16, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				5:36:33 AM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56415005
Invoice No. 55345 - 56415005

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Nail on the passenger rear tire		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	113,979 - DH

Activity Header
Activity: 20 017/001/000 TIRE, PNEUMATIC
Activity Note: FRONT TIRES
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56415005
Invoice No. 55345 - 56415005

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Nail on the passenger rear tire		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	113,979 - DH

Activity Header
Activity: 30 017/001/000 TIRE, PNEUMATIC
Activity Note: REAR TIRES
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 56415005 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56414142
Invoice No. 55345 - 56414142

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Wiper and Wiper Motor Clip		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	113,979 - DH

Chronology		
Reported	Feb 15, 2023 9:31:28 AM	Feb 15, 2023 9:31:28 AM
Started	Feb 15, 2023 9:44:00 AM	
Completed	Feb 15, 2023 10:00:00 AM	Feb 15, 2023 10:00:00 AM
Down Time		

Work Order Notes

Line 10 Compliant : brake light was missing screws and driver side wiper blade

Cause : preventive maintenance

Corretion: change driver side wiper blade and abb 4 screws to the top brake light

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 15-FEB-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Feb 15, 2023 9:56:21 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Feb 15, 2023 9:56:21 AM	No	
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Feb 15, 2023 9:56:21 AM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Feb 15, 2023 9:56:21 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Feb 15, 2023 9:56:21 AM	No	
11 - Have you successfully completed the Personal	Done		NPIERRE-	Feb 15, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	9:56:21 AM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56414142
Invoice No. 55345 - 56414142

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Wiper and Wiper Motor Clip		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	113,979 - DH

Activity Header
Activity: 20 002/035/015 BLADE, WIPER
Activity Note: WIPER BLADES
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Feb-23	28CA	BLADE, WIPER, WINDSHEILD	1	6.67	6.67

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Feb-23	NELSON PIERRE-LOUIS	0.27	65	17.55

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	6.67
Labor:	17.55
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**24.22**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56414142
Invoice No. 55345 - 56414142

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Wiper and Wiper Motor Clip		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	113,979 - DH

Activity Header
Activity: 30 002/035/001 MOTOR, WIPER, WINDSHIELD
Activity Note: WIPER MOTOR
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 56414142 Total	
Parts:	6.67
Labor:	17.55
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**24.22**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56389799
Invoice No. 55345 - 56389799

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	112,588 - DH

Chronology		
Reported	Feb 8, 2023 11:50:13 PM	Feb 8, 2023 11:50:13 PM
Started	Feb 9, 2023 5:26:00 PM	
Completed	Feb 9, 2023 7:27:00 PM	Feb 9, 2023 7:27:00 PM
Down Time		

Work Order Notes

Line 10 Needs front brakes job and 2 marker lights
Brake low spec and marker light bulbs blew
Replace front brake pads and lube guide pins
Replace marker light bulbs
Torque wheels 140 lbs second torque 140 lbs
Part number BRF-1896 qty1

Activity Header
Activity: 10 034/003/000 LAMPS, SIGNAL, PARKING & BACKUP
Activity Note: needs left and right side marker lights
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Feb-23	Gaspard,Ronald	0.83	65	53.95

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	53.95
Labor Hours:	0.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**53.95**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56389799
Invoice No. 55345 - 56389799

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	112,588 - DH

Activity Header
Activity:20 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: needs front brakes job
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Feb-23	BRF-1896	PADS, BRAKE, DISC, FRONT, TRANSIT	1	57.74	57.74

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Feb-23	Gaspard,Ronald	1.15	65	74.75

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	57.74
Labor:	74.75
Labor Hours:	1.15
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**132.49**

Work Order Footer

Work Order 56389799 Total	
Parts:	57.74
Labor:	128.70
Labor Hours:	1.98
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**186.44**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56324851
Invoice No. 55345 - 56324851

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	112,588 - DH

Chronology		
Reported	Feb 8, 2023 12:00:00 AM	Feb 8, 2023 12:00:00 AM
Started	Feb 8, 2023 3:44:00 PM	
Completed	Feb 9, 2023 2:03:00 AM	Feb 9, 2023 2:03:00 AM
Down Time		

Work Order Notes

Line 10 PMA
Service
perform PMA Service
oil filter B7449 qty1
engine oil 10w30 qty 6qts
add washer fluid

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 08-FEB-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Feb 8, 2023 11:13:18 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Feb 8, 2023 11:13:18 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RGASPARD	Feb 8, 2023 11:13:18 PM	No	
7 - Have you performed the proper LOTO?	Done		RGASPARD	Feb 8, 2023 11:13:18 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Feb 8, 2023 11:13:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Feb 8, 2023 11:13:18 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56324851
Invoice No. 55345 - 56324851

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	112,588 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Feb-23	B7449	FILTER, OIL, SPIN-ON SEE P577066	1	7.86	7.86

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Feb-23	Gaspard,Ronald	0.78	65	50.7
09-Feb-23	Gaspard,Ronald	1.47	65	95.55

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 08-FEB-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done	needs left and right side marker lights	RGASPARD	Feb 8, 2023 11:50:06 PM	Yes	56389799
10,800 - CHECK_All Destination Signage	Done	na	RGASPARD	Feb 8, 2023 11:50:06 PM	No	
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
20,200 - CHECK_Public Address System	Done	na	RGASPARD	Feb 8, 2023 11:50:06 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	na	RGASPARD	Feb 8, 2023 11:50:06 PM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	na	RGASPARD	Feb 8, 2023 11:50:06 PM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	na	RGASPARD	Feb 8, 2023 11:50:06 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	na	RGASPARD	Feb 8, 2023 11:50:06 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	na	RGASPARD	Feb 8, 2023 11:50:06 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done	na	RGASPARD	Feb 8, 2023 11:50:06 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
21,500 - INSPECT_High Idle Control	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,000 - Engine Inspection	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	Feb 8, 2023 11:50:06 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Feb 8, 2023 11:50:06 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
33,000 - CSF (Curb Side Front)	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
40,700 - CHECK_Passenger Stop Request System	Done	na	RGASPARD	Feb 8, 2023 11:50:06 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
50,400 - LUBE_All Chassis Components	Done	na	RGASPARD	Feb 8, 2023 11:50:06 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	3 32nds of an inch	needs front brakes job	RGASPARD	Feb 8, 2023 11:50:06 PM	Yes	56389799
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	3 32nds of an inch		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.229 Inch		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.229 Inch		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done	na	RGASPARD	Feb 8, 2023 11:50:06 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Feb 8, 2023 11:50:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.799 Inch		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.799 Inch		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done	na	RGASPARD	Feb 8, 2023 11:50:06 PM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done	na	RGASPARD	Feb 8, 2023 11:50:06 PM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Feb 8, 2023 11:50:06 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	7.86
Labor:	146.25
Labor Hours:	2.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**154.11**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56324851
Invoice No. 55345 - 56324851

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	112,588 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Feb-23	Gaspard,Ronald	0.53	65	34.45

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: RGASPARD Performed on: 09-FEB-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Feb 9, 2023 2:03:15 AM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Feb 9, 2023 2:03:15 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Feb 9, 2023 2:03:15 AM	No	
103,000 - FRA Check Transmission Fluid	-	na	RGASPARD	Feb 9, 2023 2:03:15 AM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Feb 9, 2023 2:03:15 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Feb 9, 2023 2:03:15 AM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	-	na	RGASPARD	Feb 9, 2023 2:03:15 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Feb 9, 2023 2:03:15 AM	No	
108,000 - Lube all pivoting Mechanisms	-	na	RGASPARD	Feb 9, 2023 2:03:15 AM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	0.00
	Labor:	34.45
	Labor Hours:	0.53
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**34.45**

Work Order Footer

Work Order 56324851 Total	
Parts:	7.86
Labor:	180.70
Labor Hours:	2.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**188.56**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56378849
Invoice No. 55345 - 56378849

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Rear A/C Flashing HA		Ford Transit	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	111,710 - DH

Chronology		
Reported	Feb 6, 2023 8:02:21 AM	Feb 6, 2023 8:02:21 AM
Started	Feb 6, 2023 8:04:00 AM	
Completed	Feb 6, 2023 12:49:00 PM	Feb 6, 2023 12:49:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear A/C Flashing H/ A & BL Battery Low Voltage

Cause: Check Pressure Found Suction Goesbelow 10 psi BlockageonLow Side

Correction: Evacuate Rear A/C Replace Dryer / Flush Condenser Recharge A/C. Remove Driver Seat T0 Check. Battery Battery Test Ok Chargeing Result Before (12.44) Ofter Test battery Retest now Chargeing at 13,45. Road test to Verify Repair.
parts #14-00288-00 Qty (1)
freon 6.14 lbs /Add (4.0) Oz Pag Oil

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 06-FEB-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Feb 6, 2023 8:05:38 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Feb 6, 2023 8:05:38 AM	No	
4 - Are you wearing the appropriate PPE?	Done		DARTHURS	Feb 6, 2023 8:05:38 AM	No	
7 - Have you performed the proper LOTO?	Done		DARTHURS	Feb 6, 2023 8:05:38 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Feb 6, 2023 8:05:38 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Feb 6, 2023 8:05:38 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56378849
Invoice No. 55345 - 56378849

Client Department:
Department: 55345M
Work Order Description
Rear A/C Flashing HA
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 111,710 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Check Rear A/C
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Feb-23	14-00288-00	DRYER, FILTER, A/C, W/SIGHT GLASS	1	41.9	41.9

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Feb-23	Arthurs,Durvin	3.12	65	202.8

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	41.90
Labor:	202.80
Labor Hours:	3.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**244.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56378849
Invoice No. 55345 - 56378849

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Rear A/C Flashing HA		Ford Transit	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	111,710 - DH

Activity Header
Activity: 25 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: A/C Control Flashing Low battery
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Feb-23	Arthurs,Durvin	1.6	65	104

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	0.00
Labor:	104.00
Labor Hours:	1.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**104.00**

Work Order Footer

Work Order 56378849 Total	
Parts:	41.90
Labor:	306.80
Labor Hours:	4.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**348.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56324833
Invoice No. 55345 - 56324833

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	108,792 - DH

Chronology		
Reported	Jan 20, 2023 12:20:42 AM	Jan 20, 2023 12:20:42 AM
Started	Jan 20, 2023 12:25:00 AM	
Completed	Jan 20, 2023 5:40:00 PM	Jan 20, 2023 5:40:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.

==========

To file warranty be sure to do the following:

1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs 2 front tires , and right rear outside tire

Cause: front tires low spec, rear outside low spec

Correction:2 new front tires mount and balance
swap rear tires mount and balance
part number 004708 qty2
torque wheels 140 lbs second torque 140 lbs

Activity Header
Activity: 10 017/003/001 TIRE, CUSHION W/TREAD
Activity Note: needs 2 front tires
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jan-23	Gaspard,Ronald	0.55	65	35.75

Activity Sublet
No Data Available

Activity Checklist
No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	35.75
Labor Hours:	0.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**35.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56324833
Invoice No. 55345 - 56324833

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	108,792 - DH

Activity Header
Activity:20 017/003/001 TIRE, CUSHION W/TREAD
Activity Note: needs right rear outside tire
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Jan-23	004708	TIRE, 195/75R16C, BSW, D/8-PLY, CV, TRANSFORCE, FIRESTONE	2	129.38	258.76

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jan-23	Gaspard,Ronald	0.93	65	60.45

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	258.76
Labor:	60.45
Labor Hours:	0.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**319.21**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56324833
Invoice No. 55345 - 56324833

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	108,792 - DH

Activity Header
Activity:30 017/009/016 VALVE, PROTECTION, PRESSURE, TIRE
Activity Note: needs left rear outside tire
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jan-23	Gaspard,Ronald	0.5	65	32.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	32.50
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**32.50**

Work Order Footer

Work Order 56324833 Total	
Parts:	258.76
Labor:	128.70
Labor Hours:	1.98
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**387.46**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56256490
Invoice No. 55345 - 56256490

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	108,792 - DH

Chronology		
Reported	Jan 18, 2023 12:00:00 AM	Jan 18, 2023 12:00:00 AM
Started	Jan 19, 2023 4:26:00 PM	
Completed	Jan 20, 2023 12:54:00 AM	Jan 20, 2023 12:54:00 AM
Down Time		

Work Order Notes

Line 10 PMB
Service
perform PMB Service
oil filter B7449 qty1
engine oil 10w30 qty 6qts
add washer fluid

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 19-JAN-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Jan 19, 2023 10:56:19 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Jan 19, 2023 10:56:19 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RGASPARD	Jan 19, 2023 10:56:19 PM	No	
7 - Have you performed the proper LOTO?	Done		RGASPARD	Jan 19, 2023 10:56:19 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Jan 19, 2023 10:56:19 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jan 19, 2023 10:56:19 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56256490
Invoice No. 55345 - 56256490

Client Department:
Department: 55345M
Work Order Description
55345-MEDIUM DUTY PMB
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 108,792 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Jan-23	B7449	FILTER, OIL, SPIN-ON SEE P577066	1	4.45	4.45

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Jan-23	Gaspard,Ronald	1.07	65	69.55
20-Jan-23	Gaspard,Ronald	0.4	65	26

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 20-JAN-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,800 - CHECK_All Destination Signage	Done	na	RGASPARD	Jan 20, 2023 12:20:35 AM	No	
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
20,200 - CHECK_Public Address System	Done	na	RGASPARD	Jan 20, 2023 12:20:35 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	na	RGASPARD	Jan 20, 2023 12:20:35 AM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	na	RGASPARD	Jan 20, 2023 12:20:35 AM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	na	RGASPARD	Jan 20, 2023 12:20:35 AM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	na	RGASPARD	Jan 20, 2023 12:20:35 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	na	RGASPARD	Jan 20, 2023 12:20:35 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done	na	RGASPARD	Jan 20, 2023 12:20:35 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
21,500 - INSPECT_High Idle Control	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
21,800 - INSPECT_Parking Brake Operation	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
32,000 - Engine Inspection	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	Jan 20, 2023 12:20:35 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Jan 20, 2023 12:20:35 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
33,000 - CSF (Curb Side Front)	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
33,020 - *RPT*INSPECT_ FRONT Springs,	Done		RGASPARD	Jan 20, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Shocks, Spring Shackles				12:20:35 AM		
33,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
40,700 - CHECK_Passenger Stop Request System	Done	na	RGASPARD	Jan 20, 2023 12:20:35 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
50,100 - *RPT*INSPECT_Steering components- Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
50,400 - LUBE_All Chassis Components	Done	na	RGASPARD	Jan 20, 2023 12:20:35 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	4 32nds of an inch	needs 2 front tires	RGASPARD	Jan 20, 2023 12:20:35 AM	Yes	56324833
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	3 32nds of an inch		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.229 Inch		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.229 Inch		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done	na	RGASPARD	Jan 20, 2023 12:20:35 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	3 32nds of an inch	needs right rear outside tire	RGASPARD	Jan 20, 2023 12:20:35 AM	Yes	56324833
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	3 32nds of an inch	needs left rear outside tire	RGASPARD	Jan 20, 2023 12:20:35 AM	Yes	56324833
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.799 Inch		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.799 Inch		RGASPARD	Jan 20, 2023 12:20:35 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
55,700 - CHECK_Spring Brake Inversion Valve	Done	na	RGASPARD	Jan 20, 2023 12:20:35 AM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done	na	RGASPARD	Jan 20, 2023 12:20:35 AM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Jan 20, 2023 12:20:35 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	4.45
Labor:	95.55
Labor Hours:	1.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**100.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56256490
Invoice No. 55345 - 56256490

Client Department:
Department: 55345M
Work Order Description
55345-MEDIUM DUTY PMB
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 108,792 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMB Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jan-23	Gaspard,Ronald	0.45	65	29.25

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	29.25
Labor Hours:	0.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**29.25**

Work Order Footer

Work Order 56256490 Total	
Parts:	4.45
Labor:	124.80
Labor Hours:	1.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**129.25**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56312172
Invoice No. 55345 - 56312172

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Deceleration light malfunction.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	108,304 - DH

Chronology		
Reported	Jan 16, 2023 4:04:28 PM	Jan 16, 2023 4:04:28 PM
Started	Jan 16, 2023 4:10:00 PM	
Completed	Jan 17, 2023 12:28:00 AM	Jan 17, 2023 12:28:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Deceleration light not working.

Cause: Mismounted and blown fuse.

Correction: Remove and replaced deceleration light right side up. Remove and replaced 5A fuse.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 16-JAN-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jan 16, 2023 10:10:41 PM	No	
2 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Jan 16, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				10:10:41 PM		
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jan 16, 2023 10:10:41 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jan 16, 2023 10:10:41 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jan 16, 2023 10:10:41 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jan 16, 2023 10:10:41 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56312172
Invoice No. 55345 - 56312172

Client Department:
Department: 55345M
Work Order Description
Deceleration light malfunction.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 108,304 - DH

Activity Header
Activity: 15 034/003/000 LAMPS, SIGNAL, PARKING & BACKUP
Activity Note: Deceleration light malfunction.
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jan-23	Earl Johnson	1.73	65	112.45

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	112.45
Labor Hours:	1.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**112.45**

Work Order Footer

Work Order 56312172 Total	
Parts:	0.00
Labor:	112.45
Labor Hours:	1.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**112.45**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56284479
Invoice No. 55345 - 56284479

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Buzzer Beeping		Ford Transit	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	106,779 - DH

Chronology		
Reported	Jan 6, 2023 11:51:01 PM	Jan 6, 2023 11:51:01 PM
Started	Jan 6, 2023 11:53:00 PM	
Completed	Jan 7, 2023 12:24:00 AM	Jan 7, 2023 12:24:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Buzzer Beeping

Cause: Exit Window Switch Loose

Correction: Adjust & Tighten Both Window Switch Seem to beok At this time

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 06-JAN-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jan 6, 2023 11:54:09 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		DARTHURS	Jan 6, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				11:54:09 PM		
4 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jan 6, 2023 11:54:09 PM	No	
7 - Have you performed the proper LOTO?	Done		DARTHURS	Jan 6, 2023 11:54:09 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jan 6, 2023 11:54:09 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jan 6, 2023 11:54:09 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56284479
Invoice No. 55345 - 56284479

Client Department:
Department: 55345M
Work Order Description
Buzzer Beeping
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 106,779 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Check Exit Window
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Jan-23	Arthurs,Durvin	0.3	65	19.5
06-Jan-23	Arthurs,Durvin	0.12	65	7.8

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	27.30
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**27.30**

Work Order Footer

Work Order 56284479 Total	
Parts:	0.00
Labor:	27.30
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**27.30**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56269626
Invoice No. 55345 - 56269626

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
coolant issue		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	106,000 - DH

Chronology		
Reported	Jan 2, 2023 12:02:00 PM	Jan 2, 2023 12:02:00 PM
Started	Jan 2, 2023 12:21:00 PM	
Completed	Jan 2, 2023 3:04:00 PM	Jan 2, 2023 3:04:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: vehicle came in for low coolant

Cause: unknown

Correction: Check and no leak found replaced two quarter wll monitor also reported two CLEARANCE LIGHT PART # MCL12AK. JOB COMPLETE RETURN VEHICLE BACK TO WORK

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 02-JAN-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Jan 2, 2023 3:03:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Jan 2, 2023 3:03:42 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Jan 2, 2023 3:03:42 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Jan 2, 2023 3:03:42 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Jan 2, 2023 3:03:42 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Jan 2, 2023 3:03:42 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56269626
Invoice No. 55345 - 56269626

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
coolant issue		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	106,000 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: coolant issue
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jan-23	Junior Hurst	1.62	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.62
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56269626
Invoice No. 55345 - 56269626

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
coolant issue		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	106,000 - DH

Activity Header
Activity: 25 030 ELECTRICAL GROUP
Activity Note: two running lighr out
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Jan-23	MCL12AK	LAMP, MARKER/CLEARANCE, LED, AMBER	2	8.83	17.66

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jan-23	Junior Hurst	1.1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	17.66
Labor:	0.00
Labor Hours:	1.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**17.66**

Work Order Footer

Work Order 56269626 Total	
Parts:	17.66
Labor:	0.00
Labor Hours:	2.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**17.66**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 56256489
Invoice No. 55345 - 56256489

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	104,866 - DH

Chronology

Reported	Dec 27, 2022 8:18:27 AM	Dec 27, 2022 8:18:27 AM
Started	Dec 27, 2022 8:19:00 AM	
Completed	Dec 27, 2022 9:20:00 AM	Dec 27, 2022 9:20:00 AM
Down Time		

Work Order Notes

Line 10 PMA Service follows up need tires

preventive maintenance

repair and rotate completed

Activity Header
Activity: 10 017/003/001 TIRE, CUSHION W/TREAD
Activity Note: front tires need To be rotate
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Dec-22	Pierre,Hubert J	1.02	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 56256489 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.02
Sublet Parts:	0.00

	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56181122
Invoice No. 55345 - 56181122

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	104,866 - DH

Chronology		
Reported	Dec 23, 2022 12:00:00 AM	Dec 23, 2022 12:00:00 AM
Started	Dec 27, 2022 5:38:00 AM	
Completed	Dec 27, 2022 8:19:00 AM	Dec 27, 2022 8:19:00 AM
Down Time		

Work Order Notes

Line 10 PMA

preventive maintenance

perform PMA Service completed

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 27-DEC-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Dec 27, 2022 7:23:38 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Dec 27, 2022 7:23:38 AM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Dec 27, 2022 7:23:38 AM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Dec 27, 2022 7:23:38 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Dec 27, 2022 7:23:38 AM	No	
11 - Have you successfully completed the Personal	Done		HPIERRE	Dec 27, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				7:23:38 AM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56181122
Invoice No. 55345 - 56181122

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	104,866 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Dec-22	B7449	FILTER, OIL, SPIN-ON SEE P577066	1	4.45	4.45

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Dec-22	Pierre,Hubert J	2.67	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: HPIERRE Performed on: 27-DEC-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
10,800 - CHECK_All Destination Signage	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
20,200 - CHECK_Public Address System	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	60 Second*		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
20,700 - RECORD_Brake Performance Test Speed	60 Miles per Hour		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
20,800 - RECORD_Brake Performance Test Distance	6 FEET		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	60 FEET		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	60 Gravitational Force		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
21,500 - INSPECT_High Idle Control	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
21,800 - INSPECT_Parking Brake Operation	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for	Done		HPIERRE	Dec 27, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Proper Routing/Chafing/Securement				8:18:20 AM		
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
31,000 - SSF (Street Side Front)	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
32,000 - Engine Inspection	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	190 Degree Fahrenheit		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
32,100 - INSPECT_Intake System	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12 Volt*		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
33,000 - CSF (Curb Side Front)	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
33,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
40,700 - CHECK_Passenger Stop Request System	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
50,100 - *RPT*INSPECT_Steering components- Drag Link, Tie Rods ends and Steering Damper	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
50,400 - LUBE_All Chassis Components	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
50,700 - INSPECT_Tire Condition	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch	front tires need To be rotate	HPIERRE	Dec 27, 2022 8:18:20 AM	Yes	56256489
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	7 32nds of an inch		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	18 Inch		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	18 Inch		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
52,100 - INSPECT_Vibration Damper	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and	Done		HPIERRE	Dec 27, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Chassis Frame for Corrosion, Cracks				8:18:20 AM		
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
53,600 - INSPECT_Tire Condition	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	7 32nds of an inch		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	7 32nds of an inch		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	18 32nds of an inch		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	18 32nds of an inch		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	18 Inch		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	18 Inch		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		HPIERRE	Dec 27, 2022 8:18:20 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	4.45
Labor:	0.00
Labor Hours:	2.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.45**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56181122
Invoice No. 55345 - 56181122

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	104,866 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: HPIERRE Performed on: 27-DEC-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Dec 27, 2022 7:22:38 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Dec 27, 2022 7:22:38 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Dec 27, 2022 7:22:38 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Dec 27, 2022 7:22:38 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Dec 27, 2022 7:22:38 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Dec 27, 2022 7:22:38 AM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	Done		HPIERRE	Dec 27, 2022 7:22:38 AM	No	
107,000 - FRA Change Primary Fuel Filter	No		HPIERRE	Dec 27, 2022 7:22:38 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Dec 27, 2022 7:22:38 AM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 56181122 Total	
Parts:	4.45
Labor:	0.00
Labor Hours:	2.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.45**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 56014394
Invoice No. 55345 - 56014394

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
WINDSHIELD REPLACEMENT		Ford Transit	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	91,745 - DH

Chronology		
Reported	Oct 6, 2022 9:42:00 AM	Oct 6, 2022 9:42:00 AM
Started	Oct 17, 2022 12:00:00 AM	
Completed	Dec 19, 2022 9:51:00 AM	Dec 19, 2022 9:51:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: WINDSHIELD CRACKED

Cause: EXTERNAL OBJECT HIT IT

Correction: SAFELITE REPLACED BROKEN GLASS,UNIT RETURNED TO SERVICE.

Activity Header
Activity: 15 002 CAB & SHEET METAL
Activity Note: WINDSHIELD CRACKED SAFELITE REPLACED DAMAGED GLASS
Reason for Repair: 31 Accident, Non-Recoverable
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet

PO No.	ACD Code	Supplier No.	SUPPLIER	Order Date	Received Value
4545135	174,681,598	125113	SAFELITE AUTOGLASS,OH,CINCINNATI,dba SAFELITE AUTOGLASS	Oct 6, 2022 12:00:00 AM	599.04

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	599.04
Sublet Labor:	0.00
Activity Sub Total	**599.04**

Work Order Footer

Work Order 56014394 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	599.04
Sublet Labor:	0.00
Activity Sub Total	**599.04**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56201946
Invoice No. 55345 - 56201946

Client Department:

Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
CATALYTIC CONVERTER REPLACEMENT/ Please Install O2 Sensors B1 S1		Ford Transit	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	102,165 - DH

Chronology		
Reported	Dec 7, 2022 8:17:17 PM	Dec 7, 2022 8:17:17 PM
Started	Dec 7, 2022 9:16:00 PM	
Completed	Dec 18, 2022 7:05:00 PM	Dec 18, 2022 7:05:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Check Engine Light on

Cause: Code PO420 /PO430 Cat below Threshold Suggest Replacement

Correction: Line 20 Remove and replaced O2 sensor (B1S1). Cleared DTCs.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 07-DEC-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Dec 7, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:51:47 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Dec 7, 2022 9:51:47 PM	No	
4 - Are you wearing the appropriate PPE?	Done		DARTHURS	Dec 7, 2022 9:51:47 PM	No	
7 - Have you performed the proper LOTO?	Done		DARTHURS	Dec 7, 2022 9:51:47 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Dec 7, 2022 9:51:47 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Dec 7, 2022 9:51:47 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56201946
Invoice No. 55345 - 56201946

Client Department:

Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
CATALYTIC CONVERTER REPLACEMENT/ Please Install O2 Sensors B1 S1		Ford Transit	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	102,165 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Check Engine Light
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Dec-22	LK4Z-5F250-L	CONVERTER, CATALYTIC, LH	1	3,075.6	3,075.6

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Dec-22	Arthurs,Durvin	0.63	0	0
18-Dec-22	Earl Johnson	0.32	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	3,075.60
Labor:	0.00
Labor Hours:	0.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**3,075.60**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56201946
Invoice No. 55345 - 56201946

Client Department:

Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
CATALYTIC CONVERTER REPLACEMENT/ Please Install O2 Sensors B1 S1		Ford Transit	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	102,165 - DH

Activity Header
Activity: 25 043 EXHAUST SYSTEM
Activity Note: O2 SENSOR BANK 1 SENSOR 1
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Dec-22	LK4Z-9F472-D	SENSOR, OXYGEN, UPSTREAM, BANK-ONE, TRANSIT	1	133.64	133.64

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Dec-22	Earl Johnson	0.75	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	133.64
Labor:	0.00
Labor Hours:	0.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**133.64**

Work Order Footer

Work Order 56201946 Total	
Parts:	3,209.24
Labor:	0.00
Labor Hours:	1.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**3,209.24**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56189199
Invoice No. 55345 - 56189199

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345 HEADLIGHTS		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	101,333 - DH

Chronology		
Reported	Dec 4, 2022 6:50:15 PM	Dec 4, 2022 6:50:15 PM
Started	Dec 4, 2022 6:51:00 PM	
Completed	Dec 4, 2022 7:39:00 PM	Dec 4, 2022 7:39:00 PM
Down Time		

Work Order Notes

Line 10 replaced front right headlight low beam bulb..

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 04-DEC-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Dec 4, 2022 7:39:32 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Dec 4, 2022 7:39:32 PM	No	
4 - Are you wearing the appropriate PPE?	Done		TDELVA	Dec 4, 2022 7:39:32 PM	No	
7 - Have you performed the proper LOTO?	Done		TDELVA	Dec 4, 2022 7:39:32 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Dec 4, 2022 7:39:32 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Dec 4, 2022 7:39:32 PM	No	

Activity Sub Total

Activity 10 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56189199
Invoice No. 55345 - 56189199

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345 HEADLIGHTS		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	101,333 - DH

Activity Header
Activity:20 034/001/000 HEADLAMP
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Dec-22	H11BP	BULB, HEADLAMP	1	11.99	11.99

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Dec-22	Delva,Terry	0.77	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	11.99
Labor:	0.00
Labor Hours:	0.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**11.99**

Work Order Footer

Work Order 56189199 Total	
Parts:	11.99
Labor:	0.00
Labor Hours:	0.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**11.99**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56110556
Invoice No. 55345 - 56110556

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	100,946 - DH

Chronology		
Reported	Nov 29, 2022 12:00:00 AM	Nov 29, 2022 12:00:00 AM
Started	Dec 1, 2022 7:55:00 AM	
Completed	Dec 1, 2022 11:13:00 AM	Dec 1, 2022 11:13:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PMA Service

Cause: preventive maintenance

Correction: Perform PMA Service and lube all Pivoting Points

check engine light on: code found: p020-p030 catalyst efficiency below ,bank 1and 2

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 01-DEC-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Dec 1, 2022 8:18:15 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Dec 1, 2022 8:18:15 AM	No	
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Dec 1, 2022 8:18:15 AM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Dec 1, 2022 8:18:15 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Dec 1, 2022 8:18:15 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Dec 1, 2022 8:18:15 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56110556
Invoice No. 55345 - 56110556

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	100,946 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Dec-22	B7449	FILTER, OIL, SPIN-ON SEE P577066	1	4.91	4.91

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Dec-22	NELSON PIERRE-LOUIS	2.2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS Performed on: 01-DEC-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done	p020 catalystic efficinency below ,p030 ,bank 1,bank 2	NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
10,800 - CHECK_All Destination Signage	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
20,200 - CHECK_Public Address System	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	0 Second*		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
20,700 - RECORD_Brake Performance Test Speed	0 Miles per Hour		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,800 - RECORD_Brake Performance Test Distance	0 FEET		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	0 FEET		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	0 Gravitational Force		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
21,500 - INSPECT_High Idle Control	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
21,800 - INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
31,000 - SSF (Street Side Front)	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
32,000 - Engine Inspection	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	280 Degree Fahrenheit		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
32,100 - INSPECT_Intake System	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.1 Volt*		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
33,000 - CSF (Curb Side Front)	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
40,700 - CHECK_Passenger Stop Request System	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
50,400 - LUBE_All Chassis Components	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
50,700 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	66 Pounds per Square Inch		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	25.5 Inch		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	25.5 Inch		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
52,100 - INSPECT_Vibration Damper	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
53,600 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	64 Pounds per Square Inch		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	17.5 Inch		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	17.5 Inch		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,200 - RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	Dec 1, 2022 11:13:36 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	4.91
Labor:	0.00
Labor Hours:	2.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.91**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56110556
Invoice No. 55345 - 56110556

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMA		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	100,946 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Dec-22	NELSON PIERRE-LOUIS	1.03	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: Medium Duty PMA Service
Task: 55345-Medium Duty PMA Inspection Performed by: NPIERRE-LOUIS Performed on: 01-DEC-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Dec 1, 2022 11:11:04 AM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Dec 1, 2022 11:11:04 AM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Dec 1, 2022 11:11:04 AM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Dec 1, 2022 11:11:04 AM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Dec 1, 2022 11:11:04 AM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Dec 1, 2022 11:11:04 AM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	Done		NPIERRE-LOUIS	Dec 1, 2022 11:11:04 AM	No	
107,000 - FRA Change Primary Fuel Filter	No		NPIERRE-LOUIS	Dec 1, 2022 11:11:04 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Dec 1, 2022 11:11:04 AM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	1.03
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 56110556 Total	
Parts:	4.91
Labor:	0.00
Labor Hours:	3.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.91**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 56110492
Invoice No. 55345 - 56110492

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	96,984 - DH

Chronology

Reported	Nov 7, 2022 5:17:46 PM	Nov 7, 2022 5:17:46 PM
Started	Nov 7, 2022 5:43:00 PM	
Completed	Nov 11, 2022 8:42:00 AM	Nov 11, 2022 8:42:00 AM
Down Time		

Work Order Notes

Line 10 CHANGE FRONT BRAKES PART GMKD 1774 IT WAS TOO LOW

Activity Header

Activity: 10 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: front brakes too low need replace
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Nov-22	B7449	FILTER, OIL, SPIN-ON SEE P577066	1	4.91	4.91
07-Nov-22	DG1774	PADS, BRAKE, DISC, FRONT	1	40.76	40.76

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Nov-22	Junior Hurst	1.73	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	45.67
Labor:	0.00
Labor Hours:	1.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**45.67**

Work Order Footer

Work Order 56110492 Total	
Parts:	45.67
Labor:	0.00
Labor Hours:	1.73
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**45.67**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 56110503
Invoice No. 55345 - 56110503

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Medium Duty		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	96,984 - DH

Chronology		
Reported	Nov 7, 2022 5:21:15 PM	Nov 7, 2022 5:21:15 PM
Started	Nov 7, 2022 7:27:00 PM	
Completed	Nov 7, 2022 9:02:00 PM	Nov 7, 2022 9:02:00 PM
Down Time		

Work Order Notes

Line 10 change rear brakes it was below specification part number LK4Z-2200-J AFTER RETURN VEHICLE BACK TO WORK

Activity Header

Activity: 10 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note:
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Nov-22	LK4Z-2200-J	PADS, BRAKE, DISC, REAR, TRANSIT	1	91.52	91.52

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Nov-22	Junior Hurst	1.58	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	91.52
Labor:	0.00
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**91.52**

Work Order Footer

Work Order 56110503 Total	
Parts:	91.52
Labor:	0.00
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**91.52**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56100199
Invoice No. 55345 - 56100199

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	SPACE	**Status:**	40 - Closed (40)
Created By:	SPACE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	96,984 - DH

Chronology		
Reported	Nov 7, 2022 12:00:00 AM	Nov 7, 2022 12:00:00 AM
Started	Nov 7, 2022 3:12:00 PM	
Completed	Nov 7, 2022 5:41:00 PM	Nov 7, 2022 5:41:00 PM
Down Time		

Work Order Notes

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 07-NOV-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Nov 7, 2022 3:11:15 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Nov 7, 2022 3:11:15 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Nov 7, 2022 3:11:15 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Nov 7, 2022 3:11:15 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Nov 7, 2022 3:11:15 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Nov 7, 2022 3:11:15 PM	No	

Activity Sub Total

Activity 5 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56100199
Invoice No. 55345 - 56100199

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	SPACE	**Status:**	40 - Closed (40)
Created By:	SPACE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	96,984 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Nov-22	B7449	FILTER, OIL, SPIN-ON SEE P577066	1	4.91	4.91

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Nov-22	Junior Hurst	1.72	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: JUHURST Performed on: 07-NOV-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
10,800 - CHECK_All Destination Signage	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
20,200 - CHECK_Public Address System	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	30 Second*		JUHURST	Nov 7, 2022 5:39:48 PM	No	
20,700 - RECORD_Brake Performance Test Speed	30 Miles per Hour		JUHURST	Nov 7, 2022 5:39:48 PM	No	
20,800 - RECORD_Brake Performance Test Distance	20 FEET		JUHURST	Nov 7, 2022 5:39:48 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	20 FEET		JUHURST	Nov 7, 2022 5:39:48 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	10 Gravitational Force		JUHURST	Nov 7, 2022 5:39:48 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
21,500 - INSPECT_High Idle Control	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for	Done		JUHURST	Nov 7, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Proper Routing/Chafing/Securement				5:39:48 PM		
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
32,000 - Engine Inspection	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Nov 7, 2022 5:39:48 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Nov 7, 2022 5:39:48 PM	No	
33,000 - CSF (Curb Side Front)	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
33,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
40,700 - CHECK_Passenger Stop Request System	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
50,100 - *RPT*INSPECT_Steering components- Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
50,400 - LUBE_All Chassis Components	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
50,700 - INSPECT_Tire Condition	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Nov 7, 2022 5:39:48 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Nov 7, 2022 5:39:48 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	64 32nds of an inch		JUHURST	Nov 7, 2022 5:39:48 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Nov 7, 2022 5:39:48 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch		JUHURST	Nov 7, 2022 5:39:48 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch	front brakes too low need replace	JUHURST	Nov 7, 2022 5:39:48 PM	Yes	56110492
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.2299 Inch		JUHURST	Nov 7, 2022 5:39:48 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.2299 Inch		JUHURST	Nov 7, 2022 5:39:48 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Nov 7, 2022 5:39:48 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Nov 7, 2022 5:39:48 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Nov 7, 2022 5:39:48 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Nov 7, 2022 5:39:48 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Nov 7, 2022 5:39:48 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Nov 7, 2022 5:39:48 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Nov 7, 2022 5:39:48 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Nov 7, 2022 5:39:48 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch	rear brakes. low	JUHURST	Nov 7, 2022 5:39:48 PM	Yes	56110503
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch	rear need replace	JUHURST	Nov 7, 2022 5:39:48 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.5 Inch		JUHURST	Nov 7, 2022 5:39:48 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.5 Inch		JUHURST	Nov 7, 2022 5:39:48 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
55,800 - CHECK_Double Check Valve - Primary,	Done		JUHURST	Nov 7, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Secondary				5:39:48 PM		
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	Nov 7, 2022 5:39:48 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	4.91
Labor:	0.00
Labor Hours:	1.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.91**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56100199
Invoice No. 55345 - 56100199

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-MEDIUM DUTY PMB		Ford Transit	
Requested By:	SPACE	**Status:**	40 - Closed (40)
Created By:	SPACE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	96,984 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMB Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Nov-22	Junior Hurst	0.73	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 56100199 Total	
Parts:	4.91
Labor:	0.00
Labor Hours:	2.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.91**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56020198
Invoice No. 55345 - 56020198

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMB		Ford Transit	
Requested By:	DARTHURS	**Status:**	99 - Cancelled (99)
Created By:	DARTHURS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	96,984 - DH

Chronology		
Reported	Nov 4, 2022 12:00:00 AM	Nov 4, 2022 12:00:00 AM
Started		
Completed	Nov 7, 2022 9:45:06 AM	Nov 7, 2022 9:45:06 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION:

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	-				No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	-				No	
4 - Are you wearing the appropriate PPE?	-				No	
7 - Have you performed the proper LOTO?	-				No	
10 - Are you aware of the potential risks of performing this repair?	-				No	
11 - Have you successfully completed the Personal Risk Assessment?	-				No	

Activity Sub Total

	Activity 5 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56020198
Invoice No. 55345 - 56020198

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMB		Ford Transit	
Requested By:	DARTHURS	**Status:**	99 - Cancelled (99)
Created By:	DARTHURS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	96,984 - DH

Activity Header
Activity: 10
Activity Note: Light Duty PMI
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	-				No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	-				No	
10,200 - !FRA!INSPECT_Starter Operation	-				No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	-				No	
10,400 - !FRA!INSPECT_Back Up Alarm	-				No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	-				No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	-				No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	-				No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	-				No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	-				No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	-				No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	-				No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	-				No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive	-				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
into Shop						
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	-				No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	-				No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	-				No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	-				No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	-				No	
20,800 - INSPECT_High Idle Control	-				No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	-				No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	-				No	
21,100 - INSPECT_Parking Brake Operation	-				No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	-				No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	-				No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	-				No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	-				No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	-				No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	-				No	
21,700 - INSPECT_Engine Fault Codes	-				No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	-				No	
31,000 - SSF (Street Side Front)	-				No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	-				No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	-				No	
31,030 - INSPECT_Mud Flaps, Brackets	-				No	
31,040 - INSPECT_Wiper Blades, Arms	-				No	
32,000 - Engine Inspection	-				No	
32,010 - INSPECT_Hood, Springs and Props	-				No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	-				No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	-				No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-				No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit				No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	-				No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	-				No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	-				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	-				No	
32,100 - INSPECT_Intake System	-				No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	-				No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	Volt*				No	
33,010 - CSF (Curb Side Front)	-				No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	-				No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	-				No	
33,040 - INSPECT_Mud Flaps, Brackets	-				No	
33,050 - INSPECT_Wiper Blades, Arms	-				No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	-				No	
40,000 - SECTION 4 - Interior Inspection	-				No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	-				No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	-				No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	-				No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	-				No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	-				No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	-				No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	-				No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	-				No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	-				No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	-				No	
41,100 - INSPECT_CLEAN_AC Filter	-				No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	-				No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	-				No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	-				No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	-				No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	-				No	
50,200 - INSPECT_Ball Joint Play	-				No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	-				No	
50,400 - LUBE_All Chassis Components	-				No	
50,500 - !FRA!CHANGE_Engine oil,filters	-				No	
50,700 - INSPECT_Tire Condition	-				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	-				No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	-				No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	32nds of an inch				No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	Pounds per Square Inch				No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	32nds of an inch				No	
51,300 - RECORD_RF-Air Pressure (psi)	Pounds per Square Inch				No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	-				No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	-				No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	-				No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	32nds of an inch				No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	32nds of an inch				No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	Inch				No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	Inch				No	
52,100 - INSPECT_Vibration Damper	-				No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	-				No	
52,400 - !FRA!INSPECT_ Starter Mounting	-				No	
52,500 - !FRA!INSPECT_Engine Exhaust System	-				No	
52,700 - INSPECT_ Engine, Transmission Mounts	-				No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	-				No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	-				No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	-				No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	-				No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	-				No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	-				No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	-				No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	-				No	
53,600 - INSPECT_Tire Condition	-				No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	-				No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	-				No	
53,900 - INSPECT_Dual Mating Tires w/Square	-				No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	-				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,100 - INSPECT_Mud Flaps, Brackets	-				No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	32nds of an inch				No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	32nds of an inch				No	
54,400 - RECORD_RRO-Air Pressure (psi)	Pounds per Square Inch				No	
54,500 - RECORD_RRI-Air Pressure (psi)	Pounds per Square Inch				No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	32nds of an inch				No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	32nds of an inch				No	
54,800 - RECORD_LRO-Air Pressure (psi)	Pounds per Square Inch				No	
54,900 - RECORD_LRI-Air Pressure (psi)	Pounds per Square Inch				No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	-				No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	-				No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	-				No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	32nds of an inch				No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	32nds of an inch				No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	Inch				No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	Inch				No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	-				No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	-				No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	-				No	
80,000 - SECTION 8 - PMI Report Completion	-				No	
80,100 - COMPLETE_PM Report; Follow-ups	-				No	
80,200 - RETURN_Vehicle to Predetermined Location	-				No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56020198
Invoice No. 55345 - 56020198

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMB
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 99 - Cancelled (99)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 96,984 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	-				No	
101,000 - FRA Change Oil Filters	No				No	
102,000 - FRA Drain Engine Oil	No				No	
103,000 - FRA Check Transmission Fluid	-				No	
104,000 - Lubricate Chassis	-				No	
105,000 - Replace or Clean A/C Filters	-				No	
107,000 - FRA Change Primary Fuel Filter	No				No	
108,000 - Lube all pivoting Mechanisms	-				No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	-				No	
201,000 - Service Crankcase Breather	-				No	
203,000 - FRA Change Automatic Transmission Fluid	No				No	
204,000 - FRA Change Power Steering Fluid and Filter	No				No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	-				No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 56020198 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56079843
Invoice No. 55345 - 56079843

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Problem with door switch.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	94,904 - DH

Chronology		
Reported	Oct 27, 2022 9:13:03 PM	Oct 27, 2022 9:13:03 PM
Started	Oct 27, 2022 9:15:00 PM	
Completed	Oct 28, 2022 12:09:00 AM	Oct 28, 2022 12:09:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Problem with door switch.

Cause: Unknown.

Correction: Could not verify Complaint. Door switch functions properly. Will monitor.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 28-OCT-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Oct 28, 2022 12:06:58 AM	No	
2 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Oct 28, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				12:06:58 AM		
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Oct 28, 2022 12:06:58 AM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Oct 28, 2022 12:06:58 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Oct 28, 2022 12:06:58 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Oct 28, 2022 12:06:58 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56079843
Invoice No. 55345 - 56079843

Client Department:
Department: 55345M
Work Order Description
Problem with door switch.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 94,904 - DH

Activity Header
Activity: 15 078 TRIM & MISCELLANEOUS HARDWARE
Activity Note: Problem with door switch.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Oct-22	Earl Johnson	2.22	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 56079843 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56041220
Invoice No. 55345 - 56041220

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Check engine light illuminated.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	93,285 - DH

Chronology		
Reported	Oct 16, 2022 10:53:19 AM	Oct 16, 2022 10:53:19 AM
Started	Oct 16, 2022 10:55:00 AM	
Completed	Oct 25, 2022 4:26:00 PM	Oct 25, 2022 4:26:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Check engine light illuminated.

Cause: DTCs p0420 & p0430 present.

Correction: Noted for catalytic converters to be replaced. AWP.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 16-OCT-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Oct 16, 2022 1:43:44 PM	No	
2 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Oct 16, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				1:43:44 PM		
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Oct 16, 2022 1:43:44 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Oct 16, 2022 1:43:44 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Oct 16, 2022 1:43:44 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Oct 16, 2022 1:43:44 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56041220
Invoice No. 55345 - 56041220

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Check engine light illuminated.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	93,285 - DH

Activity Header
Activity: 15 043 EXHAUST SYSTEM
Activity Note: Check engine light illuminated.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Oct-22	Earl Johnson	2.78	0	0
17-Oct-22	Rodriguez,Raul	1.52	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	4.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 56041220 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	4.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56059223
Invoice No. 55345 - 56059223

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Beeping sound inside.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	93,839 - DH

Chronology		
Reported	Oct 20, 2022 9:07:46 PM	Oct 20, 2022 9:07:46 PM
Started	Oct 20, 2022 9:10:00 PM	
Completed	Oct 20, 2022 11:25:00 PM	Oct 20, 2022 11:25:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Beeping sound inside.

Cause: Passenger side emergency exit window latch issue.

Correction: Readjusted window switch to correct latch.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 20-OCT-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Oct 20, 2022 11:19:47 PM	No	
2 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Oct 20, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				11:19:47 PM		
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Oct 20, 2022 11:19:47 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Oct 20, 2022 11:19:47 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Oct 20, 2022 11:19:47 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Oct 20, 2022 11:19:47 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56059223
Invoice No. 55345 - 56059223

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Beeping sound inside.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	93,839 - DH

Activity Header
Activity: 15 036 DEVICES, INFORMATION, SUPPLEMENTAL
Activity Note: Beeping sound inside.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Oct-22	Earl Johnson	1.33	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 56059223 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56020174
Invoice No. 55345 - 56020174

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Light Duty		Ford Transit	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	92,215 - DH

Chronology		
Reported	Oct 7, 2022 11:34:11 PM	Oct 7, 2022 11:34:11 PM
Started	Oct 9, 2022 1:45:00 PM	
Completed	Oct 9, 2022 5:21:00 PM	Oct 9, 2022 5:21:00 PM
Down Time		

Work Order Notes

Line 10 Rear Tire Worn To Wear Bar & Wiper Blade Streaky Mount & Balance Rear Tire & Remove & Replace both Wiper Blades Front Clearance Light out Remove & Replace Front Clearance Light.
parts #MCL12AK Qty (2).
arts #28CA Qty (1)
parts # 20CA Qty (1)
parts # 004708 Qty (4)

Activity Header
Activity: 10 002/035/015 BLADE, WIPER
Activity Note: Wiper Blade
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Oct-22	28CA	BLADE, WIPER, WINDSHEILD	1	6.95	6.95
09-Oct-22	20CA	BLADE, WIPER, WINDSHIELD	1	6.96	6.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Oct-22	Arthurs,Durvin	0.22	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	13.91
Labor:	0.00
Labor Hours:	0.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**13.91**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56020174
Invoice No. 55345 - 56020174

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Light Duty		Ford Transit	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	92,215 - DH

Activity Header
Activity:20 017/008/004 CAP, VALVE, TIRE
Activity Note: Rear Tires Worn
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Oct-22	004708	TIRE, 195/75R16C, BSW, D/8-PLY, CV, TRANSFORCE, FIRESTONE	4	140.56	562.24

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Oct-22	Arthurs,Durvin	2.35	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	562.24
Labor:	0.00
Labor Hours:	2.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**562.24**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56020174
Invoice No. 55345 - 56020174

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Light Duty		Ford Transit	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	92,215 - DH

Activity Header
Activity: 30 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Front Clearance Light
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Oct-22	MCL12AK	LAMP, MARKER/CLEARANCE, LED, AMBER	2	8.84	17.68

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Oct-22	Arthurs,Durvin	0.67	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	17.68
Labor:	0.00
Labor Hours:	0.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**17.68**

Work Order Footer

Work Order 56020174 Total	
Parts:	593.83
Labor:	0.00
Labor Hours:	3.24
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**593.83**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55910376
Invoice No. 55345 - 55910376

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	92,215 - DH

Chronology		
Reported	Oct 5, 2022 12:00:00 AM	Oct 5, 2022 12:00:00 AM
Started	Oct 7, 2022 4:25:00 PM	
Completed	Oct 8, 2022 12:28:00 AM	Oct 8, 2022 12:28:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PMA Service.

CAUSE: Service due by Mileage.

CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check Brakes. Clean Rear A/C filter.
Parts # B7449 Qty (1)
Oil 10 W30 Qty (6.0) Qts

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Oct-22	B7449	FILTER, OIL, SPIN-ON SEE P577066	1	7.65	7.65

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 08-OCT-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Oct 8, 2022 12:28:27 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Oct 8, 2022 12:28:27 AM	No	
4 - Are you wearing the appropriate PPE?	Done		DARTHURS	Oct 8, 2022 12:28:27 AM	No	
7 - Have you performed the proper LOTO?	Done		DARTHURS	Oct 8, 2022 12:28:27 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Oct 8, 2022 12:28:27 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Oct 8, 2022 12:28:27 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	7.65
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.65**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55910376
Invoice No. 55345 - 55910376

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	92,215 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Oct-22	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: DARTHURS Performed on: 08-OCT-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		DARTHURS	Oct 8, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:27:50 AM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
20,800 - INSPECT_High Idle Control	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
21,100 - INSPECT_Parking Brake Operation	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
21,700 - INSPECT_Engine Fault Codes	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
31,000 - SSF (Street Side Front)	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
32,000 - Engine Inspection	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	NA	DARTHURS	Oct 8, 2022 12:27:50 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	DARTHURS	Oct 8, 2022 12:27:50 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
32,100 - INSPECT_Intake System	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.08 Volt*		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
33,010 - CSF (Curb Side Front)	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
33,050 - INSPECT_Wiper Blades, Arms	-	Wiper Blade	DARTHURS	Oct 8, 2022 12:27:50 AM	Yes	56020174
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical	Done		DARTHURS	Oct 8, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Inputs/Outputs-SOP M038				12:27:50 AM		
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
50,400 - LUBE_All Chassis Components	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
50,700 - INSPECT_Tire Condition	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	11 32nds of an inch		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	67 Pounds per Square Inch		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	11 32nds of an inch		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	67 Pounds per Square Inch		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.228 Inch		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.228 Inch		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
52,100 - INSPECT_Vibration Damper	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
53,600 - INSPECT_Tire Condition	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	2 32nds of an inch		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	2 32nds of an inch		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	62 Pounds per Square Inch		DARTHURS	Oct 8, 2022 12:27:50 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,500 - RECORD_RRI-Air Pressure (psi)	62 Pounds per Square Inch		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	2 32nds of an inch		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	2 32nds of an inch	Rear Tires Worn	DARTHURS	Oct 8, 2022 12:27:50 AM	Yes	56020174
54,800 - RECORD_LRO-Air Pressure (psi)	62 Pounds per Square Inch		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	62 Pounds per Square Inch		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.799 Inch		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.799 Inch		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
60,100 - RECORD_Wheelchair Cycle Count	100 Cycles		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper	Done		DARTHURS	Oct 8, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alignment				12:27:50 AM		
61,000 - INSPECT_Cable Condition (If Applicable)	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
62,400 - INSPECT_All Pivot Points	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
62,500 - INSPECT_Cams and Slots	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
62,600 - INSPECT_Rollers	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
62,700 - INSPECT_All Linkages	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		DARTHURS	Oct 8, 2022 12:27:50 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55910376
Invoice No. 55345 - 55910376

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	92,215 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Oct-22	Arthurs,Durvin	0.4	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 08-OCT-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Oct 8, 2022 12:26:59 AM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Oct 8, 2022 12:26:59 AM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Oct 8, 2022 12:26:59 AM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Oct 8, 2022 12:26:59 AM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Oct 8, 2022 12:26:59 AM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Oct 8, 2022 12:26:59 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Oct 8, 2022 12:26:59 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Oct 8, 2022 12:26:59 AM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.40
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 55910376 Total	
Parts:	7.65
Labor:	0.00
Labor Hours:	2.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.65**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 55989822
Invoice No. 55345 - 55989822

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Emergency Windows Rear AC Engine Light
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 90,689 - DH

Chronology		
Reported	Sep 27, 2022 9:20:00 PM	Sep 27, 2022 9:20:00 PM
Started	Sep 27, 2022 9:21:00 PM	
Completed	Sep 28, 2022 12:25:00 AM	Sep 28, 2022 12:25:00 AM
Down Time		

Work Order Notes

Line 10 Complaint: Emer. exit windows/Check eng light illuminated/ AC malfunction.

Cause: Pass. side exit switch out of adjustment/ DTCs p0420&p0430/ unknown.

Correction: Readjusted window switch/ Noted for catalytic replacement/ could not duplicate issue, no Correction performed. Will monitor.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 27-SEP-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Sep 27, 2022 11:55:27 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Sep 27, 2022 11:55:27 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Sep 27, 2022 11:55:27 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Sep 27, 2022 11:55:27 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Sep 27, 2022 11:55:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Sep 27, 2022 11:55:27 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 55989822
Invoice No. 55345 - 55989822

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Emergency Windows Rear AC Engine Light
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 90,689 - DH

Activity Header
Activity: 20 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Check Engine Light
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Sep-22	Earl Johnson	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 55989822
Invoice No. 55345 - 55989822

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Emergency Windows Rear AC Engine Light
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 90,689 - DH

Activity Header
Activity: 30 174/024/001 HARNESS, WIRING, BODY, BUS, MAIN
Activity Note: Emergency Window
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Sep-22	Earl Johnson	0.1	0	0
28-Sep-22	Earl Johnson	0.15	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 55989822
Invoice No. 55345 - 55989822

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Emergency Windows Rear AC Engine Light
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 90,689 - DH

Activity Header
Activity: 40 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear AC
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Sep-22	Earl Johnson	0.23	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55989822 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.98
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55969304
Invoice No. 55345 - 55969304

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Check engine light illuminated.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	89,815 - DH

Chronology		
Reported	Sep 20, 2022 11:36:00 PM	Sep 20, 2022 11:36:00 PM
Started	Sep 20, 2022 11:38:00 PM	
Completed	Sep 21, 2022 12:37:00 AM	Sep 21, 2022 12:37:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Check Engine light illuminated/ TPMS light illuminated.

Cause: P0420, P0430 DTCs present/ LRI tire puncture.

Correction: Noted for repair, will monitor/ remove wheel, dismounted tire and repaired puncture. Remounted tire and re-installed wheel. Torqued to spec.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 21-SEP-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Sep 21, 2022 12:33:16 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Sep 21, 2022 12:33:16 AM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Sep 21, 2022 12:33:16 AM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Sep 21, 2022 12:33:16 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Sep 21, 2022 12:33:16 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Sep 21, 2022 12:33:16 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55969304
Invoice No. 55345 - 55969304

Client Department:
Department: 55345M
Work Order Description
Check engine light illuminated.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 89,815 - DH

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Check engine light illuminated.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Sep-22	Earl Johnson	-0.37	0	0
21-Sep-22	Earl Johnson	-0.62	0	0
21-Sep-22	Earl Johnson	0.62	0	0
20-Sep-22	Earl Johnson	0.37	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55969304
Invoice No. 55345 - 55969304

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Check engine light illuminated.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	89,815 - DH

Activity Header
Activity: 25 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note: TIRE PUNCTURE
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Sep-22	Earl Johnson	0.62	0	0
20-Sep-22	Earl Johnson	0.37	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.99
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55969304 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.99
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55948131
Invoice No. 55345 - 55948131

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Replace 2 Tires		Ford Transit	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	88,694 - DH

Chronology		
Reported	Sep 13, 2022 7:07:00 PM	Sep 13, 2022 7:07:00 PM
Started	Sep 13, 2022 7:07:00 PM	
Completed	Sep 14, 2022 12:28:00 AM	Sep 14, 2022 12:28:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs front tires

Cause: low spec

Correction:replaced front tires mount and balance
dismount left rear outside tire mount good used tire
and balance. (front tires are new 004708 qty2)
torque wheels 140 lbs second torque 140 lbs.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 13-SEP-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Sep 13, 2022 7:09:50 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Sep 13, 2022 7:09:50 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RGASPARD	Sep 13, 2022 7:09:50 PM	No	
7 - Have you performed the proper LOTO?	Done		RGASPARD	Sep 13, 2022 7:09:50 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Sep 13, 2022 7:09:50 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Sep 13, 2022 7:09:50 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55948131
Invoice No. 55345 - 55948131

Client Department:
Department: 55345M
Work Order Description
Replace 2 Tires
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 88,694 - DH

Activity Header
Activity: 15 017/001/000 TIRE, PNEUMATIC
Activity Note: Replace Front Tires
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Sep-22	004708	TIRE, 195/75R16C, BSW, D/8-PLY, CV, TRANSFORCE, FIRESTONE	2	128.16	256.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Sep-22	Gaspard,Ronald	2.03	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	256.32
Labor:	0.00
Labor Hours:	2.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**256.32**

Work Order Footer

Work Order 55948131 Total	
Parts:	256.32
Labor:	0.00
Labor Hours:	2.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**256.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55788132
Invoice No. 55345 - 55788132

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	87,279 - DH

Chronology		
Reported	Aug 31, 2022 12:00:00 AM	Aug 31, 2022 12:00:00 AM
Started	Sep 2, 2022 7:21:00 AM	
Completed	Sep 2, 2022 12:28:00 PM	Sep 2, 2022 12:28:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA

CAUSE:preventive maintenance

CORRECTION:Performed pma service completed

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 02-SEP-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Sep 2, 2022 7:58:29 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Sep 2, 2022 7:58:29 AM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Sep 2, 2022 7:58:29 AM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Sep 2, 2022 7:58:29 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Sep 2, 2022 7:58:29 AM	No	
11 - Have you successfully completed the Personal	Done		HPIERRE	Sep 2, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				7:58:29 AM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55788132
Invoice No. 55345 - 55788132

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 87,279 - DH

Activity Header
Activity: 10 017 TIRES, TUBES, LINERS & VALVES
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Sep-22	Pierre,Hubert J	1.08	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: HPIERRE Performed on: 02-SEP-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
20,800 - INSPECT_High Idle Control	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
21,100 - INSPECT_Parking Brake Operation	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
21,700 - INSPECT_Engine Fault Codes	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
31,000 - SSF (Street Side Front)	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,000 - Engine Inspection	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	190 Degree Fahrenheit		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
32,100 - INSPECT_Intake System	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12 Volt*		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
33,010 - CSF (Curb Side Front)	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
50,400 - LUBE_All Chassis Components	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
50,700 - INSPECT_Tire Condition	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		HPIERRE	Sep 2, 2022 8:09:06 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	18 Inch		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	18 Inch		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
52,100 - INSPECT_Vibration Damper	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
53,600 - INSPECT_Tire Condition	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Sep 2, 2022 8:09:06 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	18 Inch		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	18 Inch		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
60,100 - RECORD_Wheelchair Cycle Count	1324 Cycles		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
62,400 - INSPECT_All Pivot Points	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
62,500 - INSPECT_Cams and Slots	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
62,600 - INSPECT_Rollers	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
62,700 - INSPECT_All Linkages	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		HPIERRE	Sep 2, 2022 8:09:06 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55788132
Invoice No. 55345 - 55788132

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 87,279 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Sep-22	B7449	FILTER, OIL, SPIN-ON SEE P577066	1	3.25	3.25

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Sep-22	Pierre,Hubert J	0.97	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 02-SEP-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Sep 2, 2022 7:59:31 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Sep 2, 2022 7:59:31 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Sep 2, 2022 7:59:31 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Sep 2, 2022 7:59:31 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Sep 2, 2022 7:59:31 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Sep 2, 2022 7:59:31 AM	No	
107,000 - FRA Change Primary Fuel Filter	No		HPIERRE	Sep 2, 2022 7:59:31 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Sep 2, 2022 7:59:31 AM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	3.25
	Labor:	0.00
	Labor Hours:	0.97
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**3.25**

Work Order Footer

Work Order 55788132 Total	
Parts:	3.25
Labor:	0.00
Labor Hours:	2.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**3.25**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55781818
Invoice No. 55345 - 55781818

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FUEL PUMP REPLACEMENT		Ford Transit	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	82,443 - DH

Chronology		
Reported	Jul 18, 2022 11:31:00 AM	Jul 18, 2022 11:31:00 AM
Started		
Completed	Aug 26, 2022 7:52:00 PM	Aug 26, 2022 7:52:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Vehicle came in for fuel pump issue

Cause: pump worn out

Correction: change fuel pump. part # FG2066 vehicle working perfect return to work

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: JUHURST Performed on: 26-AUG-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Aug 26, 2022 7:50:08 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Aug 26, 2022 7:50:08 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Aug 26, 2022 7:50:08 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Aug 26, 2022 7:50:08 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Aug 26, 2022 7:50:08 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Aug 26, 2022 7:50:08 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55781818
Invoice No. 55345 - 55781818

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FUEL PUMP REPLACEMENT		Ford Transit	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	82,443 - DH

Activity Header
Activity: 15 044/003/000 PUMP, FUEL
Activity Note: VEHICLE HAS AN INTERMITENT STALLING CONDITION -REPLACE FUEL PUMP
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Sep-22	CK4Z-9H307-F	PUMP, FUEL, TRANSIT	1	196.99	196.99

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Jul-22	Junior Hurst	3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	196.99
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**196.99**

Work Order Footer

Work Order 55781818 Total	
Parts:	196.99
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**196.99**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55874092
Invoice No. 55345 - 55874092

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Fuel pump.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	85,532 - DH

Chronology		
Reported	Aug 21, 2022 1:31:23 PM	Aug 21, 2022 1:31:23 PM
Started	Aug 21, 2022 1:34:00 PM	
Completed	Aug 25, 2022 12:13:00 AM	Aug 25, 2022 12:13:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Replace fuel pump.

Cause: Defective.

Correction: Remove and replaced fuel pump assembly. Line 20 ****ALL 2020 ECOBOOST VEHICLES REQUIRE 91 OCTANE FUEL***

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 21-AUG-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Aug 21, 2022 5:48:10 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Aug 21, 2022 5:48:10 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Aug 21, 2022 5:48:10 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Aug 21, 2022 5:48:10 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Aug 21, 2022 5:48:10 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Aug 21, 2022 5:48:10 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55874092
Invoice No. 55345 - 55874092

Client Department:
Department: 55345M
Work Order Description
Fuel pump.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 85,532 - DH

Activity Header
Activity: 15 044 FUEL SYSTEM
Activity Note: Replace fuel pump.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Aug-22	CK4Z-9H307-F	PUMP, FUEL, TRANSIT	1	196.99	196.99

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Aug-22	Earl Johnson	4.22	0	0
21-Aug-22	Earl Johnson	-4.22	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	196.99
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**196.99**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55874092
Invoice No. 55345 - 55874092

Client Department:
Department: 55345M
Work Order Description
Fuel pump.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 85,532 - DH

Activity Header
Activity: 25 044/003/000 PUMP, FUEL
Activity Note: REPLACE FUEL PUMP
Reason for Repair: 01 Breakdown
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Aug-22	Earl Johnson	4.22	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	4.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55874092 Total	
Parts:	196.99
Labor:	0.00
Labor Hours:	4.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**196.99**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55878023
Invoice No. 55345 - 55878023

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Camera Hanging)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 85,532 - DH

Chronology		
Reported	Aug 22, 2022 6:27:00 PM	Aug 22, 2022 6:27:00 PM
Started	Aug 22, 2022 6:27:00 PM	
Completed	Aug 22, 2022 10:26:00 PM	Aug 22, 2022 10:26:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: Camera hanging.

Cause: Installed incorrectly.

Correction: Remove bracket. Prepped and cleaned both mating surfaces and reinstalled with specified adhesive.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 22-AUG-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Aug 22, 2022 9:43:26 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Aug 22, 2022 9:43:26 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Aug 22, 2022 9:43:26 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Aug 22, 2022 9:43:26 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Aug 22, 2022 9:43:26 PM	No	
11 - Have you successfully completed the	Done		EARJOHNSON	Aug 22, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				9:43:26 PM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55878023
Invoice No. 55345 - 55878023

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Camera Hanging)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 85,532 - DH

Activity Header
Activity:20 036/008/002 CAMERA, SYSTEM, SURVEILLANCE
Activity Note: Camera Hanging
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Aug-22	Earl Johnson	0.7	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55878023 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55857259
Invoice No. 55345 - 55857259

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Road Call-bus stalling		Ford Transit	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WORC - WORK ORDER ROAD CALL	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	85,220 - DH

Chronology		
Reported	Aug 15, 2022 2:51:00 PM	Aug 15, 2022 2:51:00 PM
Started	Aug 16, 2022 8:18:00 AM	
Completed	Aug 17, 2022 8:05:00 AM	Aug 17, 2022 8:05:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:vehicle was stalling when pick up from road call

Cause: check computer system found codes for catalytic converter below thresholds efficiency this codes will not cause the vehicle to stalled, perform engine running test all codes didn't come back. test fuel for contamination

Correction:road test and keep testing pcm to see if any codes came back, vehicle never stalled again at this time vehicle was sent to work under monitor

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: PRAMETER Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 17-AUG-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Aug 17, 2022 8:04:34 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Aug 17, 2022 8:04:34 AM	No	
4 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Aug 17, 2022 8:04:34 AM	No	
7 - Have you performed the proper LOTO?	Done		JAPEREZ	Aug 17, 2022 8:04:34 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Aug 17, 2022 8:04:34 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Aug 17, 2022 8:04:34 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55857259
Invoice No. 55345 - 55857259

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Road Call-bus stalling		Ford Transit	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WORC - WORK ORDER ROAD CALL	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	85,220 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55857259
Invoice No. 55345 - 55857259

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Road Call-bus stalling		Ford Transit	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WORC - WORK ORDER ROAD CALL	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	85,220 - DH

Activity Header
Activity: 20 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: check engine light on
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Aug-22	Perez,Javier	7.28	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	7.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55857259 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	7.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55861420
Invoice No. 55345 - 55861420

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Replace Fuel Door		Ford Transit	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	85,357 - DH

Chronology		
Reported	Aug 16, 2022 6:59:00 PM	Aug 16, 2022 6:59:00 PM
Started	Aug 16, 2022 6:59:00 PM	
Completed	Aug 17, 2022 12:41:00 AM	Aug 17, 2022 12:41:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Replace fuel door.

Cause: Damaged during operation.

Correction: Remove and replaced fuel door assembly.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 16-AUG-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Aug 16, 2022 8:41:55 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Aug 16, 2022 8:41:55 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Aug 16, 2022 8:41:55 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Aug 16, 2022 8:41:55 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Aug 16, 2022 8:41:55 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Aug 16, 2022 8:41:55 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55861420
Invoice No. 55345 - 55861420

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Replace Fuel Door		Ford Transit	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	85,357 - DH

Activity Header
Activity: 15 044 FUEL SYSTEM
Activity Note: Replace Fuel Door
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Aug-22	CK4Z-5427936-J	HOUSING, DOOR, FILLER, FUEL	1	54.4	54.4

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Aug-22	Earl Johnson	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	54.40
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**54.40**

Work Order Footer

Work Order 55861420 Total	
Parts:	54.40
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**54.40**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55690523
Invoice No. 55345 - 55690523

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMC		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	82,512 - DH

Chronology		
Reported	Jul 15, 2022 12:00:00 AM	Jul 15, 2022 12:00:00 AM
Started	Jul 20, 2022 8:07:00 AM	
Completed	Jul 20, 2022 9:29:00 AM	Jul 20, 2022 9:29:00 AM
Down Time		

Work Order Notes

Line 10 PMC

preventive maintenance

perform PMC Service and transmission services completed

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 20-JUL-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Jul 20, 2022 8:30:53 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Jul 20, 2022 8:30:53 AM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Jul 20, 2022 8:30:53 AM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Jul 20, 2022 8:30:53 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Jul 20, 2022 8:30:53 AM	No	
11 - Have you successfully completed the Personal	Done		HPIERRE	Jul 20, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				8:30:53 AM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55690523
Invoice No. 55345 - 55690523

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMC		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	82,512 - DH

Activity Header
Activity: 10 018 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jul-22	Pierre,Hubert J	1.35	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: HPIERRE Performed on: 20-JUL-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
20,800 - INSPECT_High Idle Control	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
21,100 - INSPECT_Parking Brake Operation	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
21,700 - INSPECT_Engine Fault Codes	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
31,000 - SSF (Street Side Front)	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,000 - Engine Inspection	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	190 Degree Fahrenheit		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
32,100 - INSPECT_Intake System	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12 Volt*		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
33,010 - CSF (Curb Side Front)	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
50,400 - LUBE_All Chassis Components	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
50,700 - INSPECT_Tire Condition	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	65 32nds of an inch		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		HPIERRE	Jul 20, 2022 8:27:39 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	18 Inch		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	18 Inch		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
52,100 - INSPECT_Vibration Damper	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
53,600 - INSPECT_Tire Condition	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	7 32nds of an inch		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	7 32nds of an inch		HPIERRE	Jul 20, 2022 8:27:39 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	17 Inch		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	17 Inch		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
60,100 - RECORD_Wheelchair Cycle Count	1334 Cycles		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
62,400 - INSPECT_All Pivot Points	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
62,500 - INSPECT_Cams and Slots	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
62,600 - INSPECT_Rollers	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
62,700 - INSPECT_All Linkages	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		HPIERRE	Jul 20, 2022 8:27:39 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55690523
Invoice No. 55345 - 55690523

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMC
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 82,512 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Jul-22	B7449	FILTER, OIL, SPIN-ON SEE P577066	1	4.12	4.12

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: HPIERRE Performed on: 20-JUL-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Jul 20, 2022 8:29:59 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Jul 20, 2022 8:29:59 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Jul 20, 2022 8:29:59 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Jul 20, 2022 8:29:59 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Jul 20, 2022 8:29:59 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Jul 20, 2022 8:29:59 AM	No	
107,000 - FRA Change Primary Fuel Filter	Done		HPIERRE	Jul 20, 2022 8:29:59 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Jul 20, 2022 8:29:59 AM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		HPIERRE	Jul 20, 2022 8:29:59 AM	No	
201,000 - Service Crankcase Breather	Done		HPIERRE	Jul 20, 2022 8:29:59 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	No		HPIERRE	Jul 20, 2022 8:29:59 AM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		HPIERRE	Jul 20, 2022 8:29:59 AM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		HPIERRE	Jul 20, 2022 8:29:59 AM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		HPIERRE	Jul 20, 2022 8:29:59 AM	No	
301,000 - Check and Lubricate Door Linkages	Done		HPIERRE	Jul 20, 2022 8:29:59 AM	No	
302,000 - Check Toe-In and Record Reading	Done		HPIERRE	Jul 20, 2022 8:29:59 AM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	N/A	HPIERRE	Jul 20, 2022 8:29:59 AM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		HPIERRE	Jul 20, 2022 8:29:59 AM	No	
305,000 - FRA Change Differential Fluid	No		HPIERRE	Jul 20, 2022 8:29:59 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	4.12
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.12**

Work Order Footer

Work Order 55690523 Total	
Parts:	4.12
Labor:	0.00
Labor Hours:	1.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.12**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55728746
Invoice No. 55345 - 55728746

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Check engine light illuminated.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	78,905 - DH

Chronology		
Reported	Jun 28, 2022 11:18:36 PM	Jun 28, 2022 11:18:36 PM
Started	Jun 28, 2022 11:21:00 PM	
Completed	Jul 6, 2022 11:27:00 AM	Jul 6, 2022 11:27:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Check engine light illuminated.

Cause: TBD.

Correction: No check engine light illuminated, no DTCs stored. Road tested vehicle without any issues. Will monitor.
Line 20 COMPLAINT: Check engine light illuminated

Cause: o2 sensor: bank 2 sensor 1

Correction: Removed the sensor the oxygen sensor replaced with a new one clear the code and test drive thebus

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 29-JUN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jun 29, 2022 12:04:53 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jun 29, 2022 12:04:53 AM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jun 29, 2022 12:04:53 AM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jun 29, 2022 12:04:53 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jun 29, 2022 12:04:53 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jun 29, 2022 12:04:53 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55728746
Invoice No. 55345 - 55728746

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Check engine light illuminated.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	78,905 - DH

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Check engine light illuminated.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Jul-22	LK4Z-9F472-C	SENSOR, OXYGEN, UPSTREAM, BANK-TWO, TRANSIT	1	106.04	106.04

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Jun-22	Earl Johnson	0.65	0	0
06-Jul-22	NELSON PIERRE-LOUIS	1.4	0	0
29-Jun-22	Earl Johnson	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	106.04
Labor:	0.00
Labor Hours:	2.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**106.04**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55728746
Invoice No. 55345 - 55728746

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Check engine light illuminated.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	78,905 - DH

Activity Header
Activity: 25 043 EXHAUST SYSTEM
Activity Note: LEFT UPSTREAM O2 SENSOR REPLACEMENT
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jul-22	NELSON PIERRE-LOUIS	2.63	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55728746 Total	
Parts:	106.04
Labor:	0.00
Labor Hours:	4.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**106.04**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55746363
Invoice No. 55345 - 55746363

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Front turn signal bulb.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	79,657 - DH

Chronology		
Reported	Jul 4, 2022 8:57:43 PM	Jul 4, 2022 8:57:43 PM
Started	Jul 4, 2022 9:01:00 PM	
Completed	Jul 4, 2022 10:07:00 PM	Jul 4, 2022 10:07:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: RF turn signal out.

Cause: Defective bulb.

Correction: Remove and replaced RF turn signal bulb.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 04-JUL-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jul 4, 2022 9:38:28 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		EARJOHNSON	Jul 4, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				9:38:28 PM		
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jul 4, 2022 9:38:28 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jul 4, 2022 9:38:28 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jul 4, 2022 9:38:28 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jul 4, 2022 9:38:28 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55746363
Invoice No. 55345 - 55746363

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Front turn signal bulb.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	79,657 - DH

Activity Header
Activity: 15 034/003/000 LAMPS, SIGNAL, PARKING & BACKUP
Activity Note: Front turn signal out.
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Jul-22	3157NA	LAMP, MINIATURE, WEDGE-MOUNT, AMBER SAME AS GE3157NA	1	1.82	1.82

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Jul-22	Earl Johnson	0.6	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	1.82
Labor:	0.00
Labor Hours:	0.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.82**

Work Order Footer

Work Order 55746363 Total	
Parts:	1.82
Labor:	0.00
Labor Hours:	0.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.82**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55721807
Invoice No. 55345 - 55721807

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345 PER DVIR		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	78,517 - DH

Chronology		
Reported	Jun 26, 2022 5:34:52 PM	Jun 26, 2022 5:34:52 PM
Started	Jun 26, 2022 5:39:00 PM	
Completed	Jun 26, 2022 7:30:00 PM	Jun 26, 2022 7:30:00 PM
Down Time		

Work Order Notes

Line 10 Driver stated that Rear ac stop working and hood open indicator light came on the dashboard twice -- Verify the complaints...Rear AC filter was dirty
Cleacn rear ac filter and adjust the hood and test drive vehicle...
under monitor,,,,

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 26-JUN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jun 26, 2022 7:29:46 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jun 26, 2022 7:29:46 PM	No	
4 - Are you wearing the appropriate PPE?	Done		TDELVA	Jun 26, 2022 7:29:46 PM	No	
7 - Have you performed the proper LOTO?	Done		TDELVA	Jun 26, 2022 7:29:46 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jun 26, 2022 7:29:46 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jun 26, 2022 7:29:46 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55721807
Invoice No. 55345 - 55721807

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345 PER DVIR		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	78,517 - DH

Activity Header
Activity: 20 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Jun-22	Delva,Terry	1.77	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55721807 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55704099
Invoice No. 55345 - 55704099

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Check engine light illuminated.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	78,108 - DH

Chronology		
Reported	Jun 19, 2022 12:24:25 PM	Jun 19, 2022 12:24:25 PM
Started	Jun 19, 2022 12:28:00 PM	
Completed	Jun 22, 2022 3:45:00 PM	Jun 22, 2022 3:45:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Check engine light illuminated.

Cause: Faulty o2 sensor (B1S1).

Correction: Noted for repair. Part not in stock. AWP. Line 20 VEHICLE CAME IN FOR O2 SENSOR REPLACE PART # LK4Z-9F472-D. AFTER CHECK UNIT COMPLETE ROAD TEST UNIT WORKING ASDESIGN RETURN UNIT BACK TO WORK

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 19-JUN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jun 19, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				4:36:17 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jun 19, 2022 4:36:17 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jun 19, 2022 4:36:17 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jun 19, 2022 4:36:17 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jun 19, 2022 4:36:17 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jun 19, 2022 4:36:17 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55704099
Invoice No. 55345 - 55704099

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Check engine light illuminated.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	78,108 - DH

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Check engine light illuminated.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Jun-22	Earl Johnson	4.12	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	4.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55704099
Invoice No. 55345 - 55704099

Client Department:
Department: 55345M
Work Order Description
Check engine light illuminated.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 78,108 - DH

Activity Header
Activity: 25 043 EXHAUST SYSTEM
Activity Note: BANK 1 UPSTREAM O2 SENSOR
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Jul-22	LK4Z-9F472-D	SENSOR, OXYGEN, UPSTREAM, BANK-ONE, TRANSIT	1	115.5	115.5

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Jun-22	Junior Hurst	2.63	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	115.50
Labor:	0.00
Labor Hours:	2.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**115.50**

Work Order Footer

Work Order 55704099 Total	
Parts:	115.50
Labor:	0.00
Labor Hours:	6.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**115.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55602255
Invoice No. 55345 - 55602255

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	77,555 - DH

Chronology		
Reported	Jun 9, 2022 12:00:00 AM	Jun 9, 2022 12:00:00 AM
Started	Jun 14, 2022 6:47:00 AM	
Completed	Jun 14, 2022 9:29:00 AM	Jun 14, 2022 9:29:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA

CAUSE:preventive maintenance

CORRECTION:performed PMA Service lube all Pivoting Points completed

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 14-JUN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Jun 14, 2022 6:58:48 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Jun 14, 2022 6:58:48 AM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Jun 14, 2022 6:58:48 AM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Jun 14, 2022 6:58:48 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Jun 14, 2022 6:58:48 AM	No	
11 - Have you successfully completed the Personal	Done		HPIERRE	Jun 14, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				6:58:48 AM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55602255
Invoice No. 55345 - 55602255

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	77,555 - DH

Activity Header
Activity: 10 017 TIRES, TUBES, LINERS & VALVES
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Jun-22	Pierre,Hubert J	1.67	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: HPIERRE Performed on: 14-JUN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
20,800 - INSPECT_High Idle Control	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
21,100 - INSPECT_Parking Brake Operation	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
21,700 - INSPECT_Engine Fault Codes	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
31,000 - SSF (Street Side Front)	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,000 - Engine Inspection	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	190 Degree Fahrenheit		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
32,100 - INSPECT_Intake System	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12 Volt*		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
33,010 - CSF (Curb Side Front)	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
50,400 - LUBE_All Chassis Components	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
50,700 - INSPECT_Tire Condition	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		HPIERRE	Jun 14, 2022 7:11:10 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	18 Inch		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	18 Inch		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
52,100 - INSPECT_Vibration Damper	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
53,600 - INSPECT_Tire Condition	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Jun 14, 2022 7:11:10 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	18 Inch		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	18 Inch		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
60,100 - RECORD_Wheelchair Cycle Count	1234 Cycles		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
62,400 - INSPECT_All Pivot Points	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
62,500 - INSPECT_Cams and Slots	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
62,600 - INSPECT_Rollers	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
62,700 - INSPECT_All Linkages	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		HPIERRE	Jun 14, 2022 7:11:10 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55602255
Invoice No. 55345 - 55602255

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	77,555 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Jun-22	B7449	FILTER, OIL, SPIN-ON SEE P577066	1	3.17	3.17

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Jun-22	Pierre,Hubert J	1.02	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 14-JUN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Jun 14, 2022 6:57:56 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Jun 14, 2022 6:57:56 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Jun 14, 2022 6:57:56 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Jun 14, 2022 6:57:56 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Jun 14, 2022 6:57:56 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Jun 14, 2022 6:57:56 AM	No	
107,000 - FRA Change Primary Fuel Filter	No		HPIERRE	Jun 14, 2022 6:57:56 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Jun 14, 2022 6:57:56 AM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	3.17
	Labor:	0.00
	Labor Hours:	1.02
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**3.17**

Work Order Footer

Work Order 55602255 Total	
Parts:	3.17
Labor:	0.00
Labor Hours:	2.69
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**3.17**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55665504
Invoice No. 55345 - 55665504

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Wheelchair Lift		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	75,974 - DH

Chronology		
Reported	Jun 5, 2022 11:31:39 AM	Jun 5, 2022 11:31:39 AM
Started	Jun 5, 2022 11:33:00 AM	
Completed	Jun 5, 2022 12:58:00 PM	Jun 5, 2022 12:58:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: wheelchair lift storage was damaged

Cause: Damaged

Correction: Remove and replaced damaged pouch storage

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 05-JUN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Jun 5, 2022 11:38:38 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Jun 5, 2022 11:38:38 AM	No	
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Jun 5, 2022 11:38:38 AM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Jun 5, 2022 11:38:38 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Jun 5, 2022 11:38:38 AM	No	
11 - Have you successfully completed the Personal	Done		NPIERRE-	Jun 5, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	11:38:38 AM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55665504
Invoice No. 55345 - 55665504

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Wheelchair Lift		Ford Transit	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	75,974 - DH

Activity Header
Activity: 20 055/023/000 LIFT, WHEELCHAIR, PASSENGER
Activity Note: WheelChair Lift bag
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Jun-22	Q5-8522	POUCH, STORAGE, Q-STRAINT, NYLON	1	28.87	28.87

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jun-22	NELSON PIERRE-LOUIS	1.42	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	28.87
Labor:	0.00
Labor Hours:	1.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**28.87**

Work Order Footer

Work Order 55665504 Total	
Parts:	28.87
Labor:	0.00
Labor Hours:	1.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**28.87**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55621989
Invoice No. 55345 - 55621989

Client Department:
Department: 55345M
Work Order Description
FLAT TIRE
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 73,329 - DH

Chronology		
Reported	May 19, 2022 1:31:00 PM	May 19, 2022 1:31:00 PM
Started	May 19, 2022 1:34:00 PM	
Completed	May 19, 2022 2:45:00 PM	May 19, 2022 2:45:00 PM
Down Time		

Work Order Notes

Line 10 unit came to shop for right rear tire flat removed and repair tire after return vehicle back to work

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 19-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	May 19, 2022 2:12:12 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	May 19, 2022 2:12:12 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	May 19, 2022 2:12:12 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	May 19, 2022 2:12:12 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	May 19, 2022 2:12:12 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	May 19, 2022 2:12:12 PM	No	

Activity Sub Total

Activity 10 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55621989
Invoice No. 55345 - 55621989

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FLAT TIRE		Ford Transit	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	73,329 - DH

Activity Header
Activity: 20 017/001/000 TIRE, PNEUMATIC
Activity Note: FRONT TIRES
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55621989
Invoice No. 55345 - 55621989

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FLAT TIRE		Ford Transit	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	73,329 - DH

Activity Header
Activity: 30 017/001/000 TIRE, PNEUMATIC
Activity Note: REAR FLAT TIRE
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-May-22	Junior Hurst	0.65	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55621989 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 55602232
Invoice No. 55345 - 55602232

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Light Duty		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	72,517 - DH

Chronology		
Reported	May 12, 2022 3:09:03 PM	May 12, 2022 3:09:03 PM
Started	May 12, 2022 3:20:00 PM	
Completed	May 12, 2022 8:10:00 PM	May 12, 2022 8:10:00 PM
Down Time		

Work Order Notes

Line 10 rotate front tires after return vehicle back to work Line 20 change front brakes part # GU2Z-2V001-D Line 30 change rear brakes part LK4Z-2200-J Line 40 change cabing filter part # pA 30000. also wash rear A/C. filter after return vehicle back to work

Activity Header

Activity: 10 001/001 AIR CONDITIONING
Activity Note: cabin need change
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-May-22	PA30000	FILTER, AIR, CABIN SEE AF56065	1	6.5	6.5

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-May-22	Junior Hurst	0.75	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	6.50
Labor:	0.00
Labor Hours:	0.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**6.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 55602232
Invoice No. 55345 - 55602232

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Light Duty		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	72,517 - DH

Activity Header
Activity:20 017/003/001 TIRE, CUSHION W/TREAD
Activity Note: front tires need rotate
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-May-22	Junior Hurst	1.52	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 55602232
Invoice No. 55345 - 55602232

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Light Duty		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	72,517 - DH

Activity Header
Activity: 30 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: Brakes too low need replace
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-May-22	GU2Z-2V001-D	PADS, BRAKE, DISC, FRONT, TRANSIT	1	34.07	34.07

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-May-22	Junior Hurst	1.45	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	34.07
Labor:	0.00
Labor Hours:	1.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**34.07**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 55602232
Invoice No. 55345 - 55602232

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Light Duty		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	72,517 - DH

Activity Header
Activity: 40 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: rear brakes need change
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-May-22	LK4Z-2200-J	PADS, BRAKE, DISC, REAR, TRANSIT	1	76.21	76.21

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-May-22	Junior Hurst	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	76.21
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**76.21**

Work Order Footer

Work Order 55602232 Total	
Parts:	116.78
Labor:	0.00
Labor Hours:	4.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**116.78**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55538882
Invoice No. 55345 - 55538882

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	72,517 - DH

Chronology		
Reported	May 10, 2022 12:00:00 AM	May 10, 2022 12:00:00 AM
Started	May 12, 2022 12:35:00 PM	
Completed	May 12, 2022 3:18:00 PM	May 12, 2022 3:18:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: vehicle came in for service

CAUSE: service by miles

CORRECTION: job complete on service oil filter change part # B 7449

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 12-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	May 12, 2022 12:34:04 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	May 12, 2022 12:34:04 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	May 12, 2022 12:34:04 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	May 12, 2022 12:34:04 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	May 12, 2022 12:34:04 PM	No	
11 - Have you successfully completed the Personal	Done		JUHURST	May 12, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				12:34:04 PM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55538882
Invoice No. 55345 - 55538882

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 72,517 - DH

Activity Header
Activity: 10 010 CHASSIS GROUP
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-May-22	Junior Hurst	2.27	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: JUHURST Performed on: 12-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	May 12, 2022 3:09:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
20,800 - INSPECT_High Idle Control	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	May 12, 2022 3:09:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
32,000 - Engine Inspection	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	May 12, 2022 3:09:28 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	May 12, 2022 3:09:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	May 12, 2022 3:09:28 PM	No	
33,010 - CSF (Curb Side Front)	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	May 12, 2022 3:09:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done	cabin need change	JUHURST	May 12, 2022 3:09:28 PM	Yes	55602232
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
50,400 - LUBE_All Chassis Components	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
50,700 - INSPECT_Tire Condition	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	9 32nds of an inch	front tires need rotate	JUHURST	May 12, 2022 3:09:28 PM	Yes	55602232
51,100 - RECORD_LF-Tire Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	May 12, 2022 3:09:28 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	May 12, 2022 3:09:28 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	May 12, 2022 3:09:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch	Brakes too low need replace	JUHURST	May 12, 2022 3:09:28 PM	Yes	55602232
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch		JUHURST	May 12, 2022 3:09:28 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.269 Inch		JUHURST	May 12, 2022 3:09:28 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.269 Inch		JUHURST	May 12, 2022 3:09:28 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	May 12, 2022 3:09:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	May 12, 2022 3:09:28 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	May 12, 2022 3:09:28 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	May 12, 2022 3:09:28 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	May 12, 2022 3:09:28 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	May 12, 2022 3:09:28 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	9 32nds of an inch		JUHURST	May 12, 2022 3:09:28 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	May 12, 2022 3:09:28 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	May 12, 2022 3:09:28 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch	rear brakes need change	JUHURST	May 12, 2022 3:09:28 PM	Yes	55602232

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch		JUHURST	May 12, 2022 3:09:28 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.34 Inch		JUHURST	May 12, 2022 3:09:28 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.34 Inch		JUHURST	May 12, 2022 3:09:28 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	1001 Cycles		JUHURST	May 12, 2022 3:09:28 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	May 12, 2022 3:09:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
62,400 - INSPECT_All Pivot Points	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
62,500 - INSPECT_Cams and Slots	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
62,600 - INSPECT_Rollers	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
62,700 - INSPECT_All Linkages	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	May 12, 2022 3:09:28 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	May 12, 2022 3:09:28 PM	No	

Activity Sub Total

Activity 10 Sub Total

Parts: 0.00

	Labor:	0.00
	Labor Hours:	2.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55538882
Invoice No. 55345 - 55538882

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	72,517 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-May-22	B7449	FILTER, OIL, SPIN-ON SEE P577066	1	4.07	4.07

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-May-22	Junior Hurst	0.32	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: JUHURST Performed on: 12-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		JUHURST	May 12, 2022 12:39:17 PM	No	
101,000 - FRA Change Oil Filters	Yes		JUHURST	May 12, 2022 12:39:17 PM	No	
102,000 - FRA Drain Engine Oil	Yes		JUHURST	May 12, 2022 12:39:17 PM	No	
103,000 - FRA Check Transmission Fluid	Done		JUHURST	May 12, 2022 12:39:17 PM	No	
104,000 - Lubricate Chassis	Done		JUHURST	May 12, 2022 12:39:17 PM	No	
105,000 - Replace or Clean A/C Filters	Done		JUHURST	May 12, 2022 12:39:17 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		JUHURST	May 12, 2022 12:39:17 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		JUHURST	May 12, 2022 12:39:17 PM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	4.07
	Labor:	0.00
	Labor Hours:	0.32
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**4.07**

Work Order Footer

Work Order 55538882 Total	
Parts:	4.07
Labor:	0.00
Labor Hours:	2.59
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.07**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55586009
Invoice No. 55345 - 55586009

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Check Engine Light		Ford Transit	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	71,504 - DH

Chronology		
Reported	May 6, 2022 10:33:30 PM	May 6, 2022 10:33:30 PM
Started	May 6, 2022 10:43:00 PM	
Completed	May 7, 2022 12:09:00 AM	May 7, 2022 12:09:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Check Engine Light on

Cause: Code P219B -B 2 O2 Sensor imbalance

Correction: Clear Code & Monitoring O2 sensor to see if light came back on. under monitoring.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 06-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	May 6, 2022 10:42:13 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		DARTHURS	May 6, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				10:42:13 PM		
4 - Are you wearing the appropriate PPE?	Done		DARTHURS	May 6, 2022 10:42:13 PM	No	
7 - Have you performed the proper LOTO?	Done		DARTHURS	May 6, 2022 10:42:13 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	May 6, 2022 10:42:13 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	May 6, 2022 10:42:13 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55586009
Invoice No. 55345 - 55586009

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Check Engine Light		Ford Transit	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	71,504 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Check Engine Light
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-May-22	Arthurs,Durvin	1.28	0	0
07-May-22	Arthurs,Durvin	0.15	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55586009 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 55538748
Invoice No. 55345 - 55538748

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Light Duty		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	67,711 - DH

Chronology		
Reported	Apr 20, 2022 4:01:18 PM	Apr 20, 2022 4:01:18 PM
Started	Apr 20, 2022 4:42:00 PM	
Completed	Apr 20, 2022 6:19:00 PM	Apr 20, 2022 6:19:00 PM
Down Time		

Work Order Notes

Line 10 rotate tires from front to rear after return vehicle back to work

Activity Header

Activity: 10 017/003/001 TIRE, CUSHION W/TREAD
Activity Note: rotate tires font to rear
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Apr-22	Junior Hurst	1.6	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55538748 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55460620
Invoice No. 55345 - 55460620

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMB		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	67,711 - DH

Chronology		
Reported	Apr 15, 2022 12:00:00 AM	Apr 15, 2022 12:00:00 AM
Started	Apr 20, 2022 2:22:00 PM	
Completed	Apr 20, 2022 4:39:00 PM	Apr 20, 2022 4:39:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Vehicle came in for service

CAUSE: Service due by Mileage

CORRECTION: ,service job complete oil filter change part # 7449

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 20-APR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Apr 20, 2022 1:14:16 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Apr 20, 2022 1:14:16 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Apr 20, 2022 1:14:16 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Apr 20, 2022 1:14:16 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Apr 20, 2022 1:14:16 PM	No	
11 - Have you successfully completed the Personal	Done		JUHURST	Apr 20, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				1:14:16 PM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55460620
Invoice No. 55345 - 55460620

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMB
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 67,711 - DH

Activity Header
Activity: 10
Activity Note: Light Duty PMI
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Apr-22	B7449	FILTER, OIL, SPIN-ON SEE P577066	1	3.59	3.59

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Apr-22	Junior Hurst	1.27	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: JUHURST Performed on: 20-APR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
20,800 - INSPECT_High Idle Control	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
32,000 - Engine Inspection	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Apr 20, 2022 4:01:51 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Apr 20, 2022 4:01:51 PM	No	
33,010 - CSF (Curb Side Front)	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical	Done		JUHURST	Apr 20, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Inputs/Outputs-SOP M038				4:01:51 PM		
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
50,400 - LUBE_All Chassis Components	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
50,700 - INSPECT_Tire Condition	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	11 32nds of an inch		JUHURST	Apr 20, 2022 4:01:51 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Apr 20, 2022 4:01:51 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	10 32nds of an inch	rotate tires font to rear	JUHURST	Apr 20, 2022 4:01:51 PM	Yes	55538748
51,300 - RECORD_RF-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Apr 20, 2022 4:01:51 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Apr 20, 2022 4:01:51 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Apr 20, 2022 4:01:51 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.299 Inch		JUHURST	Apr 20, 2022 4:01:51 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.299 Inch		JUHURST	Apr 20, 2022 4:01:51 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	11 32nds of an inch		JUHURST	Apr 20, 2022 4:01:51 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	11 32nds of an inch		JUHURST	Apr 20, 2022 4:01:51 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Apr 20, 2022 4:01:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,500 - RECORD_RRI-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Apr 20, 2022 4:01:51 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	11 32nds of an inch		JUHURST	Apr 20, 2022 4:01:51 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	11 32nds of an inch		JUHURST	Apr 20, 2022 4:01:51 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Apr 20, 2022 4:01:51 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Apr 20, 2022 4:01:51 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Apr 20, 2022 4:01:51 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Apr 20, 2022 4:01:51 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.522 Inch		JUHURST	Apr 20, 2022 4:01:51 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.522 Inch		JUHURST	Apr 20, 2022 4:01:51 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	1001 Cycles		JUHURST	Apr 20, 2022 4:01:51 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper	Done		JUHURST	Apr 20, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alignment				4:01:51 PM		
61,000 - INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
62,400 - INSPECT_All Pivot Points	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
62,500 - INSPECT_Cams and Slots	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
62,600 - INSPECT_Rollers	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
62,700 - INSPECT_All Linkages	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	Apr 20, 2022 4:01:51 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	3.59
Labor:	0.00
Labor Hours:	1.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**3.59**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55460620
Invoice No. 55345 - 55460620

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMB		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	67,711 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Apr-22	Junior Hurst	0.38	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: JUHURST Performed on: 20-APR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		JUHURST	Apr 20, 2022 2:43:59 PM	No	
101,000 - FRA Change Oil Filters	Yes		JUHURST	Apr 20, 2022 2:43:59 PM	No	
102,000 - FRA Drain Engine Oil	Yes		JUHURST	Apr 20, 2022 2:43:59 PM	No	
103,000 - FRA Check Transmission Fluid	Done		JUHURST	Apr 20, 2022 2:43:59 PM	No	
104,000 - Lubricate Chassis	Done		JUHURST	Apr 20, 2022 2:43:59 PM	No	
105,000 - Replace or Clean A/C Filters	Done		JUHURST	Apr 20, 2022 2:43:59 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		JUHURST	Apr 20, 2022 2:43:59 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		JUHURST	Apr 20, 2022 2:43:59 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		JUHURST	Apr 20, 2022 2:43:59 PM	No	
201,000 - Service Crankcase Breather	Done		JUHURST	Apr 20, 2022 2:43:59 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	Yes		JUHURST	Apr 20, 2022 2:43:59 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	Yes		JUHURST	Apr 20, 2022 2:43:59 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		JUHURST	Apr 20, 2022 2:43:59 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.38
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55460620 Total	
Parts:	3.59
Labor:	0.00
Labor Hours:	1.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**3.59**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55522923
Invoice No. 55345 - 55522923

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR LOW TIRE PRESSURE
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 67,127 - DH

Chronology		
Reported	Apr 15, 2022 8:21:00 AM	Apr 15, 2022 8:21:00 AM
Started	Apr 15, 2022 11:07:00 AM	
Completed	Apr 15, 2022 12:39:00 PM	Apr 15, 2022 12:39:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: Tire pressure light on

Cause: preventive maintenance

correction: re programming rear passenger side outer tires ,everything ok at this time

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 15-APR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Apr 15, 2022 11:07:44 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Apr 15, 2022 11:07:44 AM	No	
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Apr 15, 2022 11:07:44 AM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Apr 15, 2022 11:07:44 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Apr 15, 2022 11:07:44 AM	No	
11 - Have you successfully completed the Personal	Done		NPIERRE-	Apr 15, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	11:07:44 AM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55522923
Invoice No. 55345 - 55522923

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345 PER DVIR LOW TIRE PRESSURE		Ford Transit	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	67,127 - DH

Activity Header
Activity: 20 017/001/000 TIRE, PNEUMATIC
Activity Note: CHECK TIRES
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Apr-22	NELSON PIERRE-LOUIS	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55522923 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55371401
Invoice No. 55345 - 55371401

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FRONT AND REAR PAINT ISSUES		Ford Transit	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	61,705 - DH

Chronology		
Reported	Feb 22, 2022 9:32:00 AM	Feb 22, 2022 9:32:00 AM
Started		
Completed	Apr 11, 2022 3:03:00 PM	Apr 11, 2022 3:03:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT ; PAINT PEELING OFF FRONT AND REAR BODY OF BUS

CAUSED : DEFECTIVE PAINT JOB

CORRECTION : CONTACT BODY SHOP TO REPAIR PAINT ISSUES.
PAINT AND BODY REPAIRS COMPLETED.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: CVERGARA Performed on: 11-APR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		CVERGARA	Apr 11, 2022 3:03:08 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		CVERGARA	Apr 11, 2022 3:03:08 PM	No	
4 - Are you wearing the appropriate PPE?	Done		CVERGARA	Apr 11, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:03:08 PM		
7 - Have you performed the proper LOTO?	Done		CVERGARA	Apr 11, 2022 3:03:08 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		CVERGARA	Apr 11, 2022 3:03:08 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		CVERGARA	Apr 11, 2022 3:03:08 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55371401
Invoice No. 55345 - 55371401

Client Department:
Department: 55345M
Work Order Description
FRONT AND REAR PAINT ISSUES
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 61,705 - DH

Activity Header
Activity: 30 002 CAB & SHEET METAL
Activity Note: FRONT AND REAR PAINT ISSUES REPAIRED BY EG LABOR (BODYSHOP)
Reason for Repair: 41 Abuse of Equipment
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Mar-22	DSP-OUTSIDESERV	DIRECT PURCHASE FOR OUTSIDE SERV GL 5850	1	962.5	962.5

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	962.50
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**962.50**

Work Order Footer

Work Order 55371401 Total	
Parts:	962.50
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**962.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55475885
Invoice No. 55345 - 55475885

Client Department:
Department: 55345M
Work Order Description
Alarm sounding.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 63,700 - DH

Chronology		
Reported	Mar 29, 2022 5:57:18 PM	Mar 29, 2022 5:57:18 PM
Started	Mar 29, 2022 5:58:00 PM	
Completed	Mar 29, 2022 11:04:00 PM	Mar 29, 2022 11:04:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Alarm sounding.

Cause: TBD.

Correction: Arrived at the location of disabled vehicle and discovered passenger emergency exit window switch out of range. Adjusted window switch .

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 29-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Mar 29, 2022 11:00:19 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Mar 29, 2022 11:00:19 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Mar 29, 2022 11:00:19 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Mar 29, 2022 11:00:19 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Mar 29, 2022 11:00:19 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Mar 29, 2022 11:00:19 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55475885
Invoice No. 55345 - 55475885

Client Department:
Department: 55345M
Work Order Description
Alarm sounding.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 63,700 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Mar-22	Earl Johnson	1.18	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55475885 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55460618
Invoice No. 55345 - 55460618

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Light Duty		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	62,909 - DH

Chronology		
Reported	Mar 24, 2022 8:48:58 AM	Mar 24, 2022 8:48:58 AM
Started	Mar 24, 2022 8:51:00 AM	
Completed	Mar 24, 2022 12:57:00 PM	Mar 24, 2022 12:57:00 PM
Down Time		

Work Order Notes

Line 10 pma follow up need front tire

preventive maintenance

mount and balance 2 front tires completed Line 20 vehicle came in for tire issues on the rear. below specification. remove and replaced four new tires to rear of vehicle size 195/75R16 C Firestone after return vehicle back to work

Activity Header
Activity: 10 017/003/001 TIRE, CUSHION W/TREAD
Activity Note: need front tires
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Mar-22	FR3Z-1A189-C	SENSOR, MONITOR, PRESSURE, TIRE	2	58.53	117.06
24-Mar-22	004708	TIRE, 195/75R16C, BSW, D/8-PLY, CV, TRANSFORCE, FIRESTONE	2	111	222
11-Apr-22	004708	TIRE, 195/75R16C, BSW, D/8-PLY, CV, TRANSFORCE, FIRESTONE	4	111	444

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Mar-22	Pierre,Hubert J	2.47	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	783.06
Labor:	0.00
Labor Hours:	2.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**783.06**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55460618
Invoice No. 55345 - 55460618

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Light Duty		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	62,909 - DH

Activity Header
Activity: 20 015/004 LINKAGE, STEERING
Activity Note: VEHICLE SENT TO ELPEX GOOD YEAR FOR WHEEL ALIGNAMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Mar-22	DSP-OUTSIDESERV	DIRECT PURCHASE FOR OUTSIDE SERV GL 5850	1	89.95	89.95

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	89.95
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**89.95**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55460618
Invoice No. 55345 - 55460618

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FOLLOWUP-FT Light Duty		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	62,909 - DH

Activity Header
Activity: 30 017/001/000 TIRE, PNEUMATIC
Activity Note: REAR TIRES
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55460618 Total	
Parts:	873.01
Labor:	0.00
Labor Hours:	2.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**873.01**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55287121
Invoice No. 55345 - 55287121

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	KIVEY	**Status:**	40 - Closed (40)
Created By:	KIVEY	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	62,909 - DH

Chronology		
Reported	Mar 22, 2022 12:00:00 AM	Mar 22, 2022 12:00:00 AM
Started	Mar 23, 2022 4:12:00 PM	
Completed	Mar 24, 2022 8:50:00 AM	Mar 24, 2022 8:50:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pm

CAUSE:preventing maintenance

CORRECTION: perform pm a complete

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 24-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Mar 24, 2022 8:47:50 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Mar 24, 2022 8:47:50 AM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Mar 24, 2022 8:47:50 AM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Mar 24, 2022 8:47:50 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Mar 24, 2022 8:47:50 AM	No	
11 - Have you successfully completed the Personal	Done		HPIERRE	Mar 24, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				8:47:50 AM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55287121
Invoice No. 55345 - 55287121

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: KIVEY
Created By: KIVEY
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 62,909 - DH

Activity Header
Activity: 10 017 TIRES, TUBES, LINERS & VALVES
Activity Note: Light Duty PMI
Reason for Repair: 09 Rework
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Mar-22	Pierre,Hubert J	0.28	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: HPIERRE Performed on: 24-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		HPIERRE	Mar 24, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:47:07 AM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
20,800 - INSPECT_High Idle Control	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
21,100 - INSPECT_Parking Brake Operation	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
21,700 - INSPECT_Engine Fault Codes	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
31,000 - SSF (Street Side Front)	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
32,000 - Engine Inspection	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	190 Degree Fahrenheit		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
32,100 - INSPECT_Intake System	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12 Volt*		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
33,010 - CSF (Curb Side Front)	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical	Done		HPIERRE	Mar 24, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Inputs/Outputs-SOP M038				8:47:07 AM		
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
50,400 - LUBE_All Chassis Components	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
50,700 - INSPECT_Tire Condition	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	3 32nds of an inch	need front tires	HPIERRE	Mar 24, 2022 8:47:07 AM	Yes	55460618
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	3 32nds of an inch		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	17 Inch		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	17 Inch		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
52,100 - INSPECT_Vibration Damper	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
53,600 - INSPECT_Tire Condition	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	7 32nds of an inch		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Mar 24, 2022 8:47:07 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	7 32nds of an inch		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	18 32nds of an inch		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	17 32nds of an inch		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	17 Inch		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	17 Inch		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
60,100 - RECORD_Wheelchair Cycle Count	1253 Cycles		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		HPIERRE	Mar 24, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:47:07 AM		
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
62,400 - INSPECT_All Pivot Points	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
62,500 - INSPECT_Cams and Slots	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
62,600 - INSPECT_Rollers	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
62,700 - INSPECT_All Linkages	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		HPIERRE	Mar 24, 2022 8:47:07 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55287121
Invoice No. 55345 - 55287121

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	KIVEY	**Status:**	40 - Closed (40)
Created By:	KIVEY	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	62,909 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Mar-22	B7449	FILTER, OIL, SPIN-ON SEE P577066	1	2.73	2.73

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Mar-22	Pierre,Hubert J	0.85	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 24-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Mar 24, 2022 8:48:36 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Mar 24, 2022 8:48:36 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Mar 24, 2022 8:48:36 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Mar 24, 2022 8:48:36 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Mar 24, 2022 8:48:36 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Mar 24, 2022 8:48:36 AM	No	
107,000 - FRA Change Primary Fuel Filter	No		HPIERRE	Mar 24, 2022 8:48:36 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Mar 24, 2022 8:48:36 AM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	2.73
	Labor:	0.00
	Labor Hours:	0.85
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**2.73**

Work Order Footer

Work Order 55287121 Total	
Parts:	2.73
Labor:	0.00
Labor Hours:	1.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.73**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54403876
Invoice No. 55345 - 54403876

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
QCC FLEET INSPECTION		Ford Transit	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	62,646 -

Chronology		
Reported	Feb 21, 2022 11:38:35 AM	Feb 21, 2022 11:38:35 AM
Started		
Completed	Mar 22, 2022 3:16:00 PM	Mar 22, 2022 3:16:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: QCC INSPECTION

CAUSE :PREVENTIVE MAINTENANCE

CORRECTION: QCC INSPECTION PERFORMED

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: CVERGARA Performed on: 22-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		CVERGARA	Mar 22, 2022 3:05:31 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		CVERGARA	Mar 22, 2022 3:05:31 PM	No	
4 - Are you wearing the appropriate PPE?	Done		CVERGARA	Mar 22, 2022 3:05:31 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
7 - Have you performed the proper LOTO?	Done		CVERGARA	Mar 22, 2022 3:05:31 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		CVERGARA	Mar 22, 2022 3:05:31 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		CVERGARA	Mar 22, 2022 3:05:31 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54403876
Invoice No. 55345 - 54403876

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
QCC FLEET INSPECTION		Ford Transit	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	62,646 -

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: QCC FLEET INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54403876 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55310900
Invoice No. 55345 - 55310900

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
REAR AC SYSTEM		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	59,671 - DH

Chronology		
Reported	Feb 1, 2022 9:33:24 AM	Feb 1, 2022 9:33:24 AM
Started	Feb 1, 2022 9:37:00 AM	
Completed	Feb 4, 2022 8:47:00 AM	Feb 4, 2022 8:47:00 AM
Down Time		

Work Order Notes

Line 10 Complaint: driver stated that Rear AC not working

Cause: Intermittently external temperature sensor fail

Correction: Could not duolicate issue at this time AC working fine

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 01-FEB-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Feb 1, 2022 2:54:44 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Feb 1, 2022 2:54:44 PM	No	
4 - Are you wearing the appropriate PPE?	Done		TDELVA	Feb 1, 2022 2:54:44 PM	No	
7 - Have you performed the proper LOTO?	Done		TDELVA	Feb 1, 2022 2:54:44 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Feb 1, 2022 2:54:44 PM	No	
11 - Have you successfully completed the Personal	Done		TDELVA	Feb 1, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				2:54:44 PM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55310900
Invoice No. 55345 - 55310900

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
REAR AC SYSTEM		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	59,671 - DH

Activity Header
Activity: 20 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: REAR AC DIAG
Reason for Repair:
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Feb-22	Delva,Terry	5.22	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	5.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55310900 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	5.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55211153
Invoice No. 55345 - 55211153

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	58,251 - DH

Chronology		
Reported	Jan 21, 2022 12:00:00 AM	Jan 21, 2022 12:00:00 AM
Started	Jan 24, 2022 7:03:00 AM	
Completed	Jan 24, 2022 2:13:57 PM	Jan 24, 2022 2:13:57 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA service

CAUSE: preventive maintenance

CORRECTION: preformed pma service and lube front tires rotation

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 24-JAN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Jan 24, 2022 9:17:57 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Jan 24, 2022 9:17:57 AM	No	
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Jan 24, 2022 9:17:57 AM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Jan 24, 2022 9:17:57 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Jan 24, 2022 9:17:57 AM	No	
11 - Have you successfully completed the Personal	Done		NPIERRE-	Jan 24, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	9:17:57 AM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55211153
Invoice No. 55345 - 55211153

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 58,251 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Jan-22	NELSON PIERRE-LOUIS	2.87	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS Performed on: 24-JAN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-	Jan 24, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	9:58:44 AM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
20,800 - INSPECT_High Idle Control	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
21,100 - INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
21,700 - INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
31,000 - SSF (Street Side Front)	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
32,000 - Engine Inspection	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	0 Degree Fahrenheit		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
32,100 - INSPECT_Intake System	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	13.1 Volt*		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
33,010 - CSF (Curb Side Front)	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical	Done		NPIERRE-	Jan 24, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Inputs/Outputs-SOP M038			LOUIS	9:58:44 AM		
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
50,400 - LUBE_All Chassis Components	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
50,700 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	67 Pounds per Square Inch		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	66 Pounds per Square Inch		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	25.5 Inch		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	25.5 Inch		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
52,100 - INSPECT_Vibration Damper	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
53,600 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,500 - RECORD_RRI-Air Pressure (psi)	66 Pounds per Square Inch		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	67 Pounds per Square Inch		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	67 Pounds per Square Inch		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	17.5 Inch		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	17.5 Inch		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
60,100 - RECORD_Wheelchair Cycle Count	100 Cycles		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		NPIERRE-	Jan 24, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	9:58:44 AM		
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
62,400 - INSPECT_All Pivot Points	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
62,500 - INSPECT_Cams and Slots	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
62,600 - INSPECT_Rollers	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
62,700 - INSPECT_All Linkages	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	Jan 24, 2022 9:58:44 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55211153
Invoice No. 55345 - 55211153

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	58,251 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Jan-22	B7449	FILTER, OIL, SPIN-ON SEE P577066	1	2.73	2.73

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: NPIERRE-LOUIS Performed on: 24-JAN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Jan 24, 2022 9:18:40 AM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Jan 24, 2022 9:18:40 AM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Jan 24, 2022 9:18:40 AM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Jan 24, 2022 9:18:40 AM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Jan 24, 2022 9:18:40 AM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Jan 24, 2022 9:18:40 AM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		NPIERRE-LOUIS	Jan 24, 2022 9:18:40 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Jan 24, 2022 9:18:40 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	2.73
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**2.73**

Work Order Footer

Work Order 55211153 Total	
Parts:	2.73
Labor:	0.00
Labor Hours:	2.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.73**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55233621
Invoice No. 55345 - 55233621

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Rear AC malfunction.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	54,893 - DH

Chronology		
Reported	Jan 4, 2022 6:36:21 PM	Jan 4, 2022 6:36:21 PM
Started	Jan 4, 2022 6:42:00 PM	
Completed	Jan 4, 2022 7:44:00 PM	Jan 4, 2022 7:44:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear AC malfunction.

Cause: Interior ATS was out of range.

Correction: Relocated temperature sensor to correct temperature range.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 04-JAN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jan 4, 2022 7:39:58 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		EARJOHNSON	Jan 4, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				7:39:58 PM		
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jan 4, 2022 7:39:58 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jan 4, 2022 7:39:58 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jan 4, 2022 7:39:58 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jan 4, 2022 7:39:58 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55233621
Invoice No. 55345 - 55233621

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Rear AC malfunction.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	54,893 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear AC malfunction.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Jan-22	Earl Johnson	0.87	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55233621 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55230085
Invoice No. 55345 - 55230085

Client Department:
Department: 55345M
Work Order Description
Second passenger window rattling.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 54,813 - DH

Chronology		
Reported	Jan 3, 2022 4:22:45 PM	Jan 3, 2022 4:22:45 PM
Started	Jan 3, 2022 4:25:00 PM	
Completed	Jan 3, 2022 9:08:00 PM	Jan 3, 2022 9:08:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Passenger window rattling.

Cause: Defect.

Correction: Applied soft contact tape in between the window frame and chassis.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 03-JAN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jan 3, 2022 5:05:51 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		EARJOHNSON	Jan 3, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				5:05:51 PM		
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jan 3, 2022 5:05:51 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jan 3, 2022 5:05:51 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jan 3, 2022 5:05:51 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jan 3, 2022 5:05:51 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55230085
Invoice No. 55345 - 55230085

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Second passenger window rattling.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	54,813 - DH

Activity Header
Activity: 15 002 CAB & SHEET METAL
Activity Note: Passenger window rattling.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jan-22	Earl Johnson	0.65	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55230085 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55117573
Invoice No. 55345 - 55117573

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMC		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	53,412 - DH

Chronology		
Reported	Dec 20, 2021 12:00:00 AM	Dec 20, 2021 12:00:00 AM
Started	Dec 23, 2021 4:29:00 PM	
Completed	Dec 24, 2021 12:10:00 AM	Dec 24, 2021 12:10:00 AM
Down Time		

Work Order Notes

Line 10 PMC
Service
Perform PMC service
Oil filter B7449 qty1
Engine oil 5w20 qty 6 qts
Clean AC filter

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 23-DEC-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Dec 23, 2021 4:29:43 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Dec 23, 2021 4:29:43 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RGASPARD	Dec 23, 2021 4:29:43 PM	No	
7 - Have you performed the proper LOTO?	Done		RGASPARD	Dec 23, 2021 4:29:43 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Dec 23, 2021 4:29:43 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Dec 23, 2021 4:29:43 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55117573
Invoice No. 55345 - 55117573

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMC		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	53,412 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Dec-21	Gaspard,Ronald	1.78	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 23-DEC-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Dec 23, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				5:25:05 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
20,800 - INSPECT_High Idle Control	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	Dec 23, 2021 5:25:05 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Dec 23, 2021 5:25:05 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.24 Volt*		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
33,010 - CSF (Curb Side Front)	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical	Done		RGASPARD	Dec 23, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Inputs/Outputs-SOP M038				5:25:05 PM		
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
50,400 - LUBE_All Chassis Components	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.229 Inch		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.229 Inch		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Dec 23, 2021 5:25:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,500 - RECORD_RRI-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.799 Inch		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.799 Inch		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	102 Cycles		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Dec 23, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				5:25:05 PM		
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Dec 23, 2021 5:25:05 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55117573
Invoice No. 55345 - 55117573

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMC		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	53,412 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Dec-21	B7449	FILTER, OIL, SPIN-ON SEE P577066	1	2.73	2.73

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Dec-21	Gaspard,Ronald	0.9	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: RGASPARD Performed on: 23-DEC-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Dec 23, 2021 6:20:51 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Dec 23, 2021 6:20:51 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Dec 23, 2021 6:20:51 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Dec 23, 2021 6:20:51 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Dec 23, 2021 6:20:51 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Dec 23, 2021 6:20:51 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	na	RGASPARD	Dec 23, 2021 6:20:51 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Dec 23, 2021 6:20:51 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Dec 23, 2021 6:20:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
201,000 - Service Crankcase Breather	Done		RGASPARD	Dec 23, 2021 6:20:51 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Dec 23, 2021 6:20:51 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Dec 23, 2021 6:20:51 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Dec 23, 2021 6:20:51 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		RGASPARD	Dec 23, 2021 6:20:51 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		RGASPARD	Dec 23, 2021 6:20:51 PM	No	
302,000 - Check Toe-In and Record Reading	-	na	RGASPARD	Dec 23, 2021 6:20:51 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	na	RGASPARD	Dec 23, 2021 6:20:51 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		RGASPARD	Dec 23, 2021 6:20:51 PM	No	
305,000 - FRA Change Differential Fluid	No		RGASPARD	Dec 23, 2021 6:20:51 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	2.73
Labor:	0.00
Labor Hours:	0.90
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.73**

Work Order Footer

Work Order 55117573 Total	
Parts:	2.73
Labor:	0.00
Labor Hours:	2.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.73**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55200941
Invoice No. 55345 - 55200941

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Wheelchair Lift		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	53,079 - DH

Chronology		
Reported	Dec 20, 2021 1:07:10 PM	Dec 20, 2021 1:07:10 PM
Started	Dec 20, 2021 12:00:00 AM	
Completed	Dec 20, 2021 1:23:00 PM	Dec 20, 2021 1:23:00 PM
Down Time		

Work Order Notes

Line 10 Complaint. Lift is not working

Cause. Bad leak by the rear hydraulic high pressure hose.

Correction. Removed and replaced hose with used good one, tested, all okay at this time.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 20-DEC-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Dec 20, 2021 1:17:06 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Dec 20, 2021 1:17:06 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Dec 20, 2021 1:17:06 PM	No	
7 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Dec 20, 2021 1:17:06 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Dec 20, 2021 1:17:06 PM	No	
11 - Have you successfully completed the	Done		RAURODRIGUEZ	Dec 20, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				1:17:06 PM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55200941
Invoice No. 55345 - 55200941

Client Department:
Department: 55345M
Work Order Description
Wheelchair Lift
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 53,079 - DH

Activity Header
Activity: 20 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: WheelChair Lift
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Dec-21	Rodriguez,Raul	3.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55200941 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55180660
Invoice No. 55345 - 55180660

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Vehicle making popping sound.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	52,115 - DH

Chronology		
Reported	Dec 14, 2021 6:30:47 PM	Dec 14, 2021 6:30:47 PM
Started	Dec 14, 2021 6:32:00 PM	
Completed	Dec 14, 2021 6:34:00 PM	Dec 14, 2021 6:34:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:***VOID***

Cause:

Correction:

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 14-DEC-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Dec 14, 2021 6:33:54 PM	No	
2 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Dec 14, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				6:33:54 PM		
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Dec 14, 2021 6:33:54 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Dec 14, 2021 6:33:54 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Dec 14, 2021 6:33:54 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Dec 14, 2021 6:33:54 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55180660
Invoice No. 55345 - 55180660

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Vehicle making popping sound.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	52,115 - DH

Activity Header
Activity: 15 010 CHASSIS GROUP
Activity Note: Vehicle making popping sound.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Dec-21	Earl Johnson	0.03	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55180660 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55029134
Invoice No. 55345 - 55029134

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	48,761 - DH

Chronology		
Reported	Nov 19, 2021 12:00:00 AM	Nov 19, 2021 12:00:00 AM
Started	Nov 23, 2021 12:31:00 PM	
Completed	Nov 23, 2021 1:58:00 PM	Nov 23, 2021 1:58:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION:

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 23-NOV-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Nov 23, 2021 12:32:30 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Nov 23, 2021 12:32:30 PM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Nov 23, 2021 12:32:30 PM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Nov 23, 2021 12:32:30 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Nov 23, 2021 12:32:30 PM	No	
11 - Have you successfully completed the Personal	Done		HPIERRE	Nov 23, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				12:32:30 PM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55029134
Invoice No. 55345 - 55029134

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	48,761 - DH

Activity Header
Activity: 10
Activity Note: Light Duty PMI
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: HPIERRE Performed on: 23-NOV-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
20,800 - INSPECT_High Idle Control	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
31,000 - SSF (Street Side Front)	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
32,000 - Engine Inspection	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,010 - INSPECT_Hood, Springs and Props	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	190 Degree Fahrenheit		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
32,100 - INSPECT_Intake System	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12 Volt*		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
33,010 - CSF (Curb Side Front)	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
50,400 - LUBE_All Chassis Components	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
50,700 - INSPECT_Tire Condition	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	24 Inch		HPIERRE	Nov 23, 2021 1:58:11 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	24 Inch		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
52,100 - INSPECT_Vibration Damper	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
53,600 - INSPECT_Tire Condition	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Nov 23, 2021 1:58:11 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	22 Inch		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	22 Inch		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	2231 Cycles		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
62,400 - INSPECT_All Pivot Points	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
62,500 - INSPECT_Cams and Slots	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
62,600 - INSPECT_Rollers	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
62,700 - INSPECT_All Linkages	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		HPIERRE	Nov 23, 2021 1:58:11 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55029134
Invoice No. 55345 - 55029134

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	48,761 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Nov-21	B7449	FILTER, OIL, SPIN-ON SEE P577066	1	2.73	2.73

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Nov-21	Pierre,Hubert J	1.38	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 23-NOV-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Nov 23, 2021 12:31:59 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Nov 23, 2021 12:31:59 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Nov 23, 2021 12:31:59 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Nov 23, 2021 12:31:59 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Nov 23, 2021 12:31:59 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Nov 23, 2021 12:31:59 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		HPIERRE	Nov 23, 2021 12:31:59 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Nov 23, 2021 12:31:59 PM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	2.73
	Labor:	0.00
	Labor Hours:	1.38
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**2.73**

Work Order Footer

Work Order 55029134 Total	
Parts:	2.73
Labor:	0.00
Labor Hours:	1.38
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.73**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55098397
Invoice No. 55345 - 55098397

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Rear AC malfunction.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	47,579 - DH

Chronology		
Reported	Nov 16, 2021 7:34:27 PM	Nov 16, 2021 7:34:27 PM
Started	Nov 16, 2021 7:36:00 PM	
Completed	Nov 16, 2021 11:11:00 PM	Nov 16, 2021 11:11:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear AC malfunction.

Cause: TBD.

Correction: Rear AC works properly and blows cold. Let vehicle¿s AC run for an hour without any issues. Could not duplicate issue. Will monitor.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 16-NOV-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Nov 16, 2021 8:24:59 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Nov 16, 2021 8:24:59 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Nov 16, 2021 8:24:59 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Nov 16, 2021 8:24:59 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Nov 16, 2021 8:24:59 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Nov 16, 2021 8:24:59 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55098397
Invoice No. 55345 - 55098397

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Rear AC malfunction.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	47,579 - DH

Activity Header
Activity: 15 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear AC malfunction.
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 51 Inoperative
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Nov-21	Earl Johnson	0.8	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55098397 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55040152
Invoice No. 55345 - 55040152

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
RD CALL FLAT TIRE		Ford Transit	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	44,495 - DH

Chronology		
Reported	Oct 28, 2021 3:03:00 PM	Oct 28, 2021 3:03:00 PM
Started	Oct 28, 2021 4:11:00 PM	
Completed	Oct 28, 2021 5:35:00 PM	Oct 28, 2021 5:35:00 PM
Down Time		

Work Order Notes

Line 10 Went on road call. For this vehicle replace tire and return to shop and replace two new tires to front of vehicle check unit complete and return unit back to work

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 28-OCT-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Oct 28, 2021 5:34:23 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Oct 28, 2021 5:34:23 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Oct 28, 2021 5:34:23 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Oct 28, 2021 5:34:23 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Oct 28, 2021 5:34:23 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Oct 28, 2021 5:34:23 PM	No	

Activity Sub Total

Activity 10 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55040152
Invoice No. 55345 - 55040152

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
RD CALL FLAT TIRE		Ford Transit	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	44,495 - DH

Activity Header
Activity: 20 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Oct-21	004708	TIRE, 195/75R16C, BSW, D/8-PLY, CV, TRANSFORCE, FIRESTONE	2	104.63	209.26

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Oct-21	Junior Hurst	1.4	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	209.26
Labor:	0.00
Labor Hours:	1.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**209.26**

Work Order Footer

Work Order 55040152 Total	
Parts:	209.26
Labor:	0.00
Labor Hours:	1.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**209.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54925195
Invoice No. 55345 - 54925195

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	43,946 - DH

Chronology		
Reported	Oct 22, 2021 12:00:00 AM	Oct 22, 2021 12:00:00 AM
Started	Oct 25, 2021 12:47:00 PM	
Completed	Oct 25, 2021 2:22:00 PM	Oct 25, 2021 2:22:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Vehicle came in for service

CAUSE: service by miles

CORRECTION: Job complete replace new oil filter. Also wash rear A/C filter after return vehicle back to working line

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Oct-21	Junior Hurst	0.03	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 25-OCT-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Oct 25, 2021 12:48:35 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Oct 25, 2021 12:48:35 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Oct 25, 2021 12:48:35 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Oct 25, 2021 12:48:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Oct 25, 2021 12:48:35 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Oct 25, 2021 12:48:35 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54925195
Invoice No. 55345 - 54925195

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	43,946 - DH

Activity Header
Activity: 10
Activity Note: Light Duty PMI
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Oct-21	Junior Hurst	0.58	0	0
25-Oct-21	Junior Hurst	0.83	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: JUHURST Performed on: 25-OCT-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
20,800 - INSPECT_High Idle Control	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
32,000 - Engine Inspection	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Oct 25, 2021 1:35:07 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Oct 25, 2021 1:35:07 PM	No	
33,010 - CSF (Curb Side Front)	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
50,400 - LUBE_All Chassis Components	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
50,700 - INSPECT_Tire Condition	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Oct 25, 2021 1:35:07 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	62 Pounds per Square Inch		JUHURST	Oct 25, 2021 1:35:07 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Oct 25, 2021 1:35:07 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	62 Pounds per Square Inch		JUHURST	Oct 25, 2021 1:35:07 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	12 32nds of an inch		JUHURST	Oct 25, 2021 1:35:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	12 32nds of an inch		JUHURST	Oct 25, 2021 1:35:07 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.2299 Inch		JUHURST	Oct 25, 2021 1:35:07 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.2299 Inch		JUHURST	Oct 25, 2021 1:35:07 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Oct 25, 2021 1:35:07 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Oct 25, 2021 1:35:07 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Oct 25, 2021 1:35:07 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Oct 25, 2021 1:35:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	9 32nds of an inch		JUHURST	Oct 25, 2021 1:35:07 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Oct 25, 2021 1:35:07 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Oct 25, 2021 1:35:07 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	64 Pounds per Square Inch		JUHURST	Oct 25, 2021 1:35:07 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	12 32nds of an inch		JUHURST	Oct 25, 2021 1:35:07 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	12 32nds of an inch		JUHURST	Oct 25, 2021 1:35:07 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	1.299 Inch		JUHURST	Oct 25, 2021 1:35:07 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	1.299 Inch		JUHURST	Oct 25, 2021 1:35:07 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	100 Cycles		JUHURST	Oct 25, 2021 1:35:07 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
62,400 - INSPECT_All Pivot Points	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
62,500 - INSPECT_Cams and Slots	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
62,600 - INSPECT_Rollers	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
62,700 - INSPECT_All Linkages	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	Oct 25, 2021 1:35:07 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.41
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54925195
Invoice No. 55345 - 54925195

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 43,946 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Oct-21	B7449	FILTER, OIL, SPIN-ON SEE P577066	1	2.05	2.05

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Oct-21	Junior Hurst	0.1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: JUHURST Performed on: 25-OCT-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		JUHURST	Oct 25, 2021 2:17:56 PM	No	
101,000 - FRA Change Oil Filters	Yes		JUHURST	Oct 25, 2021 2:17:56 PM	No	
102,000 - FRA Drain Engine Oil	Yes		JUHURST	Oct 25, 2021 2:17:56 PM	No	
103,000 - FRA Check Transmission Fluid	Done		JUHURST	Oct 25, 2021 2:17:56 PM	No	
104,000 - Lubricate Chassis	Done		JUHURST	Oct 25, 2021 2:17:56 PM	No	
105,000 - Replace or Clean A/C Filters	Done		JUHURST	Oct 25, 2021 2:17:56 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		JUHURST	Oct 25, 2021 2:17:56 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		JUHURST	Oct 25, 2021 2:17:56 PM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	2.05
	Labor:	0.00
	Labor Hours:	0.10
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**2.05**

Work Order Footer

Work Order 54925195 Total	
Parts:	2.05
Labor:	0.00
Labor Hours:	1.54
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.05**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55016161
Invoice No. 55345 - 55016161

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Brakes front and rear		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	43,526 - DH

Chronology		
Reported	Oct 22, 2021 3:36:21 PM	Oct 22, 2021 3:36:21 PM
Started	Oct 22, 2021 3:40:00 PM	
Completed	Oct 22, 2021 6:39:00 PM	Oct 22, 2021 6:39:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Front and rear too low

Cause: worn down

Correction: Removed and replace new brakes front part # 1774. / rear part # LK4Z-2200-J Return vehicle back to work

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 22-OCT-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Oct 22, 2021 5:54:30 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Oct 22, 2021 5:54:30 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Oct 22, 2021 5:54:30 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Oct 22, 2021 5:54:30 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Oct 22, 2021 5:54:30 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Oct 22, 2021 5:54:30 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55016161
Invoice No. 55345 - 55016161

Client Department:
Department: 55345M
Work Order Description
Brakes front and rear
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 43,526 - DH

Activity Header
Activity: 15 013 BRAKES
Activity Note: Brakes
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Oct-21	LK4Z-2200-J	PADS, BRAKE, DISC, REAR, TRANSIT	1	93.31	93.31
22-Oct-21	FLD1774	PADS, BRAKE, FRONT, CHEV	1	45.54	45.54

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Oct-21	Junior Hurst	2.97	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	138.85
Labor:	0.00
Labor Hours:	2.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**138.85**

Work Order Footer

Work Order 55016161 Total	
Parts:	138.85
Labor:	0.00
Labor Hours:	2.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**138.85**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54937470
Invoice No. 55345 - 54937470

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
REAR AC SYSTEM		Ford Transit	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	39,918 - DH

Chronology		
Reported	Sep 27, 2021 2:08:00 PM	Sep 27, 2021 2:08:00 PM
Started		
Completed	Sep 28, 2021 10:51:00 AM	Sep 28, 2021 10:51:00 AM
Down Time		

Work Order Notes

Line 10 C: rear a/c not working

C: check system found it has a blockage

C: evacuate and recharge system replaced filter, retest system ok at this time. Vehicle is under warranty

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 28-SEP-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Sep 28, 2021 8:14:49 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Sep 28, 2021 8:14:49 AM	No	
4 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Sep 28, 2021 8:14:49 AM	No	
7 - Have you performed the proper LOTO?	Done		JAPEREZ	Sep 28, 2021 8:14:49 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Sep 28, 2021 8:14:49 AM	No	
11 - Have you successfully completed the Personal	Done		JAPEREZ	Sep 28, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				8:14:49 AM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54937470
Invoice No. 55345 - 54937470

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
REAR AC SYSTEM		Ford Transit	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	39,918 - DH

Activity Header
Activity: 20 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear a/c not working
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54937470 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54932849
Invoice No. 55345 - 54932849

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Rear A/C		Ford Transit	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	39,672 - DH

Chronology		
Reported	Sep 26, 2021 12:47:59 PM	Sep 26, 2021 12:47:59 PM
Started	Sep 26, 2021 12:50:00 PM	
Completed	Sep 26, 2021 6:12:00 PM	Sep 26, 2021 6:12:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear A/C

Cause: Compressor Cut Out When Flashing H/A code high pressure Switch fault found one condenser fan bad

Correction: Swap Condenser Fan From Bus 20116 /Replace On (2076) Evacuate /Recharge A/C Low Side goes in to Vacuum possible TXV valve .

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 26-SEP-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Sep 26, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				6:12:28 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Sep 26, 2021 6:12:28 PM	No	
4 - Are you wearing the appropriate PPE?	Done		DARTHURS	Sep 26, 2021 6:12:28 PM	No	
7 - Have you performed the proper LOTO?	Done		DARTHURS	Sep 26, 2021 6:12:28 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Sep 26, 2021 6:12:28 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Sep 26, 2021 6:12:28 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54932849
Invoice No. 55345 - 54932849

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Rear A/C		Ford Transit	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	39,672 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Check Rear A/C
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Sep-21	8050015	FAN, CONDENSER, A/C, 12"	1	59.06	59.06

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Sep-21	Arthurs,Durvin	3.65	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	59.06
Labor:	0.00
Labor Hours:	3.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**59.06**

Work Order Footer

Work Order 54932849 Total	
Parts:	59.06
Labor:	0.00
Labor Hours:	3.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**59.06**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54928481
Invoice No. 55345 - 54928481

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Rear AC malfunction.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	39,365 - DH

Chronology		
Reported	Sep 23, 2021 10:50:50 PM	Sep 23, 2021 10:50:50 PM
Started	Sep 23, 2021 10:51:00 PM	
Completed	Sep 24, 2021 12:05:00 AM	Sep 24, 2021 12:05:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear AC malfunction.

Cause: TBD.

Correction: Let vehicle idle 1.5 hrs. with rear AC running, no issue encountered. Front and rear AC systems blow cold. Could not duplicate issue. Will monitor.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 24-SEP-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Sep 24, 2021 12:04:39 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Sep 24, 2021 12:04:39 AM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Sep 24, 2021 12:04:39 AM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Sep 24, 2021 12:04:39 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Sep 24, 2021 12:04:39 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Sep 24, 2021 12:04:39 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54928481
Invoice No. 55345 - 54928481

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Rear AC malfunction.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	39,365 - DH

Activity Header
Activity: 15 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear AC malfunction.
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 51 Inoperative
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Sep-21	Earl Johnson	0.05	0	0
23-Sep-21	Earl Johnson	1.15	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54928481 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54850924
Invoice No. 55345 - 54850924

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMB		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	39,244 - DH

Chronology		
Reported	Sep 22, 2021 12:00:00 AM	Sep 22, 2021 12:00:00 AM
Started	Sep 22, 2021 11:56:00 AM	
Completed	Sep 23, 2021 5:57:00 AM	Sep 23, 2021 5:57:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA

CAUSE: preventive maintenance

CORRECTION: Performed service PMA service completed

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 22-SEP-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Sep 22, 2021 11:57:56 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Sep 22, 2021 11:57:56 AM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Sep 22, 2021 11:57:56 AM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Sep 22, 2021 11:57:56 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Sep 22, 2021 11:57:56 AM	No	
11 - Have you successfully completed the Personal	Done		HPIERRE	Sep 22, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				11:57:56 AM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54850924
Invoice No. 55345 - 54850924

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMB		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	39,244 - DH

Activity Header
Activity: 10
Activity Note: Light Duty PMI
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: HPIERRE Performed on: 23-SEP-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
20,800 - INSPECT_High Idle Control	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
21,100 - INSPECT_Parking Brake Operation	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
21,700 - INSPECT_Engine Fault Codes	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
31,000 - SSF (Street Side Front)	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
32,000 - Engine Inspection	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,010 - INSPECT_Hood, Springs and Props	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	190 Degree Fahrenheit	N/A	HPIERRE	Sep 23, 2021 5:56:50 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
32,100 - INSPECT_Intake System	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12 Volt*		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
33,010 - CSF (Curb Side Front)	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
50,400 - LUBE_All Chassis Components	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
50,700 - INSPECT_Tire Condition	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	26 Inch		HPIERRE	Sep 23, 2021 5:56:50 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	26 Inch		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
52,100 - INSPECT_Vibration Damper	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
53,600 - INSPECT_Tire Condition	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	20 32nds of an inch		HPIERRE	Sep 23, 2021 5:56:50 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	20 Inch		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	20 Inch		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
60,100 - RECORD_Wheelchair Cycle Count	2221 Cycles		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
62,400 - INSPECT_All Pivot Points	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
62,500 - INSPECT_Cams and Slots	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
62,600 - INSPECT_Rollers	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
62,700 - INSPECT_All Linkages	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		HPIERRE	Sep 23, 2021 5:56:50 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54850924
Invoice No. 55345 - 54850924

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMB
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 39,244 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Sep-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.98	1.98

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Sep-21	Pierre,Hubert J	2.27	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: HPIERRE Performed on: 22-SEP-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Sep 22, 2021 11:59:09 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Sep 22, 2021 11:59:09 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Sep 22, 2021 11:59:09 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Sep 22, 2021 11:59:09 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Sep 22, 2021 11:59:09 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Sep 22, 2021 11:59:09 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Sep 22, 2021 11:59:09 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Sep 22, 2021 11:59:09 AM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		HPIERRE	Sep 22, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:59:09 AM		
201,000 - Service Crankcase Breather	Done		HPIERRE	Sep 22, 2021 11:59:09 AM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		HPIERRE	Sep 22, 2021 11:59:09 AM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		HPIERRE	Sep 22, 2021 11:59:09 AM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		HPIERRE	Sep 22, 2021 11:59:09 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.98
Labor:	0.00
Labor Hours:	2.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.98**

Work Order Footer

Work Order 54850924 Total	
Parts:	1.98
Labor:	0.00
Labor Hours:	2.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.98**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54772773
Invoice No. 55345 - 54772773

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	34,881 - DH

Chronology		
Reported	Aug 27, 2021 12:00:00 AM	Aug 27, 2021 12:00:00 AM
Started	Aug 27, 2021 8:55:00 PM	
Completed	Aug 28, 2021 12:06:00 AM	Aug 28, 2021 12:06:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE:Service

CORRECTION:Perform pmA Service
Oil filter B7449 qty1
Engine oil 10w30 qty 6 qts

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 27-AUG-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Aug 27, 2021 8:55:44 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Aug 27, 2021 8:55:44 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Aug 27, 2021 8:55:44 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Aug 27, 2021 8:55:44 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Aug 27, 2021 8:55:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Aug 27, 2021 8:55:44 PM	No	
20 - Miles			RGASPARD	Aug 27, 2021 8:55:44 PM	No	
30 - Kilometers			RGASPARD	Aug 27, 2021 8:55:44 PM	No	
40 - Hours			RGASPARD	Aug 27, 2021 8:55:44 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54772773
Invoice No. 55345 - 54772773

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 34,881 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Aug-21	Gaspard,Ronald	1.52	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 27-AUG-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Aug 27, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:32:59 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
20,800 - INSPECT_High Idle Control	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	Aug 27, 2021 9:32:59 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Aug 27, 2021 9:32:59 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.24 Volt*		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
33,010 - CSF (Curb Side Front)	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
40,400 - INSPECT_Camera Systems, Filter,	Done		RGASPARD	Aug 27, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Electrical Inputs/Outputs-SOP M038				9:32:59 PM		
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
50,400 - LUBE_All Chassis Components	Done	na	RGASPARD	Aug 27, 2021 9:32:59 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.229 Inch		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.229 Inch		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	2 32nds of an inch		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	3 32nds of an inch		RGASPARD	Aug 27, 2021 9:32:59 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	2 32nds of an inch	needs rear tires	RGASPARD	Aug 27, 2021 9:32:59 PM	Yes	54850860
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	2 32nds of an inch		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.799 Inch		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.799 Inch		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	100 Cycles		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Aug 27, 2021 9:32:59 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00

	Labor Hours:	1.52
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 54850860
Invoice No. 55345 - 54850860

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP------> Mount And Balance 4 Tires
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 34,881 - DH

Chronology		
Reported	Aug 27, 2021 9:57:45 PM	Aug 27, 2021 9:57:45 PM
Started	Aug 27, 2021 9:59:00 PM	
Completed	Aug 28, 2021 12:06:00 AM	Aug 28, 2021 12:06:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========
To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.
==========

Complaint:needs 4 rear tires

Cause: low spec

Correction:4 new tires mount and balance
Torque wheels 140 lbs second torque 140 lbs
Part number 004708 qty4

Activity Header
Activity: 10 017/009/016 VALVE, PROTECTION, PRESSURE, TIRE
Activity Note: needs rear tires
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Aug-21	004708	TIRE, 195/75R16C, BSW, D/8-PLY, CV, TRANSFORCE, FIRESTONE	4	102.65	410.6

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Aug-21	Gaspard,Ronald	1.33	0	0
28-Aug-21	Gaspard,Ronald	0.08	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	410.60
Labor:	0.00
Labor Hours:	1.41
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**410.60**

Work Order Footer

Work Order 54850860 Total	
Parts:	410.60
Labor:	0.00
Labor Hours:	1.41
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**410.60**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54772773
Invoice No. 55345 - 54772773

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 34,881 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Aug-21	Gaspard,Ronald	0.22	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 27-AUG-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Aug 27, 2021 10:27:23 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Aug 27, 2021 10:27:23 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Aug 27, 2021 10:27:23 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Aug 27, 2021 10:27:23 PM	No	
104,000 - Lubricate Chassis	Done		RGASPARD	Aug 27, 2021 10:27:23 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Aug 27, 2021 10:27:23 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Aug 27, 2021 10:27:23 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Aug 27, 2021 10:27:23 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.22
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 54772773 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.74
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54797859
Invoice No. 55345 - 54797859

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Back up alarm not audible.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	31,747 - DH

Chronology		
Reported	Aug 9, 2021 11:30:48 PM	Aug 9, 2021 11:30:48 PM
Started	Aug 9, 2021 11:33:00 PM	
Completed	Aug 10, 2021 12:22:00 AM	Aug 10, 2021 12:22:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Back up alarm not working.

Cause: Defective.

Correction: Remove and replaced back up alarm.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 09-AUG-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Aug 9, 2021 11:56:28 PM	No	
2 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Aug 9, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				11:56:28 PM		
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Aug 9, 2021 11:56:28 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Aug 9, 2021 11:56:28 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Aug 9, 2021 11:56:28 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Aug 9, 2021 11:56:28 PM	No	
20 - Miles			EARJOHNSON	Aug 9, 2021 11:56:28 PM	No	
30 - Kilometers			EARJOHNSON	Aug 9, 2021 11:56:28 PM	No	
40 - Hours			EARJOHNSON	Aug 9, 2021 11:56:28 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54797859
Invoice No. 55345 - 54797859

Client Department:
Department: 55345M
Work Order Description
Back up alarm not audible.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 31,747 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Back up alarm not audible.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Aug-21	80833	ALARM, BACK-UP	1	37.73	37.73

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Aug-21	Earl Johnson	0.43	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	37.73
Labor:	0.00
Labor Hours:	0.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**37.73**

Work Order Footer

Work Order 54797859 Total	
Parts:	37.73
Labor:	0.00
Labor Hours:	0.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**37.73**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54781291
Invoice No. 55345 - 54781291

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Back up alarm malfunction.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	30,707 - DH

Chronology		
Reported	Aug 3, 2021 8:59:37 PM	Aug 3, 2021 8:59:37 PM
Started	Aug 3, 2021 9:01:00 PM	
Completed	Aug 4, 2021 12:20:00 AM	Aug 4, 2021 12:20:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Back up alarm stopped working.

Cause: Water Damaged.

Correction: Removed alarm and blew out water. Reinstalled and reconnected power. Works properly.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 03-AUG-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Aug 3, 2021 9:31:07 PM	No	
2 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Aug 3, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				9:31:07 PM		
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Aug 3, 2021 9:31:07 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Aug 3, 2021 9:31:07 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Aug 3, 2021 9:31:07 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Aug 3, 2021 9:31:07 PM	No	
20 - Miles			EARJOHNSON	Aug 3, 2021 9:31:07 PM	No	
30 - Kilometers			EARJOHNSON	Aug 3, 2021 9:31:07 PM	No	
40 - Hours			EARJOHNSON	Aug 3, 2021 9:31:07 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54781291
Invoice No. 55345 - 54781291

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Back up alarm malfunction.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	30,707 - DH

Activity Header
Activity: 15 036 DEVICES, INFORMATION, SUPPLEMENTAL
Activity Note: Back up alarm malfunction.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Aug-21	Earl Johnson	1.63	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54781291 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54623685
Invoice No. 55345 - 54623685

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	30,428 - DH

Chronology		
Reported	Jul 30, 2021 12:00:00 AM	Jul 30, 2021 12:00:00 AM
Started	Jul 30, 2021 1:12:00 PM	
Completed	Jul 30, 2021 4:11:00 PM	Jul 30, 2021 4:11:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PMA Service

CAUSE: Service Due by Mileage.

CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check brakes .
Parts # B7449 Qty (1)
Oil 10W30 Qty (6.0) Qt

Activity Header

Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Jul-21	Junior Hurst	1.82	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 30-JUL-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Jul 30, 2021 1:13:51 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Jul 30, 2021 1:13:51 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Jul 30, 2021 1:13:51 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Jul 30, 2021 1:13:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Jul 30, 2021 1:13:51 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Jul 30, 2021 1:13:51 PM	No	
20 - Miles			JUHURST	Jul 30, 2021 1:13:51 PM	No	
30 - Kilometers			JUHURST	Jul 30, 2021 1:13:51 PM	No	
40 - Hours			JUHURST	Jul 30, 2021 1:13:51 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.82
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54623685
Invoice No. 55345 - 54623685

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	30,428 - DH

Activity Header
Activity: 10
Activity Note: Light Duty PMI
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Aug-21	P7398	FILTER, OIL	1	1.41	1.41

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Jul-21	Junior Hurst	1.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: JUHURST Performed on: 30-JUL-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
20,800 - INSPECT_High Idle Control	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
32,000 - Engine Inspection	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Jul 30, 2021 3:34:42 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Jul 30, 2021 3:34:42 PM	No	
33,010 - CSF (Curb Side Front)	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
50,400 - LUBE_All Chassis Components	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
50,700 - INSPECT_Tire Condition	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Jul 30, 2021 3:34:42 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	62 Pounds per Square Inch		JUHURST	Jul 30, 2021 3:34:42 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Jul 30, 2021 3:34:42 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	62 Pounds per Square Inch		JUHURST	Jul 30, 2021 3:34:42 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Jul 30, 2021 3:34:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Jul 30, 2021 3:34:42 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.2299 Inch		JUHURST	Jul 30, 2021 3:34:42 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.2299 Inch		JUHURST	Jul 30, 2021 3:34:42 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	4 32nds of an inch		JUHURST	Jul 30, 2021 3:34:42 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Jul 30, 2021 3:34:42 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	67 Pounds per Square Inch		JUHURST	Jul 30, 2021 3:34:42 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	67 Pounds per Square Inch		JUHURST	Jul 30, 2021 3:34:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	5 32nds of an inch		JUHURST	Jul 30, 2021 3:34:42 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	5 32nds of an inch		JUHURST	Jul 30, 2021 3:34:42 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Jul 30, 2021 3:34:42 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Jul 30, 2021 3:34:42 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Jul 30, 2021 3:34:42 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Jul 30, 2021 3:34:42 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.722 Inch		JUHURST	Jul 30, 2021 3:34:42 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.722 Inch		JUHURST	Jul 30, 2021 3:34:42 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	100 Cycles		JUHURST	Jul 30, 2021 3:34:42 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
62,400 - INSPECT_All Pivot Points	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
62,500 - INSPECT_Cams and Slots	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
62,600 - INSPECT_Rollers	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
62,700 - INSPECT_All Linkages	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	Jul 30, 2021 3:34:42 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.41
Labor:	0.00
Labor Hours:	1.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.41**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54623685
Invoice No. 55345 - 54623685

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	30,428 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: JUHURST Performed on: 30-JUL-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		JUHURST	Jul 30, 2021 4:10:18 PM	No	
101,000 - FRA Change Oil Filters	Yes		JUHURST	Jul 30, 2021 4:10:18 PM	No	
102,000 - FRA Drain Engine Oil	Yes		JUHURST	Jul 30, 2021 4:10:18 PM	No	
103,000 - FRA Check Transmission Fluid	Done		JUHURST	Jul 30, 2021 4:10:18 PM	No	
104,000 - Lubricate Chassis	Done		JUHURST	Jul 30, 2021 4:10:18 PM	No	
105,000 - Replace or Clean A/C Filters	Done		JUHURST	Jul 30, 2021 4:10:18 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		JUHURST	Jul 30, 2021 4:10:18 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		JUHURST	Jul 30, 2021 4:10:18 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00

	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 54623685 Total	
Parts:	1.41
Labor:	0.00
Labor Hours:	2.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.41**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54689806
Invoice No. 55345 - 54689806

Client Department:
Department: 55345M
Work Order Description
BRAKES SISTEM
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 26,230 - DH

Chronology		
Reported	Jun 29, 2021 11:11:00 AM	Jun 29, 2021 11:11:00 AM
Started	Jun 29, 2021 7:04:00 PM	
Completed	Jun 29, 2021 10:28:00 PM	Jun 29, 2021 10:28:00 PM
Down Time		

Work Order Notes

Line 10 Removed and replaced rear brake pads and sensor.(LK4Z-2200-J) Qty 1.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 29-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jun 29, 2021 9:30:41 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jun 29, 2021 9:30:41 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jun 29, 2021 9:30:41 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jun 29, 2021 9:30:41 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jun 29, 2021 9:30:41 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jun 29, 2021 9:30:41 PM	No	
20 - Miles			EARJOHNSON	Jun 29, 2021 9:30:41 PM	No	
30 - Kilometers			EARJOHNSON	Jun 29, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:30:41 PM		
40 - Hours			EARJOHNSON	Jun 29, 2021 9:30:41 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54689806
Invoice No. 55345 - 54689806

Client Department:
Department: 55345M
Work Order Description
BRAKES SISTEM
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 26,230 - DH

Activity Header
Activity: 20 013/000/000 BRAKES
Activity Note: Rear Brake pads worn.
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Jul-21	LK4Z-17757-B	BUMPER, FRONT, TRANSIT	1	216.84	216.84

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Jun-21	Earl Johnson	2.43	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	216.84
Labor:	0.00
Labor Hours:	2.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**216.84**

Work Order Footer

Work Order 54689806 Total	
Parts:	216.84
Labor:	0.00
Labor Hours:	2.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**216.84**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54656432
Invoice No. 55345 - 54656432

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
WC lift malfunction.		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	26,229 - DH

Chronology		
Reported	Jun 16, 2021 4:20:19 PM	Jun 16, 2021 4:20:19 PM
Started	Jun 16, 2021 4:22:00 PM	
Completed	Jun 16, 2021 6:03:00 PM	Jun 16, 2021 6:03:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction:

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jun-21	Earl Johnson	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 16-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jun 16, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				5:59:48 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jun 16, 2021 5:59:48 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jun 16, 2021 5:59:48 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jun 16, 2021 5:59:48 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jun 16, 2021 5:59:48 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jun 16, 2021 5:59:48 PM	No	
20 - Miles			EARJOHNSON	Jun 16, 2021 5:59:48 PM	No	
30 - Kilometers			EARJOHNSON	Jun 16, 2021 5:59:48 PM	No	
40 - Hours			EARJOHNSON	Jun 16, 2021 5:59:48 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54656432
Invoice No. 55345 - 54656432

Client Department:
Department: 55345M
Work Order Description
WC lift malfunction.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 26,229 - DH

Activity Header
Activity: 15 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: WC lift malfunction.
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jun-21	Earl Johnson	1.6	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54656432 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54543599
Invoice No. 55345 - 54543599

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMC		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	26,051 - DH

Chronology		
Reported	Jun 4, 2021 12:00:00 AM	Jun 4, 2021 12:00:00 AM
Started	Jun 4, 2021 11:04:00 PM	
Completed	Jun 5, 2021 12:39:00 AM	Jun 5, 2021 12:39:00 AM
Down Time		

Work Order Notes

Line 10 PMC
Service
Perform PMC
Oil filter B7449 qty1
Engine oil 10w30 qty 6 qts
2 new tires torque wheels 140 lbs second torque 140 lbs

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 04-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Jun 4, 2021 11:03:58 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Jun 4, 2021 11:03:58 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Jun 4, 2021 11:03:58 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Jun 4, 2021 11:03:58 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Jun 4, 2021 11:03:58 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jun 4, 2021 11:03:58 PM	No	
20 - Miles			RGASPARD	Jun 4, 2021 11:03:58 PM	No	
30 - Kilometers			RGASPARD	Jun 4, 2021 11:03:58 PM	No	
40 - Hours			RGASPARD	Jun 4, 2021 11:03:58 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54543599
Invoice No. 55345 - 54543599

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMC		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	26,051 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Jun-21	B7449	FILTER, OIL, SPIN-ON SEE P577066	1	2.8	2.8

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jun-21	Gaspard,Ronald	0.42	0	0
04-Jun-21	Gaspard,Ronald	0.93	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 05-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
20,800 - INSPECT_High Idle Control	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
21,100 - INSPECT_Parking Brake Operation	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
21,700 - INSPECT_Engine Fault Codes	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
32,000 - Engine Inspection	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	Jun 5, 2021 12:01:51 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Jun 5, 2021 12:01:51 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.24 Volt*		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
33,010 - CSF (Curb Side Front)	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		RGASPARD	Jun 5, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression				12:01:51 AM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
50,400 - LUBE_All Chassis Components	Done	na	RGASPARD	Jun 5, 2021 12:01:51 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	3 32nds of an inch		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	2 32nds of an inch		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.229 Inch		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.229 Inch		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Jun 5, 2021 12:01:51 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	3 32nds of an inch		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	4 32nds of an inch		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	4 32nds of an inch		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.799 Inch		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.799 Inch		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
60,100 - RECORD_Wheelchair Cycle Count	1974 Cycles		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper	Done		RGASPARD	Jun 5, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alignment				12:01:51 AM		
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Jun 5, 2021 12:01:51 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	2.80
Labor:	0.00
Labor Hours:	1.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54543599
Invoice No. 55345 - 54543599

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMC
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 26,051 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jun-21	Gaspard,Ronald	0.2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: RGASPARD Performed on: 05-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jun 5, 2021 12:27:15 AM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jun 5, 2021 12:27:15 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jun 5, 2021 12:27:15 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jun 5, 2021 12:27:15 AM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Jun 5, 2021 12:27:15 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jun 5, 2021 12:27:15 AM	No	
107,000 - FRA Change Primary Fuel Filter	-	na	RGASPARD	Jun 5, 2021 12:27:15 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jun 5, 2021 12:27:15 AM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Jun 5, 2021 12:27:15 AM	No	
201,000 - Service Crankcase Breather	Done		RGASPARD	Jun 5, 2021 12:27:15 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Jun 5, 2021 12:27:15 AM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Jun 5, 2021 12:27:15 AM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Jun 5, 2021 12:27:15 AM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		RGASPARD	Jun 5, 2021 12:27:15 AM	No	
301,000 - Check and Lubricate Door Linkages	Done		RGASPARD	Jun 5, 2021 12:27:15 AM	No	
302,000 - Check Toe-In and Record Reading	-	na	RGASPARD	Jun 5, 2021 12:27:15 AM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	na	RGASPARD	Jun 5, 2021 12:27:15 AM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		RGASPARD	Jun 5, 2021 12:27:15 AM	No	
305,000 - FRA Change Differential Fluid	No		RGASPARD	Jun 5, 2021 12:27:15 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54543599 Total	
Parts:	2.80
Labor:	0.00
Labor Hours:	1.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54546609
Invoice No. 55345 - 54546609

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FIRST TRANSIT - NORTH AMERICA - CONSPICUITY		Ford Transit	
Requested By:	DGALLAGHER	**Status:**	40 - Closed (40)
Created By:	DGALLAGHER	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	21,922 - DH

Chronology		
Reported	May 11, 2021 2:26:43 PM	May 11, 2021 2:26:43 PM
Started		
Completed	May 23, 2021 12:56:00 PM	May 23, 2021 12:56:00 PM
Down Time		

Work Order Notes

Line 10 Existing tapes¿ No issue

Activity Header
Activity: 10 999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 23-MAY-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	May 23, 2021 12:55:27 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	May 23, 2021 12:55:27 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	May 23, 2021 12:55:27 PM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	May 23, 2021 12:55:27 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	May 23, 2021 12:55:27 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	May 23, 2021 12:55:27 PM	No	
20 - Miles			TDELVA	May 23, 2021 12:55:27 PM	No	
30 - Kilometers			TDELVA	May 23, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:55:27 PM		
40 - Hours			TDELVA	May 23, 2021 12:55:27 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54546609
Invoice No. 55345 - 54546609

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
FIRST TRANSIT - NORTH AMERICA - CONSPICUITY		Ford Transit	
Requested By:	DGALLAGHER	**Status:**	40 - Closed (40)
Created By:	DGALLAGHER	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	21,922 - DH

Activity Header
Activity:20 053/005/018 TAPE, REFLECTIVE
Activity Note: FIRST TRANSIT - NORTH AMERICA - CONSPICUITY
Reason for Repair: IC Internal Campaign
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: FIRST TRANSIT - NORTH AMERICA - CONSPICUITY
Task: FIRST TRANSIT - NORTH AMERICA - CONSPICUITY Performed by: TDELVA Performed on: 23-MAY-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Inspect Conspicuity tape:			TDELVA	May 23, 2021 12:55:43 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54546609 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54470116
Invoice No. 55345 - 54470116

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	21,699 - DH

Chronology		
Reported	May 10, 2021 12:00:00 AM	May 10, 2021 12:00:00 AM
Started	May 10, 2021 8:44:00 PM	
Completed	May 11, 2021 12:27:00 AM	May 11, 2021 12:27:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PmA

CAUSE: Service

CORRECTION: perform PmA Service
Oil filter B7449 qty 1
Engine oil 10w30 qty 6 qts

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 10-MAY-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	May 10, 2021 8:44:53 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	May 10, 2021 8:44:53 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	May 10, 2021 8:44:53 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	May 10, 2021 8:44:53 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	May 10, 2021 8:44:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	May 10, 2021 8:44:53 PM	No	
20 - Miles			RGASPARD	May 10, 2021 8:44:53 PM	No	
30 - Kilometers			RGASPARD	May 10, 2021 8:44:53 PM	No	
40 - Hours			RGASPARD	May 10, 2021 8:44:53 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54470116
Invoice No. 55345 - 54470116

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	21,699 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-May-21	B7449	FILTER, OIL, SPIN-ON SEE P577066	1	2.8	2.8

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-May-21	Gaspard,Ronald	1.3	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 10-MAY-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
20,800 - INSPECT_High Idle Control	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	May 10, 2021 9:49:51 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	May 10, 2021 9:49:51 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.24 Volt*		RGASPARD	May 10, 2021 9:49:51 PM	No	
33,010 - CSF (Curb Side Front)	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical	Done		RGASPARD	May 10, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Inputs/Outputs-SOP M038				9:49:51 PM		
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
50,400 - LUBE_All Chassis Components	Done	na	RGASPARD	May 10, 2021 9:49:51 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	May 10, 2021 9:49:51 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	May 10, 2021 9:49:51 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	May 10, 2021 9:49:51 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	May 10, 2021 9:49:51 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	May 10, 2021 9:49:51 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	May 10, 2021 9:49:51 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.229 Inch		RGASPARD	May 10, 2021 9:49:51 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.229 Inch		RGASPARD	May 10, 2021 9:49:51 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	May 10, 2021 9:49:51 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	May 10, 2021 9:49:51 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	May 10, 2021 9:49:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,500 - RECORD_RRI-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	May 10, 2021 9:49:51 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	May 10, 2021 9:49:51 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	May 10, 2021 9:49:51 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	May 10, 2021 9:49:51 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	May 10, 2021 9:49:51 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch		RGASPARD	May 10, 2021 9:49:51 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch		RGASPARD	May 10, 2021 9:49:51 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.799 Inch		RGASPARD	May 10, 2021 9:49:51 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.799 Inch		RGASPARD	May 10, 2021 9:49:51 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	1097 Cycles		RGASPARD	May 10, 2021 9:49:51 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	May 10, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:49:51 PM		
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	May 10, 2021 9:49:51 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	2.80
Labor:	0.00
Labor Hours:	1.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54470116
Invoice No. 55345 - 54470116

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 21,699 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-May-21	Gaspard,Ronald	0.47	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 10-MAY-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	May 10, 2021 10:03:21 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	May 10, 2021 10:03:21 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	May 10, 2021 10:03:21 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	May 10, 2021 10:03:21 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	May 10, 2021 10:03:21 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	May 10, 2021 10:03:21 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	May 10, 2021 10:03:21 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	May 10, 2021 10:03:21 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.47
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 54470116 Total	
Parts:	2.80
Labor:	0.00
Labor Hours:	1.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54382774
Invoice No. 55345 - 54382774

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	17,234 - DH

Chronology		
Reported	Apr 14, 2021 12:00:00 AM	Apr 14, 2021 12:00:00 AM
Started	Apr 14, 2021 8:31:00 PM	
Completed	Apr 14, 2021 10:58:00 PM	Apr 14, 2021 10:58:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PMA Service

CAUSE: Service Due by Mileage.

CORRECTION: Change Oil & Filter. Lube all Pivoting Points.Check Brakes. Clean A/C Filter.
Parts # B 7449 Qty (1)
Oil 10W30. Qty (6.0) Qt

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 14-APR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Apr 14, 2021 10:06:31 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Apr 14, 2021 10:06:31 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Apr 14, 2021 10:06:31 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Apr 14, 2021 10:06:31 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Apr 14, 2021 10:06:31 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 14, 2021 10:06:31 PM	No	
20 - Miles			DARTHURS	Apr 14, 2021 10:06:31 PM	No	
30 - Kilometers			DARTHURS	Apr 14, 2021 10:06:31 PM	No	
40 - Hours			DARTHURS	Apr 14, 2021 10:06:31 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54382774
Invoice No. 55345 - 54382774

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 17,234 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Apr-21	Arthurs,Durvin	1.55	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: DARTHURS Performed on: 14-APR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		DARTHURS	Apr 14, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:04:11 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
20,800 - INSPECT_High Idle Control	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
31,000 - SSF (Street Side Front)	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
32,000 - Engine Inspection	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	NA	DARTHURS	Apr 14, 2021 10:04:11 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	DARTHURS	Apr 14, 2021 10:04:11 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
32,100 - INSPECT_Intake System	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.06 Volt*		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
33,010 - CSF (Curb Side Front)	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical	Done		DARTHURS	Apr 14, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Inputs/Outputs-SOP M038				10:04:11 PM		
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
50,400 - LUBE_All Chassis Components	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
50,700 - INSPECT_Tire Condition	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	67 Pounds per Square Inch		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	7 32nds of an inch		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	67 Pounds per Square Inch		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.229 Inch		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.229 Inch		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
52,100 - INSPECT_Vibration Damper	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
53,600 - INSPECT_Tire Condition	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	62 Pounds per Square Inch		DARTHURS	Apr 14, 2021 10:04:11 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,500 - RECORD_RRI-Air Pressure (psi)	62 Pounds per Square Inch		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	6 32nds of an inch		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	62 Pounds per Square Inch		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	62 Pounds per Square Inch		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.799 Inch		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.799 Inch		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	100 Cycles		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		DARTHURS	Apr 14, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:04:11 PM		
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
62,400 - INSPECT_All Pivot Points	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
62,500 - INSPECT_Cams and Slots	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
62,600 - INSPECT_Rollers	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
62,700 - INSPECT_All Linkages	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		DARTHURS	Apr 14, 2021 10:04:11 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54382774
Invoice No. 55345 - 54382774

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 17,234 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Apr-21	B7449	FILTER, OIL, SPIN-ON SEE P577066	1	2.8	2.8

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Apr-21	Arthurs,Durvin	0.33	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 14-APR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Apr 14, 2021 10:05:42 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Apr 14, 2021 10:05:42 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Apr 14, 2021 10:05:42 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Apr 14, 2021 10:05:42 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Apr 14, 2021 10:05:42 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Apr 14, 2021 10:05:42 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Apr 14, 2021 10:05:42 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Apr 14, 2021 10:05:42 PM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	2.80
	Labor:	0.00
	Labor Hours:	0.33
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**2.80**

Work Order Footer

Work Order 54382774 Total	
Parts:	2.80
Labor:	0.00
Labor Hours:	1.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54059799
Invoice No. 55345 - 54059799

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
QCC FLEET INSPECTION		Ford Transit	
Requested By:	SPACE	**Status:**	40 - Closed (40)
Created By:	SPACE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	13,928 -

Chronology		
Reported	Mar 23, 2021 8:14:13 AM	Mar 23, 2021 8:14:13 AM
Started		
Completed	Mar 23, 2021 8:50:00 AM	Mar 23, 2021 8:50:00 AM
Down Time		

Work Order Notes

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: CVERGARA Performed on: 23-MAR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		CVERGARA	Mar 23, 2021 8:49:57 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		CVERGARA	Mar 23, 2021 8:49:57 AM	No	
3 - Are you wearing the appropriate PPE?	Done		CVERGARA	Mar 23, 2021 8:49:57 AM	No	
4 - Have you performed the proper LOTO?	Done		CVERGARA	Mar 23, 2021 8:49:57 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		CVERGARA	Mar 23, 2021 8:49:57 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		CVERGARA	Mar 23, 2021 8:49:57 AM	No	
20 - Miles			CVERGARA	Mar 23, 2021 8:49:57 AM	No	
30 - Kilometers			CVERGARA	Mar 23, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:49:57 AM		
40 - Hours			CVERGARA	Mar 23, 2021 8:49:57 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54059799
Invoice No. 55345 - 54059799

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
QCC FLEET INSPECTION		Ford Transit	
Requested By:	SPACE	**Status:**	40 - Closed (40)
Created By:	SPACE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	13,928 -

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: QCC FLEET INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54059799 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54308068
Invoice No. 55345 - 54308068

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMB		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	12,790 - DH

Chronology		
Reported	Mar 15, 2021 12:52:04 PM	Mar 15, 2021 12:52:04 PM
Started	Mar 15, 2021 8:42:00 PM	
Completed	Mar 15, 2021 11:56:00 PM	Mar 15, 2021 11:56:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMB Service

CAUSE: Service Due by Mileage.

CORRECTION: Change Oil & Filter.Lube all Pivoting. Check brakes. Check A/C Filter
Parts # R84502MP Qty (1)
Oil 10W30 Qty (6.0) Qt

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 15-MAR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Mar 15, 2021 10:19:26 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Mar 15, 2021 10:19:26 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Mar 15, 2021 10:19:26 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Mar 15, 2021 10:19:26 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Mar 15, 2021 10:19:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Mar 15, 2021 10:19:26 PM	No	
20 - Miles			DARTHURS	Mar 15, 2021 10:19:26 PM	No	
30 - Kilometers			DARTHURS	Mar 15, 2021 10:19:26 PM	No	
40 - Hours			DARTHURS	Mar 15, 2021 10:19:26 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54308068
Invoice No. 55345 - 54308068

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMB		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	12,790 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Mar-21	B7449	FILTER, OIL, SPIN-ON SEE P577066	1	3.18	3.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Mar-21	Arthurs,Durvin	1.67	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: DARTHURS Performed on: 15-MAR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
20,800 - INSPECT_High Idle Control	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
31,000 - SSF (Street Side Front)	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
32,000 - Engine Inspection	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	DARTHURS	Mar 15, 2021 10:17:10 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
32,100 - INSPECT_Intake System	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.08 Volt*		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
33,010 - CSF (Curb Side Front)	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical	Done		DARTHURS	Mar 15, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Inputs/Outputs-SOP M038				10:17:10 PM		
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
50,400 - LUBE_All Chassis Components	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
50,700 - INSPECT_Tire Condition	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	67 Pounds per Square Inch		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	9 32nds of an inch		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	67 Pounds per Square Inch		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.229 Inch		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.229 Inch		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
52,100 - INSPECT_Vibration Damper	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
53,600 - INSPECT_Tire Condition	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	62 Pounds per Square Inch		DARTHURS	Mar 15, 2021 10:17:10 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,500 - RECORD_RRI-Air Pressure (psi)	62 Pounds per Square Inch		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.799 Inch		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.799 Inch		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	102 Cycles		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		DARTHURS	Mar 15, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:17:10 PM		
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
62,400 - INSPECT_All Pivot Points	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
62,500 - INSPECT_Cams and Slots	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
62,600 - INSPECT_Rollers	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
62,700 - INSPECT_All Linkages	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		DARTHURS	Mar 15, 2021 10:17:10 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	3.18
Labor:	0.00
Labor Hours:	1.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**3.18**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54308068
Invoice No. 55345 - 54308068

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMB		Ford Transit	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	12,790 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Mar-21	Arthurs,Durvin	0.37	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: DARTHURS Performed on: 15-MAR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Mar 15, 2021 10:18:49 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Mar 15, 2021 10:18:49 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Mar 15, 2021 10:18:49 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Mar 15, 2021 10:18:49 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Mar 15, 2021 10:18:49 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Mar 15, 2021 10:18:49 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Mar 15, 2021 10:18:49 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Mar 15, 2021 10:18:49 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	Mar 15, 2021 10:18:49 PM	No	
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Mar 15, 2021 10:18:49 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	No		DARTHURS	Mar 15, 2021 10:18:49 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Mar 15, 2021 10:18:49 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Mar 15, 2021 10:18:49 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54308068 Total	
Parts:	3.18
Labor:	0.00
Labor Hours:	2.04
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**3.18**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54378478
Invoice No. 55345 - 54378478

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
MDT bracket		Ford Transit	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	12,399 - DH

Chronology		
Reported	Mar 14, 2021 6:26:40 PM	Mar 14, 2021 6:26:40 PM
Started	Mar 14, 2021 6:29:00 PM	
Completed	Mar 14, 2021 9:44:00 PM	Mar 14, 2021 9:44:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: MDT bracket loose.

Cause: Screws not secured.

Correction: Tightened MDT bracket screws.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 14-MAR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Mar 14, 2021 9:08:08 PM	No	
2 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Mar 14, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				9:08:08 PM		
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Mar 14, 2021 9:08:08 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Mar 14, 2021 9:08:08 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Mar 14, 2021 9:08:08 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Mar 14, 2021 9:08:08 PM	No	
20 - Miles			EARJOHNSON	Mar 14, 2021 9:08:08 PM	No	
30 - Kilometers			EARJOHNSON	Mar 14, 2021 9:08:08 PM	No	
40 - Hours			EARJOHNSON	Mar 14, 2021 9:08:08 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54378478
Invoice No. 55345 - 54378478

Client Department:
Department: 55345M
Work Order Description
MDT bracket
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 12,399 - DH

Activity Header
Activity: 15 036 DEVICES, INFORMATION, SUPPLEMENTAL
Activity Note: MDT bracket
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Mar-21	Earl Johnson	1.8	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54378478 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54171214
Invoice No. 55345 - 54171214

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	8,603 - DH

Chronology		
Reported	Feb 17, 2021 12:00:00 AM	Feb 17, 2021 12:00:00 AM
Started	Feb 17, 2021 9:19:00 PM	
Completed	Feb 18, 2021 12:44:00 AM	Feb 18, 2021 12:44:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA

CAUSE: Service

CORRECTION:Perform PMA Service
Oil filter B7449 qty1
Engine oil 10w30 qty 6 Qts

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 17-FEB-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Feb 17, 2021 9:19:50 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Feb 17, 2021 9:19:50 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Feb 17, 2021 9:19:50 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Feb 17, 2021 9:19:50 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Feb 17, 2021 9:19:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Feb 17, 2021 9:19:50 PM	No	
20 - Miles			RGASPARD	Feb 17, 2021 9:19:50 PM	No	
30 - Kilometers			RGASPARD	Feb 17, 2021 9:19:50 PM	No	
40 - Hours			RGASPARD	Feb 17, 2021 9:19:50 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54171214
Invoice No. 55345 - 54171214

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	8,603 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Feb-21	B7449	FILTER, OIL, SPIN-ON SEE P577066	1	2.79	2.79

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Feb-21	Gaspard,Ronald	1.8	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 17-FEB-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
20,800 - INSPECT_High Idle Control	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	NA	RGASPARD	Feb 17, 2021 11:04:34 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	RGASPARD	Feb 17, 2021 11:04:34 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.24 Volt*		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
33,010 - CSF (Curb Side Front)	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical	Done		RGASPARD	Feb 17, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Inputs/Outputs-SOP M038				11:04:34 PM		
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
50,400 - LUBE_All Chassis Components	Done	NA	RGASPARD	Feb 17, 2021 11:04:34 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.229 Inch		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.229 Inch		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Feb 17, 2021 11:04:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,500 - RECORD_RRI-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.799 Inch		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.799 Inch		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	186 Cycles		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Feb 17, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:04:34 PM		
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Feb 17, 2021 11:04:34 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	2.79
Labor:	0.00
Labor Hours:	1.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54171214
Invoice No. 55345 - 54171214

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 8,603 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Feb-21	Gaspard,Ronald	0.12	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 17-FEB-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Feb 17, 2021 11:08:40 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Feb 17, 2021 11:08:40 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Feb 17, 2021 11:08:40 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Feb 17, 2021 11:08:40 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Feb 17, 2021 11:08:40 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Feb 17, 2021 11:08:40 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Feb 17, 2021 11:08:40 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Feb 17, 2021 11:08:40 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.12
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 54171214 Total	
Parts:	2.79
Labor:	0.00
Labor Hours:	1.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54235935
Invoice No. 55345 - 54235935

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Road Call		Ford Transit	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WORC - WORK ORDER ROAD CALL	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	7,489 - DH

Chronology		
Reported	Jan 24, 2021 1:58:47 PM	Jan 24, 2021 1:58:47 PM
Started	Jan 24, 2021 2:00:00 PM	
Completed	Jan 26, 2021 10:29:00 AM	Jan 26, 2021 10:29:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Vehicle over heating

Cause: Low on coolant / hose leaking

Correction: Line 20 ISSUE WAS REPORTED TO SOUTH FLORIDA TRANSPORTATION FOR UNDER WARRANTY REPAIRS.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 26-JAN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jan 26, 2021 10:29:40 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jan 26, 2021 10:29:40 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Jan 26, 2021 10:29:40 AM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Jan 26, 2021 10:29:40 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jan 26, 2021 10:29:40 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jan 26, 2021 10:29:40 AM	No	
20 - Miles			TDELVA	Jan 26, 2021 10:29:40 AM	No	
30 - Kilometers			TDELVA	Jan 26, 2021 10:29:40 AM	No	
40 - Hours			TDELVA	Jan 26, 2021 10:29:40 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54235935
Invoice No. 55345 - 54235935

Client Department:
Department: 55345M
Work Order Description
Road Call
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 7,489 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Jan-21	Delva,Terry	3.32	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54235935 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54236710
Invoice No. 55345 - 54236710

Client Department:
Department: 55345M
Work Order Description
Bus leaking fluids
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 7,489 - DH

Chronology		
Reported	Jan 25, 2021 7:18:33 AM	Jan 25, 2021 7:18:33 AM
Started	Jan 25, 2021 7:19:00 AM	
Completed	Jan 25, 2021 1:09:00 PM	Jan 25, 2021 1:09:00 PM
Down Time		

Work Order Notes

Line 10 Hose leaking coolant

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 25-JAN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Jan 25, 2021 1:08:30 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Jan 25, 2021 1:08:30 PM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Jan 25, 2021 1:08:30 PM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Jan 25, 2021 1:08:30 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Jan 25, 2021 1:08:30 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Jan 25, 2021 1:08:30 PM	No	
20 - Miles			HPIERRE	Jan 25, 2021 1:08:30 PM	No	
30 - Kilometers	1		HPIERRE	Jan 25, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				1:08:30 PM		
40 - Hours	2		HPIERRE	Jan 25, 2021 1:08:30 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54236710
Invoice No. 55345 - 54236710

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
Bus leaking fluids		Ford Transit	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	7,489 - DH

Activity Header
Activity: 20 042 COOLING SYSTEM
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Jan-21	Pierre,Hubert J	2.75	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54236710 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54163756
Invoice No. 55345 - 54163756

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345 PER DVIRTRANSIT DOOR NOT WORKING		Ford Transit	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	3,711 - DH

Chronology		
Reported	Dec 28, 2020 10:35:00 AM	Dec 28, 2020 10:35:00 AM
Started		
Completed	Dec 31, 2020 12:00:00 PM	Dec 31, 2020 12:00:00 PM
Down Time		

Work Order Notes

Line 10 Can¿t duplicate issue

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 29-DEC-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Dec 29, 2020 8:01:37 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Dec 29, 2020 8:01:37 AM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Dec 29, 2020 8:01:37 AM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Dec 29, 2020 8:01:37 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Dec 29, 2020 8:01:37 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Dec 29, 2020 8:01:37 AM	No	
20 - Miles			RAURODRIGUEZ	Dec 29, 2020 8:01:37 AM	No	
30 - Kilometers			RAURODRIGUEZ	Dec 29, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:01:37 AM		
40 - Hours			RAURODRIGUEZ	Dec 29, 2020 8:01:37 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54163756
Invoice No. 55345 - 54163756

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345 PER DVIRTRANSIT DOOR NOT WORKING		Ford Transit	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	3,711 - DH

Activity Header
Activity: 20 050 GROUP, ACCESSORIES
Activity Note: VERIFY COMPLAINT
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54163756 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54059773
Invoice No. 55345 - 54059773

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	SPACE	**Status:**	40 - Closed (40)
Created By:	SPACE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	4,254 - DH

Chronology		
Reported	Dec 30, 2020 12:00:00 AM	Dec 30, 2020 12:00:00 AM
Started	Dec 30, 2020 4:04:00 PM	
Completed	Dec 30, 2020 7:18:00 PM	Dec 30, 2020 7:18:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Vehicle in for pm service

CAUSE:

CORRECTION: pm service complete.

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Dec-20	Junior Hurst	0.02	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 30-DEC-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Dec 30, 2020 4:05:34 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Dec 30, 2020 4:05:34 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Dec 30, 2020 4:05:34 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Dec 30, 2020 4:05:34 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Dec 30, 2020 4:05:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Dec 30, 2020 4:05:34 PM	No	
20 - Miles			JUHURST	Dec 30, 2020 4:05:34 PM	No	
30 - Kilometers			JUHURST	Dec 30, 2020 4:05:34 PM	No	
40 - Hours			JUHURST	Dec 30, 2020 4:05:34 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54059773
Invoice No. 55345 - 54059773

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: SPACE
Created By: SPACE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 2076
VIN: 1FDES6PG1LKA64297
Ford Transit
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 4,254 - DH

Activity Header
Activity: 10 013 BRAKES
Activity Note: Light Duty PMI
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Dec-20	Junior Hurst	1.62	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: JUHURST Performed on: 30-DEC-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Dec 30, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				5:42:45 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
20,800 - INSPECT_High Idle Control	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
32,000 - Engine Inspection	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Dec 30, 2020 5:42:45 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
32,130 - !FRA!INSPECT_Turbocharger, Mounting Condition	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Dec 30, 2020 5:42:45 PM	No	
33,010 - CSF (Curb Side Front)	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical	Done		JUHURST	Dec 30, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Inputs/Outputs-SOP M038				5:42:45 PM		
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
50,400 - LUBE_All Chassis Components	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
50,700 - INSPECT_Tire Condition	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	9 32nds of an inch		JUHURST	Dec 30, 2020 5:42:45 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Dec 30, 2020 5:42:45 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Dec 30, 2020 5:42:45 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Dec 30, 2020 5:42:45 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		JUHURST	Dec 30, 2020 5:42:45 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		JUHURST	Dec 30, 2020 5:42:45 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.229 Inch		JUHURST	Dec 30, 2020 5:42:45 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.229 Inch		JUHURST	Dec 30, 2020 5:42:45 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Dec 30, 2020 5:42:45 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Dec 30, 2020 5:42:45 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Dec 30, 2020 5:42:45 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Dec 30, 2020 5:42:45 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Dec 30, 2020 5:42:45 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Dec 30, 2020 5:42:45 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Dec 30, 2020 5:42:45 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Dec 30, 2020 5:42:45 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		JUHURST	Dec 30, 2020 5:42:45 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		JUHURST	Dec 30, 2020 5:42:45 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	1.27 Inch		JUHURST	Dec 30, 2020 5:42:45 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	1.27 Inch		JUHURST	Dec 30, 2020 5:42:45 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	6 Cycles		JUHURST	Dec 30, 2020 5:42:45 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Dec 30, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				5:42:45 PM		
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
62,400 - INSPECT_All Pivot Points	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
62,500 - INSPECT_Cams and Slots	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
62,600 - INSPECT_Rollers	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
62,700 - INSPECT_All Linkages	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	Dec 30, 2020 5:42:45 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.62
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54059773
Invoice No. 55345 - 54059773

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345-LIGHT DUTY PMA		Ford Transit	
Requested By:	SPACE	**Status:**	40 - Closed (40)
Created By:	SPACE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	4,254 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Dec-20	B7449	FILTER, OIL, SPIN-ON SEE P577066	1	2.79	2.79

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Dec-20	Junior Hurst	0.02	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: JUHURST Performed on: 30-DEC-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		JUHURST	Dec 30, 2020 5:44:47 PM	No	
101,000 - FRA Change Oil Filters	Yes		JUHURST	Dec 30, 2020 5:44:47 PM	No	
102,000 - FRA Drain Engine Oil	Yes		JUHURST	Dec 30, 2020 5:44:47 PM	No	
103,000 - FRA Check Transmission Fluid	Done		JUHURST	Dec 30, 2020 5:44:47 PM	No	
104,000 - Lubricate Chassis	Done		JUHURST	Dec 30, 2020 5:44:47 PM	No	
105,000 - Replace or Clean A/C Filters	Done		JUHURST	Dec 30, 2020 5:44:47 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		JUHURST	Dec 30, 2020 5:44:47 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		JUHURST	Dec 30, 2020 5:44:47 PM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	2.79
	Labor:	0.00
	Labor Hours:	0.02
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**2.79**

Work Order Footer

Work Order 54059773 Total	
Parts:	2.79
Labor:	0.00
Labor Hours:	1.66
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54105136
Invoice No. 55345 - 54105136

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345 SAFETY EQUIPMENT		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	1,840 - DH

Chronology		
Reported	Dec 4, 2020 6:00:20 AM	Dec 4, 2020 6:00:20 AM
Started	Dec 4, 2020 6:01:00 AM	
Completed	Dec 7, 2020 6:40:00 AM	Dec 7, 2020 6:40:00 AM
Down Time		

Work Order Notes

Line 10 Making ready to start Service

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 07-DEC-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Dec 7, 2020 6:39:43 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Dec 7, 2020 6:39:43 AM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Dec 7, 2020 6:39:43 AM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Dec 7, 2020 6:39:43 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Dec 7, 2020 6:39:43 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Dec 7, 2020 6:39:43 AM	No	
20 - Miles			RAURODRIGUEZ	Dec 7, 2020 6:39:43 AM	No	
30 - Kilometers			RAURODRIGUEZ	Dec 7, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				6:39:43 AM		
40 - Hours			RAURODRIGUEZ	Dec 7, 2020 6:39:43 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54105136
Invoice No. 55345 - 54105136

Client Department:			
Department:	55345M	**Equipment No.:**	2076
Work Order Description		**VIN:**	1FDES6PG1LKA64297
55345 SAFETY EQUIPMENT		Ford Transit	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	1,840 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Dec-20	Rodriguez,Raul	7.97	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	7.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54105136 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	7.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**