

6/30/2026
5:07:14 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Total Hours: 396.60		Labor: 25,816.20	Parts: 22,902.88	Comm: 1,221.80	Charged: 49940.88
Work Order: 833144		Meter: 0	In Date: 01/23/2008 Closed: 01/23/2008		
Problem: PRE-DELIVERY INSPECTION					
Work Completed					
- Pre-delivery Inspection					
Hours: 4.00		Comm: 0.00	Labor: 240.00	Parts: 0.00	Total: 240.00
Work Order: 833227		Meter: 41	In Date: 01/25/2008 Closed: 01/30/2008		
Problem: INSTALL STROBE LIGHT					
Work Completed			Parts Issued		Quantity
- Fabricate And Install New Top Mounted Strobe Light.install Toggle Switch			Shop Supplies		1.00
And Inline Fuse Wire In & Set To Max Intensity.cust Supp Strob L			Ds-167 Toggle Switch (standard)		1.00
- Shop Supplies			80865 Fuseholder Imperial 80865		1.00
Hours: 4.00		Comm: 0.00	Labor: 240.00	Parts: 15.23	Total: 255.23
Work Order: 835593		Meter: 1377	In Date: 03/17/2008 Closed: 03/18/2008		
Problem: LEFT FRONT TIRE FLAT					
Work Completed			Parts Issued		Quantity
- Repair Flat Tire.patch 2 Holes In Tire,high Speed Balance, Nitro Filled.			Shop Supplies		1.00
- Shop Supplies					
Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.00	Total: 62.00
Work Order: 841693		Meter: 5352	In Date: 07/21/2008 Closed: 07/28/2008		
Problem: P.M. SERVICE					
Work Completed			Parts Issued		Quantity
- Pm Service			Shop Supplies		1.00
- Winch Service			1372 Oil Filter Frm Ph2 Wix 51372		1.00
- Shop Supplies			Ca10262 Air Filter Mtc Fa1883 Wix 49883		1.00
			G10166 Fuel Filter Mtc Fg1083 Wix 33243		1.00
			5w20 Engine Oil		7.00
			31-20 Wiper Blades 20" Blade		2.00
Hours: 3.75		Comm: 0.00	Labor: 225.00	Parts: 64.46	Total: 289.46

6/30/2026
5:07:14 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 846721 **Meter:** 7540 **In Date:** 11/04/2008 **Closed:** 11/05/2008
Problem: R/F TIRE FLAT

Work Completed

- Repair R/f Tire.
- Shop Supplies

Parts Issued

Shop Supplies

Quantity

1.00

Hours: 1.00

Comm: 0.00

Labor: 60.00

Parts: 2.00

Total: 62.00

Work Order: 933521 **Meter:** 9782 **In Date:** 02/04/2009 **Closed:** 02/10/2009
Problem: P.M SERVICE

Work Completed

- Pm Service
- Repl Missing Pintle Hitch Sefety Pin And Chain.
- Service Winch. Inspect,lube,test Operation And Respool Cable
- Repair Ground To Tag Light.
- Repair 2 Tires.mount On Left Side.balance All 4 Tires
- Shop Supplies

Parts Issued

Shop Supplies

1372 Oil Filter Frm Ph2 Wix 51372

G10166 Fuel Filter Mtc Fg1083 Wix 33243

5w20 Engine Oil

31-20 Wiper Blades 20" Blade

18410 Pintle Pin

Quantity

1.00

1.00

1.00

7.00

2.00

1.00

Hours: 6.75

Comm: 0.00

Labor: 405.00

Parts: 53.57

Total: 458.57

Work Order: 941290 **Meter:** 13603 **In Date:** 07/28/2009 **Closed:** 08/17/2009
Problem: P.M service

Work Completed

- P.m service.
- Inspect & service winch.
- Rotate & balance all four tires.
- To/from Dealer for floor mat replacement. (hole in d/s floor)
- Remove items from truck for dealer to replace floor mat, reinstall when done.
- Shop Supplies

Parts Issued

Shop Supplies

1372 Oil Filter Frm Ph2 Wix 51372

5w20 Engine Oil

Used Firex Refurbed Fire Extingshers

Floor Mat Set

Quantity

1.00

1.00

7.00

1.00

1.00

Hours: 7.25

Comm: 0.00

Labor: 435.00

Parts: 92.25

Total: 527.25

6/30/2026
5:07:14 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 942635 **Meter:** 13854 **In Date:** 08/27/2009 **Closed:** 08/31/2009
Problem: check engine light on.

Work Completed

- Preform computer diagnostics, run Evap bay test, replace defective gas cap & clear codes.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
Gas Cap Fc1061	1.00

Hours: 1.00

Comm: 0.00

Labor: 60.00

Parts: 21.58

Total: 81.58

Work Order: 945958 **Meter:** 15265 **In Date:** 11/13/2009 **Closed:** 11/20/2009
Problem: Dead battery.

Work Completed

- Test starting & charging system, test & defective battery.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
Group 65 Battery (mtc Bxt-65-850)	1.00

Hours: 1.00

Comm: 0.00

Labor: 60.00

Parts: 129.43

Total: 189.43

Work Order: 1001862 **Meter:** 17289 **In Date:** 02/22/2010 **Closed:** 02/25/2010
Problem: P.M service.

Work Completed

- P.m service.
- Inspect & service winch.
- Test & replace third brake light bulb.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
Ca10262 Air Filter Mtc Fa1883 Wix 49883	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
5w20 Engine Oil	7.00
31-20 Wiper Blades 20" Blade	2.00

Hours: 4.05

Comm: 0.00

Labor: 243.00

Parts: 48.72

Total: 291.72

6/30/2026
5:07:14 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 1007265 **Meter:** 21432 **In Date:** 07/12/2010 **Closed:** 07/12/2010
Problem: Front tires not repairable.

Work Completed

- Install two new tires,nitrogen fill and balance both.
- Perform wheel alignment complete.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
179535492 Lt265/70r17 Wrangler Sr-a E	2.00
Tire Disposal Fee	2.00
Tr416 Valve Stem	2.00

Hours: 4.00

Comm: 0.00

Labor: 240.00	Parts: 387.00	Total: 627.00
---------------	---------------	---------------

Work Order: 1010036 **Meter:** 23045 **In Date:** 09/14/2010 **Closed:** 09/22/2010
Problem: Pm service.

Work Completed

- Perform pm service.
- Install two new tires to the front wheels and balance all four.
- Inspect and service power winch.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
5w20 Engine Oil	7.00
Used Firex Refurbed Fire Extingshers	1.00
31-20 Wiper Blades 20" Blade	2.00
179535492 Lt265/70r17 Wrangler Sr-a E	2.00
Tire Disposal Fee	2.00
Tr416 Valve Stem	2.00

Hours: 5.75

Comm: 0.00

Labor: 345.00	Parts: 426.09	Total: 771.09
---------------	---------------	---------------

Work Order: 1102305 **Meter:** 26506 **In Date:** 03/01/2011 **Closed:** 03/03/2011
Problem: Trailer lights inop.

Work Completed

- Diagnose and replace failed trailer harness plug receptacle with new.insulate and secure.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
5404 Female Connector	1.00
06133 3m Electric Tape Stock #832260101	1.00

Hours: 1.50

Comm: 0.00

Labor: 90.00	Parts: 16.77	Total: 106.77
--------------	--------------	---------------

6/30/2026
5:07:14 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 1102759 **Meter:** 26823 **In Date:** 03/14/2011 **Closed:** 03/21/2011

Problem: P.M. Service.

Work Completed

- Perform pm service.
- Inspect and perform power winch service.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
5w20 Engine Oil	7.00
L0135-063 Lubriplate Chain&cable Lube,03050crc	1.00
31-20 Wiper Blades 20" Blade	2.00
D3tz2457b Brake Pedal Pad	1.00

Hours: 4.75

Comm: 0.00

Labor: 285.00 Parts: 51.44 Total: 336.44

Work Order: 1105533 **Meter:** 28387 **In Date:** 05/25/2011 **Closed:** 05/27/2011

Problem: Right front tire flat.

Work Completed

- Repair flat right front tire.nitrogen fill and balance same.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1109903 **Meter:** 31183 **In Date:** 09/16/2011 **Closed:** 09/22/2011

Problem: Pm service.

Work Completed

- P.m. Service.
- Inspect and service winch.
- Repair left rear tire,rotate and balance all four.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
61a P/steering Fluid	1.00
5w20 Engine Oil	7.00
Used Firex Refurbed Fire Extingshers	1.00
31-20 Wiper Blades 20" Blade	2.00

Hours: 5.75

Comm: 0.00

Labor: 345.00 Parts: 49.09 Total: 394.09

6/30/2026
5:07:14 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 1111959 **Meter:** 32258 **In Date:** 11/07/2011 **Closed:** 11/10/2011
Problem: Right front tire going flat.

Work Completed

Parts Issued

Quantity

- Repair and balance right front tire.
- Shop Supplies

Shop Supplies

1.00

Hours: 1.00

Comm: 0.00

Labor: 60.00

Parts: 2.00

Total: 62.00

Work Order: 1200490 **Meter:** 33785 **In Date:** 01/17/2012 **Closed:** 01/19/2012
Problem: Slow leak right rear tire.

Work Completed

Parts Issued

Quantity

- Repair flat right rear tire.nitrogen fill and balance same.
- Shop Supplies

Shop Supplies

1.00

Hours: 1.00

Comm: 0.00

Labor: 60.00

Parts: 2.00

Total: 62.00

Work Order: 1202329 **Meter:** 34927 **In Date:** 03/07/2012 **Closed:** 03/08/2012
Problem: Right front and left rear tires flat.

Work Completed

Parts Issued

Quantity

- Repair and balance right front and left front tires.
- Shop Supplies

Shop Supplies

1.00

Hours: 2.00

Comm: 0.00

Labor: 120.00

Parts: 2.00

Total: 122.00

6/30/2026
5:07:14 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 1202692 **Meter:** 35407 **In Date:** 03/19/2012 **Closed:** 04/09/2012
Problem: P.M. service and strobe light toggle switch broken.

Work Completed

- P.m. Service.
- Replace broken strobe light switch.
- Replace broke extinguisher bracket.repair and adjust left side utility box latches and slide lock.
- Replace two tires,rotate and balance all four.
- Vehicle cranks slow.recharge battery and test,fail load test.replace bad battery.
- Complete wheel alignment.test drive.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
09997 Brake Clean	1.00
5w20 Engine Oil	7.00
31-20 Wiper Blades 20" Blade	2.00
Custom5lb Bracket Firex Stock #340060300	1.00
Group 65 Battery (mtc Bxt-65-850)	1.00
Ds-167 Toggle Switch (standard)	1.00
179535492 Lt265/70r17 Wrangler Sr-a E	2.00
Tire Disposal Fee	2.00

Hours: 9.75

Comm: 0.00

Labor: 585.00 Parts: 583.38 Total: 1,168.38

Work Order: 1207590 **Meter:** 38503 **In Date:** 08/13/2012 **Closed:** 08/17/2012
Problem: Check engine light on.

Work Completed

- Service and clean intake and throttle body.flush injectors.
- Diagnose check engine light.perform ignition system tune-up.replace #3 & #5 coils.clear codes and test drive.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
Ka8a Throttle Body/ Up Engine Service Kit	1.00
408 Fuel Injection Cleaner	1.00
Spark Plug	8.00
Black Boot Coil	1.00
Black Boot Coil	1.00

Hours: 7.00

Comm: 0.00

Labor: 420.00 Parts: 317.77 Total: 737.77

6/30/2026
5:07:15 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 1209157 **Meter:** 39365 **In Date:** 09/25/2012 **Closed:** 10/15/2012

Problem: Right rear tire flat.

Work Completed

- Perform pm service.
- Install two new tires to the front wheels.repair flat right rear tire.nitrogen fill and balance all four.
- Inspect and service power winch.
- Diagnose for bang when taking off and stops.r&r rear driveshaft assembly.clean and lube binding slip joint with teflon grease.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Ph2 Oil Filter Lbf Ph	1.00
31-20 Wiper Blades 20	2.00
Used Firex Refurbed F	1.00
G10166 Fuel Filter Mt	1.00
Ca10262 Air Filter Mt	1.00
L0135-063 Lubriplate	1.00
179535492 Lt265-70r17	2.00
Tr416 Valve Stem	2.00
tefon grease	1.00
Shop Supplies	1.00

Hours: 7.00

Comm: 0.00

Labor: 420.00 Parts: 628.36 Total: 1,048.36

Work Order: 1305059 **Meter:** 44116 **In Date:** 05/22/2013 **Closed:** 05/31/2013

Problem: Pm service and back up alarm inop.

Work Completed

- P.m. Service.
- Replace inop back-up alarm and repair wiring.replace missing pintle pin.
- A/c not cold. recharge and leak test system.replace pressure hose.vacuum and recharge system to specs.
- Replace both headlamps.
- Rotate and balance all tires.
- Inspect and service winch.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
F75z6730ba Drain Plug	1.00
31-20 Wiper Blades 20	2.00
Pedal Pad	1.00
Alarm	1.00
18410 Pintle Pin	1.00
Tube Asy	1.00
R134a Lv Shop 1	2.00
Halogen Lamp	2.00
Shop Supplies	1.00

Hours: 10.25

Comm: 0.00

Labor: 615.00 Parts: 254.23 Total: 869.23

6/30/2026
5:07:15 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 1306113 **Meter:** 44642 **In Date:** 06/19/2013 **Closed:** 06/27/2013
Problem: Noise from under truck on cold start ups and accel.

Work Completed

Parts Issued

Quantity

- Transport vehicle to and from dealer for replacing failed catalytic converters with new under factory warranty.
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 2.00	Comm: 0.00	Labor: 120.00	Parts: 2.00	Total: 122.00
-------------	------------	---------------	-------------	---------------

Work Order: 1312797 **Meter:** 47847 **In Date:** 12/26/2013 **Closed:** 01/10/2014
Problem: P.M. service.

Work Completed

Parts Issued

Quantity

- Perform pm service.
- Test and replace failed horn assembly with new.
- Test and repaired failed ground circuit to to right rear marker lamp.
- Perform power winch service.
- Repair flat right rear tire.nitrogen fill and balance all four.
- Shop Supplies

5w20 Engine Oil	14.00
Napagold Oil Filter	2.00
Wiper Blade	4.00
Used Fire X Refurbished	2.00
Napagold Fuel Filter	2.00
Brake Cleaner	2.00
Horn Assembly	1.00
Shop Supplies	1.00

Hours: 7.25	Comm: 0.00	Labor: 435.00	Parts: 176.72	Total: 611.72
-------------	------------	---------------	---------------	---------------

6/30/2026
5:07:15 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 1400340 **Meter:** 47916 **In Date:** 01/10/2014 **Closed:** 02/20/2014

Problem: Start to sputter and check engine light on after gas up.

Work Completed

- Computer diagnose for no power .test and replace three failed fuel injectors,three coils and spark plugs on left cylinder head with new.flush all fuel injectors and clean trottle body.clear codes with scan tool and road test.

- Diagnose and test for low compression on #2 cylinder.remove right side valve cover and replace two failed/broken exhaust valve springs with new to restore compression.

- Shop Supplies

Parts Issued

Quantity

Valve Spring	2.00
Rh Valve Cover Gasket	1.00
Fuse	2.00
Coil Assembly	3.00
Spark Plug	3.00
injector	3.00
Cut-off 310	1.00
Valve Spring Keepers	2.00
Shop Supplies	1.00

Hours: 7.00

Comm: 0.00

Labor: 420.00 Parts: 506.20 Total: 926.20

Work Order: 1401856 **Meter:** 48144 **In Date:** 02/26/2014 **Closed:** 02/28/2014

Problem: Right rear tire going flat.

Work Completed

- Repair and balance right rear tire.

- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1405092 **Meter:** 49823 **In Date:** 05/27/2014 **Closed:** 05/29/2014

Problem: Right front tire has screw.

Work Completed

- Repair and balance right front tire.

- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 60.00 Parts: 2.00 Total: 62.00

6/30/2026
5:07:15 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 1406633 **Meter:** 50357 **In Date:** 07/07/2014 **Closed:** 07/21/2014
Problem: Pm service

Work Completed

- Perform pm service.
- Install two new tires to the front wheels.nitrogen fill and balance all four.
- Test and replace failed right side seal beam with new.also replace broken licence plate lamp and bracket with new.test and replace third brake lamp bulb with new.
- Perform wheel alignment complete.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Wiper Blade	2.00
Bat Term Protector	1.00
179535492 Lt265-70r17	2.00
License Bracket W/light	1.00
Halogen Lamp	1.00
Tarp Fas	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 9.25

Comm: 0.00

Labor: 555.00 Parts: 580.01 Total: 1,135.01

Work Order: 1410499 **Meter:** 51214 **In Date:** 10/21/2014 **Closed:** 10/27/2014
Problem: Lost gas cap.

Work Completed

- Replace missing gas cap and clear code P0455 with scan tool to reset check engine light on dash.
- Shop Supplies

Parts Issued

Quantity

Gas Cap Non-locking	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 60.00 Parts: 15.61 Total: 75.61

6/30/2026
5:07:15 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 1503998 **Meter:** 53046 **In Date:** 04/17/2015 **Closed:** 04/30/2015
Problem: Pm service.

Work Completed

- Pm service.
- Replace two tires.rotate and balance all four .
- Test and replace two defective Led tail lamps.test and replace defective becon strobe lamp bulb.
- Test and replace defective blower motor resistor.
- Inspect and replace broken middle arm rest.
- Replace front brake pads.resurface both front brake rotors.service calipers.test drive.
- Inspect and service power winch.
- Shop Supplies

Parts Issued

Quantity

179535492 Lt265-70r17	2.00
5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Led Sup Mdl 44 42 Dio	2.00
Blower Resistor	1.00
Pads	1.00
Middle Seat Front	1.00
Hide Away Strob	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 13.75

Comm: 0.00

Labor: 825.00 Parts: 1,189.64 Total: 2,014.64

Work Order: 1507726 **Meter:** 53944 **In Date:** 08/03/2015 **Closed:** 08/06/2015
Problem: Tire light on

Work Completed

- Replace left rear tire and repair and balance right front tire.
- Shop Supplies

Parts Issued

Quantity

179535492 Lt265-70r17	1.00
Shop Supplies	1.00

Hours: 1.50

Comm: 0.00

Labor: 90.00 Parts: 276.14 Total: 366.14

Work Order: 1508462 **Meter:** 54197 **In Date:** 08/24/2015 **Closed:**
Problem: Right headlight inop.

Work Completed

-

Hours: 0.00

Comm: 0.00

Labor: 0.00 Parts: 0.00 Total: 0.00

6/30/2026
5:07:15 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 1509729 **Meter:** 54372 **In Date:** 09/25/2015 **Closed:** 09/30/2015

Problem: Engine runs rough.

Work Completed

Parts Issued

Quantity

- Computer diagnose check engine light on and run rough.code
P0300,p0302 and P0316.perform pinpoint test.replace defective #2 ignition
coil and spark plug.power balance test.reset Kam and test drive.

Coil Assembly	1.00
Spark Plug	1.00
Shop Supplies	1.00

- Shop Supplies

Hours: 3.00

Comm: 0.00

Labor: 180.00

Parts: 93.71

Total: 273.71

Work Order: 1600927 **Meter:** 56139 **In Date:** 01/27/2016 **Closed:** 02/10/2016

Problem: install lights

Work Completed

Parts Issued

Quantity

- Install 4 Led lights Van all wires mount 2 on/off switches drill and mount 4
lights with new hardware install breaker fuses test sys make 4 quick
connector harness

Fuse Holder	1.00
Toggle Switch	2.00
Clr Rtv Silcn Sealant	2.00
Shop Supplies	1.00

- Shop Supplies

Hours: 8.00

Comm: 0.00

Labor: 480.00

Parts: 32.68

Total: 512.68

Work Order: 1601019 **Meter:** 56235 **In Date:** 01/29/2016 **Closed:** 02/24/2016

Problem: Pm service.

Work Completed

Parts Issued

Quantity

- Pm service.
- Rotate and balance all four tires.
- Inspect and service winch.
- Replace rear brake pads and two rear brake calipers.resurface both rear
brake rotors.flush and bleed brake system.test drive.
- Test battery and charging system.battery failed loadtest.replace defective
battery.

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Drain Plug	1.00
Caliper w/ Hardware - Left Rear (eclipse	1.00
Caliper w/ Hardware - Right Rear (eclips	1.00
Rear Pads	1.00
Battery	1.00
Shop Supplies	1.00

- Shop Supplies

Hours: 10.25

Comm: 0.00

Labor: 615.00

Parts: 380.72

Total: 995.72

6/30/2026
5:07:15 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 1605729 **Meter:** 57956 **In Date:** 06/03/2016 **Closed:** 06/13/2016
Problem: Tire pressure sensor fault light on.

Work Completed

- Diagnose and replace defective tire pressure sensor.
- Replace missing fuel cap.
- Shop Supplies

Hours: 1.25

Comm: 0.00

Parts Issued

Quantity

Gas Cap Non-locking	1.00
Tpms5 Sensor Tire Pre	1.00
Shop Supplies	1.00

Labor: 75.00

Parts: 142.31

Total: 217.31

Work Order: 1606458 **Meter:** 58039 **In Date:** 06/24/2016 **Closed:** 06/28/2016
Problem: repair trailer plug

Work Completed

- Replace Trailer plug
- Shop Supplies

Hours: 1.50

Comm: 0.00

Parts Issued

Quantity

trailer plug	1.00
Shop Supplies	1.00

Labor: 90.00

Parts: 13.12

Total: 103.12

6/30/2026
5:07:15 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 1608119 **Meter:** 58793 **In Date:** 08/08/2016 **Closed:** 08/23/2016
Problem: P.M. service and noise in front end over bumps.

Work Completed

- P.m. Service.
- Check for noise while going over bumps.replace four worn out body mounts.
- Service transmission.flush and refill ssystem.
- Inspect and service transfer case.
- Replace two tires,rotate and balance all four.
- Replace both stop lamps.repair ground for marker light and brake lights.replace broken utility light switches on dash.
- Replace pintle pin.fabricate and repair utility box lids,not closing properly.
- Replace worn out rear suspension bump stops.replace rear shocks.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
20" Wiper Blade	2.00
Mac Wite Lithium Gres	1.00
Big G Degreaser 1 Gal	1.00
Body Mount Kit	2.00
Body Mount Kit	2.00
Trans Filter	1.00
Syn-atf Trans Fluid S	18.00
Tran Flu Qt Dexron3i	2.00
Lt265/70r17 Tire E	2.00
Light Switch	2.00
Napagold Fuel Filter	1.00
Pintle Pin W/clip	1.00
Bumper	2.00
Led Sup Mdl 44 42 Dio	2.00
Washer Fluid Concentr	1.00
Gas Grande Shock	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 16.25

Comm: 0.00

Labor: 975.00

Parts: 1,417.74

Total: 2,392.74

6/30/2026
5:07:15 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 1703595 **Meter:** 62585 **In Date:** 04/10/2017 **Closed:** 04/20/2017
Problem: P.M. service ,check suspension noise,door ajar light on ,A/T tires.

Work Completed

- P.m. Service.
- Replace high mount brake lamp bulbs.replace and rewire boken tag lamp.test and replace blown lighter fuse.
- Replace worn out front shocks.replace two rear cab mounts.
- Replace and balance four new tires.
- Diagnose dome lamp staying on.r&r right front door panel and replace door ajar switch.
- Complete wheel aligment.test drive.
- Inspect and service winch.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Rpl Bulb	3.00
Fmx-20 Fuse	1.00
lic light w/bracket	1.00
Gas Grande Shock	2.00
Body Mount Kit	2.00
Lt265/70r17 Tire E	4.00
Knob	1.00
Switch	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 13.75

Comm: 0.00

Labor: 825.00

Parts: 1,548.13

Total: 2,373.13

Work Order: 1706477 **Meter:** 64003 **In Date:** 06/30/2017 **Closed:** 07/20/2017
Problem: Runs rough.

Work Completed

- Replace all four rotors ,causing really bad brake pulsation.test drive.
- Diagnose engine performance issue.no codes found.possible evap system water intrusion.rear axle submerged.check gear oil,ok.unable to duplicate any engine performance issues.
- Shop Supplies

Parts Issued

Quantity

Brake Rotor	2.00
Non-chlor Brake Clnr	1.00
Front Rotor	2.00
Shop Supplies	1.00

Hours: 4.00

Comm: 0.00

Labor: 240.00

Parts: 463.97

Total: 703.97

6/30/2026
5:07:15 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 1709965 **Meter:** 65152 **In Date:** 10/12/2017 **Closed:** 10/31/2017

Problem: PM Service, Repair arm rest, Check engine light, Winch inop, Washer nozzle inop.

Work Completed

- P.m. service. Replace washer jets.
- Replace front bump stops.
- Replace broken toggle switch for rear spot lights.
- Replace broken pintle hitch clevis and chain. diagnose winch. replace bad motor. service winch and cable.
- Rotate and balance four tires. nitro service.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
20" Wiper Blade	2.00
Napagold Fuel Filter	1.00
Napagold Air Filter	1.00
Mac Wite Lithium Gres	1.00
Washer Fluid Concentr	2.00
bumper	2.00
Toggle Switch	1.00
Washer Nozzle	2.00
Pintle Pin W/clip	1.00
Winchr Motor	1.00
Shop Supplies	1.00

Hours: 7.45

Comm: 0.00

Labor: 447.00

Parts: 476.11

Total: 923.11

Work Order: 1711165

Meter: 65307

In Date: 11/13/2017 **Closed:** 11/16/2017

Problem: Hard to fuel , cuts off.

Work Completed

- Scan computer, pulled codes P0442 evap system leak. perform leak test failed due to vent solenoid valve stuck also causing fueling issue. replace canister assembly. retest. clear codes and drive to fuel lane to test fueling .add five gallons of fuel.
- Shop Supplies

Parts Issued

Quantity

Cannister	1.00
Cap	1.00
Shop Supplies	1.00

Hours: 3.50

Comm: 0.00

Labor: 210.00

Parts: 179.44

Total: 389.44

6/30/2026
5:07:15 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 1801795 **Meter:** 67122 **In Date:** 02/15/2018 **Closed:** 02/21/2018
Problem: A/C stops blowing.

Work Completed

- Diagnose A/c blower .r&r defective blower motor and resistor.retest.
- Shop Supplies

Hours: 1.20

Comm: 0.00

Parts Issued

Quantity

Blower Resistor	1.00
Fan Motor	1.00
Shop Supplies	1.00
Labor: 72.00	Parts: 154.81
Total: 226.81	

Work Order: 1802172 **Meter:** 67300 **In Date:** 02/27/2018 **Closed:** 03/06/2018
Problem: A/C evap freezes up.

Work Completed

- Perform A/c performance test .evacuate system .replace defective evaporator,condensor ,orifice tube, acculator and high side shrader valve.vacuum system and recharge to spec and retest.
- Shop Supplies

Hours: 13.10

Comm: 0.00

Parts Issued

Quantity

Evapotator Core	1.00
Tube Filter	1.00
Accumulator	1.00
A/c Condenser	1.00
Freon Lv Shop 1	2.00
Seal Kits	2.00
O Ring	3.00
O Ring	2.00
E8 A/c Oil Univ W Dye	1.00
Ac Valve Core High	1.00
Shop Supplies	1.00
Labor: 786.00	Parts: 815.95
Total: 1,601.95	

6/30/2026
5:07:15 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 1806151 **Meter:** 68602 **In Date:** 06/15/2018 **Closed:** 07/02/2018
Problem: PM Service, Replace wipers, Hole in passenger rear roof.

Work Completed

- P.m. service.
- Replace left headlight bulb.
- Replace worn serpentine belt .
- Inspect and service front differential.
- Inspect and service rear differential.
- Inspect and service winch.
- Rotate and high speed balance all four tires.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Napa Gear 80w-90 Qt	3.00
Mac Wite Lithium Gres	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Halogen Sealed Beams	1.00
V-ribbed Belt	1.00
Ptex Ultra Grey 3oz	1.00
Friction Modifier	2.00
75w140 Ford Axle Lube	3.00
Belt	1.00
20" Wiper Blade	2.00
Shop Supplies	1.00

Hours: 8.05

Comm: 0.00

Labor: 483.00

Parts: 263.42

Total: 746.42

Work Order: 1807439 **Meter:** 68602 **In Date:** 06/22/2018 **Closed:** 07/23/2018
Problem: repair rust on rgt side of roof

Work Completed

- repair rust on rgt side of roof

Hours: 0.00

Comm: 798.00

Labor: 0.00

Parts: 0.00

Total: 798.00

Work Order: 1809514 **Meter:** 69438 **In Date:** 09/14/2018 **Closed:** 09/18/2018
Problem: No Start, Starter?

Work Completed

- Diagnose bad battery . Battery would not except charge . Replace battery and retest starting and charging systems.
- Shop Supplies

Parts Issued

Quantity

Battery 65	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 60.00

Parts: 171.77

Total: 231.77

6/30/2026
5:07:15 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 1809535 **Meter:** 69409 **In Date:** 09/14/2018 **Closed:** 09/14/2018

Problem: No start

Work Completed

- Tow From: 3700 Belvedere Rd Bldg E To: Lv shop

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1809663 **Meter:** 69500 **In Date:** 09/19/2018 **Closed:** 09/19/2018

Problem: Left rear tire going flat.

Work Completed

- Repair left rear tire and balance . Nitrogen fill tires .

Parts Issued **Quantity**

Shop Supplies 1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1813035 **Meter:** 70856 **In Date:** 12/27/2018 **Closed:** 01/07/2019

Problem: P.M. service and flat tire in bed of truck .

Work Completed

- P.m. service.

Parts Issued **Quantity**

Napagold Oil Filter 1.00

- Replace all four tires . Nitrogen fill and balance all four tires.

Napa Quart 5w20 7.00

- Inspect and service winch .

Used Fire X Refurbished 1.00

- Perform complete front end alignment and road test.

20" Wiper Blade 2.00

- Shop Supplies

Tr416 Valve Stem 4.00

Lt265/70/17 Tire Nit 4.00

Napagold Fuel Filter 1.00

Shop Supplies 1.00

Tire Disposal Fee 4.00

Hours: 8.25 Comm: 0.00 Labor: 552.75 Parts: 1,218.76 Total: 1,771.51

6/30/2026
5:07:15 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 1905100 **Meter:** 72507 **In Date:** 05/10/2019 **Closed:** 05/20/2019
Problem: Check engine light, Brake pedal pad, Radio volume inop.

Work Completed

- Computer diagnose check engine light ,code P0713 ,p0710. Perform tab 13-12-22 . Remove transmission pan to replace transmission temp sensor and filter . Flush trans and refill . Clear code and test drive . Reprogram Tcm with updated calibration .

- Check and replace miassing brake pedal pad .

- Check and test radio . R&r defective radio and retest .

- Shop Supplies

Hours: 6.30

Comm: 0.00

Parts Issued

Quantity

Syn-atf Trans Fluid S	20.00
Trans Filter	1.00
Sensor	1.00
brake pedal pad	1.00
Radio	1.00
Shop Supplies	1.00

Labor: 422.10

Parts: 428.12

Total: 850.22

Work Order: 1907805 **Meter:** 73405 **In Date:** 07/29/2019 **Closed:** 08/06/2019
Problem: PM Service

Work Completed

- P.m. Service.

- Replace left rear signal lamp.diagnose inop lights in light bar.repair bad circuits and retest.

- Inspect and service winch.

- Rotate and balance tires.

- Shop Supplies

Hours: 6.25

Comm: 0.00

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
Napagold Air Filter	1.00
Led Sup Mdl 44 42 Dio	1.00
Shop Supplies	1.00

Labor: 418.75

Parts: 109.19

Total: 527.94

6/30/2026
5:07:15 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 2000808 **Meter:** 75595 **In Date:** 01/24/2020 **Closed:** 02/06/2020
Problem: P.M. service and A/c blows warm .

Work Completed

- P.m. service.
- Perform A/c performance test . Compressor not coming on .perform pinpoint test . R&r defective A/c clutch relay . Retest .
- R&r broken pintle pin .
- Test and replace defective trailer plug connector and rewire as needed . Replace blow trailer power fuse .
- Resurface both front brake rotors . Replace front calipers and pads . Flush and bleed brake system . Road test .
- Test and replace both broken toggle switches for Led lights .
- Inspect and service winch and replace cable hook .
- Test and replace defective right rear tire pressure sensor . Rotate and high speed balance all four tires . Nitrofill all.
- Test and adjust right rear bin door stricker . tighten loose lock cylinder in center bin door .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Napagold Fuel Filter	1.00
Used Fire X Refurbished	1.00
Relay	1.00
Pintle Pin W/clip	1.00
Fmx-30 Fuse	1.00
trailer plug	1.00
B Fluid Dot 3-32oz	2.00
Caliper w/ Hardware - Right Front (eclip	1.00
Caliper w/ Hardware - Left Front (eclips	1.00
Brake Pad	1.00
Toggle Switch	2.00
Clevis Slip Hook	1.00
Tire Sensor	1.00
Shop Supplies	1.00

Hours: 15.25

Comm: 0.00

Labor: 1,113.25

Parts: 431.97

Total: 1,545.22

Work Order: 2003474 **Meter:** 76502 **In Date:** 04/07/2020 **Closed:** 04/09/2020
Problem: Trailer plug broken .

Work Completed

- Test and replace broken trailer plug connector and rewire as needed .
- Shop Supplies

Parts Issued

Quantity

trailer plug	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 15.10

Total: 88.10

6/30/2026
5:07:15 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 2007996 **Meter:** 78600 **In Date:** 08/12/2020 **Closed:** 08/19/2020
Problem: P.M. service , towed in no start and A/C blower inop at low speed .

Work Completed

Parts Issued

Quantity

- P.m. service.
- Charge battery fully . Test battery and charging system . R&r defective battery .
- Diagnose A/c blower inop . Replace defective blower resistor and retest .
- Test and replace two marker light assemblies . Test and replace defective toggle switch for strobe light .
- Replace broken radio antenna . Replace broken pintle pin .
- Inspect and service winch .
- Rotate and balance all four tires . Nitrofill all .
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	8.00
20" Wiper Blade	2.00
Battery 65	1.00
Blower Motor Resistor	1.00
Toggle Switch	1.00
Pintle Pin W/clip	1.00
M C Base Mount Kit	2.00
Antenna	1.00
Shop Supplies	1.00

Hours: 9.00

Comm: 0.00

Labor: 657.00

Parts: 320.64

Total: 977.64

Work Order: 2008072 **Meter:** 78516 **In Date:** 08/12/2020 **Closed:** 08/13/2020
Problem: Hard Starting

Work Completed

- Tow From: Pbia (3700 Belvedere Rd bldg E) To: Lv shop

Hours: 0.00

Comm: 96.00

Labor: 0.00

Parts: 0.00

Total: 96.00

6/30/2026
5:07:15 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 2101677 **Meter:** 81900 **In Date:** 02/12/2021 **Closed:** 02/27/2021

Problem: PM service , check A/C and right rear tire going flat . No power on hard accel , steering wheel cover

Work Completed

- Preventive Maint. Service
- Perform A/c performance test . Diagnose A/c inop. Found to have leaking low side service port valve. R and R both service port valves. Recover and evacuate system . Vacuum and complete recharge to factory spec . Retest .
- Diagnose popping noise when opening drivers door. Found door check to be broken. R and R broken door check.
- Diagnose truck slow on hard acceleration. Performed tune up and test drove
- Perform air intake decarb and cleaning and fuel system flush
- Inspect and serviced winch
- Mounted and balanced 4 new tires. Nitrogen filled all tires. Diagnose Tpms fault light. Found to have faulty sensor. R and R bad sensor, relearn Tpms system
- Diagnose play in steering. Found to have worn out outer tie rod on right side. R and R bad tie rod.
- Performed full front end alignment.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Steering Wheel Cover Large	1.00
Napagold Fuel Filter	1.00
Freon Lv Shop 1	2.00
A/c Service Port	1.00
High Side Schrader Valve	1.00
left door check asy	1.00
Spark Plug	8.00
Motor Tune-up 16oz	1.00
Intake Cleaner Kit	1.00
Tpms5 Sensor Tire Pre	1.00
Lt265/70r17 Tire E	4.00
End Spin	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 18.95

Comm: 0.00

Labor: 1,383.35 Parts: 1,671.69 Total: 3,055.04

Work Order: 2108103 **Meter:** 84312 **In Date:** 07/27/2021 **Closed:** 07/29/2021

Problem: Vehicle runs rough and A/C kicks on and off often .

Work Completed

- Computer Diagnose check engine light. Found to have bad coil on cylinder #4. replaced coil. cleared codes and test drove. Ac cycling a lot was caused by misfire.
- Shop Supplies

Parts Issued

Quantity

Coil Assembly	1.00
Shop Supplies	1.00

Hours: 2.50

Comm: 0.00

Labor: 182.50 Parts: 58.31 Total: 240.81

6/30/2026
5:07:15 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 2111190 **Meter:** 85449 **In Date:** 10/18/2021 **Closed:** 10/26/2021
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Perform Rotate and speed balance all 4 tires , nitro fill all .
- Inspect all, R & I new rear brakes, Resurface rear rotors, R & I refurbish calipers rears, Service & lube caliper slide pins,bleed flush brake system . Road test .
- Check circuit to tail lamp Ls, R & I new lamp
- Check & replace broken Pintle
- Inspect and service winches
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Non-chlor Brake Clnr	1.00
Brk Fluid Dot 4-32oz	1.00
Caliper w/ Hardware - Left Rear (eclipse	1.00
Caliper w/ Hardware - Right Rear (eclips	1.00
Right Angle S T Pgtl	1.00
Lamp	1.00
Pintle Pin W/clip	1.00
Brake Pad	1.00
Shop Supplies	1.00

Hours: 9.45

Comm: 0.00

Labor: 689.85

Parts: 244.49

Total: 934.34

Work Order: 2112274 **Meter:** 85450 **In Date:** 11/16/2021 **Closed:** 11/18/2021
Problem: Battery keeps dying.

Work Completed

- Load test battery failed battery was replaced and re tested . Then vehicle charging system was inspected and passed.
- Shop Supplies

Parts Issued

Quantity

Battery	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 139.86

Total: 212.86

6/30/2026
5:07:15 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 2202318 **Meter:** 87136 **In Date:** 03/01/2022 **Closed:** 03/03/2022
Problem: Towed in for no start , Replace missing gas cap .

Work Completed

Parts Issued

Quantity

- Charge battery fully . Test battery and charging system . Perform Alternator circuit test . R&r defective alternator and belt . Retest .

Alternator 1.00

Belt 1.00

- Replace missing fuel cap

Gas Cap 1.00

- Shop Supplies

Shop Supplies 1.00

Hours: 2.10

Comm: 0.00

Labor: 153.30 Parts: 224.66 Total: 377.96

Work Order: 2202520 **Meter:** 87136 **In Date:** 03/01/2022 **Closed:** 03/07/2022
Problem: no start

Work Completed

- Tow From: Pbia Maint. (3700 Belvedere rd, next to bldg E) To: Lv shop

Hours: 0.00

Comm: 113.00

Labor: 0.00

Parts: 0.00

Total: 113.00

Work Order: 2204168 **Meter:** 87991 **In Date:** 04/19/2022 **Closed:** 04/28/2022
Problem: PM Service.

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service

22" Wiper Blade 2.00

- Rotated and balanced all 4 tires. Nitrogen filled all tires.

Napagold Oil Filter 1.00

- Inspect and serviced winch

Napa Quart 5w20 7.00

- Dignose oil leak found to have leaking valve cover gaskets. R and R valve cover gaskets. Clean excess oil from engine.

Napagold Fuel Filter 1.00

Napagold Air Filter 1.00

- Replaced all 8 dry rotted and bad cab mounts

White Lithium Grease 1.00

- Shop Supplies

Non-chlor Brake Clnr 3.00

Valve Cover Set Gasket 1.00

Body Mount Kit 6.00

Body Mount Kit 2.00

Shop Supplies 1.00

Hours: 16.85

Comm: 0.00

Labor: 1,230.05 Parts: 747.86 Total: 1,977.91

6/30/2026
5:07:15 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 2208097 **Meter:** 89520 **In Date:** 08/04/2022 **Closed:** 08/11/2022
Problem: Running rough and under powered A/C not cold

Work Completed

- Computer diagnose check engine light and running rough , Perform power balance test . R&r defective coils and spark plugs on 3and 8 cylinders , Clear code and retest .a/c performance test , was warm due to engine misfire shutting compressor off .

- Diagnose tire light light . Repair right front tire and balance . Nitro fill all and reset Tpms Right rear sensor inop . Remove tire and replace sensor and retrain all .

- Shop Supplies

Parts Issued

Quantity

Coil Assembly	2.00
Tpms5 Sensor Tire Pre	1.00
Spark Plug	2.00
Shop Supplies	1.00

Hours: 4.30

Comm: 0.00

Labor: 313.90

Parts: 174.83

Total: 488.73

Work Order: 2209015 **Meter:** 89871 **In Date:** 08/29/2022 **Closed:** 08/29/2022
Problem: Driver front tire goes flat.

Work Completed

- Repair left front tire and balance . Nitro fill all

- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 2.65

Total: 75.65

6/30/2026
5:07:15 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 2212563 **Meter:** 90901 **In Date:** 12/14/2022 **Closed:** 01/03/2023
Problem: PM Service. AC has been having issues they said they hit the dash for it to come on sometimes.

Work Completed

- Preventive Maint. Service
- Mount and balance 4 new tires. Nitrogen filled all tires.
- Diagnose A/c inop at times. Replaced defective blower motor.
- Diagnose tag light inop. Replaced faulty tag light socket assembly.
- Diagnose oil leak. Found to be leaking at oil filter adaptor housing. Replaced oil filter adaptor housing and cleaned excess oil from engine.
- Performed full front end alignment and road test .
- Inspect and serviced winch.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
Lt265/70/17 Tire Bfg	4.00
Non-chlor Brake Clnr	3.00
Fan Motor	1.00
License Bracket W/light	1.00
Switch Asy	1.00
Gasket	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 16.95

Comm: 0.00

Labor: 1,237.35 Parts: 1,056.11 Total: 2,293.46

Work Order: 2300203 **Meter:** 90923 **In Date:** 01/09/2023 **Closed:** 01/20/2023
Problem: AC blows hot.

Work Completed

- Diagnose A/c not cooling. Found to have leaking evaporator. Remove and replaced evaporator, accumulator, and orifice tube assemblies. Recharged freon to factory spec.

- Shop Supplies

Parts Issued

Quantity

Tube Filter	1.00
Evapotator Core	1.00
Accumulator	1.00
O Ring	2.00
Seal Kits	2.00
Rapid Seal Kit	1.00
Freon Lv Shop 1	2.00
Shop Supplies	1.00

Hours: 12.40

Comm: 0.00

Labor: 905.20 Parts: 315.56 Total: 1,220.76

6/30/2026
5:07:15 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 2306664 **Meter:** 92575 **In Date:** 07/06/2023 **Closed:** 07/12/2023
Problem: PM Service

Work Completed

- Preventive Maint. Service
- R&r Two Broken Toggle Light Switches For Front And Alley Lamps. R&r Failed Dome Lamps And High Mount Lamp Bulbs.
- R&r Driver Front Sealed Beam Headlamp Due To Water Inside.
- Replace Missing Lock Clip For Winch Cable Roller. Service Power Winch.
- Rotate And Balance Four Tires.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
Napagold Fuel Filter	1.00
Used Fire X Refurbished	1.00
Boxed Miniatures	3.00
Boxed Miniatures	4.00
Toggle Switch	2.00
Halogen Sealed Beams	1.00
Shop Supplies	1.00

Hours: 6.45

Comm: 0.00

Labor: 470.85

Parts: 93.35

Total: 564.20

Work Order: 2312565 **Meter:** 94154 **In Date:** 12/21/2023 **Closed:** 02/08/2024
Problem: Early PM and Whelen light bar stays on when turned off on backside of it only way 2 shut off is taking battery cable off

Work Completed

- Preventive Maint. Service
- Repaired Lr tire. Rotated and balanced all 4 tires. Nitrogen filled all tires.
- battery tested bad. Charged battery fully and retested bad. Replaced bad battery.
- Diagnose light bar staying on. Found to have faulty circuit board in lightbar. R&r faulty circuit board.
- Replaced Pass side head light due to moisture in light.
- Inspect and serviced winch.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Battery	1.00
Halogen Sealed Beams	1.00
Circuit Board - Liberty Lightbar	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 9.25

Comm: 0.00

Labor: 675.25

Parts: 766.49

Total: 1,441.74

6/30/2026
5:07:15 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 2404273 **Meter:** 94922 **In Date:** 04/30/2024 **Closed:** 05/09/2024
Problem: Truck running very rough dropping off today.

Work Completed

Parts Issued

Quantity

- Scan diagnose, Perform cylinder contribution test, #6 and #7 cylinders dead. R&r both coils. Repair threads for coils, Koeo, Koer, clear codes and test drive.

Coil Assembly	2.00
Shop Supplies	1.00

- Shop Supplies

Hours: 2.50 Comm: 0.00 Labor: 182.50 Parts: 128.69 Total: 311.19

Work Order: 2405544 **Meter:** 95175 **In Date:** 06/05/2024 **Closed:** 06/13/2024
Problem: AC blowing hot air, inspect and make sure AC is working properly.

Work Completed

Parts Issued

Quantity

- Computer diagnose check engine light , P0430 . Perform test . R&r defective catalytic converter assembly . Clear codes and retest

Converter	1.00
Freon Lv Shop 1	2.00

- Computer diagnose check engine code P115e also . Clean throttle body and clear code and retest .

- A/c performance test ,. recover and evacuate and vacuum system and retest .

Hours: 6.00 Comm: 0.00 Labor: 438.00 Parts: 2,365.74 Total: 2,803.74

6/30/2026
5:07:15 PM

Palm Beach County Fleet Management Asset Maintenance History
K11816 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Crew Cab

Work Order: 2411606 **Meter:** 96718 **In Date:** 12/09/2024 **Closed:** 12/26/2024
Problem: PM Service.

Work Completed

- perform Preventive Maint. Service
- perform balance rotate nitro fill and tpms relearn
- inspect and service winch
- driver front turnsignal inop, performed diag, found bulb to be faulty, confirmed power to socket with known working bulb.r&r bulb .driver side work light inop due to moisture intrusion, R&r light .pass rear brake light ino R&r light
- heater core hose leaking, R&r both hoses, top off coolant and bleed system.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Used Fire X Refurbished	2.00
Pintle Pin W/clip	1.00
Wiper Blade	2.00
Boxed Miniatures	1.00
Lamp	1.00
Led Sup Mdl 44 42 Dio	1.00
Peak Global Antifrz	2.00
Hose Assy	1.00
Hose Assy	1.00
Shop Supplies	1.00

Hours: 7.75

Comm: 0.00

Labor: 565.75

Parts: 306.50

Total: 872.25

Work Order: 2501280 **Meter:** 96748 **In Date:** 02/07/2025 **Closed:** 02/21/2025
Problem: Tow- Asset on lent mode. Doesn;t go over 5 MPH. Tow

Work Completed

- Cel, limp mode. coolant temp low. replace thermostat, clear codes and test drive.
- Shop Supplies

Parts Issued

Quantity

Thermostat	1.00
Seal	1.00
Shop Supplies	1.00

Hours: 1.50

Comm: 0.00

Labor: 109.50

Parts: 24.85

Total: 134.35

Work Order: 2501448 **Meter:** 96653 **In Date:** 02/07/2025 **Closed:** 02/14/2025
Problem: Tow- Asset on lent mode. Doesn;t go over 5 MPH. Tow

Work Completed

- Tow From: Pbia Maintenance yard building C To: Fleet Vista Lv Shop

Hours: 0.00

Comm: 118.80

Labor: 0.00

Parts: 0.00

Total: 118.80

Total Hours: 396.60

Total Labor: 25,816.20

Total Comm: 1,221.80

Total Parts: 22,902.88