

**Palm Beach County Fleet Management
Asset Maintenance History**

10169432 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Crew Cab

Workorder: 743578 **Meter:** 0 **In Date:** 09/05/2007 **Closed:** 09/05/2007
Problem: PRE-DELIVERY INSPECTION

- Pre-delivery Inspection
- Minor Weld Repair Or Machining.

Hours 3.00 Labor: 165.00 Parts: 0.00 Total: 165.00
:

Workorder: 836122 **Meter:** 2080 **In Date:** 03/27/2008 **Closed:** 04/02/2008
Problem: P.M. SERVICE.BROKEN WINDSHIELD.

- Pm Service
- Pin Point Test,remove Left Front Marker Light To Test And Replace Strobe Bulb.
- Service Winch,test Operation Of Winch And Inspect /lube Cable And Rollers
- Service Liftgate,test Operationand Lube.
- Shop Supplies

Parts List	Qty
Shop Supplies	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
5w20 Engine Oil	7.00
1066 White Lithium (crc 05037)	1.00
S30hacp Strobe Bulb For Kit S660cccc	1.00

Hours 5.25 Labor: 315.00 Parts: 58.06 Total: 373.06
:

Workorder: 836424 **Meter:** 2080 **In Date:** 04/02/2008 **Closed:** 04/03/2008
Problem: REPLACE CRACKED WINDSHEILD

- Set Up Windshield Replacement
- Replace Windshield
- Shop Supplies

Parts List	Qty
Shop Supplies	1.00

Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00
:

Workorder: 848193 **Meter:** 6074 **In Date:** 12/15/2008 **Closed:** 12/30/2008
Problem: P.M SERVICE

- Pm Service
- Check Lights,diag L/f Strobe Light Not Flashing.remove Lins To Replace Defective Strobe Light.
- Service Winch.
- Service Rear Tommy Lift.
- Rotate And Hi Speed Balance 4 Tires,nitrofill Tires.
- To/fr Dealer For R/f Outer Door Handle & Lower Front Seat Cover Repairs.
- Shop Supplies

Parts List	Qty
Shop Supplies	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
5w20 Engine Oil	7.00
1066 White Lithium (crc 05037)	1.00
31-20 Wiper Blades 20" Blade	2.00
S30hacp Strobe Bulb For Kit S660cccc	1.00
66br Clear Silicone	1.00

Hours 8.25 Labor: 495.00 Parts: 98.61 Total: 593.61
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 937558 **Meter:** 9208 **In Date:** 05/08/2009 **Closed:** 05/12/2009
Problem: PM SERVICE.

	Parts List	Qty
- Pm Service	Shop Supplies	1.00
- Rotate And Hi Speed Balance All 4 Tires.	Ca10262 Air Filter Mtc Fa1883 Wix 49883	1.00
- Service Winch	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Service Power Lift Gate.	5w20 Engine Oil	7.00
- Shop Supplies	Wd40 Spray Lube Stock# 405540002	1.00
	5lb Firex Abc Stock# 340280001	1.00
Hours 5.75	Labor: 345.00 Parts: 94.15	Total: 439.15
:		

Workorder: 946029 **Meter:** 14182 **In Date:** 11/16/2009 **Closed:** 12/02/2009
Problem: P.M service, check strobes.

	Parts List	Qty
- P.m service.	Shop Supplies	1.00
- Test & replace R/f strobe bulb, repair wiring to L/f strobe light.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Test starting & charging system, charge & test battery, replace failed battery.	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
- Inspect & service winch.	5w20 Engine Oil	7.00
- Rotate & balance all four tires.	L0135-063 Lubriplate Chain&cable Lube,03050crc	1.00
- Inspect & service power lift gate.	Used Firex Refurbered Fire Extingshers	1.00
- Shop Supplies	31-20 Wiper Blades 20" Blade	2.00
	S30hacp Strobe Bulb For Kit S660cccc	1.00
	Group 65 Battery (mtc Bxt-65-850)	1.00
	Floor Mat Set	2.00
Hours 7.75	Labor: 465.00 Parts: 355.99	Total: 820.99
:		

Workorder: 1004396 **Meter:** 17882 **In Date:** 04/28/2010 **Closed:** 05/03/2010
Problem: P.M service, check strobe lights.

	Parts List	Qty
- P.m service.	Shop Supplies	1.00
- Test & replace L/f strobe bulb & center stop lamp bulb.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Inspect & service winch, replace damages hook.	5w20 Engine Oil	7.00
- Inspect & service power lift gate.	S30hacp Strobe Bulb For Kit S660cccc	1.00
-	Saftey Hook / 2868	1.00
- Shop Supplies		
Hours 5.55	Labor: 333.00 Parts: 66.81	Total: 399.81
:		

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1012000 **Meter:** 23090 **In Date:** 10/26/2010 **Closed:** 11/03/2010
Problem: Pm service also see notes on brake lights.

<ul style="list-style-type: none"> - Perform pm service. - Test and replace failed left tail lamp bulb with new. drill out rivets for clearance light bar and secure loose ground wire. - Inspect and service power tail gate lift. - Inspect and service power winch. - Rotate and balance all four tires. - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left" colspan="2">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> <tr><td>1372 Oil Filter Frm Ph2 Wix 51372</td><td></td><td align="right">1.00</td></tr> <tr><td>Ca10262 Air Filter Mtc Fa1883 Wix 49883</td><td></td><td align="right">1.00</td></tr> <tr><td>G10166 Fuel Filter Mtc Fg1083 Wix 33243</td><td></td><td align="right">1.00</td></tr> <tr><td>5w20 Engine Oil</td><td></td><td align="right">7.00</td></tr> <tr><td>31-20 Wiper Blades 20" Blade</td><td></td><td align="right">2.00</td></tr> <tr><td>Used Firex Refurbed Fire Extingshers</td><td></td><td align="right">1.00</td></tr> <tr><td>3157 Tail Light Bulbs</td><td></td><td align="right">1.00</td></tr> </tbody> </table>	Parts List		Qty	Shop Supplies		1.00	1372 Oil Filter Frm Ph2 Wix 51372		1.00	Ca10262 Air Filter Mtc Fa1883 Wix 49883		1.00	G10166 Fuel Filter Mtc Fg1083 Wix 33243		1.00	5w20 Engine Oil		7.00	31-20 Wiper Blades 20" Blade		2.00	Used Firex Refurbed Fire Extingshers		1.00	3157 Tail Light Bulbs		1.00
Parts List		Qty																										
Shop Supplies		1.00																										
1372 Oil Filter Frm Ph2 Wix 51372		1.00																										
Ca10262 Air Filter Mtc Fa1883 Wix 49883		1.00																										
G10166 Fuel Filter Mtc Fg1083 Wix 33243		1.00																										
5w20 Engine Oil		7.00																										
31-20 Wiper Blades 20" Blade		2.00																										
Used Firex Refurbed Fire Extingshers		1.00																										
3157 Tail Light Bulbs		1.00																										
Hours 6.75 :	Labor: 405.00 Parts: 52.92 Total: 457.92																											

Workorder: 1106389 **Meter:** 28144 **In Date:** 06/17/2011 **Closed:** 06/23/2011
Problem: Pm service.

<ul style="list-style-type: none"> - P.m. Service. - Replace both front strobe light bulb. - Inspect and service winch. - Inspect and service lift gate. - Rotate and balance all tires. - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left" colspan="2">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> <tr><td>1372 Oil Filter Frm Ph2 Wix 51372</td><td></td><td align="right">1.00</td></tr> <tr><td>G10166 Fuel Filter Mtc Fg1083 Wix 33243</td><td></td><td align="right">1.00</td></tr> <tr><td>5w20 Engine Oil</td><td></td><td align="right">7.00</td></tr> <tr><td>D3tz2457b Brake Pedal Pad</td><td></td><td align="right">1.00</td></tr> <tr><td>31-20 Wiper Blades 20" Blade</td><td></td><td align="right">2.00</td></tr> <tr><td>S30hacp Strobe Bulb For Kit S660cccc</td><td></td><td align="right">2.00</td></tr> </tbody> </table>	Parts List		Qty	Shop Supplies		1.00	1372 Oil Filter Frm Ph2 Wix 51372		1.00	G10166 Fuel Filter Mtc Fg1083 Wix 33243		1.00	5w20 Engine Oil		7.00	D3tz2457b Brake Pedal Pad		1.00	31-20 Wiper Blades 20" Blade		2.00	S30hacp Strobe Bulb For Kit S660cccc		2.00
Parts List		Qty																							
Shop Supplies		1.00																							
1372 Oil Filter Frm Ph2 Wix 51372		1.00																							
G10166 Fuel Filter Mtc Fg1083 Wix 33243		1.00																							
5w20 Engine Oil		7.00																							
D3tz2457b Brake Pedal Pad		1.00																							
31-20 Wiper Blades 20" Blade		2.00																							
S30hacp Strobe Bulb For Kit S660cccc		2.00																							
Hours 6.75 :	Labor: 405.00 Parts: 128.15 Total: 533.15																								

Workorder: 1113304 **Meter:** 32359 **In Date:** 12/20/2011 **Closed:** 01/03/2012
Problem: P.M. service.

<ul style="list-style-type: none"> - P.m. Service. - R&r right tail light assemble and replace parp light bulb. - Rotate and balance all tires. - Inspect and service lift gate.inspect and service winch. - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left" colspan="2">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> <tr><td>1372 Oil Filter Frm Ph2 Wix 51372</td><td></td><td align="right">1.00</td></tr> <tr><td>1066 White Lithium (crc 05037)</td><td></td><td align="right">1.00</td></tr> <tr><td>5w20 Engine Oil</td><td></td><td align="right">7.00</td></tr> <tr><td>Used Firex Refurbed Fire Extingshers</td><td></td><td align="right">1.00</td></tr> <tr><td>31-20 Wiper Blades 20" Blade</td><td></td><td align="right">2.00</td></tr> <tr><td>D3tz2457b Brake Pedal Pad</td><td></td><td align="right">1.00</td></tr> <tr><td>4114k Bulb (acd)</td><td></td><td align="right">1.00</td></tr> </tbody> </table>	Parts List		Qty	Shop Supplies		1.00	1372 Oil Filter Frm Ph2 Wix 51372		1.00	1066 White Lithium (crc 05037)		1.00	5w20 Engine Oil		7.00	Used Firex Refurbed Fire Extingshers		1.00	31-20 Wiper Blades 20" Blade		2.00	D3tz2457b Brake Pedal Pad		1.00	4114k Bulb (acd)		1.00
Parts List		Qty																										
Shop Supplies		1.00																										
1372 Oil Filter Frm Ph2 Wix 51372		1.00																										
1066 White Lithium (crc 05037)		1.00																										
5w20 Engine Oil		7.00																										
Used Firex Refurbed Fire Extingshers		1.00																										
31-20 Wiper Blades 20" Blade		2.00																										
D3tz2457b Brake Pedal Pad		1.00																										
4114k Bulb (acd)		1.00																										
Hours 6.25 :	Labor: 375.00 Parts: 61.87 Total: 436.87																											

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1206709 **Meter:** 36902 **In Date:** 07/18/2012 **Closed:** 08/16/2012
Problem: Pm service and check over all lights.

	Parts List	Qty
- P.m. Service.		
- Replace left brake light bulb and tag light bulb.	Shop Supplies	1.00
- Replace and balance four tires.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Inspect and service lift gate.	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
- Inspect and service winch.	Ca10262 Air Filter Mtc Fa1883 Wix 49883	1.00
- Complete front wheel alignment.test drive.	5w20 Engine Oil	7.00
- Shop Supplies	31-20 Wiper Blades 20" Blade	2.00
	Tag Light	1.00
	3157 Tail Light Bulbs	1.00
	179535492 Lt265/70r17 Wrangler Sr-a E	4.00
	Tire Disposal Fee	4.00
	Tr416 Valve Stem	4.00
Hours 9.75	Labor: 585.00	Parts: 951.19
:		Total: 1,536.19

Workorder: 1301156 **Meter:** 38210 **In Date:** 01/31/2013 **Closed:** 02/20/2013
Problem: Pm service.

	Parts List	Qty
- P.m. Service		
- Test battery and charging system.recharge and retest battery,fail load test.replace defective battery.	5w20 Engine Oil	7.00
- Diagnose a/c blower inop on low speeds.replace defective blower resistor.	1372 Oil Filter	1.00
- Replace leaking right rear axle seal.check rear differential fluid level.	31-20 Wiper Blades 20	2.00
- Inspect and service lift gate.inspect and service winch.disassemble winch and clean rust from planetary gears and drum.lube gears and re-assemble.	Used Firex Refurbed F	1.00
- Rotate and balance all tires.	Blower Resistor	1.00
- Shop Supplies	Base Mount Hot Wire	1.00
	Rear Seal	1.00
	Battery 65	1.00
	Shop Supplies	1.00
Hours 12.75	Labor: 765.00	Parts: 262.25
:		Total: 1,027.25

Workorder: 1309381 **Meter:** 39596 **In Date:** 09/16/2013 **Closed:** 09/30/2013
Problem: Pm service.

	Parts List	Qty
- P.m. Service.		
- Replace both head lamps and left rear brake lamp bulb.	5w20 Engine Oil	7.00
- Inspect and service winch.	Napagold Oil Filter	1.00
- Inspect and service lift gate.	31-20 Wiper Blades 20	2.00
- Rotate and balance all tires.	Napagold Fuel Filter	1.00
- Shop Supplies	Bigg Degreaser	1.00
	Halogen Lamp	2.00
	4114k Bulb Acd	1.00
	Shop Supplies	1.00
Hours 7.00	Labor: 420.00	Parts: 71.90
:		Total: 491.90

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1402103 **Meter:** 40559 **In Date:** 03/04/2014 **Closed:** 03/13/2014
Problem: Pm service

- P.m. Service.	Parts List	Qty
- Resurface front brake rotors,replace front pads and calipers.flush and bleed system.	5w20 Engine Oil	7.00
- Inspect and service winch.	Napagold Oil Filter	1.00
- Inspect and service lift gate.	Wiper Blade	2.00
- Rotate and balance tires.	Used Fire X Refurbished	1.00
- Shop Supplies	Pads	1.00
	2232 Brake Fluid Quar	2.00
	Brake Cleaner	1.00
	Caliper w/ Hardware - Left Front (eclips	1.00
	Caliper w/ Hardware - Right Front (eclip	1.00
	Shop Supplies	1.00
Hours 10.25	Labor: 615.00	Parts: 297.61
:		Total: 912.61

Workorder: 1404411 **Meter:** 41154 **In Date:** 05/06/2014 **Closed:** 05/20/2014
Problem: Fabricate and install fuel transfer tank that was remove from 10152299 to bed and wiring.

- Fabricate and install auxiliary bed mounted fuel tank,pump and wiring harness to bed of vehicle and secure.test for operation.tank was removed from asset#10152299	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 2.00
:		Total: 242.00

Workorder: 1410236 **Meter:** 46152 **In Date:** 10/10/2014 **Closed:** 10/31/2014
Problem: P.M. service and check lights and request trailer brake controler.

- Pm service	Parts List	Qty
- Test and replace defective left seal beam headlamp.	Presto Pin 5 32	1.00
- Install trailer brake controller.fabricate wiring as needed.replace trailer harness receptacle.repair wiring.test and replace bad tow/haul switch.	Lever	1.00
- Perform transmission flush service.	Syn-atf Trans Fluid S	18.00
- Inspect and service auxiliary fuel tank.	Napagold Fuel Filter	1.00
- Inspect and service power liftgate.	Brake Control	1.00
- Inspect and service winch.	Jumper	1.00
- Rotate and balance all four tires.	Fmx-30 Fuse	1.00
- Shop Supplies	5w20 Engine Oil	7.00
	Napagold Oil Filter	1.00
	Napagold Fuel Filter	1.00
	Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Pintle Pin W/chain	1.00
	Halogen Lamp	1.00
	Female Conn Socket	1.00
	Shop Supplies	1.00
Hours 11.75	Labor: 705.00	Parts: 340.63
:		Total: 1,045.63

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1503064 **Meter:** 52105 **In Date:** 03/25/2015 **Closed:** 04/14/2015
Problem: Pm service.Ac not cold.Check engine light on.

	Parts List	Qty
- Pm service.		
- Test and replace defective right front strobe lamp bulb.	5w20 Engine Oil	7.00
- Ac performance test and leak test.tighten schrader valve.evacuate and recharge system to specs.retest on.	Napagold Oil Filter	1.00
	Napagold Air Filter	1.00
- Diagnose for check engine light on.code P0300.replace all eight defective sparkplugs.had to extract six broke sparkplugs with special tool.	Wiper Blade	2.00
	5068 Penetrating Oil	1.00
- Perform induction cleaning service and flush injectors.	Hide Away Strob	1.00
- Inspect and service auxiliary fuel tank.	R134a Lv Shop 2	2.00
- Replace two tires.rotate and balance all four.	Spark Plug	8.00
- Inspect and service power liftgate.	Ka8a Throttle Body- U	1.00
- Inspect and service power winch.	408 Fuel Injection Cl	1.00
- Shop Supplies	Napagold Fuel Filter	1.00
	179535492 Lt265-70r17	2.00
	Tr416 Valve Stem	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 17.65	Labor: 1,059.00	Parts: 891.02
:	0	Total: 1,950.02

Workorder: 1504507 **Meter:** 52136 **In Date:** 04/08/2015 **Closed:** 05/01/2015
Problem: damage to rgty frt fender, door & rgt side of bed

- damage to rgty frt fender, door & rgt side of bed	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

Workorder: 1510642 **Meter:** 53987 **In Date:** 10/21/2015 **Closed:** 11/16/2015
Problem: Pm service.Oil leaks when operating tailgate.

	Parts List	Qty
- Pm service.		
- Replace two tire.rotate and balance all four.	5w20 Engine Oil	7.00
- Inspect and service auxiliary fuel system.	Napagold Oil Filter	1.00
- Inspect oil leak at lift gate pistons.r&i both cylinders for repairs.apply heat necessary to remove pins.inspect and service liftgate.add oil to system.	Napagold Fuel Filter	1.00
	20" Wiper Blade	2.00
- Inspect electrical circiut to right back up lamp inop.replace defective bulb.	Washer Fluid Concentr	1.00
	179535492 Lt265-70r17	2.00
- Inspect and service front winch.	Napagold Fuel Filter	1.00
- Shop Supplies	Bulb	1.00
	Lift Gate Piston Cylinders	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 11.25	Labor: 675.00	Parts: 1,306.89
:		Total: 1,981.89

Workorder: 1512850 **Meter:** 54924 **In Date:** 12/21/2015 **Closed:** 12/29/2015
Problem: repair tail light

	Parts List	Qty
- Replace rear brake turn signal bulb		
	Bulb	2.00
Hours 0.50	Labor: 30.00	Parts: 1.50
:		Total: 31.50

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1601245 **Meter:** 56122 **In Date:** 02/04/2016 **Closed:** 02/11/2016

Problem: Check engine light on

- Diagnose check engine light,p0303.test and replace defectine #3 coil.clear codes and test drive.	Parts List	Qty
	Coil Assembly	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 2.50	Labor: 150.00	Parts: 77.90
:		Total: 227.90

Workorder: 1603382 **Meter:** 57382 **In Date:** 03/31/2016 **Closed:** 04/06/2016

Problem: Both rear brake lamps inop.

- Check and inspect electrical circuit to both brake lamp inop.ok.replace both lamp sockets.burnt.	Parts List	Qty
	Stp Trn TI Lgt Socket	2.00
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 15.11
:		Total: 75.11

Workorder: 1606995 **Meter:** 58906 **In Date:** 07/12/2016 **Closed:** 07/25/2016

Problem: P.M. Service.

- P.m. Service.	Parts List	Qty
- Replace both dome light bulbs.replace stop lamp bulb and socket.	Napagold Oil Filter	1.00
	5w20 Engine Oil	7.00
- Replace both rear bump stops.	20" Wiper Blade	2.00
- Inspect and service aux. fuel tank.	Washer Fluid Concentr	1.00
- Pressure test and inspect cooling system.flush and refill system.	Mac Wite Lithium Gres	1.00
	Used Fire X Refurbished	1.00
- Service transmission.flush and refill system.	Bulb	2.00
- Inspect and service winch.	Stp Trn TI Lgt Socket	1.00
- Rotate and balance all tires.	Bulb	1.00
- Shop Supplies	Bumper	2.00
	Napagold Fuel Filter	1.00
	Napagold Air Filter	1.00
	Coolant Ford Gold	2.00
	Syn-atf Trans Fluid S	20.00
	Atp Filter	1.00
	Macs Chain Cable Lube	1.00
	Shop Supplies	1.00
Hours 11.75	Labor: 705.00	Parts: 320.02
:		Total: 1,025.02

Workorder: 1608399 **Meter:** 59186 **In Date:** 08/15/2016 **Closed:** 08/24/2016

Problem: remove Z206693 and install customer supplied saddle tank

- Remove leaking saddle tank. Install customer supplied used tank. swap pumps wire in	Parts List	Qty
	Napagold Fuel Filter	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 8.00	Labor: 480.00	Parts: 6.95
:		Total: 486.95

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1611827 **Meter:** 60850 **In Date:** 11/16/2016 **Closed:** 11/30/2016
Problem: P.M. service and had to jump start in A.M. and check engine light on.

	Parts List	Qty
- P.m. Service.		
- Test battery and charging system.replace bad battery.	5w20 Engine Oil	7.00
- Replace missing brake pedal pad.	Napagold Oil Filter	1.00
- Inspect and service aux fuel system.	20" Wiper Blade	2.00
- Replace broken pintle pin.	Washer Fluid Concentr	1.00
- Replace front suspension bump stops.	Battery	1.00
- Inspect and service winch.	Pedal Pad	1.00
- Inspect and service liftgate.	Napagold Fuel Filter	1.00
- Shop Supplies	Pintle Pin W/clip	1.00
	bumper	2.00
	Shop Supplies	1.00
Hours 7.75	Labor: 465.00	Parts: 183.26
:		Total: 648.26

Workorder: 1613047 **Meter:** 61332 **In Date:** 12/27/2016 **Closed:** 01/03/2017
Problem: Tow in,no start.

	Parts List	Qty
- Check starting system.replace defective starter.		
- Shop Supplies	Starter Motorcraft	1.00
	Shop Supplies	1.00
Hours 1.50	Labor: 90.00	Parts: 167.33
:		Total: 257.33

Workorder: 1613124 **Meter:** 61235 **In Date:** 12/27/2016 **Closed:** 12/28/2016
Problem: No start

- Tow From: 3691 Oswego Ave Wpb			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1706237 **Meter:** 65481 **In Date:** 06/23/2017 **Closed:** 07/10/2017
Problem: P.M. Service.

	Parts List	Qty
- P.m. service and replace brake pedal pad.		
- Inspect and service aux fuel tank.	5w20 Engine Oil	7.00
- Remove and replace six body mount bushings with new due to wear and coming apart.	Napagold Oil Filter	1.00
	Washer Fluid Concentr	1.00
- Inspect and service rear parking brakes.resurface both rear rotors.replace worn rear brake pads and calipers with new.flush and bleed brake system.road test.	Used Fire X Refurbished	1.00
	Pedal Pad	1.00
- Replace blown high mount stop lamp bulbs and tag lamp led lamp with base.replace faulty trailer plug connector and rewire with new.replace faulty trailer controller with new and rewire.	20" Wiper Blade	2.00
	Stg Wheel Cov - Ford	1.00
- Inspect and service power tailgate.	Napagold Fuel Filter	1.00
- Rotate and balance four tires.	Napagold Fuel Filter	1.00
- Inspect and service power winch.	Body Mount Kit	2.00
- Shop Supplies	Body Mount Kit	4.00
	Caliper w/ Hardware - Left Rear (eclipse	1.00
	Caliper w/ Hardware - Right Rear (eclips	1.00
	Rear Brake Pads	1.00
	B Fluid Dot 3-32oz	1.00
	Bulb	3.00
	License Lamp	1.00
	Lamp	1.00
	Non-chlor Brake Clnr	1.00
	Rear Pads	1.00
	Caliper Washer	4.00
	Bulb	3.00
	trailer plug	1.00
	Brake Control	1.00
	Shop Supplies	1.00
Hours 19.75	Labor: 1,185.0	Parts: 1,154.80
:	0	Total: 2,339.80

Workorder: 1801987 **Meter:** 70180 **In Date:** 02/21/2018 **Closed:** 03/19/2018
Problem: P.M. Service.Check engine light on.

	Parts List	Qty
- P.m. service.		
- Inspect and service auxiliary fuel system.	Napagold Oil Filter	1.00
- Inspect and replace both head lamp bulb. Test and replace left front strobe light Test and replace lighter fuse and right rear brake light bulb.	20" Wiper Blade	2.00
	Washer Fluid Concentr	1.00
- Inspect and service winch.	Napa Hydraulic Filtr	1.00
- Inspect and service power liftgate.	Halogen Sealed Beams	2.00
- Rotate and high speed balance all four wheels .nitro fill all.	5w20 Engine Oil	7.00
- Transport to and from dealer for catalytic converter replacement per recall 10m05.	Hide Away Strob	1.00
- Shop Supplies	Fmx-20 Fuse	1.00
	Bulb	1.00
	Shop Supplies	1.00
Hours 10.25	Labor: 615.00	Parts: 108.82
:		Total: 723.82

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1809523 **Meter:** 71067 **In Date:** 09/14/2018 **Closed:** 10/04/2018
Problem: PM Service, Check A/C, Check safety flasher lights.

	Parts List	Qty
- P.m. service.		
- Inspect and service auxilary fuel tank . Replace dry rotten hose .	Napagold Oil Filter	1.00
- Check A/c . R&r defective blower resistor .	5w20 Engine Oil	7.00
- Pinpoint test strobe lamp circuits . Repair pinched shorted harness under left front floor mat . Repair harness and replace blow fuse . Retest . Test and replace washer pump and washer jets .	20" Wiper Blade	2.00
- R&r both rear shocks due worn out bushings.	Washer Fluid Concentr	1.00
- R&r both front inner and outer axle seals . Service front differential.	Used Fire X Refurbished	1.00
- Replace all four worn out tires and balance . Nitrogen fill tires.	2-pk 3in Spot Mirror	1.00
- Inspect and service winch.	3/4" X 12 ' Hardwall UI330&ulc	1.00
- Inspect and service power liftgate .	Napa Hydraulic Filtr	1.00
- Complete front end alignment and road test.	Blower Resistor	1.00
- Shop Supplies	Washer Pump	1.00
	Washer Nozzle	2.00
	Gas Grande Shock	2.00
	Front Inner Diff Seal	2.00
	Left Axle Seal	2.00
	Left Axle Out Seal	2.00
	Non-chlor Brake Clnr	1.00
	Ptex Ultra Grey 3oz	1.00
	Napa Gear 80w-90 Qt	3.00
	Tr416 Valve Stem	4.00
	Shop Supplies	1.00
	Lt245/75r17 Tire	4.00
	Tire Disposal Fee	4.00

Hours 22.55 Labor: 1,510.8 Parts: 1,260.97 Total: 2,771.82
: 5

Workorder: 1812117 **Meter:** 71599 **In Date:** 11/28/2018 **Closed:** 11/28/2018
Problem: Transition Prep Charge

- Transition Prep Charge
Hours 2.00 Labor: 134.00 Parts: 0.00 Total: 134.00
: