

**Palm Beach County Fleet Management  
Asset Maintenance History**

**10185050     2011 CHEVROLET SILVERADO Pickup, 1/2 Ton, Ext Cab, 4X4**

**Workorder:** 1104894     **Meter:** 0     **In Date:** 05/09/2011     **Closed:** 05/09/2011  
**Problem:** Pre Delivery Inspection

- Pre Delivery Inspection
- Wash Vehicle

Hours 3.00     Labor: 180.00     Parts: 0.00     Total: 180.00  
 :

**Workorder:** 1105091     **Meter:** 285     **In Date:** 05/12/2011     **Closed:** 05/12/2011  
**Problem:** 1 - Wash ticket(s) issued

- 1 - Wash ticket(s) issued

Hours 0.00     Labor: 0.00     Parts: 0.00     Total: 0.00  
 :

**Workorder:** 1109325     **Meter:** 3894     **In Date:** 08/31/2011     **Closed:** 09/07/2011  
**Problem:** Horn inop

- Diagnose horn inop.pin point test and replace failed horn assembly with new.

<b>Parts List</b>	<b>Qty</b>
Shop Supplies	1.00
Horn	1.00

- Shop Supplies

Hours 1.00     Labor: 60.00     Parts: 59.06     Total: 119.06  
 :

**Workorder:** 1111746     **Meter:** 5518     **In Date:** 11/01/2011     **Closed:** 11/09/2011  
**Problem:** Pm service.

- P.m. Service.
- Service and adjust rear brakes.
- Inspect and service winch.
- Rotate and balance all tires.
- Shop Supplies

<b>Parts List</b>	<b>Qty</b>
Big G Degreaser Stock# 485180002	1.00
Shop Supplies	1.00
Ph10060 Oil Filter Acd Pf48 Wix 57060	1.00
10-9050 Oil Dexos1 5w30	6.00

Hours 5.75     Labor: 345.00     Parts: 45.08     Total: 390.08  
 :

**Workorder:** 1204244     **Meter:** 10817     **In Date:** 05/03/2012     **Closed:** 05/16/2012  
**Problem:** Pm service also service brake warning light on see notes.

- P.m. Service.
- Replace worn out rear brake shoes,resurface rear brake drums.clean sand and mud from hardware.tighten right front hose bolt on caliper,leaking.refill and bleed brake system.
- Replace broken transmission fill tube,top off fluid.
- Inspect winch.remove gear housing assemble and clean rust and water.lube gears and service winch.
- Rotate and balance all tires.
- Shop Supplies

<b>Parts List</b>	<b>Qty</b>
Shop Supplies	1.00
Ph10060 Oil Filter Acd Pf48 Wix 57060	1.00
6678 Air Filter Frm Ca8755a Wix 46678	1.00
09997 Brake Clean	1.00
Rear Brake Shoes	1.00
10-9050 Oil Dexos1 5w30	6.00
Syn/atf Trans Fluid Synthetic	2.00
1401 Brake Fluid Brake Fluid	1.00
Trans Filler Tube	1.00
Tube Seal	1.00

Hours 11.75     Labor: 705.00     Parts: 344.14     Total: 1,049.14  
 :

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

**Workorder:** 1211260      **Meter:** 15796      **In Date:** 11/20/2012      **Closed:** 12/11/2012  
**Problem:** Pm service.

- P.m. Service.	<b>Parts List</b>	<b>Qty</b>
- Replace leaking battery.(leaking at positive post).test charging system.	Drum	2.00
- Resurface front rotors,replace worn out brake pads.clean mud and sand from calipers and lube slides.replace worn out brake drums and shoes.replace broken left side parking brake cable.flush and bleed	Reman Brake Shoes	1.00
	Wheel Cyl	2.00
- Install new extinguisher with bracket.	Rear Parking Cable	1.00
- Inspect and service winch.remove and clean power and ground cables,corroded.	2232 Brake Fluid Quar	3.00
- Rotate and balance all tires.	Used Firex Refurbed F	1.00
- Shop Supplies	5lb Bracket Firex Sto	1.00
	Battery	1.00
	Dexos 5w30	6.00
	Ph10060 Oil Filter Ac	1.00
	Brake Pads	1.00
	Wipers	2.00
	Wipers	2.00
	Shop Supplies	1.00
Hours 15.25	Labor: 915.00	Parts: 822.02
:		Total: 1,737.02

---

**Workorder:** 1300108      **Meter:** 15796      **In Date:** 12/06/2012      **Closed:** 01/03/2013  
**Problem:** damage to rgt side of bed & rgt frt bumper

- damage to rgt side of bed & rgt frt bumper

Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

---

**Workorder:** 1305901      **Meter:** 19823      **In Date:** 06/13/2013      **Closed:** 06/24/2013  
**Problem:** P.M. service.

- Perform pm service.	<b>Parts List</b>	<b>Qty</b>
- Diagnose for oil leak on right rear brake area.inspect and replace failed right rear axle seal with new and service rear differential.	Dexos 5w30	7.00
- Rotate and balance all four tires.	Napagold Oil Filter	1.00
- Perform rear drum brake service and adjust brake shoes.	Accufit Beam	2.00
- Inspect and service power winch.	Napagold Air Filter	1.00
- Shop Supplies	12345841 Gear Oil Syn	3.00
	Napa Oil Seal	1.00
	Shop Supplies	1.00
Hours 8.75	Labor: 525.00	Parts: 154.30
:		Total: 679.30

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1400429	<b>Meter:</b> 25619	<b>In Date:</b> 01/14/2014	<b>Closed:</b> 01/31/2014
<b>Problem:</b> P.M. service.			
- P.m. Service.	<b>Parts List</b>	<b>Qty</b>	
- Resurface rear brake drums,replace rear shoes and wheel cylinders.clean mud and sand and lube backing plates.flush and bleed system.	Reman Brake Shoes	1.00	
	Dexos 5w30 Oil	7.00	
	Napagold Oil Filter	1.00	
- Replace and balance four new tires.	Accufit Beam	2.00	
- Inspect and service winch.	Used Fire X Refurbished	1.00	
- Complete wheel alignment.test drive.	Wheel Cyl	2.00	
- Shop Supplies	1401 Brake Fluid Bra	1.00	
	35x12.50r17lt Cooper Discover Stt Tire	4.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	4.00	
Hours 13.25	Labor: 795.00	Parts: 2,430.03	Total: 3,225.03
:			
<b>Workorder:</b> 1406003	<b>Meter:</b> 30412	<b>In Date:</b> 06/18/2014	<b>Closed:</b> 06/25/2014
<b>Problem:</b> Replace spent fire extinguisher			
- Replace spent fire extinguisher with new and secure.	<b>Parts List</b>	<b>Qty</b>	
	Used Fire X Refurbished	1.00	
Hours 0.30	Labor: 18.00	Parts: 15.21	Total: 33.21
:			
<b>Workorder:</b> 1407835	<b>Meter:</b> 31721	<b>In Date:</b> 08/08/2014	<b>Closed:</b> 08/22/2014
<b>Problem:</b> Pm service.			
- Pm service.	<b>Parts List</b>	<b>Qty</b>	
- Rotate and balance.	Dexos 5w30 Oil	7.00	
- Inspect and service winch.had to remove winch from inside front bumper to test and replace one defective solenoid switch.	Napagold Oil Filter	1.00	
	Napagold Air Filter	1.00	
	Repl Solenoid Term Up	1.00	
- Shop Supplies	Shop Supplies	1.00	
Hours 6.50	Labor: 390.00	Parts: 97.21	Total: 487.21
:			
<b>Workorder:</b> 1410884	<b>Meter:</b> 33707	<b>In Date:</b> 10/30/2014	<b>Closed:</b> 11/10/2014
<b>Problem:</b> Towed in for no start.			
- No power in cab or instrument cluster.diagnose and replace blower main maxi-fuse.	<b>Parts List</b>	<b>Qty</b>	
	Amg175 Fuse	1.00	
- Starter not engaging.replace defective starter assemble.	Starter	1.00	
- Shop Supplies	Shop Supplies	1.00	
Hours 2.90	Labor: 174.00	Parts: 162.31	Total: 336.31
:			
<b>Workorder:</b> 1410934	<b>Meter:</b> 33522	<b>In Date:</b> 10/30/2014	<b>Closed:</b> 10/31/2014
<b>Problem:</b> No start			
- Tow From: East side of Vista Garage To: Lv shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

**Workorder:** 1502730      **Meter:** 37251      **In Date:** 03/17/2015      **Closed:** 03/31/2015  
**Problem:** P.M. service and check trailer lights

- Pm service.	<b>Parts List</b>	<b>Qty</b>
- Inspect and replace leaking differential pinion seal and left rear axle seal.also service rear differential.	Drum Brake Whl Cylind	2.00
	Brake Drum	2.00
- Replace rear brake shoes,two rear wheel cylinders and two rear brake drums.bleed and flush brake system.test drive.	Dexos 5w30 Oil	6.00
	Napagold Oil Filter	1.00
- Inspect and service winch.	Washer Fluid Concentr	1.00
- Rotate and balance all four tires.	Accufit Beam	2.00
- Shop Supplies	Used Fire X Refurbished	1.00
	Wd40 16oz	1.00
	1qt Syngear Oil 75-90	3.00
	Ptex Ultra Black 30z	1.00
	Reman Brake Shoes	1.00
	Brake Cleaner	2.00
	1401 Brake Fluid Bra	2.00
	Real Pinion Seal	1.00
	real axle seals	1.00
	Shop Supplies	1.00

Hours 12.25      Labor: 735.00      Parts: 369.35      Total: 1,104.35  
:

---

**Workorder:** 1506962      **Meter:** 40379      **In Date:** 07/14/2015      **Closed:** 07/31/2015  
**Problem:** Stabilitrak light6 on.

- Replace both noisy front hub/wheel bearing assemble.	<b>Parts List</b>	<b>Qty</b>
- Replace both rear axle leaf spring broken spacer blocks and bent 'u' bolts.	Block Kit	1.00
	U Bolt Kit	1.00
- Steering sensor warning light on.c0710.perform alignment to correct steering wheel off center.recalibrate sensor.	hub bearingassy	2.00
- Shop Supplies	Shop Supplies	1.00

Hours 9.00      Labor: 540.00      Parts: 923.12      Total: 1,463.12  
:

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1509591	<b>Meter:</b> 41450	<b>In Date:</b> 09/23/2015	<b>Closed:</b> 10/13/2015
<b>Problem:</b> P.M. service and check tires.			
- Pm service.	<b>Parts List</b>	<b>Qty</b>	
- Replace front brake pads.resurface front brake	35x1250r17	4.00	
rotors.service both front calipers Replace defective right front	Dexos 5w30	6.00	
caliper bracket.inspect and service rear brakes.	Napagold Oil Filter	1.00	
- Replace and balance all four tires.	Accufit Beam	2.00	
- Inspect and service winch.	Washer Fluid Concentr	1.00	
- Shop Supplies	Napagold Air Filter	1.00	
	Disc Pad	1.00	
	Brake Cleaner	1.00	
	Mac Battery Protect	1.00	
	Macs Battery Cleaner	1.00	
	Bracket K	1.00	
	35x12.5r17 Nitto Grap	4.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	4.00	
Hours 10.75	Labor: 645.00	Parts: 4,000.24	Total: 4,645.24
:			
<b>Workorder:</b> 1511858	<b>Meter:</b> 41450	<b>In Date:</b> 10/20/2015	<b>Closed:</b> 11/20/2015
<b>Problem:</b> damage to rgt side of bed			
- damage to rgt side of bed			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1603743	<b>Meter:</b> 44240	<b>In Date:</b> 04/08/2016	<b>Closed:</b> 04/19/2016
<b>Problem:</b> P.M. service and check brakes feel soft.			
- P.m. Service.	<b>Parts List</b>	<b>Qty</b>	
- Diagnose Trac. light.b3894-shorted brake switch.replace	Dexos 5w30	6.00	
switch.clear code.service and adjust rear brake.diagnose	Napagold Oil Filter	1.00	
spongy pedal.replace master cylinder.flush and bleed system.	Accufit Beam	2.00	
- Test battery and charging system.replace bad battery.	Washer Fluid Concentr	1.00	
- Inspect and service winch.	Battery	1.00	
- Rotate and balance all tires.	Brake Stop Swicth	1.00	
- Shop Supplies	Master Cylinder A/c Delco	1.00	
	B Fluid Dot 3-32oz	2.00	
	Brake Cleaner	1.00	
	Shop Supplies	1.00	
Hours 12.75	Labor: 765.00	Parts: 333.61	Total: 1,098.61
:			
<b>Workorder:</b> 1604006	<b>Meter:</b> 44235	<b>In Date:</b> 04/15/2016	<b>Closed:</b> 04/15/2016
<b>Problem:</b> 50 - Wash ticket(s) issued			
- 50 - Wash ticket(s) issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1604661	<b>Meter:</b> 44604	<b>In Date:</b> 05/03/2016	<b>Closed:</b> 05/13/2016
<b>Problem:</b> Abs light on .			
- Diagnose Abs light.c0161 & C0035.perform pin point test.replace defective left front wheel speed sensor.clear codes.replace frozen rear brake cylinders,rear shoes and wornout drums.flush and bleed system.	<b>Parts List</b>	<b>Qty</b>	
- Replace left head lamp and burnt connector.	hub bearingassy	1.00	
- Replace fire extinguisher.	Head Light Bulb	1.00	
- Shop Supplies	Reman Brake Shoes	1.00	
	Drum	2.00	
	Drum Brake Whl Cylind	2.00	
	B Fluid Dot 3-32oz	1.00	
	Brake Cleaner	1.00	
	Harnesslow Beam Socket	1.00	
	Used Fire X Refurbished	1.00	
	Shop Supplies	1.00	
Hours 7.50	Labor: 450.00	Parts: 807.55	Total: 1,257.55
:			
<b>Workorder:</b> 1605064	<b>Meter:</b> 44931	<b>In Date:</b> 05/16/2016	<b>Closed:</b> 05/27/2016
<b>Problem:</b> ABS and stabiltrak light on.Head light out.			
- Diagnose Abs/traction light.c0035.perform pinpoint test.repair left front wheel speed sensor harness.	<b>Parts List</b>	<b>Qty</b>	
- Shop Supplies	Connector Abs Sensor	1.00	
	Shop Supplies	1.00	
Hours 2.00	Labor: 120.00	Parts: 44.23	Total: 164.23
:			
<b>Workorder:</b> 1611990	<b>Meter:</b> 48550	<b>In Date:</b> 11/21/2016	<b>Closed:</b> 12/12/2016
<b>Problem:</b> P.M. service.			
- P.m. Service.	<b>Parts List</b>	<b>Qty</b>	
- Resurface rear brake drums,replace shoes and wheel cylinders.flush and bleed brake system.	Stg Wheel Cov - Chevy	1.00	
- Inspect and service winch.	Floor Mat-2pc Rub Bk	1.00	
- Rotae and balance tires.	Napa Syn 5w30 Qt	6.00	
- Shop Supplies	Napagold Oil Filter	1.00	
	Napagold Air Filter	1.00	
	Accufit Beam	2.00	
	Reman Brake Shoes	1.00	
	Non-chlor Brake Clnr	1.00	
	Drum Brake Whl Cylind	2.00	
	Shop Supplies	1.00	
Hours 8.75	Labor: 525.00	Parts: 214.10	Total: 739.10
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1703950      **Meter:** 52438      **In Date:** 04/19/2017      **Closed:** 05/05/2017  
**Problem:** P.M. service and vibration on accel and brakes soft,clucking on downshifts.

	<b>Parts List</b>	<b>Qty</b>
- P.m. Service.		
- Test battery and charging system.replace bad battery.	Napa Syn 5w30 Qt	6.00
- Diagnose drive line vibration.replace drive shaft assemble.	Napagold Oil Filter	1.00
(damage at rear yoke because of frozen "u"joint.	Accufit Beam	2.00
- Replace and rewire corroded trailer plug.	Used Fire X Refurbished	1.00
- Replacev worn out front brake rotors,pad and	Battery	1.00
calipers.replace rear brake drums,wheel cylinders,shoes and	trailer plug	1.00
springs.flush and bleed system.	Brake Rotor	2.00
- Replace nerf bar,step pads missing.	L/f Brake Caliper	1.00
- Inspect and service winch.	R/f Brake Caliper	1.00
- Rotate and balance tires	Brake Drum	2.00
- Shop Supplies	Reman Brake Shoes	1.00
	Drum Brake Whl Cy lind	2.00
	lube	1.00
	B Fluid Dot 3-32oz	2.00
	Non-chlor Brake Clnr	1.00
	Drum Brake Maxi-pack	1.00
	Step Bar Pad	1.00
	Shaft A/c Delco	1.00
	Drive Shaft	1.00
	Shop Supplies	1.00
Hours 18.75	Labor: 1,125.00	Parts: 2,749.01
:	0	Total: 3,874.01

**Workorder:** 1711682      **Meter:** 55875      **In Date:** 11/29/2017      **Closed:** 01/18/2018  
**Problem:** PM Service

	<b>Parts List</b>	<b>Qty</b>
- P.m. Service.		
- Replace leaking front shocks and lift adapter bushings.	Napa Quart 5w30	7.00
- Rotate and balance tires.	Napagold Oil Filter	1.00
- Inspect and service winch.	Used Fire X Refurbished	1.00
- Complete wheel alignment.test drive.	22in Exactfit-beam	2.00
- Inspect and service rear brakes.	Front Absorber	2.00
- Shop Supplies	Fabtech Bushing Kit	1.00
	Mac Wite Lithium Gres	1.00
	Shop Supplies	1.00
	Freight Charge	1.00
Hours 13.50	Labor: 810.00	Parts: 372.50
:		Total: 1,182.50

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1807901	<b>Meter:</b> 58689	<b>In Date:</b> 08/01/2018	<b>Closed:</b> 08/15/2018
<b>Problem:</b> P.M. service.			
- P.m. service.	<b>Parts List</b>	<b>Qty</b>	
- Replace rear brake shoes, drums and wheel cylinders .	Napagold Oil Filter	1.00	
Adjust brakes and flush and bleed brake system .test drive.	Napa Syn 5w30 Qt	6.00	
- Inspect and service rear differential . Replace pinion seal and center differential center pin . Refill and test drive.	Napagold Air Filter	1.00	
- Inspect and service front differential .replace right side axle seal due to leaking . Refill differential.	Used Fire X Refurbished	1.00	
- Inspect and service transmission .replace filter and flush trans fluid.	22" Wiper Blade	2.00	
- Test starting and charging systems . Battery failed load test . R&r defective battery.	Non-chlor Brake Clnr	3.00	
- Rotate and balance all four tires. Nitrogen fill tires.	Rear Adjuster Brake	2.00	
- Shop Supplies	Spring Kit Brake Shoe	2.00	
	Wheel Cyl	2.00	
	Drum	2.00	
	Shoe Kit	1.00	
	1qt Syngear Oil 75-90	3.00	
	Diff Gasket	1.00	
	Seal	1.00	
	Napa Gear 80w-90 Qt	2.00	
	Real Pinion Seal	1.00	
	Syn-atf Trans Fluid S	18.00	
	Tram Gasket	1.00	
	Fliter Tram Kit	1.00	
	Batthey	1.00	
	Shaft	1.00	
	Bolt	1.00	
	Shop Supplies	1.00	
Hours 19.25	Labor: 1,155.0	Parts: 1,311.44	Total: 2,466.44
:	0		
<b>Workorder:</b> 1901663	<b>Meter:</b> 61100	<b>In Date:</b> 02/12/2019	<b>Closed:</b> 02/22/2019
<b>Problem:</b> P.M. service .			
- P.m. service.	<b>Parts List</b>	<b>Qty</b>	
- Inspect and service rear brakes .	Napagold Oil Filter	1.00	
- Inspect and service winch .	Napa Syn 5w30 Qt	6.00	
- Rotate and high speed balance all four tires . Nitrofill all.	22in Exactfit-beam	2.00	
- Shop Supplies	Used Fire X Refurbished	1.00	
	Shop Supplies	1.00	
Hours 5.75	Labor: 385.25	Parts: 80.57	Total: 465.82
:			
<b>Workorder:</b> 1903005	<b>Meter:</b> 61973	<b>In Date:</b> 03/19/2019	<b>Closed:</b> 04/17/2019
<b>Problem:</b> Loose lug nuts.			
- Check for loose lug nuts.r&r rear wheels and replace galled out rear rims.replace one Tpms.	<b>Parts List</b>	<b>Qty</b>	
- Shop Supplies	Tire Sensor	1.00	
	Shop Supplies	1.00	
Hours 2.00	Labor: 134.00	Parts: 98.79	Total: 232.79
:			



**Palm Beach County Fleet Management  
Asset Maintenance History**

---

**Workorder:** 1903078      **Meter:** 61543      **In Date:** 03/18/2019      **Closed:** 03/20/2019  
**Problem:** Lug nuts loose issue.

- Tow From: Beeline Hwy west of Pga Blvd To: Lv shop

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
:

---

**Workorder:** 1907999      **Meter:** 63782      **In Date:** 08/02/2019      **Closed:** 08/15/2019  
**Problem:** Vehicle message "Service Trailer Brake System" ABS light, Parking brake and traction control are on.

- P.m. service.

**Parts List**

**Qty**

- R&r defective right front hub assembly . Replace left front upper control arm .

Napagold Oil Filter

1.00

- Replace two worn tires . Rotate and balance all four tires . Nitrofill all.

Napa Syn 5w30 Qt

6.00

22in Exactfit-beam

2.00

Hub Assy

1.00

- Inspect and service winch .

Arm Assy

1.00

- Perform complete alignment and road test .

35x12.5r17 Nitto Grap

2.00

- Computer diagnose Abs light ,code C0561 and U0121 .

Shop Supplies

1.00

Test and repair broken wire near Abs module . Clear codes and retest .

Tire Disposal Fee

2.00

- Shop Supplies

Hours 14.25      Labor: 954.75      Parts: 1,581.85      Total: 2,536.60  
:

---

**Workorder:** 2002892      **Meter:** 66337      **In Date:** 03/23/2020      **Closed:** 03/23/2020  
**Problem:** Transition Prep Charge

- Transition Prep Charge

Hours 2.00      Labor: 146.00      Parts: 0.00      Total: 146.00  
: