Problem: 1061 - Pre Delivery Inspection - Pra Delivery Inspection - Wash Vehicle Hours 3.00 Labor: 180.00 Parts: 0.00 Total: 180.00 Workorder: 1307481 Meter: 2396 In Date: 0.7(26/2013) Closed: 07/31/2013 Problem: Requeast for floor mats. - Floor Mat-2pc Rub Bk 1.0 1.0 - Install new floor mats to protect carpet asper operator Parts List Qit Closed: 10/22/2013 Workorder: 1303754 Meter: 5754 In Date: 09/26/2013 Closed: 10/22/2013 Problem: Preservice. Check trailer harness. Request for new pipe rack and installation. - Closed: 10/22/2013 - P.m. Service. Parts List Qit Closed: 10/22/2013 - Fabricate and install new wiring. Napagold Oil Filter 1.0 Closed: 10/22/2013 - Fabricate and balance all tires. Brake Cleaner 1.0 Labor: 464 Female Connector 1.0 - Shop Supplies 100 Parts List Qit Ditader Rack 1.0 1.0 <th></th> <th></th> <th>10192</th> <th>2670</th> <th>2013 FORD F</th> <th>250 Pick</th> <th>kup, 3/4 Toi</th> <th>n, 4X4</th> <th></th> <th></th> <th></th>			10192	2670	2013 FORD F	250 Pick	kup, 3/4 Toi	n, 4X4			
- Wash Vehicle Hours 3.00 Labor: 180.00 Parts: 0.00 Total: 180.00 Workorder: 1307481 Meter: 2396 In Date: 07/26/2013 Closed: 07/31/2013 Problem: Requeast for floor mats. Floor Mat-2pc Rub Bk 1.0 1.0 - Install new floor mats to protect carpet asper operator Parts List Closed: 07/31/2013 - Install new floor mats to protect carpet asper operator Parts List 0/26/2013 Closed: 10/22/2013 - P.m. Service. Parts List 0/26/2013 Closed: 10/22/2013 - P.m. Service. Parts List 0/26/2013 Closed: 10/22/2013 - P.m. Service. Parts List 0/26/2013 Closed: 10/22/2013 - Fabricate and install new ladder rack. 5w20 Engine Oil 7.0 7.0 - Rotate and balance all tires. Brake Cleaner 1.0 1.0 Lador: 1.0 - Hours 7.75 Labor: 465.00 Parts: 151 1.0 1.0 1.0 - Morkorder: 1311545 Meter: 6751 In Date: 11/15/2013 Closed: 11/27/2013	Workorder: Problem:						In Date:	06/28/2013	Closed:	06/28/2	013
Hours 3.00 Labor: 180.00 Parts: 0.00 Total: 180.00 Workorder: 1307481 Meter: 2396 In Date: 07/26/2013 Closed: 07/31/2013 Problem: Requeast for floor mats. - In Date: 07/26/2013 Closed: 07/31/2013 -Instail new floor mats to protect carpet asper operator request. Hours 0.30 Labor: 18.00 Parts: List Qit -Instail new floor Meter: 5754 In Date: 09/26/2013 Closed: 10/22/2013 Problem: Pm service. Parts List Qit Closed: 10/22/2013 - Instail new trailer plug fabricate and install new wiring. Napagold Oil Filter 1.0 Closed: 10/22/2013 - Rotate: Brake Cleaner 1.0 S404 Female Connector 1.0 Closed: 10/22/2013 - Shop Supplies 5404 Female Connector 1.0 Labor: 11/15/2013 Closed: 11/27/2013 Workorder: 1311545 Meter: 6751 In Date: 11/15/2013 Closed: 11/27/2013 Problem: Install saddle boxes Shop Supplies 1.0		•	on								
i Workorder: 1307481 Meter: 2396 In Date: 07/26/2013 Closed: 07/31/2013 Problem: Requeast for floor mats. Floor Mats to protect carpet asper operator Parts List Qi request. Floor Mats-2pc Rub Bk 1.0 Workorder: 1309754 Meter: 5754 In Date: 09/26/2013 Closed: 10/22/2013 Problem: Preservice. Parts List Qi 01/22/2013 Closed: 10/22/2013 Pr. Service. Parts List Qi 01/22/2013 Closed: 10/22/2013 Install new trailer plug, fabricate and install new wiring. Napagold Oll Filter 10/22/2013 Closed: 10/22/2013 - Fabricate and balance all tires. Brake Cleaner 1.0 Closed: 10/22/2013 - Shop Supplies 5404 Female Connector 1.0 Ladder Rack 1.0 - Shop Supplies 1.0 Date: 11/15/2013 Closed: 11/27/2013 Problem: Install studie boxes - Fabricate drill and install rew trailer 6751 In Date: 11/15/2013 Closed:	- Wash Vehic	le									
Problem: Requeast for floor mats. - Install new floor mats to protect carpet asper operator request. Parts List Qui Floor Mat-2pc Rub Bk 1.0 - Install new floor mats to protect carpet asper operator request. Hours 0.30 Labor: 18.00 Parts: 27.69 Total: 45.69 Workorder: 1309754 Meter: 5754 In Date: 09/26/2013 Closed: 10/22/2013 Problem: Pm service. Parts List Qui Floor Mat-2pc Rub Bk Closed: 10/22/2013 - Install new trailer plug, fabricate and install new wiring. Napagold Oil Filter 1.0 - Fabricate and balance all tires. Brake Cleaner 1.0 - Rotate and balance all tires. Brake Cleaner 1.0 - Apors 7.75 Labor: 465.00 Parts: 715.12 Total: 1,180.12 Workorder: 1311545 Meter: 6751 In Date: 11/15/2013 Closed: 11/27/2013 Problem: Install and install two side tool boxes and secure both with legs to floor of bed. Props 2.0 - Fabricate, drill and install two side tool boxes and secure Props Shop Supplies 1.0 1.0 - Abort stale, drill and install two side tool boxes and secure Props Shop Supplies 1.0 - Abort Stale, dri			Hours 3.00 :		Labor:	180.00	Parts:	0.00	Total:	180.00	
request. Floor Mat-2pc Rub Bk 1.0 Hours 0.30 Labor: 18.00 Parts: 27.69 Total: 45.69 Workorder: 1309754 Meter: 5754 In Date: 09/26/2013 Closed: 10/22/2013 Problem: Pm service. Parts List Qr - Install new trailer plug, fabricate and install new wiring. Napagold Oil Filter 1.0 - Fabricate and install new ladder rack. 5v20 Engine Oil 7.0 - Rotate and balance all tires. Brake Cleaner 1.0 - Shop Supplies 5404 Female Connector 1.0 - Rotate and balance all tires. Brake Cleaner 1.0 - Shop Supplies 5404 Female Connector 1.0 - Bours 7.75 Labor: 465.00 Parts: 715.12 Total: 1,180.12 Workorder: 1311545 Meter: 6751 In Date: 11/15/2013 Closed: 11/27/2013 Problem: Install wo side tool boxes and secure Parts List Qr Props 2.0 - Shop Supplies Shop Supplies 1.0 Parts: 12/06/2013 Closed: 12/17/2013 Problem:	Workorder: Problem:						In Date:	07/26/2013	Closed:	07/31/2	013
Hours 0.30Labor: 18.00Parts: 27.69Total: 45.69Workorder:1309754Meter: 5754In Date:09/26/2013Closed:10/22/2013Problem:Pm service. Check trailer harness .Request for new pipe rack and installation.9/26/2013Closed:10/22/2013- P.m. Service.Parts ListQ- Install new trailer plug.fabricate and install new wiring.Napagold Oil Filter1.0- Fabricate and balance all tires.Brake Cleaner1.0- Rotate and balance all tires.Stude Fire X Refurbished1.0- Shop Supplies5404 Female Connector1.0Used Fire X Refurbished1.0Ladder Rack1.0Shop Supplies1.0Hours 7.75Labor: 465.00Problem:In Date:1311545Meter: 6751In Date:11/15/2013Closed:11/27/2013Problem:Install saddle boxes- Fabricate, drill and install two side tool boxes and secureProps2.0- Shop Supplies1.0- Shop Supplies1.0- Shop Supplies1.0- Shop Supplies1.0- Check trailer plug.replace blown fuse Parts ListQi- Asemble and install computer stand- Shop SuppliesShop Supplies- Check trailer plug.replace blown fuse Asemble and install computer stand Shop Supplies- Mours 2.50- Labor:- Shop Supplies- Shop Supplies- Our s2.50 <td>- Install new f</td> <td>loor mate</td> <td>s to protect carpe</td> <td>et asper</td> <td>operator</td> <td>Parts L</td> <td>ist</td> <td></td> <td></td> <td></td> <td>Qty</td>	- Install new f	loor mate	s to protect carpe	et asper	operator	Parts L	ist				Qty
i in Date: 09/26/2013 Closed: 10/22/2013 Problem: Pm service. Check trailer harness . Request for new pipe rack and installation. Parts List Qit - Install new trailer plug.fabricate and install new wiring. Napagold Oil Filter 1.0 - Fabricate and balance all tires. Brake Cleaner 1.0 - Rotate and balance all tires. Brake Cleaner 1.0 - Shop Supplies 5404 Female Connector 1.0 - Hours 7.75 Labor: 465.00 Parts. 175.12 Total: 1,180.12 Workorder: 1311545 Meter: 6751 In Date: 11/15/2013 Closed: 11/27/2013 Problem: Install new isstell so floor of bed. Props 2.0 2.0 11/27/2013 - Shop Supplies Shop Supplies 1.0 1.0 11/15/2013 Closed: 11/27/2013 Problem: Install and install two side tool boxes and secure Parts List Qit Qit - Shop Supplies Shop Supplies 1.0 Props 2.0 - Shop Supplies Shop Supplies 1.0 1.0 1.0 1.0 1.0 <t< td=""><td>request.</td><td></td><td></td><td></td><td></td><td>Floor M</td><td>at-2pc Rub</td><td>Bk</td><td></td><td></td><td>1.00</td></t<>	request.					Floor M	at-2pc Rub	Bk			1.00
Problem: Pm service. Check trailer harness. Request for new pipe rack and installation. - P.m. Service. Parts List Quite control of the			Hours 0.30		Labor:	18.00	Parts:	27.69	Total:	45.69	
 Install new trailer plug.fabricate and install new wiring. Install new trailer plug.fabricate and install new wiring. Fabricate and install new ladder rack. Sw20 Engine Oil Rotate and balance all tires. Brake Cleaner Shop Supplies S404 Female Connector Used Fire X Refurbished In Date: 11/15/2013 Closed: 11/27/2013 Problem: Install computer stand. Bp Fmx-lp F Mx Fuse Used Fire X Refurbished Shop Supplies Used Fire X Refurbished Used Fire X Refurbished Used Fire X Refurbished U	Workorder: Problem:				s .Request for	new pipe			Closed:	10/22/2	013
- Fabricate and install new ladder rack. - Rotate and balance all tires. - Shop Supplies - Shop Supplies - Shop Supplies - Hours 7.75 - Hours 7.75 - Labor: 465.00 - Hours 7.75 - Labor: 465.00 - Hours 7.75 - Labor: 465.00 - Parts: 715.12 - Total: 1,180.12 - Hours 7.75 - Labor: 465.00 - Parts: 715.12 - Total: 1,180.12 - Hours 7.75 - Labor: 465.00 - Parts: 715.12 - Total: 1,180.12 - Hours 2.75 - Shop Supplies - Fabricate,drill and install two side tool boxes and secure - Fabricate,drill and install two side tool boxes and secure - Fabricate,drill and install two side tool boxes and secure - Fabricate,drill and install two side tool boxes and secure - Fabricate,drill and install two side tool boxes and secure - Shop Supplies - Fabricate,drill and install two side tool boxes and secure - Shop Supplies - Fabricate,drill and install two side tool boxes and secure - Check trailer plug.replace blown fuse. - Check trailer plug.replace blown fuse. - Shop Supplies - Shop Supplies - Shop Supplies - Shop Supplies - Mours 2.50 - Hours 2.50	- P.m. Service	e.				Parts L	ist				Qty
- Rotate and balance all tires. Brake Cleaner 1.0 - Shop Supplies 5404 Female Connector 1.0 - Shop Supplies 1.0 1.0 - Shop Supplies 1.0 1.0 - Burs 7.75 Labor: 465.00 Parts: 715.12 Total: 1,180.12 - Workorder: 1311545 Meter: 6751 In Date: 11/15/2013 Closed: 11/27/2013 - Fabricate,drill and install two side tool boxes and secure both with legs to floor of bed. Props 2.0 2.0 - Shop Supplies 1312230 Meter: 7362 In Date: 12/06/2013 Closed: 12/17/2013 Problem: Install computer stand and check trailer light connector. In Date: 12/06/2013 Closed: 12/17/2013 Problem: Install computer stand. Bp Fmx-lp F Mx Fuse 1.0 1.0 - Asemble and install computer stand. Bp Fmx-lp F Mx Fuse 1.0 - Shop Supplies 1.00 Parts: 6.65 Total: 156.65 - Ordeck trailer plug.replace blown fuse. Parts List Question for the context for	- Install new t	railer plu	g.fabricate and ir	nstall ne	w wiring.	Napago	ld Oil Filter				1.00
- Shop Supplies 5404 Female Connector 1.0 Used Fire X Refurbished 1.0 Ladder Rack 1.0 Shop Supplies 1.0 Hours 7.75 Labor: 465.00 Parts: 715.12 Total: 1,180.12 	- Fabricate ar	nd install	new ladder rack.			5w20 E	ngine Oil				7.00
Used Fire X Refurbished 1.0 Ladder Rack 1.0 Shop Supplies 1.0 Hours 7.75 Labor: 465.00 Parts: 715.12 Total: 1,180.12 Workorder: 1311545 Meter: 6751 In Date: 11/15/2013 Closed: 11/27/2013 Problem: Install saddle boxes And Secure Parts List Quit both with legs to floor of bed. Props 2.0 - Shop Supplies Shop Supplies 1.0 Hours 2.50 Labor: 150.00 Parts: 909.50 Total: 1,059.50 Hours 2.50 Labor: 150.00 Parts: 909.50 Total: 1,059.50 Workorder: 1312230 Meter: 7362 In Date: 12/06/2013 Closed: 12/17/2013 Problem: Install computer stand and check trailer light connector. - Check trailer plug.replace blown fuse. Parts List Quit - Asemble and install computer stand. Bp Fmx-lp F Mx Fuse 1.0 - Shop Supplies Shop Supplies 1.0 - Hours 2.50 Labor: 150.00 Parts: 6.65 Total: 156.55 - Workorder: 1402216 Meter: 10749 In Date: 03/05/2014 Closed: 03/12/2014 - Problem: needs spare key - Make And Program 1 Key Parts List Quit - Shop Supplies Ford Ignition Key Blank 1.0 Shop Supplies 1.0	- Rotate and I	balance a	all tires.			Brake C	Cleaner				1.00
Ladder Rack 1.0. Shop Supplies 1.00 Hours 7.75 Labor: 465.00 Parts: 715.12 Total: 1,180.12 Workorder: 1311545 Meter: 6751 In Date: 11/15/2013 Closed: 11/27/2013 Problem: Install saddle boxes Parts List Qrt both with legs to floor of bed. Props 2.00 - Shop Supplies Store Constrained and check trailer light connector. - Check trailer plug.replace blown fuse. Parts List Shop Supplies 1.00 - Check trailer plug.replace blown fuse. Parts List Qrt - Asemble and install computer stand and check trailer light connector. - Check trailer plug.replace blown fuse. Parts List Qrt - Shop Supplies 5.00 Parts: 909.50 Total: 1,059.50 - Check trailer plug.replace blown fuse. Parts List Qrt - Asemble and install computer stand. Bp Fmx-lp F Mx Fuse 1.00 - Shop Supplies 5.00 Parts: 6.65 Total: 156.65 - Workorder: 1402216 Meter: 10749 In Date: 03/05/2014 Closed: 03/12/2014 Problem: needs spare key - Make And Program 1 Key Parts List Qrt - Shop Supplies 1.00 - Closed: 10749 In Date: 03/05/2014 Closed: 03/12/2014 - Shop Supplies 1.00 - Shop Sup	- Shop Suppli	ies				5404 Fe	emale Conn	ector			1.00
Hours 7.75 Labor: 465.00 Parts: 715.12 Total: 1,180.12 Workorder: 1311545 Meter: 6751 In Date: 11/15/2013 Closed: 11/27/2013 Problem: Install saddle boxes Parts List Qr - Fabricate,drill and install two side tool boxes and secure both with legs to floor of bed. Parts List Qr - Shop Supplies Shop Supplies 1.0 - Shop Supplies Shop Supplies 1.0 - Shop Supplies Labor: 150.00 Parts: 909.50 Total: 1,059.50 - Shop Supplies In Date: 12/06/2013 Closed: 12/17/2013 Problem: Install computer stand and check trailer light connector. In Date: 12/06/2013 Closed: 12/17/2013 - Asemble and install computer stand. Bp Fmx-lp F Mx Fuse 1.0 1.0 - Asemble and install computer stand. Bp Fmx-lp F Mx Fuse 1.0 - Shop Supplies Shop Supplies 1.0 - Hours 2.50 Labor: 150.00 Parts: 6.65 Total: 156.65 : Workorder:						Used Fi	re X Refurb	ished			1.00
Hours 7.75Labor: 465.00Parts: 715.12Total: 1,180.12Workorder:1311545Meter:6751In Date:11/15/2013Closed:11/27/2013Problem:Install saddle boxesParts ListQt- Fabricate,drill and install two side tool boxes and secure both with legs to floor of bed.Parts ListQt- Shop SuppliesShop Supplies1.0- Shop SuppliesLabor:150.00Parts:909.50Total:1,059.50Workorder:1312230Meter:7362In Date:12/06/2013Closed:12/17/2013Problem:Install computer stand and check trailer light connector.Parts ListQt- Check trailer plug.replace blown fuse.Parts ListQt- Asemble and install computer stand.Bp Fmx-lp F Mx Fuse1.0- Shop SuppliesShop Supplies1.0- Workorder:1402216Meter:10749In Date:03/05/2014Closed:03/12/2014- Make And Program 1 KeyParts ListQt- Shop SuppliesFord Ignition Key Blank1.0- Shop Supplies<						Ladder	Rack				1.00
Hours 7.75Labor: 465.00Parts: 715.12Total: 1,180.12Workorder:1311545Meter:6751In Date:11/15/2013Closed:11/27/2013Problem:Install saddle boxesParts ListQt- Fabricate,drill and install two side tool boxes and secure both with legs to floor of bed.Parts ListQt- Shop SuppliesShop Supplies1.0- Shop SuppliesLabor:150.00Parts:909.50Total:1,059.50Workorder:1312230Meter:7362In Date:12/06/2013Closed:12/17/2013Problem:Install computer stand and check trailer light connector.Parts ListQt- Check trailer plug.replace blown fuse.Parts ListQt- Asemble and install computer stand.Bp Fmx-lp F Mx Fuse1.0- Shop SuppliesShop Supplies1.0- Workorder:1402216Meter:10749In Date:03/05/2014Closed:03/12/2014- Make And Program 1 KeyParts ListQt- Shop SuppliesFord Ignition Key Blank1.0- Shop Supplies<						Shop S	upplies				1.00
Problem: Install saddle boxes - Fabricate,drill and install two side tool boxes and secure both with legs to floor of bed. Parts List Qt - Shop Supplies Shop Supplies 1.0 - Shop Supplies Labor: 150.00 Parts: 909.50 Total: 1,059.50 - Workorder: 1312230 Meter: 7362 In Date: 12/06/2013 Closed: 12/17/2013 Problem: Install computer stand and check trailer light connector. - Check trailer plug.replace blown fuse. Parts List Qt - Shop Supplies Shop Supplies 1.00 Prose 1.00 - Check trailer plug.replace blown fuse. Parts List Qt - Asemble and install computer stand. Bp Fmx-lp F Mx Fuse 1.00 - Shop Supplies Shop Supplies 1.00 - Workorder: 1402216 Meter: 10749 - Problem: needs spare key In Date: 03/05/2014 Closed: 03/12/2014 - Shop Supplies Ford Ignition Key Blank 1.00 1.00 1.00 1.00 - Shop Supplies Ford Ignition Key Blank 1.00 1.00 1.00 1.00			Hours 7.75		Labor:			715.12	Total:	1,180.1	2
both with legs to floor of bed. - Shop Supplies Shop Supplies 1.0 Hours 2.50 Labor: 150.00 Parts: 909.50 Total: 1,059.50 : Workorder: 1312230 Meter: 7362 In Date: 12/06/2013 Closed: 12/17/2013 Problem: Install computer stand and check trailer light connector. - Check trailer plug.replace blown fuse. - Asemble and install computer stand. - Shop Supplies Shop Supplies 1.0 Hours 2.50 Labor: 150.00 Parts: 6.65 Total: 156.65 : Workorder: 1402216 Meter: 10749 In Date: 03/05/2014 Closed: 03/12/2014 Problem: needs spare key - Make And Program 1 Key - Shop Supplies Ford Ignition Key Blank 1.0 Shop Supplies 1.0	Workorder: Problem:			6751			In Date:	11/15/2013	Closed:	11/27/2	013
- Shop Supplies Shop Supplies 1,00 Hours 2.50 Labor: 150.00 Parts: 909.50 Total: 1,059.50 Workorder: 1312230 Meter: 7362 In Date: 12/06/2013 Closed: 12/17/2013 Problem: Install computer stand and check trailer light connector. - Check trailer plug.replace blown fuse. Parts List Qrit - Asemble and install computer stand. Bp Fmx-lp F Mx Fuse 1.0 - Shop Supplies Shop Supplies 1.0 Hours 2.50 Labor: 150.00 Parts: 6.65 Total: 156.65 : Workorder: 1402216 Meter: 10749 In Date: 03/05/2014 Closed: 03/12/2014 Problem: needs spare key - Make And Program 1 Key Parts List Qrit - Shop Supplies Ford Ignition Key Blank 1.0 Shop Supplies 1.0				l boxes a	and secure	Parts L	ist				Qty
Hours 2.50 Labor: 150.00 Parts: 909.50 Total: 1,059.50 Workorder: 1312230 Meter: 7362 In Date: 12/06/2013 Closed: 12/17/2013 Problem: Install computer stand and check trailer light connector. - Check trailer plug.replace blown fuse. Parts List Qr - Asemble and install computer stand. Bp Fmx-lp F Mx Fuse 1.0 - Shop Supplies Shop Supplies 1.0 - Workorder: 1402216 Meter: 10749 In Date: 03/05/2014 Closed: 03/12/2014 Problem: needs spare key - Make And Program 1 Key Parts List Qr - Shop Supplies Ford Ignition Key Blank 1.0 - Shop Supplies Ford Ignition Key Blank 1.0	-		of bed.			Props					2.00
: Workorder: 1312230 Meter: 7362 In Date: 12/06/2013 Closed: 12/17/2013 Problem: Install computer stand and check trailer light connector. - Check trailer plug.replace blown fuse. Parts List Qrit - Asemble and install computer stand. Bp Fmx-lp F Mx Fuse 1.0 - Shop Supplies Shop Supplies 1.0 Hours 2.50 Labor: 150.00 Parts: 6.65 Total: 156.65 : Workorder: 1402216 Meter: 10749 In Date: 03/05/2014 Closed: 03/12/2014 Problem: needs spare key - Make And Program 1 Key Parts List Qrit - Shop Supplies Ford Ignition Key Blank 1.0 Shop Supplies 1.0	- Shop Suppli	ies				Shop S	upplies				1.00
Problem: Install computer stand and check trailer light connector. - Check trailer plug.replace blown fuse. Parts List Qr - Asemble and install computer stand. Bp Fmx-lp F Mx Fuse 1.0 - Shop Supplies Shop Supplies 1.0 - Shop Supplies Shop Supplies 1.0 - Mours 2.50 Labor: 150.00 Parts: 6.65 Total: 156.65 :			Hours 2.50		Labor:	150.00	Parts:	909.50	Total:	1,059.5	0
- Asemble and install computer stand. Bp Fmx-lp F Mx Fuse 1.0 - Shop Supplies Shop Supplies 1.0 Hours 2.50 Labor: 150.00 Parts: 6.65 Total: 156.65 Workorder: 1402216 Meter: 10749 In Date: 03/05/2014 Closed: 03/12/2014 Problem: needs spare key - Make And Program 1 Key Parts List Qt - Shop Supplies Ford Ignition Key Blank 1.0 1.0 Shop Supplies 1.0 1.0 1.0 - Shop Supplies Ford Ignition Key Blank 1.0 - Shop Supplies 1.0 1.0	Workorder: Problem:				k trailer light co	onnector.		12/06/2013	Closed:	12/17/2	013
- Asemble and install computer stand. Bp Fmx-lp F Mx Fuse 1.0 - Shop Supplies Shop Supplies 1.0 Hours 2.50 Labor: 150.00 Parts: 6.65 Total: 156.65 Workorder: 1402216 Meter: 10749 In Date: 03/05/2014 Closed: 03/12/2014 Problem: needs spare key - Make And Program 1 Key Parts List Qt - Shop Supplies Ford Ignition Key Blank 1.0 1.0 Shop Supplies 1.0 1.0 1.0 - Shop Supplies Ford Ignition Key Blank 1.0 - Shop Supplies 1.0 1.0	- Check traile	r plug.rer	olace blown fuse	_		Parts L	ist				Qty
- Shop Supplies Shop Supplies 1.0 Hours 2.50 Labor: 150.00 Parts: 6.65 Total: 156.65 Workorder: 1402216 Meter: 10749 In Date: 03/05/2014 Closed: 03/12/2014 Problem: needs spare key - Make And Program 1 Key - Make And Program 1 Key - Shop Supplies Ford Ignition Key Blank 1.0 Shop Supplies 1.0				•				5 0			1.00
Hours 2.50 Hours 150.00 Parts: 6.65 Hours 2.50 Hours 2.50 Hou						•	•				1.00
Problem: needs spare key - Make And Program 1 Key Parts List Qr - Shop Supplies Ford Ignition Key Blank 1.0 Shop Supplies Shop Supplies 1.0	enep eappi		Hours 2.50		Labor:	-		6.65	Total:	156.65	1.00
- Make And Program 1 Key Parts List Qt - Shop Supplies Ford Ignition Key Blank 1.0 Shop Supplies 1.0	Workorder: Problem:			10749			In Date:	03/05/2014	Closed:	03/12/2	014
- Shop Supplies Ford Ignition Key Blank 1.0 Shop Supplies 1.0			-			Darte I	ict				04
Shop Supplies 1.0		-	псу					lonk			-
	- Shop Suppli	ies				-	•	Iank			
Hours 1.00 Labor: 60.00 Parts: 28.61 I otal: 88.61							••	00.01	- · ·	00.04	1.00
			Hours 1.00 :		Labor:	60.00	Parts:	28.61	i otal:	88.61	

Workorder: Problem:	1404508 Pm service.	Meter:	13222			In Date:	05/08/2014	Closed:	05/20/20	014
- Perform pm	service.				Parts Lis	st				Qty
-	balance all fou	ır tires.			5w20 En					7.00
- Shop Suppli						d Oil Filter				1.00
					Wiper Bl					2.00
					Washer					1.00
						e X Refurbi	ished			1.00
					Shop Su	pplies				1.00
	Hou	ırs 3.75		Labor:	225.00	• •	49.06	Total:	274.06	
Workorder: Problem:	1408598 Pm service.	Meter:	18553			In Date:	08/27/2014	Closed:	09/08/20	014
- Pm service.					Parts Lis	st				Qty
	tires.rotate ar	nd balance	all four.		5w20 En					7.00
- Shop Suppli						d Oil Filter				1.00
						d Air Filter				1.00
					Wiper Bl					2.00
						92 Lt245-7	5r17			2.00
					Shop Su	pplies				1.00
					-	osal Fee				2.00
	Hou	ırs 4.75		Labor:	285.00	Parts:	564.20	Total:	849.20	
Workorder: Problem:	1408880 light tower	Meter:	18560			In Date:	09/03/2014	Closed:	09/09/20	014
- Install light to	ower assembly	V			Parts Lis	st				Qty
- Shop Suppli		,			Shop Su					1.00
		ırs 8.00		Labor:	480.00	Parts:	2.00	Total:	482.00	
Workorder: Problem:	1409689 Right front ar	Meter: nd right rear	19271 r tire flat			In Date:	09/26/2014	Closed:	09/29/20	014
- Repair and b	balance right f	ront and rea	ar tires.		Parts Lis	st				Qty
- Shop Suppli	es				Shop Su	pplies				1.00
	Hou :	ırs 2.00		Labor:	120.00	Parts:	2.00	Total:	122.00	
Workorder: Problem:	1411853 Work light inc	Meter:	21883			In Date:	11/24/2014	Closed:	11/26/20	014
	ork light inop.p	oinpoint test	t and repair	fuse	Parts Lis	st				Qty
holder to hatte	ery connector.				Shop Su	pplies				1.00
- Shop Suppli	es									

Problem:	1501265 Pm service.	Meter:	25253		Ir	n Date:	02/03/2015	Closed:	02/19/2015
- Pm service.					Parts List				Q
- Replace two	tires.rotate ar	nd balance	all four.		5w20 Engi	ne Oil			7.0
- Perform con	nplete front en	d alignmen	t and roadtes	t.	Napagold	Oil Filter			1.0
- Shop Suppli	es	-			Wiper Blac	le			2.0
					Lt245 75r1	7 M/s2 T	ïre		2.0
					Shop Supp	olies			1.0
					Tire Dispos	sal Fee			2.0
	Hou :	rs 7.25		Labor:	435.00	Parts:	646.83	Total:	1,081.83
Workorder: Problem:	1501889 Has to jump s	Meter: start.	25908		Ir	n Date:	02/23/2015	Closed:	02/26/2015
	and charging			adtest	Parts List				Q
•	.replace defec	tive battery			Battery 65				1.0
- Shop Suppli	es				Shop Supp	olies			1.0
	Hou	rs 1.00		Labor:	60.00	Parts:	157.21	Total:	217.21
Workorder: Problem:	1505758 Pm service.	Meter:	30810		Ir	n Date:	06/09/2015	Closed:	06/18/2015
- Pm service.					Parts List				Q
	nt brake pads a			s.service	5w20 Engi	ne Oil			7.0
-	and flush brak	-	badtest.		Napagold	Oil Filter			1.0
	balance four tii	res.					5 - 1 I		
Chon Cunnli					Used Fire		isnea		1.0
- Shop Suppli	es				Wiper Blac	le			2.0
- Snop Suppli	es				Wiper Blac Washer Fle	le uid Conc			2.0 1.0
- Snop Suppli	es				Wiper Blac Washer Flu B Fluid Do	le uid Conc t 3-32oz			2.0 1.0 1.0
- Snop Suppli	es				Wiper Blac Washer Flu B Fluid Do Brake Clea	le uid Conc t 3-32oz aner	entr		2.0 1.0 1.0 1.0
- Snop Suppli	es				Wiper Blac Washer Flu B Fluid Do Brake Clea Front Brak	le uid Conc t 3-32oz aner e Pad D	entr		2.0 1.0 1.0 1.0 1.0
- Snop Suppli				Labor	Wiper Blac Washer Flu B Fluid Do Brake Clea Front Brak Shop Supp	le uid Conc t 3-32oz aner e Pad D blies	entr uty	Tatalı	2.0 1.0 1.0 1.0 1.0 1.0
- Snop Suppli		rs 7.75		Labor:	Wiper Blac Washer Flu B Fluid Do Brake Clea Front Brak	le uid Conc t 3-32oz aner e Pad D blies	entr uty 148.04	Total:	2.0 1.0 1.0 1.0 1.0
Workorder:		Meter:	32068 pump harnes		Wiper Blac Washer Flu B Fluid Do Brake Clea Front Brak Shop Supp 465.00	le uid Conc t 3-32oz aner e Pad D blies	entr uty	Total: Closed:	2.0 1.0 1.0 1.0 1.0 1.0
Workorder: Problem: - Replace def	Hou : 1506830 Rewire spray ective trailer h	Meter: er auxiliary	pump harnes	SS.	Wiper Blac Washer Flu B Fluid Do Brake Clea Front Brak Shop Supp 465.00	le uid Conc t 3-32oz aner e Pad D blies Parts: n Date:	entr uty 148.04		2.0 1.0 1.0 1.0 1.0 1.0 613.04
Workorder: Problem: - Replace def harness for au	Hou : 1506830 Rewire spray fective trailer h ixiliary pump.	Meter: er auxiliary	pump harnes	SS.	Wiper Blac Washer Flu B Fluid Do Brake Clea Front Brak Shop Supp 465.00	le uid Conc t 3-32oz aner e Pad D blies Parts: n Date:	entr uty 148.04		2.0 1.0 1.0 1.0 1.0 613.04 07/27/2015
Workorder: Problem: - Replace def narness for au	Hou : 1506830 Rewire spray fective trailer h ixiliary pump.	Meter: er auxiliary	pump harnes	SS.	Wiper Blac Washer Flu B Fluid Do Brake Clea Front Brak Shop Supp 465.00	de uid Conc t 3-32oz aner e Pad D blies Parts: n Date:	entr uty 148.04 07/09/2015 t		2.0 1.0 1.0 1.0 1.0 613.04 07/27/2015
Workorder: Problem: - Replace def narness for au	Hou : 1506830 Rewire spray fective trailer h ixiliary pump.	Meter: er auxiliary	pump harnes	SS.	Wiper Blac Washer Flu B Fluid Do Brake Clea Front Brak Shop Supp 465.00	de uid Conc t 3-32oz aner e Pad D blies Parts: n Date:	entr uty 148.04 07/09/2015 t		2.0 1.0 1.0 1.0 1.0 613.04 07/27/2015
Workorder: Problem: - Replace def harness for au	Hou : 1506830 Rewire spray fective trailer h ixiliary pump.	Meter: er auxiliary	pump harnes	SS.	Wiper Blac Washer Flu B Fluid Do Brake Clea Front Brak Shop Supp 465.00	de uid Conc t 3-32oz aner e Pad D blies Parts: n Date:	entr uty 148.04 07/09/2015 t		2.0 1.0 1.0 1.0 1.0 1.0 613.04 07/27/2015
Workorder: Problem: - Replace def	Hou : 1506830 Rewire spray fective trailer h ixiliary pump.	Meter: er auxiliary	pump harnes	SS.	Wiper Blac Washer Flu B Fluid Do Brake Clea Front Brak Shop Supp 465.00 Ir Parts List Adapter Trailer Cor Batt Cable Battcap Vinyl Elect	de uid Conc t 3-32oz aner e Pad D blies Parts: n Date: n Socke Connect rical Tap	entr uty 148.04 07/09/2015 t tor		2.0 1.0 1.0 1.0 1.0 1.0 613.04 07/27/2015 07/27/2015 07/27/2015 07/27/2015
Workorder: Problem: - Replace def harness for au	Hou : 1506830 Rewire spray fective trailer h ixiliary pump.	Meter: er auxiliary	pump harnes	SS.	Wiper Blac Washer Flu B Fluid Do Brake Clea Front Brak Shop Supp 465.00 Ir Parts List Adapter Trailer Cor Batt Cable Battcap Vinyl Elect Fuse Hold	le uid Conc t 3-32oz aner e Pad D blies Parts: n Date: n Date: n Socke Connect rical Tap	entr uty 148.04 07/09/2015 t tor		2.0 1.0 1.0 1.0 1.0 1.0 613.04 07/27/2015 07/27/2015 07/27/2015 07/27/2015 07/27/2015
Workorder: Problem: - Replace def harness for au	Hou 1506830 Rewire spray ective trailer h ixiliary pump. ies	Meter: er auxiliary	pump harnes	ss. wiring	Wiper Blac Washer Flu B Fluid Do Brake Clea Front Brak Shop Supp 465.00 Ir Parts List Adapter Trailer Cor Batt Cable Battcap Vinyl Elect	de uid Conc t 3-32oz aner e Pad D blies Parts: n Date: n Date: connect rical Tap er blies	entr uty 148.04 07/09/2015 t tor	Closed:	2.0 1.0 1.0 1.0 1.0 1.0 613.04 07/27/2015 07/27/2015 07/27/2015 07/27/2015

Workorder: Problem:	1507266 pump inop	Meter:	31950		I	n Date:	07/21/2015	Closed:	07/24/20	015
- Replace Def	fective pump c	n sprayer r	mounted in tr	uck	Parts List	t				Qty
- Shop Suppli	es				12vdc Del	livery Pur	р			1.00
					Shop Sup	plies				1.00
					Freight Ch	narge				1.00
	Hou	rs 1.00		Labor:	60.00	Parts:	339.77	Total:	399.77	
Workorder: Problem:	1509722 Pm service.	Meter:	36564			n Date:	09/25/2015	Closed:	10/13/20	015
- Pm service.					Parts List	t				Qty
	oth rear brake			<e< td=""><td>5w20 Eng</td><td>ine Oil</td><td></td><td></td><td></td><td>7.00</td></e<>	5w20 Eng	ine Oil				7.00
pads.service c		•			Napagold	Oil Filter				1.00
-	defective too				Napagold	Air Filter				1.00
-	tires.rotate ar	nd balance	all four.		Wiper Bla	de				2.00
- Shop Suppli	es				Brake Cle	aner				1.00
					Rear Pad	S				1.00
					Support					2.00
					17963649	2 Lt245-7	5r17			2.00
					Real Brak	e Pad				1.00
					Shop Sup	plies				1.00
					Tire Dispo	sal Fee				2.00
	Hou :	rs 9.25		Labor:	555.00	Parts:	764.63	Total:	1,319.63	3
Workorder: Problem:	1511814 Hitch Pin	Meter:	37817		I	n Date:	11/19/2015	Closed:	12/03/20)15
- replace hitch	n pin				Parts List	t				Qty
- Shop Suppli	es				Lockg 5 8	P 2 Tube	9			1.00
					Shop Sup	plies				1.00
	Hou	rs 1.00		Labor:			15.70	Total:	75.70	
	1511871	Meter:	38166		I	n Date:	11/20/2015	Closed:	11/24/20	015
Workorder:		,	ılt							
	Tire pressure	sensor fau								
Problem: - Computer di	Tire pressure agnose for tire	e pressure :	sensor fault.c		Parts List	t				Qty
Problem: - Computer di B1242.replace	Tire pressure agnose for tire defective righ	e pressure :	sensor fault.c				e Pr			Qty 1.00
Problem:	Tire pressure agnose for tire defective righ d clear code.	e pressure :	sensor fault.c			Sensor Tir	e Pr			-

Palm Beach County Fleet Management
Asset Maintenance History

	1602303 Pm service.	Meter:	42514			In Date:	03/04/2016	Closed:	03/14/2016
- Pm service.					Parts Li	ist			Qt
- Replace hitch	ı pintle pin.				5w20 Ei	ngine Oil			7.0
- Replace two		d balance	all four.			ld Oil Filter			1.0
- Check and re					Brake C				1.0
- Complete from		-	•		Used Fi	re X Refurb	ished		1.0
- Shop Supplie	es.				22" Wip	er Blade			2.0
					Pintle P	in W/chain			1.0
					1796364	492 Lt245-7	′5r17		2.0
					Bulb				1.0
					Shop Su	upplies			1.0
					Tire Dis	posal Fee			2.0
	Hours :	s 8.25		Labor:	495.00	Parts:	554.87	Total:	1,049.87
	1602831 10 - Wash tick	Meter: et(s) issue	42514 ed			In Date:	03/17/2016	Closed:	03/17/2016
- 10 - Wash tic	ket(s) issued								
	Hours :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1605739 hitch	Meter:	45917			In Date:	06/03/2016	Closed:	06/17/2016
- Order Hitch p	arts				Parts Li	ist			Qt
- Shop Supplie	S				pintle m	ount			1.0
					Pintle H	ook With Ba	all		1.0
					mountin	ig kit			1.0
					2535 D	P Hitch Mo	ount		1.0
					6033 Mo	ounted Pintl	les		1.0
					Mountin	ig Kit			1.0
					pintle ho	ook			1.0
					Shop Su	upplies			1.0
	Hours :	s 0.50		Labor:	30.00	Parts:	561.14	Total:	591.14
	1607269 P.M. service.	Meter:	47791			In Date:	07/18/2016	Closed:	07/28/2016
- P.m. Service.					Parts Li	ist			Qt
- Inspect and s	ervice transfer	case.			5w20 Er	ngine Oil			7.0
	ill transmissior	۱.			Napago	ld Oil Filter			1.0
- Flush and ref	alance all tires				Syn-atf	Trans Fluid	S		20.0
 Flush and ref Rotate and bat 									2.0
					Ford Ira	ansfer Case	Fluid		3.0
- Rotate and ba					Shop Su		FIUIO		3.0 1.0

Workorder: 1 Problem: P	610829 .M. service	Meter:	52244		I	n Date:	10/20/2016	Closed:	10/31/20)16
- P.m. Service.					Parts Lis	t				Qty
- Replace worn	out toolbox li	d struts,ar	nd install floo	r mats.	5w20 Eng	jine Oil				7.00
- Rotate and ba	ance all tires	j.			Napagold	Oil Filter				1.00
- Shop Supplies					22" Wiper	Blade				2.00
					Washer F	luid Conc	entr			1.00
					Napagold	Air Filter				1.00
					Support					2.00
					Dickie Flo	or Mat Bl	ĸ			1.00
					Shop Sup	plies				1.00
	Hour:	s 4.25		Labor:	255.00	Parts:	117.16	Total:	372.16	
Workorder: 1 Problem: P	703198 .M. service.	Meter:	57485			n Date:	03/30/2017	Closed:	04/13/20)17
- P.m. Service.					Parts Lis	t				Qty
- Pressure test	and inspect c	ooling sys	tem.flush an	d refill	5w20 Eng	jine Oil				7.00
system.					Napagold	Oil Filter				1.00
- Replace two ti					22" Wiper	Blade				2.00
- Test battery a		ystem.rep	lace bad bat	tery.	Floor Mat	-2pc Rub	Bk			1.00
- Shop Supplies					Stg Whee	l Cov - Fo	ord			1.00
					Used Fire	X Refurb	ished			1.00
					Anti Freez	ze Motorci	raft			2.00
					Battery 65	5				1.00
					17963649	2 Lt245-7	′5r17			2.00
					Shop Sup	plies				1.00
					Tire Dispo	osal Fee				2.00
	Hour:	s 7.76		Labor:	465.60	Parts:	817.80	Total:	1,283.40)
Norkorder: 1 Problem: R	707126 eplacewiper	Meter: blades.	61698		I	n Date:	07/20/2017	Closed:	07/31/20)17
- Replace wiper	blades.				Parts List	t				Qty
					22" Wiper	Blade				2.00
						Diaue				2.00

Palm Beach County Fleet Managen	nent
Asset Maintenance History	

Workorder: Problem:	1708331 P.M. service.	Meter:	62798			In Date:	08/23/2017	Closed:	09/07/201	7
- P.m. service).				Parts Lis	st				Qty
- Two new tire	es mount on fro	ont.nitroge	n fill. High spe	ed	5w20 En	gine Oil			7	7.00
balance all fou	ır.	-	- .		Napagol	d Oil Filter			1	00.1
	s new pads,nev			1.2 1	22" Wipe	er Blade			2	2.00
	e rotorsa.flush		system.test o	drive, ok.	1796364	92 Lt245-7	′5r17		2	2.00
•	service front d				Brake Pa	ad			1	00.1
•	service rear di				Reman/o	a			1	00.1
•	ont end alignm	ent.			Reman/o	a			1	00.1
- Shop Suppli	es				Napa Ge	ear 80w-90	Qt		3	3.00
					•	Ford Axle L			4	1.00
					Friction I					2.00
					Shop Su					.00
					•	osal Fee				2.00
	Hour	rs 13.25		Labor:	795.00		1,024.17	Total:	1,819.17	
Workorder: Problem:	1708844 Engine light o	Meter: n and che	63599 ck fuel light or	n.		In Date:	09/14/2017	Closed:	09/18/201	7
	uter .dddiagnois				Parts Lis	st			(Qty
	ch correct press peration.replace			olenoid	Valva As	sy .			1	.00
codes.perform	n evap test.	e puige so	ienoiu.cieai		Shop Su	pplies			1	.00
- Shop Suppli		rs 3.00		Labor	180.00	Porte	45.43	Total	225.43	
	:	5 3.00		Labui.	100.00	Faits.	40.40	TOLAI.	225.45	
Workorder: Problem:	1800733 P.M. service.	Meter:	68273			In Date:	01/22/2018	Closed:	01/31/201	8
- P.m. service	9.				Parts Lis	st			(Qty
- Rotate and I	high speed bal	ance all fo	ur wheels.nitr	ofill all.	5w20 En	gine Oil			7	7.00
- Shop Suppli	es				Napagol	d Oil Filter			1	.00
					22" Wipe	er Blade			2	2.00
					Washer	Fluid Conc	entr		1	00.1
						e X Refurb				.00
					Shop Su					.00
	Hour	rs 3.75		Labor:	225.00		44.69	Total:	269.69	
Workorder: Problem:	1804520 Left washer je	Meter:	72207			In Date:	05/01/2018	Closed:	05/03/201	8
	washer jet and				Parts Lis	st				Qty
	Justice of Jor and				Washer					.00
	Hour	rs 0.20		Labor:		Parts:	8.13	Total:	20.13	.00
	:									

Norkorder: 180525		73072		In Date:	05/22/2018	Closed:	05/30/2018
Problem: P.M. se	rvice and had to	jump start.					
- P.m. service.				Parts List			Q
- Charge battery fully .	load test battery	,failed test .r8	kr	Napagold Oil Filte	r		1.0
lefective battery .		and fluch init		5w20 Engine Oil			7.0
- Perform engine intak		-		Napagold Air Filte			1.0
 Perform tune up .rep vires and three coils .c 			a eight	Washer Fluid Con	centr		1.
- Rotate and balance a	all four tires .nitro	ogen fill tires.		22" Wiper Blade			2.
- Shop Supplies		-		Battery 65			1.
				Intake Cleaner Kit			1.
				Injector Cleaner			1.
				Espak Plug Wire			4. 4.
				Espak Plug Wire Spark Plug			4. 16.
				Al3z12029b			2.
				Coil Asy			1.
				Shop Supplies			1.
	Hours 12.25		Labor:	735.00 Parts	: 879.73	Total:	1,614.73
	:		Labor:				
Norkorder: 180955 Problem: P.M. se	: 0 Meter:	78222	Labor:	735.00 Parts In Date:	: 879.73 09/17/2018	Total: Closed:	
	: 0 Meter:	78222	Labor:				09/27/2018
Problem: P.M. se - P.m. service. - Replace two tires . B	: 0 Meter: rvice.			In Date:	09/17/2018		09/27/2018 C
Problem: P.M. se - P.m. service. - Replace two tires . B all.	: 0 Meter: rvice. alance and rotat	e all four tires.	. Nitrofill	In Date: Parts List	09/17/2018		09/27/2018 C 1.
Problem: P.M. se - P.m. service. - Replace two tires . B all. - Check and replace b	: 0 Meter: rvice. alance and rotat	e all four tires.	. Nitrofill	In Date: Parts List Napagold Air Filte	09/17/2018		09/27/2018 G 1. 1.
Problem: P.M. se - P.m. service. - Replace two tires . B all. - Check and replace b and retest.	: 0 Meter: rvice. alance and rotat oth tool box prop	e all four tires. os . Adjust stric	. Nitrofill	In Date: Parts List Napagold Air Filte Napagold Oil Filte 5w20 Engine Oil Used Fire X Refur	09/17/2018		09/27/2018 1. 1. 7. 1.
Problem: P.M. se - P.m. service. - Replace two tires . B all. - Check and replace b and retest. - Check and replace a	: 0 Meter: rvice. alance and rotat oth tool box prop Il six cab body m	e all four tires. os . Adjust stric nounts .	. Nitrofill	In Date: Parts List Napagold Air Filter Napagold Oil Filter 5w20 Engine Oil Used Fire X Refur 22" Wiper Blade	09/17/2018 er		09/27/2018 1. 1. 7. 1. 2.
Problem: P.M. se - P.m. service. - Replace two tires . B all. - Check and replace b and retest.	: 0 Meter: rvice. alance and rotat oth tool box prop Il six cab body m	e all four tires. os . Adjust stric nounts .	. Nitrofill	In Date: Parts List Napagold Air Filter Sw20 Engine Oil Used Fire X Refur 22" Wiper Blade 179636492 Lt245-	09/17/2018 er		09/27/2018 1. 1. 7. 1. 2. 2.
Problem: P.M. se - P.m. service. - Replace two tires . B all. - Check and replace b and retest. - Check and replace a - Complete front end	: 0 Meter: rvice. alance and rotat oth tool box prop Il six cab body m	e all four tires. os . Adjust stric nounts .	. Nitrofill	In Date: Parts List Napagold Air Filter Sw20 Engine Oil Used Fire X Refur 22" Wiper Blade 179636492 Lt245- Support	09/17/2018 er		09/27/2018 1. 1. 7. 1. 2. 2. 2.
Problem: P.M. se - P.m. service. - Replace two tires . B all. - Check and replace b and retest. - Check and replace a - Complete front end	: 0 Meter: rvice. alance and rotat oth tool box prop Il six cab body m	e all four tires. os . Adjust stric nounts .	. Nitrofill	In Date: Parts List Napagold Air Filter Napagold Oil Filter 5w20 Engine Oil Used Fire X Refur 22" Wiper Blade 179636492 Lt245- Support Body Mount Kit	09/17/2018 er		09/27/2018 1. 1. 1. 7. 1. 2. 2. 2. 2.
Problem: P.M. se - P.m. service. - Replace two tires . B all. - Check and replace b and retest. - Check and replace a - Complete front end	: 0 Meter: rvice. alance and rotat oth tool box prop Il six cab body m	e all four tires. os . Adjust stric nounts .	. Nitrofill	In Date: Parts List Napagold Air Filter Sw20 Engine Oil Used Fire X Refur 22" Wiper Blade 179636492 Lt245- Support Body Mount Kit Body Mount Kit	09/17/2018 er bished 75r17		09/27/2018 1. 1. 1. 7. 1. 2. 2. 2. 4.
Problem: P.M. se - P.m. service. - Replace two tires . B all. - Check and replace b and retest. - Check and replace a - Complete front end	: 0 Meter: rvice. alance and rotat oth tool box prop Il six cab body m	e all four tires. os . Adjust stric nounts .	. Nitrofill	In Date: Parts List Napagold Air Filter Napagold Oil Filter 5w20 Engine Oil Used Fire X Refur 22" Wiper Blade 179636492 Lt245- Support Body Mount Kit Body Mount Kit Mac Wite Lithium (09/17/2018 er bished 75r17		09/27/2018 0 1. 1. 1. 7. 1. 2. 2. 2. 4. 1. 1. 2. 2. 1. 1. 1. 2. 2. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
Problem: P.M. se - P.m. service. - Replace two tires . B all. - Check and replace b and retest. - Check and replace a - Complete front end	: 0 Meter: rvice. alance and rotat oth tool box prop Il six cab body m	e all four tires. os . Adjust stric nounts .	. Nitrofill	In Date: Parts List Napagold Air Filter Sw20 Engine Oil Used Fire X Refur 22" Wiper Blade 179636492 Lt245- Support Body Mount Kit Body Mount Kit	09/17/2018 er bished 75r17		09/27/2018 1. 1. 1. 7. 1. 2. 2. 2.

Palm Beach County Fleet Management
Asset Maintenance History

Workorder: 1902020 Problem: P.M. servi	Meter: ce.	83222			In Date:	02/22/2019	Closed:	03/11/20	019
- P.m. service.				Parts Li	st				Qty
- Test and replace right f	ront marker lig	ht .		Napagol	d Oil Filter				1.00
- Rotate and high speed	-		ill all .	5w20 Er					7.00
- Remove toolbox . Fabe	ricate and insta	all toolbox /fue	el tank	22" Wipe	er Blade				2.00
combo ,fuelpump ,fuel filt		. Wire in swite	ch and	Boxed N	liniatures				1.00
mount switch in cab . Tes - Shop Supplies	a system.			Napagol	d Fuel Filte	r			1.00
- Shop Supplies				Adapter					1.00
				Fab Loo	m-split Poly	/			10.00
				Primary	Wire				10.00
				Toggle S	Switch				1.00
				Fuse Ho	lder				1.00
				Shop Su	pplies				1.00
F	lours 9.25		Labor:	619.75	Parts:	69.72	Total:	689.47	
Workorder: 1908319 Problem: PM Servic	Meter:	89385			In Date:	08/09/2019	Closed:	08/19/20	019
- P.m. service.	-			Parts Li	st				Qty
- Inspect and service aux	fuel pump.			Napago	d Oil Filter				1.00
- Replace two tires . Rota		e all four tires		5w20 Er					7.00
Nitrofill all.				22" Wipe	-				2.00
- Shop Supplies				Used Fir	e X Refurbi	ished			1.00
				Napagol	d Fuel Filte	r			1.00
				Lt245/75	ir17 Mich D	efend Ltx			2.00
				Shop Su	pplies				1.00
				Tire Disp	osal Fee				2.00
F	lours 5.75		Labor:	385.25	Parts:	561.37	Total:	946.62	
Workorder: 1909192 Problem: Had to jun	Meter: np start .	89421			In Date:	09/06/2019	Closed:	09/11/20	019
- Charge battery fully . Te	est battery and	charging sys	tem .	Parts Li	st				Qty
R&r defective battery .				Battery					1.00
- Shop Supplies				Shop Su	pplies				1.00
F	lours 1.00		Labor:	67.00	Parts:	146.81	Total:	213.81	
Workorder: 2001753 Problem: Towed in f	Meter: for no start and	94026 I check engine	e light or	۱.	In Date:	02/20/2020	Closed:	02/24/20	020
- Computer diagnose che	eck engine liah	t and charging	g light .	Parts Li	st				Qty
codes P0625 and P065b	. Perform pinp	oint test and o	circuit	Alternad					1.00
test . R&r defective altern fully . Clear codes and re		and charge b	attery	Shop Su					1.00
- Shop Supplies									
F	lours 2.00		Labor:	146.00	Parts:	268.53	Total:	414.53	
:									

Workorder: Problem:	2001759 No start	Meter:	93976			In Date:	02/20/2020	Closed:	02/21/2020
- Tow From: Okeechobee Blvd and Wild Cat Way To: lv shop									
	Hou :	ırs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	2003383 TPMS light c	Meter:	96000			In Date:	04/03/2020	Closed:	04/06/2020
- Replace right rear tire sensor and balance . Nitrofill all and reset Tpms .					Parts List Tpms12 Sensor Tire Pr				Qty 1.00
- Shop Supplies					Shop Supplies			1.00	
	Hou :	ırs 1.00		Labor:	73.00	Parts:	79.89	Total:	152.89
Workorder: Problem:	2006017 Transition Pr	Meter: ep Charge	97237			In Date:	06/17/2020	Closed:	06/17/2020
- Transition Prep Charge									
	Hou :	ırs 2.00		Labor:	146.00	Parts:	0.00	Total:	146.00