<ul> <li>Workorder: 93908</li> <li>Problem: INSTA</li> <li>Install Tool Box-rention</li> <li>Shop Supplies</li> <li>Workorder: 93911</li> <li>Problem: PRE-ID</li> <li>Pre-delivery Inspect</li> <li>Workorder: 93934</li> <li>Problem: INSTA</li> <li>Remove Computer 10164768.fabricate A</li> <li>Harness.</li> <li>Shop Supplies</li> <li>Workorder: 93939</li> <li>Problem: DUPL</li> <li>Duplicate And Prog</li> </ul>	LL TOC nove Fro Hours : 6 DELIVEF tion Hours : 6 LL CON Stand 8	om A Turn s 1.00 Meter: RY INSPE s 2.00 Meter: IPUTER s Harness II Comput	0 CTION 340 STAND. Fr Asset		Parts Li Shop Su 60.00 120.00 Parts Li Shop Su	In Date: Parts: Parts: Parts: In Date:	06/17/2009	Closed:	06/18/20 62.00 06/17/20 120.00 06/26/20	<b>Qty</b> 1.00
<ul> <li>Shop Supplies</li> <li>Workorder: 93911 Problem: PRE-I</li> <li>Pre-delivery Inspect</li> <li>Workorder: 93934 Problem: INSTA</li> <li>Remove Computer 10164768.fabricate A Harness.</li> <li>Shop Supplies</li> <li>Workorder: 93939 Problem: DUPL</li> </ul>	Hours 6 DELIVEF tion Hours 6 LL CON Stand & nd Insta	s 1.00 Meter: RY INSPE s 2.00 Meter: IPUTER s Harness II Comput	0 CTION 340 STAND. Fr Asset	Labor:	Shop Su 60.00 120.00 Parts Li	In Date: Parts: Parts: Parts: In Date:	06/17/2009	Closed: Total:	06/17/20	1.00 009 009 Qty
Workorder:93911 Problem:Pre-deliveryInspect• Pre-deliveryInspectWorkorder:93934 Problem:• RemoveComputer10164768.fabricateA Harness. • Shop• ShopSuppliesWorkorder:93939 Problem:DUPL	: 6 DELIVEF Hours : 6 .LL CON Stand & nd Insta	Meter: RY INSPE s 2.00 Meter: IPUTER s Harness Il Comput	340 STAND. Fr Asset	Labor:	60.00 120.00 Parts Li	Parts: In Date: Parts: In Date:	06/17/2009	Closed: Total:	06/17/20	009 009 009 <b>Qty</b>
Problem: PRE-I - Pre-delivery Inspect Workorder: 93934 Problem: INSTA - Remove Computer 10164768.fabricate A Harness. - Shop Supplies Workorder: 93939 Problem: DUPL	: 6 DELIVEF Hours : 6 .LL CON Stand & nd Insta	Meter: RY INSPE s 2.00 Meter: IPUTER s Harness Il Comput	340 STAND. Fr Asset	Labor:	120.00 Parts Li	In Date: Parts: In Date:	06/17/2009	Closed: Total:	06/17/20	009 Qty
Problem: PRE-I - Pre-delivery Inspect Workorder: 93934 Problem: INSTA - Remove Computer 10164768.fabricate A Harness. - Shop Supplies Workorder: 93939 Problem: DUPL	DELIVEF tion Hours : 6 .LL CON Stand & nd Insta	RY INSPE s 2.00 Meter: MPUTER s Harness Il Comput	340 STAND. Fr Asset		Parts Li	Parts: In Date:	0.00	Total:	120.00	009 Qty
Workorder: 93934 Problem: INSTA - Remove Computer 10164768.fabricate A Harness. - Shop Supplies Workorder: 93939 Problem: DUPL	Hours : 6 ILL CON Stand & nd Insta	Meter: /IPUTER \$ Harness II Comput	STAND. Fr Asset		Parts Li	In Date:				Qty
Problem: INSTA - Remove Computer 10164768.fabricate A Harness. - Shop Supplies Workorder: 93939 Problem: DUPL	: 6 LL CON Stand & nd Insta	Meter: /IPUTER \$ Harness II Comput	STAND. Fr Asset		Parts Li	In Date:				Qty
Problem: INSTA - Remove Computer 10164768.fabricate A Harness. - Shop Supplies Workorder: 93939 Problem: DUPL	LL CON Stand & nd Insta	HATTER S	STAND. Fr Asset	nd Wire In		ist	06/23/2009	Closed:	06/26/20	Qty
10164768.fabricate A Harness. - Shop Supplies Workorder: 93939 Problem: DUPL	nd Insta	II Comput		nd Wire In						-
Harness. - Shop Supplies Workorder: 93939 Problem: DUPL		·	er Stand A	nd Wire In	Shop Su	upplies				1.00
Workorder: 93939 Problem: DUPL	Hours	5 00								
Problem: DUPL	Hours									
Problem: DUPL	:	\$ 5.00		Labor:	300.00	Parts:	2.00	Total:	302.00	
- Duplicate And Prog		Meter:	340 GRAM KE`	Y		In Date:	06/24/2009	Closed:	06/24/20	)09
	ram Key	/			Parts Li	ist				Qty
- Shop Supplies	-				164-r04 <sup>-</sup>	75 Ign Key 2	2010-earlier (c	don't Reorde	er)	1.00
					Shop Su	upplies				1.00
	Hours :	s 1.00		Labor:	60.00	Parts:	23.45	Total:	83.45	
Workorder: 10003 Problem: P.M. S		Meter:	5727			In Date:	01/11/2010	Closed:	01/20/20	)10
- P.m service.					Parts Li	ist				Qty
- Rotate & balance a	ll four tir	es.			Shop Su	upplies				1.00
- Repair rear hitch pi	ntal pin	chain.			1372 O	il Filter Frm	Ph2 Wix 513	372		1.00
- Shop Supplies					5w20 Er	ngine Oil				7.00
							d Fire Extings	hers		1.00
					Floor Ma	ats / 001382				1.00
					243.00	Parts:	91 62	Total <sup>.</sup>	334.62	

Proplem:	1008101 Pm servi		Meter: o see not	10400 es on noises	and fire e		In Date: r.	07/30/2010	Closed:	08/30/20	010
- Perform pm						Parts Lis					Qty
- Rotate and b		l four t	ires			Shop Sup					1.00
- Transport ve				for replacing	failed	• •	•	n Ph2 Wix 51	372		1.00
catalytic conve								Vitc Fa1883 W			1.00
warranty								Mtc Fg1083 V			1.00
- Shop Suppli	es					5w20 Eng		inte i groco v	WX 00240		7.00
						-	-	e Gel Guard (	mantek)		1.00
								s 20" Blade	mantery		2.00
		Hours	5.75		Labor:	345.00		60.72	Total:	405.72	2.00
Workorder:	1009206		Meter:	10400			In Date:	08/25/2010	Closed:	08/26/20	010
Problem:	reflash c	anceiv	er								
- Reflash Can	nceiver					Parts Lis	t				Qty
- Shop Suppli	es					Shop Sup	oplies				1.00
		Hours	1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1014076 Left brak		Meter: out.	13555			In Date:	12/27/2010	Closed:	12/28/20	010
- Test and rep	place faile	d left b	orake lam	p bulb with n	ew.	Parts Lis	t				Qty
						3157 Tail	Light Bulk	S			1.00
		Hours :	0.50		Labor:	30.00	Parts:	1.19	Total:	31.19	
Workorder:	1104413		Meter:	16179			In Date:	04/26/2011	Closed:	05/05/20	111
Problem:				10175			in Dale.	04/20/2011			511
Problem:	P.M. Ser			10175		Parts Lis		04/20/2011			
Problem: - Perform pm	P.M. Ser service.	vice.			new.		t	04/20/2011			Qty
Problem: - Perform pm - Fabricate an - Inspect and	P.M. Ser service. d replace	vice. failed	hitch pin	del pin with r		Parts Lis Shop Sup	<b>t</b> oplies	n Ph2 Wix 51:			<b>Qty</b> 1.00
Problem: - Perform pm - Fabricate an - Inspect and with new.	P.M. Ser service. nd replace replace th	vice. failed nree fa	hitch pin iled ac ve	del pin with r ents outlets o	n dash	Parts Lis Shop Sup 1372 Oil	<b>t</b> oplies Filter Frm		372		<b>Qty</b> 1.00
Problem: - Perform pm - Fabricate an - Inspect and with new. - Install two ne	P.M. Ser service. nd replace replace th ew tires to	vice. failed nree fa	hitch pin iled ac ve	del pin with r ents outlets o	n dash	Parts Lis Shop Sup 1372 Oil	<b>t</b> oplies Filter Frm Fuel Filter	n Ph2 Wix 51	372		<b>Qty</b> 1.00
Problem: - Perform pm - Fabricate an - Inspect and with new. - Install two ne balance all four	P.M. Ser service. nd replace replace th ew tires to ur.	vice. failed nree fa	hitch pin iled ac ve	del pin with r ents outlets o	n dash	Parts Lis Shop Sup 1372 Oil G10166 F	<b>t</b> oplies Filter Frm Fuel Filter gine Oil	n Ph2 Wix 51	372		<b>Qty</b> 1.00 1.00
Problem: - Perform pm - Fabricate an - Inspect and with new. - Install two ne balance all four	P.M. Ser service. nd replace replace th ew tires to ur.	vice. failed nree fa	hitch pin iled ac ve	del pin with r ents outlets o	n dash	Parts Lis Shop Sup 1372 Oil G10166 F 5w20 Eng A/c Dash 31-20 Wip	t pplies Filter Frm Fuel Filter gine Oil Outlets per Blades	n Ph2 Wix 51: Mtc Fg1083 V s 20" Blade	372 √ix 33243		<b>Qty</b> 1.00 1.00 7.00 3.00 2.00
Problem: - Perform pm - Fabricate an - Inspect and with new. - Install two ne balance all four	P.M. Ser service. nd replace replace th ew tires to ur.	vice. failed nree fa	hitch pin iled ac ve	del pin with r ents outlets o	n dash	Parts Lis Shop Sup 1372 Oil G10166 F 5w20 Eng A/c Dash 31-20 Wip 17963649	t pplies Filter Frm Fuel Filter gine Oil Outlets per Blades 92 Lt245/7	n Ph2 Wix 51: Mtc Fg1083 V	372 √ix 33243		Qty 1.00 1.00 7.00 3.00 2.00
Problem: - Perform pm - Fabricate an - Inspect and with new. - Install two ne balance all four	P.M. Ser service. nd replace replace th ew tires to ur.	vice. failed nree fa	hitch pin iled ac ve	del pin with r ents outlets o	n dash	Parts Lis Shop Sup 1372 Oil G10166 F 5w20 Eng A/c Dash 31-20 Wip	t pplies Filter Frm Fuel Filter gine Oil Outlets per Blades 92 Lt245/7	n Ph2 Wix 51: Mtc Fg1083 V s 20" Blade	372 √ix 33243		Qty 1.00 1.00 7.00 3.00 2.00
Problem: - Perform pm - Fabricate an - Inspect and with new. - Install two ne palance all four	P.M. Ser service. nd replace replace th ew tires to ur.	vice. failed nree fa	hitch pin iled ac ve	del pin with r ents outlets o	n dash	Parts Lis Shop Sup 1372 Oil G10166 F 5w20 Eng A/c Dash 31-20 Wig 17963649 Tire Dispo Tr416 Val	t pplies Filter Frm Fuel Filter gine Oil Outlets per Blades 2 Lt245/7 osal Fee Ive Stem	n Ph2 Wix 51: Mtc Fg1083 V s 20" Blade	372 √ix 33243		<b>Qty</b> 1.00 1.00 7.00 3.00 2.00 2.00 2.00 2.00
Problem: - Perform pm - Fabricate an - Inspect and with new. - Install two ne balance all four	P.M. Ser service. nd replace replace th ew tires to ur.	vice. failed nree fa	hitch pin iled ac ve	del pin with r ents outlets o	n dash	Parts Lis Shop Sup 1372 Oil G10166 F 5w20 Eng A/c Dash 31-20 Wig 17963649 Tire Dispo	t pplies Filter Frm Fuel Filter gine Oil Outlets per Blades 2 Lt245/7 osal Fee Ive Stem	n Ph2 Wix 51: Mtc Fg1083 V s 20" Blade	372 √ix 33243		<b>Qty</b> 1.00 1.00 7.00 3.00 2.00 2.00 2.00 2.00
Problem: - Perform pm - Fabricate an - Inspect and with new. - Install two ne balance all four	P.M. Ser service. nd replace replace th ew tires to ur.	vice. failed nree fa	hitch pin iled ac ve ont whee	del pin with r ents outlets o	n dash II and	Parts Lis Shop Sup 1372 Oil G10166 F 5w20 Eng A/c Dash 31-20 Wig 17963649 Tire Dispo Tr416 Val	t Filter Frm Fuel Filter gine Oil Outlets per Blades 92 Lt245/7 osal Fee Ive Stem ntle Pin	n Ph2 Wix 51: Mtc Fg1083 V s 20" Blade	372 Vix 33243 r Sr-a E	876.14	<b>Qty</b> 1.00 1.00 7.00 3.00 2.00 2.00 2.00 2.00
Problem: - Perform pm - Fabricate and with new. - Install two no balance all fou - Shop Suppli	P.M. Ser service. nd replace replace th ew tires to ur. ies 1108113	vice. failed aree fa the fr Hours :	hitch pin iled ac ve ont whee 6.00 Meter:	del pin with r ents outlets o	n dash II and	Parts Lis Shop Sup 1372 Oil G10166 F 5w20 Eng A/c Dash 31-20 Wip 17963649 Tire Dispo Tr416 Val 18410 Pir 360.00	t Filter Frm Fuel Filter gine Oil Outlets per Blades 92 Lt245/7 osal Fee Ive Stem ntle Pin	n Ph2 Wix 51: Mtc Fg1083 V s 20" Blade 5r17 Wrangle	372 Vix 33243 r Sr-a E		Qty 1.00 1.00 7.00 2.00 2.00 2.00 2.00 1.00
Problem: - Perform pm - Fabricate and with new Install two nebalance all fou - Shop Suppli Workorder: Problem:	P.M. Ser service. nd replace replace th ew tires to r. les 1108113 Left rear	vice. failed aree fa the fr the fr tire fla	hitch pin iled ac ve ont whee 6.00 Meter: t.	del pin with r ents outlets o els.nitrogen fi 18593	n dash II and Labor:	Parts Lis Shop Sup 1372 Oil G10166 F 5w20 Eng A/c Dash 31-20 Wip 17963649 Tire Dispo Tr416 Val 18410 Pir 360.00	t piles Filter Frm Fuel Filter gine Oil Outlets per Blades 2 Lt245/7 osal Fee Ive Stem ntle Pin Parts: In Date:	n Ph2 Wix 513 Mtc Fg1083 V 5 20" Blade 5r17 Wrangle 516.14	372 Vix 33243 r Sr-a E Total:	876.14	Qty 1.00 1.00 7.00 2.00 2.00 2.00 1.00
Problem: - Perform pm - Fabricate and - Inspect and with new. - Install two ne balance all fou - Shop Suppli - Shop Suppli	P.M. Ser service. Ind replace replace th ew tires to ar. les 1108113 Left rear	vice. failed aree fa the fr the fr tire fla	hitch pin iled ac ve ont whee 6.00 Meter: t.	del pin with r ents outlets o els.nitrogen fi 18593	n dash II and Labor:	<b>Parts Lis</b> Shop Sup 1372 Oil G10166 F 5w20 Eng A/c Dash 31-20 Wig 17963649 Tire Dispo Tr416 Val 18410 Pir 360.00	t pplies Filter Frm Fuel Filter gine Oil Outlets per Blades 2 Lt245/7 osal Fee Ive Stem ntle Pin Parts: In Date:	n Ph2 Wix 513 Mtc Fg1083 V 5 20" Blade 5r17 Wrangle 516.14	372 Vix 33243 r Sr-a E Total:	876.14	Qty 1.00 1.00 7.00 2.00 2.00 2.00 2.00 1.00

Workorder: Problem:	1110202 Has to jump s	Meter: start in the	19995 am.		Ir	n Date:	09/26/2011	Closed:	09/28/2	011
after recharge	g and charging e.replace failed			oad test	Parts List Shop Supp	olies				<b>Qty</b> 1.00
- Shop Suppl	ies				Group 65 E		1.00			
	Hou :	rs 1.00		Labor:	60.00	Parts:	130.75	Total:	190.75	
Workorder: Problem:	1200914 P.M. service.	Meter:	22926		Ir	n Date:	01/30/2012	Closed:	02/08/2	012
- P.m. Service	e.				Parts List					Qty
- Replace two	o tires,rotate ar	nd balance	all four.		Shop Supp	olies				1.00
- Shop Suppl	ies				1372 Oil F	ilter Frm	n Ph2 Wix 51	372		1.00
					Ca10262 A	Air Filter I	Mtc Fa1883 W	/ix 49883		1.00
					5w20 Engi	ne Oil				7.00
					179636492	2 Lt245/7	75r17 Wrangle	r Sr-a E		2.00
					Tire Dispos	sal Fee				2.00
					Tr416 Valv	e Stem				2.00
	Hou	rs 4.75		Labor:	285.00	Parts:	402.82	Total:	687.82	
Workorder:	: 1300221	Meter:	28664		Ir	n Date:	01/07/2013	Closed:	01/24/20	013
	: 1300221 Pm service a				Ir	n Date:		Closed:	01/24/20	013
Problem:	Pm service a				Ir Parts List	n Date:		Closed:	01/24/20	
Problem: - Perform pm	Pm service a	nd ac blow	s warm air.	eplace		n Date:		Closed:	01/24/20	013 <b>Qty</b> 1.00
Problem: - Perform pm - Ac performa failed compres	Pm service a service. ance and leak t ssor discharge	nd ac blow test.recove line with n	s warm air. r freon and r ew.vacume a	and	Parts List			Closed:	01/24/20	Qty
Problem: - Perform pm - Ac performation failed compresent recharge systematics	Pm service a service. ance and leak t ssor discharge em to specs wi	nd ac blow test.recove line with n	s warm air. r freon and r ew.vacume a	and	<b>Parts List</b> Tube Asy	rigerant	01/07/2013	Closed:	01/24/20	<b>Qty</b> 1.00
Problem: - Perform pm - Ac performation failed compresent recharge system debris from comparison	Pm service a service. ance and leak t ssor discharge em to specs w ondenser fins.	nd ac blow test.recove line with n ith virgin fre	s warm air. r freon and r ew.vacume a eon and oil.c	and lean	<b>Parts List</b> Tube Asy R134a Ref	rigerant ale Conn	01/07/2013 ector	Closed:	01/24/20	<b>Qty</b> 1.00 3.00
Problem: - Perform pm - Ac performation failed compresent recharge system debris from co - Diagnose tra-	Pm service a service. ance and leak t ssor discharge em to specs wi	nd ac blow test.recove line with n ith virgin fre	s warm air. r freon and r ew.vacume a eon and oil.c nop.test and	and lean replace	<b>Parts List</b> Tube Asy R134a Ref 5404 Fema	rigerant ale Conn Frailer W	01/07/2013 ector	Closed:	01/24/20	<b>Qty</b> 1.00 3.00 1.00
Problem: - Perform pm - Ac performation failed compresent recharge system debris from co - Diagnose tra-	Pm service a service. ance and leak t ssor discharge em to specs wi ondenser fins. ailer harness re	nd ac blow test.recove line with n ith virgin fre	s warm air. r freon and r ew.vacume a eon and oil.c nop.test and	and lean replace	Parts List Tube Asy R134a Ref 5404 Fema 8616-100 T	rigerant ale Conn Trailer W ne Oil	01/07/2013 ector	Closed:	01/24/20	<b>Qty</b> 1.00 3.00 1.00 2.00
Problem: - Perform pm - Ac performation failed comprese recharge systed debris from co - Diagnose tra- failed receptations secure. - Rotate and	Pm service a service. ance and leak t ssor discharge em to specs wi ondenser fins. ailer harness re cle and harnes balance all fou	nd ac blow test.recove line with n ith virgin fre eceptacle it is wiring wi	s warm air. r freon and r ew.vacume a eon and oil.c nop.test and	and lean replace	Parts List Tube Asy R134a Ref 5404 Fema 8616-100 T 5w20 Engin	rigerant ale Conn Trailer W ne Oil ilter	01/07/2013 ector	Closed:	01/24/2	<b>Qty</b> 1.00 3.00 1.00 2.00 7.00
Problem: - Perform pm - Ac performation failed compresent recharge system debris from com- - Diagnose tra- failed receptations secure. - Rotate and log- - Perform when	Pm service a service. ance and leak t ssor discharge em to specs wi ondenser fins. ailer harness re cle and harnes balance all fou eel alignment o	nd ac blow test.recove line with n ith virgin fre eceptacle it is wiring wi	s warm air. r freon and r ew.vacume a eon and oil.c nop.test and	and lean replace	Parts List Tube Asy R134a Ref 5404 Fema 8616-100 T 5w20 Engin 1372 Oil Fi	rigerant ale Conn Trailer W ne Oil ilter Filter	01/07/2013 ector /ire	Closed:	01/24/20	<b>Qty</b> 1.00 3.00 1.00 2.00 7.00 1.00
Problem: - Perform pm - Ac performation failed comprese recharge systed debris from co - Diagnose tra- failed receptations secure. - Rotate and	Pm service a service. ance and leak t ssor discharge em to specs wi ondenser fins. ailer harness re cle and harnes balance all fou eel alignment o	nd ac blow test.recove line with n ith virgin fre eceptacle it is wiring wi	s warm air. r freon and r ew.vacume a eon and oil.c nop.test and	and lean replace	Parts List Tube Asy R134a Ref 5404 Fema 8616-100 T 5w20 Engin 1372 Oil Fi Ford Fuel F	rigerant ale Conn Trailer W ne Oil ilter Filter Refurbe	01/07/2013 ector Vire	Closed:	01/24/2	<b>Qty</b> 1.00 3.00 1.00 2.00 7.00 1.00 1.00
Problem: - Perform pm - Ac performation failed compresent recharge system debris from com- - Diagnose tra- failed receptations secure. - Rotate and log- - Perform when	Pm service a service. ance and leak t ssor discharge em to specs wi ondenser fins. ailer harness re cle and harnes balance all fou eel alignment o	nd ac blow test.recove line with n ith virgin fre eceptacle it is wiring wi	s warm air. r freon and r ew.vacume a eon and oil.c nop.test and	and lean replace	Parts List Tube Asy R134a Ref 5404 Fema 8616-100 T 5w20 Engin 1372 Oil Fi Ford Fuel F Used Firex	rigerant ale Conn Trailer W ne Oil ilter Filter Refurbe er Blades	01/07/2013 ector Vire	Closed:	01/24/2	<b>Qty</b> 1.00 3.00 1.00 2.00 7.00 1.00 1.00
Problem: - Perform pm - Ac performation failed compresent recharge system debris from com- - Diagnose tra- failed receptations secure. - Rotate and log- - Perform when	Pm service a service. ance and leak t ssor discharge em to specs wi ondenser fins. ailer harness re cle and harnes balance all fou eel alignment o	nd ac blow test.recove line with n ith virgin fre eceptacle it is wiring wi	s warm air. r freon and r ew.vacume a eon and oil.c nop.test and	and lean replace	Parts List Tube Asy R134a Ref 5404 Fema 8616-100 T 5w20 Engin 1372 Oil Fi Ford Fuel F Used Firex 31-20 Wipe	rigerant ale Conn Trailer W ne Oil ilter Filter Refurbe er Blades	01/07/2013 ector Vire	Closed:	01/24/20	<b>Qty</b> 1.00 3.00 1.00 7.00 1.00 1.00 2.00
Problem: - Perform pm - Ac performation failed compresent recharge system debris from com- - Diagnose tra- failed receptations secure. - Rotate and log- - Perform when	Pm service a service. ance and leak t ssor discharge em to specs wi ondenser fins. ailer harness re cle and harnes balance all fou eel alignment o	nd ac blow test.recove line with n ith virgin fre eceptacle it is wiring wi	s warm air. r freon and r ew.vacume a eon and oil.c nop.test and	and lean replace	Parts List Tube Asy R134a Ref 5404 Fema 8616-100 T 5w20 Engin 1372 Oil Fi 1372 Oil Fi Ford Fuel F Used Firex 31-20 Wipe Brake Clea	rigerant ale Conn Trailer W ne Oil ilter Filter Refurbe er Blades aner	01/07/2013 ector Vire	Closed:	01/24/2	<b>Qty</b> 1.00 3.00 1.00 7.00 1.00 1.00 2.00 1.00
Problem: - Perform pm - Ac performation failed compresent recharge system debris from com- - Diagnose tra- failed receptations secure. - Rotate and log- - Perform when	Pm service a service. ance and leak t ssor discharge em to specs wi ondenser fins. ailer harness re cle and harnes balance all fou eel alignment o	nd ac blow test.recove line with n ith virgin fre eceptacle it is wiring wi	s warm air. r freon and r ew.vacume a eon and oil.c nop.test and	and lean replace	Parts List Tube Asy R134a Ref 5404 Fema 8616-100 T 5w20 Engin 1372 Oil Fi Ford Fuel F Used Firex 31-20 Wipe Brake Clea Tube Asy	rigerant ale Conn Trailer W ne Oil ilter Filter Refurbe er Blades aner	01/07/2013 ector Vire	Closed:	01/24/2	<b>Qty</b> 1.00 3.00 1.00 7.00 1.00 1.00 2.00 1.00 1.00

Workorder: Problem:	1302861 A/C blows v	Meter: warm air only.	29558			In Date:	03/25/2013	Closed:	04/03/20	13
- Ac performa		-		and	Parts L	ist				Qty
replace failed a					Ac Seal	Kit				2.00
valve with new freon and ac o		d recharge sy	stem to spec	cs with	O Ring					1.00
- Shop Suppli					Accumu	llator				1.00
Chop Cuppin					R134a F	Refrigerant				2.00
					E8 A-c (	Oil R134a A	-C			1.00
					Tube Fi	lter				1.00
					Shop Su	upplies				1.00
	Ho	ours 3.75		Labor:	225.00	Parts:	213.70	Total:	438.70	
Workorder: Problem:	1312233 needs pintle	Meter: e hitch	32775			In Date:	12/06/2013	Closed:	12/10/20	13
- Secure hitch	for dept (pa	rts only)			Parts L					Qty
- Shop Suppli	es				Shop Su	upplies				1.00
					Pintle H	itch				1.00
	Ho	ours 0.00		Labor:	0.00	Parts:	61.99	Total:	61.99	
Workorder: Problem:	1404379 P.M. servic	Meter: e and left fror	34656 It going flat.			In Date:	05/05/2014	Closed:	05/14/20	14
- Perform pm	service.				Parts L	ist				Qty
- Test and rep	lace failed th	nird brake lan	np bulb with r	new	5w20 Ei	ngine Oil				7.00
flush and re	new transmi	ssion fluid.			Napago	ld Oil Filter				1.00
- Repair flat le	ft front tire.n	itrogen fill an	d balance all	four.	Used Fi	re X Refurbi	ished			1.00
- Shop Suppli	es				Wiper B	lade				2.00
					Syn-atf	Trans Fluid	S		1	16.00
					Shop Su	upplies				1.00
	Ho	ours 6.55		Labor:	393.00	Parts:	119.56	Total:	512.56	
Workorder: Problem:	1411305 Pm service	Meter:	37042			In Date:	11/12/2014	Closed:		
-	Hc	ours 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	

Problem:	1411860 Pm service	<b>Meter:</b> ,Right rear tir	37294 re flat.			In Date:	11/24/2014	Closed:	12/10/2014
- Pm service.					Parts Lis	st			C
- Check batter	y and charg	jing system.t	attery failed	loadtest	5w20 En	gine Oil			7
after recharge.	•	-			Napagolo	d Oil Filter			1
<ul> <li>Diagnose blo replace defecti</li> </ul>			inop.pinpoint	t test and	Napagolo	d Fuel Filte	r		1
- Repair one fl			e all four		Wiper Bla	ade			2
- Shop Supplie					Battery 6				1
						lotor Resis	tor		1
		0.75			Shop Su		040.00	<b>-</b>	1
	HC :	ours 6.75		Labor:	405.00	Parts:	213.98	i otal:	618.98
Workorder: Problem:	1504238 wont fuel	Meter:	38643			In Date:	04/24/2015	Closed:	04/27/2015
- Test and rem	nove cancei <sup>,</sup>	ver issue fue	l card		Parts Lis	st			C
- Shop Supplie	es				Shop Su	pplies			1
	Ho	ours 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00
Workorder: Problem:	1512390 Pm service	Meter:	42141			In Date:	12/08/2015	Closed:	12/31/2018
- Pm service.					Parts Lis	st			C
- Replace one	defective le	eft ac vent an	d two defecti	ive center	5w20 En	gine Oil			7
ac vents.		<i>•</i>			Napagolo	d Oil Filter			1
- Replace and			ation hashing		Napagolo	d Fuel Filte	r		1
- Replace two			•			Fluid Conce	entr		1
- Replace both moisture.	i delective i	leadamp sea	albeams due	10	20" Wipe				2
- Complete fro	ont end align	ment and ro	adtest.			d Air Filter			1
- Shop Supplie	es				Body Mo				2
					Body Mo				4
					Halogen Tire	Lamp			2 4
					Louvre A	CV/			4
					Louvie A	.5y			3
					Shop Su	•			1
					Shop Su Tire Disp	pplies			1 4
	Hc	ours 15.25		Labor:		pplies losal Fee	1,754.08	Total:	1 4 2,669.08
	: 1603142	ours 15.25 <b>Meter:</b> nage (Broker	42920 n Headlight)	Labor:	Tire Disp	pplies losal Fee	1,754.08 03/22/2016	Total: Closed:	4 2,669.08
	: 1603142 Frt end dan	Meter: nage (Broker	n Headlight)		Tire Disp	pplies osal Fee Parts:			4 2,669.08
	: 1603142 Frt end dan 2500 40th S	<b>Meter:</b> nage (Broker	n Headlight)		Tire Disp 915.00	pplies osal Fee Parts:	03/22/2016		4 2,669.08 03/24/2016
Problem: - Tow From: 1 Workorder:	: 1603142 Frt end dan 2500 40th S Ho : 1604121	<b>Meter:</b> nage (Broker Street North-r	n Headlight) royal Palm Be 42920	each Labor:	Tire Disp 915.00 0.00	pplies losal Fee Parts: In Date:	03/22/2016	Closed:	4 2,669.08 03/24/2016
Problem: - Tow From: 1 Workorder:	: 1603142 Frt end dan 2500 40th S Ho : 1604121 damage to	Meter: mage (Broker Street North-r ours 0.00 Meter: rgt frt fender,	n Headlight) royal Palm Be 42920 , door, hood,	each Labor: grille & lig	Tire Disp 915.00 0.00	pplies losal Fee Parts: In Date: Parts:	03/22/2016	Closed: Total:	4 2,669.08 03/24/2016 0.00

Workorder: Problem:	1605741 hitch	Meter:	43198			In Date:	06/03/2016	Closed:	06/17/20	)16
- Order hitch p	parts				Parts Lis	t				Qty
- Shop Suppli	es				2535 D P	Hitch Mo	ount			1.00
					pintle hoc	k				2.00
					Mounting	Kit				1.00
					pintle mo	unt				1.00
					mounting	kit				1.00
					Shop Sup	plies				1.00
	Ho	urs 0.50		Labor:	30.00	Parts:	430.64	Total:	460.64	
Workorder: Problem:	1708224 P.M. service	Meter:	48061			In Date:	08/21/2017	Closed:	08/31/20	)17
- P.m. service	<b>)</b> .				Parts Lis	t				Qty
- Replace wor				nd replace	5w20 Eng	gine Oil				7.00
calipers.flush a	-		ve.		Napagold	Oil Filter				1.00
- Perform tran					Napagold	Fuel Filte	r			1.00
- Rotate and b		tires.nitrofill.			20" Wiper	<sup>r</sup> Blade				2.00
- Shop Suppli	es				Used Fire	X Refurb	ished			1.00
					Stg Whee	el Cov - Fo	ord			1.00
					Pedal Pa	b				1.00
					Bulb					1.00
					Colinerw		o Loft Front (	ocline		1.00
					Caliper w	/ Hardwar	e - Left Front (	eclips		
							e - Right Front	-		1.00
								-		
					Caliper w	/ Hardwar		-		1.00
					Caliper w Pads B Fluid D	/ Hardwar	e - Right Front	-		1.00 1.00
					Caliper w Pads B Fluid D	/ Hardwar ot 3-32oz isfer Case	e - Right Front	-		1.00 1.00 1.00

Workorder: Problem:	1807932 P.M. servio	Meter: ce.	52598		Ir	n Date:	08/02/2018	Closed:	08/09/20	018
- P.m. service	е.				Parts List					Qty
		ct cooling sv	stem . Flush a	and refill .	Lamp Asy					1.00
			. Replace cra		Napagold	Oil Filter				1.00
right rear tail I					5w20 Engi					7.00
- Inspect and	service fron	nt differential.			20" Wiper					2.00
- Inspect and	service real	r differential.			Used Fire		ished			1.00
- Replace fro	nt and rear b	oump stops .			Napagold I	Fuel Filte	r			1.00
- Rotate and	high speed l	balance all fo	our tires.		Coolant Fo					2.00
- Shop Suppl	lies				Boxed Min	iatures				2.00
					Napa Gea	r 80w-90	Qt			3.00
					Ptex Ultra					1.00
					Friction Mo	•				2.00
					75w140 Fc		_ube			3.00
					Bumper					2.00
					bumper					2.00
					Shop Supp	olies				1.00
	H	ours 9.75		Labor:	585.00		405.55	Total:	990.55	
We also ado as	1809534	Meter:	52598		Ir	n Date:	09/14/2018	Closed:	09/18/20	018
	Dead batte	ery.		attory fail						Otv
Problem:	Dead batte and test batte	ery. ery and charg	ing system.ba	attery fail	Parts List					-
Problem: - Recharge a	Dead batte and test batte ace defective	ery. ery and charg		attery fail	Parts List Battery					1.00
Problem: - Recharge a load test.repla	Dead batte and test batte ace defective lies	ery. ery and charg		attery fail Labor:	<b>Parts List</b> Battery Shop Supp	olies	130.64	Total:	190.64	1.00
Problem: - Recharge a load test.repla - Shop Suppl Workorder:	Dead batte and test batte ace defective lies H 1812660	ery. ery and charge battery. ours 1.00 <b>Meter:</b>	ing system.ba	Labor:	Parts List Battery Shop Supp 60.00	olies		Total: Closed:	190.64	1.00
Problem: - Recharge a load test.repla - Shop Suppl Workorder: Problem:	Dead batte and test batte ace defective lies H : 1812660 Cut off loci	ery. ery and charge battery. ours 1.00 <b>Meter:</b> king hitch pin	ing system.ba 56099 and install ne	Labor:	Parts List Battery Shop Supp 60.00	olies Parts: n Date:	130.64			1.00 1.00
Problem: - Recharge a load test.repla - Shop Suppl Workorder: Problem: - Cut off old lo	Dead batte and test batte ace defective lies H 1812660 Cut off lock	ery. ery and charge battery. ours 1.00 <b>Meter:</b> king hitch pin	ing system.ba	Labor:	Parts List Battery Shop Supp 60.00 Ir Parts List	olies Parts: n Date:	130.64			Qty
Problem: - Recharge a load test.repla - Shop Suppl Workorder: Problem: - Cut off old le missing pintle	Dead batte and test batte ace defective lies H 1812660 Cut off lock ocking hitch	ery. ery and charge battery. ours 1.00 <b>Meter:</b> king hitch pin	ing system.ba 56099 and install ne	Labor:	Parts List Battery Shop Supp 60.00 Ir Parts List Pin Hook	olies Parts: n <b>Date:</b>	130.64			1.00 1.00 018 Qty 1.00
Problem: - Recharge a load test.repla - Shop Suppl Workorder: Problem: - Cut off old lo	Dead batte and test batte ace defective lies H 1812660 Cut off lock ocking hitch	ery. ery and charge battery. ours 1.00 <b>Meter:</b> king hitch pin	ing system.ba 56099 and install ne	Labor:	Parts List Battery Shop Supp 60.00 Ir Parts List Pin Hook Pintle Hool	olies Parts: n <b>Date:</b> k Mount	130.64			1.00 1.00 018 <b>Qty</b> 1.00 1.00
Problem: - Recharge a load test.repla - Shop Suppl Workorder: Problem: - Cut off old le missing pintle	Dead batte and test batte ace defective lies H 1812660 Cut off lock ocking hitch	ery. ery and charge battery. ours 1.00 <b>Meter:</b> king hitch pin	ing system.ba 56099 and install ne	Labor:	Parts List Battery Shop Supp 60.00 Ir Parts List Pin Hook Pintle Hool Hitch Lock	blies Parts: n <b>Date:</b> k Mount	130.64			1.00 1.00 018 018 1.00 1.00 1.00
Problem: - Recharge a load test.repla - Shop Suppl Workorder: Problem: - Cut off old le missing pintle	Dead batte and test batte ace defective lies H 1812660 Cut off lock ocking hitch hitch .	ery. ery and charge battery. ours 1.00 <b>Meter:</b> king hitch pin pin and repla	ing system.ba 56099 and install ne	Labor: ew one . and	Parts List Battery Shop Supp 60.00 Ir Parts List Pin Hook Pintle Hook Hitch Lock Shop Supp	olies Parts: <b>n Date:</b> k Mount c Cls V olies	130.64 12/13/2018	Closed:	12/27/20	1.00 1.00 018 <b>Qty</b> 1.00 1.00
Problem: - Recharge a load test.repla - Shop Suppl Workorder: Problem: - Cut off old le missing pintle	Dead batte and test batte ace defective lies H 1812660 Cut off lock ocking hitch hitch .	ery. ery and charge battery. ours 1.00 <b>Meter:</b> king hitch pin	ing system.ba 56099 and install ne	Labor:	Parts List Battery Shop Supp 60.00 Ir Parts List Pin Hook Pintle Hook Hitch Lock Shop Supp	olies Parts: <b>n Date:</b> k Mount c Cls V olies	130.64	Closed:		1.00 1.00 018 018 1.00 1.00 1.00
Problem: - Recharge a load test.repla - Shop Suppl Workorder: Problem: - Cut off old lo missing pintle - Shop Suppl Workorder:	Dead batte and test batte ace defective lies H 1812660 Cut off lock ocking hitch hitch .	ery. ery and charge battery. ours 1.00 <b>Meter:</b> king hitch pin pin and repla ours 0.50 <b>Meter:</b>	ing system.ba 56099 and install ne	Labor: ew one . and	Parts List Battery Shop Supp 60.00 Ir Parts List Pin Hook Pintle Hool Hitch Lock Shop Supp 33.50	olies Parts: <b>n Date:</b> k Mount c Cls V olies	130.64 12/13/2018	Closed:	12/27/20	1.00 1.00 018 <b>Qty</b> 1.00 1.00 1.00
Problem: - Recharge a load test.repla - Shop Suppl Workorder: Problem: - Cut off old lo missing pintle - Shop Suppl Workorder:	Dead batter and test batter ace defective lies H 1812660 Cut off lock ocking hitch hitch . lies H 1900313 P.M. service	ery. ery and charge battery. ours 1.00 <b>Meter:</b> king hitch pin pin and repla ours 0.50 <b>Meter:</b>	56099 and install ne	Labor: ew one . and	Parts List Battery Shop Supp 60.00 Ir Parts List Pin Hook Pintle Hool Hitch Lock Shop Supp 33.50	blies Parts: n Date: k Mount Cls V blies Parts: n Date:	130.64 12/13/2018 197.84	Closed: Total:	12/27/20 231.34	1.00 1.00 018 <b>Qty</b> 1.00 1.00 1.00 1.00
Problem: - Recharge a load test.repla - Shop Suppl Workorder: Problem: - Cut off old lo missing pintle - Shop Suppl Workorder: Problem: - P.m. service	Dead batter and test batter ace defective lies H 1812660 Cut off lock ocking hitch hitch . lies H 1900313 P.M. service e.	ery. ery and charge battery. ours 1.00 Meter: king hitch pin pin and repla ours 0.50 Meter: ce.	56099 and install ne	Labor: ew one . and Labor:	Parts List Battery Shop Supp 60.00 Ir Parts List Pin Hook Pintle Hook Hitch Lock Shop Supp 33.50	blies Parts: n Date: k Mount Cls V blies Parts: n Date:	130.64 12/13/2018 197.84	Closed: Total:	12/27/20 231.34	1.00 1.00 1.00 018 <b>Qty</b> 1.00 1.00 1.00 019 019
Problem: - Recharge a load test.repla - Shop Suppl Workorder: Problem: - Cut off old lo missing pintle - Shop Suppl Workorder: Problem: - P.m. service	Dead batter and test batter ace defective lies H 1812660 Cut off lock ocking hitch hitch . lies H 1900313 P.M. service e. balance all f	ery. ery and charge battery. ours 1.00 Meter: king hitch pin pin and repla ours 0.50 Meter: ce.	56099 and install ne ace hitch pin a	Labor: ew one . and Labor:	Parts List Battery Shop Supp 60.00 Ir Parts List Pin Hook Pintle Hool Hitch Lock Shop Supp 33.50 Ir Parts List	olies Parts: <b>n Date:</b> k Mount Cls V blies Parts: <b>n Date:</b> Oil Filter	130.64 12/13/2018 197.84	Closed: Total:	12/27/20 231.34	1.00 1.00 018 018 018 1.00 1.00 1.00 019 019 019
Problem: - Recharge a load test.repla - Shop Suppl Workorder: Problem: - Cut off old le missing pintle - Shop Suppl Workorder: Problem: - P.m. service - Rotate and	Dead batter and test batter ace defective lies H 1812660 Cut off lock ocking hitch hitch . lies H 1900313 P.M. service e. balance all f	ery. ery and charge battery. ours 1.00 Meter: king hitch pin pin and repla ours 0.50 Meter: ce.	56099 and install ne ace hitch pin a	Labor: ew one . and Labor:	Parts List Battery Shop Supp 60.00 Ir Parts List Pin Hook Pintle Hook Hitch Lock Shop Supp 33.50 Ir Parts List Napagold (	olies Parts: <b>n Date:</b> k Mount Cls V olies Parts: <b>n Date:</b> Oil Filter rt 5w20	130.64 12/13/2018 197.84	Closed: Total:	12/27/20 231.34	1.00 1.00 1.00 018 <b>Qty</b> 1.00 1.00 1.00 019 <b>Qty</b> 1.00 7.00
Problem: - Recharge a load test.repla - Shop Suppl Workorder: Problem: - Cut off old le missing pintle - Shop Suppl Workorder: Problem: - P.m. service - Rotate and	Dead batter and test batter ace defective lies H 1812660 Cut off lock ocking hitch hitch . lies H 1900313 P.M. service e. balance all f	ery. ery and charge battery. ours 1.00 Meter: king hitch pin pin and repla ours 0.50 Meter: ce.	56099 and install ne ace hitch pin a	Labor: ew one . and Labor:	Parts List Battery Shop Supp 60.00 Ir Parts List Pin Hook Pintle Hool Hitch Lock Shop Supp 33.50 Ir Parts List Napagold O Napa Quar	olies Parts: <b>n Date:</b> k Mount Cls V olies Parts: <b>n Date:</b> Oil Filter rt 5w20 Blade	130.64 12/13/2018 197.84	Closed: Total:	12/27/20 231.34	1.00 1.00 018 <b>Qty</b> 1.00 1.00 1.00

Workorder: Problem:	1900894 Towed in for n	Meter: o start.	57876			In Date:	01/24/2019	Closed:	02/27/2019	
	start . Scan fo e key. Cut and es				Parts L Ford Igr Shop Si	nition Key Bl	ank		<b>Q</b> 1.0 1.0	
	Hours :	s 1.00		Labor:	67.00	Parts:	36.00	Total:	103.00	
Workorder: Problem:	1900895 No start	Meter:	57834			In Date:	01/24/2019	Closed:	01/24/2019	
- Tow From: 1 Lv shop	2500 40th stre	et North, F	Royal Palm Be	each To:						
	Hours :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1902741 Install aux. fue	Meter: el tank.	58184			In Date:	03/12/2019	Closed:	03/19/2019	
	sting toolbox.ins and wire 12volt			x	Parts L					ty
- Shop Suppli			ump system.		Adapter	Id Fuel Filte	r		1.( 1.(	
					Shop Si		1		1.0	
	Hours	s 6.00		Labor:	402.00		22.22	Total:	424.22	
Workorder: Problem:	1908293 PM Service, N	Meter: lo start, Ba	60913 attery low.			In Date:	08/09/2019	Closed:	08/26/2019	
- P.m. service					Parts L	ist			Q	ty
- Test and rep	lace left rear tu	ırn signal l	oulb .		Napago	ld Oil Filter			1.(	00
	service aux fue	l tank . Di	agnose fuel p	ump inop		•			7.0	
. R&r defective	y and charging	i svstem	R&r defective	hatterv	•	er Blade			2.0	
	y and charging	g system .		battery		te Lithium G			1.(	
- Rotate and b	alance all four	tires . Nitr	ofill all.			ld Air Filter			1.( 1.(	
- Shop Suppli	es					ld Fuel Filte			1.0	
						Viniatures	•		1.(	
					Napago	ld Fuel Filte	r		1.(	00
					12 Vdc	Pump 15 G	om		1.0	00
					Shop S	upplies			1.0	00
	Hours :	s 8.25		Labor:	552.75	Parts:	645.00	Total:	1,197.75	
Workorder: Problem:	1908301 wont start,	Meter:	60813			In Date:	08/09/2019	Closed:	08/09/2019	
- Tow From: 1	2500 40th st, lo	ox. Nroc	To: vista							
	Hours :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	

Workorder: Problem:	1908952 needs spare	Meter: key	60913			In Date:	08/27/2019	Closed:	08/28/2019
- Make and p	rogram spare	key			Parts Li	st			Qty
- Shop Suppli	es				Ford Igr	ition Key Bl	ank		1.00
					Shop Su	upplies			1.00
	Hou :	urs 1.00		Labor:	67.00	Parts:	29.60	Total:	96.60
Workorder: Problem:	2002891 Transition Pr	Meter: rep Charge	63237			In Date:	03/23/2020	Closed:	03/23/2020
- Transition P	rep Charge								
	Hou :	urs 2.00		Labor:	146.00	Parts:	0.00	Total:	146.00