

**Palm Beach County Fleet Management  
Asset Maintenance History**

**10179589      2010 FORD F350 Utility Body, 1 Ton**

|   |  |                            |                           |
|---|--|----------------------------|---------------------------|
| <b>Workorder:</b> 1003504   | <b>Meter:</b> 0                          | <b>In Date:</b> 04/05/2010 | <b>Closed:</b> 04/05/2010 |
| <b>Problem:</b> Pre Delivery Inspection   |  |                            |                           |
| <ul style="list-style-type: none"> <li>- Pre Delivery Inspection</li> <li>- Minor weld repair or machining</li> </ul>   |  |                            |                           |
| Hours 5.00  | Labor: 300.00                            | Parts: 0.00                | Total: 300.00             |
| :   |  |                            |                           |
| <b>Workorder:</b> 1003849   | <b>Meter:</b> 562                        | <b>In Date:</b> 04/14/2010 | <b>Closed:</b> 04/14/2010 |
| <b>Problem:</b> Install customers computer stand.   |  |                            |                           |
| <ul style="list-style-type: none"> <li>- Fabricate &amp; install customers computer stand &amp; wire harness.</li> <li>- Shop Supplies</li> </ul>   |  |                            |                           |
| Hours 4.00  | Labor: 240.00                            | Parts: 2.00                | Total: 242.00             |
| :   |  |                            |                           |
| <b>Workorder:</b> 1004789   | <b>Meter:</b> 1167                       | <b>In Date:</b> 05/10/2010 | <b>Closed:</b> 05/10/2010 |
| <b>Problem:</b> NEED RECEIVER HITCH PIN   |  |                            |                           |
| <ul style="list-style-type: none"> <li>- Replace pintle pin &amp; hitch pin.</li> </ul>   |  |                            |                           |
|   | <b>Parts List</b>                        |                            | <b>Qty</b>                |
|   | 18410 Pintle Pin                         |                            | 1.00                      |
|   | 2560 Hitch Pin/clip                      |                            | 1.00                      |
| Hours 0.50  | Labor: 30.00                             | Parts: 6.57                | Total: 36.57              |
| :   |  |                            |                           |
| <b>Workorder:</b> 1010564   | <b>Meter:</b> 5160                       | <b>In Date:</b> 09/27/2010 | <b>Closed:</b> 09/29/2010 |
| <b>Problem:</b> P. M. SERVICE   |  |                            |                           |
| <ul style="list-style-type: none"> <li>- P. M.</li> <li>- Retightened body bolts.</li> <li>- Unsiezed vise &amp; hitch &amp; lubed.</li> <li>- Repaired tire.</li> <li>- Installed driving decal.</li> <li>- Shop Supplies</li> </ul> |  |                            |                           |
|   | <b>Parts List</b>                        |                            | <b>Qty</b>                |
|   | Shop Supplies                            |                            | 1.00                      |
|   | Ca10270 Air Filter Mtc Fa1886 Wix 49886  |                            | 1.00                      |
|   | FI-2017b Oil Filter Ford/motorcraft Only |                            | 1.00                      |
|   | Cs10263 Fuel Filter (use Cs10263a )      |                            | 1.00                      |
|   | 15/40 Oil                                |                            | 15.00                     |
|   | Used Firex Refurbed Fire Extingshers     |                            | 1.00                      |
| Hours 7.25  | Labor: 435.00                            | Parts: 140.38              | Total: 575.38             |
| :   |  |                            |                           |
| <b>Workorder:</b> 1010722   | <b>Meter:</b> 5160                       | <b>In Date:</b> 09/29/2010 | <b>Closed:</b> 10/13/2010 |
| <b>Problem:</b> FRONT ENGINE OIL SEAL LEAK  |  |                            |                           |
| <ul style="list-style-type: none"> <li>- Transport &amp; pick up vehicle at dealer. (front crank seal leaking).</li> <li>- Dealer to replace front engine oil seal.</li> <li>- Shop Supplies</li> </ul>                               |  |                            |                           |
|   | <b>Parts List</b>                        |                            | <b>Qty</b>                |
|   | Shop Supplies                            |                            | 1.00                      |
| Hours 2.00  | Labor: 120.00                            | Parts: 2.00                | Total: 122.00             |
| :   |  |                            |                           |
| <b>Workorder:</b> 1013027   | <b>Meter:</b> 6730                       | <b>In Date:</b> 11/23/2010 | <b>Closed:</b> 11/30/2010 |
| <b>Problem:</b> Back tire flat, outter passenger's side   |  |                            |                           |
| <ul style="list-style-type: none"> <li>- Repaired two tires.</li> <li>- Shop Supplies</li> </ul>  |  |                            |                           |
|   | <b>Parts List</b>                        |                            | <b>Qty</b>                |
|   | Shop Supplies                            |                            | 1.00                      |
| Hours 2.00  | Labor: 120.00                            | Parts: 2.00                | Total: 122.00             |
| :   |  |                            |                           |

**Palm Beach County Fleet Management  
Asset Maintenance History**

|   |   |                            |                           |
|---|---|----------------------------|---------------------------|
| <b>Workorder:</b> 1103840   | <b>Meter:</b> 10940                     | <b>In Date:</b> 04/11/2011 | <b>Closed:</b> 04/20/2011 |
| <b>Problem:</b> P. M. SERVICE   |   |                            |                           |
| - Performed P.m.  | <b>Parts List</b>                       | <b>Qty</b>                 |                           |
| - Retightened body bolts  | Shop Supplies                           | 1.00                       |                           |
| - Unsiezed & lubed vise & hook.                                       | Ca10270 Air Filter Mtc Fa1886 Wix 49886 | 1.00                       |                           |
| - Tire repair.  | 3963 Fuel Filter Frm Cs10263a Wix 33963 | 1.00                       |                           |
| - Shop Supplies   | 7312 Oil Filterfrm Ch9549 Wix 57312     | 1.00                       |                           |
|   | 15/40 Oil                               | 16.00                      |                           |
|   | 31-22 Wiper Blades 22" Wiper Blade      | 2.00                       |                           |
| Hours 7.00  | Labor: 420.00                           | Parts: 138.30              | Total: 558.30             |
| :   |   |                            |                           |
| <b>Workorder:</b> 1104367   | <b>Meter:</b> 11142                     | <b>In Date:</b> 04/25/2011 | <b>Closed:</b> 04/28/2011 |
| <b>Problem:</b> Right front tire has a screw in it, & a slow leak     |   |                            |                           |
| - Repaired tire & rotated other tires.                                | <b>Parts List</b>                       | <b>Qty</b>                 |                           |
| - Shop Supplies   | Shop Supplies                           | 1.00                       |                           |
| Hours 1.50  | Labor: 90.00                            | Parts: 2.00                | Total: 92.00              |
| :   |   |                            |                           |
| <b>Workorder:</b> 1108314   | <b>Meter:</b> 14422                     | <b>In Date:</b> 08/08/2011 | <b>Closed:</b> 08/12/2011 |
| <b>Problem:</b> Flat tire, right side rear inner tire                 |   |                            |                           |
| - Repair right rear inner tire.                                       | <b>Parts List</b>                       | <b>Qty</b>                 |                           |
| - Shop Supplies   | Shop Supplies                           | 1.00                       |                           |
| Hours 1.00  | Labor: 60.00                            | Parts: 2.00                | Total: 62.00              |
| :   |   |                            |                           |
| <b>Workorder:</b> 1110491   | <b>Meter:</b> 16792                     | <b>In Date:</b> 10/03/2011 | <b>Closed:</b> 10/17/2011 |
| <b>Problem:</b> P.M.SERVICE   |   |                            |                           |
| - P. M. Service.  | <b>Parts List</b>                       | <b>Qty</b>                 |                           |
| - Replace 6 tires.  | Shop Supplies                           | 1.00                       |                           |
| - Repair wire harness for trailer connector.                          | 3963 Fuel Filter Frm Cs10263a Wix 33963 | 1.00                       |                           |
| - Shop Supplies   | 7312 Oil Filterfrm Ch9549 Wix 57312     | 1.00                       |                           |
|   | 15/40 Oil                               | 16.00                      |                           |
|   | 31-22 Wiper Blades 22" Wiper Blade      | 2.00                       |                           |
|   | Used Firex Refurbed Fire Extingshers    | 1.00                       |                           |
|   | 179636492 Lt245/75r17 Wrangler Sr-a E   | 6.00                       |                           |
|   | Tire Disposal Fee                       | 6.00                       |                           |
| Hours 8.50  | Labor: 510.00                           | Parts: 1,236.09            | Total: 1,746.09           |
| :   |   |                            |                           |
| <b>Workorder:</b> 1201279   | <b>Meter:</b> 22236                     | <b>In Date:</b> 02/08/2012 | <b>Closed:</b> 02/17/2012 |
| <b>Problem:</b> P. M. SERVICE   |   |                            |                           |
| - P. M. Service.  | <b>Parts List</b>                       | <b>Qty</b>                 |                           |
| - Adjust & tighten tail gate.   | Shop Supplies                           | 1.00                       |                           |
| - Transport & pick up vehicle at dealer. (driver's side battery bad). | 3963 Fuel Filter Frm Cs10263a Wix 33963 | 1.00                       |                           |
| - Dealer to replace defective left side battery.                      | 7312 Oil Filterfrm Ch9549 Wix 57312     | 1.00                       |                           |
| - Shop Supplies   | 15/40 Oil                               | 16.00                      |                           |
| Hours 6.75  | Labor: 405.00                           | Parts: 88.60               | Total: 493.60             |
| :   |   |                            |                           |

**Palm Beach County Fleet Management  
Asset Maintenance History**

|   |   |                            |                           |
|---|---|----------------------------|---------------------------|
| <b>Workorder:</b> 1205353   | <b>Meter:</b> 27335                     | <b>In Date:</b> 06/07/2012 | <b>Closed:</b> 06/12/2012 |
| <b>Problem:</b> pm svc, ck ac leak                                |   |                            |                           |
| - pm svc  | <b>Parts List</b>                       | <b>Qty</b>                 |                           |
| - disassemble light bar repaired connections to alley light       | Shop Supplies                           | 1.00                       |                           |
| - tire reapi r rear   | 3963 Fuel Filter Frm Cs10263a Wix 33963 | 1.00                       |                           |
| - tdightened body bolts   | 7312 Oil Filterfrm Ch9549 Wix 57312     | 1.00                       |                           |
| - rear brakes   | Ca10270 Air Filter Mtc Fa1886 Wix 49886 | 1.00                       |                           |
| - unsiezed & lube hitch   | 09997 Brake Clean                       | 1.00                       |                           |
| - ck operations & temp ck pressure no problems found at this time | Rear Brake Pad                          | 1.00                       |                           |
|   | 1401 Brake Fluid Brake Fluid            | 2.00                       |                           |
| - batt failled load recharged battery and tested good             | 15/40 Oil                               | 16.00                      |                           |
| - Shop Supplies   | 31-22 Wiper Blades 22" Wiper Blade      | 2.00                       |                           |
|   | Used Firex Refurbed Fire Extingshers    | 1.00                       |                           |
| Hours 16.00   | Labor: 960.00                           | Parts: 231.26              | Total: 1,191.26           |
| :   |   |                            |                           |

|   |   |                            |                           |
|---|---|----------------------------|---------------------------|
| <b>Workorder:</b> 1208803   | <b>Meter:</b> 32567                     | <b>In Date:</b> 09/17/2012 | <b>Closed:</b> 09/19/2012 |
| <b>Problem:</b> pm  |   |                            |                           |
| - pm  | <b>Parts List</b>                       | <b>Qty</b>                 |                           |
| - repaired grounds for running lights                                 | Shop Supplies                           | 1.00                       |                           |
| - unsiezed and lubed hook   | Ca10270 Air Filter Mtc Fa1886 Wix 49886 | 1.00                       |                           |
| - disassembled light bar and repaired connections to take down lights | 7312 Oil Filterfrm Ch9549 Wix 57312     | 1.00                       |                           |
|   | 3963 Fuel Filter Frm Cs10263a Wix 33963 | 1.00                       |                           |
| - tighten body hold downs   | 15/40 Oil                               | 16.00                      |                           |
| - battery failled load test recharged gattery and retested and passed | 31-22 Wiper Blades 22" Wiper Blade      | 2.00                       |                           |
| - rr and balanced 3 tires   | 179636492 Lt245/75r17 Wrangler Sr-a E   | 3.00                       |                           |
| - repaired two rr tires   | Tire Disposal Fee                       | 3.00                       |                           |
| - Shop Supplies   |   |                            |                           |
| Hours 13.00   | Labor: 780.00                           | Parts: 798.92              | Total: 1,578.92           |
| :   |   |                            |                           |

|  |                      |                            |                           |
|--|----------------------|----------------------------|---------------------------|
| <b>Workorder:</b> 1211889  | <b>Meter:</b> 36834  | <b>In Date:</b> 12/10/2012 | <b>Closed:</b> 12/20/2012 |
| <b>Problem:</b> BATTERY DEAD(ACID BLOW UP)   |                      |                            |                           |
| - ck battery blow up verify concern replace exploded battery clean acid from vehicle ck charging system and test drive left side battery | <b>Parts List</b>    | <b>Qty</b>                 |                           |
|  | Battery 65           | 1.00                       |                           |
| - install steering wheel cover   | Stg Wheel Cov - Ford | 1.00                       |                           |
| - Shop Supplies  | Shop Supplies        | 1.00                       |                           |
| Hours 2.00   | Labor: 120.00        | Parts: 162.04              | Total: 282.04             |
| :  |                      |                            |                           |

**Palm Beach County Fleet Management  
Asset Maintenance History**

|   |                         |                            |                           |
|---|-------------------------|----------------------------|---------------------------|
| <b>Workorder:</b> 1300671   | <b>Meter:</b> 38666     | <b>In Date:</b> 01/18/2013 | <b>Closed:</b> 01/30/2013 |
| <b>Problem:</b> pm  |                         |                            |                           |
| - pm  | <b>Parts List</b>       | <b>Qty</b>                 |                           |
| - repaired grounds for runniing lights                                | Napagold Fuel Filter    | 1.00                       |                           |
| - repaired switch connection for light bar                            | Air Filter              | 1.00                       |                           |
| - rr and balance two tires  | Oil Filter              | 1.00                       |                           |
| - repaired l rear tire  | 15w40 Bulk South Reg    | 16.00                      |                           |
| - Shop Supplies   | 31-22 Wiper Blades 22   | 2.00                       |                           |
|   | 179636492 Lt245-75r17   | 2.00                       |                           |
|   | Shop Supplies           | 1.00                       |                           |
|   | Tire Disposal Fee       | 2.00                       |                           |
| Hours 8.50  | Labor: 510.00           | Parts: 656.48              | Total: 1,166.48           |
| :   |                         |                            |                           |
| <b>Workorder:</b> 1303174   | <b>Meter:</b> 40840     | <b>In Date:</b> 04/02/2013 | <b>Closed:</b> 04/18/2013 |
| <b>Problem:</b> leaking at the motor                                  |                         |                            |                           |
| - transpodrt and pick up vehicle at dealer for warranty repair        | <b>Parts List</b>       | <b>Qty</b>                 |                           |
| coolant hose leaking at degas bottle                                  | Shop Supplies           | 1.00                       |                           |
| - Shop Supplies   |                         |                            |                           |
| Hours 1.50  | Labor: 90.00            | Parts: 2.00                | Total: 92.00              |
| :   |                         |                            |                           |
| <b>Workorder:</b> 1308006   | <b>Meter:</b> 44707     | <b>In Date:</b> 08/09/2013 | <b>Closed:</b> 08/29/2013 |
| <b>Problem:</b> pm,wrech light stays on,turbo leaking,shut off along. |                         |                            |                           |
| - pm  | <b>Parts List</b>       | <b>Qty</b>                 |                           |
| - rr two light assembly repaired connection to backup light           | Napagold Air Filter     | 1.00                       |                           |
| - disassembled light bar and repaired connection to alley light       | Napagold Oil Filter     | 1.00                       |                           |
|   | Napagold Fuel Filter    | 1.00                       |                           |
| - unsiezed and lubed vise and hook                                    | 15w40 Bulk South Reg    | 16.00                      |                           |
| - rr and balanced two tires   | Wiper Blade             | 2.00                       |                           |
| - tire repair rr tire   | Used Fire X Refurbished | 1.00                       |                           |
| - reanchored rear stabilizer bar                                      | Washer Fl               | 1.00                       |                           |
| - frt brakes  | 44202r Tail Light 4in   | 2.00                       |                           |
| - readjuster striker and gate assembly                                | 179636492 Lt245-75r17   | 2.00                       |                           |
| - transport and pick up vehicle at dealer for warranty repaors        | Pads                    | 1.00                       |                           |
| dealer to replace exhaust inlet pipe and e sensor                     | 1401 Brake Fluid Bra    | 2.00                       |                           |
| - Shop Supplies   | Brake Cleaner           | 2.00                       |                           |
|   | Shop Supplies           | 1.00                       |                           |
|   | Tire Disposal Fee       | 2.00                       |                           |
| Hours 20.00   | Labor: 1,200.0          | Parts: 859.88              | Total: 2,059.88           |
| :   | 0                       |                            |                           |

**Palm Beach County Fleet Management  
Asset Maintenance History**

|   |                       |                            |                           |
|---|-----------------------|----------------------------|---------------------------|
| <b>Workorder:</b> 1311843   | <b>Meter:</b> 49084   | <b>In Date:</b> 11/25/2013 | <b>Closed:</b> 11/27/2013 |
| <b>Problem:</b> DEAD BATTERY(JUMP START)  |                       |                            |                           |
| - Jump Start At W.u.d.,recharge Batteries.batt.system<br>Test.r/side Batt. Aces Code AI21kk.batt.warranty By<br>Napa.l/side Aces Code Hg00p.r&r Both Batteries. | <b>Parts List</b>     | <b>Qty</b>                 |                           |
|   | Battery 65            | 1.00                       |                           |
| - Repair Dome Light   | Bulb                  | 1.00                       |                           |
| - Shop Supplies   | Shop Supplies         | 1.00                       |                           |
| Hours 3.00  | Labor: 180.00         | Parts: 148.22              | Total: 328.22             |
| :   |                       |                            |                           |
| <b>Workorder:</b> 1312148   | <b>Meter:</b> 49287   | <b>In Date:</b> 12/05/2013 | <b>Closed:</b> 12/17/2013 |
| <b>Problem:</b> wrench light on in dash attention engine oil light on, dome lights wont turn off  |                       |                            |                           |
| - ck wench light is on perform pinpoint test and found high oil<br>level drain and replace engine with correct level  | <b>Parts List</b>     | <b>Qty</b>                 |                           |
|   | 15w40 Bulk South Reg  | 16.00                      |                           |
| - clean diesel exhaust particulate filter for code p2463  | Shop Supplies         | 1.00                       |                           |
| - replace dome light bulb   |                       |                            |                           |
| - test drive vehicle 50 miles after repair  |                       |                            |                           |
| - Shop Supplies   |                       |                            |                           |
| Hours 5.00  | Labor: 300.00         | Parts: 52.40               | Total: 352.40             |
| :   |                       |                            |                           |
| <b>Workorder:</b> 1401154   | <b>Meter:</b> 52224   | <b>In Date:</b> 02/04/2014 | <b>Closed:</b> 02/10/2014 |
| <b>Problem:</b> pm, new batteries   |                       |                            |                           |
| - pm  | <b>Parts List</b>     | <b>Qty</b>                 |                           |
| - repaired connection for cargo light rr bulb for 3rd stop light  | Napagold Air Filter   | 1.00                       |                           |
| repaired tag light assy   | Napagold Oil Filter   | 1.00                       |                           |
| - disassembled led light bar repaired connection for take<br>down light   | Fuel Filter Ford Only | 1.00                       |                           |
| - rr and balance two tires  | 15w40 Bulk South Reg  | 16.00                      |                           |
| - tire repair rr  | Wiper Blade           | 2.00                       |                           |
| - unsiezed and lubed vise   | Washer FI             | 1.00                       |                           |
| - removed shock and straightened mount  | 179636492 Lt245-75r17 | 2.00                       |                           |
| - straightened and adj latch assy and striker   | Shop Supplies         | 1.00                       |                           |
| - batteries passed load test charging sys good and no draw<br>no problem found at this time   | Tire Disposal Fee     | 2.00                       |                           |
| - Shop Supplies   |                       |                            |                           |
| Hours 12.50   | Labor: 750.00         | Parts: 682.44              | Total: 1,432.44           |
| :   |                       |                            |                           |

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1404970      **Meter:** 56260      **In Date:** 05/22/2014      **Closed:** 05/30/2014  
**Problem:** P.M.SERVICE

| <ul style="list-style-type: none"> <li>- pm</li> <li>- rr tail light assy rr bulb for cargo light repaired grounds for running light</li> <li>- unsiezed and lubed vise and hook</li> <li>- removed door panel and adjusted track assy</li> <li>- ck blower operatioin bad resistor found ordered part</li> <li>- disassembled light bar led take cown assy bad removed led and waiting for parts retro fitted parts for light bar</li> <li>- Shop Supplies</li> </ul> | <table border="0" style="width: 100%;"> <tr> <th style="text-align: left;"><b>Parts List</b></th> <th style="text-align: right;"><b>Qty</b></th> </tr> <tr><td>Napagold Air Filter</td><td style="text-align: right;">1.00</td></tr> <tr><td>Napagold Oil Filter</td><td style="text-align: right;">1.00</td></tr> <tr><td>Fuel Filter Ford Only</td><td style="text-align: right;">1.00</td></tr> <tr><td>Wiper Blade</td><td style="text-align: right;">2.00</td></tr> <tr><td>15w40 Bulk South Reg</td><td style="text-align: right;">16.00</td></tr> <tr><td>Washer FI</td><td style="text-align: right;">1.00</td></tr> <tr><td>Used Fire X Refurbished</td><td style="text-align: right;">1.00</td></tr> <tr><td>Led Sup Mdl 44 42 Dio</td><td style="text-align: right;">1.00</td></tr> <tr><td>Blower Resistor</td><td style="text-align: right;">1.00</td></tr> <tr><td>Fxalf1 Alley Light Le</td><td style="text-align: right;">1.00</td></tr> <tr><td>13 Oz Aero Kroil Aer</td><td style="text-align: right;">1.00</td></tr> <tr><td>Shop Supplies</td><td style="text-align: right;">1.00</td></tr> </table> | <b>Parts List</b> | <b>Qty</b> | Napagold Air Filter | 1.00 | Napagold Oil Filter | 1.00 | Fuel Filter Ford Only | 1.00 | Wiper Blade | 2.00 | 15w40 Bulk South Reg | 16.00 | Washer FI | 1.00 | Used Fire X Refurbished | 1.00 | Led Sup Mdl 44 42 Dio | 1.00 | Blower Resistor | 1.00 | Fxalf1 Alley Light Le | 1.00 | 13 Oz Aero Kroil Aer | 1.00 | Shop Supplies | 1.00 |
|--|--|-------------------|------------|---------------------|------|---------------------|------|-----------------------|------|-------------|------|----------------------|-------|-----------|------|-------------------------|------|-----------------------|------|-----------------|------|-----------------------|------|----------------------|------|---------------|------|
| <b>Parts List</b>  | <b>Qty</b>   |                   |            |                     |      |                     |      |                       |      |             |      |                      |       |           |      |                         |      |                       |      |                 |      |                       |      |                      |      |               |      |
| Napagold Air Filter  | 1.00   |                   |            |                     |      |                     |      |                       |      |             |      |                      |       |           |      |                         |      |                       |      |                 |      |                       |      |                      |      |               |      |
| Napagold Oil Filter  | 1.00   |                   |            |                     |      |                     |      |                       |      |             |      |                      |       |           |      |                         |      |                       |      |                 |      |                       |      |                      |      |               |      |
| Fuel Filter Ford Only  | 1.00   |                   |            |                     |      |                     |      |                       |      |             |      |                      |       |           |      |                         |      |                       |      |                 |      |                       |      |                      |      |               |      |
| Wiper Blade  | 2.00   |                   |            |                     |      |                     |      |                       |      |             |      |                      |       |           |      |                         |      |                       |      |                 |      |                       |      |                      |      |               |      |
| 15w40 Bulk South Reg   | 16.00  |                   |            |                     |      |                     |      |                       |      |             |      |                      |       |           |      |                         |      |                       |      |                 |      |                       |      |                      |      |               |      |
| Washer FI  | 1.00   |                   |            |                     |      |                     |      |                       |      |             |      |                      |       |           |      |                         |      |                       |      |                 |      |                       |      |                      |      |               |      |
| Used Fire X Refurbished  | 1.00   |                   |            |                     |      |                     |      |                       |      |             |      |                      |       |           |      |                         |      |                       |      |                 |      |                       |      |                      |      |               |      |
| Led Sup Mdl 44 42 Dio  | 1.00   |                   |            |                     |      |                     |      |                       |      |             |      |                      |       |           |      |                         |      |                       |      |                 |      |                       |      |                      |      |               |      |
| Blower Resistor  | 1.00   |                   |            |                     |      |                     |      |                       |      |             |      |                      |       |           |      |                         |      |                       |      |                 |      |                       |      |                      |      |               |      |
| Fxalf1 Alley Light Le  | 1.00   |                   |            |                     |      |                     |      |                       |      |             |      |                      |       |           |      |                         |      |                       |      |                 |      |                       |      |                      |      |               |      |
| 13 Oz Aero Kroil Aer   | 1.00   |                   |            |                     |      |                     |      |                       |      |             |      |                      |       |           |      |                         |      |                       |      |                 |      |                       |      |                      |      |               |      |
| Shop Supplies  | 1.00   |                   |            |                     |      |                     |      |                       |      |             |      |                      |       |           |      |                         |      |                       |      |                 |      |                       |      |                      |      |               |      |
| Hours 10.00<br>:   | Labor: 600.00      Parts: 381.43      Total: 981.43  |                   |            |                     |      |                     |      |                       |      |             |      |                      |       |           |      |                         |      |                       |      |                 |      |                       |      |                      |      |               |      |

**Workorder:** 1408771      **Meter:** 60744      **In Date:** 09/02/2014      **Closed:** 09/08/2014  
**Problem:** CHECK ENGINE LIGHT STAYS ON

| <ul style="list-style-type: none"> <li>- ck engine light is on perform pinpoint test and found hight oil level change engine oil and filter 6042 hrs</li> <li>- scan foiund code p2463 p246c clean diesel particulate filter</li> <li>- test drive before and after repair 48 miles</li> <li>- Shop Supplies</li> </ul> | <table border="0" style="width: 100%;"> <tr> <th style="text-align: left;"><b>Parts List</b></th> <th style="text-align: right;"><b>Qty</b></th> </tr> <tr><td>15w40 Bulk South Reg</td><td style="text-align: right;">16.00</td></tr> <tr><td>Napagold Oil Filter</td><td style="text-align: right;">1.00</td></tr> <tr><td>Shop Supplies</td><td style="text-align: right;">1.00</td></tr> </table> | <b>Parts List</b> | <b>Qty</b> | 15w40 Bulk South Reg | 16.00 | Napagold Oil Filter | 1.00 | Shop Supplies | 1.00 |
|---|---|-------------------|------------|----------------------|-------|---------------------|------|---------------|------|
| <b>Parts List</b>   | <b>Qty</b>  |                   |            |                      |       |                     |      |               |      |
| 15w40 Bulk South Reg  | 16.00   |                   |            |                      |       |                     |      |               |      |
| Napagold Oil Filter   | 1.00  |                   |            |                      |       |                     |      |               |      |
| Shop Supplies   | 1.00  |                   |            |                      |       |                     |      |               |      |
| Hours 5.50<br>:   | Labor: 330.00      Parts: 65.53      Total: 395.53  |                   |            |                      |       |                     |      |               |      |

**Workorder:** 1408788      **Meter:** 60522      **In Date:** 09/02/2014      **Closed:** 09/09/2014  
**Problem:** needs spare keys

| <ul style="list-style-type: none"> <li>- Make and program extra keys</li> <li>- Shop Supplies</li> </ul> | <table border="0" style="width: 100%;"> <tr> <th style="text-align: left;"><b>Parts List</b></th> <th style="text-align: right;"><b>Qty</b></th> </tr> <tr><td>Ford Ignition Key Blank</td><td style="text-align: right;">2.00</td></tr> <tr><td>Shop Supplies</td><td style="text-align: right;">1.00</td></tr> </table> | <b>Parts List</b> | <b>Qty</b> | Ford Ignition Key Blank | 2.00 | Shop Supplies | 1.00 |
|--|---|-------------------|------------|-------------------------|------|---------------|------|
| <b>Parts List</b>  | <b>Qty</b>  |                   |            |                         |      |               |      |
| Ford Ignition Key Blank  | 2.00  |                   |            |                         |      |               |      |
| Shop Supplies  | 1.00  |                   |            |                         |      |               |      |
| Hours 1.00<br>:  | Labor: 60.00      Parts: 55.22      Total: 115.22   |                   |            |                         |      |               |      |

**Palm Beach County Fleet Management  
Asset Maintenance History**

|   |                       |                            |                           |
|---|-----------------------|----------------------------|---------------------------|
| <b>Workorder:</b> 1409228   | <b>Meter:</b> 61462   | <b>In Date:</b> 09/15/2014 | <b>Closed:</b> 09/29/2014 |
| <b>Problem:</b> pm,, pass sideand driver side running board borken  |                       |                            |                           |
| - pm  | <b>Parts List</b>     | <b>Qty</b>                 |                           |
| - rear brake job  | Brake Fluid Qt        | 1.00                       |                           |
| - rr 4 tires  | D/s Running Board Asm | 1.00                       |                           |
| - repaired grounds for rear running lights and rr clip light bulb   | Step Asy              | 1.00                       |                           |
| - disassembled light bar and repaired connection at fuse  | Napagold Air Filter   | 1.00                       |                           |
| - ordered running boards repaired brackets and lower portion of mounting arm and installed new left and right side running boards | Napagold Oil Filter   | 1.00                       |                           |
|   | Fuel Filter Ford Only | 1.00                       |                           |
| - repaired rr tire  | 15w40 Bulk South Reg  | 16.00                      |                           |
| - unsiezed and lubed vise and hook  | Wiper Blade           | 2.00                       |                           |
| - tightened body mounts   | Washer Fl             | 1.00                       |                           |
| - Shop Supplies   | Mac Battery Protect   | 1.00                       |                           |
|   | Mac Wite Lithium Gres | 1.00                       |                           |
|   | Brake Pads            | 1.00                       |                           |
|   | Brake Cleaner         | 1.00                       |                           |
|   | 179636492 Lt245-75r17 | 4.00                       |                           |
|   | Rear Pads             | 1.00                       |                           |
|   | Shop Supplies         | 1.00                       |                           |
|   | Tire Disposal Fee     | 4.00                       |                           |
| Hours 21.50   | Labor: 1,290.0        | Parts: 2,233.77            | Total: 3,523.77           |
| :   | 0                     |                            |                           |
| <b>Workorder:</b> 1500599   | <b>Meter:</b> 66591   | <b>In Date:</b> 01/16/2015 | <b>Closed:</b> 01/28/2015 |
| <b>Problem:</b> P.M.SERVICE,WINDSHIED WASHER NOZZLES?   |                       |                            |                           |
| - pm  | <b>Parts List</b>     | <b>Qty</b>                 |                           |
| - rr bezel and lens assy rr sealed beam   | Napagold Air Filter   | 1.00                       |                           |
| - repaired open in cabinet for running lights   | Napagold Oil Filter   | 1.00                       |                           |
| - disassembled light bar and repaired connection to pack  | 15w40 Bulk South Reg  | 16.00                      |                           |
| - unsiezed and lubed hook and vise  | Wiper Blade           | 2.00                       |                           |
| - rr and balanced two tires   | Washer Fl             | 1.00                       |                           |
| - repaired lf tire  | Fuel Filter Ford Only | 1.00                       |                           |
| - straightened shock mount  | Halogen Lamp          | 1.00                       |                           |
| - repaired washer nozzle and lines and unclogged lines  | 179636492 Lt245-75r17 | 2.00                       |                           |
| - Shop Supplies   | Washer Nozzle         | 2.00                       |                           |
|   | Cd 5 Vacuum Connector | 2.00                       |                           |
|   | Cd 6 Hose Connector   | 1.00                       |                           |
|   | W W Vacuum Tubing     | 3.00                       |                           |
|   | Shop Supplies         | 1.00                       |                           |
|   | Tire Disposal Fee     | 2.00                       |                           |
| Hours 13.00   | Labor: 780.00         | Parts: 750.98              | Total: 1,530.98           |
| :   |                       |                            |                           |
| <b>Workorder:</b> 1502349   | <b>Meter:</b> 68197   | <b>In Date:</b> 03/05/2015 | <b>Closed:</b> 03/13/2015 |
| <b>Problem:</b> no lights on trailer plug to trailer  |                       |                            |                           |
| - trace and repair damage wire harness for trailer lights   | <b>Parts List</b>     | <b>Qty</b>                 |                           |
| - Shop Supplies   | Shop Supplies         | 1.00                       |                           |
| Hours 3.00  | Labor: 180.00         | Parts: 2.00                | Total: 182.00             |
| :   |                       |                            |                           |

**Palm Beach County Fleet Management  
Asset Maintenance History**

|   |                         |                            |                           |
|---|-------------------------|----------------------------|---------------------------|
| <b>Workorder:</b> 1503491   | <b>Meter:</b> 69038     | <b>In Date:</b> 04/03/2015 | <b>Closed:</b> 04/15/2015 |
| <b>Problem:</b> wont move   |                         |                            |                           |
| - ck wont move verify concern scan found po0088 perform pinpoint test found hight oil level change oil oil filter and clear codes | <b>Parts List</b>       | <b>Qty</b>                 |                           |
|   | 15w40 Bulk South Reg    | 16.00                      |                           |
|   | Napagold Oil Filter     | 1.00                       |                           |
| - pressfure test cooling sys found leaking egr hose upper rad hose thghten egr hose clap replace 3 rad hose flush cooling sys     | Brake Cleaner           | 1.00                       |                           |
|   | upper hose              | 1.00                       |                           |
| - test drive before and after repair  | Radiator Hose Lower     | 1.00                       |                           |
| - Shop Supplies   | Radiator Hose Lower     | 1.00                       |                           |
|   | Coolant Ford Gold       | 4.00                       |                           |
|   | Shop Supplies           | 1.00                       |                           |
| Hours 10.50   | Labor: 630.00           | Parts: 401.29              | Total: 1,031.29           |
| :   |                         |                            |                           |
| <b>Workorder:</b> 1503960   | <b>Meter:</b> 69411     | <b>In Date:</b> 04/16/2015 | <b>Closed:</b> 04/23/2015 |
| <b>Problem:</b> no power  |                         |                            |                           |
| - ck no power scan and found code p088 perform tsb 12-07-07 reprogram pcm and clear codes   | <b>Parts List</b>       | <b>Qty</b>                 |                           |
|   | Shop Supplies           | 1.00                       |                           |
| - clean diesel particulate filter   |                         |                            |                           |
| - test drive after repair   |                         |                            |                           |
| - Shop Supplies   |                         |                            |                           |
| Hours 6.50  | Labor: 390.00           | Parts: 2.00                | Total: 392.00             |
| :   |                         |                            |                           |
| <b>Workorder:</b> 1505645   | <b>Meter:</b> 71558     | <b>In Date:</b> 06/04/2015 | <b>Closed:</b> 06/16/2015 |
| <b>Problem:</b> pm  |                         |                            |                           |
| - pm truck utility body hit ds spoke to anthony about damage to utility (6-11-15) he was not aware of damage and scheduled repair | <b>Parts List</b>       | <b>Qty</b>                 |                           |
|   | Napagold Air Filter     | 1.00                       |                           |
|   | Napagold Oil Filter     | 1.00                       |                           |
| - repaired open for marker lights in cabinet  | Fuel Filter Ford Only   | 1.00                       |                           |
| - disassembled ligtht bar and repaired connection to light  | 15w40 Bulk South Reg    | 16.00                      |                           |
| - rr sealed beam  | Wiper Blade             | 2.00                       |                           |
| - jumped off truck in lot ck batt failed load recharged batt failed again rr boh batt one batt was warranty                       | Used Fire X Refurbished | 1.00                       |                           |
| - unsiezed and lubed vise and hook  | Halogen Lamp            | 1.00                       |                           |
| - rr frt brakes removed shell rock from compartment parts rd tested   | Battery                 | 1.00                       |                           |
|   | Brake Pads              | 1.00                       |                           |
| - repaired lr tire  | B Fluid Dot 3-32oz      | 1.00                       |                           |
| - Shop Supplies   | Brake Cleaner           | 1.00                       |                           |
|   | Shop Supplies           | 1.00                       |                           |
| Hours 18.00   | Labor: 1,080.00         | Parts: 427.97              | Total: 1,507.97           |
| :   | 0                       |                            |                           |
| <b>Workorder:</b> 1506793   | <b>Meter:</b> 71558     | <b>In Date:</b> 06/11/2015 | <b>Closed:</b> 07/08/2015 |
| <b>Problem:</b> damage to left side of bed & bin doors  |                         |                            |                           |
| - damage to left side of bed & bin doors  |                         |                            |                           |
| Hours 0.00  | Labor: 0.00             | Parts: 0.00                | Total: 0.00               |
| :   |                         |                            |                           |



**Palm Beach County Fleet Management  
Asset Maintenance History**

|   |                       |                            |                           |
|---|-----------------------|----------------------------|---------------------------|
| <b>Workorder:</b> 1507524   | <b>Meter:</b> 72687   | <b>In Date:</b> 07/28/2015 | <b>Closed:</b> 07/31/2015 |
| <b>Problem:</b> BROKE DOWN, ONLY 15 MPH SLOW  |                       |                            |                           |
| - ck only 15 mph slow verify concern scan found code p0088 perform pinpoint test and found high engine oil level change oil and clear codes | <b>Parts List</b>     |                            | <b>Qty</b>                |
| - right front tire had screw inside wall and is not repairable replace right front tire   | 15w40 Bulk South Reg  |                            | 15.00                     |
| - test drive before and after repair  | 179636492 Lt245-75r17 |                            | 1.00                      |
| - clean diesel exhaust particulate filter   | Shop Supplies         |                            | 1.00                      |
| - Shop Supplies   | Tire Disposal Fee     |                            | 1.00                      |
| Hours 7.00  | Labor: 420.00         | Parts: 311.37              | Total: 731.37             |
| :   |                       |                            |                           |
| <b>Workorder:</b> 1508115   | <b>Meter:</b> 73816   | <b>In Date:</b> 08/12/2015 | <b>Closed:</b> 08/25/2015 |
| <b>Problem:</b> TOW IN,WRECH LIGHT STAYS ON/RUNS SLOW, (DRIVE TO CLEAN EXHAUST SYSTEM)  |                       |                            |                           |
| - ck light stay on run slow scan found code p2463 2466 clean diesel particulate filter and clear codes                                      | <b>Parts List</b>     |                            | <b>Qty</b>                |
| - test drive before and after repair  | Shop Supplies         |                            | 1.00                      |
| - Shop Supplies   |                       |                            |                           |
| Hours 2.75  | Labor: 165.00         | Parts: 2.00                | Total: 167.00             |
| :   |                       |                            |                           |
| <b>Workorder:</b> 1508272   | <b>Meter:</b> 73633   | <b>In Date:</b> 08/12/2015 | <b>Closed:</b> 08/18/2015 |
| <b>Problem:</b> RUN VERY SLOW   |                       |                            |                           |
| - Tow From: 11910 S. St Rd 7 Boca To: Sr Shop Delray  |                       |                            |                           |
| Hours 0.00  | Labor: 0.00           | Parts: 0.00                | Total: 0.00               |
| :   |                       |                            |                           |
| <b>Workorder:</b> 1509230   | <b>Meter:</b> 74403   | <b>In Date:</b> 09/15/2015 | <b>Closed:</b> 09/18/2015 |
| <b>Problem:</b> flat pass tire towed in/ drive to clean exhaust.  |                       |                            |                           |
| - repair right rear tire  | <b>Parts List</b>     |                            | <b>Qty</b>                |
| - ck drive to clean exhaust is on scan and found code p2463 clean diesel particulate filter clear codes and tes drive                       | Shop Supplies         |                            | 1.00                      |
| - Shop Supplies   |                       |                            |                           |
| Hours 3.00  | Labor: 180.00         | Parts: 2.00                | Total: 182.00             |
| :   |                       |                            |                           |
| <b>Workorder:</b> 1509262   | <b>Meter:</b> 74293   | <b>In Date:</b> 09/14/2015 | <b>Closed:</b> 09/15/2015 |
| <b>Problem:</b> pass. rear flat tire  |                       |                            |                           |
| - Tow From: 19110 s. st rd 7 boca raton To: sr shop delray  |                       |                            |                           |
| Hours 0.00  | Labor: 0.00           | Parts: 0.00                | Total: 0.00               |
| :   |                       |                            |                           |

**Palm Beach County Fleet Management  
Asset Maintenance History**

|  |                         |                            |                           |
|--|-------------------------|----------------------------|---------------------------|
| <b>Workorder:</b> 1511464  | <b>Meter:</b> 77025     | <b>In Date:</b> 11/09/2015 | <b>Closed:</b> 11/30/2015 |
| <b>Problem:</b> pm, engine on and wrench light   |                         |                            |                           |
| - pm   | <b>Parts List</b>       | <b>Qty</b>                 |                           |
| - replace female trailer connector and wire harness from vehicle to connector  | Napagold Oil Filter     | 1.00                       |                           |
| - repair clearance light and center rear marker light  | 15w40 Bulk South Reg    | 16.00                      |                           |
| - replace backup alarm   | Fuel Filter Ford Only   | 1.00                       |                           |
| - ck wrench light on scan found no codes ck found high oil level change out as part of pm  | Washer Fluid Concentr   | 1.00                       |                           |
| - Shop Supplies  | Female Conn Socket      | 1.00                       |                           |
|  | M C Lamp                | 1.00                       |                           |
|  | Bulb                    | 4.00                       |                           |
|  | Med Low Noise Alarm     | 1.00                       |                           |
|  | Shop Supplies           | 1.00                       |                           |
| Hours 10.50  | Labor: 630.00           | Parts: 203.39              | Total: 833.39             |
| :  |                         |                            |                           |
| <b>Workorder:</b> 1513043  | <b>Meter:</b> 78264     | <b>In Date:</b> 12/30/2015 | <b>Closed:</b> 01/07/2016 |
| <b>Problem:</b> ck engine on   |                         |                            |                           |
| - Ck Engine Light On No Power Scan Code P0088 Found Hight Engine Oil Change Out And Clear Codes Hr 7446  | <b>Parts List</b>       | <b>Qty</b>                 |                           |
| - Test Drive Before And After Repair   | 15w40 Bulk South Reg    | 16.00                      |                           |
| - Shop Supplies  | Shop Supplies           | 1.00                       |                           |
| Hours 4.00   | Labor: 240.00           | Parts: 54.80               | Total: 294.80             |
| :  |                         |                            |                           |
| <b>Workorder:</b> 1602699  | <b>Meter:</b> 81694     | <b>In Date:</b> 03/15/2016 | <b>Closed:</b> 03/29/2016 |
| <b>Problem:</b> MOTOR BROKE DOWN ENGINE LIGH ON  |                         |                            |                           |
| - ck motor brake down scan found code poo88 perform pinpoint test found high engine oil level change oil filter and clear code hr7625  | <b>Parts List</b>       | <b>Qty</b>                 |                           |
| - replace steeringh wheel cover  | 15w40 Bulk South Reg    | 16.00                      |                           |
| - test drive before and after repair   | Napagold Oil Filter     | 1.00                       |                           |
| - Shop Supplies  | Atc-15 Fuse             | 5.00                       |                           |
|  | Stg Wheel Cov - Ford    | 1.00                       |                           |
|  | Shop Supplies           | 1.00                       |                           |
| Hours 4.25   | Labor: 255.00           | Parts: 86.29               | Total: 341.29             |
| :  |                         |                            |                           |
| <b>Workorder:</b> 1603607  | <b>Meter:</b> 82484     | <b>In Date:</b> 04/06/2016 | <b>Closed:</b> 04/29/2016 |
| <b>Problem:</b> Pm service.Wrench light on.No power  |                         |                            |                           |
| - Pm service.  | <b>Parts List</b>       | <b>Qty</b>                 |                           |
| - Computer diagnose for wrench light on.code P2463.clogg Dpf.remove exhaust system.dismantle,clean Dpf and cat.replace exhaust gasket.run regen with scan tool and roadtest.clear code and retest. | Napagold Oil Filter     | 1.00                       |                           |
| - Replace four tires.two fronts and two right rear.balance all six.  | Fuel Filter Ford Only   | 1.00                       |                           |
| - Shop Supplies  | 15w40 Bulk South Reg    | 16.00                      |                           |
|  | Washer Fluid Concentr   | 1.00                       |                           |
|  | 22" Wiper Blade         | 2.00                       |                           |
|  | Exha                    | 1.00                       |                           |
|  | Used Fire X Refurbished | 1.00                       |                           |
|  | 179636492 Lt245-75r17   | 4.00                       |                           |
|  | Shop Supplies           | 1.00                       |                           |
|  | Tire Disposal Fee       | 4.00                       |                           |
| Hours 13.00  | Labor: 780.00           | Parts: 1,313.04            | Total: 2,093.04           |
| :  |                         |                            |                           |

**Palm Beach County Fleet Management  
Asset Maintenance History**

|   |                       |                            |                           |
|---|-----------------------|----------------------------|---------------------------|
| <b>Workorder:</b> 1607215   | <b>Meter:</b> 86485   | <b>In Date:</b> 07/15/2016 | <b>Closed:</b> 07/19/2016 |
| <b>Problem:</b> Check engine light.   |                       |                            |                           |
| - Diagnose for check engine light on.clean fuel condition module and replace engine oil and filter.   | <b>Parts List</b>     | <b>Qty</b>                 |                           |
| - Shop Supplies   | Napagold Oil Filter   | 1.00                       |                           |
|   | 15w40 Bulk South Reg  | 16.00                      |                           |
|   | Seal Kit              | 1.00                       |                           |
|   | Shop Supplies         | 1.00                       |                           |
| Hours 2.00  | Labor: 120.00         | Parts: 117.74              | Total: 237.74             |
| :   |                       |                            |                           |
| <b>Workorder:</b> 1607482   | <b>Meter:</b> 86485   | <b>In Date:</b> 07/22/2016 | <b>Closed:</b> 08/12/2016 |
| <b>Problem:</b> Ac inop.  |                       |                            |                           |
| - C/s A/c Inop. Perform System Pressure Test, Leak Test. Found Leaking Hoses & schrader Valves. R/r A/c Hoses&schrader Valves. Recharge&c/k For Leaks | <b>Parts List</b>     | <b>Qty</b>                 |                           |
| - Shop Supplies   | Accumulator           | 1.00                       |                           |
|   | A/c Hose              | 1.00                       |                           |
|   | A/c Hose              | 1.00                       |                           |
|   | A/c Switch            | 1.00                       |                           |
|   | Valve Core            | 1.00                       |                           |
|   | Ac Valve Core High    | 1.00                       |                           |
|   | South Region R134a    | 3.00                       |                           |
|   | kit                   | 1.00                       |                           |
|   | E8 A/c Oil Univ W Dye | 1.00                       |                           |
|   | Shop Supplies         | 1.00                       |                           |
| Hours 9.00  | Labor: 540.00         | Parts: 527.68              | Total: 1,067.68           |
| :   |                       |                            |                           |
| <b>Workorder:</b> 1610140   | <b>Meter:</b> 87063   | <b>In Date:</b> 09/28/2016 | <b>Closed:</b> 10/18/2016 |
| <b>Problem:</b> BATTERY   |                       |                            |                           |
| - Jump start vehicle in Wud parking lot.test and replace both defective batteries.parts warranty asper Justin at Napa.                                | <b>Parts List</b>     | <b>Qty</b>                 |                           |
| - Shop Supplies   | Shop Supplies         | 1.00                       |                           |
| Hours 1.75  | Labor: 105.00         | Parts: 2.00                | Total: 107.00             |
| :   |                       |                            |                           |
| <b>Workorder:</b> 1703169   | <b>Meter:</b> 87311   | <b>In Date:</b> 03/30/2017 | <b>Closed:</b> 04/10/2017 |
| <b>Problem:</b> PM Service.Dead battery.  |                       |                            |                           |
| - Pm Service.   | <b>Parts List</b>     | <b>Qty</b>                 |                           |
| - Mount two new tires.rotate and balance all six.   | Napagold Oil Filter   | 1.00                       |                           |
| - Install steering wheel cover.   | Fuel Filter Ford Only | 1.00                       |                           |
| - Had to jump start vehicle in Wud parking lot.fully recharge and test both batteries ok.   | Napagold Air Filter   | 1.00                       |                           |
| - Repair tag lamp circuit.repair and rewire marker light circuit.   | 15w40 Bulk South Reg  | 15.00                      |                           |
| - Shop Supplies   | 22" Wiper Blade       | 2.00                       |                           |
|   | Washer Fluid Concentr | 1.00                       |                           |
|   | 179636492 Lt245-75r17 | 2.00                       |                           |
|   | Stg Wheel Cov - Ford  | 1.00                       |                           |
|   | Shop Supplies         | 1.00                       |                           |
|   | Tire Disposal Fee     | 2.00                       |                           |
| Hours 8.75  | Labor: 525.00         | Parts: 718.79              | Total: 1,243.79           |
| :   |                       |                            |                           |

**Palm Beach County Fleet Management  
Asset Maintenance History**

|   |                         |                            |                           |
|---|-------------------------|----------------------------|---------------------------|
| <b>Workorder:</b> 1706313   | <b>Meter:</b> 87311     | <b>In Date:</b> 06/27/2017 | <b>Closed:</b> 06/30/2017 |
| <b>Problem:</b> Dead batteries in WUD parking lot.  |                         |                            |                           |
| - Jump start vehicle.fully recharge and test batteries.                                   | <b>Parts List</b>       |                            | <b>Qty</b>                |
| - Shop Supplies   | Shop Supplies           |                            | 1.00                      |
| Hours 1.25  | Labor: 75.00            | Parts: 2.00                | Total: 77.00              |
| :   |                         |                            |                           |
| <b>Workorder:</b> 1707825   | <b>Meter:</b> 87866     | <b>In Date:</b> 08/10/2017 | <b>Closed:</b> 08/21/2017 |
| <b>Problem:</b> Steering wheel cover  |                         |                            |                           |
| - Install steering wheel cover.   | <b>Parts List</b>       |                            | <b>Qty</b>                |
|   | Stg Wheel Cov - Ford    |                            | 1.00                      |
| Hours 0.25  | Labor: 15.00            | Parts: 16.73               | Total: 31.73              |
| :   |                         |                            |                           |
| <b>Workorder:</b> 1709635   | <b>Meter:</b> 88099     | <b>In Date:</b> 10/03/2017 | <b>Closed:</b> 10/10/2017 |
| <b>Problem:</b> PM Service.Jump start vehicle in WUD parking lot.                         |                         |                            |                           |
| - Pm service.   | <b>Parts List</b>       |                            | <b>Qty</b>                |
| - Jump start vehicle in Wud parking lot.fully recharge and test both batteries tested ok. | Napagold Oil Filter     |                            | 1.00                      |
|   | 15w40 Bulk South Reg    |                            | 15.00                     |
| - Shop Supplies   | Napagold Oil Filter     |                            | 1.00                      |
|   | Shop Supplies           |                            | 1.00                      |
| Hours 5.00  | Labor: 300.00           | Parts: 127.75              | Total: 427.75             |
| :   |                         |                            |                           |
| <b>Workorder:</b> 1710655   | <b>Meter:</b> 88338     | <b>In Date:</b> 10/27/2017 | <b>Closed:</b> 10/27/2017 |
| <b>Problem:</b> Transition Prep Charge  |                         |                            |                           |
| - Transition Prep Charge  |                         |                            |                           |
| Hours 2.00  | Labor: 120.00           | Parts: 0.00                | Total: 120.00             |
| :   |                         |                            |                           |
| <b>Workorder:</b> 1808298   | <b>Meter:</b> 88375     | <b>In Date:</b> 08/13/2018 | <b>Closed:</b> 08/20/2018 |
| <b>Problem:</b> pm/ prepair for transfer  |                         |                            |                           |
| - pm service  | <b>Parts List</b>       |                            | <b>Qty</b>                |
| - prepare utility truck for dept  | Napagold Oil Filter     |                            | 1.00                      |
| - jump start vehicle test and replace both batteries                                      | 15-40 Oil               |                            | 15.00                     |
| - Shop Supplies   | Washer Fluid Concentr   |                            | 1.00                      |
|   | 22" Wiper Blade         |                            | 2.00                      |
|   | Used Fire X Refurbished |                            | 1.00                      |
|   | Fuel Filter Ford Only   |                            | 1.00                      |
|   | Non-chlor Brake Clnr    |                            | 2.00                      |
|   | Battery                 |                            | 2.00                      |
|   | Air Freshener           |                            | 1.00                      |
|   | Gray Sea                |                            | 1.00                      |
|   | Shop Supplies           |                            | 1.00                      |
| Hours 9.50  | Labor: 570.00           | Parts: 500.89              | Total: 1,070.89           |
| :   |                         |                            |                           |

**Palm Beach County Fleet Management  
Asset Maintenance History**

|   |                      |                            |                           |
|---|----------------------|----------------------------|---------------------------|
| <b>Workorder:</b> 1810772   | <b>Meter:</b> 88612  | <b>In Date:</b> 10/18/2018 | <b>Closed:</b> 10/24/2018 |
| <b>Problem:</b> Check engine light and right rear inner tire has nail.  |                      |                            |                           |
| - Computer diagnose chech engine light , code P2263.<br>Perform pinpoint test . Replace defective exhaust back<br>pressure sensor . Clear codes and retest.     | <b>Parts List</b>    | <b>Qty</b>                 |                           |
|   | Sensor Assembly      | 1.00                       |                           |
| - Check and repair right rear inner tire and balance . Nitrofill<br>tires.  | Shop Supplies        | 1.00                       |                           |
| - Shop Supplies   |                      |                            |                           |
| Hours 4.00  | Labor: 268.00        | Parts: 104.01              | Total: 372.01             |
| :   |                      |                            |                           |
| <b>Workorder:</b> 1811914   | <b>Meter:</b> 89794  | <b>In Date:</b> 11/21/2018 | <b>Closed:</b> 12/13/2018 |
| <b>Problem:</b> Oil leak.   |                      |                            |                           |
| - Inspect for oil leak . Replace left valve cover gasket and<br>front crankshaft seal and dipstick tube seal . Degrease engine<br>and add leak stop and retest. | <b>Parts List</b>    | <b>Qty</b>                 |                           |
|   | Gasket Kit           | 1.00                       |                           |
| - Replace right headlight bulb due to moisture in bulb.   | oil dip stick oring  | 1.00                       |                           |
| - Replace broken hood release handle . Test and replace<br>defective blower resistor . Test drive for blowing smoke .   | Front Seal           | 1.00                       |                           |
| Computer scan for codes . No problem found at this time .   | Glow Plug Harness    | 1.00                       |                           |
| - Check starting system . Perform starter circuit test . R&r<br>defective start assembly .retest.   | Coolant Ford Gold    | 2.00                       |                           |
| - Shop Supplies   | Engine Oil Stop Leak | 2.00                       |                           |
|   | Halogen Sealed Beams | 1.00                       |                           |
|   | Oil Indicator        | 1.00                       |                           |
|   | Blower Resistor      | 1.00                       |                           |
|   | Cable Asy            | 1.00                       |                           |
|   | Starter Motor        | 1.00                       |                           |
|   | Shop Supplies        | 1.00                       |                           |
| Hours 11.30   | Labor: 757.10        | Parts: 947.36              | Total: 1,704.46           |
| :   |                      |                            |                           |
| <b>Workorder:</b> 1812883   | <b>Meter:</b> 90168  | <b>In Date:</b> 12/19/2018 | <b>Closed:</b> 02/22/2019 |
| <b>Problem:</b> Check engine light on.  |                      |                            |                           |
| - Diagnose check engine light.transport vehicle to dealer to<br>replace high pressure fuel pump and worn out body mounts.                                       | <b>Parts List</b>    | <b>Qty</b>                 |                           |
| - Shop Supplies   | Shop Supplies        | 1.00                       |                           |
| Hours 1.00  | Labor: 67.00         | Parts: 3.00                | Total: 70.00              |
| :   |                      |                            |                           |

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1902094      **Meter:** 91175      **In Date:** 02/26/2019      **Closed:** 04/17/2019  
**Problem:** Check for oil leak .

|  |                       |                 |
|--|-----------------------|-----------------|
| - Clean engine to identify source of oil leak.r&r turbo charger and replace drain tubes and seal.replace drain catch elbow.replace turbo oil drain line. | <b>Parts List</b>     | <b>Qty</b>      |
|  | seal                  | 4.00            |
|  | Seal                  | 4.00            |
|  | Seal                  | 4.00            |
|  | Seal                  | 4.00            |
|  | Turbo Drain Tube      | 1.00            |
|  | Non-chlor Brake Clnr  | 3.00            |
|  | Turbo Pedestal Gasket | 1.00            |
|  | Tube Assy             | 1.00            |
|  | Crank Vent Hose       | 1.00            |
|  | Bolt                  | 1.00            |
|  | Washer                | 4.00            |
|  | Gasket                | 1.00            |
|  | Bolt                  | 3.00            |
|  | Hardware              | 1.00            |
|  | Shop Supplies         | 1.00            |
| Hours 12.00  | Labor: 804.00         | Parts: 466.82   |
| :  |                       | Total: 1,270.82 |

**Workorder:** 1907057      **Meter:** 93669      **In Date:** 07/09/2019      **Closed:** 07/16/2019  
**Problem:** P.M. service.

|  |                         |                 |
|--|-------------------------|-----------------|
| - P.m. service.  | <b>Parts List</b>       | <b>Qty</b>      |
| - Resurface both rear brake rotors . Replace rear pads and calipers . Flush and bleed brake system . Road test . | Napagold Oil Filter     | 1.00            |
|  | 15-40 Oil               | 15.00           |
| - Replace both front and rear worn bump stops .  | Fuel Filter Ford Only   | 1.00            |
| - Rotate and balance all six tires . Nitrofill all.  | 20" Wiper Blade         | 2.00            |
| - Shop Supplies  | Washer Fluid Concentr   | 1.00            |
|  | Used Fire X Refurbished | 1.00            |
|  | Pedal Pad               | 1.00            |
|  | Bumper                  | 2.00            |
|  | bumper                  | 2.00            |
|  | Reman Brake Caliper     | 1.00            |
|  | Reman Brake Caliper     | 1.00            |
|  | B Fluid Dot 3-32oz      | 2.00            |
|  | Brake Pad               | 1.00            |
|  | Reman Brake Caliper     | 1.00            |
|  | Reman Brake Caliper     | 1.00            |
|  | Shop Supplies           | 1.00            |
| Hours 11.50  | Labor: 770.50           | Parts: 750.44   |
| :  |                         | Total: 1,520.94 |

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

**Workorder:** 1907423      **Meter:** 93883      **In Date:** 07/18/2019      **Closed:** 07/23/2019

**Problem:** Check for fuel leak .

|  |                   |              |
|--|-------------------|--------------|
| - Remove leaking rail fuel pump to reseal .clean leaked fuel and reinspect for leaks . | <b>Parts List</b> | <b>Qty</b>   |
|  | Seal Kit          | 1.00         |
| - Shop Supplies  | Shop Supplies     | 1.00         |
| Hours 0.80   | Labor: 53.60      | Parts: 43.85 |
| :  |                   | Total: 97.45 |

---

**Workorder:** 2004031      **Meter:** 98966      **In Date:** 04/22/2020      **Closed:** 04/22/2020

**Problem:** Transition Prep Charge

|                          |               |             |               |
|--------------------------|---------------|-------------|---------------|
| - Transition Prep Charge |               |             |               |
| Hours 2.00               | Labor: 146.00 | Parts: 0.00 | Total: 146.00 |
| :                        |               |             |               |