

55345 Palm Tran Connection v 2.2 Page 1 of 10



WorkOrder: 53367476 **Invoice Number:** 55345-53367476

Client Department:

MRC:

WO Desc:

PM C Requested By: Created By:

Class: Arrangement: **Potential Warranty:** 55345M

Equipment:

5404

Ford E350 Champion Crusaders

1FDEE3FL2FDA02758 40

VAMRITTEEMAL VAMRITTEEMAL WO

Unassigned No

1

Phone: ETA:

VIN:

Status:

Priority:

Driver:

	Chronology	
Reported	May 7, 2020	11:32 AM
Started	May 7, 2020	
Completed	May 7, 2020	11:30 PM

Meter	Reading	UOM
wo		DH
Life	279,004	DH
System	279,063	DH

WorkOrder Notes

Line	Comment
10	PMC
	Service
	Perform PMC Service
	Oil filter B329 qty1
	Engine oil 10w30 qty 7 Qts
	Air filter PA4075 qty1
	Gear Oil 80w90 qty 4 Qts
	Replaced lift buckle atv1

Activity: 10

999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI

08 - Preventive Maintenance Reason for Repair:

Down Time

Work Accomplished: -Part Failure:

Activity Comments

Parts Issued

Date Part Number Description

Qty. Each Extended

Labor Posted

Date		Tı	echnician		ŀ	lours	Rate E	ktended	
07-May-20	Gaspard,Ronald					1.43	0.00	0.00	
			era arterigia igrazi e a contrata da escaliga a suc	*******************************	 eragera er reed een geween een	e e come ces mosce di sossignossi	e entre aprice a secretar bearing	romanigoroug tombre exe	

Activity 10 Sub Total

Parts: Labor:

Labor Hours: 1.43 Sublet Parts: Sublet Labor:

0.00 0.00

0.00

0.00

Activity Sub Total

0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note: Reason for Repair:

PM C

08 - Preventive Maintenance

Work Accomplished: C - PM Level C

Part Failure:

Activity Comments

Parts Issued

Date Part Number Description Each Extended



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52778359 **Invoice Number:** 55345-52778359

MOU

DH

DH

253,389

Client Department:

MRC: WO Desc:

55345M

Equipment:

5404

Ford E350 Champion Crusaders

PM C

AOWENS

VIN: Status: 1FDEE3FL2FDA02758

Requested By: Created By:

AOWENS WO

Priority:

40 1

Class: **Arrangement:**

Unassigned

Driver: Phone:

Potential Warranty:

No

Chronology

ETA:

AM	Meter	Reading
	MA	

Life

Reported Started Completed

Oct 8, 2019 Oct 8, 2019 Oct 9, 2019

12:16 AM

11:50

WorkOrder Notes

Line	Comment
10	PMC Service Perform PMC Service Oil filter B329 qty1 Engine oil 5w20 qty 7 Qts Gear Oil 80w90 qty 4 Qts Replaced body fluid kit Missing 4 screw from transmission Pan

Activity: 10 **Activity Note:**

999 TOTAL VEHICLE Light Medium Duty PMI

Down Time

Reason for Repair: 05 - Inspection, Routine

Work Accomplished: 06 - Inspect

Part Failure:

Activity Comments

Parts Issued

Date Part Number

Description

Qty. Each Extended

Extended

Labor Posted

08-Oct-19	Gaspard,

.Ronald

Technician

Hours 1.60 Rate 65.00

104.00

Activity 10 Sub Total

Parts: Labor: 0.00

Labor Hours: 1.60

104.00

Sublet Parts: Sublet Labor:

0.00 0.00

Activity Sub Total

104.00

Activity: 20

999 TOTAL VEHICLE

Activity Note: Reason for Repair: PM C

08 - Preventive Maintenance

Work Accomplished: C - PM Level C

Part Failure:

Activity Comments



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52267665 **Invoice Number: 55345-52267665**

Client Department:

MRC: WO Desc:

Reported

Completed

Started

55345M

Equipment:

5404

40

UOM

DH

1

226.906

Ford E350 Champion Crusaders

PM C

VIN: Status: 1FDEE3FL2FDA02758

Requested By: Created By:

DARTHURS DARTHURS

Priority:

Class: WO **Arrangement:** Unassigned No

Driver:

Phone: ETA:

Potential Warranty:

Chronology Apr 11, 2019 Apr 11, 2019 Apr 12, 2019

12:24 PM

Meter Reading

Down Time

12:12 AM Life

WorkOrder Notes

Line

Comment

wo

Perform PMC Service. Change Oil & Filter.Lube all Pivoting Points .check Brakes. Clean batteries.replace A/C Filter Replace Air Filter.Perform Transmission Service/ Differential Service.

Activity: 10 **Activity Note:**

999 TOTAL VEHICLE

Light Medium Duty PMI Reason for Repair: 05 - Inspection, Routine

Work Accomplished: 06 - Inspect

Part Failure:

Activity Comments

Parts Issued

Date Part Number Description Oty. E.	ach Extended

Labor Posted

100000	11-Арг-19	Arthur Dunan	كوتور والدواري والتوادية المتوادية والمتوادية والمتوادية والمتوادية والمتوادية والمتوادية والمتوادية			0.00
- :	11.451.13	: Arthurs,Durvin		3.00	0.00	0.00

Activity 10 Sub Total

Parts: 0.00 Labor: 0.00 Labor Hours: 3.00 Sublet Parts: 0.00

Sublet Labor:

0.00

Activity Sub Total

0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note:

PM C

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: C-PM Level C

Part Failure:

Activity Comments

	Date	Part Numi	nber Description	Qty.	Each	Extended
	11-Apr-19	PA4075	FILTER, AIR, PAPER SAME AS AF25590	1.00	5.28	5.28
į	11-Apr-19	20021	FILTER, TRANSMISSION, E350, '09 W/RUBBER NECK SEAL SAME FT180	AS 1.00	17.27	17.27



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 51787854 **Invoice Number:** 55345-51787854

Client Department:

MRC:

55345M

Equipment:

5404

WO Desc: PM C

40

1

Reading

UOM

DH

Ford E350 Champion Crusaders 1FDEE3FL2FDA02758

Requested By:

AOWENS

Created By: Class:

AOWENS WO

Priority:

Meter

wo

Arrangement:

Unassigned

Driver:

Potential Warranty:

No

Phone:

ETA:

VIN:

Status:

Reported Started

Completed

Nov 1, 2018 Nov 1, 2018 Nov 2, 2018

Chronology

1:05 PM

Life 12:03 AM

201,860 DH 202,031 System DH

Down Time

WorkOrder Notes

Line

Comment

Perform PMC Service. Change Oil& Filter. Lube all Pivoting Points. Clean batteries. Check brakes, Replace Air Filter. Perform PMC Service. Change ATF Fluid.Change differential Fluid.

Parts# B329 Qty (1) Parts# PA 4075 Qty (1) Parts#20021 Qty (1) Oil 5W20QTY (6.5) Qt ATF Fluid Qty (9.5) Qt Gear Oil Qty (3) Qt

Activity: 10

999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI Reason for Repair: 05 - Inspection, Routine

Work Accomplished: 06 - Inspect

Part Failure:

Activity Comments

Parts Issued

Date Part Number Description

Each Extended

Labor Posted

Date	Technician		Hours	Rate E	ktended	Section 2
01-Nov-18	Arthurs, Durvin		3.50	0.00	0.00	
 	Soft from the transformation of the transfor	grand area bereing	and the second second section in the second	erajaming ganja arabasiya	grayman areas of	3

Activity 10 Sub Total

Parts:

0.00

Labor:

0.00

Labor Hours: 3.50 Sublet Parts: Sublet Labor:

0.00 0.00

Activity Sub Total

0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note: Reason for Repair: PM C

08 - Preventive Maintenance

Work Accomplished: C - PM Level C

Part Failure:

Activity Comments



55345 Palm Tran Connection v 2.2 Page 1 of 9



WorkOrder: 51281954 Invoice Number: 55345-51281954

Client Department:

MRC: 55345M **Equipment:** 5404

WO Desc: Ford E350 Champion Crusaders

PM C VIN: 1FDEE3FL2FDA02758

Requested By:CVERGARAStatus:40Created By:CVERGARAPriority:1

Class: WO Driver:
Arrangement: Unassigned Phone:
Potential Warranty: No ETA:

	Chronology	
Reported	May 23, 2018	1:31 PM
Started	May 23, 2018	
Completed	May 23, 2018	10:57 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	177,264	DH
System	177,438	DH

WorkOrder Notes

Line	Comment
10	Tech performed PM-C
	Parts used Oil filter Qty:1 part#B329 Oil Qty:6.5

Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine

Work Accomplished: 06 - Inspect

Part Failure:

Activity Comments

Parts Issued

Date Part Number Description	Qty. Each Extended
------------------------------	--------------------

Labor Posted

23-May-18 KARLENS,Cyrius	2.00	0.00	0.00

| Activity 10 Sub Total | Parts: 0.00 | Labor: 0.00 | Labor Hours: 2.00 | Sublet Parts: 0.00 | Sublet Labor: 0.00 | Activity Sub Total | 0.00 |

Activity: 20 999 TOTAL VEHICLE PM C

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: C - PM Level C

Part Failure: -

Activity Comments

Date	Part Number	Description	Qty.	Each	Extended
23-May-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



55345 Palm Tran Connection v 2.2 Page 2 of 9



WorkOrder: 51281954 **Invoice Number:** 55345-51281954

Client Department:

MRC: WO Desc:

PM C

55345M

Equipment:

5404

Ford E350 Champion Crusaders 1FDEE3FL2FDA02758

Requested By: Created By:

CVERGARA CVERGARA WO

Status: **Priority:** Driver:

40 1

Class: **Arrangement:**

Unassigned No

Phone: ETA:

VIN:

Labor Posted

Potential Warranty:

Date	Technician	Hours	Rate	Extended
23-May-18	KARLENS, Cyrius	2.00	0.00	0.00

Activity 20 Sub Total 1.96 Parts: Labor: 0.00 Labor Hours: 2.00 Sublet Parts: 0.00 Sublet Labor: 0.00 1.96

Activity Sub Total

Activity: 30

999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 - Inspection, Routine

Work Accomplished: 06 - Inspect

Part Failure:

Activity Comments

Parts Issued

		Date	Part Number	Description	Qty.	Each	Extended
--	--	------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
23-May-18	KARLENS, Cyrius	0.03	0.00	0.00

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.03	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

WorkOrder 51281954 Grand Total	
Parts:	1.96
Labor:	0.00
Labor Hours: 4.03	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	1.96

Recent Repair History

WorkOrde	Date Completed	Life Meter	Class	Description
51281954	23-May-18	177,264	WO	PM C
51339595	14-May-18	175,598	WO	Alternator light is on



55345 Palm Tran Connection v 2.2 Page 3 of 9



WorkOrder: 51281954 Invoice Number: 55345-51281954

Client Department:

MRC: 55345M **Equipment:** 5404

WO Desc: Ford E350 Champion Crusaders PM C VIN: 1FDEE3FL2FDA02758

Requested By:CVERGARAStatus:40Created By:CVERGARAPriority:1

Class: WO Driver: Arrangement: Unassigned Phone: Potential Warranty: No ETA:

Potentiai w	arranty:	IN	10	EIA	\ :				
WorkOrder Date Life Meter Completed			Class			Desc	ription		_
51134274	24-Apr-18	173,277	WO	PM A					
Scheduled I	Preventativ	e Maintena	nce						
Nest PM		PM	WorkOrd	ler	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2
Other Open	Repairs			,		•			
WorkOrder8	Date Reported	Life Meter	Class			Desc	ription		
51369415	23-May-18	177,264	WO	FOLLOW	JP¿¿-Replace front and	d rear brakes			

PH: Work Order: 51281954 Desc: PM C

Equip: 5404 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FL2FDA02758

LH: 10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: CKARLENS Performed on: 23-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		CKARLENS	May 23, 2018 10:34:13 PM	No	
10,100	Safety Inspection	Done		CKARLENS	May 23, 2018 10:34:14 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		CKARLENS	May 23, 2018 10:34:13 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		CKARLENS	May 23, 2018 10:34:13 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		CKARLENS	May 23, 2018 10:34:14 PM	No	
10,140	Check Service Brakes	Done		CKARLENS	May 23, 2018 10:34:14 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		CKARLENS	May 23, 2018 10:34:14 PM	No	
10,160	FRA Check Instruments and Horns	Done		CKARLENS	May 23, 2018 10:34:15 PM	No	
10,170	Check Fast Idle	Done		CKARLENS	May 23, 2018 10:34:15 PM	No	
10,180	Check Starter Protection Circuit	Done		CKARLENS	May 23, 2018 10:34:15 PM	No	
10,190	Check Reverse Warning System	Done		CKARLENS	May 23, 2018 10:34:15 PM	No	
11,100	Check Parking Brake	Done		CKARLENS	May 23, 2018 10:34:15 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		CKARLENS	May 23, 2018 10:34:15 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		CKARLENS	May 23, 2018 10:34:15 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		CKARLENS	May 23, 2018 10:34:15 PM	No	
11,140	Road Test: Check for Proper Operation	Done		CKARLENS	May 23, 2018 10:34:16 PM	No	
11,150	Perform Brake Test	Done		CKARLENS	May 23, 2018 10:34:16 PM	No	
11,152	Decelerometer Results Test 1	FEET	na	CKARLENS	May 23, 2018 10:34:16 PM	No	
11,154	Decelerometer Results Test 2	FEET	na	CKARLENS	May 23, 2018 10:34:16 PM	No	
11,156	Decelerometer Results Test 3	FEET	na	CKARLENS	May 23, 2018 10:34:16 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	CKARLENS	May 23, 2018 10:34:17 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	na	CKARLENS	May 23, 2018 10:34:16 PM	No	
11,170	FRA Check Door Operation	Done		CKARLENS	May 23, 2018 10:34:16 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		CKARLENS	May 23, 2018 10:34:17 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		CKARLENS	May 23, 2018 10:34:17 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		CKARLENS	May 23, 2018 10:34:17 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		CKARLENS	May 23, 2018 10:34:17 PM	No	
20,230	FRA Check Wiring Under Dash	Done		CKARLENS	May 23, 2018 10:34:18 PM	No	
20,240	FRA Check Interior Lights	Done		CKARLENS	May 23, 2018 10:34:18 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		CKARLENS	May 23, 2018 10:34:18 PM	No	
20,260	Check Stop Request System	-	na	CKARLENS	May 23, 2018 10:34:18 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	na	CKARLENS	May 23, 2018 10:34:18 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		CKARLENS	May 23, 2018 10:34:18 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		CKARLENS	May 23, 2018 10:34:19 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		CKARLENS	May 23, 2018 10:34:19 PM	No	
22,110	Check Emergency Hatches	Done		CKARLENS	May 23, 2018 10:34:19 PM	No	
22,120	Check All Safety Equipment	Done		CKARLENS	May 23, 2018 10:34:19 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		CKARLENS	May 23, 2018 10:34:19 PM	No	
30,310	Check Passenger Doors	Done		CKARLENS	May 23, 2018 10:34:20 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		CKARLENS	May 23, 2018 10:34:19 PM	No	
30,330	Check Wheelchair Lift Operation	Done		CKARLENS	May 23, 2018 10:34:20 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	na	CKARLENS	May 23, 2018 10:34:20 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		CKARLENS	May 23, 2018 10:34:20 PM	No	
30,360	Check for Physical Damage and Decals	Done		CKARLENS	May 23, 2018 10:34:20 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		CKARLENS	May 23, 2018 10:34:20 PM	No	
30,380	Check Exterior Compartment Doors	Done		CKARLENS	May 23, 2018 10:34:20 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		CKARLENS	May 23, 2018 10:34:20 PM	No	
33,100	Check Lights and Reflectors	Done		CKARLENS	May 23, 2018 10:34:20 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		CKARLENS	May 23, 2018 10:34:21 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		CKARLENS	May 23, 2018 10:34:21 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		CKARLENS	May 23, 2018 10:34:21 PM	No	
40,420	Check Hood	Done		CKARLENS	May 23, 2018 10:34:21 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		CKARLENS	May 23, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:34:22 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	na	CKARLENS	May 23, 2018 10:34:22 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		CKARLENS	May 23, 2018 10:34:22 PM	No	
40,442	Freeze Point	Degree Fahrenheit	na	CKARLENS	May 23, 2018 10:34:22 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		CKARLENS	May 23, 2018 10:34:22 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	na	CKARLENS	May 23, 2018 10:34:22 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	na	CKARLENS	May 23, 2018 10:34:22 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		CKARLENS	May 23, 2018 10:34:23 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		CKARLENS	May 23, 2018 10:34:23 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		CKARLENS	May 23, 2018 10:34:23 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		CKARLENS	May 23, 2018 10:34:23 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		CKARLENS	May 23, 2018 10:34:23 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		CKARLENS	May 23, 2018 10:34:24 PM	No	
44,130	FRA Check Exhaust System	Done		CKARLENS	May 23, 2018 10:34:24 PM	No	
44,140	FRA Check Intake System	Done		CKARLENS	May 23, 2018 10:34:24 PM	No	
44,150	FRA Inspect Turbocharger	-	na	CKARLENS	May 23, 2018 10:34:24 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		CKARLENS	May 23, 2018 10:34:24 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		CKARLENS	May 23, 2018 10:34:25 PM	No	
44,180	FRA Check for Leaks	Done		CKARLENS	May 23, 2018 10:34:25 PM	No	
44,190	FRA Perform Battery Inspection	Done		CKARLENS	May 23, 2018 10:34:25 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		CKARLENS	May 23, 2018 10:34:25 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		CKARLENS	May 23, 2018 10:34:25 PM	No	
50,510	Check Entire Steering System	Done		CKARLENS	May 23, 2018 10:34:25 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		CKARLENS	May 23, 2018 10:34:26 PM	No	
60,610	FRA Check and Record Air Pressure	Done		CKARLENS	May 23, 2018 10:34:26 PM	No	
60,611	Air Pressure RF	70 Pounds per Square Inch		CKARLENS	May 23, 2018 10:34:26 PM	No	
60,612	Air Pressure LF	70 Pounds per Square Inch		CKARLENS	May 23, 2018 10:34:26 PM	No	
60,613	Air Pressure RRO	70 Pounds per Square Inch		CKARLENS	May 23, 2018 10:34:26 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	70 Pounds per Square Inch		CKARLENS	May 23, 2018 10:34:26 PM	No	
60,615	Air Pressure LRI	70 Pounds per Square Inch		CKARLENS	May 23, 2018 10:34:27 PM	No	
60,616	Air Pressure LRO	70 Pounds per Square Inch		CKARLENS	May 23, 2018 10:34:27 PM	No	
60,620	Check Valve Stems and Caps	Done		CKARLENS	May 23, 2018 10:34:27 PM	No	
60,630	Check and Record Tread Depth	Done		CKARLENS	May 23, 2018 10:34:27 PM	No	
60,631	Tread Depth RF	9 32nds of an inch		CKARLENS	May 23, 2018 10:34:27 PM	No	
60,632	Tread Depth LF	9 32nds of an inch		CKARLENS	May 23, 2018 10:34:27 PM	No	
60,633	Tread Depth RRO	7 32nds of an inch		CKARLENS	May 23, 2018 10:34:27 PM	No	
60,634	Tread Depth RRI	7 32nds of an inch		CKARLENS	May 23, 2018 10:34:27 PM	No	
60,635	Tread Depth LRI	7 32nds of an inch		CKARLENS	May 23, 2018 10:34:27 PM	No	
60,636	Tread Depth LRO	7 32nds of an inch		CKARLENS	May 23, 2018 10:36:06 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		CKARLENS	May 23, 2018 10:36:06 PM	No	
60,650	Check Sidewall Wear	Done		CKARLENS	May 23, 2018 10:36:06 PM	No	
60,660	Inspect for Cuts and Tears	Done		CKARLENS	May 23, 2018 10:36:06 PM	No	
60,670	Check Dual Mating With Square	Done		CKARLENS	May 23, 2018 10:36:06 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		CKARLENS	May 23, 2018 10:36:07 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		CKARLENS	May 23, 2018 10:36:07 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		CKARLENS	May 23, 2018 10:36:07 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		CKARLENS	May 23, 2018 10:36:07 PM	No	
70,710	Check Vibration Damper	Done		CKARLENS	May 23, 2018 10:36:07 PM	No	
70,720	Check Engine and Transmission Mounts	Done		CKARLENS	May 23, 2018 10:36:07 PM	No	
70,730	FRA Check Starter	Done		CKARLENS	May 23, 2018 10:36:07 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		CKARLENS	May 23, 2018 10:36:08 PM	No	
70,750	FRA Check Transmission for Leaks	Done		CKARLENS	May 23, 2018 10:36:08 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		CKARLENS	May 23, 2018 10:36:08 PM	No	
70,770	FRA Check Exhaust System	Done		CKARLENS	May 23, 2018 10:36:08 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		CKARLENS	May 23, 2018 10:36:09 PM	No	
70,790	Check All Body Mounts and Chassis	Done		CKARLENS	May 23, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Frame				10:36:09 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		CKARLENS	May 23, 2018 10:36:09 PM	No	
77,110	FRA Check Fuel Tank	Done		CKARLENS	May 23, 2018 10:36:09 PM	No	
77,120	Check Suspension Components	Done		CKARLENS	May 23, 2018 10:36:09 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		CKARLENS	May 23, 2018 10:36:09 PM	No	
77,131	Brake Pad Thickness LF	4 Inch	REPLACE FRONT BRAKE PADS	CKARLENS	May 23, 2018 10:36:09 PM	Yes	51369415
77,132	Brake Pad Thickness RF	5 Inch		CKARLENS	May 23, 2018 10:36:09 PM	No	
77,133	Brake Pad Thickness LR	6 Inch		CKARLENS	May 23, 2018 10:36:10 PM	No	
77,134	Brake Pad Thickness RR	6 Inch	REPLACE REAR BRAKE PADS	CKARLENS	May 23, 2018 10:36:10 PM	Yes	51369415
77,135	Brake Rotor LF	39.8 Inch		CKARLENS	May 23, 2018 10:36:10 PM	No	
77,136	Brake Rotor RF	39.8 Inch		CKARLENS	May 23, 2018 10:36:10 PM	No	
77,137	Brake Rotor LR	35.8 Inch		CKARLENS	May 23, 2018 10:36:10 PM	No	
77,138	Brake Rotor RR	35.8 Inch		CKARLENS	May 23, 2018 10:36:11 PM	No	
77,140	FRA Check Brake Hoses	Done		CKARLENS	May 23, 2018 10:36:11 PM	No	
77,150	Check King Pins	Done		CKARLENS	May 23, 2018 10:36:11 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		CKARLENS	May 23, 2018 10:36:11 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		CKARLENS	May 23, 2018 10:36:12 PM	No	
80,810	Completion of PMI Report	Done		CKARLENS	May 23, 2018 10:36:12 PM	No	
90,000	SECTION 9 Completion of PMI	Done		CKARLENS	May 23, 2018 10:36:12 PM	No	
90,910	Vehicle Returned to predetermined location	Done		CKARLENS	May 23, 2018 10:36:12 PM	No	

LH: 20 Desc: PM C

Task: PM C SERVICE Performed by: CKARLENS Performed on: 23-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		CKARLENS	May 23, 2018 10:37:25 PM	No	
101,000	FRA Change Oil Filters	Yes		CKARLENS	May 23, 2018 10:37:25 PM	No	
102,000	FRA Drain Engine Oil	Yes		CKARLENS	May 23, 2018 10:37:25 PM	No	
103,000	FRA Check Transmission Fluid	Done		CKARLENS	May 23, 2018 10:37:25 PM	No	
104,000	Lubricate Chassis	Done		CKARLENS	May 23, 2018 10:37:26 PM	No	
105,000	Replace or Clean A/C Filters	Done		CKARLENS	May 23, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:37:26 PM		
107,000	FRA Change Primary Fuel Filter	Done		CKARLENS	May 23, 2018 10:37:26 PM	No	
108,000	Lube all pivoting Mechanisms	Done		CKARLENS	May 23, 2018 10:37:26 PM	No	
200,000	"B" PMI SERVICING ITEMS (12 MONTH)	Done		CKARLENS	May 23, 2018 10:37:27 PM	No	
201,000	Service Crankcase Breather	Done		CKARLENS	May 23, 2018 10:37:27 PM	No	
203,000	FRA Change Automatic Transmission Fluid	Yes		CKARLENS	May 23, 2018 10:37:27 PM	No	
204,000	FRA Change Power Steering Fluid and Filter	Yes		CKARLENS	May 23, 2018 10:37:27 PM	No	
205,000	Complete Engine Diagnostics and Clear Codes when Completed	Done		CKARLENS	May 23, 2018 10:37:27 PM	No	
300,000	"C" PMI SERVICING ITEMS (24 MONTH)	Done		CKARLENS	May 23, 2018 10:37:27 PM	No	
301,000	Check and Lubricate Door Linkages	Done		CKARLENS	May 23, 2018 10:37:27 PM	No	
302,000	Check Toe-In and Record Reading	-	na	CKARLENS	May 23, 2018 10:37:28 PM	No	
302,001	Record Toe-In Reading	Inches, fraction- actual	na	CKARLENS	May 23, 2018 10:37:28 PM	No	
304,000	1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	Yes		CKARLENS	May 23, 2018 10:37:28 PM	No	
305,000	FRA Change Differential Fluid	Yes		CKARLENS	May 23, 2018 10:37:28 PM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 23-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	May 23, 2018 10:37:50 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	



55345 Palm Tran Connection v 2.2 Page 1 of 10

55345M

RGASPARD

Chronology

Oct 6, 2020

Oct 6, 2020

Oct 7, 2020



WorkOrder: 53819501 **Invoice Number:** 55345-53819501

Client Department:

MRC: WO Desc:

Reported

Completed

Started

55345-LIGHT DUTY PMB

Requested By: Created By: Class: **Arrangement:**

RGASPARD WO Unassigned **Potential Warranty:** No

Equipment: 5404 Ford E350 Champion Crusaders

VIN: 1FDEE3FL2FDA02758

40

12:00 AM

12:09 AM

Status: **Priority: Driver:**

3 Phone:

Meter	Reading	UOM
WO		DH
Life	292,020	DH

WorkOrder Notes

ETA:

Line Comment 10 COMPLAINT: PMB

CAUSE: Service

CORRECTION: perform PMB Service Oil filter B329 Qty1 Engine oil 10w30 Qty 7 qts Replaced exhaust bracket Qty1 Replaced left side head light bulb Qty1 Fixed washer fluid reservoir hose

Activity: 5

999/999/999 TOTAL VEHICLE

Down Time

Activity Note: PERSONAL RISK ASSESSMENT

Reason for Repair: SW - Shop Work Order

Work Accomplished: 06 - Inspect **Part Failure:** 00 - No Failure

Activity Comments

Parts Issued

Date Extended Part Number Description Each

Labor Posted

Extended Date Technician Hours Rate

> **Activity 5 Sub Total** Parts:

Labor: 0.00 Labor Hours: 0.00 Sublet Parts: 0.00 Sublet Labor: 0.00

0.00

Activity Sub Total 0.00

Activity: 10 999/999/999 TOTAL VEHICLE **Activity Note:** Light Duty PMI

08 - Preventive Maintenance Reason for Repair:

Work Accomplished: -**Part Failure:**

Activity Comments

Parts Issued

Date Part Number Description Qty. Each Extended



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 53070976 **Invoice Number:** 55345-53070976

Client Department:

MRC: WO Desc: 55345M

Equipment:

5404

Ford E350 Champion Crusaders

1FDEE3FL2FDA02758

PM B Requested By:

DARTHURS DARTHURS Status: **Priority:**

40 1

Created By: Class:

Reported

Completed

Started

WO Unassigned

ETA:

Driver: Phone:

VIN:

Arrangement: Potential Warranty:

No

Chronology Jan 3, 2020 8:06 AM Jan 3, 2020 Jan 3, 2020 1:32 PM

Meter Reading UOM wo DH Life 266,449 DH

WorkOrder Notes

more	
Lin	Comment
10	COMPLAINT:
	CAUSE:
	CORRECTION:
20	PM.
	Perform pmB service, lube front end, tire rotation, torque and re torque tires (140 f/p), R&R engine oil and filter, road test, all okay at this time.

Activity: 10

999/999/999 TOTAL VEHICLE

Activity Note:

Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Down Time

Work Accomplished: Part Failure:

Activity Comments

Parts Issued

Date Part Number Description

Each Extended

Labor Posted

Date Technicia	n Hours	Rate	Extended
03-Jan-20 Rodriguez,Raul	1.88	0.00	0.00

Activity 10 Sub Total

Parts: 0.00 Labor: 0.00 Labor Hours: 1.88 Sublet Parts: 0.00 Sublet Labor: 0.00 0.00

Activity Sub Total

Activity: 20

999 TOTAL VEHICLE

Activity Note: Reason for Repair: PM B

08 - Preventive Maintenance

Work Accomplished: B - PM Level B

Part Failure:

Activity Comments



55345 Palm Tran Connection v 2.2

Page 1 of 9



Invoice Number: 55345-52497035

Client Department:

MRC: WO Desc:

PM B

55345M

Equipment:

5404

Ford E350 Champion Crusaders 1FDEE3FL2FDA02758

Requested By: Created By:

VAMRITTEEMAL VAMRITTEEMAL

Chronology

Jul 9, 2019

Status:

VIN:

40

Class:

WO

Priority: Driver:

1

Arrangement: Potential Warranty: Unassigned

Phone: ETA:

No

11:25 AM

Keportea	
Started	
Completed	

Jul 11, 2019 7:31 AM

wo		DH
Life	240,232	DH
System	240,232	DH

Meter Reading UOM

WorkOrder Notes

Line 10

Comment COMPLAINT: Performed PM+B

CAUSE: preventive maintenance

CORRECTION: Tech Performed PM-B

Activity: 10

999 TOTAL VEHICLE

Down Time

Activity Note: Light Mediun Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: 06 - Inspect

Part Failure:

Activity Comments

Parts Issued

Date Part Number Description

Each

Rate

Extended

Labor Posted

Date

Technician

Hours

Extended

Parts:

Activity 10 Sub Total

0.00

Labor:

0.00

Labor Hours: 0.00

Sublet Parts: Sublet Labor: 0.00 0.00

Activity Sub Total

0.00

Activityi 20

999 TOTAL VEHICLE

Activity Note: Reason for Repair:

PM B

08 - Preventive Maintenance

Work Accomplished: B - PM Level B

Activity Comments

Parts Issued

Part Failure:

Date	Part Number		Description	Qty. Each E	xtended
10-Jul-19	B329(F)	FILTER, OIL	SAME AS LF3681	1.00 1.96	1.96



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52035555 Invoice Number: 55345-52035555

Client Department:

MRC: WO Desc:

PM B Requested By:

Created By: Class:

Arrangement: Potential Warranty: 55345M

Equipment:

VIN:

Status: **Priority:** Driver:

Phone: ETA:

5404

Ford E350 Champion Crusaders

1FDEE3FL2FDA02758

40 1

	Chronology	
Reported	Jan 25, 2019	11:
Started	lan 25 2019	

Unassigned

WO

No

:40 AM Completed Jan 25, 2019 11:45 PM **Down Time**

VAMRITTEEMAL

VAMRITTEEMAL

	Meter	Reading	MOU
	wo		DH
	Life	214,490	DH
1	System	214,645	DH

WorkOrder Notes

Line Comment 10 COMPLAINT:PmA CAUSE:Service CORRECTION:perform PmA Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 **Activity Note:**

999 TOTAL VEHICLE

Light Mediun Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: 06 - Inspect

Part Failure:

Activity Comments

Parts Issued

Part Number Description Qty. Each Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
25-Jan-19	Gaspard,Ronald	1.58	0.00	0.00
	Parts: Labor:	Activity 10 Sub	Total	0.00
	Labor Hours Sublet Parts: Sublet Labor: Activity Sub			0.00 0.00

Activity: 20 **Activity Note:**

999 TOTAL VEHICLE

Reason for Repair:

PM B

08 - Preventive Maintenance

Work Accomplished: B - PM Level B

Part Failure:

Activity Comments

Date	Part Number	Description	Qty.	Each	Extended
25-Jan-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



55345 Palm Tran Connection v 2.2 Page 1 of 10



WorkOrder: 53938137 Invoice Number: 55345-53938137

Client Department:

55345-LIGHT DUTY PMA

MRC: WO Desc: 55345M

Equipment:

5404

Ford E350 Champion Crusaders

1FDEE3FL2FDA02758

VIN:

Status:

RGASPARD

40

Requested By: Created By: Class:

RGASPARD WO

Priority: Driver:

3

Arrangement: Potential Warranty:

Unassigned No

Phone: ETA:

Chronology

Reported Started Completed

Nov 19, 2020 Nov 19, 2020 Nov 19, 2020

7:57 PM

12:00 AM

UOM Meter Reading WO DH Life 296,274 DH

WorkOrder Notes

Line 10 COMPLAINT: Perform PMA Service. CAUSE: Service Due by Mileage.

CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check brakes. Clean batteries. Replace A/C Filter.

Comment

Parts # B329 Qty (1) Oil 10W30 Qty (6.5) Qt

Activity: 5

999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT SW - Shop Work Order

Down Time

Reason for Repair: Work Accomplished: 06 - Inspect

Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date Part Number Description

Qty. Each Extended

Labor Posted

Date

Technician

Hours

Rate

Extended

Activity 5 Sub Total

Parts: Labor:

0.00 0.00

Labor Hours: 0.00 Sublet Parts: Sublet Labor:

0.00 0.00

Activity Sub Total

0.00

Activity: 10

999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -**Part Failure:**

Activity Comments

Parts Issued

Qty. Each Extended Date Part Number Description



55345 Palm Tran Connection v 2.2 Page 1 of 11



WorkOrder: 53677260 Invoice Number: 55345-53677260

Client Department:

MRC: WO Desc: 55345M

Equipment:

5404

Ford E350 Champion Crusaders

VIN:

1FDEE3FL2FDA02758

Requested By: Created By:

PMA SERVICE

TDELVA TDELVA WO

No

Status: **Priority: Driver:**

40 3

Class: **Arrangement: Potential Warranty:**

Unassigned

Phone: ETA:

Chronology

Reported Started Completed Aug 26, 2020 Aug 26, 2020 Aug 27, 2020

12:26 AM

12:00 AM

UOM Meter Reading WO DH Life 287,751 DH

Down Time

WorkOrder Notes

	Line	Comment				
	10	COMPLAINT:PMA				
CAUSE: service		CAUSE: service				
		CORRECTION: perform PMA service				

Oil filter B329 qty1 Engine oil 10w30 qty 7 qts

Activity: 5

999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT SW - Shop Work Order

Reason for Repair: Work Accomplished: 06 - Inspect

Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date Part Number Description

Qty. Each Extended

Labor Posted

Date

Technician

Parts:

Hours

Rate

Extended

Activity 5 Sub Total

0.00 0.00

Labor: Labor Hours: 0.00

Sublet Parts: Sublet Labor: 0.00 0.00

Activity Sub Total

0.00

Activity: 10

999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -**Part Failure:**

Activity Comments

Parts Issued

Qty. Each Extended Date Part Number Description



55345 Palm Tran Connection v 2.2 Page 1 of 10



WorkOrder: 53558533 **Invoice Number:** 55345-53558533

UOM

Client Department:

MRC: WO Desc:

Started

10

Completed

55345M

Equipment:

5404

Ford E350 Champion Crusaders

Meter

VIN:

1FDEE3FL2FDA02758 40

55345-LIGHT DUTY PMA **Requested By: Created By:** Class:

NSTOLFO **NSTOLFO** WO

Status: **Priority: Driver:**

3

Arrangement: Potential Warranty:

Unassigned No

Phone: ETA:

Chronology Reported

Jul 6, 2020 Jul 7, 2020 Jul 7, 2020 12:00 AM 12:31 PM

WO DH Life 283,470 DH System 283,470 DH

Reading

Down Time

WorkOrder Notes

Line Comment

COMPLAINT: PMA CAUSE: service due

CORRECTION: Performed and completed PMA

Activity: 5

999/999/999 TOTAL VEHICLE

PERSONAL RISK ASSESSMENT **Activity Note:**

Reason for Repair: SW - Shop Work Order Work Accomplished: 06 - Inspect

Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Part Number Date

Description

Each Extended

Rate

Extended

Labor Posted

Date Technician

Activity 5 Sub Total

Hours

Parts: Labor:

Labor Hours: 0.00 Sublet Parts:

Sublet Labor:

0.00 0.00

0.00

0.00

Activity Sub Total

0.00

Activity: 10

999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -**Part Failure:**

Activity Comments

Parts Issued

Date Each Extended Part Number Description



55345 Palm Tran Connection v 2.2 Page 1 of 9



WorkOrder: 53246506 **Invoice Number:** 55345-53246506

Client Department:

MRC: **Equipment:** 55345M

5404 Ford E350 Champion Crusaders

WO Desc: PM A VIN:

1FDEE3FL2FDA02758

Requested By: JUHURST Status: 40 **Created By: JUHURST Priority:** 1

Class: WO **Driver: Arrangement:** Phone: Unassigned **Potential Warranty:** ETA: No

Chronology						
Reported Mar 9, 2020 2:55						
Started						
Completed	Mar 9, 2020	3:38 PM				
Down Time						

Meter	Reading	UOM
WO		DH
Life	274,953	DH
System	275,057	DH

WorkOrder Notes

	Line	Comment
ĺ	10	COMPLAINT: PMA SERVICE
		CAUSE: PREVENTIVE MAINTENANCE
		CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity: 10 999/999/999 TOTAL VEHICLE **Activity Note:** Light Duty PMI

08 - Preventive Maintenance Reason for Repair:

Work Accomplished: -Part Failure:

Activity Comments

Parts Issued

Date Part Number Qty. Each Extended Description

Labor Posted

Date Technician Rate Extended Hours

Activity 10 Sub Total

Parts: 0.00 Labor: 0.00

Labor Hours: 0.00 Sublet Parts: 0.00 Sublet Labor: 0.00 0.00

Activity Sub Total

Activity: 20

999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
09-Mar-20	B329(F)	FILTER, OIL, SPIN-ON	1.00	1.96	1.96



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 53146949 **Invoice Number:** 55345-53146949

Client Department:

MRC:

55345M

Equipment:

5404

WO Desc:

PM A

VIN:

Ford E350 Champion Crusaders

1FDEE3FL2FDA02758

Requested By: Created By:

RAURODRIGUEZ RAURODRIGUEZ Status: **Priority:**

40 1

Class:

WO

Driver:

Arrangement: **Potential Warranty:** Unassigned No

Phone: ETA:

Down Time		
Completed	Feb 3, 2020	7:51 PM
Started	Feb 3, 2020	
Reported	Feb 3, 2020	1:30 PM
C	hronology	

Meter	Reading	UOM
wo		DH
Life	270,738	DH

WorkOrder Notes

Line Comment 10 COMPLAINT: Vehicle came in for service CAUSE: time for the pm. Service

CORRECTION: Pm. A service complete after return vehicle back to work Oil on filter replace

Activity: 10

999/999/999 TOTAL VEHICLE

Activity Note:

Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -Part Failure:

Activity Comments

Parts Issued

Date Part Nu	ımber	Description	Qty. Each Extended

Labor Posted

	Date	Technician	Hours	Rate	Extended
	03-Feb-20	Junior Hurst	1.60	0.00	0.00
5					and the second second second second

Activity 10 Sub Total

Parts: 0.00 Labor: 0.00 Labor Hours: 1.60 Sublet Parts: 0.00 Sublet Labor: 0.00 0.00

Activity Sub Total

Activity: 20 **Activity Note:**

999 TOTAL VEHICLE

Reason for Repair:

PM A

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

ŧ	herman en aranten en en en en aranten aranten en e	hina salata katamata kata kata karanta aranta karanta kata kata karanta kereba	in expression of the control of the	× · · · · · · · · · · · · · · · · · · ·	1
ì	03-Feb-20	B329(F)	FILTER, OIL	1.00 1.96 1.96	
	Date	Part Number		Description Qty. Each Extended	




55345 Palm Tran Connection v 2.2

Page 1 of 9

VIN:

ETA:

11:20 PM



WorkOrder: 52977405 **Invoice Number:** 55345-52977405

Client Department:

MRC:

55345M

Equipment:

5404

Ford E350 Champion Crusaders

WO Desc: PM A

1FDEE3FL2FDA02758 40 1

Requested By: Created By:

DKNOTT **DKNOTT** Status: **Priority: Driver:**

Class:

Completed

WO Unassigned

Arrangement: Potential Warranty:

No

Phone:

Reported	hronology Dec 6, 2019	11:37 AM
Started	Dec 6, 2019	,

Dec 6, 2019

Reading Meter UOM wo DH Life 262,413 DH

Down Time

WorkOrder Notes

Comment

Line 10 COMPLAINT: PMA Service

CAUSE: Service due by Mileage.

CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Remove all wheel & check b,rakes .Replace. Drain plugs. Patch & Balance L/R inner tire and replace on L/R inner.

Parts # B329 Qty (1) Parts# 65266 Qty (1) Oil 5W20 Qty (1)

Activity: 10

999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Number	Descriptio	n Oty, Each Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
06-Dec-19	Arthurs,Durvin	2,42	65.00	157.08
06-Dec-19	Arthurs, Durvin	0.08	65.00	5.42

Activity 10 Sub Total

Parts: 0.00 162.50 Labor: Labor Hours: 2.50

Sublet Parts: 0.00 Sublet Labor: 0.00 Activity Sub Total 162.50

Activity: 20

999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52877382 **Invoice Number:** 55345-52877382

Client Department:

MRC: WO Desc: 55345M

Equipment:

5404

1

Ford E350 Champion Crusaders

PM A

VIN: Status:

ETA:

1FDEE3FL2FDA02758 40

Requested By: Created By:

RGASPARD RGASPARD WO

Priority: Driver:

Class: **Arrangement: Potential Warranty:**

Unassigned No

Phone:

	Chronology	
Reported	Nov 6, 2019	7:55 AM
Started	, ·	
Completed	Nov 7, 2019	11:55 AM

Comment

Meter	Reading	MOU
wo		DH
Life	258,056	DH
System	258,056	DH

WorkOrder Notes

Line 10

COMPLAINT: pmA

CAUSE: preventive maintenance

CORRECTION: perform pmA service lube all Pivoting Points Cross Rotate Tires Completed

Activity: 10

999 TOTAL VEHICLE

Down Time

Activity Note: Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Number Description Oty, Each Extended

Labor Posted

Date Technician Hours Extended

Activity 10 Sub Total

Parts: Labor: 0.00 0.00

Labor Hours: 0.00

Sublet Parts: Sublet Labor:

0.00 0.00

Activity Sub Total

0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note: Reason for Repair:

PM A

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Date	Part Number	Description	Qty.	Each	Extended
07-Nov-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96
07-Nov-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52674519 **Invoice Number:** 55345-52674519

Client Department:

MRC: WO Desc:

Started

Completed

55345M

Equipment:

5404

Ford E350 Champion Crusaders

1FDEE3FL2FDA02758

PM A Requested By:

VAMRITTEEMAL

Status:

Created By: Class:

VAMRITTEEMAL WO

Priority: Driver:

40 1

Arrangement: Potential Warranty:

Unassigned No

Phone: ETA:

VIN:

Chronology Reported

Sep 10, 2019 Sep 10, 2019 Sep 10, 2019 10:32 AM 10:03 PM

Reading UOM Meter WO DH Life DH 248,931

Down Time

WorkOrder Notes

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMA SERVICE REPLACED AIR FILTER

REPLACED DRAIN PLUG

Activity: 10 **Activity Note:**

999 TOTAL VEHICLE Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Number	Description Qty. Each Extended

Labor Posted

Date	Technician	ŀ	lours	Rate	Extended	
10-Sep-19	AMRIT TEEMAL,VISHNU		1.50	65.00	97.50	

Activity 10 Sub Total

Parts: 0.00 Labor: 97.50 Labor Hours: 1.50

Sublet Parts: Sublet Labor:

0.00 00.0

Activity Sub Total

97.50

Activity: 20

999 TOTAL VEHICLE

Activity Note:

PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

	Date 10 Car 10	Part Number	CV TC0 410 040C0	Description	Qty. Each Extended	
	10-Sep-19	PA4075	FILTER, AIR, PAPER	SAME AS AF25590	1,00 5,28 5,28	1
1						



55345 Palm Tran Connection v 2.2 Page 1 of 9



WorkOrder: 52591585 **Invoice Number: 55345-52591585**

Client Department:

MRC: WO Desc:

PM A

55345M

Equipment:

5404

Ford E350 Champion Crusaders

1FDEE3FL2FDA02758

Requested By: Created By:

Completed

RRENE RRENE WO

Status: **Priority:**

VIN:

40 1

Class: Arrangement: **Potential Warranty:**

Unassigned No

Driver: Phone:

ETA:

1	Started	Aum O DOSO
		Aug 8, 2019
	Reported	
i		Chronology

Aug 8, 2019 Aug 8, 2019 11:51 AM 10:54 PM

Meter Reading UOM wo DH Life 244,555 DH

Down Time

WorkOrder Notes

Line Comment 10 COMPLAINT: PMA SERVICE

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity: 10 **Activity Note:**

999 TOTAL VEHICLE Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Nu	umber	Description Oby, Each Extended
		Description QDy. Each Extended

Labor Posted

Date	Technician	u	ours	Deta	F
08-Aug-19	AMRIT TEEMAL, VISHNU	,,,	vuis	Rate	Extended
	TO THAT TELETHIC YAU (RV)		1.50	65.00	97.50

Activity 10 Sub Total

Parts:

Labor:

0.00 97.50

Labor Hours: 1.50 Sublet Parts: Sublet Labor:

0.00 0.00

Activity Sub Total

97.50

Activity: 20

999 TOTAL VEHICLE

Activity Note: Reason for Repair:

PM A

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

<u> </u>	ate	Part No	umber			Description		Qty.	Each	Extended
08-A	ug-19	B329(F)		FILTER, OII	SAME AS LF368	1				
					- ONINE NO EI JUU		one or a first some and the following	1.00	1.96	1.96



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52414544 Invoice Number: 55345-52414544

Client Department:

MRC: WO Desc:

PM A

10

55345M

WO

Equipment:

5404

40

1

Ford E350 Champion Crusaders

VIN:

1FDEE3FL2FDA02758

Requested By: Created By:

DARTHURS DARTHURS Status: **Priority:** Driver:

Class: Arrangement: **Potential Warranty:**

Unassigned No

Phone: ETA:

Chronology Reported

Jun 6, 2019 Started Jun 6, 2019 Completed Jun 6, 2019

11:19 AM 10:19 PM

Meter Reading UOM WO DH Life 235,811 DΗ

Down Time

WorkOrder Notes

Line Comment COMPLAINT: PMA SERVICE

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity: 10

999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

1	Date Part N	Number	Description	Qty. Each Extended

Labor Posted

06-Jun-19 AMRIT TEEMAL, VISHNU 1.00 65.00 65.00	 Date	Technician	Hours	Rate I	Extended	indirectors.
	06-Jun-19	AMRIT TEEMAL, VISHNU	1.00	65.00	65.00	

Activity 10 Sub Total

Parts: Labor:

0.00 65.00

Labor Hours: 1.00

Sublet Parts: Sublet Labor:

0.00 0.00

65.00

Activity Sub Total

Activity: 20

999 TOTAL VEHICLE

Activity Note: PM A Reason for Repair:

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

	100 100	
06-Jun-19 B329(F) FILTER, OIL SAME AS LF3681	1.00 1.96	1.96



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52337164 Invoice Number: 55345-52337164

Client Department:

MRC: WO Desc:

PM A

55345M

Equipment:

5404 Ford E350 Champion Crusaders

1FDEE3FL2FDA02758

Requested By: Created By:

DARTHURS **DARTHURS** Status: **Priority:**

40 1

Class: **Arrangement:** WO Unassigned Driver: Phone:

Potential Warranty:

No

ETA:

VIN:

	Chronology	
Reported	May 8, 2019	12:00 AM
Started	May 8, 2019	1
Completed	May 9, 2019	12:28 AM

Comment

Meter	Reading	UOM
wo		DH
Life	231,528	DH
System	231,701	DH

WorkOrder Notes

Line 10

COMPLAINT: PMA Service

CAUSE: Service due by Mileage.

CORRECTION: Change Oil & Filter.lube all Pivoting Points. Check brakes. Clean batteries

Parts# B329 Qty (1) Oil 5W 20 Qty (6.5) Qt

Activity: 10

999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Down Time

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Number Description Extended

Labor Posted

Date	Technician	Hours	Rate E	xtended
	Arthurs,Durvin	1.50	65.00	97.50

Activity 10 Sub Total

Parts: Labor:

0.00 97.50

Labor Hours: 1.50 Sublet Parts:

0.00 0.00

Sublet Labor: **Activity Sub Total**

97,50

Activity: 20

999 TOTAL VEHICLE

Activity Note:

PM A

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Date	Part Number	Description	Qty. Each Ex	tended
08-May-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00 1.96	1.96



55345 Palm Tran Connection v 2.2

Page 1 of 9

VIN:

ETA:



WorkOrder: 52195752 **Invoice Number:** 55345-52195752

Client Department:

MRC: WO Desc:

Reported

Completed

Started

55345M

Equipment:

5404

Ford E350 Champion Crusaders

1FDEE3FL2FDA02758

PM A Requested By: **Created By:**

DARTHURS DARTHURS Status: **Priority:** 40

Class: **Arrangement:**

WO Unassigned

Driver: Phone: 1

Potential Warranty:

Chronology Mar 19, 2019 Mar 19, 2019 Mar 19, 2019

3:47 PM 10:52 PM

UOM Meter Reading WO DH Life 222,804 DH

Down Time

WorkOrder Notes

Line COMPLAINT: PMA Service CAUSE: Service due by Mileage.

CORRECTION: Change Oil & Filter, Lube all Pivoting Points. Check brakes. Clean batteries

Comment

Parts #; B329 Qty (1) Oil 5W 20 Qty (6.5) Qt

Activity: 10 **Activity Note:** Reason for Repair:

999 TOTAL VEHICLE Light Medium Duty PMI 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

	ate	Part Num		Description	Qty. Each Extended	

Labor Posted

Date	Technician		Hours	Rate	Extended
19-Mar-19	Arthurs, Durvin		1.50	0.00	0.00
		and and artigues for			

Activity 10 Sub Total

Parts: 0.00 Labor: 0.00 Labor Hours: 1.50 Sublet Parts: 0.00 Sublet Labor: 0.00 **Activity Sub Total** 0.00

Activity: 20 **Activity Note:**

999 TOTAL VEHICLE

Reason for Repair:

PM A

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Date	Part Number	Description	Qty.	Each	Extended
19-Mar-19	B329	FILTER, OIL (FGA0000399/FSC0000399)	1.00	1.96	1.96



55345 Palm Tran Connection v 2.2

Page 1 of 9

VIN:



WorkOrder: 52114817 **Invoice Number:** 55345-52114817

Client Department:

MRC: WO Desc: 55345M

Equipment:

5404

Ford E350 Champion Crusaders 1FDEE3FL2FDA02758

PM A Requested By:

RGASPARD

40

Created By:

RGASPARD WO

Status: Priority:

1

Class: Arrangement: **Potential Warranty:**

Unassigned No

Driver: Phone:

Chronology

ETA:

Reported Feb 22, 2019 Started

Down Time

Feb 22, 2019 Feb 23, 2019 12:23 PM

12:02 AM

wo		L
Life	218,655	
System	218,787	

Reading

MOU

DΗ

DH

DH

Meter

WorkOrder Notes

Line

Completed

COMPLAINT: PMA Service.

CAUSE: Service due by Mileage.

CORRECTION: Change Oil & Filter. Lube all Pivoting Points, Check brakes. Clean Batteries

Comment

Parts# B329 Oty (1) Oil 5W20 Qty (6.5) Qt

Activity: 10 **Activity Note:** 999 TOTAL VEHICLE

Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Number Description

Each Extended

Labor Posted

Date	Technician		Hours	Rate	Extended
22-Feb-19	Arthurs, Durvin	-	1.50	0.00	0.00

Activity 10 Sub Total

Parts: Labor: 0.00 0.00

Labor Hours: 1.50 Sublet Parts:

0.00

Sublet Labor:

0.00

Activity Sub Total

0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note: Reason for Repair:

PM A

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Contract of	Date	Part Number			Description		Qty. Each Ex	tended
	22-Feb-19	B329	FILTER,	OIL (FGA0000399/FS0	(0000399)	A CANADA	1.00 1.96	1.96



55345 Palm Tran Connection v 2.2 Page 1 of 9



WorkOrder: 51950236 Invoice Number: 55345-51950236

Client Department:

MRC: WO Desc: 55345M

Equipment:

5404

5404

Ford E350 Champion Crusaders

Reading

210,480

210,615

UOM

DH

DH

DH

PM A Requested By:

Line

VAMRITTEEMAL VAMRITTEEMAL VIN: Status: 1FDEE3FL2FDA02758 40 1

10:24 PM

Created By: Class:

VAN WO

Priority: Driver:

Arrangement: Potential Warranty:

Unassigned No Phone: ETA:

	Mete
11:42 AM	wo
40.04.04	Life

System

| Chronology | Dec 31, 2018 | Started | Dec 31, 2018 | Completed | Dec 31, 2018 |

Down Time

Comment

WorkOrder Notes

10	COMPLAINT: PMA Service
	CAUSE: Preventive Maintenance

CORRECTION: perform and completed PMA Service

Activity: 10

999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Number Description Qty. Each Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
31-Dec-18	AMRIT TEEMAL, VISHNU	1.50	0.00	0.00

Activity 10 Sub Total

Parts: Labor: 0.00 0.00

Labor Hours: 1.50 Sublet Parts: Sublet Labor:

0.00

Activity Sub Total

0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note:

PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Date	Part Number	Description	Qty.	Each	Extended
31-Dec-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



55345 Palm Tran Connection v 2.2Page 1 of 9

WorkOrder: 51870040 **Invoice Number:** 55345-51870040

Client Department:

MRC: WO Desc:

PM A

Class:

Reported

Completed

Started

55345M

Equipment:

5404

Ford E350 Champion Crusaders

1FDEE3FL2FDA02758

Requested By: Created By:

Arrangement:

VIN: **DARTHURS** Status: **DARTHURS**

Priority:

Driver:

40 1

2:40 PM

10:43 PM

Potential Warranty:

Unassigned No

Chronology

Nov 29, 2018

Nov 29, 2018

Nov 29, 2018

WO

Phone: ETA:

Meter	Reading	UOM
wo		DH
Life	206,020	DH

Down Time

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service
	CAUSE: Preventive Maintenance
	CORRECTION: Performed and completed PMA

Activity: 10 **Activity Note:**

999 TOTAL VEHICLE

Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Number

Description

Qty. Each Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
29-Nov-18	AMRIT TEEMAL, VISHNU	1.50	0.00	0.00

Activity 10 Sub Total

Parts: Labor: 0.00 0.00

Labor Hours: 1.50 Sublet Parts: Sublet Labor:

0.00 0.00

Activity Sub Total

0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note: Reason for Repair:

PM A

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Date	Part Number	Description	Qty.	Each	Extended
29-Nov-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



55345 Palm Tran Connection v 2.2 Page 1 of 9



WorkOrder: 51706697 **Invoice Number: 55345-51706697**

MOU

Client Department:

MRC: WO Desc: 55345M

Equipment:

5404

Started

Completed

Ford E350 Champion Crusaders

PM A Requested By:

RGASPARD

VIN: Status:

Phone:

ETA:

1FDEE3FL2FDA02758 40

Created By: Class:

RGASPARD WO

Priority: Driver:

Arrangement: Potential Warranty: Unassigned No

1

Chronology Reported

Oct 5, 2018 Oct 5, 2018 Oct 5, 2018 11:19 AM 10:53 PM

Reading WO DΗ Life 197,735 DH

Meter

Down Time

Line Comment

CAUSE: preventive maintenance

COMPLAINT: PMA Service

CORRECTION: performed and completed PMA Service Part# 8329 Oty1

WorkOrder Notes

Activity: 10 **Activity Note:** Reason for Repair:

999 TOTAL VEHICLE Light Medium Duty PMI 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Number Description

Labor Posted

	Date 05-Oct-18	Technician Owens, Arthur	Hours 1.50	Rate 0.00	Extended 0.00
2.5					

Activity 10 Sub Total

Parts: 0.00 Labor: 0.00 Labor Hours: 1.50

Sublet Parts: 0.00 Sublet Labor: 0.00

Activity Sub Total

0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note:

PM A

08 - Preventive Maintenance

Reason for Repair: Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Date	Part Nu	nber Description	Qty. Each E	xtended
05-Oct-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00 1.96	1.96



55345 Palm Tran Connection v 2.2 Page 1 of 9



WorkOrder: 51626586 Invoice Number: 55345-51626586

Client Department:

MRC: WO Desc:

55345M

Equipment:

5404

PM A Requested By:

Reported

Completed

Started

RGASPARD RGASPARD

No

VIN: Status:

1FDEE3FL2FDA02758 40

Ford E350 Champion Crusaders

Created By: Class: Arrangement:

WO Unassigned Priority: Driver: Phone:

ETA:

1

Potential Warranty:

Chronology Sep 10, 2018 Sep 10, 2018

Sep 10, 2018

3:15 PM 11:56 PM

Meter Reading UOM wo DH Life 193,606 DH 193,788 DH System

Down Time

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA
	CAUSE:Service
	CORRECTION:Perform pmA Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 **Activity Note:**

999 TOTAL VEHICLE Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Number Description Qty. Each Extended

Labor Posted

Date	Technician	0.000	Hours	Rate Ext	tended
10-Sep-18	Gaspard,Ronald		1.58	0.00	0.00

Activity 10 Sub Total

Parts: Labor:

0.00 0.00

Labor Hours: 1.58 Sublet Parts: Sublet Labor:

0.00 0.00

Activity Sub Total

0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Date	Part Number	Description	Qty, Each Exte	ended
10-Sep-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00 1.96	1.96



55345 Palm Tran Connection v 2.2 Page 1 of 9



WorkOrder: **51447128 Invoice Number:** 55345-51447128

Client Department:

MRC: WO Desc:

PM A

55345M

Equipment:

5404

Ford E350 Champion Crusaders

1FDEE3FL2FDA02758

Requested By: Created By: DARTHURS DARTHURS Status: Priority:

VIN:

40

Class:

WO Unassigned Driver: Phone: 1

Arrangement: Potential Warranty:

No

ETA:

	Chronology
Reported	Jul 17,

 Reported
 Jul 17, 2018

 Started
 Jul 18, 2018

 Completed
 Jul 18, 2018

 Down Time

8:06 AM | Meter | Reading | UOM | WO | DH |
7:58 AM | Life | 185,205 | DH |
System | 185,319 | DH |

WorkOrder Notes

Line 10

COMPLAINT:PmA

CAUSE: preventive maintenance

CORRECTION:perform PmA Service Lube all Pivoting Points cross Rotate Tires completed

Comment

Activity: 10

999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Number Description Qty. Each Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
18-Jul-18	Pierre, Hubert J	6.00	0.00	0.00

Activity 10 Sub Total

Parts: Labor: 0.00

Labor Hours: 6.00 Sublet Parts: Sublet Labor:

0.00

Activity Sub Total

0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note: Reason for Repair:

PM A

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

10 Jul 10 P320(5)		
18-Jul-18 B329(F) FILTER, OIL SAME AS LF3681 1.00	FILTER, OIL SAME AS LF3681 1.00 1.96	1,96



55345 Palm Tran Connection v 2.2 Page 1 of 9



WorkOrder: **51369428 Invoice Number:** 55345-51369428

Client Department:

MRC: 55345M **Equipment:** 5404

WO Desc: Ford E350 Champion Crusaders PM A VIN: 1FDE3FL2FDA02758

Requested By: CKARLENS Status: 40
Created By: CKARLENS Priority: 1

Created By:CKARLENSPriority:Class:WODriver:Arrangement:UnassignedPhone:Potential Warranty:NoETA:

Chronology					
Reported	Jun 20, 2018	11:32 AM			
Started	Jun 20, 2018				
Completed	Jun 21, 2018	12:10 AM			
Down Tin					

Meter	Reading	UOM
WO		DH
Life	181,325	DH
System	181,508	DH

WorkOrder Notes

Line	Comment		
10	COMPLAINT: PMA Service		
	CAUSE: Service due by Mileage		
	CORRECTION: Change Oil & Filter. lube all Pivoting Points. Check brakes. Clean Batteries.replace A/C Filter.replace two lift harm stop rubber. Servi differential .was leaking.patch & balance.one tire & Replace on R/R Outer. Parts#8329 Qty (1) Parts# 32408 Qty (2) Oil 5W20 Qty (6.5) Qt Gear Oil 80W90 Qty (3) Qt		

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

	Date	Part Number	Description	Qty.	Each	Extended	ı
--	------	-------------	-------------	------	------	----------	---

Labor Posted

Date	Technician	Hours	Rate	Extended
20-Jun-18	Arthurs, Durvin	2.50	0.00	0.00

Activity 10 Su	b Total
Parts:	0.00
Labor:	0.00
Labor Hours: 2.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20 999 TOTAL VEHICLE ACTIVITY Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments



WorkOrder

55345 Palm Tran Connection v 2.2 Page 2 of 9



WorkOrder: 51369428 **Invoice Number:** 55345-51369428

Client Department:

MRC: **Equipment:** 5404 55345M

WO Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FL2FDA02758 PM A

Requested By: CKARI FNS Status: 40 **Created By: CKARLENS Priority:** 1

Class: WO **Driver: Arrangement:** Unassigned Phone: **Potential Warranty:** ETA: No

Date	Part Number	Description	Qty.	Each	Extended
20-Jun-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted

Date	Technician	Hours	Rate	Extended
20-Jun-18	Arthurs, Durvin	0.42	0.00	0.00

Activity 20 Sub Total Parts: 1.96 0.00 Labor: Labor Hours: 0.42 0.00 Sublet Parts: Sublet Labor: 0.00 1.96

Activity Sub Total

Activity: 30

999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 - Inspection, Routine

Work Accomplished: 06 - Inspect

Part Failure:

Activity Comments

Parts Issued

Labor Posted

Date	Technician	Hours	Rate	Extended
20-Jun-18	Arthurs, Durvin	0.08	0.00	0.00

	Activity 30 Sub Total
P	Parts: 0.00
L	.abor: 0.00
	Labor Hours: 0.08
S	Sublet Parts: 0.00
S	Sublet Labor: 0.00
A	Activity Sub Total 0.00

		0.00
	WorkOrder 51369428 Grand T	otal
	Parts:	1.96
	Labor:	0.00
	Labor Hours: 3.00	
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	WorkOrder Grand Total	1.96
Recent Repair History		



WorkOrder

55345 Palm Tran Connection v 2.2 Page 3 of 9



WorkOrder: 51369428 Invoice Number: 55345-51369428

Client Department:

MRC: 55345M **Equipment:** 5404

WO Desc: Ford E350 Champion Crusaders PM A VIN: 1FDEE3FL2FDA02758

Requested By:CKARLENSStatus:40Created By:CKARLENSPriority:1

Class: WO Driver: Arrangement: Unassigned Phone: Potential Warranty: No ETA:

WorkOrder	Date Completed	Life Meter	Class	Description
51369428	21-Jun-18	181,325	WO	PM A
51281954	23-May-18	177,264	WO	PM C

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life	Due Meter	Due Life	Due Meter	ı
				Meter	Reading	Meter 2	Reading 2	ı

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
51447046	20-Jun-18	181,325	WO	Rear. Tires
51369415	23-May-18	177,264	WO	FOLLOWUP¿¿-Replace front and rear brakes

PH: Work Order: 51369428 Desc: PM A

Equip: 5404 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FL2FDA02758

LH: 10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 20-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Jun 20, 2018 11:22:26 PM	No	
10,100	Safety Inspection	Done		DARTHURS	Jun 20, 2018 11:22:26 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jun 20, 2018 11:22:27 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		DARTHURS	Jun 20, 2018 11:22:26 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Jun 20, 2018 11:22:27 PM	No	
10,140	Check Service Brakes	Done		DARTHURS	Jun 20, 2018 11:22:27 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Jun 20, 2018 11:22:27 PM	No	
10,160	FRA Check Instruments and Horns	Done		DARTHURS	Jun 20, 2018 11:22:27 PM	No	
10,170	Check Fast Idle	Done		DARTHURS	Jun 20, 2018 11:22:27 PM	No	
10,180	Check Starter Protection Circuit	Done		DARTHURS	Jun 20, 2018 11:22:27 PM	No	
10,190	Check Reverse Warning System	Done		DARTHURS	Jun 20, 2018 11:22:28 PM	No	
11,100	Check Parking Brake	Done		DARTHURS	Jun 20, 2018 11:22:27 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		DARTHURS	Jun 20, 2018 11:22:28 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Jun 20, 2018 11:22:28 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		DARTHURS	Jun 20, 2018 11:22:28 PM	No	
11,140	Road Test: Check for Proper Operation	Done		DARTHURS	Jun 20, 2018 11:22:28 PM	No	
11,150	Perform Brake Test	Done		DARTHURS	Jun 20, 2018 11:22:28 PM	No	
11,152	Decelerometer Results Test 1	FEET	NA	DARTHURS	Jun 20, 2018 11:22:28 PM	No	
11,154	Decelerometer Results Test 2	FEET	NA	DARTHURS	Jun 20, 2018 11:22:29 PM	No	
11,156	Decelerometer Results Test 3	FEET	NA	DARTHURS	Jun 20, 2018 11:22:28 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Jun 20, 2018 11:22:29 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Jun 20, 2018 11:22:29 PM	No	
11,170	FRA Check Door Operation	Done		DARTHURS	Jun 20, 2018 11:22:29 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		DARTHURS	Jun 20, 2018 11:22:29 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		DARTHURS	Jun 20, 2018 11:22:29 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		DARTHURS	Jun 20, 2018 11:22:29 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		DARTHURS	Jun 20, 2018 11:22:29 PM	No	
20,230	FRA Check Wiring Under Dash	Done		DARTHURS	Jun 20, 2018 11:22:29 PM	No	
20,240	FRA Check Interior Lights	Done		DARTHURS	Jun 20, 2018 11:22:30 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		DARTHURS	Jun 20, 2018 11:22:29 PM	No	
20,260	Check Stop Request System	-	NA	DARTHURS	Jun 20, 2018 11:22:30 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Jun 20, 2018 11:22:30 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Jun 20, 2018 11:22:30 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Jun 20, 2018 11:22:30 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		DARTHURS	Jun 20, 2018 11:22:30 PM	No	
22,110	Check Emergency Hatches	Done		DARTHURS	Jun 20, 2018 11:22:30 PM	No	
22,120	Check All Safety Equipment	Done		DARTHURS	Jun 20, 2018 11:22:30 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Jun 20, 2018 11:22:30 PM	No	
30,310	Check Passenger Doors	Done		DARTHURS	Jun 20, 2018 11:22:30 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		DARTHURS	Jun 20, 2018 11:22:31 PM	No	
30,330	Check Wheelchair Lift Operation	Done		DARTHURS	Jun 20, 2018 11:22:31 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Jun 20, 2018 11:22:31 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		DARTHURS	Jun 20, 2018 11:22:31 PM	No	
30,360	Check for Physical Damage and Decals	Done		DARTHURS	Jun 20, 2018 11:22:31 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		DARTHURS	Jun 20, 2018 11:22:31 PM	No	
30,380	Check Exterior Compartment Doors	Done		DARTHURS	Jun 20, 2018 11:22:31 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		DARTHURS	Jun 20, 2018 11:22:31 PM	No	
33,100	Check Lights and Reflectors	Done		DARTHURS	Jun 20, 2018 11:22:32 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Jun 20, 2018 11:22:32 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Jun 20, 2018 11:22:32 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Jun 20, 2018 11:22:32 PM	No	
40,420	Check Hood	Done		DARTHURS	Jun 20, 2018 11:22:32 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		DARTHURS	Jun 20, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:22:32 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Jun 20, 2018 11:22:32 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Jun 20, 2018 11:22:32 PM	No	
40,442	Freeze Point	Degree Fahrenheit	NA	DARTHURS	Jun 20, 2018 11:22:32 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Jun 20, 2018 11:22:32 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Jun 20, 2018 11:22:33 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Jun 20, 2018 11:22:33 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Jun 20, 2018 11:22:33 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		DARTHURS	Jun 20, 2018 11:22:33 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		DARTHURS	Jun 20, 2018 11:22:33 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Jun 20, 2018 11:22:33 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Jun 20, 2018 11:22:33 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Jun 20, 2018 11:22:33 PM	No	
44,130	FRA Check Exhaust System	Done		DARTHURS	Jun 20, 2018 11:22:33 PM	No	
44,140	FRA Check Intake System	Done		DARTHURS	Jun 20, 2018 11:22:33 PM	No	
44,150	FRA Inspect Turbocharger	-	NA	DARTHURS	Jun 20, 2018 11:22:34 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Jun 20, 2018 11:22:34 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Jun 20, 2018 11:22:34 PM	No	
44,180	FRA Check for Leaks	Done		DARTHURS	Jun 20, 2018 11:22:34 PM	No	
44,190	FRA Perform Battery Inspection	Done		DARTHURS	Jun 20, 2018 11:22:34 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Jun 20, 2018 11:22:34 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		DARTHURS	Jun 20, 2018 11:22:35 PM	No	
50,510	Check Entire Steering System	Done		DARTHURS	Jun 20, 2018 11:22:34 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Jun 20, 2018 11:22:35 PM	No	
60,610	FRA Check and Record Air Pressure	Done		DARTHURS	Jun 20, 2018 11:22:35 PM	No	
60,611	Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Jun 20, 2018 11:22:35 PM	No	
60,612	Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Jun 20, 2018 11:22:35 PM	No	
60,613	Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Jun 20, 2018 11:22:35 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Jun 20, 2018 11:22:35 PM	No	
60,615	Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Jun 20, 2018 11:26:37 PM	No	
60,616	Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Jun 20, 2018 11:26:37 PM	No	
60,620	Check Valve Stems and Caps	Done		DARTHURS	Jun 20, 2018 11:26:37 PM	No	
60,630	Check and Record Tread Depth	Done		DARTHURS	Jun 20, 2018 11:26:37 PM	No	
60,631	Tread Depth RF	8 32nds of an inch		DARTHURS	Jun 20, 2018 11:26:38 PM	No	
60,632	Tread Depth LF	8 32nds of an inch		DARTHURS	Jun 20, 2018 11:26:38 PM	No	
60,633	Tread Depth RRO	3 32nds of an inch		DARTHURS	Jun 20, 2018 11:26:38 PM	No	
60,634	Tread Depth RRI	5 32nds of an inch		DARTHURS	Jun 20, 2018 11:26:38 PM	No	
60,635	Tread Depth LRI	5 32nds of an inch		DARTHURS	Jun 20, 2018 11:26:38 PM	No	
60,636	Tread Depth LRO	6 32nds of an inch		DARTHURS	Jun 20, 2018 11:26:38 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		DARTHURS	Jun 20, 2018 11:26:38 PM	No	
60,650	Check Sidewall Wear	Done		DARTHURS	Jun 20, 2018 11:26:38 PM	No	
60,660	Inspect for Cuts and Tears	Done		DARTHURS	Jun 20, 2018 11:26:39 PM	No	
60,670	Check Dual Mating With Square	-	NA	DARTHURS	Jun 20, 2018 11:26:39 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Jun 20, 2018 11:26:39 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Jun 20, 2018 11:26:39 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		DARTHURS	Jun 20, 2018 11:26:39 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Jun 20, 2018 11:26:39 PM	No	
70,710	Check Vibration Damper	Done		DARTHURS	Jun 20, 2018 11:26:39 PM	No	
70,720	Check Engine and Transmission Mounts	Done		DARTHURS	Jun 20, 2018 11:26:39 PM	No	
70,730	FRA Check Starter	Done		DARTHURS	Jun 20, 2018 11:26:39 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Jun 20, 2018 11:26:39 PM	No	
70,750	FRA Check Transmission for Leaks	Done		DARTHURS	Jun 20, 2018 11:26:40 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		DARTHURS	Jun 20, 2018 11:26:40 PM	No	
70,770	FRA Check Exhaust System	Done		DARTHURS	Jun 20, 2018 11:26:40 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Jun 20, 2018 11:26:40 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		DARTHURS	Jun 20, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:26:40 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Jun 20, 2018 11:26:40 PM	No	
77,110	FRA Check Fuel Tank	Done		DARTHURS	Jun 20, 2018 11:26:40 PM	No	
77,120	Check Suspension Components	Done		DARTHURS	Jun 20, 2018 11:26:40 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Jun 20, 2018 11:26:40 PM	No	
77,131	Brake Pad Thickness LF	11 Inch		DARTHURS	Jun 20, 2018 11:26:41 PM	No	
77,132	Brake Pad Thickness RF	11 Inch		DARTHURS	Jun 20, 2018 11:26:41 PM	No	
77,133	Brake Pad Thickness LR	7 Inch		DARTHURS	Jun 20, 2018 11:26:41 PM	No	
77,134	Brake Pad Thickness RR	7 Inch		DARTHURS	Jun 20, 2018 11:26:41 PM	No	
77,135	Brake Rotor LF	1.553 Inch		DARTHURS	Jun 20, 2018 11:26:41 PM	No	
77,136	Brake Rotor RF	1.554 Inch		DARTHURS	Jun 20, 2018 11:26:41 PM	No	
77,137	Brake Rotor LR	1.414 Inch		DARTHURS	Jun 20, 2018 11:26:41 PM	No	
77,138	Brake Rotor RR	1.415 Inch		DARTHURS	Jun 20, 2018 11:26:42 PM	No	
77,140	FRA Check Brake Hoses	Done		DARTHURS	Jun 20, 2018 11:26:42 PM	No	
77,150	Check King Pins	-	NA	DARTHURS	Jun 20, 2018 11:26:41 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Jun 20, 2018 11:26:42 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		DARTHURS	Jun 20, 2018 11:26:42 PM	No	
80,810	Completion of PMI Report	Done		DARTHURS	Jun 20, 2018 11:26:42 PM	No	
90,000	SECTION 9 Completion of PMI	Done		DARTHURS	Jun 20, 2018 11:26:42 PM	No	
90,910	Vehicle Returned to predetermined location	Done		DARTHURS	Jun 20, 2018 11:26:42 PM	No	

LH: 20 Desc: PM A

Task: PM A SERVICE Performed by: DARTHURS Performed on: 20-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		DARTHURS	Jun 20, 2018 11:28:01 PM	No	
101,000	FRA Change Oil Filters	Yes		DARTHURS	Jun 20, 2018 11:28:02 PM	No	
102,000	FRA Drain Engine Oil	Yes		DARTHURS	Jun 20, 2018 11:28:01 PM	No	
103,000	FRA Check Transmission Fluid	Done		DARTHURS	Jun 20, 2018 11:28:02 PM	No	
104,000	Lubricate Chassis	Done		DARTHURS	Jun 20, 2018 11:28:02 PM	No	
105,000	Replace or Clean A/C Filters	Done		DARTHURS	Jun 20, 2018 11:28:02 PM	No	
107,000	FRA Change Primary Fuel Filter	No	NA	DARTHURS	Jun 20, 2018 11:28:02 PM	No	
108,000	Lube all pivoting Mechanisms	Done		DARTHURS	Jun 20, 2018 11:28:02 PM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 20-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jun 20, 2018 11:28:31 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	



Ford Motor Company Ford Customer Service Division P. O. Box 1904 Dearborn, Michigan 48121-1904



771044361315

5482/000001093/000000006

սելիարիրի իրի հուրա ընդում և հետարի հուրա հետարի հուրա BOARD OF COUNTY COMMISSIONERS 301 N OLIVE AVE RM 206 WEST PALM BEACH, FL 33401-4700

March 2020

Customer Satisfaction Program 19B40

Your Vehicle Identification Number (VIN): See Listing

At Ford Motor Company, we are committed not only to building high quality, dependable products, but also to building a community of happy, satisfied customers. To demonstrate that commitment, we are providing a no-charge Customer Satisfaction Program for your vehicle with the VIN shown above.

Why are you receiving this notice?

On your vehicle, the single-engaging coast one-way clutch (OWC) inside the transmission may experience a weld concern.

What is the effect?

If this weld fails, it can affect the ability of the transmission to transfer torque to the wheels. If the weld failure occurs while the vehicle is moving, the vehicle will lose drive power, with all normal engine, braking and steering functionality, as if the transmission was shifted into neutral.

What will Ford and your dealer do?

If your E-Series is a shuttle bus and the <u>Primary Use</u> is transporting individuals with unique mobility issues (e.g. handicapped, physically disabled, limited mobility, young children requiring adult supervision, medical transport service), Ford Motor Company has authorized your dealer to replace the coast clutch cylinder and replace the single-engaging coast one-way clutch (OWC) with a dual-engaging OWC free of charge (parts and labor) under the terms of this program.

This Customer Satisfaction Program will be in effect until February 21, 2021 regardless of mileage. Coverage is automatically transferred to subsequent owners.

How long will it take?

The time needed for this repair is approximately one full day. However, due to service scheduling requirements, your dealer may need your vehicle for a longer period of time.

What should you do?

Please call your dealer without delay to schedule a service appointment for Customer Satisfaction Program 19B40. Provide the dealer with your VIN, which is printed near your name at the beginning of this letter.

If you do not already have a servicing dealer, you can access www.Fordowner.com for dealer addresses, maps, and driving instructions.

What should you do? (Continued)

Ford Motor Company wants you to have this service action completed on your vehicle. The vehicle owner is responsible for making arrangements to have the work completed. Ford Motor Company can deny coverage for any vehicle damage that may result from the failure to have this service action performed on a timely basis. Therefore, please have this service action performed as soon as possible.

NOTE: You can receive information about Recalls and Customer Satisfaction Programs through our FordPass App. The app can be downloaded through the App Store or Google Play. In addition there are other features such as reserving and paying for parking in certain locations and controlling certain functions on your vehicle (lock or unlock doors, remote start) if it is equipped to allow control.

Have you previously paid for this repair?

If you have previously paid for a repair that addresses the issue described in this letter, you may still need to have this service performed. Please contact your dealer to determine whether the updated parts were installed during the previous repair.

If the previously paid for repair was performed <u>before</u> the date of this letter, you may be eligible for a refund. Refunds will only be provided for service related to a 5R110W transmission coast clutch cylinder failure and one-way clutch replacement on shuttle bus vehicles equipped with a 5.4L Engine, which have a primary use to transport individuals with unique mobility issues such as the elderly or handicapped. To verify eligibility and <u>expedite</u> reimbursement, give your paid original receipt to your dealer before **February 21**, **2021**. To avoid delays, do not send receipts to Ford Motor Company.

What if you no longer own this vehicle?

If you no longer own this vehicle, and have an address for the current owner, please forward this letter to the new owner.

You received this notice because our records, which are based primarily on state registration and title data, indicate that you are the current owner.

Can we assist you further?

If you have difficulties getting your vehicle repaired promptly and without charge, please contact your dealership's Service Manager for assistance.

<u>RETAIL OWNERS</u>: If you have questions or concerns, please contact our <u>Ford Customer Relationship Center at 1-866-436-7332</u> and one of our representatives will be happy to assist you. If you wish to contact us through the Internet, our address is: <u>www.Fordowner.com</u>.

For the hearing impaired call 1-800-232-5952 (TDD). Representatives are available Monday through Friday: 8:00AM – 8:00PM (Eastern Time).

<u>FLEET OWNERS</u>: If you have questions or concerns, please contact our **Fleet Customer Information Center at 1-800-34-FLEET**, choose Option #3, and one of our representatives will be happy to assist you. If you wish to contact us through the Internet, our address is: www.fleet.ford.com.

Representatives are available Monday through Friday: 8:00AM - 8:00PM (Eastern Time).

Thank you for your attention to this important matter.

Ford Customer Service Division



Ford Motor Company División de Servicio al Cliente de Ford P. O. Box 1904 Dearborn, Michigan 48121



Marzo de 2020

Programa de satisfacción del cliente 19B40

Número de identificación del vehículo (VIN): Vea el listado

El compromiso de Ford Motor Company no es solo fabricar productos confiables y de alta calidad, sino también lograr la plena satisfacción del cliente. Para demostrar este compromiso, le ofrecemos el Programa de satisfacción del cliente sin costo alguno para su vehículo con el VIN que aparece más arriba.

¿Por qué usted recibe este aviso?

El embrague de un solo giro (OWC) de inercia de acoplamiento único en el interior de la transmisión de su vehículo podría experimentar un problema de soldadura.

¿Cuál es el efecto?

Si esta soldadura presenta problemas, la capacidad de la transmisión de transferir la torsión a las ruedas traseras podría verse afectada. Si la soldadura falla cuando el vehículo está en movimiento, este podría perder la potencia de impulsión, con todas las funciones del motor, frenado y dirección normales, como si la transmisión se cambiara a neutral.

¿Qué medidas adoptarán Ford y su distribuidor? Si su E-Series es un autobús de transporte y su <u>uso principal</u> es trasladar personas con problemas únicos de movilidad (por ejemplo, personas con discapacidad, impedimentos físicos, movilidad limitada, niños que requieren supervisión de un adulto, servicio de transporte médico), Ford Motor Company ha autorizado a su distribuidor a reemplazar el cilindro del embrague de inercia y reemplazar el embrague de un solo giro (OWC) de inercia de acoplamiento único con el OWC de acoplamiento doble, sin costo alguno (piezas y mano de obra), conforme a los términos de este programa.

Este Programa de satisfacción del cliente tendrá vigencia hasta el 21 de febrero de 2021, independientemente del millaje. La cobertura se transfiere automáticamente a los siguientes propietarios.

¿Cuánto tiempo tomará?

El tiempo necesario para realizar esta reparación es, aproximadamente, un día. Sin embargo, debido a los requisitos de planificación de servicio, es posible que su distribuidor tarde un poco más.

¿Qué debe hacer?

Llame a su distribuidor lo antes posible para que programe una cita de servicio para realizar el Programa de satisfacción del cliente 19B40. Proporcione el VIN a su distribuidor, el cual está impreso debajo de sus datos al comienzo de esta carta.

Si aún no tiene un distribuidor para realizar el servicio, puede acceder a www.Fordowner.com para conocer las direcciones de los distribuidores, ver mapas y obtener las instrucciones para llegar.

5484/000001093/000000006

© Copyright 2020 Ford, División de Servicio al Cliente

¿Qué debe hacer? (continuación)

Ford Motor Company le recomienda realizar esta acción de servicio en su vehículo. El propietario del vehículo es responsable de realizar los arreglos para llevar a cabo el trabajo. Ford Motor Company puede negar la cobertura en caso de que el vehículo hubiese sufrido daños por no haber realizado la acción de servicio de manera oportuna. Por lo tanto, le solicitamos que realice esta acción de servicio lo antes posible.

NOTA: puede recibir información sobre las campañas y los programas de satisfacción del cliente a través de la aplicación FordPass. La aplicación se puede descargar a través de App Store o Google Play. Adicionalmente, existen otras funciones, como reserva y pago de estacionamientos en ciertos lugares, además de control de ciertas funciones en el vehículo (bloqueo y desbloqueo de puertas, arranque remoto) si así está equipado para permitir el control.

¿Ha pagado anteriormente por esta reparación?

Si usted ha pagado previamente por la reparación que aborda el problema descrito en esta carta, igualmente debería realizar este servicio. Póngase en contacto con su distribuidor para determinar si las piezas actualizadas se instalaron durante la reparación previa.

Si el pago por esta reparación se efectuó <u>antes</u> de la fecha de esta carta, podrá solicitar un reembolso. Solo se otorgarán reembolsos por servicios relacionados con desperfectos del cilindro del embrague de inercia de la transmisión 5R110W y el reemplazo del embrague de un solo giro en autobuses de transporte equipados con motor 5.4L, cuyo uso principal sea trasladar personas con problemas únicos de movilidad, como ancianos o discapacitados. Para comprobar si cumple con los requisitos y <u>agilizar el reembolso</u>, entregue el recibo de pago original a su distribuidor antes del **21 de febrero de 2021**. Para evitar demoras, no envíe los recibos a Ford Motor Company.

¿Qué pasa si usted ya no es el propietario del vehículo?

Si usted ya no es el propietario del vehículo y tiene la dirección del propietario actual, le solicitamos que le reenvíe esta carta.

Este aviso lo recibió porque en nuestros archivos, basados principalmente en datos de registro y propiedad de los EE. UU., aparece usted como el propietario actual.

¿Podemos hacer algo más por usted?

Si tiene problemas para reparar de inmediato su vehículo y sin costo alguno, comuníquese con el gerente de servicio de su distribuidor para solicitar ayuda.

PROPIETARIOS MINORISTAS: Si tiene dudas o preguntas, comuníquese con nuestro Centro de Relación con Clientes Ford al 1-866-436-7332 y uno de nuestros representantes con gusto lo atenderá. Si desea comunicarse con nosotros a través de Internet, nuestra dirección es: www.Fordowner.com.

Las personas con problemas de audición pueden llamar al 1-800-232-5952 (TDD). Los representantes atienden de lunes a viernes, 8:00 a.m. a 8:00 p.m. (hora del este).

PROPIETARIOS DE FLOTAS: Si tiene dudas o preguntas, comuníquese con nuestro Centro de Información a Clientes de flotas al 1-800-34-FLEET, elija la opción n.° 3 y uno de nuestros representantes con gusto lo atenderá. Si desea comunicarse con nosotros a través de Internet, nuestra dirección es: www.fleet.ford.com.

Los representantes atienden de lunes a viernes, 8:00 a.m. a 8:00 p.m. (hora del este).

Gracias por su atención en este asunto sumamente importante.

Ford, División de Servicio al Cliente



BOARD OF COUNTY COMMISSIONERS 301 N OLIVE AVE RM 206 WEST PALM BEACH, FL 33401-4700

1	1FDEE3FLXFDA00708	2015 E-350 Econoline 5/16
2	1FDEE3FL0FDA00698	2015 E-350 Econoline 5106
3	1FDEE3FL0FDA02970	2015 E-350 Econoline 5 2 3
4	1FDEE3FL0FDA02760	2015 E-350 Econoline 5406
5	1FDEE3FL0FDA06811	2015 E-350 Econoline 5422
6	1FDEE3FL0FDA04217	2015 E-350 Econoline 5407
7	1FDEE3FL0FDA04220	2015 E-350 Econoline 5408 Retires
8	1FDEE3FL1FDA00712	2015 E-350 Econoline 5120
9	1FDEE3FL1FDA00709	2015 E-350 Econoline 5 (17)
10	1FDEE3FL2FDA00699	2015 E-350 Econoline 5101
11	1FDEE3FL2FDA02968	2015 E-350 Econoline 5 2
12	1FDEE3FL2FDA02758	2015 E-350 Econoline 5404
13	1FDEE3FL2FDA06812	2015 E-350 Econoline 54 1 3
14	1FDEE3FL2FDA06809	2015 E-350 Econoline 5 4 1 2
15	1FDEE3FL3FDA02977	2015 E-350 Econoline 5 3 ©
16	1FDEE3FL3FDA02980	2015 E-350 Econoline 51 33 Retire
17	1FDEE3FL3FDA00694	2015 E-350 Econoline 5 1 0 2
18	1FDEE3FL4FDA00705	2015 E-350 Econoline 5 (1 3
19	1FDEE3FL4FDA02759	2015 E-350 Econoline 5'402
20	1FDEE3FL5FDA00695	2015 E-350 Econoline 5 \03
21	1FDEE3FL7FDA00696	2015 E-350 Econoline 5 0 4
22	1FDEE3FL7FDA04215	2015 E-350 Econoline 5411
23	1FDEE3FL8FDA07110	2015 E-350 Econoline 5147 Retires
24	1FDEE3FL9FDA02983	2015 E-350 Econoline 5 3 6
25	1FDEE3FL9FDA02756	2015 E-350 Econoline 5405