10169493 2007 FORD E350 Van, 1 Ton, Cargo

		1016	59493	2007 FORD	E350 Va	n, 1 Ton, C	argo			
Workorder: Problem:	742732 PRE-DELIV	Meter: /ERY INSPE	0 CTION			In Date:	08/10/2007	Closed:	08/10/20	007
- Pre-delivery	Inspection									
	Ho :	ours 2.00		Labor:	110.00	Parts:	0.00	Total:	110.00	
Workorder: Problem:	836341 P.M SERVI	Meter: CE	2604			In Date:	04/01/2008	Closed:	04/03/20	800
- Perform Pm	Service				Parts Li	st				Qty
- Shop Suppli	es				Shop Su	ıpplies				1.00
					1372 O	il Filter Frm	Ph2 Wix 513	372		1.00
					G8018 F	uel Filter Ll	of G6593 Wix	33595		1.00
					5w20 Er	ngine Oil				7.00
					Used Fir	rex Refurbe	d Fire Extings	hers		1.00
	Ho :	ours 4.00		Labor:	240.00	Parts:	35.83	Total:	275.83	
Workorder: Problem:	845905 PM SERVIO	Meter:	3532			In Date:	10/20/2008	Closed:	10/24/20	800
- Perform Pm	Service				Parts Li	st				Qty
- Rotate & Hig	gh Speed Ba	lance All 4 T	ires.		Shop Su	ıpplies				1.00
- Shop Suppli	es				Ca8039	Air Filter Lb	of Af1615 Wix	46418		1.00
					1372 O	il Filter Frm	Ph2 Wix 513	372		1.00
					G8018 F	Fuel Filter LI	of G6593 Wix	33595		1.00
					5w20 Er	ngine Oil				7.00
						iper Blades				2.00
	Hc :	ours 5.00		Labor:	300.00	Parts:	42.05	Total:	342.05	
Workorder: Problem:	936986 PM SERVIO	Meter: CE.	6893			In Date:	04/24/2009	Closed:	04/27/20	009
- Pm Service					Parts Li	st				Qty
- Balance 4 T	ires. Nitro Fil	II.			Shop Su	ıpplies				1.00
- Shop Suppli	es				1372 O	il Filter Frm	Ph2 Wix 51	372		1.00
					5w20 Er	ngine Oil				7.00
					31-20 W	iper Blades/	20" Blade			2.00
	Ho :	ours 5.00		Labor:	300.00	Parts:	31.04	Total:	331.04	
Workorder: Problem:	945038 P.M. Servic	Meter:	10723			In Date:	10/26/2009	Closed:	11/20/20	009
- P.m service					Parts Li	st				Qty
- Replace bro	ken side doo	or latch asser	mbly.(pai	rt defect)	Shop Su	ıpplies				1.00
- Rotate & ba	lance all four	tires.			1372 O	il Filter Frm	Ph2 Wix 513	372		1.00
- Shop Suppli	es				G8018 F	Fuel Filter LI	of G6593 Wix	33595		1.00
					5w20 Er	ngine Oil				7.00
							6c2z15264a01	laa		1.00
	Ho :	ours 6.20		Labor:	372.00	Parts:	91.27	Total:	463.27	

Workorder: Problem:	1004705 P.M service.	Meter:	10780			In Date:	05/06/2010	Closed:	05/10/2	010
- Perform pm	service.				Parts Lis	st				Qty
	t,cooling syster	n,flush an	d renew co	olant.	Shop Su	pplies				1.00
	palance all tires				•		n Ph2 Wix 513	372		1.00
- Shop Supplie	es				5w20 En	gine Oil				7.00
					31-20 W	iper Blades	s 20" Blade			2.00
						-	All Makes (pea	ık 407)		1.00
	Hours :	3 7.00		Labor:	420.00	Parts:	41.12	Total:	461.12	
Workorder: Problem:	1012613 P.M. service.	Meter:	11622			In Date:	11/09/2010	Closed:	11/17/2	010
- Perform pm	service.				Parts Li	st				Qty
- Rotate and b	alance all four			Shop Su	pplies				1.00	
- Shop Suppli	es			1372 Oi	l Filter Frn	n Ph2 Wix 513	372		1.00	
					Ca8039	Air Filter L	bf Af1615 Wix	46418		1.00
					G8018 F	uel Filter L	.bf G6593 Wix	33595		1.00
					5w20 En	gine Oil				7.00
					Used Fir	ex Refurbe	ed Fire Extings	hers		1.00
					31-20 W	iper Blades	s 20" Blade			2.00
	Hours :	5.00		Labor:	300.00	Parts:	51.19	Total:	351.19	
Workorder: Problem:	1014073 1 - Key(s) issu	Meter: ed	12174			In Date:	12/27/2010	Closed:	12/27/20	010
- 1 - Key(s) iss	sued				Parts Lis	st				Qty
• • • • • • • • • • • • • • • • • • • •					Duplicate	e Vehicle k	(eys			1.00
	Hours :	3 0.20		Labor:	-		3.00	Total:	15.00	
Workorder: Problem:	1100603 security scree	Meter: ns/ locks	12438			In Date:	01/14/2011	Closed:	01/26/2	011
- Secure scree	ens and locks fo	or fac ctrl			Parts Li	st				Qty
- Shop Suppli	es				Shop Su	pplies				1.00
					Security	Locks				2.00
					Lock Ha	sp				2.00
					Side Sed	curity Scree	ens			1.00
					Rear Se	curity Scre	ens			1.00
					5/16 X 1	-1/4 Carria	ge Bolts		1	00.00
	Hours	0.00		Labor:	0.00	Parts:	424.37	Total:	424.37	

	1104686 Pm service als	Meter: so left rear	14977 tire flat.		I	In Date:	05/02/2011	Closed:	05/18/2011
- P.m. Service.					Parts Lis	t			Qt
- Test battery a	and charging s	system.rec	harge and re	tset	Shop Sup	plies			1.0
battery,fail load	test.replace o	lefective b	attery.		1372 Oil	Filter Frn	n Ph2 Wix 513	372	1.0
- Flush and ref	ill transmissio	n system.			09997 Br	ake Clear	า		1.0
- Repair one tir	e,rotate and b	alance all	•		Syn/atf Tr	ans Fluid	Synthetic		15.0
- Shop Supplie	S				5w20 Eng	jine Oil			7.0
					31-20 Wip	er Blades	s 20" Blade		2.0
					Group 65	Battery (r	ntc Bxt-65-850))	1.0
	Hour :	s 8.50		Labor:	510.00	Parts:	235.84	Total:	745.84
Workorder:	1111884	Meter:	17768		I	In Date:	11/04/2011	Closed:	01/09/2012
Problem:	P.M.service. (rust hole ir	n roof)						
- P.m. Service.					Parts Lis	t			Qt
- Replace two	tires,rotate an	d balance	all four.		Shop Sup	plies			1.0
- Complete wh	eel alignment.				1372 Oil	Filter Frn	n Ph2 Wix 513	372	1.0
- Transport veh		for warrar	ity body repa	ir(rust	G8018 Fuel Filter Lbf G6593 Wix 33595				1.0
hole in roof).r&r					5w20 Eng	jine Oil			7.0
- Shop Supplie	S				Wd40 Spr	ray Lube \$	Stock# 405540	0002	1.0
					Used Fire	x Refurbe	ed Fire Extings	hers	1.0
					17974749	2 Lt245/7	5r16 Wrangle	r Sr-a E	2.0
					Tire Dispo	osal Fee			2.0
					Tr416 Val	ve Stem			2.0
	Hour :	s 11.50		Labor:	690.00	Parts:	374.25	Total:	1,064.25
	1203908 P.M. service.	Meter:	19761		I	In Date:	04/25/2012	Closed:	05/07/2012
- Perform pm s	ervice.				Parts List	t			Qt
- Install two ne		ront whee	ls.nitrogen fill	and	Shop Sup	plies			1.0
balance all four					1372 Oil	Filter Frn	n Ph2 Wix 513	372	1.0
- Shop Supplie	S				Ca8039 A	ir Filter Ll	of Af1615 Wix	46418	1.0
					5w20 Eng	jine Oil			7.0
					Used Fire	x Refurbe	ed Fire Extings	hers	1.0
					31-20 Wip	er Blades	s 20" Blade		2.0
					17974749	2 Lt245/7	5r16 Wrangle	r Sr-a E	2.0
					Tire Dispo	sal Fee			2.0
					Tr416 Val	ve Stem			2.0
	Hour	s 6.00		Labor:	360.00	Parts:	401.94	Total:	761.94

Workorder: Problem:	1210892 P.M. servi	Meter:	22692			In Date:	11/07/2012	Closed:	11/28/2012	_
- P.m. Service	Э.				Parts L	ist			Q	ty
- Rotate and I	palance all	tires.			5w20 Eı	ngine Oil			7.0	-
- Shop Suppli	es					Filter Lbf Ph	1		1.0	00
					G8018 I	Fuel Filter L	of		1.0	00
					Used Fi	rex Refurbe	d F		1.0	00
					Shop St	upplies			1.0	00
	F :	lours 5.00		Labor:	300.00	Parts:	64.82	Total:	364.82	
Workorder: Problem:	1305049 Pm servic	Meter:	25917			In Date:	05/22/2013	Closed:	05/31/2013	
- P.m. Service	Э.				Parts L	ist			Q	ty
- Resurface fr	ont brake r	otors,replace	brake pads.s	ervice	Disc Bra	ake Pads			1.0	00
and lube calip	ers.flush ar	nd bleed syste	m and test dr	rive.	1401 B	rake Fluid B	ra		1.0	00
- Rotate and I		tires.			5w20 E	ngine Oil			7.0	00
- Shop Suppli	es				Napago	ld Oil Filter			1.0	00
					31-20 W	Viper Blades	20		2.0	00
					Napago	ld Air Filter			1.0	00
					Shop St	upplies			1.0	00
	H :	lours 9.50		Labor:	570.00	Parts:	109.57	Total:	679.57	
Workorder: Problem:	1311813 Pm servic	Meter:	28969			In Date:	11/22/2013	Closed:	12/10/2013	_
- P.m. Service	Э.				Parts L	ist			Q	ty
- Test battery	and chargi	ng system.rep	lace bad bat	tery.	5w20 E	ngine Oil			7.0	00
- Rotate and I	palance all	tires.			Used Fi	re X Refurbi	shed		1.0	00
- Shop Suppli	es				Napago	ld Oil Filter			1.0	00
					Napago	ld Fuel Filte	r		1.0	00
					Wiper B	lade			2.0	00
					Battery				1.0	00
					Shop St	upplies			1.0	00
	F	lours 6.00		Labor:	360.00	Parts:	172.10	Total:	532.10	
	:									
Workorder: Problem:	: 1312643 LR flat	Meter:	29156			In Date:	12/17/2013	Closed:	12/18/2013	
	LR flat					In Date:	12/17/2013	Closed:	12/18/2013	

:

Workorder: Problem:	1405393 P.M. servio	Meter: ce.	32481	In Date:	06/03/2014	Closed:	06/19/2014
- Perform pm	service.			Parts List			Qt
- Rotate and		our tires.		5w20 Engine Oil			7.00
- Shop Suppli	ies			Napagold Oil Filter			1.00
				Wiper Blade			1.00
				Wiper Blade			1.00
				Napagold Fuel Filte	er		1.0
				Shop Supplies			1.00
	H	ours 5.00	Labor:		37.34	Total:	337.34
Workorder: Problem:	1407693 Right rear	Meter: tire flat.	33528	In Date:	08/05/2014	Closed:	08/11/2014
- Repair and	_			Parts List			Qt
- Shop Suppli	ies			Shop Supplies			1.00
	H	ours 1.00	Labor:	60.00 Parts	2.00	Total:	62.00
Workorder: Problem:	1410226 Left rear ti	Meter: re going flat.	34701	In Date:	10/10/2014	Closed:	10/27/2014
- Repair and	balance left	rear tire.		Parts List			Qt
- Shop Suppli	ies			Shop Supplies			1.00
	H	ours 1.00	Labor:	60.00 Parts	2.00	Total:	62.00
Markardar.		== .	05.10.1				
	1411932 Pm service	Meter: e.Towed in for	35431 no start.	In Date:	11/26/2014	Closed:	12/10/2014
		Meter: e.Towed in for		In Date:	11/26/2014	Closed:	
Problem: - Pm service.	Pm service	e.Towed in for		Parts List	11/26/2014	Closed:	12/10/2014 Qt ; 7.0
Problem: - Pm service Diagnose no	Pm service start.test s	e.Towed in for	no start.	Parts List		Closed:	Qt
Problem: - Pm service Diagnose no defective alter - Diagnose fo	Pm service o start.test s nator. r blower spe	e.Towed in for starting and ch	no start. narging system.replace	Parts List 5w20 Engine Oil		Closed:	Qt ;
Problem: - Pm service Diagnose no defective alter - Diagnose fo and wiring har	Pm service o start.test s nator. Ir blower spe ness pigtail	e.Towed in for starting and ch eeds inop.repl connector du	no start. narging system.replace lace blower switch le to high resistance.	Parts List 5w20 Engine Oil Napagold Oil Filter		Closed:	Qt y 7.00 1.00
Problem: - Pm service Diagnose no defective alter - Diagnose fo and wiring har - Replace two	Pm service o start.test s nator. or blower spe ness pigtail o tires.rotate	e.Towed in for starting and ch eeds inop.repl connector du and balance	no start. narging system.replace lace blower switch the to high resistance. all four.	Parts List 5w20 Engine Oil Napagold Oil Filter Wiper Blade		Closed:	Qt y 7.00 1.00 2.00
Problem: - Pm service Diagnose no defective alter - Diagnose fo and wiring har - Replace two - Battery faile	Pm service o start.test s nator. or blower spe ness pigtail o tires.rotate	e.Towed in for starting and ch eeds inop.repl connector du and balance	no start. narging system.replace lace blower switch le to high resistance.	Parts List 5w20 Engine Oil Napagold Oil Filter Wiper Blade Used Fire X Refurb		Closed:	Qt y 7.00 1.00 2.00 1.00
Problem: - Pm service. - Diagnose no defective alter - Diagnose fo and wiring har - Replace two - Battery faile battery.	Pm services o start.test so mator. or blower specimess pigtail or tires.rotate d loadtest a	e.Towed in for starting and ch eeds inop.repl connector du and balance	no start. narging system.replace lace blower switch the to high resistance. all four.	Parts List 5w20 Engine Oil Napagold Oil Filter Wiper Blade Used Fire X Refurb Atenador	oished	Closed:	Qt y 7.00 1.00 2.00 1.00
Problem: - Pm service Diagnose no defective alter - Diagnose fo and wiring har - Replace two - Battery faile	Pm services o start.test so mator. or blower specimess pigtail or tires.rotate d loadtest a	e.Towed in for starting and ch eeds inop.repl connector du and balance	no start. narging system.replace lace blower switch the to high resistance. all four.	Parts List 5w20 Engine Oil Napagold Oil Filter Wiper Blade Used Fire X Refurb Atenador Wire Asy	oished	Closed:	Qty 7.00 1.00 2.00 1.00 2.00
Problem: - Pm service. - Diagnose no defective alter - Diagnose fo and wiring har - Replace two - Battery faile battery.	Pm services o start.test so mator. or blower specimess pigtail or tires.rotate d loadtest a	e.Towed in for starting and ch eeds inop.repl connector du and balance	no start. narging system.replace lace blower switch the to high resistance. all four.	Parts List 5w20 Engine Oil Napagold Oil Filter Wiper Blade Used Fire X Refurb Atenador Wire Asy Lt245 75r16 Mich I Tr416 Valve Stem	oished	Closed:	Qty 7.00 1.00 2.00 1.00 2.00 2.00
Problem: - Pm service. - Diagnose no defective alter - Diagnose fo and wiring har - Replace two - Battery faile battery.	Pm services o start.test so mator. or blower specimess pigtail or tires.rotate d loadtest a	e.Towed in for starting and ch eeds inop.repl connector du and balance	no start. narging system.replace lace blower switch the to high resistance. all four.	Parts List 5w20 Engine Oil Napagold Oil Filter Wiper Blade Used Fire X Refurb Atenador Wire Asy Lt245 75r16 Mich I Tr416 Valve Stem Battery	oished	Closed:	Qt; 7.00 1.00 2.00 1.00 2.00 2.00 2.00 1.00
Problem: - Pm service. - Diagnose no defective alter - Diagnose fo and wiring har - Replace two - Battery faile battery.	Pm services o start.test so mator. or blower specimess pigtail or tires.rotate d loadtest a	e.Towed in for starting and ch eeds inop.repl connector du and balance	no start. narging system.replace lace blower switch the to high resistance. all four.	Parts List 5w20 Engine Oil Napagold Oil Filter Wiper Blade Used Fire X Refurb Atenador Wire Asy Lt245 75r16 Mich I Tr416 Valve Stem Battery Switch	oished	Closed:	Qty 7.00 1.00 2.00 1.00 2.00 2.00 2.00 1.00 1
Problem: - Pm service Diagnose no defective alter - Diagnose fo and wiring har - Replace two - Battery faile battery.	Pm services o start.test so mator. or blower specimess pigtail or tires.rotate d loadtest a	e.Towed in for starting and ch eeds inop.repl connector du and balance	no start. narging system.replace lace blower switch the to high resistance. all four.	Parts List 5w20 Engine Oil Napagold Oil Filter Wiper Blade Used Fire X Refurb Atenador Wire Asy Lt245 75r16 Mich I Tr416 Valve Stem Battery Switch Shop Supplies	oished	Closed:	Qt; 7.00 1.00 2.00 1.00 2.00 2.00 1.00 1.00 1
Problem: - Pm service Diagnose no defective alter - Diagnose fo and wiring har - Replace two - Battery faile battery.	Pm services o start.test sonator. or blower sperness pigtail of tires.rotate d loadtest a	e.Towed in for starting and ch eeds inop.repl connector du and balance	narging system.replace lace blower switch the to high resistance. all four. replace defective	Parts List 5w20 Engine Oil Napagold Oil Filter Wiper Blade Used Fire X Refurb Atenador Wire Asy Lt245 75r16 Mich I Tr416 Valve Stem Battery Switch Shop Supplies Tire Disposal Fee	oished		Qty 7.00 1.00 2.00 1.00 2.00 2.00 2.00 1.00 1
Problem: - Pm service Diagnose no defective alter - Diagnose for and wiring har - Replace two - Battery faile battery Shop Suppli	Pm services o start.test services or blower specimess pigtail or tires.rotate d loadtest a ies H 1412010	e.Towed in for starting and ch eeds inop.repl connector du and balance fter recharge.	r no start. narging system.replace lace blower switch le to high resistance. all four. replace defective Labor:	Parts List 5w20 Engine Oil Napagold Oil Filter Wiper Blade Used Fire X Refurb Atenador Wire Asy Lt245 75r16 Mich I Tr416 Valve Stem Battery Switch Shop Supplies Tire Disposal Fee	oished Ltx Ms2		Qty 7.00 1.00 2.00 1.00 2.00 2.00 2.00 1.00 1
Problem: - Pm service Diagnose no defective alter - Diagnose fo and wiring har - Replace two - Battery faile battery Shop Suppli	Pm service o start.test s nator. r blower sperness pigtail o tires.rotate d loadtest a ies H : 1412010 Electronic	e.Towed in for starting and charter in the eds in the e	r no start. narging system.replace lace blower switch le to high resistance. all four. replace defective Labor: 35239 ts etc) PM Service	Parts List 5w20 Engine Oil Napagold Oil Filter Wiper Blade Used Fire X Refurb Atenador Wire Asy Lt245 75r16 Mich I Tr416 Valve Stem Battery Switch Shop Supplies Tire Disposal Fee 630.00 Parts	oished .tx Ms2 : 961.55	Total:	Qty 7.00 1.00 2.00 1.00 2.00 2.00 1.00 1.00 2.00 1.00 1
- Pm service Diagnose not defective alter - Diagnose for and wiring har - Replace two - Battery faile battery Shop Suppli	Pm services o start.test services o start.test services or blower specimess pigtail or tires.rotate d loadtest a dies H : 1412010 Electronic	e.Towed in for starting and charting and charting and charter and balance fter recharge. Ours 10.50 Meter: problem (light light alpine Store)	r no start. narging system.replace lace blower switch le to high resistance. all four. replace defective Labor: 35239 Is etc) PM Service age Lot) E side of	Parts List 5w20 Engine Oil Napagold Oil Filter Wiper Blade Used Fire X Refurb Atenador Wire Asy Lt245 75r16 Mich I Tr416 Valve Stem Battery Switch Shop Supplies Tire Disposal Fee 630.00 Parts In Date:	oished Ltx Ms2 : 961.55 11/25/2014	Total:	Qty 7.00 1.00 2.00 1.00 2.00 2.00 1.00 1.00 1
Problem: - Pm service Diagnose no defective alter - Diagnose for and wiring hare - Replace two - Battery faile battery Shop Supplies - Tow From: 8	Pm services o start.test services o start.test services or blower specimess pigtail or tires.rotate d loadtest a dies H : 1412010 Electronic	e.Towed in for starting and charter in the eds in the e	r no start. narging system.replace lace blower switch le to high resistance. all four. replace defective Labor: 35239 ts etc) PM Service	Parts List 5w20 Engine Oil Napagold Oil Filter Wiper Blade Used Fire X Refurb Atenador Wire Asy Lt245 75r16 Mich I Tr416 Valve Stem Battery Switch Shop Supplies Tire Disposal Fee 630.00 Parts In Date:	oished .tx Ms2 : 961.55	Total:	Qty 7.00 1.00 2.00 1.00 2.00 2.00 1.00 1.00 1

Workorder: Problem:	1506607 Pm servic	Meter: e.	38700		I	n Date:	07/01/2015	Closed:	07/15/20)15
- Pm service.					Parts List	t				Qty
- Replace two	tires.rotate	and balance	all four.		5w20 Eng					7.00
- Shop Suppli	es				Napagold					1.00
					Wiper Bla					2.00
					Lt245 75r	16				2.00
					Tr416 Val	ve Stem				2.00
					Drain Plug	9				1.00
					Shop Sup	plies				1.00
					Tire Dispo	sal Fee				2.00
	⊢ :	lours 6.00		Labor:	360.00	Parts:	502.65	Total:	862.65	
Workorder: Problem:	1509761 Check ac	Meter: blower inop.	38783		I	n Date:	09/28/2015	Closed:	09/30/20)15
- Diagnose inc	op a/c blow	er.replace blo	wer motor a	and	Parts List	t				Qty
resistor.					Blower Mo	otor Resis	tor			1.00
- Shop Suppli	es				Blower Mo	otor Assy				1.00
					Shop Sup	plies				1.00
	F	lours 1.75		Labor:	105.00	Parts:	73.79	Total:	178.79	
Workorder: Problem:	1600166 Pm servic	Meter:	39714		I	n Date:	01/06/2016	Closed:	01/19/20)16
- Pm service.					Parts List	t				Qty
- Check and r	eplace both	n third brake la	amp bulb.		5w20 Eng	ine Oil				7.00
- Replace rea		ors.pads and o	alipers.blee	ed brake	Napagold	Oil Filter				1.00
system and te					Napagold	Fuel Filte	r			1.00
- Rotate and b		four tires.			Napagold	Air Filter				1.00
- Shop Suppli	es				Used Fire	X Refurb	ished			1.00
					20" Wiper	Blade				2.00
					Bulb					2.00
					Reman Br	ake Calip	er			1.00
					Reman Br	ake Calip	er			1.00
					B Fluid Do	ot 3-32oz				1.00
					Brake Ro	tor Only				2.00
					Disc Brake	e Pads				1.00
					Drain Plug	9				1.00
					Shop Sup	plies				1.00
	H	lours 9.50		Labor:	570.00	Parts:	363.64	Total:	933.64	

Workorder: 1607205 Meter: 41282 Problem: P.M. service.	In Date: 07/15/2016	Closed:	07/28/2016
- P.m. Service.	Parts List		Qty
- Rotate and balance all tires.	Caster-camber Bushing		2.00
- Replace both upper and lower ball joints.	Napagold Oil Filter		1.00
- Replace camber/caster adjuster bushings,complete whee	l 5w20 Engine Oil		7.00
alignment.test drive.	20" Wiper Blade		2.00
- Shop Supplies	Washer Fluid Concentr		1.00
	Upper Ball Joint		2.00
	Ball Joint		2.00
	1cart Palladium 2 Grs		1.00
	Brake Cleaner		1.00
	Napa Quart 5w20		7.00
	Shop Supplies		1.00
Hours 12.50 Labo	or: 750.00 Parts: 341.24	Total:	1,091.24
Workorder: 1700970 Meter: 43900 Problem: P.M. service and side cargo door lock broke	In Date: 01/31/2017 and door inop.	Closed:	02/08/2017
- P.m. Service.	Parts List		Qty
- Inspect and service rear differential.	5w20 Engine Oil		7.00
- Replace leaking front shocks.	Napagold Oil Filter		1.00
- Diagnose and replace inop side cargo door latch assemb	, •		1.00
- Rotate and balance tires.	20" Wiper Blade		2.00
- Shop Supplies	Used Fire X Refurbished		1.00
	75w140 Ford Axle Lube		3.00
	Friction Modifier		2.00
	Shock - Gas Grande Fleet - Fro	nt	2.00
	door latch remote control		1.00
	Retainer		1.00
	Shop Supplies		1.00
Hours 8.25 Labo	or: 495.00 Parts: 370.73	Total:	865.73
Workorder: 1707661 Meter: 45960 Problem: P.M. service.	In Date: 08/04/2017	Closed:	08/21/2017
- P.m. Service.	Parts List		Qty
- Pressure test and inspect cooling system.flush and refill	5w20 Engine Oil		7.00
system.	Napagold Oil Filter		1.00
- Rotate and balance tires.	20" Wiper Blade		2.00
- Shop Supplies	Washer Fluid Concentr		1.00
	Stg Wheel Cov - Ford		1.00
	Peak Global Antifrz		3.00
	Shop Supplies		1.00
Hours 7.00 Labo	or: 420.00 Parts: 101.53	Total:	521.53
•			

Workorder: Problem:	1712458 Right rear doc	Meter: or inop.	47349			In Date:	12/19/2017	Closed:	12/21/2017
- Diagnoise re	ear door inop.re embly.retest.	emove and	replace righ	nt rear	Parts Li				Qty 1.00
- Shop Suppli	•				Shop Su				1.00
		s 1.25		Labor:	•	• •	76.40	Total:	151.40
Workorder: Problem:	1802055 P.M. service.	Meter:	47935			In Date:	02/23/2018	Closed:	02/27/2018
- P.m. service	€.				Parts Li	st			Qty
- Rotated and	d balanced all fo	our tires.nit	trogen filled a	all tires.	5w20 En	ngine Oil			7.00
- Shop Suppli	ies				Napagol	d Oil Filter			1.00
					Napagol	d Fuel Filte	r		1.00
					20" Wipe	er Blade			2.00
					Washer	Fluid Conc	entr		1.00
					Used Fir	e X Refurb	ished		1.00
					Chan Cu	ممائمه			1.00
					Shop Su	ipplies			1.00
	Hour	s 5.00		Labor:	300.00		50.05	Total:	350.05
Workorder: Problem:	Hour: 1808189 P.M. service a	Meter:	49486 engine light		300.00		50.05	Total:	
	: 1808189 P.M. service a	Meter:			300.00	Parts:			350.05 08/20/2018
Problem: - P.m. service	: 1808189 P.M. service a	Meter: and Check	engine light	on and ru	300.00 ns rough. Parts Li	Parts:			350.05
Problem: - P.m. service - Computer d Perform powe	: 1808189 P.M. service a e. iagnose check or balance test.	Meter: and Check engine ligh Perform tu	engine light nt , Code P03 ne up . Repl	on and ru	300.00 ns rough. Parts Li	Parts: In Date: st d Oil Filter			350.05 08/20/2018 Qty
Problem: - P.m. service - Computer d Perform powe eight spark plu	: 1808189 P.M. service a e. iagnose check ir balance test. ugs and replace	Meter: and Check engine light Perform tue number to	engine light nt , Code P03 ine up . Repl wo coil.	on and rui 302. lace all	300.00 ns rough. Parts Li Napagol	Parts: In Date: st Id Oil Filter Ingine Oil			350.05 08/20/2018 Qty 1.00
Problem: - P.m. service - Computer d Perform powe eight spark plu - Charge batt	: 1808189 P.M. service a e. iagnose check or balance test. ugs and replace ery . Test batte	Meter: and Check engine light Perform tue number to	engine light nt , Code P03 ine up . Repl wo coil.	on and rui 302. lace all	300.00 ns rough. Parts Li Napagol 5w20 En	Parts: In Date: st Id Oil Filter Ingine Oil Ingine Oi			350.05 08/20/2018 Qty 1.00 7.00
Problem: - P.m. service - Computer d Perform powe eight spark plu - Charge batt defective batte	: 1808189 P.M. service a e. iagnose check ir balance test. ugs and replace ery . Test batte ery.	Meter: and Check engine ligh Perform tue number to ry and cha	engine light nt , Code P03 ine up . Repl wo coil.	on and rui 302. lace all	300.00 Parts Li Napagol 5w20 En Pedal Pa 20" Wipe	Parts: In Date: st Id Oil Filter Ingine Oil Ingine Oi			350.05 08/20/2018 Qty 1.00 7.00 1.00
Problem: - P.m. service - Computer d Perform powe eight spark plu - Charge batt defective batte - Replace righ	: 1808189 P.M. service a e. iagnose check or balance test. ugs and replace ery . Test batte ery. int headlight bull	Meter: and Check engine light Perform tue number to ry and cha	engine light nt , Code P03 ine up . Repl wo coil. irging systen	on and rui 302. lace all n . R&r	300.00 Parts Li Napagol 5w20 En Pedal Pa 20" Wipe	Parts: In Date: st Id Oil Filter Ingine Oil Id ad Inger Blade Inger Blade Inger Blade Inger Blade			350.05 08/20/2018 Qty 1.00 7.00 1.00 2.00
Problem: - P.m. service - Computer d Perform powe eight spark plu - Charge batt defective batte - Replace righ	: 1808189 P.M. service a e. iagnose check ir balance test. ugs and replace ery . Test batte ery.	Meter: and Check engine light Perform tue number to ry and cha	engine light nt , Code P03 ine up . Repl wo coil. irging systen	on and rui 302. lace all n . R&r	300.00 Parts Li Napagol 5w20 En Pedal Pa 20" Wipe	Parts: In Date: st Id Oil Filter Ingine Oil Id ad Inger Blade Inger Blade Inger Blade Inger Blade			350.05 08/20/2018 Qty 1.00 7.00 1.00 2.00 1.00
Problem: - P.m. service - Computer d Perform powe eight spark plu - Charge batt defective batte - Replace righ - Perform air codes.	: 1808189 P.M. service a e. iagnose check or balance test. ugs and replace ery . Test batte ery. int headlight bull	Meter: and Check engine ligh Perform tue number to ry and cha b. and flush in	engine light nt , Code P03 ne up . Repl wo coil. arging system njectors . Cle	on and rui 302. lace all n . R&r	300.00 Parts Li Napagol 5w20 En Pedal Pa 20" Wipe Ford Ign Spark Pl Battery	Parts: In Date: st Id Oil Filter Ingine Oil Id ad Inger Blade Inger Blade Inger Blade Inger Blade	08/09/2018		350.05 08/20/2018 Qty 1.00 7.00 1.00 2.00 1.00 8.00
Problem: - P.m. service - Computer d Perform powe eight spark plu - Charge batt defective batte - Replace righ - Perform air codes Rotate and l - Test trailer of	: 1808189 P.M. service a e. iagnose check or balance test. ugs and replace ery . Test batte ery. int headlight bull intake decarb. a connector . Rep	Meter: and Check engine ligh Perform tue number to ry and cha b. and flush in ance all for pair broken	engine light nt , Code P03 ne up . Repl wo coil. urging system njectors . Cle ur tires.	on and rui 302. lace all n . R&r	300.00 Parts Li Napagol 5w20 En Pedal Pa 20" Wipe Ford Ign Spark Pl Battery	Parts: In Date: st Id Oil Filter rigine Oil ad er Blade ition Coil lug Sealed Be	08/09/2018		350.05 08/20/2018 Qty 1.00 7.00 1.00 2.00 1.00 8.00 1.00
Problem: - P.m. service - Computer d Perform powe eight spark plu - Charge batt defective batte - Replace righ - Perform air codes Rotate and l - Test trailer of	: 1808189 P.M. service as a. iagnose check or balance test. ugs and replace ery. Test batte ery. int headlight bull intake decarb. a high speed bala connector. Rep	Meter: and Check engine ligh Perform tue number to ry and cha b. and flush in ance all for pair broken	engine light nt , Code P03 ne up . Repl wo coil. urging system njectors . Cle ur tires.	on and rui 302. lace all n . R&r	300.00 Parts Li Napagol 5w20 En Pedal Pa 20" Wipe Ford Ign Spark Pl Battery Halogen Injector (Parts: In Date: st Id Oil Filter rigine Oil ad er Blade ition Coil lug Sealed Be	08/09/2018		350.05 08/20/2018 Qty 1.00 7.00 1.00 2.00 1.00 8.00 1.00 1.00

Labor: 876.00

Hours 14.60

Total: 1,202.69

Parts: 326.69

I I UDICIII. F	901526 Meter: PM Service, Leftf rear of	52796 door will not open.	In Date:	02/08/2019	Closed:	02/22/20	19
- P.m. service.	2535, 2510 1501		Parts List				Qty
	sealed beam headlight	t hulb due to water	Napagold Oil Filter				1.00
•	_	ace left rear cargo door	5w20 Engine Oil				7.00
latches . Retest.		ace left real cargo door	20" Wiper Blade				2.00
- Rotate and hig	gh speed balance all fo	our tires . Nitrofill all.	Used Fire X Refurb	nished			1.00
- Shop Supplies			Halogen Sealed Be				2.00
			Door Handle W/cal				1.00
			Door Latch W/cable				1.00
			Shop Supplies	5			1.00
	Hours 7.10	Labor:		195.87	Total:	671.57	1.00
	905020 Meter:	53575	In Date:	05/09/2019	Closed:	05/13/20	19
Problem: A	VC omly blows out def	rost vent .					
		place defective vacuum	Parts List				Qty
	eck valve . Retest .		W W Vacuum Tubi	ng			5.00
- Shop Supplies	;		A/c Valve				1.00
			Vacuum Resevoir				1.00
			Shop Supplies				1.00
	Hours 4.40	Labor:	294.80 Parts:	34.01	Total:	328.81	
Problem: F	908695 Meter: P.M. service and main	53985 drive belt broke	In Date:	08/20/2019	Closed:	09/11/20	19
- P.m. service.			Parts List				Qty
- Test and repla	ice side cargo door rea	ar latches and retest.	Napagold Oil Filter				1.00
•	nd charging system . F	Replace binding	5w20 Engine Oil				7.00
			Napagold Fuel Filte	er			1.00
alternator.	mlaaa buulkan balt		Napagola i dei i ille	•			1.00
- Inspect and re	place broken belt.	Aller CH all	Used Fire X Refurb				1.00
Inspect and reRotate and high	gh speed balance all fo	our tires . Nitrofill all.	. •				
- Inspect and re	gh speed balance all fo	our tires . Nitrofill all.	Used Fire X Refurb				1.00
Inspect and reRotate and high	gh speed balance all fo	our tires . Nitrofill all.	Used Fire X Refurb 20" Wiper Blade				1.00 2.00
Inspect and reRotate and high	gh speed balance all fo	our tires . Nitrofill all.	Used Fire X Refurb 20" Wiper Blade latch				1.00 2.00 1.00
Inspect and reRotate and high	gh speed balance all fo	our tires . Nitrofill all.	Used Fire X Refurb 20" Wiper Blade latch				1.00 2.00 1.00 1.00
Inspect and reRotate and high	gh speed balance all fo	our tires . Nitrofill all.	Used Fire X Refurb 20" Wiper Blade latch latch Alternator				1.00 2.00 1.00 1.00
Inspect and reRotate and high	gh speed balance all fo		Used Fire X Refurb 20" Wiper Blade latch latch Alternator Belt Shop Supplies		Total:	1,090.59	1.00 2.00 1.00 1.00 1.00 1.00
- Inspect and re - Rotate and hig - Shop Supplies	Hours 8.40		Used Fire X Refurb 20" Wiper Blade latch latch Alternator Belt Shop Supplies	oished	Total:	1,090.59	1.00 2.00 1.00 1.00 1.00 1.00
- Inspect and re - Rotate and hig - Shop Supplies Workorder: 2	Hours 8.40	Labor:	Used Fire X Refurb 20" Wiper Blade latch latch Alternator Belt Shop Supplies 562.80 Parts:	527.79			1.00 2.00 1.00 1.00 1.00 1.00
- Inspect and re - Rotate and hig - Shop Supplies Workorder: 2 Problem: F	Hours 8.40	Labor: 53988	Used Fire X Refurb 20" Wiper Blade latch latch Alternator Belt Shop Supplies 562.80 Parts:	527.79			1.00 2.00 1.00 1.00 1.00 1.00
- Inspect and re - Rotate and hig - Shop Supplies Workorder: 2 Problem: F	Hours 8.40 : 2002143 Meter: P.M. service.	Labor: 53988	Used Fire X Refurb 20" Wiper Blade latch latch Alternator Belt Shop Supplies 562.80 Parts: In Date: Parts List	527.79			1.00 2.00 1.00 1.00 1.00 1.00 0
- Inspect and re - Rotate and hig - Shop Supplies Workorder: 2 Problem: F - P.m. service Rotate and ba	Hours 8.40 : 2002143 Meter: P.M. service.	Labor: 53988	Used Fire X Refurb 20" Wiper Blade latch latch Alternator Belt Shop Supplies 562.80 Parts: In Date: Parts List Napagold Oil Filter 5w20 Engine Oil	527.79			1.00 2.00 1.00 1.00 1.00 1.00 0 0 20
- Inspect and re - Rotate and hig - Shop Supplies Workorder: 2 Problem: F - P.m. service Rotate and ba	Hours 8.40 : 2002143 Meter: P.M. service.	Labor: 53988	Used Fire X Refurb 20" Wiper Blade latch latch Alternator Belt Shop Supplies 562.80 Parts: In Date: Parts List Napagold Oil Filter	527.79			1.00 2.00 1.00 1.00 1.00 1.00 0 20 Qty 1.00 7.00

Workorder: 2009402 **Meter**: 54656 **In Date**: 09/18/2020 **Closed**: 09/18/2020

Problem: Transition Prep Charge

- Transition Prep Charge

Hours 2.00 Labor: 146.00 Parts: 0.00 Total: 146.00

: