

**Palm Beach County Fleet Management  
Asset Maintenance History**

**10180779     2010 FORD RANGER Pickup, Compact**

**Workorder:** 1002719     **Meter:** 0     **In Date:** 03/17/2010     **Closed:** 03/17/2010  
**Problem:** Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00     Labor: 120.00     Parts: 0.00     Total: 120.00  
 :

**Workorder:** 1008843     **Meter:** 1855     **In Date:** 08/17/2010     **Closed:** 08/20/2010  
**Problem:** Pm service

- P.m. Service.  
 - Shop Supplies

**Parts List**  
 Shop Supplies 1.00  
 Ph9566 Oil Filter Use Fram Ph3614 1.00  
 5w20 Engine Oil 4.00

Hours 2.00     Labor: 120.00     Parts: 13.09     Total: 133.09  
 :

**Workorder:** 1009007     **Meter:** 1860     **In Date:** 08/20/2010     **Closed:** 08/24/2010  
**Problem:** reflash canceiver-spot # 225

- Flash Canceiver  
 - Shop Supplies

**Parts List**  
 Shop Supplies 1.00

Hours 1.00     Labor: 60.00     Parts: 2.00     Total: 62.00  
 :

**Workorder:** 1101859     **Meter:** 4334     **In Date:** 02/16/2011     **Closed:** 02/25/2011  
**Problem:** Pm service also see notes on tool box will not open.

- Perform pm service.  
 - Rotate and balance all four tires.  
 - Shop Supplies

**Parts List**  
 Shop Supplies 1.00  
 Ph9566 Oil Filter Use Fram Ph3614 1.00  
 3424 Fuel Filter Frm 3424 Wix 33424 1.00  
 5w20 Engine Oil 4.00  
 Nb-19 Wiper Blades 19" Anco 31-19 2.00

Hours 3.00     Labor: 180.00     Parts: 31.14     Total: 211.14  
 :

**Workorder:** 1111036     **Meter:** 7332     **In Date:** 10/17/2011     **Closed:** 10/27/2011  
**Problem:** P.M. service.

- P.m. Service.  
 - Rotate and balance all tires.  
 - Shop Supplies

**Parts List**  
 Shop Supplies 1.00  
 1348 Oil Filter Frm Ph3614 Wix 51348 1.00  
 5w20 Engine Oil 4.00

Hours 3.00     Labor: 180.00     Parts: 14.42     Total: 194.42  
 :

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1203665	<b>Meter:</b> 9697	<b>In Date:</b> 04/18/2012	<b>Closed:</b> 04/30/2012
<b>Problem:</b> Pm service.			
- Perform pm service.	<b>Parts List</b>	<b>Qty</b>	
- Rotate and balance all four tires.	Shop Supplies	1.00	
- Transport vehicle to and from dealer for performing 11s17 fuel line recall.installing new front fuel line and modify cover.	1348 Oil Filter Frm Ph3614 Wix 51348	1.00	
- Shop Supplies	Ca8243 Air Filter Lbf Af1658 Wix 46253	1.00	
	3424 Fuel Filter Frm 3424 Wix 33424	1.00	
	5w20 Engine Oil	5.00	
	Nb-19 Wiper Blades 19" Anco 31-19	2.00	
Hours 5.00	Labor: 300.00	Parts: 40.62	Total: 340.62
:			
<b>Workorder:</b> 1212359	<b>Meter:</b> 12460	<b>In Date:</b> 12/27/2012	<b>Closed:</b> 01/17/2013
<b>Problem:</b> Pm service and wiper blades.			
- P.m. Service.	<b>Parts List</b>	<b>Qty</b>	
- Test battery and charging system.recharge and retest battery,fail load test.replace defective battery.	Filter	1.00	
- Replace and balance four new tires.	5w20 Engine Oil	5.00	
- Replace both missing tag light lenses.	31-18 Wiper Blades 18	2.00	
- Complete wheel alignment.test drive.	05074 Silicone Spray	1.00	
- Shop Supplies	Group 59 Battery Mc	1.00	
	183482418 P225-70r15	4.00	
	Lamp Asy	2.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	4.00	
Hours 8.00	Labor: 480.00	Parts: 812.10	Total: 1,292.10
:			
<b>Workorder:</b> 1306901	<b>Meter:</b> 15207	<b>In Date:</b> 07/11/2013	<b>Closed:</b> 07/25/2013
<b>Problem:</b> P.M. Service.			
- P.m. Service.	<b>Parts List</b>	<b>Qty</b>	
- Replace left rear signal light bulb.	5w20 Engine Oil	5.00	
- Rotate and balance all four tires.	Napagold Oil Filter	1.00	
- Shop Supplies	Wiper Blade	2.00	
	Napagold Fuel Filter	1.00	
	Washer FI	1.00	
	Bulb	1.00	
	Shop Supplies	1.00	
Hours 3.25	Labor: 195.00	Parts: 39.19	Total: 234.19
:			
<b>Workorder:</b> 1309214	<b>Meter:</b> 15576	<b>In Date:</b> 09/10/2013	<b>Closed:</b> 09/11/2013
<b>Problem:</b> no start			
- Tow From: airport hilton To: lv shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1309480	<b>Meter:</b> 15576	<b>In Date:</b> 09/10/2013	<b>Closed:</b> 10/02/2013
<b>Problem:</b> damage to rgt frt fender, rgt lgts & frt bumper			
- damage to rgt frt fender, rgt lgts & frt bumper			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1402149	<b>Meter:</b> 19277	<b>In Date:</b> 03/05/2014	<b>Closed:</b> 03/20/2014
<b>Problem:</b> P.M. service and radio knob inop.			
- P.m. Service.	<b>Parts List</b>	<b>Qty</b>	
- Test and replace defective radio.	5w20 Engine Oil	4.00	
- Rotate and balance all tires.	Napagold Oil Filter	1.00	
- Shop Supplies	Washer FI	1.00	
	Radio	1.00	
	Shop Supplies	1.00	
Hours 3.75	Labor: 225.00	Parts: 306.56	Total: 531.56
:			
<b>Workorder:</b> 1409063	<b>Meter:</b> 22261	<b>In Date:</b> 09/09/2014	<b>Closed:</b> 09/26/2014
<b>Problem:</b> Pm service			
- Pm service.	<b>Parts List</b>	<b>Qty</b>	
- Inspect and replace two defective licence plate lamps and bulbs	5w20 Engine Oil	5.00	
	Napagold Oil Filter	1.00	
- Rotate and balance all four tires.	Napagold Fuel Filter	1.00	
- Shop Supplies	Wiper Blade	2.00	
	Napagold Air Filter	1.00	
	Bulb	2.00	
	Tag Lamp	2.00	
	Shop Supplies	1.00	
Hours 3.50	Labor: 210.00	Parts: 92.90	Total: 302.90
:			
<b>Workorder:</b> 1410036	<b>Meter:</b> 22527	<b>In Date:</b> 10/06/2014	<b>Closed:</b> 10/14/2014
<b>Problem:</b> Right side headlamp lowbeam shield fell off inside lamp.			
- Inspect and replace defective right side head lamp assembly due to low beam shield seperated from reflector inside headlamp.	<b>Parts List</b>	<b>Qty</b>	
	Headlamp Assembly	1.00	
- Shop Supplies	Shop Supplies	1.00	
Hours 0.50	Labor: 30.00	Parts: 101.66	Total: 131.66
:			
<b>Workorder:</b> 1503415	<b>Meter:</b> 24467	<b>In Date:</b> 04/01/2015	<b>Closed:</b> 04/14/2015
<b>Problem:</b> Pm service.			
- Pm service.	<b>Parts List</b>	<b>Qty</b>	
- Remove and clean power steering resevoir.flush power steering system.fill with new fluid.	5w20 Engine Oil	5.00	
	Napagold Oil Filter	1.00	
- Rotate and balance all four tires.	Wiper Blade	2.00	
- Shop Supplies	Washer Fluid Concentr	2.00	
	Syn-atf Trans Fluid S	2.00	
	Shop Supplies	1.00	
Hours 4.00	Labor: 240.00	Parts: 39.56	Total: 279.56
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1507476	<b>Meter:</b> 26501	<b>In Date:</b> 07/28/2015	<b>Closed:</b> 07/31/2015
<b>Problem:</b> power driver leaking			
- replace leaking power steering hose and flush ps sys	<b>Parts List</b>	<b>Qty</b>	
- evacuate replace leaking shrader valves recharge and ck for leaks	Power Steering Hose	1.00	
- test drive after repair	Pwr Steering FI-quart	2.00	
- Shop Supplies	Brake Cleaner	1.00	
	South Region R134a	2.00	
	Sch Core	1.00	
	Core	1.00	
	Ac Valve Core High	1.00	
	Shop Supplies	1.00	
Hours 7.00	Labor: 420.00	Parts: 88.87	Total: 508.87
:			
<b>Workorder:</b> 1510197	<b>Meter:</b> 27807	<b>In Date:</b> 10/07/2015	<b>Closed:</b> 10/20/2015
<b>Problem:</b> PM			
- pm	<b>Parts List</b>	<b>Qty</b>	
- replace two tires mount balance add n2 rotate to front	Napagold Oil Filter	1.00	
- replace steering wheel cover	Napa Quart 5w20	5.00	
- Shop Supplies	Wiper Blade	2.00	
	Washer Fluid Concentr	1.00	
	Mac Wite Lithium Gres	2.00	
	183482418 P225-70r15	2.00	
	Stg Wheel Cov - Ford	1.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	2.00	
Hours 4.00	Labor: 240.00	Parts: 373.10	Total: 613.10
:			
<b>Workorder:</b> 1604544	<b>Meter:</b> 30590	<b>In Date:</b> 04/29/2016	<b>Closed:</b> 05/06/2016
<b>Problem:</b> Pm service			
- Pm service.	<b>Parts List</b>	<b>Qty</b>	
- Replace two rear tires.balance Four tires Rotate new tires to front.	Napagold Oil Filter	1.00	
- Replace both lower ball joints.	Napa Quart 5w20	5.00	
- Replace broken shifter indicator	18" wiper blades	2.00	
- Repaired third brake light and tag lights.	Washer Fluid Concentr	1.00	
- Shop Supplies	Napagold Fuel Filter	1.00	
	Napagold Air Filter	1.00	
	183482418 P225-70r15	2.00	
	Lower Ball Joint	2.00	
	Shift indicator	1.00	
	Bulb	2.00	
	Bulb	2.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	2.00	
Hours 11.50	Labor: 690.00	Parts: 445.77	Total: 1,135.77
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1605694	<b>Meter:</b> 31196	<b>In Date:</b> 06/02/2016	<b>Closed:</b> 06/14/2016
<b>Problem:</b> NEW BATTERY			
- C/c battery.test battery..bad.check charging system.replace battery.	<b>Parts List</b>	<b>Qty</b>	
	Battery	1.00	
- Shop Supplies	Shop Supplies	1.00	
Hours 0.75	Labor: 45.00	Parts: 99.89	Total: 144.89
:			
<b>Workorder:</b> 1611195	<b>Meter:</b> 32973	<b>In Date:</b> 10/28/2016	<b>Closed:</b> 11/21/2016
<b>Problem:</b> P.M.SERVICE			
- Pm Service	<b>Parts List</b>	<b>Qty</b>	
- Rotate and balance all .add N2.	Napagold Oil Filter	1.00	
- Shop Supplies	Napa Quart 5w20	5.00	
	Shop Supplies	1.00	
Hours 2.75	Labor: 165.00	Parts: 23.05	Total: 188.05
:			
<b>Workorder:</b> 1700067	<b>Meter:</b> 33421	<b>In Date:</b> 12/02/2016	<b>Closed:</b> 01/04/2017
<b>Problem:</b> Damage to left front fender, left door & lower panel			
- Damage to left front fender, left door & lower panel			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1704669	<b>Meter:</b> 35658	<b>In Date:</b> 05/10/2017	<b>Closed:</b> 05/22/2017
<b>Problem:</b> PM Service			
- Pm Service	<b>Parts List</b>	<b>Qty</b>	
- Replace both front rotors,all wheel bearings,grease seals,front pads and service calipers.	Napagold Oil Filter	1.00	
	Napa Quart 5w20	5.00	
- Rotate and balance tires.	18" wiper blades	2.00	
- Shop Supplies	Napagold Fuel Filter	1.00	
	Napagold Air Filter	1.00	
	Disc Brake Pads	1.00	
	Tappered Bearing Set	2.00	
	Tappered Bearing Set	2.00	
	Napa Oil Seal	2.00	
	Non-chlor Brake Clnr	1.00	
	Brake Rotor Hub	2.00	
	Shop Supplies	1.00	
Hours 7.25	Labor: 435.00	Parts: 265.64	Total: 700.64
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1710826	<b>Meter:</b> 38113	<b>In Date:</b> 11/01/2017	<b>Closed:</b> 11/13/2017
<b>Problem:</b> P.M.SERVICE			
- Pm Service.	<b>Parts List</b>	<b>Qty</b>	
- Replace both stabilizer link assemblies	Napagold Oil Filter	1.00	
- Replace water pump and coolant service and flush.	Napa Quart 5w20	5.00	
- Rotate and balance four tires.	18" wiper blades	2.00	
- Vacume debris from air cowl system and engine compartment.	Washer Fluid Concentr	1.00	
- Shop Supplies	Sway Bar Repair Kit	1.00	
	New Water Pump	1.00	
	Peak Global Antifrz	1.00	
	Shop Supplies	1.00	
Hours 9.50	Labor: 570.00	Parts: 110.65	Total: 680.65
:			
<b>Workorder:</b> 1712129	<b>Meter:</b> 38568	<b>In Date:</b> 12/11/2017	<b>Closed:</b> 12/18/2017
<b>Problem:</b> Flat tire and left head lamp inop			
- Replace headlamp bulb.fabricate and repair harness and connector for left headlamp.	<b>Parts List</b>	<b>Qty</b>	
- Repair and balance left rear tire.nitrogen fill all.reset Tpms.	Halogen Capsule	1.00	
- Shop Supplies	Shop Supplies	1.00	
Hours 2.00	Labor: 120.00	Parts: 10.72	Total: 130.72
:			
<b>Workorder:</b> 1804294	<b>Meter:</b> 41373	<b>In Date:</b> 04/25/2018	<b>Closed:</b> 04/30/2018
<b>Problem:</b> P.M.SERVICE, RECALL #16S26/16V384.			
- Pm Service.	<b>Parts List</b>	<b>Qty</b>	
- Remove blower motor,clean evaporator case and reinstall.	Napagold Oil Filter	1.00	
- Transport vehicle to and from dealer for performing safety recall #16s26d	Napa Quart 5w20	5.00	
- Shop Supplies	18" wiper blades	2.00	
	Washer Fluid Concentr	1.00	
	Napagold Fuel Filter	1.00	
	Napagold Air Filter	1.00	
	Shop Supplies	1.00	
Hours 6.50	Labor: 390.00	Parts: 48.59	Total: 438.59
:			
<b>Workorder:</b> 1804980	<b>Meter:</b> 41781	<b>In Date:</b> 05/14/2018	<b>Closed:</b> 05/21/2018
<b>Problem:</b> Right rear turnsignal light inop.Left front tire flat.			
- Test and replace bad right rear signal lamp bulb.clean and repair socket.	<b>Parts List</b>	<b>Qty</b>	
- Repair and balance left front tire.	Boxed Miniatures	1.00	
- Shop Supplies	Shop Supplies	1.00	
Hours 1.50	Labor: 90.00	Parts: 2.77	Total: 92.77
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1810551	<b>Meter:</b> 44582	<b>In Date:</b> 10/15/2018	<b>Closed:</b> 10/30/2018
<b>Problem:</b> PM Service.Right front tire flat.			
- Pm Service.	<b>Parts List</b>	<b>Qty</b>	
- Replace four tires.	Napa Quart 5w20	5.00	
- Shop Supplies	Napagold Oil Filter	1.00	
	18" wiper blades	2.00	
	Washer Fluid Concentr	1.00	
	183482418 P225-70r15	4.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	4.00	
Hours 4.00	Labor: 268.00	Parts: 613.15	Total: 881.15
:			
<b>Workorder:</b> 1901832	<b>Meter:</b> 46444	<b>In Date:</b> 02/19/2019	<b>Closed:</b> 02/28/2019
<b>Problem:</b> Check engine light on.No power.			
- C/s ckeck engine light on.scan and found code P0304 and P0316 Perform pinpoint test and found bad coil pack.replace coil pack,spark plugs and wires.clear codes.	<b>Parts List</b>	<b>Qty</b>	
	Spark Plug	4.00	
	Coil Asy	1.00	
- Test drive before and after repairs.	Spark Plug Wire Set	1.00	
- Shop Supplies	Shop Supplies	1.00	
Hours 5.00	Labor: 335.00	Parts: 165.81	Total: 500.81
:			
<b>Workorder:</b> 1904775	<b>Meter:</b> 47549	<b>In Date:</b> 05/01/2019	<b>Closed:</b> 05/13/2019
<b>Problem:</b> PM			
- Pm Service.	<b>Parts List</b>	<b>Qty</b>	
- Repair right front headlamp.	Napagold Oil Filter	1.00	
- Shop Supplies	Napa Quart 5w20	5.00	
	Washer Fluid Concentr	1.00	
	18" wiper blades	2.00	
	Napagold Fuel Filter	1.00	
	Napagold Air Filter	1.00	
	Boxed Capsules	1.00	
	Shop Supplies	1.00	
Hours 3.00	Labor: 201.00	Parts: 61.56	Total: 262.56
:			
<b>Workorder:</b> 1905969	<b>Meter:</b> 48064	<b>In Date:</b> 06/06/2019	<b>Closed:</b> 06/17/2019
<b>Problem:</b> L/REAR SIGNAL LIGHT INOP.			
- Repair left rear signal light.	<b>Parts List</b>	<b>Qty</b>	
	Boxed Miniatures	1.00	
Hours 0.50	Labor: 33.50	Parts: 0.77	Total: 34.27
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1911481      **Meter:** 49988      **In Date:** 11/05/2019      **Closed:** 11/25/2019  
**Problem:** PM Service

- Pm Service.	<b>Parts List</b>	<b>Qty</b>
- Replace steering wheel cover.	Napa Quart 5w20	5.00
- Ck and replace bad battery.	Napagold Oil Filter	1.00
- Replace both front rotors,all wheel bearings,grease seals.service calipers and replace brake pads.	Washer Fluid Concentr	1.00
- Repair shifter lever and bushings.	18" wiper blades	2.00
- Shop Supplies	Ford Triton Pvc Swc	1.00
	Battery	1.00
	B Fluid Dot 3-32oz	1.00
	Permatex	1.00
	Non-chlor Brake Clnr	1.00
	Napa Oil Seal	2.00
	Tappered Bearing Set	2.00
	Tappered Bearing Set	2.00
	Brake Rotor Hub	2.00
	Disc Brake Pads	1.00
	Damper Assy	2.00
	Pin	1.00
	Pin	1.00
	Spring	1.00
	F3tz7I278a Bushing Sh	2.00
	Tube	1.00
	Lever	1.00
	Plunger	1.00
	Shop Supplies	1.00

Hours 11.00      Labor: 803.00      Parts: 665.68      Total: 1,468.68  
:

**Workorder:** 2004292      **Meter:** 52743      **In Date:** 04/29/2020      **Closed:** 05/11/2020  
**Problem:** PM Service.Check battery and charging system.

- Pm Service.	<b>Parts List</b>	<b>Qty</b>
- Replace damage battery.	Napagold Oil Filter	1.00
- Rotate and balance tires.	Napa Quart 5w20	5.00
- Shop Supplies	18" wiper blades	2.00
	Washer Fluid Concentr	1.00
	Napagold Air Filter	1.00
	Napagold Fuel Filter	1.00
	Battery	1.00
	Shop Supplies	1.00

Hours 3.50      Labor: 255.50      Parts: 185.58      Total: 441.08  
:

**Workorder:** 2009432      **Meter:** 54771      **In Date:** 09/18/2020      **Closed:** 09/18/2020  
**Problem:** Transition Prep Charge

- Transition Prep Charge

Hours 2.00      Labor: 146.00      Parts: 0.00      Total: 146.00  
: