10198898 2015 FORD ESCAPE Suv, Mid Size

Workorder: Problem:	1508750 1061 - Pre De	Meter: livery Insp	308 ection			In Date:	09/01/2015	Closed:	09/01/2015
- Pre Delivery	/ Inspection								
	Hours	s 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00
Workorder: Problem:	1600922 Pm service.	Meter:	7705			In Date:	01/27/2016	Closed:	01/28/2016
- Pm service.					Parts L	ist			Qty
- Rotate and I	balance all four	tires.			5w20 Eı	ngine Oil			6.00
- Shop Suppli	ies				Napago	ld Oil Filter			1.00
					Washer	Fluid Conce	entr		1.00
					Mac Ba	ttery Protect	t		1.00
					Shop St	upplies			1.00
	Hours	s 3.00		Labor:	180.00	Parts:	25.67	Total:	205.67
Workorder: Problem:	1604604 P.M. service.	Meter:	14067			In Date:	05/02/2016	Closed:	05/05/2016
- P.m. Service	9.				Parts L	ist			Qty
- Rotate and I	balance all tires	i.			Napago	ld Oil Filter			1.00
- Shop Suppli	ies				5w20 Eı	ngine Oil			6.00
					Washer	Fluid Conce	entr		1.00
					Accufit I	Beam			2.00
					Blade				1.00
					Used Fi	re X Refurbi	ished		1.00
					Shop St	upplies			1.00
	Hours	s 3.00		Labor:	180.00	Parts:	91.64	Total:	271.64
Workorder: Problem:	1606938 P.M. service	Meter:	20570			In Date:	07/11/2016	Closed:	07/25/2016
- P.m. Service	Э.				Parts L	ist			Qty
- Replace and	d balance four n	new tires.			5w20 Eı	ngine Oil			6.00
- Complete w	heel alignment.	test drive.			Napago	ld Oil Filter			1.00
- Shop Suppli	ies				P235 55	5r17 Fuel Ma	ax		4.00
					Shop St	upplies			1.00
					Tire Dis	posal Fee			4.00
	Hours	s 6.50		Labor:	390.00	Parts:	693.58	Total:	1,083.58

Workorder: Problem:	1610053 P.M. service.	Meter:	25616			In Date:	09/26/2016	Closed:	09/28/20	016
- P.m. Service	Э.				Parts Li	st				Qty
- Rotatev and	abalnce all tire	es.			5w20 Er	ngine Oil				6.00
- Shop Suppli	es				Napago	d Oil Filter				1.00
					Accufit E	Beam				2.00
					Wpr/blde	Э				1.00
					Washer	Fluid Conc	entr			1.00
					Shop Su	ıpplies				1.00
	Hou :	rs 3.00		Labor:	180.00	Parts:	62.11	Total:	242.11	
Workorder: Problem:	1613072 P.M. Service.	Meter: Recall	32370			In Date:	12/27/2016	Closed:	01/17/20	017
- P.m. Service	e.				Parts Li	st				Qty
- Rotate and b	palance tires.				5w20 Er	ngine Oil				6.00
	hicle to dealer	for recall	#15c06 and lea	aking	Napago	d Oil Filter				1.00
right rear shoo					Accufit E	Beam				2.00
- Shop Suppli	es				Wpr/blde	Э				1.00
					Washer	Fluid Conc	entr			1.00
					Shop Su	ıpplies				1.00
	Hou :	rs 5.00		Labor:	300.00	Parts:	62.11	Total:	362.11	
Workorder: Problem:	1700927 Had to jump s	Meter: start in A/M	33909 I.			In Date:	01/30/2017	Closed:	02/14/20	017
	attery and test				Parts Li	st				Qty
test.replace de	•	and retes	t.system pass.		Battery					1.00
- Shop Suppli	es				Shop Su	ıpplies				1.00
	Hou :	rs 1.00		Labor:	60.00	Parts:	149.99	Total:	209.99	
Workorder:	1702421 Right front tire	Meter: e going flat	36196			In Date:	03/09/2017	Closed:	03/16/20	017
Problem:										
	palance right fr	ont tire.			Parts Li	st				Qty
	•	ont tire.			Parts Li Shop Su					Qty 1.00

Problem:	1703296 P.M. service.	Meter:	37648		In	Date:	04/03/2017	Closed:	04/18/20	017
- P.m. Service	e.				Parts List					Qty
- Replace lea	king left rear s	hock.			Seat R And	R				1.00
- R&r driver s	eat for upholst	ery repairs.			5w20 Engin	e Oil				6.00
- Replacev tw	vo tires,rotate a	and balance	all four.		Napagold O	il Filter				1.00
- Shop Suppli	ies				Washer Flui	id Conc	entr			1.00
					Accufit Bear	m				2.00
					Wiper Blade)				1.00
					Napa Cabin	Air Filte	er			1.00
					Used Fire X	Refurb	ished			1.00
					235/55r17 A	Assurand	ce			2.00
					Shock Abso	ber				1.00
					Shop Suppl	ies				1.00
					Tire Disposa	al Fee				2.00
	Hou :	ırs 5.80		Labor:	348.00	Parts:	772.04	Total:	1,120.04	4
Workorder: Problem:	1705170 Left rear tire	Meter: going flat.	40027		In	Date:	05/25/2017	Closed:	05/25/20	017
- Renair left r	مطلمه مسلامه	lance nitro	gen fill tires.		Parts List					Qty
Nopali lett II	ear tire and ba	nanco initro	90		rails List					٠.,
- Shop Suppli		narioo iniiro	gori iii iii coi		Shop Suppl	ies				1.00
•	ies	ırs 1.00	go., a. co.	Labor:	Shop Suppl	ies Parts:	2.00	Total:	62.00	•
- Shop Suppli	ies	nrs 1.00	43012	Labor:	Shop Suppl 60.00		2.00	Total:	62.00	1.00
- Shop Suppli	ies Hou : 1707435 P.M. service.	nrs 1.00		Labor:	Shop Suppl 60.00	Parts:				1.00
- Shop Suppli Workorder: Problem: - P.m. service	ies Hou : 1707435 P.M. service.	Meter:		Labor:	Shop Suppl 60.00	Parts:				1.00
- Shop Suppli Workorder: Problem: - P.m. service	ies Hou : 1707435 P.M. service. e. balance four til	Meter:		Labor:	Shop Suppl 60.00 In Parts List	Parts: Date: e Oil				1.00 017 Qty
- Shop Suppli Workorder: Problem: - P.m. service - Rotate and I	ies Hou : 1707435 P.M. service. e. balance four til	Meter:		Labor:	Shop Suppl 60.00 In Parts List 5w20 Engin	Parts: Date: e Oil bil Filter				1.00 017 Qty 6.00
- Shop Suppli Workorder: Problem: - P.m. service - Rotate and I	ies Hou : 1707435 P.M. service. e. balance four til	Meter:		Labor:	Shop Suppl 60.00 In Parts List 5w20 Engin Napagold C	Parts: Date: e Oil oil Filter m	07/31/2017			1.00 017 Qty 6.00 1.00
- Shop Suppli Workorder: Problem: - P.m. service - Rotate and I	ies Hou : 1707435 P.M. service. e. balance four til	Meter:		Labor:	Shop Suppl 60.00 In Parts List 5w20 Engin Napagold O Accufit Bear	Parts: Date: e Oil bil Filter m id Conce	07/31/2017			1.00 017 Qty 6.00 1.00 2.00

Workorder: 17 Problem: P.	10994 M. service.	Meter:	48038			In Date:	11/06/2017	Closed:	11/09/20)17
- P.m. service.					Parts Li	ist				Qty
- Inspect and rep	lace two wo	rn tires on	front .rotate a	nd high	5w20 Er	ngine Oil				6.00
speed balance all	four wheels	nitro fill a	ıll.		Napago	ld Oil Filter				1.00
- Inspect all brake				ds	Wiper B	lade				1.00
resurface both fro			•		Wiper B	lade				1.00
- Install missing l			ouii nandie.		Blade					1.00
- Perform comple	te alignmen	ι.			Washer	Fluid Conce	entr			1.00
- Shop Supplies					P235 55	5r17 Fuel Ma	ЭX			2.00
					Brake P	ad				1.00
					Interior	Door Handle	e			1.00
					Non-chl	or Brake Clr	nr			1.00
					Shop Su	upplies				1.00
					Tire Dis	posal Fee				2.00
	Hours :	9.70		Labor:	582.00	Parts:	562.40	Total:	1,144.40)
Workorder: 18 Problem: P.	00718 M. service.	Meter:	53216			In Date:	01/22/2018	Closed:	01/29/20)18
- P.m. service.					Parts Li	ist				Qty
- Two new tires n	nounted on t	ront.nitro	gen fill and hig	h speed	Washer	Fluid Conce	entr			1.00
balance all four.					5w20 Er	ngine Oil				6.00
- Shop Supplies					Napago	ld Oil Filter				1.00
					Used Fi	re X Refurbi	shed			1.00
					P235 55	5r17 Fuel Ma	ax			2.00
					Shop St	upplies				1.00
					Tire Dis	posal Fee				2.00
	Hours :	3 4.00		Labor:	240.00	Parts:	378.93	Total:	618.93	
Workorder: 18 Problem: Rig	01918 ght front tire	Meter: flat ,spare	54357 e on vehicle.			In Date:	02/20/2018	Closed:	02/21/20)18
- Repair right fror	nt tire				Parts Li	ist				Qty
- Shop Supplies					Shop Su	upplies				1.00
	Hours	3 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: 18 Problem: Fla	01961	Meter:	54321			In Date:	02/17/2018	Closed:	02/21/20)18
i iobiciii.	at Tire									
- Tire Service Ok			Γire							

Workorder: Problem:	1803428 Check brakes	Meter: ,failing.	56845		l:	n Date:	04/02/2018	Closed:	04/05/20)18
- Road test .s	can for codes ,ı	no codes .	inspect all bra	akes	Parts List	:				Qty
	rear rotors and				brake fluid	i				2.00
test.	lt on rotors .flus	n and blee	ed brake syste	em .roau	Brk Fluid [Oot 4-12o	Z			3.00
- Shop Suppli	es				Brake Pad	d Real				1.00
					Front Bra	ke Rotor				2.00
					Shop Supp	plies				1.00
	Hours :	s 3.00		Labor:	180.00	Parts:	208.48	Total:	388.48	
Workorder: Problem:	1803723 A/C not working	Meter:	57160 and check bl	luetooth .		n Date:	04/09/2018	Closed:	04/26/20)18
- Computer di	iagnoise sync p	roblem .ne	o communicat	ion with	Parts List	İ				Qty
	erform Adim m			.replace	Usb Cable)				1.00
-	rogram to latest				Apim Unit					1.00
	performance to and complete				Freon Lv S	Shop 1				2.00
	place cabin air		, ,,,,,		Napa Cab	in Air Filte	er			1.00
- Shop Suppli	es				Shop Supp	plies				1.00
	Hours :	s 6.00		Labor:	360.00	Parts:	519.29	Total:	879.29	
Workorder: Problem:	1804764 P.M. service.	Meter:	58097		lı	n Date:	05/07/2018	Closed:	05/14/20)18
- P.m. service).				Parts List	t				Qty
	st and inspect c	ooling sys	tem . Flush sy	/stem	Wd40 Spr					1.00
and refill.					Anti Freez	e Motorci	raft			1.00
 Replace bot 	h rear leaking s				5w20 Eng	ine Oil				6.00
•	niah sabad hala	ince all foi	ır tıres.		Napagold	Oil Filter				1.00
- Rotate and h	•									
•	•				Rear Shoo	ck				2.00
- Rotate and h	•				Rear Shoo Shop Supp					1.00

Workorder: 1807703 Meter: 62640 Problem: P.M. service and right headlight inop.			In Date:	07/30/2018	Closed:	08/01/20	018
- P.m. service.		Parts Lis	st				Qty
- Replace two tires . Rotate and balance all four tires	i.	Napagolo	d Oil Filter				1.00
Nitrofill.		5w20 En	gine Oil				6.00
- Service transmision . Drain and refill.		Blade					1.00
- Test and replace right low beam headlight bulb.		Wiper Bla	ade				1.00
- Shop Supplies		Wiper Bla	ade				1.00
		Washer F	Fluid Conce	entr			1.00
		Ford Trite	on Pvc Sw	C			1.00
		Napa Ca	bin Air Filte	er			1.00
		P235 55r	17 Fuel Ma	ax			2.00
		oil auto					9.00
		Blister Pa	ack Capsul	es			1.00
		Shop Sup	pplies				1.00
		Tire Disp	osal Fee				2.00
Hours 5.80 :	Labor:	348.00	Parts:	533.91	Total:	881.91	
Workorder: 1810556 Meter: 66942 Problem: Left tag light inop.			In Date:	10/15/2018	Closed:	10/17/20	018
- Diagnose tag light inop.replace bulb and retest.		Parts Lis	st				Qty
		Boxed M	iniatures				1.00
Hours 0.30 :	Labor:	20.10	Parts:	0.60	Total:	20.70	
Workorder: 1811158 Meter: 67699 Problem: P.M. service.			In Date:	10/30/2018	Closed:	11/06/20	018
- P.m. service.		Parts Lis	st				Qty
- Inspect and replace upper front engine mount .		Napagolo	d Oil Filter				1.00
- Rotate and high speed balance all four wheels . Nit	rofill all.	Napa Qu	art 5w20				6.00
- Shop Supplies		Wiper Bla	ade				1.00
		Wiper Bla	ade				1.00
		Blade					1.00
		Washer F	Fluid Conce	entr			1.00
		Lug Nut					2.00
		Bracket					1.00
		Shop Sup	pplies				1.00
Hours 4.30	Labor:	288.10	Parts:	180.11	Total:	468.21	
Workorder: 1901187 Meter: 72369 Problem: Tire pressure sensor fault .			In Date:	01/31/2019	Closed:	02/07/20	019
- Diagnose tire pressure sensor fault . Replace left fr	ont tire	Parts Lis	st				Qty
pressure sensor and retrain all four sensors . Retest .		Tpms12	Sensor Tire	e Pr			1.00
- Shop Supplies		Shop Su					1.00
Hours 1.00							
110015 1.00	Labor:	67.00	Parts:	78.89	Total:	145.89	

	901560 P.M. service.	Meter:	72790			In Date:	02/11/2019	Closed:	02/14/20	19
	.ivi. service.				Danta Lia					04
- P.m. service.	ont tiron Hi	anaad hala	anaa all faur ti	iroo ond	Parts Lis					Qty
 Replace two fr nitrogen fill all. 	ont lires . Hi	speed bala	ance an lour u	ires and	Napagold					1.00 6.00
- Complete four	wheel alignn	nent and ro	oad test .		5w20 Eng	girie Oii x Refurbi	ishad			1.00
- Shop Supplies	_				Blade	X IXCIUIDI	isiicu			1.00
					Wiper Bla	ade				1.00
					Wiper Bla					1.00
					Tire235/5					2.00
					Shop Sup					1.00
					Tire Dispo	•				2.00
	Hours	s 6.50		Labor:	435.50		473.02	Total:	908.52	
Workorder: 1 Problem: H	902052 lad to jump s	Meter: tart.	73016			In Date:	02/25/2019	Closed:	02/27/20)19
- Charge battery	y fully . Test b	oattery and	I charging sys	stem .	Parts Lis	t				Qty
Battery failed loa			attery .replac	e	Bat Cable)				1.00
corroded negative	•	oie.			Battery					1.00
- Shop Supplies	i				Shop Sup	plies				1.00
	Hours	s 1.50		Labor:	100.50	Parts:	244.50	Total:	345.00	
Workorder: 1 Problem: P	905582 P.M. service.	Meter:	77944			In Date:	05/28/2019	Closed:	05/31/20)19
		Meter:	77944		Parts Lis		05/28/2019	Closed:	05/31/20)19 Qty
Problem: P - P.m. service Diagnose popp	P.M. service. Ding /clicking	noise on t		th		t	05/28/2019	Closed:	05/31/20	
Problem: P - P.m. service Diagnose popp defective front as	P.M. service. Ding /clicking xles . Road to	noise on t	urns . R&r boʻ		Parts Lis	.t I Oil Filter	05/28/2019	Closed:	05/31/20	Qty
Problem: P - P.m. service Diagnose popp defective front as - Perform transr	P.M. service. Ding /clicking xles . Road to mission service.	noise on t	urns . R&r boʻ		Parts Lis	.t I Oil Filter	05/28/2019	Closed:	05/31/20	Qty 1.00
Problem: P - P.m. service Diagnose popp defective front as - Perform transr discoloration and	P.M. service. ping /clicking xles . Road to mission service d smell.	noise on t est . ce . Flush a	urns . R&r bo		Parts Lis Napagold 5w20 Eng	i t I Oil Filter gine Oil	05/28/2019	Closed:	05/31/20	Qty 1.00 6.00
Problem: P - P.m. service Diagnose popp defective front as - Perform transr discoloration and - Rotate and bal	oing /clicking xles . Road to mission serviol d smell. lance all four	noise on t est . ce . Flush a	urns . R&r bo		Parts Lis Napagold 5w20 Eng Blade Wiper Bla Wiper Bla	it I Oil Filter gine Oil ade ade		Closed:	05/31/20	Qty 1.00 6.00 1.00
Problem: P - P.m. service Diagnose popp defective front as - Perform transr discoloration and	oing /clicking xles . Road to mission serviol d smell. lance all four	noise on t est . ce . Flush a	urns . R&r bo		Parts Lis Napagold 5w20 Eng Blade Wiper Bla Wiper Bla	it I Oil Filter gine Oil ade		Closed:	05/31/20	Qty 1.00 6.00 1.00 1.00
Problem: P - P.m. service Diagnose popp defective front as - Perform transr discoloration and - Rotate and bal	oing /clicking xles . Road to mission serviol d smell. lance all four	noise on t est . ce . Flush a	urns . R&r bo		Parts Lis Napagold 5w20 Eng Blade Wiper Bla Wiper Bla Mac Wite oil auto	it I Oil Filter gine Oil ade ade Lithium G		Closed:		Qty 1.00 6.00 1.00 1.00 1.00 1.00
Problem: P - P.m. service Diagnose popp defective front as - Perform transr discoloration and - Rotate and bal	oing /clicking xles . Road to mission serviol d smell. lance all four	noise on t est . ce . Flush a	urns . R&r bo		Parts Lis Napagold 5w20 Eng Blade Wiper Bla Wiper Bla Mac Wite	it I Oil Filter gine Oil ade ade Lithium G		Closed:		Qty 1.00 6.00 1.00 1.00 1.00 1.00 13.00
Problem: P - P.m. service Diagnose popp defective front as - Perform transr discoloration and - Rotate and bal	oing /clicking xles . Road to mission serviol d smell. lance all four	noise on t est . ce . Flush a	urns . R&r bo		Parts Lis Napagold 5w20 Eng Blade Wiper Bla Wiper Bla Mac Wite oil auto Left Front Shaft Ass	t I Oil Filter gine Oil ade ade Lithium G t Axle	res	Closed:		Qty 1.00 6.00 1.00 1.00 1.00 1.00 1.00 1.00
Problem: P - P.m. service Diagnose popp defective front as - Perform transr discoloration and - Rotate and bal	P.M. service. pring /clicking xles . Road to mission serviced smell. Ilance all four services	noise on test. ce . Flush a tires . Nitr	urns . R&r bo	to	Parts Lis Napagold 5w20 End Blade Wiper Bla Wiper Bla Mac Wite oil auto Left Front Shaft Ass Shop Sup	t I Oil Filter gine Oil ade ade Lithium G t Axle	res	Closed:		Qty 1.00 6.00 1.00 1.00 1.00 1.00 13.00
Problem: P - P.m. service Diagnose popp defective front as - Perform transr discoloration and - Rotate and bal	P.M. service. pring /clicking xles . Road to mission serviced smell. Ilance all four services	noise on t est . ce . Flush a	urns . R&r bo	to	Parts Lis Napagold 5w20 Eng Blade Wiper Bla Wiper Bla Mac Wite oil auto Left Front Shaft Ass	at I Oil Filter gine Oil ade ade Lithium G t Axle by Motorcra	res			Qty 1.00 6.00 1.00 1.00 1.00 1.00 1.00 1.00
Problem: P - P.m. service Diagnose popple defective front as a reference transfer discoloration and resolution Rotate and bales and Shop Supplies.	P.M. service. pring /clicking xles . Road to mission service dismell. lance all four to the four to	noise on test. ce . Flush a tires . Nitre	urns . R&r boand refill due ogen fill all.	to	Parts Lis Napagold 5w20 Eng Blade Wiper Bla Wiper Bla Mac Wite oil auto Left Front Shaft Ass Shop Sup 589.60	at I Oil Filter gine Oil ade ade Lithium G t Axle by Motorcra	res			Qty 1.00 6.00 1.00 1.00 1.00 1.00 1.00 1.00
Problem: P - P.m. service Diagnose popp defective front as - Perform transr discoloration and - Rotate and ball - Shop Supplies Workorder: 1 Problem: L	P.M. service. pring /clicking xles . Road to mission service dismell. lance all four significations and the service all four significance all four signi	noise on test. ce . Flush a tires . Nitro 8 8.80 Meter: headlight	urns . R&r boand refill due ogen fill all. 81267 inop.	to	Parts Lis Napagold 5w20 Eng Blade Wiper Bla Wiper Bla Mac Wite oil auto Left Front Shaft Ass Shop Sup 589.60	ot I Oil Filter gine Oil ade ade Lithium G t Axle by Motorcra pplies Parts: In Date:	res aft 621.41	Total:	1,211.01	Qty 1.00 6.00 1.00 1.00 1.00 1.00 1.00
Problem: P - P.m. service Diagnose popp defective front as - Perform transr discoloration and - Rotate and bal - Shop Supplies Workorder: 1	P.M. service. pring /clicking xles . Road to mission service dismell. lance all four significations and the service all four significance all four signi	noise on test. ce . Flush a tires . Nitro 8 8.80 Meter: headlight	urns . R&r boand refill due ogen fill all. 81267 inop.	to	Parts Lis Napagold 5w20 Eng Blade Wiper Bla Wiper Bla Mac Wite oil auto Left Front Shaft Ass Shop Sup 589.60	ot I Oil Filter gine Oil ade ade Lithium G t Axle by Motorcra oplies Parts: In Date:	res aft 621.41	Total:	1,211.01	Qty 1.00 6.00 1.00 1.00 1.00 1.00 1.00 1.00

- Test drive . Replace both front lowwer control arms and hub bearings . Road test Replace two worn front tires and balance .nitrofill all Perform complete four wheel alignment and road test Shop Supplies	Workorder: Problem:	1908090 Engine starte	Meter: ed shaking,	82238 No power, C	EL on.		In Date:	08/05/2019	Closed:	08/13/2019
body. Clear codes and retest Perform air intake decarb and cleaning . Flush injectors Perform tune up . Replace all four spark plugs Test drive . Replace both front lowwer control arms and hubbarnings . Road test Replace two worn front tires and balance .nitrofill all Perform complete four wheel alignment and road test Shop Supplies - Road test Replace two worn front tires and balance .nitrofill all Perform complete four wheel alignment and road test Shop Supplies - Tire Disposal Fee - Hours 16.00 Labor: 1,072.0 Parts: 1,176.15 Total: 2,248.15 or Tow From: Jpp admin building To: vista Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00 Workorder: 1908653 Meter: 82769 In Date: 08/19/2019 Closed: 08/26/20 Problem: P.M. service Possibalance and rotate all four tires . Nitrofill all Shop Supplies - Hours 3.00 Labor: 201.00 Parts: 97.31 Total: 298.31 Workorder: 1908958 Meter: 83081 In Date: 08/27/2019 Closed: 08/29/20 Problem: Left side parking light inop Remove left front inner fender well to test and replace parking light bulbs Test and replace right low beam headlight bulb Shop Supplies - Tipest and replace right low beam headlight bulb Shop Supplies							st			Qty
- Perform air intake decarn and cleaning . Flush injectors Perform tune up . Replace all four spark plugs Test drive . Replace both front lowwer control arms and hub bearings . Road test Replace two worn front tires and balance .nitrofill all Perform complete four wheel alignment and road test Shop Supplies				dolootivo tili	ottio		21			1.00
- Perform tune up . Replace all four spark plugs . Test drive . Replace both front lower control arms and hub bearings . Road test Replace two worn front tires and balance .nitrofill all Perform complete four wheel alignment and road test Shop Supplies - Hours 16.00 Labor: 1,072.0 Parts: 1,176.15 Total: 2,248.15 OPTOBEM: engine started shaking, died, no power, now the engine fault light is on Tow From: Jpp admin building To: vista - Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00 - Problem: P.M. service P.m. service Balance and rotate all four tires . Nitrofill all Shop Supplies - Hours 3.00 Labor: 201.00 Parts: 97.31 Total: 298.31 - Workorder: 1908958 Meter: 83081 In Date: 08/27/2019 Closed: 08/29/20 - Problem: Left side parking light inop Remove left front inner fender well to test and replace parking light bulbs Test and replace right low beam headlight bulb Shop Supplies - Shop Supplies	- Perform air	intake decarb	and cleanir	ng . Flush inje	ectors.	-				1.00
Test drive . Replace both front lowwer control arms and hub bearings . Road test . Replace two worn front tires and balance .nitrofill all Perform complete four wheel alignment and road test Replace two worn front tires and balance .nitrofill all Perform complete four wheel alignment and road test Shop Supplies Tire 235/55/17 Mic Shop Supplies Tire 235/55/17 Mic Shop Supplies Tire Disposal Fee Hours 16.00 Labor: 1,072.0 Parts: 1,176.15 Total: 2,248.15 Problem: engine started shaking, died, no power, now the engine fault light is on Tow From: Jpp admin building To: vista Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00 Workorder: 1908653 Meter: 82769 In Date: 08/19/2019 Closed: 08/26/20 Problem: P.M. service Parts List Balance and rotate all four tires . Nitrofill all Shop Supplies Hours 3.00 Labor: 201.00 Parts: 97.31 Total: 298.31 Workorder: 1908958 Meter: 83081 In Date: 08/27/2019 Closed: 08/29/20 Remove left front inner fender well to test and replace parking light bulbs Test and replace right low beam headlight bulb Shop Supplies .	- Perform tun	e up . Replace	e all four sp	ark plugs .						1.00
- Perform complete four wheel alignment and road test . - Shop Supplies - Hours 16.00 - Labor: 1,072.0 - Parts: 1,176.15 - Total: 2,248.15 - O - In Date: 08/05/2019 - Closed: 08/06/20 - Problem: engine started shaking, died, no power, now the engine fault light is on. - Tow From: Jpp admin building To: vista - Hours 0.00 - Labor: 0.00 - Parts: 0.00 - Parts: 0.00 - Total: 0.00 - Problem: P.M. service - P.m. service Balance and rotate all four tires . Nitrofill all Shop Supplies - Hours 3.00 - Labor: 201.00 - Parts: 97.31 - Total: 298.31 - Workorder: 1908958 - Hours 3.00 - Labor: 201.00 - Parts: 97.31 - Total: 298.31 - Total: 298.31 - Remove left front inner fender well to test and replace parking light bulbs - Test and replace right low beam headlight bulb - Shop Supplies			front lowwe	r control arm	s and hub	•	•			4.00 2.00
- Shop Supplies	- Replace two	o worn front tir	es and bala	nce .nitrofill a	all.	Bering				2.00
Tire235/55/17 Mic Shop Supplies Tire Disposal Fee Hours 16.00 Labor: 1,072.0 Parts: 1,176.15 Total: 2,248.15 Workorder: 1908145 Meter: 82152 In Date: 08/05/2019 Closed: 08/06/20 Problem: engine started shaking, died, no power, now the engine fault light is on. - Tow From: Jpp admin building To: vista Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00 Workorder: 1908653 Meter: 82769 In Date: 08/19/2019 Closed: 08/26/20 Problem: P.M. service. - P.m. service Balance and rotate all four tires . Nitrofill all Shop Supplies Hours 3.00 Labor: 201.00 Parts: 97.31 Total: 298.31 Workorder: 1908958 Meter: 83081 In Date: 08/27/2019 Closed: 08/29/20 Problem: Left side parking light inop. - Remove left front inner fender well to test and replace parking light bulbs Test and replace right low beam headlight bulb Shop Supplies Shop Supplies Flower Capsules Shop Supplies Flower Capsules Shop Supplies Shop Supplies Shop Supplies	- Perform cor	mplete four wh	eel alignme	ent and road t	est.	Control A	Arm Assy			1.00
Shop Supplies Tire Disposal Fee Hours 16.00 Labor: 1,072.0 Parts: 1,176.15 Total: 2,248.15 Workorder: 1908145 Meter: 82152 Problem: engine started shaking, died, no power, now the engine fault light is on. - Tow From: Jpp admin building To: vista Hours 0.00 Hours 0.00 Hours 0.00 Parts: 0.00	- Shop Suppl	ies				Arm Asy				1.00
Workorder: 1908145 Meter: 82152 In Date: 08/05/2019 Closed: 08/06/20 Problem: engine started shaking, died, no power, now the engine fault light is on. - Tow From: Jpp admin building To: vista Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00 Workorder: 1908653 Meter: 82769 In Date: 08/19/2019 Closed: 08/26/20 Problem: P.M. service . - P.m. service Balance and rotate all four tires . Nitrofill all Shop Supplies						Tire235/5	55/17 Mic			2.00
Hours 16.00 Labor: 1,072.0 Parts: 1,176.15 Total: 2,248.15						Shop Su	pplies			1.00
Workorder: 1908145 Meter: 82152 In Date: 08/05/2019 Closed: 08/06/20 Problem: engine started shaking, died, no power, now the engine fault light is on. - Tow From: Jpp admin building To: vista						Tire Disp	osal Fee			2.00
Problem: engine started shaking, died, no power, now the engine fault light is on. - Tow From: Jpp admin building To: vista		Ηου :	ırs 16.00		Labor:		Parts:	1,176.15	Total:	2,248.15
- Tow From: Jpp admin building To: vista	Workorder:	1908145	Meter:	82152			In Date:	08/05/2019	Closed:	08/06/2019
Problem: P.M. service . Parts List - P.m. service. Balance and rotate all four tires . Nitrofill all. Shop Supplies Sw20 Engine Oil Blade Wiper Blade Wiper Blade Used Fire X Refurbished Shop Supplies Hours 3.00 Labor: 201.00 Parts: 97.31 Total: 298.31 In Date: 08/27/2019 Closed: 08/29/20 Problem: Left side parking light inop. Remove left front inner fender well to test and replace parking light bulbs . Test and replace right low beam headlight bulb . Shop Supplies Parts List Boxed Miniatures Boxed Capsules Shop Supplies		Hou	urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
- Balance and rotate all four tires . Nitrofill all. - Shop Supplies - Hours 3.00 - Labor: - Workorder: 1908958 Meter: 83081 - Problem: Left side parking light inop. - Remove left front inner fender well to test and replace parking light bulbs . - Test and replace right low beam headlight bulb . - Shop Supplies		•								
- Shop Supplies 5w20 Engine Oil Blade Wiper Blade Wiper Blade Used Fire X Refurbished Shop Supplies Hours 3.00 Labor: 201.00 Parts: 97.31 Total: 298.31 Workorder: 1908958 Meter: 83081 Problem: Left side parking light inop. - Remove left front inner fender well to test and replace parking light bulbs . - Test and replace right low beam headlight bulb . - Shop Supplies - Shop Supplies - Shop Supplies				82769			In Date:	08/19/2019	Closed:	08/26/2019
Blade Wiper Blade Wiper Blade Used Fire X Refurbished Shop Supplies Hours 3.00 Labor: 201.00 Parts: 97.31 Total: 298.31 Workorder: 1908958 Meter: 83081 In Date: 08/27/2019 Closed: 08/29/20 Problem: Left side parking light inop. - Remove left front inner fender well to test and replace parking light bulbs Test and replace right low beam headlight bulb Shop Supplies Blade Wiper Blade Used Fire X Refurbished Shop Supplies 97.31 Total: 298.31 In Date: 08/27/2019 Closed: 08/29/20 Parts List Boxed Miniatures Boxed Capsules Shop Supplies	Problem:	P.M. service		82769		Parts Lis		08/19/2019	Closed:	08/26/2019 Qt y
Wiper Blade Wiper Blade Used Fire X Refurbished Shop Supplies Hours 3.00 Eabor: 201.00 Parts: 97.31 Total: 298.31 Workorder: 1908958 Meter: 83081 Problem: Left side parking light inop. - Remove left front inner fender well to test and replace parking light bulbs Test and replace right low beam headlight bulb Shop Supplies Wiper Blade Used Fire X Refurbished Shop Supplies 708/27/2019 Closed: 08/29/20 Parts List Boxed Miniatures Boxed Capsules Shop Supplies	Problem: - P.m. service	P.M. service e.					st	08/19/2019	Closed:	
Wiper Blade Used Fire X Refurbished Shop Supplies Hours 3.00 Labor: 201.00 Parts: 97.31 Total: 298.31 Workorder: 1908958 Meter: 83081 Problem: Left side parking light inop. - Remove left front inner fender well to test and replace parking light bulbs Test and replace right low beam headlight bulb Shop Supplies Wiper Blade Used Fire X Refurbished Shop Supplies Total: 298.31 In Date: 08/27/2019 Closed: 08/29/20 Parts List Boxed Miniatures Boxed Capsules Shop Supplies	Problem: - P.m. service - Balance and	P.M. service e. d rotate all fou				Napagolo	st d Oil Filter	08/19/2019	Closed:	Qty
Used Fire X Refurbished Shop Supplies Hours 3.00 Labor: 201.00 Parts: 97.31 Total: 298.31 Workorder: 1908958 Meter: 83081 In Date: 08/27/2019 Closed: 08/29/20 Problem: Left side parking light inop. - Remove left front inner fender well to test and replace parking light bulbs . Boxed Miniatures - Test and replace right low beam headlight bulb . Boxed Capsules - Shop Supplies Shop Supplies	Problem: - P.m. service - Balance and	P.M. service e. d rotate all fou				Napagolo 5w20 En	st d Oil Filter	08/19/2019	Closed:	Qty 1.00
Hours 3.00 Labor: 201.00 Parts: 97.31 Total: 298.31 Workorder: 1908958 Meter: 83081 In Date: 08/27/2019 Closed: 08/29/20 Problem: Left side parking light inop. - Remove left front inner fender well to test and replace parking light bulbs . Boxed Miniatures - Test and replace right low beam headlight bulb . Boxed Capsules - Shop Supplies Shop Supplies	Problem: - P.m. service - Balance and	P.M. service e. d rotate all fou				Napagolo 5w20 En Blade	st d Oil Filter gine Oil	08/19/2019	Closed:	Qty 1.00 6.00
Hours 3.00 Labor: 201.00 Parts: 97.31 Total: 298.31 Workorder: 1908958 Meter: 83081 In Date: 08/27/2019 Closed: 08/29/20 Problem: Left side parking light inop. - Remove left front inner fender well to test and replace parking light bulbs . Boxed Miniatures - Test and replace right low beam headlight bulb . Boxed Capsules - Shop Supplies Shop Supplies	Problem: - P.m. service - Balance and	P.M. service e. d rotate all fou				Napagolo 5w20 En Blade Wiper Bla	st d Oil Filter gine Oil ade	08/19/2019	Closed:	Qty 1.00 6.00 1.00
: Workorder: 1908958 Meter: 83081 In Date: 08/27/2019 Closed: 08/29/20 Problem: Left side parking light inop. - Remove left front inner fender well to test and replace parking light bulbs . - Test and replace right low beam headlight bulb . - Shop Supplies Shop Supplies	Problem: - P.m. service - Balance and	P.M. service e. d rotate all fou				Napagolo 5w20 En Blade Wiper Bla Wiper Bla	st d Oil Filter gine Oil ade ade		Closed:	Qty 1.00 6.00 1.00
Problem: Left side parking light inop. - Remove left front inner fender well to test and replace parking light bulbs . - Test and replace right low beam headlight bulb . - Shop Supplies Parts List Boxed Miniatures Boxed Capsules Shop Supplies	Problem: - P.m. service - Balance and	P.M. service e. d rotate all fou				Napagold 5w20 En Blade Wiper Bla Wiper Bla Used Fire	st d Oil Filter gine Oil ade ade ade		Closed:	Qty 1.00 6.00 1.00 1.00
parking light bulbs . Boxed Miniatures - Test and replace right low beam headlight bulb . Boxed Capsules - Shop Supplies Shop Supplies	Problem: - P.m. service - Balance and	P.M. service e. d rotate all fou ies	r tires . Nitro		Labor:	Napagold 5w20 En Blade Wiper Bla Wiper Bla Used Fire Shop Su	st d Oil Filter gine Oil ade ade e X Refurbi	ished		Qty 1.00 6.00 1.00 1.00 1.00 1.00
- Test and replace right low beam headlight bulb . Boxed Capsules - Shop Supplies Shop Supplies	Problem: - P.m. service - Balance and - Shop Suppl	P.M. service e. d rotate all fou ies Hou : 1908958	r tires . Nitro	ofill all. 83081	Labor:	Napagold 5w20 En Blade Wiper Bla Wiper Bla Used Fire Shop Su	st d Oil Filter gine Oil ade ade e X Refurbi pplies Parts:	ished 97.31	Total:	Qty 1.00 6.00 1.00 1.00 1.00 1.00
- Shop Supplies Shop Supplies	Problem: - P.m. service - Balance and - Shop Suppl Workorder: Problem: - Remove left	P.M. service e. d rotate all fou ies Hou : 1908958 Left side pari	r tires . Nitro	83081 op.		Napagold 5w20 En Blade Wiper Bla Wiper Bla Used Fire Shop Su 201.00	st d Oil Filter gine Oil ade ade e X Refurbi pplies Parts: In Date:	ished 97.31	Total:	Qty 1.00 6.00 1.00 1.00 1.00 298.31 Qty
Chop duppines	Problem: - P.m. service - Balance and - Shop Suppl Workorder: Problem: - Remove left parking light b	P.M. service e. d rotate all fou ies Hou : 1908958 Left side pari t front inner fer oulbs .	r tires . Nitro urs 3.00 Meter: king light in	83081 op.		Napagold 5w20 En Blade Wiper Bla Wiper Bla Used Fire Shop Su 201.00	st d Oil Filter gine Oil ade ade e X Refurbi pplies Parts: In Date: st	ished 97.31	Total:	Qty 1.00 6.00 1.00 1.00 1.00 298.31 08/29/2019 Qty 3.00
Hours 1.00 Labor: 67.00 Parts: 16.68 Total: 83.68	Problem: - P.m. service - Balance and - Shop Suppl Workorder: Problem: - Remove left parking light be - Test and re	P.M. service e. d rotate all fou ies Hou : 1908958 Left side park t front inner fer oulbs . place right low	r tires . Nitro urs 3.00 Meter: king light in	83081 op.		Napagold 5w20 En Blade Wiper Bla Wiper Bla Used Fire Shop Sul 201.00	st d Oil Filter gine Oil ade ade e X Refurbi pplies Parts: In Date: st liniatures apsules	ished 97.31	Total:	Qty 1.00 6.00 1.00 1.00 1.00 298.31 08/29/2019 Qty 3.00 1.00
	Problem: - P.m. service - Balance and - Shop Suppl Workorder: Problem: - Remove left parking light be - Test and re	P.M. service e. d rotate all fou ies Hou : 1908958 Left side part t front inner fer oulbs . place right low ies	r tires . Nitro r tires . Nitro Meter: king light incomplete well to beam head	83081 op.	ace	Napagold 5w20 En Blade Wiper Bla Wiper Bla Used Fire Shop Su 201.00 Parts Lis Boxed M Boxed C Shop Su	st d Oil Filter gine Oil ade ade e X Refurbi pplies Parts: In Date: st liniatures apsules	ished 97.31	Total:	Qty 1.00 6.00 1.00 1.00 1.00 298.31 08/29/2019 Qty 3.00 1.00

Problem:	1911914 P.M. service .	Meter:	87876		In	Date:	11/18/2019	Closed:	11/21/20)19
- P.m. service.					Parts List					Qty
- Test and repl	lace rear tag b	ulbs .			5w20 Engir	ne Oil				6.00
- Rotate and b	palance all fou	r tires . Nit	rofill all.		Napagold (Dil Filter				1.00
- Shop Supplie	∍s				Washer Flu	uid Conc	entr			1.00
					Wd40 Spr					1.00
					Permatex					1.00
					Boxed Mini	atures				2.00
					Shop Supp	lies				1.00
	Hour	s 3.50		Labor:	255.50	Parts:	37.44	Total:	292.94	
Workorder: Problem:	1912158 Coolant leak.	Meter:	87972		In	Date:	11/25/2019	Closed:	11/27/20)19
- Pressure test	t and inspect o	cooling sys	tem for leak	s.replace	Parts List					Qty
leaking coolant	reservoir and	refill syste	m.	·	Tank Asy					1.0
- Shop Supplie	es				Shop Supp	lies				1.00
	Hour	s 1.00		Labor:	73.00	Parts:	69.66	Total:	142.66	
	2002165	Meter:	92565		In	Date:	03/02/2020	Closed:	03/05/20	120
Problem:	P.M. service.				•••				03/03/20)20
- P.m. service.					Parts List				03/03/20	
		rotors and	l service ca	lipers .	Parts List				03/03/20	Qty 1.00
- P.m. service.	oth front brake				Parts List Napagold (Oil Filter			03/03/20	Qty
- P.m. service.	oth front brake . Flush and ble	ed brake	system . Roa	ad test .	Parts List	Oil Filter			03/03/20	Qt y
- P.m. service. - Resurface bo Replace pads .	oth front brake . Flush and ble iigh speed bala	ed brake	system . Roa	ad test .	Parts List Napagold 0 5w20 Engir	Oil Filter ne Oil			03/03/20	Qty 1.00
P.m. service.Resurface bothReplace pads .Rotate and h	oth front brake . Flush and ble iigh speed bala	ed brake	system . Roa	ad test .	Parts List Napagold (5w20 Engir Blade	Dil Filter ne Oil e			03/03/20	Qty 1.00 6.00 1.00
P.m. service.Resurface bothReplace pads .Rotate and h	oth front brake . Flush and ble iigh speed bala	ed brake	system . Roa	ad test .	Parts List Napagold 0 5w20 Engir Blade Wiper Blad	Dil Filter ne Oil e e	entr		03/03/20	Qty 1.00 6.00 1.00
P.m. service.Resurface bothReplace pads .Rotate and h	oth front brake . Flush and ble iigh speed bala	ed brake	system . Roa	ad test .	Parts List Napagold (5w20 Engir Blade Wiper Blad Wiper Blad	Oil Filter ne Oil e e uid Conc			03/03/20	Qty 1.00 6.00 1.00 1.00
P.m. service.Resurface bothReplace pads .Rotate and h	oth front brake . Flush and ble iigh speed bala	ed brake	system . Roa	ad test .	Parts List Napagold (5w20 Engir Blade Wiper Blad Wiper Blad Washer Fla	Oil Filter ne Oil e e uid Conc			03/03/20	Qty 1.00 6.00 1.00 1.00 1.00
P.m. service.Resurface bothReplace pads .Rotate and h	oth front brake . Flush and ble iigh speed bala	ed brake	system . Roa	ad test .	Parts List Napagold C 5w20 Engir Blade Wiper Blad Wiper Blad Washer Flu Brk Fluid D Brake Pad	Dil Filter ne Oil e e uid Conc ot 4-12o	Z		03/03/20	Qty 1.00 1.00 1.00 1.00 1.00 1.00
P.m. service.Resurface bothReplace pads .Rotate and h	oth front brake . Flush and ble iigh speed bala	ed brake	system . Roa	ad test .	Parts List Napagold C 5w20 Engir Blade Wiper Blad Wiper Blad Washer Fluid D	Dil Filter ne Oil e e uid Conco ot 4-12o Brake Cli	Z		03/03/20	Qty 1.00 6.00 1.00 1.00 1.00 1.00

Workorder: Problem:	2006659 P.M. service.	Meter:	97742			In Date:	07/07/2020	Closed:	07/14/2020
- P.m. service) .				Parts L	ist			Q
- Replace wo	rn out left front	inner tie ro	od end .		Napago	ld Oil Filter			1.0
- Perform cor	nplete four whe	el alignme	nt and roa	d test .	5w20 E	ngine Oil			6.0
	rear tire . Rota	te and high	n speed ba	lance all	Napa Ai	ir Filter			1.0
four tires . Niti					Blade				1.0
- Shop Suppli	ies				Wiper B	lade			1.0
					Wiper B	lade			1.0
					Used Fi	re X Refurbi	ished		1.0
					Rod Asy	y			1.0
					Shop Si	upplies			1.0
	Hour	rs 8.30		Labor:	605.90	Parts:	146.28	Total:	752.18
Workorder: Problem:	2006919 Bolt in left rea	Meter:	97797			In Date:	07/15/2020	Closed:	07/16/2020
- Replace left	rear tire and b	alance . Ni	trofill all.		Parts L	ist			Q
- Shop Suppli	ies				Tire235	/55/17 Mic			1.0
					Shop Si	upplies			1.0
					Tire Dis	posal Fee			1.0
	Hour :	s 0.50		Labor:	36.50	Parts:	187.26	Total:	223.76
Workorder: Problem:	2008504 remove extra	Meter: decals for	98606 surplus			In Date:	08/26/2020	Closed:	08/26/2020
- remove extr	a decals for su	rplus			Parts L	ist			Q
- Shop Suppli		. p. 3.0			Shop Si				1.0
Chief Cappi		s 1.00		Labor:	•	Parts:	4.00	Total:	77.00
Workorder: Problem:	2008508 Transition Pre	Meter: ep Charge	98606			In Date:	08/26/2020	Closed:	08/26/2020
- Transition P	rep Charge								
	Hour :	s 2.00		Labor:	146.00	Parts:	0.00	Total:	146.00
Workorder: Problem:	2008509 Transition Pre	Meter: ep Charge	98606			In Date:	08/26/2020	Closed:	08/26/2020
- Transition P	rep Charge								
	Hour	s 2.00		Labor:	146.00	Parts:	0.00	Total:	146.00