10165597 2006 FORD FREESTAR Van, Mini Cargo Workorder: 641146 Meter: 8 In Date: 06/19/2006 Closed: 06/26/2006 Problem: CUT KEY & PROGRAM Parts List - Cut Key And Program Qty - Shop Supplies 164-r0475 Ign Key 2010-earlier (don't Reorder) 1.00 Shop Supplies 1.00 Labor: 50.00 Hours 1.00 Parts: 23.45 Total: 73.45 Workorder: 641147 Meter: In Date: 06/19/2006 Closed: 06/19/2006 0 Problem: PRE-DELIVERY INSPECTION - Pre-delivery Inspection Labor: 100.00 Total: 100.00 Hours 2.00 Parts: 0.00 Workorder: 732722 Meter: 3861 In Date: 01/11/2007 Closed: 01/22/2007 Problem: P.M SERVICE - Pm Service Parts List Qty - Nitrogen Fill Tires. Shop Supplies 1.00 1516 Oil Filterfrm Ph3600 Wix 51516 - Shop Supplies 1.00 5w20 Engine Oil 5.00 Hours 3.75 Labor: 206.25 Parts: 25.55 Total: 231.80 Workorder: 741900 Meter: 7946 In Date: 07/24/2007 Closed: 07/26/2007 Problem: P.M SERVICE - Pm Service Parts List Qty - Balance All 4-tires And Nitro Fill. Shop Supplies 1.00 1516 Oil Filterfrm Ph3600 Wix 51516 - Shop Supplies 1.00 5w20 Engine Oil 5.00 31-20 Wiper Blades 20" Blade 1.00 31-24 Wiper Blades 24" Blade 1.00 Labor: 206.25 Parts: 37.84 Total: 244.09 Hours 3.75 : 834286 13288 02/15/2008 02/22/2008 Workorder: Meter: In Date: Closed: Problem: P.M SERVICE, LTPM LIGHT ON - Pm Service Parts List Qty - High Speed Balance And Nitro Fill All Tires Shop Supplies 1.00 - Shop Supplies 1516 Oil Filterfrm Ph3600 Wix 51516 1.00 Air Filter 1.00 Cabin Air Filter 1.00 5w20 Engine Oil 6.00 Hours 3.75 Labor: 225.00 Parts: 51.18 Total: 276.18

Workorder:	844403	Meter:	19135			n Date:	09/18/2008	Closed:	09/29/2	008
	PM SERVICE			WARNIN			09/10/2000	Ciosea.	03/23/2	000
- Pm Service					Parts List					Qty
- Perform Tra	nsmission Flue	sh.test Driv	e.		Shop Supp	olies				1.00
	g Light Flashin				Fuel Filter					1.00
Sensor W/ids, To Correct Pre	repl L/f Tire Pr	ess Senso	r W/new & Re	etrain All	1516 Oil F	Filterfrm F	2h3600 Wix 51	1516		1.00
		a 1 Tiraa F	ill \//nitrogon		5w20 Engi	ne Oil				5.00
	Speed Balanc		iii w/nitrogen		Syn/atf Tra	ans Fluid	Synthetic			16.00
- Shop Suppl	les				31-16 Wip	er Blades	16" Wiper Bla	ade		1.00
					31-20 Wip	er Blades	20" Blade			1.00
					31-24 Wip	er Blade	s 24" Blade			1.00
					Tire Press	ure Sens	or			1.00
	Hou	rs 7.05		Labor:	423.00	Parts:	197.74	Total:	620.74	
	:									
Workorder: Problem:	937245 PM SERVICE	Meter:	25718		lı	n Date:	04/30/2009	Closed:	05/11/2	009
- Pm Service					Parts List					Qty
- Replace 2 T	ires Mount On	Front.bala	nce All 4		Shop Supp	olies				1.00
Tires.nitrogen					1516 Oil F	Filterfrm F	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1516		1.00
- Complete A	lignment.test D	Drive.			Air Filter					1.00
- Shop Suppl	ies				5w20 Engi	ne Oil				5.00
					-		20" Blade			1.00
							s 24" Blade			1.00
					Cabin Air I					1.00
					Tire Dispo					2.00
					P235/60r1					2.00
	Hou	rs 7.25		Labor:	435.00		219.91	Total:	654.91	
Workorder: Problem:	941454 right rear tail	Meter: light inop	27664		lı	n Date:	07/31/2009	Closed:	07/31/2	009
- R/rright tail	iaht hulb				Parts List					Qty
i vingit tan	ight build.				4114k Bull					1.00
	Ноц	rs 0.50		Labor:		Parts:	2 93	Total [.]	32.93	1.00
	:			Labor.						
Workorder: Problem:	947281 P.M service.	Meter:	30042		lı	n Date:	12/23/2009	Closed:	01/07/2	010
- P.m service					Parts List					Qty
- Test & repla	ice L/r turn sigr	nal bulb.			Shop Supp	olies				1.00
•	lance all four ti						2 h3600 Wix 51	1516		1.00
- Shop Suppl	ies				Air Filter /	Fa-1679				1.00
1 1 F -					Fuel Filter					1.00
					5w20 Engi	-				5.00
					7083blk F		6			1.00
							d Fire Extings	hers		1.00
					3157 Tail I		•			1.00
	Ноц	rs 3.50		Labor.	210.00	-	127.87	Total [.]	337.87	
	:									

Workorder: Problem:	1008409 Pm service.	Meter:	34836		I	n Date:	08/05/2010	Closed:	08/12/2	010
- Perform pm	service.				Parts List					Qty
- Test starting		g system.ba	tery failed loa	ad test	Shop Sup	plies				1.00
after recharge							Ph3600 Wix 51	1516		1.00
- Rotate and	balance all for	ur tires.			10w30 Mo	tor Oil				5.00
- Shop Suppl	es				Used Fire	k Refurbe	ed Fire Extings	hers		1.00
					31-20 Wip	er Blades	s 20" Blade			1.00
					31-24 Wip	ber Blade	s 24" Blade			1.00
					31-16 Wip	er Blades	s 16" Wiper Bla	ade		1.00
					Group 59	Battery (r	ntc Bxt 59)			1.00
	Hou :	urs 4.00		Labor:	240.00	Parts:	160.82	Total:	400.82	
Workorder: Problem:	1101440 P.M. Service	Meter:	38607		I	n Date:	02/07/2011	Closed:	02/17/2	011
- Perform pm	service.				Parts List	:				Qty
- Install four r	ew tires.nitro	gen fill and b	alance all fo	ur.	Shop Sup	plies				1.00
- Perform who	eel alignment	complete.			Air Filter					1.00
- Shop Suppl	es				1516 Oil I	Filterfrm F	Ph3600 Wix 51	1516		1.00
					3424 Fuel	Filter Fr	m 3424 Wix 3	3424		1.00
					5w20 Eng					5.00
						•	Stock# 405540			1.00
							ed Fire Extings	hers		1.00
					•		s 20" Blade			1.00
					•		s 24" Blade			1.00
							s 16" Wiper Bla	ade		1.00
					Tire Dispo Tires	sal Fee				4.00
	Hou	urs 6.50		Labor:	390.00	Parts:	483.50	Total:	873.50	4.00
Workorder: Problem:	1108485 Pm service a	Meter: and check bi	42258 rakes see no	tes.	l	n Date:	08/11/2011	Closed:	08/25/2	011
- Perform pm	service.				Parts List					Qty
- Replace bot					Shop Sup	plies				1.00
new.install ner automated ble				d	1516 Oil I	Filterfrm F	Ph3600 Wix 51	1516		1.00
- Rotate and			can looi.		Cabin Filte	er				1.00
- Shop Suppli		ai (1153.			Brake Rot	ors				2.00
Chief Outph					Brake Cal	iper R/s				1.00
					Brake Cal	iper L/s				1.00
					Brake Pac					1.00
					2232 Brak		luart			1.00
					5w20 Eng	ine Oil				5.00
					-					
							s 24" Blade			1.00
					31-20 Wip	er Blades	s 24" Blade s 20" Blade s 16" Wiper Bla			1.00 1.00 1.00

:

Labor: 465.00

Parts: 416.74

Total: 881.74

Workorder: Problem:	1204281 Pm service	Meter:	48085		lı	n Date:	05/04/2012	Closed:	05/10/20	012
- P.m. Service	э.				Parts List					Qty
- Rotate and I	balance all tires	5.			Shop Supp	olies				1.00
- Shop Suppli	es				1516 Oil F	- ilterfrm I	Ph3600 Wix 51	516		1.00
					5w20 Engi	ne Oil				5.00
					31-24 Wip	er Blade	s 24" Blade			1.00
					31-20 Wip	er Blades	s 20" Blade			1.00
	Hour :	s 3.75		Labor:	225.00	Parts:	27.01	Total:	252.01	
Workorder: Problem:	1210316 P.M. Service.	Meter:	51939		lı	n Date:	10/26/2012	Closed:	11/28/20	012
- P.m. Service	э.				Parts List					Qty
- Test battery	and charging	system.rep	lace bad batte	əry.	5w20 Engi	ne Oil				5.00
	ugh idle and cl	neck engir	e light.replace	e idle	Ph3600 O	il Filter Ll	of			1.00
solenoid.clear					31-24 Wip	er Blade	s 2			1.00
	balance all tires	6.			31-20 Wip	er Blades	s 20			1.00
- Shop Suppli	es				G9343 Fu	el Filter N	/Itc			1.00
					Group 59 l	Battery M	1tc			1.00
					Air Filter					1.00
					Cabin Air I	Filter				1.00
					Idle Air Co	ntrol Val	v			1.00
					Shop Supp	olies				1.00
	Hour :	s 6.00		Labor:	360.00	Parts:	243.23	Total:	603.23	
Workorder: Problem:	1301616 stalling out	Meter:	53705		lı	n Date:	02/14/2013	Closed:	02/14/20	013
- Tow From: 3	3650 Summit B	lvd								
	Hour :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder:	1301632 Towed in.Eng	Meter: ine stalls.	53918		h	n Date:	02/14/2013	Closed:	03/05/20	013
				ronlago	Parts List					Qty
Problem:	alling complain			epiace						-
Problem: - Diagnose sta plugs,wires an	nd coil pack.cle			epiace	Coil Pack					1.00
Problem:	nd coil pack.cle			epiace		9				1.00 6.00
Problem: - Diagnose sta plugs,wires an	nd coil pack.cle			epiace	Coil Pack]				
Problem: - Diagnose sta plugs,wires an	nd coil pack.cle			epiace	Coil Pack Spark Plug					6.00

Workorder: Problem:	1304951 Pm service	Meter: e.	55364		I	n Date:	05/17/2013	Closed:	05/30/2013
- P.m. Service	Э.				Parts List	t			Qty
- Replace ino	p back-up a	alarm.			5w20 Eng	ine Oil			5.00
- Rotate and b					Napagold				1.00
- Shop Suppli					31-24 Wi		s 2		1.00
					31-20 Wip				1.00
					Wiper Bla				1.00
					Used Fire		ished		1.00
					Alarm				1.00
					Shop Sup	plies			1.00
	H	lours 4.25		Labor:	255.00	•	106.18	Total:	361.18
Workorder: Problem:	1312222 Pm service	Meter:	59398		I	n Date:	12/06/2013	Closed:	12/18/2013
- Perform pm	service.				Parts List	t			Qty
- Rotate and b	balance all f	four tires.			5w20 Eng	jine Oil			5.00
- Shop Suppli	ies				Napagold	Oil Filter			1.00
					Napagold	Fuel Filte	r		1.00
					31-24 Wi	per Blade	s 2		1.00
					20" Wiper	Blade			1.00
					Wiper Bla	de			1.00
					Washer F	I			1.00
					Washer F Shop Sup				1.00 1.00
	Н	lours 3.75		Labor:		plies	44.78	Total:	
	H : 1406349 Pm service	Meter:	63772	Labor:	Shop Sup 225.00	plies	44.78 06/27/2014	Total: Closed:	1.00
Problem:	: 1406349 Pm service	Meter:	63772	Labor:	Shop Sup 225.00	plies Parts: n Date:			1.00 269.78 07/08/2014
Problem: - Perform pm	: 1406349 Pm service service.	Meter:			Shop Sup 225.00	plies Parts: In Date:	06/27/2014		1.00 269.78
Problem: - Perform pm - Install four n	: 1406349 Pm service service. new tires. Ni	Meter: e. trogen fill and	balance all f		Shop Sup 225.00	plies Parts: n Date: t per Blade	06/27/2014		1.00 269.78 07/08/2014 Qty 1.00
Problem: - Perform pm - Install four n - Replace three	: 1406349 Pm service service. new tires. Ni ee failed ext	Meter: e. trogen fill and haust hangers	balance all f		Shop Sup 225.00	plies Parts: n Date: t per Blade de	06/27/2014		1.00 269.78 07/08/2014 Qty 1.00 1.00
Problem: - Perform pm - Install four n - Replace thre - Perform whe	: 1406349 Pm service service. new tires. Ni ee failed ext eel alignmer	Meter: e. trogen fill and haust hangers	balance all f		Shop Sup 225.00 I Parts List 31-24 Wij Wiper Bla Wiper Bla	plies Parts: n Date: t per Blade de	06/27/2014		1.00 269.78 07/08/2014 07/08/2014 07/08/2014
Problem: - Perform pm - Install four n - Replace three	: 1406349 Pm service service. new tires. Ni ee failed ext eel alignmer	Meter: e. trogen fill and haust hangers	balance all f		Shop Sup 225.00	plies Parts: n Date: t per Blade de de	06/27/2014		1.00 269.78 07/08/2014 07/08/2014 1.00 1.00 3.00
Problem: - Perform pm - Install four n - Replace thre - Perform whe	: 1406349 Pm service service. new tires. Ni ee failed ext eel alignmer	Meter: e. trogen fill and haust hangers	balance all f		Shop Sup 225.00 I Parts List 31-24 Wi Wiper Bla Wiper Bla Insulator Tire P235	plies Parts: In Date: t per Blade de de /60r16	06/27/2014		1.00 269.78 07/08/2014 07/08/2014 1.00 1.00 1.00 3.00 4.00
Problem: - Perform pm - Install four n - Replace thre - Perform whe	: 1406349 Pm service service. new tires. Ni ee failed ext eel alignmer	Meter: e. trogen fill and haust hangers	balance all f		Shop Sup 225.00	plies Parts: In Date: t per Blade de de de /60r16 jine Oil	06/27/2014		1.00 269.78 07/08/2014 1.00 1.00 1.00 3.00 4.00 5.00
 Perform pm Install four n Replace three Perform whee 	: 1406349 Pm service service. new tires. Ni ee failed ext eel alignmer	Meter: e. trogen fill and haust hangers	balance all f		Shop Sup 225.00 I Parts List 31-24 Wi Wiper Bla Wiper Bla Insulator Tire P235 5w20 Eng Napagold	plies Parts: In Date: t per Blade de de /60r16 jine Oil Oil Filter	06/27/2014		1.00 269.78 07/08/2014 07/08/2014 1.00 1.00 1.00 3.00 4.00 5.00 1.00
Problem: - Perform pm - Install four n - Replace thre - Perform whe	: 1406349 Pm service service. new tires. Ni ee failed ext eel alignmer	Meter: e. trogen fill and haust hangers	balance all f		Shop Sup 225.00 I Parts List 31-24 Wij Wiper Bla Wiper Bla Insulator Tire P235 5w20 Eng Napagold Shop Sup	plies Parts: In Date: In Date:	06/27/2014		1.00 269.78 07/08/2014 1.00 1.00 1.00 4.00 5.00 1.00 1.00
Problem: - Perform pm - Install four n - Replace thre - Perform whe	: 1406349 Pm service service. new tires. Ni ee failed ext eel alignmen ies	Meter: e. trogen fill and haust hangers	balance all f	our.	Shop Sup 225.00 I Parts List 31-24 Wi Wiper Bla Wiper Bla Insulator Tire P235 5w20 Eng Napagold	plies Parts: In Date: t per Blade de /60r16 jine Oil Oil Filter plies osal Fee	06/27/2014	Closed:	1.00 269.78 07/08/2014 07/08/2014 1.00 1.00 1.00 3.00 4.00 5.00 1.00
Problem: - Perform pm - Install four n - Replace thre - Perform whe - Shop Suppli Workorder:	: 1406349 Pm service service. new tires. Ni ee failed ext eel alignmen ies H 1407221	Meter: e. trogen fill and haust hangers nt complete. lours 7.75 Meter:	l balance all fo s with new. 64150	our.	Shop Sup 225.00	plies Parts: In Date: t per Blade de /60r16 jine Oil Oil Filter plies osal Fee	06/27/2014 s 2	Closed:	1.00 269.78 07/08/2014 07/08/2014 1.00 1.00 1.00 5.00 1.00 4.00 4.00
Problem: - Perform pm - Install four n - Replace thre - Perform whe - Shop Suppli Workorder: Problem:	: 1406349 Pm service service. new tires. Ni ee failed exh eel alignmen ies H : 1407221 Check eng	Meter: e. trogen fill and haust hangers nt complete. lours 7.75 Meter: gine light on a	l balance all fo s with new. 64150 nd missing.	our. Labor:	Shop Sup 225.00 I Parts List 31-24 Wij Wiper Bla Unsulator Tire P235 5w20 Eng Napagold Shop Sup Tire Dispo 465.00	plies Parts: n Date: t per Blade de /60r16 jine Oil Oil Filter plies psal Fee Parts:	06/27/2014 s 2 670.39	Closed:	1.00 269.78 07/08/2014 07/08/2014 07/08/2014 07/08/2014
Problem: - Perform pm - Install four n - Replace thre - Perform whe - Shop Suppli Workorder: Problem: - Diagnose ch	: 1406349 Pm service service. new tires. Ni ee failed ext eel alignmen ies H : 1407221 Check eng neck engine	Meter: e. trogen fill and haust hangers nt complete. lours 7.75 Meter: gine light on a	l balance all fo s with new. 64150 nd missing. rottle body ar	our. Labor:	Shop Sup 225.00	plies Parts: n Date: t per Blade de de /60r16 jine Oil Oil Filter plies osal Fee Parts: n Date: t	06/27/2014 s 2 670.39 07/23/2014	Closed:	1.00 269.78 07/08/2014 07/08/2014 00 1.00
Problem: - Perform pm - Install four n - Replace thre - Perform whe - Shop Suppli Workorder: Problem: - Diagnose ch	: 1406349 Pm service service. new tires. Ni ee failed ext eel alignmen ies H : 1407221 Check engine meck engine	Meter: e. trogen fill and haust hangers nt complete. lours 7.75 Meter: gine light on a	l balance all fo s with new. 64150 nd missing. rottle body ar	our. Labor:	Shop Sup 225.00	plies Parts: n Date: t per Blade de de /60r16 jine Oil Oil Filter plies psal Fee Parts: n Date: t ntake Clnr	06/27/2014 s 2 670.39 07/23/2014	Closed:	1.00 269.78 07/08/2014 07/08/2014 00 1.00
Problem: - Perform pm - Install four n - Replace thre - Perform whe - Shop Suppli Workorder: Problem:	i 1406349 Pm service service. new tires. Ni ee failed ext eel alignmen ies H 1407221 Check engine meck engine mine.clear ies	Meter: e. trogen fill and haust hangers nt complete. lours 7.75 Meter: gine light on a	l balance all fo s with new. 64150 nd missing. rottle body ar	our. Labor: nd repair	Shop Sup 225.00	plies Parts: n Date: t per Blade de de /60r16 jine Oil Oil Filter plies psal Fee Parts: n Date: t ntake Clnr	06/27/2014 s 2 670.39 07/23/2014	Closed: Total: Closed:	1.00 269.78 07/08/2014 07/08/2014 00 1.00

Workorder: Problem:	1500619 Pm service.	Meter:	67140		In Date:	01/16/2015	Closed:	01/30/20	015
- P.m. Service	э.				Parts List				Qty
- Resurface b	orear brake rot	ors,replace	pads and		Disc Brake Pads				1.00
calipers.flush					Brake Rotor Only				2.00
- Replace bot	h leaking rear	shocks.			5w20 Engine Oil				5.00
- Rotate and I	balance tires.				Napagold Oil Filter				1.00
- Shop Suppli	ies				Wiper Blade				1.00
					31-24 Wiper Blade	s 2			1.00
					Wiper Blade				1.00
					Silicone Spray 10o	z			1.00
					Semi Loaded Calip	er			1.00
					14165520				1.00
					Brk Fluid Dot 4-12c	Z			2.00
					Napagold Fuel Filte	er			1.00
					Sensa-trac Lt Truck	ŚŚ			2.00
					Shop Supplies				1.00
	Hou	ırs 7.75		Labor:	465.00 Parts:	495.53	Total:	960.53	
Workorder: Problem:	1507270 Pm service.	Meter:	69822		In Date:	07/21/2015	Closed:	08/06/20	015
- P.m. Service	Э.				Parts List				Qty
- Test battery	and charging	system.rep	lace bad batt	ery.	5w20 Engine Oil				5.00
- Pressure tes	st and inspect	cooling sys	tem.flush and	d refill	Napagold Oil Filter				1.00
system.					31-24 Wiper Blade	s 2			1.00
	balance all tire	es.			Wiper Blade				1.00
- Shop Suppli	ies				Wiper Blade				1.00
					Battery				1.00
					Peak Global				2.00
					Shop Supplies				
					Chop Cappiloo				1.00
	Hou	ırs 6.75		Labor:		177.41	Total:	582.41	1.00
Workorder: Problem:	Hou : 1600808 P.M. service	Meter:	72633	Labor:		177.41 01/25/2016	Total: Closed:	582.41 01/29/20	
	: 1600808	Meter:	72633	Labor:	405.00 Parts:				016
Problem:	: 1600808 P.M. service	Meter:		Labor:	405.00 Parts:				
Problem: - Pm service. - Resurface fr	: 1600808 P.M. service. ront brake roto	Meter:	ace brake	Labor:	405.00 Parts: In Date: Parts List				016 Qty
Problem: - Pm service. - Resurface fr pads.service c - Check and r	: 1600808 P.M. service. ront brake roto calipers and bl replace defect	Meter: ors and repla eed system ive serpenti	ace brake	Labor:	405.00 Parts: In Date: Parts List 5w20 Engine Oil	01/25/2016			016 Qty 5.00
Problem: - Pm service. - Resurface fr pads.service of - Check and r - Rotate and r	: 1600808 P.M. service ront brake roto calipers and bl replace defect balance all fou	Meter: ors and repla eed system ive serpenti	ace brake	Labor:	405.00 Parts: In Date: Parts List 5w20 Engine Oil Napagold Oil Filter	01/25/2016 er			016 Qty 5.00 1.00
Problem: - Pm service. - Resurface fr pads.service c - Check and r	: 1600808 P.M. service ront brake roto calipers and bl replace defect balance all fou	Meter: ors and repla eed system ive serpenti	ace brake	Labor:	405.00 Parts: In Date: Parts List 5w20 Engine Oil Napagold Oil Filter Napagold Fuel Filter	01/25/2016 er			016 Qty 5.00 1.00
Problem: - Pm service. - Resurface fr pads.service of - Check and r - Rotate and r	: 1600808 P.M. service ront brake roto calipers and bl replace defect balance all fou	Meter: ors and repla eed system ive serpenti	ace brake	Labor:	405.00 Parts: In Date: Parts List 5w20 Engine Oil Napagold Oil Filter Napagold Fuel Filter Napagold Air Filter	01/25/2016 er			016 Qty 5.00 1.00 1.00
Problem: - Pm service. - Resurface fr pads.service of - Check and r - Rotate and r	: 1600808 P.M. service ront brake roto calipers and bl replace defect balance all fou	Meter: ors and repla eed system ive serpenti	ace brake	Labor:	405.00 Parts: In Date: Parts List 5w20 Engine Oil Napagold Oil Filter Napagold Fuel Filter Napagold Air Filter Wiper	01/25/2016 er			016 Qty 5.00 1.00 1.00 1.00
Problem: - Pm service. - Resurface fr pads.service of - Check and r - Rotate and r	: 1600808 P.M. service ront brake roto calipers and bl replace defect balance all fou	Meter: ors and repla eed system ive serpenti	ace brake	Labor:	405.00 Parts: In Date: Parts List 5w20 Engine Oil Napagold Oil Filter Napagold Fuel Filter Napagold Air Filter Wiper 20" Wiper Blade	01/25/2016 er			016 Qty 5.00 1.00 1.00 1.00 1.00
Problem: - Pm service. - Resurface fr pads.service of - Check and r - Rotate and r	: 1600808 P.M. service ront brake roto calipers and bl replace defect balance all fou	Meter: ors and repla eed system ive serpenti	ace brake	Labor:	405.00 Parts: In Date: Parts List 5w20 Engine Oil Napagold Oil Filter Napagold Fuel Filter Napagold Air Filter Wiper 20" Wiper Blade Disc Brake Pads	01/25/2016			016 Qty 5.00 1.00 1.00 1.00 1.00 1.00
Problem: - Pm service. - Resurface fr pads.service of - Check and r - Rotate and r	: 1600808 P.M. service ront brake roto calipers and bl replace defect balance all fou	Meter: ors and repla eed system ive serpenti	ace brake	Labor:	405.00 Parts: In Date: Parts List 5w20 Engine Oil Napagold Oil Filter Napagold Fuel Filter Napagold Air Filter Wiper 20" Wiper Blade Disc Brake Pads Drive Belt	01/25/2016			016 Qty 5.00 1.00 1.00 1.00 1.00 1.00 1.00

Hours 7.75 :

Problem: P.M	7056 . service.	Meter:	75047		I	n Date:	07/13/2016	Closed:	07/25/2	016
- P.m. Service.					Parts List	ŀ				Qty
- Service transmis	sion.flush a	and refill s	vstem.		Napagold					1.00
- Rotate and balan			,		5w20 Eng					6.00
- Shop Supplies					Wiper Bla					1.00
•					20" Wiper					1.00
					Wiper	Diado				1.00
					Syn-atf Tr	ans Fluid	S			16.00
					Trans Filte		0			1.00
					Shop Sup					1.00
	Hour	s 6.25		Labor:	375.00		119.77	Total:	494.77	
Workorder: 170 Problem: P.M	0850 . service.	Meter:	79252		I	n Date:	01/27/2017	Closed:	02/14/20	017
- P.m. Service.					Parts List	t				Qty
- Replace loose in	ner and ou	ter tie rod	ends.		5w20 Eng	ine Oil				5.00
- Complete wheel	alignment.	test drive.			Napagold	Oil Filter				1.00
- Rotate and balan	ce tires.				Washer F	luid Conc	entr			1.00
- Shop Supplies					Napagold	Fuel Filte	er			1.00
					Wiper Bla	des 24"				1.00
					20" Wiper	Blade				1.00
					Wiper					1.00
					Vinyl Elec	trical Tap	e			1.00
					Outer Tie	Rod End				2.00
					Inner Tie	Rod End				2.00
					Shop Sup	-				1.00
	Hours :	s 8.25		Labor:	495.00	Parts:	154.15	Total:	649.15	
Workorder: 170 Problem: P.M	8778 . service a	Meter: nd ABS liq		nt infested		n Date:	09/06/2017	Closed:	10/05/2	017
				nt infested			09/06/2017	Closed:	10/05/20	
Problem: P.M - P.m. Service.	. service a	nd ABS lio	ght on and ar	nt infested	Parts List	t	09/06/2017	Closed:	10/05/20	Qty
Problem: P.M - P.m. Service. - Diagnose Abs lig circuit.perform pin J	. service a ht.c1096-2 point test.r	nd ABS lig 20. Abs pu eplace def	ght on and ar mp motor fective modu		Parts Lis t 5w20 Eng	t ine Oil	09/06/2017	Closed:	10/05/2	
Problem: P.M - P.m. Service. - Diagnose Abs lig circuit.perform pin j codes,reprogram a	. service a ht.c1096-2 point test.r nd bleed s	nd ABS lig 20. Abs pu eplace def ystem and	ght on and ar mp motor fective modu		Parts List	t ine Oil Oil Filter		Closed:	10/05/20	Qty 5.00
Problem: P.M - P.m. Service. - Diagnose Abs lig circuit.perform pin p codes,reprogram a - Replace front and	. service a ht.c1096-2 point test.r nd bleed s d rear asse	nd ABS lig 20. Abs pu eplace def ystem and	ght on and ar mp motor fective modu		Parts List 5w20 Eng Napagold Washer F	t ine Oil Oil Filter luid Conc		Closed:	10/05/2	Qty 5.00 1.00 1.00
Problem: P.M - P.m. Service. - Diagnose Abs lig circuit.perform pin j codes,reprogram a - Replace front and - Rotate and balan	. service a ht.c1096-2 point test.r nd bleed s d rear asse	nd ABS lig 20. Abs pu eplace def ystem and	ght on and ar mp motor fective modu		Parts List 5w20 Eng Napagold Washer F Wiper Bla	t ine Oil Oil Filter luid Conc des 24"		Closed:	10/05/20	Qty 5.00 1.00 1.00 1.00
Problem: P.M - P.m. Service. - Diagnose Abs lig circuit.perform pin p codes,reprogram a - Replace front and	. service a ht.c1096-2 point test.r nd bleed s d rear asse	nd ABS lig 20. Abs pu eplace def ystem and	ght on and ar mp motor fective modu		Parts List 5w20 Eng Napagold Washer F Wiper Bla 20" Wiper	t ine Oil Oil Filter luid Conc des 24"		Closed:	10/05/2	Qty 5.00 1.00 1.00 1.00 1.00
Problem: P.M - P.m. Service. - Diagnose Abs lig circuit.perform pin p codes,reprogram a - Replace front and - Rotate and balan	. service a ht.c1096-2 point test.r nd bleed s d rear asse	nd ABS lig 20. Abs pu eplace def ystem and	ght on and ar mp motor fective modu		Parts List 5w20 Eng Napagold Washer F Wiper Bla 20" Wiper Wiper	t Oil Filter luid Conc des 24" Blade		Closed:	10/05/20	Qty 5.00 1.00 1.00 1.00 1.00
Problem: P.M - P.m. Service. - Diagnose Abs lig circuit.perform pin p codes,reprogram a - Replace front and - Rotate and balan	. service a ht.c1096-2 point test.r nd bleed s d rear asse	nd ABS lig 20. Abs pu eplace def ystem and	ght on and ar mp motor fective modu		Parts List 5w20 Eng Napagold Washer F Wiper Bla 20" Wiper Wiper Abs Contr	t Oil Filter luid Conc des 24" Blade ol	entr	Closed:	10/05/2	Qty 5.00 1.00 1.00 1.00 1.00 1.00
Problem: P.M - P.m. Service. - Diagnose Abs lig circuit.perform pin p codes,reprogram a - Replace front and - Rotate and balan	. service a ht.c1096-2 point test.r nd bleed s d rear asse	nd ABS lig 20. Abs pu eplace def ystem and	ght on and ar mp motor fective modu		Parts List 5w20 Eng Napagold Washer F Wiper Bla 20" Wiper Wiper Abs Contr Abs Pump	t Oil Filter luid Conc des 24" Blade ol		Closed:	10/05/20	Qty 5.00 1.00 1.00 1.00 1.00 1.00 1.00
Problem: P.M - P.m. Service. - Diagnose Abs lig circuit.perform pin p codes,reprogram a - Replace front and - Rotate and balan	. service a ht.c1096-2 point test.r nd bleed s d rear asse	nd ABS lig 20. Abs pu eplace def ystem and	ght on and ar mp motor fective modu		Parts List 5w20 Eng Napagold Washer F Wiper Bla 20" Wiper Wiper Abs Contr Abs Pump brake fluid	t Oil Filter luid Conc des 24" Blade ol o/module	entr Salvage Part	Closed:	10/05/20	Qty 5.00 1.00 1.00 1.00 1.00 1.00 1.00 2.00
Problem: P.M - P.m. Service. - Diagnose Abs lig circuit.perform pin p codes,reprogram a - Replace front and - Rotate and balan	. service a ht.c1096-2 point test.r nd bleed s d rear asse	nd ABS lig 20. Abs pu eplace def ystem and	ght on and ar mp motor fective modu		Parts List 5w20 Eng Napagold Washer F Wiper Bla 20" Wiper Wiper Abs Contr Abs Pump brake fluid Non-chlor	t Oil Filter luid Conc des 24" Blade ol o/module	entr Salvage Part	Closed:	10/05/24	Qty 5.00 1.00 1.00 1.00 1.00 1.00 2.00 1.00
Problem: P.M - P.m. Service. - Diagnose Abs lig circuit.perform pin codes,reprogram a - Replace front and - Rotate and balan	. service a ht.c1096-2 point test.r nd bleed s d rear asse	nd ABS lig 20. Abs pu eplace def ystem and	ght on and ar mp motor fective modu		Parts List 5w20 Eng Napagold Washer F Wiper Bla 20" Wiper Abs Contr Abs Contr Abs Pump brake fluid Non-chlor Shop Sup	t ine Oil Oil Filter luid Conc des 24" Blade blade o/module d Brake Cl plies	entr Salvage Part	Closed:	10/05/20	Qty 5.00 1.00 1.00 1.00 1.00 1.00 2.00 1.00 1
Problem: P.M - P.m. Service. - Diagnose Abs lig circuit.perform pin codes,reprogram a - Replace front and - Rotate and balan	. service a ht.c1096-2 point test.r nd bleed s d rear asse ce tires.	nd ABS lig 20. Abs pu eplace def ystem and	ght on and ar mp motor fective modu	le.clear	Parts List 5w20 Eng Napagold Washer F Wiper Bla 20" Wiper Wiper Abs Contr Abs Pump brake fluid Non-chlor	t Oil Filter luid Conc des 24" Blade o/module b/module Brake Cl plies narge	entr Salvage Part		10/05/24	Qty 5.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00

Workorder: Problem:	1709835 Towed in, dea	Meter: ad battery.	83684			In Date:	10/06/2017	Closed:	10/17/2017
- Charge batte cell in battery.	ery fully.test ba r&r defective b		harging sy	stem.bad	Parts L	ist			Qt
- Shop Suppli		inter y :			Battery	unnling			1.0
		s 1.00		Labor:	Shop S		118.75	Total	1.0 178.75
	:	5 1.00		Labui.	00.00	rans.	110.75	TOTAL.	170.75
Workorder: Problem:	1709895 No start	Meter:	83673			In Date:	10/06/2017	Closed:	10/11/2017
- Tow From: 8 Lv shop	60 Military Tra	iil (dunkin I	Donuts par	king) To:					
	Hour :	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1801262 Towed in for r	Meter: no start.	85544			In Date:	02/01/2018	Closed:	02/08/2018
- Diagnoise de replace ajar sv	oor ajar light st vitch .retest.	aying on .r	&r right fro	nt latch to	Parts L Switch				Qt 1.0
- Charge batte	ery fully.test ba		harging sy	stem .r&r	Alenato	•			1.0
defective alter		.retest.			Belt	, e			1.0
- Shop Suppli	es				Switch				1.0
					Shop S	upplies			1.0
	Hour	rs 3.15		Labor:	189.00	Parts:	389.14	Total:	578.14
Workorder: Problem:	1801350 No start	Meter:	85467			In Date:	02/01/2018	Closed:	02/05/2018
	650 Summit B	lyd (library) Far west	sida To: Ly					
shop		iva (library) 1 al west						
	Hour :	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder:	1803185	Meter:				In Date:	03/27/2018	Closed:	04/26/2018
Problem:	PM Service, 7	Fransmissi	on slipping	at 45 mph, 0	Check re	ar left windo	DW.		
- Perform tran	smission perfo	ormance te	st. Replace	;	Parts L	ist			Qt
transmission a transmission fl			nission line	s and fill	Transm	ission Asse	mbly		1.0
- P.m. service		•			5w20 E	ngine Oil			5.0
	point test on let	ft rear vent	window F	2&r window	Napago	old Oil Filter			1.0
motor and ret			Window . I		Wiper E	Blades 24"			1.0
- Replace and	balance all fo	ur tires. Ni	trogen fill ti	res.	20" Wip	er Blade			1.0
- A/c performa and retest syst	ance test .r&r c æm.	lefective hi	gh pressur	e switch		old Fuel Filte for Motor	r		1.0 1.0
- Complete fro	ont end alignm	ent. Road	test.		235/60r	16sl Gdy All	-season		4.0
- Shop Suppli	es				A/c Swi	tch			1.0
					Shop S	upplies			1.0
					Tire Dis	posal Fee			4.0

Workorder:	1805369	Meter:	86788			n Date:	05/25/2018	Closed:	06/05/20)18
Problem:	Towed in for	check engi	he light and v	vill not mo	ve.					
	iagnose check				Parts List	:				Qty
	p0304 . Perfor defective coil				Spark Plu	g Wire				1.00
clear codes a		pack ,spair	r plugs and w	ne set	Spark Plu	g				6.00
- Shop Suppli	es				Coil Pack					1.00
					Shop Sup	plies				1.00
	Hou	rs 4.50		Labor:	270.00	Parts:	182.57	Total:	452.57	
Workorder:		Meter:	86639		I	n Date:	05/25/2018	Closed:	05/29/20)18
Problem:	Check Engine	e light came	e on and it wi	ll not mov	е					
- Tow From: 3 Shop	3650 Summit E	Blvd Far We	est Parking Lo	ot To: Lv						
	Hou	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1811633 P.M. service.	Meter:	89414		I	n Date:	11/13/2018	Closed:	11/26/20)18
- P.m. service).				Parts List	:				Qty
	oise from engir		en turning . R	&r	Napagold	Oil Filter				1.00
	n drive belt. Ro				Napa Qua	rt 5w20				5.00
	rotate all four	tires. Nitro	fill all.		Used Fire	X Refurb	ished			1.00
- Shop Suppli	es				Wiper					1.00
					20" Wiper	Blade				1.00
					Wiper Bla	des 24"				1.00
					Ford Trito	n Pvc Swe	C			1.00
					V Belt					1.00
					Shop Sup	plies				1.00
	Hou	rs 4.55		Labor:	304.85	Parts:	120.81	Total:	425.66	
Workorder:		Meter:	91354		I	n Date:	03/11/2019	Closed:	03/28/20)19
Problem:	Noise from pe	ower sterrir	ig pump on c	old start.						
	replace leakin				Parts List	:				Qty
	ill pump and re and return ho				Ret/hose					1.00
	m . Road test		and nush pov	VEI	Outer Tie	Rod End				2.00
• •	nplete front en		t and road te	st.	Reman/rp					1.00
- Shop Suppli	•	-			Pawer Ste	ering Pur	np			2.00
,					Syn-atf Tr	ans Fluid	S			6.00
					Rack &am	ıp; Pinion				1.00
					~ ~					
					Shop Sup	plies				1.00

Workorder: 1905244 Meter: 92488 Problem: P.M. service .	In Date: 05/15/2019	Closed:	05/20/2019
- P.m. service.	Parts List		Qt
- Test and replace right rear quarter glass window motor .	Napagold Oil Filter		1.0
Retest .	5w20 Engine Oil		5.0
- Balance and rotate all four tires . Nitrofill all.	Wiper		1.0
- Shop Supplies	20" Wiper Blade		1.0
	Wiper Blades 24"		1.0
	Regulator		1.0
	Shop Supplies		1.0
Hours 4.75 Labor:	318.25 Parts: 72.90	Total:	391.15
Workorder: 1908916 Meter: 94932 Problem: P.M. service.	In Date: 08/26/2019	Closed:	09/30/2019
- P.m. service.	Parts List		QI
- Resurface both front rotors .replace brake pads and	Napagold Oil Filter		1.0
calipers . Flush and bleed brake system . Perform automated			5.0
bleed with scan tool . Road test .	Napagold Fuel Filter		1.0
- Rotate and balance all four tires . Nitrofill all.	20" Wiper Blade		1.0
 Replace left upper motor mount and both lower front mounts. Road test. 	Wiper Blades 24"		1.0
	Washer Fluid Concentr		1.0
- 2000 2000lles			
- Shop Supplies	Wiper		1.0
- Shop Supplies			1.0 1.0
- Shop Supplies	Wiper		1.0
- Shop Supplies	Wiper Used Fire X Refurbished		1.0 1.0
- Shop Supplies	Wiper Used Fire X Refurbished Non-chlor Brake Clnr		1.0 1.0 1.0
- Shop Supplies	Wiper Used Fire X Refurbished Non-chlor Brake CInr B Fluid Dot 3-32oz		1.0 1.0 1.0 1.0
- Shop Supplies	Wiper Used Fire X Refurbished Non-chlor Brake Clnr B Fluid Dot 3-32oz Brake Caliper		1.0 1.0 1.0 1.0 1.0
- Shop Supplies	Wiper Used Fire X Refurbished Non-chlor Brake Clnr B Fluid Dot 3-32oz Brake Caliper Brake Caliper		
- Shop Supplies	Wiper Used Fire X Refurbished Non-chlor Brake Clnr B Fluid Dot 3-32oz Brake Caliper Brake Caliper Brake Pads		1.0 1.0 1.0 1.0 1.0 1.0
- Shop Supplies	Wiper Used Fire X Refurbished Non-chlor Brake Clnr B Fluid Dot 3-32oz Brake Caliper Brake Caliper Brake Pads Insulator		1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0
- Shop Supplies	Wiper Used Fire X Refurbished Non-chlor Brake Clnr B Fluid Dot 3-32oz Brake Caliper Brake Caliper Brake Pads Insulator Strut		1.0 1.0 1.0 1.0 1.0 1.0 1.0

Workorder: Problem:	2004717 P.M. service	Meter: , brake peo	99712 Ial goes down t	oo far a	nd detail	In Date:	05/11/2020	Closed:	06/30/20	020
- P.m. Service	2				Parts L	ist				Qty
		nd brake b	ooster.resurfac	e front		old Oil Filter				1.00
and rear rotors	s.replace rear		d hoses.flush a			ngine Oil				5.00
pressure bleed	•				Wiper					1.00
	both headlam	p lenses.			-	er Blade				1.00
- Rotate and I						Blades 24"				1.00
 Diagnose a/ defective blow 		perating or	all speeds.rep	lace	•	or Brake Clr	hr			4.00
- Shop Suppli					B Fluid	Dot 3-32oz				2.00
	63				Brake M	/later				1.00
					3m Tm	Headlight Le	ens			1.00
					Brk/hos	-				1.00
					Brake P	Pad				1.00
					Brake C	Caliper				1.00
					Brake C	Caliper				1.00
					Brake H	lose				1.00
					Brake B	Booster				1.00
					Blower	Motor Resis	tor			1.00
					Shop S	upplies				1.00
					Freight	Charge				1.00
	Hou :	rs 15.75		Labor:	1,149.7 5	Parts:	1,095.98	Total:	2,245.73	3
Workorder:	2006076	Meter:	99401			In Date:	06/18/2020	Closed:	06/18/20	020
Problem:	1 - Detail Ver	nicle Wash	Ticket(s) Issue	d						
- 1 - Detail Ve	hicle Wash Ti	cket(s) Issu	led							
	Hou :	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder:	2008275	Meter:	101455			In Date:	08/18/2020	Closed:	08/20/20	020
Problem:	Left front wip	er blade co	meing apart .							
- Replace bro	ken left front v	viper blade			Parts L	ist				Qty
					Wiper B	Blades 24"				1.00
	Hou :	rs 0.20		Labor:	14.60	Parts:	4.17	Total:	18.77	
Workorder:	2010938	Meter:	102671			In Date:	10/30/2020	Closed:	10/30/20	020
Problem:	Transition Pro	ep Charge								
- Transition P	rep Charge									
		rs 2.00		Labor:	146.00	Parts:	0.00	Total:	146.00	
	:									