Workorder:       1506624       Meter:       122       In Date:       07/01/2015       Closed:       07/01/2015         Problem:       1061 - Pre Delivery Inspection       -       -       Pre Delivery Inspection       -       -       Closed:       07/01/2015       Closed:       07/01/2015         - Pre Delivery Inspection       -       Hours 2.00       Labor:       120.00       Parts:       0.00       Total:       120.00         Workorder:       1507143       Meter:       128       In Date:       07/17/2015       Closed:       07/28/2015         Problem:       Install battery isolator.       -       Parts       List       Q       07/28/2015         - Install battery isolator.       Fast List       Pwr Conv       1.0       Cb185-100 Cir Brkr       1.0         - Shop Supplies       Cb185-100 Cir Brkr       1.0       Batt Cable Connector       1.0       Cs21 Black Cable 2 Ga       10.0         - Shop Supplies       Hours 5.00       Labor:       30.00       Parts:       324.49       Total:       624.49         Workorder:       1509881       Meter:       791       In Date:       09/29/2015       Closed:       10/13/2015         - Problem:       Install larger connector for cables to pump unit		1	019837	70 20	15 FORD F	250 Pickup	o, 3/4 To	n, Ext Cab,	4X4			
Hours 2.00Labor:120.00Parts:0.00Total:120.00Workorder:1507143Meter:128In Date:07/17/2015Closed:07/28/2015Problem:Install battery isolatorIn Date:07/17/2015Closed:07/28/2015- Install battery isolator fabricate wire with quick disconnect and route to back o vehicle.Parts List Pwr ConvQ- Shop SuppliesCb185-100 Cir Brkr1.0- Shop SuppliesCb185-100 Cir Brkr1.0- Batt Cable Connector1.0Batt Cable Connector1.0Batt Cable Connector1.0Batt Cable Connector1.0Fab Loom-split Poly10.0Chorder:1509881Hours 5.00Labor:300.00Parts:324.49Total:624.49Workorder:1509881Meter:791Problem:In Date:09/29/2015Closed:101/13/2015Problem:Install larger connector end on cables- Remove small ends and connector for cables to pump unit in truck bed then solder larger ends and replace with large connector Shop Supplies1.0Hours 1.00Labor:60.00Parts:951.00Hours 1.00Labor:60.00Parts:701In Date:701/2016Closed:7020.00703Parts List704Quiter:704Meter:705 <td< th=""><th></th><th></th><th></th><th></th><th></th><th></th><th></th><th>In Date:</th><th>07/01/2015</th><th>Closed:</th><th>07/01/2015</th></td<>								In Date:	07/01/2015	Closed:	07/01/2015	
Workorder:       1507143       Meter:       128       In Date:       07/17/2015       Closed:       07/28/2015         Problem:       Install battery isolator.fabricate wire with quick disconnect and route to back o vehicle.       Parts List       Pwr Conv       1.0         - Shop Supplies       Cb185-100 Cir Brkr       1.0       1.0       Electrical Tape       1.0         - Shop Supplies       Electrical Tape       1.0       Electrical Tape       1.0         - Shop Supplies       Hours 5.00       Labor:       300.00       Parts:       324.49       Total:       624.49         Workorder:       1509881       Meter:       791       In Date:       09/29/2015       Closed:       10/13/2015         Problem:       Install larger connector for cables to pump unit truck bed then solder larger ends and replace with large connector       1.0       Shop Supplies       1.0         - Shop Supplies       Hours 1.00       Labor:       60.00       Parts:       56.06       Total:       116.06         Workorder:       1600874       Meter:       8471       In Date:       01/26/2016       Closed:       02/04/2016         Problem:       Pm service.       Pm service.       Parts List       Q         - Problem:       Pm service.       Na	- Pre Delivery	/ Inspecti	on									
Problem:       Install battery isolator.         - Install battery isolator.fabricate wire with quick disconnect and route to back o vehicle.       Parts List       Q         - Shop Supplies       Cb185-100 Cir Brkr       1.0         - Batt Cable Connector       1.0         Batt Cable Connector       1.0         Batt Cable Connector       1.0         Fab Loom-split Poly       10.0         Shop Supplies       1.0         Hours 5.00       Labor:       300.00       Parts: 324.49       Total:       624.49         Workorder:       1509881       Meter: 791       In Date:       09/29/2015       Closed:       10/13/2015         Problem:       Install larger connector for cables to pump unit in truck bed then solder larger ends and replace with large connector.       Parts List       Q         Shop Supplies       1.0       Labor:       60.00       Parts:       50.06       Total:       116.06         ''       Hours 1.00       Labor:       60.00       Parts:       50.06       Total:       116.06         ''			Hours :	2.00		Labor:	120.00	Parts:	0.00	Total:	120.00	
and route to back o vehicle. - Shop Supplies - Shop Supplies - Shop Supplies - Shop Supplies - Shop Supplies - Remove small ends and connector for cables to pump unit r truck bed then solder larger ends and replace with large connector. - Shop Supplies - Remove small ends and connector for cables to pump unit r truck bed then solder larger ends and replace with large connector. - Shop Supplies - Remove small ends and connector for cables to pump unit r truck bed then solder larger ends and replace with large - Remove small ends and connector for cables to pump unit r truck bed then solder larger ends and replace with large - Remove small ends and connector for cables to pump unit - Remove small ends and connector for cables to pump unit - Remove small ends and connector for cables to pump unit - Remove small ends and connector for cables to pump unit - Remove small ends and connector for cables to pump unit - Remove small ends and connector for cables to pump unit - Remove small ends and connector for cables to pump unit - Remove small ends and connector for cables to pump unit - Remove small ends and connector for cables to pump unit - Remove small ends and connector for cables to pump unit - Remove small ends and connector for cables to pump unit - Remove small ends and replace with large - Por service. - Pm service.			-		128			In Date:	07/17/2015	Closed:	07/28/2015	
- Shop Supplies Cb185-100 Cir Brkr 1.0 Electrical Tape 1.0 Batt Cable Connector 1.0 Bat/cabl 200.0 Cs2l Black Cable 2 Ga 10.0 Fuse Holder 1.0 Fuse Holder 1.0 Fab Loom-split Poly 10.0 Shop Supplies 1.0 Hours 5.00 Labor: 300.00 Parts: 324.49 Total: 624.49 Workorder: 1509881 Meter: 791 In Date: 09/29/2015 Closed: 10/13/2015 Problem: Install larger connector end on cables - Remove small ends and connector for cables to pump unit in truck bed then solder larger ends and replace with large connector. - Shop Supplies 1.0 Hours 1.00 Labor: 60.00 Parts: 56.06 Total: 116.06 Workorder: 1600874 Meter: 8471 In Date: 01/26/2016 Closed: 02/04/2016 - Pm service. - Pm service. - Pm service. - Pm service. - Pm service. - Pm service. - Shop Supplies 5.00 Labor: 60.00 Parts: 56.06 Total: 116.06 Workorder: 1600874 Meter: 8471 In Date: 01/26/2016 Closed: 02/04/2016 - Swap Supplies 0.00 Parts: 56.06 Total: 116.06 - Workorder: 1600874 Meter: 8471 In Date: 01/26/2016 Closed: 02/04/2016 - Pm service. - Pm service. - Pm service. - Pm service. - Shop Supplies 0.00 Parts: 56.06 Total: 116.06 - Swap Supplies 0.00 Parts: 56.06 Total: 10.07 - Swap Supplies 0.00 Parts: 56.06 Total: 10.07 - Sw				ate wire v	vith quick dis	sconnect						
Electrical Tape       1.4         Electrical Tape       1.6         Bat/cabl       20.0         Bat/cabl       20.0         Cs2l Black Cable 2 Ga       10.0         Fuse Holder       1.0         Fab Loom-split Poly       10.0         Shop Supplies       1.0         Hours 5.00       Labor:         Shop Supplies       1.0         Problem:       In Date:       09/29/2015         Closed:       10/13/2015         Problem:       Install larger connector end on cables       1.0         - Remove small ends and connector for cables to pump unit in truck bed then solder larger ends and replace with large connector.       Parts List       Q         - Shop Supplies       1.00       Labor:       60.00       Parts:       56.06       Total:       116.06         Workorder:       1600874       Meter:       8471       In Date:       01/26/2016       Closed:       02/04/2016         Problem:       Pm service.       Parts List       Q         - Pm service.       Parts List       Q         - Pm service.       Parts List       Q         - Rotate and balance all four tires.       Napagold Oil Filter       1.0         - Shop Supplies			licie.									
Batt Cable Connector       1.0         Bat/cabl       20.0         Cs2l Black Cable 2 Ga       10.0         Fuse Holder       1.0         Fab Loom-split Poly       10.0         Shop Supplies       1.0         Hours 5.00       Labor:       300.00       Parts:       324.49       Total:       624.49         Workorder:       1509881       Meter:       791       In Date:       09/29/2015       Closed:       10/13/2015         Problem:       Install larger connector end on cables       9       Parts:       324.49       10/13/2015         - Remove small ends and connector for cables to pump unit in truck bed then solder larger ends and replace with large connector.       9       Parts List       Q         - Shop Supplies       Hours 1.00       Labor:       60.00       Parts:       56.06       Total:       116.06         Workorder:       1600874       Meter:       8471       In Date:       01/26/2016       Closed:       02/04/2016         Problem:       Pm service.       Parts List       Q       Q         - Pm service.       Parts List       Q       Q       Q       Q       Q       Q       Q       Q       Q       Q       Q       Q	- Shop Suppli	les										
Bat/cabl       20.0         Cs2l Black Cable 2 Ga       10.0         Fuse Holder       1.0         Fab Loom-split Poly       10.0         Shop Supplies       1.0         Hours 5.00       Labor:       30.00       Parts: 324.49       Total:       624.49         '''       In Date:       09/29/2015       Closed:       10/13/2015         Problem:       Install larger connector end on cables       Parts List       Qr         - Remove small ends and connector for cables to pump unit in truck bed then solder larger ends and replace with large connector.       Parts List       Qr         - Shop Supplies       1.00       Labor:       60.00       Parts: 56.06       Total:       116.06         ''       Hours 1.00       Labor:       60.00       Parts:       56.06       Total:       116.06         ''       Hours 1.00       Labor:       60.00       Parts:       56.06       Total:       116.06         ''       Hours 1.00       Labor:       60.00       Parts:       56.06       Total:       10.02         ''       Hours 1.00       Labor:       60.00       Parts:       56.06       Total:       116.06         ''       Hours 1.00       Swortorter:       <								•			1.0	
Cs2l Black Cable 2 Ga       10.0         Fuse Holder       1.0         Fab Loom-split Poly       10.0         Shop Supplies       1.0         Hours 5.00       Labor:       300.00       Parts: 324.49       Total:       624.49         Workorder:       1509881       Meter:       791       In Date:       09/29/2015       Closed:       10/13/2015         Problem:       Install larger connector end on cables       Parts List       Qa       Batt Cable Connector       1.0         - Remove small ends and connector for cables to pump unit in truck bed then solder larger ends and replace with large connector.       Parts List       Qa         - Shop Supplies       Hours 1.00       Labor:       60.00       Parts:       56.06       Total:       116.06         Workorder:       1600874       Meter:       8471       In Date:       01/26/2016       Closed:       02/04/2016         Problem:       Pm service.       Parts List       Qa         - Pm service.       Parts List       Qa         - Shop Supplies       Napagold Oil Filter       1.0         - Shop Supplies       Sw20 Engine Oil       60.00       Closed:       02/04/2016         - Pm service.       Sw20 Engine Oil       60.00       Was									or			
Fuse Holder       1.0         Fab Loom-split Poly       10.0         Shop Supplies       1.0         Hours 5.00       Labor:         300.00       Parts:       324.49         Total:       624.49         Problem:       Install larger connector end on cables         - Remove small ends and connector for cables to pump unit in truck bed then solder larger ends and replace with large connector.       Parts List       Qr         - Shop Supplies       Hours 1.00       Labor:       60.00       Parts:       56.06       Total:       116.06         Workorder:       1600874       Meter:       8471       In Date:       01/26/2016       Closed:       02/04/2016         Problem:       Pm service.       In Date:       01/26/2016       Closed:       02/04/2016         - Pm service.       Parts List       Qr         - Rotate and balance all four tires.       Napagold Oil Filter       1.0         - Shop Supplies       Sw20 Engine Oil       60.00         - Shop Supplies       5w20 Engine Oil       60.00         - Shop Supplies       5w20 Engine Oil       60.00         - Shop Supplies       5w20 Engine Oil       60.00         - Shop Supplies       1.0       5w20 Engine Oil							Bat/cab				20.0	
Hours 5.00       Labor:       300.00       Parts:       324.49       Total:       624.49         Workorder:       1509881       Meter:       791       In Date:       09/29/2015       Closed:       10/13/2015         Problem:       Install larger connector end on cables       Parts List       09/29/2015       Closed:       10/13/2015         - Remove small ends and connector for cables to pump unit in truck bed then solder larger ends and replace with large connector.       Parts List       00       Batt Cable Connector       1.0         - Shop Supplies       Hours 1.00       Labor:       60.00       Parts:       56.06       Total:       116.06         Workorder:       1600874       Meter:       8471       In Date:       01/26/2016       Closed:       02/04/2016         - Pm service.       -       Parts List       Qr         - Rotate and balance all four tires.       Napagold Oil Filter       1.0         - Shop Supplies       Sw20 Engine Oil       6.0       6.0         - Shop Supplies       Sw20 Engine Oil       6.0       0.0         - Shop Supplies       Sw20 Engine Oil       6.0       0.0         - Shop Supplies       Sw20 Engine Oil       6.0       0.0         - Shop Supplies       1.0									Ga		10.0	
Hours 5.00       Labor:       300.00       Parts:       324.49       Total:       624.49         Workorder:       1509881       Meter:       791       In Date:       09/29/2015       Closed:       10/13/2015         Problem:       Install larger connector end on cables       Parts List       Qatter and balance all four tires.       Qatter and balance all four tires.       1.0         - Remove small ends and connector for cables to pump unit in truck bed then solder larger ends and replace with large connector.       Parts List       Qatter and balance all four tires.       Qatter and balance all four tires.       1.0         - Pm service.       Parts 1.00       Labor:       60.00       Parts:       56.06       Total:       116.06         - Pm service.       Parts List       In Date:       01/26/2016       Closed:       02/04/2016         - Pm service.       Parts List       Qatter and balance all four tires.       Qatter and balance all four tires.       Qatter and balance all four tires.       1.0         - Shop Supplies       Sw20 Engine Oil       Gatter and balance all four tires.       1.0         - Shop Supplies       Sw20 Engine Oil       Gatter and balance all four tires.       1.0         - Shop Supplies       Shop Supplies       1.0												
Hours 5.00Labor:300.00Parts:324.49Total:624.49Workorder:1509881Meter:791In Date:09/29/2015Closed:10/13/2015Problem:Install larger connector end on cablesParts ListQr- Remove small ends and connector for cables to pump unit in truck bed then solder larger ends and replace with large connector.Parts ListQr- Shop SuppliesHours 1.00Labor:60.00Parts:56.06Total:116.06- Workorder:1600874Meter:8471In Date:01/26/2016Closed:02/04/2016- Pm serviceParts ListQr- Pm serviceNapagold Oil Filter1.0- Shop Supplies5w20 Engine Oil6.0- Shop Supplies5w20 Engine Oil6.0- Shop Supplies5w20 Engine Oil6.0- Shop Supplies5w20 Engine Oil6.0- Shop Supplies1.01.0- Shop Supplies5w20 Engine Oil6.0- Shop Supplies5w20 Engine Oil6.0- Shop Supplies1.01.0- Shop Supplies1.0- Shop Supplies1.0- Shop Supplies1.0- Shop Supplies1.0- Shop Supplies1.0- Shop Supplies1.0									/			
i Workorder: 1509881 Meter: 791 In Date: 09/29/2015 Closed: 10/13/2015 Problem: Install larger connector end on cables - Remove small ends and connector for cables to pump unit in truck bed then solder larger ends and replace with large connector. - Shop Supplies Hours 1.00 Labor: 60.00 Parts: 56.06 Total: 116.06 i Workorder: 1600874 Meter: 8471 In Date: 01/26/2016 Closed: 02/04/2016 Problem: Pm service. - Pm service. - Pm service. - Pm service. - Pm service. - Shop Supplies 56.06 Total: 116.06 i Workorder: 1600874 Meter: 8471 In Date: 01/26/2016 Closed: 02/04/2016 - Pm service. - Pm service. - Shop Supplies 56.06 Total: 116.06 i Workorder: 1600874 Meter: 8471 In Date: 01/26/2016 Closed: 02/04/2016 - Shop Supplies 56.06 Total: 116.06 i - Closed: 02/04/2016 Closed: 02/04/2016 - Clos							•	upplies			1.0	
Problem: Install larger connector end on cables       Parts List       Qi         - Remove small ends and connector for cables to pump unit in truck bed then solder larger ends and replace with large connector.       Parts List       Qi         - Shop Supplies       Hours 1.00       Labor:       Shop Supplies       1.0         Hours 1.00       Labor:       60.00       Parts: 56.06       Total: 116.06         ''       In Date:       01/26/2016       Closed:       02/04/2016         Problem:       Pm service.       Parts List       Qi         - Pm service.       Parts List       01/26/2016       Closed:       02/04/2016         - Pm service.       Parts List       01/26/2016       Closed:       02/04/2016         - Shop Supplies       Sw20 Engine Oil       6.0       02/04/2016         - Shop Supplies       Sw20 Engine Oil       6.0       02/04/2016			Hours :	5.00		Labor:	300.00	Parts:	324.49	Total:	624.49	
in truck bed then solder larger ends and replace with large connector. - Shop Supplies Hours 1.00 Connector. - Shop Supplies Hours 1.00 Hours 1.00					-	es		In Date:	09/29/2015	Closed:	10/13/2015	
in truck bed then solder larger ends and replace with large connector. - Shop Supplies Hours 1.00 : Workorder: 1600874 Meter: 8471 In Date: 01/26/2016 Closed: 02/04/2016 Problem: Pm service. - Pm service. - Rotate and balance all four tires. - Shop Supplies - Shop Suppl	- Remove sm	all ends a	and con	nector fo	or cables to p	oump unit	Parts L	ist			Q	
- Shop Supplies Shop Supplies 1.0 Hours 1.00 : Workorder: 1600874 Meter: 8471 In Date: 01/26/2016 Closed: 02/04/2016 Problem: Pm service. - Pm service. - Pm service. - Rotate and balance all four tires. - Shop Supplies 5w20 Engine Oil 6.0 Washer Fluid Concentr 1.0 Shop Supplies 1.0	in truck bed th											
Shop Supplies       Hours 1.00       Labor: 60.00       Parts: 56.06       Total: 116.06         Workorder:       1600874       Meter: 8471       In Date: 01/26/2016       Closed: 02/04/2016         Problem:       Pm service.       Parts List       Qr         - Pm service.       Parts List       Qr         - Rotate and balance all four tires.       Napagold Oil Filter       1.0         - Shop Supplies       5w20 Engine Oil       6.0         Washer Fluid Concentr       1.0         Shop Supplies       1.0							Shop Su	upplies			1.0	
: Workorder: 1600874 Meter: 8471 In Date: 01/26/2016 Closed: 02/04/2016 Problem: Pm service. - Pm service. - Rotate and balance all four tires. - Shop Supplies - Shop Supplies - Shop Supplies - Shop Supplies - Shop Supplies - Shop Supplies - Closed: 02/04/2016 - Parts List - Napagold Oil Filter - Shop Supplies - Shop Supplies - Closed: 02/04/2016 - Closed:	- Shop Suppli	ies	Hours	1 00		Labor:	60.00	Parts	56.06	Total	116.06	
Problem: Pm service.Parts ListQr- Pm service.Parts List1.0- Rotate and balance all four tires.Napagold Oil Filter1.0- Shop Supplies5w20 Engine Oil6.0Washer Fluid Concentr1.0Shop Supplies1.0			:	1.00		Labor	00.00	r arto.	00.00	rotai.	110.00	
- Rotate and balance all four tires. Napagold Oil Filter 1.0 - Shop Supplies 5w20 Engine Oil 6.0 Washer Fluid Concentr 1.0 Shop Supplies 1.0				Meter:	8471			In Date:	01/26/2016	Closed:	02/04/2016	
- Shop Supplies 5w20 Engine Oil 6.0 Washer Fluid Concentr 1.0 Shop Supplies 1.0	- Pm service.						Parts L	ist			Q	
Washer Fluid Concentr   1.0     Shop Supplies   1.0	- Rotate and I	balance a	all four t	ires.			Napago	ld Oil Filter			1.0	
Washer Fluid Concentr1.0Shop Supplies1.0	- Shop Suppli	ies					5w20 Ei	ngine Oil			6.0	
								-	entr		1.0	
							Shop Su	upplies			1.0	
:			Hours	3.75		Labor:		• •	19.19	Total:		
			:									

Workorder: Problem:	1604346 P.M. service.	Meter:	14878		I	n Date:	04/26/2016	Closed:	05/04/201	6	
- P.m. Service	e.				Parts List	t				Qty	
- Rotate and I	balance all tires	S.			Napagold		1.00				
- Complete w	heel alignment	.test drive.			5w20 Eng				f	6.00	
- Shop Suppli	-				Napagold					1.00	
					22" Wiper					2.00	
		Washer F	luid Conc	entr			1.00				
		Used Fire	X Refurb	ished			1.00				
					Shop Sup	plies				1.00	
	Hour :	rs 7.50		Labor:	450.00	Parts:	54.34	Total:	504.34		
Workorder: Problem:	1609788 P.M. Service.	Meter: Alignment.	25597		I	n Date:	09/19/2016	Closed:	09/30/201	6	
- P.m. Service	е.				Parts List	t				Qty	
•	d balance four	new tires.re	eplace spare	tire with	5w20 Eng	ine Oil			7	7.00	
one tire from t					Napagold	Oil Filter				1.00	
·	d rewire corrod	•	ug.		22" Wiper		2.00				
•	heel alignment				Washer Fluid Concentr					1.00	
- Replace and sensor.	d reprogram lea	aking left re	ar tire press	ure	Lt245 75r	2	4.00				
- Shop Suppli	ies				trailer plug					1.00	
0.10p 0.0pp.					Tire Press	1	1.00				
					Shop Sup					1.00	
					Tire Dispo					4.00	
	Hour :	rs 11.00		Labor:	660.00	Parts:	1,142.77	Total:	1,802.77		
Workorder: Problem:	1700880 Left front tire	Meter: going flat.	36167		I	n Date:	01/27/2017	Closed:	03/02/201	17	
- Repair and I	balance left fro	nt tire.			Parts List	t				Qty	
- P.m. Service	e.				Napagold	Oil Filter				1.00	
	ront brake roto		ront pads.se	rvice and	d 5w20 Engine Oil						
-	lush and bleed	-			22" Wiper Blade						
	efill transmissio				Washer Fluid Concentr						
	and charging and test.replace of			test	Napagold	Air Filter			1	1.00	
- Shop Suppli	•		attory.		Mac Wite		1	1.00			
ouppi					Syn-atf Tr		S			6.00	
					Battery 65					1.00	
					Front Brak					1.00 1.00	
							Non-chlor Brake Clnr				
		rs 11.25			Shop Sup 675.00	plies	372.68			1.00	

Workorder: Problem:	1705554 Left front til	Meter: re going flat.	41494			In Date:	06/05/2017	Closed:	06/06/20	17
- Repair left fr	ont flat tire.r	oad force ba	lance and rei	nstall on	Parts Lis	st				Qty
left front of veh - Shop Suppli		nitrogen fille	d.		Shop Su	pplies				1.00
		ours 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder:	1707182	Meter:	44029			In Date:	07/21/2017	Closed:	08/03/20	17
Problem:	P.M. servic	e and install	quick connec	ctor for slip	unit.					
- P.m. service	).				Parts Lis	st				Qty
- Replace two	front tires.b	alance and r	otate all four	tires.	5w20 En	gine Oil				8.00
- Check and r	eplace two o	defective tag	light lens.		Napagol	d Oil Filter				1.00
- Shop Suppli	es				Used Fire	e X Refurbi	shed			1.00
					22" Wipe	er Blade				2.00
					Non-chlo	or Brake Clr	nr			1.00
					Tire					2.00
					Lamp As	sy				2.00
					Shop Su	pplies				1.00
					Tire Disp	osal Fee				2.00
	Ho	ours 5.25		Labor:	315.00	Parts:	606.41	Total:	921.41	
	•								00/00/00	47
Workorder:	1707422	Meter:	44029			In Date:	07/31/2017	Closed:	08/03/20	17
			44029 battery and w	ire in		In Date:	07/31/2017	Closed:	08/03/20	17
	mount slip	unit, supply b	pattery and w		Parts Lis		07/31/2017	Closed:	08/03/20	Qty
Problem:	mount slip y unit in bed	unit, supply b	battery and w					Closed:	08/03/20	
Problem: - Mount Spray	mount slip y unit in bed	unit, supply b	battery and w		Batt Cab	st	or	Closed:	08/03/20	Qty
Problem: - Mount Spray	mount slip y unit in bed	unit, supply b	battery and w		Batt Cab Vinyl Ele	<b>st</b> le Connect	or	Closed:	08/03/20	<b>Qty</b> 1.00 1.00
Problem: - Mount Spray	mount slip y unit in bed	unit, supply b	battery and w		Batt Cab Vinyl Ele Bulk Batt	<b>st</b> le Connect ctrical Tape	or	Closed:	08/03/20	<b>Qty</b> 1.00 1.00
Problem: - Mount Spray	mount slip y unit in bed	unit, supply b	battery and w		Batt Cab Vinyl Ele Bulk Batt	<b>st</b> le Connect ctrical Tape tery Cable	or	Closed:	08/03/20	<b>Qty</b> 1.00 1.00 4.00
Problem: - Mount Spray	mount slip y unit in bed	unit, supply b	battery and w		Batt Cab Vinyl Ele Bulk Batt Bulk Batt	<b>st</b> le Connect octrical Tape tery Cable tery Cable	or	Closed:	08/03/20	<b>Qty</b> 1.00 1.00 4.00 4.00
Problem: - Mount Spray	mount slip y unit in bed es	unit, supply b	battery and w	1	Batt Cab Vinyl Ele Bulk Batt Bulk Batt Battery	st le Connect ectrical Tape tery Cable tery Cable pplies	or		455.68	<b>Qty</b> 1.00 1.00 4.00 4.00 1.00
Problem: - Mount Spray	mount slip y unit in bed es	unit, supply b	battery and w	1	Batt Cab Vinyl Ele Bulk Batt Bulk Batt Battery Shop Su	st le Connect ectrical Tape tery Cable tery Cable pplies	or Ə			<b>Qty</b> 1.00 4.00 4.00 1.00 1.00
Problem: - Mount Spray - Shop Suppli	mount slip y unit in bed es Ho : 1708722	unit, supply b , install batter burs 5.00 Meter:	pattery and w	Labor:	Batt Cab Vinyl Ele Bulk Batt Bulk Batt Battery Shop Su 300.00	st le Connect ectrical Tape tery Cable tery Cable pplies Parts: In Date:	or 9 155.68	Total:	455.68	<b>Qty</b> 1.00 4.00 4.00 1.00 1.00
Problem: - Mount Spray - Shop Suppli	mount slip y unit in bed es Ho : 1708722 Damage to	unit, supply b , install batter ours 5.00 <b>Meter:</b> front & rear	attery and w ry and wire in 44187 bumper & rig	Labor: ht top of w	Batt Cab Vinyl Ele Bulk Batt Bulk Batt Battery Shop Su 300.00	st le Connect ectrical Tape tery Cable tery Cable pplies Parts: In Date:	or 9 155.68	Total:	455.68	<b>Qty</b> 1.00 4.00 4.00 1.00 1.00
Problem: - Mount Spray - Shop Suppli Workorder: Problem: - Damage to f	mount slip y unit in bed es Ho 1708722 Damage to front & rear b	unit, supply b , install batter ours 5.00 <b>Meter:</b> front & rear	attery and w ry and wire in 44187 bumper & rig	Labor: ht top of w	Batt Cab Vinyl Ele Bulk Batt Bulk Batt Battery Shop Su 300.00	st le Connect ectrical Tape tery Cable tery Cable pplies Parts: In Date:	or 9 155.68 08/02/2017	Total:	455.68 09/01/20	<b>Qty</b> 1.00 4.00 4.00 1.00 1.00
Problem: - Mount Spray - Shop Suppli Workorder: Problem: - Damage to f cracked Workorder:	mount slip y unit in bed es Ho 1708722 Damage to front & rear b	unit, supply b , install batter ours 5.00 <b>Meter:</b> front & rear oumper & righ ours 0.00 <b>Meter:</b>	attery and w ry and wire in 44187 bumper & rig	Labor: ht top of w	Batt Cab Vinyl Ele Bulk Batt Bulk Batt Battery Shop Su 300.00	st le Connect ectrical Tape tery Cable tery Cable pplies Parts: In Date: cracked	or 9 155.68 08/02/2017	Total: Closed:	455.68 09/01/20	<b>Qty</b> 1.00 4.00 1.00 1.00
Problem: - Mount Spray - Shop Suppli Workorder: Problem: - Damage to f cracked Workorder:	mount slip y unit in bed es Ho : 1708722 Damage to front & rear to the information of the front & rear to Ho : 1800774 PM Service	unit, supply b , install batter ours 5.00 <b>Meter:</b> front & rear oumper & righ ours 0.00 <b>Meter:</b>	attery and w ry and wire in 44187 bumper & rig ht top of winc	Labor: ht top of w	Batt Cab Vinyl Ele Bulk Batt Bulk Batt Battery Shop Su 300.00	st de Connect ectrical Tape tery Cable tery Cable Parts: Parts: In Date: Parts: In Date:	or 155.68 08/02/2017 0.00	Total: Closed: Total:	455.68 09/01/20 0.00	<b>Qty</b> 1.00 4.00 1.00 1.00 1.00
Problem: - Mount Spray - Shop Suppli Workorder: Problem: - Damage to f cracked Workorder: Problem:	mount slip y unit in bed es Ho 1708722 Damage to front & rear to 1800774 PM Service	unit, supply b , install batter ours 5.00 Meter: front & rear oumper & righ ours 0.00 Meter:	attery and w ry and wire in 44187 bumper & rig ht top of winc	Labor: ht top of w	Batt Cab Vinyl Ele Bulk Batt Bulk Batt Battery Shop Su 300.00	st le Connect ectrical Tape tery Cable tery Cable pplies Parts: In Date: cracked Parts: In Date: st	or 155.68 08/02/2017 0.00	Total: Closed: Total:	455.68 09/01/20 0.00	Qty 1.00 4.00 1.00 1.00 1.7 17
Problem: - Mount Spray - Shop Suppli Workorder: Problem: - Damage to f cracked Workorder: Problem: - P.m. service - Balance and	mount slip y unit in bed es Ho 1708722 Damage to front & rear to 1800774 PM Service 2. d rotate all fo	unit, supply b , install batter ours 5.00 Meter: front & rear oumper & righ ours 0.00 Meter:	attery and w ry and wire in 44187 bumper & rig ht top of winc	Labor: ht top of w	Batt Cab Vinyl Ele Bulk Batt Bulk Batt Battery Shop Su 300.00 indshield 0.00	st le Connect ectrical Tape tery Cable tery Cable Parts: In Date: cracked Parts: In Date: st gine Oil	or 155.68 08/02/2017 0.00	Total: Closed: Total:	455.68 09/01/20 0.00	Qty 1.00 4.00 1.00 1.00 1.00 17 17 18 8.00
Problem: - Mount Spray - Shop Suppli Workorder: Problem: - Damage to f cracked Workorder: Problem: - P.m. service	mount slip y unit in bed es Ho 1708722 Damage to front & rear to 1800774 PM Service 2. d rotate all fo	unit, supply b , install batter ours 5.00 Meter: front & rear oumper & righ ours 0.00 Meter:	attery and w ry and wire in 44187 bumper & rig ht top of winc	Labor: ht top of w	Batt Cab Vinyl Ele Bulk Batt Bulk Batt Battery Shop Su 300.00 indshield 0.00 <b>Parts Lis</b> 5w20 En Napagolo	st le Connect tery Cable tery Cable pplies Parts: In Date: cracked Parts: In Date: st lgine Oil d Oil Filter	or 155.68 08/02/2017 0.00	Total: Closed: Total:	455.68 09/01/20 0.00	Qty 1.00 4.00 1.00 1.00 1.00 17 18 18 Qty 8.00 1.00
Problem: - Mount Spray - Shop Suppli Workorder: Problem: - Damage to f cracked Workorder: Problem: - P.m. service - Balance and	mount slip y unit in bed es Ho 1708722 Damage to front & rear to 1800774 PM Service 2. d rotate all fo	unit, supply b , install batter ours 5.00 Meter: front & rear oumper & righ ours 0.00 Meter:	attery and w ry and wire in 44187 bumper & rig ht top of winc	Labor: ht top of w	Batt Cab Vinyl Ele Bulk Batt Bulk Batt Battery Shop Su 300.00 indshield 0.00 Parts Lis 5w20 En Napagolo 22" Wipe	st le Connect ectrical Tape tery Cable tery Cable Parts: In Date: cracked Parts: In Date: gine Oil d Oil Filter er Blade	or 155.68 08/02/2017 0.00	Total: Closed: Total:	455.68 09/01/20 0.00	Qty 1.00 4.00 4.00 1.00 1.00 1.00 17 18 18 0ty 8.00 1.00 2.00
Problem: - Mount Spray - Shop Suppli Workorder: Problem: - Damage to f cracked Workorder: Problem: - P.m. service - Balance and	mount slip y unit in bed es Ho 1708722 Damage to front & rear to 1800774 PM Service s. d rotate all for es	unit, supply b , install batter ours 5.00 Meter: front & rear oumper & righ ours 0.00 Meter:	attery and w ry and wire in 44187 bumper & rig ht top of winc	Labor: ht top of w Ishield Labor:	Batt Cab Vinyl Ele Bulk Batt Bulk Batt Battery Shop Su 300.00 indshield 0.00 <b>Parts Lis</b> 5w20 En Napagolo	st le Connect ectrical Tape tery Cable tery Cable Parts: In Date: cracked Parts: In Date: gine Oil d Oil Filter er Blade	or 155.68 08/02/2017 0.00 01/23/2018	Total: Closed: Total: Closed:	455.68 09/01/20 0.00	Qty 1.00 4.00 1.00 1.00 1.00 17 18 18 Qty 8.00 1.00

Problem:	1801636 damage to rg	Meter: t frt fender	49411			In Date:	01/30/2018	Closed:	02/12/2018		
- damage to re	gt frt fender										
	-	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00		
Workorder: Problem:	1805415 Dead battery.	Meter:	54025			In Date:	05/29/2018	Closed:	05/29/2018		
- Charge batte was on all wee			charging syst	tem .radio	1						
	Hou :	rs 0.50		Labor:	30.00	Parts:	0.00	Total:	30.00		
Workorder: Problem:	1805486 PM Service	Meter:	54113			In Date:	05/30/2018	Closed:	06/07/2018		
- P.m. service					Parts L	.ist			Qty		
- Replace two	tires . Rotate	and high s	peed balance	e all four	Napago	old Oil Filter			1.00		
tires. Nitrofill.						ingine Oil			8.00		
<ul><li>Test and rep</li><li>Perform fron</li></ul>	-	-				old Air Filter			1.00		
- Shop Supplie	-	i ii.			Used Fire X Refurbished 1.						
	00				Lamp A	Asy			1.00		
						or Plada			2.00 2.00		
					-	per Blade iton Pvc Swe	~		2.00		
					Shop S				1.00		
						sposal Fee			2.00		
	Hou	rs 7.55		Labor:	453.00	•	559.53	Total:	1,012.53		
	:										
	1900129 P.M. service .	Meter:	63360			In Date:	01/03/2019	Closed:	01/16/2019		
Problem:	P.M. service		63360		Parts L		01/03/2019	Closed:			
Problem: - P.m. service	P.M. service			rs and	<b>Parts L</b> Drain P	.ist	01/03/2019	Closed:	01/16/2019 Qty 1.00		
Problem: - P.m. service - Inspect brake	P.M. service . es . Replace fi	ront brake	rotors ,calipe	rs and	Drain P	.ist	01/03/2019	Closed:	Qty		
Problem: - P.m. service - Inspect brake pads . Flush and - Rotate and h	P.M. service . es . Replace fi nd bleed brake nigh speed bal	ront brake e system .	rotors ,calipe Road test.		Drain P Napago	<b>.ist</b> 'lug	01/03/2019	Closed:	<b>Qty</b> 1.00		
Problem: - P.m. service - Inspect brake pads . Flush a	P.M. service . es . Replace fi nd bleed brake nigh speed bal	ront brake e system .	rotors ,calipe Road test.		Drain P Napago Napa C	<b>.ist</b> Yug old Oil Filter	01/03/2019	Closed:	<b>Qty</b> 1.00 1.00		
Problem: - P.m. service - Inspect brake pads . Flush and - Rotate and h	P.M. service . es . Replace fi nd bleed brake nigh speed bal	ront brake e system .	rotors ,calipe Road test.		Drain P Napago Napa C 22" Wip	<b>.ist</b> Plug old Oil Filter Quart 5w20		Closed:	<b>Qty</b> 1.00 1.00 7.00		
Problem: - P.m. service - Inspect brake pads . Flush and - Rotate and h	P.M. service . es . Replace fi nd bleed brake nigh speed bal	ront brake e system .	rotors ,calipe Road test.		Drain P Napago Napa C 22" Wip Washer	<b>.ist</b> Plug old Oil Filter Quart 5w20 oer Blade	entr	Closed:	<b>Qty</b> 1.00 1.00 7.00 2.00		
Problem: - P.m. service - Inspect brake pads . Flush and - Rotate and h	P.M. service . es . Replace fi nd bleed brake nigh speed bal	ront brake e system .	rotors ,calipe Road test.		Drain P Napago Napa C 22" Wip Washen Simple	<b>.ist</b> Plug old Oil Filter Quart 5w20 Der Blade r Fluid Conce	entr	Closed:	<b>Qty</b> 1.00 1.00 7.00 2.00 1.00		
Problem: - P.m. service - Inspect brake pads . Flush and - Rotate and h	P.M. service . es . Replace fi nd bleed brake nigh speed bal	ront brake e system .	rotors ,calipe Road test.		Drain P Napago Napa C 22" Wip Washer Simple Brake F Non-ch	ist Plug old Oil Filter Quart 5w20 Der Blade r Fluid Conce Green Clear Pedal Pad lor Brake Clr	entr her	Closed:	Qty 1.00 1.00 7.00 2.00 1.00 1.00 1.00		
Problem: - P.m. service - Inspect brake pads . Flush and - Rotate and h	P.M. service . es . Replace fi nd bleed brake nigh speed bal	ront brake e system .	rotors ,calipe Road test.		Drain P Napago Napa C 22" Wip Washen Simple Brake F Non-ch B Fluid	ist Plug old Oil Filter Quart 5w20 oer Blade r Fluid Conce Green Clear Pedal Pad lor Brake Clr Dot 3-32oz	entr her	Closed:	Qty 1.00 1.00 7.00 2.00 1.00 1.00 1.00 1.00		
Problem: - P.m. service - Inspect brake pads . Flush and - Rotate and h	P.M. service . es . Replace fi nd bleed brake nigh speed bal	ront brake e system .	rotors ,calipe Road test.		Drain P Napago Napa C 22" Wip Washer Simple Brake P Non-ch B Fluid Front R	ist Plug old Oil Filter Quart 5w20 Der Blade r Fluid Conce Green Clear Pedal Pad lor Brake Clr Dot 3-32oz	entr her	Closed:	Qty 1.00 1.00 7.00 2.00 1.00 1.00 1.00 1.00 2.00		
Problem: - P.m. service - Inspect brake pads . Flush and - Rotate and h	P.M. service . es . Replace fi nd bleed brake nigh speed bal	ront brake e system .	rotors ,calipe Road test.		Drain P Napago Napa C 22" Wip Washen Simple Brake F Non-ch B Fluid Front R Brake F	ist Plug old Oil Filter Quart 5w20 oer Blade r Fluid Conce Green Clear Pedal Pad lor Brake Clr Dot 3-32oz cotor Assy Pad	entr her	Closed:	Qty 1.00 1.00 7.00 2.00 1.00 1.00 1.00 1.00 2.00 1.00		
Problem: - P.m. service - Inspect brake pads . Flush and - Rotate and h	P.M. service . es . Replace fi nd bleed brake nigh speed bal	ront brake e system .	rotors ,calipe Road test.		Drain P Napago Napa C 22" Wip Washer Simple Brake F Non-ch B Fluid Front R Brake F Caliper	ist Plug old Oil Filter Quart 5w20 oer Blade r Fluid Conce Green Clear Pedal Pad lor Brake Clr Dot 3-32oz cotor Assy Pad Washer	entr her	Closed:	Qty 1.00 1.00 7.00 2.00 1.00 1.00 1.00 2.00 1.00 4.00		
Problem: - P.m. service - Inspect brake pads . Flush and - Rotate and h	P.M. service . es . Replace fi nd bleed brake nigh speed bal	ront brake e system .	rotors ,calipe Road test.		Drain P Napago Napa C 22" Wip Washen Simple Brake F Non-ch B Fluid Front R Brake F Caliper Reman	ist Plug old Oil Filter Quart 5w20 Der Blade r Fluid Conce Green Clear Pedal Pad lor Brake Clr Dot 3-32oz cotor Assy Pad Washer /ca	entr her	Closed:	Qty 1.00 1.00 7.00 2.00 1.00 1.00 1.00 1.00 2.00 1.00 4.00 1.00		
<ul> <li>P.m. service</li> <li>Inspect brake</li> <li>pads . Flush and</li> <li>Rotate and h</li> </ul>	P.M. service . es . Replace fi nd bleed brake nigh speed bal	ront brake e system .	rotors ,calipe Road test.		Drain P Napago Napa C 22" Wip Washer Simple Brake F Non-ch B Fluid Front R Brake F Caliper	ist Plug old Oil Filter Quart 5w20 Der Blade r Fluid Conce Green Clear Pedal Pad lor Brake Clr Dot 3-32oz cotor Assy Pad Washer /ca	entr her	Closed:	Qty 1.00 1.00 7.00 2.00 1.00 1.00 1.00 2.00 1.00 4.00		

:

Workorder: Problem:	1904348 Slow cranl	Meter: k and battery	67883 light flickers		l	n Date:	04/22/2019	Closed:	04/25/20	)19
- Charge batte Perform voltag isolator and re	je drop on i				<b>Parts List</b> Smartglo Maxi 70a Fus					<b>Qty</b> 1.00
- Shop Suppli	es				Pwr Conv					1.00
				Lahaw	Shop Sup		00.00	Tatali	007.00	1.00
	:	lours 2.00		Labor:	134.00	Pans:	93.26	Total:	227.26	
Workorder: Problem:	1905199 P.M. servi	Meter: ce.	68954		lı	n Date:	05/14/2019	Closed:	05/20/20	)19
- P.m. service					Parts List					Qty
- Computer di				spark	5w20 Eng	ine Oil				8.00
olug and wire					Napagold	Oil Filter				1.00
<ul> <li>Perform com injectors . Clear</li> </ul>			ind cleaning	. Flush	Napagold	Air Filter				1.00
- Resurface b			d service cali	iners	oil auto		1.00			
Replace brake				•	22" Wiper		2.00			
Road test .					Washer Fl	uid Conc			1.00	
- Rotate and b	balance all	four tires . Nit	rofill all and	reset	Used Fire	X Refurb			1.00	
Tpms.	~~				Spark Plug	9				16.00
- Shop Suppli	65				Espak Plu	g Wire				4.00
					Espak Plu	g Wire				4.00
					Injector Cl					1.00
					Intake Cle	aner Kit				1.00
					Non-chlor		nr			1.00
					B Fluid Do	ot 3-32oz				1.00
					Brake Cali	•				1.00
					Brake Cali	•				1.00
					Brake Pad					1.00
					Shop Sup					1.00
	H	lours 14.55		Labor:	974.85	Parts:	655.16	Total:	1,630.01	
Workorder: Problem:	1912301 Dead batte	Meter: ery.	74999		l	n Date:	12/02/2019	Closed:	12/04/20	)19
- Charge batte				ystem .	Parts List					Qty
Battery failed I		&r defective	battery.		Battery 65					1.00
- Shop Suppli	es				Shop Sup	olies				1.00
		lours 1.00		Labor:		<b>–</b> (	180.69	<b>T</b> . ( . )	253.69	

Workorder: Problem:	1912533 PM Service	Meter:	75111		Ir	n Date:	12/06/2019	Closed:	12/18/20	)19
- P.m. service	Э.				Parts List					Qt
- Replace fou	ir tires and bla	nce . Nitrofi	II allI and rese	et Tpms .	5w20 Engi	ine Oil				8.0
- Perform con	nplete front en	nd alignmen	t.		Napagold	Oil Filter				1.00
- Shop Suppli	ies				22" Wiper	Blade				2.00
					Mac Wite I	Lithium G	res			1.00
					245/75/17/	/tire Nitiro				4.00
					Shop Supp	olies				1.00
					Tire Dispos	sal Fee				4.00
	Hou :	ırs 7.25		Labor:	529.25	Parts:	1,177.95	Total:	1,707.20	)
Workorder: Problem:	2003307 Right rear tire	Meter: e going flat	79125		Ir	n Date:	04/01/2020	Closed:	04/06/20	)20
	rear tire, repl				Parts List					Qty
•	ure sensor. N	Nitrofill all ar	nd reset Tpms	S.	Tire Press	ure Monit	oring System	Sensor (		1.00
- Shop Suppli	ies				Tpms12 Se	ensor Tir	e Pr			1.00
					Shop Supp	مانمع				1.00
					Onop Oupp	51163				
	Hou :	urs 2.00		Labor:	146.00		83.50	Total:	229.50	
	Hou : 2005971 P.M. Service	Meter:	82885	Labor:	146.00		83.50 06/16/2020	Total: Closed:	229.50 06/25/20	
	: 2005971 P.M. Service	Meter:	82885	Labor:	146.00	Parts: n Date:				)20
Problem: - P.m. Service	: 2005971 P.M. Service e.	Meter:	82885	Labor:	146.00 Ir	Parts: n Date:				)20 Qty
Problem: - P.m. Service - rotate and b	: 2005971 P.M. Service e.	Meter:		Labor:	146.00 Ir Parts List	Parts: n Date: Oil Filter				)20 <b>Qty</b> 1.00
Problem: - P.m. Service - rotate and b	: 2005971 P.M. Service e. balance tires. theel alignmen	Meter:		Labor:	146.00 Ir Parts List Napagold	Parts: n Date: Oil Filter ine Oil				)20 <b>Qty</b> 1.00 7.00
Problem: - P.m. Service - rotate and b - Complete w	: 2005971 P.M. Service e. balance tires. theel alignmen	Meter:		Labor:	146.00 Ir Parts List Napagold 5w20 Engi	Parts: n Date: Oil Filter ine Oil Blade	06/16/2020			
Problem: - P.m. Service - rotate and b - Complete w	: 2005971 P.M. Service e. balance tires. theel alignmen	Meter:		Labor:	146.00 Ir Parts List Napagold 5w20 Engi 22" Wiper	Parts: n Date: Oil Filter ine Oil Blade uid Conc	06/16/2020 entr			020 Qty 1.00 7.00 2.00
<ul> <li>P.m. Service</li> <li>rotate and b</li> <li>Complete w</li> </ul>	: 2005971 P.M. Service e. balance tires. theel alignmen	Meter:		Labor:	146.00 <b>Parts List</b> Napagold 5w20 Engi 22" Wiper Washer Flu	Parts: n Date: Oil Filter ine Oil Blade uid Conc X Refurb	06/16/2020 entr			020 Qty 1.00 7.00 2.00 1.00
Problem: - P.m. Service - rotate and b - Complete w	: 2005971 P.M. Service e. balance tires. theel alignmen ies	Meter:			146.00 Ir Parts List Napagold 5w20 Engi 22" Wiper Washer Flu Used Fire	Parts: n Date: Oil Filter ine Oil Blade uid Conce X Refurb blies	06/16/2020 entr	Closed:		)20 <b>Qty</b> 1.00 7.00 2.00 1.00
Problem: - P.m. Service - rotate and b - Complete w - Shop Suppli Workorder:	: 2005971 P.M. Service e. balance tires. theel alignmen ies	Meter:  .ttest drive. urs 6.25 Meter:			146.00 Ir Parts List Napagold 5w20 Engi 22" Wiper Washer Flu Used Fire Shop Supp 456.25	Parts: n Date: Oil Filter ine Oil Blade uid Conce X Refurb blies	06/16/2020 entr ished	Closed:	06/25/20	020 <b>Qty</b> 1.00 7.00 2.00 1.00 1.00
Problem: - P.m. Service - rotate and b - Complete w - Shop Suppli Workorder: Problem:	: 2005971 P.M. Service e. balance tires. heel alignmen ies Hou : 2006991	Meter:       	84377	Labor:	146.00 Ir Parts List Napagold ( 5w20 Engi 22" Wiper Washer Fle Used Fire Shop Supp 456.25	Parts: n Date: Oil Filter ine Oil Blade uid Conce X Refurb blies Parts: n Date:	06/16/2020 entr ished 50.17	Closed: Total:	06/25/20	)20 <b>Qty</b> 1.00 7.00 2.00 1.00 1.00 1.00
Problem: - P.m. Service - rotate and b - Complete w - Shop Suppli Workorder: Problem: - Repair left re	: 2005971 P.M. Service e. balance tires. theel alignmen ies Hou 2006991 Left rear tire ear tire and ba	Meter:       	84377	Labor:	146.00 Ir Parts List Napagold ( 5w20 Engi 22" Wiper Washer Fle Used Fire Shop Supp 456.25	Parts: n Date: Oil Filter ine Oil Blade uid Conce X Refurb blies Parts: n Date:	06/16/2020 entr ished 50.17	Closed: Total:	06/25/20	Qty 1.00 7.00 1.00 1.00 1.00 1.00 220 Qty
Problem: - P.m. Service - rotate and b - Complete w - Shop Suppli Workorder: Problem:	: 2005971 P.M. Service e. balance tires. heel alignmen ies <u>Hou</u> 2006991 Left rear tire ear tire and ba	Meter:       	84377	Labor:	146.00 Ir Parts List Napagold ( 5w20 Engi 22" Wiper Washer Fle Used Fire Shop Supp 456.25 Ir Parts List Shop Supp	Parts: n Date: Oil Filter ine Oil Blade uid Conce X Refurb blies Parts: n Date:	06/16/2020 entr shed 50.17 07/17/2020	Closed: Total:	06/25/20 506.42 07/20/20	020 <b>Qty</b> 1.00 7.00 2.00 1.00 1.00

Workorder:	2009783	ł	Meter:	88920			In Date:	09/29/2020	Closed:	10/06/2020
				in for battery l	ight and	dead batt		JUI 201 2020	010000.	. 0, 00, 2020
- P.m. service	Э.					Parts Li	st			Qty
- Charge batt						5w20 Er	ngine Oil			7.00
R&r defective			harging s	ystem . R&r d	efective	Napagol	d Oil Filter		1.00	
battery isolato			niofiro D	ower belener	toot	22" Wipe	er Blade		2.00	
- Computer d R&r defective						Used Fir	e X Refurbi	shed		1.00
retest .						Napagol	d Air Filter			1.00
	- Test and replace corroded trailer plug connector and rewi									1.00
- Rotate and I	halance a	ll four ti	ires Nitr	ofill all		Battery 6	65			1.00
- Shop Suppli			103.111			Coil				1.00
						trailer pl	-			1.00
						-	egreaser 1 (	Gal		1.00
						Shop Su	••			1.00
		Hours :	9.75		Labor:	711.75	Parts:	509.38	Total:	1,221.13
Workorder:	2009848		Meter:	88822			In Date:	09/29/2020	Closed:	09/30/2020
Problem:	battery li	ght was	s on yest	erday, today v	wont star	t				
- Tow From: I	Mosquito	Control	To: lv sl	hop						
		Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	2010196 Towed in		Meter: ed and wo	89007 on't start .			In Date:	10/08/2020	Closed:	10/14/2020
- Charge batt	ery fully .	Test ba	attery and	d charging sys	stem .	Parts Li	st			Qty
Perform charg						Fuse Ho	lder			1.00
isolator and re spary rig in rea			epiace de	etective batter	y in	Fab Loo	m-split Poly	,		7.00
- Shop Suppli						Primary	Wire			7.00
Chief Cupph						Battery				1.00
						0				1.00
						Shop St	pplies			1.00
		Hours	2.00		Labor:	Shop St 146.00	pplies Parts:	75.57	Total:	
Workorder: Problem:	2010231 Stalled C	:	2.00 Meter:	89006	Labor:	•	••	75.57 10/08/2020	Total: Closed:	1.00
<b>Problem:</b> - Tow From: (	Stalled C	: Dut	Meter:			•	Parts:			1.00 221.57
Problem:	Stalled C	: Dut	Meter:			146.00	Parts:	10/08/2020		1.00 221.57 10/09/2020
Problem: - Tow From: ( Worth To: Lv	Stalled C cypress L shop	: Dut .akes E Hours :	Meter: states) 4 0.00	552 Wokker [	Dr, Lake	146.00	Parts: In Date: Parts:	0.00	Closed: Total:	1.00 221.57 10/09/2020 0.00
<b>Problem:</b> - Tow From: (	Stalled C cypress L shop 2012504	: Dut Lakes E Hours :	Meter: States) 4 0.00 Meter:	552 Wokker [ 92129	Dr, Lake	146.00	Parts:	10/08/2020	Closed:	1.00 221.57 10/09/2020
Problem: - Tow From: ( Worth To: Lv Workorder: Problem:	Stalled C cypress L shop 2012504 Remove	: Dut Lakes E Hours : spray	Meter: States) 4 0.00 Meter: rig from t	552 Wokker [ 92129	Dr, Lake	0.00	Parts: In Date: Parts: In Date:	0.00	Closed: Total:	1.00 221.57 10/09/2020 0.00 01/11/2021
Problem: - Tow From: ( Worth To: Lv Workorder: Problem: - Remove Sp	Stalled C (cypress L shop 2012504 Remove ray Rig fro	: Dut Lakes E Hours : spray	Meter: States) 4 0.00 Meter: rig from t	552 Wokker [ 92129	Dr, Lake	146.00 0.00 Parts Li	Parts: In Date: Parts: In Date: st	0.00	Closed: Total:	1.00 221.57 10/09/2020 0.00 01/11/2021 Qty
Problem: - Tow From: ( Worth To: Lv Workorder: Problem:	Stalled C (cypress L shop 2012504 Remove ray Rig fro	: Dut Lakes E Hours : spray	Meter: States) 4 0.00 Meter: rig from t Asset.	552 Wokker [ 92129	Dr, Lake Labor:	0.00	Parts: In Date: Parts: In Date: st	10/08/2020 0.00 12/16/2020	Closed: Total: Closed:	1.00 221.57 10/09/2020 0.00 01/11/2021

Workorder: Problem:	2101437 Transition Pre	Meter: ep Charge	92129			In Date:	02/08/2021	Closed:	02/08/2021
- Transition P	rep Charge								
	Hou :	rs 2.00		Labor:	146.00	Parts:	0.00	Total:	146.00