10186234 2012 FORD F350 Utility Body, 1 Ton, Crew Cab, Gas

Workorder: Problem:	1206722 1061 - Pr		Meter: /ery Insp	29 ection				In Date:	07/19/2012	Closed:	07/19/2	012
- Pre Delivery	Inspection	า										
	H :	Hours	4.00		Lab	or:	240.00	Parts:	0.00	Total:	240.00	
Workorder:	1300331		Meter:	2582				In Date:	01/09/2013	Closed:	01/18/2	013
Problem:	pm											
- pm							Parts Li	ist				Qty
- Shop Suppli	es						Napa Q	uart 5w20				8.00
							1372 Oi	l Filter				1.00
							Shop St	upplies				1.00
	H .	Hours	4.00		Lab	or:	240.00	Parts:	38.26	Total:	278.26	
Workorder: Problem:	1300530 cotter pin		Meter:	2582				In Date:	01/15/2013	Closed:	01/18/2	013
- replace latch	pin clip						Parts Li	ist				Qty
							2560 Hi	tch Pin-clip				1.00
	ŀ	Hours	0.25		Lab	or:	15.00	Parts:	11.43	Total:	26.43	
Workorder: Problem:	1306512 ADJUST		Meter: H/NEEDS	7055 PINTLE	E PIN			In Date:	06/28/2013	Closed:	07/12/2	013
- ck adj hitch r		verify	complai	int remov	ve hitch ad	j	Parts Li	ist				Qty
install pintle pi							18410 F	Pintle Pin				1.00
- Shop Suppli	es						Shop Su	upplies				1.00
	H	Hours	1.00		Lab	or:	60.00	Parts:	4.61	Total:	64.61	
Workorder: Problem:	1307028 PM, REP		Meter: FRONT	7399 TIRES				In Date:	07/15/2013	Closed:	07/25/2	013
- pm							Parts Li	ist				Qty
- tighten hold	downs						Napago	ld Oil Filter				1.00
- rr and baland	ced two frt	tires					Napa Q	uart 5w20				8.00
- Is and rs rea	r tire repai	r					Used Fi	re X Refurbi	ished			1.00
- Shop Suppli	es						1796364	492 Lt245-7	5r17			2.00
							Shop St	upplies				1.00
								posal Fee				2.00
	H	Hours	8.50		Lab	or:	510.00	Parts:	545.66	Total:	1,055.6	6

Workorder: 1	4404700		40000				00/04/0044	<u> </u>	00/40/0044	_
	1401733 P.M.SERVIC	Meter: E/SEE NO	13336 TE			In Date:	02/21/2014	Closed:	03/18/2014	1
- pm					Parts Li	st			c	Qty
- replace and re	ewire trailer p	olug			Napagol	d Oil Filter			1.	.00
- replace missir	ng left side ta	ail gate brad	ce		Napa Qu	art 5w20			8.	.00
- replace both f	ront and righ	nt rear tires			Napagol	d Air Filter		1.	.00	
fill all side tires with nitrogenrepair wire harness for backup alarm				Washer	FI			1.	.00	
				Trailer C	onn Plug			1.	.00	
- replace defective door lock for left rear door on utility body				1796364	92 Lt245-7	5r17		4.	.00	
door lock provid	led by dealer	r nc			Tailgate	Knee Brace	е		1.	.00
- Shop Supplies	S				Shop Su	pplies			1.	.00
					Tire Disp	osal Fee			4.	.00
					Freight C	Charge			1.	.00
	Hou	rs 13.25		Labor:	795.00	Parts:	1,111.89	Total:	1,906.89	
		Meter:	14671			In Date:	05/19/2014	Closed:	05/19/2014	1
- 2 - Key(s) issu	ued				Parts Lis	st			C	Qty
					Duplicate	e Vehicle K	eys		2.	.00
	Hou	irs 0.40		Labor:	24.00	Parts:	6.00	Total:	30.00	
	1409100 P.M.SERVIC	Meter: E,L/FRON	17728 T TIRE HAS N	NAIL		In Date:	09/10/2014	Closed:	09/15/2014	1
- pm					Parts Li	st			c	Qty
- replaced and		e running li	ght and repair	one	Napagol	d Oil Filter			1.	.00
open in utility bo	-				None O	1			0	
	المائمينة مام مرمانا	بحصراء حميمها		_ III	Mapa Qu	ıart 5w20			0.	.00
	ck and straig	htened mou	unt and reinst	alled	Washer					.00 .00
shock assy	J	htened mou	unt and reinst	alled	Washer		ished		1.	
shock assy - rr two tires and	d balanced		unt and reinst	alled	Washer Used Fir	FI			1. 1.	.00
shock assy - rr two tires and - repaired two t	d balanced ire If and rr ti		unt and reinst	alled	Washer Used Fir Gromme Marker L	FI e X Refurb it Mount Kit .amp			1. 1. 1.	.00 .00
shock assy - rr two tires and - repaired two t - unsiezed and	d balanced ire If and rr ti lubed vise	ires		alled	Washer Used Fir Gromme Marker L	FI e X Refurb t Mount Kit			1. 1. 1. 2.	.00 .00 .00
shock assy - rr two tires and - repaired two t - unsiezed and - readjusted str	d balanced ire If and rr ti lubed vise iker and latc	ires		alled	Washer Used Fir Gromme Marker L	FI e X Refurb It Mount Kit .amp 92 Lt245-7			1. 1. 1. 2. 2.	.00 .00 .00
shock assy - rr two tires and - repaired two t - unsiezed and	d balanced ire If and rr ti lubed vise iker and latc	ires			Washer Used Fir Gromme Marker L 1796364 Shop Su Tire Disp	FI e X Refurb It Mount Kit .amp 92 Lt245-7			1. 1. 1. 2. 2. 1.	.00 .00 .00 .00
shock assy - rr two tires and - repaired two t - unsiezed and - readjusted str	d balanced ire If and rr ti lubed vise iker and latch s	ires			Washer Used Fir Gromme Marker L 1796364 Shop Su	FI e X Refurb at Mount Kit amp 92 Lt245-7 pplies posal Fee		Total:	1. 1. 1. 2. 2. 1.	.00 .00 .00 .00 .00
shock assy - rr two tires and - repaired two t - unsiezed and - readjusted str - Shop Supplies	d balanced ire If and rr ti lubed vise iker and latch s Hou :	ires h for rear ta			Washer Used Fir Gromme Marker L 1796364 Shop Su Tire Disp	FI e X Refurb at Mount Kit amp 92 Lt245-7 pplies posal Fee	5r17	Total:	1. 1. 1. 2. 2. 1.	.00 .00 .00 .00 .00
shock assy - rr two tires and - repaired two t - unsiezed and - readjusted str - Shop Supplies	d balanced ire If and rr ti lubed vise iker and latch s Hou : 1411076 pintle pin	ires h for rear ta irs 11.50	ail gate		Washer Used Fir Gromme Marker L 1796364 Shop Su Tire Disp	FI e X Refurb t Mount Kit amp 92 Lt245-7 pplies posal Fee Parts: In Date:	5r17 611.73		1. 1. 2. 2. 1. 2. 1,301.73	.00 .00 .00 .00 .00
shock assy - rr two tires and - repaired two to - unsiezed and - readjusted strictly - Shop Supplies Workorder: 10 Problem: p	d balanced ire If and rr ti lubed vise iker and latch s Hou : 1411076 pintle pin	ires h for rear ta irs 11.50	ail gate		Washer Used Fir Gromme Marker L 1796364 Shop Su Tire Disp 690.00	FI e X Refurb t Mount Kit amp 92 Lt245-7 pplies posal Fee Parts: In Date:	5r17 611.73		1. 1. 2. 2. 1. 2. 1,301.73	.00 .00 .00 .00 .00 .00
shock assy - rr two tires and - repaired two to - unsiezed and - readjusted strictly - Shop Supplies Workorder: 10 Problem: p	d balanced ire If and rr ti lubed vise iker and latch s Hou : 1411076 pintle pin	ires h for rear ta irs 11.50	ail gate		Washer Used Fir Gromme Marker L 1796364 Shop Su Tire Disp 690.00 Parts Lie Pintle Pin	FI e X Refurb t Mount Kit amp 92 Lt245-7 pplies posal Fee Parts: In Date:	5r17 611.73 11/05/2014	Closed:	1. 1. 2. 2. 1. 2. 1,301.73	.00 .00 .00 .00 .00 .00
shock assy - rr two tires and - repaired two t - unsiezed and - readjusted str - Shop Supplies Workorder: 1 Problem: p - Replace Pintle	d balanced ire If and rr ti lubed vise iker and latch s Hou : 1411076 pintle pin	h for rear tans 11.50 Meter: Meter:	ail gate 19544 21535	Labor:	Washer Used Fir Gromme Marker L 1796364 Shop Su Tire Disp 690.00 Parts Lie Pintle Pin	FI e X Refurb t Mount Kit amp 92 Lt245-7 pplies posal Fee Parts: In Date: st n W/chain	5r17 611.73 11/05/2014	Closed:	1. 1. 2. 2. 1. 2. 1,301.73 11/19/2014	.00 .00 .00 .00 .00 .00
shock assy - rr two tires and - repaired two t - unsiezed and - readjusted str - Shop Supplies Workorder: 1 Problem: p - Replace Pintle	d balanced ire If and rr ti lubed vise iker and latch s Hou : 1411076 bintle pin e Pin Hou : 1500612 JTILITY DOO	h for rear taurs 11.50 Meter: Meter: OR LOCK I	ail gate 19544 21535	Labor:	Washer Used Fir Gromme Marker L 1796364 Shop Su Tire Disp 690.00 Parts Lie Pintle Pin	FI e X Refurb t Mount Kit amp 92 Lt245-7 pplies posal Fee Parts: In Date: st n W/chain Parts:	5r17 611.73 11/05/2014 2.61	Closed:	1. 1. 2. 2. 1. 2. 1,301.73 11/19/2014 01/22/2015	.00 .00 .00 .00 .00 .00
shock assy - rr two tires and - repaired two to - unsiezed and - readjusted strong - Shop Supplies Workorder: Problem: Problem: Problem: Problem:	d balanced ire If and rr ti lubed vise iker and latch s Hou : 1411076 pintle pin e Pin Hou : 1500612 JTILITY DOO e utility door	h for rear taurs 11.50 Meter: Meter: OR LOCK I	ail gate 19544 21535	Labor:	Washer Used Fir Gromme Marker L 1796364 Shop Su Tire Disp 690.00 Parts Lie Pintle Pin 15.00	FI e X Refurb t Mount Kit .amp .92 Lt245-7 pplies posal Fee Parts: In Date: In Date: In Date: In Date:	5r17 611.73 11/05/2014 2.61	Closed:	1. 1. 2. 2. 1,301.73 11/19/2014 C 1. 17.61	.00 .00 .00 .00 .00 .00 .00

Workorder: Problem:	1503077 pm, new hit	Meter: ch pin	24322		ı	n Date:	03/25/2015	Closed:	03/31/2015
- pm	 ,	о р			Parts List	ŀ			Qt
- repaired op	en in cabinet	to runnina lia	nhts		Napagold				1.0
- tightened he			,. n.o		Napagold				1.00 1.00 8.00 1.00
- repaired If ti					Napa Qua				
- rr pintal pin					Washer F				
- Shop Supplies				Wiper Bla				2.0	
					Pintle Pin				1.0
					Shop Sup	plies			1.0
	Ho	urs 7.00		Labor:	420.00	-	57.82	Total:	477.82
Workorder:	1509070	Meter:	28946			n Date:	09/10/2015	Closed:	09/18/2015
Problem:	P.M.SERVI	CE/ CHECK	L/REAR TIR	E FOR LE	AK.				
- pm					Parts List	t			Qt
- rear running					Napagold		1.0		
compartments		•		-	Napa Qua	8.0			
 removed sh shock 	ock and strai	ghtened mou	int and reins	talled	Wiper Bla		2.0		
- rr and balar	ced four tires	.			Washer Fl				1.0
- repaired left		,			Used Fire		1.0		
- Shop Suppl					17963649	4.0			
опор опрр.					Shop Sup	plies			1.0
					Tire Dispo				4.0
	Ho :	urs 11.00		Labor:	660.00	Parts:	1,105.93	Total:	1,765.93
Workorder: Problem:	1602472 pm	Meter:	33327		I	n Date:	03/08/2016	Closed:	03/14/2016
- pm dent on	hood rear bu	mper hit and	vise broken		Parts List	t			Qt
- unsiezed ar	nd lube hood	and installed	new pintal p	in	Napagold	Air Filter			1.0
- repaired gro	ound of triple	light assy an	d replace two	running	Napagold	Oil Filter			1.0
lights					Napa Qua	rt 5w20			8.0
- body bolt br	oken off utilit	y body drilled	d out bolt and	replaced	Washer F	luid Conc	entr		1.0
- rr two tires					22" Wiper	Blade			2.0
- repaired rr t			ala affina ilar	_	Lock Pin				1.0
- blew off and	•	ass and deb	ris off radiato	r	17963649	2 Lt245-7	5r17		2.0
- Shop Suppl	ies				Grommet				1.0
					Grommet	Mount Kit	:		1.0
					Shop Sup	plies			1.0
					Tire Dispo	sal Fee			2.0
					•				

Workorder: 1611009 Meter: 38950 Problem: PM service	In Date: 10/25/2016	Closed:	11/21/2016	
- Pm service.	Parts List		Qty	
- Repair and adjust tail gate.	Battery		1.00	
- Install steering wheel cover and floor mats.	Napagold Oil Filter		1.00	
- Service front calipers and replace front pads.service rear	Napa Quart 5w20		8.00	
calipers and replace rear pads.	Washer Fluid Concentr		1.00	
- Remove battery clean corrosion from terminals, hold down	22" Wiper Blade		2.00	
bracket and battery case, replace battery and repaint bracket.	Used Fire X Refurbished		1.00	
- Rotate and balance tires.fill all tires with nitrogen.	Floor Mat-2pc Rub Bk		1.00	
- Shop Supplies	Stg Wheel Cov - Ford		1.00	
	Brake Pads		1.00	
	Brake Pad		1.00	
	Non-chlor Brake Clnr		2.00	
	Ceramic Brake Lube		1.00	
	3/8 Lock Washer		1.00	
	5/16 Flat Washer		1.00	
	Shop Supplies		1.00	
Hours 19.00 Labor :	1,140.0 Parts: 452.26 0	Total:	1,592.26	
Workorder: 1612871 Meter: 39521 Problem: Accident damage	In Date: 12/14/2016	Closed:	12/15/2016	
- Tow From: South County Regional Maint Compound To: Accident Line				
Hours 0.00 Labor :	0.00 Parts: 0.00	Total:	0.00	
Workorder: 1700511 Meter: 39628 Problem: ac not cooling well	In Date: 01/18/2017	Closed:	01/24/2017	
- Evacuate, Vacuum and recharge A/c leak check system	Parts List		Qty	
- Shop Supplies	Freon Lv Shop 2		2.00	
	Shop Supplies		1.00	
Hours 1.50 Labor	90.00 Parts: 14.42	Total:	104.42	
Workorder: 1700845 Meter: 39632 Problem: Damage to hood, grille, left head light, left from		Closed:	01/26/2017	
- Damage to hood, grille, left head light, left front fender & possible under hood				
•	0.00 Parts: 0.00	Total:	0.00	

Workorder: Problem:	1704760 Pm Service	Meter: 42051			In Date:	05/12/2017	Closed:	05/22/2017	
- Pm Service- Mount and balance four tires.rotate and balance two tires.- Replace brake pedal pad.					Parts List Napagold Oil Filter Napa Quart 5w20				
- Shop Suppli	es			Washer	Fluid Conc	entr		1.00	
				22" Wipe	er Blade			2.00	
				1796364	92 Lt245-7	'5r17		4.00	
				Pedal Pa	ad			1.00	
				Shop Su	pplies			1.00	
				•	osal Fee			4.00	
	Hour :	s 6.75	Labor:	405.00	Parts:	1,079.38	Total:	1,484.38	
Workorder: Problem:	1707206 AC Not working	Meter: 43000 ng.Check trailer plu	ıg.		In Date:	07/24/2017	Closed:	08/07/2017	
- C/s ac not w	orking.verify co	oncern.perform sys	tem pressure	Parts Lis	st			Qty	
test and found leaking schrader valves.replace both schrader valves.flush ac system.recharge and leak test system Replace trailer socket.trace wire harness for trailer charging				Freon Sr		3.00			
				Ac Valve	1.00				
	harness replac		raller charging	A/c Serv	ice Port			1.00	
- Shop Suppli	-			trailer plu	ng			1.00	
				Fuse Cir	cuit			2.00	
				Shop Su	pplies			1.00	
	Hour :	s 9.50	Labor:	570.00	Parts:	76.78	Total:	646.78	
Workorder: Problem:	1710334 P.M.SERVICE	Meter: 44729 E/CHECK ENGINE	LIGHT IS ON		In Date:	10/20/2017	Closed:	11/30/2017	
- Pm Service				Parts Lis	st			Qty	
- Mount two ti	res.rotate and l	balance 6 tires		Napagol	d Oil Filter			1.00	
- Remount rea	ar cargo lamp.			Napa Qu	art 5w20			7.00	
		light on.code P145		Napagol	d Air Filter			1.00	
		ad engine purge va ear code with scan		22" Wipe	er Blade			2.00	
test.ok.	Control valve.cle	ear code with scan	tool and load	Washer	Fluid Conc	entr		1.00	
- Shop Suppli	es			1796364	92 Lt245-7	'5r17		2.00	
				Valve As	•			1.00	
				Solenoid				2.00	
				Shop Su				1.00	
					osal Fee			2.00	
	Hour :	s 11.00	Labor:	660.00	Parts:	833.58	Total:	1,493.58	
Workorder: Problem:	1710588 1 - Wash ticke	Meter: 44684 et(s) issued			In Date:	10/26/2017	Closed:	10/26/2017	
- 1 - Wash ticl	ket(s) issued								
	• •	s 0.00	Labor:	0.00	Parts:	0.00	Total:	0.00	
	·	0.00	Labor.	0.00		0.00		0.00	

	1803516 SCREW IN L/	Meter: FRONT TI	47694 RE			In Date:	04/04/2018	Closed:	04/12/2018
- Repair and ba		nt tire.nitro	gen fill all.		Parts Li Shop Su				Qty 1.00
	Hour :	s 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00
	1804197 Ac not working	Meter:	48203			In Date:	04/23/2018	Closed:	05/14/2018
- Replace leaki		alves.rech	arge system a	and	Parts Li	st			Qty
check for leaks.					Ac Valve	e Core High			1.00
- Shop Supplies	S				Freon S	r Shop			3.00
					E8 A/c (Dil Univ W D	уе		1.00
					A/c Serv	ice Port			1.00
					Valve				1.00
					A/c Valv				1.00
					Shop Su	• •			1.00
	Hour	s 4.00		Labor:	240.00	Parts:	76.75	Total:	316.75
	1805167 P.M.SERVICE	Meter: , SQUEA	48489 KING IN FROI	NT END		In Date:	05/18/2018	Closed:	06/26/2018
- Pm Service.					Parts Li	st			Qty
- Replace right	side marker l	amp bulb.			Napa Q	uart 5w20			7.00
- Replace six b		eat frozen	bolts to remo	ve	Napago	ld Oil Filter			1.00
mounts.with tor					Dielect S	Silicone Cor	np		1.00
- Replace 6 wa	-	-	ness.		Washer	Fluid Conce	entr		1.00
- Rotate and ba					22" Wip	er Blade			2.00
 Lube and adjunction rear sway bar for 		orings and	shackles and	lube	Used Fi	re X Refurbi	ished		1.00
- Clean debris f		and vacum	ne debris from	air	Term 24	-22 Conn			10.00
cowl.	irom radiator	and vacan	ic debile from	an	trailer pl	ug			1.00
- Shop Supplies	S				Boxed N	/liniatures			1.00
					Body Mo	ount Kit			4.00
					Body Mo				2.00
						Silicone Cor	mp		1.00
					Cable T				1.00
					Shop Su				1.00
	Hour :	s 17.50		Labor:	1,050.0 0	Parts:	627.23	Total:	1,677.23

Workorder: 1900388 Meter: 54002 Problem: PM Service.Ac not cooling.	In Date: 01/	/10/2019 Closed :	01/28/2019
- Pm service	Parts List		Qty
- Repair marker light.	Napagold Oil Filter		1.00
- Install floor mats and steering wheel cover.	Napa Quart 5w20		7.00
- Replace two front tires.	22" Wiper Blade		2.00
- Install bench vise.	Washer Fluid Concentr		1.00
- C/s Ac not cooling.verify concern,perform pressure	Wd40 Spr		1.00
test,evacuate,recharge system,add dye.found no leaks at thi	Boxed Miniatures		2.00
time.	Ford Triton Pvc Swc		1.00
- Replace both front shocks.	2pc Hd Mat Set Blk		1.00
- Shop Supplies	179636492 Lt245-75r17	7	2.00
	ridgid vise handle		1.00
	Freon Sr Shop		6.00
	Gas Grande Fleet Shoc	:	2.00
	Vise		1.00
	Shop Supplies		1.00
	Tire Disposal Fee		2.00
Hours 12.75 Labor	854.25 Parts: 1,1	09.43 Total:	1,963.68
Workorder: 1903332 Meter: 55492 Problem: Broken pintle pin.	In Date: 03/	/27/2019 Closed :	03/29/2019
	In Date: 03/	/27/2019 Closed :	03/29/2019 Qty
Problem: Broken pintle pin.		/27/2019 Closed :	Qty
Problem: Broken pintle pin Replace damage pintle pin and chain.	Parts List		
Problem: Broken pintle pin Replace damage pintle pin and chain.	Parts List Pintle Pin W/clip 16.75 Parts: 2.6		Qty 1.00
Problem: Broken pintle pin. - Replace damage pintle pin and chain. Hours 0.25 : Workorder: 1907672 Meter: 57983	Parts List Pintle Pin W/clip 16.75 Parts: 2.6	61 Total:	Qty 1.00 19.36 08/12/2019
Problem: Broken pintle pin. - Replace damage pintle pin and chain. Hours 0.25 Labor: Workorder: 1907672 Meter: 57983 Problem: P.M.SERVICE, CHECK A/C NOT COOLING	Parts List Pintle Pin W/clip 16.75 Parts: 2.6 In Date: 07/	61 Total:	Qty 1.00 19.36
Problem: Broken pintle pin. - Replace damage pintle pin and chain. Hours 0.25 : Workorder: 1907672 Meter: 57983 Problem: P.M.SERVICE, CHECK A/C NOT COOLING - Pm Service Replace leaking schrader valves.evacuate,recharge and test system for leaks.	Parts List Pintle Pin W/clip 16.75 Parts: 2.6 In Date: 07/ GOOD. Parts List	61 Total:	Qty 1.00 19.36 08/12/2019
Problem: Broken pintle pin. - Replace damage pintle pin and chain. Hours 0.25 Labor: Workorder: 1907672 Meter: 57983 Problem: P.M.SERVICE, CHECK A/C NOT COOLING - Pm Service.	Parts List Pintle Pin W/clip 16.75 Parts: 2.6 In Date: 07/ GOOD. Parts List Napa Quart 5w20	51 Total: /24/2019 Closed:	Qty 1.00 19.36 08/12/2019 Qty 7.00
Problem: Broken pintle pin. - Replace damage pintle pin and chain. Hours 0.25 : Workorder: 1907672 Meter: 57983 Problem: P.M.SERVICE, CHECK A/C NOT COOLING - Pm Service Replace leaking schrader valves.evacuate,recharge and test system for leaks.	Parts List Pintle Pin W/clip 16.75 Parts: 2.6 In Date: 07/ GOOD. Parts List Napa Quart 5w20 Napagold Oil Filter	51 Total: /24/2019 Closed:	Qty 1.00 19.36 08/12/2019 Qty 7.00 1.00
Problem: Broken pintle pin. - Replace damage pintle pin and chain. Hours 0.25 Labor: Workorder: 1907672 Meter: 57983 Problem: P.M.SERVICE, CHECK A/C NOT COOLING - Pm Service. - Replace leaking schrader valves.evacuate,recharge and test system for leaks. - Repair roof marker lights	Parts List Pintle Pin W/clip 16.75 Parts: 2.6 In Date: 07/ GOOD. Parts List Napa Quart 5w20 Napagold Oil Filter Washer Fluid Concentr	51 Total: /24/2019 Closed:	Qty 1.00 19.36 08/12/2019 Qty 7.00 1.00
Problem: Broken pintle pin. - Replace damage pintle pin and chain. Hours 0.25 Labor: Workorder: 1907672 Meter: 57983 Problem: P.M.SERVICE, CHECK A/C NOT COOLING - Pm Service. - Replace leaking schrader valves.evacuate,recharge and test system for leaks. - Repair roof marker lights	Parts List Pintle Pin W/clip 16.75 Parts: 2.6 In Date: 07/ GOOD. Parts List Napa Quart 5w20 Napagold Oil Filter Washer Fluid Concentr 22" Wiper Blade	61 Total: /24/2019 Closed:	Qty 1.00 19.36 08/12/2019 Qty 7.00 1.00 2.00
Problem: Broken pintle pin. - Replace damage pintle pin and chain. Hours 0.25 Labor: Workorder: 1907672 Meter: 57983 Problem: P.M.SERVICE, CHECK A/C NOT COOLING - Pm Service. - Replace leaking schrader valves.evacuate,recharge and test system for leaks. - Repair roof marker lights	Parts List Pintle Pin W/clip 16.75 Parts: 2.6 In Date: 07/ GOOD. Parts List Napa Quart 5w20 Napagold Oil Filter Washer Fluid Concentr 22" Wiper Blade Napagold Air Filter	61 Total: /24/2019 Closed:	Qty 1.00 19.36 08/12/2019 Qty 7.00 1.00 2.00 1.00
Problem: Broken pintle pin. - Replace damage pintle pin and chain. Hours 0.25 Labor: Workorder: 1907672 Meter: 57983 Problem: P.M.SERVICE, CHECK A/C NOT COOLING - Pm Service. - Replace leaking schrader valves.evacuate,recharge and test system for leaks. - Repair roof marker lights	Parts List Pintle Pin W/clip 16.75 Parts: 2.6 In Date: 07/ GOOD. Parts List Napa Quart 5w20 Napagold Oil Filter Washer Fluid Concentr 22" Wiper Blade Napagold Air Filter Used Fire X Refurbished	61 Total: /24/2019 Closed: d	Qty 1.00 19.36 08/12/2019 Qty 7.00 1.00 2.00 1.00 1.00
Problem: Broken pintle pin. - Replace damage pintle pin and chain. Hours 0.25 Labor: Workorder: 1907672 Meter: 57983 Problem: P.M.SERVICE, CHECK A/C NOT COOLING - Pm Service. - Replace leaking schrader valves.evacuate,recharge and test system for leaks. - Repair roof marker lights	Parts List Pintle Pin W/clip 16.75 Parts: 2.6 In Date: 07/ GOOD. Parts List Napa Quart 5w20 Napagold Oil Filter Washer Fluid Concentr 22" Wiper Blade Napagold Air Filter Used Fire X Refurbisher Valve	61 Total: /24/2019 Closed: d	Qty 1.00 19.36 08/12/2019 Qty 7.00 1.00 2.00 1.00 1.00 1.00
Problem: Broken pintle pin. - Replace damage pintle pin and chain. Hours 0.25 Labor: Workorder: 1907672 Meter: 57983 Problem: P.M.SERVICE, CHECK A/C NOT COOLING - Pm Service. - Replace leaking schrader valves.evacuate,recharge and test system for leaks. - Repair roof marker lights	Parts List Pintle Pin W/clip 16.75 Parts: 2.6 In Date: 07/ GOOD. Parts List Napa Quart 5w20 Napagold Oil Filter Washer Fluid Concentr 22" Wiper Blade Napagold Air Filter Used Fire X Refurbisher Valve High Side Schrader Valve	61 Total: /24/2019 Closed: d	Qty 1.00 19.36 08/12/2019 Qty 7.00 1.00 2.00 1.00 1.00 1.00
Problem: Broken pintle pin. - Replace damage pintle pin and chain. Hours 0.25 Labor: Workorder: 1907672 Meter: 57983 Problem: P.M.SERVICE, CHECK A/C NOT COOLING - Pm Service. - Replace leaking schrader valves.evacuate,recharge and test system for leaks. - Repair roof marker lights	Parts List Pintle Pin W/clip 16.75 Parts: 2.6 In Date: 07/ GOOD. Parts List Napa Quart 5w20 Napagold Oil Filter Washer Fluid Concentr 22" Wiper Blade Napagold Air Filter Used Fire X Refurbisher Valve High Side Schrader Valve Freon Sr Shop	61 Total: /24/2019 Closed: d	Qty 1.00 19.36 08/12/2019 Qty 7.00 1.00 1.00 1.00 1.00 1.00 2.00

Workorder: Problem:	2002675 PM Service.	Meter: Towed in fo	62745 r no crank/no s	start.		In Date:	03/16/2020	Closed:	03/30/2020
- Pm Service			The oraniene c	, iai ii	Parts Lis	st			Qt
		g lot.replace	battery .service	ce	Napagolo	1.0			
cables.	iii vaa pariiii	giomopiaco	battery loor vie		Napa Qu	7.00			
- Replace pir	ntle pin.				22" Wipe				2.00
- Replace 6 v	way socket an	d repaired v	viring harness.		-	Fluid Conc	entr		1.00
Mount two tires.rotate and balance all 6.Replace lamps in roof lights.				Battery	raia corre	51 IC		1.00	
				Pintle Pir	n W/clin			1.0	
- Repaired a	nd adjust tailg	ate to open	and close prop	erly	trailer plu	•			1.0
- Wash engir	ne compartme	nt.			•	^{.9} 92 Lt245-7	5r17		2.0
- Repaired le	eft rear outer ti	re.			Boxed M		0117		2.00
- Shop Supp					Shop Su				1.00
					Tire Disp				2.00
	Ца	urs 13.75		Lobor	1,003.7		650.22	Total	
	: :	uis 13.75		Labor.	1,003. <i>1</i>	rails.	650.23	TOlal.	1,653.98
Workorder:	2002749	Meter:	62488			In Date:	03/16/2020	Closed:	03/18/2020
Problem:	Towed in for	No Start ar	nd PM Service.						
	22334 Lions F 026 Jog Road		andalfoot Cobe	Park					
		urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	2010423 : P.M.SERVIC	Meter: CE, TIC IN E	65619 NGINE.			In Date:	10/16/2020	Closed:	10/27/2020
- p.m. service	Э.				Parts Lis	st			Qty
•		adlight and	replace marke	r light.	Napa Qu	art 5w20			7.00
	ewire right side			J	•	d Oil Filter			1.00
- Replace 2 t	ires, rotate an	d balance a	II 6.			Fluid Conc	entr		1.00
- c/s engine l	nave a ticking	noise. Scan	and found cod	de	22" Wipe	r Blade			2.00
	orm pinpoint te #3, all wires, 1		d coil #3 leakir	ıg.	•	e X Refurb	ished		1.00
•		o spark and	clear codes.			d Air Filter			1.00
- Test drive a	•					t Mount Kit			1.00
- Shop Supp	lies				Boxed M				2.00
						92 Lt245-7	5r17		2.00
					Spark Plu		0117		16.00
					Espak Pl	_			4.00
						•			
					Espak Pl	ug vvire			4.00
					Call				4.00
					Coil	I.			1.00
					Shop Su				1.00
					Shop Sup Tire Disp	osal Fee			1.00 2.00
	Ho:	urs 14.75		Labor:	Shop Su	osal Fee	905.75	Total:	1.00
Workorder: Problem:	Hou : 2101997 : Transition P	Meter:	66551	Labor:	Shop Sup Tire Disp 1,076.7 5	osal Fee	905.75	Total:	1.00 2.00
	: 2101997 : Transition P	Meter:	66551	Labor:	Shop Sup Tire Disp 1,076.7 5	osal Fee Parts:			1.00 2.00 1,982.50