



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V713**

In Date: 11/24/2005  
Close Date: 12/01/2005

Meter Reading:

**Problem?**

WILL NOT GO INTO PUMP, RE-20

**Task performed:**

Parts	Quantity
200-2450-00NC SWITCH OK TO PUMP	1

**Workorder: V992**

In Date: 12/21/2005  
Close Date: 12/27/2005

Meter Reading:

**Problem?**

1 SIREN SPEAKER INOP, RE-20

**Task performed:**

Parts	Quantity
NO PARTS USED	

**Workorder: V1010**

In Date: 12/27/2005  
Close Date: 12/30/2005

Meter Reading:

**Problem?**

A/C FAN MOTOR SPEED SWITCH INOP, RE-20

**Task performed:**

Parts	Quantity
ABPN8332229011-3050 SWITCH BLOWER	1

**Workorder: V1142**

In Date: 01/09/2006  
Close Date: 01/20/2006

Meter Reading:

**Problem?**

GASKET ON LADDER COMPT, NOT SEALING RE-20

**Task performed:**

Parts	Quantity
NO PARTS USED	



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

## Workorder: V1213

In Date: 01/18/2006

Meter Reading:

Close Date: 01/23/2006

### Problem?

WATER LEAK AT COUPLING ON REAR DISCHARGE, CIRCLE D LIGHT CONN. LOOSE, RE-20

Task performed:

Parts

Quantity

NO PARTS USED

## Workorder: V1261

In Date: 01/23/2006

Meter Reading:

Close Date: 01/24/2006

### Problem?

TAILLIGHTS INOP, RE-20

Task performed:

Parts

Quantity

NO PARTS USED



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V1327**

**In Date:** 01/27/2006

**Meter Reading:** 20,515.00

**Close Date:** 03/06/2006

**Problem?**

INSTALL BRACKETS TO HOLD ELEC, CORDS AND HURST HOSES, RE-20

**Task performed:**

See B Inspection pre-printed form

Parts	Quantity
0106837849C8COMP LIGHT WHITE LED 200	1
038-1550-00VALVE CHECK HALE 1/4"	1
048009000SPEEDCOUNTER PUMP PANEL	1
05-17223-000CAP RADIATOR 10 LB	1
101291015434 LATCH TRIGGER S/O	1
17211ZG98000AIR FILTER HONDA	1
180R002HURST HYD. FLUID QT	8
200-2450-00NC SWITCH OK TO PUMP	2
3530033USE 353R222 HOSE HURST SWIVEL/ORING	4
5462300020VALVE KIT SS VALVE 3 IN	2
5499FRE801910 REPAIR BRACKET A/C COMPRESSOR	1
55790-1350000008 ELECTRONIC THROTTLE 100076 FELS	1
60R00FRR600 SERIES RED LED W/O FLANGE	1
6806970098SEAL DOOR	1
7001-30ESEAL	1
78R536078R5360M 2PK FILTER AIR COND	1
9440BELT	1
9480BELT	1
A0631087000CABLE BATT. POS.	1
A0631088000CABLE BATT. NEG.	1
A1834388002MOLD L/H	3
A1834388003MOLD R/H	3
BPR5ESSPARK PLUG 7734	2
CA8193AIR FILTER 46744 WIX	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
IMMF11358SEAT BELTS	1
K080716BELT	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1
RD-5-7123-0 18-2108 FIVE BLADE FAN 3382	1
UMVS-0811-11STRAP ZICO	4
VML-T1413T3248 SIGHT GLASS	1

**Vendor?:** CENT0002



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V1678**

In Date: 03/01/2006

Meter Reading:

Close Date: 03/24/2006

**Problem?**

SCENE LIGHTS INOP, RE-20

Task performed:

Parts

Quantity

24117SOLENOID INS CONT DUTY

1

**Workorder: V1833**

In Date: 03/13/2006

Meter Reading:

Close Date: 03/27/2006

**Problem?**

L/REAR WHEEL COVER DAMAGED, RE-20

Task performed:

Parts

Quantity

NO PARTS USED

**Workorder: V2462**

In Date: 05/03/2006

Meter Reading:

Close Date: 05/04/2006

**Problem?**

TRASH LINE GAUGE LEAKS WATER, RE-20

Task performed:

Parts

Quantity

5462280020VALVE KIT 2 IN SS VALVE 546-2280-02-0

1

**Workorder: V1153**

In Date: 01/09/2006

Meter Reading:

Close Date: 05/11/2006

**Problem?**

HURST TOOL LOW POWER RE20

Task performed:

Parts

Quantity

NO PARTS USED



4/27/2021

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V1806**

In Date: 03/09/2006

Meter Reading:

Close Date: 05/11/2006

**Problem?**

REPAIR 2 HURST POWER UNITS (OUTSIDE VENDER- TEAM EQUIPMENT)

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: TEAM0001

**Workorder: V2698**

In Date: 05/22/2006

Meter Reading:

Close Date: 05/22/2006

**Problem?**

NEED NEW WIPER BLADES, E-20

Task performed:

Parts

Quantity

52-24WIPER BLADES ANCO 24

2

**Workorder: V2508**

In Date: 05/08/2006

Meter Reading:

Close Date: 05/25/2006

**Problem?**

VALVE STEM ON L/REAR INNER TIRE MISSING, RE-20

Task performed:

Parts

Quantity

6010000000NODE MINI V-MUX 6010-0000-00

1

**Workorder: V2748**

In Date: 05/25/2006

Meter Reading:

Close Date: 05/25/2006

**Problem?**

REAR A/C LEAKING WATER IN CAB, FOAM SYSTEM INOP, RE-20

Task performed:

Parts

Quantity

NO PARTS USED



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V2800**

In Date: 05/31/2006  
Close Date: 06/14/2006

Meter Reading:

**Problem?**

QUARTZ LIGHT INOP, PRIMER HOSE, E-20

**Task performed:**

Parts	Quantity
012-0010-00KNOB DRAIN	1
24117SOLENOID INS CONT DUTY	2

**Workorder: V3001**

In Date: 06/15/2006  
Close Date: 06/23/2006

Meter Reading:

**Problem?**

P/SIDE REAR WHEEL CHROME AXEL COVER MISSING, RE-20

**Task performed:**

Parts	Quantity
NO PARTS USED	

**Workorder: V3542**

In Date: 07/19/2006  
Close Date: 07/26/2006

Meter Reading:

**Problem?**

The tray on the driver's side is not connecting or locking correctly. Only one side of the tray will lock not the other.RE20

**Task performed:**

Parts	Quantity
NO PARTS USED	

**Workorder: V3526**

In Date: 07/18/2006  
Close Date: 07/27/2006

Meter Reading:

**Problem?**

repair scene light re20

**Task performed:**

Parts	Quantity
NO PARTS USED	



4/27/2021

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V3994**

In Date: 08/18/2006

Meter Reading:

Close Date: 08/22/2006

**Problem?**

PRIMER STICKING ON RE20

**Task performed:**

Parts	Quantity
2000071102000072100 SOLENOID HALE PRIMER	2
538028052VALVE PRIMER PUMP W/HARDWARE	1
9096-02SWITCH	1

**Workorder: V4021**

In Date: 08/20/2006

Meter Reading:

Close Date: 08/22/2006

**Problem?**

Driver's side scene light not working. RE20

**Task performed:**

Parts	Quantity
NO PARTS USED	

**Workorder: V4271**

In Date: 09/05/2006

Meter Reading: 1,698.00

Close Date: 09/11/2006

**Problem?**

WE WERE ON A CAR FIRE LAST NIGHT.THE FOAN SYSTEM DID NOT PICK UP ANY FOAM.WE WERE UNABLE TO GET FOAM.I BACK FLUSHED IT,BUT STILL DID NOT WORK. RE20

**Task performed:**

Parts	Quantity
NO PARTS USED	



4/27/2021

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V4654**

In Date: 09/29/2006  
Close Date: 10/17/2006

Meter Reading: 1,715.00

**Problem?**

indicator light on pressure relief valve not operating properly. RE20

**Task performed:**

1. TRAVELED TO STN 20, RELIEF VALVE NEEDS TO BE BROUGHT BACK TO SHOP FOR REBUILD.
2. TRAVELED TO STN 20 INSTALLED NEW RELIEF VALVE AND SCREEN, NEED CONTROL HEAD.
3. TRAVELED TO STN 20 R/R CONTROL HEAD. TEST/ OK

Parts	Quantity
0100080010STRAINER	2
0401130000SEAL	1
200226200200-2262-50 SWITCH-PROXIMITY QG VALVE	2
519007110SLIDE CONTROL 519-0071-10	1
538-0201-02-0QG RELIEF VALVE COMPLETE	1
538-1400-00QG VALVE	1
546-0852-01SWITCH OLD # 200-0020-00	1
546126000TPM/QG HALE REPAIR KIT	1
562008002PM CONTROL 562-0080-02	1

**Workorder: V4633**

In Date: 09/28/2006  
Close Date: 10/26/2006

Meter Reading: 1,715.00

**Problem?**

foam panel is flasing "flush" E-20

**Task performed:**

1. TRAVELED TO STN 20. INSTALLED BYPASS PLUG IN COMPUTER NEED TO BRING TO SHOP.
2. HOOK UP NEW HEAD STILL FLASHING FLUSH, INSTALL NEW WIRE SYSTEM, OK.

Parts	Quantity
NO PARTS USED	

**Workorder: V5036**

In Date: 10/23/2006  
Close Date: 10/30/2006

Meter Reading: 1,746.30

**Problem?**

battery tray on drivers side does not open. E-20

**Task performed:**

1. TRAVELED TO STN 20. REWORK LATCH FOR BATT TRAY TEST/ OK.

Parts	Quantity
NO PARTS USED	



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V5168**

**In Date:** 10/30/2006

**Meter Reading:** 1,749.00

**Close Date:** 11/08/2006

**Problem?**

L REAR COMPARTMENT INDICATOR LIGHT 10-7.COMPARTMENT OPEN LIGHT IN CAB STAYS ON. re20

**Task performed:**

1. TRAVELED TO STN 20. INSTALLED NEW SWITCH,  
TEST/ OK.

**Parts**

52-624SWITCH DOOR

**Quantity**

2



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V6326**

**In Date:** 01/17/2007

**Meter Reading:** 26,951.00

**Close Date:** 02/05/2007

**Problem?**

B INSPECTION AND REPAIRS AS NEEDED RE20

**Task performed:**

Parts

Quantity



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

1. B Inspection	0100080010STRAINER	1
2. Replaced batteries and cleaned all connections	038-1010-01HALE RELIEF VALVE W/ VULCANIZED SEAT	1
3. Service T-case	038-1790-00CHECK VALVE INJECTOR HALE FOAM SYS.	1
4. Service differential	040-1160-03-00 RING SEAL	1
5. Clean and lubricate battery drawer slides and handles	0460050000GASKET	4
6. R&R collett hoses and service cooling system	05-16422-000HOSE LOWER RADIATOR	1
7. Replaced belts and idler pully bearing	05-16423-000HOSE LOWER RADIATOR	2
8. Extend breather tube to prevent oil from being blown on engine	108-12FBEADED CHAIN W/CONN 12	1
9. Front suction hose rubbing frame bolt secured and protected hose with mud flap and reposition hose	180R002HURST HYD. FLUID QT	1
10. Foam system intermittent. Replaced injector check valve, remove check and clean flow seneor. R&R foam pump and check ok	2000071102000072100 SOLENOID HALE PRIMER	1
11. Right rear discharge leaking. Installed updated ball and rebuilt valve. Rebuilt deck gun valve and upgraded ball. Upgraded remaining valves to new ball as needed	203FFBEARING PULLEY	1
12. Intake relief valve leaking. Piping to valve loose. Remove and clean screw on flange to piping tighten and reinstall. Rebuild relief valve and install. Check valve operating properly. Replace sv sensing valve. Made gasket for valve factory valve to thin	2483224832 HOSE RADIATOR	1
13. Electronic control module. Diagnose system. Found UFT pump bad warranty sent to Cummins	2483824838 RADIATOR HOSE	1
14. Transport unit to Cummins. Pick up from Cummins.	372000084MARKER LIGHT	1
15. Cab door and under carrage light inop. Diagnose and trace wiring. Found bad ground wire to frame. Pump walk through lights all connected to node 1 found to be bad. Replaced and reprogramed node 1 . Replaced bad door switch	501-3130-00PUMP HALE FOR FOAMMASTER	1
16. Repaired faulty grounds to pump comp,engine comp, and work lights. Replaced left and right turn signal lens'	52-24WIPER BLADES ANCO 24	2
17. Install crosslay netting	52-624SWITCH DOOR	1
18. A/C filter replace and fabricate protective mesh for a/c filter	5460990500GASKET SEAL KIT P25/30	1
19. Wiper blade and fluid bug solvent	5462270020VALVE KIT SS 546-2270-02-0	1
20. Secure loose drivers side mirror	5462300020VALVE KIT SS VALVE 3 IN	2
21. Service power steering	6000000003NODE HERCULES V-MUX	1
22. Service hurst tool	78R536078R5360M 2PK FILTER AIR COND	1
23. R&R window moldings	91513AMBER LENS	2
24. Secure door latch and striker	9440BELT	1
25. Pump panal audible alarm functioning normally	9480BELT	1
	A1834388002MOLD L/H	2
	A1834388003MOLD R/H	2
	B2420LP-SMUD FLAP 24 X 24	1
	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
	CA8193AIR FILTER 46744 WIX	1
	FG87904MFG3937557S FILTER P/S NEW STYLE	1
	FGQ79699GASKET-P/S FILTER NEW STYLE	1
	FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
	HP-31DBATTERY 950CCA HP-31D	4
	HPH6349AOIL FILTER 51748	1
	K080716BELT	1
	PR338324070 WIX FILTER WATER	1
	PVG-KITORING KIT	2
	R90PFILTER FUEL 33231	1
	U-7421SWITCH - ROCKER FOR UNITY LIGHT	1



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V6403**

In Date: 01/22/2007 Meter Reading: 26,951.00

Close Date: 02/12/2007

**Problem?**

replace hose bed cover central auto trim re20

**Task performed:**

Parts

Quantity

Replace hose bed cover central auto trim

NO PARTS USED

Vendor?: CENTRAL AUTO TRIM

**Workorder: V6402**

In Date: 01/22/2007 Meter Reading: 26,951.00

Close Date: 02/21/2007

**Problem?**

rplace tires at shop callaghan ent

**Task performed:**

Parts

Quantity

replace 6 tires callaghans

NO PARTS USED

Vendor?: CALLAGHAN

**Workorder: V6770**

In Date: 02/14/2007 Meter Reading: 27,425.00

Close Date: 02/21/2007

**Problem?**

change blades on cutters e20

**Task performed:**

Parts

Quantity

1. replace blades on cutters

110R030CUTTER BLADE EXTRATOR2

2

**Workorder: V6818**

In Date: 02/18/2007 Meter Reading: 1,784.00

Close Date: 03/06/2007

**Problem?**

miv light bulbs ( amber, green, red) do not light up E20

**Task performed:**

Parts

Quantity

1. Drive to station micro switch bad needs new switches

005-1210-00-0SWITCH MNT PLATE

1

2. Rebuilt MIV valve

0073250000GEARBOX ADAPTER

1

3. Drive to station. Hook new valve to wiring still inop.

037211000SHAFT MIV VLV

1

Found positive wire bad in harness repaired ok

0409160000O-RING

1

513-0270-01513-0270-01 HALE HARNESS

1

546-1620-02MASTER INTAKE KIT

1



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

### Workorder: V7448

In Date: 03/30/2007  
Close Date: 04/13/2007

Meter Reading: 1,809.70

#### Problem?

Need 20 ft of 5 inch soft sleeve supply line. cut to outer sleeve. Noted during inspection per DC Gaffney. E -20

#### Task performed:

Wayne gave parts to station

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V8190

In Date: 05/10/2007  
Close Date: 05/22/2007

Meter Reading: 1,871.20

#### Problem?

Driver's side, rear light bar is very loose. Screws that attach the bracket to the truck body are very loose. E-20

#### Task performed:

Take seal light apart and drill tap new screw holes;  
installed screws-test ok

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V8350

In Date: 05/21/2007  
Close Date: 06/13/2007

Meter Reading: 1,877.00

#### Problem?

the front air condition is not blowing cold air, also we have an air leak around the pull out button for the air brakes. R20

#### Task performed:

1. Drive to sta, r/r A/C switch, test OK  
2. Drive to sta r/r fuel sender and parking brake valve.  
Test OK

#### Parts

22-27156-000 GASKET FUEL SENDER  
800034 VALVE PARKING BRK.  
A2243065003 FUEL SENDING UNIT  
ABPN8332229011-3050 SWITCH BLOWER

#### Quantity

1  
1  
1  
1

### Workorder: V8544

In Date: 06/01/2007  
Close Date: 06/29/2007

Meter Reading: 1,877.00

#### Problem?

when lever to deck gun is fully closed it causes all electric to pump panel to shut down. mechanic stated he will be out first thing in morning. also staed to put in code cls s1 E20

#### Task performed:

1. Drive to sta intalled new class one. Test OK

#### Parts

101847 ENGINE STATUS CTR

#### Quantity

1



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V7262**

In Date: 03/19/2007      Meter Reading: 1,809.70  
Close Date: 07/06/2007

**Problem?**

HALE SYSTEM LED READS " FLUSH". I FLUSHED THE SYSTEM AND IT STILL READS "FLUSH". IT STILL PRODUCES FOAM AND SEEMS TO FUNCTION CORRECTLY. THANKS!! RE20

**Task performed:**

1. Drive to sta, installed bypass plug. Trouble shoot. Get parts from parts room

Parts	Quantity
513-0320-03WIRING HARNES HALE MST SWITCH	1
513-0320-04WIRING HARNES MST HALE	1

**Workorder: V9371**

In Date: 07/17/2007      Meter Reading: 30,136.00  
Close Date: 07/19/2007

**Problem?**

PRIMER 10-7 RE20

**Task performed:**

1. DRIVE TO STA. R&R PRIMER MOTOR. WON'T PULL A DRAFT. R&RCHECK VALVE, TEST-OK.

Parts	Quantity
038-1550-00VALVE CHECK HALE 1/4"	1

**Workorder: V9158**

In Date: 07/05/2007      Meter Reading: 1,923.80  
Close Date: 07/20/2007

**Problem?**

hydraulic manifold malfunctioning, removed from service. E20

**Task performed:**

1. DRIVE TO STA. CHECK MANIFOLD. GIVE SPARE. BRING TO SHOP FOR REPAIR.

Parts	Quantity
NO PARTS USED	

**Workorder: V9604**

In Date: 07/29/2007      Meter Reading: 1,975.40  
Close Date: 08/07/2007

**Problem?**

AC fan control has only high speed E-20

**Task performed:**

replaced wires tested ok

Parts	Quantity
ABPN8332229011-3050 SWITCH BLOWER	1



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V9663**

In Date: 08/01/2007  
Close Date: 09/11/2007

Meter Reading: 30,405.00

**Problem?**

valve stem broken E20

**Task performed:**

Valve stem broken on tire

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN

**Workorder: V10201**

In Date: 08/31/2007  
Close Date: 09/13/2007

Meter Reading: 1,995.00

**Problem?**

every morning we find oil and transmission fluid on the ground,directly under the engine. e20

**Task performed:**

drive to Stn; fnd coolant leak which is red; ighten hose clamp; test ok; oil pan has small leak

Parts

Quantity

NO PARTS USED

**Workorder: V10373**

In Date: 09/11/2007  
Close Date: 09/25/2007

Meter Reading: 1,995.00

**Problem?**

Bracket for the Jaws cutter needs welding. e20

**Task performed:**

1. Drive to Stn; rem bracket; bring to shop for welding
2. Weld bracket
3. Drive to stn; installed cutters

Parts

Quantity

NO PARTS USED

**Workorder: V10456**

In Date: 09/14/2007  
Close Date: 09/25/2007

Meter Reading: 1,995.00

**Problem?**

Master Intake Valve lights out of service on passenger side of eng/20

**Task performed:**

Needs to be done at next B-Inspection

Parts

Quantity

ABPN8332229011-3050 SWITCH BLOWER

1



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V10267**

In Date: 09/05/2007  
Close Date: 09/26/2007

Meter Reading: 1,995.00

**Problem?**

Transmission temp. light is lit. Trans temp. is at 160 at normal operating temp.

**Task performed:**

Parts

Quantity

1. DRIVE TO STATION, TRACED WIRE FOUND BARE WIRE IN HARNESS, REPAIRED TEST O.K.
2. ASST. LEHAN WITH REPAIRS.

NO PARTS USED

**Workorder: V10622**

In Date: 09/24/2007  
Close Date: 09/27/2007

Meter Reading: 30,696.00

**Problem?**

ON CALL E20 COMP WARNING LT ON

**Task performed:**

Parts

Quantity

1. DOOR OPEN LIGHT WON'T TURN OFF- NESS TO REMOVE PIN SWITCHES AND CLEAN TERMINAL AND REINSTALL AND ADJUST.

NO PARTS USED

**Workorder: V10710**

In Date: 09/27/2007  
Close Date: 10/01/2007

Meter Reading: 1,995.00

**Problem?**

rear door buzzer will not shut off E20

**Task performed:**

Parts

Quantity

1. DROVE TO STATION, R/R REAR DOOR CAB LEFT SIDE SWITCH, TEST O.K.

52-624SWITCH DOOR

1

**Workorder: V9575**

In Date: 07/27/2007  
Close Date: 10/15/2007

Meter Reading: 1,969.50

**Problem?**

Front A/C on E20 not blowing cold.

**Task performed:**

Parts

Quantity

- drive to station. fill with freon ckeck for leak, tigthen fitting tested ok

NO PARTS USED



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V10704**

In Date: 09/27/2007      Meter Reading: 1,995.00  
Close Date: 10/22/2007

**Problem?**

please have on road guy come by about moving a mounting bracket E-20

**Task performed:**

drive to station. mount equipment in compartment. repair ground lights on tail board. test ok..

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V11535**

In Date: 11/09/2007      Meter Reading: 31,892.00  
Close Date: 11/15/2007

**Problem?**

on call re 20 check brakes

**Task performed:**

1. Check brake squeek sound, check ok, Check drive line bolts, OK at this time.

**Parts**

032-0116549297 BATTERY INDICATOR

**Quantity**

1

**Workorder: V11786**

In Date: 11/28/2007      Meter Reading: 32,189.00  
Close Date: 12/12/2007

**Problem?**

tank lid baffle missisng e20

**Task performed:**

1. Drive to Sta. installed baffle.

**Parts**

2FC00ZCR4 IN ROUND LED  
A240258TANK BAFFEL  
FREIGHTSHIPPING CHARGES  
MFG01876GROUND LT BRACKET

**Quantity**

1  
1  
1  
1

**Workorder: V10198**

In Date: 08/31/2007      Meter Reading: 1,995.00  
Close Date: 01/14/2008

**Problem?**

the lights indicating open or closed on the intake steamer,passenger side are not working. e20

**Task performed:**

1. Check system, water in gear box need rebuild.  
2. Repaired in shop at PM.

**Parts**

NO PARTS USED

**Quantity**



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V12055**

**In Date:** 12/13/2007

**Meter Reading:** 32,518.00

**Close Date:** 01/15/2008

**Problem?**

Ladder heat indicators expired. e20

**Task performed:**

Parts

Quantity

1. Drive to station inspection on ladder and installed indicators.

NO PARTS USED

---



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V12407**

**In Date:** 01/07/2008

**Meter Reading:** 32,761.00

**Close Date:** 01/24/2008

**Problem?**

c inspection and repairs as needed e20

**Task performed:**

1. Lock tight screws on axe bracket.
2. Service gen, fan, Hurst power unit, plugs- oil- filter.
3. REplace cab door wether strips.
4. REplace all heat stickers on ladders.
5. "B" inspection.
6. Service air dryer.
7. Batt try latches frozen, ness to remove ass and replace latches.
8. Master intake indicator Inop. ness to R+R gear ass to diagnose and repair.
9. Meeting with Tim.
10. Coolant leaking, ness to remove fuel filter and tighten all coolant hoses to air comp.
11. Adjust front and rear brakes.
12. Primer valves sticking on, ness to remove both valves and rebuild.
13. Replace R-rear discharge valve to Acron.
14. Rear tail board markers, R+R L.E.D. bulbs.

Parts	Quantity
038-1550-00VALVE CHECK HALE 1/4"	1
05-17223-000CAP RADIATOR 10 LB	1
073004100PISTON	2
10129102690ZNF/WO FLUSH LOCK BOLT	2
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
1160033 IN FLANGE ADPT W/ HOLES P2S	2
15-18150-04OIL DRAIN CUMMINS ISB ISC	1
15W40BSYN OIL BULK QTS	21
17211ZG98000AIR FILTER HONDA	1
2863428634 PLASTIC TEE	1
29526898 29548988 TRANS FILTER ALLISON	1
35200-RLIGHT MARKER LED RED	3
4537BULB 100W SPOT	1
50R00FRRFLASHER RED LED FLANGED	1
52-24WIPER BLADES ANCO 24	2
5462270020VALVE KIT SS 546-2270-02-0	1
55790-1350000008 ELECTRONIC THROTTLE 100076 FELS	1
6806970098SEAL DOOR	1
78308930 AKRON 3 IN VALVE	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
8113-483IN SS NIPPLE	1
883088301201 3 IN SLO-CLOZ W/R1 HANDLE	1
BPR5ESSPARK PLUG 7734	2
CA8193AIR FILTER 46744 WIX	1
CD2004DRAIN HOSE	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
PR338324070 WIX FILTER WATER	1
PVG-KITORING KIT	2
R90PFILTER FUEL 33231	1



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V12635**

In Date: 01/16/2008  
Close Date: 01/31/2008

Meter Reading: 32,761.00

**Problem?**

repair front intake e20

**Task performed:**

1. Drive to Stn20
2. Replc front intake switch j

Parts

Quantity

MJTV5 VALVE AIR CONTROL

1

**Workorder: V12661**

In Date: 01/17/2008  
Close Date: 02/01/2008

Meter Reading: 2,149.00

**Problem?**

losing air for brakes had mechcanic work on the truck yesterday for the front suction valve not opening,he fix it but now losing air t brakes? e20

**Task performed:**

1. Drive to Stn20
2. Rep air leaks j

Parts

Quantity

NO PARTS USED

**Workorder: V12910**

In Date: 01/30/2008  
Close Date: 02/05/2008

Meter Reading: 30,975.00

**Problem?**

DECK GUN VALVE 10-7 E20

**Task performed:**

1. Drive to stn;; work with them on pump test; valve came apart; missing parts.
2. have turck come to shop; replc the valve & clutch; test ok. j

Parts

Quantity

5462300020VALVE KIT SS VALVE 3 IN

1

**Workorder: V2583**

In Date: 05/12/2006  
Close Date: 02/07/2008

Meter Reading:

**Problem?**

K-12 SAW PULL CORD BROKE, RE-20

**Task performed:**

Parts

Quantity

NO PARTS USED



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V2834**

In Date: 06/02/2006  
Close Date: 02/07/2008

Meter Reading:

**Problem?**

FOAM SYSTEM INOP, DRAIN HANDLE MISSING #4 DISCHARGE, HURST TOOL DUMP VALVE INOP, RE-20

**Task performed:**

Parts

Quantity

NO PARTS USED

**Workorder: V13482**

In Date: 02/25/2008  
Close Date: 03/18/2008

Meter Reading: 33,874.00

**Problem?**

install slow close on rt rear discharge e20

**Task performed:**

Parts

Quantity

1. Drive to station, installed slow close valve, test OK

FZ51368FEET RUBBER RAM-FAN

4

**Workorder: V14201**

In Date: 04/01/2008  
Close Date: 04/03/2008

Meter Reading: 1,288.00

**Problem?**

red coolant leak on e20

**Task performed:**

Parts

Quantity

1. Drive to station, water pump leaking. Remove pump, wait for parts, install and test OK

40896474309418 PUMP-WATER ISC REBUILT

1

**Workorder: V15112**

In Date: 05/15/2008  
Close Date: 06/17/2008

Meter Reading: 32,713.00

**Problem?**

ON A CALL YESTERDAY THE PUMP ENGAGED ON ITS OWN WHILE IN NEUTRAL. WHEN TRANSMISSION ENGAGED, MOTOR STALLED. IT WAS THEN NOTICED THE PUMP LIGHT WAS ON. THE MOTOR WAS RESTARTED, PLAYED WITH AIF ACTUATOR AND IT SEEMED OK E-20

**Task performed:**

Parts

Quantity

1. drive to station transfer case switch shorted out switch full of oil replaced switch tested ok

200-2450-00NC SWITCH OK TO PUMP

1



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V15469**

In Date: 06/02/2008  
Close Date: 07/07/2008

Meter Reading: 32,713.00

**Problem?**

repair electrical problem re20

**Task performed:**

1. drive to sta. reprogram. node 3 installed test ok

**Parts**

601000000NODE MINI V-MUX 6010-0000-00

**Quantity**

1

**Workorder: V15475**

In Date: 06/02/2008  
Close Date: 07/07/2008

Meter Reading:

**Problem?**

need new hurst tool holding strap,need to have the hurst tool tips mounted,and medal tray has dropped down e20

**Task performed:**

1. drive to station. repair shelf and installed strap and hook ojn jaws. test ok

**Parts**

UMVS162511STRAP

UMVS254411STRAP 46 IN

**Quantity**

2

3

**Workorder: V15883**

In Date: 06/21/2008  
Close Date: 07/07/2008

Meter Reading: 2,413.00

**Problem?**

while using the foam unit i noticed no foam was coming out.i tried to adjust it,and it turned off.was unable to get it back on. E20

**Task performed:**

1. drive to station low volts going to motor check wires , need solenoid

**Parts**

24117SOLENOID INS CONT DUTY

**Quantity**

1

**Workorder: V16341**

In Date: 07/13/2008  
Close Date: 07/22/2008

Meter Reading:

**Problem?**

master drain leaking at valve on e20

**Task performed:**

Drive to Stn; R/R drain; test ok. j

**Parts**

104967DIAPHRAM FOR 6 PORT DUMP VALVE

**Quantity**

1



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V16579**

**In Date:** 07/25/2008

**Meter Reading:** 3,251.20

**Close Date:** 07/28/2008

**Problem?**

NEED DRY CHEMICAL EXTINGUISHER REFILLED. USED ON A CALL e20

**Task performed:**

1. no charge , crew picked up at HQ

Parts

NO PARTS USED

Quantity



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V17225**

**In Date:** 08/21/2008

**Meter Reading:** 37,164.70

**Close Date:** 09/24/2008

**Problem?**

C INSPECTION AND REPAIRS AS NEEDED E20

**Task performed:**

Parts

Quantity



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

1. C INSPECTION	02036317300STROBE LINEAR REFLECTOR 6ELTUBE	1
2. R&R RT SIDE CAB OVERHEAD LT ASS	038-1010-01HALE RELIEF VALVE W/ VULCANIZED SEAT	1
3. SERVICED HURST TOOLS	038-1550-00VALVE CHECK HALE 1/4"	1
4. SERVICED GENERATOR	040154000O-RING FOR HALE FOAM PUMP	2
5.SERVICED TRASH LINE AND BATTERY BOX PULL OUTS	042002000SPRING RELIEF VALVE HALE	1
6. REAR MARKER LTS INOP REPAIR AND REPLACED AS NEEDED	0460050000GASKET	2
7. REPLACED BELTS	101281011GSS6297UM 60# DOOR STRUT QUINT	2
8. U JOINTS WONT TAKE GREASE REPLACED BAD U JOINTS	107796DRYER KIT AD9 -NEW	1
9. ASSIST WITH U JOINT REPLACEMENT (LARSON)	107800VALVE CHECK AD9	1
10. FAILED VACCUM TEST REBUILD INTAKE RELIEF ALSO ADJUSTED DISCHARGE VALVES TO FULLY CLOSE	1212BTURTLE TILE 12X12 BLACK	3
11. FOAM LEAK FOUND FITTING AT TANK DEFECTIVE REPLACED FITTING AND FLUSHED OLD FOAM FROM SYSTEM	15W40BSYN OIL BULK QTS	41
12. FOAM FILL PUMP INOP REPLACED PUMP ASS ALSO FOUND HOSES CLOGGED REPLACED HOSES	1654-8FERRULE .718	1
13. MOVED ALL HURST BRACKET AND EQUIPMENT TO RT SIDE REPAIRED SLIDE OUT TRAYS AND SHELVES	168-0380-51USE 168-0380-56-0 OLD CONTROL UNIT HALE	1
14. UNIT PULLS TO RT. SWAPED TIRES AND ROAD TESTED NPF	17211ZG98000AIR FILTER HONDA	1
15. STEERING WHEEL OFF CENTER REMOVE WHEEL AND CENTER ROAD TEST	18-45484-000LATCH L/H	1
16. L HIGH BEAM 10-7 AND MARKER LTS 10-7 REPAIR AS NEEDED	19615ZG9800ZCOVER HONDA HURST ENGINE	1
	200-2481-00-0546-3240-00-0 FOAM PUMP SENSOR KIT	2
	322051400 CKVLV FITTING	1
	35200-RLIGHT MARKER LED RED	3
	35200-YLIGHT MARKER LEDAMBER	2
	3530016HOSE HURST 16 ORANGE	2
	39768315259022 GROOVED TENSIONER OLD#3936213	1
	4300-505PUMP FLOJET 12V	1
	440-44 1/8 IN VALVE EXT	3
	5-280XU-JOINT	2
	52-24WIPER BLADES ANCO 24	4
	5269LPVM-5 SM MOUNT	1
	538-1410-00VALVE SENSING SV HALE	1
	538-1490-02FLUSH SELECT HALE FOAM SYS	1
	546-0852-01SWITCH OLD # 200-0020-00	1
	546126000TPM/QG HALE REPAIR KIT	1
	6811813635S68-1181363-5S LENS RED 64 SERIES	1
	75W90GEAR OIL SYN QT	19
	78R536078R5360M 2PK FILTER AIR COND	1
	800405PURGE VALVE KIT	1
	9440BELT	1
	9480BELT	1
	ANTICOOLANT ANTIFREEZE GAL	11
	BPR5ESSPARK PLUG 7734	2
	CA8193AIR FILTER 46744 WIX	1
	CD2004DRAIN HOSE	1
	ECVDMLT00DOME LIGHT	1
	FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
	H6054USE CV TYPE SEALED BEAM	2
	HPH6349AOIL FILTER 51748	1





4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V17929**

In Date: 09/25/2008  
Close Date: 09/30/2008

Meter Reading: 37,164.70

**Problem?**

RELIEF VALVE LT 10-7 E20

**Task performed:**

1. Drive to Sta-20. Installed ground wires/Test (OK).

**Parts**

200226200200-2262-50 SWITCH-PROXIMITY QG VALVE

**Quantity**

1

(R.T.)

**Workorder: V18082**

In Date: 10/02/2008  
Close Date: 10/07/2008

Meter Reading: 37,164.70

**Problem?**

rebuild relief valve control (bench)

**Task performed:**

Rebuild relief valve. j

**Parts**

040-1130-03RING-PISTON SEAL (QG RELIEF VALVE)

250-8002-00250-8002-00 BEARING-THRUS

538-1400-00QG VALVE

546126000TPM/QG HALE REPAIR KIT

**Quantity**

1

1

1

1

**Workorder: V18096**

In Date: 10/02/2008  
Close Date: 10/09/2008

Meter Reading: 3,251.20

**Problem?**

back door passenger door alarm keeps going off,door doesnt close wright e20

**Task performed:**

1. Drive to Sta-20. R/R door lock and S+W adjusted.  
Test (OK).

**Parts**

NO PARTS USED

**Quantity**

(R.T.)



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V18050**

**In Date:** 09/30/2008  
**Close Date:** 10/20/2008

**Meter Reading:** 3,251.20

**Problem?**

foam system is not flowing any foam,also the pressure relief valve light did not function at all today. E20

**Task performed:**

1. Replc relief valve, control, screen; rework wiring on relief light; test ok; form help with foam sys.
2. Foam sys inop; works intermittently; adj optical sensor; got foam to work on 1.0%; then back off to .5%; needs more troubleshooting. j

Parts	Quantity
0100080010STRAINER	1
516-0670-52-0TALL SENSOR GEARS	2
538-0201-02-0QG RELIEF VALVE COMPLETE	1
546085303NC SWITCH/BRACKT	1
562008150PMD CONTROL VALVE	1

**Workorder: V18295**

**In Date:** 10/12/2008  
**Close Date:** 10/21/2008

**Meter Reading:** 36,508.20

**Problem?**

E20 PRIMER 10-7

**Task performed:**

- dri ve to Stn; replc pump, valve, hoses leaking air on new valve; rework; test ok. j

Parts	Quantity
103103THROTTLE INTERFACE	1
501-3090-00PRIMER PUMP MOTOR	1
538028052VALVE PRIMER PUMP W/HARDWARE	1

**Workorder: V18367**

**In Date:** 10/16/2008  
**Close Date:** 10/21/2008

**Meter Reading:** 2,574.00

**Problem?**

moderate to heavy leak from Relief Valve. Pressurized at hydrant per shop - fixed - no longer leaking e20

**Task performed:**

- drive to Stn; still lkeaing after fire; adj valve & chkd foam sys; test ok; send to shop for foam. j

Parts	Quantity
NO PARTS USED	



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V18317**

In Date: 10/14/2008  
Close Date: 10/24/2008

Meter Reading: 36,508.20

**Problem?**

on call primer 10-7 e20

**Task performed:**

Primer inop; motor bad & primer valve switch sticking; installed new motor/valve; send motor burned up; went back to shop for fittings; cld not get pump throttle back in panel w/new valve; needs additional work. j

Parts	Quantity
2000071102000072100 SOLENOID HALE PRIMER	1
502-0061-00502-0061-00 PRIMER PUMP	1
538028052VALVE PRIMER PUMP W/HARDWARE	1

**Workorder: V18379**

In Date: 10/16/2008  
Close Date: 10/24/2008

Meter Reading: 2,574.00

**Problem?**

FOAM SYSTEM DID NOT WORK ON A CALL UNTIL AFTER THE FIRE WAS EXTINGUISHED. PROBLEM SEEMS INTERMITTENT E20

**Task performed:**

1. Drive truck on lift; talk w/John about repairs.  
2. Assist in foam sys.  
3. Foam sys inop; sensor intermittent failure; replc foam; now sensor sys ok. j

Parts	Quantity
200-2491-00SENSOR HALE HPF FOAM FLOW	1
BM6AU5E 5921 SPARK PLUG	3

**Workorder: V18827**

In Date: 11/04/2008  
Close Date: 11/17/2008

Meter Reading: 2,606.00

**Problem?**

left headlight out on E20

**Task performed:**

Drive to Stn; replc headlight; test ok. j

Parts	Quantity
H6054USE CV TYPE SEALED BEAM	1

**Workorder: V18876**

In Date: 11/05/2008  
Close Date: 11/19/2008

Meter Reading: 37,016.00

**Problem?**

incoming pressure releaf valve is leaking e20

**Task performed:**

drive to stn; take to Hyd Hush; rework valve; test ok. j

Parts	Quantity
NO PARTS USED	



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V18954**

In Date: 11/10/2008  
Close Date: 11/19/2008

Meter Reading: 37,382.70

**Problem?**

MARKER LIGHT 10-7

**Task performed:**

Drive to stn; bring vent saw buck Y& replcd markere; test ok. j

Parts

372000084MARKER LIGHT

Quantity

1

**Workorder: V19204**

In Date: 11/20/2008  
Close Date: 11/26/2008

Meter Reading: 37,382.70

**Problem?**

honda eg3500 generator needs a new gas cap. ours broke on e20

**Task performed:**

Drive to Stn; installed new fuel cap; fuel leak at tank; rep; test ok. j

Parts

4527495GAS CAP HONDA ENG

Quantity

1

**Workorder: V19451**

In Date: 12/02/2008  
Close Date: 12/02/2008

Meter Reading: 2,655.00

**Problem?**

the cap on the right rear wheels is missing e20

**Task performed:**

Drive to Stn; rem caps & hardware; test ok. j

Parts

NO PARTS USED

Quantity

**Workorder: V18813**

In Date: 11/03/2008  
Close Date: 12/04/2008

Meter Reading: 37,016.00

**Problem?**

REPAIR VENT SAW E 20 REGAN

**Task performed:**

Repair vent saw E20-Regan

Parts

NO PARTS USED

Quantity

Vendor?: REGAN



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

### Workorder: V19616

In Date: 12/09/2008  
Close Date: 12/15/2008

Meter Reading: 2,655.00

#### Problem?

passenger side window crank is not working wright,also there is a lot of fluids on the floor in the area of the rear end. e20

#### Task performed:

1-drive to station installed new crank. test ok.

#### Parts

#### Quantity

78R536078R5360M 2PK FILTER AIR COND

1

A1818557002HANDLE-WINDOW

1

### Workorder: V19739

In Date: 12/14/2008  
Close Date: 12/23/2008

Meter Reading: 2,683.00

#### Problem?

ON BOARD AIR PRESSURE SYSTEM LEAKS DOWN TOO 60LBS WITHIN A COUPLE HRS. E-20

#### Task performed:

Drive to Stn; rebuild air shift; look for leak; test shifter;  
test ok. j

#### Parts

#### Quantity

5460370530VPS SHIFT KIT 546-0370-53-0

1

### Workorder: V19736

In Date: 12/14/2008  
Close Date: 01/02/2009

Meter Reading: 2,683.00

#### Problem?

right main side light, bulb #2 is burnt out. E-20

#### Task performed:

drive to Stn; rework wire & replc bulb; test ok. j

#### Parts

#### Quantity

LB-D30BULB QUARTZ HAL. 12V 150W

1

### Workorder: V20443

In Date: 01/18/2009  
Close Date: 02/04/2009

Meter Reading: 40,954.00

#### Problem?

One of the prongs for the TIC battery charger in E20 is broken off.

#### Task performed:

1- Drive to station, install and wire new charger test ok.

#### Parts

#### Quantity

NO PARTS USED



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V20696**

In Date: 01/29/2009

Meter Reading:

Close Date: 02/24/2009

**Problem?**

leak coming from pump when in gear. significant leak when pumping onto wiring harnesses E20

**Task performed:**

**Parts**

**Quantity**

Drive to stn; tighten bolts for valve; test ok. j

NO PARTS USED

**Workorder: V21288**

In Date: 02/23/2009

Meter Reading: 40,101.80

Close Date: 02/24/2009

**Problem?**

wont pull draft e20

**Task performed:**

**Parts**

**Quantity**

Rep pressure relief valve that was leaking & replc chk valve. j

546126000TPM/QG HALE REPAIR KIT

1

**Workorder: V21235**

In Date: 02/20/2009

Meter Reading: 40,101.80

Close Date: 02/28/2009

**Problem?**

relief valve innop, need engine oil, generator won't start E20

**Task performed:**

**Parts**

**Quantity**

drive to Stn; change oil on gen; adj carb; test ok; chk relief; rebuild; give oil to stn. j

15W40QSYN OIL QT

12

180R002HURST HYD. FLUID QT

1

**Workorder: V21300**

In Date: 02/23/2009

Meter Reading:

Close Date: 02/28/2009

**Problem?**

relief valve leaking alot try to reset e20

**Task performed:**

**Parts**

**Quantity**

1. Drive to Stn; rebuild inlet relief valve & remove piping & rework piping & flanges on pump; test ok.

538-1410-00VALVE SENSING SV HALE

1

2. Get parts for Mike; re build intake relief valve; rep pump flange gskt leak; reseal leaking piping. - Vasko.

546126000TPM/QG HALE REPAIR KIT

1

3. Travel to Stn20 from shop. j

EG-3500OIL CAP HONDA

1



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

**Workorder: V21336**

In Date: 02/25/2009

Meter Reading:

Close Date: 02/28/2009

**Problem?**

pressure relief does not work e20

**Task performed:**

1. R/R relief valve; took ol one apart-ok; chk plumbing on sensing valve; fnd (2) hoses swapped; rep hoses-ok.
2. Assist with above - Reines. j

Parts	Quantity
0100080010STRAINER	2
538-0201-02-0QG RELIEF VALVE COMPLETE	1

**Workorder: V16829**

In Date: 08/05/2008

Meter Reading: 37,164.70

Close Date: 03/02/2009

**Problem?**

generator oil plug stripped E17 (Honda EG3500)

**Task performed:**

Parts	Quantity
EG-3500OIL CAP HONDA	1

**Workorder: V17241**

In Date: 08/22/2008

Meter Reading: 3,251.20

Close Date: 03/02/2009

**Problem?**

fast EDIE could we meaning you guys move the hurst tools to the other side of the truck passenger side we would be grateful if yc could.also the driver door keeps comming open by it self or maybe the crew? thanks BOB W e20

**Task performed:**

Parts	Quantity
NO PARTS USED	

**Workorder: V21664**

In Date: 03/09/2009

Meter Reading: 2,834.70

Close Date: 03/17/2009

**Problem?**

water leak under pump area e20

**Task performed:**

Drive to Stn; replace filling; test ok. j

Parts	Quantity
NO PARTS USED	



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V21722**

In Date: 03/11/2009  
Close Date: 03/17/2009

Meter Reading: 2,834.70

**Problem?**

officers window crank handle stripped or loose. E20.....

**Task performed:**

drive to Stn; installed crank; test ok. j

Parts	Quantity
39768315259022 GROOVED TENSIONER OLD#3936213	1
5269LPVM-5 SM MOUNT	1
640179E1 A/C BELT TENSIONER	1
A1818557002HANDLE-WINDOW	1

**Workorder: V21777**

In Date: 03/13/2009  
Close Date: 03/17/2009

Meter Reading: 1,881.70

**Problem?**

Pressure relief valve sticks open and tank to pump lever sticks closed. E20

**Task performed:**

Work done on another W/O 21822. j

Parts	Quantity
NO PARTS USED	

**Workorder: V21822**

In Date: 03/16/2009  
Close Date: 03/18/2009

Meter Reading: 43,224.20

**Problem?**

tank to pump valve not working properley e20

**Task performed:**

Svc call to Stn20; fnd tank to pump valve not working; adj/tightened linkage; ran/tested with opr; ck ok; went to Stn28. j

Parts	Quantity
NO PARTS USED	

**Workorder: V23182**

In Date: 05/10/2009  
Close Date: 05/20/2009

Meter Reading: 2,945.00

**Problem?**

Rear upper red clearance light red lens dome cover is missing. E-20

**Task performed:**

Drive to Stn; replcd light; test ok. j

Parts	Quantity
NO PARTS USED	



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V23455**

In Date: 05/21/2009

Meter Reading: 45,043.30

Close Date: 05/21/2009

**Problem?**

replace tires at shop callaghan

**Task performed:**

**Parts**

**Quantity**

NO PARTS USED

Vendor?: CALLAGHAN

**Workorder: V23391**

In Date: 05/19/2009

Meter Reading: 45,043.30

Close Date: 05/22/2009

**Problem?**

B INSPECTION AND REPAIRS AS NEEDED E20

**Task performed:**

**Parts**

**Quantity**

- Road test & B-Inspection
- 2. Load test of btys; slow weak cells fail test; rem/install L1 new btrys.
- 3. Rem brkn pump panel light lens; install new lens.
- 4. Replc dirty A/C filter.
- 5. P/S svc, oil & filter.
- 6. Primer valve sticking; rem valve, cln/rebuild valve; reinstall/operate primer valve.
- 7. Rem faded flag decals & install new flags.
- 8. Foam slow to flow; inspect/cln strainer; cln foam injector nozzle; cln foam flow sensor; operate foam sys/fill water tank.
- 9. Roof top spotlight inop; dia failure; fnd loose connection at globe; correct fault.
- 10. Pump RPM cable brkn; rem pieces, flush tube & make up new cable & install.
- 11. L-3 door struts weak; rem/install new struts.
- 12. Aux equip on trucks; chk opn & fluid of exh fan; gen & Hurst power unit. j

68-3963453-30LENS CLEAR FOR STRIP LIGHT	1
680-10LAMERICAN FLAG W UV CLEAR LEFT	1
680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
78R536078R5360M 2PK FILTER AIR COND	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HP-31DBATTERY 950CCA HP-31D	4
HPH6349AOIL FILTER 51748	1
PVG-KITORING KIT	1
R90PFILTER FUEL 33231	1

**Workorder: V23370**

In Date: 05/19/2009

Meter Reading: 2,949.00

Close Date: 05/26/2009

**Problem?**

headlight out e20

**Task performed:**

**Parts**

**Quantity**

Replcd headlight & rep wires. j

NO PARTS USED



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V23790**

In Date: 06/03/2009  
Close Date: 06/04/2009

Meter Reading: 45,043.30

**Problem?**

repair station blower sta 20 (outside agency-regan's small engine service)

**Task performed:**

Parts

Quantity

NO PARTS USED

Vendor?: REGANS

**Workorder: V23456**

In Date: 05/21/2009  
Close Date: 06/19/2009

Meter Reading: 45,043.30

**Problem?**

replace window trim moldings e20 (deferred) parts ordered 5/21

**Task performed:**

Parts

Quantity

drive to Stn; installed panels. j

A1834388002MOLD L/H

1

A1834388003MOLD R/H

1

**Workorder: V23841**

In Date: 06/04/2009  
Close Date: 06/19/2009

Meter Reading: 45,043.30

**Problem?**

the vent fan is not working properly. i have to feather the choke to get a constant throttle speed. maybe carb needs to be cleaned? E-20

**Task performed:**

Parts

Quantity

Drive to Stn; installed plug to adj carb; call Regan. j

NO PARTS USED

**Workorder: V23608**

In Date: 05/28/2009  
Close Date: 06/23/2009

Meter Reading: 2,949.00

**Problem?**

E20 side panel primer switch not working. Primer on the pump panel works fine.

**Task performed:**

Parts

Quantity

Drive to Stn; bad grd on switch; rework; test ok. j

NO PARTS USED



4/27/2021

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V24097**

In Date: 06/15/2009  
Close Date: 06/23/2009

Meter Reading: 45,708.00

**Problem?**

repair three tic lanyards E20

**Task performed:**

Mod original assemble of lanyards; rep (3) lanyards.  
j

Parts

Quantity

NO PARTS USED

**Workorder: V24415**

In Date: 06/28/2009  
Close Date: 07/08/2009

Meter Reading: 3,003.00

**Problem?**

steamer primer not working E-20

**Task performed:**

dRIVE TO sTN; INSTALLED NEW PRIMER VALVE &  
FITTING; TEST OK. J

Parts

Quantity

538028052VALVE PRIMER PUMP W/HARDWARE

1

**Workorder: V24110**

In Date: 06/15/2009  
Close Date: 07/09/2009

Meter Reading: 45,708.00

**Problem?**

repair ram fan E20 (outside agency-regan's small engine service)

**Task performed:**

Repair ram fan E20 - Regans j

Parts

Quantity

NO PARTS USED

Vendor?: REGANS SMALL ENG

**Workorder: V23734**

In Date: 06/02/2009  
Close Date: 07/22/2009

Meter Reading: 45,043.30

**Problem?**

tic lanyard is broken from fire e20

**Task performed:**

Drive to Stn; chk TIC & lanyard. j

Parts

Quantity

NO PARTS USED

Vendor?: \*



4/27/2021

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

### Workorder: V25018

In Date: 07/23/2009

Meter Reading: 3,003.00

Close Date: 07/30/2009

#### Problem?

primer making funny noises this am, then stopped working. seconds later worked fine. e20

#### Task performed:

Drive to stn; cln pos connections; test ok. j

Parts

NO PARTS USED

Quantity

### Workorder: V25019

In Date: 07/23/2009

Meter Reading: 3,003.00

Close Date: 07/30/2009

#### Problem?

trash line and battery drawers broken. mechanic already looked at needs to bring parts/hardware.. e20

#### Task performed:

drive to stn; take latches apart; cln; installed; test ok. j

Parts

NO PARTS USED

Quantity

### Workorder: V25937

In Date: 08/31/2009

Meter Reading: 42,900.50

Close Date: 09/21/2009

#### Problem?

driver side rear compartment door switch is broke. temp.fixed or rided e20

#### Task performed:

Drive to Stn; replc door swtch & tested ok. j

Parts

52-624SWITCH DOOR

Quantity

3

### Workorder: V26311

In Date: 09/17/2009

Meter Reading: 3,074.00

Close Date: 09/24/2009

#### Problem?

driver side rear door needs to be adjusted, hard to close., also check other rear door E-20

#### Task performed:

Went to Stn20; fnd driver's side rear door closing hard; adj striker pin; ck opn; ck ok; ck officers side rear door; fnd door hard to open frm inside; adj pin; ck ok; went to Stn18. j

Parts

NO PARTS USED

Quantity



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V26765**

In Date: 10/08/2009

Meter Reading:

Close Date: 11/06/2009

**Problem?**

last compartment on drivers side, 1 shock absorber broken and the other one is loose. e20

**Task performed:**

Parts

Quantity

Drive to Stn; drill out & tap both doors; replc (1) shock;  
test ok. j

EAA-8500-90GAS STRUT 6348UD

1

**Workorder: V26771**

In Date: 10/08/2009

Meter Reading:

Close Date: 11/06/2009

**Problem?**

K12 ON E20 WILL NOT START ASSET # 101522251

**Task performed:**

Parts

Quantity

See W/O 26659 j

NO PARTS USED

**Workorder: V27929**

In Date: 11/24/2009

Meter Reading: 3,207.00

Close Date: 12/07/2009

**Problem?**

rear left upper compartment door switch broke. needs replacement. door open lights flash and buzzer sounds but door is closed.  
E20

**Task performed:**

Parts

Quantity

1. Travel to Stn20 from C/S.
2. R/R L/R compt door switch. j

52-624SWITCH DOOR

1

**Workorder: V28596**

In Date: 12/27/2009

Meter Reading: 3,248.00

Close Date: 01/06/2010

**Problem?**

during morning check the primer motor is not working properly, it would disengage at times. E20

**Task performed:**

Parts

Quantity

tested primer several times - ok. j

NO PARTS USED



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V28737**

In Date: 01/01/2010  
Close Date: 01/28/2010

Meter Reading: 3,264.10

**Problem?**

Foam system does not work during pump operations. Trouble shooted on system with no success. E20

**Task performed:**

Foam system inop; test - working properly. j

Parts

NO PARTS USED

Quantity

**Workorder: V29211**

In Date: 01/17/2010  
Close Date: 02/10/2010

Meter Reading: 47,665.30

**Problem?**

FLOAT A PUMP WON'T STAY RUNNING, THROTTLE DOES NOT SEEM TO BE WORKING PROPERLY.E20

**Task performed:**

Went to Stn20; brought float-a-pump to shop; tried to adj vent saw; doesnt idle; brought to shop. j

Parts

NO PARTS USED

Quantity

**Workorder: V29633**

In Date: 02/02/2010  
Close Date: 03/01/2010

Meter Reading: 47,665.30

**Problem?**

replace burnt modual in battery comp

**Task performed:**

1. Went to Stn20 from Stn18; fnd module/wires melted; replcd module & mnt screws; replcd term at mod; wired mod; R/R 3 AMP fuse; started & ck ok; opn ck ok.
2. Fnd right rear wheel splash guard loose; fnd screws brkn; drilled/replcd brkn screws; ck ok. j

Parts

0R80-0615-00INTERFACE MODULE

Quantity

1



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

**Workorder: V29814**

In Date: 02/08/2010

Meter Reading: 48,071.10

Close Date: 03/08/2010

**Problem?**

C INSPECTION AND REPAIRS AS NEEDED E 20

**Task performed:**

1. C-Inspection
2. Svc T-case.
3. R/R eng belts.
4. Fireup, cln/lube btry & tras line slides.
5. R/R primer valve.
6. R/R door seals.
7. Fast adapt trans.
8. Tighten/adj all compt doors.
9. Adj air horns.
10. Chk for coolant leak; rem fuel filter asy; tighten air compressor cooing line.
11. R/R shocks.
- 12./R air dryer.
13. Replc deck gun valve w/new Akron valve; mod/adj linkage.
14. rem, rebuild/adj #1, 2, 3, & 4 discharge valve.
15. Rem, rebuild/ajd crosslay valves & hose real valve.
16. R/R compt door shocks. j

**Parts**

**Quantity**

107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
15W40BSYN OIL BULK QTS	24
35200-RLIGHT MARKER LED RED	1
52-24WIPER BLADES ANCO 24	2
538028052VALVE PRIMER PUMP W/HARDWARE	1
5462270020VALVE KIT SS 546-2270-02-0	2
5462280020VALVE KIT 2 IN SS VALVE 546-2280-02-0	2
5462290020VALVE KIT SS VALVE 2 1/2 546-2290-02-0	3
6803230300 65482 SHOCK FRONT ENGINE	2
6806840018DOOR SILL L/H	1
6806970098SEAL DOOR	1
800405PURGE VALVE KIT	1
883088301201 3 IN SLO-CLOZ W/R1 HANDLE	1
9440BELT	1
9480BELT	1
CA8193AIR FILTER 46744 WIX	1
EAA-8350-60UGSS6557UP STRUT-LIFT	2
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
K080716BELT	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1

**Workorder: V30880**

In Date: 03/19/2010

Meter Reading: 48,888.80

Close Date: 04/09/2010

**Problem?**

Foam system, ref. Mike Lehan e20

**Task performed:**

- Went to HQ; FNP w/water going into foam tank; fnd foam fill pump inop; rem hoses/pump; R/R pump asy; ck opn; ck ok. j

**Parts**

**Quantity**

4300-505PUMP FLOJET 12V	1
-------------------------	---



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

## Workorder: V31732

In Date: 04/23/2010

Meter Reading: 49,184.10

Close Date: 05/03/2010

### Problem?

Foam system need to be check for foam stop flowing doing operation. After several tries turning off and on, it started working again for a short time. Unknown problem for sometime per other Drivers. e20

### Task performed:

1. Travel to Stn20; chk foam sys; fnd sys working but display bar flashing & dumping too much foam for wtr flow; set control head to factory default; sys needs to be calibrated; wait on veh.

2. Travel to Stn20; calibrate wtr flow. j

### Parts

NO PARTS USED

### Quantity

## Workorder: V31862

In Date: 04/28/2010

Meter Reading: 49,184.10

Close Date: 05/17/2010

### Problem?

Front hood (R) emergency lights not working E20

### Task performed:

Fnd R/hood lite inop; ck power/grnd; ck ok; replc bulb asy; installed connector terms; mntd lite/lens; ck all lites; ck ok. j

### Parts

60R00FRR600 SERIES RED LED W/O FLANGE

1

## Workorder: V31838

In Date: 04/27/2010

Meter Reading: 49,184.10

Close Date: 05/20/2010

### Problem?

Could you please hardwire our GPS on E20 so it always remains on ? E20

### Task performed:

Went to Stn20; rem dash panels; ran/fused wire to power outlet; ck ok. j

### Parts

NO PARTS USED

### Quantity

## Workorder: V32149

In Date: 05/12/2010

Meter Reading: 52,105.00

Close Date: 05/20/2010

### Problem?

Deck gun warning light and buzzer sounding. Two wires coming off deck gun disconnected and loose. E20

### Task performed:

Went to HQ; fnd alarm going off on deck gun; fnd wires brkn off switch & touching grnd; rep wires to switch; ck alarm opn; ck ok. j

### Parts

NO PARTS USED

### Quantity



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V32197**

In Date: 05/13/2010      Meter Reading: 52,105.00  
Close Date: 05/20/2010

**Problem?**

Air leaks when ever brakes or applied. Do not notice drop in pressure. Leak can be heard in cab e20

**Task performed:**

Went to Stn20 from Stn18; aired truck; rem dash panels;  
fnd air switch leaking; R/R switch; ck for leaks; ck ok.  
j

Parts	Quantity
FSC17492134NC SW PARK BK SPADE TYPE CONNECTOR	1

**Workorder: V32096**

In Date: 05/10/2010      Meter Reading: 52,003.00  
Close Date: 05/25/2010

**Problem?**

Top rear emergency flasher driver's side not working E20

**Task performed:**

Went to Stn20; fnd tailboard light out; R/R light; fnd left  
marker light out; R/R bulb; ck all lights ck ok.      j

Parts	Quantity
35200-RLIGHT MARKER LED RED	1
35200-YLIGHT MARKER LEDAMBER	1

**Workorder: V32541**

In Date: 06/01/2010      Meter Reading: 52,778.00  
Close Date: 06/08/2010

**Problem?**

ON CALL DOOR ALRAM ON E20

**Task performed:**

went to 20 from 28; fnd officers door switch inop; R/R  
switch; ck opn; chk ok; return home.      j

Parts	Quantity
52-624SWITCH DOOR	1

**Workorder: V32235**

In Date: 05/16/2010      Meter Reading: 52,243.40  
Close Date: 06/10/2010

**Problem?**

the pump on the engine continues to trip from under the apparatus at a steady rate. Unable to see were leak is from. The leak is bad enough that the water has to be removed from the floor every 4 hrs or so. E20

**Task performed:**

1. Ck for wtr leak w/operator; fnd very small leak at pipe  
thread on lower flange for rear discharge; ck intake  
relief-not leaking; after driver operated on shift change -  
no leak present.  
2. Went to 20; fnd L-3 compt door opening too far; rem  
shocks & installed shock mnt end in correction position;  
fnd out-stripped; rep & chnk ok.      j

Parts	Quantity
NO PARTS USED	



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V32688**

In Date: 06/07/2010      Meter Reading: 52,857.00  
Close Date: 06/18/2010

**Problem?**  
on call e 20 electrical short

Task performed:	Parts	Quantity
Cut out AMP reader to v-mux sys; short & cut fire. j	0R80-0615-00INTERFACE MODULE	2

**Workorder: V33176**

In Date: 06/27/2010      Meter Reading: 52,857.00  
Close Date: 07/15/2010

**Problem?**  
Unable to draft from front steamer E20

Task performed:	Parts	Quantity
Went to 20; opened frnt suction pipe valve; drained pump & suction pipe; tightened all end caps; pulled 18" vac; suction pulley vac; went to 25; pulled draft & fan pump ck ok. j	NO PARTS USED	

**Workorder: V33488**

In Date: 07/12/2010      Meter Reading: 52,857.00  
Close Date: 07/23/2010

**Problem?**  
Replace spot light E20

Task performed:	Parts	Quantity
went to Stn20; fnd L/scene light out; R/R bulb; ck opn; ck ok. j	LB-D30BULB QUARTZ HAL. 12V 150W	1

**Workorder: V32623**

In Date: 06/03/2010      Meter Reading: 52,778.00  
Close Date: 08/02/2010

**Problem?**  
Engine RPM reading on the Engine Staus Center (Class 1) not working E20

Task performed:	Parts	Quantity
went to 20; ran truck in pump - NPF; ck w/ all shifts; NPF. j	NO PARTS USED	



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V34273**

In Date: 08/14/2010  
Close Date: 09/03/2010

Meter Reading: 53,495.00

**Problem?**

red flasher on left side rear out E20

**Task performed:**

1. Went to 20; fnd rear tailboard light out; R/R LED ight; Chk opn; ck ok.
2. Fnd Right marker light out; Rem light; rep connection; ck ok. js

Parts

Quantity

60R00FRR600 SERIES RED LED W/O FLANGE

1

**Workorder: V34808**

In Date: 09/08/2010  
Close Date: 09/23/2010

Meter Reading: 53,495.00

**Problem?**

E20 beep/tone in the cab when pump is engaged E20

**Task performed:**

1. Went to 20; started/ran truck in pump gear; fnd beeping from dash; normal opn.
2. Ck for fuel leak; fnd wtr filter leaking; rep leak; ran/ck ok. j

Parts

Quantity

NO PARTS USED

**Workorder: V33410**

In Date: 07/08/2010  
Close Date: 10/19/2010

Meter Reading: 52,857.00

**Problem?**

right front tire needs to be checked out because it is starting to cup on the inside E20

**Task performed:**

completed j

Parts

Quantity

NO PARTS USED



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V35401**

**In Date:** 10/04/2010

**Meter Reading:** 55,453.00

**Close Date:** 11/05/2010

**Problem?**

**B INSPECTION AND REPAIRS E 20**

**Task performed:**

1. b inspection
2. test and service batteries
3. r&r clearance light bulb
4. repair tail board marker lights, found bad ground, test ok.
5. check and add trans fluid
6. check tires and adjust to proper pressure.
7. no ok to pump light, inspected and found missing screw, r&r light fixture , test ok.
8. test pump relief valve, found valve slow,check and adjusted switch, relief valve still hanging up, r&r relief valve and rebuild.
9. master pump display guage missing led bulbs, replaced display, sent old display out for repairs.
10. check instrument cluster, instrument cluster doesnt display, r&r instrument cluster and transfer gauge. old milage is 55464.
11. diagnose passenger side window problem, found stripped out window crank handle, replaced handle , test ok.
12. rebuild primer valve.
13. inspect rear cab a/c, found leak at high side port, recover freon, replace fitting and recharge. test ok.
14. fill water tank, calibrate water and foam gauge flow.
15. r&r relief valve and rebuild.
16. primer valve leaks, repair primer valve lines
17. calibrate foam pump, would not calibrate, replaced motor feed back sensor, removed foam pump and cleaned, reinstall foam pump and calibrate, test ok.
18. check foam pump operation, fill water tank.
19. replace fitting on bypass valve. jab

<u>Parts</u>	<u>Quantity</u>
040-1130-03RING-PISTON SEAL (QG RELIEF VALVE)	1
040-2420-00RING-VALVE BODY SEAL (QG VALVE)	1
042-0091-00SPRING PRIMER	1
042-0550-00SPRING-VALVE QG RELIEF VALVE	1
082-2007-00-0GREASE ZERK W/CHECK VLV	1
15W40BSYN OIL BULK QTS	24
200-2481-00-0546-3240-00-0 FOAM PUMP SENSOR KIT	1
52-24WIPER BLADES ANCO 24	2
546-2210-02-0LIGHT KIT HALE	1
546126000TPM/QG HALE REPAIR KIT	1
A1818557002HANDLE-WINDOW	1
A2249250001 A22-49250-003 CLUSTER ASSY	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
IOA200A00DISPLAY MODULE REBUILD ONLY SEND IN	1
PVG-KITORING KIT	2
R90PFILTER FUEL 33231	1



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V36410**

In Date: 11/12/2010  
Close Date: 11/18/2010

Meter Reading: 55,552.00

**Problem?**

primer making different sounds, and will not pull draft. Also floating strainer weld broke needs repair or new strainer sent out to station... dm E20

**Task performed:**

1. Drop off new floating strainer to stn.
  2. Had no primer work at either locns; rep wires on primer motor & (1) switch primer; works ok.
  3. Rep pump throttle \_\_\_\_ problem; change throttle & cln out connection to nodes & press gov/class one unit.
- j

**Parts**

**Quantity**

Parts	Quantity
55790-135000008 ELECTRONIC THROTTLE 100076 FELS	1

**Workorder: V36326**

In Date: 11/09/2010  
Close Date: 11/30/2010

Meter Reading: 55,552.00

**Problem?**

When relief valve light comes on, it will not disengage until you throttle down so it will release. e20

**Task performed:**

- (1) TRAVELED TO ST 20 FOR PROBLEM WITH E20 RELIEF VALVE NOT DISENGAGING WHEN THE LIGHT COMES ON. YOU HAVE TO THROTTLE DOWN FOR IT TO RELEASE. BACK FLUSHED PUMP AND INTAKE RELIEF. OK
- (2) E20 FAILS DRY VACUUM TEST AND WILL NOT DRAFT. TESTED FOR DRAFTING,NEEDS ADDITIONAL WORK DONE.
- (3) TRAVELED TO ST20 AND INSTALLED ON E20 A NEW STEP & REMOUNTED 5" HOSE AS/ STATION REQUEST. DONE. J.W.

**Parts**

**Quantity**

Parts	Quantity
SAHSVS2510STRAP	2

**Workorder: V36840**

In Date: 12/03/2010  
Close Date: 01/05/2011

Meter Reading: 55,948.90

**Problem?**

buzzer for deck gun wont turn off. E20

**Task performed:**

1. Travel to stn; Deck gun warning stays on; sensor bad - no sensor on truck.
2. Replc deck gun sensor. j

**Parts**

**Quantity**

Parts	Quantity
XG840-KITEXTENDA GUN SWITCH	1



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

### Workorder: V36737

In Date: 11/30/2010  
Close Date: 01/06/2011

Meter Reading: 55,948.90

#### Problem?

Black pressurized door assist/stabilizer attached to the It rear (generator compartment) door broke off. E20

#### Task performed:

Travel to stn; door strut brkn L-3 compt; replc strut. j

#### Parts

EAA-8350-30UGSS1783UQ STRUT-LIFT

#### Quantity

2

### Workorder: V36802

In Date: 12/01/2010  
Close Date: 01/06/2011

Meter Reading: 55,948.90

#### Problem?

antilock brake It on e 20

#### Task performed:

1. Travel to stn; ABS light on; R/F sensor out of adj; adj sensor & cleared code. j

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V36970

In Date: 12/07/2010  
Close Date: 01/12/2011

Meter Reading: 55,948.90

#### Problem?

air leak. delayed response. Engine wont move until refilled e20

#### Task performed:

(1) TRAVELED TO ST-20 TO REPAIR AIR LEAK ON E20. FOUND LEAK IN DASH VALVE.  
(2) REPLACED THE GOVERNOR THAT WAS LEAKING AIR.  
(2) CAB LEVELING VALVE LEAKING AIR. ORDERED NEW VALVE.

#### Parts

284358GOVERNOR D-2  
800034VALVE PARKING BRK.  
LML-1350-0113AIR RIDE VALVE (CAB)

#### Quantity

3  
1  
1

### Workorder: V37657

In Date: 01/05/2011  
Close Date: 01/18/2011

Meter Reading: 112,445.00

#### Problem?

air leaks on engine. needs to be checked out. E20

#### Task performed:

1. Travel to stn. Cab air ride wolve leaking; replc valve.  
2. Officers seat air leak - fitting bad under seat; diss cable & rep seat. j

#### Parts

NO PARTS USED

#### Quantity



4/27/2021

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10152055

\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

### Workorder: V37809

In Date: 01/14/2011

Meter Reading: 57,365.00

Close Date: 01/24/2011

#### Problem?

Our spotlight on the top of E20 is too dim for proper viewing at low light conditions. The housing also has a short, when the light is moved with the remote it constantly goes out. E20

#### Task performed:

drive to spotlight inop - worn; replcd roof mnt search lights. j

#### Parts

620122SPOT LIGHT REMOTE

#### Quantity

1

### Workorder: V38967

In Date: 03/04/2011

Meter Reading: 58,719.00

Close Date: 03/17/2011

#### Problem?

check tic charging system. does not seem to charge properly E20

#### Task performed:

Travel to stn20; relocated TIC charger & hand light; replc headlights.

#### Parts

15W40QSYN OIL QT

H6054USE CV TYPE SEALED BEAM

#### Quantity

12

2

### Workorder: V39466

In Date: 03/27/2011

Meter Reading: 59,799.00

Close Date: 04/01/2011

#### Problem?

front tires are worn on the inner right and outer left. They are worn to the wear bar. The wear has uneven dips at their location. Th truck has uneven ride when turning. E 20

#### Task performed:

travel to 20; ordered frt tires for eng. j

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V39508

In Date: 03/28/2011

Meter Reading: 59,892.30

Close Date: 04/08/2011

#### Problem?

replace front tires E20

#### Task performed:

Replc front tires E20 - Tiresole j

#### Parts

NO PARTS USED

#### Quantity

Vendor?: TIRESOLE



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V40288**

In Date: 05/02/2011      Meter Reading: 60,631.70  
Close Date: 05/17/2011

**Problem?**

Right side slide for E20 Hurst tool tray sticking (bearings falling out). Slide has to be put back in manually. E20

**Task performed:**

- 1. Trqvel to 20; cld not take truck out of svc; will return.
- 2. Travel to 20; R/R drawer slides.      j

Parts	Quantity
C938-22AH7600-22 TRAY SLIDES 22 IN HD	2

**Workorder: V40603**

In Date: 05/13/2011      Meter Reading: 60,795.00  
Close Date: 05/20/2011

**Problem?**

SHORELINE IN STATION DOESN'T FIT JACK IN TRUCK, Sta 20.

**Task performed:**

- Need btry charging sys; install in truck; no on-board charger.      j

Parts	Quantity
NO PARTS USED	

**Workorder: V41399**

In Date: 06/16/2011      Meter Reading: 61,785.70  
Close Date: 06/24/2011

**Problem?**

spot light on roof has a poss loose ground. turns on but shuts off when moved. Sta 20.

**Task performed:**

- Travel to 20; replc support clip & bulb for spotlight.      j

Parts	Quantity
H3-100WBP1210H3 BULB	1

**Workorder: V41740**

In Date: 07/01/2011      Meter Reading: 62,153.00  
Close Date: 07/07/2011

**Problem?**

K saw will not fire no spare plugs in station. Sta 20.

**Task performed:**

- TRAVEL TO 20 REPLACED PLUG AND TRIED TO GET RUNNING NO GO BROUGHT TO SHOP AK

Parts	Quantity
4626BPMR7A SPARK PLUG	1
BPR5ESSPARK PLUG 7734	1



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V42069**

In Date: 07/16/2011  
Close Date: 07/20/2011

Meter Reading: 62,153.00

**Problem?**

Tip on spreader chipped, needs to be replaced. tried to enter under its own asset but would not allow. E 20

**Task performed:**

travel to 20 repaired spreader tips ak

Parts

347R012SPREADER TIPS

Quantity

2

**Workorder: V42128**

In Date: 07/19/2011  
Close Date: 07/20/2011

Meter Reading: 62,153.00

**Problem?**

Trans temp light on. Sta 20.

**Task performed:**

travel to st 20 found grounded wire and repaired. ak

Parts

NO PARTS USED

Quantity

**Workorder: V42222**

In Date: 07/22/2011  
Close Date: 07/28/2011

Meter Reading: 62,153.00

**Problem?**

Hurst power unit inop. Sta 23.

**Task performed:**

Travel to 20 & swapped out power units. j

Parts

NO PARTS USED

Quantity

**Workorder: V38460**

In Date: 02/12/2011  
Close Date: 08/01/2011

Meter Reading: 58,177.00

**Problem?**

The tail end of the hose bed cover is frayed and needs to be replaced. E20

**Task performed:**

closed per mike nothing in files or related wo

Parts

NO PARTS USED

Quantity



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V42445**

**In Date:** 08/01/2011

**Meter Reading:** 62,500.00

**Close Date:** 08/03/2011

**Problem?**

Auto eject for shoreline not working on E20, Sta 20.

**Task performed:**

TRAVEL TO ST 20 REPLACED AUTO EJECT AND  
REWired CORRECTLY AK

**Parts**

0915520120AUTO EJECT 20 AERO OTL3925

**Quantity**

1



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V41813**

**In Date:** 07/05/2011

**Meter Reading:** 117,673.00

**Close Date:** 08/10/2011

**Problem?**

C INSPECTION AND REPAIRS E 20

**Task performed:**

Parts

Quantity



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

C INSPECTION	012-0010-00KNOB DRAIN	1
2. BATTERY FAIL LOAD TEST REMOVE 4 BATTERY TO INSTALL 4 NEW BATTERY	05-16422-000HOSE LOWER RADIATOR	1
	05-16423-000HOSE LOWER RADIATOR	2
	05-17223-000CAP RADIATOR 10 LB	1
3. AL 4 WINDOW MOLDING BROKEN REMOVE AND INSTALL NEW WINDOW MOLDINGS	073-0010-00PISTON RELIEF VALVE HALE	1
	0913912CHARGER 2000	1
	0915520120AUTO EJECT 20 AERO OTL3925	1
	107796DRYER KIT AD9 -NEW	1
	108-12FBEADED CHAIN W/CONN 12	4
5. WINDSHIELD WIPER BLADE TO BUG SOLVENT SERVICE	15W40BSYN OIL BULK QTS	25
	194BULB	1
	203FFBEARING PULLEY	1
6. BOTH FRONT TURN SIGNAL LENSE BROKEN REMOVE AND INSTALL REPLACEMENT LENSES	22-49905-000CABLE HEATER	1
	29526898 29548988 TRANS FILTER ALLISON	1
	377R054FEET - HURST TOOL	1
7. TRANSMISSION SERVICE	386579HOSE AND FITTING	1
8. COOLANT SYSTEM SERVICE	39768315259022 GROOVED TENSIONER OLD#3936213	1
9. HOSES SERVICE	52-24WIPER BLADES ANCO 24	2
10. T-CASE SERVICE	6805450828PLUG A/C BLR	1
	6808300074VENT A/C LH	1
	6808300174VENT A/C RH	1
11. DIFFERENTIAL SERVICE	7460967AIR FILTER 17210-ZE2-515 HONDA	1
12. BETLS SERVICE 2 AC BELT 1 ENGINE BELT TEN-- AND -- PULLY -- ASSEMBLY SERVICE	7821-3440TERM END A/C BLOCK	6
	78R536078R5360M 2PK FILTER AIR COND	1
	91368904 VALVE KIT 1 1/2 IN	1
13. AR DRYER SERVICE	91398907 VALVE KIT 3 IN AKRON	1
14. INSTALL ASSETT TAG IN WINDSHIELD	91513AMBER LENS	2
15. INSTALL BATTERY CHARGER	92541676VAC TEST GAUGE 0-30	1
	9440BELT	1
	9480BELT	1
16. RADIATOR CAP FAIL PSI TEST INSTALL NEW RADIATOR CAP	A1834388002MOLD L/H	2
	A1834388003MOLD R/H	2
17. POWER STEERING SERVICE	ABPN83322930CONTROL HEAD AC/HEAT	1
	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
	BPR5ESSPARK PLUG 7734	1
	CA8193AIR FILTER 46744 WIX	1
	FG87904MFG3937557S FILTER P/S NEW STYLE	1
	FGQ79699GASKET-P/S FILTER NEW STYLE	1
	FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
19. BATTERY TRAY SLICE TO LOCK INOP CLEAN AND LUBRICAE SLIDER LOCK AND LOCKING MECHANISM	HP-31DBATTERY 950CCA HP-31D	4
	HPH6349AOIL FILTER 51748	1
	K080716BELT	1
20.L3 DRAW SLIDER LOOSE REMOVE TRAY CLEAN AND LUBE - SLIDER REMOUNT TRAY AK	PR338324070 WIX FILTER WATER	1
	R90PFILTER FUEL 33231	1
	SS-25SC5025 SUCTION SCREEN	1



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

- 21. Rear/rear lower compt striker pin loose; screw holes worn; retap holes & secure striker pin.
- 22. Grnd ladder & \_\_\_ ladder heat sensor stickers expired. Rem, cln area & install updated sensor stickers.
- 23. Lube hose reel fitting & adj loose hose reel gear chain.
- 24. R-1 door lock needs timing; rem door panel, adj lock timing & remnt door panel.
- 25. Svc gen.
- 26. Svc Hurst tool power unit & tools; power unit feet msgng; install new feet; press test tools & power unit.
- 27. R-3 tool \_\_\_ tray loose; replc msgng tray screws & realign & secure.
- 28. Pump fail vac test; fnd R/rear discharge valve & hose reel valve;; intake relief valve & securing valve chk valve; vac line leaking; mk all rep; fill wtr tank after repair.
- 29. Hosebed cvr torn; rem for rep; install rep hose bed cvr; install holddown straps.
- 30. intake suction screen msgng; install new screen.
- 31. (5) cap chain for discharge & suction msgng; install missing cap chain.
- 32. Quality check. j

TRANSYNDALLISON TRANS FLUID GAL

6

**Workorder: V42947**

**In Date:** 08/21/2011      **Meter Reading:** 62,952.00  
**Close Date:** 08/24/2011

**Problem?**

when pump engaged, the 1/10 engine speed cap/outlet making a loud clicking noise. E 20

**Task performed:**

travel to 20 replaced rpm counter

Parts

048009000SPEEDCOUNTER PUMP PANEL

Quantity

1

**Workorder: V43384**

**In Date:** 09/02/2011      **Meter Reading:** 63,151.00  
**Close Date:** 09/08/2011

**Problem?**

air leak ...don't know where.....leaks down in a few hours.....also transmission light comes on sometimes...not overheating just comes on, Sta 20.

**Task performed:**

travel to 20 checked engine code and trans codes none found no light on

Parts

NO PARTS USED

Quantity

repaired air leak at tank



4/27/2021

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V43487**

In Date: 09/07/2011

Meter Reading: 63,199.80

Close Date: 09/08/2011

**Problem?**

engineer compartment door shock absorber failed...need new one, sta 20.

**Task performed:**

replaced hold open shocks

**Parts**

**Quantity**

EAA-8350-30UGSS1783UQ STRUT-LIFT

2

EAA-8350-60UGSS6557UP STRUT-LIFT

2

**Workorder: V44471**

In Date: 10/18/2011

Meter Reading:

Close Date: 10/19/2011

**Problem?**

air leak. low air alarm after unit sits. Sta 20.

**Task performed:**

travel to st 20 replaced air govener and tightened line at dryer to slow air leaks

**Parts**

**Quantity**

284358GOVERNOR D-2

1

**Workorder: V44499**

In Date: 10/19/2011

Meter Reading:

Close Date: 10/20/2011

**Problem?**

the trans temp orange indication light is flickering on the panel, Sta 20.

**Task performed:**

checked system found loose connection and ---

**Parts**

**Quantity**

NO PARTS USED

**Workorder: V44538**

In Date: 10/20/2011

Meter Reading: 63,825.80

Close Date: 10/20/2011

**Problem?**

Trans temp light on, check for air leaks.

**Task performed:**

travel to 20 checked trans temp light no problem found

**Parts**

**Quantity**

NO PARTS USED

checked air system all working normally



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V44612**

In Date: 10/23/2011

Meter Reading:

Close Date: 11/01/2011

**Problem?**

air leak. have to wait for air fill before we can move E 20

**Task performed:**

Parts

Quantity

Svc loose fittings in tank. j

NO PARTS USED

**Workorder: V44759**

In Date: 10/29/2011

Meter Reading:

Close Date: 11/02/2011

**Problem?**

Shore line power inlet not working properlyE20

**Task performed:**

Parts

Quantity

1. Travel to 20; maxi fuse blown for charger; none on truck; will return.

NO PARTS USED

2. Travel to 20; replc blown maxi fuse. j

**Workorder: V45053**

In Date: 11/08/2011

Meter Reading:

Close Date: 11/15/2011

**Problem?**

air leak E 20

**Task performed:**

Parts

Quantity

Travel to Stn20; not there; travel to HQ; chk for leak; replc leaking fittings; rechk ok. j

NO PARTS USED

**Workorder: V45134**

In Date: 11/13/2011

Meter Reading:

Close Date: 11/21/2011

**Problem?**

E20 has a burnt brake smell, possible brake hang up. needs to be looked at..dm E 21

**Task performed:**

Parts

Quantity

checked brakes and adjustment checked ok

NO PARTS USED



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V46059**

In Date: 12/24/2011  
Close Date: 12/28/2011

Meter Reading: 64,975.00

**Problem?**

slow radiator leak on the top hose E20

**Task performed:**

CHECKED FOR COOLANT LEAK. SECURED HOSE CLAMPS FOR UPPER HOSE.

Parts

NO PARTS USED

Quantity

ADDED PS OIL.

**Workorder: V46060**

In Date: 12/24/2011  
Close Date: 12/28/2011

Meter Reading: 64,975.00

**Problem?**

TIC. SPAIR BATTERY CHARGER NOT WORKING, UNABLE TO CHARGE A BATTERY.

**Task performed:**

TRAVEL TO STA 20 R&R TIC CHARGER.

Parts

NO PARTS USED

Quantity

**Workorder: V46385**

In Date: 01/06/2012  
Close Date: 01/10/2012

Meter Reading: 65,350.20

**Problem?**

Heater blow hot even if system is off. Also cant get front a/c to work. E 20

**Task performed:**

TRAVEL TO STATION 20 REPAIRED HEATER VALVE.

Parts

NO PARTS USED

Quantity

**Workorder: V46723**

In Date: 01/20/2012  
Close Date: 01/26/2012

Meter Reading: 65,660.00

**Problem?**

Officer side flood light has one of the two bulbs out, Sta 20

**Task performed:**

REPLACED SCENE LIGHT BULB.

Parts

LB-D30BULB QUARTZ HAL. 12V 150W

Quantity

1



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V46960**

In Date: 01/30/2012  
Close Date: 02/07/2012

Meter Reading: 65,755.20

**Problem?**

A/C not working in cab, Blows hot all the time like heat is on. Sta 20

**Task performed:**

TRAVEL TO STATION FOUND HEATER VALVE OPEN  
CHARGED AND TESTED OK.

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V46992**

In Date: 01/31/2012  
Close Date: 02/28/2012

Meter Reading: 65,755.20

**Problem?**

E20 HOSEBED COVER WAS TORN AND REMOVED BEFORE IT BLEW AWAY. NEED A NEW ONE..Sta 20

**Task performed:**

CHECKED COVER SENT TO SHOP.

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V47664**

In Date: 03/01/2012  
Close Date: 03/19/2012

Meter Reading: 66,427.10

**Problem?**

Honda generator will not stay running.It only run when the choke is on. E 20

**Task performed:**

TRAVEL TO STATION CHECK GENERATOR SPARK  
PLUG, AIR FILTER - FUEL SWAP OUT WITH SPACE.

**Parts**

S153BLOW GUN  
S777COUPLING NIPPLE

**Quantity**

1  
1

**Workorder: V48174**

In Date: 03/25/2012  
Close Date: 04/10/2012

Meter Reading: 67,104.40

**Problem?**

Problem actually with gas power fan, cant find asset # on it and not listed in office. Fan not running right poss gummed up carb.

**Task performed:**

BROUGHT TO SHOP.

**Parts**

NO PARTS USED

**Quantity**



4/27/2021

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V48233**

In Date: 03/27/2012

Meter Reading: 67,104.40

Close Date: 04/10/2012

**Problem?**

portable light needs a new cord, frays at the light source. the light works

**Task performed:**

REPAIRED CORD ON LIGHT

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V48228**

In Date: 03/27/2012

Meter Reading: 67,104.40

Close Date: 04/16/2012

**Problem?**

B INSPECTION E 20

**Task performed:**

1. B-SERVICE. (PUMP VAC TEST FAILED NEED WORK.)
2. REPLACE LIGHTS IN BUMPER; CLEAN A/C UNIT IN REAR AND CHANGE FILTER; REPLACE T ON WASHER TO WIPER.
3. REPLACE SHOCKS ON 4 OF COMPARTMENT DOORS; REPLACE TAG LIGHT; TIP OFF COOLER AND CHECK SYSTEM, TIGHTEN SOME CLAMP.
4. CLEAN ALL SLIDES TO STEP ON SIDE OF TRUCK; CLEAN AND LUBE BATTERY TRY SLIDES, CLEAN LOCK TOP OFF DIFF.
5. REPLACE REAR LEFT SIDE TOP MARKER LIGHT, ALSO REPAIR WIRES TO GROUND AND POWER BAD.
6. REPLACE REAR LED EMERGENCY LIGHT ON BACK OF TRUCK, OVER LEFT OF THE LIGHT OUT, DRILL OUT SCREW THAT BROKEN OFF RETAP AND REMOUNT LIGHTS.
7. REPAIR CHECK VALVE TO PUMP AND REPLACE SOME LINES ALSO GREASE VALUE FOR VAC TEST, REPAIR PUMP DRUM LEAKING.
8. RETORQUE ALL U-BOLTS FRONT AND REAR; RECHECK VAC ON PUMP AFTER REPAIRS. FILL PUMP AND RUN OK.
9. Q. C. TRUCK.

**Parts**

- 101281012GSS6298UH STRUTS 90#
- 15W40QSYN OIL QT
- 35200-RLIGHT MARKER LED RED
- 372000084MARKER LIGHT
- 60R00FRR600 SERIES RED LED W/O FLANGE
- 78R536078R5360M 2PK FILTER AIR COND
- EAA-8350-30UGSS1783UQ STRUT-LIFT
- FS1022FILTER FUEL WIX 33422 PS8689 FRAM
- HPH6349AOIL FILTER 51748
- R90PFILTER FUEL 33231
- SPR-W58-1TEE PLASTIC

**Quantity**

- 2
- 6
- 3
- 1
- 2
- 1
- 4
- 1
- 1
- 1
- 1



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V48770**

In Date: 04/19/2012  
Close Date: 04/25/2012

Meter Reading: 25,198.00

**Problem?**

small radiator leak coming from the top hose connected to the radiator. poss. due to a faulty radiator clamp or a bad hose E 20

**Task performed:**

TRAVEL TO 20 CHECKED UPPER HOSE FOR LEAK  
FOUND CLAMP BAD R&R HOSE CLAMP AND TESTED  
OK.

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V48791**

In Date: 04/20/2012  
Close Date: 04/25/2012

Meter Reading: 67,417.50

**Problem?**

bracket that hold halligan in place broke off, needs replaced. E20

**Task performed:**

REPLACED HALLIGAN TOOL BRACKETS.

**Parts**

5269LPVM-5 SM MOUNT

**Quantity**

2

**Workorder: V48967**

In Date: 04/29/2012  
Close Date: 05/04/2012

Meter Reading: 67,521.00

**Problem?**

Dewalt saw zall battery will not keep charge. bad battery needs replace or re conditioning. E20

**Task performed:**

- TRAVEL TO STA 20 DROP OFF BATTERIES FOR SAW.
- CHECKED TIRES ON ENGINE LOW ON AIR  
ADJUSTED AIR ON 3 RR I FLAT VALVE STEM  
BROKEN.

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V49082**

In Date: 05/03/2012  
Close Date: 05/08/2012

Meter Reading: 67,688.00

**Problem?**

REPAIR FLAT

**Task performed:**

REPAIR FLAT.

**Parts**

NO PARTS USED

**Quantity**

**Vendor?:** BOULEVARD TIRE CENTE



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

## Workorder: V49638

In Date: 05/26/2012

Meter Reading: 68,091.90

Close Date: 05/31/2012

### Problem?

on morning check out i noticed the hose under the pass front wheel well " front suction" has some mild abrasions. needs to be looked at. E 20

### Task performed:

1. TRAVEL TO ST 20 CHECKED SUCTION HOSE - SAME AS ALL FERRALANS TIRE TOUCHES HOSE OF
2. REWIRED PLUG FOR AUTO EJECT.

### Parts

NO PARTS USED

### Quantity

## Workorder: V51173

In Date: 07/27/2012

Meter Reading: 69,162.00

Close Date: 07/30/2012

### Problem?

air leak secondary line

### Task performed:

WENT TO ST 20 - RAN TRUCK - FOUND TRANS. RETARDER SOLENOID LEAKING - REMOVED LINES AND SOLENOID - SWAPTED FITTINGS - REPLACED SOLENOID - RAN AND CHECK FOR LEAKS - CHECK OK RETURNED HOME.

### Parts

2952271729552377 VALVE ASSY.ACCUM

1

### Quantity

## Workorder: V51142

In Date: 07/26/2012

Meter Reading:

Close Date: 09/17/2012

### Problem?

incoming pressure relief valve is leaking under the truck E 20

### Task performed:

FLUSHED INTAKE RELIEF VALVE OK.

### Parts

546126000TPM/QG HALE REPAIR KIT

1

### Quantity

## Workorder: V52239

In Date: 09/07/2012

Meter Reading:

Close Date: 09/19/2012

### Problem?

left turn signal not working.E20

### Task performed:

REPAIRED SIGNAL LIGHT.

### Parts

NO PARTS USED

### Quantity



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V52287**

In Date: 09/10/2012

Meter Reading:

Close Date: 09/19/2012

**Problem?**

left front turn signal out. E20

**Task performed:**

Parts

Quantity

TRVL TO 20 R&R SIGNAL BULB.

NO PARTS USED

**Workorder: V52735**

In Date: 10/01/2012

Meter Reading: 15,044.80

Close Date: 10/05/2012

**Problem?**

REPLACE REAR TIRES

**Task performed:**

Parts

Quantity

REPLACE REAR TIRES.

NO PARTS USED

Vendor?: ELPEX

**Workorder: V52832**

In Date: 10/03/2012

Meter Reading:

Close Date: 10/12/2012

**Problem?**

drivers side rear spot light lens broken. 5" intake valve leaking at center of handle (grease fitting??) E20

**Task performed:**

Parts

Quantity

INSTALLED NEW LIGHT AND REPAIRED LEAK.

44144414 SEALED BEAM LAMP

1

**Workorder: V52962**

In Date: 10/09/2012

Meter Reading: 15,044.80

Close Date: 10/16/2012

**Problem?**

it sounds like the bearings in the turbo are going bad when driving E20

**Task performed:**

Parts

Quantity

1. TRAVEL TO ST 20 FOUND MISSING BOLTS IN TURBO WILL ORDER NEW TURBO.

3818824TURBO NUT

4

2. TRAVEL TO 20 R&R TURBO. TEST DRIVE AND CHECK OK.

4955658RXTURBO REPLACES 3800401RX

1



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

### Workorder: V53090

In Date: 10/15/2012      Meter Reading: 15,044.80  
Close Date: 10/24/2012

#### Problem?

Passenger side scene light out. ( telescoping light above the pump panel) e20

#### Task performed:

TRAVEL TO ST 20 CHECK OUT LIGHT ON PASS SIDE  
REPLACE WIRE ENDS AND REWIRE LIGHT PLUG.

#### Parts

LB-D30BULB QUARTZ HAL. 12V 150W

#### Quantity

4

### Workorder: V53243

In Date: 10/22/2012      Meter Reading: 71,322.00  
Close Date: 10/26/2012

#### Problem?

1. gas power fan not running properly( hesitation) 2. rear scene light blown Capt. side 3. test on the Whelen show only 1 light for the speakers

#### Task performed:

1. TRAVEL TO ST 25 CHECK OUT GAS POWER FAN  
CLEAN CARB REPLACE FUEL TEST OK.  
2. REPAIR W IRE ON SIREN.

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V53301

In Date: 10/25/2012      Meter Reading: 71,322.00  
Close Date: 10/31/2012

#### Problem?

1. On the Whelen electronic siren a silent test was conducted and only one light illuminated and the other did not. 2. Gas power fa is not running properly, it hesitatlightes and then shut off after 2 mins. E20

#### Task performed:

1. TRAVEL TO 20 REPLACED BLOWN SIREN  
SPEAKER.  
2. REPLACED FUEL DISC IN FUEL LINE.

#### Parts

SD-210RSIREN DRIVER  
SD-210RXSIREN DRIVER SMALL

#### Quantity

1

1

### Workorder: V53302

In Date: 10/25/2012      Meter Reading: 71,322.00  
Close Date: 10/31/2012

#### Problem?

Scene light/ round light bulb located on the rear of the engine is blown. Capt .Side E20

#### Task performed:

REPLACED SCENE LIGHT BULB.

#### Parts

4419BULB

#### Quantity

1



4/27/2021

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V53336**

In Date: 10/27/2012

Meter Reading: 71,433.00

Close Date: 10/31/2012

**Problem?**

Right rear flood light out E 20

**Task performed:**

REPLACED FLOOD LIGHT BULB.

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V49063**

In Date: 05/03/2012

Meter Reading: 67,688.00

Close Date: 11/20/2012

**Problem?**

E-20 failed vac test, also failed capacity test and 70% test

**Task performed:**

CORRECTED PROBLEM RETESTED PASSED.

**Parts**

91368904 VALVE KIT 1 1/2 IN

91378905 VALVE KIT 2 IN AKRON

91388906 VALVE KIT 2.5 IN AKRON

91398907 VALVE KIT 3 IN AKRON

**Quantity**

1

1

2

2

**Workorder: V53953**

In Date: 11/22/2012

Meter Reading:

Close Date: 01/09/2013

**Problem?**

turbo leak no power to the engine low air on brakes E20

**Task performed:**

TRAVEL TO 20 FOUND BROKEN BOLT IN EXHAUSTMANIFOLD WILL RREPAIR AT SERVICE. REPAIRED SERVERAL AIR LEAKS.

**Parts**

223-485V91-8301 85 PSI CLOSED 67 OPEN PREESURE PF

5460370530VPS SHIFT KIT 546-0370-53-0

**Quantity**

1

1



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V54962**

**In Date:** 01/09/2013

**Close Date:** 02/11/2013

**Problem?**

C INSPECTION E 20

**Meter Reading:** 72,526.00

**Task performed:**

Parts

Quantity



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

1. C INSPECTION.
2. BATTERY BOX LATCH AND SLIDES FROZEN; BLOW OUT LOOSE DEBRIE - WASH AND SOAK LATCHES WITH PEN. OIL WORK LATCHES TO FREE UP - WASH OUTDEBRIE AND WORK AGAIN UNTIL FREE AND SMOOTH - LUE WITH OIL - NOW DO THIS SAME WITH DRAWSLIDES UNTIL ALL IS WORKING FREE.
3. INNER REAR TIRES COULD NOT BE ACCESSED TO CHECK OR FILL TIRES - FIND AND INSTALL SOLID STYLE EXTENSIONS TO COME THROUGH OUTER WHEELS FOR ACCESS.
4. CHECK MAP LIGHT FOUND BROKEN WIRE INSIDE SWITCH AND SWITCH BAD GOT NEW MAP LIGHT AND INSTALL IT.
5. CHECK CLEARNESS LIGHT ON RIGHT FENDER FOUND ASS. RUSTED OUT, WENT TO PART ROOM AND FOUND NEW LIGHT ASS. INSTALLED NEW LIGHTASS, AND REPLACE BULLET LIGHT ON REAR CLEARANCE LIGHT.
6. R&R WIPER BLADES.
7. R&R REAR A/C FILTER.
8. R&R WEATHER STRIPING ON ALL FOUR DOOR.
9. R&R SEAT BELT ON DRIVERS SEAT AND REMOVE DRIVES SEAT TO SEND TO BE REPAIRED.
10. DRILL BOLT AND REMOVE BOLT FROM EXHAUST MANIFOLD AND PLACE WITH NEW BOLT AND SPACER.
11. R&R FAN BELTS, HAD TO REMOVE FAN BLADE TO PUT BELT ON.
12. REMOVE DRIVER SEAT TO SEND FOR REPAIR INSTALL NEW SEAT ON DRIVER SIDE.
13. INSTALL TRUCK HEIGHT STRICKER ON WINDSHIELD.
14. INSTALL WIPER SWITCH.
15. INSTALL NEW BATTERY SWITCH.
16. TIGHTEN UP BOTH MIRRORS AND ADJUST THEM
17. REMOVE AIR DRYER ASS. CLEAN AND R&R AIR DRYER, CHECK VALVE AND PURGE VALVE AND INSTALLED ASS.
18. REMOVE AND REPLACE GASKET ON PUMP DRAIN.
19. TIGHTEN SCREW ON R/SIDE STEP/HOSE FROM OFF UNDER PUMP PANEL.
20. REMOVE ACCREDIATION STICKERS FROM REAR CAB DOORS. BUFFED OUT DOOR PANEL WITH COLOR CAPTURE.
21. TRACED NO POWER AT SWITCH FOR FOAM FILL PUMP. REPAIRED BREAK IN WIRE. FOAM FILL PUMP WORKS PUT PUMPING PROPERLY. REPLACED FOAM FILL PUMP AND RETEST ALL OK.
22. PUT FOAM PUMP IN SIMULATION MODE - FOUND FOAM PUMP CYLING ON AND OFF - NOT TURNING MUCH. SUSPECT SMALL PENCIL TYPE SENSOR

0100030000SCREEN 6 IN	2
0401590000O-RING SEAL	2
064615900006-46159-001 SWITCH WIPER	1
0773095TRUNNION THREAD	1
082-2007-00-0GREASE ZERK W/CHECK VLV	1
104967DIAPHRAM FOR 6 PORT DUMP VALVE	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
108-12FBEADED CHAIN W/CONN 12	4
15W40BSYN OIL BULK QTS	27
17211ZG98000AIR FILTER HONDA	1
2000071102000072100 SOLENOID HALE PRIMER	1
372000084MARKER LIGHT	1
3944593EXH. MAN. BOLT	1
3945252SPACER EXH. MAN.	1
4300-505PUMP FLOJET 12V	1
440-44 1/8 IN VALVE EXT	2
52-24WIPER BLADES ANCO 24	2
5462270020VALVE KIT SS 546-2270-02-0	1
5462290020VALVE KIT SS VALVE 2 1/2 546-2290-02-0	1
5462300020VALVE KIT SS VALVE 3 IN	1
6806970098SEAL DOOR	2
6808200020LIGHT ASSY. TURN SIGNAL	1
75908SWITCH BATTERY MASTER 300A	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
91398907 VALVE KIT 3 IN AKRON	1
9440BELT	1
9480BELT	1
BPR5ESSPARK PLUG 7734	2
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
IMMF11358SEAT BELTS	1
K080716BELT	1
LF18TS-LEDMAP LIGHT LED 18 IN	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1
SS-25SC5025 SUCTION SCREEN	1



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

NOT WORKING PROPERLY.

23. SET UP FOR VACCUM TEST CHECK ALL INLETS AND CAPPED THEM CHECK ALL DISCHARGE VALVE GREASED AND OPEN AND CLOSED THEM AND CHECK ALL DRAINS, PULLED A VACUUM IT WENT TO 23 LBS BUT OFF FAST AND FOUND NO 2 DISCHARGE LEAKING SO I REMOVED AND REBHUIOLT NO. 2 DISCHARGE ALSO FOUND THE DECK GUN VALVE LEAKING DO I R&R THE DECK GUN VALVE AND RETESTED TEST FOUND NO MORE LEAKING SO I THOUGHT IT HAD TO BE TANK TO PUMO OR TANK FILL SO THE TANK FILL WAS EASY SO I R&R TANK FILL AND DID VACUUM TEST AGAIN IT HELPED BUT WAS NOT GOOD DID NOT PASS.

24. START R&R TANK TO PUMP VALVE CHECK ED E. TO SEE IF HE WANT TO CHANGE HALE VALVE TO AN AKRON VALVE HE SAID NO. SO CLEAN UP HALE VALVE AND REBUILTED IT INSTALLED VALVE BUT CUT O-RING ON VALVE PUTTING IT IN SO I REMOVED VALVE AND REPLACE O-RINGS AND INSTALLED VALVE AND DID VACUUM TEST AGAIN BUT PRIME PUMP WOULD NOT WORK SO I CHECK POWER AT PUMP SOLINOID AND HAD POWER SO TRYED TO JUMP SOLINOID AND SOLINOID DID NOT WORK SO I R&R PRIMER PUMP SOLINOID AND PUMP WORK BUT IT STILL WOULD NOT HOLD VACUUM SO I PUT AIR PRESSURE TO PUMP AND FOUND A GREASE ZERK LEAKING SO R&R GREASE ZERK AND DID VACUUM TEST AAIN AND IT PASS VACUUM TEST.

25. ASSISTED JERRY IN VACCUM TESTING AND TROUBLESHOOTING.

26. STARTED TO CHECK FOAM SYSTEM FOUND WORK GOOD.

27. JACK TRUCK AND MOVED FRONT TIRE FROM SIDE TO SIDE. CHECK AIR IN TIRE AND ADJUSTED FRON BRAKE, TEST DROVE FOUND NO PULL.

28. CHECK FOR COOLANT LEAK AT START DID NOT SEE LEAK WHEN HOT WILL CHECK WHEN COOL.

29. FILL WATER TANK AND FLUSH FOAM.

30. Q.A. CHECK OK.

**Workorder: V55571**

**In Date:** 02/06/2013

**Meter Reading:** 72,667.00

**Close Date:** 02/21/2013

**Problem?**

left rear spot light is out. E 20

**Task performed:**

TRAVEL TO 20 REPLACED LR SPOT LIGHT.

**Parts**

AG-RDECK LIGHT ROUND BASE

**Quantity**

1



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V55677**

In Date: 02/10/2013  
Close Date: 02/21/2013

Meter Reading: 72,667.00

**Problem?**

LR flood out

**Task performed:**

- CHECKED LIGHTS OK.
- DRIVER COMPLAINED OF AIR LEAKS FOUND PRESSURE PROTECTION VALVE LEAKING AND REPLACED FOUND VPS SHIFTER LEAKING RESEALED OK.

Parts

Quantity

5460370530VPS SHIFT KIT 546-0370-53-0

1

**Workorder: V55963**

In Date: 02/24/2013  
Close Date: 02/26/2013

Meter Reading:

**Problem?**

front A/C blowing hot.unable to use. E 20

**Task performed:**

TRAVEL TO 20 ADJUSTED HEATER CONTROL CABLE A/C COLD OK.

Parts

Quantity

NO PARTS USED

**Workorder: V56411**

In Date: 03/15/2013  
Close Date: 03/22/2013

Meter Reading: 73,303.00

**Problem?**

air leak is pretty bad. having to wait for air to build up to respond to calls. E-20

**Task performed:**

CHECKED TRUCK FOR AIR LEAKS FOUND MOISTURE EJECTER LEAKING SWAPPED CHECKED OK RETURNED TO SERVICE.

Parts

Quantity

NO PARTS USED

**Workorder: V46781**

In Date: 01/23/2012  
Close Date: 04/03/2013

Meter Reading: 10,206.70

**Problem?**

NEED AIRPACK MOUNT IN OFFICERS SEAT ADJUSTED TO ACCOMODATE THE NEW SCOTT PACKS GOING INTO SERVICE TOMORROW. Sta 20

**Task performed:**

WORK DONE ON WORK ORDER 45968. PLEASE CLOSE.

Parts

Quantity

NO PARTS USED



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V56963**

In Date: 04/11/2013  
Close Date: 04/15/2013

Meter Reading: 73,819.00

**Problem?**

HOSE BED COVER NEEDS TO HAVE VELCRO ATTACHED TO IT TO KEEP IT FROM FLAPPING IN THE WIND. ATTACHMEN FOR HOSE BED COVER ON TRUCK NEED TO BE REPLACED AS SEVERAL ARE BROKEN. COVER IS CURRENTLY OFF OF THE TRUCK.

**Task performed:**

TRAVEL T O STA 20 DRILLED OUT AND REPLACED HOSE BED COVER FASTENERS.L REINSTALLED COVER OK.

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V57977**

In Date: 05/26/2013  
Close Date: 06/04/2013

Meter Reading: 74,868.60

**Problem?**

Strobe light driver side, midship, next to MIV.

**Task performed:**

REPLACED LED EMERGENCY LIGHT.

**Parts**

02036317300STROBE LINEAR REFLECTOR 6ELTUBE  
60R00FRR600 SERIES RED LED W/O FLANGE

**Quantity**

1  
1

**Workorder: V58238**

In Date: 06/06/2013  
Close Date: 06/11/2013

Meter Reading: 75,016.70

**Problem?**

replace hadlight

**Task performed:**

REPLACE LEFT FRONT HEAD LIGHT OUT AFTER STORM IN A/M

**Parts**

H6054USE CV TYPE SEALED BEAM

**Quantity**

1

**Workorder: V59298**

In Date: 07/23/2013  
Close Date: 08/08/2013

Meter Reading: 75,828.00

**Problem?**

onboard battery charger not working (FRIED) per mechanic

**Task performed:**

REPLACED ON BOARD BATTERY CHARGER.

**Parts**

0913912CHARGER 2000

**Quantity**

1



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V59503**

In Date: 08/02/2013  
Close Date: 08/08/2013

Meter Reading: 75,828.00

**Problem?**

Exhaust manifold

**Task performed:**

INSTALLED NEW EXHAUST MANIFOLD AND ROAD TESTED OK.

Parts

Quantity

200-2481-00-0546-3240-00-0 FOAM PUMP SENSOR KIT

1

**Workorder: V58778**

In Date: 06/29/2013  
Close Date: 08/09/2013

Meter Reading: 75,564.00

**Problem?**

On board foam system is not working on E20. Tried multiple discharges that flow foam, and still not getting foam out of it.

**Task performed:**

1. TRAVEL TO STATION 20 FOUND PADDLE WHEEL SENSOR NOT READING WILL GET PARTS AND RETURN.
2. TRAVEL TO STATION 20 REPLACED WATER FLOW SENSOR AND NOW SYSTEM READS WHATER FLOW. FOAM STILL NOT WORKING PANEL SENSOR NOT READING FOAM FLOW. ALSO REPLACED SOLENOID FOR MAIN SYSTEM POWER.
3. INSTALLED SENSOR IN PUMP AND TESTED FOAM SYSTEM OK.
4. REPLACED SENSOR IN FOAM PUMP. HAD TO R&R PUMP TO ACCESS SENSOR. RECALIBRATED SYSTEM.
5. CONTINUED WORKING ON FOAM SYSTEM. OPERATED FOAM SYSTEM. SYSTEM IS NOW OPERATING NORMALLY.
6. REPLACED ON BOARD BATTERY CHARGER. TESTED SYSTEM.

Parts

Quantity

200-2481-00-0546-3240-00-0 FOAM PUMP SENSOR KIT

1

200-2491-00SENSOR HALE HPF FOAM FLOW

1



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V60226**

**In Date:** 09/03/2013  
**Close Date:** 09/10/2013

**Meter Reading:** 76,175.90

**Problem?**

EXTENSION LADDER HEAT SENSORS ARE OUT OF DATE. E20

**Task performed:**

1. TRAVEL TO ST 20 DRIVER COMPLAINT HEAT SENSORS EXPIRED ON LADDERS REPLACED EXPIRED SENSORS ON ESTENSION LADDER.
2. DRIVER COMPLAINT CHECK ENGINE LIGHT ON INTERMITTENTLY CHECKED ENGINE CODES FOUND 596 CODE 73 COUNTS REPLACED TRANSIENT DIODE ON SIDE OF BLOCK.

**Parts**

3944110DIODE SUPPRESSOR

**Quantity**

1

**Workorder: V60780**

**In Date:** 09/25/2013  
**Close Date:** 10/10/2013

**Meter Reading:**

**Problem?**

hand light charger in the back seat is broken,bad air leak engine on 0 pressure every morning,5 inch ldh valve on drivers side is leaking,and we still have the shops back up gas fan.jim souza

**Task performed:**

1. TRAVEL TO 20 DRIVER COMPLAINT HAND LIGHT BASE BROKEN REPLACED BASE AND REWIRED OK
2. DRIVER COMPLAINT 5" SUPPLY VALVE LOOKING. WILL HAVE TO GET ONE FROM SHOP AND REPLACE.
3. DRIVER COMPLAINT AIR LEAKS DOWN. REPLACED SEVERAL LEAKS UNDER TRUCK.
4. TRAVEL TO STA 20 REPLACED MASTER WHOLE VALVE.

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V59836**

**In Date:** 08/15/2013  
**Close Date:** 10/11/2013

**Meter Reading:**

**Problem?**

reliefvalve leaking....failed dry pump test

**Task performed:**

DRIVER COMPLAINT RELIEF VALVE OPENING UNDER VACUUM RPAIED CHECK VALVE AND TESTED OK.

**Parts**

038-1550-00VALVE CHECK HALE 1/4"

**Quantity**

1



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

**Workorder: V60239**

In Date: 09/03/2013

Meter Reading:

Close Date: 10/11/2013

**Problem?**

OIC seatis torn and has a spring wire poking thru it. The SCBA cushioned seat cover has also been torn by the wire. E20

**Task performed:**

Parts

Quantity

DRIVER COMPLAINT OF SEAT SPRING. WILL TAKE SEAT FROM PARTS TRUVK AND BRING BACK TOMORROW.

NO PARTS USED

**Workorder: V61028**

In Date: 10/05/2013

Meter Reading: 77,184.00

Close Date: 10/25/2013

**Problem?**

While on a car fire the Hale foam system would not produce any foam out of the trash line. Foam % was increased to 3% and nothing came out. Turned Hale on and off and tried again with no foam produced

**Task performed:**

Parts

Quantity

REPAIRS DONE ON WORK ORDER V61116.

NO PARTS USED

**Workorder: V61829**

In Date: 11/06/2013

Meter Reading: 77,553.00

Close Date: 11/14/2013

**Problem?**

Water leak at pump

**Task performed:**

Parts

Quantity

WENT TO 20- FOUND LINE-OFF OF SENSING VALVE- REINSTALLED LINE- RAN AND CHK OK- FOUND MIV HARD TO OPERATE- REMOVED STEAMER CAP AND SCREEN- LUBED VALVES-REASSEMBLED.

NO PARTS USED

**Workorder: V62078**

In Date: 11/16/2013

Meter Reading:

Close Date: 11/20/2013

**Problem?**

Compartment will not stay open and slams. E20

**Task performed:**

Parts

Quantity

REPLACE COMPARTMENT DOOR, SHOCK ABSORBORS AND STRUTS.

101281012GSS6298UH STRUTS 90#

2



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V62338**

In Date: 11/28/2013

Meter Reading:

Close Date: 12/12/2013

**Problem?**

1. Tailboard upper grab handle came off and two screws are missing. 2. Officer side MIV will not open 3. Two air leaks - one is behind the panel on the front suction switch and two under carriage near officer side intake E20

**Task performed:**

Parts

Quantity

- 1. DRIVER COMPLAINT GRAB HANDLE LOOSE SECOND GRAB HANDLE. REDRILLED AND TAPPED HOLES.
- 2. DRIVER COMPLAINT MIV INOP. REPLACED BROKEN SET SCREW IN HANDLE AND LUBRICATED VALVE.
- 3. DRIVER COMPLAINT AIR LOOKING DOWN REPLACED AIR LEAK AT GOVENOR AND FT AIR TANK.

NO PARTS USED

**Workorder: V62235**

In Date: 11/24/2013

Meter Reading:

Close Date: 12/13/2013

**Problem?**

HOSEBED TARP ON ENGINE 20 NEEDS REPLACEMENT

**Task performed:**

Parts

Quantity

REPAIRED BY CENTRAL AUTO TRIM.

NO PARTS USED

**Workorder: V62835**

In Date: 12/19/2013

Meter Reading:

Close Date: 12/31/2013

**Problem?**

One of the lines coming from the power unit sprung a significant leak and no tools can be run without hydraulic fluid loss. e20

**Task performed:**

Parts

Quantity

TRAVEL TO ST-20 HURST LINES LEAK R&R LINES ON POWER UNIT.

353R222ML28 SPREADER HOSE

2



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V61116**

**In Date:** 10/08/2013

**Close Date:** 01/03/2014

**Meter Reading:** 77,553.00

**Problem?**

B inspection E20

**Task performed:**

Parts

Quantity



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

1. B INSP.
2. BATT FAILED LOAD TEST-R&R 4BATT CHK OK.
3. B INSP.
4. B INSP.
5. FOUND SLIDE PLATFORMS INOP-CLEANED, LABELED TRACKS AND ROLLER.
6. FOUND TOOL NUTS LOSSE- REPLACED AND TIGHTENED SCREW FOR NUTS IN COMPARTMENT.
7. REPLACE NUMBER PLATES AND HOLDERS-REMOVED HOLDERS.
8. REPLACE NUMBER PLATES AND HOLDERS CONT-REMOVED OLD DOUBLE STICK TAPE-REPLACED METAL HOLDERS- INSTALLED NUMBERS ONTO PLATES.
9. CHECK FOR AIR LEAKS- SPAYED LINES AND FITTINGS- R&R AIR TANK DRAIN- FOUND NO AIR TO CAB AIR BAGS-REMOVED LINES AT SUPPLY VALVE-REPLACED PRIORITY VALVE.
10. CHECK AIR LEAKS CONT- REPLACED AIR FITTINGS AND INSTALLED VALVE RAN AND CHECK FOR LEAK-CHK OK.
11. CHECK FOR COOLANT LEAKS-PRESSURE SYSTEM- FOUND RAD HOSE CLAMP LEAKING- R&R CLAMP-FOUND AIR COMP. FITTINGS /LEAKING-REPAIRED LEAKS-CHK OK.
12. BRAKE RETARTER INOP-REMOVED DASH PANELS- CHK CONNECTIONS AND ACTIVATIONS-REPAIR CONNECTIONS TEST DRIVE- CHK OK, REINSTALLED PANELS.
13. CHK FOR FUEL LEAK AT FUEL PUMP- CLEANED PUMP-RAN ENGINE- REPAIRED LEAK AT FITTING ON PUMP CHK OK.
14. CHK FOAM SYSTEM- RAN PUMP AND FOAM SYSTEM INOP- REMOVED AND CLEARED CONNECTIONS- RAN PUMP AND SYSTEM- FOAM CHK OK.
15. CHK FOR INTAKE RELEASE VALVE UNLOADING WHEN PUMPING REMOVED SENSING VLAVE-REPLACED VALVE AND FITTINGS.
16. CHK INTAKE VALVE CONT; INSTALLED VALVE-REMOVE PUMP LINE STRAINS- SCREEN BROKE OFF IN PUMP- REMOVED SCREEN AND REPLACED.
17. FOUND OFFICERS SEAT LOWER CUSHION SPRING COMING THROUGH-REMOVED SEAT.
18. CHK INTAKE RELIEF CONTS- RAN AND PUMPED-RELIEF UNLOADING WITH PUMP PRESS RELIEF VALVE.
19. CK RELIEF VALVE CONT; R&R FITTINGS AT CONTROLLER.
20. CK RELIEF VLAVE CONT-REMOVED AL PUMP CONTROL LINES- TROUBLESHOOT SENSING VALVE AND LINES- CLEANED LINES.
21. CHK PUMP OPERATION CONT-REMOVED PUMP RELIEF VALVE DISASSEMBLED, CLEANED AND

0100080010STRAINER	2
038-0191-00CONTROL VALVE	2
038-1010-01HALE RELIEF VALVE W/ VULCANIZED SEAT	1
103385NDRAIN COCK	1
223-485V91-8301 85 PSI CLOSED 67 OPEN PREEURE PF	1
440-5 VALVE EXT.	1
516TIRE INFLATOR	1
538-0790-00-0BODY CONTROL ASSEMBLY	1
538-1410-00VALVE SENSING SV HALE	1
546085303NC SWITCH/BRACKT	1
546126000TPM/QG HALE REPAIR KIT	1
78R536078R5360M 2PK FILTER AIR COND	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
CA8193AIR FILTER 46744 WIX	1
EL12FLASHER ELECTRONIC	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HP-31DBATTERY 950CCA HP-31D	4
HPH6349AOIL FILTER 51748	1
L PLACARD INSERTLARGE PLACARD INSERT CARD	2
R90PFILTER FUEL 33231	1
S PLACARDFRONT AND BACK PLACARD	1
S PLACARD INSERTFRONT AND BACK INSERT CARD	1
S1003-A3103015 SEAL	4
S777COUPLING NIPPLE	1



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

REBUILT VALVE.

22. CHK PUMP OPERATION; REMOVED LINES AND RELIEF VALVE.

23. CHK PUMP CONT REMOVE CONTROLLER AND LINES CLEARED LINES REMOVED TANK DRAIN-FUSHED TANK AND BACK FLUSHED PUMP AND SYSTEM. CK OPERATION- NO RELIEF VALVE OPERATION.

24. REPAIR OFFICERS SEAT CONT; INSTALLED REPAIRED SEAT- INSTALLED SEAT BELTS CHK OK.

25. CHK PUMP- INSTALLED TANK DRAIN PLUG-REPAIRED INTAKE DRAIN.\

26. CHK PUMP- RAN AND BLED PUMP-INTAKE DISCHARGE.

27. CK-PUMP- REMOVED SENSING VLAVE AND VALVE ASSEMBLY-REMOVED RELEASE VALVE-DISASSEMBLED CLEANED AND REBUILT-INSTALLED INTAKE RELIEF VALVE-REPLACED INTAKES.

28. CHK PUMP-REPAIRED AND REWIRED INTAKE RELIEF SW- ADJUSTED SWITCH-REMOVED REPLACED FITTINGS AND MOVED VACUUM PUMP LINES AT PUMP- REPLACED SCREW-R&R SENSE VALVE DIAPHRAM- FLUSHED AND CHK OPERATION-CHK OK.

29. CHK FOR MORE COOLANT LEAKS- FOUND REAR FITINGS FOR AIR COMP TUBES LEAKING-REMOVED FUEL FILTERED, DRAINED RAD; REMOVED CLAMPS TUBES R&R 4 SEAL GRAMMETS- REASSEMBLED FILLED RAD-RAD CHK OK.

30. REPLACED AIR FILTER- REMOVED AIR TUBES AND FILTER ASSEMBLY REPLACED FILTER AND REASSEMBLED.

31. INSTALLED ALL PUMP PANELS-FILLED WATER TANK.

32. Q.A TRUCK.

**Workorder: V60055**

**In Date:** 02/20/2014

**Meter Reading:** 76,175.90

**Close Date:** 02/21/2014

**Problem?**

ENGINE 20-FAILED DRY VACUUM TEST-INTAKE PSI RELIEF VALVE IS FAILING THE DRY VAC TEST.

**Task performed:**

REPAIRED ON PM.

Parts

NO PARTS USED

Quantity



4/27/2021

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V64037**

In Date: 02/06/2014

Meter Reading:

Close Date: 02/26/2014

**Problem?**

light bar lenses faded, can I get some compound to polish them out.

**Task performed:**

Parts

Quantity

DELIVERED.

NO PARTS USED

**Workorder: V66133**

In Date: 05/01/2014

Meter Reading:

Close Date: 05/02/2014

**Problem?**

Engine oil at add mark, no oil in station supply. need a few quarts of engine oil

**Task performed:**

Parts

Quantity

PARTS ONLY.

NO PARTS USED

**Workorder: V66723**

In Date: 05/24/2014

Meter Reading: 81,524.00

Close Date: 06/17/2014

**Problem?**

tank to pump lever knob broke

**Task performed:**

Parts

Quantity

tank to pump lever broken return to shop and remove from suphen truck and installed on eng, 20.

NO PARTS USED

**Workorder: V67248**

In Date: 06/16/2014

Meter Reading:

Close Date: 06/18/2014

**Problem?**

lanyard for the tic broke

**Task performed:**

Parts

Quantity

TRAVEL TO 20 REPLACED LANYARD FOR TIC.

NO PARTS USED



4/27/2021

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V67691**

In Date: 07/05/2014

Meter Reading:

Close Date: 07/10/2014

**Problem?**

Jiffy Jack wire is missing. E20

**Task performed:**

Parts

Quantity

Delivered Jiffy Jack tool to station 20

NO PARTS USED

**Workorder: V67894**

In Date: 07/14/2014

Meter Reading:

Close Date: 07/16/2014

**Problem?**

front a/c not blowing cold

**Task performed:**

Parts

Quantity

Travel to 20 driver complaint A/C not cold waited on unit to arrive at station. Cleaned out condenser and added freon.Okay now.

91388906 VALVE KIT 2.5 IN AKRON

1

**Workorder: V67969**

In Date: 07/17/2014

Meter Reading:

Close Date: 07/17/2014

**Problem?**

Shop spare generator when placed under load started stalling. Then had a difficult time running at all. Our original generator has been at the shop for approx a month, maybe its ready to be returned? Thanks

**Task performed:**

Parts

Quantity

gen returned to station

NO PARTS USED

**Workorder: V66646**

In Date: 05/21/2014

Meter Reading:

Close Date: 07/23/2014

**Problem?**

Generator has steady fuel leak coming from bottom of fuel tank. Also we need a new combo blade for the K12 saw.

**Task performed:**

Parts

Quantity

repaired at shop on ticket v67969

NO PARTS USED



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V68596**

**In Date:** 08/11/2014

**Close Date:** 12/12/2014

**Meter Reading:** 82,594.00

**Problem?**

C inspection SE2

**Task performed:**

Parts

Quantity



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

1. C inspection	012-0010-00KNOB DRAIN	1
2. Replaced batteries	04020900300 RING	1
3. Repair, rebuild and adjusted valves and perform dry vac	042-0091-00SPRING PRIMER	1
4. Replace wiperblades	042-0550-00SPRING-VALVE QG RELIEF VALVE	1
5. Replaced fittings and check valve for pump sensing valve and drain valve. Redo dry vacuum, test til passed.	073004100PISTON	1
6. R front door light inop-diagnose problem-found bad wire connection. Repaired connection.	107796DRYER KIT AD9 -NEW	1
7. Remove hosebed cover for repair	15W40BSYN OIL BULK QTS	25
8. Replaced rear AC filter, repair spring loaded filter clamp	25-358SWITCH COVER	1
9. replaced pump panel, air horn waterproof cover for switch	29526898 29548988 TRANS FILTER ALLISON	1
10. Circle D bracket broken, replaced bracket	3576REAR BRAKE DRUMS	2
11. Diagnose foam fill pump inop-found bad relay-replaced relay, clean and apply silicone grease to connections. Test ok	3905216VCLAMP TURBO SIDE HORTON	1
12. Fill foam tank and check for leaks(Ok)	486575HOSE & FITTINGS	1
13. Rear compartment striker loose-found both bolts stripped out. Replaced bolts and repair treaded holes.	52-24WIPER BLADES ANCO 24	2
14. R-1 door striker loose with frozen bolts-extract bolts, clean up threads with tap. Install new bolts with star washers and tightened.	546126000TPM/QG HALE REPAIR KIT	1
15. Service trans	5462270020VALVE KIT SS 546-2270-02-0	1
16. Service "T"case	78R536078R5360M 2PK FILTER AIR COND	1
17. Service P/S	800405PURGE VALVE KIT	1
18. Paint fuel cap	87499RY48 RELAY	1
19. Remove front suction cap and adapter. Remove old strainer, cut new strainer to size and install. Reinstall adapter and steamer cup.	91398907 VALVE KIT 3 IN AKRON	1
20. Tighten door shock bolts on L-1, L-3 and R-1 doors	A1834388002MOLD L/H	1
21. Replaced rear brake shoes, drums and hardware-adjusted shoes.	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
22. Rebuild primer valve-replaced kinked tubes and fittings. R/R throttle control for acess, test ok.	CA8193AIR FILTER 46744 WIX	1
23. Rebuild dryer and replaced purge valve	FG87904MFG3937557S FILTER P/S NEW STYLE	1
24. Remove campaign frames and mastick from body-buff out body with compound.	FGQ79699GASKET-P/S FILTER NEW STYLE	1
25. Loose wire hanging down by trans-found wire disconnected from trans switch, clean terminal and switch tightened terminal lugs and connected to switch.	FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
26. Install hose bed cover, replaced strap on engine hand rail.	HP-31DBATTERY 950CCA HP-31D	4
27. Tets drive vehicle burnish rear brakes and test-recheck trans fluid and P/S fluid hot after service. Add 2.5 qts trans fluid. Test from pump after filling foam tank that was empty. Inop bled pump and retried still inop, checked/relief valve and rear discharge plumbing for leaks both leaking slightly. Looked for missing deck gun tips. Found tip and installed.	HPH6349AOIL FILTER 51748	1
28. L rear door trim broken removed handle and door panel. Replaced trim piece, install washers with screws to better support trim.	IMMF11358SEAT BELTS	1
	PVG-KITORING KIT	1
	R90PFILTER FUEL 33231	1
	TRANSYNDALLISON TRANS FLUID GAL	8
	WAT61403STRAINER 6 IN	1
	XK4034707QPMHD SHOE KIT 3/8 BEAM	2



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

29. R-3 shelf loose missing channel nut-replaced nut and bolt and tightened all fastners. Tighten tool bracket screws and install acorn nuts to protect from personal injury.

30. Adjusted belt tension on both AC compressor

31. Exhaust loose at turbo, found clamp bad and frozen bolt-cut off bolt, remove clamp and install new clamp, tightened clamp and test for leak-OK.

32. Vehicle drifts left, raise vehicle and swapped left and right wheels. Road test, drifts right now-checked history tires swapped 2-2013. Swapped wheels back.

33. Replaced R front seat belt

34. Remove decals from windshield, clean mastic from windshield

35. Diagnose foam system inop-found pump locked up, free up pump and calibrate foam pump and water flow sensor.

36. Foam supply hose cracked, removed hose and sent out for newhose fitted.

37. R rear discharge nipple to supply pipe leaking. Removed hose going to valve and support hose. Remove valve lever, remove valve and remove base and nipple rebuild valve. Remove nipple, clean threads and apply tape and thread sealer to threads. Install nipple and valve base, install valve, valve top flange and hose. Install linkage, test for leaks-ok.

38. Relief valve leaking, remove #4 discharge linkage, relief valves switch wire connector, drain line and actuating line. Remove valve. Rebuild valve and reinstall test still leaking. Remove valve, disassemble. Check o-rings and parts- OK.

39. Install loose drain hoses and secure with tie strap.

40. Replaced R intake, drain knob.

41. Defroster inop, removed dash found cable binding, reroute defroster cable and install dash and test ok.

#42-44 on WO#71601

## Workorder: V71601

In Date: 12/12/2014

Meter Reading: 82,594.00

Close Date: 12/12/2014

### Problem?

c service continued from 68596

### Task performed:

### Parts

### Quantity

42. Install foam supply hose-bleed foam system and check for leaks/ok.

NO PARTS USED

43. Air horns sound quality bad, horn adjust trumpets froze on nut. Apply penetrating oil and free up trumpets. Remove trumpets clean and lube threads. Reinstall parts and adjusted for sound quality.

44. Order drain valve label for intake relief drain handle.



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V72371**

In Date: 01/15/2015  
Close Date: 01/20/2015

Meter Reading: 27,825.90

**Problem?**

alternator not charging

**Task performed:**

Parts

Quantity

1. Low voltage complaint - Check alternator 14.1 volts out. Check battery 12.1 volts. Clean battery terminal, alternator terminal, starter terminal and clean rail shunt and battery switch terminal. Operating voltage full load 13.4 volts.

NO PARTS USED

**Workorder: V72098**

In Date: 01/06/2015  
Close Date: 01/22/2015

Meter Reading: 82,594.00

**Problem?**

replace hood broken hinge

**Task performed:**

Parts

Quantity

1. Remove hood from engine. Busted glass work. Go to surplus to get other truck and remove good hood.  
2. Installed hood on surplus unit and installed wiring to take back to surplus after reinstalling hood.  
3. Installed hood on spare unit. Bolt on all equipment and adjust to fit. Wire in all lights to work. Installed air lines to air horns. Install grill and lights.

NO PARTS USED

**Workorder: V72686**

In Date: 01/28/2015  
Close Date: 02/03/2015

Meter Reading: 28,150.00

**Problem?**

REPAIR CHARGING SYSTEM E32

**Task performed:**

Parts

Quantity

1. Diagnose charging system. Check batteries. R & R alt. Remove air cleaner housing and bracket.  
2. Assist in charging system repair.

103385NDRAIN COCK

1

4867JB320 UPGRADE ALTERNATOR

1



4/27/2021

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V72764**

In Date: 01/31/2015

Meter Reading:

Close Date: 02/20/2015

**Problem?**

Air horn pedal leaking air E32

**Task performed:**

Parts

Quantity

Traced out air leak. Found on pump shifter. Repaired and tested.

NO PARTS USED

**Workorder: V73324**

In Date: 02/21/2015

Meter Reading:

Close Date: 02/23/2015

**Problem?**

voltage reading 12.4 On call tech is at station/32 working on problem

**Task performed:**

Parts

Quantity

No voltage. R & R alternator and batteries. All ok.

4867JB320 UPGRADE ALTERNATOR

1

BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY

4

HP-31D BATTERY 950CCA HP-31D

4

**Workorder: V69306**

In Date: 09/11/2014

Meter Reading:

Close Date: 06/08/2015

**Problem?**

check valve maybe bad, foam is leaking into the pump. dead batteries. D#2 bleeder not completely closing charging volts 12.6-12.2

**Task performed:**

Parts

Quantity

NO PARTS USED

**Workorder: V73830**

In Date: 03/12/2015

Meter Reading:

Close Date: 06/30/2015

**Problem?**

Officer side mirror won't stay in place. No lock washers. Duct tape for now. @32

**Task performed:**

Parts

Quantity

NO PARTS USED



4/27/2021

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10152055

**\* FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

**Workorder: V73770**

**In Date:** 03/10/2015

**Meter Reading:**

**Close Date:** 07/08/2015

**Problem?**

Left rear window... The weather strip on the outside door frame is coming out. Won't stay in place. @32

**Task performed:**

Parts

Quantity

037-1341-50-0VPS SHIFT KIT 2 PIECE

1

---



# Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (10152055) 2003 - FERRARA FL80 1250 Gpm Pumper

10152055

## CSHOP-2015-1573

Comments: **QUALITY CHECK**  
Date Opened: 7-6-2015

Date Finished: 7-21-2015      Meter 1 Reading: 141,000

### TASKS PERFORMED

### Q      PARTS

A INSPECTION  
FIRE APPARATUS  
OIL  
TIRES & WHEELS  
CAB-INTERIOR ACCESSORIES  
QUALITY CHECK-REPAIRS

1      WINDOW; MOLD L/H

---

## CSHOP-2015-1952

Comments: **HEADLIGHT OUT E 33**  
Date Opened: 7-27-2015

Date Finished: 7-29-2015      Meter 1 Reading: 141,000

### TASKS PERFORMED

### Q      PARTS

TRAVEL TO BE CHARGED TO WORK ORDER  
HEADLIGHTS LOW BEAM

1      LIGHT; HEADLIGHT EXTRA BRIGHT

---

## CSHOP-2015-2390

Comments: **E33 CHECK BRAKES, SQUEALING ALL THE TIME, ALSO BUZZER IS SOUNDING FROM PRESSURE RELIEF VALVE ON THE PUMP PANEL PRE-CONNECT MISSING SCREW FROM SCREW PORT MISSING AFTER PISTOL GRIP REMOVED. NEED WD40 OR EQUIVALENT LEFT WITH THEM**  
Date Opened: 8-19-2015      Date Finished: 8-20-2015      Meter 1 Reading: 143,018

### TASKS PERFORMED

### NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER  
FIRE PUMP  
FIRE APPARATUS

---

## CSHOP-2015-24

Comments: **ENTER WORK ACCOMPLISHED CODE**  
Date Opened: 4-13-2015      Date Finished: 4-20-2015

Meter 1 Reading: 140,548

### TASKS PERFORMED

### NO PARTS USED

A INSPECTION

---

**Asset Work Order History 10152055**

**CSHOP-2015-2572**

Comments: **A-INSPECTION**

Date Opened: 8-27-2015

Date Finished

9-2-2015

Meter 1 Reading:

87,621

**TASKS PERFORMED**

**Q PARTS**

A INSPECTION  
WASHER RESERVOIR  
SPOT LIGHTS  
PARK-CLEARANCE LIGHTS  
TIRES ALL  
A/C FILTER SCREENS

1 LIGHT; HEADLIGHT  
1 FILTER; 78R5360M 2PK FILTER AIR COND

**CSHOP-2015-3058**

Comments: **CHECK REAR TIRE CONDITION SE @32**

Date Opened: 9-24-2015

Date Finished

9-24-2015

Meter 1 Reading:

87,621

**TASKS PERFORMED**

**NO PARTS USED**

TIRES & WHEELS

**CSHOP-2015-3315**

Comments: **REPAIRS FROM PM**

Date Opened: 10-8-2015

Date Finished

11-5-2015

Meter 1 Reading:

88,024

**TASKS PERFORMED**

**Q PARTS**

BUTTON  
INTERIOR TRIM-MOLDINGS-UPHOLS

1 DOOR; DOOR SILL R/H

**CSHOP-2015-3318**

Comments: **B INSPECTION SE2**

Date Opened: 10-8-2015

Date Finished

10-19-2015

Meter 1 Reading:

88,024

**TASKS PERFORMED**

**Q PARTS**

PM SERVICE B

1 FILTER; OIL FILTER 51748  
1 FILTER; FILTER FUEL 33231  
1 FILTER; FILTER FUEL WIX 33422 PS8689 FRAM  
3 FLUID; SYN OIL BULK QTS

**CSHOP-2015-381**

Comments: **FOAM SYSTEM NOT WORKING SPARE ENGINE @ 36**

Date Opened: 4-30-2015

Date Finished

5-12-2015

Meter 1 Reading:

140,648

**TASKS PERFORMED**

**NO PARTS USED**

FIRE PUMP  
DOOR HANDLES INSIDE-OUTSIDE  
AIR CONDITIONING

**Asset Work Order History 10152055**

**CSHOP-2015-4136**

Comments: **SE2 EXTENDA GUN ALARM GOING OFG**

Date Opened: 11-24-2015 Date Finished 12-7-2015 Meter 1 Reading: 88,025

**TASKS PERFORMED**

**Q PARTS**

ALARM-BUZZER-WARNING LIGHT

1 SWITCH; EXTENDA GUN SWITCH

**CSHOP-2015-4291**

Comments: **E31 CHECK GEAR LUBE LEAKING**

Date Opened: 12-3-2015 Date Finished 1-5-2016 Meter 1 Reading: 88,411

**TASKS PERFORMED**

**NO PARTS USED**

LIGHTING SYSTEM  
REAR TIRES

**Service Requests:**

12/03/2015 TIRES / 19: LOOSE / REPAIR

12/03/2015 LIGHTS / 10: BENT / REPAIR  
LEFT REAR YELLOW WARNING LIGHT NOT WORKING. GEAR LUBE LEAKING FROM UNKNOWN SOURCE

**CSHOP-2015-4457**

Comments: **E31 WINDOW PROBLEM QC ALSO**

Date Opened: 12-14-2015 Date Finished 1-6-2016 Meter 1 Reading: 88,530

**TASKS PERFORMED**

**Q PARTS**

QUARTZ LIGHT  
LIGHTING SYSTEM  
WINDOW CHANNEL

1 SOLENOID; SOLENOID INS CONT DUTY  
1 WINDOW; MOLD L/H

**Service Requests:**

12/12/2015 BODY / 12: BROKEN / RE-TAP SUPPORT HOLES INSTALL NEW SCREWS AND SECURE  
FIREFIGHTER WINDOW IS FALLING OUT OF THE WINDOW FRAME. WINDOW IS ABLE TO BE PUSHED IN FROM THE  
OUTSIDE.

12/12/2015 LIGHTS / 12: BROKEN / DIAGNOSE LIGHT FAILURE  
OFFICER SCENE LIGHT WIRING STARTED TO BURN AND MELT THE CASING. LIGHT SHUT OFF AND FRAYS WERE  
PULLED APART AND TAPED SEPARATELY.

12/14/2015 LIGHTS / 12: BROKEN / DUPLICATE REPORT  
RIGHT SCENE LIGHT NOT TURNING ON

**CSHOP-2015-879**

Comments: **SE2 A INSPECTION**

Date Opened: 5-29-2015 Date Finished 6-2-2015 Meter 1 Reading: 141,000

**TASKS PERFORMED**

**Q PARTS**

A INSPECTION  
FIRE APPARATUS  
UPHOLSTERY

1 SLIDE; SLIDE CONTROL 519-0071-10  
1 PUMP; DUPLICATE NUMBER  
1 BEARING; 250-8002-00 BEARING-THRUS

**Asset Work Order History 10152055**

**CSHOP-2016-1800**

Comments: **E38 K12 SAW MISSING SCREWS ALSO A PROBLEM WITH MEDICAL COMPARTMENT DOOR**  
Date Opened: 4-18-2016 Date Finished 4-20-2016 Meter 1 Reading: 90,192

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
FIRE APPARATUS  
LIGHTING SYSTEM  
DOOR

**Service Requests:**

04/16/2016 LIGHTS / 12: BROKEN / REPAIR  
LEFT SIDE SCENE LIGHT NOT WORKING ALONG WITH THE RIGHT REAR SCENE LIGHT.

04/16/2016 SERVICE REQUEST / 12: BROKEN / REPAIR  
THE PARTNER K12 SAW ASSET # 10169673 IS MISSING 2 SCREWS THAT HOLD THE PULL START COVER ON. THE SAW IS WEARING THE INSIDE OF THE COVER OUT WHEN RUNNING BECAUSE IT IS FLAPPING AROUND.

**CSHOP-2016-2163**

Comments: **SE @ ST38**  
Date Opened: 5-4-2016 Date Finished 5-10-2016 Meter 1 Reading: 90,665

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
QUARTZ LIGHT

**Service Requests:**

05/04/2016 ENGINE / 12: BROKEN / REPAIR  
SCENE LIGHT ON DRIVER SIDE IS NOT WORKING

**CSHOP-2016-2872**

Comments: **SE @ ST38**  
Date Opened: 6-15-2016 Date Finished 8-23-2016 Meter 1 Reading: 91,899

**TASKS PERFORMED**

**Q PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
FIRE APPARATUS  
HEADLIGHTS LOW BEAM  
LIGHTING SYSTEM

1 LIGHT; HEADLIGHT EXTRA BRIGHT

**Service Requests:**

08/15/2016 SERVICE REQUEST / 19: LOOSE / W  
FOAM SYSTEM NOT WORKING PROPERLY. LEAKING HEAVILY FROM UNDER THE PUMP PANEL WHEN PUMPING THE YELLOW PRE-CONNECT. ALSO LEAKING OIL

08/17/2016 LIGHTS / 18: LEAKING / R  
VEHICLE LIGHTS NOT WORKING RIGHT SIDE HEADLIGHT OUT 1B1 UNIT IS AT STATION 31

06/15/2016 LIGHTS / 18: LEAKING / E  
TELESCOPIC LIGHT IS OUT ON DRIVER SIDE. THIS ENGINE IS A BACK UP CURRENTLY AT STATION 38

**Asset Work Order History 10152055**

**CSHOP-2016-3643**

Comments: **A INSPECTION**

Date Opened: 8-1-2016

Date Finished

8-3-2016

Meter 1 Reading:

91,899

**TASKS PERFORMED**

**Q PARTS**

A INSPECTION  
FIRE APPARATUS  
TURN SIGNAL LIGHTS  
QUARTZ LIGHT  
DOOR

1 LIGHT; LIGHT ASSY. TURN SIGNAL  
1 SOLENOID; SOLENOID INS CONT DUTY  
1 STRUT; GSS6557UP STRUT-LIFT

---

**CSHOP-2016-4280**

Comments: **ST31**

Date Opened: 8-31-2016

Date Finished

9-2-2016

Meter 1 Reading:

92,399

**TASKS PERFORMED**

**NO PARTS USED**

FIRE APPARATUS  
AIR CONDITIONING

**Service Requests:**

---

08/31/2016

SERVICE REQUEST / 19: LOOSE / REPAIR

THE PULL CORD ON E31 GENERATOR HAS RIPPED IN HALF. THE GENERATOR DOES NOT HAVE AN ASSET NUMBER ON IT.

---

**Asset Work Order History 10152055**

**CSHOP-2016-4419**

Comments: **REPAIRS FROM PM**

Date Opened: 9-10-2016

Date Finished

10-25-2016

Meter 1 Reading:

92,686

**TASKS PERFORMED**

TRAVEL TO BE CHARGED TO WORK ORDER  
INTAKE VALVE  
FOAM SYSTEM  
FIRE FIGHTING EQUIPMENT  
GEAR BOX FIRE PUMP  
UNDERBODY COMPARTMENT BODY  
HOSE BED BODY  
FIRE APPARATUS  
DOOR LATCH  
EXHAUST PIPE  
TURN SIGNAL LIGHTS  
HEADLIGHTS HIGH BEAM  
TIRES ALL  
RESERVOIR  
AIR DRIER  
DOOR HANDLES INSIDE-OUTSIDE  
A/C CONDENSER FAN  
A/C FILTER SCREENS  
AIR CONDITIONING

**Q PARTS**

1 PUMP; SC5025 SUCTION SCREEN  
1 PUMP; FLUSH SELECT HALE FOAM SYS  
18 DECAL; LADDER OUT OF SERVICE STICKER  
4 GEAR; GEAR OIL SYN QT  
23 FLUID; SYN OIL BULK QTS  
1 SLIDE; SLIDE 18IN 500 LBS  
1 SLIDE; SLIDE 18IN 500 LBS  
1 VALVE; REL.VALVE KIT  
2 9IP; SEAL SVS DRAIN VALVE  
1 VALVE; 8907 VALVE KIT 3 IN AKRON  
1 VALVE; HALE RELIEF VALVE W/ VULCANIZED SEAT  
1 SEAL; SEAL  
1 9IP; LATCH TRIGER W/O LOCK  
1 CLAMP; CLAMP 4"" 33969  
1 BULB; BULB  
1 9IP; VALVE CORE  
1 VALVE; PURGE VALVE KIT  
1 VALVE; VALVE CHECK AD9  
1 DRYER; DRYER KIT AD9 -NEW  
1 HANDLE; HANDLE DOOR  
-1 9IP; 18-2108 FIVE BLADE FAN 3382  
2 9IP; 18-2108 FIVE BLADE FAN 3382  
-1 9IP; 01-2616 MOTOR 12V 73R-0542 3512  
2 9IP; 01-2616 MOTOR 12V 73R-0542 3512  
1 FILTER; 78R5360M 2PK FILTER AIR COND  
1 NEWPART; HOSE & FITTINGS

**Service Requests:**

09/10/2016 LIGHTS / 44: WORN / R&R FUSE  
NO HIGH BEAM HEADLIGHTS

09/11/2016 LIGHTS / 44: WORN / R&R BULB  
RIGHT SIDE FRONT TURN SIGNAL NOT WORKING.

**CSHOP-2016-4563**

Comments: **C INSPECTION**

Date Opened: 9-19-2016

Date Finished

9-22-2016

Meter 1 Reading:

92,686

**TASKS PERFORMED**

PM SERVICE C

**Q PARTS**

1 FILTER; AIR FILTER 46744 WIX  
1 FILTER; FILTER FUEL 33231  
1 FILTER; FILTER FUEL WIX 33422 PS8689 FRAM  
1 FILTER; 24070 WIX FILTER WATER  
1 FILTER; OIL FILTER 51748

**Asset Work Order History 10152055**

**CSHOP-2016-5094**

Date Opened: 10-25-2016      Date Finished      11-15-2016      Meter 1 Reading:      93,250

**TASKS PERFORMED**

**NO PARTS USED**

---

BODY - PUMP HOUSE  
AIR SYSTEM

**Service Requests:**

---

- 10/25/2016      SERVICE REQUEST / 19: LOOSE / REPAIR  
TATOMMY VIA LAND LINE. ADVISED HE WILL COME BY STATION 46 TO LOOK AT.NK TO PUMP VALVE FROZEN UNABLE TO MOVE. CONTACTED
  - 10/27/2016      BODY / 19: LOOSE / REPAIR  
BODY ISSUE - TRUCK AT 46 AS OF 10/27/16. INSTALL MOUNTING BRACKETS FOR NEW YORK HOOK ON DIAMOND PLATE ABOVE RUNNING BOARD, PASSENGER SIDE OF CAB.
- 

**CSHOP-2016-5124**

Date Opened: 10-27-2016      Date Finished      11-15-2016      Meter 1 Reading:      93,250

**TASKS PERFORMED**

**NO PARTS USED**

---

COOLING SYSTEM  
AIR SYSTEM

**Service Requests:**

---

- 10/27/2016      BRAKES / 19: LOOSE / REPAIR  
BRAKE ISSUES, AIR LEAKING FROM BRAKE PEDAL WHILE PRESSING PEDAL DURING AND WHILE STOPPING AT A LIGHT ETC.
  - 10/27/2016      BRAKES / 19: LOOSE / REPAIR  
BRAKE ISSUES TRUCK AT STATION 46. FOOT VALVE LEAKING WHEN APPLYING BRAKES.
- 

**CSHOP-2016-716**

Comments:      **ON-CALL E26 BROKEN DOOR HANDLE**

Date Opened: 2-16-2016      Date Finished      2-17-2016      Meter 1 Reading:      88,606

**TASKS PERFORMED**

**Q      PARTS**

---

DOOR

	1	HANDLE; D PADDLE HANDLE
	1	LATCH; LATCH ASSY. FOR D-PADDLE HANDLE

**Service Requests:**

---

- 02/15/2016      DOOR / 12: BROKEN / EXCHANGE - NEW  
MEDICAL COMPARTMENT DOOR WILL NOT OPEN
-

**Asset Work Order History 10152055**

**CSHOP-2016-773**

Comments: **E26**

Date Opened: 2-17-2016

Date Finished

3-14-2016

Meter 1 Reading:

89,394

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
RELIEF VALVE  
THROTTLE CONTROLS  
FRONT TIRES

**Service Requests:**

- 
- 02/17/2016 SERVICE REQUEST / 15: FOREIGN MATERIAL / EXERCISED RELIEF VALVE OK  
PRESSURE RELIEF VALVE NOT WORKING PROPERLY, WILL NOT MAINTAIN CONSTANT PRESSURE. VALVE SEEMS TO BE FULLY OPEN OR FULLY CLOSED WHEN OPERATING.
- 02/23/2016 SERVICE REQUEST / 15: FOREIGN MATERIAL / INSPECT  
PRESSURE RELIEF VALVE WILL NOT SHUT OFF (YELLOW LIGHT ALWAYS ON)
- 02/23/2016 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / COULD NOT DUPLICATE  
CANNOT RUN PUMP OVER 180 PSI, THROTTLE UP TO 180 AND ENGINE WILL GO BACK TO IDLE.
- 

**CSHOP-2017-1133**

Date Opened: 2-23-2017

Date Finished

3-9-2017

Meter 1 Reading:

94,220

**TASKS PERFORMED**

**Q PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
HURST TOOL CUTTERS

- 1 9IP; BULB QUARTZ HAL. 12V 150W  
1 9IP; BULB QUARTZ HAL. 12V 150W  
1 9AP; LAWNMOWER HDQ HONDA HOSE

**Service Requests:**

- 
- 02/22/2017 SERVICE REQUEST / 18: LEAKING / INSPECT  
SERVICE REQUEST HURST CUTTERS CURRENTLY ON ENGINE DO NOT HAVE A ASSET NUMBER. THE 10000 SERIES CUTTERS ARE LEAKING HYDRAULIC FLUID WHILE HOOKED TO THE POWER UNIT WHILE IN USE OR NOT. FLUID IS LEADING FROM A SEAL MOUNTED IN THE MID PART OF THE BODY OF THE CUTTER
- 

**CSHOP-2017-1790**

Comments: **ENGINE AT 73**

Date Opened: 3-24-2017

Date Finished

4-19-2017

Meter 1 Reading:

95,185

**TASKS PERFORMED**

**Q PARTS**

FIRE PUMP CONTROLS

- 2 5TN; HANDLE

**Service Requests:**

- 
- 03/24/2017 PLUMBING / 12: BROKEN / EXCHANGE - NEW  
2 1/2 INCH INTAKE ON THE PASSENGER SIDE OF THE ENGINE HAS NO LEVER TO OPEN IT. SO WE ARE ONLY ABLE TO USE THE DRIVER SIDE 2 1/2 INCH INTAKE AT THIS TIME
-

**Asset Work Order History 10152055**

**CSHOP-2017-1893**

Comments: **SPARE AT 73**

Date Opened: 3-30-2017      Date Finished      4-7-2017      Meter 1 Reading:      95,185

**TASKS PERFORMED**

**Q      PARTS**

WAIT TIME TO BE CHARGED TO WORK ORDER  
TRAVEL TO BE CHARGED TO WORK ORDER  
DOOR LATCH

1      9IP; DOOR HANDLE TRIMARK  
1      9IP; LATCH ASSY. FOR D-PADDLE HANDLE

**Service Requests:**

03/30/2017      BODY / 12: BROKEN / EXCHANGE - NEW  
BODY ISSUE LATCH FOR REAR COMPARTMENT BROKEN, UNABLE TO OPEN TO ACCESS BOOSTER LINE AND CRIBBING

**CSHOP-2017-2000**

Date Opened: 4-5-2017      Date Finished      4-7-2017      Meter 1 Reading:      95,185

**TASKS PERFORMED**

**NO PARTS USED**

WAIT TIME TO BE CHARGED TO WORK ORDER  
TRAVEL TO BE CHARGED TO WORK ORDER  
RELIEF VALVE FIRE PUMP  
STEERING

**Service Requests:**

04/05/2017      STEERING / 49: CAN NOT DUPLICATE CONCERN / INSPECT  
STEERING/ALIGNMENT. RIGHT FRONT WHEEL RUBBING ON THE FRONT SUCTION. FRONT AND REAR OF THE TIRE.

**CSHOP-2017-2523**

Comments: **SPARE ENGINE OUT AT BATT 7**

Date Opened: 5-1-2017      Date Finished      5-11-2017      Meter 1 Reading:      95,185

**TASKS PERFORMED**

**Q      PARTS**

RELIEF VALVE  
CONTROL VALVE

1      9IP; SPRING-VALVE QG RELIEF VALVE  
1      5HP; RELIEF VALVE KIT HALE  
1      SWIVEL; BD55015-1616-01 SWIVEL  
1      9LO; BD55015161601 SWIVEL  
1      9IP; VALVE KIT SS 546-2270-02-0

**Service Requests:**

04/30/2017      SERVICE REQUEST / 18: LEAKING / EXCHANGE - NEW  
SERVICE REQUEST BOOSTER VALVE IS LEAKING

**CSHOP-2017-438**

Comments: **A INSPECTION**

Date Opened: 1-19-2017      Date Finished      1-19-2017      Meter 1 Reading:      93,769

**TASKS PERFORMED**

**NO PARTS USED**

A INSPECTION

**Asset Work Order History 10152055**

**CSHOP-2017-4413**

Comments: **SERVICE REQUEST: PRIMER WILL NOT ENGAGE ON PUMP. SEEMS TO BE A SHORT AND A ELECTRICAL BURN SMELL.**

Date Opened: 7-31-2017      Date Finished      8-21-2017      Meter 1 Reading:      95,601

**TASKS PERFORMED**

**Q      PARTS**

RELIEF VALVE FIRE PUMP	1	9IP; TPM/QG HALE REPAIR KIT
FIRE PUMP	2	ECH; RELAY (AR462)
FIRE APPARATUS	1	5EF; MANSAVER COVER
AIR FILTER		
COOLING SYSTEM		
DIAGNOSE ELECTRICAL		
ELECTRICAL		
U-BOLTS		
AIR TANK		
SAFTEY-EMERGENCY EQUIPMENT		

**Service Requests:**

---

07/31/2017      SERVICE REQUEST / 12: BROKEN / REPAIR  
SERVICE REQUEST: PRIMER WILL NOT ENGAGE ON PUMP. SEEMS TO BE A SHORT AND A ELECTRICAL BURN SMELL.

---

**CSHOP-2017-4477**

Date Opened: 8-2-2017      Date Finished      8-11-2017      Meter 1 Reading:      95,390

**TASKS PERFORMED**

**Q      PARTS**

PM SERVICE B	1	FIL; NAPAGOLD AIR FILTER
	1	FIL; FUEL WATER SEPARATOR
	1	FIL; NAPAGOLD FUEL FILTER
	1	FIL; NAPAGOLD OIL FILTER

**CSHOP-2017-6144**

Date Opened: 10-24-2017      Date Finished      10-30-2017      Meter 1 Reading:      96,995

**TASKS PERFORMED**

**Q      PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER AIR SYSTEM	1	9IP; VALVE AIR CONTROL
---	---	------------------------

**CSHOP-2017-6482**

Comments: **ENGINE BEING USED BY L73 CREW**

Date Opened: 11-9-2017      Date Finished      11-21-2017      Meter 1 Reading:      97,198

**TASKS PERFORMED**

**Q      PARTS**

DIAGNOSE ELECTRICAL	1	9IP; NODE MINI V-MUX 6010-0000-00
ELECTRICAL	1	9IP; NODE MINI V-MUX 6010-0000-00

**Service Requests:**

---

11/09/2017      SERVICE REQUEST / 12: BROKEN / REPAIR  
PTO WILL NOT SHIFT INTO PUMP. NO GREEN LIGHTS. TRIED SHUTTING TRUCK DOWN AND TURNING OFF BATTERY WITH NO LUCK. ALSO, NONE OF THE EMERGENCY LIGHTS OR SCENE LIGHTS WILL WORK.

---

**Asset Work Order History 10152055**

**CSHOP-2017-6741**

Comments: **ON-CALL**

Date Opened: 11-27-2017      Date Finished      12-4-2017      Meter 1 Reading:      97,632

**TASKS PERFORMED**

**NO PARTS USED**

FIRE PUMP

**Service Requests:**

---

11/24/2017      SERVICE REQUEST / 12: BROKEN / REPAIR  
TANK TO PUMP STEM BROKEN OFF OF VALVE

**CSHOP-2017-6795**

Comments: **SPARE ENG AT STATION 73**

Date Opened: 11-28-2017      Date Finished      12-8-2017      Meter 1 Reading:      97,713

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
FIRE FIGHTING EQUIPMENT  
TIRE

**Service Requests:**

---

11/30/2017      SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW  
GENESIS HYDRAULIC POWER UNIT LEAKING OIL FROM PLUG WHILE RUNNING. DOES NOT LEAK UNLESS UNIT IS  
RUNNING

12/02/2017      SERVICE REQUEST / 12: BROKEN / REPAIR  
THE TANK TO PUMP LEVER ON THE PUMP PANEL HAS SNAPPED OFF WHERE THE ROD MEETS THE PANEL AGAIN.  
THE TANK TO PUMP VAVLE CAN STILL BE OPERATED BY OPENING THE ACCESS PANEL ON FRONT OF THE PUMP AND  
OPERATING BY HAND.

**CSHOP-2017-6910**

Date Opened: 12-4-2017      Date Finished      12-4-2017      Meter 1 Reading:      97,632

**TASKS PERFORMED**

**NO PARTS USED**

FIRE PUMP

**CSHOP-2018-1463**

Comments: **ORDERED NEW SEATBELT WAS REMOVED TO GET 10155551 GOING**

Date Opened: 3-12-2018      Date Finished      7-3-2018      Meter 1 Reading:      154,262

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER

**Service Requests:**

---

03/12/2018      SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT  
DURING PUMP TESTING, THE VEHICLE STARTED LEAKING A SIGNIFICANTLY AT THE PUMP MANIFOLD...

**Asset Work Order History 10152055**

**CSHOP-2018-2380**

Date Opened: 5-1-2018

Date Finished

5-18-2018

Meter 1 Reading:

154,262

**TASKS PERFORMED**

	<b><u>Q</u></b>	<b><u>PARTS</u></b>
QUALITY CHECK-REPAIRS	1	2FR; TANKVISION (WATER KIT)
WATER TANK LEVEL LIGHTS	-1	5TN; FLAPPER KIT
FIRE PUMP PLUMBING	2	9IP; GREASE ZERK W/CHECK VLV
PRIMING PUMP FIRE PUMP	1	5TN; FLAPPER KIT
EQUIPMENT MOUNTING BRACKETS	-1	5TN; GASKET
HOSE BED BODY	1	5TN; GASKET
REAR DOOR SEAL	2	5SC; KNOB
REPAIR FROM PM - GROUND LADDERS	-1	5TN; GASKET
AIR FILTER	1	5TN; GASKET
EXHAUST SYSTEM	2	5SC; HANDLE
COOLING SYSTEM	8	9AP; HEAT SENSOR LADDER LABELS
REPAIR FROM PM - TRANS/TRANSFER CASE	8	9AP; HEAT SENSOR LADDER LABELS
QUARTZ LIGHT	1	FIL; NAPAGOLD AIR FILTER
LIGHTING SYSTEM	1	BK; RADIATOR CAP
BATTERY TRAY	4	9OC; GEAR OIL BULK
BATTERY	1	9AP; BULB, 150W HALOGEN
U-BOLTS	4	1AD; BATTERY 31 SERIES
AIR DRIER	4	9AP; U BOLTS
AIR SYSTEM	8	9AP; WASHER
SEAT BELTS	8	9AP; EP NUT
ALARM-BUZZER-WARNING LIGHT	1	9IP; VALVE CHECK AD9
HEATER CONTROL VALVE	1	TWD; AD-9KIT
AIR CONDITIONING	1	TWD; AD-9KIT MINOR
	1	9ME; VPS POWER SHIFT & CONTROL KIT
	2	5AH; GAS SPRING, 12.087", 94LB
	2	ECH; SWITCH - DOOR JAMB
	1	MMM; ELECTRICAL TAPE
	1	MMM; ELECTRICAL TAPE
	1	9IP; 11-3050 SWITCH BLOWER
	1	9IP; CABLE HEATER
	1	TEM; EXPANSION VALVE
	1	TEM; FILTER DRIER
	1	2TK; FILTER

**CSHOP-2018-2381**

Date Opened: 5-1-2018

Date Finished

5-15-2018

Meter 1 Reading:

154,262

**TASKS PERFORMED**

	<b><u>Q</u></b>	<b><u>PARTS</u></b>
PM SERVICE C	1	FIL; NAPAGOLD FUEL FILTER
	1	FIL; NAPA COOLANT FILTER
	24	4PC; 15W40 PREMIUM BLUE OIL
	1	FIL; NAPAGOLD OIL FILTER
	1	FIL; FUEL WATER SEPARATOR

**Asset Work Order History 10152055**

**CSHOP-2018-2408**

Comments: **ORDERED NEW SEATBELT WAS REMOVED TO GET 10155551 GOING**

Date Opened: 5-2-2018      Date Finished      5-2-2018      Meter 1 Reading:      154,267

**TASKS PERFORMED**

**NO PARTS USED**

---

SEAT BELTS

---

**CSHOP-2018-2769**

Comments: **UNIT BLOWING BLACK SMOKE**

Date Opened: 5-18-2018      Date Finished      5-18-2018      Meter 1 Reading:      154,262

**TASKS PERFORMED**

**NO PARTS USED**

---

ENGINE AND ACCESSORIES

---

**CSHOP-2018-2966**

Date Opened: 5-29-2018      Date Finished      6-1-2018      Meter 1 Reading:      154,262

**TASKS PERFORMED**

**NO PARTS USED**

---

TRAVEL TO BE CHARGED TO WORK ORDER  
SIDE COMPARTMENT BODY  
ALARM-BUZZER-WARNING LIGHT

**Service Requests:**

---

05/29/2018      ALARMS / 21: MISADJUSTED / ADJUST  
ALARM SIGNALS, REAR COMPARTMENT ALARM MALFUNCTION, ALARM AND LIGHT STAY ON CONTINUOUSLY,

05/29/2018      SERVICE REQUEST / 18: LEAKING / REPAIR  
TYPE PROBLEM INTO DESCRIPTION, MEDICAL AND DRIVER COMPARTMENT NOT SEALING CORRECTLY, BOTH  
COMPARTMENTS GET WET DURING ANY KIND OF RAIN

---

**CSHOP-2018-3030**

Date Opened: 6-1-2018      Date Finished      6-4-2018      Meter 1 Reading:      154,262

**TASKS PERFORMED**

**NO PARTS USED**

---

TRAVEL TO BE CHARGED TO WORK ORDER  
DOOR

**Service Requests:**

---

06/01/2018      ALARMS / 21: MISADJUSTED / ADJUST  
THE COMPARTMENT ALARM STILL BUZZING, INDICATING OPEN COMPARTMENT. SENSOR MALFUNCTION

---

**Asset Work Order History 10152055**

**CSHOP-2018-3208**

Comments: **SPARE ENGINE AT ST22**

Date Opened: 6-8-2018      Date Finished      6-13-2018      Meter 1 Reading:      154,262

**TASKS PERFORMED**

**Q      PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
THROTTLE CONTROLS

1      5SC; D-DECK ELEC HAND THROTTLE

**Service Requests:**

---

06/08/2018      ENGINE / 12: BROKEN / EXCHANGE - NEW  
WHILE PUMP IS ENGAGED, IT INTERMITTENTLY FLUCTUATES RPM'S HIGH AND LOW FOR UNDETERMINED REASONS  
AND IS NOT RESPONDING TO THE THROTTLE CONTROL APPROPRIATELY

---

**CSHOP-2018-3215**

Comments: **SPARE ENGINE AT 22**

Date Opened: 6-8-2018      Date Finished      7-17-2018      Meter 1 Reading:      154,262

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
LIGHTING SYSTEM

**Service Requests:**

---

07/16/2018      LIGHTS / 38: SHORTED / REPAIR  
VEHICLE LIGHTS NOT WORKING, TELESCOPING SCENE LIGHTS NOT WORKING ONLY, 1 BULB ON THE DRIVERS  
SIDE IS LIGHTING UP, AND THE PASSENGER SIDE IS NOT WORKING AT ALL

---

**CSHOP-2018-3289**

Comments: **SPARE ENGINE AT 22**

Date Opened: 6-12-2018      Date Finished      6-14-2018      Meter 1 Reading:      154,262

**TASKS PERFORMED**

**Q      PARTS**

AIR CONDITIONING

2      BK; HI-AMP FLUSH MOUNT

**Service Requests:**

---

06/12/2018      A/C / 38: SHORTED / EXCHANGE - NEW  
REAR A/C SURGING ON AND OFF. BLOWS FOR APPROX 2 SEC THE OFF FOR ABOUT 10 SEC

---

**CSHOP-2018-3561**

Date Opened: 6-25-2018      Date Finished      6-27-2018      Meter 1 Reading:      154,262

**TASKS PERFORMED**

**Q      PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
FIRE PUMP PLUMBING

1      5SC; ENGINESTATUSCENTER

**Service Requests:**

---

06/25/2018      SERVICE REQUEST / 12: BROKEN / REPAIR  
PTO FAILED STARTED STEAMING AND LEADING FLUID DURING MORNING CHECKOUT. DIGITAL PUMP DISPLAY  
SHORTED OUT AND WAS NOT SHOWING ANY INFORMATION

---

**Asset Work Order History 10152055**

**CSHOP-2018-4042**

Comments: **CHECK BRAKES AND SEE IF RETARDER IS WORKING**  
Date Opened: 7-18-2018      Date Finished: 8-14-2018      Meter 1 Reading: 154,262

**TASKS PERFORMED**

**Q      PARTS**

FIRE PUMP CONTROLS	1	5AB; 3IN SLOW CLOSE VALVE R1 HANDLE
ENGINE AND ACCESSORIES	1	9IP; GASKET
LIGHTING SYSTEM	1	9IP; FLAPPER KIT
ELECTRICAL	1	9AP; GROTTETOGGLESWITCH
BRAKES	1	GRO; SWITCH, BOOT
	1	TWD; E-6VALVE BRAKE

**Service Requests:**

07/17/2018      LIGHTS / 12: BROKEN / REPAIR  
LEFT SCENE LIGHT BULB INOP

07/18/2018      SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW  
THE TANK TO PUMP VALVE IS BROKEN. THE VALVE HANDLE MOVES FREELY OPEN TO CLOSED BUT IS NO LONGER ATTACHED TO THE VALVE. TANK TO PUMP IS STUCK OPEN.

**CSHOP-2018-4366**

Date Opened: 8-6-2018      Date Finished: 8-6-2018      Meter 1 Reading: 154,262

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER

**Service Requests:**

08/06/2018      SERVICE REQUEST / 18: LEAKING / REPAIR  
TYPE PROBLEM INTO DESCRIPTION, SPARE E91 10152055 IS LEAKING LARGE AMOUNT OF WATER. APPEARS TO BE AROUND 1 GALLON PER MIN. LOOKS TO BE COMING FROM TANK.

**Asset Work Order History 10152055**

**CSHOP-2018-5369**

Comments: **WATER TANK LEAKING**

Date Opened: 9-20-2018

Date Finished

12-3-2018

Meter 1 Reading:

100,259

**TASKS PERFORMED**

A INSPECTION  
FIRE APPARATUS  
CONTROL VALVE  
SERPENTINE BELT TENSIONER  
BATTERY CABLE  
WHEEL BEARINGS  
BRAKE CHAMBER  
AIR SYSTEM  
WINDOW REGULATOR  
AIR BAG SYSTEM  
AIR CONDITIONING

**Q PARTS**

---

1	9IP; G150T SEAL
1	5EF; FOAM TANK LEVEL SENSOR
1	LUC; LUCAS RED-TACKY GRS
1	9HY; SEAL
1	MAC; MAC WITE LITHIUM GRES
-1	5AB; 2.5 BALL KIT COMPOSITE
1	5AB; 2.5 BALL KIT COMPOSITE
1	5HP; HALE 2.5 VALVE REPAIR KIT
1	NBH; V-BELT
1	NBH; TENSIONER-HEAVY DUTY
1	NBH; SERPENTINE BELT
1	NBH; V-BELT
12	9AP; BRAKE CLEAN
2	BK; PTEX ULTRA BLACK 30Z
1	BK; MPACT BLK GRAY XL
2	9HD; BEARING
25	4PC; GEAR OIL-SYN BULK (DELO)
2	9HD; HD TRUCK SCOTSEAL
2	2FL; FUEL CAP
4	CRC; CLEANRCARB 200Z
2	2TP; BRAKE CHAMBER
2	2TP; SLACK ADJUSTER
1	BK; PTEX THRD LCK BLUE LG
1	TWD; BENDIX D-2 GOV
1	9IP; 29552377 VALVE ASSY.ACCUM
3	NTH; REGULATR
1	MBI; AIR PRESSURE VALVE
1	9AP; HAND SOAP PUM (TOTAL TRK)
1	MBI; PRESSURE PROTECT VLV
-1	NLE; 12 TN AIR BOTTLE JACK
1	2FL; CAB LEVEL VALVE
2	2FL; CAB AIR BAG
1	NLE; 12 TN AIR BOTTLE JACK
1	BK; GRN LIQ ELEC TAPE
2	TEM; BLOW/MOT
1	8AM; DIODE
1	TEM; TAPE
1	TEM; PAG 100 OIL
3	9XX; AC FREON 10199801
2	9IP; 18-2108 FIVE BLADE FAN 3382
3	9XX; AC FREON 10174676
1	9AP; KWIK KLEAN AC FLUSH
1	TEM; NEW COMPRESSOR
1	TEM; FILTER DRIER
1	TEM; EXPANSION VALVE
3	9XX; AC FREON 10199801
2	8HD; GAP FILLER FOAM

---

**Asset Work Order History 10152055**

**CSHOP-2018-6499**

Date Opened: 11-15-2018

Date Finished

3-15-2019

Meter 1 Reading:

154,262

**TASKS PERFORMED**

FOAM SYSTEM  
FIRE PUMP PLUMBING  
FIRE PUMP  
DISCHARGE GAUGE  
SIDE COMPARTMENT BODY  
ENGINE AND ACCESSORIES  
TURN SIGNAL LIGHTS  
STARTER  
AUTO-EJECT  
BODY EXTERIOR

<u>Q</u>	<u>PARTS</u>
1	5EF; FOAM TANK LEVEL SENSOR
1	5AB; KIT, 3" & 3.5" BALL VALVE
1	5HP; HALE 2.5 VALVE REPAIR KIT
1	5HP; MIV PARTS FOR REPAIR
1	FRT
1	5SC; ORING
1	9IP; GEAR BOX MIV VALVE
1	5AB; TRUNNION 3IN VLAVE
4	5TN; GAUGE 35
1	9IP; SWITCH TURN SIGNAL
1	TWD; STARTER
-1	2IH; STARTER 37MT
1	2IH; STARTER 37MT
1	6KU; AC2000 12V PLC TEN8

**CSHOP-2019-2004**

Date Opened: 4-17-2019

Date Finished

4-24-2019

Meter 1 Reading:

155,823

**TASKS PERFORMED**

HOSE BED BODY  
FUEL SYSTEM  
OIL  
SPOT LIGHTS  
DIAGNOSE ELECTRICAL  
AIR SYSTEM  
AIR HORN

<u>Q</u>	<u>PARTS</u>
1	2FL; SENSOR, WIF (DOR9047370)
1	BK; SWITCH
1	9IP; 9IP
1	8GR; FOOT SWITCH

**CSHOP-2019-2020**

Date Opened: 4-17-2019

Date Finished

4-18-2019

Meter 1 Reading:

154,899

**TASKS PERFORMED**

PM SERVICE B

<u>Q</u>	<u>PARTS</u>
1	FIL; NAPAGOLD FUEL FILTER
1	LUC; LUCAS RED-TACKY GRS
26	4PC; 15W40 PREMIUM BLUE OIL
1	FIL; NAPAGOLD OIL FILTER
1	FIL; FUEL WATER SEPARATOR

**CSHOP-2019-2609**

Date Opened: 5-20-2019

Date Finished

5-20-2019

Meter 1 Reading:

155,823

**TASKS PERFORMED**

PRE TRIP INSPECTION  
COOLING SYSTEM  
DOOR STRIKER PLATE

<u>Q</u>	<u>PARTS</u>
1	5AH; GAS SPRING

**Asset Work Order History 10152055**

**CSHOP-2019-2730**

Date Opened: 5-28-2019      Date Finished      6-19-2019      Meter 1 Reading:      156,123

**TASKS PERFORMED**

**NO PARTS USED**

---

FOAM SYSTEM  
FIRE APPARATUS

**Service Requests:**

-----  
05/28/2019      SERVICE REQUEST / 19: LOOSE / REPAIR  
                    SPARE ENGINE IN BOARD FOAM SYSTEM 10-7. DISPLAY KEEPS FLASHING "FLUSH" THANKS BARRY E51  
-----

---

**CSHOP-2019-4466**

Date Opened: 8-22-2019      Date Finished      8-26-2019      Meter 1 Reading:      156,453

**TASKS PERFORMED**

**NO PARTS USED**

---

SAFTEY-EMERGENCY EQUIPMENT

**Service Requests:**

-----  
08/22/2019      SERVICE REQUEST / 18: LEAKING / REPAIR  
                    SEVERAL PIECES OF THIS SPARE TRUCK ARE EITHER NOT FUNCTIONING PROPERLY OR MISSING .THE 1 3/8" TIP OF  
                    THE DECK GUN CANNOT BE LOCATED (WAS MISSING ALREADY WHEN SWAPPED INTO). THE FOAM SYSTEM DOES  
                    NOT WORK SO THE EDUCTOR MUST BE USED. THE PRIMER FOR THE PUMP DOES NOT SOUND LIKE IT IS WORKING.  
                    IT DOES NOT SEEM TO INHIBIT PUMPING FUNCTIONS.  
-----

---

**CSHOP-2019-4482**

Date Opened: 8-23-2019      Date Finished      8-26-2019      Meter 1 Reading:      156,453

**TASKS PERFORMED**

**NO PARTS USED**

---

AIR SYSTEM

**Service Requests:**

-----  
08/23/2019      HAZARD / 18: LEAKING / REPAIR  
                    PRIMER NOT WORKING  
-----

---

**CSHOP-2019-4500**

Date Opened: 8-24-2019      Date Finished      9-12-2019      Meter 1 Reading:      101,129

PRIMER INOP.

**TASKS PERFORMED**

**Q      PARTS**

---

PRIMING PUMP FIRE PUMP      1      5HP; EPS PRIMER PUMP

---

**Asset Work Order History 10152055**

**CSHOP-2019-4524**

Comments: SPARE ENGINE AT ST41 JERRY S. ORDERED A PRIMER PUMP IT SHOWS COMPLETED AND HE ALSO ORDERED A NEW SWITCH FOR THE SIDE PUMP PANEL

Date Opened: 8-26-2019 Date Finished 8-26-2019 Meter 1 Reading: 101,129

**TASKS PERFORMED**

**NO PARTS USED**

PRIMING PUMP FIRE PUMP

**Service Requests:**

08/24/2019 HAZARD / 37: SEIZED / REPLACED PRIMER ASSEMBLY AND PRIMER VALVE/SWITCH ORDERED O PRIMER NOT WORKING

**CSHOP-2019-5006**

Comments: SPARE ENGINE AT 18

Date Opened: 9-23-2019 Date Finished 10-7-2019 Meter 1 Reading: 101,460

**TASKS PERFORMED**

**Q PARTS**

FIRE APPARATUS  
EXHAUST PIPE  
BODY EXTERIOR

10 2TP; EXHAUST PIPE 4IN  
3 BK; CLAMP  
2 4AH; GAS SPRING

**Service Requests:**

09/21/2019 SERVICE REQUEST / 18: LEAKING / REPAIR  
TYPE PROBLEM INTO DESCRIPTION THE PRESSURE RELIEF VALVE IS NOT WORKING PROPERLY. IT STICKS AND WILL NOT TURN OFF. THE VALVE WILL REMAIN OPEN EVEN WHEN PRESSURE IS IN NEUTRAL.

09/22/2019 SERVICE REQUEST / 18: LEAKING / REPAIR  
WATER LEAKING FROM A VALVE ONTO BAY FLOOR DRIVER WILL POINT OUT THE LOCATION.

**CSHOP-2019-5543**

Comments: THIS LABOR GOES ON 10155563 WO#5060

Date Opened: 10-21-2019 Date Finished 10-21-2019 Meter 1 Reading: 101,714

PRIMER PUMP INOP.

**TASKS PERFORMED**

**NO PARTS USED**

PRIMING PUMP FIRE PUMP

**CSHOP-2019-6082**

Date Opened: 11-20-2019 Date Finished 12-3-2019 Meter 1 Reading: 101,753

**TASKS PERFORMED**

**Q PARTS**

RELIEF VALVE FIRE PUMP

-1 TWD; PURGE VALVE ASSY KIT  
1 5HP; TPM REBUILD KIT  
1 TWD; PURGE VALVE ASSY KIT

**Service Requests:**

11/19/2019 ENGINE / 37: SEIZED / REPAIR  
ENGINE: PRESSURE RELIEF VALVE CONSISTANTLY STICKING IN ON POSITION LIMITING PUMP PRESSURE. PER MECHANIC TOMMY DO NOT SWAP INTO ENGINE TILL HE CHECKS IT. ENGINE AT STATION 52

**Asset Work Order History 10152055**

**CSHOP-2019-6084**

Date Opened: 11-20-2019      Date Finished      12-12-2019      Meter 1 Reading:      101,753

**TASKS PERFORMED**

**Q      PARTS**

HOSE STORAGE BOX BODY  
LIGHTING SYSTEM

1      1WL; LIGHT 18 LED STRIP  
1      1WL; LIGHT 18 LED STRIP  
2      GRO; 3 CENTER LED RED  
1      CRC; LECTRAMOTIVECLEANER  
2      GRO; REFLECTOR  
4      9ES; BULB 150W HALOGEN

**Service Requests:**

11/19/2019      LIGHTS / 12: BROKEN / REPARE  
VEHICLE LIGHTS NOT WORKING: OFFICER SIDE TELELIGHT OUT, DRIVER SIDE ONLY ONE BLUB WORKING, REAR REFLECTOR MISSING ENGINE AT 52 AWAITING SWAP.

**CSHOP-2020-1567**

Date Opened: 3-18-2020      Date Finished      3-27-2020      Meter 1 Reading:      102,264

**TASKS PERFORMED**

**NO PARTS USED**

BATTERY TRAY  
WIRING  
DIAGNOSE ELECTRICAL  
ELECTRICAL  
VENDOR TIRE REPAIR/CHANGE  
AIR SYSTEM

**Service Requests:**

03/16/2020      TIRES / 44: WORN / EXCHANGE - NEW  
BAD TIRES- REAR TIRES TREAD IS WORN

**CSHOP-2020-1604**

Comments:      **ON CALL**

Date Opened: 3-19-2020      Date Finished      3-24-2020      Meter 1 Reading:      102,264

**TASKS PERFORMED**

**NO PARTS USED**

BATTERY TRAY  
WIRING  
FUSE  
DIAGNOSE ELECTRICAL  
ELECTRICAL

**CSHOP-2020-2436**

Date Opened: 5-7-2020      Date Finished      5-20-2020      Meter 1 Reading:      102,408

**TASKS PERFORMED**

**Q      PARTS**

PM SERVICE C

25      4PC; 15W40 PREMIUM BLUE OIL  
1      FIL; NAPAGOLD FUEL FILTER  
1      FIL; NAPAGOLD OIL FILTER  
1      FIL; FIL  
1      FIL; NAPAGOLD AIR FILTER

**Asset Work Order History 10152055**

**CSHOP-2020-2580**

Date Opened: 5-15-2020

Date Finished

5-27-2020

Meter 1 Reading:

102,408

**TASKS PERFORMED**

**Q PARTS**

---

PUMP PANEL	2	5CS; GAUGE 3 5 0 600 WH
PRIMING PUMP FIRE PUMP	1	5HP; VALVE
DISCHARGE GAUGE	2	5HP; HALE RELIEF VALVE STRAINER
SIDE COMPARTMENT BODY	2	9IP; 434 LATCH TRIGGER S O
CONTROL VALVE	2	1AN; 24 WIPER BLADE
WIPER BLADES	1	GAT; CAP RADIATOR SUTPHEN
RADIATOR	1	9ES; BULB 150W HALOGEN
SPOT LIGHTS	2	LIT; LED M C LAMP
PARK-CLEARANCE LIGHTS	2	LIT; LED M C LAMP
FILTER	1	9HY; SWIVELS MAKO GREASE
TRANSMISSION	1	PTX; PERMATEX
REPAIR FROM PM - WHEEL SEALS	1	NTL; TEF SEAL UPGRADE
AIR SYSTEM	1	NTL; AXL GSKT
SIREN	3	9XX; 134A 10194654
AIR CONDITIONING		

---

**CSHOP-2020-3455**

Date Opened: 7-2-2020

Date Finished

7-22-2020

Meter 1 Reading:

157,898

**TASKS PERFORMED**

**NO PARTS USED**

SPOTLIGHT MOUNTING EQUIPMENT  
BATTERY

**Service Requests:**

---

07/01/2020 LIGHTS / 19: LOOSE / REPAIR  
VEHICLE LIGHTS NOT WORKING. SPOTLIGHT ON TOP OF THE ENGINE IS NOT TURNING ON/AND ROTATING. THANK YOU.

---

**CSHOP-2020-4953**

Date Opened: 9-21-2020

Date Finished

10-8-2020

Meter 1 Reading:

47,539

**TASKS PERFORMED**

**Q PARTS**

---

QUALITY CHECK-REPAIRS	2	1AN; 24 WIPER BLADE
STORAGE CABINET EMERGENCY VEH		
WIPER BLADES		
SAFTEY-EMERGENCY EQUIPMENT		
HEATING AND VENTILATION		

---

**CSHOP-2020-5641**

Date Opened: 10-26-2020

Date Finished

1-22-2021

Meter 1 Reading:

47,539

**TASKS PERFORMED**

**Q PARTS**

---

BATTERY	4	1AD; 1000 CCA 31 SERIES BATTERY
---------	---	---------------------------------

---

**Asset Work Order History 10152055**

**CSHOP-2020-615**

Comments: **FIRE PUMP RELIEF VALVE STUCK**

Date Opened: 2-4-2020      Date Finished      2-19-2020      Meter 1 Reading:      101,753

**TASKS PERFORMED**

**Q      PARTS**

---

RELIEF VALVE FIRE PUMP  
FIRE PUMP

1      5TN; PILOT VALVE W PM CONTROL

---

**SSHOP-2019-158**

Date Opened: 5-28-2019      Date Finished      5-29-2019      Meter 1 Reading:      156,000

**TASKS PERFORMED**

**Q      PARTS**

---

TRAVEL TO BE CHARGED TO WORK ORDER  
QUALITY CHECK-REPAIRS  
CAB-INTERIOR ACCESSORIES

1      5SC; GAUGE, CROSSFIRE

---

**SSHOP-2019-195**

Date Opened: 6-26-2019      Date Finished      7-24-2019      Meter 1 Reading:      156,123

**TASKS PERFORMED**

**Q      PARTS**

---

FIRE PUMP

1      9HY; FITTING45DEG  
1      5HP; SENSING VALVE  
1      NF; FLASHER-ELECTRO MECH  
1      5HP; QGRELIEFASM  
1      9IP; SWITCH OLD # 200-0020-00  
1      5HP; SWITCHRVSSENSINGWBRACKET  
1      5HP; HALE RELIEF VALVE W VULCANIZED SEAT  
1      9HY; FITTING

---

**SSHOP-2019-266**

Date Opened: 8-21-2019      Date Finished      8-21-2019      Meter 1 Reading:      156,123

**TASKS PERFORMED**

**NO PARTS USED**

---

LIGHTING SYSTEM

---

**SSHOP-2020-198**

Comments: **LOSING POWER AND DOOR ALARM COMING ON**

Date Opened: 6-21-2020      Date Finished      7-16-2020      Meter 1 Reading:      102,521

**TASKS PERFORMED**

**Q      PARTS**

---

ELECTRICAL

1      TWD; SWROT2POSLEVER2STUDS  
1      5TN; DOOR SWITCH CONNECTOR

---