



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V025

In Date: 10/07/2005
Close Date: 10/07/2005

Meter Reading:

Problem?
rear a/c leaking in cab

Task performed:

Parts	Quantity
78R536078R5360M 2PK FILTER AIR COND	2

Workorder: V124

In Date: 10/11/2005
Close Date: 10/13/2005

Meter Reading:

Problem?
R/SIDE HEADLIGHT INOP, RE-45

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V424

In Date: 11/02/2005
Close Date: 11/03/2005

Meter Reading:

Problem?
R/REAR DISCHARGE WILL NOT OPEN, RE-45

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V429

In Date: 11/02/2005
Close Date: 11/10/2005

Meter Reading:

Problem?
replace r/f tire elpex E45

Task performed:

Parts	Quantity
NO PARTS USED	

Vendor?: ELPEX



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V368

In Date: 10/31/2005
Close Date: 11/15/2005

Meter Reading:

Problem?

L/REAR DOOR ON DRIVER SIDE OF CAB HAS BROKEN HINGES RE-45

Task performed:

<u>Parts</u>	<u>Quantity</u>
NO PARTS USED	

Workorder: V744

In Date: 11/30/2005
Close Date: 12/12/2005

Meter Reading:

Problem?

GFI FOR GENERATOR LIGHT INOP, NEED NEW BATTERY FOR 24V RECIP. SAW, RE-45

Task performed:

<u>Parts</u>	<u>Quantity</u>
NO PARTS USED	

Workorder: V1062

In Date: 12/29/2005
Close Date: 01/04/2006

Meter Reading:

Problem?

D/SIDE HEADLIGHT INOP, RE-45

Task performed:

<u>Parts</u>	<u>Quantity</u>
H6054USE CV TYPE SEALED BEAM	6

Workorder: V1191

In Date: 01/17/2006
Close Date: 01/23/2006

Meter Reading:

Problem?

R/REAR DISCHARGE VALVE INOP, HOSE REEL HOSE SLIPPING FROM COUPLING, RE-45

Task performed:

<u>Parts</u>	<u>Quantity</u>
NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V1306

In Date: 01/26/2006
Close Date: 02/14/2006

Meter Reading:

Problem?
A/C INOP, RE-45

Task performed:

	<u>Parts</u>	<u>Quantity</u>
NO PARTS USED		

Workorder: V1572

In Date: 02/21/2006
Close Date: 03/06/2006

Meter Reading:

Problem?
#1 DISCHARGE INOP, RELIEF VALVE BULB INOP, PASS, SEAT BELT INOP, RE-45

Task performed:

	<u>Parts</u>	<u>Quantity</u>
NO PARTS USED		

Workorder: V1790

In Date: 03/09/2006
Close Date: 03/16/2006

Meter Reading:

Problem?
SMALL AMBER LIGHT UNDER DRIVER DOOR INOP, RE-45

Task performed:

	<u>Parts</u>	<u>Quantity</u>
NO PARTS USED		

Vendor?: CENT0002

Workorder: V1663

In Date: 02/28/2006
Close Date: 03/27/2006

Meter Reading:

Problem?
SOFT SUCTION HOSE WRAPPED AROUND REAR WHEEL, RE-45

Task performed:

	<u>Parts</u>	<u>Quantity</u>
NO PARTS USED		



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V1682

In Date: 03/01/2006

Meter Reading: 21,453.00

Close Date: 03/29/2006

Problem?

R/REAR DISCHARGE INOP, RE-45

Task performed:

Parts	Quantity
038-1010-01HALE RELIEF VALVE W/ VULCANIZED SEAT	1
038-1550-00VALVE CHECK HALE 1/4"	1
107796DRYER KIT AD9 -NEW	1
108-12FBEADED CHAIN W/CONN 12	3
180R002HURST HYD. FLUID QT	1
29526898 29548988 TRANS FILTER ALLISON	1
5460990500GASKET SEAL KIT P25/30	1
67BULB 12 VOLT	1
6806970098SEAL DOOR	2
7300000050VALVE SS 3IN NEW # 830-0000-00-50	1
78R536078R5360M 2PK FILTER AIR COND	1
A1834388002MOLD L/H	2
A1834388003MOLD R/H	1
CA8193AIR FILTER 46744 WIX	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HP-31DBATTERY 950CCA HP-31D	4
HPH6349AOIL FILTER 51748	2
R90PFILTER FUEL 33231	1

Workorder: V1970

In Date: 03/27/2006

Meter Reading:

Close Date: 03/29/2006

Problem?

FRONT A/C INOP, RE-45

Task performed:

Parts	Quantity
NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V2061

In Date: 03/31/2006
Close Date: 04/03/2006

Meter Reading: 21,797.00

Problem?

DECK GUN AND R/REAR DISCHARGE VALVE NOT CLOSING, RE-45

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V1596

In Date: 02/22/2006
Close Date: 04/10/2006

Meter Reading:

Problem?

DECK GUN LIGHT IS ON RE45

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V2297

In Date: 04/19/2006
Close Date: 04/21/2006

Meter Reading:

Problem?

DECK GUN WILL NOT FLOW WATER, RE-45

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V2538

In Date: 05/09/2006
Close Date: 05/24/2006

Meter Reading:

Problem?

SPOT LIGHT INOP, RE-45

Task performed:

Parts	Quantity
180R002HURST HYD. FLUID QT	3
620122SPOT LIGHT REMOTE	1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V3036

In Date: 06/19/2006 Meter Reading:
Close Date: 06/26/2006

Problem?
DECK GUN VALVE HARD TO OPEN, E-45

Task performed:	Parts	Quantity
	NO PARTS USED	

Workorder: V3186

In Date: 06/27/2006 Meter Reading:
Close Date: 06/30/2006

Problem?
LEFT DOOR LATCH 10-7 E 45

Task performed:	Parts	Quantity
	18-29935-001RH DOOR LATCH NEW	4

Workorder: V3254

In Date: 07/01/2006 Meter Reading:
Close Date: 07/07/2006

Problem?
Crosslay #1 did not charge. Trouble shooting by D/O found only the "OK to pump" light on. Sequence was begun again at which time the pump engaged and the crosslay was charged. Worked fine before and after. E45

Task performed:	Parts	Quantity
	NO PARTS USED	

Workorder: V3422

In Date: 07/12/2006 Meter Reading:
Close Date: 07/14/2006

Problem?
DECK GUN HANDLE BROKEN E45

Task performed:	Parts	Quantity
	RC-4101 AKRON SHORT HANDLED VALVE REMOTE	1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V3586

In Date: 07/21/2006
Close Date: 07/27/2006

Meter Reading:

Problem?

miv light bulb lense on the close indicator need to be replace. E45

Task performed:

Parts	Quantity
200-0540-03200-0540-15-0 LIGHT YELLOW/HALE	1
200054013LENS RED	1
200054014LENS GREEN	1

Workorder: V3637

In Date: 07/26/2006
Close Date: 07/27/2006

Meter Reading:

Problem?

ON CALL PRIMER LEAKING E45

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V3623

In Date: 07/25/2006
Close Date: 07/31/2006

Meter Reading:

Problem?

repair and aim headlights re45

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V3695

In Date: 07/31/2006
Close Date: 08/04/2006

Meter Reading:

Problem?

HEADLIGHT OUT E 45 ON CALL

Task performed:

Parts	Quantity
H6054USE CV TYPE SEALED BEAM	2



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V3948

In Date: 08/16/2006 Meter Reading:
Close Date: 08/17/2006

Problem?
ON CALL PRIMER LEAKING WATER RE45

Task performed:	<u>Parts</u>	<u>Quantity</u>
	NO PARTS USED	

Workorder: V3949

In Date: 08/16/2006 Meter Reading:
Close Date: 08/21/2006

Problem?
REPAIR PRIMER VALVES RE45

Task performed:	<u>Parts</u>	<u>Quantity</u>
	538028052VALVE PRIMER PUMP W/HARDWARE	2

Workorder: V3950

In Date: 08/16/2006 Meter Reading:
Close Date: 08/21/2006

Problem?
PRIMER VALVE NEEDS REPAIR E-45

Task performed:	<u>Parts</u>	<u>Quantity</u>
	NO PARTS USED	

Workorder: V4038

In Date: 08/21/2006 Meter Reading:
Close Date: 08/24/2006

Problem?
Circular Saw on RE45 (asset #D6299) will not start. Have tried new fuel without success.

Task performed:	<u>Parts</u>	<u>Quantity</u>
	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V4090

In Date: 08/23/2006 Meter Reading:
Close Date: 09/08/2006

Problem?
REPLACE TIRES AT STA 46 CALLAGHAN TIRE

Task performed:	<u>Parts</u>	<u>Quantity</u>
	NO PARTS USED	

Vendor?: VC-15214

Workorder: V4303

In Date: 09/07/2006 Meter Reading: 15,984.00
Close Date: 09/08/2006

Problem?
ON CALL DECK GUN LT ON RE45

Task performed:	<u>Parts</u>	<u>Quantity</u>
	NO PARTS USED	

Workorder: V4390

In Date: 09/11/2006 Meter Reading: 26,680.00
Close Date: 09/25/2006

Problem?
foam system not functioning, quartz light needs height adjustment due to alarm sounding when in the full down position. RE45

Task performed:	<u>Parts</u>	<u>Quantity</u>
1. ADJUST SWITCH HIEGHT FOR QUARTS LIGHTS.	NO PARTS USED	

Workorder: V4862

In Date: 10/11/2006 Meter Reading: 2,656.00
Close Date: 11/07/2006

Problem?
- Deck Gun valve very difficult to close. - Rear red reflector (left side) broken. Possibly from contact with hose coupling during DO test today.

Task performed:	<u>Parts</u>	<u>Quantity</u>
1. repair deck gun valve 2. replace reflector left rear	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V5352

In Date: 11/11/2006 **Meter Reading:** 28,189.00
Close Date: 11/14/2006

Problem?
 Pump panel lights and air horn button not working. Quartz telelights not working. E45

Task performed:	<u>Parts</u>	<u>Quantity</u>
1. repair disconnected wire that powers horn button, panel light, and quartz lights	NO PARTS USED	

Workorder: V5353

In Date: 11/11/2006 **Meter Reading:** 2,701.90
Close Date: 11/14/2006

Problem?
 Upon morning inspection, the officer's side outer dual rear tire was at 70 psi compared to the driver's side outer rear tire at 110 psi. Only an additional 18 psi was able to be added to the low tire. E45

Task performed:	<u>Parts</u>	<u>Quantity</u>
1. fill low tire	NO PARTS USED	

Workorder: V5308

In Date: 11/08/2006 **Meter Reading:** 28,189.00
Close Date: 11/20/2006

Problem?
 REPLACE HOSE BED COVER CENTRAL AUTO TRIM

Task performed:	<u>Parts</u>	<u>Quantity</u>
1. replace hose bed cover	NO PARTS USED	

Vendor?: CENTRAL AUTO TRIM



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V5175

In Date: 10/31/2006

Meter Reading: 28,189.00

Close Date: 11/22/2006

Problem?

B INSPECTION AND REPAIRS AS NEEDED E45

Task performed:

1. PERFORM PM "B" INSPECTION.
2. REPLACED PINION SEAL.
3. SERVICED "T" CASE.
4. COOLING SYSTEM.
5. SERVICE DIFF.
6. REMOVED BOTH SEATS FOR UPHULSTRY REPAIR. REINSTALLED SEATS AFTER REPAIRS.
7. REPLACED BROKEN EXHAUST HANGER CLAMP, RELOCATED TRANS COOLER HOSES & REPLACED CLAM/ HANGER. HOSE WERE HANGING DOWN TOO LOW. ADJUST UPPER RADIATOR HOSE AWAY FROM A/C BELT.
8. DISASSEMBLE FRT. HUBS TO CLEAN OUT WATER CONTAMINATION. INSTALL NEW SEAL & REASSEMBLE.
9. REPLACED REAR A/C FILTER, REPLACED T/S SIDE LENSES, REPLACED REAR FLAG, STICKERS. REPLACED 3 A/C DEFUSER VENTS, REPLACED WIPER BLADES, PAINTED FUEL CAPS.
10. REPLACED REFLECTOR ON REAR BUMPER, REPLACED L/S STROBE AT STEP.
11. SERVICED HURST TOOLS, REPLACED L/S STROBE AT STEP.
12. SERVICED HURST TOOLS, REPALCED 4 HOSES ON RAMS.
13. SERVICED GENERATOR.
14. REPLACED DECK GUN VALVE, REPLACED DECK GUN LEVER.
15. REPLACED CONTROL HEAD FOR FOAM SYSTEM
16. TIGHTEN ALL COMP DOOR HOLD OPENS.
17. REPLACED PASS, FRT SEAT BELT.
18. REPLACE ALL 4 DOOR TRIMS & WEATHERSTRIPS.
19. TROUBLE SHOOT TANK VISION LIGHT PROBLEM, TRACED PROBLEM TO REMOVE LIGHT DRIVER. ORDERED NEW REMOTE LIGHT DRIVER.
20. FABRICATE COVER FOR NODE IN PUMP COMPARTMENT.
21. REPAIR RPM COUNTER.
22. TESTED FOAM SYSTEM AT HYDRANT AND FILLED TRUCK.
23. CLEAN SHOP.

Parts	Quantity
0100080010STRAINER	1
048009000SPEEDCOUNTER PUMP PANEL	1
168-0380-51USE 168-0380-56-0 OLD CONTROL UNIT HALE	1
17211-2L8-02330-347 HURST UNITS 06 HONDA	1
3530016HOSE HURST 16 ORANGE	2
353R023HURST HOSE W/O SWIVEL	4
35799FLAT CLAMP 4 IN	1
370001ASEAL 35066	2
50R03ZRRLIGHT 500 TIR LED	1
52-24WIPER BLADES ANCO 24	2
6.5-70-18XSTRAP U-JOINT	1
61516001HANDLE FOR RC4 VALVE	1
680-10LAMERICAN FLAG W UV CLEAR LEFT	1
680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
6806970098SEAL DOOR	2
6808300074VENT A/C LH	1
6808300174VENT A/C RH	3
73000000050VALVE SS 3IN NEW # 830-0000-00-50	1
7460967AIR FILTER 17210-ZE2-515 HONDA	1
78R536078R5360M 2PK FILTER AIR COND	1
91513AMBER LENS	2
98032R 41032-3 RED REFLECTOR OVAL REFLECTOR	1
A1205Q2591OIL SEAL PINION A11205A2731 NEW #	1
A1834388002MOLD L/H	2
A1834388003MOLD R/H	2
BPR5ESSPARK PLUG 7734	1
CA8193AIR FILTER 46744 WIX	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
HU024AHUB COVER	2
IMMF11358SEAT BELTS	1
IOA200A00DISPLAY MODULE REBUILD ONLY SEND IN	1
J19LMUSE 1147 NGK SPARK PLUG	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V5387

In Date: 11/14/2006 Meter Reading: 28,189.00
Close Date: 11/27/2006

Problem?
replace module for w l gauge re45

Task performed:	Parts	Quantity
1. REPLACE WATER LEVEL MODULE	352090021FRC LEVEL DRIVER	1

Workorder: V5431

In Date: 11/17/2006 Meter Reading: 28,542.00
Close Date: 11/27/2006

Problem?
flat repair at st 45 re45

Task performed:	Parts	Quantity
1. REPAIR FLAT ON RE 45	NO PARTS USED	

Vendor?: CALLAGHAN TIRE

Workorder: V5639

In Date: 12/02/2006 Meter Reading: 2,778.00
Close Date: 12/06/2006

Problem?
re45 officer's side footwell panel snapped off with missing connectors. Electrical components exposed to foot traffic.

Task performed:	Parts	Quantity
1. TRAVELED TO STN 45. FOUND FOOTWELL COVER INPLACE.	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V5765

In Date: 12/11/2006 Meter Reading: 28,944.00
Close Date: 12/12/2006

Problem?
OFFICER SIDE TOP REAR LIGHT BAR BROKEN OFF DUE TO HITTING TREE BRANCH, E-45

Task performed:	Parts	Quantity
replace light bar bracket r/rear, coolant leak, fitting loose on coolant line on left side of block next to fuel filter, tighten fitting. noise from rear of truck found rear leaf springs dry on slide bracket.	372000082CHROME MARKER LIGHT MOUNT	1
	372000083GASKET MOUNTING	1
	372000084MARKER LIGHT	1
	372000085HARNES FOR MARKER LIGHT	1
	39377593937759 OIL CAP	1
	C10745SHORT LIGHT STANCHION	1
	NI PLATEMARKER LIGHT MOUNTING PLATE	1
	SWT3100TRANSDUCER OXY TANK	1

Workorder: V5939

In Date: 12/23/2006 Meter Reading: 2,787.00
Close Date: 12/29/2006

Problem?
when transferring from N to D, the transmission jumps into gear. RE45

Task performed:	Parts	Quantity
1. Found no problem with trans	NO PARTS USED	

Workorder: V6129

In Date: 01/07/2007 Meter Reading: 29,695.00
Close Date: 01/09/2007

Problem?
Deck gun valve leaking large amounts of water. Hareware seems to be loose. E-45

Task performed:	Parts	Quantity
1. Removed deck gun valve and installed new o-rings. Reinstalled and tested ok	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V6360

In Date: 01/19/2007 Meter Reading: 29,906.00

Close Date: 01/23/2007

Problem?

repair saw re45

Task performed:

Parts

Quantity

1. TRAVELED TO STN 45 TO PICK UP SAW FOR REPAIRS. LT SAYS SAW WAS PICKED UP ALREADT AND BROUGHT TO SHOP FOR REPAIRS.

NO PARTS USED

Workorder: V6488

In Date: 01/26/2007 Meter Reading: 30,143.00

Close Date: 02/01/2007

Problem?

REPAIR K 12 SAW RE45 REGANS SMALL EQUIP

Task performed:

Parts

Quantity

Repair K12 saw Regans Small Engine

NO PARTS USED

Vendor?: REGANS SMALL ENGINE

Workorder: V6501

In Date: 01/27/2007 Meter Reading: 2,927.00

Close Date: 02/01/2007

Problem?

front a/c not blowing cold... E-45

Task performed:

Parts

Quantity

1. Found no problem with a/c
2. Horn button inop repaired horn button

NO PARTS USED

Workorder: V6805

In Date: 02/17/2007 Meter Reading: 2,927.00

Close Date: 02/26/2007

Problem?

deck gun valve extremely difficult to open and close... E-45

Task performed:

Parts

Quantity

TEST VALVE - NO PROBLEM FOUND

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V6819

In Date: 02/18/2007 Meter Reading: 2,927.00
 Close Date: 02/26/2007

Problem?
 A/C temp. control nob/cable not switching from Cold to Heat. R45

Task performed:	Parts	Quantity
FOUND NO PROBLEM WITH CABLE	NO PARTS USED	

Workorder: V7138

In Date: 03/09/2007 Meter Reading:
 Close Date: 03/19/2007

Problem?
 Deck Gun valve on E45 is very stiff. This is the 2nd time writing this up that I am aware of. Can it be loosened, greased or replaced? Thank You!

Task performed:	Parts	Quantity
Adjusted linkage for valve and tested ok	NO PARTS USED	

Workorder: V7484

In Date: 04/02/2007 Meter Reading: 32,380.00
 Close Date: 04/09/2007

Problem?
 REPAIR K12 SAW RE45

Task performed:	Parts	Quantity
Repaired K12 saw E45	NO PARTS USED	

Vendor?: REGANS SMALL ENGINE

Workorder: V7713

In Date: 04/16/2007 Meter Reading: 3,229.00
 Close Date: 04/25/2007

Problem?
 Both telescope lights, panel lights and pressure relief valve lights not working. Extended Gun lights also flashing and buzzing when parking brake released and the deck gun in not extended. E45

Task performed:	Parts	Quantity
Reprogrammed node #2 & tested.	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V7793

In Date: 04/18/2007 Meter Reading: 3,229.00
Close Date: 04/30/2007

Problem?

air leak low air alarm upon morning check out. e45

Task performed:

Chkd for air leaks; let sit for 1.45 min & did not move

Parts

NO PARTS USED

Quantity

Workorder: V7898

In Date: 04/24/2007 Meter Reading: 3,252.00
Close Date: 05/02/2007

Problem?

Map light not working. E45

Task performed:

Repaired map light

Parts

NO PARTS USED

Quantity

Workorder: V7954

In Date: 04/27/2007 Meter Reading: 3,252.00
Close Date: 05/03/2007

Problem?

Map light not working, needs to be fixed. e45

Task performed:

Repaired bad connection

Parts

LF18TS-LED MAP LIGHT LED 18 IN

Quantity

1

Workorder: V7857

In Date: 04/22/2007 Meter Reading: 3,246.00
Close Date: 05/04/2007

Problem?

air leak low air alarm post engine 45 sitting for more than a couple of hours...

Task performed:

Reboot pump shifter
Replc solenoid for scene lights

Parts

24117SOLENOID INS CONT DUTY

5460370530VPS SHIFT KIT 546-0370-53-0

Quantity

1

1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V8367

In Date: 05/22/2007 Meter Reading: 33,691.00
Close Date: 06/01/2007

Problem?

sharpen vent saw blades e45 regans

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: REGANS MOBILE SMALL

Workorder: V8477

In Date: 05/30/2007 Meter Reading: 33,835.00
Close Date: 06/05/2007

Problem?

COMP DOOR INOP SIREN INOP E45

Task performed:

Parts

Quantity

1. Replace siren button on steering wheel
2. Repair rear door latch
3. Checked problem with master pump guage, found bad connection on sloenoid

NO PARTS USED

Workorder: V8561

In Date: 06/04/2007 Meter Reading: 33,835.00
Close Date: 06/14/2007

Problem?

AIR LEAKS RE45

Task performed:

Parts

Quantity

1. Traced out air leaks and repaired where needed
2. Checked out problem with relief valve, removed screen and cleaned and tested

NO PARTS USED

Workorder: V8648

In Date: 06/07/2007 Meter Reading: 3,335.70
Close Date: 06/19/2007

Problem?

Digital display for pump discharge/intake is out (up in the pump panel).E45

Task performed:

Parts

Quantity

1. Repaired radio mount in dash
2. Deck gun leaking. Adjusted deck gun linkage
3. Foam leak at filter. Repaired leak

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V8891

In Date: 06/18/2007 Meter Reading: 3,390.00
Close Date: 06/29/2007

Problem?

Deck and panel lights aren't working. e45

Task performed:

Parts

Quantity

1. Traced out problem with light. Did not get lights to shut off

NO PARTS USED

Workorder: V9090

In Date: 07/02/2007 Meter Reading: 34,727.00
Close Date: 07/06/2007

Problem?

AIR LEAK, RADIO INOP, K-12 SAW, RE-45

Task performed:

Parts

Quantity

1. Traced out air leak. Found parking brake valve leaking. Removed & replaced
2. Ran k-12 saw found unit needs belt, sent to shop
3. Rebuilt master drain valve
4. Repaired am/fm radio/ found bad ground in wiring

0467020000VALVE SEAT DRAIN

1

104967DIAPHRAM FOR 6 PORT DUMP VALVE

1

800034VALVE PARKING BRK.

1

Workorder: V9141

In Date: 07/05/2007 Meter Reading: 3,439.90
Close Date: 07/06/2007

Problem?

truck will need tires soon E-45

Task performed:

Parts

Quantity

1. Will monitor tire

NO PARTS USED

Workorder: V9198

In Date: 07/07/2007 Meter Reading: 3,445.00
Close Date: 07/18/2007

Problem?

Master Intake / Discharge guage not working properly. E45

Task performed:

Parts

Quantity

1. RAN PUMP AND CHECKED OPERATION OF GAUGE AND TESTED- OK.
2. TURN SIGNALS INOP-FOUND BAD CONNECTION AT RELAY BOARD REPAIRED AND TESTED.

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V9203

In Date: 07/07/2007 Meter Reading: 3,445.00
Close Date: 07/18/2007

Problem?
Water found on front floor board on lietenant side. E-45

Task performed:	Parts	Quantity
1. WATER ON FLOOR OF CAB- RAN A/C AND FOUND UNIT DRAINING TO GROUND.	FSC17491907NO SWITCH LOW AIR PRESSURE	1
	FSC17492134NC SW PARK BK SPADE TYPE CONNECTOR	1

Workorder: V9225

In Date: 07/09/2007 Meter Reading: 34,940.00
Close Date: 07/19/2007

Problem?
repair k-1200 saw E45 (outside agency-regan's small engine service)

Task performed:	Parts	Quantity
REPAIR K-1200 SAW FOR E45. (REGAN'S SMALL ENGINE SVC)	NO PARTS USED	
REPLACE WORN BELT. REPLACE MISSING BOLT AND SPACER.		
Vendor?: REGAN'S SMALL ENG.		

Workorder: V9728

In Date: 08/04/2007 Meter Reading: 3,507.00
Close Date: 08/09/2007

Problem?
Spot light on E45 on / off button popped off and need to be replaced. e45

Task performed:	Parts	Quantity
replaced spot light controller	NO PARTS USED	

Workorder: V9839

In Date: 08/12/2007 Meter Reading: 3,527.90
Close Date: 08/30/2007

Problem?
The deck gun valve is not opening all the way. This was a previous problem and was fixed by Tommy awhile ago. E45

Task performed:	Parts	Quantity
Chkd valve; fnd valve opening all the way	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V9926

In Date: 08/14/2007 Meter Reading: 35,895.00
Close Date: 08/31/2007

Problem?
repair oil cap on generator e45

Task performed:	Parts	Quantity
Installed oil cap for generator	EG-3500OIL CAP HONDA	1

Workorder: V10020

In Date: 08/21/2007 Meter Reading: 36,127.00
Close Date: 09/05/2007

Problem?
DECK GUN VALVE BROKEN RE45

Task performed:	Parts	Quantity
1. installed new deck gun handle	7300000050VALVE SS 3IN NEW # 830-0000-00-50	1
2. Chk cab A/C; recharge system	RC-4101 AKRON SHORT HANDLED VALVE REMOTE	1

Workorder: V10022

In Date: 08/21/2007 Meter Reading: 3,562.00
Close Date: 09/05/2007

Problem?
Replaced right headlight on the engine. Need to replace the spare that was used.E45

Task performed:	Parts	Quantity
Dropped off spare headlights	NO PARTS USED	

Workorder: V10142

In Date: 08/27/2007 Meter Reading: 3,562.00
Close Date: 09/07/2007

Problem?
When reaching speeds of 40 mph and above and attempting to stop the truck pulls extremely hard to the left. This is a nwe proble for this engine. re45

Task performed:	Parts	Quantity
Travel Chkd frt end; fnd loose spring hanger bolts; tightened; road test; pulls to left; chk brakes; adj frt/rear brakes; still pulls; to be brought to shop	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V9688

In Date: 08/02/2007

Meter Reading: 35,524.00

Close Date: 09/10/2007

Problem?

REPLACE ALL 6 TIRES AT STATION 45 E45 CALLAGHAN ENT

Task performed:

Parts

Quantity

Replace all (6) tires - Callaghan

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V10052

In Date: 08/22/2007

Meter Reading: 3,562.00

Close Date: 09/11/2007

Problem?

2 clearance lights out on cab of engine E45

Task performed:

Parts

Quantity

1. Installed (2) bulbs in marker lights
2. Hurst unit inop; clnd carb & rep float

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V10153

In Date: 08/28/2007

Meter Reading: 36,127.00

Close Date: 09/13/2007

Problem?

b inspection and repairs as needed e45

Task performed:

- B-Inspection
- 2. Svc/tested Hurst tools; rep hoses & sapre plug
- 3. Svc small engines
- 4. Svc air dryer
- 5. svc T-Case
- 6.Svc high water breather
- 7. Unloaded trailers at shop
- 8. Torqued U-bolts
- 9. Svc power steering
- 10. Assist finding parts
- 11. vcn/holiday
- 12. Replc intake screens
- 13. Rem frt wheels; replc brake hardware kits & reinstalled wheels
- 14. Adj linkage to treadle valve
- 15. Sec spring hanger bolts
- 16. Sec exhaust bracket
- 17. Rep all belts
- 18. Adj valve linkage & replc check valve; revac tested & passed-ok
- 19. Replc retader switch
- 20. Rem knob from traffic advisor
- 21. Replc door seals & molds
- 22. Replc A/C filter
- 23. Replc officers seat belt
- 24. Replc compt door holdopns
- 25. Rep lights as needed
- 26. Moved all eqmt in (2) rear compts from side to side Hurst stuff on RT-gen on left
- 27. Replc R-R discharge valve from Hale to Akron; replumb & adj as needed
- 28. Replc R/R seat belt

Parts	Quantity
0100030000SCREEN 6 IN	1
038-1550-00VALVE CHECK HALE 1/4"	1
05-17223-000CAP RADIATOR 10 LB	1
0769027STRAINER 2.5 IN	1
101111019SLO-CLOZ 7675 AKRON	1
101281011GSS6297UM 60# DOOR STRUT QUINT	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
1160033 IN FLANGE ADPT W/ HOLES P2S	1
1212BTURTLE TILE 12X12 BLACK	8
16302RETAINER CLIP	4
17211-ZE7-W03HONDA AIR FILTER	1
35200-RLIGHT MARKER LED RED	1
35200-YLIGHT MARKER LEDAMBER	2
372000084MARKER LIGHT	1
5462300020VALVE KIT SS VALVE 3 IN	1
6806970098SEAL DOOR	1
7001-30ESEAL	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
883088301201 3 IN SLO-CLOZ W/R1 HANDLE	1
9440BELT	1
9480BELT	1
A1834388002MOLD L/H	2
A1834388003MOLD R/H	2
A2241425020SW ROCKER RETARDER	1
BPR5ESSPARK PLUG 7734	2
EAA-8350-60UGSS6557UP STRUT-LIFT	8
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
FREIGHTSHIPPING CHARGES	1
IMMF11358SEAT BELTS	1
IMMF13238SEAT BELT	1
K080716BELT	1
KIT8081BK SPRING KIT	2



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V10181

In Date: 08/30/2007 Meter Reading: 36,127.00
 Close Date: 09/18/2007

Problem?

replace hose bed cover central auto trim e45

Task performed:	Parts	Quantity
Replace hose bed cover - Central Auto Trim	NO PARTS USED	

Vendor?: CENTRAL AUTO

Workorder: V10692

In Date: 09/26/2007 Meter Reading: 36,400.00
 Close Date: 09/27/2007

Problem?

Noise under truck by transmission E45 (on-call)

Task performed:	Parts	Quantity
Travel Stn45; fnd loose exhaust clamp; tightened clamp	NO PARTS USED	

Workorder: V5176

In Date: 10/31/2006 Meter Reading: 28,189.00
 Close Date: 10/15/2007

Problem?

REPAIR SEATS AT CENTRAL AUTO TRIM E45

Task performed:	Parts	Quantity
RECOVER SEATS	NO PARTS USED	

Vendor?: CENTRAL AUTO TRIM

Workorder: V8062

In Date: 05/02/2007 Meter Reading: 3,264.00
 Close Date: 10/15/2007

Problem?

Driver's compartment on E45 the cradle for the sledge hammer fell off and the screw holes are stripped so unable to put back on.

Task performed:	Parts	Quantity
Mounted bracket	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V9624

In Date: 07/30/2007
Close Date: 10/15/2007

Meter Reading: 3,487.00

Problem?

ALL tires, except for the RIGHT-FRONT tire, seem to be worn out. Also seems to need alignment. Spoke to Ed in the morning of 7/30/07 regarding issue. E45

Task performed:

all six tires need replaced

Parts

NO PARTS USED

Quantity

Workorder: V10931

In Date: 10/10/2007
Close Date: 10/22/2007

Meter Reading: 3,612.00

Problem?

Relieve Valve light not coming ON. Light bulb was checked and seems to be OK. E-45

Task performed:

1. repaired bad connection on switch for relief valve light.
2. deck gun valve leaking. replaced valve.
3. traced out problem - losing lights when pulling primer. found bad ground.

Parts

73000000050VALVE SS 3IN NEW # 830-0000-00-50

1

Quantity

Workorder: V11021

In Date: 10/14/2007
Close Date: 10/23/2007

Meter Reading: 3,646.00

Problem?

On officer side, right intake bleeder knob broken. Unable to bleed water. Threads on knob are stripped E-45

Task performed:

1. replaced knob on right side of pump panel

Parts

NO PARTS USED

Quantity

Workorder: V11154

In Date: 10/22/2007
Close Date: 10/25/2007

Meter Reading: 3,665.00

Problem?

e45 spot light not turning.

Task performed:

1. search light not turning. remote defective. r/r remote.

Parts

NO PARTS USED

Quantity



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V11252

In Date: 10/26/2007 Meter Reading: 37,320.00
Close Date: 11/06/2007

Problem?
pump master gauge 10-7 e45

Task performed:	Parts	Quantity
1. Rem gauge & installed new one	IOA200A00DISPLAY MODULE REBUILD ONLY SEND IN	1

Workorder: V11465

In Date: 11/06/2007 Meter Reading: 3,672.00
Close Date: 11/14/2007

Problem?
needs coolant E-45

Task performed:	Parts	Quantity
1. dropped off coolant	NO PARTS USED	
2. checked for foam leak found filter leaking repaired		

Workorder: V11741

In Date: 11/25/2007 Meter Reading: 3,745.00
Close Date: 12/06/2007

Problem?
On board Hale foam system not working properly. It will turn on for a little bit and then automatically shut off. Says No Pri when the system shuts off. E45

Task performed:	Parts	Quantity
1. Installed new Hale Foam display and calabrated.	200-2481-00-0546-3240-00-0 FOAM PUMP SENSOR KIT	1

Workorder: V12119

In Date: 12/18/2007 Meter Reading: 3,811.10
Close Date: 12/21/2007

Problem?
horn siren is getting stuck and wont activate / silence in a timely manner upon tapping the horn. E-45

Task performed:	Parts	Quantity
1. Repaired horn siren switch that had bad connection.	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V12181

In Date: 12/20/2007 Meter Reading: 3,811.10
 Close Date: 01/04/2008

Problem?
 Engine 45 have water leaking from tank.

Task performed:	<u>Parts</u>	<u>Quantity</u>
1. Will monator water leak until comes to shop.	NO PARTS USED	

Workorder: V8938

In Date: 06/21/2007 Meter Reading: 3,404.00
 Close Date: 01/14/2008

Problem?
 D6299 K-12 SAW BELT NOT WORKING WHEN BLADE APPLIED TO CURRING SURFACE BLADE STOPS SPINNING... E45

Task performed:	<u>Parts</u>	<u>Quantity</u>
	NO PARTS USED	

Workorder: V3636

In Date: 07/25/2006 Meter Reading:
 Close Date: 02/07/2008

Problem?
 FIX MINOR LEAK UNDERNEATH VEHICLE.E45

Task performed:	<u>Parts</u>	<u>Quantity</u>
	NO PARTS USED	

Workorder: V4164

In Date: 08/29/2006 Meter Reading:
 Close Date: 02/07/2008

Problem?
 foam system electronics won't function E45

Task performed:	<u>Parts</u>	<u>Quantity</u>
	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V4226

In Date: 09/03/2006 Meter Reading:
Close Date: 02/07/2008

Problem?
HALE FOAM DISPLAY NOT TURNING ON E45

Task performed:	Parts	Quantity
	168-0380-51USE 168-0380-56-0 OLD CONTROL UNIT HALE	1
	73000000050VALVE SS 3IN NEW # 830-0000-00-50	1

Workorder: V5114

In Date: 10/26/2006 Meter Reading: 28,189.00
Close Date: 02/07/2008

Problem?
headlight on driver side needs adjustment. re45

Task performed:	Parts	Quantity
	NO PARTS USED	

Workorder: V9752

In Date: 08/07/2007 Meter Reading: 3,507.00
Close Date: 02/07/2008

Problem?
Small connector cable on the back of the Circle D light is missing a prong on it.

Task performed:	Parts	Quantity
	NO PARTS USED	

Workorder: V12773

In Date: 01/23/2008 Meter Reading: 3,898.00
Close Date: 02/08/2008

Problem?
Marker light on front passenger side broken. Needs replacement lens. r45

Task performed:	Parts	Quantity
1. Replaced LED light that was broken	50R03ZCRLIGHT LED RED TIR 6	1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V13010

In Date: 02/03/2008 Meter Reading: 3,919.00

Close Date: 02/08/2008

Problem?

safety bar on officers side of walk through bolts loose... ra E45

Task performed:

- | | Parts | Quantity |
|------------------------------------------------------------|----------------------------|----------|
| 1. tightened bolts on safety bar and dropped off Hurst oil | 180R002HURST HYD. FLUID QT | 4 |

Workorder: V13198

In Date: 02/12/2008 Meter Reading: 3,944.00

Close Date: 02/13/2008

Problem?

Seat belts do not retract. E-45

Task performed:

- | | Parts | Quantity |
|-------------------------------------------------|---------------|----------|
| 1. checked out seatbelts and all checked out OK | NO PARTS USED | |

Workorder: V13309

In Date: 02/17/2008 Meter Reading: 3,944.00

Close Date: 02/20/2008

Problem?

Emergency lights occasionally do not shut off. E45 must be shut down with battery switch off to resolve problem. Also, the left rear turn signal does not work when the hazards are on.

Task performed:

- | | Parts | Quantity |
|--------------------------------------------------------------|---------------|----------|
| 1. Checked all connections and found no problem with lights. | NO PARTS USED | |
| 2. Adjusted rear Cab door latches that were hard to open | | |

Workorder: V13318

In Date: 02/18/2008 Meter Reading: 40,397.00

Close Date: 02/20/2008

Problem?

front light bar initially did not come on with first check in am shut down and reset the batteries and lights did work.. 11240 ra E45

Task performed:

- | | Parts | Quantity |
|----------------------------------------------|---------------|----------|
| 1. Found no problem with lights shutting off | NO PARTS USED | |



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V13837

In Date: 03/12/2008
Close Date: 03/13/2008

Meter Reading: 40,859.00

Problem?

on call e45 emergency lts 10-7

Task performed:

Nodes on console showing lights out; fnd water in plugs;
repair j

Parts

DT043PP007DEUTSCH RECEPTACLE

Quantity

1

Workorder: V13840

In Date: 03/12/2008
Close Date: 03/20/2008

Meter Reading: 40,859.00

Problem?

Officer's side SEAT BELT twisted. E-45

Task performed:

1 REPAIRED R SIDE SEAT BELT, THAT WAS TWISTED

Parts

NO PARTS USED

Quantity

Workorder: V13925

In Date: 03/17/2008
Close Date: 03/20/2008

Meter Reading: 41,006.00

Problem?

B INSP AND REPAIRS AS NEEDED E45

Task performed:

- "B" service
- Installed strap on tail board and Footmans loop
- Tighten drive line bolts
- Lube Battery box locks, stuck, would not open. Lube trash line box, stuck and would not open.
- Repair tag light
- Replace red strobe light on lower right side, not flashing
- Replace A/C vet in rear compartment of truck
- Replace all 3 sockets on master intake valve panel.

Parts

- 15W40BSYN OIL BULK QTS
- 200-0540-03200-0540-15-0 LIGHT YELLOW/HALE
- 50R03ZCRLIGHT LED RED TIR 6
- 78R536078R5360M 2PK FILTER AIR COND
- FS1022FILTER FUEL WIX 33422 PS8689 FRAM
- HPH6349AOIL FILTER 51748
- PR338324070 WIX FILTER WATER
- R90PFILTER FUEL 33231
- UMVS254411STRAP 46 IN

Quantity

- 24
- 3
- 1
- 1
- 1
- 1
- 1
- 1
- 1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V14517

In Date: 04/17/2008 Meter Reading: 4,108.50
Close Date: 04/22/2008

Problem?
Rear passenger door not closing properly. Door opening on its own while driving. E-45

Task performed:	Parts	Quantity
Door opening. Removed and replaced door latch and four hinges	18-29935-001RH DOOR LATCH NEW	4

Workorder: V14522

In Date: 04/17/2008 Meter Reading: 41,756.00
Close Date: 04/22/2008

Problem?
BRAKES SMOKING, E-45

Task performed:	Parts	Quantity
1. brakes smoking checked brakes found driver drove truck without return on.	NO PARTS USED	

Workorder: V14603

In Date: 04/21/2008 Meter Reading: 41,756.00
Close Date: 04/23/2008

Problem?
engine driver compartment lock mechanism stuck E45

Task performed:	Parts	Quantity
1. L-1 compartment inoperative. Latch Broken. Installed new latch. Had to open compartment and go to shop for parts,	101280018LATCH ASSY. FOR D-PADDLE HANDLE	1
	14996-02D PADDLE HANDLE	1

Workorder: V14526

In Date: 04/17/2008 Meter Reading: 4,108.50
Close Date: 05/09/2008

Problem?
E45 has a broken strap to hold the hurst jaws. Right rear door not working properly. Also, would like to mount the hose clamp on t outside.

Task performed:	Parts	Quantity
Right rear cab door not closing; rem latch; install new; tested opns of door; tested ok. j	18-29935-001RH DOOR LATCH NEW	1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V14750

In Date: 04/29/2008
Close Date: 05/09/2008

Meter Reading: 4,141.00

Problem?

Right rear door hard to open, it pops. Also large compartment door on R45B spring is broken.

Task performed:

Replc door spring on side door. j

Parts

HLD374211 IN HOLD-OPEN 30LB

Quantity

1

Workorder: V15334

In Date: 05/27/2008
Close Date: 06/05/2008

Meter Reading: 42,751.00

Problem?

STRETCHER LATCH 10-7 R45

Task performed:

1. Adj stretcher latch & lube.
2. Rear scene lights inop; fnd bad connection in rear of lights. j

Parts

NO PARTS USED

Quantity

Workorder: V15213

In Date: 05/20/2008
Close Date: 06/18/2008

Meter Reading: 42,435.00

Problem?

repair ground ladders

Task performed:

1. repair 2 ground ladders replace stops & supports.

Parts

NO PARTS USED

Quantity

Workorder: V15646

In Date: 06/09/2008
Close Date: 06/19/2008

Meter Reading: 4,233.00

Problem?

Right outside rear tire has a screw in it. E-45

Task performed:

Right outside rear tire has a screw in it E45 - Callaghan j

Parts

NO PARTS USED

Quantity

Vendor?: CALLAGHAN



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V15864

In Date: 06/20/2008 Meter Reading: 4,243.00
Close Date: 06/23/2008

Problem?

deck gun valve loose will not completely close e45

Task performed:

	Parts	Quantity
--	-------	----------

6-20 Deck Gun valve inoperable; Hale valve coming apart; closed valve; ordered poart for tommy to replace.

NO PARTS USED

Workorder: V15791

In Date: 06/17/2008 Meter Reading: 43,290.00
Close Date: 06/30/2008

Problem?

REPLACE PRE CONNECT NETS E45

Task performed:

	Parts	Quantity
--	-------	----------

1. Installed new preconnect netting.
2. Mounted tool on side of engine. j

NO PARTS USED

Workorder: V15302

In Date: 05/23/2008 Meter Reading:
Close Date: 07/01/2008

Problem?

E45 needs one rubber mallet. The head broke off the current one during training.E45

Task performed:

	Parts	Quantity
--	-------	----------

DC will get rubber mallet. j

NO PARTS USED

Workorder: V15972

In Date: 06/25/2008 Meter Reading: 4,269.00
Close Date: 07/09/2008

Problem?

Deck gun broken. e45

Task performed:

	Parts	Quantity
--	-------	----------

1. adjusted deck gun valve and tested

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V16078

In Date: 07/01/2008

Meter Reading: 43,563.00

Close Date: 07/10/2008

Problem?

on call e 45 check brakes

Task performed:

On-call; no brakes; adj free play in brake & rep air sender connection & replc second one. j

Parts

Quantity

76577-4-NC76577-4-NC SWITCH

1

FSC17492134NC SW PARK BK SPADE TYPE CONNECTOR

2

Workorder: V15725

In Date: 06/13/2008

Meter Reading: 4,233.00

Close Date: 07/11/2008

Problem?

replace rear tires e 45

Task performed:

replace reat tires E45 - Callaghan j

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V16008

In Date: 06/26/2008

Meter Reading: 43,563.00

Close Date: 07/11/2008

Problem?

MOTOR MOUNT ON HURST POWER UNIT (10155927) BROKEN MOTOR SITTING ON A LEAN. UNABLE TO FIND ASSET NUMBER IN IBEM. e45

Task performed:

1. installed new Hurst feet & motor mounts.
2. Dropped off two Hurst hoses & fuild. j

Parts

Quantity

180R002HURST HYD. FLUID QT

2

3530016HOSE HURST 16 ORANGE

1

353R091USE 353R403 HURST HOSE 16 GREEN

1

377R054FEET - HURST TOOL

1

HR149460107MOUNT VIBRATION (NEWER POWER UNITS

4

Workorder: V16133

In Date: 07/03/2008

Meter Reading: 4,269.00

Close Date: 07/18/2008

Problem?

On board foam not working at all. e45

Task performed:

1. Recalibrated foam gauge & tested.
2. Headlight out; replc headlight. j

Parts

Quantity

H6054USE CV TYPE SEALED BEAM

1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V16230

In Date: 07/08/2008 Meter Reading: 4,249.00
Close Date: 07/18/2008

Problem?

low batteries will not charge with running showing (-) amperage with running and driving... r45

Task performed:

Traced out problem w/truck not charging; fnd (1) bad batry & replc. also fnd bad connection on btry shunt.
j

Parts	Quantity
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
HP-31DBATTERY 950CCA HP-31D	4
S448GAUGE TIRE TREAD DEPTH	1

Workorder: V17546

In Date: 09/07/2008 Meter Reading: 4,394.00
Close Date: 09/29/2008

Problem?

halogen scene light burned out, map light burned out. E-45

Task performed:

Repaired Scene light that was not working.
Rear step lights inoperative, traced and found broken wire.

Parts	Quantity
NO PARTS USED	

Workorder: V17555

In Date: 09/07/2008 Meter Reading: 4,394.00
Close Date: 09/29/2008

Problem?

A/C draining into cab compartment. E-45

Task performed:

Cleaned ac drain and tested.
Rear light not working - repaired broken wire on rear rotator.

Parts	Quantity
NO PARTS USED	

Workorder: V17556

In Date: 09/07/2008 Meter Reading: 4,394.00
Close Date: 09/29/2008

Problem?

Map light not working. E-45

Task performed:

Repaired bad ground in map light.

Parts	Quantity
NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V17879

In Date: 09/23/2008
Close Date: 09/29/2008

Meter Reading: 44,909.00

Problem?

a/c 10-7 r45

Task performed:

replace 1 a/c condenser fan

Parts

Quantity

60027FAN A/C COND 12IN 860026-2-W

1

Workorder: V16363

In Date: 07/14/2008
Close Date: 09/30/2008

Meter Reading: 4,249.00

Problem?

cannot get foam from onboard tank, onboard tank filling with water...11240 E45

Task performed:

1. Replace rear tail board. Replace at B-Insp
 2. Air leak repaired at air horn solenoid.
- (R.T.)

Parts

Quantity

038-1790-00CHECK VALVE INJECTOR HALE FOAM SYS.

1

3320-0027CHECK VALVE 1/2 FOAMPRO

1

352000037SHUNT 300 AMP

1

FREIGHTSHIPPING CHARGES

1

RTBASSYREAR TAIL BRD OUT 91 IN

1

Workorder: V17413

In Date: 08/31/2008
Close Date: 09/30/2008

Meter Reading: 44,909.00

Problem?

AC runs warm after a few minutes. AC hose is clogged on Officer's side. E45

Task performed:

Ran A/C Cleaned AC coils and tested.

Parts

Quantity

NO PARTS USED

Workorder: V17501

In Date: 09/04/2008
Close Date: 09/30/2008

Meter Reading: 4,394.00

Problem?

AC still leaking in the front cab E45

Task performed:

Re-route AC drain and test.

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V17781

In Date: 09/17/2008
Close Date: 09/30/2008

Meter Reading: 4,394.00

Problem?

Water in fuel light is on (10:00 a.m.) E45 needs approx. 1-2 quarts of oil.

Task performed:

R & R water/fuel sender
coolant leak-repaired leak at fitting

Parts

Quantity

RAIRK30880N122WSKL4000 SENSOR WATER IN FUEL

1

Workorder: V17995

In Date: 09/29/2008
Close Date: 10/07/2008

Meter Reading: 45,648.00

Problem?

CHECK ENG LIGHT ON E45

Task performed:

1- installed laptop, checked for codes found/ code cleared.
2- driver air seat inop, removed seat and repaired air line, reinstalled seat

Parts

Quantity

NO PARTS USED

Workorder: V18101

In Date: 10/03/2008
Close Date: 10/15/2008

Meter Reading: 45,648.00

Problem?

1. Air horn switch on pump panel not working. 2. O.K. to pump light bulb is out. e45

Task performed:

1-Air horn/ pump light inop- replaced node 4

Parts

Quantity

600000003NODE HERCULES V-MUX

1

Workorder: V18177

In Date: 10/07/2008
Close Date: 10/15/2008

Meter Reading: 4,465.00

Problem?

both handlights in front light box holders will not hold a charge, will turn on in holder but will not when out of the charger...11240 ra e45

Task performed:

1- Swaped hand lights with spares.

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V18396

In Date: 10/17/2008 Meter Reading: 46,035.00
Close Date: 10/28/2008

Problem?
We need 6" gaskets for the hard suction and adapters. e45

Task performed:	Parts	Quantity
Hurst bracket broken; replc broken bracket on Hurst unit. j	T69-15.5 STRAP FOR TOOL HOLDER	1

Workorder: V18426

In Date: 10/20/2008 Meter Reading: 46,181.00
Close Date: 10/28/2008

Problem?
trans shifts hard e45

Task performed:	Parts	Quantity
Road tested & fast adapted trans; road tested & tested ok. j	NO PARTS USED	

Workorder: V18589

In Date: 10/24/2008 Meter Reading: 46,181.00
Close Date: 10/31/2008

Problem?
a headlight is out on E 45. number on headlight box is h6054

Task performed:	Parts	Quantity
1. Headlight inop; rep bad connection in wire that was shorting out. 2. Foam sys inop; ran foam sys & tested ok. 3. Pump water leak; fnd relief valve leaking; hooked up to hydrant & flushed out valve. j	NO PARTS USED	

Workorder: V18674

In Date: 10/29/2008 Meter Reading: 46,181.00
Close Date: 10/31/2008

Problem?
UNIT PULLS TO RT E45

Task performed:	Parts	Quantity
1. Road tested truck for pulling to the right; will send out to get wheel alignment. 2. headlight inop; FNP with headlight. j	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V18527

In Date: 10/22/2008 Meter Reading: 46,181.00
Close Date: 11/10/2008

Problem?
REPAIR HURST POWER UNIT, AND HURAST RAM 20 E-45 (TEAM EQUIPMENT)

Task performed:	Parts	Quantity
Repair Hurst power unit & ram 20 E45 - Team Equipment j	NO PARTS USED	
Vendor?: TEAM EQUIPMENT		

Workorder: V18877

In Date: 11/05/2008 Meter Reading: 4,543.00
Close Date: 12/01/2008

Problem?
Float-a-strainer broken, needs to be either replaced or welded back together. e45

Task performed:	Parts	Quantity
1. Mount tools; mnted tools in L-1.	5269LPVM-5 SM MOUNT	5
2. BC5 will order new float-a-strainer.		
3. installed new brkt handle for Hurst units. j	54177 TO 4 TRAILER WIRE CONNECTOR	1

Workorder: V18962

In Date: 11/10/2008 Meter Reading: 4,543.00
Close Date: 12/01/2008

Problem?
Need to have float-a-strainer replaced or fixed off E45.

Task performed:	Parts	Quantity
BC4 will order new float-a-strainer. j	NO PARTS USED	

Workorder: V18678

In Date: 10/29/2008 Meter Reading: 46,181.00
Close Date: 12/04/2008

Problem?
FRONT END ALIGNMENT E45 CALLAGHAN

Task performed:	Parts	Quantity
Front end alignment E-45 Callaghan MG	NO PARTS USED	
Vendor?: CALLAGHAN		



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V19647

In Date: 12/09/2008

Meter Reading: 47,084.00

Close Date: 01/07/2009

Problem?

C INSPECTION AND REPAIRS AS NEEDED E 45

Task performed:

- 1. C-Inspection
- 2. t-Case svc.
- 3. Rem/rebuilt hand primer valves.
- 4. Rebuilt discharge valve #4 & retested; pump vac test.
- 5. Rep tele light.
- 6. Replc/rewired rear step.
- 7. Rep aux gen 20AMP svc recep.
- 8. Air dryer svc.
- 9. Rep RPM counter.
- 10. Replcd belts.
- 11. Lifts stopped working; tried to fix; fnd master is bad; tagged out.
- 12. Electrical test.
- 13. Chk for tires under shed; fnd two in ok shape for front use; foreman non-approved; return tires; tire guy will swap tires. j

Parts	Quantity
042-0091-00SPRING PRIMER	2
048009000SPEEDCOUNTER PUMP PANEL	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
15W40BSYN OIL BULK QTS	24
3530016HOSE HURST 16 ORANGE	1
5462290020VALVE KIT SS VALVE 2 1/2 546-2290-02-0	1
800405PURGE VALVE KIT	1
9440BELT	1
9480BELT	1
CA8193AIR FILTER 46744 WIX	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
K080716BELT	1
LB-D30BULB QUARTZ HAL. 12V 150W	1
PR338324070 WIX FILTER WATER	1
PVG-KITORING KIT	2
R90PFILTER FUEL 33231	1

Workorder: V19838

In Date: 12/18/2008

Meter Reading: 47,291.00

Close Date: 01/13/2009

Problem?

replace hose bed cover e45

Task performed:

Replace hose bed co ver E45 - Central Auto Trim j

Parts	Quantity
NO PARTS USED	

Vendor?: CENTRAL AUTO



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V19837

In Date: 12/18/2008
Close Date: 01/15/2009

Meter Reading: 47,291.00

Problem?

replace front tires

Task performed:

Replace front tires - Callaghan j

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V19992

In Date: 12/28/2008
Close Date: 01/27/2009

Meter Reading: 4,629.00

Problem?

deck gun leaking. Deck gun valve needs to be calibrated E45

Task performed:

1- Ran pump and checked deck gun for leaks, found no leaks at this time.

Parts

Quantity

NO PARTS USED

Workorder: V20032

In Date: 12/30/2008
Close Date: 01/27/2009

Meter Reading: 47,488.00

Problem?

GAS FAN ON ENGINE WONT STAY RUNNING. e45

Task performed:

1- gas fan inop, readjusted carb,ran fan and tested.

Parts

Quantity

BCPR5ESSPARK PLUGS 6130

4

Workorder: V20501

In Date: 01/21/2009
Close Date: 01/28/2009

Meter Reading: 4,678.00

Problem?

(No Pr) reading on the Foam System. Unable to pump foam. E-45

Task performed:

1- Testd foam system and tested ok.

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V20853

In Date: 02/03/2009 Meter Reading: 4,733.10
Close Date: 02/11/2009

Problem?

The valve controlling the deck gun is difficult to open. The valve will not completely close if there is pressure in the pump. E45

Task performed:

	Parts	Quantity
--	-------	----------

1- service call to sta-45 ck deckgun valve, found linkage and valve control arm loose. tightened linkage and arm assembly. (hale valve) ck operation ok

NO PARTS USED

Will change deck gun valve to Akron at "B". j

Workorder: V20734

In Date: 01/30/2009 Meter Reading: 4,678.00
Close Date: 02/17/2009

Problem?

Right rear discharge leaking and valve broke off trying to close. Also, on board foam system reading no PR. E45

Task performed:

	Parts	Quantity
--	-------	----------

1. R/R discharge leaking; needs to be rebuilt; out of adj; re built valve & adj.
2. R/R discharge - handle broke; replcd handle.
3. Foam sys inop; filter clogged & out of calibration; cldnd filter & calibrated foam sys. j

RC-4101 AKRON SHORT HANDLED VALVE REMOTE

1

Workorder: V20684

In Date: 01/29/2009 Meter Reading: 4,678.00
Close Date: 02/18/2009

Problem?

Attempted to activate the foam system while flowing water without success at .25% increased to 1%. Flushed the system for four minutes and then attempted again at 3% without any success. E-45

Task performed:

	Parts	Quantity
--	-------	----------

Rep foam sys at south shop. j

NO PARTS USED

Workorder: V20454

In Date: 01/20/2009 Meter Reading: 4,678.00
Close Date: 02/19/2009

Problem?

The backlight for the fuel guage is not working. E-45

Task performed:

	Parts	Quantity
--	-------	----------

Fuel gauge light out; replcd w/new bulb. j

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V20979

In Date: 02/09/2009 Meter Reading: 4,733.10
Close Date: 02/19/2009

Problem?
The cap of the windshield washer reservoir is broken. e45

Task performed:	Parts	Quantity
installed new cap for windshield washer. j	22-40868-000WASHER CAP WPB-FREIGHTLINER	1

Workorder: V20881

In Date: 02/05/2009 Meter Reading: 4,733.10
Close Date: 02/23/2009

Problem?
Inside the cab while driving has a strong smell of deisel fumes. e45

Task performed:	Parts	Quantity
Fuel leak; injector nozzles loose #4,5 & 6; cleared eng; fnd/rep leaks; road tested; all ok. j	NO PARTS USED	

Workorder: V20980

In Date: 02/09/2009 Meter Reading: 4,733.10
Close Date: 02/25/2009

Problem?
The second numeral from the right is not working on the electronic display.e45

Task performed:	Parts	Quantity
Replcd master pump throttle & reprogrammed. j	ELA101-ATHROTTLE EXCEL CUMMINS IS SERIES	1

Workorder: V21259

In Date: 02/22/2009 Meter Reading: 4,733.10
Close Date: 03/06/2009

Problem?
The tire inflator of the engine leaks and can not obtain accurate reading on the air gauge portion. We need a new tire inflator. We need a truck gauge to measure the tire pressure on the rescues for safety. E45

Task performed:	Parts	Quantity
dropped off new tire inflator. j	S986AIR GAUGE 160 PSI	1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V21865

In Date: 03/17/2009 Meter Reading: 49,365.20
Close Date: 03/20/2009

Problem?
CHARGING SYSTEM 10-7 E45

Task performed:	Parts	Quantity
1. Not charging; replcd alt & tested.	15W40QSYN OIL QT	12
2. Need oil; dropped off oil. j	4867JB320 UPGRADE ALTERNATOR	1

Workorder: V21792

In Date: 03/13/2009 Meter Reading: 1,212.10
Close Date: 03/23/2009

Problem?
Missing strobe light cover on the engine hood. (Drivers side). e45

Task performed:	Parts	Quantity
Strobelight broken; replcd strobe light cover & LED light. j	50R03ZCRLIGHT LED RED TIR 6	2

Workorder: V22263

In Date: 04/01/2009 Meter Reading: 1,312.90
Close Date: 04/23/2009

Problem?
A/C condensate leaking into the cab on the driver side while driving. The gas line leading to the left A/C compressor cold and sweating in the engine compartment. e45

Task performed:	Parts	Quantity
Ran A/C chkd for leaks & fnd none. j	NO PARTS USED	

Workorder: V22421

In Date: 04/08/2009 Meter Reading: 1,312.90
Close Date: 05/05/2009

Problem?
E45's chainsaw STIHL MS 290 needs a new spark plug R10 and new air filter.

Task performed:	Parts	Quantity
1. Chain saw inop; rep saw & tested.	NO PARTS USED	
2. Truck not stopping; readj brakes & road tested. j		



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V22641

In Date: 04/19/2009 Meter Reading: 1,359.00
Close Date: 05/05/2009

Problem?

Low beam on the right side headlight is out. Reflector on the left side of the tailboard is broken. Red light lens on the left side of the tailboard is badly scratched. E-45

Task performed:

	Parts	Quantity
Brkn light; rep brkn light in rear & rep tailboard. j	NO PARTS USED	

Workorder: V22802

In Date: 04/25/2009 Meter Reading: 1,366.30
Close Date: 05/05/2009

Problem?

Left front headlight low beam is out. LED water tank right side green one of four bars is out. Need a knob for the Whelen Traffic Advisor E-45

Task performed:

	Parts	Quantity
1. Replcd headlight.	NO PARTS USED	
2. Air leak; traced out air leaks & rep. j		

Workorder: V23271

In Date: 05/14/2009 Meter Reading: 1,413.00
Close Date: 05/21/2009

Problem?

Air horn floor switch began to sound constantly while attending to a patient. Floor around the switch is wet with condensate. Disconnected and removed switch e45

Task performed:

	Parts	Quantity
1. Air horn stuck; water in swith; clnd/dried switch.	NO PARTS USED	
2. Water leak in cab; evap drain-clogged; cleand evap drain; also lcn/dry fuse relay board. j (Murray 5/21/09		
3. Rep bad connection on air horn switch. Torchia 5/22/09 j		

Workorder: V23351

In Date: 05/18/2009 Meter Reading: 51,608.00
Close Date: 05/21/2009

Problem?

repair head lights e45

Task performed:

	Parts	Quantity
Headlight out-replcd bulbs. j	H6054USE CV TYPE SEALED BEAM	2



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V22964

In Date: 05/01/2009 Meter Reading: 1,381.70
Close Date: 05/26/2009

Problem?
Bleeder knob on the right intake is stripped out and will not open the bleeder.E45

Task performed:	Parts	Quantity
Replcd bleeder knob on #2 discharge. j	012-0010-00KNOB DRAIN	1
	3753BRAKE DRUM RUMPER FRONT	2
	KSMA2124703QFRONTBRAKE KIT RUMPER AND 4DR RE	2

Workorder: V23315

In Date: 05/16/2009 Meter Reading: 1,417.20
Close Date: 06/01/2009

Problem?
BELOW RIGHT REARCOMPARTMENT NON FLASHING RUNNING LIGHT ,LED, MOUNTED IN THE MOULDING IS OUT E45

Task performed:	Parts	Quantity
Replaced rear marker light. j	NO PARTS USED	

Workorder: V24025

In Date: 06/12/2009 Meter Reading: 52,184.60
Close Date: 07/01/2009

Problem?
replace spot light assy E45

Task performed:	Parts	Quantity
1. Roof spotlight inop; light asy defective; needs new light asy; installed new light asy.	620122SPOT LIGHT REMOTE	1
2. R/S turn marker inop; + (1) cab marker inop; installed new bulbs. j		

Workorder: V23936

In Date: 06/09/2009 Meter Reading: 1,509.30
Close Date: 07/06/2009

Problem?
right lower yellow clearance LED below right forward cabinet is out e45

Task performed:	Parts	Quantity
rep bad grnd on marker lights. j	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V24048

In Date: 06/13/2009 Meter Reading: 1,478.60
 Close Date: 07/06/2009

Problem?
 The spotlight is out of top of the cab. E45

Task performed:	Parts	Quantity
1. Rep brkn wire for spotlight.	NO PARTS USED	
2. Recalibrated water level gauge. j		

Workorder: V24485

In Date: 07/01/2009 Meter Reading: 52,497.40
 Close Date: 07/08/2009

Problem?
 siren 10-7 e 45

Task performed:	Parts	Quantity
Siren inop; replcd siren speaker. j	SD-210RXSIREN DRIVER SMALL	1

Workorder: V25062

In Date: 07/25/2009 Meter Reading: 1,561.80
 Close Date: 07/28/2009

Problem?
 Pump leaking water from under master drain. E-45

Task performed:	Parts	Quantity
1. rep leak at master drain.	NO PARTS USED	
2. Overheated pump; ran pump & chkd out ok. j		

Workorder: V24472

In Date: 06/30/2009 Meter Reading: 1,500.40
 Close Date: 08/10/2009

Problem?
 On morning check out the speaker light #1 would not light on manual test. Confirmed non function with second person.

Task performed:	Parts	Quantity
(1) speaker inop; wire connection loose @ speaker; rep connection. j	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V25265

In Date: 08/03/2009 Meter Reading: 53,171.00
Close Date: 08/12/2009

Problem?
LOW POWER, NOISE FROM ENG E45

Task performed:

1. Low power eng noise; turbo damaged; travel to breakdown & brought back to shop.
2. Rem turbo; replcd.
3. Rem charge air cooler; need to cln metal & oil out of cooler; reinstalled charge air cooler & road test.
4. Several markers dim; installed new bulbs & asy as needed. j

Parts	Quantity
3883284O-RING AIR INTAKE	1
4955658RXTURBO REPLACES 3800401RX	1
CLEAN AND TESTCOOLER/RADIATOR	4

Workorder: V25047

In Date: 07/24/2009 Meter Reading: 52,966.90
Close Date: 08/24/2009

Problem?
The left lower rear red LED is becoming very dim. E45

Task performed:

- Rep rear light that was dim. rep grnd wire. j

Parts	Quantity
50R03ZCRLIGHT LED RED TIR 6	3

Workorder: V25438

In Date: 08/10/2009 Meter Reading: 53,171.00
Close Date: 08/25/2009

Problem?
replace 4 rear tires E45 (outside agency-tiresoles)

Task performed:

- Replc (4) rear tires E45 - Tiresoles j

Parts	Quantity
NO PARTS USED	

Vendor?: TIRESOLES

Workorder: V25760

In Date: 08/25/2009 Meter Reading: 53,171.00
Close Date: 08/26/2009

Problem?
repair saw regans

Task performed:

- Repair saw - Regans j

Parts	Quantity
NO PARTS USED	

Vendor?: REGANS SMALL ENG



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V25311

In Date: 08/05/2009

Meter Reading: 53,171.00

Close Date: 08/27/2009

Problem?

B INSPECTION E45

Task performed:

- B-Inspection
- 2. L/R emergency LED inop - defective.
- 3. Btry box & trash line boxes hard to open; dirt on tracks/locks; svc btry box & trash line box.
- 4. Rear brakes worn; replc brakes & drums.
- 5. Tank to pump hard to open; needs lube; lubed Hale valve; still won;t opn under pressure.
- 6. Pump panel stp loose; secured step.
- 7. EZ lock inop; rear bumper brkn; replc EZ lock.
- 8. Rear bumper reflectors cracked; replc reflectors.
- 9. Svc T-case.
- 10. Deck gun inop; Hale valve defective; installed Akron valve.
- 11. Exh loose; bolts loose & brkn; rep exh hanger.
- 12. Chk for trans leak; u-joint ____ oily; grease @ rear of trans; chld off mess ok.
- 13. post cable @ starter loose; tightened cable.
- 14. L/R lower marker inop; replcd lamp asy.
- 15. Pulls to the right - tire worn; rotated frnt tires & road tested ok.
- 16. Right headlight out of adj; adj headlight.
- 17. Replc tank to pump valve; won;t open under press; replcd Hale valve with Akron.
- 18. Rear A/C not cooling well; low refrigerant; located leak @ discharge connection; recrimped/recharged.
- 19. Replc worn steering wheel.
- 20. compt door struts loose; nuts loose & missing; rep compt door struts.
- 21. Sledge hammer mnt loose; screws stripped; remounted hammer brkt.
- 22. Hood noise when eng idles; brkt betwn trash line & btry box loose; locate/secured brkt. j

Parts

Quantity

25-358SWITCH COVER	1
29535973ACCUM.KIT	1
35200-RLIGHT MARKER LED RED	1
3576REAR BRAKE DRUMS	2
373-2.5E-Z LOK BRACKET	1
50R03ZCRLIGHT LED RED TIR 6	1
52-24WIPER BLADES ANCO 24	2
6804640001NEW# 3184640001 STEERING WHEEL	1
78308930 AKRON 3 IN VALVE	1
883088301201 3 IN SLO-CLOZ W/R1 HANDLE	1
CA8193AIR FILTER 46744 WIX	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
R90PFILTER FUEL 33231	1
XK3014707QPUSE XK4034707QPM QPLUS BRAKE SHOES	2

Workorder: V25907

In Date: 08/31/2009

Meter Reading: 5,196.00

Close Date: 09/21/2009

Problem?

Move the TIC to where the light box is so it will keep a charge and move the light box somewhere else. e45

Task performed:

Rem TIC charger & belt charger; drilled, mntd & wired both chargers in new locations; ck opn; ck ok; went to Stn53. j

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V26068

In Date: 09/05/2009 Meter Reading: 5,207.60
Close Date: 09/21/2009

Problem?
The bulb of the spotlight is not working. e45

Task performed:	Parts	Quantity
Rear spotlight inop; poor grnd; rep grnd. j	NO PARTS USED	

Workorder: V26069

In Date: 09/05/2009 Meter Reading: 5,207.60
Close Date: 09/29/2009

Problem?
Right rear valve is not fully closing. While setting the pressure relief valve, pressure is building beyond the closed valve. The valve position indicator is fully against the stop of the valve body. e45

Task performed:	Parts	Quantity
1. R/R discharge not fully closing; valve defective; adj valve still leaks; replc valve.	91398907 VALVE KIT 3 IN AKRON	1
2. T-signal cancel inop; cancel pin brkn from steering wheel; ordered new pin. j	PGL/22019CPIN TURN SIGNAL STEERING WHEEL	1

Workorder: V26370

In Date: 09/21/2009 Meter Reading: 5,237.00
Close Date: 10/08/2009

Problem?
Replaced head light on E-45, need spare head light at station for next time.

Task performed:	Parts	Quantity
Left headlight inop; installed new bulb. j	H6054USE CV TYPE SEALED BEAM	2

Workorder: V26754

In Date: 10/08/2009 Meter Reading: 54,361.50
Close Date: 10/21/2009

Problem?
on call anti lock light on at training E45

Task performed:	Parts	Quantity
Drive to HQ; hookup lap top; C/O brakes; clear code frequency high; drive truck - ok. j	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V26329

In Date: 09/18/2009

Meter Reading:

Close Date: 11/06/2009

Problem?

Per john at station 42, E45 needs a new pin to turn off the turn signal. e45

Task performed:

Parts

Quantity

1. Rear taillight inop; fnd bad grnd.
2. Air leak; fnd no leaks. j

NO PARTS USED

Workorder: V26729

In Date: 10/07/2009

Meter Reading: 5,251.60

Close Date: 11/06/2009

Problem?

The spotlight on top of the cab is not functioning during morning check out. E45

Task performed:

Parts

Quantity

1. Rep bad grn on spotlight.
2. Water leak at pump; rep leak at master drain valve. j

NO PARTS USED

Workorder: V26970

In Date: 10/19/2009

Meter Reading: 54,488.30

Close Date: 11/12/2009

Problem?

SPOT LT 10-7 E 45

Task performed:

Parts

Quantity

1. Rep bad grnd on spotlight.
2. Rep water leak in cab. j

NO PARTS USED

Workorder: V27658

In Date: 11/14/2009

Meter Reading: 5,321.20

Close Date: 11/30/2009

Problem?

Foam system is reading no prime after 15-30 seconds of operation. This has happened multiple times in the past. E45

Task performed:

Parts

Quantity

- Foam sys inop; metering wheels sticking; cln out pump body & adj sensor. j

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V27916

In Date: 11/24/2009
Close Date: 12/02/2009

Meter Reading: 55,148.70

Problem?

TURN SIGNALS WONT CANCEL E45

Task performed:

T-signals wont cancel; Pin out frm udner steering wheel; reinstalled pin. j

Parts

Quantity

NO PARTS USED

Workorder: V27333

In Date: 11/02/2009
Close Date: 12/09/2009

Meter Reading: 5,319.00

Problem?

E45 left intake is leaking and the swivel doesn't work on the intake. Makes it difficult to hook up the three inch hose too. We are using adapters in case of a fire.

Task performed:

Rep left side intake swivel.

Parts

Quantity

NO PARTS USED

Workorder: V27462

In Date: 11/06/2009
Close Date: 12/09/2009

Meter Reading: 5,321.20

Problem?

Parking brake handle is leaking air. E45

Task performed:

Replc air brake valve. j

Parts

Quantity

800034VALVE PARKING BRK.

1

Workorder: V28352

In Date: 12/15/2009
Close Date: 12/17/2009

Meter Reading: 55,786.00

Problem?

on call tank leak E45

Task performed:

water leak frm right rear of tank area; probably has to be rem to repair. j

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V28542

In Date: 12/22/2009 Meter Reading: 55,786.00
Close Date: 12/29/2009

Problem?
REPAIR SAW E 45 REGAN

Task performed:	Parts	Quantity
	NO PARTS USED	

Vendor?: REGANS

Workorder: V28451

In Date: 12/17/2009 Meter Reading: 55,786.00
Close Date: 01/08/2010

Problem?
remove hose and hose deck for access E45

Task performed:	Parts	Quantity
1. Rem water tank frm trk; filled water after rep to chk for leaks; reinstalled tank.	194BULB	1
2. Rem water tank; chk repairs w/water; redrain tank; get ready to install foam. swch is brkn; set trk back up0; fill tank, etc.	200211002USE 2510-0032 TANK SENSOR FOAM PRO	2
3. Assist w/tank removal.	72R311018-2640 VENT A/C NEW # 1719	1
4. Finish install hose bed; fill tank; ck for leaks; isntall dividers; load hose back on trk.	78R536078R5360M 2PK FILTER AIR COND	1
5. Rem hose bed.		
6. A-Inspection		
7. R/R A/C filter; R/R rear unit A/C vent; rem frm _____; replc vent; reinstall.		
8. Rep (4) gauge wiring. j		

Workorder: V27825

In Date: 11/20/2009 Meter Reading: 5,350.20
Close Date: 01/13/2010

Problem?
Foam system is not working properly again. Took it to 42 a few shifts back and it is still not working... Need to be fixed. E45

Task performed:	Parts	Quantity
Tested foam sys; clnd foam screen & adj foam svc; tested & tested ok. j	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V28137

In Date: 12/05/2009
Close Date: 01/14/2010

Meter Reading: 55,574.00

Problem?

The TIC off of E45 has a broken cable that clips to the jacket from a fire we had today. Cable need to be repaired.

Task performed:

Replcd rubber strap on TIC charger. j

Parts

Quantity

NO PARTS USED

Workorder: V28140

In Date: 12/06/2009
Close Date: 01/14/2010

Meter Reading:

Problem?

The vent saw will not run at high speed and chokes it self out. Air filter clean, low adjust OK E45

Task performed:

Rep saw, adj & clnd; carb unit was running at 90%. j

Parts

Quantity

NO PARTS USED

Workorder: V28301

In Date: 12/12/2009
Close Date: 01/14/2010

Meter Reading: 5,400.30

Problem?

Water is leaking from the pneumatic line leading to the front intake valve solenoid.E45

Task performed:

Water leak; fnd no leaks. j

Parts

Quantity

NO PARTS USED

Workorder: V28198

In Date: 12/08/2009
Close Date: 01/15/2010

Meter Reading: 5,387.00

Problem?

water leaking from right rear of E45. near to mud flap. unknown origin of leak. e45

Task performed:

Water tank has hole in rear; will be sent to shop. j

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V29450

In Date: 01/26/2010 Meter Reading: 56,551.70
Close Date: 01/29/2010

Problem?
L-1 COMPARTMENT DOOR HOLD OPEN BROKEN, NEED SPARK PLUG FOR STATION BLOWER, E-45

Task performed:	Parts	Quantity
L-1 compt door hold open brkn; steel ball brk off in gas _____; drill out ball; replc steel ball. j	BPM8YSPRK PLUG BLOWER	1

Workorder: V29390

In Date: 01/24/2010 Meter Reading: 5,489.20
Close Date: 02/17/2010

Problem?
Shock for driver's compartment door broken. Poss needs to be replaced.E45

Task performed:	Parts	Quantity
Rep door shock. j	NO PARTS USED	

Workorder: V29692

In Date: 02/03/2010 Meter Reading: 56,801.50
Close Date: 03/19/2010

Problem?
L passenger door panel loose at the bottom & at the top.E45 Also - L speaker falling out, needs to be secured. TK, 15748

Task performed:	Parts	Quantity
1. Rep radio spkr that was falling off. 2. Rep rear door panel that was falling off. j	NO PARTS USED	

Workorder: V31053

In Date: 03/26/2010 Meter Reading: 57,999.50
Close Date: 04/20/2010

Problem?
TIGHTEN RT MIRROR E 45 AT TRAINING

Task performed:	Parts	Quantity
Went to HQ; fnd mirror loose; loosened mnt brkts; tighten mirror; ck ok. j	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V31098

In Date: 03/28/2010 Meter Reading: 58,144.00
Close Date: 04/20/2010

Problem?
soft suction has big hole and missing gasket. out of service E45

Task performed:	Parts	Quantity
Lt. duty T. Thomas took to Stn45; j	NO PARTS USED	

Workorder: V31293

In Date: 04/06/2010 Meter Reading: 58,204.00
Close Date: 05/01/2010

Problem?
HEADLIGHTS 10-7 E45

Task performed:	Parts	Quantity
replcd headlight. j	NO PARTS USED	

Workorder: V31385

In Date: 04/09/2010 Meter Reading: 58,204.00
Close Date: 05/01/2010

Problem?
red bulb on MIV valve does not come on. Amber light stays on, valve opens and closes normally. e45

Task performed:	Parts	Quantity
1. Will have lite rep at B. 2. Foam leak - rep foam leak at filter. j	NO PARTS USED	

Workorder: V31472

In Date: 04/12/2010 Meter Reading: 58,437.90
Close Date: 05/01/2010

Problem?
Onboard foam system reading no prime. E45

Task performed:	Parts	Quantity
Tested foam sys & tested ok. j	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V31771

In Date: 04/25/2010

Meter Reading: 58,741.10

Close Date: 05/05/2010

Problem?

The spotlight on top of the cab is out. E45

Task performed:

Chk spotlite works O/C; L/side & R/side rear red LED lites not flashing; replc both LED lites. j

Parts

50R03ZCRLIGHT LED RED TIR 6

Quantity

2

Workorder: V31558

In Date: 04/15/2010

Meter Reading: 58,437.90

Close Date: 05/11/2010

Problem?

k12 pull cord, hurst unit cutters binding, hurst power unit/not enough pressure for tool e45

Task performed:

ran pump & chkd hurst unit; swapped out unit for repair. j

Parts

NO PARTS USED

Quantity



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V32277

In Date: 05/18/2010

Meter Reading: 59,174.00

Close Date: 06/15/2010

Problem?

C INSPECTION AND REPAIRS AS NEEDED E 45

Task performed:

Parts

Quantity



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

C-Inspection	013-2020-056 PIN CABLE HALE CONTROL	1
Svc P/S.	038-1790-00CHECK VALVE INJECTOR HALE FOAM SYS.	1
3. Svc rear axle.	091-3YWCOVER KUSSMAUL AUTO EJECT	1
4. Svc T-case.	0913912CHARGER 2000	1
5. Replc frnt shocks.	0915520120AUTO EJECT 20 AERO OTL3925	1
6. Svc trans.	107796DRYER KIT AD9 -NEW	1
7. replc all (4) A/C vents on cab dash; all were brkn.	107800VALVE CHECK AD9	1
8. Rebuild air dryer.	108-12FBEADED CHAIN W/CONN 12	3
9. Replcd cab A/C filler.	15W40BSYN OIL BULK QTS	24
10. Replcd foam fill wtr proof switch cvr; replc foam test lite wtr proff switch cvr.	200-2481-00-0546-3240-00-0 FOAM PUMP SENSOR KIT	1
11. Replcd red lite on MIV valve.	2002501500DISTRIBUTION BOX	1
12. Replc T-signal switch.	29526898 29548988 TRANS FILTER ALLISON	1
13. Rem fan; replc both A/C belts; replc alt belt; reinstall fan; adj belts; replc belt tensioner.	2FC00ZCR4 IN ROUND LED	1
14. Drain cooling sys; replc wtr pump; refill cooling sys w/new coolant.	372000031IGNITION ON DISPLAY	1
15. Replcd lng on lite switch on dash.	3920773WASHER DRAIN PLUG	1
16. Replc w/strip on cab doors.	3924147OIL DRAIN PLUG CUMMINS	1
17. Replc pump panel walkway led's.	39768315259022 GROOVED TENSIONER OLD#3936213	1
18. Replc lite in L-1 compt.	40896474309418 PUMP-WATER ISC REBUILT	1
19. Replc rear compt lite.	607141-05USE 61H01 COPMPARTMENT LIGHT	4
20. Replc R/rear cab door entry lite	60R00XRRBRAKE/TAILLIGHT LED	1
21. R/R (3) torn seats in cab, driver seat, officer seat & crew seat behind driver.	6803230300 65482 SHOCK FRONT ENGINE	2
22. Replc female seat belt latch on seat behind officer.	6805450124SWITCH TURN SIGNAL	1
23. Replc chains for caps on intake & discharge valves.	6806970098SEAL DOOR	3
24. Replc horn contact & horn button.	6808300074VENT A/C LH	2
25. install btry charger, auto-ejet & btry indicator.	6808300174VENT A/C RH	2
26. Rem frnt grill; replc frnt red lens fro LED lites that were cracked.	6811813635S68-1181363-5S LENS RED 64 SERIES	2
27. Replc all (4) btrys; cln terms.	681181583LIS68-1181583-LIS LENS AMBER	1
28. Replc foam fill hose; hose had kink in it; replc #4 discharge hose that was missing (drain).	6814600340A14-15472-000 HORN BUTTON	1
29. Replc heat sensors on grd ladders.	78R536078R5360M 2PK FILTER AIR COND	1
30. T-shoot foam sys inop; pull pump guage apart; fnd nothing wrong with	800405PURGE VALVE KIT	1
w/gears; rem complete foam sys; replc computer/cables; reinstall foam sys; refill foam tank.	8126482-2106 TOGGLE GUARD	2
31. test foam system, foam not laying a thick blanket of foam. calibrate system, check lines, check motor. found new check valve bad, pelace check valve. j	9440BELT	1
	9480BELT	1
	98032R 41032-3 RED REFLECTOR OVAL REFLECTOR	1
	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
	BPR5ESSPARK PLUG 7734	2
	FG87904MFG3937557S FILTER P/S NEW STYLE	1
	FGQ79699GASKET-P/S FILTER NEW STYLE	1
	FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
	HP-31DBATTERY 950CCA HP-31D	4
	HPH6349AOIL FILTER 51748	1
	K080716BELT	1
	MSA150-A18MANSAYER COVER	2
	MSA150-A20MANSAYER COVER	2
	PR338324070 WIX FILTER WATER	1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

R90PFILTER FUEL 33231

1

Workorder: V32383

In Date: 05/25/2010 Meter Reading: 59,174.70
 Close Date: 07/06/2010

Problem?
 repair seats and hose bed cover E45 Central

Task performed:	Parts	Quantity
	NO PARTS USED	

Vendor?: CENTRAL AUTO

Workorder: V33493

In Date: 07/12/2010 Meter Reading: 59,851.40
 Close Date: 07/22/2010

Problem?
 INSTALL MAN SAVER'S ON R/SIDE AND L/SIDE PUMP PANEL E-45

Task performed:	Parts	Quantity
Replc mansavers on pump panel. j	NO PARTS USED	

Workorder: V33297

In Date: 07/02/2010 Meter Reading: 59,618.00
 Close Date: 07/30/2010

Problem?
 PPV fan stalls while running on high. The fan will start back up but will only run on low.

Task performed:	Parts	Quantity
Ran vent fan; started surging; suspect bad fuel; drained fuel & put fresh fuel in; ran some more; probably needs to be completely drained & ran longer. j	NO PARTS USED	

Workorder: V33290

In Date: 07/01/2010 Meter Reading: 59,618.00
 Close Date: 08/17/2010

Problem?
 Chainsaw on E45 shuts off at idle. Asset # 10179480.

Task performed:	Parts	Quantity
Rem carb & cln; reinsrtalled & ran. ja	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V33820

In Date: 07/27/2010 Meter Reading: 60,019.00
Close Date: 08/18/2010

Problem?
siren operates spontaneously and on it's own. e45

Task performed:	Parts	Quantity
Replcd siren head & tested. j	NO PARTS USED	

Workorder: V34289

In Date: 08/16/2010 Meter Reading: 60,356.00
Close Date: 09/17/2010

Problem?
REAR A/C IS BLOWING HOT AIR E45

Task performed:	Parts	Quantity
1. Traced out problem; fnd condensor fan not working; fnd both fans need to be replcd.	RD-5-7123-0 18-2108 FIVE BLADE FAN 3382	2
2. installed new condensor fans. j	RD571290 01-2616 MOTOR 12V 73R-0542 3512	2

Workorder: V34294

In Date: 08/16/2010 Meter Reading: 60,356.00
Close Date: 09/17/2010

Problem?
The brake line system is not holding air pressure over several hours. E45

Task performed:	Parts	Quantity
Chk for air leaks; fnd none at this time. j	800405PURGE VALVE KIT	1

Workorder: V35107

In Date: 09/22/2010 Meter Reading: 61,473.20
Close Date: 10/18/2010

Problem?
K12 on E45 will not idle. It stalls out without throttle. It starts without problems.

Task performed:	Parts	Quantity
1. clean cab and tested ok. jab	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V30983

In Date: 03/23/2010
Close Date: 10/19/2010

Meter Reading: 57,999.50

Problem?

During morning checkout, belt squeaking from engine compartment. No loose belts during inspection. E45

Task performed:

Compelted j

Parts

Quantity

NO PARTS USED

Workorder: V31223

In Date: 04/02/2010
Close Date: 10/19/2010

Meter Reading: 58,204.00

Problem?

Right front headlight out. Thanks!!

Task performed:

Completed j

Parts

Quantity

NO PARTS USED

Workorder: V35034

In Date: 09/18/2010
Close Date: 10/20/2010

Meter Reading: 61,387.10

Problem?

Left telelight on E45 has one bulb not working. Needs to be replaced.

Task performed:

Replcd LED light that was out. j

Parts

Quantity

RSC03ZCRTIR3 CLEAR WHITE

1

Workorder: V35869

In Date: 10/23/2010
Close Date: 11/12/2010

Meter Reading: 61,822.00

Problem?

E45 need a intake screen on the left side behind the siamese. Its missing. E45

Task performed:

Rep leak at left side intake valve. j

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V35627

In Date: 10/13/2010 Meter Reading: 61,822.00
Close Date: 11/17/2010

Problem?

Needs 6 new tires for E45 per ATECH13 Tommy. All tires are worn and need to be replaced...E45

Task performed:

	Parts	Quantity
Needs (6) new tires for E45 per Atech13 Tommy; Boulevard j	NO PARTS USED	

Vendor?: BOULEVARD TIRE

Workorder: V36046

In Date: 10/30/2010 Meter Reading: 62,049.90
Close Date: 12/07/2010

Problem?

3 issues to address: Left scene light bulb is out, RED bulb cover for master intake is missing, K12 on E45 will not idle. It starts and will run. Will stall if not throttled.

Task performed:

	Parts	Quantity
1. Scene light out; replc buld. 2. K12 no start; sent unit to shop. 3. Fuel leak on gen, rep fuel leak at tank. j	NO PARTS USED	

Workorder: V36285

In Date: 11/08/2010 Meter Reading: 62,713.00
Close Date: 12/08/2010

Problem?

Generator on E45 was leaking fuel. Tommy replaced the gasket and it is not leaking any longer.

Task performed:

	Parts	Quantity
1. Rep fuel leak on gen tank. 2. Remntd tools in L-1 compt. j	NO PARTS USED	

Workorder: V36449

In Date: 11/15/2010 Meter Reading: 62,916.20
Close Date: 12/15/2010

Problem?

E45 top right rear running light is missing.

Task performed:

	Parts	Quantity
(1) TRAVELED TO STATION 45 TO CHECK ABOUT THE TOP REAR RUNNING LIGHT ON E45 THAT IS MISSING. LIGHT WASN'T MISSING. IT WAS FALLING OFF. RECONNECTED THE LIGHT TO THE ENGINE. OK. (2) READJUSTED E45 CAB DOORS THAT WERE HARD TO CLOSE. J.W.	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V36633

In Date: 11/23/2010 Meter Reading: 62,916.20
Close Date: 12/15/2010

Problem?
E45 compressed air system is leaking. Also, A/C is leaking into cab on officer's side.

Task performed:	Parts	Quantity
(1)TRAVELED TO STATION 45 FOR AIR LEAK PROBLEM ON E45. CHECKED FOR LEAKS AND FOUND SEVERAL. REPAIRED AND TESTED OK. J.W.	NO PARTS USED	

Workorder: V31719

In Date: 04/22/2010 Meter Reading: 58,437.90
Close Date: 12/22/2010

Problem?
repair power unit E45 (outside agency-team equipment)

Task performed:	Parts	Quantity
	NO PARTS USED	

Workorder: V33336

In Date: 07/05/2010 Meter Reading: 59,618.00
Close Date: 12/22/2010

Problem?
E45's siren is turning on and off on its own. Siren works fine while responding to emergencies.

Task performed:	Parts	Quantity
	295SLSA1SIREN	1

Workorder: V35426

In Date: 10/06/2010 Meter Reading: 61,822.00
Close Date: 12/22/2010

Problem?
The Thermal Imaging Camera (TIC) base will not charge the unit while it is placed in it. e45

Task performed:	Parts	Quantity
(1) TRAVELED TO ST45 TO CHECK OUT NO CHARGING OF TIC WHILE INSERTED IN E45 CHARGER. CHECKED OUT THE CHARGER , REPAIRED CHARGER,TESTED OUT OK. J.W.	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V35555

In Date: 10/11/2010
Close Date: 12/22/2010

Meter Reading: 61,822.00

Problem?

The system will not hold pressure after vehicle is turned off. It bleeds down after one to two hours. E45

Task performed:

(1)E45 AIR SYSTEM BLEEDS DOWN WITHIN ONE/TWO HRS. REPAIRED AIR HORN SUPPLY LINE. OK. J.W.

Parts

NO PARTS USED

Quantity

Workorder: V37651

In Date: 01/05/2011
Close Date: 01/05/2011

Meter Reading: 64,431.00

Problem?

no a/c blower, E-45

Task performed:

1. remove dash board, replace blower switch

Parts

ABPN8332229011-3050 SWITCH BLOWER

Quantity

1

Workorder: V36879

In Date: 12/04/2010
Close Date: 01/11/2011

Meter Reading: 63,417.00

Problem?

Front Cab A/C not working E45

Task performed:

Readj cab heater cable. j

Parts

NO PARTS USED

Quantity

Workorder: V37837

In Date: 01/17/2011
Close Date: 01/18/2011

Meter Reading: 65,448.00

Problem?

Both headlights on E45 are not working. One works on high beam only and the other works on low only. Please send 3 headlights so we can have 1 for reserve.

Task performed:

1. replace both front headlights

Parts

H6054USE CV TYPE SEALED BEAM

Quantity

2



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V37949

In Date: 01/21/2011 Meter Reading: 65,858.00
Close Date: 01/21/2011

Problem?

Primer motor will not work at all. After backflushing the pump I went to reprime the pump and the primer started but stopped and the truck showed low battery. The high idle recharged the batteries to normal voltage. E45

Task performed:

	Parts	Quantity
--	-------	----------

1. check primer motor inop, replace primer motor, replace solenoid for primer motor in electrical box, remove primer valve and replace o rings, found that primer motor stayed on while driver was responding to a call and burnt up the system.

NO PARTS USED

Workorder: V38051

In Date: 01/25/2011 Meter Reading: 66,037.00
Close Date: 01/28/2011

Problem?

a/c draining and undue amount of water into the cab e 45

Task performed:

	Parts	Quantity
--	-------	----------

Went to 45; fnd A/C not draining; rem drain line & cleaned; reinstalled drain; ck ok; return home. j

NO PARTS USED

Workorder: V37435

In Date: 12/27/2010 Meter Reading: 64,006.00
Close Date: 02/07/2011

Problem?

right headlamp high beam is out. we have none in the station. e45

Task performed:

	Parts	Quantity
--	-------	----------

1. Replcd headlight.
2. Rep console that was loose.
3. Readj rear air pack brkts. j

NO PARTS USED

Workorder: V37621

In Date: 01/04/2011 Meter Reading: 64,431.00
Close Date: 02/07/2011

Problem?

a/c fan control defunct. Needs help. E45

Task performed:

	Parts	Quantity
--	-------	----------

1. Fan inop; replc fan swtch & tested.
2. Rep spotlight that was out. j

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V38454

In Date: 02/11/2011

Meter Reading: 66,765.00

Close Date: 02/24/2011

Problem?

bracket that supports the hurst spreaders is broken and will not support the tool. needs replacement asap. E45

Task performed:

1. Readj tool brkt to fit Hurst unit.
2. Air leak; fnd leak at fitting on air horns. j

Parts

3599155C2SUN VISOR CLIP R/H

Quantity

1

Workorder: V38686

In Date: 02/22/2011

Meter Reading: 67,568.00

Close Date: 02/28/2011

Problem?

ON CALL K12 SAW 10-7 E 45

Task performed:

- K12 wont run - carb dirty; cln carb, replcd fuel. j

Parts

BPR5ESSPARK PLUG 7734

Quantity

2



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V38326

In Date: 02/07/2011

Meter Reading: 66,765.00

Close Date: 03/02/2011

Problem?

B INSPECTION AND REPAIRS AS NEEDED E 45

Task performed:

- Road test & B-Inspection
- 2. Btry tray lock/slider seized up; blow out dirt, cln sliders & lock mechanism; lube.
- 3. A/C air filter; replc dirty air filter.
- 4. Tire lugnut cvr missing; install (20) new lugnut cvrs.
- 5. Coolant lost - test sys - no leaks; test radiator cap; cap failed test; install new rad cap & top off fluid level.
- 6. Frnt L&R side t-signal lens brkn; rem lens & install new lenses.
- 7. L/side pump panel light lens brkn; rem/install new light lens.
- 8. Primary air tank no drain valve; drain air, rem plug & install pull drain valve.
- 9. Dash A/C vent louvers pop out; rem vent asy; ___ vent louver slide & panel; reinstall asy in dash.
- 10. All (4) window molding brkn & msng screws; rem window moldings; install new moldings & screws.
- 11. L-3 tray strut msng; rem mntng pin; install new mntng pin & new strut.
- 12. Taglight 10-7 - tag bulb blown; rem bulb & isntall new bulb.
- 13. Master intake ___ intake warning light bulb shield msng; install replacement bulb shield.
- 14. Pump panel light switch loose; reposition switch & secure to pump control panel.
- 15. L-1 door lock loose, striker for lock loose & lock out of timing; sec striker & locking mechanism; retime locking mechanism; sec loose door struts.
- 16. L-3 door strut loose - door striker loose; sec door strut & door striker.
- 17. R-3 strut pin loose; sec strut pins.
- 18. R-3 sliding tray unsecure to slider; rem stripped nut/bolts; install/sec new nuts/bolt to sliders.
- 19. R-1 door struts loose; rem nut & brkn lock washer; install new nut/lock washer; sec strut.
- 20. Rear compt striker loose & door lock; sec striker & door lock.
- 21. T- case output shaft seal leaking; jackup, drain oil, diss drive line; rem output shaft asy & flange; replc bad seal & reassem; fill w/oil; operate pump.
- 22. Back A/C register cntrl knob fell off; fnd behind seat; reinstall.
- 23. Quality inspection. j

Parts	Quantity
0465130010GASKET GEARBOX COVER	1
05-17223-000CAP RADIATOR 10 LB	1
101281011GSS6297UM 60# DOOR STRUT QUINT	1
12105QUICK DRAIN	1
15W40BSYN OIL BULK QTS	24
200054013LENS RED	1
2962540000SEAL SAME AS 29867 C/R	1
35200-RLIGHT MARKER LED RED	1
68-3963453-30LENS CLEAR FOR STRIP LIGHT	1
78R536078R5360M 2PK FILTER AIR COND	1
89BULB	1
9150391503 LENS AMBER	1
91513AMBER LENS	2
A1834388002MOLD L/H	2
A1834388003MOLD R/H	2
ACX-84534LUG NUT COVER PK10	20
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V38060

In Date: 01/26/2011 Meter Reading: 66,037.00
Close Date: 03/08/2011

Problem?
spot light on E45 is not working.

Task performed:	Parts	Quantity
Rep bad connection on spotlight. j	NO PARTS USED	

Workorder: V38124

In Date: 01/28/2011 Meter Reading: 66,225.00
Close Date: 03/08/2011

Problem?
E45 throttle response is sluggish. Tommy was here and checked the truck and advised that it seems fine.

Task performed:	Parts	Quantity
road tested & FNP w/engine. j	NO PARTS USED	

Workorder: V38473

In Date: 02/13/2011 Meter Reading: 66,945.00
Close Date: 03/15/2011

Problem?
map light bulb out on E45.

Task performed:	Parts	Quantity
Replcd bulb in maplight. j	NO PARTS USED	

Workorder: V38588

In Date: 02/17/2011 Meter Reading: 67,266.00
Close Date: 03/15/2011

Problem?
saw difficult to start. throttle sticks wide open, with throttle activation saw winds up very high. on/off switch not working, had to use choke to shut unit off.

Task performed:	Parts	Quantity
Ran saw & tested ok. j	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V39028

In Date: 03/07/2011

Meter Reading: 68,313.00

Close Date: 03/28/2011

Problem?

when engine and pump are off, hydrant water put into intake and there is a water leak coming from rear of engine. Tried closing tank fill and tank to pump- did not work. E45

Task performed:

Parts

Quantity

1. Pumpleak; readj tank to fill valve & retested.
 2. Maplight inop; rewire maplight & tested.
 3. Air leak; chkd for air leak & rep where needed.
- j

NO PARTS USED

Workorder: V39403

In Date: 03/23/2011

Meter Reading: 68,936.40

Close Date: 04/05/2011

Problem?

Officer door handle on E45 not working properly and feels loose.

Task performed:

Parts

Quantity

1. Replcd doorhandle.
 2. Air leak; rep air line that was leaking.
- j

NO PARTS USED

Workorder: V39190

In Date: 03/14/2011

Meter Reading: 68,819.00

Close Date: 04/06/2011

Problem?

SIDE WATER GUAGE LIGHTS READ FULL WHEN THE TANK IS EMPTY. ONLY PUMP PANEL GUAGE REACTS TO DECREASING WATER IN THE TANK. sta 45

Task performed:

Parts

Quantity

Recalibrated guage. j

NO PARTS USED

Workorder: V40030

In Date: 04/20/2011

Meter Reading: 69,738.00

Close Date: 04/27/2011

Problem?

Discharge 4 leaking water. Cant shut it off. Emptying pump water. Sta45.

Task performed:

Parts

Quantity

Discharge #4 leaking - valve out of adj; ajd #4 discharge.
j

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V40353

In Date: 05/03/2011 Meter Reading: 70,286.10

Close Date: 05/04/2011

Problem?

on call e45 shut down on turnpike

Task performed:

Unit will not start; chk eng code 05-277 - fuel injection valve; call for tow truck to tow to shop. Swap into 10142409. j

Parts

Quantity

R90PFILTER FUEL 33231

1

Workorder: V39456

In Date: 03/26/2011 Meter Reading: 68,936.40

Close Date: 05/05/2011

Problem?

air pressure leak. after sitting about four to six hours the air pressure in both tanks dropped below 50 psi. R45

Task performed:

traced out air leaks & repaired. j

Parts

Quantity

NO PARTS USED

Workorder: V40089

In Date: 04/22/2011 Meter Reading: 69,738.00

Close Date: 05/09/2011

Problem?

E45 water level multi-color light bar on both sides of truck read full when the water tank is empty. Also, some of the LED lights are out. E45

Task performed:

Recalibrated wtr level gauges & tested. j

Parts

Quantity

NO PARTS USED

Workorder: V40280

In Date: 04/30/2011 Meter Reading: 70,286.10

Close Date: 05/10/2011

Problem?

Engine 45 is leaking oil. Dipstick showed approx. 2 quarts low after shift with a good amount of oil on bay floor. E45

Task performed:

Oil on stn floor; fnd dipstick tube loose; secure & add 3 qts eng oil.
R/side LED warning 10-7; rem/install new LED asy.
j

Parts

Quantity

50R03ZCRLIGHT LED RED TIR 6

1



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V39851

In Date: 04/11/2011 Meter Reading: 69,462.00
Close Date: 05/11/2011

Problem?

L.E.D. emergency light on the hood (Officer's side) not working. E45

Task performed:

Rep LED light on rear of truck that was out. j Parts ----- Quantity
NO PARTS USED

Workorder: V40518

In Date: 05/10/2011 Meter Reading: 70,381.00
Close Date: 05/23/2011

Problem?

Check repairs on fuel system.

Task performed:

A-Inspection Parts ----- Quantity
2. R/R wiper blades. 52-24WIPER BLADES ANCO 24 2
3. Tighten mansavers.
4. Chk for air leaks; replc quick connect fittings on gov & air horn solenoid.
5. Start t-shoot upper side wtr level lights; always shows full; fnd lights hooked into foam level. j

Workorder: V40201

In Date: 04/27/2011 Meter Reading: 70,035.00
Close Date: 05/31/2011

Problem?

Rear AC blowing hot air in the engine cab... E45

Task performed:

Recharged A/C & rep leak. j Parts ----- Quantity
NO PARTS USED

Workorder: V40365

In Date: 05/03/2011 Meter Reading: 70,286.10
Close Date: 06/14/2011

Problem?

REPAIR FUEL SYSTEM CUMMINS POWER SOUTH

Task performed:

work completed on WO 40518 Parts ----- Quantity
NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V41224

In Date: 06/09/2011 Meter Reading: 70,844.00
Close Date: 06/28/2011

Problem?

REPLACE RT REAR TIRE E 45

Task performed:

Replc RT rear tire E45 - Boulevard j

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD

Workorder: V41325

In Date: 06/14/2011 Meter Reading: 71,149.00
Close Date: 06/30/2011

Problem?

replaced a bad headlight, used last spare we had. Please send more headlights. Sta 45.

Task performed:

Dropped off headlights. j

Parts

Quantity

NO PARTS USED

Workorder: V41888

In Date: 07/08/2011 Meter Reading: 71,805.00
Close Date: 07/08/2011

Problem?

when hooked up to hyd. water overflowing from tank over flow tube. E-45

Task performed:

1. hook up to hyd. found tank to pump valve leaking,
rebuild hale tank to pump valve.

Parts

Quantity

5462270020VALVE KIT SS 546-2270-02-0

1

Workorder: V42255

In Date: 07/25/2011 Meter Reading: 72,213.00
Close Date: 07/28/2011

Problem?

The rear a/c unit on E45 not blowing cold.

Task performed:

SEE W/O # 42255

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V42331

In Date: 07/26/2011 Meter Reading: 72,213.00
 Close Date: 07/28/2011

Problem?
 The A/C in the rear is blowing hot air. e 45

Task performed:	Parts	Quantity
1. check rear cab a/c, found low on freon. charge system check for leaks found both scharader valves for rear cab a/c leaking replace both valves, evecaute and recharge system, recheck for leaks none found at this time.	NO PARTS USED	

Workorder: V39942

In Date: 04/15/2011 Meter Reading: 69,738.00
 Close Date: 08/02/2011

Problem?
 The control arm on the valvestem came off. It was resecured with the washer and bolt. Now the valve will not close completely. Al the tank refill valve will not close completely, Sta.45.

Task performed:	Parts	Quantity
no wo found in files	NO PARTS USED	

Workorder: V41876

In Date: 07/08/2011 Meter Reading: 71,805.00
 Close Date: 08/08/2011

Problem?
 The tank fill valve will not close completely. The foam system loses it's prime after approixmately 45 - 60 seconds. Sta 45.

Task performed:	Parts	Quantity
tested foam system and tested ok	NO PARTS USED	

Workorder: V42072

In Date: 07/16/2011 Meter Reading: 71,805.00
 Close Date: 08/08/2011

Problem?
 Rear Cab A/C not working - hot air. R45

Task performed:	Parts	Quantity
unit sentto south shop	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V42665

In Date: 08/08/2011 Meter Reading: 72,487.00
Close Date: 08/15/2011

Problem?
E45 rear a/c not working. Please help!

Task performed:	Parts	Quantity
1. rear a/c inop replaced tranery switch	160012-2012A EXPANSION VALVE 71R8301	1
2. check rear a/c, evacute system, replace drier, recharge still not cold ordered expansion valve	RD546400P11-2630 SWITCH BINARY	2

Workorder: V42766

In Date: 08/12/2011 Meter Reading: 72,625.00
Close Date: 08/22/2011

Problem?
Need expansion valve on rear a/c. Sta 45.

Task performed:	Parts	Quantity
Replc rear expansion valve; evac & recharge A/C sys.	160012-2012A EXPANSION VALVE 71R8301	1
j	78R536078R5360M 2PK FILTER AIR COND	1

Workorder: V42757

In Date: 08/11/2011 Meter Reading: 72,625.00
Close Date: 09/12/2011

Problem?
rear a/c still not blowing out cold, Sta 45.

Task performed:	Parts	Quantity
cleaned condencer fans and tested ac	NO PARTS USED	

Workorder: V43416

In Date: 09/04/2011 Meter Reading: 72,936.80
Close Date: 09/19/2011

Problem?
BATT SPARE LOCATED AT STA 45 TIC SPARE BATTERY CHARGER STRAP BROKEN E 45

Task performed:	Parts	Quantity
repair tic charger on engine at station ok at this time, charging ok	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V43662

In Date: 09/14/2011 Meter Reading: 72,936.80
 Close Date: 09/20/2011

Problem?
 tires on rear E45 BLVD. TIRE

Task performed:	<u>Parts</u>	<u>Quantity</u>
Tires on rear E45 - Boulevard j	NO PARTS USED	

Vendor?: BOULEVARD

Workorder: V43014

In Date: 08/23/2011 Meter Reading: 72,936.80
 Close Date: 09/23/2011

Problem?
 Primer on E45 turning on and off on it's own. Primer handle in breezway, not handle next to MIV.

Task performed:	<u>Parts</u>	<u>Quantity</u>
repaired primer switch that was falling off	377R054FEET - HURST TOOL	1
	538028052VALVE PRIMER PUMP W/HARDWARE	1
	9096-02SWITCH	2



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V43153

In Date: 08/29/2011

Meter Reading: 73,274.00

Close Date: 10/11/2011

Problem?

C INSPECTION AND REPAIRS AS NEEDED E 45

Task performed:

Parts

Quantity



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

1. C-Inspection
2. Paint fuel cap.
3. Coolant at "O"; locate leak & rep; also adj coolant protion.
4. Assset # msng frm windshield; make up new label & install.
5. Active trns code P070 open ckt @ pin 15 wire 161; locate loose connection to pin connector; rep wiring; cleared code; ok.
6. Rotate frnt tires; slight pull to the right.
7. Svc gen.
8. Air leaks - air tank pull drains leaking; rem pull wires & plug; added manual drains.
9. Svc air dryer/purge valve;.
10. Svc btry/trash line pull outs.
11. replc eng air filter.
12. Replc wiper blades & top off washeer fluid.
13. Trans retarder swith brkn; replc retarder switch.
14. Replc inner cab door trim - brkn.
15. A/C vent deflectors brkn; replc deflectors & reinstalld/freed up (2) center ones.
16. Frnt T-signal side lamps inop; installed new bulbs.
17. Rear/side markers dim; replc marker lights; also replc R/center emerg light lens.
18. Install new maplight -brkn.
19. Heater cntrl inop - controller brkn; replc controller.
20. Vent controller cables not working properly; cable brkn, others not adj properly; rep vent cbles/doors as needed.
21. Dash panels loose; plastic mnt tabs msng; install new tabs.
22. Svc all doors/lights; installed new screws as needed.
23. Door weather strip worn; replc.
24. Failed vac test tank-to-pump & recirc hale leaking; replc tank-to-pump/recirc; also had to mod linkage/arm to work properly.
25. R/S air hoen ino - out of adj; adj air horn.
26. Assist John Murray w/vac & tank-to-pump valve - Larson.
27. Relief valve leaking; rebuilt reliev valve/sensing valve not ____ vac; replc chk valve.
28. Tele lights wont lock; set screws seized; freed up set screws/adjuster.
29. Fail vac test; relief valve leaking; rebuild relief valve, sesning valve; also replc chk valve; fnd fittings leaking at primer valve; back flushed all valves; inspect/clnd screens.
30. Relief valve light inop; wires pulled out in pump panel; t-shoot/rep relief valve cntrl sys wiring.
31. Pump panel fuel/trans gauge inop; gauge brkn; also wiring problem; rewire gauge grnd sys; rep corroded pin at T-case switch; replc gauge relay.
32. Exten gun warning inop; wiring cut in dash; t-shoot wiring; rep wiring; rewired grnd sys - replc sensor.

038-1010-01HALE RELIEF VALVE W/ VULCANIZED SEAT	1
042002000SPRING RELIEF VALVE HALE	1
073-0190-01PISTON TPM RELIEF VALVE	1
103385NDRAIN COCK	3
107796DRYER KIT AD9 -NEW	1
15W40BSYN OIL BULK QTS	24
194BULB	10
23-11829-050SCREW	2
301-502301-104 FUEL GAUGE	1
310-303TRANS TEMP GAUGE	1
35200-YLIGHT MARKER LEDAMBER	2
372000084MARKER LIGHT	2
391701HOSE AND FITTING	1
501-3090-00PRIMER PUMP MOTOR	1
52-24WIPER BLADES ANCO 24	2
546-2210-02-OLIGHT KIT HALE	1
546126000TPM/QG HALE REPAIR KIT	1
6806890001LOCK DASH	6
6806970098SEAL DOOR	1
6808300074VENT A/C LH	1
6808300174VENT A/C RH	1
6808330631CABLE ASSY HEATER	1
6819634283068-1963428-30 LENS CLR	1
78158915 VALVE 1 1/2	1
800405PURGE VALVE KIT	1
87401RY-30T RELAY 5 PIN 12V	1
87499RY48 RELAY	1
91398907 VALVE KIT 3 IN AKRON	1
A1834388002MOLD L/H	2
A1834388003MOLD R/H	2
A2241425020SW ROCKER RETARDER	1
ABPN83322930CONTROL HEAD AC/HEAT	1
CA8193AIR FILTER 46744 WIX	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
LF18TS-LEDMAP LIGHT LED 18 IN	1
R90PFILTER FUEL 33231	1
XG840-KITEXTENDA GUN SWITCH	1



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

- 33. Quartz light UP warning inop - wired improperly; R/R wiring to get working; sys operational; fnd sensor mntd out of adj on L/S; adj magnet; working properly now.
- 34. Inside cab electrical box ____; msng outer safety cvr; make up new seal & isntalled.
- 35. Foam tank guage not accurate; calibrated foam gauge & topped off foam sys.
- 36. Repl primer pump - inop.
- 37. Quality check.
- 38. Air leak in dash; fitting to air gauges - isntalled new fittings. j

Workorder: V44123

In Date: 10/03/2011 Meter Reading: 72,936.80
Close Date: 10/14/2011

Problem?

The control solenoid for the intake relief valve appears to be leaking. The solenoid is located on the left underside of E45 aft of the pump.

Task performed:	Parts	Quantity
FOUND RELIEF VALVE LEAKING, REPAIRED LEAK AND TESTED	NO PARTS USED	

Workorder: V44238

In Date: 10/08/2011 Meter Reading: 72,936.80
Close Date: 10/14/2011

Problem?

E45 thermal image camera isnt working properly and it will freeze the picture. The TIC needs to be fixed or replaced ASAP for crew safety. Please have someone come out and fix the camera.E45

Task performed:	Parts	Quantity
THEY SWAPPED OUT THERMAL IMAGE WITH SHOP	NO PARTS USED	

Workorder: V44248

In Date: 10/09/2011 Meter Reading: 72,936.80
Close Date: 10/14/2011

Problem?

While in pump the motor's fuel gauge on the pump panel is not working. E 45

Task performed:	Parts	Quantity
REPAIRED BROKEN WIRES FOR FUEL GAUGE	NO PARTS USED	
REPALCED HEAD LIGHT		
CONDENCER FANS INOP, REPLACED RELAYS, AND TESTED		



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V44685

In Date: 10/25/2011 Meter Reading: 73,614.80

Close Date: 10/26/2011

Problem?
REPAIR FLAT BOULEVARD

Task performed:	Parts	Quantity
Rep flat - Boulevard j	NO PARTS USED	

Vendor?: BOULEVARD

Workorder: V44830

In Date: 10/31/2011 Meter Reading:

Close Date: 11/01/2011

Problem?
Driver compartment buzzer went off even though the compartment was closed. We adjusted the switch and were able to get it to turn off. E 45

Task performed:	Parts	Quantity
check door ajar alarm going off, found switches in in L-1 compt bad, replace both switches	52-624SWITCH DOOR	2

Workorder: V44084

In Date: 10/03/2011 Meter Reading: 72,936.80

Close Date: 11/09/2011

Problem?
6 inch hard suction on E45 is leaking at the coupling during drafting operations. Sta 45

Task performed:	Parts	Quantity
repaired suction hose and tested	NO PARTS USED	
repaired coolant leak at lower hose and retested		

Workorder: V44358

In Date: 10/13/2011 Meter Reading:

Close Date: 11/14/2011

Problem?
one of the orange hurst hoses has multiple burns in it. e 45

Task performed:	Parts	Quantity
1. dropped off new hose.	3530016HOSE HURST 16 ORANGE	1
2. Rep coolant leak on eng j		



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V44754

In Date: 10/29/2011

Meter Reading:

Close Date: 11/14/2011

Problem?

While responding to emergency call we went through water that was up past the axle. We are concerned that the air filter may have taken on water. Needs to be checked. E45

Task performed:

Parts

Quantity

Chkd truck & tested ok. j

NO PARTS USED

Workorder: V44083

In Date: 10/03/2011

Meter Reading: 72,936.80

Close Date: 11/21/2011

Problem?

Digital Display on master intake and discharge gauge is unreadable during pumping operations. Sta 45.

Task performed:

Parts

Quantity

Deck gun swivel; replc/tested. j

14-7014HGR-1 HELMET HOOK

10

X170DECK GUN ROTATION LOCK INSERT

1

Workorder: V44733

In Date: 10/27/2011

Meter Reading: 74,006.20

Close Date: 11/21/2011

Problem?

e-45 warning alarm inside cab continuously on, Sta 45

Task performed:

Parts

Quantity

Rep/adj quartz switch. j

NO PARTS USED

Workorder: V45083

In Date: 11/10/2011

Meter Reading:

Close Date: 11/21/2011

Problem?

Lost vehicle tag. TK, 15748, Sta 45

Task performed:

Parts

Quantity

Installed new tag. j

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V45418

In Date: 11/25/2011 Meter Reading:
Close Date: 12/05/2011

Problem?
Starter not working properly, engine will not turn over and start.E45

Task performed:	Parts	Quantity
FOUND ALL WIRES ON STARTER WERE LOSE - REPAIRED AND TESTED.	NO PARTS USED	

Workorder: V45922

In Date: 12/18/2011 Meter Reading:
Close Date: 01/03/2012

Problem?
The Recip saw box is broken, please replace. Sta 45

Task performed:	Parts	Quantity
sent saw to shop and replaced with new one	NO PARTS USED	

Workorder: V46065

In Date: 12/25/2011 Meter Reading:
Close Date: 01/03/2012

Problem?
light is hanging/broken. Right rear red clearance light. E45

Task performed:	Parts	Quantity
repaired rear lights	NO PARTS USED	

Workorder: V46406

In Date: 01/08/2012 Meter Reading: 76,112.00
Close Date: 01/13/2012

Problem?
Headlamp on E45 needs to be replaced. Sta 45

Task performed:	Parts	Quantity
DOOR NOT OPENING, REPLACED DOOR LATCH.	101280018LATCH ASSY. FOR D-PADDLE HANDLE	1
	14996-02D PADDLE HANDLE	1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V47112

In Date: 02/06/2012 **Meter Reading:** 76,711.70
Close Date: 02/27/2012

Problem?

In the rear middle of the motor compartment there is a possible coolant leak. Also, station 45 needs a case of motor oil. Sta 45

Task performed:

	Parts	Quantity
--	-------	----------

- | | | |
|-----------------------------------------------------|---------------|--|
| 1. PRESSURE TESTED FOR COOLANT LEAK FOUND NO LEAKS. | NO PARTS USED | |
| 2. CHECKED FOR AIR LEAK - FOUND NO LEAKS. | | |

Workorder: V47077

In Date: 02/03/2012 **Meter Reading:** 76,711.70
Close Date: 02/28/2012

Problem?

The spotlight is not functioning on morning check out. Sta 45

Task performed:

	Parts	Quantity
--	-------	----------

- | | | |
|-------------------------------------------|---------------|--|
| 1. REPAIRED BAD CONNECTION ON SPOT LIGHT. | NO PARTS USED | |
| 2. AIR LEAKS - CHECKED FOR AIR LEAKS. | | |

Workorder: V45419

In Date: 11/25/2011 **Meter Reading:**
Close Date: 03/09/2012

Problem?

Air leak in the brakes and it is making the engine response time delayed due to not enough pressure to relieve the air brake.E45

Task performed:

	Parts	Quantity
--	-------	----------

NO PARTS USED

Workorder: V47634

In Date: 02/29/2012 **Meter Reading:** 77,228.00
Close Date: 03/13/2012

Problem?

PRESSURE RELIEF VALVE INOPERATIVE ON MORNING CHECK E 45

Task performed:

	Parts	Quantity
--	-------	----------

RAN PUMP AND TESTED OK.	NO PARTS USED	
-------------------------	---------------	--



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V48065

In Date: 03/20/2012 Meter Reading: 77,793.20
Close Date: 03/20/2012

Problem?
ON CALL DOOR ALARM GOING OFF E 45

Task performed:	Parts	Quantity
UNIT GOT CALLED OUT TO STRUCTURE FIRE. WAIT AT STATION - DOOR OPEN ALARM AND LIGHT GOING OFF. CHECK SWITCHES AND WIRING NO FAULT FOUND - DISABLED ALARM & LIGHT AND TEMPERALY - STATION VERY BUSY - INTERMITTING PROBLEM POSSIBLE NODE NEED REPROGRAMMING.	NO PARTS USED	

Workorder: V48165

In Date: 03/24/2012 Meter Reading:
Close Date: 03/28/2012

Problem?
Intake valve handle on driver's side was broken off during training.

Task performed:	Parts	Quantity
1. found l/side intake pump panel handle broken off at the valve, drill and use an easy out to remove broken part of handle, install new handle.	012-1510-00-0HANDLE	1

Workorder: V48067

In Date: 03/20/2012 Meter Reading: 77,793.20
Close Date: 04/02/2012

Problem?
DOOR ALARM GOING OFF E 45

Task performed:	Parts	Quantity
1. TRACED OUT PROBLEM WITH DOOR AJAR FOUND WATER IN CONNECTORS. 2. AIR LEAK - TRACED OUT AIR LEAKS.	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V48144

In Date: 03/23/2012 Meter Reading: 77,844.00
Close Date: 04/16/2012

Problem?
search/spot light (on top of cab) out

Task performed:	Parts	Quantity
1. REPAIRED AIR LEAK AT DASH.	NO PARTS USED	
2. REPAIRED SPOT LIGHT, FOUND BAD GROUND WIRE IN UNIT.		

Workorder: V48268

In Date: 03/28/2012 Meter Reading: 77,991.00
Close Date: 04/16/2012

Problem?
pump selector is leaking air. e 45

Task performed:	Parts	Quantity
REBUILT PUMP SHIFTER, AND TESTED.	5460370530VPS SHIFT KIT 546-0370-53-0	1

Workorder: V48341

In Date: 04/02/2012 Meter Reading: 78,091.00
Close Date: 04/16/2012

Problem?
Engine 45 is leaning to the officers side a few inches. E45

Task performed:	Parts	Quantity
TRUCK NEEDS NEW SPRINGS, WILL MAKE NOTE FOR B-INSPECTION/OR SOONER.	NO PARTS USED	

Workorder: V48509

In Date: 04/07/2012 Meter Reading:
Close Date: 04/19/2012

Problem?
Fan for a/c in front cab of E45 nor working.

Task performed:	Parts	Quantity
1. check blower, remove dash found blower switch and connector melted, replace switch and cut out connector and rewire. replace dash.	ABPN8332229011-3050 SWITCH BLOWER	1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V48762

In Date: 04/19/2012 **Meter Reading:**
Close Date: 04/19/2012

Problem?
Rear compartment of E45 will not stay closed because the latch is loose.

Task performed:	Parts	Quantity
1. check rear compt. door, found screw threads stripped, drill and tap to next size larger, install 3/8 bolts with lock washers and lock tight.	NO PARTS USED	

Workorder: V46510

In Date: 05/03/2012 **Meter Reading:**
Close Date: 05/03/2012

Problem?
TIC is not charging. TIC battery locking mechanism on the handle is broken. Sta 45

Task performed:	Parts	Quantity
1. travel to sta-45	NO PARTS USED	
2. check TIC charger, repair lock on handle, still not charging, trace wiring found broken wire in console, repair wire		
3. travel back to s/shop		

Workorder: V46529

In Date: 05/01/2012 **Meter Reading:**
Close Date: 05/03/2012

Problem?
Slow air brake leak. Sta 45

Task performed:	Parts	Quantity
1. check for air leak, use soap and water to check, found air line fittings on foot valve leaking, replace push on fittings, recheck found air tank drain leaking, replace drain cock valve, recheck no more leaks found at this time..	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V49550

In Date: 05/22/2012 Meter Reading: 79,239.00
Close Date: 05/22/2012

Problem?

driver side headlight inop, E-45

Task performed:

replace driver side headlight, remove torx screws and replace with phillps screws per sta. per sta. officer (did not have tool to remove) give officer another headlight for station

Parts

H6054USE CV TYPE SEALED BEAM

Quantity

2

Workorder: V49293

In Date: 05/11/2012 Meter Reading: 79,003.90
Close Date: 06/01/2012

Problem?

Air leak and buzzer for open doors not working properly E45

Task performed:

REPAIRED AIR LEAK AT DRAIN VALVE.

Parts

NO PARTS USED

Quantity

Workorder: V49735

In Date: 05/30/2012 Meter Reading: 79,527.00
Close Date: 06/01/2012

Problem?

The fuel gauge on the pump panel does not accurately show fuel level when pump is in gear. E 45

Task performed:

RECALBRATED GAUGE WILL MONITOR.

Parts

NO PARTS USED

Quantity

Workorder: V49622

In Date: 05/25/2012 Meter Reading: 79,239.00
Close Date: 06/08/2012

Problem?

Relief valve on E45 not operating properly. Also, right rear, top emergency light next to clearance light is out.

Task performed:

RAN PUMP AND TESTED VALVE ALL TESTED GOOD.

Parts

NO PARTS USED

Quantity



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V49805

In Date: 06/01/2012

Meter Reading: 79,624.00

Close Date: 06/11/2012

Problem?

B INSPECTION E 45

Task performed:

1. B insp.
2. replace missing a/c vent on cab rear a/c
3. red LED lite under d/side cab door inop, replace lite
4. officer side cab door entry lite inop, check lite found wires broken in a post, repair wires
5. air leak, use soap and water to trace out air leak, found air line on governor leaking replace push on fitting, recheck found VPS shifter leaking rebuild shifter
6. replace worn fan belt
7. change cab a/c filters
8. service T case had water in it, possibly from VPS leaking
9. replace missing wheel lug nut covers

Parts

Quantity

50R03ZCRLIGHT LED RED TIR 6	1
5460370530VPS SHIFT KIT 546-0370-53-0	1
607141-05USE 61H01 COPMPARTMENT LIGHT	1
72R31001720 DIFFUSER A/C 3.5 IN	1
78R536078R5360M 2PK FILTER AIR COND	1
ACX-84534LUG NUT COVER PK10	10
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
K080716BELT	1
R90PFILTER FUEL 33231	1

Workorder: V50408

In Date: 06/26/2012

Meter Reading: 80,029.20

Close Date: 07/25/2012

Problem?

The pump panel fuel guage does not accurately show fuel level when in gear. The cab's fuel guage is at 7/8 in road operation and when pump is in gear the panel fuel guage is at 3/8. E 45

Task performed:

RECALBRATE FUEL GAUGE AND RETESTED.

Parts

Quantity

NO PARTS USED

Workorder: V50829

In Date: 07/13/2012

Meter Reading: 80,380.00

Close Date: 07/25/2012

Problem?

Light box will not shut off

Task performed:

1. AIR LEAK - FOUND AND REPAIRED LEAK AT MAIN AIR TANK.
2. RECALBRATED FOAM LEVEL GAUGE AND TESTED.

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V51948

In Date: 08/28/2012

Meter Reading:

Close Date: 08/28/2012

Problem?

The 18v DeWalt drill trigger is not working . e45

Task performed:

went to BC-4 and got them a new drill

Parts

NO PARTS USED

Quantity

Workorder: V51954

In Date: 08/28/2012

Meter Reading: 81,600.00

Close Date: 08/28/2012

Problem?

pump throttle inop, E-45

Task performed:

check pump throttle interlocks for loose wires and water contamination, found water proof connector on pump shift switches corroded, replace both pump shift switches and cut out connectors and install water proof butt connectors, pump throttle now works ok.

Parts

200-2450-00NC SWITCH OK TO PUMP
546-0852-01SWITCH OLD # 200-0020-00

Quantity

1
1

Workorder: V52008

In Date: 08/30/2012

Meter Reading:

Close Date: 09/04/2012

Problem?

passenger rear compartment door will not open. pulled handle to open door and handle stayed in the open position but door did not open. Tried key and that also did not work. E 45

Task performed:

see w/o#52041

Parts

NO PARTS USED

Quantity



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V52041

In Date: 08/30/2012
Close Date: 09/04/2012

Meter Reading: 81,600.00

Problem?

repair rear a/c

Task performed:

1. check rear cab a/c, found compressor clutch locked up, remove air cleaner and hoses, remove a/c compressor, check oil and add correct amount in new compressor and install new compressor, replace dryer, reinstall air cleaner and hoses, evacaute and charge system, check for leaks, found both scharder valves leaking at ports and low side compressor line leaking, evacaute system, replace both scharder valves, cut out 90 deg. fitting on hose to compressor and crimp new fitting on hose, evacaute and recharge system, recheck for leaks, none found. system cools to 29 deg.
2. replace rear cab a/c filter
3. L-3 compt. door will not open, drill out handle to open door, install new door handle and adjust rods.

Parts	Quantity
14996-02D PADDLE HANDLE	1
4411S08-6962BS 90 DEGREE SB1322	1
4412S08-6963BS FITTING A/C	1
576403-3470 COMPRESSOR A/C 5720	2
74R258607-2613A RED DOT DRIER 7127	1
78R536078R5360M 2PK FILTER AIR COND	1

Workorder: V51192

In Date: 07/29/2012
Close Date: 09/14/2012

Meter Reading:

Problem?

Severe air leak in system, with less than 3 hours of engine off the leak was so bad we were unable to respond for a few minutes. Wasnt able to disengage parking brake and then taking a long time to get the air up. E 45

Task performed:

CHKD FOR AIR LEAKS FOUND AND REPAIRED WHERE NEEDED, PUMP LEAKING WATER REPAIRED PUMP COOLER LINE AND RETESTER.

Parts	Quantity
NO PARTS USED	

Workorder: V51385

In Date: 08/06/2012
Close Date: 09/14/2012

Meter Reading: 81,044.00

Problem?

batteries vent fumes

Task performed:

1. REPLACED BATTERIES.

Parts	Quantity
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
HP-31DBATTERY 950CCA HP-31D	4



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V51595

In Date: 08/14/2012 Meter Reading:
Close Date: 09/17/2012

Problem?
Left telescope light on E45 has a burned out bulb.

Task performed:	Parts	Quantity
REPLACED BULBS IN LIGHT.	NO PARTS USED	

Workorder: V52244

In Date: 09/07/2012 Meter Reading:
Close Date: 09/25/2012

Problem?
Drive belt for K12 saw is broken. Asset #10173646. E45

Task performed:	Parts	Quantity
REPLACED BULB IN REAR LIGHTS THAT WERE OUT	H35DSN12BULB 35W DUAL FILAMENT DOME	3
	H35SN12BULB	3
	K-12BELT K12 SAW	1

Workorder: V52403

In Date: 09/15/2012 Meter Reading:
Close Date: 10/16/2012

Problem?
The handle for the left intake valve is missing. e45

Task performed:	Parts	Quantity
QUARTZ LIGHT OUT, REPAIRED WIRING ON LIGHT.	012-1510-05-0KNOB	2
	LB-D30BULB QUARTZ HAL. 12V 150W	3

Workorder: V52917

In Date: 10/08/2012 Meter Reading: 82,739.00
Close Date: 10/26/2012

Problem?
bulb light out for water level guage on pump panel E 45

Task performed:	Parts	Quantity
1. RECALABRATED WATER LEVEL GAUGE AND TESTED.	60R00FRR600 SERIES RED LED W/O FLANGE	1
2. REPLACE LED LIGHT LIGHT ON REAR OF TRUCK		



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V53270

In Date: 10/23/2012 Meter Reading:
Close Date: 11/09/2012

Problem?
door warning light flashing when all doors are secure and closed

Task performed:	Parts	Quantity
DOOR OPEN LIGHT INOP, REWIRED AND REPAIRED GROUND WIRE. AIR LEAK FOUND AND REPAIRED LEAK.	NO PARTS USED	

Workorder: V53828

In Date: 11/16/2012 Meter Reading: 83,054.00
Close Date: 11/28/2012

Problem?
repair air leaks

Task performed:	Parts	Quantity
1. TEST FOR AIR LEAKS.	097-1971-00-05MM SEAL WASHER FOR SPEED SENSOR	1
2. REPLACE CAB AIR BAGS RETEST FOR LEAKS	200-2481-00-0546-3240-00-0 FOAM PUMP SENSOR KIT	1
REPLACE 2 SLOAN VALVES AND 2 FITTINGS ON REAR TANK.	200-2491-00SENSOR HALE HPF FOAM FLOW	1
3. FILL WATER TANK AND TEST FOAM SYSTEM	223-485V91-8301 85 PSI CLOSED 67 OPEN PREEASURE PF	2
DIAGNOSE FAULTY FLOW MOTOR AND FOAM PUMP SENSOR AND REPLACED RETEST.	LML-1102-0023CAB AIR BAG IS4007	2

Workorder: V53543

In Date: 11/05/2012 Meter Reading: 83,054.00
Close Date: 12/10/2012

Problem?
REPAIR SUSPENSION E45

Task performed:	Parts	Quantity
REPAIR SUSPENSION E45.	NO PARTS USED	

Vendor?: TOTAL TRUCK PARTS



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V54253

In Date: 12/06/2012
Close Date: 12/19/2012

Meter Reading: 83,470.00

Problem?
REPLACE REAR TIRES

Task performed:	Parts	Quantity
REPLACE REAR TIRES.	NO PARTS USED	

Vendor?: BOULEVARD TIRE

Workorder: V54107

In Date: 11/30/2012
Close Date: 01/03/2013

Meter Reading:

Problem?
E45 recently had some work done on suspension. When making left turns there is a hard knocking sound. Needs to be checked.
C. Recht

Task performed:	Parts	Quantity
ROAD TESTED FOUND NO NOISE.	NO PARTS USED	

Workorder: V54781

In Date: 01/03/2013
Close Date: 01/14/2013

Meter Reading:

Problem?
TIC is not charging. TIC holder and spare battery. E45

Task performed:	Parts	Quantity
REPAIRED TIC CHARGE. PUMP PANEL AIR HORN INOP, REPAIRED CONNECTION.	NO PARTS USED	

Workorder: V55020

In Date: 01/12/2013
Close Date: 01/14/2013

Meter Reading:

Problem?
D/O seat belt latch broken. repaired by on call mechanic on 1/12/13

Task performed:	Parts	Quantity
DRIVERS SEATBELT INOP, LATCH BROKEN REPLACED SEATBELT.	IMMF11358SEAT BELTS	1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V55212

In Date: 01/10/2013
Close Date: 01/24/2013

Meter Reading: 84,898.00

Problem?

replace front tires

Task performed:

REPLACE FRONT TIRES.

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD TIRE CENTE

Workorder: V54915

In Date: 01/07/2013
Close Date: 01/25/2013

Meter Reading: 84,322.00

Problem?

E45 involved in minor MVA. E45 was struck on front driver wheel and step area. Wheel lugnut covers were broken off. No other apparent damage noted

Task performed:

1. AIR LEAKS - TRACED OUT AIR LEAKS.
2. REPAIRED REAR DOOR.

Parts

NO PARTS USED

Quantity

Workorder: V54939

In Date: 01/08/2013
Close Date: 01/25/2013

Meter Reading:

Problem?

The front tires on E45 need to be replaced. C. R.

Task performed:

1. travel to sta-45, check front tires. found down to wear bar, call c/shop and have new tires installed, travel back to s/shop

Parts

S986AIR GAUGE 160 PSI

Quantity

2

Workorder: V55418

In Date: 01/30/2013
Close Date: 01/30/2013

Meter Reading: 85,179.00

Problem?

Engine loss power, check engine lite on, E-45

Task performed:

1. travel to sta-45, hook up laptop and check for codes, found code 142 and 123 boost pressure, follow unit to south shop to check out further, found boost pressure sensor bad, called c/shop to send down, replase sensor and recheck for codes, no active codes, road test ok

Parts

3348747NX4921497 SENSOR PRESS.

Quantity

1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V55200

In Date: 01/22/2013
Close Date: 02/05/2013

Meter Reading: 84,898.00

Problem?
RRO tire leaking E 45

Task performed:	Parts	Quantity
RRO TIRE LEAKING E-45	NO PARTS USED	

Vendor?: BOULEVARD TIRE CENTE

Workorder: V55051

In Date: 01/14/2013
Close Date: 02/11/2013

Meter Reading:

Problem?
pressure relief valve very slow to engage. Engine 45

Task performed:	Parts	Quantity
1. hurst compt. door will not open, enter through back compt. and remove equipment to gain access to door, open compt. door and repair latch found door latch assy. falling off, install new screws and secure	NO PARTS USED	
2. check relief valve, found to be slow, hook up to hydrant work valve, n/g will need to order a valve kit...		
3. operated valve and tested ok.		

Workorder: V55692

In Date: 02/11/2013
Close Date: 02/11/2013

Meter Reading: 85,557.00

Problem?
engine oil down 4 qts, E-45

Task performed:	Parts	Quantity
1. check oil level, add 4 qts oil	15W40QSYN OIL QT	12

Workorder: V54966

In Date: 01/09/2013
Close Date: 02/12/2013

Meter Reading: 84,322.00

Problem?
Door open alarm buzzer not sounding. Flashes lights in the cab, but no buzzer. Thanks!

Task performed:	Parts	Quantity
AIR HOSE FOR TRUCK DROPPED OFF.	S153BLOW GUN	1
	S777COUPLING NIPPLE	1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V55771

In Date: 02/14/2013
Close Date: 03/15/2013

Meter Reading: 85,654.00

Problem?

One of the brackets from the exhaust system fell off engine. E-45

Task performed:

INSTALLED NEW BRACKET.

Parts	Quantity
35775CLAMP 5 IN	1
357884 IN CLAMP	1
35795CLAMP 6 IN	1

Workorder: V55806

In Date: 02/16/2013
Close Date: 03/15/2013

Meter Reading: 85,707.00

Problem?

E45's exhaust system needs to be checked. It seems that there may be a leak at the manifold.

Task performed:

CHECKED FOR LEAK IN EXHAUST AND FOUND NO LEAKS.

Parts	Quantity
NO PARTS USED	

Workorder: V46302

In Date: 01/04/2012
Close Date: 04/08/2013

Meter Reading:

Problem?

The air brake system loses air pressure after E45 is at station for three hours or more. sta 45

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V46358

In Date: 01/05/2012
Close Date: 04/08/2013

Meter Reading:

Problem?

Battery cover for the TIC on E45 is broken and needs to be replaced. Also, TIC is not charging while in charger. Sta 45

Task performed:

Parts	Quantity
NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V47350

In Date: 02/15/2012 Meter Reading:
Close Date: 04/08/2013

Problem?
right rear upper red light missing only the connector is present. Sta 45

Task performed:	Parts	Quantity
	372000084MARKER LIGHT	2

Workorder: V49347

In Date: 05/15/2012 Meter Reading:
Close Date: 04/08/2013

Problem?
Light box needs to be replaced with new base, behind officers seat.

Task performed:	Parts	Quantity
	NO PARTS USED	

Workorder: V50081

In Date: 06/12/2012 Meter Reading:
Close Date: 04/08/2013

Problem?
Left front turn signal not working on E45.

Task performed:	Parts	Quantity
	NO PARTS USED	

Workorder: V50409

In Date: 06/26/2012 Meter Reading:
Close Date: 04/08/2013

Problem?
Signal light: Front left turn signal is out. Signal light: Rear right upper red flasher in board is out. E45

Task performed:	Parts	Quantity
	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V52802

In Date: 10/02/2012
Close Date: 04/08/2013

Meter Reading: 82,507.00

Problem?

Red TFT nozzle on E45 is not working properly. Needs to be replaced asap. C. R. 5088.....

Task performed:

REPAIRED NOZZLE HOLDER AND NEW STRAP.

Parts

NO PARTS USED

Quantity

Workorder: V53180

In Date: 10/18/2012
Close Date: 04/08/2013

Meter Reading:

Problem?

The air brake system loses air when turned off at the station. A delay in response is occurring due to allowing air pressure to build up. E45

Task performed:

Parts

NO PARTS USED

Quantity

Workorder: V55391

In Date: 01/29/2013
Close Date: 04/18/2013

Meter Reading:

Problem?

Head lamp on E45 needs to be replaced.

Task performed:

Parts

NO PARTS USED

Quantity

Workorder: V56461

In Date: 03/18/2013
Close Date: 04/26/2013

Meter Reading: 86,123.00

Problem?

The left intake is leaking water steadily. Possible valve seats need to be replaced or adjusted. E45

Task performed:

REPLACED VALVE ON SIDE.

Parts

7250000050VALVE SS 2 1/2

Quantity

1



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V57171

In Date: 04/21/2013

Meter Reading:

Close Date: 04/29/2013

Problem?

Capt side last compartment, extracation tray will not slide out. E45

Task performed:

REPAIRED TRAY THAT WAS NOT COMING OUT.

Parts

NO PARTS USED

Quantity



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V55989

In Date: 02/25/2013

Close Date: 04/30/2013

Meter Reading: 86,086.00

Problem?

C INSPECTION E 45

Task performed:

Parts

Quantity



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

1. C insp.	01-026B807-50LINAER CORNER	1
2. found exhaust manifold bolts broken and manifold cracked during insp. remove coolant hoses, turbo hoses, turbo, turbo oil lines, heat up and drill out broken bolts using easy out. install new front and rear exhaust manifold and gaskets, install all new manifold bolts and tourge to spec's	042-0550-00SPRING-VALVE QG RELIEF VALVE	1
3. water leaking in cab from a/c, remove fuse panel cover and blow out a/c drain lines. reinstall hoses to accumulator box, and fuse panel cover	048009000SPEEDCOUNTER PUMP PANEL	1
4. l/side a/c dash vents broken, replace vents	05-17223-000CAP RADIATOR 10 LB	1
5. replace cab a/c filter	073-0011-00PISTON-RELIEF VALVE (QG VALVE)	1
6. l/side pre-connect net broken, install new net	091-39-INDAUTO CHARGER INDICATOR	1
7. r/rear light bar red LED inop, remove lite assy. check wiring, found lite n/g replace LED lite	107796DRYER KIT AD9 -NEW	1
8. struts on booster compt. door inop, replace struts	107800VALVE CHECK AD9	1
9. replace heat sensors on ground ladders	108-12FBEADED CHAIN W/CONN 12	4
10. 2 r/side, 2 l/side rear red LED lites half inop, replace all 4 LED lites	14022-1-5COOLER 14032	1
11. compt. door under r/rear seat broken, repair door and lock	15W40BSYN OIL BULK QTS	30
12. r/side middle lower amber led lite inop, replace lite	2332920005SMASK LENS W/RST BUTTON VDO	1
13. l/side lower front and rear red led lite inop, replace both lites	301-502301-104 FUEL GAUGE	1
14. r/side pump panel lite lens broken, replace lens	3282159LINE TURBO FEED	1
15. relief valve inop, rebuild intake, discharge, and TPM control valves, fouind broken spring in intake valve, found discharge stem frozen, and TPM hard to turn test relief valves on hydrant. all work ok	3519807TURBO GASKET	1
16. RPM counter inop, make up new cable and ends, install new counter,	35200-RLIGHT MARKER LED RED	3
17. foam system inop, recalibrate system, flow foam ok	35200-YLIGHT MARKER LEDAMBER	1
18. replace missing discharge cap chains (all)	372000030BATTERY ON DISPLAY	1
19. service generator	3818824TURBO NUT	4
20. air system leaks down over night, check for leaks, found multiple air leaks, repair all leaks, holds air overnight	39013563901356 EXH.GASKET	1
21. green batt. lite on,on dash inop, replace lite	3920773WASHER DRAIN PLUG	1
22. service p/s	3922794SEAL O RING	2
23. install all 6 tire pressure montior caps	3924147OIL DRAIN PLUG CUMMINS	1
24. replace broken l/side red reflector	3937477MANIFOLD EXHAUST	1
25. replace wiper blades	39374795269779 EXHAUST GASKET C	6
26. service air dryer	3943841EXHAUST MANIFOLD	1
27. found l/rear brake chamber leaking, cut rods to size, replace both rear brake chambers	3944593EXH. MAN. BOLT	12
28. r/rear auto slack adjuster inop, replace both rear auto slack adjusters. set up adjuster's and test. ok	3945252SPACER EXH. MAN.	12
29. found oil leak during insp. clean down engine, run engine, found oil line for turbo leaking, replace hose and o rings	40010140SLACK ADJUSTER WAB-409-10615	2
30. service T case	52-24WIPER BLADES ANCO 24	2
31. found dash gauge cluster broken, replace gauge cluster	5264569DRAIN GASKET 3937706	1
32. hurst tool pull out tray inop, found bent tabs	529008000529-0080-10-0 1 1/4 ANODE KIT	1
	538-1400-00QG VALVE	1
	546-0200-50QD REL.VALVE KIT	1
	546126000TPM/QG HALE REPAIR KIT	1
	60R00FRR600 SERIES RED LED W/O FLANGE	4
	60R00XRRBRAKE/TAILLIGHT LED	2
	6808300074VENT A/C LH	1
	75W90GEAR OIL SYN QT	18
	78R536078R5360M 2PK FILTER AIR COND	1
	800405PURGE VALVE KIT	1
	98032R 41032-3 RED REFLECTOR OVAL REFLECTOR	1
	A2241425020SW ROCKER RETARDER	1
	EAA-8700-90ULIFT SUPPORT GSS6364UL 90LB	2
	FG87904MFG3937557S FILTER P/S NEW STYLE	1



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

straighten tebs, clean and lube tracks
 33. found coolant leak, check and found sight glass leaking, replace sight glass
 34. battery tray will not open, use service truck to pull open tray, clean and lube tracks and work tracks. (frozen)
 35. replace broken retarter switch on dash
 36. drain cooling system, replace transmission cooler, refill coolant. top off transmission. run engine and check for leaks. top off coolant
 37. battery charger indiactor inop, replace indiactor
 38. replace pump andoide
 39. road test vehicle, return to shop, recheck adjustments on rear brakes, fill water tank, run pump and test foam system and relief valves, all systems ok

FGQ79699GASKET-P/S FILTER NEW STYLE	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
LML-1350-0113AIR RIDE VALVE (CAB)	1
MA15445NT3030 STD CHAMBER 30/30	2
R90PFILTER FUEL 33231	1
RWTG1234LED PRESSURE CAP	6
VML-T1413T3248 SIGHT GLASS	1

Workorder: V57138

In Date: 04/19/2013 Meter Reading:
 Close Date: 05/03/2013

Problem?
 DRAIN TUBING FALLING OFF BELOW DRIVERS COMPARTMENT.

Task performed:	Parts	Quantity
REPAIRED ALL DRAIN TUBES.	NO PARTS USED	

Workorder: V57276

In Date: 04/26/2013 Meter Reading:
 Close Date: 05/08/2013

Problem?
 The system leaks down to zero in six hours or less. E45

Task performed:	Parts	Quantity
see w/o#57482	NO PARTS USED	

Workorder: V57482

In Date: 05/04/2013 Meter Reading:
 Close Date: 05/13/2013

Problem?
 Air brake system / tank have severe leak. This is causing considerable delays responding to calls waiting for the air pressure to build up. E45

Task performed:	Parts	Quantity
1. cab air ride leveling valve air leak was found on C inspection, part had to be ordered, part came in brought unit to s/shop to install new valve..	NO PARTS USED	

part charged out to w/o#55989 c insp.



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V57944

In Date: 05/24/2013
Close Date: 05/24/2013

Meter Reading: 88,031.30

Problem?

No start E45

Task performed:

DROVE TO STATION, TRUCK NOT START REPAIRED CONNECTION ON STARTER.

Parts

NO PARTS USED

Quantity

Workorder: V57535

In Date: 05/07/2013
Close Date: 05/31/2013

Meter Reading:

Problem?

Right rear LED light bar - one side is out. E45

Task performed:

- AIR LEAK REPAIRED AIR LEAK AND ROAD TESTED.
- REPLACED HOOD LATCH THAT WAS BROKEN.

Parts

17-14781-000PLASTIC HOOD LATCH
292850BRIDGESTONE 12R22.5 TIRE

Quantity

1
4

Workorder: V57945

In Date: 05/24/2013
Close Date: 06/07/2013

Meter Reading: 88,031.30

Problem?

Replace starter E45

Task performed:

REMOVED AND REPLACED STARTER.

Parts

15W40QSYN OIL QT
82000056808 38MT 12T STARTER

Quantity

12
1

Workorder: V58119

In Date: 06/01/2013
Close Date: 06/07/2013

Meter Reading:

Problem?

right telelight is out. E45

Task performed:

- TURN SIGNALS INOP, FOUND BAD CONNECTION.
- COMPARTMENT LIGHTS OUT, REPAIRED CONNECTION ON RELAY BOARD.
- REAR EMERGENCY LIGHT OUT, REPAIRED P.C BOARD.

Parts

1094KIT-AIR HORN-GROVER
6805450124SWITCH TURN SIGNAL
H27SN12BULB
LB-D30BULB QUARTZ HAL. 12V 150W

Quantity

1
1
4
4



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V58354

In Date: 06/12/2013 Meter Reading:
Close Date: 06/12/2013

Problem?
hose leak near the master drain valve E45

Task performed:	Parts	Quantity
1. check water leak, found line going to thermal relief valve leaking, none in stock, on order, will replace when it comes in, install plug in meantime to stop leak, advised crew.	538-1260-00VALVE THERMAL RELIEF	1

Workorder: V58174

In Date: 06/03/2013 Meter Reading: 88,348.60
Close Date: 06/14/2013

Problem?
teelight was fixed this morning and is out again. possible fuse

Task performed:	Parts	Quantity
1. REPAIRED SPOTLIGHTS AND TESTED. 2. REPAIRED WATER LEAK AT PUMP.	NO PARTS USED	

Workorder: V58295

In Date: 06/10/2013 Meter Reading: 88,470.40
Close Date: 06/21/2013

Problem?
PRESSURE RELIEF VALVE NOT WORKING. OFFICER SIDE TELESCOPIC LIGHT OUT. OFFICER SIDE REAR EMERGENCY LIGHT OUT E 45

Task performed:	Parts	Quantity
1. REAR EMERGENCY LIGHT, WAITING FOR REPAIRS, DUE TO PARTS. 2. PRESSURE RELIEF VALVE INOP, REPAIRED AND TESTED. 3. RIGHT SIDE SPOTLIGHT INOP - REPAIRED. 4. REAR LIGHT OUT - REPLACED PC BOARD.	01-02698572 CH LED FLASHER	1

Workorder: V58606

In Date: 06/21/2013 Meter Reading: 88,757.50
Close Date: 07/02/2013

Problem?
hot pump indicator light is on while engine is in pump. SE@45

Task performed:	Parts	Quantity
TRAVEL TO ST 48 CHECK OUT PUMP OVER HEAT SYSTEM CHECK WIRING AND SWITCH WATER IN PLUG DRY OUT RETEST OK.	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V58753

In Date: 06/28/2013
Close Date: 07/03/2013

Meter Reading: 88,966.80

Problem?

K12 on E45 needs a gasket for fuel cap. It is leaking fuel when in use. Asset # 10173646. Unable to put in IBEM under Fire Equipment. C. R.

Task performed:

TRAVEL TO ST 48 R*R FUEL CAP ON SAW.

Parts

505312226FUEL CAP PARDNERS

Quantity

1

Workorder: V58635

In Date: 06/23/2013
Close Date: 07/05/2013

Meter Reading: 88,828.40

Problem?

A knob from one of the drain valves came off

Task performed:

TRAVEL TO ST 45 R & R DRAIN KNOW AND R & R O-RING.

Parts

012-0010-00KNOB DRAIN

012-1510-05-0KNOB

Quantity

1

1

Workorder: V58834

In Date: 07/03/2013
Close Date: 07/05/2013

Meter Reading: 89,073.80

Problem?

Driver compartment door handle broken E45

Task performed:

DRIVERS COMPARTMENT DOOR INOP/ HANDLE/ GET COMPARTMENT OPEN AND REPLACED HANDLE.

Parts

14996-02D PADDLE HANDLE

Quantity

2

Workorder: V59012

In Date: 07/11/2013
Close Date: 07/11/2013

Meter Reading: 89,209.70

Problem?

check engine lite on, E-45

Task performed:

1. check engine lite on, hook up laptop, check for engine codes, found code 278 14 counts lift pump inactive. but check engine lite is on. called c/shop per Steve R c/shop had alot going on and to keep unit in service...

Parts

NO PARTS USED

Quantity



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V58898

In Date: 07/07/2013 Meter Reading: 89,209.70
Close Date: 07/19/2013

Problem?
K12 saw on E45 not working

Task performed:	Parts	Quantity
REPAIRED K-12 SAW - CLEAN CARB AND TESTED.	NO PARTS USED	

Workorder: V59399

In Date: 07/29/2013 Meter Reading: 89,564.50
Close Date: 08/09/2013

Problem?
E45 no start

Task performed:	Parts	Quantity
FOUND LIFT PUMP GOING BAD. TEMP REPAIRED UNIT LEFT DECISION TO STATION OFFICER ABOUT SWAPING INTO BATILLION SPARE.	NO PARTS USED	

Workorder: V59518

In Date: 08/02/2013 Meter Reading: 89,564.50
Close Date: 08/19/2013

Problem?
Officer side tele light out; pressure relief valve sticks. E45

Task performed:	Parts	Quantity
RAN PUMP AND TESTED RELIEF VALVE AND TESTED OK.	NO PARTS USED	

Workorder: V59714

In Date: 08/10/2013 Meter Reading: 90,045.00
Close Date: 08/19/2013

Problem?
e45 failed vacuum test during pump testing. pressure relief valve is not working and 2 may be related per DO Phil Williams....

Task performed:	Parts	Quantity
TESTED RELIEF VALVE AND TESTED OK.	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V59985

In Date: 08/22/2013
Close Date: 09/11/2013

Meter Reading: 90,045.00

Problem?

Repair fuel system

Task performed:

REPAIR FUEL SYSTEM.

Parts

NO PARTS USED

Quantity

Vendor?: CUMMINS POWER SOUTH

Workorder: V60050

In Date: 09/04/2013
Close Date: 09/12/2013

Meter Reading: 90,045.00

Problem?

ENGINE 45-RELIEF VALVE NOT WORKING-NO RESPONSE AT 250 TEST. FAILED DRY VACUUM TEST.

Task performed:

1. FAILED DRY VACUUM TEST, FOUND VALVES LEAKING. START REBUILDING VALES.
2. FINISH REBUILDING VALVES, CHECK TIMING ON ALL VALVES.
3. TROUBLE SHOOT RELIEF VALVE, INOP REMOVE AND REBUILD VALVE AND SENSOR VALVE REPLACE BOTH SCREENS.
4. RETEST RELIEF VALVE, REINSTALL VALVE DRAIN LINES.

Parts

- 0100080010STRAINER
- 038-1290-00VALVE-SENSING NEEDLE
- 546126000TPM/QG HALE REPAIR KIT
- 5462280020VALVE KIT 2 IN SS VALVE 546-2280-02-0
- 5462290020VALVE KIT SS VALVE 2 1/2 546-2290-02-0
- 91368904 VALVE KIT 1 1/2 IN

Quantity

- 2
- 1
- 1
- 2
- 2
- 1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V60101

In Date: 08/27/2013
Close Date: 09/18/2013

Meter Reading: 90,045.00

Problem?
B inspection E45

Task performed:

1. B-INSPECTION.
2. B-INSPECTION.
3. REMOVE CLEAN AND ADJUST BATTERY SLIDE LATCHES WOULD NOT OPEN.
4. FINISH BE INSPECTION.
5. R&R ENGINE AIR FILTER.
6. REMOVE TURBO OIL RETURN LINE, REPLACE O-RING REINSTALL.
7. REPAIR L/R UPPER BULLET LIGHT AND L/R TOOL/STEP LIGHT.
8. TROUBLE SHOOT TELE LIGHT ALARM GOING ON AND OFF, RESECURE SWITCH AND WIRING.
9. AIR LEAKING DOWN TO 40 PSI OVER NIGHT CAUSED BY LEAKING FITTINGS, REPLACE ALL BAD FITTINGS.
10. RESECURE ALL TOOL HOLDERS.
11. TIGHTEN ALL COMP DOOR LATCHES.

Parts	Quantity
3922794SEAL O RING	1
78R536078R5360M 2PK FILTER AIR COND	1
89BULB	2
CA8193AIR FILTER 46744 WIX	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
R90PFILTER FUEL 33231	1

Workorder: V60503

In Date: 09/14/2013
Close Date: 10/10/2013

Meter Reading: 90,483.80

Problem?
Battery switch on E45 is cracked and needs to be replaced. Also, need several 2-cycle engine oils to make 50:1.

Task performed:

1. REMOVED BATTERY SWITCH AND REPLACED WITH NEW ONE REPAIRED SHORTED WIRES.
2. AIR LEAK. TRACED OUT ALL AIR LEAKS AND REPAIRED.

Parts	Quantity
75908SWITCH BATTERY MASTER 300A	1

Workorder: V60653

In Date: 09/20/2013
Close Date: 10/11/2013

Meter Reading:

Problem?
Brake lights on E45 not working properly. Also, Left rear clearance light not working.

Task performed:

CHECKED BRAKE LIGHTS AND ALL TESTED OK.

Parts	Quantity
NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V60663

In Date: 09/21/2013 Meter Reading:
Close Date: 10/11/2013

Problem?
Turn signals are not working. E45

Task performed:	Parts	Quantity
TURN SIGNALS INOP REPAIRED BAD CONNECTION IN STEERING COLUMN.	NO PARTS USED	

Workorder: V58905

In Date: 07/07/2013 Meter Reading: 90,838.00
Close Date: 10/18/2013

Problem?
K12 on E45 #10173646 is running. We changed the fuel and spark plug. We need a proper fuel cap and gasket. The replacement we recently received does not fit. Also, need a replacement spark plug for back up. C. R.

Task performed:	Parts	Quantity
REPAIRED ON WORK ORDER V58898	NO PARTS USED	

Workorder: V59033

In Date: 07/12/2013 Meter Reading: 90,838.00
Close Date: 10/18/2013

Problem?
Check engine light on. Foam system not working properly. At .5% no foam exiting the nozzle, at 5% the foam barely trickles out of the nozzle.

Task performed:	Parts	Quantity
REPAIRED ON WORK ORDER V60101	NO PARTS USED	

Workorder: V60460

In Date: 09/12/2013 Meter Reading:
Close Date: 03/20/2014

Problem?
K-12 not performing properly E45

Task performed:	Parts	Quantity
WILL BE LOOKED AT ON NEXT INSPECTION.	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V65938

In Date: 04/24/2014
Close Date: 04/24/2014

Meter Reading: 90,838.00

Problem?

A insp.

Task performed:

- 1. A insp.
- 2. rear cab a/c inop. (red dot) low on freon, charge system, check for leak, found schrader vale leaking replace both valves

* had other items to be fixed, called john Murray who called Tommy, Tommy called me and said to deliver truck to sta-47 and he will repair items that are wrong with truck.

Parts

Quantity

NO PARTS USED

Workorder: V66228

In Date: 05/05/2014
Close Date: 05/05/2014

Meter Reading: 91,530.50

Problem?

slow starting

Task performed:

SLOW STARTING- REPAIRED BATTERY CHARGER AND CHARGED BATTERIES.

Parts

Quantity

NO PARTS USED

Workorder: V65953

In Date: 04/24/2014
Close Date: 05/08/2014

Meter Reading:

Problem?

Replace steer tires and L/R/I L/R/O

Task performed:

Replace steer tires and L/R/I L/R/O

Parts

Quantity

NO PARTS USED

Vendor?: ELPEX



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V65952

In Date: 04/24/2014 Meter Reading:
Close Date: 05/13/2014

Problem?
Driver's side 2 1/2" intake coupling is missing a screen. Thanks.

Task performed:	Parts	Quantity
1. INSTALLED NEW 12 VOLT CHARGER FOR TRIP TIX.	NO PARTS USED	
2. INSTALLED NEW 2 1/2 INTAKE STRAINER.		

Workorder: V65962

In Date: 04/24/2014 Meter Reading:
Close Date: 05/13/2014

Problem?
Officer side scene light out. Engine is a Batt spare that is being used at 47 right now.

Task performed:	Parts	Quantity
1. WILL NEED TO HAVE LIGHT REPLACED WORKING AT THIS TIME.	NO PARTS USED	
2. AIR LEAK- REPAIRED AIR LEAK AT PUMP SHIFTOR.		

Workorder: V66363

In Date: 05/09/2014 Meter Reading:
Close Date: 05/13/2014

Problem?
Bacl ledt brake light remains on wether break is applied or not.

Task performed:	Parts	Quantity
BRAKE LIGHT STUCK ON- FOUND PEDAL HAD NO FREE TRAVEL. BRAKE SWITCH CLOSED ALL THE TIME ADJUSTED PEDAL TO HAVE FREE TRAVEL.	NO PARTS USED	

Workorder: V66241

In Date: 05/05/2014 Meter Reading: 91,530.50
Close Date: 05/23/2014

Problem?
primer inop

Task performed:	Parts	Quantity
1. TRACED OUT PROBLEM WITH PRIMER FOUND BAD CONNECTION ON SOLENOID.	NO PARTS USED	
2. AIR LEAKS, REPAIRED ALL AIR LEAKS.		



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V66535

In Date: 05/16/2014
Close Date: 06/10/2014

Meter Reading:

Problem?

Upon Fri. pump backflush, couldn't get the 6" intake on the front bumper to open. Air powered valve not opening???? No sound of air moving when switch on pump panel is moved.

Task performed:

- 1) tested valve and was working at this time.
- 2) traced out problem wiht primer found bad connection.

Parts	Quantity
NO PARTS USED	

Workorder: V66742

In Date: 05/25/2014
Close Date: 06/12/2014

Meter Reading:

Problem?

Batt 4 spare now at station 47 with left brake light out of service.

Task performed:

removed and replaced led light.

Parts	Quantity
60R00XRRBRAKE/TAILLIGHT LED	1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V66826

In Date: 05/29/2014

Meter Reading: 92,249.10

Close Date: 06/19/2014

Problem?

C inspection SBE4

Task performed:

1. C insp
2. a/c vents broken, replace
3. door ajar lite and alarm inop, trace and repair wiring
4. r/side intake drain valve handle broken, repair handle
5. cab marker lites inop, repair broken ground wires, reseal lites
6. front intake not opening, replace air valve
7. low on coolant, pressure test and tighten all hoses, retest hold pressure, replace radiator cap
8. driver door and rear door panels falling off, reattached panels
9. l/side and r/side upper red led lites inop, check wiring repalce 2 ballast
10. hurst tool compt. lite burnt, replace lite
11. hurst tool tray broken, repair tray
12. r/side telescoping broken, remove lite assy, and replace lite head and iring
13. relief valve inop, rebuild intake relief valve
14. driver and rear door window molding falling off, replace both
15. service air dryer
16. service transmission
17. all tire sensors flashing, adjust tire pressure's
18. vehicle loses air over night, repair mulitple air leaks at fittings
19. install new rainbow water level lites on r/side and l/side, rewire and drill new holes

Parts	Quantity
01-0269606-D0LIGHT BALLEST MINI BAR	3
038-1010-01HALE RELIEF VALVE W/ VULCANIZED SEAT	1
042002000SPRING RELIEF VALVE HALE	1
05-17223-000CAP RADIATOR 10 LB	1
073-0190-01PISTON TPM RELIEF VALVE	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
15W40BSYN OIL BULK QTS	24
29526898 29548988 TRANS FILTER ALLISON	1
35103HANGAR EXHAUST	1
3920773WASHER DRAIN PLUG	1
3924147OIL DRAIN PLUG CUMMINS	1
546126000TPM/QG HALE REPAIR KIT	1
61H01LED GROUND LITE CLEAR	1
6808300074VENT A/C LH	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
A1834388002MOLD L/H	1
A1834388003MOLD R/H	1
FCA100-V15LED SCENELIGHT HEAD	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
MJTV4 VALVE AIR CONTROL	1
PSTANKWATER LEVEL LED LIGHT	2
R90PFILTER FUEL 33231	1
TRANSYNDALLISON TRANS FLUID GAL	5

Workorder: V68761

In Date: 08/18/2014

Meter Reading: 92,314.00

Close Date: 08/18/2014

Problem?

replace ing, switch SBE-4

Task performed:

1. could not find keys for engine, no spare keys, needed unit to swap out w/E-42 for pm, replaced ing. switch, fill water tank ,hose off tree leaves on truck,

Parts	Quantity
468438C91IGN SWITCH	1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V68772

In Date: 08/18/2014 Meter Reading:
Close Date: 08/19/2014

Problem?
pressure relief valve not working e42

Task performed:	<u>Parts</u>	<u>Quantity</u>
rebuild intake relief valve, had kit in stock marked DNI	NO PARTS USED	

Workorder: V70373

In Date: 10/22/2014 Meter Reading:
Close Date: 10/23/2014

Problem?
turn signals not working, left or right sides. hazard switch works both sides. E52

Task performed:	<u>Parts</u>	<u>Quantity</u>
repair wire	NO PARTS USED	

Workorder: V69503

In Date: 09/19/2014 Meter Reading: 92,754.00
Close Date: 10/29/2014

Problem?
tray that hurst equipment is on does not slide in like supposed to, have to lift the drawer up while sliding it in, E54

Task performed:	<u>Parts</u>	<u>Quantity</u>
Repaired slide out tray. Repaired tray slide and tested.	NO PARTS USED	

Workorder: V69735

In Date: 09/28/2014 Meter Reading: 92,754.00
Close Date: 10/29/2014

Problem?
Asset (10132059) Hurst hydra fitting bent/leaking also found the metal frame broken. Asset (10126831) Chain saw runs for two minutes, shuts off, and won't restart for 10 minutes. GFI plug inop. E54

Task performed:	<u>Parts</u>	<u>Quantity</u>
Swapped out hurst unit	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V70683

In Date: 11/03/2014

Meter Reading: 93,029.50

Close Date: 11/07/2014

Problem?

A inspection SBE4

Task performed:

1. A inspection.
2. Pump TPM will not work. Remove TPM and found broken O ring valve sticking. Clean surface. Install new TPM valve assembly. Operate unit. Pump operating as to specs.
3. Transmission oil low. No leaks found. Add 2 quarts oil
4. Cab rear A/C charge port fitting leaking. Compressor fitting leaking. Recover freeon and remove low side A/C line. Cut out leaking section, rerimp new charging port and A/C connection. Vacuum system and charge unit.
5. Rear A/C vent register missing. Install replacement register.
6. Fire main radio microphone cable damaged. Remove microphone assembly. Got replacement part from radio shop and install.
7. Generator, RAM fan - Inspect and operate auxiliary unit and tools. Operating as per specs. Hurst tool sp and RAM.
8. Right rear wing light bar assembly LED inoperable. None in stock, discontinued. Research repairable outside vendor - waiting for information from Ed Ehrke. Look for light bar in building 3. No light bar found. Search road truck, found LED and install.
9. Officer's window molding broken. Remove and install new molding.
10. Box light charger in cab damaged. Remove and install new charger.

Parts	Quantity
4411S08-6962BS 90 DEGREE SB1322	1
4579S08-3422BS SPLICE	1
538-0201-02-0QG RELIEF VALVE COMPLETE	1
A1834388003MOLD R/H	1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V70460

In Date: 10/27/2014 Meter Reading: 98,824.00
Close Date: 11/10/2014

Problem?
the small red light on the upper tail left rear is out.

Task performed:	Parts	Quantity
1.Repaired rear tail light and tested	NO PARTS USED	
2. Repaired air leak at main tank		

Workorder: V73052

In Date: 02/10/2015 Meter Reading: 93,521.00
Close Date: 02/11/2015

Problem?
pump shift leaking air, Batt-4 spare

Task performed:	Parts	Quantity
1. pump shift leaking air, remove center console, replace pump shift, still leaks air, remove and rebuild VPS air shift on T case, no more air leaks	538-0180-00SHIFT CONTROL VALVE PUMP ROAD	1
	5460370530VPS SHIFT KIT 546-0370-53-0	1

Workorder: V73278

In Date: 02/19/2015 Meter Reading: 93,521.00
Close Date: 02/19/2015

Problem?
l/side intake valve broke, E-42

Task performed:	Parts	Quantity
repair broken valve open and close mechanism, replace broken pull cord handle on floto-pump	722643.5 IN BALL WATEROUS	1
	9064-3MASTER DRAIN WATEROUS	1
	FRT 66081FREIGHT CHARGE	1
	K681-1WATEROUS KIT	1

Workorder: V73396

In Date: 02/24/2015 Meter Reading:
Close Date: 03/02/2015

Problem?
Passenger side spot light broke. E42

Task performed:	Parts	Quantity
quartz lite base broken off, remove lite assy, replace base and re-wire	NO PARTS USED	

* had base in stock as DNI



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V73465

In Date: 02/26/2015 Meter Reading:
Close Date: 03/02/2015

Problem?

The rear light bar bolt is loose causing it to hang down. If it continues to loosen, the light bar and rear marker light might fall off.

Task performed:	<u>Parts</u>	<u>Quantity</u>
r/rear upper lite bar broken, remove staton and replace bolts	NO PARTS USED	

Workorder: V73869

In Date: 03/13/2015 Meter Reading:
Close Date: 03/16/2015

Problem?

The rear light bar on the passenger side is hanging by one bolt. It appears the metal where the screw goes in is torn from wear and tear. I am afraid the entire light bar is going to fall off.

Task performed:	<u>Parts</u>	<u>Quantity</u>
drill new holes and rethread to next size bigger	NO PARTS USED	

Workorder: V73905

In Date: 03/16/2015 Meter Reading:
Close Date: 03/17/2015

Problem?

right side light bar needs to be tighten e42

Task performed:	<u>Parts</u>	<u>Quantity</u>
repaired on w/o#73465	NO PARTS USED	

Workorder: V73904

In Date: 03/16/2015 Meter Reading:
Close Date: 03/26/2015

Problem?

low tire tread on left rear driver side e42

Task performed:	<u>Parts</u>	<u>Quantity</u>
replaced LRIO tire	NO PARTS USED	

Vendor?: BOULEVARD



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V74322

In Date: 03/31/2015
Close Date: 03/31/2015

Meter Reading: 95,533.70

Problem?
REPLACE R/REAR TIRES

Task performed:	<u>Parts</u>	<u>Quantity</u>
	NO PARTS USED	

Vendor?: BOULEVARD

Workorder: V73689

In Date: 03/06/2015
Close Date: 04/21/2015

Meter Reading:

Problem?
When truck hook up to hydrant relief valve will not shut off. when tank to pump is open it works.

Task performed:	<u>Parts</u>	<u>Quantity</u>
	NO PARTS USED	

Workorder: V73690

In Date: 03/06/2015
Close Date: 04/21/2015

Meter Reading:

Problem?
drivers side indicator light is out.

Task performed:	<u>Parts</u>	<u>Quantity</u>
	NO PARTS USED	

Workorder: V73791

In Date: 03/10/2015
Close Date: 04/21/2015

Meter Reading:

Problem?
LEFT TELESCOPE LIGHT IS OUT at 42

Task performed:	<u>Parts</u>	<u>Quantity</u>
	1141BULB	1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155557

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V73888

In Date: 03/15/2015 Meter Reading:
Close Date: 04/21/2015

Problem?
Left tele spot light burnt out. E42

Task performed:	Parts	Quantity
	NO PARTS USED	

Workorder: V73901

In Date: 03/16/2015 Meter Reading:
Close Date: 04/21/2015

Problem?
lights out left side pump panel e42

Task performed:	Parts	Quantity
	NO PARTS USED	

Workorder: V74445

In Date: 04/06/2015 Meter Reading: 95,666.80
Close Date: 04/21/2015

Problem?
air leak

Task performed:	Parts	Quantity
1. Traced out air leak and repaired drain valve on air tank.	15W40BSYN OIL BULK QTS	38
	75W90GEAR OIL SYN QT	24
	PL-11005 WATERWAY RELIEF VALVE	1

Workorder: V73735

In Date: 03/18/2015 Meter Reading:
Close Date: 04/30/2015

Problem?
SIAMESE APPLIANCE HANDLE BROKE OFF DURING TRAINING... E41

Task performed:	Parts	Quantity
1. Repaired handle on side pump panel.	NO PARTS USED	



Palm Beach County Fire Rescue

Fleet Maintenance Asset History

Asset: (10155557) 2004 - FERRARA FL80 1250 Gpm Pumper

10155557

CSHOP-2015-1234

Comments: **REAR BRAKES NOT ADJUSTING EVENLY SBE4**

Date Opened: 6-17-2015 Date Finished: 6-23-2015 Meter 1 Reading: 95,737

TASKS PERFORMED

Q PARTS

REAR BRAKE DRUMS	2	9IP; USE XK4034707QPM QPLUS BRAKE SHOES
BRAKES	2	BRAKE; REAR BRAKE DRUMS

CSHOP-2015-1546

Comments: **E29 PASS SIDE REAR TOP EMER LIGHT OUT DRIVERS SIDE TELE SCENE LIGHT OUT**

Date Opened: 7-6-2015 Date Finished: 7-8-2015 Meter 1 Reading: 95,737

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER LIGHTING SYSTEM AIR CONDITIONING	1	LIGHT; LED SCENELIGHT HEAD
---------------------------------------------------------------------	---	----------------------------

CSHOP-2015-1681

Comments: **REAR AC HOT FRONT WARM BURNING SMELL IN CAB SPARE ENGINE AT 29**

Date Opened: 7-9-2015 Date Finished: 7-23-2015 Meter 1 Reading: 95,737

TASKS PERFORMED

NO PARTS USED

AIR CONDITIONING

CSHOP-2015-1782

Comments: **"A" INSPECTION**

Date Opened: 7-16-2015 Date Finished: 7-29-2015 Meter 1 Reading: 96,264

REAR A/C BLOWS WARM & COMPRESSOR DOESN`T ENGAGE

TASKS PERFORMED

Q PARTS

A INSPECTION	4	BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY
OIL	4	BATTERY; BATTERY 950CCA HP-31D
LIGHTING SYSTEM	1	COVER; OVAL AUTO EJECT COVER
BATTERY TRAY	1	ASSEMBLY; MCFLED2R STANTION ASSBLY
BATTERY	2	LIGHT; LINAER CORNER
AUTO-EJECT	1	FILTER; 78R5360M 2PK FILTER AIR COND
AIR SYSTEM	1	VALVE; 8915 VALVE CORE A/C 3544706C1
LIGHT BAR	1	9IP; 08-3422BS SPLICE
BODY EXTERIOR	2	A/C; 08-6962BS 90 DEGREE SB1322
AIR CONDITIONING		

Asset Work Order History 1015557

CSHOP-2015-2208

Comments: **QUARTZ LIGHT INDICATOR ON**
Date Opened: 8-7-2015 Date Finished 8-7-2015 Meter 1 Reading: 96,327

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL

CSHOP-2015-2450

Comments: **SBE4 AT 46 HAS DOOR ALARM**
Date Opened: 8-24-2015 Date Finished 9-8-2015 Meter 1 Reading: 96,622

TASKS PERFORMED

NO PARTS USED

ALARM-BUZZER-WARNING LIGHT

CSHOP-2015-2648

Comments: **WINDOWS LOOSE IN TRACKS**
Date Opened: 9-1-2015 Date Finished 9-2-2015 Meter 1 Reading: 96,622

TASKS PERFORMED

Q PARTS

DOOR GLASS

4 9IP; 673-720-00-54 SEAL WINDOW

CSHOP-2015-2658

Comments: **A INSPECTION**
Date Opened: 9-2-2015 Date Finished 9-2-2015 Meter 1 Reading: 96,622

TASKS PERFORMED

NO PARTS USED

A INSPECTION

CSHOP-2015-2963

Comments: **INSTALL TIC CHARGER BASE IN BATT 4 SPARE BEING USED AT ST 47**
Date Opened: 9-17-2015 Date Finished 10-7-2015 Meter 1 Reading: 97,775

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
INSTRUMENTS-GAUGES-METERS
AIR CONDITIONING

CSHOP-2016-1166

Comments: **SPARE BATT 4 ENGINE NO START AT ST46**
Date Opened: 3-11-2016 Date Finished 3-11-2016 Meter 1 Reading: 98,282

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
ELECTRICAL

Asset Work Order History 1015557

CSHOP-2016-1186

Comments: **A INSPECTION**

Date Opened: 3-11-2016

Date Finished

3-22-2016

Meter 1 Reading:

98,282

TASKS PERFORMED

Q PARTS

A INSPECTION

1 KNOB; KNOB DRAIN
1 BULB; BULB
4 FLUID; SYN OIL BULK QTS

CSHOP-2016-1941

Comments: **TICKET MADE TO CHARGE OUT PART FOR E41 CHAINSAW**

Date Opened: 4-25-2016

Date Finished

4-27-2016

Meter 1 Reading:

100,342

TASKS PERFORMED

Q PARTS

FIRE FIGHTING EQUIPMENT

1 STARTER; PARTNER STARTER PULLEY

CSHOP-2016-1989

Comments: **E41**

Date Opened: 4-27-2016

Date Finished

4-27-2016

Meter 1 Reading:

100,342

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

Service Requests:

04/27/2016

ENGINE / 19: LOOSE / REPAIR
LEAKING OIL ONTO BAY FLOOR

CSHOP-2016-2470

Comments: **REPLACED FRONT TIRES LABOR ONLY**

Date Opened: 5-23-2016

Date Finished

5-23-2016

Meter 1 Reading:

101,367

TASKS PERFORMED

NO PARTS USED

FRONT TIRES

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2016-2486

Comments: **C INSPECTION**

Date Opened: 5-23-2016

Date Finished

5-25-2016

Meter 1 Reading:

101,434

TASKS PERFORMED

Q PARTS

PM SERVICE C

25 FLUID; SYN OIL BULK QTS
1 FILTER; FILTER FUEL 33231
1 PLUG; OIL DRAIN PLUG CUMMINS
1 FILTER; FILTER FUEL WIX 33422 PS8689 FRAM
1 9IP; WASHER
1 FILTER; 24070 WIX FILTER WATER
1 FILTER; OIL FILTER 51748
1 FILTER; AIR FILTER 46744 WIX

Asset Work Order History 1015557

CSHOP-2016-2513

Comments: **PM FOLLOW UPS**

Date Opened: 5-25-2016

Date Finished

7-1-2016

Meter 1 Reading:

101,434

TASKS PERFORMED

Q PARTS

FOAM SYSTEM	1	NEWPART; HOSE & FITTING
FIRE FIGHTING EQUIPMENT	1	FILTER; FUEL FILTER 33001
PUMP PANEL	1	LIGHT; HALE RED INDICATOR LED
RELIEF VALVE FIRE PUMP	1	NEWPART; MASTER PRESSURE GAUGE
PRIMING PUMP FIRE PUMP	1	PUMP; TPM/QG HALE REPAIR KIT
FIRE PUMP	1	ORING; ORING KIT
EQUIPMENT MOUNTING BRACKETS	5	CHAIN; BEADED CHAIN W/CONN 12
HOSE BED BODY	1	HANDLE; SVS HANDLE 6.75
CROSSWAY BODY	1	PUMP; SC5025 SUCTION SCREEN
SIDE COMPARTMENT BODY	2	STRAINER; STRAINER
FIRE APPARATUS	1	9IP; O-RING FOR HALE FOAM PUMP
REAR DOOR	1	VALVE; VALVE KIT SS VALVE 2 1/2 546-2290-02-0
DOOR PROP CYLINDER	1	VALVE; VALVE KIT SS VALVE 2 1/2 546-2290-02-0
WIPER BLADES	2	9IP; SHORT SENSOR GEARS
WIPERS-WASHER	1	MOUNT; LPVM-5 SM MOUNT
REPAIR FROM PM - FOAM SYS	1	ORING; ORING KIT
REPAIR FROM PM - FIRE PUMP SYS	1	VALVE; VALVE KIT SS VALVE 2 1/2 546-2290-02-0
REPAIR FROM PM - GROUND LADDERS	1	VALVE; 8907 VALVE KIT 3 IN AKRON
FUEL TANK	1	VALVE; 8907 VALVE KIT 3 IN AKRON
EXHAUST SYSTEM	1	PUMP; TPM/QG HALE REPAIR KIT
COOLING SYSTEM	1	SWITCH; NC SWITCH OK TO PUMP
OIL FILTER HOUSING	2	VALVE; 8904 VALVE KIT 1 1/2 IN
INSTRUMENT PANEL LIGHTS	2	9IP; SEAL SVS DRAIN VALVE
DOME LIGHTS	1	9IP; VALVE SENSING SV HALE
LICENSE PLATE LIGHTS	1	WINDOW; MOLD L/H
LENS	2	WIPER; WIPER BLADES ANCO 24
PARK-CLEARANCE LIGHTS	1	9IP; TEE PLASTIC
REPAIR FROM PM - POWER STEERING	20	DECAL; LADDER OUT OF SERVICE STICKER
ELECTRICAL	1	EXHAUST; CHROME STACK 24 IN 4 IN
CABLE	1	9IP; PLUG RAD. DRAIN
TRANSFER CASE	8	FLUID; COOLANT ANTIFREEZE GAL
TRANSMISSION	1	9IP; GASKET 4942874
REPAIR FROM PM - BELTS	1	SWITCH; NC SWITCH/BRACKT
REPAIR FROM PM - DECALS/CLEANLINESS	1	9IP; 4 IN ROUND LED
AIR DRIER	1	LIGHT; LIGHT MARKER LED RED
AIR SYSTEM	1	9IP; GASKET-P/S FILTER NEW STYLE
SWITCH	1	FLUID; ALLISON TRANS FLUID GAL
AIR HORN	1	FILTER; FG3939557S FILTER P/S NEW STYLE
SAFTEY-EMERGENCY EQUIPMENT	1	9IP; SPEEDCOUNTER PUMP PANEL
DOOR STRIKER PLATE	8	GEAR; GEAR OIL SYN QT
DOOR WEATHER MOLDING	1	BELT; BELT
DOOR HINGE-PINS-BUSHINGS	1	BELT; BELT
SEAT BELTS	1	BELT; BELT
SEAT REAR	2	EMBLEM; FRONT AND BACK PLACARD
CAB-INTERIOR ACCESSORIES	2	EMBLEM; LARGE SIDE PLACARD
ALARM-BUZZER-WARNING LIGHT	1	DRYER; DRYER KIT AD9 -NEW
A/C FILTER SCREENS	1	VALVE; PURGE VALVE KIT
QUALITY CHECK-REPAIRS	1	SWITCH; 82-2106 TOGGLE GUARD
AIR CONDITIONING	1	BRACKET; 244770R1 HORN SUPPORT BRKT
	2	SEAL; SEAL DOOR
	1	BRAKE; BRAKE PEDAL PAD
	1	FILTER; 78R5360M 2PK FILTER AIR COND
	1	9IP; 1720 DIFFUSER A/C 3.5 IN

Asset Work Order History 10155557

CSHOP-2016-302

Comments: **INSTALL TIC CHARGER IN BATT 4 SPARE ENGINE AT ST45**

Date Opened: 1-21-2016 Date Finished 1-29-2016 Meter 1 Reading: 98,282

TASKS PERFORMED

NO PARTS USED

SAFTEY-EMERGENCY EQUIPMENT

CSHOP-2016-3450

Date Opened: 7-18-2016 Date Finished 7-18-2016 Meter 1 Reading: 101,434

TASKS PERFORMED

NO PARTS USED

HOSE BED BODY

VENDOR? CENTRAL AUTO TRIM CO.

CSHOP-2016-3596

Comments: **REPLACE MAN SAVERS LEFT REAR WHEEL SEAL LEAKING LOUD POPPING NOISE FROM FRONT END ON TURNS**

Date Opened: 7-28-2016 Date Finished 7-29-2016 Meter 1 Reading: 101,494

TASKS PERFORMED

Q PARTS

REAR HUB SEAL-GASKET	1	GASKET; GASKET AXLE FL80 R002435
FRONT SPRING	1	9IP; SEAL
SAFTEY-EMERGENCY EQUIPMENT	2	COVER; MANSAYER COVER
INTERIOR TRIM-MOLDINGS-UPHOLS	-2	COVER; MANSAYER COVER
QUALITY CHECK-REPAIRS	2	COVER; MANSAYER COVER
	2	9IP; MOLD R/H
	1	WINDOW; MOLD L/H

CSHOP-2016-3865

Comments: **SAFETY PAD NOT CHARGING**

Date Opened: 8-8-2016 Date Finished 9-6-2016 Meter 1 Reading: 102,880

TASKS PERFORMED

Q PARTS

HEADLIGHTS LOW BEAM	2	LIGHT; HEADLIGHT EXTRA BRIGHT
CAB-INTERIOR ACCESSORIES		

Service Requests:

08/08/2016 SERVICE REQUEST / 19: LOOSE / REPAIR
SAFETY PAD WONT CHARGE WHILE ENGINE IS OFF

Asset Work Order History 1015557

CSHOP-2016-463

Comments: **E45**

Date Opened: 1-29-2016

Date Finished

2-16-2016

Meter 1 Reading:

98,282

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS

Service Requests:

01/29/2016

SERVICE REQUEST / 19: LOOSE / REPAIR

VENTILATION FAN WILL NOT START. CHECKED ALL LEVELS. UNIT STILL WILL NOT START.

CSHOP-2016-476

Comments: **SPARE ENGINE AT 42 RIGHT HEADLIGHT OUT**

Date Opened: 2-1-2016

Date Finished

2-9-2016

Meter 1 Reading:

98,282

TASKS PERFORMED

Q PARTS

HEADLIGHTS LOW BEAM

2 LIGHT; HEADLIGHT EXTRA BRIGHT

Service Requests:

01/31/2016

LIGHTS / 19: LOOSE / REPAIR

RIGHT HEAD LIGHT IS OUT

01/31/2016

LIGHTS / 19: LOOSE / REPAIR

RIGHT FRONT HEAD LIGHT IS OUT

CSHOP-2016-4928

Date Opened: 10-17-2016

Date Finished

10-20-2016

Meter 1 Reading:

104,310

TASKS PERFORMED

Q PARTS

AIR SYSTEM

INSTRUMENTS-GAUGES-METERS

1 PUMP; VPS SHIFT KIT 546-0370-53-0

Service Requests:

10/16/2016

AIR RIDE / 19: LOOSE / REPAIR

AIR RIDE ISSUE THE "LOW AIR" VISIBLE SIGNAL AND AUDIBLE ALARM SOUND EACH TIME TRUCK IS STARTED EVEN WHEN TRUCK IS CONNECTED TO SHORE POWER. THE TOP AIR GAUGE READS BELOW 40 PSI UPON START. THE PROBLEM TAKES ABOUT 30 SECONDS TO RESOLVE ITSELF EACH TIME.

CSHOP-2016-5357

Date Opened: 11-16-2016

Date Finished

11-17-2016

Meter 1 Reading:

104,761

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS

AIR SYSTEM

Asset Work Order History 1015557

CSHOP-2016-5384

Comments: **BATT4 SPARE AT ST52**

Date Opened: 11-17-2016 Date Finished 12-2-2016 Meter 1 Reading: 104,761

TASKS PERFORMED

Q PARTS

DIAGNOSE ELECTRICAL
SIREN 1 SIREN; SIREN

Service Requests:

11/17/2016 BRAKES / 19: LOOSE / REPAIR
BRAKE ISSUES- SIGNIFICANT AIR LEAK. BRAKES WILL NOT RELEASE WITHOUT IDLING FOR EXTENDED PERIOD OF TIME

11/29/2016 ALARMS / 19: LOOSE / REPAIR
ALARM SIGNALS SIRENS NOT WORKING CUT IN AND OUT MAYBE A SHORT

CSHOP-2017-1695

Date Opened: 3-20-2017 Date Finished 4-14-2017 Meter 1 Reading: 106,451

TASKS PERFORMED

Q PARTS

CONTROL VALVE FIRE PUMP 1 5TN; HALE DIAPHRAM
RELIEF VALVE FIRE PUMP 1 PUMP; TPM/QG HALE REPAIR KIT
HOSE BED BODY 1 5SC; ROLLER
SIDE COMPARTMENT BODY 1 NONSTOCK; FREIGHT CHARGE
FIRE APPARATUS 1 5SC; SLIDE BAR TFT
PARK-CLEARANCE LIGHTS 1 LIGHT; MARKER LIGHT
QUARTZ LIGHT 1 LIGHT; MARKER LIGHT
LIGHTING SYSTEM 1 9IP; MARKER LIGHT MOUNTING PLATE
BATTERY 1 LIGHT; CHROME MARKER LIGHT MOUNT
AIR SYSTEM 1 LIGHT; CHROME MARKER LIGHT MOUNT
STROBE LIGHTS 1 9IP; BULB
DOOR STRIKER PLATE 4 1AD; BATTERY 31 SERIES
ALARM-BUZZER-WARNING LIGHT 1 9HY; GUAGE
A/C FILTER SCREENS 1 9IP; DRAIN COCK
1 VALVE; 90555409 VALVE CHECK PRESSURE PROTECTED
1 LIGHT; LIGHT LED RED TIR 6
1 FILTER; 78R5360M 2PK FILTER AIR COND

Service Requests:

03/19/2017 SERVICE REQUEST / 12: BROKEN / REPAIR
DECK GUN ON SPARE ENGINE IS LOCKED IN THE FULLY EXTENDED POSITION...WILL NOT RETRACT

CSHOP-2017-1743

Comments: **B INSPECTION CHANGE OIL AND FILTERS**

Date Opened: 3-22-2017 Date Finished 3-22-2017 Meter 1 Reading: 106,435

TASKS PERFORMED

Q PARTS

PM SERVICE B 1 FIL; FUEL WATER SEPARATOR
4 9OC; COOLANT
1 FIL; NAPAGOLD OIL FILTER
1 FIL; NAPAGOLD FUEL FILTER
23 9OC; SYN 15W40

Asset Work Order History 1015557

CSHOP-2017-2548

Date Opened: 5-1-2017 Date Finished 5-3-2017 Meter 1 Reading: 107,158

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM

1 LMP; HALOGEN LAMP

Service Requests:

05/01/2017 LIGHTS / 18: LEAKING / REPAIR
LEFT HEADLIGHT NOT WORKING.

CSHOP-2017-3480

Date Opened: 6-12-2017 Date Finished 6-12-2017 Meter 1 Reading: 108,477

TASKS PERFORMED

NO PARTS USED

COMMERCIAL WORK - OUTSIDE AGENCY

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2017-4229

Date Opened: 7-20-2017 Date Finished 7-26-2017 Meter 1 Reading: 109,657

TASKS PERFORMED

Q PARTS

SAFTEY-EMERGENCY EQUIPMENT

26 9AP; HEAT SENSOR LADDER LABELS

CSHOP-2017-4381

Date Opened: 7-28-2017 Date Finished 7-28-2017 Meter 1 Reading: 109,706

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS

Service Requests:

07/28/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
SPARE BATT 4 ENGINE (CURRENTLY IN USE AS E-47) HAS A WATER LEAK FROM THE MASTER DRAIN (DRIVER'S SIDE
BELOW THE PUMP PANEL)

CSHOP-2017-5378

Comments: **E41**

Date Opened: 9-15-2017 Date Finished 9-18-2017 Meter 1 Reading: 110,247

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

Service Requests:

09/15/2017 AIR RIDE / 18: LEAKING / REPAIR
AIR LEAK, AFTER SITTING FOR A WHILE IT NEEDS YOU HAVE TO WAIT FOR AIRBRAKES TO REFILL

Asset Work Order History 1015557

CSHOP-2017-5586

Date Opened: 9-26-2017 Date Finished 9-26-2017 Meter 1 Reading: 110,247

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2017-5655

Date Opened: 9-28-2017 Date Finished 10-4-2017 Meter 1 Reading: 110,598

TASKS PERFORMED

NO PARTS USED

CONTROL VALVE

Service Requests:

09/28/2017 SERVICE REQUEST / 17: INSUFFICIENT LUBRICANT / LUBRICATE
DISCHARGE 3 HAS NO LUBRICANT AND BARELY MOVES NOT ALLOWING FOR EASY DISCHARGE OF WATER.

CSHOP-2017-6489

Date Opened: 11-9-2017 Date Finished 12-12-2017 Meter 1 Reading: 112,007

TASKS PERFORMED

Q PARTS

AIR SYSTEM

1 TWD; GOVERNOR
1 5TN; VPS SHIFT CONTROL PUMP KIT
1 5TN; VPS CYLINDER
1 5TN; VPS GEARSHAFT KIT
1 TWD; WILLIAM
1 9IP; VALVE PARKING BRK.

Service Requests:

11/09/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
AIR SYSTEM LEAK. EXTENDED RESPONSE TIMES (AVL) WAITING FOR AIR TO BUILD UP

CSHOP-2017-658

Comments: **SPARE BAT 4 ENGINE AT 42 AIR LEAK**

Date Opened: 1-31-2017 Date Finished 3-2-2017 Meter 1 Reading: 106,782

TASKS PERFORMED

Q PARTS

AIR SYSTEM

1 STARTER; PARTNER STARTER PULLEY
1 9AP; HUSQ RETURN SPRING

Service Requests:

01/30/2017 SERVICE REQUEST / 18: LEAKING / REPAIR

01/31/2017 ENGINE / 18: LEAKING / REPAIR
DISCHARGE #4 LEVER (PUMP PANEL) MALFUNCTIONING ENGINE42 SPARE

Asset Work Order History 1015557

CSHOP-2017-678

Comments: **SPARE BATT 4 ENGINE AT 42**

Date Opened: 2-1-2017 Date Finished 2-14-2017 Meter 1 Reading: 106,782

TASKS PERFORMED

Q PARTS

FIRE PUMP
AIR SYSTEM

1 9IP; 200-2262-50 SWITCH-PROXIMITY QG VALVE

Service Requests:

01/31/2017 SERVICE REQUEST / 19: LOOSE / REPAIR
DISCHARGE #4 DOES NOT FUNCTION. THE ROD THAT CONNECTS THE LEVER TO THE PUMP IS NOT ATTACHED TO THE PUMP.

01/31/2017 SERVICE REQUEST / 19: LOOSE / REPAIR
PRESSURE RELIEF VALVE LIGHT DOES NOT FUNCTION/DOES NOT LIGHT UP.

01/31/2017 SERVICE REQUEST / 19: LOOSE / REPAIR
BOX LIGHTS ARE NOT FUNCTIONING/CAN NOT DETERMINE IF THE VEHICLE IS CHARGING THE LIGHTS OR NOT.

01/31/2017 BRAKES / 19: LOOSE / REPAIR
WHILE RESPONDING TO A MOTOR VEHICLE ACCIDENT/CAR VS. MOTORCYCLE, E42 WAS DELAYED IN ITS RESPONSE APPROX. 2 MINUTES DUE TO LOW AIR PRESSURE PREVENTING THE BRAKES FROM RELEASING.

02/01/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
K12 SPRING RECOIL FOR PULL CORD

CSHOP-2017-775

Date Opened: 2-7-2017 Date Finished 2-7-2017 Meter 1 Reading: 105,783

TASKS PERFORMED

NO PARTS USED

BRAKES

Service Requests:

02/06/2017 BRAKES / 19: LOOSE / REPAIR
WHILE RETURNING BACK TO STATION FROM A CALL THE VEHICLE, WHILE LIGHTLY DEPRESSING THE BRAKE PEDAL, LOCKED UP ITS' BRAKES FOR A HALF SECOND, THEN RETURNED TO NORMAL AFTER INSTANTLY RELEASING THE BRAKE PEDAL.

CSHOP-2017-818

Comments: **SPARE BAT 4 ENGINE AT 42**

Date Opened: 2-9-2017 Date Finished 2-9-2017 Meter 1 Reading: 105,889

TASKS PERFORMED

NO PARTS USED

AUTO-EJECT
DIAGNOSE ELECTRICAL

Service Requests:

02/08/2017 BODY / 18: LEAKING / REPAIR
SHORE POWER LINE WILL NOT AUTO EJECT WHEN THE VEHICLE IS TURNED ON.

Asset Work Order History 1015557

CSHOP-2018-1836

Comments: **E45**

Date Opened: 4-2-2018

Date Finished

4-3-2018

Meter 1 Reading:

112,593

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
BODY EXTERIOR

Service Requests:

03/31/2018

SERVICE REQUEST / 18: LEAKING / REPAIR

SHELF ON REAR OFFICERS SIDE(EXTRICATION) ABOUT TO FAIL, NEEDS REINFORCING

CSHOP-2018-1919

Date Opened: 4-5-2018

Date Finished

6-5-2018

Meter 1 Reading:

113,100

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE PUMP
CANOPY
WIPERS-WASHER
HOSE LOWER
LIGHTING SYSTEM
ELECTRICAL
FRONT TIRES
BRAKES
AIR SYSTEM

3	5TF; CUP SEAL
1	5SC; GAUGE, CROSSFIRE
2	5SC; GAUGE, CROSSFIRE
3	9HY; SEAL
1	9IP; VALVE KIT SS 546-2270-02-0
1	5AB; 1.5 BALL KIT
-1	5AB; 1.5 BALL KIT
1	5TN; TPM/QG HALE REPAIR KIT
1	5TN; TPM/QG HALE REPAIR KIT
1	5AB; 3- 3.5 BALL KIT COMPOSITE
1	5AB; 3- 3.5 BALL KIT COMPOSITE
1	5AB; 3- 3.5 BALL KIT COMPOSITE
1	9IP; KNOB DRAIN
3	5TN; 2.5" VALVE REPAIR KIT
2	9HY; 4" VIC SEAL
1	5AB; 2.5 BALL KIT COMPOSITE
3	9IP; VALVE KIT SS VALVE 3 IN
-1	5AB; 2.5 BALL KIT COMPOSITE
3	9IP; SEAL
2	1AN; WIPER BLADES
1	2FL; LOWER RAD HOSE
1	2FL; HOSE
1	PAF; ANTIFRZ
1	LMP; HALOGEN BULB
2	2FL; AUTOMATIC SLACK ADJUSTER
2	TWD; BRAKE DRUM
2	MBI; GRIP/KIT

CSHOP-2018-1929

Date Opened: 4-6-2018

Date Finished

5-10-2018

Meter 1 Reading:

112,825

TASKS PERFORMED

Q PARTS

PM SERVICE C

1	FIL; NAPAGOLD FUEL FILTER
1	FIL; NAPAGOLD OIL FILTER
1	FIL; NAPA COOLANT FILTER
1	FIL; NAPAGOLD AIR FILTER

Asset Work Order History 1015557

CSHOP-2018-3173

Date Opened: 6-7-2018 Date Finished 8-7-2018 Meter 1 Reading: 113,857

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
RELIEF VALVE FIRE PUMP
FUEL SYSTEM

1 9IP; SPRING RELIEF VALVE HALE
1 9IP; 200-2262-50 SWITCH-PROXIMITY QG VALVE

CSHOP-2018-4496

Date Opened: 8-13-2018 Date Finished 8-21-2018 Meter 1 Reading: 114,449

TASKS PERFORMED

NO PARTS USED

FOAM SYSTEM

Service Requests:

08/13/2018 SERVICE REQUEST / 12: BROKEN / REPAIR
TYPE PROBLEM INTO DESCRIPTION: INTERNAL FOAM SYSTEM NOT FUNCTIONING. LIGHTS ON FOAM SYSTEM LIGHT UP BUT NO FOAM APPEARS TO FLOW.

CSHOP-2018-4717

Date Opened: 8-21-2018 Date Finished 11-29-2018 Meter 1 Reading: 114,849

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
UL REPAIRS
BATTERY
CRANKING SYSTEM

1 FRT
1 8AM; STARTER
1 1AD; BATTERY

CSHOP-2018-6343

Comments: E54

Date Opened: 11-7-2018 Date Finished 11-13-2018 Meter 1 Reading: 114,849

TASKS PERFORMED

NO PARTS USED

SAFTEY-EMERGENCY EQUIPMENT

Service Requests:

11/05/2018 SERVICE REQUEST / 18: LEAKING / REPAIR
DRAEGER X-AM2500 4-GAS MONITOR "CH4 LEL%" SENSOR HAS AN ERROR AND HAS AN "X" IN THE UPPER RIGHT CORNER OF THE SCREEN. UNABLE TO BUMP TEST. BATTALION CHIEF ADVISED.

11/07/2018 SERVICE REQUEST / 18: LEAKING / REPAIR
HURST 5000 PSI EXTRICATION POWER UNIT HAS BROKEN BOLTS WHICH SECURE ENGINE TO THE METAL BASE CAGE. ENGINE IS COMPLETELY IS CONNECTED. EXTRICATION POWER UNIT IS UNSAFE TO USE.

11/07/2018 SERVICE REQUEST / 18: LEAKING / REPAIR
CHECK TIC CHARGING UNIT ON SPARE ENGINE 1016844, CURRENTLY AT STATION 54 AS E54. TIC UNIT AND SPARE BATTERY WILL NOT HOLD CHARGE. I AM ALSO EMAILING BC57 TO ADVISE OF ISSUE AND TO SEND ACTUAL TIC TO SHOP FOR ASSESMENT.

Asset Work Order History 1015557

CSHOP-2018-6868

Date Opened: 12-4-2018 Date Finished 1-10-2019 Meter 1 Reading: 116,331

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS	1	5TN; HANDLE
FIRE PUMP CONTROLS	1	5AB; 25 SUB ASSY FOR 8825 VALVE
PRIMING PUMP FIRE PUMP	1	5AB; KIT, 3" & 3.5" BALL VALVE
ENGINE COOLANT TEMPERATURE SE	1	5AB; 1.5 BALL KIT
PARK-CLEARANCE LIGHTS	1	5TN; TPM/QG HALE REPAIR KIT
LIGHTING SYSTEM	4	5TN; VANE, IMPREGNATED ESP12
LIGHT BAR	1	9IP; 41032-3 RED REFLECTOR OVAL REFLECTOR
INSTRUMENTS-GAUGES-METERS	2	LMP; LAMP
AIR CONDITIONING	1	1WL; LED STROBE LIGHT RED
	1	2RD; FILTER, 17.5X5.5, MASTER PK (2)
	4	9XX; AC FREON 10199801
	2	9IP; 182640 VENT AC NEW 1719

CSHOP-2018-7156

Date Opened: 12-17-2018 Date Finished 12-17-2018 Meter 1 Reading: 115,621

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS

CSHOP-2019-103

Date Opened: 1-7-2019 Date Finished 1-31-2019 Meter 1 Reading: 116,331

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

Service Requests:

01/06/2019 SERVICE REQUEST / 19: LOOSE / INSPECT
PRESSURE RELIEF VALVE RESPONDS EXTREMELY SLOWLY

CSHOP-2019-1936

Date Opened: 4-15-2019 Date Finished 4-19-2019 Meter 1 Reading: 116,331

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS

Asset Work Order History 1015557

CSHOP-2019-2076

Date Opened: 4-22-2019 Date Finished 4-23-2019 Meter 1 Reading: 118,305

TASKS PERFORMED

NO PARTS USED

BRACKET

Service Requests:

04/21/2019 SERVICE REQUEST / 19: LOOSE / REPAIR
SCBA BRACKET- BRACKET ON FIREFIGHTER SEAT IS BROKEN.

CSHOP-2019-2121

Date Opened: 4-23-2019 Date Finished 4-23-2019 Meter 1 Reading: 118,305

TASKS PERFORMED

NO PARTS USED

TIRES & WHEELS

Service Requests:

04/22/2019 TIRES / 44: WORN / EXCHANGE - NEW
BAD TIRES. RIGHT REAR TIRE IS NEAR OR AT THE TREAD WEAR BAR.

CSHOP-2019-2201

Date Opened: 4-25-2019 Date Finished 4-25-2019 Meter 1 Reading: 118,509

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2019-2297

Date Opened: 4-30-2019 Date Finished 5-8-2019 Meter 1 Reading: 118,509

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FIL; NAPAGOLD FUEL FILTER
1 FIL; FUEL WATER SEPARATOR
32 4PC; 15W40 PB OIL DRM/QT
1 FIL; NAPA COOLANT FILTER
1 FIL; NAPAGOLD OIL FILTER

CSHOP-2019-2774

Comments: **HEADLINER MOLD AND MILDEW**

Date Opened: 5-30-2019 Date Finished 6-12-2019 Meter 1 Reading: 118,509

TASKS PERFORMED

Q PARTS

BODY EXTERIOR
HEAD LINER
CAB-INTERIOR ACCESSORIES

4 MMM; MARINEADHSEALWHITE
1 2FL; HANDLE, DOOR

Asset Work Order History 1015557

CSHOP-2019-3500

Comments: **SPARE BATTALION ENGINE AT ST44**

Date Opened: 7-5-2019 Date Finished 7-15-2019 Meter 1 Reading: 119,580

TASKS PERFORMED

NO PARTS USED

INSTRUMENTS-GAUGES-METERS

Service Requests:

07/05/2019 SERVICE REQUEST / 18: LEAKING / REPAIR
PUMP DISCHARGE GUAGE NUMBERS UNREADABLE ON DISPLAY

CSHOP-2019-3565

Comments: **I ORDERED A DECK GUN ORING SET FOR BATT4 SPARE JOHN MURRAY**

Date Opened: 7-9-2019 Date Finished 1-17-2020 Meter 1 Reading: 123,673

TASKS PERFORMED

Q PARTS

RELIEF VALVE FIRE PUMP	1	TWD; RADIO RAY W WIRELESS
FIRE PUMP	1	5FS; SPOTLIGHT VISIBEAM II W WIRED REMOTE
SPOT LIGHTS	1	6KU; AUTO EJECT W STD YEL CVR
ALTERNATOR-GENERATOR	1	5SC; GAUGE
INSTRUMENTS-GAUGES-METERS	1	5CS; GAUGE 3 5 0 600 WH

Service Requests:

07/09/2019 SERVICE REQUEST / 12: BROKEN / REPAIR
PRESSURE RELIEF VALVE LIGHT IS BROKEN ON THE PUMP PANEL.

CSHOP-2019-4332

Date Opened: 8-16-2019 Date Finished 8-19-2019 Meter 1 Reading: 120,052

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

CSHOP-2019-4385

Date Opened: 8-19-2019 Date Finished 8-20-2019 Meter 1 Reading: 120,052

TASKS PERFORMED

NO PARTS USED

SAFTEY-EMERGENCY EQUIPMENT

Service Requests:

08/18/2019 SERVICE REQUEST / 18: LEAKING / REPAIR
E47'S VENT SAW WON'T START AFTER MULTIPLE TRIES. SAW IS TAGGED AND LEFT IN THE MIDDLE OF THE BAY AT ST.
47...

Asset Work Order History 1015557

CSHOP-2019-6022

Date Opened: 11-18-2019 Date Finished 1-8-2020 Meter 1 Reading: 123,673

TASKS PERFORMED

NO PARTS USED

SIDE COMPARTMENT BODY
CHARGING SYSTEM

Service Requests:

11/17/2019 ALARMS / 17: INSUFFICIENT LUBRICANT / INSPECT
THE "OPEN DOOR" ALARM (VISUAL AND AUDIBLE) IS GOING OFF EVEN THOUGH ALL DOORS APPEAR TO BE FULLY CLOSED.

CSHOP-2019-6394

Date Opened: 12-10-2019 Date Finished 1-10-2020 Meter 1 Reading: 123,673

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES
SHORELINE CHARGER
INSTRUMENTS-GAUGES-METERS

Service Requests:

12/10/2019 ENGINE / 18: LEAKING / INSPECT
SMALL OIL LEAK FROM BOTTOM OF ENGINE.

12/10/2019 SERVICE REQUEST / 17: INSUFFICIENT LUBRICANT / LUBRICATE
SHORELINE DOES NOT EJECT WHEN TRUCK IS STARTED

12/10/2019 SERVICE REQUEST / 12: BROKEN / INSPECT
DIGITAL MASTER PUMP DISCHARGE PRESSURE GAUGE NEEDS TO BE REPLACED. DISPLAY DOES NOT SHOW A COMPLETE NUMBER.

CSHOP-2019-6534

Date Opened: 12-18-2019 Date Finished 1-7-2020 Meter 1 Reading: 123,673

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES

8 NOL; NAPA QT 15W40 CJ4

Service Requests:

12/17/2019 ENGINE / 17: INSUFFICIENT LUBRICANT / LUBRICATE
NEED 2 CASES OF OIL FOR THE STATION. I PLACED 8 QUARTS IN THE ENGINE55 AND IT IS STILL LOW. THANK YOU.

CSHOP-2019-6644

Date Opened: 12-26-2019 Date Finished 1-7-2020 Meter 1 Reading: 123,673

TASKS PERFORMED

NO PARTS USED

HURST TOOL CUTTERS

Service Requests:

12/23/2019 SERVICE REQUEST / 13: CHIPPED / EXCHANGE - NEW
THE BLADES ON THE HURST CUTTING TOOL HAVE GAUGES AND NEED TO BE REPLACED. THANK YOU

Asset Work Order History 1015557

CSHOP-2020-1120

Date Opened: 2-26-2020 Date Finished 8-6-2020 Meter 1 Reading: 126,614

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS
LIGHTING SYSTEM

Service Requests:

-
- 02/26/2020 SERVICE REQUEST / 19: LOOSE / EXCHANGE - NEW
ALL THREE BOX LIGHT WOULD HOLD A CHARGE. B.JL 7839.
 - 04/01/2020 SERVICE REQUEST / 17: INSUFFICIENT LUBRICANT / LUBRICATE
TYPE PROBLEM INTO DESCRIPTION DISCHARGES 2 AND 4 WILL NOT OPEN WHEN PUMP IS UNDER PRESSURE.
PROBLEM WAS DISCOVERED WHEN ATTEMPTING TO SET-UP DECON KIT BUT BOTH PRE-CONNECTS WERE
CURRENTLY UNDER OPERATING PRESSURES.
-

CSHOP-2020-1296

Date Opened: 3-5-2020 Date Finished 3-6-2020 Meter 1 Reading: 124,995

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

Service Requests:

-
- 03/05/2020 SERVICE REQUEST / 18: LEAKING / REPAIR
SPARE ENGINE HAS NO ACCELERATION, ALL FLUID LEVELS CORRECT, GOES INTO PUMP WITH NO PROBLEMS
TRANSMISSION SEEMS TO BE SHIFTING. B.JL, 7839 THANKS
-

CSHOP-2020-1592

Date Opened: 3-19-2020 Date Finished 5-11-2020 Meter 1 Reading: 125,850

TASKS PERFORMED

Q PARTS

PM SERVICE C

- 1 FIL; NAPAGOLD FUEL FILTER
 - 1 FIL; FUEL WATER SEPARATOR
 - 24 4PC; 15W40 PREMIUM BLUE OIL
 - 1 MAC; MAC WITE LITHIUM GRES
 - 1 FIL; NAPAGOLD AIR FILTER
 - 1 FIL; NAPA COOLANT FILTER
 - 1 FIL; NAPAGOLD OIL FILTER
-

CSHOP-2020-2367

Date Opened: 5-4-2020 Date Finished 5-4-2020 Meter 1 Reading: 125,818

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

Asset Work Order History 10155557

CSHOP-2020-3331

Date Opened: 6-23-2020 Date Finished 6-24-2020 Meter 1 Reading: 126,494

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR HORN

CSHOP-2020-3372

Date Opened: 6-26-2020 Date Finished 7-10-2020 Meter 1 Reading: 126,614

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
STARTER

1 1AD; STARTER

CSHOP-2020-6118

Date Opened: 11-23-2020 Date Finished 4-26-2021 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

FIRE PUMP

1 FREIGHT
1 5EF; HANDLE VALVE 8 LONG
1 5EF; HANDLE VALVE 8 LONG
1 5EF; 5EF
-1 5AB; HANDLE W CVR AND ATTACHMENT
1 5AB; HANDLE W CVR AND ATTACHMENT
1 FREIGHT

Service Requests:

11/21/2020 SERVICE REQUEST / 12: BROKEN / REPAIR
TYPE PROBLEM INTO DESCRIPTION THE OFFICER SIDE INTAKE HANDLE IS BROKEN OFF AND STRIPPED. THE
INTAKE IS UNABLE TO OPENED AND CLOSED.

Asset Work Order History 1015557

CSHOP-2020-787

Comments: **REPLACE SEALS IN DECK GUN**

Date Opened: 2-11-2020

Date Finished

6-9-2020

Meter 1 Reading:

126,086

TASKS PERFORMED

Q PARTS

FOAM SYSTEM	2	5TF; DECK GUN WEAR STRIP
FIRE PUMP PLUMBING	2	5AB; STRAINER 2 5
EQUIPMENT MOUNTING BRACKETS	2	5TF; CUP SEAL
DISCHARGE GAUGE	8	5CS; GAUGE 3 5 30 600 WH
CROSSWAY BODY	2	6ZA; 11 TO 16 VARIABLE STRAP
FIRE APPARATUS	1	5HP; PMG6970 WHEEL ASSY
DOOR PROP CYLINDER	1	4AH; GAS SPRING 12 008 61 LBS
CAB	1	5AH; 10MM BALL STUD
COOLING SYSTEM	1	2FL; COVER PILAR
QUARTZ LIGHT	10	2FL; 2FL
LIGHTING SYSTEM	1	2FL; 2FL
TRANSMISSION	10	2FL; FASTENERS, FUSE COVER
FRONT HUB	10	2FL; RETAINER SNAP IN
STEERING	1	BK; RADIATOR CAPS
FRAME	1	5FR; LIGHT BEDDING
LIGHT BAR	1	2FR; 510 FLANGE W SW ASSY
SAFTEY-EMERGENCY EQUIPMENT	1	LIT; LED M C LAMP
DOOR LOCKS	29	9OC; BULK TRANS SYN
DOOR PANEL	1	2DD; FILTER KIT TRANS SUMP 4
HEATER CONTROL VALVE	2	9OC; BULK TRANS SYN
A/C FILTER SCREENS	1	FIL; NAPA HYDRAULIC FILTER
AIR CONDITIONING	1	9IP; GASKET P S FILTER NEW STYLE
	2	8GR; GAUGE
	1	2IH; HI HORN
	2	2FL; MOLDING LH
	1	2FL; HANDLE DOOR
	1	2FL; MOLD R H
	1	2RD; FILTER 17 5X5 5 MASTER PK 2
	3	9HD; LOWER UNIT SEAL KIT

Service Requests:

02/11/2020 SERVICE REQUEST / 12: BROKEN / REPAIR
VELCRO STRAP ON 2 1/2 NOZZLE NEEDS TO BE REPLACED, WEBBING ON CROSS LAY NEEDS TO BE REATTACHED.
THANKS BARRY

CSHOP-2020-921

Date Opened: 2-18-2020

Date Finished

7-22-2020

Meter 1 Reading:

126,614

TASKS PERFORMED

NO PARTS USED

BODY EXTERIOR

Service Requests:

02/16/2020 SERVICE REQUEST / 16: GLAZED / EXCHANGE - NEW
NEED TO REPLACE VELCRO STRAP FOR SAFETY CONES. ALSO REPLACE WEBBING THAT HOLDS THE CROSSLAYS.
BOTH STRAPS ARE BROKEN AND NOT HOLDING SECURE

Asset Work Order History 1015557

SSHOP-2015-15

Date Opened: 4-20-2015 Date Finished 4-21-2015 Meter 1 Reading: 95,667

REPAIR WIRING

TASKS PERFORMED

Q PARTS

A INSPECTION	1	9IP; MARKER LIGHT MOUNTING PLATE
DOME LIGHTS	1	9IP; GASKET MOUNTING
PARK-CLEARANCE LIGHTS	1	9IP; HARNESS FOR MARKER LIGHT
QUARTZ LIGHT	1	LIGHT; LED GROUND LITE CLEAR
REAR BRAKE PADS-SHOES	1	LIGHT; MARKER LIGHT
LIGHT BAR	1	LIGHT; CHROME MARKER LIGHT MOUNT
	1	KNOB; KNOB DRAIN

SSHOP-2015-56

Date Opened: 6-3-2015 Date Finished 6-12-2015 Meter 1 Reading: 95,737

TASKS PERFORMED

Q PARTS

BATTERY	1	ASSEMBLY; ABS ASSBLY
BRAKES		
STROBE LIGHTS		
DOOR STRIKER PLATE		
DASH CONTROLS		
AIR CONDITIONING		

SSHOP-2015-57

Date Opened: 6-3-2015 Date Finished 6-8-2015 Meter 1 Reading: 95,737

TASKS PERFORMED

Q PARTS

PM SERVICE B	1	FILTER; FILTER FUEL WIX 33422 PS8689 FRAM
	1	FILTER; FILTER FUEL 33231
	1	FILTER; OIL FILTER 51748

SSHOP-2019-121

Date Opened: 4-19-2019 Date Finished 4-19-2019 Meter 1 Reading: 116,331

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

SSHOP-2019-137

Date Opened: 5-8-2019 Date Finished 5-20-2019 Meter 1 Reading: 118,509

TASKS PERFORMED

NO PARTS USED

FIRE PUMP
HOSE BED BODY
SIDE COMPARTMENT BODY
LIGHTING SYSTEM
AIR SYSTEM

Asset Work Order History 1015557

SSHOP-2019-153

Date Opened: 5-21-2019 Date Finished 5-28-2019 Meter 1 Reading: 118,509

TASKS PERFORMED

Q PARTS

ROOF
AIR SYSTEM

1 TWD; AD-9KIT MINOR
1 TWD; AD-9KIT

SSHOP-2019-273

Date Opened: 8-27-2019 Date Finished 8-29-2019 Meter 1 Reading: 120,500

TASKS PERFORMED

Q PARTS

BATTERY
BLOWER MOTOR

1 1AD; ALTERNATOR 3 BOLT
1 TEM; BLOWER MOTOR

SSHOP-2019-381

Date Opened: 11-13-2019 Date Finished 11-13-2019 Meter 1 Reading: 122,361

TASKS PERFORMED

NO PARTS USED

FUEL SYSTEM

SSHOP-2019-428

Date Opened: 12-23-2019 Date Finished 1-10-2020 Meter 1 Reading: 123,673

TASKS PERFORMED

NO PARTS USED

LIGHTING SYSTEM

Service Requests:

12/22/2019 SERVICE REQUEST / 19: LOOSE / REPAIR
CAB ROOF LIGHT BAR, DRIVER SIDE, FRONT CORNER, STROBE LIGHT OUT.

Asset Work Order History 1015557

SSHOP-2020-220

Date Opened: 7-2-2020

Date Finished

8-5-2020

Meter 1 Reading:

126,614

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES

1 2CU; SCREW
1 2CU; TUBE INJECTOR
6 2CU; ISOLATOR
6 2CU; SCREW
1 2CU; TUBE INJECTOR
4 2CU; SCREW
1 2CU; TUBE INJECTOR
4 2CU; BRACE
2 2CU; ISOLATOR
1 2CU; GASKET
4 2CU; ISOLATOR
1 2CU; TUBE INJECTOR
1 2CU; BRACE
1 2CU; TUBE INJECTOR
1 2CU; TUBE INJECTOR
1 2CU; GASKET INTAKE
4 2CU; BRACE
6 2CU; LINE FUEL
24 CRC; CLEAN R CARB 200Z
2 2CU; BRACE
2 2CU; BRACE
3 PAF; ANTIFRZ
6 2CU; LINE FUEL

SSHOP-2020-36

Date Opened: 1-28-2020

Date Finished

1-28-2020

Meter 1 Reading:

123,673

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
BATTERY

4 1AD; BATTERY GROUP 31

SSHOP-2020-388

Date Opened: 11-24-2020

Date Finished

12-9-2020

Meter 1 Reading:

127,511

TASKS PERFORMED

NO PARTS USED

STROBE LIGHTS
