		1018368	36 2	011 FORD ES	CAPE Su	v, Mid Size	, Hybrid			
Workorder: Problem:	1102991 Pre Delivery In	Meter:	0			In Date:	03/21/2011	Closed:	03/21/2	011
- Pre Delivery	Inspection									
- Wash Vehic	le									
	Hours :	3.00		Labor:	180.00	Parts:	0.00	Total:	180.00	
Workorder: Problem:	1103114 1 - Wash ticke	Meter: t(s) issued	318 1			In Date:	03/22/2011	Closed:	03/22/2	011
- 1 - Wash ticl	ket(s) issued									
	Hours :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1109565 PM Service	Meter:	3398			In Date:	09/07/2011	Closed:	09/12/2	011
- Pm Service				Parts L	ist				Qty	
- Clean Rear	brakes and adju			Shop Si	upplies				1.00	
- Rotate & balanced tires					1348 Oil Filter Frm Ph3614 Wix 51348					1.00
- Shop Suppli				09997	Brake Clear	ı			1.00	
					5w20 E	ngine Oil				6.00
	Hours :	s 4.00		Labor:	240.00	Parts:	32.47	Total:	272.47	
	1111854 Check Tire Pre	Meter: essure	4162			In Date:	11/03/2011	Closed:	11/09/2	011
- check tire ps		s 0.50		Labor:	30.00	Parts:	0.00	Total:	30.00	
	:									
Workorder: Problem:	1111891 3 - Wash ticke	Meter: t(s) issued	4301 1			In Date:	11/04/2011	Closed:	11/04/2	011
- 3 - Wash ticl	ket(s) issued									
	Hours :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1112947 Right front tire	Meter: low	5001			In Date:	12/07/2011	Closed:	12/15/2	011
- Repaired lef	t front tire, flat				Parts L	ist				Qty
- Shop Suppli	es				Shop Si	upplies				1.00
	Hours :	s 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1202017 pm service	Meter:	6451			In Date:	02/28/2012	Closed:	03/06/2	012
- pm service					Parts L	ist				Qty
-	st rear brakes				Shop Si	upplies				1.00
- rotate & bala							Ph3614 Wix	51348		1.00
- Shop Suppli	es				5w20 E	ngine Oil				6.00
-	Hours :	s 4.00		Labor:	240.00	Parts:	31.37	Total:	271.37	

Workorder: Problem:	1205023 2 - Wash ticket	Meter: (s) issuec	8463 I			In Date:	05/30/2012	Closed:	05/30/20	12
- 2 - Wash ticl	ket(s) issued									
	Hours	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1208395 PM SERVICE	Meter:	10243			In Date:	09/05/2012	Closed:	09/20/20	12
- Pm Service					Parts L	.ist				Qty
- Clean, Inspe	ect And Adjust R	ear Brak	es		Shop S	Supplies				1.00
- Rotate And I	Road Force Bala	ance Tire	5		1348 O	il Filter Frm	Ph3614 Wix	51348		1.00
- Shop Supplies						ngine Oil				6.00
		Used F		1.00						
	Hours	4.00		Labor:	240.00	Parts:	46.29	Total:	286.29	
Workorder: Problem:	1302963 Pm service	Meter:	13102			In Date:	03/26/2013	Closed:	04/02/20	13
- Pm service					Parts L	ist				Qty
- Clean and a	djust rear brake	s.			Wiper E	Blade				2.00
- Rotate and b	alance tires.				Filter					1.00
- Test drive.					Ca1017	70 Air Filter L	b			1.00
- Shop Suppli	es				Napa C	Quart 5w20				6.00
					Shop S	Supplies				1.00
	Hours	4.50		Labor:	270.00	Parts:	77.69	Total:	347.69	
Workorder: Problem:	1307308 Antenna missir	Meter:	15606			In Date:	07/22/2013	Closed:	08/08/20	13
- Replace mis	sing antenna.				Parts L	ist				Qty
- Shop Suppli	-				Antenn	а				1.00
					Shop S	Supplies				1.00
	Hours	0.50		Labor:			38.05	Total:	68.05	
Workorder: Problem:	1309409 check engine li	Meter: ght is on	16696			In Date:	09/17/2013	Closed:	09/25/20	13
- Checked and	d cleared dtc's.	No proble	m found.							
	Hours :	0.50		Labor:	30.00	Parts:	0.00	Total:	30.00	

Workorder: Problem:	1312074 Pm service.	Meter:	18126		In Date:	12/03/2013	Closed:	12/10/2013			
- Pm service.					Parts List			Qty			
- Clean and a	idjust rear bra	kes.			Wiper Blade			2.00			
- Rotate and I	balance tires.				Napagold Oil Filter			1.00			
- Test drive.					Washer Fluid Conc	entr		1.00			
- Shop Suppli	ies				Brake Cleaner			1.00			
					Napa Quart 5w20			6.00			
					Shop Supplies			1.00			
	Hou :	urs 4.50		Labor:	270.00 Parts:	58.36	Total:	328.36			
Workorder: Problem:	1402577 Flat tire.	Meter:	19820		In Date:	03/18/2014	Closed:	03/18/2014			
- Repair tire.	- Repair tire.					Parts List					
- Clear Tpms - Shop Suppli					Shop Supplies			1.00			
	Hou	urs 1.50		Labor:	90.00 Parts:	2.00	Total:	92.00			
Workorder:	1402607	Meter:	19785		In Date:	03/18/2014	Closed:	03/18/2014			
Problem:	Flat life.										
• Tow From: H		To: Pa shop	)								
	Health Dept.	To: Pa shop urs 0.00	)	Labor:	0.00 Parts:	0.00	Total:	0.00			
- Tow From: H Workorder:	Health Dept.	-	21556	Labor:	0.00 Parts:	0.00 06/30/2014	Total: Closed:	0.00 07/03/2014			
- Tow From: H Workorder:	Health Dept. Hou : 1406398	urs 0.00		Labor:							
- Tow From: H Workorder: Problem:	Health Dept. Hou : 1406398 Pm service.	Meter:		Labor:	In Date:			07/03/2014			
- Tow From: H Workorder: Problem: - Pm service.	Health Dept. Hou : 1406398 Pm service. ndjust rear bra	Meter:		Labor:	In Date: Parts List			07/03/2014 Qty			
- Tow From: H Workorder: Problem: - Pm service. - Clean and a	Health Dept. Hou : 1406398 Pm service. ndjust rear bra	Meter:		Labor:	In Date: Parts List Napa Quart 5w20			07/03/2014 Qty 6.00			
- Tow From: H Workorder: Problem: - Pm service. - Clean and a - Rotate and H	Health Dept. Hou : 1406398 Pm service. Idjust rear bra balance tires.	Meter:		Labor:	In Date: Parts List Napa Quart 5w20 Napagold Oil Filter	06/30/2014		07/03/2014 Qty 6.00 1.00			
<ul> <li>Tow From: H</li> <li>Workorder: Problem:</li> <li>Pm service.</li> <li>Clean and a</li> <li>Rotate and b</li> <li>Test drive.</li> </ul>	Health Dept. Hou : 1406398 Pm service. Idjust rear bra balance tires.	Meter:		Labor:	In Date: Parts List Napa Quart 5w20 Napagold Oil Filter Wiper Blade	06/30/2014		07/03/2014 <b>Qty</b> 6.00 1.00 2.00			
<ul> <li>Tow From: H</li> <li>Workorder: Problem:</li> <li>Pm service.</li> <li>Clean and a</li> <li>Rotate and b</li> <li>Test drive.</li> </ul>	Health Dept. Hou : 1406398 Pm service. Idjust rear bra balance tires.	Meter:			In Date: Parts List Napa Quart 5w20 Napagold Oil Filter Wiper Blade Washer Fluid Conc Shop Supplies	06/30/2014	Closed:	07/03/2014 Qty 6.00 1.00 2.00 1.00			
<ul> <li>Tow From: H</li> <li>Workorder: Problem:</li> <li>Pm service.</li> <li>Clean and a</li> <li>Rotate and b</li> <li>Test drive.</li> <li>Shop Suppli</li> <li>Workorder:</li> </ul>	Health Dept. Hou : 1406398 Pm service. Idjust rear bra balance tires.	wrs 0.00 Meter:			In Date: Parts List Napa Quart 5w20 Napagold Oil Filter Wiper Blade Washer Fluid Conc Shop Supplies	06/30/2014 entr	Closed:	07/03/2014 <b>Qty</b> 6.00 1.00 2.00 1.00 1.00			
<ul> <li>Tow From: H</li> <li>Workorder: Problem:</li> <li>Pm service.</li> <li>Clean and a</li> <li>Rotate and b</li> <li>Test drive.</li> <li>Shop Suppli</li> <li>Workorder:</li> </ul>	Health Dept. Hou 1406398 Pm service. Idjust rear bra balance tires. ies Hou : 1500147 Pm service	wrs 0.00 Meter: kes. urs 4.50	21556		In Date: Parts List Napa Quart 5w20 Napagold Oil Filter Wiper Blade Washer Fluid Conc Shop Supplies 270.00 Parts:	06/30/2014 entr 54.65	Closed: Total:	07/03/2014 Qty 6.00 1.00 2.00 1.00 324.65			
<ul> <li>Tow From: H</li> <li>Workorder: Problem:</li> <li>Pm service.</li> <li>Clean and a</li> <li>Rotate and k</li> <li>Test drive.</li> <li>Shop Suppli</li> <li>Workorder: Problem:</li> </ul>	Health Dept. Hou 1406398 Pm service. Idjust rear bra balance tires. ies Hou 1500147 Pm service	wrs 0.00 Meter: kes. urs 4.50	21556		In Date: Parts List Napa Quart 5w20 Napagold Oil Filter Wiper Blade Washer Fluid Conc Shop Supplies 270.00 Parts: In Date:	06/30/2014 entr 54.65	Closed: Total:	07/03/2014 <b>Qty</b> 6.00 1.00 2.00 1.00 324.65 01/07/2015			
<ul> <li>Tow From: H</li> <li>Workorder: Problem:</li> <li>Pm service.</li> <li>Clean and a</li> <li>Rotate and h</li> <li>Test drive.</li> <li>Shop Suppli</li> <li>Workorder: Problem:</li> <li>Pm service.</li> </ul>	Health Dept. Hou 1406398 Pm service. Idjust rear bra balance tires. ies Hou 1500147 Pm service	wrs 0.00 Meter: kes. urs 4.50	21556		In Date: Parts List Napa Quart 5w20 Napagold Oil Filter Wiper Blade Washer Fluid Conc Shop Supplies 270.00 Parts: In Date: Parts List	06/30/2014 entr 54.65	Closed: Total:	07/03/2014 Qty 6.00 1.00 2.00 1.00 324.65 01/07/2015 Qty			
<ul> <li>Tow From: H</li> <li>Workorder: Problem:</li> <li>Pm service.</li> <li>Clean and a</li> <li>Rotate and k</li> <li>Test drive.</li> <li>Shop Suppli</li> <li>Workorder: Problem:</li> <li>Pm service.</li> <li>Rotate and k</li> </ul>	Health Dept. Hou 1406398 Pm service. Idjust rear bra balance tires. Hou 1500147 Pm service balance tires.	urs 0.00 Meter: kes. urs 4.50 Meter:	21556		In Date: Parts List Napa Quart 5w20 Napagold Oil Filter Wiper Blade Washer Fluid Conc Shop Supplies 270.00 Parts: In Date: Parts List Napagold Oil Filter	06/30/2014 entr 54.65 01/06/2015	Closed: Total:	07/03/2014 <b>Qty</b> 6.00 1.00 2.00 1.00 324.65 01/07/2015 <b>Qty</b> 1.00			
<ul> <li>Tow From: H</li> <li>Workorder: Problem:</li> <li>Pm service.</li> <li>Clean and a</li> <li>Rotate and b</li> <li>Test drive.</li> <li>Shop Suppli</li> <li>Workorder: Problem:</li> <li>Pm service.</li> <li>Rotate and b</li> <li>Test drive.</li> </ul>	Health Dept. Hou 1406398 Pm service. Idjust rear bra balance tires. Hou 1500147 Pm service balance tires.	urs 0.00 Meter: kes. urs 4.50 Meter:	21556		In Date: Parts List Napa Quart 5w20 Napagold Oil Filter Wiper Blade Washer Fluid Conc Shop Supplies 270.00 Parts: In Date: Parts List Napagold Oil Filter Wiper Blade	06/30/2014 entr 54.65 01/06/2015	Closed: Total:	07/03/2014 Qty 6.00 1.00 2.00 1.00 324.65 01/07/2015 Qty 1.00 2.00			
<ul> <li>Tow From: H</li> <li>Workorder: Problem:</li> <li>Pm service.</li> <li>Clean and a</li> <li>Rotate and H</li> <li>Test drive.</li> <li>Shop Suppli</li> </ul> Workorder: Problem: <ul> <li>Pm service.</li> <li>Rotate and H</li> <li>Test drive.</li> <li>Clean and a</li> </ul>	Health Dept. Hou 1406398 Pm service. Idjust rear bra balance tires. Hou 1500147 Pm service balance tires.	urs 0.00 Meter: kes. urs 4.50 Meter:	21556		In Date: Parts List Napa Quart 5w20 Napagold Oil Filter Wiper Blade Washer Fluid Conc Shop Supplies 270.00 Parts: In Date: Parts List Napagold Oil Filter Wiper Blade Washer Fluid Conc	06/30/2014 entr 54.65 01/06/2015	Closed: Total:	07/03/2014 <b>Qty</b> 6.00 1.00 2.00 1.00 324.65 01/07/2015 <b>Qty</b> 1.00 2.00 1.00 2.00 1.00 2.00 1.00			

Problem:       P.M. service andTowed in for noise in front end         - Pm service.       Parts List         - Install fire extinguisher bracket in cargo area.       5w20 Engine Oil         - Test starting and charging system.battery failed loadtest after recharge.replace defective battery.       Napagold Oil Filter         - Check front end noise.replace defective right front axle and intermediate shaft assemblies.       Wiper Blade         - Shop Supplies       Ww-1202 Wiper Blade M         Custom Bracket Fire Ex       Bxt96r 59         shaft into tramsmission       Left Front Shaft         Syn-atf Trans Fluid S       Shop Supplies         Hours 7.00       Labor:       420.00       Parts: 838.21       Total: 1,25	Qty 6.00 2.00 4.00 1.00 1.00 4.00 1.53
<ul> <li>Test drive.</li> <li>Shop Supplies</li> <li>Wiper Blade</li> <li>183407418 P235-70r16</li> <li>Washer Fluid Concentr</li> <li>Napagold Air Filter</li> <li>Shop Supplies</li> <li>Tre Disposal Fee</li> <li>Hours 4.00</li> <li>Labor: 240.00</li> <li>Parts: 851.53</li> <li>Total: 1,09</li> <li>Workorder: 1512697</li> <li>Meter: 30308</li> <li>In Date: 12/16/2015</li> <li>Closed: 01/0</li> <li>Problem: P.M. service andTowed in for noise in front end</li> <li>Pm service.</li> <li>Install fire extinguisher bracket in cargo area.</li> <li>Test starting and charging system.battery failed loadtest after recharge.replace defective battery.</li> <li>Check front end noise.replace defective right front axle and intermediate shaft assemblies.</li> <li>Shop Supplies</li> <li>Shop Supplies</li> <li>Hours 7.00</li> <li>Labor: 420.00</li> <li>Parts: 838.21</li> <li>Parts: 12/16/2015</li> <li>Closed: 12/1</li> <li>Problem: 1512737</li> <li>Meter: 30234</li> <li>Morkorder: 1512737</li> <li>Meter: 30234</li> <li>Meter: 30234</li> <li>In Date: 12/16/2015</li> <li>Closed: 12/1</li> </ul>	6.00 1.00 2.00 4.00 1.00 1.00 4.00
- Shop Supplies Wiper Blade 183407418 P235-70r16 Washer Fluid Concentr Napagold Air Filter Shop Supplies Tire Disposal Fee Hours 4.00 Labor: 240.00 Parts: 851.53 Total: 1,09 Workorder: 1512697 Meter: 30308 Problem: P.M. service andTowed in for noise in front end - Pm service. - Install fire extinguisher bracket in cargo area. - Test starting and charging system.battery failed loadtest after recharge.replace defective battery. - Check front end noise.replace defective right front axle and intermediate shaft assemblies. - Shop Supplies - Shop Supplies Hours 7.00 Hours	2.00 4.00 1.00 1.00 4.00 1.53
183407418 P235-70r16         Washer Fluid Concentr         Napagold Air Filter         Shop Supplies         Tire Disposal Fee         Hours 4.00       Labor: 240.00         Parts: 851.53       Total: 1,09         Workorder:       1512697         Meter:       30308         In Date:       12/16/2015         Closed:       01/0         Problem:       P.M. service andTowed in for noise in front end         - Pm service.       Parts List         - Install fire extinguisher bracket in cargo area.       5w20 Engine Oil         - Test starting and charging system.battery failed loadtest after recharge.replace defective battery.       Swaper Fluid Concentr         - Check front end noise.replace defective right front axle and intermediate shaft assemblies.       Sw20 Engine Oil         - Shop Supplies       Www-1202 Wiper Blade         Www-1202 Wiper Blade       Www-1202 Wiper Blade M         Custom Bracket Fire Ex       Bxt96r 59         shaft into tramsmission       Left Front Shaft         Syn-atf Trans Fluid S       Shop Supplies         Hours 7.00       Labor:       420.00       Parts: 838.21       Total: 1,25         Workorder:       1512737       Meter:       30234       In Date:       12/16/2015	4.00 1.00 1.00 4.00 1.53
Washer Fluid Concentr Napagold Air Filter Shop Supplies Tire Disposal Fee Hours 4.00 Labor: 240.00 Parts: 851.53 Total: 1,09 Workorder: 1512697 Meter: 30308 Problem: P.M. service andTowed in for noise in front end - Pm service. - Install fire extinguisher bracket in cargo area. - Test starting and charging system.battery failed loadtest after recharge.replace defective battery. - Check front end noise.replace defective right front axle and intermediate shaft assemblies. - Shop Supplies - Shop Supplies - Shop Supplies - Shop Supplies - Mours 7.00 - Hours 7.00 - Meter: 30234 - Meter: 30234 - Meter: 30234 - Meter: 30234 - Meter: 12/16/2015 -	1.00 1.00 1.00 4.00
Napagold Air Filter Shop Supplies Tire Disposal Fee Hours 4.00 240.00 Parts: 851.53 Total: 1,09 Workorder: 1512697 Meter: 30308 In Date: 12/16/2015 Closed: 01/0 Problem: P.M. service andTowed in for noise in front end - Pm service. - Install fire extinguisher bracket in cargo area. - Test starting and charging system.battery failed loadtest after recharge.replace defective battery. - Check front end noise.replace defective right front axle and intermediate shaft assemblies. - Shop Supplies - Shop Supplies - Shop Supplies - Mours 7.00 Labor: 420.00 Parts: 838.21 Total: 1,25 - Mours 7.00 Labor: 420.00 Parts: 838.21 Total: 1,25 - Workorder: 1512737 Meter: 30234 In Date: 12/16/2015 Closed: 12/1 Problem: When put in reverse it stalls/PM Service	1.00 1.00 4.00 1.53
Shop Supplies Tire Disposal Fee Hours 4.00 240.00 Parts: 851.53 Total: 1,09 Workorder: 1512697 Meter: 30308 In Date: 12/16/2015 Closed: 01/0 Problem: P.M. service andTowed in for noise in front end - Pm service. - Install fire extinguisher bracket in cargo area. - Test starting and charging system.battery failed loadtest after recharge.replace defective battery. - Check front end noise.replace defective right front axle and intermediate shaft assemblies. - Shop Supplies - Shop Supplies - Shop Supplies - Mours 7.00 - Test 1512737 Meter: 30234 In Date: 12/16/2015 Closed: 12/1 Workorder: 1512737 Meter: 30234 In Date: 12/16/2015 Closed: 12/1 Problem: When put in reverse it stalls/PM Service	1.00 4.00 1.53
Tire Disposal Fee         Hours 4.00       Labor:       240.00       Parts:       851.53       Total:       1,09         Workorder:       1512697       Meter:       30308       In Date:       12/16/2015       Closed:       01/0         Problem:       P.M. service andTowed in for noise in front end       Parts       12/16/2015       Closed:       01/0         - Pm service.       -       Install fire extinguisher bracket in cargo area.       Sw20 Engine Oil       Napagold Oil Filter         - Test starting and charging system.battery failed loadtest after recharge.replace defective battery.       -       Napagold Oil Filter         - Check front end noise.replace defective right front axle and intermediate shaft assemblies.       Sw20 Engine Oil       Napagold Oil Filter         - Shop Supplies       -       Www-1202 Wiper Blade       Www-1202 Wiper Blade M         - Custom Bracket Fire Ex       Bxt96r 59       shaft into tramsmission       Left Front Shaft         Syn-atf Trans Fluid S       Shop Supplies       Hours 7.00       Labor:       420.00       Parts: 838.21       Total: 1,25         Workorder:       1512737       Meter:       30234       In Date:       12/16/2015       Closed:       12/14	4.00 1.53
Hours 4.00Labor:240.00Parts:851.53Total:1,09Workorder:1512697Meter:30308In Date:12/16/2015Closed:01/0Problem:P.M. service andTowed in for noise in front end-PartsList01/0- Pm serviceInstall fire extinguisher bracket in cargo area.5w20 Engine OilNapagold Oil Filter- Test starting and charging system.battery failed loadtest after recharge.replace defective battery.Napagold Oil FilterWasher Fluid Concentr- Check front end noise.replace defective right front axle and intermediate shaft assemblies.Sw20 Engine OilNapagold Oil Filter- Shop Supplies-Staff assemblies.Ww-1202 Wiper BladeWw-1202 Wiper Blade- Shop SuppliesEther Front ShaftSyn-atf Trans Fluid S- Hours 7.00Labor:420.00Parts:838.21Total:- Hours 7.00Labor:420.00Parts:838.21Total:1,25Workorder:1512737Meter:30234In Date:12/16/2015Closed:12/16	1.53
Workorder:       1512697       Meter:       30308       In Date:       12/16/2015       Closed:       01/0         Problem:       P.M. service andTowed in for noise in front end       Parts List       5w20 Engine Oil       1       1         - Pm service.       - Install fire extinguisher bracket in cargo area.       5w20 Engine Oil       Napagold Oil Filter       Washer Fluid Concentr         - Check front end noise.replace defective battery.       Vasher Fluid Concentr       Used Fire X Refurbished       Used Fire X Refurbished         - Shop Supplies       Www-1202 Wiper Blade M       Custom Bracket Fire Ex       Bxt96r 59       shaft into tramsmission         - Hours 7.00       Labor:       420.00       Parts:       838.21       Total:       1,25         Workorder:       1512737       Meter:       30234       In Date:       12/16/2015       Closed:       12/16	
Problem: P.M. service andTowed in for noise in front end         - Pm service.         - Install fire extinguisher bracket in cargo area.         - Test starting and charging system.battery failed loadtest after recharge.replace defective battery.         - Check front end noise.replace defective right front axle and intermediate shaft assemblies.         - Shop Supplies         - Shop Supplies         - Mours 7.00         Labor:         Hours 7.00         - Hours 7.00         - Burst:         1512737         Meter:         30234         Problem:         When put in reverse it stalls/PM Service	5/2016
<ul> <li>Pm service.</li> <li>Install fire extinguisher bracket in cargo area.</li> <li>Test starting and charging system.battery failed loadtest after recharge.replace defective battery.</li> <li>Check front end noise.replace defective right front axle and intermediate shaft assemblies.</li> <li>Shop Supplies</li> <li>Shop Supplies</li> <li>Ww-1202 Wiper Blade M</li> <li>Custom Bracket Fire Ex</li> <li>Bxt96r 59</li> <li>shaft into tramsmission</li> <li>Left Front Shaft</li> <li>Syn-atf Trans Fluid S</li> <li>Shop Supplies</li> <li>Hours 7.00</li> <li>Labor:</li> <li>Morkorder:</li> <li>1512737</li> <li>Meter: 30234</li> <li>Meter: 30234</li> <li>In Date:</li> <li>12/16/2015</li> <li>Closed:</li> <li>12/16</li> </ul>	
<ul> <li>Install fire extinguisher bracket in cargo area.</li> <li>Test starting and charging system.battery failed loadtest after recharge.replace defective battery.</li> <li>Check front end noise.replace defective right front axle and intermediate shaft assemblies.</li> <li>Shop Supplies</li> <li>Shop Supplies</li> <li>Wwwwwwwwwwwwwwwwwwwwwwwwwwwwwwwwwwwww</li></ul>	-
<ul> <li>Test starting and charging system.battery failed loadtest after recharge.replace defective battery.</li> <li>Check front end noise.replace defective right front axle and intermediate shaft assemblies.</li> <li>Shop Supplies</li> <li>Ww-1202 Wiper Blade</li> <li>Ww-1202 Wiper Blade M</li> <li>Custom Bracket Fire Ex</li> <li>Bxt96r 59</li> <li>shaft into tramsmission</li> <li>Left Front Shaft</li> <li>Syn-atf Trans Fluid S</li> <li>Shop Supplies</li> <li>Hours 7.00</li> <li>Labor: 420.00</li> <li>Parts: 838.21</li> <li>Total: 1,25</li> <li>Workorder: 1512737</li> <li>Meter: 30234</li> <li>In Date: 12/16/2015</li> <li>Closed: 12/1</li> </ul>	Qty
after recharge.replace defective battery. - Check front end noise.replace defective right front axle and intermediate shaft assemblies. - Shop Supplies - Sh	5.00
- Check front end noise.replace defective right front axle and intermediate shaft assemblies. - Shop Supplies - Shop Suppli	1.00
<ul> <li>Shop Supplies</li> <li>Shop Supplies</li> <li>Shop Supplies</li> <li>Ww-1202 Wiper Blade</li> <li>Ww-1202 Wiper Blade M</li> <li>Custom Bracket Fire Ex</li> <li>Bxt96r 59</li> <li>shaft into tramsmission</li> <li>Left Front Shaft</li> <li>Syn-atf Trans Fluid S</li> <li>Shop Supplies</li> <li>Hours 7.00</li> <li>Labor: 420.00</li> <li>Parts: 838.21</li> <li>Total: 1,25</li> <li>Workorder: 1512737</li> <li>Meter: 30234</li> <li>In Date: 12/16/2015</li> <li>Closed: 12/1</li> </ul>	1.00
- Shop Supplies Ww-1202 Wiper Blade M Custom Bracket Fire Ex Bxt96r 59 shaft into tramsmission Left Front Shaft Syn-atf Trans Fluid S Shop Supplies Hours 7.00 Labor: 420.00 Parts: 838.21 Total: 1,25 Workorder: 1512737 Meter: 30234 In Date: 12/16/2015 Closed: 12/1 Problem: When put in reverse it stalls/PM Service	1.00
Custom Bracket Fire Ex Bxt96r 59 shaft into tramsmission Left Front Shaft Syn-atf Trans Fluid S Shop Supplies Hours 7.00 Labor: 420.00 Parts: 838.21 Total: 1,25 Workorder: 1512737 Meter: 30234 In Date: 12/16/2015 Closed: 12/1 Problem: When put in reverse it stalls/PM Service	2.00 1.00
Bxt96r 59 shaft into tramsmission Left Front Shaft Syn-atf Trans Fluid S Shop Supplies Hours 7.00 Labor: 420.00 Parts: 838.21 Total: 1,25 Workorder: 1512737 Meter: 30234 In Date: 12/16/2015 Closed: 12/1 Problem: When put in reverse it stalls/PM Service	1.00
shaft into tramsmission Left Front Shaft Syn-atf Trans Fluid S Shop Supplies Hours 7.00 Labor: 420.00 Parts: 838.21 Total: 1,25 Workorder: 1512737 Meter: 30234 In Date: 12/16/2015 Closed: 12/1 Problem: When put in reverse it stalls/PM Service	1.00
Left Front Shaft Syn-atf Trans Fluid S Shop Supplies Hours 7.00 : Workorder: 1512737 Meter: 30234 In Date: 12/16/2015 Closed: 12/1 Problem: When put in reverse it stalls/PM Service	1.0
Syn-atf Trans Fluid S Shop Supplies Hours 7.00 : Workorder: 1512737 Meter: 30234 In Date: 12/16/2015 Closed: 12/1 Problem: When put in reverse it stalls/PM Service	1.00
Shop Supplies         Hours 7.00       Labor: 420.00       Parts: 838.21       Total: 1,25         Workorder:       1512737       Meter: 30234       In Date: 12/16/2015       Closed: 12/1         Problem:       When put in reverse it stalls/PM Service	4.00
Hours 7.00       Labor: 420.00       Parts: 838.21       Total: 1,25         Workorder:       1512737       Meter:       30234       In Date:       12/16/2015       Closed:       12/1         Problem:       When put in reverse it stalls/PM Service	1.00
Problem: When put in reverse it stalls/PM Service	
	7/2015
- Tow From: 1150 45th street (rear of Bldg)-health Dept	
Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00	
Workorder:         1601438         Meter:         30922         In Date:         02/10/2016         Closed:         02/1           Problem:         4 - Wash ticket(s) issued         6         7         6 <td></td>	
- 4 - Wash ticket(s) issued	0/2016
Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00	0/2016
Workorder: 1603859 Meter: 32424 In Date: 04/12/2016 Closed: 04/1 Problem: 4 - Wash ticket(s) issued	J/2016
	D/2016 2/2016
- 4 - Wash ticket(s) issued Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00	

Workorder: Problem:	1605236 P.M. service.	Meter:	33720			In Date:	05/19/2016	Closed:	05/31/20	016
- P.m. Service	э.				Parts Li	st				Qty
- Rotate and I	balance tires.				5w20 Er	ngine Oil				5.00
- Service and	adjust rear bra	akes.				d Oil Filter				1.00
- Shop Suppli	es				Accufit E	Beam				2.00
					Ww-120	2 Wiper Bla	ide M			1.00
					Shop Su	ipplies				1.00
	Houi :	rs 4.00		Labor:	240.00	Parts:	65.89	Total:	305.89	
Workorder: Problem:	1606851 Left rear tire g	Meter: going flat T	34364 PMS light on.			In Date:	07/07/2016	Closed:	07/18/20	016
- Replace and	d balance left r	ear tire.			Parts Li	st				Qty
- Shop Suppli	es				183407418 P235-70r16					
					Shop Su	ipplies				1.00
					Tire Dis	oosal Fee				1.00
	Hour :	rs 0.50		Labor:	30.00	Parts:	185.14	Total:	215.14	
Workorder: Problem:	1609149 Check engine	Meter: e light on.	35559			In Date:	09/01/2016	Closed:	09/29/20	016
- Diagnose ch	neck engine lig	ht P2450.p	erform pin poi	nt	Parts Li	st				Qty
test.replace de	efective evap s	ystem can			Vapor C	annister				1.00
	system bay tes	st.			Shop Su	pplies				1.00
- Shop Suppli		0.00		1 - 1	400.00	Dente	040.00	<b>T</b> . ( . )	000.00	
	Houi :	rs 3.00		Labor:	180.00	Parts:	216.22	i otal:	396.22	
Workorder: Problem:	1611971 P.M. service.	Meter:	36635			In Date:	11/18/2016	Closed:	11/30/20	016
- P.m. Service	Э.				Parts Li	st				Qty
- Rotate and I	balance tires.				5w20 Engine Oil					5.00
- Service and	adjust rear bra	akes.			Accufit E	Beam				2.00
- Shop Suppli	es				Accufit F	Rear				1.00
					Napago	d Oil Filter				1.00
					Washer	Fluid Conce	entr			1.00
					Used Fi	e X Refurbi	ished			1.00
					Shop Su	pplies				1.00
	Hour	rs 4.00		Labor:	240.00	Parts:	73.94	Total:	313.94	
Workorder: Problem:	1702919 1 - Detail Veh	Meter: icle Wash	38541 Ticket(s) Issue	ed		In Date:	03/22/2017	Closed:	03/22/20	017
	hicle Wash Tid									
		rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
	:	5 0.00			0.00	i ano.	0.00	i Utal.	0.00	

Workorder: Problem:	1704605 Not shifting (	<b>Meter:</b> Gears prope	39592 erly			In Date:	05/08/2017	Closed:	05/09/2017
- Tow From: "	1150 45th Stre	et, Health [	Dept To: Lv	Shop					
	Ηοι :	urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1704817 P.M. Service	<b>Meter:</b> e.Towed in,n	39651 not shifting p	roperly		In Date:	05/15/2017	Closed:	05/22/2017
- P.m service	)				Parts L	ist			Q
- Inspect and	I flush and serv	vice transmi	ssion .no filt	er.	5w20 E	ngine Oil			6.0
- Rotate and	high speed ba	lance all fou	ur wheels.nit	ro fill all.	Napago	old Oil Filter			1.(
- Shop Suppli	ies				Wiper E	Blade			2.0
					Accufit	Rear			1.(
					Washer	r Fluid Conce	entr		1.(
					Syn-atf	Trans Fluid	S		6.0
					Shop S	upplies			1.(
	Hou	urs 4.50		Labor:	270.00	Parts:	78.56	Total:	348.56
Workorder: Problem:	1710858 P.M. service	Meter:	41243			In Date:	11/02/2017	Closed:	11/16/2017
- P.m. service	Э.				Parts L	ist			Q
- Inspect and	service rear b	orakes.			5w20 E	ngine Oil			6.0
- Rotate and	balance four ti	ires.			Napago	old Oil Filter			1.(
- Shop Suppli	ies				Wiper E	Blade			2.0
					Accufit	Rear			1.(
					Washer	r Fluid Conce	entr		1.(
					Used Fi	ire X Refurbi	shed		1.(
					Shop S	upplies			1.(
	Hou	urs 4.00		Labor:	240.00	Parts:	67.61	Total:	307.61
Workorder: Problem:	1711685 5 - Wash tick		41243 d			In Date:	11/29/2017	Closed:	11/29/2017
- 5 - Wash tic	ket(s) issued								
	. ,	urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
	1800646	Meter:	41642			In Date:	01/19/2018	Closed:	01/31/2018
	ABS light on	comes on .							
Problem: - Computer d test.replace H		light,code C em and repr	1039.perforr		A.B.S	S . Module			<b>Q</b> 1.(
Problem: - Computer d test.replace H	ABS light on liagnoise Abs l lcu.bleed syste les and test dri	light,code C em and repr	1039.perforr		A . B . S B Fluid	S . Module Dot 3-32oz			1.0 4.0
Problem: - Computer d test.replace H Hcu.clear cod	ABS light on liagnoise Abs l lcu.bleed syste les and test dri	light,code C em and repr	1039.perforr		A . B . S B Fluid Non-chl	S . Module Dot 3-32oz Ior Brake Clr	ır		1.0 4.0 1.0
- Computer d test.replace H Hcu.clear cod	ABS light on liagnoise Abs I lcu.bleed syste les and test dri lies	light,code C em and repr	1039.perforr	calibrate	A . B . S B Fluid	S . Module Dot 3-32oz lor Brake Clr upplies	nr 1,640.71	<b>-</b>	1.0 4.0

Problem:	1803862 6 - Wash tick	Meter: (et(s) issued	42410 d			In Date:	04/13/2018	Closed:	04/13/20	)18
- 6 - Wash tic	cket(s) issued									
	Ηοι :	urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1804639 P.M. service	Meter: and radio in	42837 nop.			In Date:	05/03/2018	Closed:	05/17/20	)18
- P.m. service	е.				Parts L	ist				Qt
- Test radio a	and replace mi	ssing anten	na mast.rete	st	5w20 Ei	ngine Oil				6.0
	d adjust rear br					ld Oil Filter				1.0
- Rotate and	high speed ba	lance all for	ur wheels . N	itro fill all.	Washer	Fluid Conce	entr			1.0
- Shop Suppl	lies					actfit-beam				2.0
						actfit-rear				1.00
					Antenna					1.00
					Shop Su			<b>-</b>		1.00
	Hou :	ırs 4.30		Labor:	258.00	Parts:	91.40	l otal:	349.40	
Workorder: Problem:	1811321 P.M. service	Meter:	44222			In Date:	11/01/2018	Closed:	11/06/20	)18
- P.m. service	е.				Parts L	ist				Qty
- Test and re	place left rear	turn signal l	oulb.		Napago	ld Oil Filter				1.00
- Inspect and	l service rear b	orakes .			Napa Q	uart 5w20				6.00
- Rotate and	high speed ba	lance all for	ur tires.		12in Exa	actfit-rear				1.00
- Shop Suppl	lies				20in Exactfit-beam					2.00
					Used Fi	re X Refurbi	shed			1.00
						<i>liniatures</i>				1.00
					Shop Su					1.00
	Ηοι :	ırs 4.50		Labor:	301.50	Parts:	79.20	Total:	380.70	
Workorder: Problem:	1904745 P.M. service	Meter:	44734			In Date:	05/01/2019	Closed:	05/09/20	019
					Dente					04
- P.m. service	е.	- P.m. service.								QU
		ng system .	Battery faile	d load	Parts Li Napago					-
- Check starti	ing and chargi	ng system .	Battery faile	d load	Napago	ld Oil Filter				1.00
- Check starti test .r&r defec	ing and chargi		Ē		Napago 5w20 Ei		shed			1.00 6.00
- Check starti test .r&r defec - Rotate and	ing and chargi ctive battery . high speed ba		Ē		Napago 5w20 Ei Used Fi	ld Oil Filter ngine Oil	shed			1.00 6.00 1.00
- Check starti test .r&r defec - Rotate and	ing and chargi ctive battery . high speed ba		Ē		Napago 5w20 Ei Used Fi	ld Oil Filter ngine Oil re X Refurbi	shed			1.00 6.00 1.00 2.00
- Check starti test .r&r defec - Rotate and	ing and chargi ctive battery . high speed ba		Ē		Napago 5w20 Ei Used Fi 20in Exa	ld Oil Filter ngine Oil re X Refurbi	shed			1.00 6.00 1.00 2.00 1.00
- Check starti test .r&r defec - Rotate and	ing and chargi ctive battery . high speed ba		Ē		Napago 5w20 Er Used Fi 20in Exa Battery	ld Oil Filter ngine Oil re X Refurbi actfit-beam	shed			1.00 6.00 1.00 2.00 1.00
- Check starti est .r&r defec - Rotate and	ing and chargi ctive battery . high speed ba lies		Ē	ofill all.	Napago 5w20 Er Used Fi 20in Exa Battery Blade	ld Oil Filter ngine Oil re X Refurbi actfit-beam upplies	shed 195.74	Total:	463.74	1.00 6.00 1.00 2.00 1.00
- Check starti test .r&r defec - Rotate and - Shop Suppl	ing and chargi ctive battery . high speed ba lies Hou : 1910839	urs 4.00	ur tires . Nitro 44986	ofill all.	Napago 5w20 Er Used Fi 20in Exa Battery Blade Shop Si	ld Oil Filter ngine Oil re X Refurbi actfit-beam upplies		Total: Closed:	463.74	Qty 1.00 6.00 1.00 2.00 1.00 1.00 1.00
<ul> <li>Check starti test .r&amp;r defect</li> <li>Rotate and</li> <li>Shop Suppl</li> <li>Workorder: Problem:</li> </ul>	ing and chargi ctive battery . high speed ba lies Hou : 1910839 5 - Wash tick	urs 4.00	ur tires . Nitro 44986	ofill all.	Napago 5w20 Er Used Fi 20in Exa Battery Blade Shop Si	ld Oil Filter ngine Oil re X Refurbi actfit-beam upplies Parts:	195.74			1.00 6.00 1.00 2.00 1.00 1.00
<ul> <li>Check startitest .r&amp;r defect</li> <li>Rotate and</li> <li>Shop Suppl</li> <li>Workorder: Problem:</li> </ul>	ing and chargi ctive battery . high speed ba lies Hou : 1910839 : 5 - Wash tick cket(s) issued	urs 4.00	ur tires . Nitro 44986	ofill all.	Napago 5w20 En Used Fi 20in Exa Battery Blade Shop Sa 268.00	ld Oil Filter ngine Oil re X Refurbi actfit-beam upplies Parts:	195.74 10/22/2019		10/22/20	1.00 6.00 1.00 2.00 1.00 1.00

Problem:	1911271 P.M. service	Meter:	45090		Ir	n Date:	10/30/2019	Closed:	11/06/20	019
- P.m. service	Э.				Parts List					Qty
- Rotate and I	balance all fou	ur tires . Nitr	ofill all .		Napagold	Oil Filter				1.00
- Inspect and	service rear b	orakes.			5w20 Engine Oil					6.0
- Shop Suppli	ies				12in Exactfit-rear					1.0
					Washer Fl	uid Conc	entr			1.0
					20in Exact	fit-beam				2.00
					Shop Supp	olies				1.0
	Ηοι	urs 4.00		Labor:	292.00	Parts:	60.25	Total:	352.25	
Workorder: Problem:	2003306 P.m. service	Meter:	45879		Ir	n Date:	04/01/2020	Closed:	04/09/20	)20
- P.m. service		Parts List					Qt			
- Rotate and I	Napagold	Oil Filter				1.00				
- Inspect and	service rear b	orakes.			5w20 Engi	ne Oil				6.00
	iagnose no sta				12in Exact	fit-rear				1.0
Test starting . strating syster	R&r defective	sterring co	lumn flange	and retest	Washer Fl	uid Conc	entr			1.0
- Shop Suppli					20in Exact	fit-beam				2.0
- Shop Suppli	162				Used Fire	X Refurb	ished			1.0
					Steering Column Flange					1.0
						olies				1.00
	Hou :	urs 5.50		Labor:	401.50	Parts:	205.62	Total:	607.12	
Workorder: Problem:	2004484 Left rearwind	Meter: dow inop .	45924		Ir	n Date:	05/05/2020	Closed:	05/07/20	)20
- Diagnose le	ft rear window	vinop.R&r	broken left	rear	Parts List					Qty
	ator . Adjust gl				Window R	egulator				1.00
	ies				Shop Supp	-				1.00
<ul> <li>Shop Suppli</li> </ul>								Total	192.13	
- Shop Suppli	Hou	urs 1.00		Labor:	73.00	Parts:	119.13	Total.	102110	
Workorder:	Hou : 2010268 PM Service	urs 1.00 Meter:	46710	Labor:		Parts:	119.13	Closed:	10/19/20	)20
Workorder: Problem:	: 2010268 PM Service		46710	Labor:						
Norkorder: Problem: - P.m. service	: 2010268 PM Service	Meter:	46710	Labor:	Ir	n Date:				Qty
Norkorder: Problem: - P.m. service - Inspect and	: 2010268 PM Service e.	Meter:		Labor:	lr Parts List	<b>Date:</b> Oil Filter				<b>Qt</b> y 1.00
Norkorder: Problem: - P.m. service - Inspect and - Rotate and I	: 2010268 PM Service e. service rear b balance all fou	Meter:		Labor:	Ir Parts List Napagold	<b>Date:</b> Oil Filter ne Oil	10/13/2020			<b>Qt</b> 1.00 6.00
Norkorder: Problem: - P.m. service - Inspect and - Rotate and I	: 2010268 PM Service e. service rear b balance all fou	Meter:		Labor:	Ir Parts List Napagold 5w20 Engi	Dil Filter Dil Conce	10/13/2020			<b>Qt</b> 1.00 6.00 1.00
Norkorder: Problem: - P.m. service - Inspect and - Rotate and I	: 2010268 PM Service e. service rear b balance all fou	Meter:		Labor:	Ir Parts List Napagold 5w20 Engi Washer Fla	Dil Filter Dil Filter ne Oil uid Conce	10/13/2020 entr			<b>Qt</b> 1.00 6.00 1.00 2.00
Workorder: Problem: - P.m. service - Inspect and - Rotate and I	: 2010268 PM Service e. service rear b balance all fou	Meter:		Labor:	Ir Parts List Napagold 5w20 Engi Washer Fla 20in Exact	Dil Filter Dil Filter ne Oil uid Conce	10/13/2020 entr			<b>Qt</b> 1.00 6.00 1.00 2.00 1.00
Workorder: Problem: - P.m. service - Inspect and	: 2010268 PM Service e. service rear b balance all fou	Meter:		Labor:	Ir Parts List Napagold 5w20 Engi Washer Fla 20in Exact Non-chlor	<b>Dil Filter</b> ne Oil uid Conce fit-beam Brake Cli	10/13/2020 entr			<b>Qty</b> 1.00 6.00 1.00 2.00 1.00 2.00

Workorder: Problem:	2010313 4 - Wash ticke	Meter: t(s) issued	46681 I			In Date:	10/14/2020	Closed:	10/14/2020		
- 4 - Wash ticl	ket(s) issued										
	Hours	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00		
Workorder: Problem:	2103770 P.M. service.	Meter:	47478			In Date:	04/01/2021	Closed:	04/12/2021		
- Preventive Maint. Service						Parts List Qt					
- Rotated and	balanced all 4	tires. Nitro	ogen filled all t	ires.	12in Exactfit-rear 1.0						
	service rear bra	akes . clea	ned, lubed, a	nd	20in Exactfit-beam 2.0						
adjusted rear	brakes.				Napago	d Oil Filter			1.00		
	orn out rear win	dow lift st	uts. Replaced	d missing	5w20 Er	6.00					
antenna.					Used Fi	1.00					
- Shop Suppli	es				Antenna	l			1.00		
					Lift				1.00		
					Lift				1.00		
					Shop Su	pplies			1.00		
	Hours	s 4.80		Labor:	350.40	Parts:	172.41	Total:	522.81		
Workorder: Problem:	2105594 Transition Pre	Meter: p Charge	47478			In Date:	05/19/2021	Closed:	05/19/2021		
- Transition P	rep Charge										
	Hours :	s 2.00		Labor:	146.00	Parts:	0.00	Total:	146.00		