Palm Beach County Fleet Management Asset Maintenance History 10194205 2014 FORD F150 Pickup, 1/2 Ton

Total Hours: 97.75 Labor: 6,312.90 Parts: 8,171.05 Comm: 1,979.76 Charged: 16463.70

Work Order: 1403328 Meter: 0 In Date: 04/04/2014 Closed: 04/04/2014

Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1409580 Meter: 3614 In Date: 09/24/2014 Closed: 10/08/2014

Problem: Pm service.

Work Completed	Parts Issued	Quantity
- Pm service.	Napagold Oil Filter	1.00
- Right tag lamp inop.test and replace right tag lamp due to defe	ctive 5w20 Engine Oil	6.00
socket.	Floor Mat-2pc Rub Bk	1.00
- Rotate and balance all four tires.	Used Fire X Refurbished	1.00
- Shop Supplies	Tag Lamp	1.00
	Shop Supplies	1.00
Hours: 3.50 Comm: 0.00	Labor: 210.00 Parts: 90.79	Total: 300.79

Work Order: 1504311 Meter: 8818 In Date: 04/28/2015 Closed: 05/07/2015

Problem: Pm service.

Work Completed	Parts Issued	Quantity
- Pm service.	Tag Lamp	2.00
- Both tag lamp lens seperated.replace both defective ta	g lamp assemblies. 5w20 Engine Oil	6.00
- Rotate and balance all four tires.	Napagold Oil Filter	1.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Stg Wheel Cov - Ford	1.00
	Shop Supplies	1.00
Hours: 3.50 Comm: 0.00	Labor: 210.00 Parts: 93.20	Total: 303.20

Palm Beach County Fleet Management Asset Maintenance History 10194205 2014 FORD F150 Pickup, 1/2 Ton

Work Order: 1507982 Meter: 10710 In Date: 08/10/2015 Closed: 08/13/2015

Problem: Right front tire and left rear tire going flat.

Work CompletedParts IssuedQuantity- Repair abd balance right front and left rear tires.Shop Supplies1.00

- Shop Supplies

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 2.00 Total: 122.00

Work Order: 1510552 Meter: 13300 In Date: 10/19/2015 Closed: 10/29/2015

Problem: Pm service.

Work Completed		Parts Issued		Quantity
- Pm service Replace and balance all four tires.		Napagold Oil Filte	r	1.00
		5w20 Engine Oil		6.00
- Perform complete alignment.test drive.		22" Wiper Blade		2.00
- Shop Supplies		Used Fire X Refurb	oished	1.00
		Bigg Degreaser		1.00
		Hankook P235 75i	r17 Dp At	4.00
		Shop Supplies		1.00
		Tire Disposal Fee		4.00
Hours: 6.50	Comm: 0.00	Labor: 390.00	Parts: 908.61	Total: 1,298.61

Work Order: 1604477 Meter: 18470 In Date: 04/28/2016 Closed: 05/05/2016

Problem: P.M. Service

Work Completed		Parts Issued		Quantity
- P.m. Service.		Napagold Oil Filte	r	1.00
- Check trailer plug.replace corroded trailer plug	and rewire.	5w20 Engine Oil		6.00
- Replace broken right tail light.		Washer Fluid Cond	centr	1.00
- Rotate and balance all tires.		Napagold Air Filte	er	1.00
- Shop Supplies		trailer plug		1.00
		Clr Rtv Silcn Sealant		1.00
		Lamp Assembly		1.00
		Shop Supplies		1.00
Hours: 4.75	Comm: 0.00	Labor: 285.00	Parts: 155.96	Total: 440.96

Palm Beach County Fleet Management Asset Maintenance History 10194205 2014 FORD F150 Pickup, 1/2 Ton

Work Order: 1612392 Meter: 23289 In Date: 12/02/2016 Closed: 12/14/2016

Problem: P.M. Service.

Work Completed	Parts Issued	Quantity
- P.m. Service.	5w20 Engine Oil	6.00
- Blower inop on #1 setting.diagnose and replace defective blower re	sistor. Napagold Oil Filter	1.00
- Test battery and charging system.recharge and retest battery,fail loa	d 22" Wiper Blade	2.00
test.replace defective battery.	Washer Fluid Concentr	1.00
- Rotate and balance tires.	Used Fire X Refurbished	1.00
- Shop Supplies	Blower Resistor	1.00
	Battery 65	1.00
	Stg Wheel Cov - Ford	1.00
	Shop Supplies	1.00
Hours: 5.00 Comm: 0.00	Labor: 300.00 Parts: 241.30	Total: 541.30

Work Order: 1706122 Meter: 26921 In Date: 06/21/2017 Closed: 06/29/2017

Problem: P.M. Service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		6.00
 Replace and balance four new tires. Diagnose noise from engine area.replace noise belt tensioner and serpentine belt. Complete wheel alignment.test drive. Steering wheel vibrate when brakes applied.resurface front brake rotors.sand brake pads,service and caliper. Shop Supplies 		Napagold Oil Filte	r	1.00
		22" Wiper Blade		2.00
		Washer Fluid Concentr		1.00
		lube		1.00
		Hankook P235 75r17 Dp At		4.00
		Used Fire X Refurb	pished	1.00
		Tensioner Assy		1.00
		V Belt		1.00
		Shop Supplies		1.00
		Tire Disposal Fee		4.00
Hours: 10.50	Comm: 0.00	Labor: 630.00	Parts: 1,019.97	Total: 1,649.97

Palm Beach County Fleet Management Asset Maintenance History 10194205 2014 FORD F150 Pickup, 1/2 Ton

Work Order: 1712167 Meter: 32493 In Date: 12/12/2017 Closed: 12/19/2017

Problem: P.M. service and A/C inop.

Work Completed		Parts Issued		Quantity
P.m. service.Left front seat trim broken .r&r trim with new.Rotate and high speed balance all four tires.		5w20 Engine Oil		6.00
		Napagold Oil Filte	er	1.00
		22" Wiper Blade		2.00
- Shop Supplies		Washer Fluid Cond	centr	1.00
		seatpanel shield a	sy	1.00
		Housing		1.00
		Shop Supplies		1.00
Hours: 3.60	Comm: 0.00	Labor: 216.00	Parts: 141.52	Total: 357.52

Work Order: 1806049 Meter: 37811 In Date: 06/13/2018 Closed: 06/25/2018

Problem: PM Service

Work Completed	Parts Issued	Quantity
- P.m. Service.	5w20 Engine Oil	6.00
- Replace left brake lamp bulb.	Napagold Oil Filter	1.00
- Replace front and rear brake rotors and pads.service and lube	Used Fire X Refurbished	1.00
calipers.flush and bleed system.	22" Wiper Blade	2.00
- Rotate and balance tires.	Ford Triton Pvc Swc	1.00
- Shop Supplies	Lamp Asy	1.00
	Boxed Miniatures	1.00
	Brake Rotor	2.00
	Brake Pad	1.00
	Brake Pad	1.00
	Brake Rotor-dih Parki	2.00
	Brk Fluid Dot 4-12oz	3.00

Hours: 10.50 Comm: 0.00 Labor: 630.00 Parts: 580.97 Total: 1,210.97

Shop Supplies

1.00

Palm Beach County Fleet Management Asset Maintenance History 10194205 2014 FORD F150 Pickup, 1/2 Ton

Work Order: 1807904 Meter: 37811 In Date: 06/21/2018 Closed: 08/01/2018

Problem: Damage to right door, cab & all of the right side of bed

Work Completed

- Damage to right door, cab & all of the right side of bed

Hours: 0.00 Comm: 1,979.76 Labor: 0.00 Parts: 0.00 Total: 1,979.76

Work Order: 1900360 Meter: 42077 In Date: 01/09/2019 Closed: 01/17/2019

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.	Napagold Oil Filter		1.00	
- Test and replace left brake light bulb and high moun	5w20 Engine Oil		6.00	
- Rotate and high speed bal;ance all four tires . Nittrofi	22" Wiper Blade		2.00	
- Shop Supplies		Boxed Miniatures		1.00
		Boxed Miniatures		1.00
		Shop Supplies		1.00
Hours: 3.80	Comm: 0.00	Labor: 254.60	Parts: 29.37	Total: 283.97

Work Order: 1902841 Meter: 43204 In Date: 03/14/2019 Closed: 03/21/2019

Problem: Check engine light, No A/C.

Work Completed		Parts Issued		Quantity
- Diagnose check engine light.p0455.perform pin point test.replace defective purge valve.clear codes and retest.		Purge Valve		1.00
		Freon Lv Shop 2		2.00
- A/c performance test,leaking evaporator.r&r dash board	E8 A/c Oil Univ W Dye		1.00	
leaking evaporator, accumulator. vacuum and resharge system to specs.		A/c Evaporator		1.00
- Shop Supplies		accumulator		1.00
		Kit O		1.00
		Shop Supplies		1.00
Hours: 14.50	Comm: 0.00	Labor: 971.50	Parts: 870.11	Total: 1,841.61

Palm Beach County Fleet Management Asset Maintenance History 10194205 2014 FORD F150 Pickup, 1/2 Ton

Work Order: 1908494 Meter: 46990 In Date: 08/14/2019 Closed: 08/26/2019

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.	- P.m. service.			2.00
- Replace and balance all four tires . Nitrofill all.		Washer Fluid Concentr		1.00
- Complete front end alignment and road test		Napagold Oil Filte	r	1.00
- Shop Supplies		5w20 Engine Oil		6.00
		Used Fire X Refurbished		1.00
		Hankook P235 75r17 Dp At Shop Supplies		4.00
				1.00
		Tire Disposal Fee		4.00
Hours: 6.50	Comm: 0.00	Labor: 435.50	Parts: 944.45	Total: 1,379.95

Palm Beach County Fleet Management Asset Maintenance History 10194205 2014 FORD F150 Pickup, 1/2 Ton

Work Order: 2001362 Meter: 50828 In Date: 02/07/2020 Closed: 02/20/2020

Problem: PM Service.

Work Completed

- P.m. service.
- Check battery and charging system after fully charging battery . Battery failed load test . R&r defective battery .
- Resurface both front brake rotors . Replace front brake hoses , calipers, and pads . Flush and bleed brake system . Road test .
- Test and replace defective dome light bulb and high mount brake light bulbs .
- Replace broken right outside mirror glass . Replace broken fire extinguisher mount .
- Test and replace broken wiper transmission asembly .
- Rotate and balance all four tires. Nitrofill all.
- Shop Supplies

Parts Issued		Quantity
Napagold Oil Filte	r	1.00
5w20 Engine Oil		6.00
22" Wiper Blade		2.00
Washer Fluid Cond	centr	1.00
Battery 65		1.00
Brk Fluid Dot 4-32	OZ	2.00
Brake Pad		1.00
Reman/ca		1.00
Reman/ca		1.00
Boxed Miniatures		3.00
Boxed Miniatures		3.00
side mirror glass a	sy	1.00
Reman/ca		1.00
Aw68 Hydro Fluid	Hydr	40.00
Wiper Transmissic	n	1.00
Rf Brake Hose		1.00
Lf Brake Hose		1.00
Brk Fluid Dot 4-12	OZ	1.00
Caliper Washer		4.00
Fire Ext Mount Str	ap Style	1.00
Shop Supplies		1.00
Labor: 751.90	Parts: 856.84	Total: 1,608.7

Hours: 10.30 Comm: 0.00 Labor: 751.90

Palm Beach County Fleet Management Asset Maintenance History 10194205 2014 FORD F150 Pickup, 1/2 Ton

Work Order: 2005856 Meter: 52575 In Date: 06/12/2020 Closed: 06/18/2020

Problem: Fix driver healight

Work Completed		Parts Issued		Quantity
- Replace broken left headlight assemble.		Headlamp		1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 0.50	Comm: 0.00	Labor: 36.50	Parts: 388.02	Total: 424.52

Work Order: 2100387 Meter: 56227 In Date: 01/12/2021 Closed: 01/22/2021

Problem: P.M. service and brake light out and tire light on .

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Steering Wheel Cover Large	e 1.00
- Inspect and R & I two new tires on front, rotate and speed balar	ce all, 22" Wiper Blade	2.00
nitro fill	Washer Fluid Concentr	1.00
- Inspect rattling noise in exhaust system, catalytic convertor, R & R left	R left Napagold Oil Filter	1.00
catalytic convertor . Replace rusted nuts on manifold .	5w20 Engine Oil	6.00
- Inspect and R & I new left rear tail lamp asm, cracked	Used Fire X Refurbished	1.00
- Shop Supplies	Hankook P235 75r17 Dp At	2.00
	Converter	1.00
	Lamp Assembly	1.00
	Nut	4.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours: 7.50 Comm:	0.00 Labor: 547.50 Parts	s: 1,817.38 Total: 2,364.88

Work Order: 2106011 Meter: 58200 In Date: 06/02/2021 Closed: 06/08/2021

Problem: Please order a new ignition and door key for this truck. Thank you!

Work Completed Par		Parts Issued	Parts Issued	
- Program ignition key, replace spare		Ford Ignition Key Blank		1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 0.80	Comm: 0.00	Labor: 58.40	Parts: 30.60	Total: 89.00

Palm Beach County Fleet Management Asset Maintenance History

10194205 2014 FORD F150 Pickup, 1/2 Ton

Work Order: 2109820 Meter: 59578 In Date: 09/10/2021 Closed: 09/10/2021

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 97.75 Total Labor: 6,312.90 Total Comm: 1,979.76 Total Parts: 8,171.05