

10/25/2024  
4:04:46 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10196234 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body**

---

**Total Hours: 472.00    Labor: 32,577.40    Parts: 29,793.18    Comm: 49,835.39    Charged: 112205.96**

---

**Work Order:** 1502094      **Meter:** 1159      **In Date:** 02/26/2015    **Closed:** 02/26/2015  
**Problem:** 1062 - Make & Apply Decals. Check Fluids, Belts and Operation

**Work Completed**

- Make & Apply Decals. Check Fluids, Belts and Operation

Hours: 1.00      Comm: 0.00      Labor: 60.00      Parts: 0.00      Total: 60.00

---

**Work Order:** 1502098      **Meter:** 1159      **In Date:** 02/26/2015    **Closed:** 02/27/2015  
**Problem:** Check In

**Work Completed**

- Check in equipment  
- Shop Supplies

<b>Parts Issued</b>	<b>Quantity</b>
Shop Supplies	1.00

Hours: 5.00      Comm: 0.00      Labor: 300.00      Parts: 2.00      Total: 302.00

---

**Work Order:** 1502361      **Meter:** 1159      **In Date:** 03/05/2015    **Closed:** 04/16/2015  
**Problem:** Boom rest

**Work Completed**

- Modify Boom Rest

Hours: 0.00      Comm: 1,095.60      Labor: 0.00      Parts: 0.00      Total: 1,095.60

---

**Work Order:** 1508016      **Meter:** 6142      **In Date:** 08/11/2015    **Closed:** 08/25/2015  
**Problem:** PM

**Work Completed**

- pm  
- pm bucket  
- to altec  
- Shop Supplies

<b>Parts Issued</b>	<b>Quantity</b>
15-40 Oil	30.00
Napagold Oil Filter	1.00
Fuel Fil	1.00
2602212c1 Air Filter	1.00
Wiper Blade	2.00
Shop Supplies	1.00

Labor: 792.00      Parts: 299.41      Total: 1,091.41

Hours: 13.20      Comm: 0.00



10/25/2024  
4:04:46 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10196234 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body**

**Work Order:** 1603506  
**Problem:** PM/list

**Meter:** 13405

**In Date:** 04/04/2016 **Closed:** 04/20/2016

**Work Completed**

- Pm
- Scan codes code 23 repair Lf wheel sencer
- Pull wheel and replace Lf sencer
- Bucket Pm
- Fabricate rear cone holder
- Install missing trim panel on boom
- To Rechten 2xs
- Test Run
- Shop Supplies

**Parts Issued**

**Quantity**

Cabin Air Filter	1.00
15-40 Oil	30.00
Napagold Oil Filter	1.00
Fuel Fil	1.00
2602212c1 Air Filter	1.00
Napa Cabin Air Filter	1.00
Washer Fluid Concentr	1.00
Brake Cleaner	2.00
Used Fire X Refurbished	1.00
22" Wiper Blade	2.00
Speed Sensor	1.00
Hydraulic Filter	1.00
Gl Whit	1.00
Gray Sea	1.00
Retainer	1.00
11/8 cold roll steel	1.00
Shop Supplies	1.00

Hours: 20.50

Comm: 0.00

Labor: 1,230.00      Parts: 812.57      Total: 2,042.57

10/25/2024  
4:04:46 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10196234 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body**

**Work Order:** 1609741      **Meter:** 19056      **In Date:** 09/19/2016      **Closed:** 10/21/2016  
**Problem:** pm/strobe light

**Work Completed**

- pm
- pm upper
- directional light replace and strobe light in rear
- clean and retape upper boom
- Shop Supplies

**Parts Issued**

**Quantity**

Wiper Blade	2.00
Washer Fluid Concentr	1.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Fuel Fil	1.00
Napagold Oil Filter	1.00
2602212c1 Air Filter	1.00
15-40 Oil	30.00
Hydraulic Filter	1.00
Bulb	1.00
Boltron Tape	1.00
strobe light	1.00
Shop Supplies	1.00

Hours: 15.00

Comm: 0.00

Labor: 900.00

Parts: 699.95

Total: 1,599.95

**Work Order:** 1700474      **Meter:** 22403      **In Date:** 01/17/2017      **Closed:** 01/17/2017  
**Problem:** 1 - Key(s) issued

**Work Completed**

- 1 - Key(s) issued

**Parts Issued**

**Quantity**

Duplicate Vehicle Keys	1.00
------------------------	------

Hours: 0.30

Comm: 0.00

Labor: 18.00

Parts: 3.00

Total: 21.00

**Work Order:** 1700674      **Meter:** 22694      **In Date:** 01/24/2017      **Closed:** 02/01/2017  
**Problem:** NO Start

**Work Completed**

- Jump start and replace batteries
- To Traffic 2xs
- Shop Supplies

**Parts Issued**

**Quantity**

Group 31 Stud Delco	2.00
Shop Supplies	1.00

Hours: 3.00

Comm: 0.00

Labor: 180.00

Parts: 294.68

Total: 474.68









10/25/2024  
4:04:46 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10196234 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body**

**Work Order:** 1812608

**Meter:** 42742

**In Date:** 12/12/2018 **Closed:** 02/13/2019

**Problem:** PM/ air leak

**Work Completed**

- Pm
- Bucket Pm
- Repair air leaks
- Pull Codes Spn 164, Spn 1323, Spn 2659, Spn 520863,520862, 520861
- Head Light
- Service Ac, Replace highside valve evac and charge, Replaced Ac control assembly
- Tested and replaced lcp sensor under the valve cover
- Pintle Pin
- Replaced rear step
- Road test
- Tested and replaced batteries. Tested electrical system
- Shop Supplies

**Parts Issued**

**Quantity**

Non-chlor Brake Clnr	2.00
15-40 Oil	30.00
Filter	1.00
Air Filter	1.00
Napagold Oil Filter	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
1cart Palladium 2 Grs	1.00
Hydraulic Filter	1.00
tee	1.00
W W Vacuum Tubing	6.00
Boxed Capsules	1.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Evap Odor Elinitator	1.00
Cable Tie	1.00
Gasket	1.00
lcp Sensor	1.00
Pintle Pin W/clip	1.00
Group 31 Stud Delco	2.00
Freon He Shop	3.00
A/c Controler Panel	1.00
Shop Supplies	1.00

Hours: 41.00

Comm: 0.00

Labor: 2,747.00

Parts: 2,519.94

Total: 5,266.94











10/25/2024  
4:04:46 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10196234 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body**

**Work Order:** 2105506      **Meter:** 61294      **In Date:** 05/17/2021      **Closed:** 06/30/2021

**Problem:** Do for PM check up also truck has a water leak ,air leak ,please check brakes

**Work Completed**

- Preventive Maint. Service
- Bucket inspection
- Clean and adjust front brakes.
- Rr rear brakes measured below allowed specs
- Trace air leaks, found one under cab behind engine bay and another one in Schrader valve, repaired lines .
- Service rear differential.
- Service air conditioning
- Travel time to International and back.
- Did not find any water leaks, in cab or by engine
- Shop Supplies

**Parts Issued**

**Quantity**

15-40 Oil	30.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Filter	1.00
Air Filter	1.00
Non-chlor Brake Clnr	6.00
1cart Palladium 2 Grs	1.00
Hydraulic Filter	1.00
Dielectric Oil Aw Hvi	1.00
85-140 Gear Oil Gear	20.00
Gear Oil	6.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Brake Shoe Kits- New	2.00
Brake Drum	2.00
Shop Supplies	1.00

Hours: 33.50

Comm: 0.00

Labor: 2,445.50

Parts: 1,335.58

Total: 3,781.08

**Work Order:** 2107146      **Meter:** 61294      **In Date:** 06/29/2021      **Closed:** 07/08/2021

**Problem:** check engine light on

**Work Completed**

- Engine,other

Hours: 0.00

Comm: 1,083.18

Labor: 0.00

Parts: 0.00

Total: 1,083.18



10/25/2024  
4:04:46 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10196234 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body**

---

**Work Order:** 2200385      **Meter:** 64826      **In Date:** 01/12/2022      **Closed:** 02/17/2022  
**Problem:** PM Service ,AC and heating needs checking AC blows hot air and cuts in & out .

**Work Completed**

**Parts Issued**

**Quantity**

- Preventive Maint. Service	15-40 Oil	30.00		
- Bucket Pm	Napagold Oil Filter	1.00		
- service A/c system & check A/c system over	Filter	1.00		
- To Altec 2xs	Air Fltr	1.00		
- Road test	Washer Fluid Concentr	1.00		
- Shop Supplies	Wiper Blade	2.00		
	Non-chlor Brake Clnr	3.00		
	Used Fire X Refurbished	1.00		
	Napa Cabin Air Filter	1.00		
	Cabin Air Filter	1.00		
	Hydraulic Filter	1.00		
	Shop Supplies	1.00		
Hours: 19.00	Comm: 0.00	Labor: 1,387.00	Parts: 379.48	Total: 1,766.48

---

**Work Order:** 2200752      **Meter:** 64826      **In Date:** 01/24/2022      **Closed:** 02/02/2022  
**Problem:** annual/repairs

**Work Completed**

- Annual Bucket Inspection				
- dielectric test				
- repairs by altec				
Hours: 0.00	Comm: 3,045.46	Labor: 0.00	Parts: 0.00	Total: 3,045.46

---

**Work Order:** 2204183      **Meter:** 66196      **In Date:** 04/20/2022      **Closed:** 04/25/2022  
**Problem:** Driver side needs a head light bulb replaced . Will drive truck down to be put in. Thank You

**Work Completed**

**Parts Issued**

**Quantity**

- Lights,headlites	Boxed Capsules	1.00		
- Shop Supplies	Shop Supplies	1.00		
Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 10.10	Total: 83.10

10/25/2024  
4:04:46 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10196234 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body**

---

**Work Order:** 2204899      **Meter:** 66493      **In Date:** 05/05/2022      **Closed:** 06/06/2022  
**Problem:** Oil pressure jumps all over the place the light comes on ,Truck shut down twice also has the up side down triangle

**Work Completed**

**Parts Issued**

**Quantity**

- oil pressure gauge inop. - check sensor, leaking internally shorted. replace sensor and clean connector ok

Sensor 1.00

Drive Belt 1.00

- belt squeak - found tensioner coming apart. replace belt and tensioner

Tensioner 1.00

- air leak - found several leaking fittings, remove dog house to access. replace fittings. leak when brakes applied, found bad rear chambers. replace

Brake Chamber 2.00

Shop Supplies 1.00

- a/c low air flow - found 2 very dirty cabin air filters. clean filters and check ok

- Shop Supplies

Hours: 9.00

Comm: 0.00

Labor: 657.00

Parts: 861.50

Total: 1,518.50

---

**Work Order:** 2207686      **Meter:** 67057      **In Date:** 07/25/2022      **Closed:** 07/25/2022  
**Problem:** 1 - Key(s) Issued

**Work Completed**

**Parts Issued**

**Quantity**

- 1 - Key(s) Issued

Duplicate Vehicle Keys 1.00

Hours: 0.30

Comm: 0.00

Labor: 21.90

Parts: 3.00

Total: 24.90

10/25/2024  
4:04:46 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10196234 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body**

**Work Order:** 2209648      **Meter:** 68239      **In Date:** 09/15/2022      **Closed:** 10/31/2022  
**Problem:** PM Service.When starting displaying wrench light on dash,(2) Check engine light,# DPF Exhaust filter warning light,(3)

**Work Completed**

**Parts Issued**

**Quantity**

- Pm service
- Pm Bucket
- Dpf warning ; check engine ; wrench light on - scan truck, codes (3719 soot load 2/3), (94 fuel pressure low) // low fuel pressure causes wrench light //
- perform parked regen - light went off. cleared code
- Road test
- Service A/c system
- Install Rh strobe light & Rewire
- Service Transmission
- Shop Supplies

15-40 Oil	30.00
Napa Trans Filter	1.00
Syn-atf Trans Fluid S	20.00
strobe light	1.00
Napagold Oil Filter	1.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Dielectric Oil Aw Hvi	8.00
Filter	1.00
Hydraulic Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Air Fltr	1.00
Shop Supplies	1.00

Hours: 18.50

Comm: 0.00

Labor: 1,350.50

Parts: 731.29

Total: 2,081.79

**Work Order:** 2211313      **Meter:** 68886      **In Date:** 11/02/2022      **Closed:** 01/11/2023  
**Problem:** Please check AC driver states it blows cool some time and hot the next

**Work Completed**

- Air Conditioning

Hours: 0.00

Comm: 0.00

Labor: 0.00

Parts: 0.00

Total: 0.00

**Work Order:** 2301986      **Meter:** 70802      **In Date:** 02/28/2023      **Closed:** 04/26/2023  
**Problem:** Backup alarm not working ,Ac will blow cold then goes warm Barely blows Park regeneration. wont work/ PM/ Annual

**Work Completed**

**Parts Issued**

**Quantity**

- Preventive Maint. Service
- To Altec 2xs
- Annual

Hose Made Mako	1.00
Hose Made Mako	1.00
15-40 Oil	30.00

10/25/2024  
4:04:46 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10196234 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body**

	<b>Parts Issued</b>	<b>Quantity</b>
- Dielectric Test	Wiper Blade	2.00
- Bucket Pm	Washer Fluid Concentr	1.00
- Altec Repairs	Napagold Oil Filter	1.00
- Rear reflectors cracked. R&r reflectors	Filter	1.00
- Radiator drain connector leaking. R&r drain coupler.	Air Fltr	1.00
- To Mako 2x	Stiction Elimint 32oz	2.00
- Service A/c system	Non-chlor Brake Clnr	3.00
- Back up alarm inop. Inspect wiring. Found faulty buzzer. R&r backup alarm buzzer.	Hydraulic Filter	1.00
- Tag light broken, Cab light out, and turn signal inop.. Replace broken tag light, cab light, and turn signal bulb	Clearance Light	1.00
- R&r air drier.	fuel pump	1.00
- Operator states warning lights on. Connect scan tool and retrieve codes. Codes for Low fuel pressure, Dpf, and low Egr flow present. Perform Diagnostics per repair manual.	Used Fire X Refurbished	1.00
- Diagnostics show low fuel pressure. Replace fuel pumps assy and housing.	Dryer	1.00
- Egr flow insufficient. Extract seized into housing Egr valve. Decarbonize housing and deburr and clean sealing surfaces. Replace Egr valve, Pressure transducer and Temp sensor.	Napa Cabin Air Filter	1.00
- Dpf soot level high. Perform manual regen.	Cabin Air Filter	1.00
- A/c inop. Found Low refrigerant level. Charge and leak test. Found leaking shaft seal and evaporator. R&r compressor, drier, evaporator, and condenser assy. Evac and fill unit.	Boxed Miniatures	1.00
- Service P/s system	Led Tag Light	1.00
- Service cooling system	Ad Ip Dryer Cart	1.00
- Front hub caps leaking and slop in bearings. Retorque front bearings and replace hub caps. Fill front hubs.	Egr Actuator	1.00
- Batteries failed load test. R&r batteries	Non-chlor Brake Clnr	3.00
- Test Run	Freon He Shop	30.00
- Shop Supplies	Temp Sensor	1.00
	Expansion Valve	1.00
	evap coil	1.00
	A/c Compressor	1.00
	Condenser	1.00
	Psf Qt	3.00
	Power Steering Filter	1.00
	Rotell Elc Antifeerze	8.00
	Napa Gear 80w-90 Qt	2.00
	oil hub cap	2.00

10/25/2024  
4:04:46 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10196234 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body**

<b>Parts Issued</b>	<b>Quantity</b>
A/c Seal Kit	1.00
Reflectr	1.00
Group 31 Stud Delco	2.00
Heater Hose 10196234	1.00
13 Oz Aero Kroil	1.00
Sensor	1.00
switch	1.00
Switch	1.00
Hose Clamp	6.00
2507061c1 Gasket P-st	1.00
Alarm	1.00
Preco Back Up Alarm	1.00
Fuel Filter Housing	1.00
Shop Supplies	1.00
Freight Charge	1.00
Hours: 57.00	Comm: 1,626.44
Labor: 4,161.00	Parts: 9,272.18
Total: 15,059.62	

---

**Work Order:** 2306545      **Meter:** 72419      **In Date:** 07/05/2023      **Closed:** 07/06/2023  
**Problem:** No Start

**Work Completed**

- Battery Rr battery no crank
- To Traffic engineering
- Shop Supplies

<b>Parts Issued</b>	<b>Quantity</b>
Group 31 Stud Delco	2.00
Shop Supplies	1.00
Hours: 3.00	Comm: 0.00
Labor: 219.00	Parts: 295.21
Total: 514.21	



10/25/2024  
4:04:46 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10196234 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body**

- Fire bracket
- Hub seals crack Rr
- Drag link and shocks
- replace headlights
- king pins alignment by Onsite
- Shop Supplies

<b>Parts Issued</b>	<b>Quantity</b>	
Wiper Blade	2.00	
Air Fltr	1.00	
Filter	1.00	
Hotshot	1.00	
Dielectric Oil Aw Hvi	8.00	
Hydraulic Filter	1.00	
Lucas 85-140 Gear Oil	3.00	
Cabin Air Filter	1.00	
Cabin Air Filter	1.00	
6" Vise	1.00	
Blade Guide Org 3 4in	1.00	
Group 31 Stud Delco	3.00	
Gfil Gasket	2.00	
Fire Ext Mount Strap Style	1.00	
Steering Link	1.00	
Front Shocks	2.00	
9007 Led	2.00	
On Site Aligment	1.00	
Shop Supplies	1.00	
<b>Labor: 4,453.00</b>	<b>Parts: 6,163.21</b>	<b>Total: 12,680.18</b>

Hours: 61.00

Comm: 2,063.97

10/25/2024  
4:04:46 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10196234 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body**

---

**Work Order:** 2404308      **Meter:** 77746      **In Date:** 05/01/2024      **Closed:** 06/17/2024  
**Problem:** annual/inverter inop/bucket only works from lower controls

**Work Completed**

**Parts Issued**

**Quantity**

- Annual Bucket Inspection
- diagnose upper controls not working
- to altec 2xs
- repairs by altec
- dielectric testing
- Shop Supplies

Shop Supplies

1.00

---

Hours: 5.00      Comm: 8,225.91      Labor: 365.00      Parts: 2.65      Total: 8,593.56

---

**Work Order:** 2405439      **Meter:** 77746      **In Date:** 06/04/2024      **Closed:** 08/06/2024  
**Problem:** ABS light/Engine light derate

**Work Completed**

**Parts Issued**

**Quantity**

- engine light on along with Abs .
- Shop Supplies

Shop Supplies

1.00

---

Hours: 2.00      Comm: 0.00      Labor: 146.00      Parts: 2.65      Total: 148.65

---

**Work Order:** 2407144      **Meter:** 77746      **In Date:** 07/24/2024      **Closed:** 07/31/2024  
**Problem:** Transition Prep Charge

**Work Completed**

- Transition Prep Charge

---

Hours: 2.00      Comm: 0.00      Labor: 146.00      Parts: 0.00      Total: 146.00

---

**Total Hours: 472.00      Total Labor: 32,577.40      Total Comm: 49,835.39      Total Parts: 29,793.18**