

Department of Public Works

650 Old Dixie Highway, Lake Park, Florida 33403

Vehicle Work Order

Vehicle Information

ID/Make/Model/Year: 50 Autocar/WX64 side loader/2009/5VCDC6JF79H208151
Division: SANITATION

Requested by (Dept/Div/Name)

Date: 6/7/21

Location:

Assigned To: *Henry*

Completed By:

Priority:

Scheduled Completion Date:

Description of Work: Two way radio does not work.

Actual Work Performed: *Diagnosis of radio concern, faulty speaker in radio. Replaced radio with a stock unit.*

Actual Completion Date: *6/8/21*

Total Man Hours: *1.0*

AUTHORIZING
SIGNATURE: _____

[Handwritten Signature]

Department of Public Works

650 Old Dixie Highway, Lake Park, Florida 33403

Vehicle Work Order

Vehicle Information

ID/Make/Model/Year: 50 Autocar/WX64 side loader/2009/5VCDC6JF79H208151
Division: SANITATION

Requested by (Dept/Div/Name)

Date: 6/7/21

Location:

Assigned To:

Completed By: *Henry*

Priority:

Scheduled Completion Date:

Description of Work: # 4 # 8 and # 9 tires are bad.

Actual Work Performed: *Replaced tires #4, #8 and #9*

Actual Completion Date: *6/8/21* Total Man Hours: *1.5*

AUTHORIZING
SIGNATURE: _____

[Handwritten Signature]

WORK REQUEST

TOWN OF LAKE PARK, FLORIDA
DEPARTMENT OF PUBLIC WORKS

25904

REQUESTED BY (DEPT./DIV./NAME): Sanitation/Sam DATE: 11/13/14

LOCATION/EQUIPMENT NO.: # 50

DESCRIPTION/NATURE OF WORK: # 9 tire is ~~very~~ Bad

(For Public Works Department Use Only)

ASSIGNED TO: Vehicle Maint AUTHORIZED BY: Dwg DATE: 11/13/14
(Gets White & Yellow Copies) (Keep Pink Copy)

PRIORITY: _____ SCHEDULED COMPLETION DATE: _____

WORK PERFORMED: Replaced #9 Tire.

ACTUAL COMPLETION DATE: 11/14/14 WORK COMPLETED SATISFACTORILY: _____
(Supervisor)

NO. OF MEN PERFORMED THIS WORK: 1 TOTAL MAN HOURS TO COMPLETE: .8
(Materials/Parts/Supplies Used)

Qty	Part No.	Description	Unit Price	Amount
1	11R	Tire		\$188.00

Notes: _____

Total

WORK REQUEST

TOWN OF LAKE PARK, FLORIDA
DEPARTMENT OF PUBLIC WORKS

25525

REQUESTED BY (DEPT./DIV./NAME): Sanitation DATE: 4/21/14

LOCATION/EQUIPMENT NO.: #50

DESCRIPTION/NATURE OF WORK: #10 tire is very bad / Engine light coming on / ABS light says on / Air leak inside cab?
(For Public Works Department Use Only) passenger side

ASSIGNED TO: Vehicle Maint AUTHORIZED BY: [Signature] DATE: 4/21/14
(Gets White & Yellow Copies) (Keep Pink Copy)

PRIORITY: _____ SCHEDULED COMPLETION DATE: _____

WORK PERFORMED: Replaced #10 Tire, Air Pressure Valve Leaking. Replace Valve, Vehicle to go to Dealer for CEL & ABS Lamp.

ACTUAL COMPLETION DATE: 4/23/14 WORK COMPLETED SATISFACTORILY: [Signature]
(Supervisor)

NO. OF MEN PERFORMED THIS WORK: 1 TOTAL MAN HOURS TO COMPLETE: 2.5h
(Materials/Parts/Supplies Used)

Qty	Part No.	Description	Unit Price	Amount
1		11R 22.5	\$	180.00
1		Air Valve	\$	54.31

Notes: _____ Total

WORK REQUEST

TOWN OF LAKE PARK, FLORIDA
DEPARTMENT OF PUBLIC WORKS

24712

REQUESTED BY (DEPT./DIV./NAME): Sanitation / Sam DATE: 12/19/13

LOCATION/EQUIPMENT NO.: #50

DESCRIPTION/NATURE OF WORK: Antifreeze leaking

(For Public Works Department Use Only)

ASSIGNED TO: Vehicle Maintenance AUTHORIZED BY: Dwayne DATE: 12/19/13
(Gets White & Yellow Copies) (Keep Pink Copy)

PRIORITY: _____ SCHEDULED COMPLETION DATE: _____

WORK PERFORMED: Replaced Radiator Cap.

ACTUAL COMPLETION DATE: 12-19-13 WORK COMPLETED SATISFACTORILY: PM
(Supervisor)

NO. OF MEN PERFORMED THIS WORK: 1 TOTAL MAN HOURS TO COMPLETE: .5
(Materials/Parts/Supplies Used)

Qty	Part No.	Description	Unit Price	Amount
		<u>Rad. Cap</u>		<u>\$13.00</u>

Notes: _____

Total

WORK REQUEST

TOWN OF LAKE PARK, FLORIDA
DEPARTMENT OF PUBLIC WORKS

24710

REQUESTED BY (DEPT./DIV./NAME): Sanitation / Sam DATE: 12/19/13

LOCATION/EQUIPMENT NO.: # 50

DESCRIPTION/NATURE OF WORK: Hydraulic Leak / on tank.
Need gasket

(For Public Works Department Use Only)

ASSIGNED TO: Vehicle Maintenance AUTHORIZED BY: Dwayne DATE: 12/19/13
(Gets White & Yellow Copies) (Keep Pink Copy)

PRIORITY: _____ SCHEDULED COMPLETION DATE: _____

WORK PERFORMED: Replace L/S Packen Cylinder Hose.
Replace Sump Door Gasket on left Side.

ACTUAL COMPLETION DATE: 12-19-13 WORK COMPLETED SATISFACTORILY: (PW)
(Supervisor)

NO. OF MEN PERFORMED THIS WORK: 1 TOTAL MAN HOURS TO COMPLETE: 2.0h
(Materials/Parts/Supplies Used)

Qty	Part No.	Description	Unit Price	Amount
1		L/S Packen Hose	\$	159.00
1		Sump Door Seal		54.95

Notes: _____

Total

WORK REQUEST

TOWN OF LAKE PARK, FLORIDA
DEPARTMENT OF PUBLIC WORKS

21918

REQUESTED BY (DEPT./DIV./NAME): V. M. DATE: 4/24/12

LOCATION/EQUIPMENT NO.: 50

DESCRIPTION/NATURE OF WORK: P.M. Service

(For Public Works Department Use Only)

ASSIGNED TO: Henry AUTHORIZED BY: _____ DATE: _____
(Gets White & Yellow Copies) (Keeps Pink Copy)

PRIORITY: _____ SCHEDULED COMPLETION DATE: _____

WORK PERFORMED: Completed P.M. Service,

ACTUAL COMPLETION DATE: 4/24/12 WORK COMPLETED SATISFACTORILY: PM
(Supervisor)

NO. OF MEN PERFORMED THIS WORK: 1 TOTAL MAN HOURS TO COMPLETE: 3.0 hrs
(Materials/Parts/Supplies Used)

Qty	Part No.	Description	Unit Price	Amount
1	RS 3518	Air Filter		\$59.01
1	BD7309	Oil Filter		\$38.68
7.2	15W-40	Oil		

Notes: _____

Total

WORK REQUEST

TOWN OF LAKE PARK, FLORIDA
DEPARTMENT OF PUBLIC WORKS

18571

REQUESTED BY (DEPT./DIV./NAME): Sanitation DATE: 4/26/2010

LOCATION/EQUIPMENT NO.: # 50

DESCRIPTION/NATURE OF WORK: Need Tire # 2, 3, and 4, 9

(For Public Works Department Use Only)

ASSIGNED TO: Paul AUTHORIZED BY: _____ DATE: _____
(Gets White & Yellow Copies) (Keeps Pink Copy)

PRIORITY: _____ SCHEDULED COMPLETION DATE: _____

WORK PERFORMED: Replaced Tires 2, 3, 4 and 9

ACTUAL COMPLETION DATE: 5/5/10 WORK COMPLETED SATISFACTORILY: PN
(Supervisor)

NO. OF MEN PERFORMED THIS WORK: 1 TOTAL MAN HOURS TO COMPLETE: 3.0
(Materials/Parts/Supplies Used)

Qty	Part No.	Description	Unit Price	Amount
3	11R	Tires	\$167.00	\$501.00
1	325	Tire		\$378.00

Notes: _____

Total

WORK REQUEST

TOWN OF LAKE PARK, FLORIDA
DEPARTMENT OF PUBLIC WORKS

17650

REQUESTED BY (DEPT./DIV./NAME): Sam / Sanitation DATE: 12/3/09

LOCATION/EQUIPMENT NO.: # 50

DESCRIPTION/NATURE OF WORK: Check Camera, and replace # 7 and # 8 tires.

(For Public Works Department Use Only)

ASSIGNED TO: *Paul Head* AUTHORIZED BY: _____ DATE: _____
(Get White & Yellow Copies) (Keep Pink Copy)

PRIORITY: _____ SCHEDULED COMPLETION DATE: _____

WORK PERFORMED: Diag, Replaced Truck Monitor And Cable That Feeds Hopper Camera.

See W.R. # 18244 For Tires.

ACTUAL COMPLETION DATE: 12/11/09 WORK COMPLETED SATISFACTORILY: *PM*
(Supervisor)

NO. OF MEN PERFORMED THIS WORK: 1 TOTAL MAN HOURS TO COMPLETE: 2.5
(Materials/Parts/Supplies Used)

Qty	Part No.	Description	Unit Price	Amount
1		Monitor		\$ 616.20
1		Cable		\$ 31.20

Notes: _____ Total

SAFETY RECALL NOTICE



#50

AUTOCAR SAFETY RECALL A-0901
NHTSA RECALL 09V- 060
March 2009

Dear Autocar Truck Owner:

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act. Autocar, LLC has decided that a defect which relates to motor vehicle safety exists in a total of 690 model-year 2008 and 2009 ACX, WX and WXLL-model heavy-duty class 8 vehicles built between 11 June 2008 and 17 November 2008, with serial numbers in the range 206951 through 208933.

MODELS
AFFECTED:

Autocar ACX, WX and WXLL 2008 and 2009

COMPONENTS
AFFECTED:

Quick Release Valves (QRV) (Autocar Part number 72901-00 16)

SAFETY DEFECT:

The defect occurs in the QRV's of the affected vehicles. Some or all of the QRV's leak. Autocar based its determination of the vehicle range on the QRV supplier's reported time line of production of the affected QRV's commencing 27 May 2008 with a Julian date code of 148 and continuing through 15 October 2008 with a production date code of 289.

POTENTIAL RISK:

There are QRV's in two areas of Autocar's vehicles (the attached drawing shows the general locations where the QRV's may be located on different Autocar model vehicles):

1. Tag Axle Air Lines QRV: A leak in the QRV of the tag axle air lines would release pressure on the tag axle lift mechanism. A minor or slow leak may affect the rate at which the tag axle is lowered or raised. A spontaneous catastrophic failure of the QRV would result in a rapid drop of a raised tag axle, potentially causing serious injury or death to a person working under or near the axle who failed to take proper safety precautions prior to working under or near the truck.
2. Park Brake Air Lines QRV: A leak in the QRV of the park brake air lines would release pressure on the park brake springs, which may, if the leak is large enough, cause the pressure to drop and set the brakes on the rear axle or axles, potentially resulting in the loss of vehicle control.

PRECAUTIONS YOU
CAN TAKE:

During routine maintenance, release the parking brakes (push in the dash control valve) and then inspect the QRV valves for leakage (audible) out of the exhaust ports.

CAUTION: FOLLOW LOCKOUT / TAGOUT PROCEDURES

Before entering the vehicle or vehicle body, read and follow OSHA regulations concerning entry and working in "CONFINED SPACE" OSHA 1910.146 and "LOCKOUT/TAGOUT" OSHA 1910.147. Follow OSHA regulations while performing any work on the vehicle. The vehicle must be disabled by the following steps before performing any work on the vehicle:

#20

SAFETY RECALL NOTICE



1. Place the transmission in NEUTRAL.
2. Set the parking brake.
3. Shut the engine OFF.
4. Lock the cab doors. Keep the key in your pocket. Block the wheels before entering the body or performing any work on the vehicle.
5. Turn the battery disconnect switch OFF.
6. Completely drain the air from the primary/A system and secondary/B system by opening the drain valves on the air tanks themselves or by using the drain manifold if supplied. When draining the air tanks, do not look into the area where air is draining. Dirt or sludge particles may be expelled in the air stream and can cause eye injury.
7. Place magnetic "DANGER" signs on both cab doors before entering the body or performing any work on the vehicle.
8. Take proper precautions before working under the vehicle. Use ramps approved for the weight of your vehicle, or use floor jacks and stands. Never work under a vehicle supported by jacks alone. Always use jack stands to support the vehicle.

REPAIR REQUIRED: At no charge to you regardless of your truck's age or mileage, Autocar will replace the affected the QRV's.

TIME REQUIRED FOR THE REPAIR: The labor time required to repair your truck is about 0.5 hours.

WHAT YOU SHOULD DO: Contact an Autocar dealer to schedule a service appointment to have your vehicle checked. For further assistance, call Autocar at 877-973-3486 or 888-218-3611.

PRIOR REPAIRS: If you have previously paid for repairs relating to the leaking QRV's, you may be entitled to recover of the amount you paid for those repairs. Submit a copy of all documentation supporting your claim to Autocar at the address set forth below in the "Assistance" section.

NOTICE REGARDING LEASED VEHICLES: If you are a Lessor (as defined below) of a vehicle that is affected by this Notice, you are obligated under federal law to provide a copy of this Notice to the lessee of such vehicle within 10 days of your receipt of this Notice. Further, you must maintain a record, which identifies the lessee(s) to whom you send a copy of this Notice, the date you send the Notice and the VIN of the vehicle that you have leased to the lessee(s).

For purposes of this Notice, the term "Lessor" means a person or entity that is the owner, as reflected on the vehicle's title, of any five or more leased vehicles (as defined in 49 CFR Section 577.4), as of the date of this Notice.

OWNER RECALL RESPONSE CARD: The enclosed Owner Recall Response Card identifies your truck. Please complete this postage-paid card and return it to Autocar. If you do not own, have sold or have traded the vehicle identified on the card, please indicate that on the postage-paid card and return it to Autocar.

SAFETY RECALL NOTICE



ASSISTANCE:

If you need assistance with this recall, call our toll-free numbers below or write to Autocar at:

Autocar, LLC
Service & Warranty Department
P. O. Box 190
Hagerstown, IN 47346-0190
888-218-3611 (Toll Free)
877-973-3486 (Toll Free)

You may also submit a complaint to:

Administrator
National Highway Traffic Safety Administration
1200 New Jersey Avenue SE
Washington, DC 20590

or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 800-424-9153);
or go to <http://www.safercar.gov>.


We regret any inconvenience this recall may cause, but we hope you recognize Autocar's concern for your safety and satisfaction with your truck.

Sincerely,


AUTOCAR, LLC

Locations of Autocar QRV

	Number of QRV's
Truck with typical single rear axle	0
Truck with typical tandem rear axles	1
Truck with tandem rear + tag or Pusher	3
Truck with tandem rear + Tag + Pusher Axles	5



#1 Picture for typical tandem rear axles



#2 picture for Tag (auxiliary) axles - Location may vary a little due to options

#3 Picture for Pusher (auxiliary) axles - looks like the #2 only on a cross member near the pusher axle

