

5/8/2025
3:50:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10206698 2018 LEBOY 400 Roller, Vibratory, 2.5 - 5 Ton

Total Hours: 151.25 Labor: 10,818.75 Parts: 11,860.51 Comm: 305.00 Charged: 22984.26

Work Order: 1803956 **Meter:** 10 **In Date:** 04/17/2018 **Closed:** 04/18/2018
Problem: pre delivery inspection

Work Completed

- pre delivery inspection
- install trailer plug
- Shop Supplies

Parts Issued

Quantity

Male Trailer Connector	1.00
Shop Supplies	1.00

Hours: 5.00 Comm: 0.00 Labor: 300.00 Parts: 9.52 Total: 309.52

Work Order: 1804786 **Meter:** 16 **In Date:** 05/08/2018 **Closed:** 05/11/2018
Problem: rear roller is loose

Work Completed

- ring power to Fleet to warranty rubber insulators from hub to rollers left side

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

Work Order: 1805097 **Meter:** 22 **In Date:** 05/16/2018 **Closed:** 05/18/2018
Problem: 9950

Work Completed

- Onsite Lube
- To Jp Park
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 2.00 Total: 122.00

Work Order: 1805116 **Meter:** 22 **In Date:** 05/17/2018 **Closed:** 05/18/2018
Problem: overheating

Work Completed

- diagnose overheating. radiator loose and fan shroud bent. repair and retest .
- move hitch eye ring down
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 2.50 Comm: 0.00 Labor: 150.00 Parts: 2.00 Total: 152.00

5/8/2025
3:50:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10206698 2018 LEBOY 400 Roller, Vibratory, 2.5 - 5 Ton

Work Order: 2000728

Meter: 97

In Date: 01/22/2020 **Closed:** 01/30/2020

Problem: fuel tank leaking

Work Completed

- replace leaking fuel tank and fittings. transfer fuel sending unit. refuel
- Shop Supplies

Parts Issued

Quantity

Filler Breather Cap Gasket	1.00
Full Sender Mount Gasket	1.00
Fuel Tank, 8 Gal, 400/420 Roller	1.00
Fittings	1.00
Thread Sealer	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 4.00

Comm: 0.00

Labor: 292.00

Parts: 829.01

Total: 1,121.01

5/8/2025
3:50:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10206698 2018 LEBOY 400 Roller, Vibratory, 2.5 - 5 Ton

Work Order: 2003349 **Meter:** 100 **In Date:** 04/02/2020 **Closed:** 04/22/2020
Problem: pm service

Work Completed

- pm service
- R&r trailer plug/ ck. all lights
- complete bake job: backing plates, drums, bearings, seals
- remove left axle pivot / remove (cut off) axle spindle / clean surface/ align placement and weld new spindle/ replace left axle pivot
- replace tire and rim
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	6.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Fuel Fil	1.00
Seal 2.250x3.371x.375	2.00
Used Fire X Refurbished	1.00
Male Trailer Connector	1.00
brake 12x2 lh	1.00
brake 12x2 rh	1.00
Hub & Drum Assembly	2.00
St235/80r16herc All Steel 14ply	1.00
Tr416 Valve Stem	1.00
Axle	1.00
Rim	1.00
Wheel 16x6	1.00
School Bus Yel Aeros	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00
Freight Charge	1.00

Hours: 19.50

Comm: 0.00

Labor: 1,423.50

Parts: 1,745.33

Total: 3,168.83

5/8/2025
3:50:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10206698 2018 LEBOY 400 Roller, Vibratory, 2.5 - 5 Ton

Work Order: 2012572 **Meter:** 156 **In Date:** 12/17/2020 **Closed:** 12/18/2020
Problem: needs a battery

Work Completed

Parts Issued

Quantity

- replace blown fuses replace broken terminal to pump
- replace dead battery - test charging system - remove seat n drain water tank to get to battery
- Shop Supplies

Battery	1.00
Shop Supplies	1.00

Hours: 3.00 Comm: 0.00 Labor: 219.00 Parts: 124.05 Total: 343.05

Work Order: 2103597 **Meter:** 156 **In Date:** 03/30/2021 **Closed:** 03/31/2021
Problem: Roller 10206698 needs a new fuel cap. The one it has currently came apart yesterday. Please let me know when it is ready

Work Completed

Parts Issued

Quantity

- secure fuel cap for dept
- Shop Supplies

Fuel Cap	1.00
Shop Supplies	1.00

Hours: 0.50 Comm: 0.00 Labor: 36.50 Parts: 55.18 Total: 91.68

Work Order: 2107188 **Meter:** 186 **In Date:** 06/30/2021 **Closed:** 07/21/2021
Problem: PM Service.

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Replaced Corroded Trailer Connector, Repair Damaged Wires At Front Headlight
- Cleaned Out Water Tank, Removed And Clean Filter Screen, Clear Lines, Cleared Sprayer Nozles, Test And Replaced Shorted Water Pump
- Shop Supplies

15-40 Oil	6.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Fuel Fil	1.00
Non-chlor Brake Clnr	1.00
Male Trailer Connector	1.00
Shurflo Pump	1.00
Water Pump	1.00
Fab Loom-split Poly	1.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 10.50 Comm: 0.00 Labor: 766.50 Parts: 532.82 Total: 1,299.32

5/8/2025
3:50:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10206698 2018 LEBOY 400 Roller, Vibratory, 2.5 - 5 Ton

Work Order: 2203459 **Meter:** 190 **In Date:** 03/30/2022 **Closed:** 03/31/2022
Problem: Safety brake cable is missing on the roller. Can't be used without it. Located at JPP yard - nursery

Work Completed

Parts Issued

Quantity

- break away switch 3/30- replace breakaway switch, repair threads on mounting bolt, verify operation.

Breakaway Switch 1.00

Shop Supplies 1.00

- Field Service Call

- Shop Supplies

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 12.19

Total: 158.19

Work Order: 2203581 **Meter:** 236 **In Date:** 03/31/2022 **Closed:** 04/04/2022
Problem: Right wheel is not working/ functioning. Located in the yard / nursery at JPP

Work Completed

Parts Issued

Quantity

- Diagnosed And Repaired Breakaway Wire To Battery

Non-chlor Brake Clnr 1.00

- Replaced Right Side Backing Plate Assembly

brake 12x2 rh 1.00

- Shop Supplies

School Bus Yel Aeros 1.00

Shop Supplies 1.00

Hours: 3.50

Comm: 0.00

Labor: 255.50

Parts: 73.63

Total: 329.13

Work Order: 2203846 **Meter:** 236 **In Date:** 03/31/2022 **Closed:** 04/08/2022
Problem: problem with brakes

Work Completed

- Tow From: Jpp nursery To: 2601 vistaparkway

Hours: 0.00

Comm: 113.00

Labor: 0.00

Parts: 0.00

Total: 113.00

Work Order: 2209081 **Meter:** 293 **In Date:** 08/30/2022 **Closed:** 09/02/2022
Problem: PM Service./ battery

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service Cancelled

Battery 1.00

- Ck Wont Start. Charge Battery And Jump Start In Parking Lot. R&i Seat/ Water Tank Cover To Test Electrical System, Replace Battery And One Electrical Connection

Shop Supplies 1.00

- Shop Supplies

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 100.57

Total: 246.57

5/8/2025
3:50:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10206698 2018 LEBOY 400 Roller, Vibratory, 2.5 - 5 Ton

Work Order: 2209256 **Meter:** 295 **In Date:** 09/02/2022 **Closed:** 10/31/2022

Problem: PM Service. Battery doesn't hold a charge, please replace. Thank you

Work Completed

- Preventive Maint. Service
- Check Battery And Charging System. Direct Short In System. Diagnose Short Internal In Alternator. Replace Alternator.
- Replace V-belt
- Replace Trailer Plug And Rear Center Work Light .
- Replace Left Side Brake Unit And Service Right Side.
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Air Filter	1.00
Fuel Fil	1.00
15-40 Oil	6.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
Battery	1.00
V-belt	1.00
Qt Hd40w	6.00
Male Trailer Connector	1.00
Seal 2.250x3.371x.375	2.00
Non-chlor Brake Clnr	1.00
brake 12x2 lh	1.00
Alternator	1.00
8 Diode Round Lamp	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 14.25

Comm: 0.00

Labor: 1,040.25

Parts: 735.65

Total: 1,775.90

Work Order: 2211334 **Meter:** 298 **In Date:** 11/03/2022 **Closed:** 11/30/2022

Problem: Fire extinguisher bracket needs to be replaced. May need to change location due to heavy vibration of unit.

Work Completed

- Accessories / Attachments, Install Heavy Duty Fire X Bracket
- Shop Supplies

Parts Issued

Quantity

Fire Extinguisher Bracket	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 56.61

Total: 129.61

5/8/2025
3:50:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10206698 2018 LEBOY 400 Roller, Vibratory, 2.5 - 5 Ton

Work Order: 2301890 **Meter:** 314 **In Date:** 02/27/2023 **Closed:**
Problem: Need battery replacement. Will be at Jupiter Beach Park all day today 2/27/2023. Contact Scott @ 561-436-0263

Work Completed

Parts Issued

Quantity

- Battery
Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 116.35 Total: 116.35

Work Order: 2312391 **Meter:** 361 **In Date:** 12/14/2023 **Closed:** 12/21/2023
Problem: Expedite Please And Thanks

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Replace Lunette Eye
- Replace All Brakes
- Repair Front Water Pipe
- Shop Supplies
Hours: 11.00 Comm: 0.00 Labor: 803.00 Parts: 448.35 Total: 1,251.35

5/8/2025
3:50:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10206698 2018 LEBOY 400 Roller, Vibratory, 2.5 - 5 Ton

Work Order: 2403069 **Meter:** 382 **In Date:** 03/27/2024 **Closed:** 05/02/2024
Problem: roller sweeper/ coolant leak/ murphy switch

Work Completed

Parts Issued

Quantity

- Replace Roller Sweeper Mat
- Check Cooling System For Leak. Pressure Test System Leaking From Radiator.remove Exh Pipe, Hydrulaic Lines, Fan Shroud And Blades To Access Radiator. Remove Radiator With Hydrulaic Cooler. Install New Radiator Assembly And Reverse Procedure. And Run.
- Check And Replace Murphy Switch
- Shop Supplies

Cocoa Mat	1.00
Murphy Switch	1.00
Radiator Cap	1.00
Radiator	1.00
1gal Rtu Antifreeze	2.00
Prem Aw 68 Hyd Fl 5g	1.00
Shop Supplies	1.00

Hours: 10.50

Comm: 0.00

Labor: 766.50

Parts: 1,866.25

Total: 2,632.75

Work Order: 2404354 **Meter:** 383 **In Date:** 05/02/2024 **Closed:** 05/03/2024
Problem: rear mat

Work Completed

Parts Issued

Quantity

- Replace Rear Coco Mat .
- Replace Brake Away Cable
- Shop Supplies

Cocoa Mat	1.00
Shop Supplies	1.00

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 102.70

Total: 248.70

5/8/2025
3:50:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10206698 2018 LEBOY 400 Roller, Vibratory, 2.5 - 5 Ton

Work Order: 2407013 **Meter:** 398 **In Date:** 07/22/2024 **Closed:** 08/29/2024

Problem: pm/ radiator is leaking

Work Completed

- Pm Service
- Hydraulic Cooler Leaking Fluid. Remove And Replace Cooler Assembly. Replace Cooling Fan Assembly.
- Replace Termostate, Drain And Fill
- Service All Brakes. Repair Ground Wire To Left Brake.
- Replace Trailer Plug And Riht Tail Light Bulb
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Fuel Fil	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Non-chlor Brake Clnr	1.00
Seal 2.250x3.371x.375	2.00
Napa Qt 15w40	6.00
Thermostat Gasket	1.00
Thermostat	1.00
Fan	1.00
1gal Rtu Antifreeze	2.00
Prem Aw 68 Hyd Fl 5g	3.00
Boxed Miniatures	1.00
Trailer Wiring Connector	1.00
Radiator	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 16.50

Comm: 0.00

Labor: 1,204.50

Parts: 2,023.33

Total: 3,227.83

Work Order: 2409376 **Meter:** 401 **In Date:** 09/26/2024 **Closed:** 09/30/2024

Problem: roller pads coming off

Work Completed

- Repair Rear Damaged Coco Mat
- Battery Dead. Charge Battery, Load Test, Pass Test.check Alternator, Broken Harness. Repair Wiring And Test Run.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 3.00

Comm: 0.00

Labor: 219.00

Parts: 2.65

Total: 221.65

5/8/2025
3:50:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10206698 2018 LEBOY 400 Roller, Vibratory, 2.5 - 5 Ton

Work Order: 2409703 **Meter:** 401 **In Date:** 10/04/2024 **Closed:** 10/30/2024

Problem: Roller pad was not installed properly after one use already coming off/ comments

Work Completed

Parts Issued

Quantity

- Relocate Coco Mate According To Instruction. Install Rubber Mat On Front Rear Back Roller	Non-chlor Brake Clnr	1.00
- Brakes Lockup And Burned Shoes. Replace Brake Unit And Hub Drum Assembly	brake 12x2 rh	1.00
- Shop Supplies	brake 12x2 lh	1.00
	Hub & Drum Assembly	2.00
	Rear Scraper Assy	1.00
	Shop Supplies	1.00
	Freight Charge	1.00
Hours: 6.50 Comm: 0.00	Labor: 474.50 Parts: 869.63	Total: 1,344.13

Work Order: 2410539 **Meter:** 405 **In Date:** 10/31/2024 **Closed:** 11/19/2024

Problem: Bearing bad in front roller (barrel splitting). Needs Rubber Piece on Front. Contact: Scott 561-436-0263

Work Completed

Parts Issued

Quantity

- Front Roller Splitting. Remove Front Drums, Damaged Axle, Drum And Broken Water Pipe. Not Cost Effective To Repair	Shop Supplies	1.00
- Shop Supplies		
Hours: 2.00 Comm: 0.00	Labor: 146.00 Parts: 2.65	Total: 148.65

Work Order: 2502900 **Meter:** 405 **In Date:** 03/26/2025 **Closed:** 04/04/2025

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 151.25 Total Labor: 10,818.75 Total Comm: 305.00 Total Parts: 11,860.51