

5/8/2025
4:04:50 PM

10210038 Palm Beach County Fleet Management Asset Maintenance History
2019 JOHN DEERE GATOR HPX815E Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Total Hours: 80.00 Labor: 5,828.00 Parts: 16,471.12 Comm: 237.60 Charged: 22536.72

Work Order: 1903353 **Meter:** 1 **In Date:** 03/27/2019 **Closed:** 03/28/2019
Problem: pre delivery inspection

Work Completed

- pre delivery inspection
- Shop Supplies

Parts Issued

	Quantity
Shop Supplies	1.00

Hours: 2.00 Comm: 0.00 Labor: 134.00 Parts: 3.00 Total: 137.00

Work Order: 1912489 **Meter:** 300 **In Date:** 12/05/2019 **Closed:** 12/11/2019
Problem: front tires

Work Completed

- replace front tires
- pm service
- Shop Supplies

Parts Issued

	Quantity
24x9.5x10 At Tire	2.00
Napagold Oil Filter	1.00
15-40 Oil	3.00
Napagold Fuel Filter	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 5.50 Comm: 0.00 Labor: 401.50 Parts: 326.23 Total: 727.73

Work Order: 2007218 **Meter:** 563 **In Date:** 07/23/2020 **Closed:** 07/30/2020
Problem: tires

Work Completed

- replace all 4 tires
- service equipment
- Shop Supplies

Parts Issued

	Quantity
24-1050-10b Nhs All Trail	2.00
24x9.5x10 At Tire	2.00
Napagold Oil Filter	1.00
Napa Qt 15w40	3.00
Napagold Air Filter	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 4.50 Comm: 0.00 Labor: 328.50 Parts: 618.11 Total: 946.61

5/8/2025
4:04:50 PM

10210038 Palm Beach County Fleet Management Asset Maintenance History
2019 JOHN DEERE GATOR HPX815E Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 2105885 **Meter:** 867 **In Date:** 05/27/2021 **Closed:** 07/30/2021

Problem: This asset rolled into a lake,... engine partially submerged and won't start. Please let us know what you find out.

Work Completed

- Diagnose Won't Start, Removed Air Intake And Injectors To Clear Water Out Of Engine, Took Fuel Sample, Performed Engine Compression Test, Removed Cylinder Head For Inspection, Replaced Complete Engine Assembly.
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	6.00
Napagold Oil Filter	2.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Diesel Water Remover	1.00
Diesel Engine	1.00
Cool Guard Coolant	1.00
Diesel Engine	1.00
Liquid Tape	1.00
15-40 Oil	3.00
Shop Supplies	1.00

Hours: 14.00

Comm: 0.00

Labor: 1,022.00 Parts: 9,790.50 Total: 10,812.50

Work Order: 2113008 **Meter:** 1067 **In Date:** 12/08/2021 **Closed:** 12/10/2021

Problem: two front tires for this gator. Thank you!

Work Completed

- Replace Front Tires.
- Shop Supplies

Parts Issued

Quantity

24x9.5x10 At Tire	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 1.50

Comm: 0.00

Labor: 109.50 Parts: 257.16 Total: 366.66

5/8/2025
4:04:50 PM

10210038

Palm Beach County Fleet Management Asset Maintenance History
2019 JOHN DEERE GATOR HPX815E Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 2204755 **Meter:** 1313 **In Date:** 05/02/2022 **Closed:** 05/26/2022

Problem: pm/ needs 2 new front tires see notes

Work Completed

- Preventive Maint. Service
- diagnose 4 way flasher not working - replace flasher relay - zip tie any loose wires
- replace 2 front tires
- readjust parking brake asm - take apart brake caliper cables readjust calipers
- Shop Supplies

Parts Issued

Quantity

Qt Hd40w	3.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
24x9.5x10 At Tire	2.00
Flasher Relay	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 7.00

Comm: 0.00

Labor: 511.00

Parts: 359.39

Total: 870.39

Work Order: 2208371 **Meter:** 1426 **In Date:** 08/11/2022 **Closed:** 10/05/2022

Problem: Transmission shifter broken

Work Completed

- Ck Shifter Broke. R&i Console To Replace Shifter Assembly.
- Shop Supplies

Parts Issued

Quantity

Lever	1.00
m126552	1.00
Nut	2.00
cap	1.00
Shop Supplies	1.00

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 61.01

Total: 207.01

Work Order: 2211221 **Meter:** 1426 **In Date:** 11/01/2022 **Closed:** 11/02/2022

Problem: Need 2 front tires.

Work Completed

- Tire Replacement
- Shop Supplies

Parts Issued

Quantity

24x9.5x10 At Tire	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 1.50

Comm: 0.00

Labor: 109.50

Parts: 256.75

Total: 366.25

5/8/2025
4:04:50 PM

10210038

Palm Beach County Fleet Management Asset Maintenance History
2019 JOHN DEERE GATOR HPX815E Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 2302520 **Meter:** 1426 **In Date:** 03/13/2023 **Closed:** 03/14/2023
Problem: Need a new battery please. Will bring in the old one when new one is ready.

Work Completed

- secure battery for dept
- Shop Supplies

Hours: 0.00

Comm: 0.00

Parts Issued

Battery	1.00
Shop Supplies	1.00

Labor: 0.00 Parts: 116.19 Total: 116.19

Work Order: 2304858 **Meter:** 1711 **In Date:** 05/15/2023 **Closed:** 06/05/2023
Problem: PM Service. tires/ pass seat

Work Completed

- Preventive Maint. Service
- replace all 4 tires
- replace drive belt
- readjust parking brake asm
- replace 2 front seats
- replace asset numbers
- Shop Supplies

Hours: 10.00

Comm: 0.00

Parts Issued

Napa Qt 15w40	3.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
24-1050-10b Nhs All Trail	2.00
24x9.5x10 At Tire	2.00
Drive Belt	1.00
Seat Assy	2.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Labor: 730.00 Parts: 1,100.82 Total: 1,830.82

Work Order: 2305736 **Meter:** 1757 **In Date:** 06/08/2023 **Closed:** 06/16/2023
Problem: Transmission/ wont go into gear

Work Completed

- Ck Wont Go Into Gear., Stalls Out. Replace Both Clutch Assemblies
- Shop Supplies

Hours: 4.50

Comm: 0.00

Parts Issued

Non-chlor Brake Clnr	2.00
Primary Clutch	1.00
Clutch	1.00
Shop Supplies	1.00

Labor: 328.50 Parts: 1,401.69 Total: 1,730.19

5/8/2025
4:04:50 PM

10210038

Palm Beach County Fleet Management Asset Maintenance History
2019 JOHN DEERE GATOR HPX815E Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 2500341 **Meter:** 2437 **In Date:** 01/13/2025 **Closed:** 01/17/2025
Problem: get ready to transfer, tires and drive shaft

Work Completed

Parts Issued

Quantity

- Replace Drive Shaft With Splined Coupling
- Replace Front Tires
- Shop Supplies

24x9.5x10 At Tire	2.00
Splined Coupling	2.00
Drive Shaft	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 5.50 Comm: 0.00 Labor: 401.50 Parts: 1,094.31 Total: 1,495.81

Work Order: 2500864 **Meter:** 2437 **In Date:** 01/21/2025 **Closed:** 01/30/2025
Problem: Tow- DELIVER REPLACEMENT CART TO CUSTOMER

Work Completed

- Tow From: 2601 Vista Pkwy, West Palm Beach 33411 To: 2956 Pinehurst Dr
Lake Worth Fl 33467

Hours: 0.00 Comm: 118.80 Labor: 0.00 Parts: 0.00 Total: 118.80

Work Order: 2501778 **Meter:** 2437 **In Date:** 02/25/2025 **Closed:** 03/04/2025
Problem: Transition Prep Charge

Work Completed

Parts Issued

Quantity

- Transition Prep Charge
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 2.65 Total: 148.65

Work Order: 2502033 **Meter:** 2437 **In Date:** 02/19/2025 **Closed:** 02/28/2025
Problem: Tow- return old asset back to Fleet Vista SE shop after transport new asset CA2000037539 to dept

Work Completed

- Tow From: 2956 Pinehurst, water plant 2 To: Fleet Vista Se shop

Hours: 0.00 Comm: 118.80 Labor: 0.00 Parts: 0.00 Total: 118.80

Total Hours: 80.00 Total Labor: 5,828.00 Total Comm: 237.60 Total Parts: 16,471.12