

5/8/2025
4:10:20 PM

L00719

Palm Beach County Fleet Management Asset Maintenance History
2012 TORO GRNDSMSTER 7200 Mower, Zero Turn Radius (Ztr) 72 In.

Total Hours: 137.00 Labor: 9,049.50 Parts: 9,605.05 Comm: 0.00 Charged: 18654.55

Work Order: 1207320 **Meter:** 1 **In Date:** 08/03/2012 **Closed:** 08/03/2012
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1303750 **Meter:** 256 **In Date:** 04/16/2013 **Closed:** 04/30/2013
Problem: replace (tire only)

Work Completed

- repalce tire
- Shop Supplies

Parts Issued	Quantity
15-6.00-6 Tibbed Tire	1.00
Shop Supplies	1.00
Freight Charge	1.00
Labor: 60.00 Parts: 70.17 Total: 130.17	

Hours: 1.00 Comm: 0.00

Work Order: 1308308 **Meter:** 380 **In Date:** 08/19/2013 **Closed:** 08/26/2013
Problem: pm/ see multiple notes

Work Completed

- pm service and lubed deck pivots works ok
- replace 2 frt tires lube and adjust wheel bearing
- Hyd service
- seat frame pinching wire harness for lights reposition harness and replace fuse
- Shop Supplies

Parts Issued	Quantity
Napagold Air Filter	1.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
15-40 Oil	4.00
Tire	2.00
Napa Hydraulic Filtr	1.00
Shop Supplies	1.00
Labor: 390.00 Parts: 111.19 Total: 501.19	

Hours: 6.50 Comm: 0.00

5/8/2025
4:10:20 PM

L00719

Palm Beach County Fleet Management Asset Maintenance History
2012 TORO GRNDSMSTER 7200 Mower, Zero Turn Radius (Ztr) 72 In.

Work Order: 1511582

Meter: 931

In Date: 11/12/2015 **Closed:** 11/24/2015

Problem: pm/ radiator fitting/ battery/ see notes

Work Completed

- Pm
- Hyd Service
- Replace air cleaner assemnbly w/filter
- coolant service and repair filler tube to radiator
- replace tire
- Recondtion caster wheel (rf)
- Ck charging. Replace Battery
- replace alt belt
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Qt 15w40	4.00
Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
Napa Hydraulic Filtr	1.00
Aw68 Hydro Fluid Hydr	6.00
Valve-actuator	1.00
Napa Antifreeze Gal	2.00
15-600-6 Nhs Str Rib 04	1.00
Napa Antifreeze Gal	1.00
Air Cleaner Assy	1.00
Gasket	1.00
Seal	2.00
Bearing	2.00
Spacer	2.00
Front Caster Spacer	1.00
Screw	1.00
Stop Nut	1.00
Battery	1.00
Belt	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 12.00

Comm: 0.00

Labor: 720.00

Parts: 676.03

Total: 1,396.03

5/8/2025
4:10:20 PM

L00719

Palm Beach County Fleet Management Asset Maintenance History
2012 TORO GRNDSMSTER 7200 Mower, Zero Turn Radius (Ztr) 72 In.

Work Order: 1702256 **Meter:** 1099 **In Date:** 03/06/2017 **Closed:** 03/15/2017
Problem: pm service

Work Completed

- Pm
- Hyd Service
- Ck All Light inop check electrical sys. Replace lighting relay and right top light bulb
- Shop Supplies

Parts Issued

Quantity

Relay	1.00
Bulb	1.00
15-40 Oil	4.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
Non-chlor Brake Clnr	1.00
Napa Hydraulic Filtr	1.00
Aw68 Hydro Fluid Hydr	4.00
Shop Supplies	1.00

Hours: 7.00

Comm: 0.00

Labor: 420.00 Parts: 78.32 Total: 498.32

Work Order: 1704682 **Meter:** 1106 **In Date:** 05/10/2017 **Closed:** 05/22/2017
Problem: mower went into lake

Work Completed

- mower submerged, drain oil, change filter, remove glow plugs to remove water from engine, clean electrical connections
- drain and flush water from hydraulic system
- replaced seized starter, fuses, key switch and stop solenoid
- check charging system, replace battery
- drain, flush and clean fuel tanks and fuel system
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	4.00
Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
Napa Hydraulic Filtr	1.00
Aw68 Hydro Fluid Hydr	8.00
Non-chlor Brake Clnr	1.00
Battery	1.00
Pm-22-a Additive Dies	1.00
Stop Solenoid	1.00
Key Switch Assy	1.00
Powersport Starter	1.00
Shop Supplies	1.00

Hours: 12.50

Comm: 0.00

Labor: 750.00 Parts: 693.67 Total: 1,443.67

5/8/2025
4:10:20 PM

L00719

Palm Beach County Fleet Management Asset Maintenance History
2012 TORO GRNDSMSTER 7200 Mower, Zero Turn Radius (Ztr) 72 In.

Work Order: 1709218 **Meter:** 1191 **In Date:** 09/22/2017 **Closed:** 09/29/2017
Problem: broken baffle/ rear tire going flat

Work Completed

Parts Issued

Quantity

- r/r Center and right hand baffle chambers
- R/r bent blades
- R/r rear tires
- Shop Supplies

24x12x12 6 Ply Kenda	2.00
Center Chamber Assy	1.00
Rh Recycler Chamber Assy	1.00
Rotary Blades	3.00
Shop Supplies	1.00

Hours: 4.50 Comm: 0.00 Labor: 270.00 Parts: 1,172.72 Total: 1,442.72

Work Order: 1711041 **Meter:** 1217 **In Date:** 11/07/2017 **Closed:** 11/14/2017
Problem: replace bent rim and tire (tire only)

Work Completed

Parts Issued

Quantity

- R&tire rim asm
- Shop Supplies

15-6.00x6 Ribbed Tire	1.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 324.28 Total: 384.28

Work Order: 1800480 **Meter:** 1270 **In Date:** 01/12/2018 **Closed:** 01/30/2018
Problem: adjust deck and inspect for damage/ hit a palm

Work Completed

Parts Issued

Quantity

- Straightened bend deck lift arm and adjust deck height and pitch
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 2.00 Total: 122.00

5/8/2025
4:10:20 PM

L00719

Palm Beach County Fleet Management Asset Maintenance History
2012 TORO GRNDSMSTER 7200 Mower, Zero Turn Radius (Ztr) 72 In.

Work Order: 1802469 **Meter:** 1282 **In Date:** 03/06/2018 **Closed:** 03/29/2018
Problem: pm service

Work Completed

- pm service
- hydraulic service
- replace front and rear headlights/ replace 4 turn signal bulbs
- replace front tire and bent rim
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	4.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
Non-chlor Brake Clnr	1.00
Napa Hydraulic Filtr	1.00
Aw68 Hydro Fluid Hydr	4.00
Bulb	2.00
Bulb	2.00
Worklight	6.00
15-6.00x6 Ribbed Tire	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 8.00 Comm: 0.00 Labor: 480.00 Parts: 1,628.11 Total: 2,108.11

Work Order: 1803443 **Meter:** 1283 **In Date:** 04/02/2018 **Closed:**
Problem: deck lowers too slowly/ hydro fluid low

Work Completed

-

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

Work Order: 1804357 **Meter:** 1291 **In Date:** 04/26/2018 **Closed:** 04/30/2018
Problem: repair or replace tire (tire only)

Work Completed

- replace tire
- Shop Supplies

Parts Issued

Quantity

Tire	1.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 37.06 Total: 97.06

5/8/2025
4:10:20 PM

L00719

Palm Beach County Fleet Management Asset Maintenance History
2012 TORO GRNDSMSTER 7200 Mower, Zero Turn Radius (Ztr) 72 In.

Parts Issued	Quantity
Belt	1.00
Belt	1.00
Idler Pulley	1.00
Pulley	1.00
Grommet	5.00
Screw	1.00
Retainer Pin	1.00
Valve-actuator	1.00
Gasket	1.00
Air Cleaner Cover Assy	1.00
Bolt	3.00
Gearbox Bracket Rh	1.00
Gearbox Bracket Lh	1.00
Rubber Mount	3.00
Snao Ring	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00
Freight Charge	1.00
Freight Charge	1.00
Freight Charge	1.00

Hours: 15.00

Comm: 0.00

Labor: 1,095.00

Parts: 946.14

Total: 2,041.14

Work Order: 2208581

Meter: 2141

In Date: 08/17/2022 **Closed:** 08/19/2022

Problem: Worn front tire. Request to repair / replace

Work Completed

- Replace Wheel Bearings,seals And Tire
- Shop Supplies

Parts Issued	Quantity
Seal	2.00
Bearing	2.00
15-600-6 Nhs Str Rib 04	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 82.87

Total: 155.87

5/8/2025
4:10:20 PM

L00719

Palm Beach County Fleet Management Asset Maintenance History
2012 TORO GRNDSMSTER 7200 Mower, Zero Turn Radius (Ztr) 72 In.

Work Order: 2210601 **Meter:** 2171 **In Date:** 10/17/2022 **Closed:** 12/07/2022

Problem: Mower wont start and driver rear wheel had hydraulic fluid on ground not sure from where.

Work Completed

Parts Issued

Quantity

- Ck Won't Start. Ck Electrical System, Replace Battery.

Battery 1.00

- Replace Left Front Tire

15-600-6 Nhs Str Rib 04 3.00

- Clean Debris From Underside Of Mower, Replace Hydraulic Filter That Was Leaking, Flush System And Replace Hydraulic Fluid

Aw68 Hydro Fluid Hydr 10.00

- Shop Supplies

Napa Hydraulic Filtr 1.00

Non-chlor Brake Clnr 3.00

Shop Supplies 1.00

Tire Disposal Fee 1.00

Hours: 3.50

Comm: 0.00

Labor: 255.50

Parts: 283.80

Total: 539.30

Work Order: 2303439 **Meter:** 2186 **In Date:** 04/05/2023 **Closed:** 04/20/2023

Problem: Runs good but shuts off sometimes while driving or after a while of using it just wont start.

Work Completed

Parts Issued

Quantity

- Replace Right Rear Tire

15-600-6 Nhs Str Rib 04 1.00

- Diag, Replace Right Traction Arm Switch

Turf Tread 24x12x12 1.00

- Shop Supplies

Switch 1.00

Shop Supplies 1.00

Tire Disposal Fee 0.00

Freight Charge 1.00

Hours: 3.00

Comm: 0.00

Labor: 219.00

Parts: 362.76

Total: 581.76

5/8/2025
4:10:20 PM

L00719

Palm Beach County Fleet Management Asset Maintenance History
2012 TORO GRNDSMSTER 7200 Mower, Zero Turn Radius (Ztr) 72 In.

Work Order: 2305613

Meter: 2206

In Date: 06/07/2023 **Closed:** 06/15/2023

Problem: PM Service

Work Completed

- Preventive Maint. Service
- replace missing air filter asm
- repair front tire
- replace spindle seals and grease
- Shop Supplies

Parts Issued

Quantity

Pm-22-a Additive Dies	1.00
Napagold Fuel Filter	1.00
Delvac 15w40 1 Ga	1.00
Napagold Oil Filter	1.00
Tire Rep Brown String	1.00
Grease Cap	2.00
Air Cleaner Cover Assy	1.00
Napagold Air Filter	1.00
Shop Supplies	1.00
Freight Charge	1.00
Freight Charge	1.00

Hours: 7.00

Comm: 0.00

Labor: 511.00

Parts: 264.55

Total: 775.55

5/8/2025
4:10:20 PM

L00719

Palm Beach County Fleet Management Asset Maintenance History
2012 TORO GRNDSMSTER 7200 Mower, Zero Turn Radius (Ztr) 72 In.

Work Order: 2311916

Meter: 2340

In Date: 11/30/2023 **Closed:** 12/15/2023

Problem: Belt keeps popping off of deck. Early PM.

Work Completed

- Preventive Maint. Service
- replace air filter housing
- fix belt problem - replace mounts and bushings - test run
- Shop Supplies

Parts Issued

Quantity

Napa Gal 15w40	1.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Mercon V Atf	1.00
Non-chlor Brake Clnr	1.00
Pm-22-a Additive Dies	1.00
Air Cleaner Cover Assy	1.00
Grease Cap	2.00
Rubber Mount	6.00
Gearbox Bracket Rh	1.00
Gearbox Bracket Lh	1.00
Grommet	5.00
Shop Supplies	1.00
Freight Charge	1.00
Freight Charge	1.00

Hours: 6.50

Comm: 0.00

Labor: 474.50

Parts: 537.60

Total: 1,012.10

5/8/2025
4:10:20 PM

L00719

Palm Beach County Fleet Management Asset Maintenance History
2012 TORO GRNDSMSTER 7200 Mower, Zero Turn Radius (Ztr) 72 In.

Work Order: 2405437

Meter: 2340

In Date: 06/04/2024 **Closed:** 06/24/2024

Problem: Coolant reservoir broke off fan shroud, front tires need to be replaced, seat weight adjuster broken.

Work Completed

- Remove Radiator To Replace Damaged Fan Shroud & Coolant Resivoir
- Replace Front Tires And Lube Mower
- R&i Seat And Disassemble To Replace Adjuster Hardware Components

Parts Issued

Quantity

15-600-6 Nhs Str Rib 04	2.00	
Hose	1.00	
Hose	1.00	
Fan Shroud	1.00	
Weight Adjuster Kit	1.00	
Spring And Saddle Kit	1.00	
Shock Absorber Kit	1.00	
1gal Rtu Antifreeze	1.00	
Overflow Bottle	1.00	
Tire Disposal Fee	2.00	
Freight Charge	1.00	
Freight Charge	1.00	
Labor: 547.50	Parts: 1,016.99	Total: 1,564.49

Hours: 7.50

Comm: 0.00

Total Hours: 137.00

Total Labor: 9,049.50

Total Comm: 0.00

Total Parts: 9,605.05