

5/8/2025
4:12:31 PM

**L00729 Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNMASTER 7210 Mower, 72in, Ztr, W/Mulcher**

Total Hours: 195.30 Labor: 12,484.40 Parts: 19,320.24 Comm: 0.00 Charged: 31804.64

Work Order: 939309 **Meter:** 0 **In Date:** 06/22/2009 **Closed:** 06/22/2009
Problem: PRE-DELIVERY INSPECTION

Work Completed

- Pre-delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 941379 **Meter:** 24 **In Date:** 07/29/2009 **Closed:** 07/30/2009
Problem: CHECK OVER SEE REQUEST

Work Completed

- remove glow plugs to clear cylinders
- check fuel for contamination
- check for damage /was in canal
- wash engine compartment
- Shop Supplies

Parts Issued	Quantity
Shop Supplies	1.00

Hours: 4.50 Comm: 0.00 Labor: 270.00 Parts: 2.00 Total: 272.00

Work Order: 1008819 **Meter:** 318 **In Date:** 08/16/2010 **Closed:** 08/26/2010
Problem: PM / BLADE BOLT BROKEN

Work Completed

- Pm Service
- Replace Spindle shaft and replace black bolt grease remount blade
- Wash
- Shop Supplies

Parts Issued	Quantity
Shop Supplies	1.00
6438 Air Filterfrm Ca9550 Wix 46438	1.00
P8043 Fuel Filter Lbf Lff8062 Wix 33472	1.00
Oil Filter	1.00
15/40 Oil	4.00
Shaft	1.00
Bolt	3.00

Hours: 6.50 Comm: 0.00 Labor: 390.00 Parts: 99.58 Total: 489.58

5/8/2025
4:12:31 PM

L00729

Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNMASTER 7210 Mower, 72in, Ztr, W/Mulcher

Work Order: 1105829 **Meter:** 501 **In Date:** 06/02/2011 **Closed:** 06/08/2011

Problem: left blade bolt wont tighten

Work Completed

- Pm Mower
- Replace 2 Frt Caster Tires (bald)
- Hyd Sys Service
- Cooling Sys Service
- Replace Spindle Shaft (left outer) and blade bolt lubne assy
- Wash Eqpt
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
Hyd Filter	1.00
6438 Air Filterfrm Ca9550 Wix 46438	1.00
P8043 Fuel Filter Lbf Lff8062 Wix 33472	1.00
Oil Filter	1.00
15/40 Oil	4.00
15x6.00-6 Ribbed Tire	2.00
Tire Disposal Fee	2.00
Thermostat Gasket	1.00
Thermostat Gasket	1.00
Spindle Shaft	1.00
Blade Bolt	1.00

Hours: 10.00

Comm: 0.00

Labor: 600.00

Parts: 285.78

Total: 885.78

Work Order: 1205580 **Meter:** 785 **In Date:** 06/13/2012 **Closed:** 06/27/2012

Problem: pm service/ pto not working

Work Completed

- Pm Motor
- Diagnose and repair mower Pto system confirm malfunction, replace computer
- Hyd sys service
- Replace Rt Frt Caster tire
- R&r tires, mount and dismount to flip tires to extend tire life
- Replac Pto Switch
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
Hyd Filter	1.00
6438 Air Filterfrm Ca9550 Wix 46438	1.00
P8043 Fuel Filter Lbf Lff8062 Wix 33472	1.00
Ph7317 Oil Filter Wix 51356	1.00
15/40 Oil	4.00
Control Module	1.00
Pto Switch	1.00
15x6.00-6 Ribbed Tire	1.00
Tire Disposal Fee	1.00

Hours: 12.00

Comm: 0.00

Labor: 720.00

Parts: 472.67

Total: 1,192.67

5/8/2025
4:12:31 PM

L00729 Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNMASTER 7210 Mower, 72in, Ztr, W/Mulcher

Work Order: 1410650 **Meter:** 1133 **In Date:** 10/24/2014 **Closed:** 10/31/2014
Problem: pm service

Work Completed

Parts Issued

Quantity

- Pm	15-40 Oil	4.00
- Wash eqpt	Napagold Air Filter	1.00
- Cooling sys service	Napagold Fuel Filter	1.00
- Repair left side light amber light not working, repair open circuit at power supply.	Napagold Oil Filter	1.00
- service gear box	1gal Rtu Antifreeze	1.00
- Shop Supplies	85-140 Gear Oil Gear	1.00
	Thermostat Assy	1.00
	Thermostat Gasket	1.00
	Serv Indicator	1.00
	Shop Supplies	1.00

Hours: 9.00

Comm: 0.00

Labor: 540.00

Parts: 156.07

Total: 696.07

Work Order: 1503485 **Meter:** 1181 **In Date:** 04/03/2015 **Closed:** 04/15/2015
Problem: change oil, filter and grease all fittings

Work Completed

Parts Issued

Quantity

- Change oil, flter grease all fittings	15-40 Oil	4.00
- Shop Supplies	Napagold Oil Filter	1.00
	1cart Palladium 2 Grs	1.00
	Shop Supplies	1.00

Hours: 1.50

Comm: 0.00

Labor: 90.00

Parts: 23.23

Total: 113.23

5/8/2025
4:12:31 PM

Palm Beach County Fleet Management Asset Maintenance History
L00729 2009 TORO GRNMASTER 7210 Mower, 72in, Ztr, W/Mulcher

Work Order: 1506651 **Meter:** 1235 **In Date:** 07/02/2015 **Closed:** 07/27/2015

Problem: pm/ radiator leak/ check parking brake

Work Completed

- pm service
- hydraulic service
- R&r radiator, upper and lower hoses and radiator cap. flush system, renew coolant
- R&r front castor wheel assy, repack bearings
- R&r idler pulleys on deck
- R&r waterpump belt and deck belts
- replace parking brake calipers and adjust
- Shop Supplies

Parts Issued

Quantity

Radiator	1.00
Upper Radiator Hose	1.00
Lower Radiator Hose	1.00
15-40 Oil	4.00
Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
Napagold Oil Filter	1.00
Brake Cleaner	1.00
Napa Hydraulic Filtr	1.00
Aw68 Hydro Fluid Hydr	4.00
Napakool	1.00
Napa Antifreeze Gal	2.00
Tire & Wheel Assy	2.00
Front Caster Spacer	2.00
Screw	2.00
Spacer	4.00
Bearing	4.00
Seal	4.00
Idler Pulley	1.00
Idler Pulley	1.00
Grommet	4.00
Belt	1.00
Belt	1.00
V-belt	1.00
Left Brake Caliper	1.00
Right Brake Caliper	1.00
Shop Supplies	1.00

Hours: 15.00

Comm: 0.00

Labor: 900.00

Parts: 2,846.96

Total: 3,746.96

5/8/2025
4:12:31 PM

L00729

Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNMASTER 7210 Mower, 72in, Ztr, W/Mulcher

Work Order: 1511584 **Meter:** 1303 **In Date:** 11/12/2015 **Closed:** 11/24/2015
Problem: check spindle bearings

Work Completed

- Replace spindle
- Shop Supplies

Parts Issued

Quantity

Spindle Shaft Assy	1.00
Spacer,spindle Shaft	1.00
O-ring	1.00
Spindle Housing	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 1.50

Comm: 0.00

Labor: 90.00 Parts: 405.00 Total: 495.00

Work Order: 1607421 **Meter:** 1379 **In Date:** 07/20/2016 **Closed:** 07/27/2016
Problem: pm service

Work Completed

- pm service
- wash equipment debris in radiator
- hydraulic service
- replace light bulb (r) side
- Shop Supplies

Parts Issued

Quantity

Napa Qt 15w40	6.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
Napa Hydraulic Filtr	1.00
Aw68 Hydro Fluid Hydr	3.00
Drain Plug	1.00
Shop Supplies	1.00

Hours: 6.50

Comm: 0.00

Labor: 390.00 Parts: 76.45 Total: 466.45

Work Order: 1609407 **Meter:** 1384 **In Date:** 09/09/2016 **Closed:** 09/28/2016
Problem: replace tire (tire only)

Work Completed

- Replace tire
- Shop Supplies

Parts Issued

Quantity

Tire	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 60.00 Parts: 36.46 Total: 96.46

5/8/2025
4:12:31 PM

L00729 Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNMASTER 7210 Mower, 72in, Ztr, W/Mulcher

Work Order: 1700879 **Meter:** 1469 **In Date:** 01/27/2017 **Closed:** 02/16/2017
Problem: broken drive shaft

Work Completed

- Diag replace Pto gear box asy and pulley
- replace drive shaft
- Replac both deck belts
- Shop Supplies

Parts Issued

Quantity

Rubber Mount	3.00
Gearbox	1.00
Gearbox Bracket Rh	1.00
Gearbox Bracket Lh	1.00
set screw	2.00
Bushing	1.00
Pulley	1.00
Driveshaft	1.00
Belt	1.00
Belt	1.00
Keyway	1.00
Shop Supplies	1.00

Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 2,074.81 Total: 2,314.81

Work Order: 1704683 **Meter:** 1470 **In Date:** 05/10/2017 **Closed:** 05/22/2017
Problem: spindle bolt

Work Completed

- replace center spindle assy and all blade bolts
- Shop Supplies

Parts Issued

Quantity

16.5 Oz Aero Kroil	1.00
Double Driven Spindle Assy	1.00
Blade Bolt	3.00
Shop Supplies	1.00

Hours: 2.50 Comm: 0.00 Labor: 150.00 Parts: 758.93 Total: 908.93

5/8/2025
4:12:31 PM

L00729

Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNDMASTER 7210 Mower, 72in, Ztr, W/Mulcher

Work Order: 1707107

Meter: 1517

In Date: 07/20/2017 **Closed:** 08/09/2017

Problem: pm service

Work Completed

- Pm
- Wash Eqpt
- Hyd service
- Replace 2 rear tires
- Diag time replace flasher controller. clean light sockets
- Adj steering to hold in neutral
- Shop Supplies

Parts Issued

Quantity

24x12x12 6 Ply Kenda	2.00
24-1200-12b Turf M Carl	2.00
15-40 Oil	6.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
Napa Hydraulic Filtr	1.00
Aw68 Hydro Fluid Hydr	3.00
1cart Palladium 2 Grs	1.00
Bulb	1.00
Bulb	1.00
Flasher	1.00
Shop Supplies	1.00
Tire Disposal Fee	0.00

Hours: 12.00

Comm: 0.00

Labor: 720.00

Parts: 1,256.09

Total: 1,976.09

Work Order: 1710898

Meter: 1588

In Date: 11/02/2017 **Closed:** 11/14/2017

Problem: pto works but blades dont spin

Work Completed

- R&r Pto gear box to reinstall pulley and test run
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.50

Comm: 0.00

Labor: 90.00

Parts: 2.00

Total: 92.00

5/8/2025
4:12:31 PM

**L00729 Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNMASTER 7210 Mower, 72in, Ztr, W/Mulcher**

Work Order: 1807572 **Meter:** 1736 **In Date:** 07/25/2018 **Closed:** 07/31/2018
Problem: pm service

Work Completed

- pm service
- hydraulic service
- wash mower
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	6.00
Napagold Fuel Filter	1.00
Napagold Air Filter	1.00
Napagold Oil Filter	1.00
Aw68 Hydro Fluid Hydr	4.00
Napagold Oil Filter	1.00
Shop Supplies	1.00

Hours: 6.00 Comm: 0.00 Labor: 360.00 Parts: 56.62 Total: 416.62

Work Order: 1808409 **Meter:** 1738 **In Date:** 08/15/2018 **Closed:** 08/20/2018
Problem: wont stay running when you release the brake

Work Completed

- diagnose no start, inspect all switches. adjust seat switch
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1808859 **Meter:** 1738 **In Date:** 08/28/2018 **Closed:** 09/17/2018
Problem: seat/ latch/ tires/ remove grease fittings/ see notes

Work Completed

- replace grease cap, cap zerk fitting, install customer supplied latch
- r/r seat to replace switch and controll module
- replace damaged front tires
- Shop Supplies

Parts Issued

Quantity

Grease Cap	2.00
Bail Switch	1.00
15-600-6 Nhs Str Rib 04	2.00
Control Module Assy	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 539.64 Total: 779.64

5/8/2025
4:12:31 PM

L00729 Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNDMASTER 7210 Mower, 72in, Ztr, W/Mulcher

Work Order: 1911158 **Meter:** 1820 **In Date:** 10/28/2019 **Closed:** 11/06/2019
Problem: shuts off when steering sticks engaged

Work Completed

Parts Issued

Quantity

- Check for shut off - traced to seat switch unplugged; reconnect switch & test run
- Shop Supplies

Shop Supplies 1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 4.00 Total: 77.00

Work Order: 1913178 **Meter:** 1841 **In Date:** 12/30/2019 **Closed:** 01/02/2020
Problem: shuts off when handles are pulled in

Work Completed

Parts Issued

Quantity

- check all switches and wiring. adjust
- Shop Supplies

Shop Supplies 1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 4.00 Total: 77.00

Work Order: 2000389 **Meter:** 1841 **In Date:** 01/13/2020 **Closed:** 01/27/2020
Problem: shuts off when steering sticks pulled in

Work Completed

Parts Issued

Quantity

- replace module and parking brake switch
- repair deck for blade clearance
- Shop Supplies

Switch 1.00

Control Module Assy 1.00

Shop Supplies 1.00

Hours: 2.50 Comm: 0.00 Labor: 182.50 Parts: 571.74 Total: 754.24

5/8/2025
4:12:31 PM

**L00729 Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNMASTER 7210 Mower, 72in, Ztr, W/Mulcher**

Work Order: 2003763 **Meter:** 1868 **In Date:** 04/15/2020 **Closed:** 04/28/2020

Problem: tensioner worn, belt comes off, repl frt tires, repair roll bar, pm service

Work Completed

- pm service
- R&r front tires
- repair and replace missing bolts on Rops
- R&r two belt tentionersstock Parts entry
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	6.00
Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
Non-chlor Brake Clnr	1.00
15-6.00x6 Ribbed Tire	2.00
Castor Bushing	4.00
Torsion Spring	2.00
Shop Supplies	1.00

Hours: 9.30

Comm: 0.00

Labor: 678.90

Parts: 863.35

Total: 1,542.25

Work Order: 2005368 **Meter:** 1876 **In Date:** 05/28/2020 **Closed:** 06/11/2020

Problem: PTO not working

Work Completed

- check switch, controller, safety system. repair wire connection at pto clutch solenoid on transaxle
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.50

Comm: 0.00

Labor: 109.50

Parts: 4.00

Total: 113.50

Work Order: 2101457 **Meter:** 1920 **In Date:** 02/08/2021 **Closed:**

Problem: pm/ dead battery/ bent baffles

Work Completed

- Preventive Maint. Service

Hours: 0.00

Comm: 0.00

Labor: 0.00

Parts: 0.00

Total: 0.00

5/8/2025
4:12:31 PM

L00729 Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNMASTER 7210 Mower, 72in, Ztr, W/Mulcher

Work Order: 2105851 **Meter:** 2004 **In Date:** 05/26/2021 **Closed:** 06/08/2021
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- wash
- replace 2 bulbs
- Shop Supplies

Parts Issued

Quantity

Napa Qt 15w40	6.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Napagold Air Filter	1.00
Non-chlor Brake Clnr	2.00
Boxed Miniatures	1.00
Boxed Miniatures	1.00
Shop Supplies	1.00

Hours: 5.50

Comm: 0.00

Labor: 401.50 Parts: 63.18 Total: 464.68

Work Order: 2108323 **Meter:** 2059 **In Date:** 08/02/2021 **Closed:** 08/05/2021
Problem: needs 2 new spare front caster wheels w/ tires

Work Completed

- Parts only
- Shop Supplies

Parts Issued

Quantity

15-6.00x6 Ribbed Tire	2.00
Shop Supplies	1.00

Hours: 0.50

Comm: 0.00

Labor: 36.50 Parts: 548.21 Total: 584.71

Work Order: 2108332 **Meter:** 2051 **In Date:** 08/02/2021 **Closed:** 08/06/2021
Problem: Needs front tire replaced seems like bearings are bad

Work Completed

- Replace Tire and Wheel with Bearings
- Shop Supplies

Parts Issued

Quantity

Tire & Wheel Assy	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00 Parts: 209.55 Total: 282.55

Work Order: 2112573 **Meter:** 2173 **In Date:** 11/29/2021 **Closed:** 12/02/2021
Problem: Tire is bad has about 4 to 5 pin holes in it.

Work Completed

- Replace Tire
- Shop Supplies

Parts Issued

Quantity

15x6.00-6	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00 Parts: 29.86 Total: 102.86

5/8/2025
4:12:31 PM

L00729 Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNMASTER 7210 Mower, 72in, Ztr, W/Mulcher

Work Order: 2200829 **Meter:** 2217 **In Date:** 01/25/2022 **Closed:** 03/30/2022

Problem: Rear tires go flat. Broken Pulley.

Work Completed

- Replaced 2 Tires
- Replaced Both Belts, Replaced Gearbox Pully, Double Pulley, And Left Spindle
- Shop Supplies

Parts Issued

Quantity

Rubber Mount	1.00
V-belt	1.00
V-belt	1.00
Double Driven Spindle	1.00
Pulley	1.00
Pulley	1.00
Double Driven Spindle	1.00
24x12-12 6ply Mower Tire	2.00
High Driven Spindle Assy (ls)	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 7.50

Comm: 0.00

Labor: 547.50

Parts: 2,733.70

Total: 3,281.20

5/8/2025
4:12:31 PM

Palm Beach County Fleet Management Asset Maintenance History
L00729 2009 TORO GRNDMASTER 7210 Mower, 72in, Ztr, W/Mulcher

Work Order: 2206313 **Meter:** 2263 **In Date:** 06/14/2022 **Closed:** 07/25/2022

Problem: PM Service. Front tires shake. Spindles had stuff wrapped in them. See comment 2 as well.

Work Completed

- Preventive Maint. Service
- Remove Seized/ Stripped Bolt, Replace 3 Blades & Bolts, Clean Spindles Of Debris
- Replace Front Caster Wheel W/ Tire Assemblies
- Clean Debris From Brakes
- Wash Mower
- Repair Rear Tire
- Shop Supplies

Parts Issued

Quantity

Napa Qt 15w40	2.00
Prem Blue 15w40 1 Gal	1.00
Napagold Fuel Filter	1.00
Napagold Air Filter	1.00
1cart Palladium 2 Grs	1.00
Non-chlor Brake Clnr	2.00
High Gloss Coating	1.00
Blade 20.5 Med Flo	3.00
Napagold Oil Filter	1.00
Blade Bolt	3.00
15-6.00x6 Ribbed Tire	2.00
Shop Supplies	1.00
Freight Charge	1.00
Freight Charge	1.00

Hours: 11.50

Comm: 0.00

Labor: 839.50

Parts: 994.58

Total: 1,834.08

Work Order: 2303440 **Meter:** 2339 **In Date:** 04/05/2023 **Closed:** 04/18/2023

Problem: Possible bad battery, keeps dying but once its started it will stay running. Driver rear tire goes flat.

Work Completed

- Charge, Check Battery, Replace Positive Battery Lug And Battery
- Replace Left Rear Tire And Replace Leaking Valve Stem On Right Rear Tire
- Shop Supplies

Parts Issued

Quantity

Batt Cable Terminal	1.00
Battery	1.00
Turf Tread 24x12x12	1.00
Shop Supplies	1.00

Hours: 2.50

Comm: 0.00

Labor: 182.50

Parts: 320.80

Total: 503.30

5/8/2025
4:12:31 PM

Palm Beach County Fleet Management Asset Maintenance History
L00729 2009 TORO GRNMASTER 7210 Mower, 72in, Ztr, W/Mulcher

Work Order: 2305047 **Meter:** 2354 **In Date:** 05/22/2023 **Closed:** 05/25/2023
Problem: Tire needs replacement front.

Work Completed

- Replace Tire
- Shop Supplies

Hours: 1.00 Comm: 0.00

Parts Issued

	Quantity
15-600-6 Nhs Str Rib 04	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00
Labor: 73.00	Parts: 37.25
Total: 110.25	

Work Order: 2306873 **Meter:** 2392 **In Date:** 07/12/2023 **Closed:** 07/12/2023
Problem: tire only

Work Completed

- Replaced Valve Stem And Checked Bearings
- Shop Supplies

Hours: 1.00 Comm: 0.00

Parts Issued

	Quantity
Shop Supplies	1.00
Labor: 73.00	Parts: 2.65
Total: 75.65	

Work Order: 2307114 **Meter:** 2393 **In Date:** 07/19/2023 **Closed:** 08/09/2023
Problem: PM Service Dropping off soon.

Work Completed

- Preventive Maint. Service
- Hydraulic Service
- Service Parking Brake
- Wash Debris From Mower
- Shop Supplies

Hours: 6.50 Comm: 0.00

Parts Issued

	Quantity
Delvac 15w40 1 Ga	1.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Napagold Air Filter	1.00
Non-chlor Brake Clnr	3.00
Napagold Oil Filter	1.00
Napa Hydraulic Filtr	1.00
Shop Supplies	1.00
Labor: 474.50	Parts: 79.63
Total: 554.13	

Total Hours: 195.30

Total Labor: 12,484.40

Total Comm: 0.00

Total Parts: 19,320.24