

10/16/2025
3:04:28 PM

10208524 Palm Beach County Fleet Management Asset Maintenance History
2019 INTERNATIONAL 4300 Garbage Packer, 16 Yd, 33,000 Gvwr, Rear Loader

Total Hours: 313.00 Labor: 22,702.00 Parts: 55,424.42 Comm: 11,468.83 Charged: 89595.25

Work Order: 1900324 **Meter:** 926 **In Date:** 01/08/2019 **Closed:** 01/10/2019
Problem: pre delivery inspection

Work Completed

- pre delivery inspection
- def service
- Shop Supplies

Hours: 5.50

Comm: 0.00

Parts Issued

	Quantity
Blue Df	1.00
Shop Supplies	1.00

Labor: 368.50

Parts: 18.51

Total: 387.01

Work Order: 1906590 **Meter:** 8803 **In Date:** 06/24/2019 **Closed:** 07/03/2019
Problem: hyd leak

Work Completed

- Repair hyd. leak @ filter housing
- Hyd. oil
- Wash packer
- Shop Supplies

Hours: 5.00

Comm: 0.00

Parts Issued

	Quantity
Aw68 Hydro Fluid Hydr	30.00
Shop Supplies	1.00

Labor: 335.00

Parts: 70.50

Total: 405.50

10/16/2025
3:04:28 PM

10208524

Palm Beach County Fleet Management Asset Maintenance History
2019 INTERNATIONAL 4300 Garbage Packer, 16 Yd, 33,000 Gvwr, Rear Loader

Work Order: 1911056
Problem: pm/list

Meter: 14462

In Date: 10/25/2019 **Closed:** 12/11/2019

Work Completed

- pm
- ac service
- add def change filter
- add coolant
- R&r strobe. rewire harness and diagnose switch
- replace bent exhaust system
- install rear work lights run wires and install switch with fuse and relay
- weld mudflap mounts to body. install mud flaps
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	23.00
oil filter	1.00
Air Fltr	1.00
fuel filter	1.00
fuel filter	1.00
Washer Fluid Concentr	2.00
Wiper Blade	2.00
Non-chlor Brake Clnr	3.00
Used Fire X Refurbished	1.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Def Filter	1.00
Blue Df	1.00
Rotell Elc Antifeerze	1.00
Strobe Lp Led	1.00
Stack Pipe	1.00
Tail Pipe	1.00
Led Worklamp	2.00
Releasable Cable Tie	2.00
Fab Loom-split Poly	70.00
Toggle Led Blu	2.00
Primary Wire	100.00
Mud Flap - Chevron De	2.00
Shop Supplies	1.00

Hours: 38.00

Comm: 0.00

Labor: 2,774.00

Parts: 3,275.17

Total: 6,049.17

10/16/2025
3:04:28 PM

10208524 Palm Beach County Fleet Management Asset Maintenance History
2019 INTERNATIONAL 4300 Garbage Packer, 16 Yd, 33,000 Gvwr, Rear Loader

Work Order: 2104406 **Meter:** 31218 **In Date:** 04/20/2021 **Closed:** 06/28/2021
Problem: pm/adjust brakes/replace cargo light switch/rusted ladder passenger side/grease packer blade and slides/list

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service/ Performed Complete	Washer Fluid Concentr	1.00
- Performed Road Test/ Performed Complete	Wiper Blade	2.00
- Add Def Replace Filter/ Top Fluid Replaced Def Filter Complete	fuel filter	1.00
- Performed Cooling System Service/ Performed Service Complete	Fuel Filter Repace Ff63009	1.00
- Performed Trans Service Fluid Low Filters At 18%/ Performed Transmission Service Complete Reset Life Meter	Air Fltr	1.00
- Replaced Driver And Passenger Steps Rusted Out	Silicone Spray 10oz	1.00
- A/c System Service With Filters/ Performed A/c Service With Filters Complete	Motor Tune-up 16oz	1.00
- Air Brake Filter Replaced/ Replaced Air Brake Drier Filter Complete	Non-chlor Brake Clnr	2.00
- Adjust All Brakes And Slack Adjusters	oil filter	1.00
- Rear Cargo Lights Inop- Replace Switch	Used Fire X Refurbished	1.00
- Aps Compactor Pm Service	Def Filter	1.00
- Rear Abs Brake Valves	Blue Df	2.00
- Test And Pressure Test Hydraulic System For Packer Blade	Rotell Elc Antifeerze	12.00
- Clean/grind And Lube Packer Tracks And Blade Tracks	Napa Cabin Air Filter	1.00
- Replace Garbage Packer Blade Plastic Slides/worn	Cabin Air Filter	1.00
- Duel Stage Packing Cylinder Has Internal Failure	15-40 Oil	23.00
- Shop Supplies	Red N Tacky Grs Ars	1.00
	Valve	2.00
	step	2.00
	Bolt	3.15
	Nut	12.00
	Reinforcement	2.00
	Ad Ip Dryer Cart	1.00
	Thread Sealer	1.00
	Napa Ep Grease 4 Can	2.00
	Shoe Slid And Hardware	1.00
	Syn-atf Trans Fluid S	24.00
	Napa Trans Filter	1.00

10/16/2025
3:04:28 PM

10208524

Palm Beach County Fleet Management Asset Maintenance History
2019 INTERNATIONAL 4300 Garbage Packer, 16 Yd, 33,000 Gvwr, Rear Loader

Parts Issued	Quantity
Aw68 Hydro Fluid Hydr	20.00
Toggle Switch	1.00
Ext/cord	1.00
Macs Chain Cable Lube	1.00
Aw68 Hydro Fluid Hydr	10.00
Hydraulic Filter	1.00
Mounting Hardware And Step	1.00
Elbow Pipe Fittings	2.00
New Pig	1.00
Cylinder Assy	1.00
Pin	1.00
Pin	1.00
Shop Supplies	1.00
Freight Charge	1.00
Freight Charge	1.00

Hours: 46.00

Comm: 0.00

Labor: 3,358.00

Parts: 7,760.00

Total: 11,118.00

Work Order: 2108527
Problem: DEF

Meter: 34072

In Date: 08/06/2021 **Closed:** 08/17/2021

Work Completed

- Add Def Fluid
- Shop Supplies

Parts Issued	Quantity
Blue Df	2.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 26.12

Total: 99.12

Work Order: 2109778
Problem: headlight

Meter: 35643

In Date: 09/09/2021 **Closed:** 09/10/2021

Work Completed

- change headlight
- Shop Supplies

Parts Issued	Quantity
Boxed Capsules	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 10.16

Total: 83.16

10/16/2025
3:04:28 PM

10208524

Palm Beach County Fleet Management Asset Maintenance History
2019 INTERNATIONAL 4300 Garbage Packer, 16 Yd, 33,000 Gvwr, Rear Loader

Work Order: 2206730

Meter: 46172

In Date: 06/27/2022 **Closed:** 07/11/2022

Problem: PM/air breaks leaking

Work Completed

- Preventive Maint. Service
- operator states air brake leak , found left rear brake chamber to be leaking. replace brake chamber
- to and from avenue p parks maintenance complex
- air dryer service, replace entire air dryer assembly , install all new air fittings
- a/c service
- def service
- rear pm
- fuel tank strap/cab step rusted and broken off . replace both straps and step brackets
- replace 4 marker lights
- Shop Supplies

Parts Issued

Quantity

oil filter	1.00
fuel filter	1.00
Fuel Filter Repace Ff63009	1.00
Air Fltr	1.00
Non-chlor Brake Clnr	3.00
Spring Brake Chamber	1.00
Ad Ip Dryer Cart	1.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Blue Df	2.00
Def Filter	1.00
Hyd Filter	1.00
Bolt	1.00
Lining	1.00
Strap Fuel Tank	1.00
Reinforcement	1.00
step	2.00
hose clap	1.00
Led M C Lamp	4.00
15-40 Oil	23.00
Wiper Blade	2.00
Shop Supplies	1.00
Freight Charge	1.00
Freight Charge	1.00

Hours: 24.50

Comm: 0.00

Labor: 1,788.50

Parts: 2,367.65

Total: 4,156.15

10/16/2025
3:04:28 PM

10208524 Palm Beach County Fleet Management Asset Maintenance History
2019 INTERNATIONAL 4300 Garbage Packer, 16 Yd, 33,000 Gvwr, Rear Loader

Work Order: 2206827 **Meter:** 46172 **In Date:** 06/27/2022 **Closed:** 06/28/2022
Problem: airbrakes leaking/ set for 6/28/22 at 9:00am

Work Completed

- Tow From: port rd. 825 ave P To: 2601 vista

Hours: 0.00 Comm: 124.30 Labor: 0.00 Parts: 0.00 Total: 124.30

Work Order: 2207417 **Meter:** 46869 **In Date:** 06/30/2022 **Closed:** 07/15/2022
Problem: Rear rims

Work Completed

- Tire Service: He Problem: Rear rims

Hours: 0.00 Comm: 175.15 Labor: 0.00 Parts: 0.00 Total: 175.15

Work Order: 2207702 **Meter:** 47314 **In Date:** 07/25/2022 **Closed:** 07/27/2022
Problem: truck needs def fluid

Work Completed

- Add Def Fluid
- Shop Supplies

Parts Issued

Quantity

Blue Df 2.00
Shop Supplies 1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 34.73 Total: 107.73

Work Order: 2208286 **Meter:** 47985 **In Date:** 08/09/2022 **Closed:**
Problem: LS mirror assembly

Work Completed

- Cab Miscellaneous

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

10/16/2025
3:04:28 PM

10208524 Palm Beach County Fleet Management Asset Maintenance History
2019 INTERNATIONAL 4300 Garbage Packer, 16 Yd, 33,000 Gvwr, Rear Loader

Work Order: 2210138 **Meter:** 49428 **In Date:** 10/03/2022 **Closed:** 11/28/2022

Problem: packer blade/roller cover blown off. hyd leak rear cylinder

Work Completed

Parts Issued

Quantity

- Driver lower mirror glass missing. Replace mirror glass.
- License plate ripped off unit. Drill new mounting holes in plate and remount.
- Operator states warning lights on. Abs and master warning light on. Connect scan tool and retrieve codes. Codes present for Abs communication loss and Idle over speed most severe.
- Operator states roller access cover fell off. Weldment threads ripped out. Inspect unit. Roller seized and missing grease fitting. R&r fitting and grease. Carrier binding up. Unit to dealer for repairs.
- to Epg 2xs
- Epg repair slide rollers and replace cylinders
- To international 2x
- Shop Supplies

Side Driver Mirror	1.00
Parts And Service From Epc	1.00
Parts And Service From Epc	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 19.50 Comm: 491.55 Labor: 1,423.50 Parts: 15,104.93 Total: 17,019.98

Work Order: 2212182 **Meter:** 49813 **In Date:** 12/05/2022 **Closed:** 12/06/2022

Problem: needs hydraulic fluid

Work Completed

Parts Issued

Quantity

- Check and fill hydraulic fluid, note that hydraulic fluid was very low, added back to spec
- Shop Supplies

Aw68 Hydro Fluid Hydr	15.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 53.47 Total: 126.47

Work Order: 2212424 **Meter:** 50211 **In Date:** 11/28/2022 **Closed:** 12/13/2022

Problem: Tires: LFS; Flat. Replace Tire

Work Completed

- Tire Service: He Problem: Tires: Lfs; Flat. Replace Tire

Hours: 0.00 Comm: 541.11 Labor: 0.00 Parts: 0.00 Total: 541.11

10/16/2025
3:04:28 PM

10208524 Palm Beach County Fleet Management Asset Maintenance History
2019 INTERNATIONAL 4300 Garbage Packer, 16 Yd, 33,000 Gvwr, Rear Loader

Work Order: 2300266 **Meter:** 52340 **In Date:** 01/10/2023 **Closed:** 01/19/2023

Problem: injector handle broken/can't unload/ PM

Work Completed

- Vehicle won't start, Jump start, load test battery fail test. Remove and replace Batteries
- To Jpp 2xs
- Shop Supplies

Parts Issued

	Quantity
Group 31 Stud Delco	3.00
Shop Supplies	1.00

Hours: 4.00

Comm: 0.00

Labor: 292.00

Parts: 441.48

Total: 733.48

10/16/2025
3:04:28 PM

10208524

Palm Beach County Fleet Management Asset Maintenance History
2019 INTERNATIONAL 4300 Garbage Packer, 16 Yd, 33,000 Gvwr, Rear Loader

Work Order: 2301067

Meter: 53107

In Date: 02/01/2023 **Closed:** 04/06/2023

Problem: PM/AC inop

Work Completed

- Preventive Maint. Service
- add def
- coolant low search for leaks none found add coolant
- multiple test drives
- R&r compressor. Txv, pressure switches, drier. evac and charge system
- Shop Supplies

Parts Issued

Quantity

Non-chlor Brake Clnr	3.00
Wiper Blade	2.00
Washer Fluid Concentr	1.00
15-40 Oil	23.00
oil filter	1.00
Aw68 Hydro Fluid Hydr	15.00
Hyd Filter	1.00
Used Fire X Refurbished	1.00
Air Fltr	1.00
fuel filter	1.00
Fuel Filter Repace Ff63009	1.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Blue Df	2.00
Rotell Elc Antifeerze	1.00
Ac Uv Dye 5 Shot	1.00
Freon He Shop	10.00
E8 A/c Oil Univ W Dye	2.00
Accumulator	1.00
Switch	1.00
Expansion Valve	1.00
A/c Seal Kit	1.00
switch	1.00
A/c Compressor	1.00
Shop Supplies	1.00

Hours: 17.00

Comm: 0.00

Labor: 1,241.00

Parts: 2,420.22

Total: 3,661.22

10/16/2025
3:04:28 PM

**10208524 Palm Beach County Fleet Management Asset Maintenance History
2019 INTERNATIONAL 4300 Garbage Packer, 16 Yd, 33,000 Gvwr, Rear Loader**

Work Order: 2310226 **Meter:** 58377 **In Date:** 10/10/2023 **Closed:** 10/13/2023
Problem: 16yd packer full of trash - Blowing oil all over - @ Carlin Maint Comp - Contact Mark LeCounte (561) 373-6884

Work Completed

- engine oil leak - found oil coming out of dip stick. check oil cap, excess pressure. clogged crankcase filter. replace filter. top off oil.
- to and from carlin park
- wash engine bay
- Shop Supplies

Parts Issued

	Quantity
Crankcase Breather Element	1.00
Gasket	1.00
Napa Qt 15w40	1.00
Shop Supplies	1.00

Hours: 6.00 Comm: 0.00 Labor: 438.00 Parts: 121.07 Total: 559.07

Work Order: 2310935 **Meter:** 58549 **In Date:** 10/05/2023 **Closed:** 10/30/2023
Problem: Tires: LFS; Flat. Repair Tire

Work Completed

- Tire Service: Ave P Problem: Tires: Lfs; Flat. Repair Tire

Hours: 0.00 Comm: 553.32 Labor: 0.00 Parts: 0.00 Total: 553.32

Work Order: 2312708 **Meter:** 59012 **In Date:** 12/28/2023 **Closed:** 05/29/2024
Problem: PM Service/needs to go for recalls

Work Completed

- Preventive Maint. Service
- Recall: Recall 19e020/cummin-c2127:fuel modules s/electric fuel heater-internal electrical arcing
- Recall: Campaign-c2302/nhtsa Recall 20e-018-electric fuel heater fuel modules Fs9030&fs90453 make inoperable
- Recall: Safety Campaign #c2302/20e-018 - Fuel Module overheating causing fire.
- Recall: 3rd. Notice -- Safety Campaign #c2302/20e-018 - Fuel Module overheating causing fire.
- Recall: Safety recall #22502 Def quality sensor and coolant control valve
- Recall: Safety Recall # 23510/23v-248 Blower motor circuit wiring overheated
- Add Def
- Service air conditioning system

Parts Issued

	Quantity
Napa Gal 15w40	6.00
Used Fire X Refurbished	1.00
Brake Parts Cleaner	6.00
Hot Shot's Lx4	1.00
oil filter	1.00
Fuel Filter Repace Ff63009	1.00
fuel filter	1.00
Air Fltr	1.00
Wiper Blade	2.00
Washer Fluid Concentr	1.00
Blue Df	2.00
Def Filter	1.00
Smokex Odor Elim 2 Oz	1.00
Cabin Air Filter	1.00

10/16/2025
3:04:28 PM

10208524 Palm Beach County Fleet Management Asset Maintenance History
2019 INTERNATIONAL 4300 Garbage Packer, 16 Yd, 33,000 Gvwr, Rear Loader

- found 3 bad lights removed and replaced rear middle marker light also replaced front upper right marker light
- Service air dryer
- Found Engine oil pan to be extremely rusty ie chunks of rust remove and replaced oil pan along with required seals
- Found toebar to be extremely rusty and tie rod ends to be damaged removed and replaced all toe bar parts. Pressed and heated siezed tie rod ends out of knuckles. Removed damaged cotter pins.
- Found rear brakes to be extremely worn down and needing replacment removed and replaced all rear brake drums shoes and hardware
- Travel time to mako plus wait for replacment fittings
- to rechtien 2xs
- repairs by Onsite
- repairs by rechtien
- Shop Supplies

Parts Issued	Quantity
Napa Cabin Air Filter	1.00
Cable Tie	1.00
Gray Sea	1.00
Px Grey Rtv Silicone	1.00
Oil Pan	1.00
Gasket	1.00
Oil Pan Gasket	1.00
Non-chlor Brake Clnr	5.00
Drag Link	1.00
Drum	2.00
brake shoe kit	2.00
Fitting From Mako	1.00
Led M C Lamp	1.00
Lamp	1.00
Ad Ip Dryer Cart	1.00
Non-chlor Brake Clnr	6.00
Ford Red	1.00
Parts And Service	1.00
Parts And Service Rechtien	1.00
Shop Supplies	1.00

Hours: 32.00

Comm: 0.00

Labor: 2,336.00

Parts: 10,421.74

Total: 12,757.74

Work Order: 2407327

Meter: 63267

In Date: 07/30/2024 **Closed:** 08/12/2024

Problem: Needs hydrolic fluid

Work Completed

- diag hydro leak , found leaking fitting remove fitting and hardlines. replace all o rings on fittings re install all hoses and fittings. no issues found top off hydro fluid.

- Shop Supplies

Parts Issued	Quantity
Aw68 Hydro Fluid Hydr	20.00
Shop Supplies	1.00

Hours: 3.50

Comm: 0.00

Labor: 255.50

Parts: 60.73

Total: 316.23

10/16/2025
3:04:28 PM

10208524 Palm Beach County Fleet Management Asset Maintenance History
2019 INTERNATIONAL 4300 Garbage Packer, 16 Yd, 33,000 Gvwr, Rear Loader

Work Order: 2502271 **Meter:** 71261 **In Date:** 02/28/2025 **Closed:** 03/10/2025
Problem: Tires: RRAO;LRAO; Flat. Replace Tire

Work Completed

- Tire Service: 825 P Ave, Port Road, Riviera Bch, Fl Problem: Tires: Rrao;lrao;
Flat. Replace Tire

Hours: 0.00 Comm: 894.56 Labor: 0.00 Parts: 0.00 Total: 894.56

Work Order: 2503121 **Meter:** 72280 **In Date:** 04/02/2025 **Closed:**
Problem: PM Service / list

Work Completed

- Preventive Maint. Service

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

Work Order: 2507259 **Meter:** 72280 **In Date:** 08/05/2025 **Closed:** 08/08/2025
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge
- Shop Supplies

Parts Issued	Quantity
Shop Supplies	1.00

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 2.65 Total: 148.65

Total Hours: 313.00 Total Labor: 22,702.00 Total Comm: 11,468.83 Total Parts: 55,424.42