

10/16/2025
2:50:56 PM

10198114

Palm Beach County Fleet Management Asset Maintenance History
2015 CATERPILLAR 420F2IT Backhoe w/Ext-A-Hoe Boom, 4x4, A/C Cab

Total Hours: 654.00 Labor: 45,251.50 Parts: 66,306.95 Comm: 8,315.62 Charged: 119874.07

Work Order: 1509347 **Meter:** 7 **In Date:** 09/16/2015 **Closed:** 09/16/2015
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 6.00 Comm: 0.00 Labor: 360.00 Parts: 0.00 Total: 360.00

Work Order: 1509412 **Meter:** 7 **In Date:** 09/17/2015 **Closed:** 10/19/2015
Problem: Ripper Tooth

Work Completed

- ripper
- Shop Supplies

Parts Issued

Quantity

Hensley Box	2.00
Hensley Shank	1.00
Hensley Box Pin	1.00
Hensley Tooth	2.00
Pin	6.00
Hensley Shank	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 1,507.57 Total: 1,507.57

Work Order: 1509550 **Meter:** 7 **In Date:** 09/22/2015 **Closed:** 10/09/2015
Problem: bucket teeth

Work Completed

- bucket teeth
- Replace O-ring at bucket disconnect
- Mosquito Control
- Shop Supplies

Parts Issued

Quantity

Bucket Teeth	12.00
Weldment Adapter	6.00
Pin	12.00
Pin Retainer	12.00
Shop Supplies	1.00

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 806.06 Total: 926.06

10/16/2025
2:50:56 PM

10198114

Palm Beach County Fleet Management Asset Maintenance History
2015 CATERPILLAR 420F2IT Backhoe w/Ext-A-Hoe Boom, 4x4, A/C Cab

Work Order: 1607759 **Meter:** 488 **In Date:** 07/29/2016 **Closed:** 08/17/2016
Problem: pm/hyd leak

Work Completed

Parts Issued

Quantity

- pm	15w40 serv truck	36.00		
- replace clamp at suction line	Napagold Oil Filter	1.00		
- lube boom extension	Element Fuel	1.00		
- to mosquito control	Filter Fuel	1.00		
- air up tires	Air Fil	2.00		
- road test	Element Sec	1.00		
- fill Def	Element Hyd	2.00		
- Shop Supplies	6v-7419 Wiper Blade	1.00		
	Multi-trac Hyd Fluid	4.00		
	Breather Filter	1.00		
	rear wiper blade	1.00		
	Air Filter	1.00		
	Aw68 Hydro Fluid Hydr	1.00		
	Shop Supplies	1.00		
Hours: 13.00	Comm: 0.00	Labor: 780.00	Parts: 760.63	Total: 1,540.63

Work Order: 1608538 **Meter:** 513 **In Date:** 08/17/2016 **Closed:** 08/18/2016
Problem: Hyd Leak

Work Completed

Parts Issued

Quantity

- R&r cut o-ring on valve body hose	Shop Supplies	1.00		
- To Mosquito Control				
- Shop Supplies				
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 2.00	Total: 182.00

10/16/2025
2:50:56 PM

10198114

Palm Beach County Fleet Management Asset Maintenance History
2015 CATERPILLAR 420F2IT Backhoe w/Ext-A-Hoe Boom, 4x4, A/C Cab

Work Order: 1611864
Problem: DEF

Meter: 681

In Date: 11/17/2016 **Closed:** 11/23/2016

Work Completed

Parts Issued

Quantity

- refill Def

Blue Df

4.00

- to 10th ave

Shop Supplies

1.00

- Shop Supplies

Hours: 1.50

Comm: 0.00

Labor: 90.00

Parts: 56.30

Total: 146.30

10/16/2025
2:50:56 PM

10198114

Palm Beach County Fleet Management Asset Maintenance History
2015 CATERPILLAR 420F2IT Backhoe w/Ext-A-Hoe Boom, 4x4, A/C Cab

Work Order: 1612397

Meter: 816

In Date: 12/02/2016 **Closed:** 03/08/2017

Problem: Clam won't close

Work Completed

- Pm
- Battery
- Strobe light
- To R&b 3xs
- Def
- Unchain from trailer
- Replace rubber mounting from end of boom for hoses
- Shop Supplies

Parts Issued

Quantity

Air Fil	1.00
Element Hyd	2.00
6v-7419 Wiper Blade	1.00
strobe light	1.00
Battery	1.00
Element Pri	1.00
Element Sec	1.00
Air Filter	1.00
15w40 serv truck	36.00
Blue Df	2.00
Hard Washer	9.00
bolt	4.00
Bolt	2.00
Washer	6.00
Washer	4.00
bolt	4.00
grommet	4.00
clip	2.00
clip	2.00
bracket assy	2.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 14.50

Comm: 0.00

Labor: 870.00

Parts: 1,394.84

Total: 2,264.84

10/16/2025
2:50:56 PM

10198114

Palm Beach County Fleet Management Asset Maintenance History
2015 CATERPILLAR 420F2IT Backhoe w/Ext-A-Hoe Boom, 4x4, A/C Cab

Work Order: 1702194
Problem: Wipers

Meter: 944

In Date: 03/02/2017 **Closed:** 04/04/2017

Work Completed

Parts Issued

Quantity

- Replace wiper assembly
- To Hagen Ranch, Charleston Shores Blvd. and to roads
- Replace broken hoses on bucket
- To Mako
- Def
- Shop Supplies

wiper motor	1.00
rear wiper motor	1.00
switch	1.00
switch	1.00
hose made	1.00
Blue Df	2.00
Shop Supplies	1.00

Hours: 10.00

Comm: 0.00

Labor: 600.00

Parts: 1,131.91

Total: 1,731.91

Work Order: 1704211
Problem: Oil leak

Meter: 1039

In Date: 04/26/2017 **Closed:**

Work Completed

-

Hours: 0.00

Comm: 0.00

Labor: 0.00

Parts: 0.00

Total: 0.00

10/16/2025
2:50:56 PM

10198114

Palm Beach County Fleet Management Asset Maintenance History
2015 CATERPILLAR 420F2IT Backhoe w/Ext-A-Hoe Boom, 4x4, A/C Cab

Work Order: 1704786

Meter: 1070

In Date: 05/12/2017 **Closed:** 06/06/2017

Problem: pm no start

Work Completed

- Pm
- Def
- Replace bad fuel line
- Fresh air knob
- 2 Tires
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	36.00
Napagold Oil Filter	1.00
Element Fuel	1.00
Filter Fuel	1.00
Element Pri	1.00
Element Sec	1.00
Element Hyd	1.00
Breather Filter	1.00
rear wiper blade	1.00
Air Filter	1.00
Key	1.00
6v-7419 Wiper Blade	1.00
Def Bulk Qts	5.00
fuel hose	47.00
control knob	1.00
Big G Degreaser 1 Gal	1.00
19.5I-24 Galaxy 12ply	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 9.00

Comm: 0.00

Labor: 540.00

Parts: 2,169.06

Total: 2,709.06

Work Order: 1705117

Meter: 1052

In Date: 05/24/2017 **Closed:** 05/25/2017

Problem: Rear tires

Work Completed

- Rear tires

Hours: 0.00

Comm: 236.36

Labor: 0.00

Parts: 0.00

Total: 236.36

10/16/2025
2:50:56 PM

10198114

Palm Beach County Fleet Management Asset Maintenance History
2015 CATERPILLAR 420F2IT Backhoe w/Ext-A-Hoe Boom, 4x4, A/C Cab

Work Order: 1709040

Meter: 1319

In Date: 09/20/2017 **Closed:** 11/03/2017

Problem: window broke

Work Completed

- Repair Ls door handle, and glass
- Pulled seat and replaced blower motor repair wirring
- R&r shifter and horn assembly
- Shop Supplies

Parts Issued

Quantity

Retainer	1.00
washer	1.00
bolt	1.00
latch	1.00
plug	5.00
rubber washer	4.00
bolt	2.00
handle	1.00
Air Filter	1.00
resistor	1.00
lh glass	1.00
lh side glass	1.00
blower motor	1.00
cab filter	1.00
Harness	1.00
a/c switch	1.00
shifter lever	1.00
Bumper	1.00
Retainer	1.00
Seal	1.00
Ptex Sup Wthstrp Adh	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 15.50

Comm: 0.00

Labor: 930.00

Parts: 2,197.85

Total: 3,127.85

10/16/2025
2:50:56 PM

10198114

Palm Beach County Fleet Management Asset Maintenance History
2015 CATERPILLAR 420F2IT Backhoe w/Ext-A-Hoe Boom, 4x4, A/C Cab

Work Order: 1711830
Problem: pm

Meter: 1491

In Date: 12/04/2017 **Closed:** 02/09/2018

Work Completed

- Pm
- Def
- Service Transmission
- Rd Test
- Shop Supplies

Parts Issued

Quantity

15w40 serv truck	36.00
Napagold Oil Filter	1.00
Element Fuel	1.00
fuel water sep	1.00
Element Pri	1.00
Element Sec	2.00
Breather Filter	1.00
rear wiper blade	1.00
Element Hyd	1.00
Filter	1.00
6v-7419 Wiper Blade	1.00
Non-chlor Brake Clnr	2.00
Air Filter	1.00
trans fither	1.00
o ring	1.00
seal	1.00
Blue Df	1.00
Oil Filter	1.00
Shop Supplies	1.00

Hours: 10.00

Comm: 0.00

Labor: 600.00

Parts: 925.67

Total: 1,525.67

Work Order: 1800846
Problem: DPF

Meter: 1464

In Date: 01/24/2018 **Closed:** 03/01/2018

Work Completed

- Repair Dpf
- Replace front tires

Hours: 0.00

Comm: 2,521.10

Labor: 0.00

Parts: 0.00

Total: 2,521.10

10/16/2025
2:50:56 PM

10198114

Palm Beach County Fleet Management Asset Maintenance History
2015 CATERPILLAR 420F2IT Backhoe w/Ext-A-Hoe Boom, 4x4, A/C Cab

Work Order: 1812428
Problem: AC

Meter: 2083

In Date: 12/06/2018 **Closed:** 02/15/2019

Work Completed

- Pm
- Repair head light
- Def
- R&r freon tested and found bad presure switch and repaired
- Replaced boom hyd. lines and repaired bracket
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	10.00
cab filter	1.00
Breather Filter	1.00
Air Filter	1.00
Element Fuel	1.00
fuel water sep	1.00
Element Sec	1.00
Element Pri	1.00
Washer Fluid Concentr	1.00
6v-7419 Wiper Blade	1.00
Relay	1.00
Freon He Shop	8.00
Blister Pack Capsules	1.00
Blue Df	2.00
Plate	1.00
Hose	1.00
Hose Assy	1.00
Hose Assy	1.00
Hose Asy	1.00
Hose Asy	1.00
Hose Asy	2.00
Plate Assy	1.00
Hose Made Bk	57.00
Coupling	2.00
Coupling	2.00
Hose Made	217.00
Coupling	1.00

10/16/2025
2:50:56 PM

10198114

Palm Beach County Fleet Management Asset Maintenance History
2015 CATERPILLAR 420F2IT Backhoe w/Ext-A-Hoe Boom, 4x4, A/C Cab

Parts Issued **Quantity**

Coupling 3.00

Pressure Switch 1.00

Shop Supplies 1.00

Hours: 26.50

Comm: 0.00

Labor: 1,775.50 Parts: 2,496.84 Total: 4,272.34

Work Order: 1901246

Meter: 2174

In Date: 02/01/2019 **Closed:** 03/05/2019

Problem: PM/ AC

Work Completed

- Pm
- Tested Ac found short in harness and repaired
- Def
- Service transmission
- Service axel and hubs
- Service front axel and hubs
- Test run
- Shop Supplies

Parts Issued **Quantity**

Napagold Oil Filter 1.00

15-40 Oil 36.00

fuel water sep 1.00

Element Fuel 1.00

Element Hyd 1.00

Napa Cabin Air Filter 1.00

Element Pri 1.00

Element Sec 1.00

rear wiper blade 1.00

6v-7419 Wiper Blade 1.00

Electrical Tape 1.00

Non-chlor Brake Clnr 3.00

Cable Tie 1.00

Air Filter 1.00

Blue Df 2.00

Cat Tdto 30 1.00

Napa Hydraulic Filtr 1.00

Cat Tdto 30 1.00

oil additive 2.00

Cat Tdto 30 1.00

oil additive 2.00

Shop Supplies 1.00

Hours: 22.50

Comm: 0.00

Labor: 1,507.50 Parts: 1,041.62 Total: 2,549.12

10/16/2025
2:50:56 PM

10198114

Palm Beach County Fleet Management Asset Maintenance History
2015 CATERPILLAR 420F2IT Backhoe w/Ext-A-Hoe Boom, 4x4, A/C Cab

Work Order: 1907966
Problem: PM

Meter: 2406

In Date: 08/01/2019 **Closed:** 08/28/2019

Work Completed

Parts Issued

Quantity

- Pm
- Service transmission
- Def
- Test run
- Service Ac
- Mosquito Control
- Shop Supplies

Motor Tune-up 16oz	2.00
15w40 serv truck	36.00
Napagold Oil Filter	1.00
Element Hyd	1.00
rear wiper blade	1.00
Breather Filter	1.00
Element Sec	2.00
Element Pri	1.00
fuel water sep	1.00
Element Fuel	1.00
Air Filter	1.00
Filter	1.00
6v-7419 Wiper Blade	1.00
Oil Filter	1.00
trans fither	1.00
Blue Df	2.00
Shop Supplies	1.00

Hours: 13.50

Comm: 0.00

Labor: 904.50

Parts: 952.10

Total: 1,856.60

Work Order: 1909751
Problem: LF tire

Meter: 2444

In Date: 09/12/2019 **Closed:** 09/20/2019

Work Completed

- Tire Service mosquito control - Lf tire

Hours: 0.00

Comm: 101.84

Labor: 0.00

Parts: 0.00

Total: 101.84

10/16/2025
2:50:56 PM

10198114

Palm Beach County Fleet Management Asset Maintenance History
2015 CATERPILLAR 420F2IT Backhoe w/Ext-A-Hoe Boom, 4x4, A/C Cab

Work Order: 1910171

Meter: 2491

In Date: 10/02/2019 **Closed:** 11/26/2019

Problem: RF Flasher

Work Completed

- replace turn sig assys
- to mosq cont x2
- test run
- order outrigger pads and install
- 2 tires
- ac condenser leaking. replace condenser lines evac and charge system
- replace front end parts, grille, hood, cover, frame, rubber bumpers
- test run
- Shop Supplies

Parts Issued

Quantity

19.5I-24 Galaxy 12ply	2.00
Lamp Gp Signal	2.00
Cable Tie	1.00
Freon He Shop	8.00
A/c Condenser	1.00
Hose Made Mako	1.00
Gas Spring	2.00
Bumper	1.00
Bumper	1.00
Film Cat	1.00
Washer	12.00
Washer	2.00
Latch	2.00
Pawl	2.00
ball stud	4.00
Grill Frame	1.00
Cover	1.00
Grill	1.00
cover	1.00
Latch	2.00
Plate	2.00
Screw	12.00
pad	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 24.50

Comm: 0.00

Labor: 1,788.50

Parts: 5,395.28

Total: 7,183.78

10/16/2025
2:50:56 PM

10198114

Palm Beach County Fleet Management Asset Maintenance History
2015 CATERPILLAR 420F2IT Backhoe w/Ext-A-Hoe Boom, 4x4, A/C Cab

Work Order: 2008912 **Meter:** 3135 **In Date:** 09/03/2020 **Closed:** 10/24/2020
Problem: Boom Won't go up

Work Completed

- replace battery
- R&r outrigger cylinder. heat pins to remove
- stow outrigger cylinder with crane
- to sherwood forest
- Shop Supplies

Parts Issued

Quantity

Battery	1.00
Gland Nut	1.00
Nut Wrench	1.00
New Cylinder	1.00
Aw68 Hydro Fluid Hydr	10.00
Shop Supplies	1.00

Hours: 10.50

Comm: 0.00

Labor: 766.50

Parts: 5,410.92

Total: 6,177.42

Work Order: 2012560 **Meter:** 3353 **In Date:** 12/17/2020 **Closed:** 03/23/2021
Problem: PM/ repair leaking bucket cylinders

Work Completed

- Preventive Maint. Service
- Hydraulic system service
- A/c service
- Test Run
- To Mosquito Control 2/22, 2/24, 3/17
- hyd leak at loader bucket split cyls- remove and repack 2 cyls reinstall test good
- a/c blower stuck on high speed, blower switch broken- replace switch
- replace switch and missing throttle control knob- plastic door latch cover broke, replace- hoe boom hose holders missing rubber, stripped mounting holes, replace rubber and new hardware
- right side stabilizer leg drifts down, wont hold- cap off in and out and verify internal leak- disassemble cyl , found damaged seal, replace seals and reassemble, retest and top off fluid
- left door latch weld broke, metal cracked- disassemble and remove door, weld repair and paint, reinstall and adjust
- Shop Supplies

Parts Issued

Quantity

15w40 serv truck	10.00
Breather Filter	1.00
Element	1.00
Element Sec	1.00
fuel water sep	1.00
Element Fuel	1.00
Washer Fluid Concentr	1.00
6v-7419 Wiper Blade	1.00
rear wiper blade	1.00
Napagold Oil Filter	1.00
Service Aw68	3.00
Element Hyd	1.00
cab filter	1.00
Napa Cabin Air Filter	1.00
Seal Kit	2.00
Non-chlor Brake Clnr	3.00
control knob	1.00

10/16/2025
2:50:56 PM

10198114

Palm Beach County Fleet Management Asset Maintenance History
2015 CATERPILLAR 420F2IT Backhoe w/Ext-A-Hoe Boom, 4x4, A/C Cab

Parts Issued	Quantity
Blower Switch	1.00
grommet	4.00
Cover Latch	1.00
Aw68 Hydro Fluid Hydr	16.00
Seal	2.00
Wear Ring	2.00
Seal-o-ring	2.00
Seal-o-ring	2.00
Switch Assy	1.00
Seal Wiper	2.00
Seal-u-cup	2.00
Seal As-buff	2.00
Seal	2.00
Ring Backup	2.00
Shop Supplies	1.00
Hours: 32.50	Comm: 0.00
Labor: 2,372.50	Parts: 2,049.76
Total: 4,422.26	

Work Order: 2104720

Meter: 3624

In Date: 04/28/2021 **Closed:** 04/28/2021

Problem: machine door will not latch it will be on Lechalet between Military and Jog. #506-1250

Work Completed

Parts Issued	Quantity
Shop Supplies	1.00

- Operator states door will not latch. Repaired door latch mechanism. Test ok.

- Service Call to Lechalet in Boynton Beach and back.

- Shop Supplies

Hours: 3.00

Comm: 0.00

Labor: 219.00

Parts: 4.00

Total: 223.00

10/16/2025
2:50:56 PM

10198114

Palm Beach County Fleet Management Asset Maintenance History
2015 CATERPILLAR 420F2IT Backhoe w/Ext-A-Hoe Boom, 4x4, A/C Cab

Work Order: 2105735

Meter: 3688

In Date: 05/24/2021 **Closed:** 06/23/2021

Problem: PM Service. at Mosquito Control

Work Completed

- Preventive Maint. Service
- Tire
- a/c service
- fill def
- travel to mosquito control twice
- road tested
- trans service
- replaced broken grease fitting right support leg
- Shop Supplies

Parts Issued

Quantity

19.5I-24bkt R4 Tr459	1.00
15w40 serv truck	10.00
Breather Filter	1.00
Element	1.00
Element Sec	1.00
fuel water sep	1.00
Element Fuel	1.00
Washer Fluid Concentr	1.00
6v-7419 Wiper Blade	1.00
rear wiper blade	1.00
Element Hyd	1.00
Napagold Oil Filter	1.00
Non-chlor Brake Clnr	3.00
Filter	1.00
Air Fil	1.00
Air Filter	1.00
Motor Tune-up 16oz	2.00
Electrical Tape	1.00
Air Freshener	1.00
cab filter	1.00
Napa Cabin Air Filter	1.00
Blue Df	1.00
Syn Atf	6.00
Napa Hydraulic Filtr	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 14.50

Comm: 0.00

Labor: 1,058.50

Parts: 1,738.42

Total: 2,796.92

10/16/2025
2:50:56 PM

10198114

Palm Beach County Fleet Management Asset Maintenance History
2015 CATERPILLAR 420F2IT Backhoe w/Ext-A-Hoe Boom, 4x4, A/C Cab

Work Order: 2112697
Problem: PM

Meter: 4091

In Date: 11/30/2021 **Closed:** 01/28/2022

Work Completed

- Preventive Maint. Service
- transmission serviced
- filled def
- travel to mosquito control twice
- road tested
- service a/c system
- Hyd pipe bent on left out rigger, remove and replace line
- Add Hyd oil
- Shop Supplies

Parts Issued

Quantity

15w40 serv truck	10.00
Element Sec	1.00
Element Fuel	1.00
Breather Filter	1.00
fuel water sep	1.00
Air Fil	1.00
Napagold Oil Filter	1.00
Element Hyd	1.00
rear wiper blade	1.00
6v-7419 Wiper Blade	1.00
Washer Fluid Concentr	1.00
Electrical Tape	1.00
Non-chlor Brake Clnr	3.00
Motor Tune-up 16oz	2.00
Syn-atf Trans Fluid S	6.00
trans fither	1.00
Blue Df	1.00
Air Freshener	1.00
Napa Cabin Air Filter	1.00
cab filter	1.00
Non-chlor Brake Clnr	2.00
Hyd Tube	1.00
Aw68 Hydro Fluid Hydr	8.00
Shop Supplies	1.00

Hours: 16.00

Comm: 0.00

Labor: 1,168.00

Parts: 656.69

Total: 1,824.69

10/16/2025
2:50:56 PM

10198114

Palm Beach County Fleet Management Asset Maintenance History
2015 CATERPILLAR 420F2IT Backhoe w/Ext-A-Hoe Boom, 4x4, A/C Cab

Work Order: 2203800

Meter: 4399

In Date: 04/08/2022 **Closed:** 04/27/2022

Problem: PM Service. machine will be at mosquito control on Monday

Work Completed

- Preventive Maint. Service
- fill def
- a/c service
- service transmission
- travel to mosquito control
- road test
- Shop Supplies

Parts Issued

Quantity

15w40 serv truck	10.00
Hose Clamp	2.00
Electrical Tape	1.00
Motor Tune-up 16oz	2.00
Non-chlor Brake Clnr	3.00
Napagold Oil Filter	1.00
Element Fuel	1.00
fuel water sep	1.00
Air Fil	1.00
Element Sec	1.00
Breather Filter	1.00
Element Hyd	1.00
Washer Fluid Concentr	1.00
6v-7419 Wiper Blade	1.00
rear wiper blade	1.00
Blue Df	1.00
Napa Cabin Air Filter	1.00
cab filter	1.00
Air Freshener	1.00
trans fither	1.00
Shop Supplies	1.00

Hours: 12.50

Comm: 0.00

Labor: 912.50

Parts: 555.92

Total: 1,468.42

10/16/2025
2:50:56 PM

10198114

Palm Beach County Fleet Management Asset Maintenance History
2015 CATERPILLAR 420F2IT Backhoe w/Ext-A-Hoe Boom, 4x4, A/C Cab

Work Order: 2205184 **Meter:** 4457 **In Date:** 05/13/2022 **Closed:** 05/26/2022
Problem: Dist.3 Robert, Steering wheel column will stray locked will turn in today/ AC fan switch

Work Completed

Parts Issued

Quantity

- Tilt Steering Column loose, perform inspection found tilt column defective causing looseness

Gas Shock 1.00

Blower Switch 1.00

- A/c fan not operating all the time, perform circuit diagnose and found A/c switch has open circuit on two contacts, Replace A/c switch

Shop Supplies 1.00

- Shop Supplies

Hours: 3.00

Comm: 0.00

Labor: 219.00

Parts: 105.90

Total: 324.90

Work Order: 2206490 **Meter:** 4502 **In Date:** 06/13/2022 **Closed:** 06/17/2022
Problem: RF tire nail

Work Completed

- Tire Service: mosquito control Problem: Rf tire nail

Hours: 0.00

Comm: 96.62

Labor: 0.00

Parts: 0.00

Total: 96.62

Work Order: 2206529 **Meter:** 4502 **In Date:** 06/21/2022 **Closed:** 06/22/2022
Problem: DEF

Work Completed

Parts Issued

Quantity

- Add Def Fluid

Blue Df 2.00

- to Rose Marie Ave. and La Chalet Blvd.

Shop Supplies 1.00

- Shop Supplies

Hours: 2.50

Comm: 0.00

Labor: 182.50

Parts: 34.73

Total: 217.23

Work Order: 2207932 **Meter:** 4621 **In Date:** 08/01/2022 **Closed:** 08/03/2022
Problem: Dist.3 Robert, machine has a light out in front and rear of machine, it will be at Mosquito Complex on Monday

Work Completed

Parts Issued

Quantity

- Front and rear lights out, replace both H3 light bulbs

Blister Pack Capsules 2.00

- To Mosquito Control 2xs

Shop Supplies 1.00

- Shop Supplies

Hours: 3.50

Comm: 0.00

Labor: 255.50

Parts: 15.45

Total: 270.95

10/16/2025
2:50:56 PM

10198114

Palm Beach County Fleet Management Asset Maintenance History
2015 CATERPILLAR 420F2IT Backhoe w/Ext-A-Hoe Boom, 4x4, A/C Cab

Parts Issued	Quantity
Blue Df	1.00
Napa 10w30 Qt	3.00
resistor	1.00
Blower	1.00
seal kit	1.00
Ultra Supreme 238 Moly Grease	2.00
Tensioner	1.00
Belt	1.00
Ultra Supreme 238 Moly Grease	1.00
Non-chlor Brake Clnr	1.00
Aw68 Hydro Fluid Hydr	12.00
Shop Supplies	1.00

Hours: 35.00 Comm: 0.00 Labor: 2,555.00 Parts: 1,594.25 Total: 4,149.25

Work Order: 2210578 **Meter:** 4816 **In Date:** 10/05/2022 **Closed:** 10/17/2022

Problem: Tires: RFS; Flat. Replace Tire

Work Completed

- Tire Service: Lyons Problem: Tires: Rfs; Flat. Replace Tire

Hours: 0.00 Comm: 124.87 Labor: 0.00 Parts: 0.00 Total: 124.87

Work Order: 2210626 **Meter:** 4909 **In Date:** 10/18/2022 **Closed:** 01/03/2023

Problem: Dist.3 Robert, machine is missing three bucket teeth it is at mosquito control

Work Completed

- replacement pins, keepers and teeth for backhoe bucket

- Shop Supplies

Parts Issued	Quantity
Pin Retainer	10.00
Pin	10.00
Bucket Teeth	5.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 260.00 Total: 333.00

10/16/2025
2:50:56 PM

10198114

Palm Beach County Fleet Management Asset Maintenance History
2015 CATERPILLAR 420F2IT Backhoe w/Ext-A-Hoe Boom, 4x4, A/C Cab

Work Order: 2304075 **Meter:** 5169 **In Date:** 04/25/2023 **Closed:** 05/17/2023

Problem: Dist.3 Robert, has a Hyd. leak from the cylinder

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service	Blower Switch	1.00
- a/c svc. - blower speed switch broke. replace switch and repair connection	Washer	8.00
- trans svc	4k0367 Nuts 5-8 For B	8.00
- hyd leak - leaking cyls on loader bucket. rebuild both top cyls.	3f5108 Bolt-nut Blade	8.00
- add Def	Edge Cutting	2.00
- Replaced worn blades on front bucket.	New Pig	1.00
- Removed and replaced rear drive shaft u-joints	Kit Seal	2.00
- Removed and replaced battery. Cleaned all corrosion from battery terminals.	Spider Kit	2.00
- Hydraulic system service	Strap	4.00
- Degreased and washed off oils and debris.	Bolt	8.00
- Test Run	3yr Wty Bat	1.00
- Shop Supplies	Shop Supplies	1.00

Hours: 27.50 Comm: 0.00 Labor: 2,007.50 Parts: 1,312.81 Total: 3,320.31

Work Order: 2306178 **Meter:** 5200 **In Date:** 06/23/2023 **Closed:** 06/27/2023

Problem: Dist.3 Jeff, has a Hyd. leak Lt. side fitting in front of the grill it will be at Mosquito Control

Work Completed

Parts Issued

Quantity

- operator states hyd leak from front of machine. found hose ruptured on boom, remove and replace hose. found hardline damaged on boom. remove bring to mako and have it repaired. check for any leaks after repair.	Hose Made Mako	1.00
- to and from mosquito control x2	Shop Supplies	1.00
- road test		
- to and fom mako +wait time x2		
- Shop Supplies		

Hours: 9.00 Comm: 0.00 Labor: 657.00 Parts: 115.61 Total: 772.61

10/16/2025
2:50:56 PM

10198114

Palm Beach County Fleet Management Asset Maintenance History
2015 CATERPILLAR 420F2IT Backhoe w/Ext-A-Hoe Boom, 4x4, A/C Cab

Work Order: 2310596

Meter: 5451

In Date: 10/19/2023 **Closed:** 01/30/2024

Problem: PM Service

Work Completed

- Preventive Maint. Service
- Travel To Mosquito Control
- Road Test
- Perform A/c Service
- Perform Transmission Service
- Perform Hydraulic Service
- Shop Supplies

Parts Issued

Quantity

Napa Gal 15w40	3.00
Non-chlor Brake Clnr	3.00
Element	1.00
Element Fuel	1.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Breather Filter	1.00
Element Sec	1.00
6v-7419 Wiper Blade	1.00
rear wiper blade	1.00
Electrical Tape	1.00
Motor Tune-up 16oz	1.00
Element Hyd	1.00
fuel water sep	1.00
cab filler	1.00
cab filter	1.00
Cable Tie	1.00
Tree Royal Pine 3pk	1.00
trans fither	1.00
Prem Aw 68 Hyd Fl 5g	1.00
Shop Supplies	1.00

Hours: 11.50

Comm: 0.00

Labor: 839.50

Parts: 848.44

Total: 1,687.94

10/16/2025
2:50:56 PM

10198114

Palm Beach County Fleet Management Asset Maintenance History
2015 CATERPILLAR 420F2IT Backhoe w/Ext-A-Hoe Boom, 4x4, A/C Cab

Work Order: 2403895
Problem: fuel lube

Meter: 5892

In Date: 04/19/2024 **Closed:** 04/22/2024

Work Completed

Parts Issued

Quantity

- Onsite Fueling, Lube
- to and from mosquito control
- Shop Supplies

Shop Supplies

1.00

Hours: 2.50

Comm: 0.00

Labor: 182.50

Parts: 2.65

Total: 185.15

10/16/2025
2:50:56 PM

10198114

Palm Beach County Fleet Management Asset Maintenance History
2015 CATERPILLAR 420F2IT Backhoe w/Ext-A-Hoe Boom, 4x4, A/C Cab

Work Order: 2404297

Meter: 6011

In Date: 05/01/2024 **Closed:** 07/22/2024

Problem: pm

Work Completed

- Preventive Maint. Service
- Hydraulic Service
- Perform A/c Service
- Perform Transmission Service
- Travel He Shop
- Road Test
- Fueled With Diesel 5/13 And 5/17
- Traveled To Purdy And Haverhill 5/13/24
- Travel To Kirk And 10th Ave 5/17
- Fill Def
- Shop Supplies

Parts Issued

Quantity

Motor Tune-up 16oz	1.00
Marvel	1.00
Element Sec	1.00
Element	1.00
Rain-x Original Glass	1.00
Electrical Tape	1.00
Non-chlor Brake Clnr	3.00
rear wiper blade	1.00
6v-7419 Wiper Blade	1.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
fuel water sep	1.00
Element Fuel	1.00
Breather Filter	1.00
Aw68 Serv Truck	3.00
Element Hyd	1.00
Tree Royal Pine 3pk	1.00
cab filler	1.00
cab filter	1.00
trans fither	1.00
Syn-atf Trans Fluid S	6.00
15-40 Oil	10.00
Blue Df	2.00
Shop Supplies	1.00

Hours: 15.00

Comm: 0.00

Labor: 1,095.00

Parts: 865.15

Total: 1,960.15

Work Order: 2404849

Meter: 6016

In Date: 05/15/2024 **Closed:** 09/30/2024

Problem: D3 Robert, A/C is not blowing cold air. hyd leak at cyl. teeth and pins.

Work Completed

10/16/2025
2:50:56 PM

10198114

Palm Beach County Fleet Management Asset Maintenance History
2015 CATERPILLAR 420F2IT Backhoe w/Ext-A-Hoe Boom, 4x4, A/C Cab

- a/c blower intermittent, remove interior panels to replace blower assembly, found harness from switch to blower motors burnt . replaced entire hvac wiring harness. reassemble interior
- hyd leak - found dipper cyl. leaking on hoe boom. rebuild cyl. outrigger cylinders damaged. R&r outriggers
- Robert, would like to order Pin-get Coil part number 238-3200 2 pack of 10 and would like to order teeth for the rear bucket. R&r teeth on hoe bucket
- front grille assembly extremely damaged. replace grille frame , rubber bumpers and related parts
- a/c condenser damaged from front grille damage, replace a/c condenser , compressor & dryer
- test run
- Shop Supplies

Parts Issued	Quantity
Blower Switch	1.00
Relay Assy	2.00
Switch	1.00
Blower	1.00
Seal Kit Hc	1.00
Bucket Teeth	5.00
Pin	10.00
Pin Retainer	10.00
Pin	10.00
Hose Made Mako	1.00
Gas Spring	2.00
Film Cat	1.00
Nut	4.00
Plate	1.00
Gas Spring	2.00
Grill Frame	1.00
Grill	1.00
Bulk Seal	63.00
Screw	16.00
Bumper	1.00
Bumper	1.00
Lamp Gp Signal	1.00
Screw Button	2.00
A/c Condenser	1.00
A/c Compressor	1.00
Map Gas Cylinder	1.00
Non-chlor Brake Clnr	14.00
Wiper Seal	2.00
Wiper Seal	2.00
Seal Kit	2.00

10/16/2025
2:50:56 PM

10198114

Palm Beach County Fleet Management Asset Maintenance History
2015 CATERPILLAR 420F2IT Backhoe w/Ext-A-Hoe Boom, 4x4, A/C Cab

Parts Issued	Quantity
Hose Assy	1.00
Hose Assy	1.00
Non-chlor Brake Clnr	12.00
Cylinder	1.00
Reman Hyd	1.00
Aw68 Hydro Fluid Hydr	20.00
Seal	2.00
Pressure Switch	1.00
Harness	1.00
Harness	1.00
Pressure A/c Switch	1.00
Relay	1.00
Shop Supplies	1.00
Freight Charge	1.00
Hours: 37.50 Comm: 0.00 Labor: 2,737.50 Parts: 9,894.34 Total: 12,631.84	

Work Order: 2409758 **Meter:** 6117 **In Date:** 10/08/2024 **Closed:** 11/05/2024

Problem: D3 Robert, can you send a Mechanic to mosquito control to help change the bucket on this Backhoe we will have a

Work Completed

Parts Issued	Quantity
Shop Supplies	1.00

- Inspected bucket and attachment pins. Made sure all retaining pins were secure.

- fuel and lube

- To Mosquito control

- Shop Supplies

Hours: 3.00 Comm: 0.00 Labor: 219.00 Parts: 2.65 Total: 221.65

10/16/2025
2:50:56 PM

10198114

Palm Beach County Fleet Management Asset Maintenance History
2015 CATERPILLAR 420F2IT Backhoe w/Ext-A-Hoe Boom, 4x4, A/C Cab

Work Order: 2506686 **Meter:** 6593 **In Date:** 07/11/2025 **Closed:** 07/18/2025
Problem: Tires: RF; Flat. Repair Tire

Work Completed

- Tire Service: mosq. cont. Problem: Tires: Rf; Flat. Repair Tire

Hours: 0.00 Comm: 124.20 Labor: 0.00 Parts: 0.00 Total: 124.20

Work Order: 2506852 **Meter:** 6612 **In Date:** 07/25/2025 **Closed:** 08/05/2025
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 654.00

Total Labor: 45,251.50

Total Comm: 8,315.62

Total Parts: 66,306.95