

12/28/2017
3:54:35PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178913 2009 FORD F150 Pickup, 1/2 Ton, W/Tow Pkg

Workorder: 938964

Problem: PRE-DELIVERY INSPECTION

Meter Reading: 0		Labor	Parts	
In Date: 06/15/2009	Close Date: 06/15/2009	Hours	Description	Quantity
- Pre-Delivery Inspection		2.00		
Parts Charge:	0.00	Labor Charge:	120.00	

Workorder: 939111

Problem: MAKE & PROGRAM NEW KEY

Meter Reading: 335		Labor	Parts	
In Date: 06/17/2009	Close Date: 06/18/2009	Hours	Description	Quantity
- Cut Key & Program& Test		1.00	164-R0475 IGN KEY 2010-EARLIER (DON'T REORDER)	1.00
- Shop Supplies			SHOP SUPPLIES	1.00
Parts Charge:	23.45	Labor Charge:	60.00	

Workorder: 1000625

Problem: P.M.SERVICE/LOW TIRE PRESSURE

Meter Reading: 7137		Labor	Parts	
In Date: 01/15/2010	Close Date: 01/26/2010	Hours	Description	Quantity
- P. M.		2.50	SHOP SUPPLIES	1.00
- C/C: Low Tire Pressure. Ck All Tires For Nails Or			5W20 ENGINE OIL	7.00
Damage, Found Nothing. Add N2 To All Tires At 38 Psi.			1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Shop Supplies				
Parts Charge:	38.68	Labor Charge:	150.00	

Workorder: 1006192

Problem: P. M. SERVICE

Meter Reading: 13420		Labor	Parts	
In Date: 06/10/2010	Close Date: 06/22/2010	Hours	Description	Quantity
- P. M. Service.		2.25	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Install Bumper Sticker.			5W20 ENGINE OIL	7.00
- Shop Supplies			SHOP SUPPLIES	1.00
Parts Charge:	38.65	Labor Charge:	135.00	

12/28/2017
3:54:35PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178913 2009 FORD F150 Pickup, 1/2 Ton, W/Tow Pkg

Workorder: 1012476

Problem: P. M. SERVICE

Meter Reading: 18969		Labor		Parts	
In Date: 11/08/2010	Close Date: 11/18/2010	Hours	Description		Quantity
-	P. M.	3.00	CA10262 AIR FILTER MTC FA1883 WIX 49883		1.00
-	Verify, Bumper Trim Coming Disconnected, Repair.		5W20 ENGINE OIL		7.00
-	Repair Mounting Hardware On Fire Extinguisher Holder.		SHOP SUPPLIES		1.00
-	Shop Supplies		12345841 GEAR OIL SYNTHETIC 75W-90		1.00
			1372 OIL FILTER FRM PH2 WIX 51372		1.00
Parts Charge:		56.43	Labor Charge:	180.00	

Workorder: 1103315

Problem: Fix flat tire

Meter Reading: 22090		Labor		Parts	
In Date: 03/28/2011	Close Date: 03/29/2011	Hours	Description		Quantity
-	Repair Rr Tire.	1.00	SHOP SUPPLIES		1.00
-	Shop Supplies				
Parts Charge:		2.00	Labor Charge:	60.00	

Workorder: 1103975

Problem: NEEDS 4 TIRES

Meter Reading: 22679		Labor		Parts	
In Date: 04/13/2011	Close Date: 04/20/2011	Hours	Description		Quantity
-	C/C: Needs Four Tires. Verify. Dismount, Mount,	2.00	183783418 P235/70R17 WRANGLER SR-A XL		4.00
	Balance, Add 35 Psi Of Nitrogen.		SHOP SUPPLIES		1.00
-	Shop Supplies		TIRE DISPOSAL FEE		4.00
Parts Charge:		435.76	Labor Charge:	120.00	

Workorder: 1104980

Problem: P. M. SERVICE

Meter Reading: 23439		Labor		Parts	
In Date: 05/11/2011	Close Date: 05/20/2011	Hours	Description		Quantity
-	P. M. Service.	3.00	1372 OIL FILTER FRM PH2 WIX 51372		1.00
-	Repair Rr Tire.		31-22 WIPER BLADES 22" WIPER BLADE		2.00
-	Shop Supplies		5W20 ENGINE OIL		7.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			SHOP SUPPLIES		1.00
Parts Charge:		62.23	Labor Charge:	180.00	

12/28/2017
3:54:35PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178913 2009 FORD F150 Pickup, 1/2 Ton, W/Tow Pkg

Workorder: 1105278

Problem: Check engine light is on

Meter Reading: 23507		Labor		Parts	
In Date: 05/18/2011	Close Date: 05/20/2011	Hours	Description		Quantity
- C/S: Check Engine Light Stays On. E.E.C. System Diagnosis, Code P2135, Pinpoint Test. Found Defective T.P.S.		2.75	SHOP SUPPLIES		1.00
- Transport & Pick Up Vehicle At Dealer. (Defective T.P. Sensor).					
- Dealer To Replace T.B. & Motor Assy.					
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	165.00	

Workorder: 1112152

Problem: P. M. SERVICE

Meter Reading: 28240		Labor		Parts	
In Date: 11/14/2011	Close Date: 11/30/2011	Hours	Description		Quantity
- P. M. Service.		4.25	5W20 ENGINE OIL		8.00
- Install "No Smoking & Idling" Decal. Install "How'S My Driving" Decal.			1372 OIL FILTER FRM PH2 WIX 51372		1.00
			SHOP SUPPLIES		1.00
- Transport & Pick Up Vehicle At Dealer. (R/Side Outer Door Latch Inop).			31-22 WIPER BLADES 22" WIPER BLADE		2.00
			CA10262 AIR FILTER MTC FA1883 WIX 49883		1.00
- Dealer To Replace Defective Passenger Door Latch.					
- Shop Supplies					
Parts Charge:		55.77	Labor Charge:	255.00	

Workorder: 1204549

Problem: pm vehicle

Meter Reading: 33790		Labor		Parts	
In Date: 05/14/2012	Close Date: 05/16/2012	Hours	Description		Quantity
- Pm Service		2.00	61A P/STEERING FLUID		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			5W20 ENGINE OIL		6.00
			1372 OIL FILTER FRM PH2 WIX 51372		1.00
			5W20 ENGINE OIL		1.00
Parts Charge:		49.40	Labor Charge:	120.00	

12/28/2017
3:54:35PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178913 2009 FORD F150 Pickup, 1/2 Ton, W/Tow Pkg

Workorder: 1206589

Problem: windshield wiper need to be replaced

Meter Reading: 36911

Labor

Parts

In Date: 07/16/2012

Close Date: 07/18/2012

Hours

Description

Quantity

- Ck Wipers Replace Rr Two Wipers	0.25	31-22 WIPER BLADES 22" WIPER BLADE	2.00
Parts Charge:	8.80	Labor Charge:	15.00

Workorder: 1209080

Problem: pm, ck tires

Meter Reading: 39538

Labor

Parts

In Date: 09/21/2012

Close Date: 09/28/2012

Hours

Description

Quantity

- Pm	2.00	SHOP SUPPLIES	1.00
- Shop Supplies		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		31-22 WIPER BLADES 22" WIPER BLADE	2.00
		5W20 ENGINE OIL	8.00
Parts Charge:	44.73	Labor Charge:	120.00

Workorder: 1211226

Problem: nail in l/front tire

Meter Reading: 40610

Labor

Parts

In Date: 11/19/2012

Close Date: 11/26/2012

Hours

Description

Quantity

- Repair Left Front Tire	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Workorder: 1302413

Problem: left front tire flat

Meter Reading: 44722

Labor

Parts

In Date: 03/11/2013

Close Date: 03/13/2013

Hours

Description

Quantity

- Repaired Tire	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

12/28/2017
3:54:35PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178913 2009 FORD F150 Pickup, 1/2 Ton, W/Tow Pkg

Workorder: 1302760

Problem: PM OIL CHANGE CK WIPERS ON IS BROKEN PASS SIDE REPLACE FRONT TIRES FRONT DRIVERS PAT

Meter Reading: 45136		Labor		Parts	
In Date: 03/20/2013	Close Date: 03/28/2013	Hours	Description		Quantity
- Pm		4.00	SHOP SUPPLIES		1.00
- Ck Tires Verify Needs 4 Tires Dismount Mounq Balance			TIRE DISPOSAL FEE		4.00
Add N2			1372 OIL FILTER		1.00
- Shop Supplies			31-22 WIPER BLADES 22		2.00
			183783418 P235-70R17		4.00
			NAPA QUART 5W20		8.00
Parts Charge: 895.72		Labor Charge:	240.00		

Workorder: 1305987

Problem: nail in left rear tire

Meter Reading: 48756		Labor		Parts	
In Date: 06/17/2013	Close Date: 06/20/2013	Hours	Description		Quantity
- Verify Nail In Tire Repair Left Rear Patch Mount Balance		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 2.00		Labor Charge:	60.00		

Workorder: 1310373

Problem: P.M.

Meter Reading: 53849		Labor		Parts	
In Date: 10/15/2013	Close Date: 10/23/2013	Hours	Description		Quantity
- Pm		2.75	NAPAGOLD AIR FILTER		1.00
- Verfiy Dead Battery Ck Charging Sys Replace Battery			NAPAGOLD OIL FILTER		1.00
After Tested Bad			NAPA QUART 5W20		8.00
- Shop Supplies			WIPER BLADE		2.00
			USED FIRE X REFURBISHED		1.00
			GROUP 59 BATTERY MC		1.00
			SHOP SUPPLIES		1.00
Parts Charge: 197.13		Labor Charge:	165.00		

12/28/2017
3:54:35PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178913 2009 FORD F150 Pickup, 1/2 Ton, W/Tow Pkg

Workorder: 1312385

Problem: canceiver

Meter Reading: 56133

In Date: 12/12/2013

Close Date: 12/18/2013

Labor

Hours

Description

Parts

Quantity

- | | | | |
|--|------|---------------|------|
| - Test And Remove Canceiver Issue Fuel Card. | 1.00 | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | |

Parts Charge: 2.00

Labor Charge: 60.00

Workorder: 1401891

Problem: pm, engine ltrd on fuel door keeps opening while driving

Meter Reading: 59442

In Date: 02/26/2014

Close Date: 03/11/2014

Labor

Hours

Description

Parts

Quantity

- | | | | |
|--|------|---------------------|------|
| - Pm | 4.00 | NAPAGOLD OIL FILTER | 1.00 |
| - Replace Broken Fuel Door Assembly | | NAPA QUART 5W20 | 8.00 |
| - Ck Engine Light Was On Test Drive Scan For Codes | | FUEL HOUSING | 1.00 |
| Found No Code And Ws Unable To Find Any Problem | | SHOP SUPPLIES | 1.00 |
| With The Vehicle At This Time | | | |
| - Shop Supplies | | | |

Parts Charge: 100.71

Labor Charge: 240.00

Workorder: 1407046

Problem: pm

Meter Reading: 63944

In Date: 07/17/2014

Close Date: 07/22/2014

Labor

Hours

Description

Parts

Quantity

- | | | | |
|-----------------|------|---------------------|------|
| - Pm | 2.00 | NAPAGOLD OIL FILTER | 1.00 |
| - Shop Supplies | | WASHER FL | 1.00 |
| | | NAPA QUART 5W20 | 7.00 |
| | | WIPER BLADE | 2.00 |
| | | SHOP SUPPLIES | 1.00 |

Parts Charge: 43.10

Labor Charge: 120.00

12/28/2017
3:54:35PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178913 2009 FORD F150 Pickup, 1/2 Ton, W/Tow Pkg

Workorder: 1410413

Problem: NAIL IN L/REAR TIRE, CHECK ENGINE LIGHT ON

Meter Reading: 67207		Labor		Parts	
In Date: 10/17/2014	Close Date: 10/23/2014	Hours	Description		Quantity
- Ck Engone Light Is On Scan And Found Code Po130		4.75	SHOP SUPPLIES		1.00
Po150 Perform Pinpoint Test And Found Both Bank 1 & 2			SENSOR		2.00
02 Sensor No Switching Replace Both Sensor And Clear Codes					
- Repair Left Front Tire					
- Shop Supplies					
Parts Charge:		310.67	Labor Charge:	285.00	

Workorder: 1412047

Problem: pm, left rear blinker not working, pass door will not hook

Meter Reading: 68487		Labor		Parts	
In Date: 12/02/2014	Close Date: 12/15/2014	Hours	Description		Quantity
- Pm		10.25	SHOP SUPPLIES		1.00
- Ck Tires Replace Two Front Tires Rotate Add N2			TIRE DISPOSAL FEE		2.00
- Verify Needs Pads Replace Front Brake Pads Turn Rotors			NAPAGOLD OIL FILTER		1.00
Svc Calipers			NAPA QUART 5W20		7.00
- Verify Engine Coolant Needs Replaced, Change Engine Coolant			183783418 P235-70R17		2.00
- Replace Two Tail Light Bulbs			DISC BRAKE PADS		1.00
- Ck Sunvisor Wont Hook Verify Camplaine Remove And			COOLANT FORD GOLD		2.00
Repair Visor Clip			BULB		2.00
- Shop Supplies					
Parts Charge:		575.24	Labor Charge:	615.00	

12/28/2017
3:54:35PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178913 2009 FORD F150 Pickup, 1/2 Ton, W/Tow Pkg

Workorder: 1502329

Problem: pm, ck windshield wipers, needs steerig wheel cover

Meter Reading: 70795		Labor		Parts	Quantity
In Date: 03/04/2015	Close Date: 03/13/2015	Hours	Description		
- Pm		3.00	NAPAGOLD AIR FILTER		1.00
- Ck Steering Wheel Cover Install New Cover Replace Drain Plug			NAPAGOLD OIL FILTER		1.00
			WIPER BLADE		2.00
- Shop Supplies			STG WHEEL COV - FORD		1.00
			NAPA QUART 5W20		7.00
			WASHER FL		1.00
			SHOP SUPPLIES		1.00
			DRAIN PLUG		1.00
Parts Charge:		73.13	Labor Charge:	180.00	

Workorder: 1505257

Problem: pm, ck tireson rear uck not dirving right

Meter Reading: 72335		Labor		Parts	Quantity
In Date: 05/26/2015	Close Date: 05/29/2015	Hours	Description		
- Pm		6.50	TIRE DISPOSAL FEE		2.00
- Replace Two Tires Mount Add N2			SHOP SUPPLIES		1.00
- Verify Needs Rear Pads Turn Rotors Svc Calipers Replace Pads			DISC BRAKE PADS		1.00
			NAPAGOLD OIL FILTER		1.00
- Shop Supplies			NAPA QUART 5W20		7.00
			183783418 P235-70R17		2.00
Parts Charge:		534.63	Labor Charge:	390.00	

Workorder: 1507287

Problem: damage to rear bumper & rgt rear fender

Meter Reading: 73403		Labor		Parts	Quantity
In Date: 07/07/2015	Close Date: 07/22/2015	Hours	Description		
- Damage To Rear Bumper & Rgt Rear Fender					
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 1,164.00

12/28/2017
3:54:35PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178913 2009 FORD F150 Pickup, 1/2 Ton, W/Tow Pkg

Workorder: 1512983

Problem: PM

Meter Reading: 77360

In Date: 12/28/2015

Close Date: 01/07/2016

Labor

Hours

Description

Parts

Quantity

- Pm	2.00	NAPAGOLD OIL FILTER	1.00
- Shop Supplies		NAPA QUART 5W20	7.00
		22" WIPER BLADE	2.00
		SHOP SUPPLIES	1.00
		WASHER FLUID CONCENTR	1.00
Parts Charge:	39.80	Labor Charge:	120.00

Workorder: 1605938

Problem: P.M.SERVICE, ABS and brake warning lights on.

Meter Reading: 80795

In Date: 06/09/2016

Close Date: 06/29/2016

Labor

Hours

Description

Parts

Quantity

- Pm Service.	6.50	SHOP SUPPLIES	1.00
- Computer Diagnose For Abs Light On.Code C1300.Abs		NAPAGOLD OIL FILTER	1.00
Pump Circuit.Pin Point Test And Replace Defective Abs		NAPA QUART 5W20	7.00
Module And Reprogram.Bleed System And Roadtest.		ABS CONTROL MODULE	1.00
- Rotate And Balance All Tires.			
- Shop Supplies			
Parts Charge:	886.84	Labor Charge:	390.00

Workorder: 1608984

Problem: Low tire pressure warning light on.Right rear tire flat.

Meter Reading: 82131

In Date: 08/29/2016

Close Date: 08/30/2016

Labor

Hours

Description

Parts

Quantity

- Repair And Balance R/Rear Tire.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

12/28/2017
3:54:35PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178913 2009 FORD F150 Pickup, 1/2 Ton, W/Tow Pkg

Workorder: 1613214

Problem: PM Service.TPMS light on.

Meter Reading: 83796		Labor		Parts	Quantity
In Date: 12/30/2016	Close Date: 01/17/2017	Hours	Description		
-	Pm Service.	5.75	BATTERY		1.00
-	C/C Tpms Light On.Replace Two Bad Wheel		SHOP SUPPLIES		1.00
-	Sensors.Reset Tpms.Rotate And Balance All.Correct N2.		WASHER FLUID CONCENTR		1.00
-	Verify Battery Dragging.Test Bad.Replace Battery.		NAPAGOLD OIL FILTER		1.00
-	Shop Supplies		20" WIPER BLADE		2.00
			TPMS KIT		2.00
			22" WIPER BLADE		2.00
			NAPA QUART 5W20		7.00
Parts Charge:		315.46	Labor Charge:	345.00	

Workorder: 1704338

Problem: Will not start.

Meter Reading: 85674		Labor		Parts	Quantity
In Date: 04/28/2017	Close Date: 05/15/2017	Hours	Description		
-	Diagnose For No Start.Fabricate And Repair For Fuel	5.50	FUSE RELOCATE KIT		1.00
-	Pump Fuse Relocation Kit..Fully Recharge And Test		BRAKE SHOES PARK		1.00
-	Battery And Charging System.		SHOP SUPPLIES		1.00
-	Repair And Balance Right Rear Tire.Nitrogen Fill All.				
-	Shop Supplies				
Parts Charge:		20.06	Labor Charge:	330.00	

Workorder: 1706587

Problem: Pm service.

Meter Reading: 86489		Labor		Parts	Quantity
In Date: 07/05/2017	Close Date: 07/12/2017	Hours	Description		
-	Pm Service	5.75	WASHER FLUID CONCENTR		1.00
-	Rotate And Balance Four Tires.		NAPA QUART 5W20		7.00
-	Repaired Wiring Harness To Front Strobe Lights Left Side		NAPAGOLD OIL FILTER		1.00
-	Inop.(Inside Cab)		USED FIRE X REFURBISHED		1.00
-	Shop Supplies		22" WIPER BLADE		2.00
			DRAIN PLUG		1.00
			SHOP SUPPLIES		1.00
			NAPAGOLD AIR FILTER		1.00
Parts Charge:		66.46	Labor Charge:	345.00	

12/28/2017
3:54:35PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178913 2009 FORD F150 Pickup, 1/2 Ton, W/Tow Pkg

Workorder: 1712195

Problem: Transition Prep Charge

Meter Reading: 88915

Labor

Parts

In Date: 12/12/2017

Close Date: 12/12/2017

Hours

Description

Quantity

- Transition Prep Charge

2.00

Parts Charge: 0.00

Labor Charge: 120.00

Total Parts Charges: 4,886.85

Total Labor Charges: 5,865.00

Total Comm. Charges: 1,164.00